



CABRILLO BRIDGE Rehab/Retrofit Project

Description of work

Grade the abutment slopes on the inside to fill in gullies and eroded areas and to restore proper slope. Photos show existing conditions.



Repair existing drainage systems to prevent further water damage.



Photo of Bent 6 - interior broken down drain before repairs were made.

Repair broken drainage pipe inside east abutment – existing condition

Add netting to prevent re-entry of birds and bats at the openings, to prevent re-contamination.



Photo taken of Bent 4