CITY OF SAN DIEGO HISTORICAL RESOURCES BOARD

DESIGN ASSISTANCE SUBCOMMITTEE

Wednesday, April 4, 2012, at 4:00 PM 5th Floor Large Conference Room City Operations Building, Development Services Department 1222 First Avenue, San Diego, CA

MEETING NOTES

1. ATTENDANCE

Subcommittee Members	Alex Bethke (Chair); Gail Garbini; Linda Marrone; Ann Woods
Recusals	N/A
City Staff	
HRB	Jodie Brown; Cathy Winterrowd
Guests	-
Item 3A	Bob Bauer
Item 3B	Kelly Kincaid, Todd Massure
Item 3C	Kelly Kincaid, Todd Massure
Other	Bruce Coons, SOHO; Ashley Christensen, SOHO

2. Public Comment (on matters not on the agenda)

3. Project Reviews

• **<u>ITEM 3A</u>**:

Listings: HRB Site #528 Address: 7890 Torrey Lane Historic Name: Dr. Harold C. & Frieda Daum Urey/Russell Forester House Significance: Architecture (Custom Residential Ranch); Master Architect Russell Forrester <u>Mills Act Status</u>: Yes <u>PTS #</u>: 272502 <u>Project Contact</u>: Bob Bauer, Annette and Terry Buis <u>Treatment</u>: Rehabilitation <u>Project Scope</u>: This project proposes an addition of 720.5 SF to an existing single family residence at the rear of the principle structure. Conversion of the existing master bedroom into a sitting area for a new master bedroom. Conversion of the existing master bathroom into an internal laundry room. Provide a new master bath and walk-in closet. Install one factory fabricated gas-only fireplace in the new bedroom area. Remodel an existing bedroom with a total remodel of 550 SF. Replace three existing windows and two exterior single light doors, with equivalent wood framed units in the original residence. <u>Existing Square Feet</u>: 3,126 <u>Additional Square Feet</u>: 721 <u>Total Proposed Square Feet</u>: 3,847 <u>Prior DAS Review</u>: 3/1/2012

<u>Staff Presentation</u>: This project was reviewed at the March DAS meeting. The subcommittee members wanted an opportunity to visit the site on their own time with a copy of the plans to help understand the relationship of the house and the proposed addition to the street.

<u>Applicant Presentation</u>: Concerns from the previous meeting were views of the addition from the public right of way. The reason that the addition/modifications were proposed was to stop water intrusion that has always been a problem for this lot. There is a problem with mold and mildew in the master closet which has resulted in damage to the wood. A question from last month is whether we are removing the rear wall and the answer is yes. We would be raising the foundation 6" and correcting the roof and site drainage. Secondarily, the owners would like to have an interior laundry. The owners would also like to have more storage. The new addition would be compatible but it would be distinguished from the older construction.

Public Comment:

Name	Comments
Coons	Ranch houses are designed to be added to over time.
	Their style is meant to be added on. My concern is the
	removal of the historic fabric and the inability to restore
	the original house

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
Garbini-It appears that the only thing that	
you can really see is the garage. I thought	
you would be able to see more from the	
street. From the two roads above you	
cannot really see the building.	
Garbini-How was it designated?	It was designated under Criteria A, B,
	C, and D.
Bethke-What are the materials of the	Proposing to use Certainteed paneling
addition?	to make the appearance of board and
	batten. The original house has
	overhangs and the addition would not
	have overhangs and the master
	bedroom would have a flat roof with
	parapet walls. Wherever the roof is

Subcommittee-member Issue or Question	Applicant's Response
	new we would be cropping the eaves.
	Any sightline from the side of the
	house would not be visible.
Bethke-What about taking the addition back	There are a number of easements that
to the property line instead of moving it to	we have to contend with. The
the interior of the lot?	perimeter easement, one that takes that
	corner, one that cuts through the
	master bedroom/bathroom. There is
	also an existing retaining wall.
	Removal of the retaining wall would
	be a nightmare with coastal permits,
	etc. The addition is also in an existing
	brush management zone.

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Bethke	It seems that the addition could be a little more linear and
	back towards that property line. Otherwise, the addition
	is fine.
Garbini	I don't think that you have significantly altered the
	interior other than putting a laundry room in a previous
	bathroom. It meets the Standards from the street view,
	but it seems that it was not really a clean example of a
	Russell Forrester designed home. However, it is not
	designated solely on C.
Marrone	I was familiar with this property, so I had a feeling that
	the addition was not going to be visible. Even though
	there have been some additions to the house they are
	mostly at the rear of the house.
Woods	Agree with Gail. Although not visible from the street, it
	will no longer be an "L" shaped house and the flat roof at
	the rear it changes the nature of the house.

Staff Comment:

N/A

Recommended Modifications:

N/A

Consensus:

 \blacksquare Consistent with the Standards

Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

• <u>ITEM 3B</u>:

Listings: HRB Site #208-138 Address: 506 22nd Street Historic Name: Sherman Heights District Contributor Significance: District Contributor Mills Act Status: Yes PTS #: 275476 Project Contact: Kelly Kincaid, Massure & Associates Treatment: Rehabilitation Project Scope: Work consists of removal of existing metal siding, restoration of existing wood siding, doors and windows. Remodel of the interior. Upgrade electrical, install water heater in attic, new HVAC, install new gas fireplace insert, remove exisitng chain link fence, and tree in ROW, remove existing chimney. Existing Square Feet: 3,186 Additional Square Feet: 0 Total Proposed Square Feet: 3,186 Prior DAS Review: N/A

<u>Staff Presentation</u>: The property owner has a previously approved addition and would like to do additional work to the house. The additional work was done without a permit and the owner is in the process of trying to resolve the code case. The work that would need to be approved would include the removal of the historic chimney and the restoration of the side porch that was previously enclosed.

<u>Applicant Presentation</u>: We are fixing issues related to Code Enforcement. We were approved for a new addition, but the chimney was removed. The owner is requesting to keep the chimney off of the house. If the chimney were to remain it would not be operable.

Public Comment:

Name	Comments
Bruce	The building was a mess. The question is should it be
	reconstructed and removed with the addition? A lot of
	work has been done to the house to restore it.

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
Bethke-What is the addition that encroaches	There is addition at the rear of the
on that portion of the house?	house that was previously approved
	and the chimney is enveloped into the
	addition. The chimney would only
	protrude two feet up.
Bethke-Did staff approve the addition?	Yes, it was reviewed and approved by
	Kelley Stanco in 2009.
Bethke-Is there more than on chimney?	There is only one

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Bethke	It is not worth reconstructing the chimney.
Garbini	What would be the purpose of adding a non-functioning
	chimney?
Marrone	It seems after the fact. It is seems that the chimney is
	dead center and the addition is off to the side.
Woods	It was approved without a chimney in 2009

Staff Comment:

N/A

Recommended Modifications:

N/A

Consensus:

 \blacksquare Consistent with the Standards

Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

• <u>ITEM 3C</u>:

<u>Listings</u>: HRB Site #208-324 <u>Address</u>: 2245 22nd Street <u>Historic Name</u>: Sherman Heights District Contributor <u>Significance</u>: District Contributor <u>Mills Act Status</u>: Yes <u>PTS #</u>: N/A <u>Project Contact</u>: Kelly Kincaid, Massure & Associates <u>Treatment</u>: Rehabilitation <u>Project Scope</u>: Proposed addition of new skylights on the west and east side of the roof. Modification to the gable end window to replace the fixed window with either an operable pair of casements or an awning window. <u>Existing Square Feet</u>: 4,270 <u>Additional Square Feet</u>: 0 <u>Total Proposed Square Feet</u>: 4,270 <u>Prior DAS Review</u>: N/A

<u>Staff Presentation</u>: The property owner would like to add additional skylights to the side of the mansard roof. Previously, the property owner was approved for three skylights and they would like to add one more to the rear, two to the side and three to the other side and make the front dormer windows operable.

<u>Applicant Presentation</u>: The space gets up to 100 degrees and it heats up the upper floors. We rely on the skylights to cool the area

Public Comment:

Name	Comments
Bruce	I don't think that they should be able to visible from
	street. Typically, they would have added a roof hatch.

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
Garbini-How is the space accessed?	Via stairs
Garbini-Is there a basement?	Yes
Garbini-If there was a roof hatch what	They would provide the same result,
would be the difference with a skylight?	which is air ventilation.
Garbini-What about cross ventilation	We would like to make the dormer
through some front windows?	windows operable.
Bethke-On the east elevation why are the	On the west side they are on the rear
skylights located towards the front?	so it provides more cross ventilation
	by off-setting them.
Marrone-Are there other options?	The eaves are small and not conducive
	to adding ventilation
Marrone-I think you should investigate the	
roof hatch. There is no need to go out to the	
site.	

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Bethke	Investigate the existing front dormer window, and if they
	were operable they should be repaired. The south
	elevation extra skylight is fine, but I am not sure how
	you would not see the additional skylights. My

Subcommittee-member	Comments
	recommendation is not to have the side skylights. I
	would direct the applicant to look to a roof hatch. I am
	concerned about cutting into the character-defining
	feature of the roof. There are other ways to accomplish
	what you are trying to do. Vegetation should not be
	something that blocks alterations. Not appropriate to cut
	into an original feature.
Garbini	You could purchase the hardware for the dormer window
	and keep the existing frame to repair the windows. I
	don't have the same issues with skylights. If historically
	they had roof hatch, then I don't have an issue with
	skylights they operate in a similar manner.
Marrone	If it had a roof hatch would that be enough? (no because
	of storage in the attic)
Woods	I would like to look at the site.

Staff Comment:

N/A

<u>Recommended Modifications</u>: DAS recommends that you investigate the roof hatch and the dormer window at the front to determine the operation. The side skylights are not appropriate, but one additional one at the rear is fine.

Consensus:

Consistent with the Standards

 \blacksquare Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

4. Adjourned at 5:23 PM

The next regularly-scheduled Subcommittee Meeting will be on May 2, 2012 at 4:00 PM.

For more information, please contact Jodie Brown at <u>JDBrown@sandiego.gov</u> or 619.533.6300