

# **REMMEN BUILDING**

TREATMENT PLAN September 1, 2016

#### **PROJECT DESCRIPTION:**

The historic Remmen Building is a two-story Craftsman (Arts and Crafts) style structure with Eclectic Neo-Classical features on the corner of G Street and Park Boulevard in San Diego's East Village. The wood-framed structure was built in 1907 by Mr. O. Remmen. Identified as a potential historic site in a 1988 survey, the building was designated as City of San Diego Historical Site #426 in 2000.

The property on which the Remmen Building is located is part of a proposed redevelopment project called Park+Market which will occupy the entire block bounded by G Street, Market, 11<sup>th</sup> Avenue, and Park Boulevard. The proposed redevelopment project includes the construction of a 50,000 square foot office building on Market Street and a mixed-use residential tower at the corner of G Street and 11<sup>th</sup> Avenue. Site improvements will include the addition of a subterranean parking garage, public plaza, amphitheater, and private open space. To facilitate the construction of the underground parking garage and other site improvements, the Remmen Building will be temporarily relocated to a holding site at the corner of Market Street and 13<sup>th</sup> Street. The building will then be transported back to the site where it will be shifted to the east and rotated 90 degrees to face a new tree-lined sidewalk along Park Boulevard.



Figure 1: Park + Market site development plan.

Page 1 of 10

#### **INTRODUCTION:**

The implementation of this Treatment Plan for the relocation and exterior rehabilitation of the Remmen Building will be facilitated by a qualified historic structure mover. Construction Observation services will be provided by the Project Architect, Carrier Johnson, and the Historic Architect/Monitor, Heritage Architecture & Planning. The project shall be completed in accordance with the mitigation, monitoring, and reporting program for this project. This Treatment Plan is accompanied by schematic drawings which depict the proposed exterior rehabilitation of the building.

#### **RELOCATION/REHABILITATION STRATEGY:**

Prior to the development of the site, the Remmen Building will be temporarily moved offsite for a period of approximately one year during the construction of the proposed subterranean parking garage. The main structure will be transported in one piece to a vacant lot at 1301 Market Street, approximately two blocks southeast of its current location. The building will then be mothballed per the NPS Preservation Briefs 31: Mothballing Historic Buildings.

After the completion of the subterranean parking garage at the Park+Market site, the Remmen Building will be relocated back to the original site at the northeast corner of the block. The building will be rotated 90 degrees clockwise so that the primary entry faces Park Boulevard, enabling the creation of a larger central public plaza area to the south. The City of San Diego will vacate a 10-foot strip of right-of-way along the east property line allowing the front entry porch to encroach into the current right-of-way space.



Figure 2: Existing and temporary relocation sites.

Source: Google Maps.

Page 2 of 10

ARCHITECTURE & PLANNING

The future tenant of the rehabilitated building has not yet been identified. The proposed future use of the building will likely change its occupancy classification from residential/office to restaurant. Due to the proposed change in use, it is assumed that some exterior changes will be required in order to provide disabled access to the building and facilitate the proposed public use. The proposed site improvements include the addition of a ramp and elevated patio area adjacent to the building. An accessible entrance on the new south facade will also be created by modifying one or two of the existing window openings to install a new door. The leaded glass windows located at the front of the building that are premiere character-defining features will not be affected. The windows that are proposed to be altered are located toward the back of the building on the side elevation and they are standard 1/1 wood double-hung windows of a more simple construction. Modifications to the Remmen building shall be in compliance with *The Secretary of the Interior's Standards for the Treatment of Historic Properties (The Standards*), specifically the *Standards for Rehabilitation*.

Since the future tenant of the rehabilitated building has not yet been identified, the exact scope of the future interior rehabilitation is not known at this time. However, it appears certain that the current interior layout of the four apartment units could not support a restaurant use. The rehabilitated building will need to include a commercial restaurant kitchen, food services facilities, accessible restrooms, and other improvements to facilitate the restaurant use. There is a general understanding that significant interior alterations will be required, including the removal of existing historic features and finishes in order to accommodate the proposed future use. If feasible, depending on the eventual interior layout, representative examples of character-defining interior features will be preserved and re-used in the rehabilitated building. The Remmen Building interior was not included in the designation report.

Additional review and approval by the City of San Diego's Development Services Department and the Historical Resources Board will be required when the full scope of the restaurant rehabilitation is defined.

### PREPARATION, RELOCATION, & REHABILITATION REQUIREMENTS:

### 1. Preparation of the Structure Prior to Relocation:

<u>Coordination Meeting & Monitoring</u>: Prior to the start of any work the Project Architect and Historic Architect/Monitor shall meet on site with the moving contractor to review the scope of demolition, removal, salvage, temporary shoring, and relocation. Through the course of all work, the moving contractor shall notify the Historic Architect/Monitor of discovery of any architectural elements on site. The Historic Architect/Monitor shall evaluate the significance of such material prior to determining the appropriate treatment in compliance with *The Secretary of the Interior's Standards for Rehabilitation*.

Construction monitoring shall be provided prior to preparation of the building for relocation. The construction Monitor shall provide a Consultant Site Visit Record summarizing the field conditions and any recommendations for compliance with *The Standards*.

<u>Temporary Shoring</u>: The moving contractor shall provide and maintain necessary shoring to protect and stabilize the building during the relocation and storage phases. Means and methods for temporary shoring will be determined by the moving contractor and the implementation of these procedures shall occur only after review by the Historic Architect/Monitor. The

Page 3 of 10

mover shall outline any proposed points of entry and attachment for anchors or beams. Historic siding or trim affected by the attachment of temporary shoring shall be removed prior to installation of shoring, catalogued, labeled and securely stored in a weather-tight lockable container pending reinstallation at the final site.

<u>Windows:</u> All window shall be protected by plywood prior to relocation. The existing windows on the first floor and rear facade of the building are currently protected by plywood to prevent vandalism. Existing plywood may be kept in place, if deemed adequate by the moving contractor. Unprotected windows shall be covered with <sup>3</sup>/<sub>4</sub>" exterior grade plywood installed in a similar manor as the existing plywood, without causing damage to the existing historic windows, frames, and trim.

<u>Doors</u>: The four existing historic exterior doors at the front façade of the building shall be protected in place. The existing plywood covering shall be maintained pending the exterior rehabilitation. The exterior door openings at the rear façade are also covered with plywood. The plywood shall be inspected by the contractor and replaced if needed.

<u>Masonry Foundation Cladding</u>: Prior to relocation, the ashlar masonry cladding on the foundations walls shall be documented, photographed, catalogued, salvaged, and stored by the moving contractor. All documentation will be submitted to the City for review and approval prior to removal of the ashlar masonry cladding. All salvaged items will be stored on labeled and wrapped pallets and secured in a weather-tight lockable steel container that will be located at the temporary relocation site adjacent to the building.

<u>Chimneys</u>: Prior to relocation, the remaining historic brick chimney on the west side of the building shall be disassembled above the roofline. Prior to disassembly, the chimney shall be measured and photo documented. All documentation will be submitted to the City for review and approval prior to removal of the chimney. The brick shall be catalogued, salvaged, and stored for reinstallation at the final site. All salvaged items will be stored on labeled and wrapped pallets and secured in a weather-tight lockable steel container that will be located at the temporary relocation site adjacent to the building.

<u>Front Steps and Porch</u>: Prior to relocation the concrete front steps and ashlar masonry wing walls will be removed to facilitate the relocation. Prior to disassembly, the wing walls shall be measured, photo documented, and salvaged. All documentation will be submitted to the City for review and approval prior to removal of the steps and wing walls. The concrete steps will not be salvaged, but samples of the concrete shall be retained for future matching of the concrete color and texture. All salvaged items will be stored on labeled and wrapped pallets and secured in a weather-tight lockable steel container that will be located at the temporary relocation site adjacent to the building.

The front porch, including the porch floor, balustrade, columns, roof, trim, railings, and decorative elements shall be protected in place and securely shored in order to facilitate the structure relocation and temporary storage.

<u>Rear Porches:</u> The rear porched are historic and they shall be protected in place. Temporary shoring shall be provided by the moving contractor to protect these elements during relocation and storage. The raised wood deck and stairs at the rear porches are not historic. These elements shall be demolished prior to the relocation.

#### 2. Relocation Procedures:

The Remmen Building will be moved approximately 800 feet to a temporary storage site located on a City-owned property at the southeast corner of Market and 13<sup>th</sup> Street. The building will be moved in one piece and will be stored at the temporary relocation site for a period of approximately one year pending completion of a subterranean parking structure and other improvements at the Park+Market site that must be completed prior to the final relocation and rehabilitation of the building.

The mover shall outline the route, schedule, and sequence of the move as well as the means by which the building will be secured for the relocation. The Historic Architect/Monitor and City staff shall approve the plan prior to the relocation date.

<u>Monitoring</u>: Construction monitoring shall be provided during the relocation process, both when the building is moved to the temporary storage site and when it is moved to its final location. Following each site visit, the Monitor shall provide a Consultant Site Visit Record summarizing the field conditions and any recommendations for compliance with *The Standards*.

#### 3. Protection Measures at the Temporary Relocation Site:

<u>Security:</u> The Remmen Building has been vacant for several years. In 2009 Civic San Diego (formerly the Centre City Development Corporation) completed a project to restore the exterior of the building. The project included painting the exterior to match the original color scheme, minor wood repair, and installation of temporary plywood covering over existing windows and doors to protect the building from vagrancy and vandalism. A chain link fence has also been added on all sides of the building for additional security. These temporary protection measures, along with routine visual inspection by City crews, have been successful in protecting the building since 2009. Similar measure are proposed at the temporary relocation site. Plywood will be maintained over all window and door openings and a 6-foot tall chain-link fence will be added around the perimeter of the building. Monitoring and visual inspection of the exterior of the building will be provided weekly by Holland Construction while the building is at the temporary relocation site.

All salvaged materials will be stored on palettes and secured in a weather-tight, lockable steel storage container which will be kept at the temporary relocation site adjacent to the Remmen Building.

<u>Mothballing</u>: During temporary storage, and until the building is successfully rehabilitated, it shall be securely mothballed. Mothballing essentially means closing up the building temporarily to protect it from weather and vandalism. Mothballing should include providing necessary temporary structural stabilization (shoring), adequately eliminating and controlling pests, protecting the interior from moisture, providing adequate security, ensuring adequate interior

ventilation, and implementing a maintenance and monitoring plan to ensure that the building is adequately secured and routinely inspected.

<u>Monitoring</u>: Construction monitoring shall be provided to ensure that the building is securely stored and adequately mothballed at the temporary storage site. The Monitor shall complete a Consultant Site Visit Record summarizing the field conditions and any recommendations for compliance with *The Standards*.

#### 4. Building Rehabilitation:

Following the relocation of the Remmen Building, the exterior of the structure will be rehabilitated and repaired in accordance with *The Secretary of the Interior's Standards for Rehabilitation*.

The concrete entry steps to the porch will be replicated in-kind and the curved outer walls will be reconstructed using salvaged ashlar masonry where feasible. The reconstructed stairs will eliminate up to two risers in order to lower the building's finished floor level to approximately 30" above the adjacent sidewalk. The square-cut ashlar masonry foundation walls will be replicated using salvaged square-cut ashlar masonry units.

<u>Construction Monitoring</u>: Periodic construction monitoring shall be provided during the rehabilitation process. Following each site visit, the construction monitor shall provide a Consultant Site Visit Record summarizing the field conditions and any recommendations for compliance with *The Standards*.

<u>Rehabilitation Design</u>: The future rehabilitation of the building shall be completed in accordance with *The Standards*. The design team shall include the services of a Historic Architect that meets the Secretary of the Interior's Professional Qualification Standards. The rehabilitation design will require review and approval by the City of San Diego's Development Services Department and the Historical Resources Board staff and/or Design Assistance Subcommittee.

#### **REHABILITATION RECOMMENDATIONS:**

<u>Site</u>:

• In accordance with *The Standards*, new additions such as the proposed new elevated exterior restaurant seating areas, shall not destroy historic materials, features, and spatial relationships that characterize the property. They should be differentiated from the historic construction and compatible in materials, features, size, scale, proportion, and massing. They should also be constructed in such a manner that, if removed in the future, the essential form and integrity of the building would be unimpaired.

<u>Roof</u>:

• Remove and replace existing composite shingle roofing with new composite shingles with a natural cedar color.

#### Exterior Walls:

• Repair deteriorated wood siding and repaint the building using the existing historic color scheme.

#### Front Porch:

- Repair deteriorated wood flooring and repaint using the existing historic color.
- Repair and repaint other wood features using the existing historic color scheme.
- Reconstruct the front steps with new concrete steps matching the detailing of the original steps in-kind using salvaged square-cut ashlar masonry to reconstruct the curved wing walls. Salvaged concrete samples from the original steps should be used to ensure that the new concrete matches the original concrete color and texture in-kind. The reconstructed stairs will eliminate no more than two of the original risers in order to lower the building's finish floor elevation to approximately 30-inches above the adjacent sidewalk.

#### Rear Porches:

- Demolish non-historic deck and exterior stairs.
- Stabilize and/or reconstruct historic rear porches.

### Foundation:

• The proposed building relocation will require the removal of the existing foundation and construction of a new foundation system. The original ashlar masonry cladding will be salvaged and reinstalled on the new foundation to match the existing appearance in-kind. Damaged masonry units will be replaced in-kind.

### Chimneys:

- Seismically retrofit or reconstruct remaining original chimney.
- Reconstruct two missing brick chimneys.
- Depending on the desired future use (if any) of the chimneys, the reconstructed chimney could be cosmetic, meaning the structure would be wood framed and clad with a decorative brick veneer matching the original chimney appearance. The reconstructed chimneys could also be utilized to conceal new mechanical vents that may be required for the rehabilitated building.

#### Windows:

- Replace broken glass with restoration glass.
- Restore existing historic windows to working condition and add weatherstripping. Repair exterior using the existing historic colors and refinish the interior.

#### Exterior Doors:

- Replace broken glass and restore the existing front entry doors.
- Install ADA compliant door hardware.
- Replicate damaged and missing rear porch doors.

#### Interior:

• Install ADA compliant door hardware where required.

#### Page 7 of 10



- Any historic doors that are removed during rehabilitation should be salvaged.
- Remove non-historic carpeting and restore/refinish original wood flooring.
- New flooring may be required in some areas to serve the new restaurant use, but public areas and undisturbed portions of the building should reuse the existing historic flooring if feasible.
- Maintain existing lath and plaster wall and ceiling finishes where feasible. Where new walls are required, match the existing plaster where feasible, particularly in public areas.
- Restore and reuse existing historic lighting wherever feasible. Where removal is required to serve the new use, salvage the historic fixtures.
- Some historic features such as stairs, guardrails, fireplaces, built-ins, walls, doors, trim, fixtures, and finishes may be removed during future rehabilitation efforts. Where feasible, preserve and protect the remaining character-defining interior features and finishes in the rehabilitated building.

Mechanical, Plumbing, and Electrical Systems:

- Install an approved automatic fire sprinkler system.
- Upgrade electrical service and panel(s) for new restaurant use.
- Design and install new HVAC system and kitchen exhaust to serve the new restaurant use.
- Install new accessible restrooms to serve the new restaurant use.
- Design and install required electrical, lighting, mechanical, and plumbing systems to serve the new restaurant kitchen.

### SUMMARY OF EXISTING HISTORIC FEATURES:

### Exterior:

Historically significant exterior features and finishes should be preserved and protected in accordance with *The Standards*. Existing historic exterior features include:

- Leaded glass and curved windows.
- Leaded glass doors.
- Corinthian columns supporting the front balcony and dormer window.
- Square-cut ashlar masonry foundation walls.
- 1/1 double-hung wood windows.
- Front and rear porches.
- Four single-light front doors.
- Horizontal wood siding.
- Existing exterior trim and decorative elements.

### Interior:

The interior of the building also retains a high degree of historical integrity. Existing historic interior features include:

- Built-in desk, shelf, and columns between the living and dining rooms in the two ground floor apartments.
- Curved bay windows and built-in window seats in the two second floor apartments.
- Brick fireplaces and tiled hearths in all four apartments.

#### Page 8 of 10

- Original light fixtures.
- Wood floors and baseboards.
- Wood door and window trim.
- Interior 5-panel wood doors.
- Pocket doors between the living and dining rooms in the two second floor apartments.
- Built-in wood cupboards and closets.
- Wood kitchen cabinets, ice boxes, sinks, and drain boards.
- Claw foot tubs in all four bathrooms and remaining chrome shower risers and curtain rings in two bathrooms.
- Recessed wood medicine cabinets in all four bathrooms.
- One original towel bar/shelf in the bathroom of the second floor west apartment (Unit 1133).
- Obscured glass interior windows at the bathrooms.
- Wall-mounted lavatories in all four bathrooms.
- One original toilet in the bathroom of the second floor west apartment (Unit 1133).

### Non-Historic Features:

The Remmen Building retains a high degree of historical integrity. Only a few minor alterations have been completed since the building's construction in 1907. Non-historic exterior features are limited to the raised wood deck and stairs on the back side of the building. The existing composite shingle roofing is also not original. All of other existing features and finishes on the exterior of the building are historic and they contribute to the historical character of the building.

The interior of the building possesses a similarly high level of historical integrity. The only apparent interior alterations to the building are the addition of carpeting on the original wood floors and the addition of two door openings in the original demising wall separating the apartment units on each floor.

### SUMMARY OF APPLICABLE STANDARDS AND GUIDELINES:

Any work undertaken on the historic Remmen Building, including the proposed relocation and subsequent rehabilitation, shall be completed in compliance with *The Secretary of the Interior's Standards for the Treatment of Historic Properties (The Standards)*. There are separate standards for acquisition, protection, stabilization, preservation, rehabilitation, restoration, and reconstruction. Rehabilitation has been identified as the appropriate treatment for the Remmen Building due to the proposed change in use to a restaurant occupancy. Rehabilitation is defined as "the process of returning a property to a state of utility, through repair or alteration, which makes possible an efficient contemporary use while preserving those portions and features of the property which are significant to its historic, architectural, and cultural values." The ten standards for rehabilitation are:

### Rehabilitation Standards

1. A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.

# HERITAGE

ARCHITECTURE & PLANNING



- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 3. Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken.
- 4. Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.
- 5. Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a historic property shall be preserved.
- 6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
- 7. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.
- 8. Significant archeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

The City of San Diego will use *The Standards* as a guideline for confirming the appropriateness of proposed rehabilitation work for the building. Rehabilitation work and proposed alterations and modifications to the building will also need to comply with the current (2013) California Building Code and the Americans with Disabilities Act (ADA). Additionally, since the Remmen Building is a designated historical resource, the provisions of the California Historical Building Code are also applicable to all future relocation and rehabilitation work.

# REMMEN BUILDING TREATMENT



### STATEMENT OF SIGNIFICANCE

THE REMMEN BUILDING IS A CRAFTSMAN (ARTS AND CRAFTS) STYLE STRUCTURE WITH ECLECTIC NEO-CLASSICAL FEATURES. THE TWO-STORY WOOD-FRAMED FOUR-UNIT BUILDING IS LOCATED NEAR THE CORNER OF G STREET AND PARK BOULEVARD IN DOWNTOWN SAN DIEGO. COMPLETED IN 1907, THE REMMEN BUILDING IS LOCALLY DESIGNATED ON THE CITY OF SAN DIEGO'S REGISTER OF HISTORICAL RESOURCES (HRB #426).

### **PROJECT INFORMATION**

THE PROPERTY ON WHICH THE REMMEN BUILDING IS LOCATED IS PART OF A PROPOSED REDEVELOPMENT PROJECT CALLED PARK+MARKET WHICH WILL OCCUPY THE ENTIRE BLOCK BOUNDED BY G STREET, MARKET, 11TH AVENUE, AND PARK BOULEVARD. THE PROPOSED REDEVELOPMENT PROJECT INCLUDES THE CONSTRUCTION OF A 50,000 SQUARE FOOT OFFICE BUILDING ON MARKET STREET AND A MIXED-USE RESIDENTIAL TOWER AT THE CORNER OF G STREET AND 11TH AVENUE. SITE IMPROVEMENTS WILL INCLUDE THE ADDITION OF A SUBTERRANEAN PARKING GARAGE, PUBLIC PLAZA, AMPHITHEATER, AND PRIVATE OPEN SPACE. TO FACILITATE THE CONSTRUCTION OF THE UNDERGROUND PARKING GARAGE AND OTHER SITE IMPROVEMENTS, THE REMMEN BUILDING WILL BE TEMPORARILY RELOCATED TO A HOLDING SITE AT THE CORNER OF MARKET STREET AND 13TH STREET. THE BUILDING WILL THEN BE TRANSPORTED BACK TO THE SITE WHERE IT WILL BE SHIFTED TO THE EAST AND ROTATED 90 DEGREES TO FACE A NEW TREE-LINED SIDEWALK ALONG PARK BOULEVARD.

THE IMPLEMENTATION OF THIS TREATMENT PLAN FOR THE RELOCATION AND EXTERIOR REHABILITATION OF THE REMMEN BUILDING WILL BE FACILITATED BY A QUALIFIED HISTORIC STRUCTURE MOVER. CONSTRUCTION OBSERVATION FOR THE RELOCATION AND EXTERIOR REHABILITATION OF THE REMMEN BUILDING WILL BE PROVIDED BY HERITAGE ARCHITECTURE & PLANNING. THE PROJECT WILL BE COMPLETED IN ACCORDANCE WITH THE MITIGATION, MONITORING, AND REPORTING PROGRAM FOR THIS PROJECT. THESE TREATMENT DRAWINGS ARE ACCOMPANIED BY A WRITTEN TREATMENT PLAN (SHEET TP1.1) WHICH PROVIDES A DETAILED SUMMARY OF THE HISTORIC TREATMENT PROCEDURES FOR THIS PROJECT.





0

9 2 1

Ū

DIEGO,

SAN

STREET

Ċ Э Э

129-

SHEET 1 OF 8

#### HERITAGE 1

- Original light fixtures,
  Wood floors and baseboards.
  Wood door and window trim.
  Interior 5-panel wood doors.
- Pocket door between the living and dining rooms in the two second floor apariments. Built-in wood cupboards and closets.
- Wood kitchen cabinets, ice boxes, sinks, and drain boards. Claw foot tubs in all four bathrooms and remaining chrome shower risers and curtain rings
- in two bathrooms. Recessed wood medicine cabinets in all four bathrooms.
- One original towel har/shelf in the bathroom of the second floor west anartment (Unit
- Obscured plass interior windows at the bathrooms.
- Wall-mounted lawatories in all four bathrooms.
   One original toilet in the bathroom of the second floor west apartment (Unit 1133).

Non-Historic Features: The Remmen Building retains a high degree of historical integrity. Only a few minor alterations have been completed since the building's construction in 1907. Non-historie exterior features are limited to the nisled wood deck and stairs on the back side of the building. The existing composite shingle erofting is also not original. All of other existing situatures and finishes on the exterior of the building are historic and they contribute to the historical character of the building.

The interior of the building possesses a similarly high level of historical integrity. The only apparent interior alterations to the building are the addition of carpeting on the original wood floors and the addition of two door openings in the original demising wall separating the spartment units on each

#### SUMMARY OF APPLICABLE STANDARDS AND GUIDELINES:

SUMMARY OF APPLICABLE STANDARDS AND GUIDBLINES: Any work understaken on the bistoric Remmen Building, including the proposed relocation and subsequent relationation and the completed in compliance with TB's *Sorting of the Interior's Standards* for *Ms Transmet of Elitoric Properties* (TM Standard). There are separate standards for acquibition, protections, sublishant, preservation, relabilitation, restoration, and the proposed change more construction. Relabilitation is defined as "the property based in use to a restance toccupance, Relabilisation is defined as "the property has a state of utility, through repair or alternation, which makes possible an efficient contemporary use while preserving those portions and features of the property has equipated to the significant to its bistoric, architectural, and cultural values." The ten standards for rehabilitation are:

#### Rehabilitation Standards

A property shall be used for its bistoric purpose or be placed in a new un that requires minimal change to the defining sharacteristics of the building and its site and environment.

Page 9 of 10 431 FIFTH AVENUE, SAN DURGD, CA 92101 TH ALR.234.4285 HERITAGRARCHITECTURE.COM

#### :

- The bitmete doenative of a property shall be retained and practical. The reasonal of bitmete materials or advention of futures and spaces that doenaterity a property shall be availed. Each property shall be receptived as a copyright neurof of its time, pater, and use. Changes that create a future some of kinterial development, with us adding conjectural futures or architectural doenation form other minimum et al. on anomalous.
- 3.
- fair sens of Matried development, reds as adding conjectural features or architectural shawness from sober waldings, table and the undertabane. Must properties change new time; these changes that have explained histories significance is their new right shall be related as imported. Distinctive features, finishes, and construction hebriques or examples of reafteneouslob that characterize a latterier property. Mult be provend. Distribution features, finishes, and construction hebriques or examples of reafteneouslob that characterize a latterier property. Mult be provend. Distribution fails in the source of the source of the source of the source of the register replanement of a distinction failers, the new feature shall method he old in design, own, booten, and show various qualities and, show packing, were started as advanted here the source of the source shall be substantished by charameterized as a medications, flow can change to historie meetrical shall was the and. The source characterized as anotherized to be and constructions and the source of th

- partillo. Significant arthoological resources efficiend by a project shall be protected and preserved. If such resources man be distorted, integration measures shall be indicatedane. Now additants, control adventus, or a thand was constructions shall not descrey historie materials that characterity the property. The new work shall be differentiated from the solid out shall be seengabled with the maximity stays and, and enviloations flatement to histories that have the property and its start of the property. The property of the property and its flatement to prove the histories instays for the property and its start of the property. 9.
- environment. New additions and adjacent or related new construction shall be undertahen in such a manner that if removed in the future, the examinal form and integrity of the historic property and its environment so-aid be 10.

The Gity of 8an Diego will use *The Standards* as a guideline for confirming the appropriateness of proposed rehabilitation work for the building. Rehabilitation work and proposed elterations and modifications to the building will also need to comply with the current (2013) California Building Code and the Americans with Disabilities Act (ADA). Additionally, since the Remmen Building is a designated historical resource, the provisions of the California Historical Building Code are a applicable to all future relocation and rehabilitation work.

Page 10 of 10

452 FIFTH AVENUE, SAN DIEGO, CA 92101 TI619.239.7485 FIBIP.234.6285 HERITADEARCHITECTURE.COM

#### HERITAGE

Exterior Walls Repair deteriorated wood siding and repaint the building using the existing historic color

- Front Porch:
- ar Everyi: Repair deteriorated wood flooting and repaint using the axisting historic color. Repair and repaint other wood floatures using the caleing historic color scheme. Reconstruct the front steps with new concerns tesps naturabing the detailing of the original steps In-Mod using subsynch square-cut schlar maxemp to memorrate the curved wing walk. Subsynged concerns samples from the original tesps should be used to ensure that the new concerts matches the original concerts color and texture is -kind. The reconstructed satist will eliminate no more than two or the original tests in orders to lower the building's finish floor elevation to approximately 30-inches above the adjacent sidewalk.

 Bear Porches:

 Demolish non-historic deck and exterior stairs.

 Stabilize and/or reconstruct historic rear porch

<sup>100</sup> The proposed building relocation will require the removal of the existing foundation and construction of a new foundation system. The original schlar maxonry cladding will be subtraged and reinstulled on the new foundation to match the axisting appearance in-kind. Damaged masonry units will be replaced in-kind.

innggi Desimically retrofit or reconstruct remaining original chimney.
Reconstruct two missing brick chimneys,
Depending on the chairef driver use of fany of the chimneys, the reconstructed chimney rould be construit, meaning the structure would be wood framed and chid with a deconstruction varaer matching the original chimney appearance. The reconstructed chimneys could also be utilized to conceal new mechanical versis that may be required for the rehabilitated building.

Windows

News: Replace broken glass with restoration glass. Restore existing historic windows to working condition and add weatherstripping. Repair exterior using the existing historic colors and refinish the interior.

- Exterior Doors: Replace broken glass and restore the existing front entry doors.
   Install ADA compliant door hardware.
   Replicate damaged and missing rear porch doors.

 Install ADA compliant door hardware where required Page 7 of 10

ATT FIFTH AVENUE, BAN DUNGD, CA 92101 TINIS SIN 254.6266 HERITAGRARCHITECTURE.COM

#### HERITAGE -

- Any historic doors that are removed during rehabilitation should be salvaged. Remove non-historic carpeting and restore/refinish original wood flooring.
- New flooring may be required in some areas to serve the new restaurant use, but public area bed portions of the building should reuse the existing historic flooring if feasible
- Maintain existing lath and plaster wall and ceiling finishes where feasible. Where new walls are required, match the existing plaster where feasible, particularly in public areas.
- Restore and reuse existing historic lighting wherever feasible. Where removal is required to serve the new use, salvage the historic fixtures.
- For the set of the
- Mechanical, Plumbing, and Electrical Systems: Install an approved automatic fire sprinkler system. Upgende electrical service cand panel(s) for new ressummt use. Design and install new HVAC system and kitchen exhaust to serve the new restaurant use.
- Install new accessible restrooms to serve the new restaurant use. Design and install regulted electrical, lighting, mechanical, and plumbing systems to serve the

#### SUMMARY OF EXISTING HISTORIC FEATURES:

- Exterior Historically significant exterior features and finishes should be preserved and protected in accordance with Tie Manderdi. Existing historic exterior features include: Leaded glass and curved windows.
- Leaded glass and curved window. Leaded glass doors. Corinthian columns supporting the front balcony and domier window.
- Square-cut ashlar masonry foundation walls. 1/1 double-hung wood windows.
- Front and rear porches. Four single-light front doors.
- Horizontal wood siding.
- Existing exterior trim and decorative elements.

Interior. The interior of the building also retains a high degree of historical integrity. Existing historic interior

res include: Built-in desk, shelf, and columns between the living and dining rooms in the two ground

- floor apartments. Curved bay windows and built-in window seats in the two second floor apartments. Brick fireplaces and tiled hearths in all four apartments
- Page 8 of 10
- 833 FIFTH AVENUE, NAN DISGO, CA 92101 TIS19.239.7888 FIS19.254.6386 HERITADEARCHITECTURE.COM

#### HERITAGE

Rear Porches: The rear porched are historic and they shall be protected in place. Temporary shoring shall be provided by the moving contractor to protect these elements during relocation and storage. The related wood deck and stairs at the year better the patter relation of the storage and storage. The related wood deck and stairs at the rear porches are not historic. These elements shall be demolished prior to the relocation.

2. Relocation Procedures: The Remness Building will be moved approximately 800 feet to a temporary storage site located on a City-owned property at the southeast corner of Market and 13<sup>rd</sup> Street. The building will be moved in one piece and will be stored at the temporary relocation size for a period of approximately one year pending completion of a subtermaean parking structure and other impovements at the Park-Market site that must be completed prior to the final relocation and rehabilitation of the building.

The mover shall outline the route, schedule, and sequence of the move as well as the mean by which the building will be secured for the relocation. The Historic Architect/Monitor and City staff shall approve the plan prior to the relocation date.

Monitoring: Construction monitoring shall be provided during the relocation process, both when the building is moved to the temporary storage size and when it is moved to its final location. Following each site visit, the Monitor shall provide a Consultant Site Visit Record summaking the field conditions and any recommendations for compliance with TMs Islandowic.

3. Protection Measures at the Temporary Redocution to Compare the two informations of the two information of the two information of the two informations of the two informations of the two informations of the two informations of the information of the infor

All salvaged materials will be stored on palettes and secured in a weather-tight, lockable steel storage container which will be kept at the temponary relocation size adjacent to the Remmen storage co Building.

Mothballing: During temporary storage, and until the building is successfully rehabilitated, it shall be securely mothballed. Mothballing essentially mesos cloring up the building temporarily to protect it from weather and vandaliam. Mothballing ishould husballe providing necessary temporary structural stabilitation (shoring), adequately delinitating and concolling pests, protecting the interfor from moissure, providing dequates executior, structing also interfor from the interform.

Page 5 of 10 533 FIFTH AVENUS, NAN DIEGO, DA 42(0) T(4)3 FIGUR.314.6288 HERITAGEARCHITE

#### HERITAGE

### ventilation, and implementing a maintenance and monitoring plan to ensure that the building is adequately secured and routinely inspected.

Monitoring: Construction monitoring shall be provided to ensure that the building is securely stored and adequately mothballed at the temporary storage site. The Monitor shall complete a Consultant Site Visit Record summarizing the field conditions and any recommendations for compliance with The Standards

Building Rehabilitation: Following the relocation of the Remman Building, the exterior of the structure will be rehabilizated and repaired in accordance with *The Seculary of the Interior's Shandards for* 

The concrete entry steps to the porch will be teplicated in-kind and the curved outer walls will The contracts that y keps to use point was be replaced in which is what in the current outer was well be reconstructed using savinged salar masony where feasible. The reconstructed sairs will eliminate up to two sizes in order to lower the building's finished floor level to approximately 30° above the adjacent sidewalt. The square-cut shalar masonry foundation walls will be replicated using salvaged square-cut shalar masonry units.

<u>Construction Monitoring</u>: Periodic construction monitoring shall be provided during the rehabilitation process. Following each site visit, the construction monitor shall provide a Consultant Site Visit Record summatizing the field conditions and any recommendations for compliance with The Standard

Rehabilitation Design: The future rehabilitation of the building shall be completed in accordance with *The Sumamin*. The design team shall include the services of a Hintoch Architect that means the Scenzerus of the Instrict's Professional Qualification Sanafaria. The relativistic that there are the Scenzerus of the Instrict's Professional Qualification Sanafaria. The relativistic of the Scenzerus and the Scenzerus of the Scenzerus of the Scenzerus of the Scenzerus Services Department and the Hintocical Resources Board staff and/or Design Austiance

#### REHABILITATION RECOMMENDATIONS:

- ter In secondance with The Standard, new additions such as the proposed new clevated exterior restaurant searing areas, shall not desarely historic materials, features, and spatial relationships that characteriste the property. They should be differentiated from the historic construction and compatible in materials, features, size, scale, proportion, and massing. They should also be constructed in such asmanne that, if emroued in the future, the essential form and integrity of the building would be unimpaired
- Remove and replace existing composite shingle roofing with new composite shingles with a

Page 6 of 10 533 FIFTH AVENUS, SAN DIEGO, CA 92(0) T(6)9.239.7548 F(6)9.334.0288 HERITAGEARCHITECTURE.COM HERITAGE 

The future tenant of the rehabilitated building has not yet been identified. The proposed future use of the building will lakely change its occupancy classification from residential/office to restaurant. Due to the proposed change in use, this sourced that some extender thatness will be required in order to provide disabled access to the building and facilitate the proposed public use. The proposed the building, and the future of the source state of the the building of a same paid elevated public use. The proposed is the building that are premiere chances: definiting that are premiere chances: defining fastures will not be affected. The windows hat are proposed to be altered an obtained roward the back of the building on the site devision and they are standard 1/1 wood double-hung windows of a more simple construction. Modifications to the Hermann building shall be in compliance with The Sorthy of the District's Soundow's first of Histories (The Standardy), specifically the Standard's Radebilitation. Since the future instants of the relabilitation is not submaring it intermentation in the state of the set of

Additional review and approval by the City of San Diego's Development Services Department and the Historical Resources Board will be required when the full scope of the restaurant rehabilitation is

PREPARATION, RELOCATION, & REHABILITATION REQUIREMENTS: 1. Preparation of the Structure Prior to Relocation: <u>Coordination Resting & Monitoring</u> Prior to the start of any work the Project Architect and Historic Architect/Monitor shall meet on all with the moving contactor to review the scope of damolition, ramoval, salvage, immports shoring, and relocation. Through the course of all work, the moving contactors shall movie to the Historic Architect/Monitor of discovery of any architectural elements on site. The Historic Architect/Monitor of discovery of any architectural elements on site. The Historic Architect/Monitor of such material prior to determining the appropriate treatment in compliance with T& Seretary of the Interior's Stendards for Rehebilitation.

Construction monitoring shall be provided prior to preparation of the building for relocation. The construction Monitor shall provide a Consultant Site Viait Record summarizing the field conditions and any recommendations for compliance with *The Standards*.

Temporary Shoring: The moving contractor shall provide and maintain necessary shoring to protect and stabilize the building during the relocation and storage phases. Means and mathods for temporary shoring will be determined by the moving contractors and the implementation of these procedures shall occur only after review by the Histotic Architect/Monitor. The

Page 3 of 10

.

mover shall outline any proposed points of entry and attachment for anchors or beams. Historic siding or trim affected by the attachment of temporary shoring shall be removed prior to installation or shoring, establiqued, labeled and securaly wored in a weather-tight lockable container pending reinstallation at the final site.

Windows: All window shall be protected by plywood prior to relocation. The existing windows accounter, na wataw man of protection of physical prior to the initial windows on the first floor and near facidad of the building are currently protected by physical to prevent wandhim. Existing physical may be kept in place, if desmud dequate by the moving contanctor. Unprotected windows thall be covered with W<sup>2</sup> cattoric grade physical installed in a similar manor as the exitting physical, without causing damage to the existing historic windows, frames, and trim.

Doors: The four existing historic exterior doors at the front fuçade of the bullding shall be protected in place. The achieve physicol covering shall be maintained pending the exterior rehabilitation. The exterior door openings at the rear fuçade are also covered with physood. The physicol shall be inspected by the contrastors and replaced if needed.

Masonry Roundation Cladding: Prior to relocation, the ashlar masonry cladding on the foundators wells shall be documented, phonographed, estalogued, asirqaed, and stored by the moving contrastors. All documentation will be shortisted to the City for review and approval prior to removal of the ashlar masonry cladding. All salvaged items will be stored on labeled and wrapped pallets and securit is a weather-right locable steel container that will be located at the temporary relocation site adjacent to the building.

Chinnegy Prior to relocation, the remaining historic brick chinney on the west side of the building shall be disassembled above the roofline. Prior to disassembly, the chinney shall be measured and photo documented. All documentation will be submitted to the Chinney shall be and approval pairs to removal of the chinney. The block shall be outlogoed, anivged, and stored for reinstallation at the final size. All salvaged items will be stored on labeled and wrapped palles and secured in a watch-edgite lockhalb steel container that will be located at the temporary relocation site adjacent to the building.

From Steps and Parchi Pider to relocation the concretes front steps and stellar masonry wing walls will be removed to facilitate the relocation. Prior to disassembly, the wing walls shall be measured, phone documented, and subwaged. All documentation will be technistice to the Giy for review and approval phore to removal of the steps and wing walls. The concrete steps will not be subwaged, but samples of the concrete shall be resinted for divince maching of the concrete scolar and instants. All subwaged items will be torized on labeled and wapped pallets and secured in a weather-tight location list concater shat will be located at the temporary relocation site adjacent to the building.

The front porch, including the porch floor, balustrade, columns, roof, trim, railings, and decorative elements shall be protected in place and securely shored in order to facilitate the

Page 4 of 10

533 FIFTH AVENUE, SAN DIEGO, CA 93101 TIGI9.239.7885 FIG19.234.6285 HERITADEARCHITECTURE.COM

structure relocation and temporary storage

AND FIFTH AVENUE, SAN DIEDD, CA 92101 TISID.239.7888 FIGUR.354.4288 HERITAGEAS



#### REMMEN BUILDING TREATMENT PLAN

September 1, 2016

PROJECT DESCRIPTION: The historic Remmen Buliding is a two-story Conforman (Avts and Confu) styles structures with Edectic Neo-Classical features on the corner of G Strees and Parck Boulevend in San Diego's East Village. The wood-framed structures was built in 1907 by Mo. O. Remmen. Identified as a potential biotics itse in a 1988 survey, the building was designated as City of San Diego Flavorieal Site ##26 in 2000.

The property on which the Remmen Building is located is part of a proposed redevelop The pupper, on what the contrast work of the contrast work of the contrast which will occupy the entire block bounded by G Street, Market, 11° Avenue, and Park Boulevand. The proposed redevelopment project includes the construction of a 50,000 square foot offices building on Marker Street and a male-use reindential tower at the corner of G Street and 11° Avenue. Site improvements will include the addition of a subtermeant parking gauge, public blass, amplitudes the approximation of the blass of the subtermeant parking gauge. Street and 11<sup>th</sup> Avenue. Site improvements will include the addition of a subterranean packing garage, public plans, amphilabeter, and private open space. To facilitate the construction of the underground packing garage and other site improvements, the flearment Building will be temporally relocated to a hobling its at the corner of Market Street and 13<sup>th</sup> Street. The building will then be transported back to the site where it will be shifted to the cast and rotated 90 degrees to face a new tree-lined sidewalk along Park Boulevard.



Figure 1: Park + Market site development plan.

Page 1 of 10 823 FIFTH AVENUE, BAN DISGD, CA 92101 T-615 FINIR 254,6124 HERITAGRARCHIVECTURE.COM

:

INTRODUCTION: The implementation of this Treatment Plan for the elocation and exterior rehabilitation of the Remmer Building will be facilitated by a qualified historic survexne mover. Construction Observation services will be provided by the Project Architect, Gattier Johnson, and the Historic Architect/Monton, Heringa Architecteux & Planning. The project stable scoredness with the misguido, monitoring, and rebording program for this project. This Treatment Plan is accompanied by schematic deawing which depict the proposed exterior rehabilition of the building.

#### RELOCATION/REHABILITATION STRATEGY:

RELOCATION//REHABULITATION STRATEGY: Point oth development of the site, the Remman Bulking will be tempontily moved offsite for a period of approximately one yeas tharker the construction of the proposed subterranean parking ganges. The main structure will be transported in one piece to a vescut lot et 3101 Market Strest, approximately two blocks southeast of its current location. The building will then be motiballed per the NPS Preservation Build 311 Morballing Historic Buildings.

After the completion of the subterranean parking gauge at the Park+Market site, the Remmen Building will be relocated back to the original site at the northeast corner of the block. The building will be notated to degrees chockwise so that the primary entry faces Park Boulevard, enabling the creation of a larger central public plaze areas to the north. The City of San Diago will vecate a 10-foot stip of fight-of-way along the east property line allowing the front entry porth to encroach into the current fight-of-way place.



Page 2 of 10 823 FIFTH AVENUE, MAN DISGO, CA 92101 TIBI9.239.7888 FIS19.254.6286 RERITAGEARCHITECTURE.COM



#### 

- Pre-Move (CM, HA, RC)

   Observe temporary shoring and protection.
   Review storage of salvaged building materials.
   Approve structure as ready for relocation.

4.

6.

7.

- Preparation for Storage (CM, HA) a. Hintofe Architect/Monitor to observe motiballing and temporary protection measures of retocated balling at temporary storage site (Site B). b. Review storage and temporary protection measures of salvaged items at temporary storage site (Site B).
- 5. Continued Monitoring During Storage at Site B (CM)
  - a. Monitoring to occur weekly.
     b. Observe site to verify continued compliance with the Treatment Plan.
- Pre-construction Meeting for Relocation to **Site C** (D, CM, PA, HA, RC, BI) a. Overview of Treasment Plan, architectural, landscape, and engineering documents as related to **Site C**. b. Review work required to prepare the site for arrival of the building.
- New Footings, Foundation, Utilities, and Site Preparation at Site C (CM, HA, RC) a. Review preparation work at Site C prior to relocation of building.
- Move to Site C (CM, HA, BI)
   Review building relocation, Review overall Treatment Plan for rehabilitation of building as well as architectural, landscape, and engineering documents.
- 9. Continued Monitoring during Rehabilitation (CM, PA, HA) Monitoring to occur monthly as required by construction activity. Observe schabilitation of the building in accordance with the Treatment Plan and approved architectural, landscape, and engineering documents. а. b.
- Final Monitoring (D, CM, PA, HA)

   Final Monitoring (D, CM, PA, HA)
   Final punch list of items to complete seconding to the Treatment Plan and architectural, landscape, and engineering documents.
- Draft Monitoring Report (HA, BI)

   Draft memory of monitoring process to be submitted to the BI for review.
- Final Monitoring Report (D, HA, BI) a. Final Monitoring Report, review and update of HABS documents to be submitted to Development Services and the San Diego Flistory Center.

Page 3 of 4 633 fifth avenue, san dicco. Ca 92101 tig19.239.7898 fig19.234.6286 heattagearchitecture.com



Figure 2: Park + Market site development plan showing the Remmen Building in its final location in telation to the papposed new development.



Page 4 of 4 655 FIFTH AVENUE, SAN DIEDD, CA 93101 TISL Table Projector and provide an entry of a security of the security of the



SHEET 3 OF 8

:

#### REMMEN BUILDING MONITORING PLAN

DATE: September 1, 2016

PROJECT: Remmen Building Current Addresset 120:1133 G Steeet, San Diego, CA 92101 Current Addresset 120:1133 G Steeet, San Diego, CA 92101 Current APN# 535-134-1000 Previous APN# 355-134-0700 HBB Site# 426 Yeas Built: 1907 Period of Significance: 1907

SUBJECT: Monitoring Plan for Historic Resource

PROJECT TEAM: D (Developer & Construction Manager) CM (Construction Manager) PA (Project Architect) PA (Project Architect) HA (Hintoric Architect & Monitor) HA (Hintoric Architect & Monitor) RC (Relocation Constructor) Bi (Building Inspector) Bi (Building Inspector) City of San Diago Development Services Environmental and Historical staff

LOCATIONS: Existing Site (Site A) - 1129-1135 G Street, San Diego, GA 92101

Temporary Relocation Site (Site B) - Southeast corner of Market and 13th Street.

Final Site (Site C) – Southwest corner of G Street and Park Boulevard (same location as Site A, but rotated 90 degrees so the front entrance faces Park Boulevard).

PROPERTY DESCRIPTION: The Remmen Building is locally designated under the Chy of San Diego Register of Histofeal Resources as HTMR #426. Its elevated its significance for its architecture, as a good example of a Craftsman (Arts and Crafts) two-snoy apartment building with eelevate Norolastical desils. The building exhibits its architectural details, is well maintaiced, and has not undergoor any major changes to its histofead fabric. Is predict of significance is 1907, the date of its original construction.

This Monitoring Plan will follow the Treatment Plan and supporting architectural documents prepared to move the historic structure from its current location at Site A to the temporary storage site at Site B where it will be stored for a period of approximately one year until the final relocation to Site C.

HERITAGE



Figure 1: Site plan showing the existing location (Site A) in red, temporary storage site (Site B) in orange, and the final Park+Market location of the relocated historic Remmen Building in yellow.

MONITORING
1. Preconstruction Meeting (D, CM, PA, HA, RC, BI)
a. Overview of Treatment Plan and Monitoring Plan as related to the historic resource
on Site A. Visit to Site B.

Preparation of structure for moving (CM, HA)

 Histoic Architect/Monitor to be present to observe removal of the ashiar masonary
 foundation caldiding and forat steps. Other items, including disconnection/capping of
 utility connection, removal of exterior plumbing and electrical lines, removal non historic rear statis and wood deek, which are required for the relocation, shall be
 complete prior to the meeting.

Page 2 of 4

623 FIFTH AVENUE, SAN DINGO, CA 92101 T:619.359.7888 F:519.334.6286 REBITAGEARCHIVECTURE.COM



SCALE: 1/8" = 1'-0"

# GENERAL NOTES

- 1. THE REMMEN BUILDING IS A DESIGNATED HISTORICAL RESOURCE, ALL WORK SHALL BE COMPLETED IN COMPLIANCE WITH THE SECRETARY OF THE INTERIOR'S STANDARDS FOR THE TREATMENT OF HISTORIC PROPERTIES.
- 2. THESE CONCEPTUAL DRAWINGS ARE PROVIDED TO ILLUSTRATE THE TREATMENT PLAN FOR THE RELOCATION OF THE REMMEN BUILDING. THE FINAL CONSTRUCTION DRAWINGS SHALL BE APPROVED BY THE CITY OF SAN DIEGO'S DEVELOPMENT SERVICES DEPARTMENT PRIOR TO ISSUANCE OF A PERMIT FOR THE REHABILITATION OF THE BUILDING.
- 3. REHABILITATION SHALL INCLUDE REPAINTING THE EXTERIOR OF THE BUILDING TO MATCH THE EXISTING (HISTORIC) PAINT COLORS.

- 1 NEW DOUBLE DOOR IN PREVIOUS WINDOW LOCATION. RETAIN UPPER TRIM ON WINDOW AND PROVIDE NEW SIDE TRIM TO MATCH HISTORIC TRIM IN-KIND ON BOTH SIDES OF DOOR. SALVAGE WINDOW.
  - RECONSTRUCTED CONCRETE STEPS TO MATCH ORIGINAL STEPS. NEW STEPS SHALL BE REDUCED IN HEIGHT BY TWO RISERS TO LOWER THE OVERALL BUILDING ELEVATION APPROXIMATELY 13' FROM THE HISTORIC HEIGHT.
  - RECONSTRUCTED ASHLAR MASONRY WING WALL USING ORIGINAL MATERIAL SALVAGED PRIOR TO RELOCATION.
- 4 NEW PERIOD-STYLE STEEL HANDRAIL, PAINTED.
- 5 RECONSTRUCTED ASHLAR MASONRY CLADDING OVER NEW FOUNDATION WALLS USING ORIGINAL MATERIAL SALVAGED PRIOR TO RELOCATION.
- 6 EXISTING WOOD PORCH TO BE PRESERVED AND RESTORED.
- 7 NEW SEATING.
- 8 NEW CONCRETE RAMP WITH STEEL HANDRAILS.
- 9 NEW RAISED WOOD PATIO.
- 10 NEW PLANTER.
- 11 NEW CONCRETE STEPS WITH STEEL HANDRAILS.





## GENERAL NOTES

 THE REMMEN BUILDING IS A DESIGNATED HISTORICAL RESOURCE, ALL WORK SHALL BE COMPLETED IN COMPLIANCE WITH THE SECRETARY OF THE INTERIOR'S STANDARDS FOR THE TREATMENT OF HISTORIC PROPERTIES.

2. THESE CONCEPTUAL DRAWINGS ARE PROVIDED TO ILLUSTRATE THE TREATMENT PLAN FOR THE RELOCATION OF THE REIMMEN BUILDING. THE FINAL CONSTRUCTION DRAWINGS SHALL BE APPROVED BY THE CITY OF SAN DIEGO'S DEVELOPMENT SERVICES DEPARTMENT PRIOR TO ISSUANCE OF A PERMIT FOR THE REHABILITATION OF THE BUILDING.

3. REHABILITATION SHALL INCLUDE REPAINTING THE EXTERIOR OF THE BUILDING TO MATCH THE EXISTING (HISTORIC) PAINT COLORS.

- 1 NEW DOUBLE DOOR IN PREVIOUS WINDOW LOCATION. RETAIN UPPER TRIM ON WINDOW AND PROVIDE NEW SIDE TRIM TO MATCH HISTORIC TRIM IN-KIND ON BOTH SIDES OF DOOR. SALVAGE WINDOW.
- 2 RECONSTRUCTED CONCRETE STEPS TO MATCH ORIGINAL STEPS. NEW STEPS SHALL BE REDUCED IN HEIGHT BY TWO RISERS TO LOWER THE OVERALL BUILDING ELEVATION APPROXIMATELY 13" FROM THE HISTORIC HEIGHT.
- 3 RECONSTRUCTED ASHLAR MASONRY WING WALL USING ORIGINAL MATERIAL SALVAGED PRIOR TO RELOCATION.
- 4 NEW PERIOD-STYLE STEEL HANDRAIL, PAINTED.
- 5 RECONSTRUCTED ASHLAR MASONRY CLADDING OVER NEW FOUNDATION WALLS USING ORIGINAL MATERIAL SALVAGED PRIOR TO RELOCATION.
- 6 EXISTING WOOD PORCH TO BE RESTORED.
- 7 EXISTING HISTORIC BEVELED DROP SIDING TO BE PROTECTED IN PLACE. REPAIR AS NEEDED AND REPAINT.
- 8 NEW CONCRETE RAMP WITH STEEL HANDRAILS.
- 9 NEW RAISED WOOD PATIO.
  - RECONSTRUCT EXISTING HISTORIC CHIMNEY TO MATCH ORIGINAL APPEARANCE IN-KIND USING SALVAGED BRICK.
- 11
   RECONSTRUCT MISSING BRICK CHIMNEY TO MATCH HISTORIC CHIMNEY IN-KIND USING NEW MATERIAL.
- 12 REPLACE MISSING HISTORIC LEADED GLASS WINDOW TO MATCH ADJACENT WINDOW IN-KIND.
- 13EXISTING HISTORIC WINDOW TO BE RESTORED. ALL<br/>WINDOWS TO BE COVERED WITH PLYWOOD DURING<br/>BUILDING RELOCATION AND TEMPORARY STORAGE.
- EXISTING HISTORIC DOOR TO BE RESTORED. ALL

   EXTERIOR DOORS TO BE COVERED WITH PLYWOOD

   DURING BUILDING RELOCATION AND TEMPORARY

   STORAGE.
- 15 NEW COMPOSITION SHINGLE ROOFING SYSTEM.
  - REMOVE EXISTING FOUNDATION BELOW FIRST FLOOR FRAMING. CONSTRUCT NEW FOUNDATION AND CLAD USING SALVAGED ASHLAR MASONRY.





# **GENERAL NOTES**

- 1. THE REMMEN BUILDING IS A DESIGNATED HISTORICAL RESOURCE, ALL WORK SHALL BE COMPLETED IN COMPLIANCE WITH THE SECRETARY OF THE INTERIOR'S STANDARDS FOR THE TREATMENT OF HISTORIC PROPERTIES.
- 2. THESE CONCEPTUAL DRAWINGS ARE PROVIDED TO ILLUSTRATE THE TREATMENT PLAN FOR THE RELOCATION OF THE REMMEN BUILDING. THE FINAL CONSTRUCTION DRAWINGS SHALL BE APPROVED BY THE CITY OF SAN DIEGO'S DEVELOPMENT SERVICES DEPARTMENT PRIOR TO ISSUANCE OF A PERMIT FOR THE REHABILITATION OF THE BUILDING.
- 3. REHABILITATION SHALL INCLUDE REPAINTING THE EXTERIOR OF THE BUILDING TO MATCH THE EXISTING (HISTORIC) PAINT COLORS.

- 1 NEW PERIOD-STYLE WOOD DOOR IN PREVIOUS DOOR LOCATION.
- 2 RECONSTRUCTED CONCRETE STEPS TO MATCH ORIGINAL STEPS. NEW STEPS SHALL BE REDUCED IN HEIGHT BY TWO RISERS TO LOWER THE OVERALL BUILDING ELEVATION APPROXIMATELY 13" FROM THE HISTORIC HEIGHT.
- 3 RECONSTRUCTED ASHLAR MASONRY WING WALL USING ORIGINAL MATERIAL SALVAGED PRIOR TO RELOCATION.
- 4 NEW PERIOD-STYLE STEEL HANDRAIL, PAINTED.
- RECONSTRUCTED ASHLAR MASONRY CLADDING OVER NEW FOUNDATION WALLS USING ORIGINAL MATERIAL SALVAGED PRIOR TO RELOCATION.
- 6 EXISTING WOOD PORCH TO BE RESTORED.
- 7 EXISTING HISTORIC BEVELED DROP SIDING TO BE PROTECTED IN PLACE REPAIR AS NEEDED AND REPAINT.
- 8 NEW CONCRETE RAMP WITH STEEL HANDRAILS.
- 9 NEW RAISED WOOD PATIO.
- [10] RECONSTRUCT EXISTING HISTORIC CHIMNEY TO MATCH ORIGINAL APPEARANCE IN-KIND USING SALVAGED BRICK.
- [11] RECONSTRUCT MISSING BRICK CHIMNEY TO MATCH HISTORIC CHIMNEY IN-KIND USING NEW MATERIAL.
- 12 REPLACE MISSING HISTORIC LEADED GLASS WINDOW TO MATCH ADJACENT WINDOW IN-KIND.
- EXISTING HISTORIC WINDOW TO BE RESTORED. ALL

   WINDOWS TO BE COVERED WITH PLYWOOD DURING

   BUILDING RELOCATION AND TEMPORARY STORAGE.
- Image: EXISTING HISTORIC DOOR TO BE RESTORED. ALL

   EXTERIOR DOORS TO BE COVERED WITH PLYWOOD

   DURING BUILDING RELOCATION AND TEMPORARY

   STORAGE.
- 15 NEW COMPOSITION SHINGLE ROOFING SYSTEM.
- REMOVE EXISTING FOUNDATION BELOW FIRST FLOOR FRAMING. CONSTRUCT NEW FOUNDATION AND CLAD USING SALVAGED ASHLAR MASONRY.





# GENERAL NOTES

- 1. THE REMMEN BUILDING IS A DESIGNATED HISTORICAL RESOURCE, ALL WORK SHALL BE COMPLETED IN COMPLIANCE WITH THE SECRETARY OF THE INTERIOR'S STANDARDS FOR THE TREATMENT OF HISTORIC PROPERTIES.
- 2. THESE CONCEPTUAL DRAWINGS ARE PROVIDED TO ILLUSTRATE THE TREATMENT PLAN FOR THE RELOCATION OF THE REMMEN BUILDING. THE FINAL CONSTRUCTION DRAWINGS SHALL BE APPROVED BY THE CITY OF SAN DIEGO'S DEVELOPMENT SERVICES DEPARTMENT PRIOR TO ISSUANCE OF A PERMIT FOR THE REHABILITATION OF THE BUILDING.
- REHABILITATION SHALL INCLUDE REPAINTING THE EXTERIOR OF THE BUILDING TO MATCH THE EXISTING (HISTORIC) PAINT COLORS.

- 1 NEW DOUBLE DOOR IN PREVIOUS WINDOW LOCATION. RETAIN UPPER TRIM ON WINDOW AND PROVIDE NEW SIDE TRIM TO MATCH HISTORIC TRIM IN-KIND ON BOTH SIDES OF DOOR. SALVAGE WINDOW.
- 2 NEW FOUNDATION WITH HISTORIC ASHLAR MASONRY CLADDING SALVAGED PRIOR TO BUILDING RELOCATION.
- 3 EXISTING HISTORIC BEVELED DROP SIDING TO BE PROTECTED IN PLACE REPAIR AS NEEDED AND REPAINT.
- 4 NEW RAISED WOOD PATIO.
- 5 RECONSTRUCT EXISTING HISTORIC CHIMNEY TO MATCH ORIGINAL APPEARANCE IN-KIND USING SALVAGED BRICK.
- 6 RECONSTRUCT MISSING BRICK CHIMNEY TO MATCH HISTORIC CHIMNEY IN-KIND USING NEW MATERIAL.
- 7 EXISTING HISTORIC WINDOW TO BE RESTORED. ALL WINDOWS TO BE COVERED WITH PLYWOOD DURING BUILDING RELOCATION AND TEMPORARY STORAGE.
- 8 NEW COMPOSITION SHINGLE ROOFING.
- 9 REMOVE EXISTING FOUNDATION BELOW FIRST FLOOR FRAMING. CONSTRUCT NEW FOUNDATION AND CLAD USING SALVAGED ASHLAR MASONRY.



