

PHOTO-LOG FORM

Project: City of San Diego MSWSMP
 Location: Nestor Creek, Map 134 from MSWSMP Appx B Biology Maps
 Date: 10/18/2010
 Photographer: S. NIGRO
 Team members: S. Trnka
 *Pre-maintenance Condition

Photo #	Time	Photo Point ID	Photo Pt. Description & Location	Bearing to Subject	Subject Description
1	10:05	1	32.584981 N 117.096055 W	East	Looking upstream from access pt.
2		2	" "	West	Looking downstream from access pt.
3		3	32.584921 N 117.095692 W	West	West end of concrete channel North of Palm Ave
4		4	" "	East	Looking upstream at area to be dewatered for maint.
5		5	32.584555 N 117.094761 W	West	Looking downstream from Thermal Ave
6		6	32.584317 N 117.094761 W	North	" "
7		7	" "	South	Looking upstream toward Palm Ave from Thermal Ave
12		12	32.583403 N 117.094766 W	East	Looking east at concrete channel south of Palm, along 18th St
13	12:30	13	32.583025 N 117.092880 W	West	Looking west from Saturn Blvd south of Palm Ave.

General Notes or Comments (weather, cloud cover, time of sunrise and sunset, other pertinent information):

Photos document pre-maintenance condition of concrete-lined reach of Nestor Creek north + south of Palm Avenue.

PRE-MAINTENANCE SITE PHOTOS Map 134 Nestor Creek 11/18/10

	
<p>PHOTO NOTES: Looking east/upstream from access point for maintenance north of Palm Avenue. Vegetation in this area will be driven over but not removed.</p>	<p>PHOTO NOTES: Looking west/downstream from access point for maintenance north of Palm Avenue. Vegetation in this area will not be maintained.</p>

	
<p>PHOTO NOTES: Looking west/downstream at beginning of maintenance area for the concrete channel north of Palm Avenue. Standing water is present.</p>	<p>PHOTO NOTES: Looking east/upstream at maintenance area for the concrete channel north of Palm Avenue. Standing water is present.</p>

SITE PHOTOS Map 134_ Nestor Creek_101810 SN



PHOTO NOTES:

Looking west/downstream at maintenance area for the concrete channel north of Palm Avenue. Standing water is present.



PHOTO NOTES:

Looking north/downstream at maintenance area for the concrete channel north of Palm Avenue. Standing water and freshwater marsh are present.



PHOTO NOTES:

Looking south/upstream at maintenance area for the concrete channel north of Palm Avenue. Freshwater marsh and southern willow scrub are present.



PHOTO NOTES:

Looking east/upstream at maintenance area for the concrete channel south of Palm Avenue.

SITE PHOTOS Map 134_ Nestor Creek_101810 SN



PHOTO NOTES:

Looking west at the concrete channel from upstream of the area proposed for maintenance.

PHOTO NOTES:




PHOTO NOTES:

PHOTO NOTES: