



W:\18187-B-FY18_Channel_Prioritization\GIS\Appendix_E_Culverts\Map81_Layout.mxd, 04/2018

Legend

- Channel Area
- ⊗ City Storm Drain Structure
- City Storm Drain

Photos:



Assessment Results

- Channel Prioritization Score: **56.2 out of 100**
- Capacity Prior to Maintenance: **2-year storm event**
- Capacity After Maintenance (As-built Capacity): **100-year storm event**
- Clogging Potential: **MEDIUM**
- Approximate Invasive Vegetation Coverage: **LOW**
- Surrounding Area: **Residential**
- Infrastructure Failures: **Broken concrete**
- Site Evaluation Date: **March 8, 2018**
- Notes/Comments: **The channel has broken concrete from the trees on the channel bottom.**