



W:\18187-B-FY18_Channel_Prioritization\GIS\Appendix_F_Culverts\Map77_04.2018

Legend

- Channel Area
- ⊗ City Storm Drain Structure
- City Storm Drain

Scale in Feet

North

Photos:



Assessment Results

- Channel Prioritization Score: **26.2 out of 100**
- Capacity Prior to Maintenance: **100-year storm event**
- Capacity After Maintenance (As-built Capacity): **100-year storm event**
- Clogging Potential: **LOW**
- Approximate Invasive Vegetation Coverage: **LOW**
- Surrounding Area: **Roads**
- Infrastructure Failures: **NONE**
- Site Evaluation Date: **March 15, 2018**
- Notes/Comments: **The downstream end of the channel has accumulated approximately 4 feet of sediment.**