

Photos:











Assessment Results

- Channel Prioritization Score: 50.5 out of 100
- Capacity Prior to Maintenance: Less than 2-year storm event
- Capacity After Maintenance (As-built Capacity):
 Less than 2-year storm event
- Clogging Potential: LOW
- Approximate Invasive
 Vegetation Coverage: HIGH
- Surrounding Area: Commercial
- Infrastructure Failures: NONE
- Site Evaluation Date: March 13, 2018
- Notes/Comments: This channel is relatively small and has a portion of channel with dense arundo.