Unacceptable Waste Diverted From Miramar Landfill

Black powder

Unacceptable Waste Diverted From Miramar Landfill

Medical waste containing liquid blood

Unacceptable Waste Diverted From Miramar Landfill

Pigments from a printing company

Unacceptable Waste Diverted From Miramar Landfill

Industrial cleaning products and lubricants from a trucking company

Unacceptable Waste Diverted From Miramar Landfill

Hazardous waste solvent from a body shop

Unacceptable Waste Diverted From Miramar Landfill

Muriatic acid from a pool construction company

Unacceptable Waste Diverted From Miramar Landfill

Paint, solvents, and paint related waste from a theater

Unacceptable Waste Diverted From Miramar Landfill

Asbestos containing acoustic ceiling material

Unacceptable Waste Diverted From Miramar Landfill

Paint waste from a construction company

Unacceptable Waste Diverted From Miramar Landfill

Fluorescent light bulbs

Unacceptable Waste Diverted From Miramar Landfill

Lead Paint Chips

Unacceptable Waste Diverted From Miramar Landfill

PCB containing light ballasts from an electrical company

Unacceptable Waste Diverted From Miramar Landfill

Approximately 2,000 fluorescent light bulbs from a building retrofit disposed at Miramar Landfill prior to cleanup

Unacceptable Waste Diverted From Miramar Landfill

Paint from a painting contractor disposed at Miramar Landfill prior to cleanup