Return to City Engineers Office
City Hall, San Diego, Cal.

400

LEVEL

F. B. 364

Published by H. S. CROCKER COMPANY, Stationers, Drawing Materials, and Mathematical Instruments, San Francisco.

*Table showing the difference of latitude and departure in running 80 chains at any course from 1 to 60 minutes.*

364

| MINUTES. | LKS. | MINUTES. | LKS. | MINUTES. | LKS. |
|---|---|---|---|---|---|
| 1 | 2⅓ | 21 | 49 | 41 | 95⅔ |
| 2 | 4⅔ | 22 | 51⅓ | 42 | 98 |
| 3 | 7 | 23 | 53⅔ | 43 | 100⅓ |
| 4 | 9⅓ | 24 | 56 | 44 | 102⅔ |
| 5 | 11⅔ | 25 | 58⅓ | 45 | 105 |
| 6 | 14 | 26 | 60⅔ | 46 | 107⅓ |
| 7 | 16⅓ | 27 | 63 | 47 | 109⅔ |
| 8 | 18⅔ | 28 | 65⅓ | 48 | 112 |
| 9 | 21 | 29 | 67⅔ | 49 | 114⅓ |
| 10 | 23⅓ | 30 | 70 | 50 | 116⅔ |
| 11 | 25⅔ | 31 | 72⅓ | 51 | 119 |
| 12 | 28 | 32 | 74⅔ | 52 | 121⅓ |
| 13 | 30⅓ | 33 | 77 | 53 | 123⅔ |
| 14 | 32⅔ | 34 | 79⅓ | 54 | 126 |
| 15 | 35 | 35 | 81⅔ | 55 | 128⅓ |
| 16 | 37⅓ | 36 | 84 | 56 | 130⅓ |
| 17 | 39⅔ | 37 | 86⅓ | 57 | 133 |
| 18 | 42 | 38 | 88⅔ | 58 | 135⅓ |
| 19 | 44⅓ | 39 | 91 | 59 | 137⅔ |
| 20 | 46⅔ | 40 | 93⅓ | 60 | 140 |

Retired Co. Surveyor (1) Copy Only Ellis Smith Dec. 1964

## TABLE FOR RUNNING ON SLOPES.

MICROFILMED DEC 19 1964

*In the following table the first column shows the angle, the second the number of links to be added to each chain for the slopes, to make one chain, horizontal measurement.*

| ANGLE | COR. IN LINKS | ANGLE | COR. IN LINKS | ANGLE | COR. IN LINKS | ANGLE | COR. IN LINKS |
|---|---|---|---|---|---|---|---|
| ° | | ° | | ° | | ° | |
| 4 | 0.24 | 11 | 1.88 | 18 | 5.14 | 25 | 10.54 |
| 5 | 0.38 | 12 | 2.24 | 19 | 5.76 | 26 | 11.26 |
| 6 | 0.55 | 13 | 2.63 | 20 | 6.42 | 27 | 12.24 |
| 7 | 0.76 | 14 | 3.06 | 21 | 7.11 | 28 | 13.37 |
| 8 | 0.98 | 15 | 3.53 | 22 | 7.85 | 29 | 14.34 |
| 9 | 1.24 | 16 | 4.02 | 23 | 8.64 | 30 | 15.47 |
| 10 | 1.55 | 17 | 4.56 | 24 | 9.47 | 35 | 22.07 |

521.2-12

LORINGS BOOK STORE 765 5TH ST. SAN DIEGO

Clough
Taylor
Wardy
Sept 08

67.78

Crossection of Locust St
Continued from Book 405

1

Center of Merriduth St

| | | | | |
|---|---|---|---|---|
| ms | | | 21 | 65.7 |
| bh | | | 19 | 65.9 |
| " | | | 20 | 65.8 |
| b | | | 26 | 65.2 |
| " | | | 33 | 64.5 |
| bh | | | 36 | 64.2 |
| ES | | | 37 | 64.1 |

N 1/4 of Merriduth St

| | | | | |
|---|---|---|---|---|
| ES | | | 37 | 64.1 |
| bh | | | 35 | 64.3 |
| " | | | 31 | 64.7 |
| b | | | 26 | 65.2 |
| " | | | 2 | 65.6 |
| bh | | | 18 | 66.0 |
| ms | | | 18 | 66.0 |

POSTED

POSTED

67.78

N bk of Meredith St

| | | | | |
|---|---|---|---|---|
| WL | | | 1,5 | 66.3 |
| bk | | | 1,9 | 65.9 |
| " | | | 2,2 | 65.6 |
| b | | | 2,5 | 65.3 |
| " | | | 2,9 | 64.9 |
| bk | | | 3,5 | 64.3 |
| EL | | | 3,8 | 64.0 |

N Line of Meredith St

| | | | | |
|---|---|---|---|---|
| EL | | | 3,4 | 64.4 |
| bk | | | 3,1 | 64.7 |
| " | | | 2,6 | 65.2 |
| b | | | 2,1 | 65.7 |
| " | | | 1,9 | 65.9 |
| bk | | | 1,6 | 66.2 |
| WL | | | 1,3 | 66.5 |

67.78 Locust St



50' N of Meredith St

| | | | | |
|---|---|---|---|---|
| WL | | | 0,0 | 67.8 |
| bk | | | 0,4 | 67.4 |
| " | | | 1,2 | 66.6 |
| b | | | 1,1 | 66.7 |
| " | | | 1,8 | 66.0 |
| bk | | | 2,9 | 64.9 |
| EL | | | 3,5 | 64.3 |

100' N of Meredith

| | | | | |
|---|---|---|---|---|
| EL | | | 4,2 | 63.6 |
| bk | | | 3,4 | 64.4 |
| " | | | 2,7 | 65.1 |
| b | | | 2,5 | 65.3 |
| TP | 341 | 6891 | 2,28 | 6550 |
| " | | | 3,3 | 65.6 |
| bk | | | 3,0 | 65.9 |
| WL | | | 2,7 | 66.2 |

| | | | | |
|---|---|---|---|---|
| | | 68.91 | | |
| | 150' | n of | Merrideth st | |
| WL | | | 2,9 | 66.0 |
| bl | | | 2,7 | 66.2 |
| y | | | 3,2 | 65.7 |
| b | | | 4,0 | 64.9 |
| y | | | 4,7 | 64.5 |
| bb | | | 5,7 | 63.2 |
| EL | | | 6,5 | 62.4 |
| | 200' | n of | Merrideth st | |
| EL | | | 6,7 | 62.2 |
| bl | | | 5,7 | 63.2 |
| y | | | 4,8 | 64.1 |
| b | | | 4,7 | 64.2 |
| y | | | 4,1 | 64.8 |
| bl | | | 3,8 | 65.1 |
| WL | | | 3,2 | 65.3 |

| | | | | |
|---|---|---|---|---|
| | | 68.91 | | Locust st |
| | 210' | n = | Pueblo Line | N Line of Roseview |
| WL | | | 3,3 | 65.6 |
| bl | | | 3,7 | 65.2 |
| y | | | 4,4 | 64.5 |
| b | | | 4,7 | 64.2 |
| y | | | 5,2 | 63.9 |
| bl | | | 5,7 | 63.2 |
| EL | | | 6,8 | 62.1 |

POSTED

Crossection of Plum st (70')
Roseville
Cannon Road to N.S. Dumas st

| | | | | |
|---|---|---|---|---|
| 7.16 | 28.15 | | 20.99 | Bm New Man Ice Store |
| 9.79 | 36.94 | 1.00 | 27.15 | |
| 11.40 | 48.02 | 0.32 | 36.62 | |
| 10.99 | 57.30 | 1.71 | 46.31 | |
| 12.55 | 69.19 | 0.66 | 56.64 | Bm N End Culvert Abutment |
| | | 4.83 | 64.39 / 64.36 | Bm S E 1st + Nd |
| 11.35 | 79.79 | 0.75 | 68.44 | |
| | | | 104.51 | # S W 1st + Plum |

79.79 Plum st

4

80' S of 1st st = Cannon Road

| | | | | |
|---|---|---|---|---|
| EL | | | 11.5 | 68.3 |
| bl | | | 11.5 | 68.3 |
| " | | | 11.0 | 68.8 |
| b | | | 10.5 | 69.3 |
| " | | | 10.0 | 69.8 |
| bl | | | 8.6 | 71.2 |
| WL | | | 8.3 | 71.5 |

75' S of 1st st

| | | | | |
|---|---|---|---|---|
| WL | | | 2.0 | 77.8 |
| bl | | | 2.4 | 77.4 |
| " | | | 2.8 | 77.3 |
| b | | | 2.6 | 77.2 |
| " | | | 3.7 | 76.1 |
| bl | | | 4.2 | 75.6 |
| EL | | | 5.2 | 74.6 |
| TP | 11.36 | 88.54 | 26.1 | 77.18 |

POSTED

| | | | | |
|---|---|---|---|---|
| | | 8854 | | |
| | 50' | S of | 1st st | |
| EL | | | 7.2 | 81.3 |
| bb | | | 6.1 | 82.4 |
| " | | | 5.0 | 83.5 |
| b | | | 4.0 | 84.5 |
| " | | | 2.3 | 86.2 |
| bb | | | 0.8 | 87.7 |
| WL | | | 1.0 | 87.5 |
| TP | 11.45 | 98.28 | 1.71 | 86.83 |
| | 25' | S of | 1st st | |
| WL | | | 2.2 | 96.1 |
| bb | | | 3.3 | 95.0 |
| " | | | 4.5 | 93.8 |
| b | | | 6.0 | 92.3 |
| " | | | 7.6 | 90.7 |
| bb | | | 9.0 | 89.3 |
| EL | | | 8.5 | 89.8 |
| TP | 12.90 | 10896 | 2.22 | 96.06 |

| | | | | | |
|---|---|---|---|---|---|
| | | 10896 | | Plum st | |
| | S Line of | | 1st st (70') | | |
| EL | | | 13.0 | 96.0 | |
| bb | | | 11.8 | 97.2 | |
| " | | | 10.0 | 99.0 | |
| b | | | 8.8 | 100.2 | |
| " | | | 7.2 | 101.8 | |
| bb | | | 6.0 | 103.0 | |
| WL | | | 4.45 | 104.51 | Bm SW H. 1st & Plum |
| | S bb of | | 1st st | | |
| WL | | | 2.1 | 106.9 | |
| bb | | | 3.2 | 105.8 | |
| " | | | 4.6 | 104.4 | |
| b | | | 6.1 | 102.9 | |
| " | | | 7.6 | 101.4 | |
| bb | | | 10.0 | 99.0 | |
| EL | | | 11.5 | 97.5 | |

1896

S 1/4 of 1st st

| | | |
|---|---|---|
| EL | 10.5 | 98.5 |
| bk | 9.0 | 100.0 |
| y | 7.1 | 101.9 |
| b | 5.7 | 103.3 |
| y | 3.8 | 105.2 |
| bk | 1.8 | 107.2 |
| WL | 0.8 | 108.2 |

Center of 1st st

| | | |
|---|---|---|
| WL | 0.0 | 109.0 |
| bk | 1.3 | 107.7 |
| y | 3.0 | 106.0 |
| b | 4.8 | 104.2 |
| y | 6.5 | 102.5 |
| bk | 8.7 | 100.3 |
| | 10.4 | 98.6 |

1896 Plum st

N 1/4 of 1st st

| | | |
|---|---|---|
| EL | 11.3 | 97.7 |
| bk | 8.4 | 100.6 |
| y | 6.6 | 102.4 |
| b | 4.8 | 104.2 |
| y | 3.5 | 105.5 |
| bk | 1.4 | 107.6 |
| WL | 0.0 | 109.0 |

N bk of 1st st

| | | |
|---|---|---|
| WL | 0.6 | 108.4 |
| bk y | 2.2 | 106.8 |
| y | 3.8 | 105.2 |
| b | 6.4 | 102.6 |
| y | 8.0 | 101.0 |
| bk | 11.0 | 98.0 |
| EL | 13.7 | 95.7 |

10896

| | N Line of | 1st st | |
|---|---|---|---|
| EL | | 15.6 | 93.4 |
| bk | | 13.7 | 95.3 |
| y | | 11.0 | 98.0 |
| b | | 9.0 | 100.0 |
| y | | 6.5 | 102.5 |
| bk | | 3.8 | 105.2 |
| WL | | 2.0 | 107.0 |
| | 25' n of | 1st st | |
| WL | | 7.0 | 102.0 |
| bk | | 8.6 | 100.4 |
| y | | 10.0 | 99.0 |
| b | | 11.8 | 97.2 |
| TP | -.02 | 97.49 | 11.45 97.51 |
| y | | | 6.5 91.0 |
| bk | | | 9.1 88.4 |
| EL | | | 11.00 86.5 |

97.49

Plum st

7

| | 50' n of | 1st | st |
|---|---|---|---|
| EL | | 11.6 | 85.9 |
| bk | | 11.5 | 86.0 |
| y | | 10.6 | 86.9 |
| b | | 9.6 | 87.9 |
| y | | 7.7 | 89.5 |
| bl | | 6.4 | 91.1 |
| WL | | 3.5 | 94.0 |
| | 75' n of | 1st | st |
| WL | | 7.2 | 90.3 |
| bk | | 7.6 | 89.9 |
| y | | 7.8 | 89.7 |
| b | | 6.5 | 91.0 |
| y | | 4.5 | 93.0 |
| bl | | 3.5 | 94.0 |
| EL | | 4.0 | 93.5 |
| TP | 12.14 | 109.17 | 0.46 97.03 |

10917

| | | | | |
|---|---|---|---|---|
| | 100' | n of | 1st | st |
| EL | | | 10,0 | 99.2 |
| bh | | | 9,8 | 99.4 |
| y | | | 9,9 | 99.3 |
| b | | | 10,1 | 99.1 |
| y | | | 10,7 | 98.5 |
| b | | | 11,1 | 98.1 |
| WL | | | 12,0 | 97.2 |
| | 125' | n of | 1st | st |
| WL | | | 3,5 | 105.7 |
| bh | | | 3,3 | 105.9 |
| y | | | 3,0 | 106.2 |
| b | | | 2,8 | 106.4 |
| y | | | 2,6 | 106.6 |
| bh | | | 3,0 | 106.2 |
| EL | | | 3,2 | 106.0 |
| TP | 11.30 | 11906 | 1.41 | 107.72 |

11906

Plum st

8

| | | | | |
|---|---|---|---|---|
| | 150' | n of | 1st | st |
| EL | | | 6,0 | 113.1 |
| bh | | | 7,0 | 112.1 |
| y | | | 6,5 | 112.6 |
| b | | | 6,8 | 112.3 |
| y | | | 6,8 | 112.3 |
| bh | | | 5,0 | 114.1 |
| WL | | | 5,1 | 114.0 |
| TP | 11.68 | 13014 | 0.60 | 118.48 |
| | 175' | n of | 1st | st |
| EL | | | 11,0 | 119.1 |
| bh | | | 10,0 | 120.1 |
| y | | | 9,4 | 120.7 |
| b | | | 9,2 | 120.9 |
| y | | | 8,8 | 121.3 |
| bh | | | 8,0 | 122.1 |
| WL | | | 7,3 | 122.8 |

13014

| | | | | | |
|---|---|---|---|---|---|
| 2 | 200' | n = S ℄ of | 2nd st (70') | | |
| WL | | | 4,24 | 125.90 | BM SW 2nd |
| bb | | | 4,6 | 125.5 | |
| y | | | 5,0 | 125.1 | |
| b | | | 5,7 | 124.4 | |
| y | | | 6,4 | 123.7 | |
| bb | | | 7,2 | 122.9 | |
| EL | | | 7,8 | 122.3 | |
| | S bb | of | 2nd | st | |
| EL | | | 6,4 | 123.7 | |
| bb | | | 5,8 | 124.3 | |
| y | | | 5,2 | 124.9 | |
| b | | | 4,2 | 125.9 | |
| y | | | 3,8 | 126.3 | |
| bb | | | 3,1 | 127.0 | |
| WL | | | 2,7 | 127.4 | |

13014 Plum st

| | | | | | |
|---|---|---|---|---|---|
| | S 1/4 | of | 2nd | st | |
| WL | | | 1,0 | 129.1 | |
| bb | | | 1,3 | 128.8 | |
| y | | | 2,2 | 127.9 | |
| b | | | 2,8 | 127.3 | |
| y | | | 3,6 | 126.5 | |
| bb | | | 4,2 | 125.9 | |
| EL | | | 5,0 | 125.1 | |
| | Center | of | 2nd | st | |
| EL | | | 3,3 | 126.8 | |
| bb | | | 2,8 | 127.3 | |
| y | | | 2,0 | 128.1 | |
| TP | 12,48 | 140.67 | 1,95 | 128.19 | |
| b | | | 11,8 | 128.9 | |
| y | | | 11,4 | 129.3 | |
| bb | | | 10,2 | 130.5 | |
| WL | | | 10,0 | 150.7 | |

14067

| | | | |
|---|---|---|---|
| | N'ly of | 2nd st | |
| WL | | 7,6 | 133.1 |
| bk | | 8,4 | 132.3 |
| y | | 8,7 | 132.0 |
| b | | 10,0 | 130.7 |
| y | | 10,6 | 130.1 |
| bk | | 11,~ | 129.5 |
| EL | | 11,8 | 128.9 |
| | N bk of | 2nd st | |
| EL | | 9,5~ | 131.2 |
| bk | | 8,8 | 131.9 |
| y | | 8,1 | 132.6 |
| b | | 7,0 | 133.7 |
| y | | 6,~ | 134.5 |
| bk | | 6,0 | 134.7 |
| WL | | 5,4 | 135.3 |

14067 Plum st

| | | | | |
|---|---|---|---|---|
| | N line of | | 2nd st | |
| WL | | | 4,~ | 136.5 |
| bk | | | 4,8 | 135.9 |
| y | | | 5,0 | 135.7 |
| b | | | 5,6 | 135.1 |
| y | | | 6,6 | 134.1 |
| bk | | | 7,7 | 133.0 |
| EL | | | 8,5~ | 132.2 |
| | 25' | n of | 2nd st | |
| EL | | | 6,0 | 134.7 |
| bk | | | 4,9 | 135.8 |
| y | | | 3,8 | 136.9 |
| b | | | 0,0 | 137.7 |
| y | | | 2,~ | 138.5 |
| bk | | | 1,9 | 138.8 |
| WL | | | 1,4 | 139.3 |
| TP | 588 | 14610 | 0,45 | 140~ |

14610

| | 50' | n of | 2nd st | |
|---|---|---|---|---|
| WR | | | 3,9 | 142.2 |
| bk | | | 4,4 | 141.7 |
| y | | | 5,4 | 140.7 |
| b | | | 6,6 | 139.5 |
| r | | | 8,1 | 138.0 |
| bk | | | 9,6 | 136.5 |
| EL | | | 10,8 | 135.3 |
| | 75' | n of | 2nd | st |
| EL | | | 11,0 | 135.1 |
| bk | | | 9,0 | 137.1 |
| y | | | 7,6 | 138.5 |
| b | | | 5,8 | 140.3 |
| r | | | 4,6 | 141.5 |
| bk | | | 3,2 | 142.9 |
| WR | | | 2,2 | 143.9 |

14610 Plum st

11

| | 100 | n of | 2nd | st |
|---|---|---|---|---|
| WR | | | 2,7 | 143.4 |
| bk | | | 4,0 | 142.1 |
| y | | | 5,4 | 140.7 |
| b | | | 6,7 | 139.4 |
| r | | | 8,2 | 137.9 |
| bk | | | 10,1 | 136.0 |
| EL | | | 10,8 | 135.3 |
| | 125' | n of | 2nd | st |
| EL | | | 10,0 | 136.1 |
| bk | | | 9,1 | 137.0 |
| r | | | 8,1 | 138.0 |
| b | | | 7,0 | 139.1 |
| y | | | 5,4 | 140.7 |
| bk | | | 4,6 | 141.5 |
| WR | | | 3,2 | 142.9 |

1460

| | 150' | n of | 2nd | st |
|---|---|---|---|---|
| WL | | | 4.6 | 141.5 |
| bb | | | 5.8 | 140.3 |
| y | | | 6.5 | 139.6 |
| b | | | 7.4 | 138.7 |
| y | | | 8.4 | 137.7 |
| bl | | | 9.5 | 136.6 |
| EL | | | 10.6 | 135.5 |
| | 175' | n of | 2nd | st |
| EL | | | 11.7 | 134.6 |
| bb | | | 10.7 | 135.6 |
| y | | | 9.7 | 136.4 |
| b | | | 8.2 | 137.9 |
| y | | | 7.0 | 139.1 |
| bl | | | 6.5 | 139.6 |
| WL | | | 5.3 | 140.8 |

1460

Plum st

| | 200' | n = | S L of | 3d st (50') |
|---|---|---|---|---|
| | | | | Bm Sm 3d st |
| WL | | | 6.8 | 139.2 |
| bb | | | 7.7 | 138.4 |
| y | | | 8.7 | 137.4 |
| b | | | 9.6 | 136.5 |
| y | | | 10.6 | 135.5 |
| bl | | | 11.6 | 134.5 |
| EL | | | 12.4 | 133.7 |
| | S bb | of | 3d st | |
| EL | | | 12.7 | 133.4 |
| bl | | | 12.0 | 134.1 |
| y | | | 11.0 | 135.1 |
| b | | | 10.0 | 136.1 |
| y | | | 9.2 | 136.9 |
| bb | | | 8.1 | 138.0 |
| WL | | | 7.2 | 138.9 |

1461.0

S ¼ of 3d st

| | | |
|---|---|---|
| WL | 7.0 | 139.1 |
| bk | 8.0 | 138.1 |
| y | 8.9 | 137.2 |
| b | 9.9 | 136.2 |
| y | 10.9 | 135.2 |
| bk | 11.8 | 134.3 |
| EL | 12.7 | 133.4 |

Center of 3d st

| | | |
|---|---|---|
| EL | 12.6 | 133.5 |
| bk | 12.0 | 134.1 |
| y | 11.1 | 135.0 |
| b | 10.1 | 136.0 |
| y | 9.1 | 137.0 |
| bk | 8.2 | 137.9 |
| WL | 7.2 | 138.9 |

1461.0 Plum st

N ¼ of 3d st

| | | |
|---|---|---|
| WL | 7.4 | 138.7 |
| bk | 8.2 | 137.9 |
| y | 9.2 | 136.9 |
| b | 10.0 | 136.1 |
| y | 11.0 | 135.1 |
| bk | 12.1 | 134.0 |
| EL | 13.0 | 133.1 |

N bk of 3d st

| | | |
|---|---|---|
| EL | 13.3 | 132.8 |
| bk | 12.4 | 133.7 |
| y | 11.5 | 134.6 |
| b | 10.5 | 135.6 |
| y | 9.5 | 136.6 |
| bk | 8.6 | 137.5 |
| WL | 7.6 | 138.5 |
| TP 3.0 | 14.12 | 8.00 138.10 |

| | | | | |
|---|---|---|---|---|
| | | 14112 | | |
| | n Sin | of | 3d | st |
| WL | | | 3,00 | 138.1 |
| bb | | | 4,0 | 137.1 |
| " | | | 4,9 | 136.2 |
| b | | | 5,8 | 135.3 |
| " | | | 6,9 | 134.2 |
| bb | | | 7,7 | 133.4 |
| EL | | | 8,4 | 132.7 |
| | 50' | n of | 3d st | |
| EL | | | 8,6 | 132.5 |
| bb | | | 7,7 | 133.4 |
| " | | | 6,7 | 134.4 |
| b | | | 5,8 | 135.3 |
| " | | | 4,7 | 136.4 |
| bb | | | 4,2 | 136.9 |
| WL | | | 35 | 137.6 |

| | | | | |
|---|---|---|---|---|
| | | 14112 | | Plum st |
| | 100' | n of | 3d | st |
| WL | | | 4,5 | 136.6 |
| bb | | | 5,0 | 136.1 |
| " | | | 5,4 | 135.7 |
| b | | | 5,8 | 135.3 |
| " | | | 6,4 | 134.7 |
| bb | | | 7,3 | 133.8 |
| EL | | | 8,1 | 133.0 |
| | 125' | n of | 3d st | |
| EL | | | 9,0 | 132.1 |
| bb | | | 8,4 | 132.7 |
| " | | | 7,7 | 133.4 |
| b | | | 7,2 | 133.9 |
| " | | | 7,0 | 134.1 |
| bb | | | 6,8 | 134.3 |
| WL | | | 6,8 | 134.3 |

| | | | | |
|---|---|---|---|---|
| | | 141.12 | | |
| | 150 | n of | 3d st | |
| WL | | | 10.7 | 30.4 |
| bh | | | 10.8 | 130.3 |
| " | | | 10.8 | 130.3 |
| b | | | 10.7 | 130.4 |
| " | | | 11.1 | 130.0 |
| bh | | | 11.4 | 129.7 |
| EL | | | 11.3 | 129.8 |
| TP | 2.48 | 131.78 | 11.82 | 129.30 |
| | 175 | n of | 3d st | |
| EL | | | 5.5 | 126.3 |
| bh | | | 5.4 | 126.4 |
| " | | | 5.3 | 126.5 |
| b | | | 5.0 | 126.8 |
| " | | | 5.5 | 126.3 |
| bh | | | 6.0 | 125.8 |
| WL | | | 4.8 | 127.0 |

| | | | | | |
|---|---|---|---|---|---|
| | | 131.78 | | Plum st | |
| | 200 | n = | Sd | 4th st | (70°) |
| WL | | | 12.0 | 119.8 | |
| bh | | | 13.0 | 118.8 | |
| " | | | 13.8 | 118.0 | |
| b | | | 13.6 | 118.2 | |
| " | | | 13.0 | 118.8 | |
| bh | | | 12.6 | 119.2 | |
| EL | | | 12.0 | 119.8 | |
| TP | | | 13.73 | 128.05 | Bm n w # 4th + Plum |
| | Sbb | of | 4th | st | |
| EL | | | 15.0 | 116.8 | |
| bh | | | 15.5 | 116.3 | |
| " | | | 16.7 | 115.1 | |
| b | | | 16.2 | 115.6 | |
| " | | | 15.1 | 116.7 | |
| bh | | | 12.1 | 119.2 | |
| WL | | | 11.0 | 120.8 | |

| | | | | | |
|---|---|---|---|---|---|
| | | 131.78 | | | |
| | S 1/4 of | | 4th | st | |
| WL | | | 10,4 | 121.8 | |
| bb | | | 11,4 | 120.4 | |
| " | | | 13,3 | 118.5 | |
| b | | | 15,7 | 116.1 | |
| " | | | 17,8 | 114.0 | |
| bb | | | 19,6 | 112.2 | |
| EL | | | 19,6 | 112.2 | |
| | Center of | | 4th | st | |
| EL | | | 21,0 | 110.8 | |
| bb | | | 19,0 | 112.8 | |
| " | | | 16,6 | 115.2 | |
| b | | | 14,0 | 117.8 | |
| " | | | 12,2 | 119.6 | |
| bb | | | 10,2 | 121.6 | |
| WL | | | 9,0 | 122.8 | |

| | | | | | |
|---|---|---|---|---|---|
| | | 131.78 | | Plum | |
| | N 1/4 of | | 4th | st | |
| WL | | | 7,2 | 124.6 | |
| bb | | | 8,8 | 123.0 | |
| " | | | 10,5 | 121.3 | |
| b | | | 12,6 | 119.2 | |
| " | | | 14,8 | 117.0 | |
| bb | | | 16,4 | 115.2 | |
| EL | | | 18,8 | 113.0 | |
| | N bb of | | 4th | st | |
| EL | | | 17,3 | 114.5 | POSTED |
| bb | | | 15,0 | 116.8 | |
| " | | | 12,4 | 119.4 | |
| b | | | 10,6 | 121.2 | |
| " | | | 8,4 | 123.4 | |
| bb | | | 6,5 | 125.3 | |
| WL | | | 5,0 | 126.8 | |
| TP | 2.86 | 130.91 | 3,73 | 128.05 | BM NW H 4th & P |

13091

N Side of 4th St

| | | |
|---|---|---|
| WL | 2,9 | 128.0 |
| bh | 4,5 | 126.4 |
| 4 | 8,1 | 122.8 |
| 6 | 9,6 | 121.3 |
| 4 | 11.1 | 119.8 |
| bh | 13,1 | 117.8 |
| EL | 15,2 | 115.7 |

75' N of 4th St

| | | |
|---|---|---|
| EL | 10,7 | 120.2 |
| bh | 8,7 | 122.2 |
| 4 | 6,6 | 124.3 |
| 6 | 5,1 | 125.8 |
| 4 | 3,8 | 127.1 |
| bh | 2,4 | 128.5 |
| WL | 1,4 | 129.5 |

13091

Plum St

50 N of 4th St

| | | |
|---|---|---|
| WL | 0,8 | 130.1 |
| bh | 1,8 | 129.1 |
| 4 | 3,1 | 127.8 |
| 6 | 4,6 | 126.3 |
| 4 | 6,0 | 124.9 |
| bh | 7,5 | 123.4 |
| EL | 8,6 | 122.3 |

75' N of 4th St

| | | |
|---|---|---|
| EL | 2,3 | 123.6 |
| bh | 6,2 | 124.7 |
| 4 | 5,7 | 125.2 |
| 6 | 4,4 | 126.5 |
| 4 | 3,2 | 127.7 |
| bh | 2,4 | 128.5 |
| WL | 1,3 | 129.6 |

13091

| | 100' | n of | 4 ft | el |
|---|---|---|---|---|
| WL | | | 3.0 | 127.9 |
| bk | | | 3.5 | 127.4 |
| y | | | 4.5 | 126.4 |
| b | | | 5.5 | 125.4 |
| y | | | 6.3 | 124.6 |
| bk | | | 6.8 | 124.1 |
| EL | | | 7.5 | 123.4 |
| | 125' | n of | 4 ft | el |
| EL | | | 9.0 | 121.9 |
| bk | | | 8.3 | 122.6 |
| y | | | 7.8 | 123.1 |
| b | | | 7.1 | 123.8 |
| y | | | 6.1 | 124.8 |
| bk | | | 5.3 | 125.6 |
| WL | | | 4.4 | 126.5 |

13091

Plum

| | 150' | n of | 4 ft | el |
|---|---|---|---|---|
| WL | | | 6.8 | 124.1 |
| bk | | | 7.5 | 123.4 |
| y | | | 8.4 | 122.5 |
| b | | | 9.4 | 121.5 |
| y | | | 10.1 | 120.8 |
| bk | | | 10.6 | 120.3 |
| EL | | | 10.9 | 120.0 |
| ~~TP~~ | 175' | n of | 4 ft | el |
| EL | | | 13.4 | 117.5 |
| bk | | | 13.2 | 117.7 |
| y | | | 12.3 | 118.6 |
| b | | | 11.7 | 119.2 |
| y | | | 11.3 | 119.6 |
| bk | | | 10.8 | 120.1 |
| WL | | | 9.5 | 121.4 |
| TP | 134 | 120.01 | 12.24 | 118.67 |

12001

| | | | | | |
|---|---|---|---|---|---|
| | 200' | n = | S 2 5th st | (70') | BM SW 4th st |
| WL | | | 25.4 | 117.47 | |
| bb | | | 3.1 | 116.9 | |
| y | | | 3.8 | 116.2 | |
| b | | | 4.2 | 115.8 | |
| y | | | 5.0 | 115.0 | |
| bb | | | 5.4 | 114.6 | |
| EL | | | 5.7 | 114.3 | |
| | S bb | of | 5th st | | |
| EL | | | 7.3 | 112.7 | |
| bb | | | 6.8 | 113.2 | |
| y | | | 5.8 | 114.2 | |
| b | | | 5.8 | 114.2 | |
| y | | | 5.0 | 115.0 | |
| bb | | | 4.4 | 115.6 | |
| WL | | | 4.1 | 115.9 | |

12001 Plum st

| | | | | |
|---|---|---|---|---|
| | S 1/4 of | 5th | st | |
| WL | | 6.2 | 113.8 | |
| bb | | 6.9 | 113.1 | |
| y | | 7.3 | 112.7 | |
| b | | 7.8 | 112.2 | |
| y | | 7.2 | 112.8 | |
| bb | | 8.2 | 111.8 | |
| EL | | 9.1 | 110.9 | |
| | Center of | 5th | st | |
| EL | | 11.5 | 108.5 | |
| bb | | 10.8 | 109.2 | |
| y | | 10.8 | 109.2 | |
| b | | 10.5 | 109.5 | |
| y | | 10.0 | 110.0 | |
| bb | | 9.0 | 111.0 | |
| WL | | 8.5 | 111.5 | |

| | | | | |
|---|---|---|---|---|
| | | 12001 | | |
| | N 1/4 of | | 5th | st |
| WL | | | 10,6 | 109.4 |
| bl | | | 11,4 | 108.6 |
| y | | | 12,0 | 108.0 |
| b | | | 13,4 | 106.6 |
| TP | 0,62 | 108,06 | 12,57 | 107.44 |
| y | | | 1,8 | 106.3 |
| bl | | | 2,3 | 105.8 |
| EL | | | 2,8 | 105.3 |
| | N bl of | | 5th | st |
| EL | | | 7,0 | 101.1 |
| bl | | | 6,0 | 102.1 |
| y | | | 5,6 | 102.5 |
| b | | | 5,2 | 102.9 |
| y | | | 4,7 | 103.4 |
| bl | | | 3,2 | 104.9 |
| WL | | | 3,2 | 104.9 |

| | | | | |
|---|---|---|---|---|
| | | 10806 | | Plum st |
| | N line of | | 5th | st |
| WL | | | 6,2 | 101.9 |
| bl | | | 6,3 | 101.8 |
| y | | | 7,4 | 100.7 |
| b | | | 7,6 | 100.5 |
| y | | | 8,8 | 99.3 |
| bl | | | 10,6 | 97.5 |
| EL | | | 11,5 | 96.6 |
| TP | 1,15 | 96,55 | 12,66 | 95.40 |
| EL | 30' n of | | 5th st | |
| EL | | | 14,0 | 82.6 |
| bl | | | 11,0 | 85.6 |
| y | | | 9,8 | 86.8 |
| b | | | 9,0 | 87.6 |
| y | | | 8,0 | 88.6 |
| bl | | | 7,5 | 89.1 |
| WL | | | 5,0 | 91.6 |

96,55

| | 50' | n of | 5 it | at |
|---|---|---|---|---|
| WL | | | +0,4 | 97.0 |
| bk | | | 0,0 | 96.6 |
| y | | | 1,0 | 95.6 |
| b | | | 2,5 | 94.1 |
| y | | | 3,6 | 93.0 |
| bk | | | 5,5 | 91.1 |
| EL | | | 6,3 | 90.3 |
| TP | 11,23 | 10649 | 1,29 | 95.24 |

| | 75' | n of | 5 it | at |
|---|---|---|---|---|
| EL | | | 9,8 | 96.7 |
| bk | | | 8,6 | 97.9 |
| y | | | 7,3 | 99.2 |
| b | | | 6,4 | 100.1 |
| y | | | 3,0 | 101.5 |
| bk | | | 4,1 | 102.4 |
| WL | | | 4,7 | 102.9 |

10649 Plum st

| | 100 | n of | 5 it | at |
|---|---|---|---|---|
| WL | | | 0,3 | 106.2 |
| bk | | | 1,4 | 105.1 |
| y | | | 2,7 | 103.8 |
| b | | | 4,0 | 102.5 |
| y | | | 5,2 | 101.3 |
| bk | | | 6,5 | 100.0 |
| EL | | | 7,9 | 98.6 |

| | 125' | n of | 5 it | at |
|---|---|---|---|---|
| EL | | | 7,4 | 99.1 |
| bk | | | 6,1 | 100.4 |
| y | | | 4,7 | 101.8 |
| b | | | 3,2 | 103.3 |
| y | | | 1,6 | 104.9 |
| bk | | | 0,0 | 106.5 |
| WL | | | +0,5 | 107.0 |

10649

| | | | | |
|---|---|---|---|---|
| | 150' | n of | 5 it | st |
| Wh | | | +0,6 | 107.1 |
| bh | | | 0,0 | 106.5 |
| y | | | 1,7 | 104.8 |
| b | | | 3,0 | 103.5 |
| y | | | 4,5 | 102.0 |
| bh | | | 6,2 | 100.3 |
| Eh | | | 7,7 | 98.8 |
| | 175' | n of | 5 it | st |
| Eh | | | 9,0 | 97.5 |
| bh | | | 7,8 | 98.7 |
| y | | | 6,3 | 100.2 |
| b | | | 4,6 | 101.9 |
| y | | | 3,3 | 103.2 |
| bh | | | 2,0 | 104.5 |
| Wh | | | 1,0 | 105.5 |

10649 Plum st



| | | | | | |
|---|---|---|---|---|---|
| | 200' | n = S | & 6 it | st (70') | |
| Wh | | | 2.75 | 103.74 | Bm H SW 6 it |
| bh | | | 4,0 | 102.5 | |
| y | | | 5,5 | 101.0 | |
| b | | | 6,9 | 99.6 | |
| y | | | 8,0 | 98.5 | |
| bh | | | 9,6 | 96.9 | |
| Eh | | | 11,0 | 95.5 | |
| | S bb | of | 6 it | st | |
| Eh | | | 11,6 | 94.9 | |
| bh | | | 10,4 | 96.1 | |
| y | | | 9,0 | 97.5 | |
| b | | | 7,4 | 99.1 | |
| y | | | 6,0 | 100.5 | |
| bh | | | 4,6 | 101.9 | |
| Wh | | | 3,3 | 103.2 | |

10649

S 1/4 of 6th st

| | | |
|---|---|---|
| WL | 3,2 | 103.3 |
| bh | 4,8 | 101.7 |
| 4 | 6,4 | 100.1 |
| b | 8,0 | 98.5 |
| 4 | 9,5 | 97.0 |
| bh | 11,2 | 95.3 |
| EL | 12,7 | 93.8 |

Center of 6th st

| | | |
|---|---|---|
| EL | 13,5 | 93.0 |
| bh | 12,3 | 94.2 |
| 4 | 10,6 | 95.9 |
| b | 8,4 | 98.1 |
| 4 | 6,6 | 99.9 |
| bh | 4,4 | 101.8 |
| WL | 2,4 | 104.1 |

10649 Plum st

N 1/4 of 6th st

| | | |
|---|---|---|
| WL | 2,3 | 104.2 |
| bh | 4,1 | 102.4 |
| 4 | 5,2 | 101.3 |
| b | 7,2 | 99.3 |
| 4 | 9,8 | 96.7 |
| bh | 12,5 | 94.0 |
| EL | 14,5 | 92.0 |

N bb of 6th st

| | | |
|---|---|---|
| EL | 14,3 | 92.2 |
| bh | 12,5 | 94.0 |
| 4 | 10,3 | 96.2 |
| b | 7,8 | 98.7 |
| 4 | 6,0 | 100.5 |
| bh | 4,2 | 102.3 |
| WL | 2,4 | 104.1 |

10649

N.L of 6th st

| | | | |
|---|---|---|---|
| WL | 2,2 | 104.3 | |
| bk | 4,0 | 103.5 | |
| y | 5,7 | 100.8 | |
| b | 8,5 | 98.0 | |
| y | 11,3 | 95.2 | |
| bk | 12,7 | 93.8 | |
| EL | 14,2 | 92.3 | |
| TP | 11,94 | 10635 | 12,08 | 94.41 |

25' n of 6th st

| | | | |
|---|---|---|---|
| EL | 14,0 | 92.4 | |
| bk | 12,8 | 93.6 | |
| y | 10,8 | 95,6 | |
| b | 8,5 | 97.9 | |
| y | 6,5 | 99.9 | |
| bk | 3,6 | 102.8 | |
| WL | 2,1 | 104.3 | |

10635 Plum st

50 n of 6th st

| | | | |
|---|---|---|---|
| WL | 2,9 | 103.5 | |
| bk | 4,8 | 101.6 | |
| y | 7,0 | 99.4 | |
| b | 9,4 | 97.0 | |
| y | 11,3 | 95.1 | |
| bk | 12,6 | 93.8 | |
| EL | 13,6 | 92.8 | |

75' n of 6th st

| | | | |
|---|---|---|---|
| EL | 11,0 | 95.4 | |
| bk | 10,0 | 96.4 | |
| y | 8,6 | 97.8 | |
| b | 6,8 | 99.6 | |
| y | 5,9 | 100.9 | |
| bk | 3,5 | 102.9 | |
| WL | 2,0 | 104.4 | |

POSTED

| | | 106.35 | | |
|---|---|---|---|---|
| | 100' | n of | 6 ft | at |
| WL | | | 1.6 | 104.8 |
| | | | 3.0 | 103.4 |
| " | | | 4.0 | 102.4 |
| " | | | 5.0 | 101.4 |
| " | | | 5.3 | 101.1 |
| bk | | | 5.8 | 100.6 |
| EL | | | 6.5 | 99.9 |
| | 125' | n of | 6 ft | at |
| EL | | | 4.3 | 102.1 |
| bk | | | 3.7 | 102.7 |
| " | | | 3.0 | 103.4 |
| " | | | 1.4 | 104.8 |
| " | | | 2.0 | 104.4 |
| bk | | | 1.6 | 104.8 |
| WL | | | 0.6 | 105.8 |
| TP | 1.27 | 106.78 | 0.84 | 105.57 |

| | | 106.78 | | Plum st |
|---|---|---|---|---|
| | 150' | n of | 6 ft | at |
| WL | | | 3.0 | 103.8 |
| bk | | | 2.1 | 104.7 |
| " | | | 1.8 | 105.0 |
| " | | | 2.6 | 104.2 |
| " | | | 2.9 | 103.9 |
| bk | | | 3.3 | 103.5 |
| EL | | | 4.0 | 102.8 |
| | 175' | n of | 6 ft | at |
| EL | | | 6.4 | 100.4 |
| bk | | | 6.6 | 100.2 |
| " | | | 7.0 | 99.8 |
| " | | | 7.6 | 99.2 |
| " | | | 9.0 | 97.8 |
| bk | | | 9.2 | 97.6 |
| WL | | | 9.3 | 97.5 |
| TP | 0.70 | 95.37 | 12.11 | 94.67 |

95.37

200' n = S ⅓ of 7th st (70')

| | | | | | |
|---|---|---|---|---|---|
| WL | | | 3,12 | 92.25 | Bm ⊥ SW 7th |
| bb | | | 3,7 | 91.7 | |
| " | | | 3,3 | 92.1 | |
| b | | | 3,0 | 92.4 | |
| " | | | 2,0 | 93.4 | |
| bb | | | 2,2 | 93.2 | |
| EL | | | 2,3 | 93.1 | |
| | S bb of | | 7th st | | |
| EL | | | 6,9 | 88.5 | |
| bb | | | 6,7 | 88.7 | |
| " | | | 6,5 | 88.9 | |
| b | | | 7,0 | 88.4 | |
| " | | | 7,2 | 88.2 | |
| bb | | | 7,0 | 88.4 | |
| WL | | | 6,5 | 88.9 | |

95.37 Plum st

S ¼ of 7th st

| | | | | |
|---|---|---|---|---|
| WL | | | 10,3 | 85.1 |
| bb | | | 10,8 | 84.6 |
| " | | | 11,0 | 84.4 |
| b | | | 11,0 | 84.4 |
| " | | | 10,4 | 85.0 |
| bb | | | 11,5 | 83.9 |
| EL | | | 11,4 | 84.0 |
| TP | 2,46 | 85,55 | 12,28 | 83.09 |
| | Center of | | 7th st | |
| EL | | | 6,2 | 79.4 |
| | | | 6,4 | 79.2 |
| " | | | 6,6 | 79.0 |
| b | | | 6,4 | 79.2 |
| " | | | 6,0 | 79.6 |
| bb | | | 5,6 | 80.0 |
| WL | | | 5,5 | 80.1 |

POSTED

8555

n ¼ of 7th st

| | | | |
|---|---|---|---|
| WL | | 11,8 | 73.8 |
| bl | | 13,0 | 72.6 |
| y | | 13,2 | 72.4 |
| b | | 15,0 | 70.6 |
| y | | 14.0 | 71.6 |
| bl | | 13,0 | 72.6 |
| EL | | 12,0 | 73.6 |

n blk of 7th st

| | | | |
|---|---|---|---|
| EL | | 155 | 70.1 |
| bl | | 150 | 70.6 |
| y | | 13,0 | 72.6 |
| b | | 10,0 | 75.6 |
| y | | 8,0 | 77.6 |
| bl | | 7,0 | 78.6 |
| WL | | 6,0 | 79.6 |

8555 Plum st

27

n 2 of 7th st

| | | | |
|---|---|---|---|
| WL | | 14 | 84.2 |
| bl | | 4,0 | 81.6 |
| y | | 6,0 | 79.6 |
| b | | 7,0 | 78.6 |
| y | | 10,3 | 75.3 |
| bl | | 12,4 | 73.2 |
| EL | | 12,5 | 73.1 |
| TP | 1255 | 9732 | 0.78 8477 |

Rock at n w

30 n of 7th st

| | | | |
|---|---|---|---|
| WL | | 1,5 | 95.8 |
| bl | | 1,8 | 95.5 |
| y | | 2,4 | 94.9 |
| b | | 3,2 | 94.1 |
| y | | 4,7 | 92.6 |
| bl | | 5,2 | 92.1 |
| EL | | 6,3 | 91.0 |
| TP | 1262 | 10991 | 0,03 97.29 |

109.91

| | 50' | n of | 7th | st |
|---|---|---|---|---|
| EL | | | 12.6 | 97.3 |
| bh | | | 12.1 | 97.8 |
| 4 | | | 11.1 | 98.8 |
| 6 | | | 10.4 | 99.5 |
| 4 | | | 9.4 | 100.5 |
| bh | | | 8.7 | 101.2 |
| WL | | | 8.8 | 101.1 |
| | 75' | n of | 7th | st |
| WL | | | 5.3 | 104.6 |
| bh | | | 5.3 | 104.6 |
| 4 | | | 5.8 | 104.1 |
| 6 | | | 6.2 | 103.7 |
| 4 | | | 6.7 | 103.2 |
| bh | | | 7.1 | 102.8 |
| EL | | | 7.5 | 102.4 |

109.91

Plum st

| | 100' | n of | 7th | st |
|---|---|---|---|---|
| EL | | | 3.2 | 106.7 |
| bh | | | 2.6 | 107.3 |
| 4 | | | 2.0 | 107.9 |
| 6 | | | 1.5 | 108.4 |
| 4 | | | 1.7 | 108.2 |
| bh | | | 1.9 | 108.0 |
| WL | | | 1.6 | 108.3 |
| | 125' | n of | 7th | st |
| WL | | | 0.2 | 109.7 |
| bh | | | 0.0 | 109.9 |
| 4 | | | 0.0 | 109.9 |
| 6 | | | 0.3 | 109.6 |
| 4 | | | 0.3 | 109.6 |
| bh | | | 0.8 | 109.1 |
| EL | | | 1.2 | 108.7 |
| TP | 781 | 11647 | 1.25 | 108.66 |

11647

130 n of 7th st

| | | |
|---|---|---|
| EL | 7.1 | 109.4 |
| bh | 6.6 | 109.9 |
| 4 | 6.0 | 110.5 |
| 6 | 5.9 | 110.6 |
| 4 | 5.5 | 111.0 |
| bh | 5.4 | 111.1 |
| WL | 5.7 | 110.8 |

175 n of 7th

| | | |
|---|---|---|
| WL | 4.6 | 111.9 |
| bh | 4.7 | 111.8 |
| 4 | 5.0 | 111.5 |
| 6 | 4.9 | 111.6 |
| 4 | 4.7 | 111.8 |
| bh | 5.0 | 111.5 |
| EL | 5.4 | 111.1 |

11647 Plum st

200 n=S of 8th st (70')

| | | |
|---|---|---|
| EL | 5.7 | 110.8 |
| bh | 5.4 | 111.1 |
| 4 | 4.8 | 111.7 |
| 6 | 4.7 | 111.8 |
| 4 | 4.7 | 111.8 |
| bh | 4.6 | 111.9 |
| WL | 4.70 | 111.71 |

Bm Sw 8th st

Slab of 8th st

| | | |
|---|---|---|
| WL | 4.5 | 112.0 |
| bh | 4.4 | 112.1 |
| 4 | 4.4 | 112.1 |
| 6 | 4.5 | 112.0 |
| 4 | 4.8 | 111.7 |
| bh | 5.2 | 111.3 |
| EL | 5.2 | 111.3 |

POSTED

11647

| | | | |
|---|---|---|---|
| | S ½ of | Sect | |
| E2 | | 5,1 | 111.4 |
| bl | | 4,5 | 112.0 |
| 4 | | 4,4 | 112.1 |
| b | | 4,1 | 112.4 |
| 4 | | 4,0 | 112.5 |
| bl | | 4,0 | 112.5 |
| W2 | | 4.1 | 112.4 |
| | Center of | Sect | st |
| W2 | | 3,9 | 112.6 |
| bl | | 3,9 | 112.6 |
| 4 | | 3,9 | 112.6 |
| b | | 4,0 | 112.5 |
| 4 | | 4,3 | 112.2 |
| bl | | 4,6 | 111.9 |
| E2 | | 5,0 | 111.5 |

11647 Plum st

| | | | |
|---|---|---|---|
| | N ½ of | Sect | st |
| E2 | | 4,6 | 111.9 |
| bl | | 4,3 | 112.2 |
| 4 | | 4,0 | 112.5 |
| b | | 4,0 | 112.5 |
| 4 | | 3,7 | 112.8 |
| bl | | 3,7 | 112.8 |
| W2 | | 3,6 | 112.9 |
| | N bl of | Sect | st |
| W2 | | 3,4 | 113.1 |
| bl | | 3,5 | 113.0 |
| 4 | | 3,6 | 112.9 |
| b | | 3,7 | 112.8 |
| 4 | | 3,7 | 112.8 |
| bl | | 3,8 | 112.7 |
| E2 | | 4,0 | 112.5 |

11647

| | n line of | 8 ft | st |
|---|---|---|---|
| EL | | 4.1 | 112.4 |
| bh | | 3.7 | 112.8 |
| 4 | | 3.7 | 112.8 |
| 6 | | 3.6 | 112.9 |
| 4 | | 3.5 | 113.0 |
| bh | | 3.5 | 113.0 |
| WL | | 3.3 | 113.2 |
| | 25' n of | 8 ft | st |
| WL | | 3.6 | 112.9 |
| bh | | 3.4 | 113.1 |
| 4 | | 3.4 | 113.1 |
| 6 | | 3.6 | 112.9 |
| 4 | | 3.9 | 112.6 |
| bh | | 4.4 | 112.1 |
| EL | | 5.0 | 111.5 |

11647 Plum st

61

| | 50' | n of | 8 ft | st |
|---|---|---|---|---|
| EL | | | 6.5 | 110.0 |
| bh | | | 5.6 | 110.9 |
| 4 | | | 4.8 | 111.7 |
| 6 | | | 4.3 | 112.2 |
| 4 | | | 4.1 | 112.4 |
| bh | | | 4.2 | 112.3 |
| WL | | | 4.2 | 112.3 |
| | 75' | n of | 8 ft | st |
| WL | | | 6.0 | 110.5 |
| bh | | | 6.1 | 110.4 |
| 4 | | | 6.6 | 109.9 |
| 6 | | | 7.0 | 108.5 |
| 4 | | | 7.6 | 108.9 |
| bh | | | 8.3 | 108.2 |
| EL | | | 9.0 | 107.5 |
| TP | 171 | 109.36 | 8.82 | 107.65 |

| | | | 109.36 | |
|---|---|---|---|---|
| | 100' | n of | 8th st | |
| EL | | | 8,9 | 100.5 |
| bk | | | 9,0 | 100.4 |
| 4 | | | 7,3 | 102.1 |
| b | | | 5,7 | 103.7 |
| 4 | | | 5,2 | 104.2 |
| bk | | | 3,7 | 105.7 |
| WL | | | 3,7 | 105.7 |
| | 125' | n of | 8th st | |
| WL | | | 11,4 | 98.0 |
| bk | | | 12,0 | 97.4 |
| 4 | | | 13,0 | 96.4 |
| TP | 1,77 | 98,65 | 12,93 | 96,93 |
| b | | | 3,8 | 94.9 |
| 4 | | | 4,6 | 94.1 |
| bk | | | 5,5 | 93.2 |
| EL | | | 6,7 | 92.0 |

| | | | 98.65 | Plum st |
|---|---|---|---|---|
| | 150' | n of | 8th st | |
| WL | | | 9,0 | 89.7 |
| bk | | | 10,0 | 88.7 |
| 4 | | | 11,0 | 87.7 |
| b | | | 13,0 | 85.7 |
| TP | 1,70 | 88,65 | 11,70 | 86,95 |
| 4 | | | 4,5 | 84.2 |
| bk | | | 7,8 | 80.9 |
| EL | | | 10,5 | 78.2 |
| | 175' | n of | 8th st | |
| WL | | | 8,0 | 80.7 |
| bk | | | 9,0 | 79.7 |
| 4 | | | 11,4 | 77.3 |
| b | | | 13,5 | 75.2 |
| TP | 0,09 | 75,79 | 12,95 | 75,70 |
| 4 | | | 4,5 | 71.3 |
| bk | | | 6,3 | 69.5 |
| EL | | | 6,8 | 69.0 |

75.79

| | 200' | n = | S ℄ of | 9th st | Ingelow (70') |
|---|---|---|---|---|---|
| EL | | | 13,5 | 62.3 | |
| bb | | | 14,0 | 61.8 | |
| " | | | 13,4 | 62.4 | |
| b | | | 11,6 | 64.2 | |
| " | | | 9,6 | 66.2 | |
| bb | | | 5,7 | 70.1 | |
| WL | | | 3,22 | 72.57 | BM & SW 9th |
| | S bb of | | 9th st | | |
| WL | | | 6,7 | 69.1 | |
| bb | | | 8,7 | 67.1 | |
| " | | | 11,0 | 64.8 | |
| b | | | 13,0 | 62.8 | |
| " | | | 13,8 | 62.0 | |
| bb | | | 14,0 | 61.8 | |
| EL | | | 14,0 | 61.8 | |

75.79 Plum st

| | S 1/4 of | | 9th | st |
|---|---|---|---|---|
| EL | | | 10,0 | 65.8 |
| bb | | | 12,0 | 63.8 |
| " | | | 12,7 | 63.1 |
| b | | | 14,0 | 61.8 |
| " | | | 13,0 | 62.8 |
| bb | | | 11,0 | 64.8 |
| WL | | | 9,6 | 66.2 |
| | Center of | | 9th st | |
| WL | | | 12,9 | 63.7 |
| bb | | | 12,5 | 63.3 |
| " | | | 11,5 | 64.3 |
| b | | | 10,0 | 65.8 |
| " | | | 8,3 | 67.5 |
| bb | | | 6,4 | 69.4 |
| EL | | | 6,8 | 69.0 |

POSTED

| | | | | | |
|---|---|---|---|---|---|
| | | 7579 | | | |
| | N 1/4 | of | 9th | st | |
| EL | | | 1,0 | 74.8 | |
| bh | | | 1,8 | 74.0 | |
| y | | | 1,5 | 74.3 | |
| b | | | 2,3 | 73.5 | |
| y | | | 3,4 | 72.4 | |
| bh | | | 6,6 | 69.2 | |
| WL | | | 8,0 | 67.8 | |
| | N bb | of | 9th | st | |
| WL | | | 1,6 | 74.2 | |
| bh | | | 0,6 | 75.2 | |
| y | | | 0,8 | 75.0 | |
| TP | 12,73 | 8660 | 1,92 | 73.87 | Rock |
| b | | | 11,7 | 74.9 | |
| y | | | 10,0 | 76.6 | |
| bh | | | 7,4 | 79.2 | |
| EL | | | 6,0 | 80.6 | |

| | | | | | |
|---|---|---|---|---|---|
| | | 8660 | | Plum | st |
| | N Line | of | 9th | st | |
| EL | | | +0,4 | 87.0 | |
| bh | | | 1,2 | 85.4 | |
| y | | | 3,6 | 83.0 | |
| b | | | 5,0 | 81.6 | |
| y | | | 6,0 | 80.6 | |
| bh | | | 7,0 | 79.6 | |
| WL | | | 7,6 | 79.0 | |
| TP | 12,85 | 9647 | 2,98 | 83.69 | |
| | 25' | in of | 9th | st | |
| WL | | | 4,7 | 91.8 | |
| bh | | | 3,7 | 92.8 | |
| y | | | 2,2 | 94.3 | |
| b | | | 1,0 | 95.5 | |
| TP | 11,26 | 10633 | 1,40 | 95,07 | |
| y | | | 10,2 | 96.1 | |
| bh | | | 8,6 | 97.7 | |
| EL | | | 7,5 | 98.8 | |

COPIED

| | | | | |
|---|---|---|---|---|
| | | 106.33 | | |
| | 50' | n of | 9 ch | st |
| EL | | | +1,0 | 107.3 |
| bh | | | +0,5 | 106.8 |
| y | | | +1,0 | 107.3 |
| b | | | +1,0 | 107.3 |
| y | | | 0,5 | 105.8 |
| bh | | | 2,0 | 104.3 |
| WL | | | 3,0 | 103.3 |
| TP | 11,97 | 116,70 | 1,60 | 104,73 |
| | 75' | n of | 9 ch | st |
| WL | | | 5,3 | 111.4 |
| bh | | | 4,5 | 112.2 |
| y | | | 3,6 | 113.1 |
| b | | | 2,7 | 114.0 |
| y | | | 2,6 | 114.1 |
| bh | | | 3,0 | 113.7 |
| EL | | | 3,6 | 113.1 |

| | | | | |
|---|---|---|---|---|
| | | 116,70 | | Plum st |
| | 100' | n of | 9 ch | st |
| EL | | | 1,5 | 115.2 |
| bh | | | 1,0 | 115.7 |
| y | | | 0,0 | 116.7 |
| TP | 4.57 | 121,03 | 0,24 | 116,46 |
| b | | | 4,2 | 116.8 |
| y | | | 4,3 | 116.7 |
| bh | | | 4,5 | 116.5 |
| WL | | | 4,6 | 116.4 |
| | 125' | n of | 9 ch | st |
| WL | | | 2,3 | 118.7 |
| bh | | | 2,3 | 118.7 |
| y | | | 2,7 | 118.3 |
| b | | | 3,0 | 118.0 |
| y | | | 3,2 | 117.8 |
| bh | | | 3,9 | 117.1 |
| EL | | | 5,0 | 116.0 |

121.03

| | | | | |
|---|---|---|---|---|
| | 150 | n of | 9th | st |
| Et | | | 6,2 | 114.8 |
| bb | | | 4,9 | 116.1 |
| y | | | 3,8 | 117.2 |
| b | | | 3,1 | 117.9 |
| y | | | 2,4 | 118.6 |
| bb | | | 1,6 | 119.4 |
| Wt | | | 1,5 | 119.5 |
| | 175' | n of | 9th | st |
| Wt | | | 2,1 | 118.9 |
| bb | | | 2,4 | 118.6 |
| y | | | 2,8 | 118.2 |
| b | | | 3,3 | 117.7 |
| y | | | 4,3 | 116.7 |
| bb | | | 5,2 | 115.8 |
| Et | | | 6,5 | 114.5 |

121.03 Plum St

| | | | | | |
|---|---|---|---|---|---|
| | 200' n = S line of | | 10th st (70') | | |
| Et | | | 6,0 | 115.0 | |
| bb | | | 5,0 | 116.0 | |
| y | | | 3,8 | 117.2 | |
| b | | | 2,7 | 118.3 | |
| y | | | 2,4 | 118.6 | |
| bb | | | 2,2 | 118.8 | |
| Wt | | | 2,20 | 118,83 | Bm Sw H 10th |
| | S bb of | | 10th | st | |
| Wt | | | 2,1 | 118.9 | |
| bb | | | 2,2 | 118.8 | |
| y | | | 2,2 | 118.8 | |
| b | | | 2,4 | 118.6 | |
| y | | | 3,3 | 117.7 | |
| bb | | | 5,0 | 116.0 | |
| Et | | | 6,0 | 115.0 | |

12/03

| | S 1/4 of | 10 th | st |
|---|---|---|---|
| EL | | 6,4 | 114.6 |
| th | | 5,4 | 115.6 |
| 4 | | 4,7 | 116.3 |
| 6 | | 3,8 | 117.2 |
| 4 | | 2,5 | 118.5 |
| th | | 1,8 | 119.2 |
| WL | | 1,8 | 119.2 |
| | Center of | 10th | st |
| WL | | 1,5 | 119.5 |
| th | | 1,5 | 119.5 |
| 4 | | 2,0 | 119.0 |
| 6 | | 2,8 | 118.2 |
| 4 | | 3,9 | 117.1 |
| th | | 5,2 | 115.8 |
| EL | | 5,8 | 115.2 |

changed to Jarrisst.

12/03 Plum st

| | N 1/4 of | 10th | st |
|---|---|---|---|
| EL | | 5,2 | 115.7 |
| th | | 4,6 | 116.4 |
| 4 | | 4,1 | 116.9 |
| 6 | | 3,2 | 117.8 |
| 4 | | 2,2 | 118.8 |
| th | | 1,5 | 119.5 |
| WL | | 1,3 | 119.7 |
| | N 6th of | 10th | st |
| WL | | 1,4 | 119.6 |
| th | | 1,6 | 119.4 |
| 4 | | 2,0 | 119.0 |
| 6 | | 3,0 | 118.0 |
| 4 | | 3,6 | 117.4 |
| th | | 4,1 | 116.9 |
| EL | | 5,0 | 116.0 |

| | | | | |
|---|---|---|---|---|
| | | 121.03 | | |
| | n line | of | 10th st | |
| EL | | | 5,4 | 115.6 |
| bh | | | 4,4 | 116.6 |
| y | | | 3,6 | 117.4 |
| b | | | 2,7 | 118.3 |
| y | | | 2,0 | 119.0 |
| bh | | | 1,6 | 119.4 |
| WL | | | 1,4 | 119.6 |
| TP | 1,08 | 120.66 | 1,45 | 119,58 |
| | 50' | n of | 10th | st |
| WL | | | 1,0 | 119.7 |
| bh | | | 1,6 | 119.1 |
| y | | | 2,0 | 118.7 |
| b | | | 2,5 | 118.2 |
| y | | | 3,5 | 117.2 |
| bh | | | 4,3 | 116.4 |
| EL | | | 5,4 | 115.3 |

| | | | | |
|---|---|---|---|---|
| | | 120.66 | | Plum st |
| | 100' | n of | 10th | st |
| EL | | | 6,5 | 114.2 |
| bh | | | 5,7 | 115.0 |
| y | | | 5,1 | 115.6 |
| b | | | 4,5 | 116.2 |
| y | | | 4,2 | 116.5 |
| bh | | | 3,9 | 116.8 |
| WL | | | 3,3 | 117.4 |
| | 150' | n of | 10th | st |
| WL | | | 5,0 | 115.7 |
| bh | | | 6,0 | 114.7 |
| y | | | 6,4 | 114.3 |
| b | | | 7,2 | 113.5 |
| y | | | 8,0 | 112.7 |
| bh | | | 8,6 | 112.1 |
| EL | | | 9,3 | 111.4 |

12066

| | | | | | |
|---|---|---|---|---|---|
| | 200 | n = | S S | 11th st (70') | |
| EL | | | 11,6 | 109.1 | |
| bb | | | 11,2 | 109.5 | |
| y | | | 10,6 | 110.1 | |
| b | | | 10,0 | 110.7 | |
| y | | | 9,3 | 111.4 | |
| bb | | | 8,6 | 112.1 | |
| WL | | | 7,8 | 112.9 | |
| TP | 00 | 113.31 | 7,35 | 113.31 | SW H 11th |
| | S bb | of | 11th st | | |
| WL | | | 1,4 | 111.9 | |
| bb | | | 2,0 | 111.3 | |
| y | | | 2,8 | 110.5 | |
| b | | | 3,3 | 110.0 | |
| y | | | 4,4 | 108.9 | |
| bb | | | 5,0 | 108.3 | |
| EL | | | 5,0 | 108.3 | |

11331 Plum st

| | | | | |
|---|---|---|---|---|
| | S 1/4 of | | 11th | st |
| EL | | | 7,0 | 106.3 |
| bb | | | 7,1 | 106.2 |
| y | | | 6,8 | 106.5 |
| b | | | 6,3 | 107.0 |
| y | | | 5,3 | 108.0 |
| bb | | | 4,3 | 109.0 |
| WL | | | 3,2 | 110.1 |
| | center of | | 11th | st |
| WL | | | 4,9 | 108.4 |
| bb | | | 5,8 | 107.5 |
| y | | | 6,6 | 106.7 |
| b | | | 7,3 | 106.0 |
| y | | | 8,0 | 105.3 |
| bb | | | 8,4 | 104.9 |
| EL | | | 8,7 | 104.6 |

POSTED

| | | 11331 | | |
|---|---|---|---|---|
| | N 1/4 of | | 11th | st |
| EL | | | 10,0 | 103.3 |
| bh | | | 9,8 | 103.5 |
| y | | | 9,6 | 103.7 |
| b | | | 9,4 | 103.9 |
| y | | | 8,7 | 104.6 |
| bh | | | 7,6 | 105.7 |
| WL | | | 6,9 | 106.4 |
| | N bb of | | 11th | st |
| WL | | | 8,0 | 105.3 |
| bh | | | 8,7 | 104.6 |
| y | | | 9,6 | 103.7 |
| b | | | 10,6 | 102.7 |
| y | | | 11,2 | 102.1 |
| bh | | | 11,4 | 101.9 |
| EL | | | 11,7 | 101.6 |

| | | 11331 | | Plum st |
|---|---|---|---|---|
| | N Line of | | 11th | st |
| EL | | | 13,1 | 100.2 |
| bh | | | 12,7 | 100.6 |
| y | | | 11,9 | 101.4 |
| b | | | 11,1 | 102.2 |
| y | | | 10,6 | 102.7 |
| bh | | | 9,9 | 103.4 |
| WL | | | 9,3 | 104.0 |
| TP | 1.07 | 105.08 | 9,30 | 104.01 |
| | 50' | n of | 11th | st |
| WL | | | 2,7 | 102.4 |
| bh | | | 3,5 | 101.6 |
| y | | | 4,6 | 100.5 |
| b | | | 5,7 | 99.4 |
| y | | | 6,9 | 98.2 |
| bh | | | 8,0 | 97.1 |
| EL | | | 8,5 | 96.6 |

POSTED

105.08

| | 100' | n of | Inst | St |
|---|---|---|---|---|
| ER | | | 9.7 | 95.4 |
| bb | | | 8.4 | 96.7 |
| ff | | | 7.3 | 97.8 |
| b | | | 6.4 | 98.7 |
| y | | | 5.6 | 99.5 |
| bl | | | 5.0 | 100.1 |
| WR | | | 4.6 | 100.5 |
| | 150' | n of | Inst | St |
| WR | | | 9.0 | 96.1 |
| bl | | | 9.8 | 95.3 |
| y | | | 10.4 | 94.7 |
| b | | | 10.9 | 94.2 |
| y | | | 11.7 | 93.4 |
| bl | | | 12.5 | 92.6 |
| ER | | | 13.2 | 91.9 |
| TP | 3.16 | 95.59 | 12.65 | 92.43 |

95.59

Plum St

| | 200 | n = | SR | Inst | St (70') |
|---|---|---|---|---|---|
| ER | | | 9.0 | 86.6 | |
| bl | | | 7.9 | 87.7 | |
| y | | | 6.9 | 88.7 | |
| b | | | 5.5 | 90.1 | |
| y | | | 4.4 | 91.2 | |
| bl | | | 3.4 | 92.2 | |
| WR | 155 | 93.38 | 3.52 | 92.03 | BM n w H Inst |
| | Sbb | of | Inst | n | |
| WR | | | 2.4 | 91.2 | |
| bl | | | 3.4 | 90.2 | |
| y | | | 4.2 | 89.4 | |
| b | | | 4.9 | 88.7 | |
| y | | | 5.8 | 87.8 | |
| bl | | | 7.0 | 86.6 | |
| ER | | | 7.6 | 86.0 | |

9358

| | S ¼ of | 12th | st |
|---|---|---|---|
| E2 | | 8.6 | 85.0 |
| bk | | 8.8 | 84.8 |
| 4 | | 7.1 | 86.5 |
| 6 | | 6.3 | 87.3 |
| 4 | | 5.0 | 88.6 |
| bk | | 3.8 | 89.8 |
| W2 | | 3.0 | 90.6 |
| | Center of | 12th | st |
| W2 | | 3.8 | 89.8 |
| bk | | 4.5 | 89.1 |
| 4 | | 5.4 | 88.2 |
| 6 | | 6.5 | 87.1 |
| 4 | | 7.3 | 86.3 |
| bk | | 8.6 | 85.0 |
| E2 | | 9.6 | 84.0 |

9358 Plum st

| | N ¼ of | 12th | st |
|---|---|---|---|
| E2 | | 9.7 | 83.9 |
| bk | | 8.9 | 84.7 |
| 4 | | 7.8 | 85.8 |
| 6 | | 6.8 | 86.8 |
| 4 | | 5.6 | 88.0 |
| bk | | 4.8 | 88.8 |
| W2 | | 4.2 | 89.4 |
| | N bk of | 12th | st |
| W2 | | 4.8 | 88.8 |
| bk | | 5.5 | 88.1 |
| 4 | | 6.2 | 87.4 |
| 6 | | 7.2 | 86.4 |
| 4 | | 8.5 | 85.1 |
| bk | | 9.7 | 83.9 |
| E2 | | 10.1 | 83.5 |

93.58

| | | | | |
|---|---|---|---|---|
| | N Line of | | 12th st | |
| El | | | 10,4 | 83.2 |
| bh | | | 9,6 | 84.0 |
| y | | | 8,4 | 85.2 |
| b | | | 7,4 | 86.2 |
| y | | | 6,7 | 86.9 |
| bh | | | 6,1 | 87.5 |
| wh | | | 5,3 | 88.3 |
| | 50' | n of | 12th st | |
| wh | | | 6,7 | 86.9 |
| bh | | | 7,5 | 86.1 |
| y | | | 8,6 | 85.0 |
| b | | | 9,6 | 84.0 |
| y | | | 10,5 | 83.1 |
| bh | | | 11,3 | 82.3 |
| El | | | 12,0 | 81.6 |

93.58 Plum st

| | | | | |
|---|---|---|---|---|
| | 100' | n of | 12th st | |
| El | | | 10,1 | 83.5 |
| bh | | | 9,7 | 83.9 |
| y | | | 9,7 | 83.9 |
| b | | | 8,8 | 84.8 |
| y | | | 7,9 | 85.7 |
| bh | | | 7,1 | 86.5 |
| wh | | | 6,3 | 87.3 |
| | 150' | n of | 12th st | |
| wh | | | 3,3 | 90.3 |
| bh | | | 3,8 | 89.8 |
| y | | | 4,0 | 89.6 |
| b | | | 4,7 | 88.9 |
| y | | | 5,0 | 88.6 |
| bh | | | 5,8 | 87.8 |
| El | | | 6,0 | 87.6 |
| TP | 1074 | 10331 | 101 | 92.57 |

10.31

200' n = S line of 13th st (70')

| | | |
|---|---|---|
| E2 | 10.4 | 92.9 |
| ll | 10.2 | 93.1 |
| y | 10.3 | 93.0 |
| b | 10.0 | 93.3 |
| y | 9.6 | 93.7 |
| bl | 9.5 | 93.8 |
| W2 | 9.1 | 94.2 |

S bl of 13th st

| | | |
|---|---|---|
| W2 | 8.1 | 95.2 |
| ll | 8.5 | 94.8 |
| y | 9.3 | 94.0 |
| b | 8.9 | 94.4 |
| y | 8.9 | 94.4 |
| bl | 8.9 | 94.4 |
| E2 | 9.0 | 94.3 |

10.31

Plum st

41

S 1/4 of 13th st

| | | |
|---|---|---|
| E2 | 7.4 | 95.9 |
| bl | 7.5 | 95.8 |
| y | 7.4 | 95.9 |
| b | 7.3 | 96.0 |
| y | 7.5 | 95.8 |
| bl | 7.7 | 95.6 |
| W2 | 7.8 | 95.5 |

Center of 13th st

| | | |
|---|---|---|
| W2 | 6.5 | 96.8 |
| bl | 6.4 | 96.9 |
| y | 6.3 | 97.0 |
| b | 6.1 | 97.2 |
| y | 5.8 | 97.5 |
| bl | 5.7 | 97.6 |
| E2 | 5.8 | 97.5 |

10331

| | n 1/4 of | 13 th | st |
|---|---|---|---|
| E2 | | 4.5 | 98.8 |
| bh | | 4.5 | 98.8 |
| y | | 4.5 | 98.8 |
| b | | 4.6 | 98.7 |
| y | | 5.2 | 98.1 |
| bh | | 5.6 | 97.7 |
| W2 | | 5.6 | 97.7 |
| | 2 bt of | 13 th | st |
| W2 | | 4.7 | 98.6 |
| bh | | 4.6 | 98.7 |
| y | | 4.0 | 99.3 |
| b | | 3.5 | 99.8 |
| y | | 3.4 | 99.9 |
| bl | | 3.5 | 99.8 |
| E2 | | 3.7 | 99.6 |

10331 Plum st

| | n 2nd of | 13 th | st |
|---|---|---|---|
| E2 | | 3.6 | 99.7 |
| bh | | 3.4 | 99.9 |
| y | | 3.1 | 100.2 |
| b | | 3.0 | 100.3 |
| y | | 3.2 | 100.1 |
| bl | | 3.7 | 99.6 |
| W2 | | 4.0 | 99.3 |
| TP | 210 | 10178 | 3.63 | 99.68 | Bm n E th 13 th |
| | 25' | n b | 13 th | st |
| E2 | | 3.6 | 98.2 |
| bh | | 3.3 | 98.5 |
| y | | 3.0 | 98.8 |
| b | | 2.2 | 99.5 |
| y | | 1.8 | 100.0 |
| bl | | 1.8 | 100.0 |
| W2 | | 1.7 | 100.1 |

| | | 101.78 | | | |
|---|---|---|---|---|---|
| | 50' | n of | 13 | th st | |
| WL | | | 3,2 | 98.6 | |
| bl | | | 3,8 | 98.0 | |
| y | | | 4,2 | 97.6 | |
| b | | | 4,6 | 97.2 | |
| y | | | 5,4 | 96.4 | |
| bl | | | 6,0 | 95.8 | |
| EL | | | 6,6 | 95.2 | |
| | 75' | n of | 13th | st | |
| EL | | | 9,0 | 92.8 | |
| bl | | | 8,3 | 93.5 | |
| y | | | 7,8 | 94.0 | |
| b | | | 7,0 | 94.8 | |
| y | | | 6,8 | 95.0 | |
| bl | | | 5,9 | 95.9 | |
| WL | | | 5,3 | 96.5 | |

| | | 101.78 | | Plum st | |
|---|---|---|---|---|---|
| | 100' | n of | 13th | st | |
| WL | | | 6,3 | 95.5 | |
| bl | | | 7,4 | 94.4 | |
| y | | | 8,6 | 93.2 | |
| b | | | 9,6 | 92.2 | |
| y | | | 10,4 | 91.4 | |
| bl | | | 11,8 | 90.0 | |
| EL | | | 12,3 | 89.5 | |
| | 125' | n of | 13th | st | |
| EL | | | 15,9 | 85.9 | |
| bl | | | 14,8 | 87.0 | |
| y | | | 13,2 | 88.6 | |
| b | | | 12,1 | 89.7 | |
| y | | | 10,5 | 91.3 | |
| bl | | | 7,2 | 92.6 | |
| WL | | | 7,7 | 94.1 | |

POSTED

| | | | | |
|---|---|---|---|---|
| | 150' | n of | 12th | st |
| WL | | | 8,5 | 93.3 |
| bl | | | 9,7 | 92.1 |
| y | | | 11,1 | 90.7 |
| b | | | 12,6 | 89.2 |
| | 175' | n of | 13th | st |
| WL | | | 9,8 | 92.0 |
| bl | | | 10,6 | 91.2 |
| y | | | 12,0 | 89.8 |
| TP | 2,1 | 91.49 | 12,40 | 89.38 |
| | 150' | n of | 13th | st |
| EL | | | 7,0 | 84.5 |
| bl | | | 5,9 | 85.6 |
| y | | | 3,8 | 87.7 |
| | 175' | n of | 13th | |
| EL | | | 8,2 | 83.3 |
| bl | | | 6,8 | 84.7 |
| y | | | 5,1 | 86.4 |
| b | | | 3,3 | 88.2 |

91.49

Plum st

| | | | | |
|---|---|---|---|---|
| | 200' | n = | S L of | 14th st (70') |
| WL | | | 0,4 | 91.1 |
| bl | | | 1,6 | 89.9 |
| y | | | 3,1 | 88.4 |
| b | | | 4,8 | 86.7 |
| y | | | 6,8 | 84.7 |
| bl | | | 8,8 | 82.7 |
| EL | | | 10,2 | 81.3 |
| | S blk | of | 14th | st |
| EL | | | 10,8 | 80.7 |
| bl | | | 9,0 | 82.5 |
| y | | | 7,2 | 84.3 |
| b | | | 5,8 | 85.7 |
| y | | | 4,0 | 87.5 |
| bl | | | 2,4 | 89.1 |
| WL | | | 1,0 | 90.5 |

| | | | | |
|---|---|---|---|---|
| | | 9149 | | |
| | S 1/4 of | | 14th | st |
| WL | | | 1,4 | 90.1 |
| bh | | | 2,8 | 88.7 |
| " | | | 4,9 | 86.6 |
| b | | | 6,5 | 85.0 |
| " | | | 8,6 | 82.9 |
| bh | | | 10,5 | 81.0 |
| EL | | | 12,5 | 79.0 |
| | center of | | 14th | st |
| EL | | | 14,6 | 76.9 |
| b | | | 12,4 | 79.1 |
| " | | | 10,6 | 80.9 |
| b | | | 8,0 | 83.5 |
| " | | | 6,2 | 85.3 |
| bh | | | 4,6 | 86.9 |
| WL | | | 3,1 | 88.4 |

| | | | | |
|---|---|---|---|---|
| | | 9149 | | Plum st |
| | N 1/4 of | | 14th | st |
| WL | | | 5,2 | 86.3 |
| | | | 6,0 | 85.5 |
| " | | | 7,5 | 84.0 |
| b | | | 9,5 | 82.0 |
| " | | | 11,6 | 79.9 |
| | N bb | of | 14th | |
| WL | | | 6,8 | 84.7 |
| bh | | | 7,8 | 83.7 |
| " | | | 9,3 | 82.2 |
| b | | | 11,0 | 80.5 |
| | N L | of | 14th | st |
| WL | | | 8,1 | 83.4 |
| bh | | | 9,3 | 82.2 |
| " | | | 11,0 | 80.5 |
| b | | | 12,3 | 79.2 |
| TP | 1,22 | 79.96 | 12,75 | 78,74 |

| | | | | |
|---|---|---|---|---|
| | | 79.96 | | |
| | N Line of | | 14th | st |
| EL | | | 10,0 | 70.0 |
| bb | | | 7,4 | 72.6 |
| y | | | 4,2 | 75.8 |
| | N bbl of | | 14th | st |
| EL | | | 7,7 | 72.3 |
| bb | | | 4,5 | 75.5 |
| y | | | 2,2 | 77.8 |
| | N 1/4 of | | 14th | st |
| EL | | | 5,2 | 74.8 |
| bb | | | 2,0 | 78.0 |
| | 25' | n of | 14th | st |
| EL | | | 14,4 | 65.6 |
| bb | | | 12,8 | 67.2 |
| y | | | 11,2 | 68.8 |
| b | | | 8,0 | 72.0 |
| y | | | 5,4 | 74.6 |
| bb | | | 2,5 | 77.5 |
| WL | | | 0,0 | 80.0 |

| | | | | |
|---|---|---|---|---|
| | | 79.96 | | Plum st |
| | 50' | n of | 14th | st |
| WL | | | 4,5 | 75.5 |
| bb | | | 7,1 | 72.9 |
| y | | | 10,2 | 69.8 |
| b | | | 12,2 | 67.8 |
| TP | 0,23 | 67.84 | 12,35 | 67.61 |
| y | | | 2,3 | 65.5 |
| bb | | | 6,1 | 61.7 |
| EL | | | 9,2 | 58.6 |
| | 60' | n of | = RR Rt of ry on E | |
| EL | | | 12,3 | 55.5 |
| bb | | | 10,0 | 57.8 |
| y | | | 7,0 | 60.8 |
| b | | | 3,7 | 64.1 |

| | | | | |
|---|---|---|---|---|
| | | 79.96 | | |
| | 75' | n of | 14th | st |
| WL | | | +1,0 | 81,0 |
| bh | | | 0,8 | 79.2 |
| y | | | 3,5 | 76.5 |
| b | | | 7,4 | 72.6 |
| y | | | 10,0 | 70.0 |
| +10 | RR bat | | 11,5 | 78.5 |
| | 100' | n of | 14th | st |
| WL | | | 2,8 | 77.2 |
| bh | | | 4,9 | 75.1 |
| y | | | 7,7 | 72.3 |
| +10 | RR bat | | 9,8 | 70.2 |
| | 120' | n of | 14th | st |
| WL | Top of RR bat on w | | 7,0 | 73.0 |
| TP | 0,30 | 55,69 | 12,45 | 55.39 |

| | | | | |
|---|---|---|---|---|
| | | 55.69 | | Plum st |
| | 75' | n of | 14th | st |
| Ebh | | | 1,8 | 53.9 |
| EL | Bottom RR bat | | 9,5 | 46.2 |
| | 100' | n of | 14th | st |
| EL | | | 8,4 | 47.3 |
| bh | | | 8,3 | 47.4 |
| y | | | 7,8 | 47.9 |
| +7' | | | 8,5 | 47.2 |
| b | | | 5,0 | 50.7 |
| | 120' | n of | 14th | st |
| EL | | | 9,3 | 46.4 |
| bh | | | 8,1 | 47.6 |
| y | | | 8,0 | 47.7 |
| b | | | 7,9 | 47.8 |
| y | | | 7,6 | 48.1 |
| bh | | | 8,0 | 47.7 |

POSTED

5-5-69

| | 150' | n of | 14th | st |
|---|---|---|---|---|
| WL | | | 6,8 | 48.9 |
| bl | | | 6,9 | 48.8 |
| y | | | 7,2 | 48.5 |
| b | | | 7,4 | 48.3 |
| y | | | 13,0 | 42.7 |
| +8 | | | 15,2 | 40.5 |
| bl | | | 16,2 | 39.5 |
| EL | | | 16,3 | 39.4 |
| | 170' | n of | 14th | st |
| EL | | | 13,0 | 42.7 |
| bl | | | 14,2 | 41.5 |
| y | | | 16,3 | 39.4 |
| b | | | 15,4 | 40.3 |
| y | | | 14,4 | 41.3 |
| bl | | | 10,6 | 45.1 |
| WL | | | 7,5 | 48.2 |

5-5-69 Plum st

F1

| | 200 | n = | SL | 15th | st (70') |
|---|---|---|---|---|---|
| WL | | | 15,4 | 40.3 | |
| bl | | | 15,3 | 40.4 | |
| y | | | 14,0 | 41.7 | |
| b | | | 12,1 | 43.6 | |
| y | | | 10,8 | 44.9 | |
| EL | | | 9,3 | 46.4 | |
| EL | | | 7,6 | 48.1 | |
| | 5 bl | of | 15th | st | |
| EL | | | 5,5 | 50.2 | |
| bl | | | 7,2 | 48.5 | |
| y | | | 8,5 | 46.9 | |
| b | | | 10,7 | 45.0 | |
| y | | | 12,4 | 43.3 | |
| bl | | | 14,1 | 41.6 | |
| WL | | | 15,4 | 40.3 | |

| | | | | |
|---|---|---|---|---|
| | | 5564 | | |
| | S 1/4 | of | 15th | st |
| WL | | | 13,0 | 42.7 |
| bh | | | 11.1 | 44.6 |
| " | | | 9,8 | 45.9 |
| b | | | 8,3 | 47.4 |
| " | | | 6,2 | 49.5 |
| bh | | | 3,8 | 51.9 |
| EL | | | 1,8 | 53.9 |
| | Center | of | 15th | st |
| EL | | | | 57,0 |
| bh | | | 0,0 | 55.7 |
| " | | | 3,2 | 52.5 |
| b | | | 5,0 | 50.7 |
| " | | | 7,0 | 48.7 |
| bh | | | 8,5 | 47.2 |
| WL | | | 10,0 | 45.7 |

| | | | | |
|---|---|---|---|---|
| | | 5569 | | Plum st |
| | N 1/4 | of | 15th | st |
| WL | | | 5,8 | 49.9 |
| bh | | | 4,2 | 51.5 |
| " | | | 2,2 | 53.5 |
| TP | 12,40 | 67.79 | 0,30 | 55.39 |
| b | | | 12,8 | 55.0 |
| " | | | 11,0 | 56.8 |
| bh | | | 8,2 | 59.6 |
| EL | | | 5,6 | 62.2 |
| | Center | of | 15th | st |
| EL | | | 10,8 | 67,0 |
| | N bh | of | 15th | st |
| EL | | | 1,4 | 66.4 |
| bh | | | 3,3 | 64.5 |
| " | | | 5,3 | 62.5 |
| b | | | 7,2 | 60.6 |
| " | | | 9,5 | 58.3 |
| bh | | | 11,0 | 56.8 |
| WL | | | 13,8 | 54.0 |

| | | | | |
|---|---|---|---|---|
| | | 67.79 | | |
| | N S of | | 15-st | st |
| WL | | | 10.5 | 57.3 |
| bb | | | 6.7 | 61.1 |
| y | | | 3.4 | 64.4 |
| b | | | 2.0 | 65.8 |
| y | | | 1.3 | 66.5 |
| TP | 12.75 | 80.27 | 0.27 | 67.52 |
| | N S of | | 15-st | st |
| EL | | | 8.4 | 71.9 |
| bb | | | 11.0 | 69.3 |
| | 25' | N of | 15-st | st |
| EL | | | 0.0 | 80.3 |
| bb | | | 2.4 | 77.9 |
| y | | | 3.6 | 76.7 |
| b | | | 4.7 | 75.6 |
| y | | | 6.8 | 73.5 |
| bb | | | 10.4 | 69.9 |
| WL | | | 13.8 | 66.5 |

| | | | | |
|---|---|---|---|---|
| | | 80.27 | | Plum st |
| | 50' | N of | 15-st | st |
| WL | | | 5.8 | 74.5 |
| bb | | | 2.8 | 77.5 |
| y | | | 0.0 | 80.3 |
| TP | 12.78 | 91.89 | 11.6 | 79.11 |
| b | | | 9.8 | 82.1 |
| y | | | 7.4 | 84.5 |
| bb | | | 4.6 | 87.3 |
| EL | | | 2.7 | 89.2 |
| | 75' | N of | 15-st | st |
| WL | | | 11.0 | 80.9 |
| bb | | | 9.6 | 82.3 |
| y | | | 6.3 | 85.6 |
| b | | | 3.4 | 88.5 |
| y | | | 1.4 | 90.5 |
| TP | 12.64 | 103.79 | 0.74 | 91.15 |
| bb | | | 11.2 | 92.6 |
| EL | | | 9.1 | 94.7 |

Rock

POSTED

10379

| | 100' | n of | 15-ft | st |
|---|---|---|---|---|
| EL | | | 4.0 | 99.8 |
| bl | | | 6.8 | 97.0 |
| y | | | 8.2 | 95.5 |
| b | | | 11.0 | 92.8 |
| y | | | 12.6 | 91.2 |
| bl | | | 13.0 | 88.8 |
| WL | | | 16.8 | 87.0 |
| | 125' | n of | 15-ft | st |
| WL | | | 11.5 | 92.0 |
| bl | | | 10.5 | 93.3 |
| y | | | 8.2 | 95.6 |
| b | | | 6.2 | 97.6 |
| y | | | 4.0 | 99.8 |
| bl | | | 1.7 | 102.4 |
| EL | | | 0.0 | 103.8 |

10379 Plum st

54

| | 150' | n of | 15-ft | st |
|---|---|---|---|---|
| WL | | | 8.4 | 95.4 |
| bl | | | 6.7 | 97.1 |
| y | | | 4.6 | 99.2 |
| b | | | 1.8 | 102.0 |
| TP | 1x54 | 114.99 | 1.34 | 10.45 |
| y | | | 10.3 | 93.5 |
| bl | | | 8.0 | 95.8 |
| EL | | | 5.4 | 109.6 |
| | 175' | n of | 51.5-ft | st |
| EL | | | 0.0 | 115.0 |
| bl | | | 5.8 | 100.0 |
| y | | | 6.6 | 97.2 |
| b | | | 9.5 | 104.5 |
| y | | | 11.0 | 92.8 |
| bl | | | 13.2 | 90.6 |
| WL | | | 15.2 | 99.6 |

| | | | | | |
|---|---|---|---|---|---|
| | | 114.99 | | | |
| | 200' n = | S ℄ of | 16th st (70') | | |
| WL | | | 11.58 | 103.41 | Bm S n 16th st |
| bh | | | 10.0 | 105.0 | |
| y | | | 7.5 | 107.5 | |
| b | | | 4.0 | 111.0 | |
| y | | | 1.5 | 113.5 | |
| bh | | | 0.0 | 115.0 | |
| | Sbb of | | 16th st | | |
| WL | | | 10.2 | 104.8 | |
| bh | | | 8.0 | 107.0 | |
| y | | | 5.6 | 109.4 | |
| b | | | 2.0 | 113.0 | |
| y | | | +0.4 | 115.4 | |
| | S 1/4 of | 16 th st | | | |
| WL | | | 7.5 | 107.5 | |
| bh | | | 5.5 | 109.5 | |
| y | | | 2.4 | 112.6 | |
| b | | | +0.5 | 115.5 | |

| | | | | | |
|---|---|---|---|---|---|
| | | 114.99 | | Plum st | |
| | Center of | | 16th st | | |
| WL | | | 5.1 | 109.9 | |
| bh | | | 2.4 | 112.6 | |
| y | | | +0.4 | 115.4 | |
| TP | 12.36 | 125.98 | 1.37 | 113.62 | |
| | 200' n = S ℄ of | | 16th st ? | | |
| EL | | | 4.5 | 121.5 | |
| | Sbb of | | 16th | | |
| EL | | | 1.0 | 125.0 | |
| bh | | | 4.1 | 121.9 | |
| | S 1/4 of | 16th | | | |
| EL | | | +3.00 | 129.0 | |
| bh | | | 2.0 | 124.0 | |
| y | | | 6.5 | 119.5 | |
| | N 1/9 of | | 16th | | |
| WL | | | 13.8 | 112.2 | |
| bh | | | 11.5 | 114.5 | |
| y | | | 8.3 | 117.7 | |
| ~~b~~ | | | ~~4.3~~ | | |

POSTED

| | | | | | |
|---|---|---|---|---|---|
| | | 125.98 | | | |
| | N bb of | | 16th | st | [illegible] |
| WL | | | 12,0 | 114.0 | |
| bh | | | 9,5 | 116.5 | |
| y | | | 5,5 | 120.5 | |
| ~~b~~ | | | ~~1,8~~ | | |
| | N L of | | 16th | st | |
| WL | | | 10,0 | 116.0 | |
| bh | | | 7,4 | 118.6 | |
| y | | | 3,8 | 122.2 | |
| b | | | 0,5 | 125.5 | |
| | 25' | N of | 16th | | |
| WL | | | 8,0 | 118.0 | |
| bh | | | 4,8 | 121.2 | |
| y | | | 1,5 | 124.5 | |
| TP | 12,82 | 138.46 | 0.34 | 125.64 | |

| | | | | | |
|---|---|---|---|---|---|
| | | 138.46 | | Plum st | |
| | Center of | | 16th | st | |
| EL | | | 6,3 | 132.2 | |
| bh | | | 9,8 | 128.7 | |
| y | | | 13,3 | 125.2 | |
| b | | | 16,4 | 122.1 | |
| | N 1/4 of | | 16th | st | |
| EL | | | 3,4 | 135.1 | |
| bh | | | 6,5 | 132.0 | |
| y | | | 10,0 | 128.5 | |
| b | | | 13,4 | 125.1 | |
| | N bb of | | 16th | | |
| EL | | | 2,0 | 136.5 | |
| bh | | | 5,1 | 133.4 | |
| y | | | 8,0 | 130.5 | |
| b | | | 12,6 | 125.9 | |
| | N L of | | 16th | st | |
| EL | | | 0,0 | 138,5 | |
| bh | | | 3,6 | 134.9 | |
| y | | | 7,0 | 131.5 | |

| | | | | |
|---|---|---|---|---|
| | | 13846 | | |
| TP | | | | |
| | 50' | n of | 16th | 2s |
| WR | | | 13,0 | 125.5 |
| bk | | | 10,0 | 128.5 |
| 4 | | | 5,0 | 133.5 |
| b | | | 0,0 | 138.5 |
| TP | 1246 | 15018 | 0.74 | 13772 |
| 4 | | | 8,0 | 142.2 |
| bk | | | 3,2 | 147.0 |
| ER | | | 0,0 | 150.2 |
| | 75' | n of | 16th | 2s |
| ER | | | 4,4 | 145.8 |
| bk | | | 7,2 | 143.0 |
| 4 | | | 10,2 | 140.0 |
| b | | | 13,0 | 135.2 |

| | | | | |
|---|---|---|---|---|
| | | 15018 | | Plum st |
| | 75' | n of | 16th | 2s |
| WR | | | 17,0 | 133.2 |
| bk | | | 14,0 | 136.2 |
| 4 | | | 11,5 | 138.7 |
| b | | | 6,7 | 143.5 |
| 4 | | | 3,8 | 156.4 |
| bk | | | 0,0 | 150.2 |
| | 100' | n of | 16th | 2s |
| WR | | | 8,4 | 140.8 |
| bk | | | 6,0 | 144.2 POSTED |
| 4 | | | 2,2 | 148.0 |
| b | | | 0,0 | 150.2 |
| TP | 1214 | 16226 | 0,06 | 15012 |
| 4 | | | 1,08 | 151.5 |
| bk | | | 8,9 | 153.4 |
| ER | | | 7,2 | 155.1 |
| | 75' | n of | 16th | |
| CR | | | 8,0 | 154.3 |

16226

| | 125' | n of | 16 ft | st |
|---|---|---|---|---|
| EL | | | 4,1 | 158.2 |
| bh | | | 6,7 | 155.6 |
| " | | | 8,8 | 153.5 |
| b | | | 10,3 | 152.0 |
| " | | | 11,6 | 150.7 |
| bh | | | 14,8 | 147.5 |
| WL | | | 17,0 | 145.3 |
| | 150' | n of | 16 ft | |
| WL | | | 13,4 | 148.9 |
| bh | | | 11,4 | 150.9 |
| " | | | 9,0 | 153.3 |
| b | | | 7,3 | 155.0 |
| " | | | 5,3 | 157.0 |
| bh | | | 2,8 | 159.5 |
| EL | | | 0,8 | 161.5 |

16226

| | 175' | n of | 16 ft | st | |
|---|---|---|---|---|---|
| EL | | | +0,6 | 162.8 | |
| bh | | | 0,8 | 161.5 | |
| " | | | 1,4 | 160.9 | |
| b | | | 2,3 | 160.0 | |
| " | | | 4,0 | 158.3 | |
| bh | | | 6,0 | 156.3 | |
| WL | | | 8,1 | 154.2 | |
| | 200' | n = | SL of | 17 ft | st (701) |
| WL | | | 5,44 | 156.82 | BM SW 17 ft |
| bh | | | 3,8 | 158.5 | |
| " | | | 2,3 | 160.0 | |
| b | | | 1,0 | 161.3 | |
| TP | 10,31 | 17156 | 1.01 | 16125 | |
| " | | | 9,4 | 162.2 | |
| bh | | | 7,0 | 164.6 | |
| EL | | | 6,7 | 164.9 | |

17156

S bk of 17th St

| | | |
|---|---|---|
| E2 | 6,3 | 165.3 |
| bk | 7,0 | 164.6 |
| y | 8,8 | 162.8 |
| b | 10,2 | 161.4 |
| y | 11,4 | 160.2 |
| bk | 12,7 | 158.9 |
| W2 | 13,8 | 157.8 |

S 1/4 of 17th St

| | | |
|---|---|---|
| W2 | 13,1 | 158.5 |
| bk | 12,5 | 159.1 |
| y | 11,0 | 160.6 |
| b | 9,6 | 162.0 |
| y | 8,2 | 163.4 |
| bk | 6,9 | 164.7 |
| E2 | 5,6 | 166.0 |

17156

Plum St

Center of 17th St

| | | |
|---|---|---|
| E2 | 4,8 | 166.8 |
| bk | 5,8 | 165.8 |
| y | 7,0 | 164.6 |
| b | 8,6 | 163.0 |
| y | 10,2 | 161.4 |
| bk | 11,5 | 160.1 |
| W2 | 12,0 | 159.6 |

N 1/4 of 17th St

| | | |
|---|---|---|
| W2 | 10,6 | 161.0 |
| bk | 10,4 | 161.2 |
| y | 8,9 | 162.7 |
| b | 7,5 | 164.1 |
| y | 6,2 | 165.4 |
| bk | 5,2 | 166.4 |
| E2 | 4,1 | 167.4 |

POSTED

| | | 171.56 | | |
|---|---|---|---|---|
| | n bb of | 17 ft | st | |
| Et | | 3,0 | 168.6 | |
| bb | | 4,0 | 167.6 | |
| y | | 5,4 | 166.2 | |
| b | | 6,4 | 165.2 | |
| y | | 7,5 | 164.1 | |
| bb | | 9,6 | 162.0 | |
| wh | | 10,0 | 161.6 | |
| | n line of | 17 ft | st | |
| wh | | 10,1 | 161.5 | |
| bb | | 8,8 | 162.8 | |
| y | | 6,5 | 165.1 | |
| b | | 5,4 | 166.2 | |
| y | | 5,2 | 166.4 | |
| bb | | 3,5 | 168.1 | |
| Et | | 2,3 | 169.3 | |

| | | 171.56 | | Plum st |
|---|---|---|---|---|
| | 25' | n of | 17 ft | st |
| Et | | | 0,0 | 171.6 |
| bb | | | 1,2 | 170.4 |
| y | | | 1,8 | 169.8 |
| b | | | 3,5 | 168.1 |
| y | | | 5,6 | 166.0 |
| bb | | | 7,3 | 164.3 |
| wh | | | 8,4 | 163.2 |
| | 50' | n of | 17 ft | st |
| wh | | | 6,3 | 165.3 |
| bb | | | 5,0 | 166.6 |
| y | | | 3,4 | 168.2 |
| b | | | 1,9 | 169.7 |
| y | | | 0,8 | 170.8 |
| TP | 9,28 | 180.51 | 0,33 | 171,23 |
| bb | | | 8,4 | 172.1 |
| Et | | | 7,4 | 173.1 |

| | | 1805 | | |
|---|---|---|---|---|
| | 75' | n. of | 17th | st |
| Eh | | | 5,5 | 175.0 |
| bh | | | 6,3 | 174.2 |
| y | | | 8,2 | 172.3 |
| b | | | 9,3 | 171.2 |
| y | | | 10,0 | 170.5 |
| bh | | | 11,1 | 169.4 |
| wh | | | 12,0 | 168.5 |
| | 100' | n of | 17th | st |
| wh | | | 10,3 | 170.2 |
| bh | | | 9,8 | 170.7 |
| y | | | 9,3 | 171.2 |
| b | | | 8,3 | 172.2 |
| y | | | 6,7 | 173.8 |
| bh | | | 5,5 | 175.0 |
| Eh | | | 4,8 | 175.7 |

| | | 1805 | | Plum st |
|---|---|---|---|---|
| | 125' | n of | 17th | st |
| Eh | | | 4,5 | 176.0 |
| bh | | | 4,8 | 175.7 |
| y | | | 5,6 | 174.9 |
| b | | | 6,4 | 174.1 |
| y | | | 7,0 | 173.5 |
| bh | | | 7,8 | 172.7 |
| wh | | | 9,2 | 171.3 |
| | 150 | n of | 17th | st |
| wh | | | 8,2 | 172.3 |
| bh | | | 7,1 | 173.4 |
| y | | | 6,1 | 174.4 |
| b | | | 5,5 | 175.0 |
| y | | | 4,8 | 175.7 |
| bh | | | 4,6 | 175.9 |
| Eh | | | 4,9 | 175.6 |

POSTED

| | | | | | |
|---|---|---|---|---|---|
| | | 180,51 | | | |
| | 175' | n of | 17th st | | |
| Et | | | 6,5 | 174.0 | |
| bh | | | 6,5 | 174.0 | |
| y | | | 5,7 | 174.8 | |
| b | | | 5,6 | 174.9 | |
| y | | | 6,0 | 174.5 | |
| bh | | | 6,6 | 173.9 | |
| Wt | | | 7,0 | 173.5 | |
| | 200' | n = | S ℄ | 18th (70') | Bm SW 18th |
| Wt | | | 6,41 | 174.0 | |
| bh | | | 6,6 | 173.9 | |
| y | | | 7,0 | 173.5 | |
| b | | | 7,0 | 173.5 | |
| y | | | 6,7 | 173.8 | |
| bh | | | 6,7 | 173.8 | |
| Et | | | 7,0 | 173.5 | |

| | | | | | |
|---|---|---|---|---|---|
| | | 180,57 | | Plum st | |
| | Sbb of | | 18th | st | |
| Et | | | 7,5 | 173.0 | |
| bh | | | 7,2 | 173.3 | |
| y | | | 7,3 | 173.2 | |
| b | | | 7,5 | 173.0 | |
| y | | | 7,7 | 172.8 | |
| bh | | | 7,4 | 173.1 | |
| Wt | | | 7,0 | 173.5 | |
| | S 1/4 | of | 18th | st | |
| Wt | | | 6,9 | 173.6 | |
| bh | | | 7,7 | 172.8 | |
| y | | | 8,1 | 172.4 | |
| b | | | 8,3 | 172.2 | |
| b | | | 8,5 | 172.0 | |
| bh | | | 8,7 | 171.8 | |
| Et | | | 8,8 | 171.7 | |

18051

| | | | | |
|---|---|---|---|---|
| | Center of | 18th | st | |
| EL | | 8,8 | 171.7 | |
| bb | | 8,6 | 171.9 | |
| y | | 8,7 | 171.8 | |
| b | | 8,5 | 172.0 | |
| y | | 8,3 | 172.2 | |
| bb | | 8,0 | 172.5 | |
| WL | | 7,3 | 173.2 | |
| | N 1/4 of | 18th | st | |
| WL | | 8,2 | 172.3 | |
| bb | | 8,5 | 172.0 | |
| y | | 8,4 | 172.1 | |
| b | | 8,6 | 171.9 | |
| y | | 8,8 | 171.7 | |
| bb | | 8,8 | 171.7 | |
| EL | | 9,0 | 171.5 | |

18051 Plum st

| | | | | |
|---|---|---|---|---|
| | N bb of | 18th | st | |
| EL | | 9,0 | 171.5 | |
| bb | | 8,6 | 171.9 | |
| y | | 8,3 | 172.2 | |
| b | | 8,2 | 172.3 | |
| y | | 8,0 | 172.5 | |
| bb | | 8,0 | 172.5 | |
| WL | | 8,2 | 172.3 | |
| | N L of | 18th | st | |
| WL | | 7,20 | 173.3 | |
| bb | | 6,8 | 173.7 | |
| y | | 6,7 | 173.8 | |
| b | | 7,3 | 173.2 | |
| y | | 7,6 | 172.9 | |
| bb | | 8,3 | 172.2 | |
| EL | | 8,9 | 171.6 | |
| TP | | | | |

HWL

POSTED

1805

| | 25' | n of | 18 st | |
|---|---|---|---|---|
| EL | | | 8,6 | 171.9 |
| bl | | | 7,7 | 172.8 |
| y | | | 7,0 | 173.5 |
| b | | | 6,8 | 173.7 |
| y | | | 6,3 | 174.2 |
| bl | | | 6,0 | 174.5 |
| WL | | | 6,2 | 174.2 |
| TP | +93 | 1777.6 | 5,68 | 174,83 |

| | 50' | n of | 18 st | |
|---|---|---|---|---|
| WL | | | 4,2 | 173.6 |
| bl | | | 4,1 | 173.7 |
| y | | | 4,0 | 173.8 |
| b | | | 3,9 | 173.9 |
| y | | | 4,0 | 173.8 |
| bl | | | 5,1 | 172.7 |
| EL | | | 6,5 | 171.6 |

1777.76 Plum st

| | 75' | n of | 18 st | |
|---|---|---|---|---|
| EL | | | 7,2 | 170.5 |
| bl | | | 6,6 | 171.2 |
| y | | | 7,0 | 170.8 |
| b | | | 5,5 | 172.3 |
| y | | | 5,0 | 172.8 |
| bl | | | 5,0 | 172.8 |
| WL | | | 5,2 | 172.6 |

| | 100' | n of | 18 st | |
|---|---|---|---|---|
| WL | | | 7,6 | 170.2 |
| bl | | | 7,6 | 170.2 |
| y | | | 7,7 | 170.1 |
| b | | | 7,9 | 169.9 |
| y | | | 8,5 | 169.3 |
| bl | | | 9,1 | 168.7 |
| EL | | | 9,8 | 168.0 |

| | | | | |
|---|---|---|---|---|
| | | 17776 | | |
| | 125' | n of | 18th | st |
| EL | | | 11.0 | 166.8 |
| bl | | | 10.7 | 167.1 |
| y | | | 10.2 | 167.6 |
| b | | | 9.8 | 168.0 |
| y | | | 9.6 | 168.2 |
| bl | | | 9.0 | 168.8 |
| WL | | | 8.7 | 169.1 |
| | 150' | n of | 18th | st |
| WL | | | 10.2 | 167.6 |
| bl | | | 10.5 | 167.3 |
| y | | | 10.7 | 167.1 |
| b | | | 10.7 | 167.1 |
| y | | | 11.2 | 166.6 |
| bl | | | 11.2 | 166.6 |
| EL | | | 11.8 | 166.0 |

| | | | | | |
|---|---|---|---|---|---|
| | | 17776 | | Plum st | |
| | 175' | n of | 18th | st | 65 |
| EL | | | 14.3 | 163.5 | |
| bl | | | 13.8 | 164.0 | |
| y | | | 13.4 | 164.4 | |
| b | | | 13.0 | 164.8 | |
| y | | | 12.7 | 165.1 | |
| bl | | | 12.5 | 165.3 | |
| WL | | | 12.2 | 165.6 | |
| TP | 444 | 16260 | 12.60 | 165.16 | BM SW 19th |
| | 200' | n of | S S of | 19th | st (70') |
| WL | | | 4.4 | 165.2 | |
| bl | | | 5.4 | 164.2 | |
| y | | | 6.4 | 163.2 | |
| b | | | 6.9 | 162.7 | |
| y | | | 7.4 | 162.2 | |
| bl | | | 7.6 | 162.0 | |
| EL | | | 7.6 | 162.0 | |

POSTED

| | | | | |
|---|---|---|---|---|
| | | 16960 | | |
| | Slab | of | 19th | st |
| EL | | | 7,7 | 161.9 |
| bh | | | 7,7 | 161.9 |
| y | | | 7,5 | 162.1 |
| b | | | 7,3 | 162.3 |
| y | | | 7,2 | 162.4 |
| bh | | | 6,5 | 163.1 |
| WL | | | 5,7 | 163.9 |
| | S 1/4 | of | 19th | st |
| WL | | | 6,7 | 162.9 |
| bh | | | 7,1 | 162.5 |
| y | | | 7,4 | 162.2 |
| b | | | 7,5 | 162.1 |
| y | | | 7,8 | 161.8 |
| bh | | | 8,2 | 161.4 |
| EL | | | 8,3 | 161.3 |

| | | | | |
|---|---|---|---|---|
| | | 16960 | | Plum st |
| | Center | of | 19th | st |
| EL | | | 8,5 | 161.1 |
| bh | | | 8,4 | 161.2 |
| y | | | 7,6 | 162.0 |
| b | | | 7,4 | 162.2 |
| y | | | 7,4 | 162.2 |
| bh | | | 7,0 | 162.6 |
| WL | | | 6,7 | 162.9 |
| | N 1/4 | of | 19th | st |
| WL | | | 6,0 | 163.6 |
| bh | | | 6,6 | 163.0 |
| y | | | 7,3 | 162.3 |
| b | | | 7,5 | 162.1 |
| y | | | 7,6 | 162.0 |
| bh | | | 8,4 | 161.2 |
| EL | | | 8,6 | 161.0 |

| | | | | |
|---|---|---|---|---|
| | | 169.60 | | |
| | N bb | of | 19th | st |
| EL | | | 8,3 | 161.3 |
| bh | | | 8,2 | 161.4 |
| y | | | 8,1 | 161.5 |
| b | | | 7,9 | 161.7 |
| y | | | 7,6 | 162.0 |
| bh | | | 7,0 | 162.6 |
| WL | | | 6,3 | 163.3 |
| | N Line | of | 19th | st |
| WL | | | 7,2 | 162.4 |
| bh | | | 7,4 | 162.2 |
| y | | | 7,8 | 161.8 |
| b | | | 7,9 | 161.7 |
| y | | | 8,1 | 161.5 |
| bh | | | 8,2 | 161.4 |
| EL | | | 8,2 | 161.4 |

| | | | | |
|---|---|---|---|---|
| | | 169.60 | | Plum st |
| | 25' | n of | 19th | st |
| EL | | | 6,0 | 163.6 |
| bh | | | 6,2 | 163.4 |
| y | | | 7,0 | 162.6 |
| b | | | 7,7 | 161.9 |
| y | | | 7,8 | 161.8 |
| bh | | | 7,6 | 162.0 |
| WL | | | 7,4 | 162.2 |
| | 50' | n of | 19th | st |
| WL | | | 6,7 | 162.9 |
| bh | | | 6,1 | 163.5 |
| y | | | 6,2 | 163.4 |
| b | | | 7,0 | 162.6 |
| y | | | 7,0 | 162.6 |
| bh | | | 6,6 | 163.0 |
| EL | | | 6,6 | 163.0 |

POSTED

16960

| | 75' | n of | 19 ft | |
|---|---|---|---|---|
| EL | | | 4,8 | 164.8 |
| bk | | | 4,6 | 165.0 |
| ↓ | | | 4,3 | 165.3 |
| b | | | 5,2 | 164.0 |
| ↓ | | | 5,4 | 164.2 |
| bk | | | 5,0 | 164.6 |
| WL | | | 5,2 | 164.4 |
| | 100' | n of | 19 ft | |
| WL | | | 5,2 | 164.4 |
| bk | | | 4,8 | 164.8 |
| ↓ | | | 4,7 | 164.9 |
| b | | | 4,4 | 165.2 |
| ↓ | | | 4,0 | 165.6 |
| bk | | | 3,4 | 166.2 |
| EL | | | 3,1 | 166.5 |

16960 Plum st

| | 125' | n of | 19 ft | |
|---|---|---|---|---|
| EL | | | 1,20 | 168.4 |
| bk | | | 1,0 | 168.6 |
| ↓ | | | 1,5 | 168.1 |
| b | | | 3,0 | 166.6 |
| ↓ | | | 3,7 | 165.9 |
| bk | | | 3,7 | 165.9 |
| WL | | | 3,9 | 165.7 |
| TP | 1037 | 18792 | 2,05 | 167.55 |
| | 130' | n of | 19 ft | |
| WL | | | 1,04 | 167.5 |
| bk | | | 1,07 | 167.2 |
| ↓ | | | 1,03 | 167.6 |
| b | | | 1,01 | 167.8 |
| ↓ | | | 9,7 | 168.2 |
| bk | | | 9,1 | 168.8 |
| EL | | | 9,0 | 168.9 |

177.92

| | 175' | n of | 19th | st |
|---|---|---|---|---|
| Eh | | | 8,3 | 169.6 |
| bh | | | 8,4 | 169.5 |
| y | | | 8,7 | 169.2 |
| b | | | 8,9 | 169.0 |
| y | | | 9,5 | 168.4 |
| bh | | | 10,3 | 167.6 |
| Wh | | | 10,4 | 167.5 |

| | 200 | n = S ⅓ of | 20th | (70) |
|---|---|---|---|---|
| Wh | | | 9,30 | 168.62 |
| bh | | | 8,9 | 169.0 |
| y | | | 8,4 | 169.5 |
| b | | | 8,5 | 169.4 |
| y | | | 8,2 | 169.7 |
| bh | | | 7,8 | 170.1 |
| Eh | | | 7,0 | 170.9 |

Bm Sh 20th

177.92 Plum st

69

| | Slb of | 20th | st |
|---|---|---|---|
| Eh | | 5,8 | 172.1 |
| bh | | 6,7 | 171.2 |
| y | | 7,8 | 170.1 |
| b | | 8,3 | 169.6 |
| y | | 8,2 | 169.7 |
| bh | | 8,4 | 169.5 |
| Wh | | 8,2 | 169.7 |

| | S ¼ of | 20th | st |
|---|---|---|---|
| Wh | | 7,6 | 170.3 |
| bh | | 8,3 | 169.6 |
| y | | 7,7 | 170.2 |
| b | | 7,8 | 170.1 |
| y | | 7,1 | 170.8 |
| bh | | 5,3 | 172.6 |
| Eh | | 4,8 | 173.1 |

POSTED

| | | 177.92 | | |
|---|---|---|---|---|
| | Center of | | 20th st | |
| Et | | | 4,8 | 173.1 |
| bh | | | 5,3 | 172.6 |
| y | | | 6,4 | 171.5 |
| b | | | 7,2 | 170.7 |
| y | | | 7,6 | 170.3 |
| bh | | | 8,0 | 169.9 |
| Wh | | | 8,0 | 169.9 |
| | N 1/4 of | | 20th st | |
| Wh | | | 8,0 | 169.9 |
| bh | | | 7,2 | 170.7 |
| y | | | 6,5 | 171.4 |
| b | | | 5,4 | 172.5 |
| y | | | 4,5 | 173.4 |
| bh | | | 4,4 | 173.5 |
| Et | | | 3,8 | 174.1 |

| | | 177.92 | | Plum st |
|---|---|---|---|---|
| | N bk of | | 20th st | |
| Et | | | 2,9 | 175.0 |
| bh | | | 3,5 | 174.4 |
| y | | | 3,9 | 174.0 |
| b | | | 4,6 | 173.3 |
| y | | | 5,0 | 172.9 |
| bh | | | 6,0 | 171.9 |
| Wh | | | 6,8 | 171.1 |
| | N line of | | 20th st | |
| Wh | | | 5,7 | 172.2 |
| bh | | | 5,6 | 172.3 |
| y | | | 5,0 | 172.9 |
| b | | | 4,2 | 173.7 |
| y | | | 3,3 | 174.6 |
| bh | | | 2,6 | 175.3 |
| Et | | | 1,4 | 176.5 |
| TP | 11,70 | 188.84 | 0.78 | 177.14 |

| | | | | |
|---|---|---|---|---|
| | | 18884 | | |
| | 25' | n of | 20th | st |
| Ek | | | 9,2 | 179.6 |
| bh | | | 10,0 | 178.8 |
| y | | | 11,6 | 177.2 |
| b | | | 13,2 | 175.6 |
| y | | | 13,6 | 175.2 |
| bh | | | 14,0 | 174.8 |
| Wh | | | 14,4 | 174.4 |
| | 50' | n of | 20th | st |
| Wh | | | 13,2 | 175.6 |
| bh | | | 11,9 | 176.9 |
| y | | | 10,6 | 178.2 |
| b | | | 10,0 | 178.8 |
| y | | | 8,7 | 180.1 |
| bh | | | 6,8 | 182.0 |
| Ek | | | 4,9 | 183.9 |

| | | | | |
|---|---|---|---|---|
| | | 18884 | | Plum st |
| | 75' | n of | 20th | st |
| Ek | | | 0,0 | 188.8 |
| bh | | | 1,7 | 187.1 |
| y | | | 3,7 | 185.1 |
| b | | | 6,0 | 182.8 |
| y | | | 7,0 | 181.8 |
| bh | | | 9,0 | 179.8 |
| Wh | | | 10,7 | 178.1 |
| | 100' | n of | 20th | st |
| Wh | | | 7,7 | 181.1 |
| bh | | | 6,5 | 182.3 |
| y | | | 4,5 | 184.3 POSTED |
| b | | | 2,8 | 186.0 |
| y | | | 1,1 | 187.7 |
| TP | 857 | 19647 | 0,88 | 187.96 |
| bh | | | 8,3 | 188.2 |
| Ch | | | 7,0 | 189.5 |

19647

| | | | | |
|---|---|---|---|---|
| | 125' | n of | 20th | st |
| Eh | | | 4,8 | 191.7 |
| bh | | | 5,1 | 191.4 |
| y | | | 5,4 | 191.1 |
| b | | | 6,7 | 189.8 |
| y | | | 7,9 | 188.6 |
| bh | | | 9,9 | 186.6 |
| Wh | | | 11,1 | 185.4 |
| | 150' | n of | 20th | st |
| Wh | | | 7,6 | 188.9 |
| bh | | | 6,6 | 189.9 |
| y | | | 5,5 | 191.0 |
| b | | | 4,7 | 191.8 |
| y | | | 3,1 | 193.4 |
| bh | | | 3,0 | 193.5 |
| Eh | | | 3,5 | 193.0 |

19647 Plum st

72

| | | | | |
|---|---|---|---|---|
| | 175' | n of | 20th | st |
| Eh | | | 3,0 | 193.5 |
| bh | | | 3,0 | 193.5 |
| y | | | 3,6 | 192.9 |
| b | | | 4,3 | 192.2 |
| y | | | 4,3 | 192.2 |
| bh | | | 4,3 | 192.2 |
| Wh | | | 5,3 | 191.2 |
| | 200' | n = | SS of | 21st (70') |
| Wh | | | 3,55 | 192.92 BMSW 21st |
| bh | | | 3,0 | 193.5 |
| y | | | 2,8 | 193.7 |
| b | | | 3,2 | 193.3 |
| y | | | 2,3 | 194.2 |
| bh | | | 1,5 | 195.0 |
| Eh | | | 1,7 | 194.8 |

| | 19647 | | | | | 19647 | | Plum st |
|---|---|---|---|---|---|---|---|---|
| | S bb of | | 21st | st | | Center of | 21st st | |
| EL | | | 2,3 | 194.2 | EL | | 1,6 | 194.9 |
| bh | | | 2,4 | 194.1 | bh | | 1,3 | 195.2 |
| " | | | 2,6 | 193.9 | " | | 2,5 | 194.0 |
| b | | | 3,2 | 193.3 | b | | 3,7 | 192.8 |
| " | | | 3,0 | 193.5 | " | | 3,7 | 192.8 |
| bh | | | 2,7 | 193.8 | bh | | 4,0 | 192.5 |
| WL | | | 3,1 | 193.4 | WL | | 4,1 | 192.4 |
| | S 1/4 of | | 21st | st | | N 1/4 of | 21st | |
| WL | | | 3,5 | 193.0 | WL | | 4,3 | 192.2 |
| bh | | | 3,0 | 193.5 | bh | | 4,2 | 192.3 |
| " | | | 3,6 | 192.9 | " | | 3,6 | 192.9 POSTED |
| b | | | 3,4 | 193.1 | b | | 4,0 | 192.5 |
| " | | | 2,3 | 194.2 | " | | 2,9 | 193.6 |
| bh | | | 2,1 | 194.4 | bh | | 1,8 | 194.7 |
| EL | | | 2,3 | 194.2 | EL | | 2,0 | 194.5 |

~~200.47~~
196.47

| | | | | |
|---|---|---|---|---|
| | N bb of | | 21st | st |
| EL | | | 3,7 | 192.8 |
| bh | | | 3,5 | 193.0 |
| y | | | 4,0 | 192.5 |
| b | | | 4,3 | 192.2 |
| y | | | 4,4 | 192.1 |
| bh | | | 4,3 | 192.2 |
| WL | | | 3,8 | 192.7 |
| | N Line of | | 21st | st |
| WL | | | 3,7 | 192.8 |
| bh | | | 3,6 | 192.9 |
| y | | | 4,7 | 191.8 |
| b | | | 4,5 | 192.0 |
| y | | | 4,4 | 192.1 |
| bh | | | 3,3 | 193.2 |
| EL | | | 3,2 | 193.3 |

~~200.47~~
196.47

Plum st

4

| | | | | |
|---|---|---|---|---|
| | 25' | N of | 21st | st |
| EL | | | 5,6 | 190.9 |
| bh | | | 5,8 | 190.7 |
| y | | | 5,1 | 191.4 |
| b | | | 4,4 | 192.1 |
| y | | | 4,7 | 191.8 |
| bh | | | 5,6 | 190.9 |
| WL | | | 6,2 | 190.3 |
| | 50' | N of | 21st | st |
| WL | | | 6,5 | 190.0 |
| bh | | | 6,9 | 189.6 |
| y | | | 6,9 | 189.6 |
| b | | | 6,6 | 189.9 |
| y | | | 7,1 | 189.4 |
| bh | | | 7,0 | 189.5 |
| EL | | | 6,5 | 188.0 |

1964?

| | | | | |
|---|---|---|---|---|
| | 75' | n of | 21st | st |
| EL | | | 8.0 | 188.5 |
| bk | | | 8.3 | 188.2 |
| y | | | 7.4 | 189.1 |
| L | | | 7.7 | 188.8 |
| y | | | 7.7 | 188.8 |
| bk | | | 7.0 | 189.5 |
| WL | | | 6.? | 190.3 |
| JP | 4.14 | 1936H | 6.97 | 189.50 |
| | 100' | n of | 21st | st |
| WL | | | 3.? | 190.4 |
| bk | | | 3.9 | 189.7 |
| y | | | 4.6 | 189.0 |
| L | | | 5.? | 188.3 |
| y | | | 6.1 | 187.5 |
| bk | | | 6.8 | 186.8 |
| EL | | | 7.3 | 186.3 |

1936?

Plum St

| | | | | |
|---|---|---|---|---|
| | 125' | n of | 21st | st |
| EL | | | 8.3 | 185.3 |
| bk | | | 7.3 | 186.3 |
| y | | | 6.8 | 186.8 |
| L | | | 6.7 | 187.2 |
| y | | | 5.4 | 188.2 |
| bk | | | 4.6 | 189.0 |
| WL | | | 3.4 | 190.2 |
| | 150' | n of | 21st | st |
| WL | | | 5.? | 188.4 |
| bk | | | 6.0 | 187.6 |
| y | | | 6.3 | 187.3 |
| L | | | 7.? | 186.4 |
| y | | | 8.1 | 185.5 |
| bk | | | 9.0 | 184.6 |
| EL | | | 9.4 | 184.2 |

POSTED

| | | | | | |
|---|---|---|---|---|---|
| | | 193.64 | | | |
| | 175' | n of | 21st | st | |
| EL | | | 11,0 | 182.6 | |
| bh | | | 10,0 | 183.6 | |
| y | | | 9,0 | 184.6 | |
| b | | | 8,5 | 185.1 | |
| y | | | 7,4 | 186.2 | |
| bh | | | 7,2 | 186.4 | |
| WL | | | 6,2 | 187.4 | |
| | 200' | n = | S L of | 22nd | (70') |
| WL | | | 8,8,0 | 184.84 | Bm SW 22nd |
| bh | | | 9,3 | 184.3 | |
| y | | | 9,8 | 183.8 | |
| b | | | 10,3 | 183.3 | |
| y | | | 10,9 | 182.7 | |
| bh | | | 11,9 | 181.7 | |
| EL | | | 12,7 | 180.9 | |
| | 2,65 | 187,49 | | 184.84 | Bm 22 |

| | | | | | |
|---|---|---|---|---|---|
| | | 187.49 | | Plum st | |
| | S bb of | | 22nd | st | |
| WL | | | 3,7 | 183.8 | |
| bh | | | 4,3 | 183.2 | |
| y | | | 4,3 | 183.2 | |
| b | | | 4,7 | 182.8 | |
| y | | | 5,2 | 182.3 | |
| bh | | | 5,2 | 182.3 | |
| EL | | | 7,2 | 180.3 | |
| | S 1/4 | of | 22nd | st | |
| EL | | | 7,9 | 179.6 | |
| bh | | | 7,3 | 180.2 | |
| y | | | 6,6 | 180.9 | |
| b | | | 6,0 | 181.5 | |
| y | | | 5,6 | 181.9 | |
| bh | | | 4,8 | 182.7 | |
| WL | | | 4,2 | 183.3 | |

POSTED

1879

Center of 22nd st

| | | |
|---|---|---|
| Wk | 4,7 | 182.8 |
| Mk | 4,8 | 182.7 |
| Y | 5,8 | 181.7 |
| C | 6,2 | 181.3 |
| Y | 7,7 | 179.8 |
| Bk | 8,2 | 179.3 |
| EL | 8,5 | 179.0 |

N 1/4 of 22nd st

| | | |
|---|---|---|
| EL | 9,2 | 178.3 |
| Bk | 9,0 | 178.5 |
| Y | 8,2 | 179.3 |
| C | 7,8 | 179.7 |
| Y | 6,4 | 181.1 |
| Bk | 5,8 | 181.7 |
| Wk | 6,1 | 181.4 |

1879 Plum st

N bk of 22nd st

| | | |
|---|---|---|
| Wk | 7,1 | 180.4 |
| Bk | 7,6 | 179.9 |
| Y | 8,1 | 179.4 |
| C | 8,8 | 178.7 |
| Y | 9,2 | 178.3 |
| Bk | 9,7 | 177.8 |
| EL | 9,8 | 177.7 |

N line of 22nd st

| | | |
|---|---|---|
| EL | 10,1 | 177.4 |
| Bk | 9,8 | 177.7 |
| Y | 9,4 | 178.1 |
| C | 9,0 | 178.5 |
| Y | 8,4 | 179.1 |
| Bk | 8,0 | 179.5 |
| Wk | 7,5 | 180.0 |

18749

| | | | | |
|---|---|---|---|---|
| | 50' | n of | 22 nd st | |
| WL | | | 7,6 | 179.9 |
| bb | | | 8,0 | 179.5 |
| y | | | 8,4 | 179.1 |
| b | | | 8,7 | 178.8 |
| y | | | 9,2 | 178.3 |
| bb | | | 10,0 | 177.5 |
| EL | | | 10,3 | 177.2 |
| | 100' | n of | 22 nd st | |
| EL | | | 10,4 | 177.1 |
| bb | | | 9,8 | 177.7 |
| y | | | 9,6 | 177.9 |
| b | | | 9,2 | 178.3 |
| y | | | 8,6 | 178.9 |
| bb | | | 8,1 | 179.4 |
| WL | | | 7,5 | 180.0 |

18749 Plum st

| | | | | | |
|---|---|---|---|---|---|
| | 130' | n of | 22 nd st | | |
| WL | | | 6,6 | 180.9 | |
| bb | | | 6,4 | 181.1 | |
| y | | | 7,5 | 180.0 | |
| b | | | 8,3 | 179.2 | |
| y | | | 9,2 | 178.3 | |
| bb | | | 9,5 | 178.0 | |
| EL | | | 9,5 | 178.0 | |
| | 200' | n = | S L | 23d st (70') | |
| EL | | | 8,8 | 178.7 | |
| bb | | | 8,1 | 179.4 | |
| y | | | 7,5 | 180.2 | |
| b | | | 6,6 | 180.9 | |
| y | | | 6,0 | 181.5 | |
| bb | | | 5,3 | 182.2 | |
| WL | 1,32 | 18400 | 4,81 | 18268 | BMSW 23d |

1846

Slab of 23d st

| | | |
|---|---|---|
| W2 | 0,7 | 183.3 |
| bk | 1,3 | 182.7 |
| y | 2,0 | 182.0 |
| b | 2,8 | 181.2 |
| y | 3,5 | 180.5 |
| bk | 4,4 | 179.6 |
| E2 | 5,0 | 179.0 |

S 1/4 of 23d st

| | | |
|---|---|---|
| E2 | 4,5 | 179.5 |
| bk | 4,0 | 180.0 |
| y | 3,2 | 180.8 |
| b | 2,4 | 181.6 |
| y | 1,6 | 182.4 |
| bk | 0,8 | 183.2 |
| W2 | 0,5 | 183.5 |

1846

Plan

73

Center of 23d st

| | | |
|---|---|---|
| W2 | 0,2 | 183.0 |
| bk | 0,7 | 183.3 |
| y | 1,2 | 182.8 |
| b | 2,2 | 181.8 |
| y | 3,1 | 180.9 |
| bk | 3,8 | 180.2 |
| E2 | 4,7 | 179.3 |

N 1/4 of 23d st

| | | |
|---|---|---|
| E2 | 5,0 | 179.0 |
| bk | 4,2 | 179.8 |
| y | 3,1 | 180.9 |
| b | 2,2 | 181.8 |
| y | 1,6 | 182.4 |
| bk | 1,0 | 183.0 |
| W2 | 0,2 | 183.8 |

1840

| | | | | |
|---|---|---|---|---|
| | n bk | of | 23 d | st |
| WL | | | 1,4 | 182.6 |
| bk | | | 1,6 | 182.4 |
| y | | | 2,3 | 181.7 |
| b | | | 2,9 | 181.1 |
| y | | | 3,7 | 180.3 |
| bk | | | 4,8 | 179.2 |
| EL | | | 5,4 | 178.6 |
| | n Line | of | 23 d | st |
| EL | | | 6,2 | 177.8 |
| bk | | | 5,5 | 178.5 |
| y | | | 4,5 | 179.5 |
| b | | | 3,8 | 180.2 |
| y | | | 3,2 | 180.8 |
| bk | | | 2,8 | 181.2 |
| WL | | | 2,6 | 181.4 |

1840 Plum st

| | | | | |
|---|---|---|---|---|
| | 25' | n of | 23 d | st |
| WL | | | 6,3 | 177.7 |
| bk | | | 6,6 | 177.4 |
| y | | | 7,0 | 177.0 |
| b | | | 7,5 | 176.5 |
| y | | | 8,0 | 176.0 |
| bk | | | 8,4 | 175.6 |
| EL | | | 8,4 | 175.6 |
| | 50' | n of | 23 d | st |
| EL | | | 10,7 | 173.3 |
| bk | | | 10,5 | 173.5 |
| y | | | 10,3 | 173.7 |
| b | | | 9,9 | 174.1 |
| y | | | 9,5 | 174.5 |
| bk | | | 9,2 | 174.8 |
| WL | | | 9,2 | 174.8 |

| | | | | |
|---|---|---|---|---|
| Clough Allan Wardi | Oct 6 08 | 184.00 | | |
| | 100' | n of | 22.0 | |
| WL | | | 9.8 | 174.2 |
| bl | | | 10.5 | 173.5 |
| y | | | 11.4 | 172.6 |
| b | | | 12.3 | 171.7 |
| bh | | | 12.3 | 171.7 |
| bh | | | 12.7 | 171.3 |
| EL | | | 12.2 | 171.8 |
| TP | | | 12.00 | 172.00 |

Plum st Continued in Book 420

Published by H. S. CROCKER COMPANY, Stationers, Drawing Materials, Mathematical Instruments, etc., San Francisco.

# TRAVERSE TABLE FOR TRANSIT BOOK.

## From 1° to 90° for a distance of 100.

| Degrees. | DEGREES. | | ¼ DEGREE. | | ½ DEGREE. | | ¾ DEGREE. | | Degrees. |
|---|---|---|---|---|---|---|---|---|---|
| | Lat. | Dep. | Lat. | Dep. | Lat. | Dep. | Lat. | Dep. | |
| 0 | | | 100.00 | 0.44 | 100.00 | 0.87 | 99.99 | 1.31 | 89 |
| 1 | 99.98 | 1.75 | 99.98 | 2.18 | 99.97 | 2.62 | 99.95 | 3.05 | 88 |
| 2 | 99.94 | 3.49 | 99.92 | 3.93 | 99.91 | 4.36 | 99.88 | 4.80 | 87 |
| 3 | 99.86 | 5.23 | 99.84 | 5.67 | 99.81 | 6.10 | 99.79 | 6.54 | 86 |
| 4 | 99.76 | 6.98 | 99.73 | 7.41 | 99.69 | 7.85 | 99.66 | 8.28 | 85 |
| 5 | 99.62 | 8.72 | 99.58 | 9.15 | 99.54 | 9.58 | 99.50 | 10.02 | 84 |
| 6 | 99.45 | 10.45 | 99.41 | 10.89 | 99.36 | 11.32 | 99.31 | 11.75 | 83 |
| 7 | 99.25 | 12.19 | 99.20 | 12.62 | 99.14 | 13.05 | 99.09 | 13.49 | 82 |
| 8 | 99.03 | 13.92 | 98.97 | 14.35 | 98.90 | 14.78 | 98.84 | 15.21 | 81 |
| 9 | 98.77 | 15.64 | 98.70 | 16.07 | 98.63 | 16.50 | 98.56 | 16.93 | 80 |
| 10 | 98.48 | 17.36 | 98.40 | 17.79 | 98.33 | 18.22 | 98.25 | 18.65 | 79 |
| 11 | 98.16 | 19.08 | 98.08 | 19.51 | 97.99 | 19.94 | 97.90 | 20.36 | 78 |
| 12 | 97.81 | 20.79 | 97.72 | 21.22 | 97.63 | 21.64 | 97.53 | 22.07 | 77 |
| 13 | 97.44 | 22.50 | 97.34 | 22.92 | 97.24 | 23.34 | 97.13 | 23.77 | 76 |
| 14 | 97.03 | 24.19 | 96.92 | 24.62 | 96.81 | 25.04 | 96.70 | 25.46 | 75 |
| 15 | 96.59 | 25.88 | 96.48 | 26.30 | 96.36 | 26.72 | 96.25 | 27.14 | 74 |
| 16 | 96.13 | 27.56 | 96.00 | 27.98 | 95.88 | 28.40 | 95.76 | 28.82 | 73 |
| 17 | 95.63 | 29.24 | 95.50 | 29.65 | 95.37 | 30.07 | 95.24 | 30.49 | 72 |
| 18 | 95.11 | 30.90 | 94.97 | 31.32 | 94.83 | 31.73 | 94.69 | 32.14 | 71 |
| 19 | 94.55 | 32.56 | 94.41 | 32.97 | 94.26 | 33.38 | 94.12 | 33.79 | 70 |
| 20 | 93.97 | 34.20 | 93.82 | 34.61 | 93.67 | 35.02 | 93.51 | 35.43 | 69 |
| 21 | 93.36 | 35.84 | 93.20 | 36.24 | 93.04 | 36.65 | 92.88 | 37.06 | 68 |
| 22 | 92.72 | 37.46 | 92.55 | 37.86 | 92.39 | 38.27 | 92.22 | 38.67 | 67 |
| 23 | 92.05 | 39.07 | 91.88 | 39.47 | 91.71 | 39.87 | 91.53 | 40.27 | 66 |
| 24 | 91.35 | 40.67 | 91.18 | 41.07 | 91.00 | 41.47 | 90.81 | 41.87 | 65 |
| 25 | 90.63 | 42.26 | 90.45 | 42.66 | 90.26 | 43.05 | 90.07 | 43.44 | 64 |
| 26 | 89.88 | 43.84 | 89.69 | 44.23 | 89.49 | 44.62 | 89.30 | 45.01 | 63 |
| 27 | 89.10 | 45.40 | 88.90 | 45.79 | 88.70 | 46.17 | 88.50 | 46.56 | 62 |
| 28 | 88.29 | 46.95 | 88.09 | 47.33 | 87.88 | 47.72 | 87.67 | 48.10 | 61 |
| 29 | 87.46 | 48.48 | 87.25 | 48.86 | 87.04 | 49.24 | 86.82 | 49.62 | 60 |
| 30 | 86.60 | 50.00 | 86.38 | 50.38 | 86.16 | 50.75 | 85.94 | 51.13 | 59 |
| 31 | 85.72 | 51.50 | 85.49 | 51.88 | 85.26 | 52.25 | 85.04 | 52.62 | 58 |
| 32 | 84.80 | 52.99 | 84.57 | 53.36 | 84.34 | 53.73 | 84.10 | 54.10 | 57 |
| 33 | 83.87 | 54.46 | 83.63 | 54.83 | 83.39 | 55.19 | 83.15 | 55.56 | 56 |
| 34 | 82.90 | 55.92 | 82.66 | 56.28 | 82.41 | 56.64 | 82.16 | 57.00 | 55 |
| 35 | 81.92 | 57.36 | 81.66 | 57.71 | 81.41 | 58.07 | 81.16 | 58.42 | 54 |
| 36 | 80.90 | 58.78 | 80.64 | 59.13 | 80.39 | 59.48 | 80.13 | 59.83 | 53 |
| 37 | 79.86 | 60.18 | 79.60 | 60.53 | 79.34 | 60.88 | 79.07 | 61.22 | 52 |
| 38 | 78.80 | 61.57 | 78.53 | 61.91 | 78.26 | 62.25 | 77.99 | 62.59 | 51 |
| 39 | 77.71 | 62.93 | 77.44 | 63.27 | 77.16 | 63.61 | 76.88 | 63.94 | 50 |
| 40 | 76.60 | 64.28 | 76.32 | 64.61 | 76.04 | 64.94 | 75.76 | 65.28 | 49 |
| 41 | 75.47 | 65.61 | 75.18 | 65.93 | 74.90 | 66.26 | 74.61 | 66.59 | 48 |
| 42 | 74.31 | 66.91 | 74.02 | 67.24 | 73.73 | 67.56 | 73.43 | 67.88 | 47 |
| 43 | 73.14 | 68.20 | 72.84 | 68.52 | 72.54 | 68.84 | 72.24 | 69.15 | 46 |
| 44 | 71.93 | 69.47 | 71.63 | 69.78 | 71.33 | 70.09 | 71.02 | 70.40 | 45 |
| 45 | 70.71 | 70.71 | | | | | | | |

| Degrees. | DEGREES | | ¾ DEGREE. | | ½ DEGREE. | | ¼ DEGREE. | | Degrees |
|---|---|---|---|---|---|---|---|---|---|
| | Dep. | Lat. | Dep. | Lat. | Dep. | Lat. | Dep. | Lat. | |