416
CONDUIT

380

FIELD

F.B. 416

## TRAVERSE TABLE FOR TRANSIT BOOK.

From 1° to 90° for a distance of 100.

| Degrees. | DEGREES. | | ¼ DEGREE. | | ½ DEGREE. | | ¾ DEGREE. | | Degrees. |
|---|---|---|---|---|---|---|---|---|---|
| | Lat. | Dep. | Lat. | Dep. | Lat. | Dep. | Lat. | Dep. | |
| 0 | | | 100.00 | 0.44 | 100.00 | 0.87 | 99.99 | 1.31 | 89 |
| 1 | 99.98 | 1.75 | 99.98 | 2.18 | 99.97 | 2.62 | 99.95 | 3.05 | 88 |
| 2 | 99.94 | 3.49 | 99.92 | 3.93 | 99.91 | 4.36 | 99.88 | 4.80 | 87 |
| 3 | 99.86 | 5.23 | 99.84 | 5.67 | 99.81 | 6.10 | 99.79 | 6.54 | 86 |
| 4 | 99.76 | 6.98 | 99.73 | 7.41 | 99.69 | 7.85 | 99.66 | 8.28 | 85 |
| 5 | 99.62 | 8.72 | 99.58 | 9.15 | 99.54 | 9.58 | 99.50 | 10.02 | 84 |
| 6 | 99.45 | 10.45 | 99.41 | 10.89 | 99.36 | 11.32 | 99.31 | 11.75 | 83 |
| 7 | 99.25 | 12.19 | 99.20 | 12.62 | 99.14 | 13.05 | 99.09 | 13.49 | 82 |
| 8 | 99.03 | 13.92 | 98.97 | 14.35 | 98.90 | 14.78 | 98.84 | 15.21 | 81 |
| 9 | 98.77 | 15.64 | 98.70 | 16.07 | 98.63 | 16.50 | 98.56 | 16.93 | 80 |
| 10 | 98.48 | 17.36 | 98.40 | 17.79 | 98.33 | 18.22 | 98.25 | 18.65 | 79 |
| 11 | 98.16 | 19.08 | 98.08 | 19.51 | 97.99 | 19.94 | 97.90 | 20.36 | 78 |
| 12 | 97.81 | 20.79 | 97.72 | 21.22 | 97.63 | 21.64 | 97.53 | 22.07 | 77 |
| 13 | 97.44 | 22.50 | 97.34 | 22.92 | 97.24 | 23.34 | 97.13 | 23.77 | 76 |
| 14 | 97.05 | 24.21 | 96.92 | 24.62 | 96.81 | 25.04 | 96.70 | 25.46 | 75 |
| 15 | 96.59 | 25.88 | 96.48 | 26.30 | 96.36 | 26.72 | 96.25 | 27.14 | 74 |
| 16 | 96.13 | 27.56 | 96.00 | 27.98 | 95.88 | 28.40 | 95.76 | 28.82 | 73 |
| 17 | 95.63 | 29.24 | 95.50 | 29.65 | 95.37 | 30.07 | 95.24 | 30.49 | 72 |
| 18 | 95.11 | 30.90 | 94.98 | 31.32 | 94.83 | 31.73 | 94.69 | 32.14 | 71 |
| 19 | 94.55 | 32.56 | 94.42 | 32.97 | 94.26 | 33.38 | 94.12 | 33.79 | 70 |
| 20 | 93.97 | 34.20 | 93.82 | 34.61 | 93.67 | 35.02 | 93.51 | 35.43 | 69 |
| 21 | 93.36 | 35.84 | 93.20 | 36.24 | 93.04 | 36.65 | 92.88 | 37.06 | 68 |
| 22 | 92.72 | 37.46 | 92.55 | 37.86 | 92.39 | 38.27 | 92.22 | 38.67 | 67 |
| 23 | 92.05 | 39.07 | 91.88 | 39.47 | 91.71 | 39.87 | 91.53 | 40.27 | 66 |
| 24 | 91.35 | 40.67 | 91.18 | 41.07 | 91.00 | 41.47 | 90.81 | 41.87 | 65 |
| 25 | 90.63 | 42.26 | 90.45 | 42.66 | 90.26 | 43.05 | 90.07 | 43.44 | 64 |
| 26 | 89.88 | 43.84 | 89.69 | 44.23 | 89.49 | 44.62 | 89.30 | 45.01 | 63 |
| 27 | 89.10 | 45.40 | 88.90 | 45.79 | 88.70 | 46.17 | 88.50 | 46.56 | 62 |
| 28 | 88.29 | 46.95 | 88.09 | 47.33 | 87.88 | 47.72 | 87.67 | 48.10 | 61 |
| 29 | 87.46 | 48.48 | 87.25 | 48.86 | 87.04 | 49.24 | 86.82 | 49.62 | 60 |
| 30 | 86.60 | 50.00 | 86.38 | 50.38 | 86.16 | 50.75 | 85.94 | 51.13 | 59 |
| 31 | 85.72 | 51.50 | 85.49 | 51.88 | 85.26 | 52.25 | 85.04 | 52.62 | 58 |
| 32 | 84.80 | 52.99 | 84.57 | 53.36 | 84.34 | 53.73 | 84.10 | 54.10 | 57 |
| 33 | 83.87 | 54.46 | 83.63 | 54.83 | 83.39 | 55.19 | 83.15 | 55.56 | 56 |
| 34 | 82.90 | 55.92 | 82.66 | 56.28 | 82.41 | 56.64 | 82.16 | 57.00 | 55 |
| 35 | 81.92 | 57.36 | 81.66 | 57.71 | 81.41 | 58.07 | 81.16 | 58.42 | 54 |
| 36 | 80.90 | 58.78 | 80.64 | 59.13 | 80.39 | 59.48 | 80.13 | 59.83 | 53 |
| 37 | 79.86 | 60.18 | 79.60 | 60.53 | 79.34 | 60.88 | 79.07 | 61.22 | 52 |
| 38 | 78.80 | 61.57 | 78.53 | 61.91 | 78.26 | 62.25 | 77.99 | 62.59 | 51 |
| 39 | 77.71 | 62.93 | 77.44 | 63.27 | 77.16 | 63.61 | 76.88 | 63.94 | 50 |
| 40 | 76.60 | 64.28 | 76.32 | 64.61 | 76.04 | 64.94 | 75.76 | 65.28 | 49 |
| 41 | 75.47 | 65.61 | 75.18 | 65.93 | 74.90 | 66.26 | 74.61 | 66.59 | 48 |
| 42 | 74.31 | 66.91 | 74.02 | 67.24 | 73.73 | 67.56 | 73.43 | 67.88 | 47 |
| 43 | 73.14 | 68.20 | 72.84 | 68.52 | 72.54 | 68.84 | 72.24 | 69.15 | 46 |
| 44 | 71.93 | 69.47 | 71.63 | 69.78 | 71.33 | 70.09 | 71.02 | 70.40 | 45 |
| 45 | 70.71 | 70.71 | | | | | | | |
| Degrees. | Dep. | Lat. | Dep. | Lat. | Dep. | Lat. | Dep. | Lat. | Degrees |
| | DEGREES | | ¾ DEGREE. | | ½ DEGREE. | | ¼ DEGREE. | | |

Published by H. S. Crocker Company, Stationers, Drawing Materials, Mathematical Instruments, etc., San Francisco.

MICROFILMED
DEC 01 1964

416

Return to City Engineers Office
City Hall, San Diego, Cal.

Crocker Quality

# FIELD BOOK

No._____

MANUFACTURED BY

H. S. CROCKER CO.

SAN FRANCISCO AND SACRAMENTO
CALIFORNIA

A10

Location of 30th St. drain pipe 8/21/08 { Davis, Donnan, Williams.

+17.85

7+34.83

0+00



25+51.83 - P.T. 28th St Conduit - Sta 1+53.52

24+52.36

+91.95 - 29th St drain.
18+36.40





Levels for 30th St drain pipe 8/31/07 Davis Dinnan Sam

| | | | | |
|---|---|---|---|---|
| | 5.74 | 79.72 | | 73.98 B.M. Spk. pole |
| 0 | | | 10.4 | 69.3 |
| 1 | | | 9.8 | 69.9 |
| 2 | | | 9.2 | 70.5 |
| 3 | | | 8.2 | 71.5 |
| 4 | | | 7.0 | 72.7 |
| 5 | | | 6.6 | 73.1 |
| 6 | | | 6.8 | 73.9 |
| 7 | | | 5.0 | 74.7 |
| +34.83 | Ctr M. St Track | | 4.6 | 75.1 |
| +60 | | | 5.2 | 74.5 |
| 8 | | | 4.5 | 75.2 |
| +75 | | | 4.1 | 75.6 |
| 9 | | | 4.9 | 74.8 |
| +50 | | | 6.5 | 73.2 |
| T.P. | 3.92 | 77.21 | 6.43 | 73.28 |
| 10 | | | 4.4 | 72.8 |
| 11 | | | 5.4 | 71.8 |
| +10 | | | 4.6 | 72.6 |
| +16.80 | Ctr S.D. | | 3.9 | 73.3 |
| +25 | | | 4.8 | 72.4 |
| +32.2 | Ctr C.B.L. | | 3.6 | 73.6 |
| +38 | | | 4.6 | 72.6 |
| △ +42.2 | | | 5.8 | 71.4 |
| +50 | | | 5.1 | 72.1 |

N.E. 30th and L Sts.

| | | | | |
|---|---|---|---|---|
| +70 | | | 5.4 | 71.8 |
| +74 | | | 6.2 | 71.0 |
| 12 | | | 5.8 | 71.4 |
| +8 | | | 5.0 | 72.2 |
| +16 | | | 5.1 | 72.1 |
| +25 | | | 5.8 | 71.4 |
| +65 | | | 4.7 | 72.5 |
| 13 | | | 4.3 | 72.9 |
| 14 | | | 6.2 | 71.0 |
| 15 | | | 6.8 | 70.4 |
| TP | 4.85 | 75.80 | 6.26 | 70.95 |
| +12 | | | 5.1 | 70.7 |
| +16 | | | 3.9 | 71.9 |
| +22 | | | 4.1 | 71.7 |
| +30 | | | 5.4 | 70.4 |
| 16 | | | 5.8 | 70.0 |
| 17 | | | 6.0 | 69.8 |
| +95 | | | 5.3 | 70.5 |
| 18 | | | 4.6 | 71.2 |
| +21 | | | 4.8 | 71.0 |
| +27 | | | 5.6 | 70.2 |
| 19 | | | 6.2 | 69.6 |
| 20 | | | 6.7 | 69.1 |
| 21 | | | 8.0 | 67.8 |

| | | | | |
|---|---|---|---|---|
| TR | 3.89 | 73.77 | 5.90 | 69.90 |
| 22 | | | 6.6 | 67.2 |
| 23 | | | 6.2 | 67.6 |
| +45 | | | 5.4 | 68.4 |
| 24 | | | 6.4 | 67.4 |
| +52.36 | PT Curve 24° St Cdt | | 7.6 | 66.2 |
| 25+51.33 | PT Curve 24° St Cdt. | | 9.2 | 64.6 |

Location of 29th St drain pipe 8/22/08 {Davis, Dennon, Evans

5+81.67



# Levels and Cross Sections for 29th St drain pipe

No 50

5.34 76.05 70.71

0+00
+25
+50
+75
1
+25
+50
+75
2
+17
+19
+55
+80
3
+20
+23
+28
+55
4
+40
5
+49
+57
+64
+72
+81.67 = connection with 30th St drain.

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 72.7 / 64 | 72.3 / 50 | 71.3 / 49 | 71.6 / 37 | 71.8 / 24 | 71.3 / 12 | 70.9 / 0 | 70.9 / 1 | 71.5 / 2 | 71.7 / 16 |
| 72.7 / 64 | 72.2 / 50 | 71.4 / 49 | 71.6 / 37 | 71.7 / 24 | 71.2 / 12 | 70.7 / 0 | 70.9 / 1 | 71.3 / 2 | 71.5 / 16 |
| 72.5 / 64 | 72.1 / 50 | 71.2 / 49 | 71.4 / 37 | 71.5 / 24 | 71.3 / 12 | 70.6 / 0 | 70.7 / 1 | 71.0 / 2 | 71.3 / 16 |
| 72.3 / 64 | 72.0 / 50 | 71.3 / 49 | 71.3 / 37 | 71.5 / 24 | 70.8 / 12 | 70.4 / 0 | | 71.0 / 2 | 71.3 / 16 |
| 72.5 / 64 | 72.0 / 50 | 71.1 / 49 | 71.1 / 37 | 71.5 / 24 | 71.1 / 12 | 70.5 / 0 | | 71.1 / 2 | 71.4 / 16 |
| 72.3 / 64 | 72.0 / 50 | 71.2 / 49 | 71.3 / 37 | 71.5 / 24 | 71.3 / 12 | 70.5 / 0 | 70.5 / 1 | 71.1 / 2 | 71.3 / 16 |
| 72.7 / 64 | 72.1 / 50 | 71.5 / 49 | 71.5 / 37 | 71.7 / 24 | 71.3 / 12 | 70.6 / 0 | 70.7 / 1 | 71.2 / 2 | 71.5 / 16 |
| 72.7 / 64 | 72.4 / 50 | 71.5 / 44 | 72.0 / 37 | 72.0 / 24 | 71.6 / 12 | 70.8 / 0 | 70.9 / 1 | 71.3 / 2 | 71.6 / 16 |
| 72.5 / 64 | | 71.8 / 49 | 72.2 / 37 | 72.2 / 24 | 71.8 / 12 | 71.1 / 0 | | | 71.6 / 16 |

71.7
73.0
72.9
71.5
70.1
70.0
69.2
70.1
70.0
71.4
71.5
69.9
69.3
70.5
69.6
71.1
69.6

Postal

8

Survey for the opening of Newton Ave. to 13th St. 10 Davis 15 Donnan 08 Williams.



# 15th St. Conduit Entrance

## X Sections for Wing Walls and Dam.

X sections W side conduit

| | | | | | | |
|---|---|---|---|---|---|---|
| +33.3 | 68.3 S.S. 2.0 | | 68.3 0 | 68.3 S.S. 2.0 | | |
| +33.3 | S.S. 67.7 5.0 | | 66.9 0 | S.S. 66.6 2.8 | | |
| +28 | S.S. 62.6 12.5 | 63.7 6.0 | 64.0 0 | S.S 65.3 6.0 | 65.6 14.0 | 66.5 26.0 |
| +13.1 | | 61.2 S. 14.6 | 62.8 0 | S.S 63.0 10.6 | 63.0 wing 14.0 | |
| +10.0 | S 60.6 20. | 60.8 0.0 | 61.1 14.0 | 61.2 20. | 61.9 30 | Same rate for 25 ft further. |
| 0+00 | S 60.3 20.0 | | 60.7 0 | N 61.3 20. | | |

South ↑ North ↑

| Sta | Area. □′ | A.A. □′ | Vol. Cy. | 1½:1 | | 2:1 |
|---|---|---|---|---|---|---|
| 0+00 | 130.00 | | | F 8.0 16.0 | 7.6 0 | F 7.0 14.0 |
| 0+10 | 125.86 | 127.9 | 47.37 | F 7.7 15.5 | 7.5 0 | 7.2 14.2 |
| 0+13 | 83.32 | 104.5 | 11.61 | 7.1 14.6 | 5.5 0 | 5.3 10.6 |
| 0+28 | 51.03 | 67.2 | 37.33 | 5.7 12.5 | 4.3 0 | 3.0 6.0 |
| 0+33 | 7.00 | 29.0 | 5.37 | 0.6 4.9 | 1.4 0 | 1.7 3.4 |
| 0+33 | 0.00 | — | | 0 | 0 | 0 |
| | | | 101.68 | | | |

Note BM Stake in post 69.00 City Pump Time Ends

Note line marked X used as ℄ for X sections

Hatch
Sezick
Churchman
Smith notes
Nov 2/08



See Page 9

X sections Dam E side Conduit

| | Area □' | A.A. | □' Vol. Cy. |
|---|---|---|---|
| 0+00 | 138.27 | | |
| | | 136.8 | 101.33 |
| 0+20 | 135.35 | | |
| | | 124.1 | 91.92 |
| +40 | 112.90 | | |
| | | 112.7 | 41.74 |
| +50 | 112.55 | | |
| | | 98.0 | 54.44 |
| +65 | 83.49 | | |
| | | 77.6 | 14.37 |
| +70 | 71.69 | | |
| | | 60.7 | 22.48 |
| +80 | 49.78 | | |
| | | 44.9 | 33.26 |
| 1+00 | 40.03 | | |
| | | 32.5 | 30.09 |
| 1+25 | 24.92 | | |
| | | 21.3 | 19.72 |
| 1+50 | 17.78 | | |
| | | 16.9 | 15.64 |
| 1+75 | 16.01 | | |
| | | 12.2 | 11.29 |
| 2+00 | 8.33 | | |
| | | 7.7 | 7.13 |
| | | | 443.41 |



Base 4.0 ft. Grade level = 68.3

S side 1½:1 N side 2:1

| | | | |
|---|---|---|---|
| S.S. F 8.1 / 16.1 | F 8.4 / 10.0 | F 7.8 / 0 | F 7.2 / 14.4 N.S. |
| F 8.0 / 16.0 | | F 7.7 / 0 | F 7.5 / 15.0 |
| F 7.3 / 14.9 | F 7.0 / 0 | F 6.8 / 10.0 | F 6.3 / 12.6 |
| F 7.8 / 15.7 | F 7.0 / 0 | F 6.0 / 12.0 | |
| F 6.2 / 13.3 | F 5.9 / 0 | F 5.4 / 10.8 | |
| F 4.6 / 10.9 | F 5.3 / 10.1 | F 5.6 / 0 | F 5.1 / 10.2 |
| F 3.1 / 8.6 | F 4.4 / 4.5 | F 4.5 / 0 | F 4.8 / 9.6 |
| F 3.1 / 8.6 | F 3.8 / 3.5 | F 4.0 / 0 | F 4.0 / 8.0 |
| F 2.8 / 8.2 | F 2.8 / 0 | F 2.8 / 5.6 | |
| F 2.4 / 7.6 | F 2.2 / 0 | F 2.1 / 4.2 | |
| F 2.1 / 7.1 | F 2.0 / 0 | F 2.1 / 4.2 | |
| F 1.1 / 5.6 | F 1.4 / 0 | F 1.6 / 3.2 | |

POSTED

| | Area □' | A.A. □' | Vol. Cy. |
|---|---|---|---|
| 2+25 | 7.09 | | Brt. Forward 443.41 |
| | | 5.3 | 4.90 |
| 2+50 | 3.62 | | |
| | | 1.8 | 1.67 |
| 2+75 | 0 | | 449.98 Cy. |

449.98
101.68
551.66 Total Cy in Dam.

1st Dam

Base 4.0 ft,
S side 1½:1 N Side 2:1



| F1.1 | F1.2 | F1.3 |
|---|---|---|
| 5.6 | 0 | 2.6 |
| F0.7 | F0.7 | F0.7 |
| 5.0 | 0 | 1.4 |
| 0 | 0 | 0 |

## Evans & N Sts.

4.22 69.23 65.01 BM

| | | | |
|---|---|---|---|
| 0+00 | CB#14 ✓ | 5.3 | 64.0 |
| 0+12 | | 4.7 | 64.6 |
| +27 | | 4.5 | 64.8 |
| +36 | | 4.8 | 64.5 |
| +47 | | 3.8 | 65.5 |
| +51 | | 4.8 | 64.5 |
| +61 | | 5.3 | 64.0 |
| 0+00 | CB#15 ✓ | 5.8 | 63.5 |
| +05 | | 5.8 | 63.5 |
| +12 | | 4.5 | 64.8 |
| +18 | | 3.6 | 65.4 |

## 26th & N.

1.78 65.70 63.92 BM

| | | | |
|---|---|---|---|
| 0+00 | CB#16 ✓ | 7.1 | 58.6 |
| +19 | | 7.6 | 58.1 |
| +29 | | 8.4 | 57.3 |
| +43 | | 6.0 | 59.7 |
| +53 | | 6.4 | 59.3 |
| +60 | | 5.8 | 59.9 |
| +80 | | 6.7 | 59.0 |
| 0+00 | CB#17 ✓ | 7.0 | 58.7 |
| +15 | | 6.2 | 59.5 |
| 1+25 | | 7.0 | 58.7 |
| +30 | | 6.4 | 59.3 |

## Levels for catch basins



25th & N. 35.

| | | 0.30 | 59.24 | | 58.94 | BM. |
|---|---|---|---|---|---|---|
| 0+00 | CB #18 ✓ | | | 5.5 | 53.7 | N.E. cor. |
| 0+22 | | | | 5.6 | 53.6 | |
| +28 | | | | 5.9 | 53.3 | |
| +37 | | | | 5.0 | 54.2 | N. rail. |
| +47 | | | | 5.2 | 54.0 | |
| +52 | | | | 5.2 | 54.0 | N. rail |
| +64 | | | | 6.4 | 52.8 | |
| +76 | | | | 7.2 | 52.0 | |
| 0+00 | CB #19 ✓ | | | 5.6 | 53.6 | N.W. cor. |
| +17 | | | | 5.4 | 53.8 | |
| +36 | | | | 5.3 | 53.9 | N. rail |
| +46 | | | | 5.7 | 53.5 | |
| +52 | | | | 5.6 | 53.6 | N rail |
| +75 | | | | 6.5 | 52.7 | |
| 0+00 | CB #20 ✓ | | | 6.3 | 52.9 | N.W. cor. |
| 0+12 | | | | 5.8 | 53.4 | |
| 0+24 | | | | 4.6 | 54.6 | Top rail |
| 0+32 | | | | 4.7 | 54.5 | |

25th & N. 35. gutter




25th & N. gutter.

Grant & N.

POSTED

29½ 8"N 57S.

| | | 9.58 | 55.50 | | 54.97 | BM |
|---|---|---|---|---|---|---|
| 0+00 | CB #24 | ✓ | | 6.8 | 48.7 | NW Co 24 |
| 0+22 | | | | 6.5 | 49.0 | |
| 0+40 | | | | 7.0 | 48.5 | NE Co 24 |
| = | | | | | | |
| 0+00 | CB #23 | ✓ | | 7.0 | 48.5 | NE " " " |
| +23 | | | | 6.5 | 49.0 | |
| +50 | | | | 6.4 | 49.1 | |
| +67 | | | | 5.9 | 49.6 | |
| +68 | | | | 12.1 | 43.4 | railroad bridge |
| +81 | | | | 13.1 | 42.4 | |
| +82 | | | | 5.6 | 49.9 | |
| +98 | | | | 6.9 | 48.6 | |
| 1+15 | | | | 5.8 | 49.7 | |
| 1+23 | | | | 6.3 | 49.2 | |
| +34 | | | | 9.2 | 46.3 | |
| +50 | | | | 9.0 | 46.5 | |
| 0+00 | CB #22 | ✓ | | 9.0 | 46.5 | |
| 0+10 | | | | 8.8 | 46.7 | |
| 0+16 | | | | 6.7 | 48.8 | |
| 0+26 | | | | 6.5 | 49.0 | |
| 0+27 | | | | 13.7 | 41.8 | Bottom crane at bridge |



Julian Art

| | | | | | |
|---|---|---|---|---|---|
| | 0.68 | 43.53 | | 42.85 | B.M. |
| T.P. | 6.07 | 37.44 | .1216 | 31.37 | |
| 0+00 | CB#26 ✓ | | 8.5 | 28.9 | |
| 0+07 | | | 9.5 | 27.9 | |
| 0+20 | | | 10.0 | 27.4 | |
| 0+35 | | | 10.0 | 27.4 | |
| 0+50 | | | 9.3 | 28.1 | |
| 0+66 | | | 8.5 | 28.9 | |
| 1+00 | | | 5.0 | 32.4 | |
| | 20" S "N" 57. | | | | |
| | 2.84 | 37.80 | | 34.96 | B.M. |
| 0+00 | CB#28 ✓ | | 2.5 | 35.3 | N.W. Cor. 20" S N 57. gutter |
| 0+10 | | | 3.0 | 34.8 | |
| +73 | | | 2.8 | 35.0 | |
| +39 | | | 3.2 | 34.6 | |
| +52 | | | 3.1 | 34.7 | N.E. Cor. 20" S N. gutter. |
| 0+00 | CB#27 ✓ | | 3.1 | 34.7 | |
| 0+05 | | | 3.4 | 34.4 | |
| 0+14 | | | 3.4 | 34.4 | |
| 0+23 | | | 1.0 | 36.8 | Top rail cuyamaca. |
| 0+33 | | | 2.3 | 35.5 | |
| 0+38 | | | 1.2 | 36.6 | Top rail Belt Line |
| 0+46 | | | 2.3 | 35.5 | |
| 0+53 | | | 4.0 | 33.8 | |
| 0+69 | | | 5.1 | 32.7 | |
| 1+00 | | | 4.8 | 33.0 | |
| 1+14 | | | 14.5 | 23.3 | bottom di Inch |
| 1+25 | | | 15.9 | 21.9 | " |



National & "N" Sts.

| | | | | | |
|---|---|---|---|---|---|
| | 1.12 | 15.07 | | 13.95 | BM. |
| T.P. | 1.13 | 8.01 | 8.19 | 6.88 | |
| 0+00 | | | 4.6 | 3.41 | |
| 0+08 | | | 4.1 | 3.91 | |
| 0+16 | | | 5.9 | 2.11 | |
| 0+24 | | | 3.7 | 4.31 | |
| 0+34 | | | 3.6 | 4.41 | |
| 0+44 | | | 3.7 | 4.31 | |
| 0+52 | | | 4.0 | 4.01 | |
| 0+63 | | | 4.9 | 3.11 | |
| | | | | | |
| | 2.55 | 9.43 | | 6.88 | BM. |
| T.P. | 4.43 | 7.46 | 6.40 | 3.03 | |
| 0+00 = | | | 5.5 | 1.96 | N.W. Cor. 13th & N. Sts. |
| 0+15 | | | 4.8 | 2.66 | |
| +31 | | | 4.5 | 2.96 | E. rail |
| +43 | | | 5.0 | 2.46 | |
| +58 | | | 5.1 | 2.36 | N.E. Cor. 13th & N. Sts. |
| | | | | | |
| 0+00 = | | | 5.1 | 2.36 | N.E. Cr. 13th & N. centerline gutter |
| +13 | | | 4.6 | 2.86 | |
| +25 | | | 4.5 | 2.96 | |
| +38 | | | 4.4 | 3.06 | |
| +51 | | | 4.2 | 3.26 | |
| +65 | | | 4.2 | 3.26 | |




POSTED

X sec. E side 13th from M'St. South

Hi
7.46

| | | |
|---|---|---|
| 0+00 | 4.3 | 3.16 = |
| 0+50 | 4.9 | 2.56 |
| 1 | 4.4 | 3.06 |
| +50 | 4.7 | 2.76 |
| +70 | 7.8 | - 0.34 |
| 2+00 | 7.6 | - 0.14 |
| +50 | 8.1 | - 0.64 |
| +92 | 7.4 | 0.06 |
| 3+00 | 8.6 | - 1.14 |
| +44 | 3.9 | 3.56 |
| +50 | 9.2 | - 1.74 |
| 4+00 | 9.9 | - 2.44 |
| +50 | 9.8 | - 2.34 |
| 5+00 | 10.3 | - 2.84 |
| 5+34 | 5.1 | 2.36 Δ Pt. |
| +50 | 5.2 | 2.26 |
| +75 | 11.0 | - 3.54 |
| 6+14 | 10.8 | - 3.34 |
| 6+20 | 8.2 | - 0.74 |

gutter line

3. line of "J" St.

POSTED

rt. Line "K" St.
Top rail - bridge -
bottom

POSTED

Intersection Line St. Center Line 13th St. Top R.R. Embankment

POSTED

POSTED

# Xsections for Dam at intake 15-1/2 St. Conduit

W. Side of 0+00 shown on sketch P. 18

N. (2:1)

S (1½:1)

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 0+00 | SS | F 14.3 / 31.5 | F 13.8 / 16 | F 13.6 / 4 | F 13.3 / 00 | F 13.6 / 3 | F 12.4 / 24.7 | SS |
| 0+07 | SS | F 14.1 / 31 | F 14.0 / 25 | F 13.5 / 15 | F 13.4 / 00 | F 13.5 / 27 | SS | |
| 0+13 | SS | -13.2 / 30 | -13.4 / 28 | -13.1 / 13 | -13.1 / 0 | -13.3 / 12 | -13.7 / 27.5 | SS |
| 0+19 | SS | -12.0 / 28 | -11.6 / 25 | -11.3 / 12 | -11.3 / 0 | -11.1 / 22.3 | SS | |
| 0+28 | SS | -10.3 / 25.5 | -10.4 / 20 | -8.3 / 13 | -9.1 / 11 | -8.8 / 0 | -9.4 / 9 | -8.9 / 17.3 | SS |
| 0+32 | SS | -8.1 / 22 | -8.0 / 17 | -5.8 / 8 | -6.2 / 4 | -6.7 / 0 | -6.6 / 6 | -5.6 / 8 | -7.5 / 15 | SS |
| 0+35 | SS | -3.2 / 14.3 | -3.6 / 12 | -4.1 / 11 | -2.8 / 6 | -3.7 / 0 | -4.5 / 6 | -3.0 / 10 | SS |
| 0+43.4 | | +2.6 / 10 | +1.8 / 7 | -0.0 / 0 | | | | |

grade elev. - 74.5 Top of Dam - Conduit

## Sketch showing how sections are taken for Dam at intake of 15-1/2 St Conduit

13
12
09 Hatch
Moore
Dezie l



POSTED

X sections for Dam on East side of 0+00 as shown on sketch P.18

S (1/2:1) N (2:1)

| | S | | | | | | | N |
|---|---|---|---|---|---|---|---|---|
| 0+00 | SS | -14.4 / 31.5 | -13.8 / 20 | -13.4 / 0 | | | | |
| 0+05 | SS | -14.3 / 31.5 | -13.8 / 20 | -13.9 / 7 | -13.9 / 0 | -13.4 / 21 | -13.7 / 27.5 | SS ✓ |
| 0+10 | SS | -14.6 / 32 | -14.2 / 11 | -13.4 / 5 | -13.2 / 0 | -12.5 / 20 | -12.7 / 25.5 | SS ✓ |
| 0+20 | SS | -14.1 / 31 | -13.3 / 0 | -12.0 / 15 | -12.6 / 20 | -12.0 / 24 | | SS |
| 0+30 | SS | -14.2 / 31 | -14.1 / 19 | -13.3 / 5 | -12.5 / 0 | -11.6 / 14 | -12.3 / 20 | -12.4 / 24.8 |
| 0+40 | SS | -13.2 / 29.5 | -13.2 / 12 | -11.9 / 3 | -11.2 / 0 | -10.9 / 15 | -11.6 / 23 | SS |
| 0+47 | SS | -13.1 / 29.7 | -12.7 / 15 | -10.9 / 5 | -10.6 / 0 | -10.7 / 18 | -11.0 / 22 | SS |
| 0+50 | SS | -13.5 / 30.3 | -12.6 / 15 | -11.5 / 7 | -11.1 / 0 | -10.6 / 12 | -10.8 / 21.6 | SS |
| 0+55 | SS | -14.1 / 31 | -12.9 / 25 | -12.1 / 2 | -11.5 / 0 | -10.7 / 2 | -10.7 / 15 | -10.8 / 21.6 SS |
| 0+70 | SS | -12.0 / 28 | -11.2 / 0 | -10.7 / 21.5 | SS | | | |
| 1+00 | SS | -10.0 / 25 | -10.2 / 0 | -10.8 / 20.5 | SS | | | |
| 1+25 | SS | -8.9 / 23.4 | -9.1 / 0 | -9.3 / 18.6 | SS | | | |
| 1+50 | SS | -8.3 / 22.4 | -8.5 / 0 | -8.3 / 16.6 | SS | | | |
| 1+75 | SS | -8.3 / 22.5 | -8.3 / 0 | -7.9 / 15.8 | SS | | | |
| 2+00 | SS | -7.6 / 21.5 | -8.0 / 0 | -8.0 / 16 | SS | | | |
| 2+25 | SS | -7.5 / 21.31 | -7.6 / 0 | -7.4 / 14.8 | SS | | | |
| 2+50 | SS | -6.9 / 20.3 | -7.3 / 0 | -6.8 / 13.6 | SS | | | |
| 2+75 | SS | -6.3 / 19.4 | -6.9 / 0 | -6.8 / 13.6 | SS | | | |
| 3+00 | SS | -5.8 / 18.7 | -6.4 / 0 | -6.1 / 13.2 | SS | | | |
| 3+25 | SS | -5.4 / 18.1 | -5.7 / 0 | -5.7 / 11.4 | SS | | | |
| 3+50 | SS | -4.9 / 17.3 | -5.2 / 0 | -5.3 / 11 | SS | | | |
| 3+75 | SS | -4.1 / 16.2 | -4.8 / 0 | -5.2 / 10.4 | SS | | | |
| 4+00 | SS | -2.8 / 14.2 | -2.8 / 0 | -2.6 / 5.2 | SS | | | |
| 4+15 | SS | -1.4 / 12.1 | -1.7 / 0 | -1.4 / 3 | SS | | | |
| 4+30.5 | SS | -0.5 / 10.75 | 0.0 / 0 | | | | | |

# Xsections ℄ St Bridge at 18th St.

NW 16th ℄

| | | | | |
|---|---|---|---|---|
| BM | 0.82 | 61.36 | | 60.54 |
| | 477 | 5308 | 13.25 | 24.31 |

Sec A (0+00)

| | | |
|---|---|---|
| E | 1.2 | √1.9 |
| + 3 | 1.7 | √1.4 |
| W. | 1.5 | √1.6 |

Sec B. (0+00)

| | | |
|---|---|---|
| W | 1.5 | √1.6 |
| Cr. | 2.7 | √0.4 |
| E | 1.0 | √2.1 |

0+45

| | | |
|---|---|---|
| W | 1.5 | √1.6 |
| E | 1.3 | √1.8 |

1+10

| | | | |
|---|---|---|---|
| W | Top | 3.3 | 49.8 |
| | Bottom | 5.3 | 47.8 |
| E | Top | 3.4 | 49.7 |
| | Bottom | 5.4 | 47.7 |

1+23

| | | |
|---|---|---|
| W | 5.2 | 47.9 |
| E | 4.9 | 48.2 |

1+50

| | | |
|---|---|---|
| E | 4.9 | 48.2 |
| W | 5.2 | 47.9 |

South end.

| | | |
|---|---|---|
| W | 5.6 | 47.√ |
| Cr | 5.0 | 48.1 |
| E | 4.9 | 48.2 |

19th

3/12/09 {Hatch Moore Deziel



# Xsections Bridge at 16th D.

SW 16th D

| | | | | |
|---|---|---|---|---|
| BM | 1.03 | 56.92 | | 55.89 |
| | 1.44 | 45.28 | 13.08 | 43.84 |

Sec "E"

| | | | |
|---|---|---|---|
| E | | 5.1 | 40.2 |
| 15 | POS | 5.4 | 39.9 |
| 30 | | 4.4 | 40.9 |
| 45 | | 3.0 | 42.3 |
| W | | 0.2 | 45.1 |

Sec "D"

| | | | |
|---|---|---|---|
| W | | 3.6 | 41.7 |
| 13' | | 4.2 | 41.1 |
| 20' E | | 4.9 | 40.4 |

Sec "C"

| | | | |
|---|---|---|---|
| E | | 3.1 | 40.2 |
| Cr. | | 4.9 | 40.4 |
| W | | 3.1 | 42.2 |

25' N.

| | | | |
|---|---|---|---|
| E | | 4.7 | 40.6 |
| Cr. | | 5.0 | 40.3 |
| 22' | | 4.7 | 40.6 |
| W | | 1.9 | 43.4 |

50' N.

| | | | |
|---|---|---|---|
| E | | 4.2 | 41.1 |
| Cr. | | 4.5 | 40.8 |
| 20' | | 4.4 | 40.9 |
| W | | 2.3 | 43.0 |

3/13/09 Hatch Moore Dezial

21



45.28

75' N.

| | | |
|---|---|---|
| E | 3.5 | 41.8 |
| Cr. | 4.2 | 41.1 |
| 21' | 4.0 | 41.3 |
| W | 1.7 | 43.6 |

100' N

| | | |
|---|---|---|
| E | 2.7 | 42.6 |
| Cr. | 4.2 | 41.1 |
| 20' | 4.0 | 41.3 |
| W | 1.6 | 42.7 |

125 N

| | | |
|---|---|---|
| E | 1.4 | 42.9 |
| Cr | 3.5 | 41.8 |
| 23' | 4.2 | 41.1 |
| W | 3.1 | 42.2 |

150' N

| | | |
|---|---|---|
| E | 1.7 | 43.6 |
| Cr. | 2.7 | 42.6 |
| 20' | 3.7 | 41.6 |
| W | 3.3 | 42.0 |

175' N

| | | |
|---|---|---|
| E | 2.1 | 43.2 |
| Cr. | 2.9 | 42.4 |
| W | 2.8 | 42.4 |

45.28

189 N (Sec "B")

| | | |
|---|---|---|
| E | 2.0 | 43.3 |
| Cr | 2.8 | 42.5 |
| W | 2.4 | 42.9 |

Sec "A"

| | | |
|---|---|---|
| E | 2.0 | 43.3 |
| Cr. | 2.6 | 42.7 |
| W | 0.5 | 44.8 |

# Xsections of Bridge

15th and F.

NW 15th F.

| | | | | |
|---|---|---|---|---|
| BM | 0.86 | 43.70 | | 42.84 |
| | 4.47 | 38.41 | 9.76 | 33.94 |

S. end of Bridge

| | | | |
|---|---|---|---|
| E | | 2.1 | 36.3 |
| Cr. | | 6.3 | 32.1 |
| 25' N. | | | |
| E | | 5.4 | 33.0 |
| Cr. | | 5.6 | 32.8 |
| 50' N. | | | |
| E | | 3.9 | 34.5 |
| Cr. | | 5.1 | 33.3 |
| 75' N. | | | |
| E | | 4.2 | 34.2 |
| Cr. | | 5.9 | 32.5 |
| 80' = N end. | | | |
| E | | 4.0 | 34.4 |
| Cr. | | 6.5 | 31.9 |
| T.P. | 1.83 | 35.77 | 4.47 | 33.94 |
| S. end. | | | |
| W | | 4.5 | 31.3 |
| Cr. | | 4.6 | 31.2 |
| 25' N. | | | |
| W | | 4.2 | 31.6 |
| Cr. | | 4.9 | 30.9 |

3/13/09 {Hatch Moore Deziel

Note - Fill back of Wingwalls is about street grade.



| | | | |
|---|---|---|---|
| | 35-77 | | |
| | 50' N | | |
| W | | 4.8 | 31.0 |
| Cr. | | 3.9 | 31.9 |
| | 75' N | | |
| W | | 4.7 | 31.1 |
| Cr. | | 3.5 | 32.3 |
| | 80' N = Nerd. | | |
| W | | 4.3 | 31.5 |
| Cr. | | 4.2 | 31.6 |

# Xsections of Bridge on 15th and "G"

NE 15th "G"

| | | | | |
|---|---|---|---|---|
| BM. | 0.75 | 36.31 | | 35.560 |
| | 3.60 | 32.43 | 7.48 | 28.83 |
| | | N end. | | |
| E | | | 3.6 | 28.8 |
| Cr | | | 3.7 | 28.7 |
| | | 5's. | | |
| E | | | 3.6 | 28.8 |
| Cr. | | | 3.5 | 28.9 |
| | | 30's. | | |
| E | | | 3.3 | 29.1 |
| Cr. | | | 3.8 | 28.6 |
| | | 55's. | | |
| E | | | 3.9 | 28.5 |
| Cr. | | | 4.2 | 28.2 |
| | | 80's = S end | | |
| E | | | 3.1 | 29.3 |
| 10'. | | | 5.0 | 27.4 |
| Cr. | | | 4.1 | 28.3 |
| BM. | 2.95 | 31.78 | 3.60 | 28.83 |
| | | N end. | | |
| W | | | 2.8 | 29.0 |
| 10' | | | 3.6 | 28.2 |
| Cr. | | | 3.1 | 28.7 |
| | | 5's | | |
| W. | | | 2.9 | 28.9 |
| 10' | | | 3.7 | 28.1 |
| Cr. | | | 2.8 | 29.0 |

POSTED

3/13/09 Hatch, Moore, Dezid



Note - Fill behind wings is about Street grade -



3178

30' S.

| | | |
|---|---|---|
| W | 3.7 | 28.1 |
| 10' | 3.5 | 28.3 |
| Cr. | 30 | 28.8 |

55' S.

| | | |
|---|---|---|
| W | 3.7 | 28.1 |
| Cr. | 3.9 | 27.9 |

80' S = S. end

| | | |
|---|---|---|
| W | 3.6 | 28.2 |
| 10' | 4.4 | 27.4 |
| Cr. | 3.2 | 28.6 |

X sections of Bridge on I St.
between 14th & 15th Sts.

| | | | | |
|---|---|---|---|---|
| NW 15th I | | | | |
| BM. | 409 | 29.57 | | 25.48 |
| | 803 | 24.20 | 1040 | 19.17 |
| | | S end. | Sec A | |
| W | | | 5.6 | 18.6 |
| S | | | 7.9 | 16.8 |
| Cr. | | | 8.0 | 16.2 |
| | | Sec. B. | | |
| W | | | 5.9 | 18.3 |
| C | | | 7.9 | 16.3 |
| Cr. | | | 8.0 | 16.2 |
| | | 11.5 N. | | |
| W | | | 7.6 | 16.6 |
| Cr. | | | 8.2 | 16.0 |
| | | 36.5 N. | | |
| W | | | 7.4 | 16.8 |
| Cr. | | | 7.9 | 16.3 |
| | | 61.5 | | |
| W | | | 7.5 | 16.7 |
| Cr. | | | 8.0 | 16.2 |
| | | 86.5 = N end (sec C) | | |
| W | | | 7.7 | 16.5 |
| Cr. | | | 7.2 | 17.0 |
| | | Sec D. | | |
| W | | | 7.7 | 16.5 |
| Cr. | | | 6.9 | 17.3 |
| T.P. | 3.51 | 29.29 | 3.42 | 20.78 |

17.2

16.9

POSTED

3/13/09 Hatch Moore Dazie



2429

5, end of Bridge

| | | | |
|---|---|---|---|
| E | 5.1 | 19.2 | 18.3 |
| Cr. | 6.9 | 17.4 | |
| 11.5 N. | | | |
| E | 5.3 | 19.0 | |
| Cr. | 6.5 | 17.8 | |
| 36.5 N. | | | |
| E | 4.8 | 19.5 | |
| 5' | 5.7 | 18.6 | |
| Cr. | 5.4 | 18.9 | |
| 61.5 N. | | | |
| E | 4.6 | 19.7 | |
| 5' | 5.5 | 18.8 | |
| Cr. | 5.6 | 18.7 | |
| 80.5 N. | | | |
| E | 4.0 | 20.3 | |
| 7' | 5.5 | 18.8 | |
| Cr. | 4.9 | 19.4 | |
| Sec E | | | |
| E | 4.2 | 20.1 | 19.0 |
| Cr. | 6.4 | 17.9 | |

# Xsections of Bridge on 14th and J Sts

| | | | | | |
|---|---|---|---|---|---|
| BM NW 15th J | 460 | 26,56 | | 21.96 | |
| | 421 | 19.01 | 11.76 | 14.80 | |

N end of Bridge

| | | | | |
|---|---|---|---|---|
| W | | 6,8 | 12.2 | |
| 7' | | 6,6 | 13.4 | 126 |
| Cr. | | 5-6 | 13.4 | |
| | 20's. | | | |
| W | | 6.6 | 12.4 | |
| Cr. | | 6.5 | 12.5 | 12.4 |
| | 40's. | | | |
| W | | 6,5 | 12.5 | |
| Cr. | | 6.8 | 12.2 | 12.3 |
| | 60's | | | |
| W | | 6.5 | 12.5 | |
| Cr | | 7.3 | 11.7 | 12.2 |
| | 80's = S end | | | |
| W | | 6.4 | 12.6 | |
| 7' | | 7.7 | 11.3 | |
| Cr. | | 7.5- | 11.5 | 12.0 |
| Cr. | | 7.1 | 11.9 | |
| 28' | | 6.6 | 12.4 | |
| | | 5-2 | 13.8 | |
| E | | 4.8 | 14.2 | |
| | 60's of N end | | | |
| E | | 4.7 | 12,3 | |
| Cr. | | 6.5 | 12.7 | 12.5 |

POSTED

3/15/09 {Hatch Moore Dezio}



1901

40's

| | | | |
|---|---|---|---|
| E | 5.2 | 13.8 | |
| A | 5.7<br>6.5 | 13.3<br>12.5 | 12.9 |
| cr. | 6.4 | 12.6 | |

20's

| | | | |
|---|---|---|---|
| E | 5.8 | 13.7 | 13 |
| cr. | 6.4 | 12.6 | |

Kend.

| | | | |
|---|---|---|---|
| E | 6.4 | 12.6 | 12.5 |
| cr. | 6.1 | 12.9 | |

# Xsections of Bridge on 14th and K. Sts.

3/12/09 {Hatch Moore Deziel

| | | | | |
|---|---|---|---|---|
| NW Cor Bm 15th K. | 242 | 18.90 | | 16.48 |
| | 4.60 | 12,00 | 11.50 | 7.40 |
| | | S end. | | |
| W | | | 1,6 | 10.4 |
| 10' | | | 3,4 | 8.6 | 9.7 |
| Cr. | | | 2.8 | 9.2 |
| | | 20' N. | | |
| W | | | 2,1 | 9.9 |
| Cr. | | | 2.7 | 9.3 |
| | | 40' N. | | |
| W | | | 2,4 | 9.6 | 9.8 |
| Cr | | | 1.9 | 10.1 |
| | | 60' N. | | |
| W | | | 2,1 | 9.9 |
| Cr. | | | 1,8 | 10.2 |
| | | 80' N. = N end. | | |
| W | | | 1.3 | 10.7 | 10.2 |
| Cr | | | 2.5 | 9.5 |
| T.P. | 440 | 11,80 | 16.0 | 7.40 |
| | | S end. | | |
| E | | | 2.2 | 9.6 |
| 5' | | | 4,2 | 7.6 | 8,0 |
| Cr. | | | 3.9 | 7.9 |
| | | 20' N. | | |
| E | | | 3.0 | 8.8 |
| 4' | | | 3.9 | 7.9 |
| Cr. | | | 3,8 | 8.0 |



11,80

40 N

| | | | | |
|---|---|---|---|---|
| E | | 3.7 | 8.1 | 80 |
| Cr | | 4.0 | 7.8 | |
| | 60 N | | | |
| E | | 3,2 | 8.6 | |
| Cr | | 3.8 | 8,0 | |
| | 80 N = N end | | | |
| E | | 3.5 | 8.3 | 8.5 |
| Cr | | 3,1 | 8.7 | |

POSTED

Base Line for Crosssections in Park from end of Proposed Conduit to Centre of Wood Bridge



4/12/09 Hatch Moore Thomas

Cross sections of line shown on P. 33

POSTED

| | | | | |
|---|---|---|---|---|
| B.M. | 7.45 | 71.45 | | 64.00 |
| 0+00 | | | 10.6 | 60.9 |
| 0+25 | | | 8.6 | 62.9 |
| 0+50 | | | 8.1 | 63.4 |
| 1+00 | | | 6.5 | 65.0 |
| 1+36 | | | 8.3 | 63.2 |
| 1+62 | | | 6.2 | 65.3 |
| 2+00 | | | 4.3 | 67.2 |
| 2+02 | | | {1.2 / 6.1} | 67.3 / 65.1 |
| 2+20 | | | 7.8 | 63.7 |
| 2+52 | | | 7.9 | 63.6 |
| 2+67 | | | 5.8 | 65.7 |
| 3+00 | | | 5.2 | 66.3 |
| T.P. | 9.19 | 76.34 | 4.30 | 67.15 |
| 3+50 | | | 9.4 | 66.9 |
| 3+85 | | | 8.6 | 67.7 |
| 4+00 | | | 10.3 | 66.0 |
| 4+25 | | | 8.9 | 67.4 |
| 4+50 | | | 8.1 | 68.2 |
| 5+00 | | | 7.6 | 68.7 |
| 5+50 | | | 7.1 | 69.2 |
| 6+00 | | | 6.2 | 70.1 |
| 6+50 | | | 6.1 | 70.2 |
| 7+00 | | | 6.0 | 70.3 |
| 7+25 | | | 7.2 | 69.1 |

Sections to West Tangent to Beginning of Spiral to the East of Spiral of Boulevard

{+ = Cut from Gr. Elev.
− = fill " " "}

W E

34

+7.3/20 +3.4/15 +2.2/9 +1.8/7 +1.0/8 +0.8/20

+4.0/28 +1.5/26 −0.2/8 −1.7/14 −1.1/5 +0.6/15 +0.8/30

+3.3/30 0.0/30 −2.2/18 −1.2/5 −0.5/20 −0.5/56

+4.2/27 −0.7/17 −1.3/10 +1.2/8 +2.1/16 +2.4/33 +2.8/50 +3.5/70

+3.8/34 −3.6/22 −0.2/3 −1.6/14 +1.1/8 +1.9/60

+2.3/53 −1.0/41 −3.6/35 −3.8/21 −4.1/6 −3.6/14 0.0/2 +0.6/22 +0.7/43

+7.5/58 +2.4/28 +2.7/23 +0.8/13 +1.1/6 +0.2/5 −2.2/34 +2.4/39

+7.4/61 +3.0/52 +2.6/29 +3.1/14 −1.9/5 −3.0/7 +4.9/16 +4.9/36 +0.5/56

+3.2/64 +1.2/37 +0.7/7 −1.4/2 −1.1/16 +2.1/26 +2.5/62

+2.8/73 +2.0/44 +0.2/26 −0.2/8 −1.5/19 −1.8/30 +2.7/36 +2.7/64

+5.6/82 +4.4/46 +3.9/33 +1.8/10 0.0/2 +0.2/16 −0.9/20 +2.9/28 +2.8/33 +4.4/67

+2.0/59 +2.7/45 −0.9/40 −0.5/19 −1.8/14 +2.9/27 +2.8/67

+4.6/72 +3.4/59 +0.4/49 −1.2/44 0.4/19 −0.5/37 +2.9/42 +2.3/68

+5.7/75 +4.4/58 +2.7/46 +3.3/44 −1.7/29 −0.2/33 +3.2/26 +3.4/42 +3.0/70 Same for 50'

+4.1/68 +3.1/62 +1.0/57 +0.6/43 −1.2/33 −1.9/20 −0.7/7 +0.9/32 +1.3/44 +2.2/72 Same for 100'

+3.2/62 +2.3/49 +1.1/40 −1.2/33 −2.7/21 −1.3/10 +0.7/6 +0.6/33 +2.5/44 +3.2/71 Same for 100'

+3.1/77 +2.3/57 +2.7/46 −1.2/19 +0.2/16 +1.4/47 +2.6/71 +3.2/95 " " 75'

| | | | | |
|---|---|---|---|---|
| | | 76.34 | | |
| 7+32 | | | 5.3 | 71.1 |
| 7+35 | | | 2.1 | 74.2 |
| T.P. | 7.30 | 81.36 | 5.48 | 75.86 |
| 7+50 | | | 6.6 | 74.6 |
| 8+00 | | | 5.7 | 75.5 |
| 8+50 | | | 5.3 | 75.9 |
| 9+00 | | | 5.0 | 76.2 |
| 9+48 | | | 4.2 | 77.0 |
| 9+55 | | | 7.5 | 73.7 |
| 9+82 | | | 7.5 | 73.7 |
| 10+00 | | | 5.6 | 75.6 |
| T.P. | 10.65 | 87.51 | 4.07 | 76.89 |
| 10+50 | | | 14.5 | 76.0 |
| 11+00 | | | 10.6 | 76.9 |
| 11+50 | | | 8.4 | 79.1 |
| 11+86 | | | 7.0 | 80.5 |
| 11+88 | | | 9.1 | 78.4 |
| 12+00 | | | 8.5 | 79.0 |
| 12+50 | | | 6.0 | 81.5 |
| 12+75 | | | 6.5 | 81.0 |
| 13+00 | | | 5.7 | 81.8 |
| 13+50 | | | 5.8 | 81.7 |
| T.P. | 9.18 | 92.06 | 4.66 | 87.88 |
| 14+00 | | | 8.7 | 83.4 |
| 14+50 | | | 7.2 | 84.9 |

VM E

+0.9/100 −0.8/57 −0.3/37 −1.3/15 −4.7/28 −6.8/44 −3.4/63 −1.7/63 −1.8/100 +0.2/105

0.0/100 +1.1/55 −0.5/25 −0.2/30 +2.5/60 −2.4/56 −4.5/44 −3.6/100 −3.1/135 +3.3/140 +4.1/150

+0.6/145 −0.9/62 −0.9/40 −0.3/25 0.0/48 −2.5/76 −3.7/85 −3.0/123 −4.5/133 −5.0/150 +2.0/167 +1.4/180 same slope for 30'

+1.0/125 0.0/100 −2.4/61 −1.5/47 −0.6/91 +0.5/66 2.0/76 −3.0/100 −4.2/134 −3.7/138 −0.7/145 +1.3/155 same slope for 30'

+2.5/110 3.0/68 +1.3/50 −0.7/28 +2.8/8 −4.1/36 −2.4/48 −2.4/71 −2.1/90 +1.0/95 +0.3/100 +2.0/140 same slope for 60'

+3.3/125 +3.7/83 +3.2/57 +2.1/35 −0.5/25 +1.9/8 +1.1/30 +1.5/54 +5.8/66 +7.0/75 +5.8/100 same slope for 70'

+1.7/100 +0.9/51 −2.6/21 −1.6/25 −0.5/19 −0.3/38 +3.3/47 +6.4/140 same slope for 80'

+3.5/160 +3.1/100 +2.3/85 −0.5/84 −0.9/72 +1.8/57 +0.2/50 +2.0/18 +0.5/10 +1.8/12 +3.6/38 +4.7/75 same slope for 75'

+1.7/160 +0.7/135 −1.3/120 −1.0/100 +0.7/75 0.0/49 +3.0/34 +2.2/34 +1.1/12 +2.9/8 +2.9/8 +3.1/80 +4.6/66 same slope for 75'

−3.5/160 −1.3/125 −1.6/80 +0.9/75 +0.8/23 −0.5/23 −0.8/2 +1.2/1 +1.8/8 +2.6/44 same slope for 40'

−1.3/180 −2.6/160 −3.5/100 0.0/88 +0.7/52 +0.8/36 −1.0/32 −0.5/21 −1.9/2 +0.5/19 +2.9/58 same slope for 30'

at ring wall −1.1/180 −0.5/150 +0.2/100 −0.7/59 +2.3/32 +0.5/27 +0.8/12 +2.0/14 +3.4/28 +4.7/37 same slope for 20'

at bridge

+0.2/165 −0.3/140 +0.0/100 0.0/50 −1.6/29 +1.0/37 −1.4/13 −0.7/13 −1.7/20 +1.3/30 +2.5/55 toe slope

+2.9/150 +0.3/100 0.0/43 −1.0/61 −1.5/34 −0.3/5 +1.0/31 +3.0/49 toe slope

+1.0/155 +1.4/100 +2.1/97 +0.9/83 +2.9/14 0.0/23 +1.9/28 +1.9/48 +3.0/172 toe slope

+1.1/150 +1.8/120 +1.3/88 +1.4/38 +1.0/5 +0.4/21 −0.9/41 +0.5/21 +1.5/61 +2.3/87 toe slope

+0.4/165 +0.9/100 +0.9/44 −0.2/19 +1.8/18 −2.1/36 +0.4/46 +1.5/86 toe slope

9206

| | | | |
|---|---|---|---|
| 14+75 | | 6.8 | 85.3 |
| 14+80 | | 8.3 | 83.8 |
| 15+00 | | 8.2 | 83.9 |
| 15+50 | | 7.7 | 84.4 |
| 16+00 | | 5.8 | 86.3 |
| 16+46 | Centre South Side Bridge | 6.0 | 86.1 |
| Brg Top of 1st Floor Bolt from SE Cor of Bridge | | 1.45 | 90.61 |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| +5.0 / 145 | +8.2 / 100 | +2.4 / 98 | +1.6 / 8 | -0.2 / 5 | +1.3 / 14 | +0.4 / 38 | +3.0 / 36 | +2.6 / 68 | +2.9 / 92 | same slope for 75' | | |
| +5.9 / 78 | +4.5 / 42 | +3.6 / 22 | +1.8 / 23 | +1.3 / 9 | +0.6 / 3 | +1.0 / 8 | +2.5 / 21 | +3.2 / 63 | 47 / 96 | same slope for 40' | | |
| +4.6 / 90 | +3.7 / 20 | +0.2 / 10 | -1.0 / 18 | +1.2 / 18 | +1.8 / 154 | same slope for 60' | | | | | | |
| Line taken N.E. with Bridge | +0.9 / 7 | +3.0 / 7 | +2.9 / 36 | +2.7 / 33 | same slope for 100' | | | | | | | |

4
19-21
09

Watch Traverse from Station 6–12
Thomas on Baseline in Sculze Cañon
600' East.

Note These figures are elevations.

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| To 5+00 | 710 / 100 | 72.9 / 120 | 72.1 / 142 | 75.9 / 200 | 80.5 / 225 | 86.3 / 300 | 89.6 / 340 | 93.2 / 385 | 95.6 / 430 | 96.0 / 450 | 113.1 / 500 |
| " 6+00 | | | | | 72.5 / 100 | | 74.9 / 200 | | 75.4 / 310 | | 82.4 / 325 |
| " 7+00 | 74.5 / 100 | 76.7 / 190 | 79.7 / 200 | 85.8 / 230 | 94.0 / 250 | 104.2 / 275 | 112.6 / 300 | | 123.0 / 350 | | 133.0 / 400 |
| " 8+00 | 80.8 / 175 | 87.3 / 200 | | 95.3 / 225 | | 105.9 / 250 | 119.8 / 300 | | 132.0 / 350 | | 143.5 / 400 |
| " 9+00 | 90.7 / 200 | 98.6 / 240 | Drain 112.6 / 300 | | 126.7 / 350 | | 141.1 / 400 | | 151.3 / 450 | | 159.5 / 500 |
| " 9+48 | 90.1 / 175 | 94.4 / 200 | | 101.9 / 250 | Drain 103.8 / 300 | Drain 105.2 / 350 | 117.9 / 400 | | 127.0 / 450 | | 133.4 / 500 |
| " 10+00 | 85.7 / 150 | | 92.5 / 200 | | 98.9 / 225 | | 109.2 / 250 | | 114.4 / 300 | | 115.7 / 350 |
| " 11+00 | 83.3 / 100 | 88.1 / 150 | 91.9 / 175 | 98.4 / 200 | | 110.8 / 225 | | 121.7 / 250 | | 129.9 / 275 | |
| " 12+00 | 89.5 / 100 | | 94.3 / 150 | | 107.3 / 175 | | 113.0 / 200 | | 130.3 / 225 | | 122.1 / 250 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| To 5+00 | 113.5 / 609 Park Line | | | | | | | | | | |
| " 6+00 | 88.9 / 350 | | 102.3 / 300 | | 114.8 / 350 | | 122.1 / 400 | | 128.0 / 440 | | 124.6 / 450 |
| " 7+00 | 142.4 / 450 | | 150.9 / 500 | | 162.3 / 560 | | 163.6 / 600 | | | | |
| " 8+00 | 167.7 / 500 | | 178.1 / 550 | | 176.0 / 600 | | | | | | |
| " 9+00 | | | | | | | | | | | |
| " 9+48 | | | | | | | | | | | |
| " 10+00 | 103.5 / 450 | | 122.3 / 475 | | 124.3 / 500 | | 137.1 / 550 | Drain 128.5 / 560 | Drain 124.5 / 580 | | 130.4 / 600 |
| " 11+00 | 173.2 / 425 | | 173.9 / 475 | | 176.0 / 525 | | 174.5 / 575 | | 179.9 / 600 | | 173.2 / 625 |
| " 12+00 | 170.0 / 325 | | 177.7 / 350 | | 184.2 / 375 | | 189.7 / 400 | Roads 191.1 / 425 | | 192.9 / 450 | 195.5 / 500 |

| | | | |
|---|---|---|---|
| To 5+00 | | | |
| " 6+00 | 124.5 / 500 | 129.9 / 550 | 147.8 / 600 |
| " 7+00 | | | |
| " 8+00 | | | |
| " 9+00 | | | |
| " 9+48 | | | |
| " 10+00 | | | |
| " 11+00 | | | |
| " 12+00 | 194.9 / 550 | 195.2 / 600 | |

POSTED

I Davis
7 Williams
09 Churchman

Culvert to Connect with Switzer Creek Storm Drain.

2+13 ± Connection with Conduit at Sta 3+65.82 ±

1+08 = Connection with pipe from C.B.

0+93.5 ± E.C.

0+02 ± P.C.

0+00 End of Present 30" C.R.



P38 sum

## Levels for Pipe Culvert to connect with Switzer Creek Drain

| | HI | | | |
|---|---|---|---|---|
| | 1.43 | 61.97 | | 60.54 B.M. Pig N.W. 16 C. |
| | 8.05 | 62.35 ✓ | 7.67 | 54.30 |
| | 10.96 | 72.32 ✓ | 0.99 | 61.86 |
| | 11.66 | 83.52 ✓ | 0.46 | 71.86 |
| | 2.56 | 86.91 ✓ | 0.17 | 83.35 |
| | 0.11 | 76.36 ✓ | 10.66 | 76.25 |
| 0+00 Inside bottom 30" C.P. | | | 5.42 | 70.93 |
| 0+02 71 P.C. | | | 5.0 | 71.35 |
| 0+25 | | | 6.5 | 69.85 |
| 0+48 1/2 C.C. | | | 6.5 | 69.85 |
| +70 | | | 7.0 | 69.35 |
| +93 50 E.C. | | | 4.9 | 71.45 |
| 1+08 Connection with C.B.'s | | | 5.1 | 71.25 |
| +17 | | | 6.0 | 70.35 |
| +30 | | | 9.1 | 67.25 |
| +47 | | | 12.6 | 63.75 |
| TP | 2.39 | 67.51 ✓ | 11.23 | 65.12 |
| +57 | | | 2.2 | 65.3 |
| +65 | | | 5.5 | 62.0 |
| +89 | | | 2.9 | 59.6 |
| +90 | | | 9.5 | 58.0 |
| 2+13 5th Connection with S.C.D. | | | 10.8 | 56.7 |

## Levels for Catch Basins & Pipes at 19th A - Sketch P38

| | HI 76.35 | | |
|---|---|---|---|
| 0+00 C.B. 1 | | 5.2 | 71.15 |
| 0+08 | | 4.8 | 71.55 |
| 0+35 | | 2.7 | 73.65 |
| 0+50 | | 2.5 | 73.85 |
| 1+00 | | 4.1 | 72.25 |
| 1+42 5 Connection with culvert. | | 5.1 | 71.25 |

POSTED

8/1/13 Davis Hanover Herrick

Location of Conduit from 16th & Logan to 13th & Newton




class of flow line of pipe from E curb line of 16th St. 6.2'

pipe 9.4' from end of culvert.

+73.27 = WL 16th St & R 3°02'

0'+00 - End of Old Culvert






5+48.23 P.L.-E. line Hortons Add. ΔR 0°04'2"

5+31.53 = Int with 10' line Natl Ave

On plat No. 594 L, Sta 9+49.00 P.T. is identical with Sta 9+51.07 EC of this survey, and course from this point to outlet is same as shown in this book.


13th St
14th St
P.I.
Δ 46°06'
T 42.07
L 91.38
E 8.98
R = 100
Union Oil Co
Sinclair Refining Co
Ware House
Platform
Oil Line
Telephone Line
Pole Line
Incandescent Steel Co
Pole Line
Pole Line
Pole Line

Levels over proposed Culvert line from 16th & Logan to 13th & Newton

| | + | H.I. | − | Elev. |
|---|---|---|---|---|
| | 1.39 | 13.91 | | 12.52 BM. pig N.E. 16th N. |
| 0+00 · End old Culvert Top | | | 5.2 | 8.7 |
| " " " Ext. | | | 9.3 | 4.6 |
| +16 | | | 9.2 | 4.7 |
| +16 | | | 5.3 | 8.6 |
| +35 | | | 5.4 | 8.5 |
| +56.6 = Gutr | | | 6.6 | 7.3 |
| +57.7 = Top Ct | | | 5.9 | 8.0 |
| +70 | | | 5.7 | 8.2 |
| +73.87 = W.L. 16th. | | | 6.6 | 7.3 |
| T.P | 3.47 | 12.01 | 5.37 | 8.54 |
| +79 | | | 6.4 | 6.6 |
| +87 | | | 2.9 | 9.1 |
| 1 | | | 3.5 | 8.5 |
| +50 | | | 5.6 | 6.4 |
| 2 | | | 7.1 | 4.9 |
| +50 | | | 8.0 | 4.0 |
| +70 | | | 7.9 | 4.1 |
| +84 | | | 6.3 | 5.7 |
| 3 | | | 4.6 | 7.4 |
| +20 | | | 3.3 | 8.7 |
| +45 | | | 5.5 | 6.5 |
| +50 | | | 7.3 | 4.7 |
| +56 | | | 8.9 | 3.1 |
| +60 | | | 8.1 | 3.9 |

Culv. 16th + Logan

Elev. flow line, west end 4.44
" " " East " 8.01 on South
" " " " " 8.08 " north

Gregory 11/29/16

| | H.I. 12.01 | |
|---|---|---|
| 4 | | 8.7 — 3.3 |
| +20 | | 9.8 — 2.2 |
| T.P. +76 | 8.36 | P.L. — 3.59 |
| +50 | | 8 — 3.6 |
| +70.2 = Top Ct No side 16th | | 4.0 — 3.5 |
| +71.2 Gutr " " " | | 5.6 — 2.8 |
| 5 | | 5.0 — 3.4 |
| +50 | | 5.9 — 2.5 |
| +51.8 = So Gutr North | | 6.0 — 2.4 |
| +51.5 = " Ct. " | | 5.2 — 3.2 |
| 6 | | 4.9 — 3.5 |
| +50 | | 5.2 — 3.2 |
| 7 | | 5.4 — 3.0 |
| +50 | | 5.5 — 2.9 |
| +84.4 | | 5.4 — 3.0 |
| +87 | | 7.0 — 1.4 |
| 8 | | 6.7 — 1.7 |
| +50 | | 7.0 — 1.4 |
| T.P 16th & Ed. | 6.29 | 7.41 — 7.23 — 1.18 |
| 9+10.35 = CC | | 5.2 — 2.2 |
| Top N. rail Oil Co's Track | | 4.20 — 3.4 |
| " So. " " | | 4.07 — 3.3 |
| 9+51.2 = E.C. | | 4.1 — 3.3 |
| +92 | | 4.5 — 2.9 |
| 10 | | 4.9 — 2.5 |

141

7+41

| | | | |
|---|---|---|---|
| 10+05.28 | N. Ct. Newton | 5.05 | 2.4 |
| | " Gutter | 5.3 | 2.1 |
| +27.07 | N. rail Natl City Elect line | 4.82 | 2.53 |
| | So " " " | 4.78 | 2.63 |
| +44.81 | 13' Line Newton Ave | 5.4 | 2.0 |
| +74 | | 4.7 | 2.7 |
| +76.54 | Top N. rail Stone Col Spur Track | 3.47 | 3.94 |
| | " So. " " " " | 3.60 | 3.91 |
| +84 | | 12.50 | -5.1 |
| 11 | | 12.5 | -5.1 |
| T.P | +4.59 | 8.54 | 3.45 | 3.96 |
| | | | 5.08 | 2.97+ 3" B.M. N.E. 13711 |

4+95.60 - E.C.

+66.60 C.C.

4+38 - P.C.

3+98.20

3+76.99 E.C.

3+00.29 - C.C.

+73.29 - P.C.

+37.95 E.C.

2+08.12 C.C.

+78.29 P.C.

+76.49 - E.C.

+50.31 - C.C.

1+24.13 P.C.

+37.25 - E.C.

+20 - C.C.

0+0.94 - P.C.

0+00 End 36" C.P. Culvert.

Location of Culvert from Columbia & Laurel to Connect with proposed Drain on Brickyard Canon Road at Sta 487+90 ℄

(Reynard Way)

Ctr State and Maple Man

89.38

89°58'

143.78

S 0°02' E

Δ 46°36'
R 200'
T 29.00
L 57.60
E 2.09

Δ 44°22'
R 500'
T 33.96
L 59.66
E 1.01

D 60°0'
R 50'
T 28.87
L 51.36
E 7.73

Δ 44°22'
R 500
T 1.9106
L 38.11
E 0.36

42.43

39.85

4.46

S 39°58' 12" E

5798 ℄ Laurel St

Ctr Col

7+68.13 = Connection with Canon Road Culvert

5+97.23 E.C.

+78.26 C.C

+59.49 P.C.

5+43 = Branch Culvert

B.C. Road Sta 48+86.50



Levels over line of proposed Conduit from present Conduit at State and Columbia to connect with proposed drain in B. C. Road.

I. Davis
Hannock
Horrock

| | | Left | N.I. | Ctr | Right | |
|---|---|---|---|---|---|---|
| T. P. 1 | | 0.76 | 57.09 | | | 56.33 Mon NE India Laurel |
| Y | | 2.07 | 46.08 | 13.03 | | 44.06 x |
| | | 6.34 | 46.73 | 11.69 | | 34.39 |
| 0+00 = inside bottom 36" C.P. | | | 29.83 | | | |
| +20 C.C | | | 30.5 | | | |
| +39.25 EC | | | 31.4 | | | |
| +50 | | | 32.2 | 30.8/3 | | |
| | | | 31.3 | | | |
| +54.13 PC | | | 31.6 | | | |
| +32 | | | 31.8 | | | |
| +36 | | | 32.4 | 31.25/4 | | |
| +58.21 C.C | | | 32.6 | 32.2/7 | | |
| +62 | | | 34.5 | 30.9/10 | | |
| +70 | | | 34.6 | 31.5/7 | | |
| +74.40 EC | | | 32.9 | 32.0/3 | | |
| +78.29 PC | | | 33.7 | 33.1/2 | | |
| +84 | | | 33.5 | | | |
| +88 | | | 33.2 | | | |
| +96 | | | 32.7/8 | 33.3 | | |
| 2+09.13 C.C. | | | 32.7/6 | 38.1 | | |
| T. P. | | 4.94 | 38.96 | | 2.72 | 36.01 |
| +18 | | | 33.5 | | | |
| +37.45 EC | | | 33.1 | | | |
| +37.79 PC | | | 33.8 | | | |
| 3+00.39 C.C. | | | 30.3 | | | |
| T. P. | | 8.02 | 42.53 | | 4.44 | 34.51 |

| | Left | Ctr | Right | | |
|---|---|---|---|---|---|
| 3+76.20 E.C | | 34.5 | | | |
| +87 | | 36.5 | | | |
| +90 | | 36.5 | | | |
| +70 | | 37.4 | | | |
| +96 | | 36.4 | | | |
| 4 | 36.9/2 | 37.8 | | | |
| +20 | 38.1/5 | 39.3 | | | |
| +38 P.C | 38.1/3 | 39.1 | | | |
| +66.22 C.C | 38.7/2 | 39.0 | | | |
| T.P. | 6.54 | 45.67 | | 3.45 | 39.08 |
| +82 | | 39.6 | | | |
| +95.6 E.C | | 40.6 | 39.3/3 | | |
| 5+07 | | 41.1 | 38.5/4 | | |
| +16 | | 40.6 | 39.9/2 | | |
| +43 | | 41.1 | 40.8/3 | | |
| +59.44 P.C. | | 40.4 | | | |
| +79.26 C.C. | 40.5/5 | 42.2 | | | |
| +97.80 E.C. | 41.0/5 | 42.7 | | | |
| T.P. | 1.38 | 52.61 | | 4.39 | 41.23 |
| 6+18 | 43.1/10 | 42.9 | | | |
| +32 | | 41.5 | | | |
| +35 | | 42.7 | 41.5/3 | | |
| +50 | | 46.5 | 41.6/12 | | |
| +70 | | 46.3 | | | |
| +77 | | 42.7 | 42.5/2 | | |

HI
5261

| | Left | Ctr | Right | |
|---|---|---|---|---|
| 649+ | | 47.0 | | |
| 7 | | 46.8 | 49.3 / 15 | |
| +37 | | 47.2 | | |
| +50 | | 50.1 | 46.9 / 4 | 46.2 / 10 |
| +57 | | 51.2 | | |
| +62 | | 50.5 | | |
| +64 | | 49.0 | | |
| +68 | Connecting with B.C. Road Col. | 48.0 | 46.7 / 12 | |
| | 10.47 | 59.49 | 3.57 | 49.02 |
| | 6.16 | 65.91 | 0.74 | 59.75 |
| | 2.89 | 58.41 | 10.39 | 55.52 |
| | 2.62 | 51.52 | 7.55 | 50.86 |
| ✓ | T.P. [illegible] | | 7.56 | 44.06 X |

Location of Improvements in Proposed 28th Street

9/21 Lt { Doris Hancock, Harriett E. Hancock, Emerson Fletcher



| | + | H.I. | − | Elev. |
|---|---|---|---|---|
| | 4.63 | 38.67 | | 34.04 BM N.W. Bndy Sec 18 |
| 50 Gutr | | | 5.43 | 33.24 |
| No " | | | 4.73 | 33.94 |

Location of Catch Basins Univ. Ave. bet Bancroft & Boundary



| | | | | |
|---|---|---|---|---|
| | +306, | N 289.18 | | Elev 286.12 Spike in W. Lincoln 2nd pole |
| Top end 18" Pipe | | | 10.47 | 78.71 |
| " 20 " = 0+00 | | | 12.0 | 77.18 |
| +14 | | | 4.4 | 84.8 |
| +50 | | | 4.0 | 85.2 |
| | | | 4.7 | 84.5 |
| +50 | | | 4.6 | 84.6 |
| | | | 5.1 | 84.1 |
| +50 | | | 6.3 | 82.9 |
| +62 | | | 6.3 | 82.9 |
| T. P. | 1.98 | 279.10 | 12.06 | 277.12 |
| +80.5 = Top end 12" Pipe | | | 9.9 | 69.20 |



6/12/15 { Davis, Hancock, Hermik

## Levels for Culvert at Cypress & Florida

| | + | HI | − | Elev | |
|---|---|---|---|---|---|
| | 1.59 | 237.59 | | 236.00 | B.M. S.W. Stake SW Cor Florida |
| 0+00 bot 12" C.P. | | | 10.24 | 27.35 | |
| +3 | | | 10.0 | 27.6 | |
| +7 | | | 7.5 | 30.1 | |
| +73 | | | 6.1 | 31.5 | |
| +127 | | | 7.4 | 30.2 | |
| +332 End proposed Cul. | | | 7.8 | 229.8 | |



## Levels over Line of Proposed Culvert.

| | + | HI | Elev | |
|---|---|---|---|---|
| | 2.95 | 237.20 | | 234.25 Grade Stake |
| 0+00 | | | 0.2 | 237.0 |
| +25 | | | 3.4 | 233.8 |
| +50 | | | 6.6 | 230.6 |
| +62 43 - P.C. | | | 8.3 | 228.9 |
| +75 | | | 9.9 | 227.3 |
| +95 | | | 11.0 | 226.2 |
| 1 | | | 10.4 | 226.8 |
| T.P. | 1.52 | 226.04 | 12.68 | 224.52 |
| +20 | | | 5.8<br>7.9 | 220.2<br>217.1 |
| +20: Top wall | | | 4.6 | 221.4 |
| +25 | | | 10.0 | 216.0 |
| T.P. | 0.56 | 213.69 | 12.91 | 213.13 |
| +46 67 | | | 4.6 | 209.1 |
| +50 | | | 6.3 | 207.4 |
| +75 | | | 12.0 | 201.7 |
| T.P. | 0.49 | 201.49 | 12.69 | 201.00 |
| 2 | | | 4.8 | 196.7 |
| +68 2 | | | 11.1 | 190.4 |

## Location of Proposed Culvert on Curlew St Near Robinson

6 / 26 / 15 { Doris, Hancock, Herrick

Note: Intersection Alley & 1st should be cleared out as it will drain west down canon. Culvert should be placed across Robinson on east side of 1st. If this is not done this culvert should be a 16" pipe.



## Levels over Line of Proposed Culvert

| | + | HI | − | Elev |
|---|---|---|---|---|
| | 0.67 | 170.91 | | 170.24 BM Nub 7' E Elm Curlew * |
| T.P | 1.51 | 169.88 | 12.54 | 158.37 |
| 0+00 | | | 6.0 | 153.9 |
| +25 | | | 6.6 | 153.3 |
| +50 | | | 7.8 | 152.1 |
| +75 | | | 8.7 | 151.2 |
| +85 | | | 8.5 | 151.4 |
| +90 | | | 7.2 | 152.7 |
| 1+00 | | | 6.6 | 153.3 |
| +25 | | | 7.7 | 152.2 |
| +50 | | | 9.6 | 150.3 |
| +55 | | | 9.5 | 150.4 |
| +61 | | | 7.1 | 152.8 |
| +75 | | | 7.3 | 152.6 |
| +92 | | | 8.2 | 151.7 |
| 2+00 | | | 10.2 | 149.7 |
| +09.76 | | | 11.7 | 148.2 |

## Cross Section for fill across Culvert at Intake

| | | | |
|---|---|---|---|
| 8' E Ctr Cul. | | 2.9 | 157.0 |
| Ctr | | 6.0 | 153.9 |
| 10' W | | 5.1 | 154.8 |
| 25' W | | 2.9 | 157.0 |

Note Fill should be about 8' wide on top. Elev top fill 157.00

## Location of Proposed Culvert on W. Side of Curlew at Mission



6 Davis
7 Hancock
15 Herrick

## Levels over Line of Proposed Culvert

| + | M' | − | Elev |
|---|---|---|---|
| 0.55 | 142.72 | | 142.17 BM Hub 25 E Curlew x |
| 25 E of Intake | | 1.7 | 141.0 |
| 0+00 | | {2.7<br>4.4 | 140.0<br>138.3 |
| + 11 | | 4.7 | 138.0 |
| + 12 | | 5.5 | 137.2 |
| + 30 | | 5.2 | 137.5 |
| + 49 | | 6.4 | 136.3 |
| + 51 | | 5.6 | 137.1 |
| + 61 | | 5.3 | 137.4 |
| + 71 | | 12.7 | 130.0 |

## Location of Proposed Culvert Across Curlew St at Walnut




Note Ditch 2' wide should be dug from intake to a point 25' E

| | + | H.I. | − | Elev. |
|---|---|---|---|---|
| | | | | 298.02 B.M. Spk Pole SW Cypress P.Blvd. |
| | 2.35 | 300.37 | | |
| | 0.89 | 290.33 | 10.93 | 289.44 |
| | 0.36 | 277.75 | 12.94 | 277.39 |
| | 3.50 | 268.84 | 12.41 | 265.34 |
| 0+00 = Toe Slope | | | 10.4 | 258.4 |
| +25 | | | 9.7 | 259.1 |
| +46.64 | | | 8.1 | 260.7 |
| +64.11 = P.C. | | | 6.8 | 262.0 |
| +75 | | | 6.7 | 262.1 |
| 1+00 | | | 5.5 | 263.3 |
| +21.20 E.C. | | | 4.8 | 264.0 |
| +25 | | | 4.6 | 264.2 |
| +50 | | | 3.6 | 265.2 |

7 Davis
30 Hancock
15 Herrick

59

Location of Proposed Culvert - Herbert & Myrtle Sts



| | + | H.I. | - | Elev. |
|---|---|---|---|---|
| | 0.09 | 87.25 | | 86.91 BM NE India Spruce |
| T.P | 0.42 | 74.54 | 12.93 | 74.12 |
| T.P | 0.17 | 62.10 | 12.61 | 61.93 |
| | 4.99 | 58.11 | 1.98 | 53.12 |
| 0+00 - Toe Slope | | | 5.8 | 52.3 |
| +22 | | | 7.0 | 51.1 |
| +29 | | | 4.6 | 53.5 |
| +42.33 - Ctr Arctic | | | 3.6 | 54.5 |
| +52 | | | 5.0 | 53.1 |
| +63 | | | 10.3 | 47.8 |
| +89.18 - Toe Slope | | | 10.8 | 47.3 |

4 Davis
30 Hancock
15 Herrick

60

Location of Proposed Culvert Across Arctic St bet Rwid & Spruce

Spk Pole



2 + 42 45 : End 36" C.P. Culvert
+ 35 66 : End outlet

475 ft : 6" V.t Sewer pipe
1471 ft E.C.

1+50 85 P.C

1+35 07 E.C.

1+00 51 P.C.

0+77 18 E.C.

0+52 77 P.C
0+51 : 6" Sewer
0+45 : E Pipe Trestle

0+19 25 : opp. end mud sill

0+00

Location of Proposed Culvert - Kalmio St Arctic to India.



Levels over Proposed Culvert on Kalmia St. Arctic to India

8/3/15 Davis, Hamerik, Hamrie

| | | | | |
|---|---|---|---|---|
| | 0.22 | 46.67 | | H6.46 BM Top Hydt S.E. India & Kalmia |
| T.P | 0.46 | 34.04 | 12.89 | 33.78 |
| T.P | 0.12 | 21.16 | 13.00 | 21.04 |
| T.P. | 4.97 | 14.21 | 11.92 | 9.24 |
| 0+00 = End 4'x4' Concrete Cul. (bottom) | | | 8.20 | 6.01 |
| +16 | | | 6.7 | 7.5 |
| +19.5 Top mud Sill | | | 5.6 | 8.6 |
| +26 | | | 4.3 | 9.9 |
| +32 = Ctr R.R. | | | 4.9 | 9.3 |
| +48 = Ctr Pipeline | | | 4.7 | 9.5 |
| +51 = Top 6" Kalamein sewer pipe | | | 5.65 | 8.56 |
| +52.22 = P.C. | | | 5.4 | 8.8 |
| +77.43 = E.C. | | | 6.2 | 9.0 |
| 1+00.51 = P.C. | | | 5.0 | 9.2 |
| T.P | 8.03 | 17.27 | 4.97 | 9.24 |
| +35.07 = E.C. | | | 8.1 | 9.2 Ctr 9.3 1.0 No 11.7 2.0 No. |
| +50.25 P.C. | | | 7.5 | 9.8 Ctr 14.6 2.0 No. |
| Top 14" Vit. Sewer Pipe | | | 6.9 | 10.4 |
| +71.19 E.C. | | | 7.2 | 10.1 |
| Top 6" Vit. Sewer Pipe | | | 6.7 | 10.6 |
| 2+00 | | | 6.2 | 12.1 |
| +25 | | | 4.4 | 12.9 |
| +32 | | | 5.2 | 12.1 |
| +38.81 | | | 0.9 | 16.4 |
| +42.15 | | | 0.87 | 16.40 |

Preliminary Levels Old Town Storm Drain

| | 5.02 | 17+ 11.06 | | Cor Mon SW Taylor & Chestnut |
|---|---|---|---|---|
| 0+00 S.E. Taylor & Whitman | | | 5.7 | 5.4 |
| 1 | | | 5.7 | 5.2 |
| 2 | | | 5.7 | 5.4 |
| 3 | | | 4.0 | 6.1 |
| 4 | | | 4.0 | 7.1 |
| 5 | | | 1.8 | 9.3 |
| T.P. | 7+9 | 17.75 | 0.60 | 10.46 |
| 6 | | | 4.5 | 11.3 |
| +31 Δ 47° 30' | | | 4.5 | 13.0 |
| 7 | | | 5.1 | 12.7 |
| 8 | | | 4.3 | 13.6 |
| 9 | | | 2.6 | 15.2 |
| +10 | | | 2.6 | 15.2 |
| +60 | | | 17.0 | 0.75 |



0+00

0+07.5 - No 7 Line

1+77.5 - ℄ Track
1+41.5 "
1+55.2 " "



NE. 10 " M. 7.48
B.M. SE. 9th & M. Plug. 5.01

0+00

0+96
1+08

1+40 07

1+55 70

1+87 89

1+74 92 △

1+69

Location of Drain foot of 8th St

Note: In connection with this drain there should be drains placed on the east side of 8th St across "L" & "M" Sts.




65

Levels over Line of Proposed 8th St Storm Drain

| | | | | |
|---|---|---|---|---|
| | 2.03 | 10.72 | | 8.69 |
| | 2.97 | 7.89 | 6.30 | 4.92 |
| 0+00 | | | 6.0 | 1.4 |
| +96 - Rail Elev. | | | 5.72 | 1.69 |
| +40.07 | " | " | 5.71 | 1.68 |
| +50 | | | 5.9 | 1.5 |
| +55.75 | " | " | 5.65 | 1.74 |
| +78 | | | 6.1 | 1.3 |
| +87.59 | | | 6.8 | -1.4 |
| 1+00 | | | 8.6 | -1.2 |
| +20 | | | 10.6 | -3.2 |
| +33 | | | 6.9 | 0.5 |
| +50 | | | 6.9 | 0.5 |
| +74.92 | | | 6.8 | 0.6 |
| T.P. | 4.43 | 5.02 | 6.80 | 0.59 |
| 2 | | | 4.6 | 0.4 |
| +50 | | | 4.4 | 0.6 |
| 3 | | | 3.1 | 1.9 |
| +50 | | | 2.7 | 2.3 |
| 4 | | | 3.8 | 1.2 |
| +45 | | | 4.9 | 0.1 |
| +59 - Bottom bay | | | 13.6 | -8.6 |

Offsets - Hubs - 2' East & 2' S. of ℄ Pipe.

0.89% Gr.

| Stg. | + | HI | - | Elev | Bot. Gr. | Cuts |
|---|---|---|---|---|---|---|
| BM SE 9th & N. Flag | | | | 5.01 | 3.00 Curb 2.34 Gutter | |
| 75' Hub 10' E. of Grade | 4.42 | 9.43 | 7.38 | 2.05 | | |
| | 3.75 | 5.80 | | | | |
| 0+00 | | | 4.98 | 1.72 | - 1.32 | 3.0 |
| +50 | | | 4.28 | 1.52 | - 1.72 | 3.24 |
| 1+00 | | | 4.75 | 1.05 | - 2.12 | 3.17 |
| +50 | | | 4.45 | 1.35 | - 2.52 | 3.82 |
| +75.7 MH. | | | 5.30 | 0.50 | - 2.73 | 3.23 |
| 2+00 | | | 4.98 | 0.82 | - 2.92 | 3.74 |
| +50 | | | 5.21 | 0.59 | - 3.32 | - 3.91 |
| 3+00 | | | 3.86 | 1.94 | - 3.72 | 5.66 |
| +50 | | | 3.35 | 2.45 | - 4.12 | 6.57 |
| 4+00 | | | 4.80 | 1.00 | - 4.52 | 5.5 |
| +50 | | | 5.27 | 0.53 | - 4.92 | 5.45 |
| +70 | | | 5.45 | 0.15 | - 5.08 | 5.23 |
| +80 toe fill water | | | | | - 5.16 | |

Note last 20ft should be iron pipe.

E 27 { Davis, Hancock, Herriak

## Levels for Torrence St Culvert

| Sta | + | HI | − | Elev. | |
|---|---|---|---|---|---|
| | 0.49 | 264.53 | | 264.03 | B.M. Pig in Ct on Dr. Encircled Manhole Rim + M.T. Add |
| T.P. | 1.10 | 252.76 | 12.87 | 251.66 | |
| 0+00 | | | 0.5 | 252.3 | |
| +50 | | | 3.1 | 249.7 | |
| +56 | | | 8.5 | 244.3 | |
| T.P. | 0.08 | 240.06 | 12.78 | 239.98 | |
| +77 | | | 7.1 | 233.0 | |
| +92 | | | 12.0 | 228.1 | |
| 3'E | | | 12.9 | 227.2 | |
| T.P. | 0.04 | 227.26 | 12.84 | 227.22 | |
| 1+00 | | | 3.2 | 224.1 | |
| +05 | | | 7.8 | 219.5 | |
| +15.22 | | | 11.66 | 215.60 | on hub |
| T.P. | 0.05 | 214.41 | 12.90 | 214.36 | |
| 1+26 | | | 1.5 | 212.9 | |
| 3'E | | | 3.7 | 210.7 | |
| +38 | | | 7.3 | 207.1 | |
| 3'E | | | 7.8 | 206.6 | |
| +42 | | | 10.0 | 204. | |
| +52 | | | 11.9 | 202.5 | |
| 2'S. | | | 13.2 | 201.2 | |
| T.P. | 0.10 | 201.79 | 12.72 | 201.69 | |
| +04 | | | 0.8 | 201.0 | |
| 5'E | | | 4.5 | 197.3 | |
| +76 | | | 4.9 | 196.9 | |
| 8'E | | | 6.7 | 195.1 | |
| +86 | | | 5.9 | 195.9 | |
| 11'E | | | 9.9 | 191.9 | |

## Location of Culvert on Torrence St

E 27 15 { Davis, Hancock, Herriak




| Sta | + | HI | − | Elev. |
|---|---|---|---|---|
| 1+97 | | 201.79 | 9.2 | 192.5 |
| 7'E | | | 12.6 | 189.3 |
| 2+14 | | | 15.7 | 186.1 |
| +27 | | | 16.4 | 185.4 |

9/11/15
Gregory
Moore
Miller

# LEVELS FOR CULVERT ON MONROE AVE Between Florida & Alabama Sts

| | | | | | |
|---|---|---|---|---|---|
| B.M. | | 2.33 | 326.93 | | 324.60 SE Alabama & Florida |
| T.P. | | 6.95 | 324.12 | 9.76 | 317.17 |
| 0.0 = 6.6' No. of N.L. MONROE = Inlet. | | | | 6.2 | 317.9 |
| + 6.6 = N.L. MONROE | | | | 6.3 | 317.8 |
| + 44.6 = 18'50 of " " | | | | 7.2 | 316.9 |
| + 46.6 = Ctr of MONROE | | | | 7.5 | 316.6 |
| + 68.6 = 62'50 of N.L. " | | | | 7.2 | 316.9 |
| + 86.6 = S.L. of MONROE | | | | 8.1 | 316.0 |
| + 95.6 = 9'50 " " " = Outlet for MONROE | | | | 8.3 | 315.8 |

NOTES for CONTINUATION OF CULVERT TO CLEAR MISSION

| | | |
|---|---|---|
| 47'50 of S.L. MONROE | 9.2 | 314.8 |
| 57.58' " " " = S.L. MISSION | 9.3 | 314.8 |
| 9.8' " " " " = OUTLET | 9.4 | 314.7 |
| 15' N. of N.L. of MONROE | 5.8 | 318.3 |
| 86' N. of N.L. of MONROE on ℄ Culv prod. | 4.2 | 319.9 |
| 75' W of above pt | 6.1 | 318.0 |
| 20' " " ℄ of Culv on N.L. MONROE | 6.8 | 317.3 |
| 75' " " " " " " | 6.6 | 317.5 |

LOCATION OF CULVERT ON MONROE AVE BET ALABAMA & FLORIDA



## Levels for Proposed Culvert at Thorn & Dale Sts

2/21/16 Grade Plan Thorn

| Sta | + | H.I. | − | Elev. |
|---|---|---|---|---|
| | 0.39 | 319.78 | | 318.39 Pig Nail Dale & Thorn |
| 0+00 | CB #1 | | 1.3 | |
| +33 | | | 0.5 | |
| +66 | CB #3 | | 1.2 | |
| 0+00 | CB #2 = bot present pipe | | 1.9 | |
| 0+00 | Top " " | | 0.3 | |
| +30 | | | 0.8 | |
| +49 | CB #2 | | 1.7 | |
| +60 | = S. Line Thorn: 0+00 | | 1.5 | |
| +25 | | | 3.9 | |
| +50 | | | 6.1 | |
| +79 | | | 7.3 | |
| +89 | | | 12.6 | |
| 1+00 | | | 14.1 | |
| +07 | | | 12.8 | |
| +15 | | | 13.2 | |
| +18 | | | 17.7 | |
| +23 | | | 17.7 | |
| +28 | | | 14.8 | |
| +28 Bot | | | 18.67 | |



# Location of Culverts Old Town

| | | | | | |
|---|---|---|---|---|---|
| | 4.98 | 11.02 | | Cut B.M. Mon. & w/ Taylor & Chestnut | |
| T.P. | 7.24 | 7.70 | 5.46 | 5.46 | |
| | 7.60 | 8.40 | 1.90 | 5.80 - Hub Ch. S.D.Ave. & Taylor St. | |

"A" Line

| | L | C | | R | Grade |
|---|---|---|---|---|---|
| 0+00 | | | 0.8 | | 0.80 |
| +50 | | 0.4 / 24 | -0.2 | 0.7 / 4 | 0.58 |
| 1 | | 0.4 / 19 | -1.4 | 0.3 / 6 | 0.36 |
| +50 | | 0.4 / 28 -0.6 / 6 | -1.8 | 0.7 / 7 | 0.14 |
| 2 | | 0.3 / 20 -1.0 / 5 | -2.1 | 0.4 / 7 | -0.08 |
| +40 | | 0.4 / 5 | -0.8 | 0.3 / 6 | -0.75 |
| +50 | | | 0.3 | | -0.29 |
| +60 | | | 4.2 | | -0.34 |
| +69 | | | 5.6 | | -0.38 |
| +76 | | | 4.9 | | -0.41 |
| +90 | | | 0.5 | | -0.47 |
| 3+00 | | | 0.8 | | -0.51 |
| +25 | | | 0.6 | | -0.62 |
| +50 | | | 0.4 | | -0.73 |
| +63 | | | -0.4 | | -0.79 |
| +65.6 | | | -2.8 | | -0.80 |
| East end box culvert | | | -0.69 | | |
| West " | | | -0.80 | | |
| 0+00 "B" Line | 1.0 / 15 | 0.4 / 11 -1.2 / 10 | -2.8 | -1.4 / 4 | -0.80 |
| +08 | 0.7 / 10 | 1.0 / 4 -0.3 / 3 | -1.4 | 0.5 / 4 0.7 / 8 | -0.80 |
| +50 | 0.3 / 10 | 1.4 / 4 0.7 / 2 | -0.6 | 0.5 / 3 2.3 / 8 | -0.82 |



F.40

B Line

| | L | | | C | | R | Grade |
|---|---|---|---|---|---|---|---|
| 1+00 | 0.3/10 | 0.6/3 | -0.7/2 | -0.4 | | 1.3/8 | -0.84 |
| +50 | 0.2/10 | | | 0.8 | | 1.1/10 | -0.86 |
| 2 | | 0.1/10 | 0.3/1 | -0.3 | | 0.7/10 | -0.88 |
| +50 | | 0.3/15 | | 0.0 | | 0.3/10 | -0.90 |
| 3 | | -0.3/10 | -0.4/3 | 0.1 | | 0.2/10 | -0.92 |
| +50 | | 0.1/10 | -0.7/4 | -0.1 | 0.4/5 | -0.4/10 | -0.94 |
| T.P | 6.94 | | 7.27 | 8.07 | | 0.33 | |
| 4 | | -0.5/12 | -0.9/10 | -0.8 | 0.0/5 | -0.3/10 | -0.96 |
| +50 | | -0.2/15 | | -1.2 | -0.6/5 -0.1/7 -1.8/11 -0.2/15 | | -0.98 |
| 5 | | -0.6/15 | -0.5/12 | -1.3 | -0.4/8 -1.1/12 -0.3/15 | | -1.00 |
| +50 | | -0.3/27 | -1.3/15 | -1.6 | -1.7/5 -1.9/10 -0.9/17 | | -1.02 |
| 6 | 0.2/50 | -0.3/40 | -1.1/30 | -1.8 | -1.3/7 -1.6/15 -0.5/17 | | -1.04 |
| +50 | -0.3/75 | -0.9/67 | 0.1/40 -0.7/24 -2.0/10 | -1.3 | -1.9/12 -0.4/18 -0.3/20 | | -1.06 |
| 7 | | -0.4/73 | -1.9/30 | -2.2 | -1.6/6 -2.3/12 -0.2/20 | | -1.08 |
| +27 | | -0.4/80 | -1.8/40 | -0.4 | -1.5/12 1.0/20 | | -1.09 |
| +33 | | | | 0.4 | 4.7/25 | | -1.10 |
| +42 | 0.7/52 | -0.5/75 | -0.4/40 -0.5/13 | 0.7 | 4.8/25 | | -1.10 |
| +58 | | | | 0.3 | 4.4/25 | | -1.10 |
| +55 | 0.0/81 | -0.8/60 | -0.7/15 | 0.3 | 1.5/24 | | -1.11 |
| +72 | 0.1/100 | -0.9/40 | -0.3/15 | -0.8 | -1.2/14 1.0/24 | | -1.11 |
| 8 | 0.0/100 -0.8/50 | -0.3/50 | -2.7/27 -2.0/15 | -1.7 | -0.6/20 4.2/24 | | -1.12 |
| +50 | 0.4/130 -0.4/120 | -0.4/100 | -0.6/50 0.0/30 -0.8/10 | -1.4 | -0.8/11 -0.2/22 1.6/25 | | -1.14 |
| 9 | 0.0/115 -1.0/110 | -1.0/85 | -0.5/40 -0.7/13 | -1.4 | -0.7/22 0.1/25 | | -1.16 |
| +50 | 0.0/140 -0.3/130 | -0.9/110 | -0.4/74 -0.8/45 | -1.9 | -0.8/12 -1.0/22 1.4/27 | | -1.19 |
| T.P | 5.27 | | 4.93 | 7.61 | | -0.34 Nail telpole Sta 9+10 | |

Continued on P. 74



Levels over ℄ Wagen Road over Santa Fe Track at Sta 7+40 B Line

14.1
7.27

| | | |
|---|---|---|
| 0+00 ℄ Santa Fe | 1.4 | 5.9 |
| 6' W | 1.7 | 5.6 |
| 38 " | 6.5 | 0.8 |
| 50 | 7.2 | -0.5 |
| 1.00 | 8.0 | -0.7 |
| 1.15 | 7.5 | -0.2 |
| 1.25 | 6.7 | 0.6 |
| 8' E | 1.7 | 5.6 |
| 20 " | 2.1 | 4.2 |
| 4.35+ | 6.4 | 0.9 |
| 50 " | 6.6 | 0.7 |
| 100 " | 6.4 | 0.9 |

7.27

"C" Line

| | L | | C | | | R | |
|---|---|---|---|---|---|---|---|
| 0+00 | | 16/15 | -0.3/9 | 1.8 | | | +0.39 |
| +50 | | 1.0/15 | 0.0/8 | 1.8 | | | +0.29 |
| 1 | | 1.1/19 | -0.3/8 | 1.6 | | | + 0.19 |
| +50 | | 0.7/16 | -0.4/7 | 0.9 | | | + 0.09 |
| +95 | | | | | | | 0.0 |
| 2 | | 1.0/25 | -0.6/15 | -1.0/7 | -0.1 | 0.4/6 | - 0.01 |
| +50 | | 0.8/24 | -0.5/15 | -1.3/8 | -1.0 | -0.8/4 0.0/6 | -0.11 |
| 3 | | 0.6/25 | -3.2/22 | -1.1/15 | -1.5/6 -1.4 | -0.5/6 0.0/8 | -0.21 |
| +50 | | 0.3/24 | -2.1/18 | -1.1/14 | -1.4 | -0.9/10 -0.1/11 | -0.31 |
| 4 | | 1.2/25 | -2.2/20 | -0.3/14 | -1.2 | -1.1/15 0.5/30 | -0.41 |
| +50 | | 1.0/24 | -0.6/20 | -0.2/14 | -0.5/7 -0.3 | 0.5/20 0.9/40 | -0.50 |
| +95 | | 1.6/25 | -0.2/21 | 1.1/10 | 1.0 | | -0.59 |
| 5 | | 1.2/25 | 2.3/12 | | 0.9 | 0.6/10 0.9/30 | -0.60 |
| +15 | | 1.4/20 | | | 0.7 | 0.9/10 0.7/25 | -0.63 |
| +29 | | 1.2/16 | -0.3/12 | | -1.3 | -0.8/18 -0.7/20 | -0.66 |
| +50 | | 0.6/18 | -1.2/8 | | -2.0 | -1.5/7 -0.3/23 | -0.70 |
| 6 | | 0.3/18 | -1.2/9 | | -1.3 | -1.3/9 0.2/20 | -0.80 |
| +50 | | 0.5/22 | -1.3/9 | | -1.4 | -1.1/7 -0.1/15 0.9/20 | -0.70 |
| 7 | | 0.0/24 | -1.0/12 | | -1.6 | -1.1/8 0.9/23 1.4/27 | -0.60 |
| T.P. | 4.23 | 4.99 | | 6.51 | | 0.76 | |
| +50 | | 1.0/25 | -0.5/19 | | -1.1 | -0.7/17 -0.7/31 0.5/40 | -0.51 |
| 8 | | 1.1/25 | 0.3/22 | | -0.8 | -0.7/11 0.4/30 | -0.41 |
| +50 | | 1.3/22 | -0.9/16 | | -1.3 | -1.4/20 -0.1/30 0.7/35 | -0.31 |
| 9 | 1.5/20 | 0.3/18 | -1.7/5 | | -1.3 | 1.0/32 | -0.21 |
| +50 | | 1.2/14 | -1.0/5 | | -1.1 | -1.1/9 0.7/22 | -0.12 |
| 10 | | | 1.1/12 | | -0.9 | 0.8/7 | -0.02 |
| +10 | | | | | | | 0.0 |
| +20 | | | | | 1.0 | | |

14.
7.27

73

Levels over the Proposed Culvert Across Santa Fe Track

| | | |
|---|---|---|
| 0+00 = Sta 6+00 "C" Line | 8.6 | - 1.3 |
| +09 | 8.4 | - 1.1 |
| +22 | 6.3 | 1.0 |
| +34 | 2.5 | 4.8 |
| +41 | 1.6 | 5.7 |
| +49 | 2.3 | 5.0 |
| +60 | 8.2 | - 0.9 |
| +80 = Int with "B" Line | 9.0 | - 1.7 |

4.9.3

"B" Line

| Stg | L | C | R | Grade |
|---|---|---|---|---|
| 10+00 | 0.6/120 -1.2/100 -0.1/50 -0.7/20 | -1.9 | -2.3/20 -1.1/25 0.3/28 | -1.71 |
| +50 | 0.0/120 -1.2/100 -0.2/60 -0.7/30 -1.9/15 | -1.8 | -1.1/20 -1.2/28 0.6/32 | -1.23 |
| 11 | 0.1/90 -1.2/70 -0.5/30 | -1.7 | -2.0/15 -2.0/33 -0.9/40 1.1/45 | -1.25 |
| +50 | 0.0/80 -0.7/60 -0.3/45 -1.3/20 | -0.8 | -2.0/20 -1.6/40 1.7/45 | -1.27 |
| 12 | 0.1/80 -1.3/35 -0.6/30 | -1.0 | 0.0/15 -1.9/35 -1.5/44 1.0/45 | -1.29 |
| +50 | 0.0/65 -1.0/35 | -0.5 | -0.3/15 -2.1/35 -1.8/45 0.6/0.0 | -1.31 |
| 13 | 0.0/60 -0.9/30 -0.3/18 | -0.7 | 0.2/25 -1.5/40 -1.9/50 -1.5/55 1.3/60 | -1.33 |
| PC +13.20 | 0.0/65 | -0.6 | 1.1/30 -1.6/45 -2.3/45 0.9/60 | -1.33 |
| +50 | -0.3/50 -1.3/35 -0.5/15 | -0.5 | -1.1/20 0.0/40 | -1.35 |
| 14 | -0.2/45 | -1.0 | -1.1/15 0.0/25 | -1.37 |
| +50 | 0.0/40 | -1.6 | 0.0/60 | -1.39 |
| 15 | -0.1/30 | -1.0 | -0.8/45 -0.3/90 | -1.41 |
| +50 | 0.1/25 | -1.0 | -1.1/45 -1.5/90 -0.3/130 | -1.43 |
| 16 | -0.7/10 | -0.8 | -1.2/40 -1.9/80 -0.4/85 | -1.45 |
| EC. +16.29 | -0.6/10 | -0.6 | -1.0/35 -1.5/70 -0.5/75 | -1.45 |
| +50 | -0.4/10 | -0.4 | -0.8/25 -1.5/65 -0.5/60 | -1.47 |
| 17 | -1.0/10 | -1.0 | -1.0/30 -1.2/45 -0.5/60 | -1.49 |
| +50 | -1.3/10 | -1.4 | -1.0/15 -1.3/30 -0.4/35 | -1.51 |
| T.P. | 5.16 3.85 | 42 | -1.31 | |
| 18 | | -1.5 | | -1.53 |
| +50 | | -1.5 | | -1.55 |
| 19 | | -1.3 | | -1.57 |
| +50 | | -1.1 | | -1.59 |
| 20 | | -1.7 | | -1.61 |

3.85

| | | Grade |
|---|---|---|
| +50 | -1.7 | -1.63 |
| 21 | -1.7 | -1.65 |
| +50 | -1.7 | -1.67 |
| 22 | -1.9 | -1.69 |
| +16 | -2.9 | -1.70 |
| +40.75 End K.K. Cul. | -1.71 | -1.71 |
| Last " " " | -1.85 | |
| B.M. Nail N.E. Cor Culvert Top | 0.47 | |

Levels over ℄ proposed Culvert on 16th St from present Culvert at Logan Ave to E. Line Hartupee Tract

10 Davis
17 Hancock
16 Herrick

| Sta | + | H.I. | − | Elev. |
|---|---|---|---|---|
| | 795 | 11.75 | | 380 Bm Pkg in N Side Stob |
| 0 + 00 | Bottom present Cul | | 7.3 | 4.5 |
| | Top " " | | 3.4 | 8.4 |
| + 10 | | | 7.0 | 4.8 |
| + 14 | | | 3.5 | 8.3 |
| + 25 | | | 3.5 | 8.3 |
| + 50 | | | 3.9 | 7.9 |
| + 75 | | | 4.2 | 7.6 |
| 1 | | | 4.7 | 7.1 |
| + 25 | | | 5.7 | 6.1 |
| + 50 | End Sidewalk | | 4.8 | 7.0 |
| + 75 | | | 5.2 | 6.6 |
| 2 | | | 5.5 | 6.3 |
| + 096 | End Sidewalk | | 5.7 | 6.1 |
| + 25 | | | 6.0 | 5.8 |
| + 50 | | | 6.2 | 5.6 |
| + 75 | | | 6.3 | 5.5 |
| + 86 | | | 6.2 | 5.6 |
| + 92 | | | 6.8 | 5.0 |
| 3 | | | 6.9 | 4.9 |
| + 02 | | | 6.9 | 4.9 |
| | | | 7.3 | 4.6 |
| + 25 | | | 7.3 | 4.6 |
| + 42.5 | 53' 13' Line Not Ⅱ | | 7.6 | 4.2 |
| + 50 | | | 7.7 | 4.1 |
| + 75 | | | 8.0 | 3.8 |

Location Proposed Culvert on 16th St.



| Sta | + | HI 11.75 | − | Elev |
|---|---|---|---|---|
| 4+00 | | | 8.4 | 3.4 |
| T.P. | 3.67 | 7.07 | 8.30 | 3.45 |
| +25 | | | 4.3 | 2.8 |
| +50 | | | 4.3 | 2.8 |
| +75 | | | 4.6 | 2.5 |
| 5 +00 | | | 4.9 | 2.2 |
| +25 | | | 4.7 | 2.4 |
| +50 | | | 5.7 | 1.4 |
| +75 | | | 6.2 | 0.9 |
| 6 | | | 5.5 | 1.6 |
| +25 | | | 5.7 | 1.4 |
| +50 | | | 5.4 | 1.7 |
| +75 | | | 4.7 | 2.4 |
| 7 | | | 5.0 | 2.1 |
| +16.3: ℄ N.C. Elect Ry | | | 5.2 | 1.9 |
| +22.7: ℄ Line Newton | | | 5.2 | 1.9 |
| +30 | | | 5.3 | 1.8 |
| +50 | | | 6.2 | 0.9 |
| +53 | | | 7.8 | -0.7 |
| +75 | | | 8.3 | -1.2 |
| 8 | | | 8.1 | -1.0 |
| +25 | | | 8.3 | -1.2 |
| +50 | | | 8.4 | -1.3 |
| +58.4: P.L. | | | 8.4 | -1.3 |
| +75 | | | 8.2 | -1.1 |

| Sta | + | HI | − | Elev |
|---|---|---|---|---|
| 9 | | | 10.3 | -3.7 |
| +25 | | | 10.6 | -3.5 |
| +50 | | | 10.7 | -3.6 |
| +75 | | | 10.9 | -3.8 |
| 10+00 | | | 11.0 | -3.9 |
| +25 | | | 11.1 | -4.0 |
| +50 | | | 11.1 | -4.0 |
| +75 | | | 11.1 | -4.0 |
| 11 | | | 11.1 | -4.0 |
| +25 | | | 11.2 | -4.1 |
| +50 | | | 11.1 | -4.0 |
| +75 | | | 11.1 | -4.0 |
| 12 | | | 11.4 | -4.3 |
| +13 | | | 11.4 | -4.3 |
| +15: water | | | 12.1 | -5.0 |

Levels over ℄ Proposed Storm Drain from 12 (Davis 23) Hancock 7 Harrick
N.E. Cor 9th & N Sts to Bay.

| Sta | + | Ht. | − | Elev. |
|---|---|---|---|---|
| | 2.79 | 7.80 | | 5.01 BM. Pgrt S.E. 9th & N. |
| 0+00 | | | 5.3 | 2.5 |
| +08 | | | 4.9 | 2.9 |
| +26 | | | 4.9 | 2.9 |
| +50 | | | 5.1 | 2.7 |
| +52.7 | | | 5.0 | 2.8 |
| +55.10 | | | 5.1 | 2.7 |
| +66.6 | | | 5.1 | 2.7 |
| +76 | | | 5.1 | 2.7 |
| +84.2 | | | 5.0 | 2.8 |
| +89.3 | | | 5.1 | 2.7 |
| 1+00 | | | 5.5 | 2.3 |
| +25 | | | 5.6 | 2.2 |
| +50 | | | 5.9 | 1.9 |
| +75 | | | 6.2 | 1.4 |
| +90 | | | 6.9 | 0.9 |
| +98 | | | 6.0 | 1.8 |
| 2+08 | | | 7.2 | 0.4 |
| +15 | | | 9.0 | −1.2 |
| +25 | | | 9.9 | −2.1 |
| +50 | | | 11.2 | −3.4 |
| +70 | | | 12.6 | −4.8 |

0+00 − 3' below curb
Grade − 0.8'

18" pipe
2 7/8" thick

Location of Proposed Storm Drain 9th & N Sts.



11/20/6
Gregory
Moore
Miller

Location of Tracks, at
14th & N STs




693 NE 14th & M

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 352 | 356 | 360 | 376 | 391 | 330 | 324 | 317 | 320 |
| 4.33 | 4.29 | 4.25 | 4.09 | 3.94 | 4.53 | 4.61 | 4.68 | 4.64 |

1252 NE 16th & N 4.45 4.26
23 8.30 8.47
1275

Elev of bottom of 4"x6" mudsill at S.E. cor of bldg = 8.30'
Elev of ditto center of So Side bldg = 8.28
Elev of ditto SW cor bldg = 8.47
This mudsill is the lowest point of foundation on bldg.



Cuts for Drain - 9th & N to Bay

1/18/17 Davis, Hancock, Harrison

| Sta | R.R. | Ground | Grade | ± |
|---|---|---|---|---|
| | 2.47 | 7.48 | | 5.01 S.E 9th & N |
| 0+00 | 5.00 | 2.48 | −1.50 | +4.0 |
| +25 | | | | |
| +36 ± Pipe | 4.16 | 3.33 | −1.70 | +5.03 |
| +51 | 4.73 | 2.75 | −1.90 | +4.65 |
| +80 ± Pipe | | | | |
| +83 | 5.24 | 2.24 | −2.16 | +4.40 |
| 1+00 | 5.11 | 2.37 | −2.30 | +4.67 |
| +25 | 5.38 | 2.10 | −2.50 | +4.6 |
| +40 ± C.P. | | | | |
| +50 | 5.61 | 1.87 | −2.70 | +4.57 |
| +60 ± M.H. | | | | |
| +75 | 6.41 | 1.07 | −2.90 | +4.0 |
| 2+00 | 7.47 | 0.01 | −3.10 | +3.1 |
| +20 | 9.97 | −2.49 | −3.26 | +0.77 |
| | 5.43 | 7.30 | | 1.87 |
| 0+00 · Top Ch. | | 2.48 | × 0.17 | +2.31 |
| +25 | | 3.33 | | |
| +36 ± | 7.05 | | × 0.25 Top pipe | |
| | | | × 0.08 Grade | 2" below pipe |
| +51 | | 2.75 | −0.11 | +2.86 |
| +80 Pipe | | | −0.50 | Pipe |
| +83 | | 2.24 | −0.55 | +2.79 |
| 1+00 | | 2.37 | −0.85 | +3.22 |
| +25 | | 2.10 | −1.30 | +3.40 |
| +43 ± C.P. | 8.97 | | −1.62 | = bell of C.P. |
| +50 | | 1.87 | −1.97 | +3.79 |
| +60 | 5.61 | 1.69 | −2.10 | +3.79 |
| +75 | | 1.07 | −2.36 | +3.43 |
| 2+00 | | 0.01 | −2.80 | +2.81 |
| +40 | | −2.49 | −3.15 | +0.66 |
| | | 4.40 | | 2.90 · Bell nail Square pole S.E 9th N. |



*Table showing the difference of latitude and departure in running 80 chains at any course from 1 to 60 minutes.*

| MINUTES. | LKS. | MINUTES. | LKS. | MINUTES. | LKS. |
|---|---|---|---|---|---|
| 1 | 2⅓ | 21 | 49 | 41 | 95⅔ |
| 2 | 4⅔ | 22 | 51⅓ | 42 | 98 |
| 3 | 7 | 23 | 53⅔ | 43 | 100⅓ |
| 4 | 9⅓ | 24 | 56 | 44 | 102⅔ |
| 5 | 11⅔ | 25 | 58⅓ | 45 | 105 |
| 6 | 14 | 26 | 60⅔ | 46 | 107⅓ |
| 7 | 16⅓ | 27 | 63 | 47 | 109⅔ |
| 8 | 18⅔ | 28 | 65⅓ | 48 | 112 |
| 9 | 21 | 29 | 67⅔ | 49 | 114⅓ |
| 10 | 23⅓ | 30 | 70 | 50 | 116⅔ |
| 11 | 25⅔ | 31 | 72⅓ | 51 | 119 |
| 12 | 28 | 32 | 74⅔ | 52 | 121⅓ |
| 13 | 30⅓ | 33 | 77 | 53 | 123⅔ |
| 14 | 32⅔ | 34 | 79⅓ | 54 | 126 |
| 15 | 35 | 35 | 81⅔ | 55 | 128⅓ |
| 16 | 37⅓ | 36 | 84 | 56 | 130⅓ |
| 17 | 39⅔ | 37 | 86⅓ | 57 | 133 |
| 18 | 42 | 38 | 88⅔ | 58 | 135⅓ |
| 19 | 44⅓ | 39 | 91 | 59 | 137⅔ |
| 20 | 46⅔ | 40 | 93⅓ | 60 | 140 |

## TABLE FOR RUNNING ON SLOPES.

*In the following table the first column shows the angle, the second the number of links to be added to a chain on the slopes, to make one chain, horizontal measurement.*

| ANGLE | COR. IN LINKS | ANGLE | COR. IN LINKS | ANGLE | COR. IN LINKS | ANGLE | COR. IN LINKS |
|---|---|---|---|---|---|---|---|
| ° | | ° | | ° | | ° | |
| 4 | 0.24 | 11 | 1.88 | 18 | 5.14 | 25 | 10.54 |
| 5 | 0.38 | 12 | 2.24 | 19 | 5.76 | 26 | 11.26 |
| 6 | 0.55 | 13 | 2.63 | 20 | 6.42 | 27 | 12.24 |
| 7 | 0.76 | 14 | 3.06 | 21 | 7.11 | 28 | 13.37 |
| 8 | 0.98 | 15 | 3.53 | 22 | 7.85 | 29 | 14.34 |
| 9 | 1.24 | 16 | 4.02 | 23 | 8.64 | 30 | 15.47 |
| 10 | 1.55 | 17 | 4.56 | 24 | 9.47 | 35 | 22.07 |