

Save Our Heritage Organisation Protecting San Diego's architectural and cultural heritage since 1969

April 18, 2024

Suzanne Segur, Senior Planner/HRB Liaison City San Diego Development Services Department 1222 First Avenue, MS 401 San Diego, CA 92101

Dear Ms. Segur,

Save Our Heritage Organisation (SOHO) is expressing our enthusiastic support for the designation of the Arnold and Choate's Addition/North Florence Heights Historic District (ACNFH).

ACNFH holds a special place in the history of San Diego, particularly as it reflects the growth and evolution of the Mission Hills community during the early 1900s. When the San Diego Electric Railway Company (SDERC) extended the streetcar line to Mission Hills it transformed the area into a thriving streetcar suburb, attracting middle-income households.

One of the most striking aspects of ACNFH is its intact architectural landscape, which showcases a diverse range of styles spanning from the late Victorian era through the Minimal Traditional period. The district boasts an impressive collection of residential, commercial, and institutional buildings, each contributing to its unique character and culture. From modest single-family homes to larger residences and small-scale commercial properties, ACNFH epitomizes the architectural richness of San Diego's early streetcar suburban neighborhoods.

ACNFH is also distinguished by the contributions of local master builders and renowned architects who left an indelible mark on its built environment. The eclectic mix of architectural styles, influenced by visionaries such as Morris B. Irvin, Louis J. Gill, Richard Requa, Alexander Screiber, William Templeton Johnson, Frank Mead, and many others, underscores the district's cultural and historical significance.

It is also noteworthy that ACNFH remains a vibrant and dynamic community, adapting to changing times while preserving the integrity of its historic fabric. The presence of multi-family residences, alongside single-family homes, reflects the district's ability to accommodate evolving housing needs without compromising its architectural heritage.

The designation of the Arnold and Choate's Addition/North Florence Heights Historic District is a commitment to safeguarding our cultural legacy for future generations. We wholeheartedly endorse this nomination for designation and urge the Historical Resources Board to recognize ACNFH as a deserving addition to the esteemed list of historic districts.

Sincerely,

Bruce Coons Executive Director Scott A. Moomjian Attorney at Law 5173 Waring Road, #145 San Diego, California 92120 Telephone (619) 230-1770 Facsimile (619) 785-3340 smoomjian68@yahoo.com

April 16, 2024

Mr. Tim Hutter, Chair & City of San Diego, Historical Resources Board (HRB) Members 1222 First Avenue, Fifth Floor San Diego, CA 92101

Re: Draft "Arnold and Choate's Addition-North Florence Heights Historic District" National Register Nomination; 4128 Ibis Street, San Diego, California (District Resource #108); HRB Agenda For April 25, 2024 (Item-2)

Dear Chair Hutter & HRB Members:

I represent David and Sarah Potter, owners of the 4128 Ibis Street property ("Property") with regard to the above-referenced Draft "Arnold and Choate's Addition-North Florence Heights Historic District" National Register Nomination.

As detailed in my attached letter to the Office of Historic Preservation/State Historical Resources Commission, we believe that the Property should be reclassified as a "Contributor" to the Historic District.

It is important to understand that the Property was included in the *Uptown Community Plan Area, Historic Resources Survey Report*. This Survey was *adopted by the City* in November 2016 and specifically identified the Property as a "Minimally Altered" Craftsman bungalow that was a "Contributor" to a future "Arnold And Choate's Historic District."

In addition, most changes to the Property occurred a long time ago. They are minor in nature, and do not adversely impact original integrity. As discussed in the HRB Staff Report for the Item, contributing resources are those that are unaltered, or have "some alterations that are minor and do not compromise original design intent." Alterations to district contributors "do not significantly impair integrity and include minor alterations such as window replacements in original openings..." The Property is exactly in this class of resources.

1

_

¹ City of San Diego, Report To The Historical Resources Board, *Arnold and Choate's Addition-North Florence Heights Historic District National Register Nomination*, Report Number HRB-24-016, April 11, 2024, p.7.

On behalf of the Potter family, we request that you concur with our request for reclassification and urge the State Historical Resources Commission to act accordingly.

Sincerely,

Scott A. Moomjian

Attorney at Law

Scott A. Moomjian Attorney at Law 5173 Waring Road, #145 San Diego, California 92120 Telephone (619) 230-1770 Facsimile (619) 785-3340 smoomjian68@yahoo.com

April 15, 2024

Ms. Julianne Polanco, State Historic Preservation Officer Office of Historic Preservation (OHP)
State Historical Resources Commission (SHRC)
1725 23rd Street, Suite 100
Sacramento, CA 95816-7100

Re: <u>Draft "Arnold and Choate's Addition-North Florence Heights Historic District"</u>
National Register Nomination; SHRC Agenda For May 3, 2024; 4128 Ibis Street, San <u>Diego, California (District Resource #108)</u>

Dear Ms. Polanco, Chair Brandes & State Historical Resources Commissioners:

I represent David and Sarah Potter, owners of the property located at 4128 Ibis Street, San Diego, California, Assessor's Parcel Number 444-382-12-00 ("Property"). This property corresponds to the Draft Arnold and Choate's Addition-North Florence Heights National Register Historic District ("District") Nomination, Resource Number 108 (See Attachment #1).

While my clients are strongly in favor of the establishment of the District, they disagree with the survey assessment that the Property is a "Non-Contributor" to the significance of the District. To the contrary, based upon the information and documentation herein presented, we respectfully request that the SHRC (1) formally determine the Property to be a "Contributor" to the District; (2) amend that Draft Nomination to reflect such reclassification, and (3) forward the amended Nomination to the Keeper for inclusion within the National Register of Historic Places.

Historical research indicates that the Property was constructed as a one-story, Craftsman style, single-family residence for original owner/builder, J.S. Graves in 1920 (See Attachment #2). Graves is known to have been an active builder within the Mission Hills community during this period. The 1920 date of construction is also supported by the Residential Building Record. Modifications made to the structure over the years include the replacement of some windows and the front entry door, as well as the introduction of metal porch railings along the main (east) elevation. In addition, while the exterior is largely composed of original stucco, a section of non-original horizontal siding exists along the northeast elevation. Review of the Residential Building Record indicates that the home featured a stucco exterior with wood clapboard siding

Ms. Julianne Polanco, OHP April 15, 2024

Page Two

"on the front only." (Italics added). Because this observation was made in 1956 (the first year the Property was assessed), and the Record notes that a "Remodel" occurred in 1950, it is believed that the wood siding was added to the Property at this time as part of the remodeling effort (See Attachment #3).

It is important to note that in November 2016, the Property was included as part of the *Uptown Community Plan Area, Historic Resources Survey Report* as a "Minimally Altered" Craftsman bungalow which was a "Contributor" to a future "Arnold And Choate's Historic District," and therefore, eligible for local historical designation (*See Attachment #4*). However, despite this determination, the National Register District survey inexplicably and curiously reaches a different conclusion. While the Nomination identifies changes to the Property, including "primary door replaced, railings added/replaced, some windows replaced, and wall cladding replaced," our review of the Nomination has identified many other properties which have been determined to be contributors to the District with similar changes to primary doors, railings, and windows.¹

Thus, it appears that the only plausible explanation as to why the Property was not classified as a Contributor to the National Register District must be based upon the belief that the introduction of non-original wood cladding which replaced stucco along the northeast elevation, resulted in a substantial, adverse impact to the home's original integrity.

In an effort to determine whether original construction material presently exists underneath the wood clapboard, an experienced stucco contractor was retained. According to Mr. Paul Burgio (President of Burgio Stucco), there exists intact, minimally damaged, and "rather smooth stucco" underneath the wood clapboard along the northeast elevation. The presence of the stucco is evidenced by Mr. Burgio's letter and accompanying photographs (See Attachment #5). Moreover, in Mr. Burgio's professional opinion, "the stucco underneath the clapboard is original, and that the wood siding was added in later years as a way to defer maintenance, and/or change the appearance of the home...." As a result, since the wood clapboard merely obscures the underlying historic stucco material, a condition which the property owners intend to soon remedy through restoration efforts, we submit that the Property has a high degree of original integrity and must be reclassified as a resource which contributes to the significance of the District.

In conclusion, on behalf of the Potter family, we thank you for consideration of our request and look forward to a proper determination of District inclusion.

¹ A cursory review of the Nomination, for example, reveals several examples of other properties deemed to be "Contributors" with these same changes, including but not limited to, homes located at 1212 West Arbor Drive (Resource #5); 1225 West Arbor Drive (Resource #8); 905 Barr Avenue (Resource #10); 4074 Eagle Street (Resource #15); and 4094 Eagle Street (Resource #20).

Ms. Julianne Polanco, OHP April 15, 2024

Page Three

Respectfully Submitted,

Scott A. Moomjian Attorney at Law

Attachment #1

United States Department of the Interior National Park Service / National Register of Historic Places Registration Form NPS Form 10-900 OMB Control No. 1024-0018

Arnold and Choate's Addition-North Florence Heights Historic District

San Diego, CA County and State

A one-story single-family residence in a vernacular idiom. It has an irregular plan and its cladding is wood shingles. Details include a projecting porch. The roof is side gabled and hipped with open eaves, surfaced with composition shingle. Related features include ancillary building(s) and a carport. Alterations: rear addition, some windows replaced, and carport added.

107. 4125-4129 Ibis Street Builder: G.F. Stone APN: 4443950300

Contributor

1926

A one-and-a-half story multiple-family residence (triplex) in the Spanish Colonial Revival style. It has an irregular plan and its cladding is textured stucco. Details include applied decoration, arch(es), and a stoop. The roof is cross gabled and flat with clay tile coping, a flat parapet, and vents, surfaced with clay tile and a material not visible. Related features include an attached garage. Alterations: restuccoed (compatible).

4128 Ibis Street
 Builder: J.S. Graves

APN: 4443821200

Non-contributor

1920

A one-story single-family residence in the Craftsman style. It has an irregular plan and its cladding is wood vertical board and engineered wood siding. Details include a recessed porch. The roof is front gabled with open eaves, exposed rafter tails, exposed purlins, and decorative vents, surfaced with composition shingle. Related features include a detached garage. Alterations: primary door replaced, railings added/replaced, some windows replaced, and wall cladding replaced.

109. 4135 Ibis Street

APN: 4443950200

Contributor

1914

A one-story single-family residence (now a duplex) in the Craftsman style. It has an irregular plan and its cladding is wood shingles. Details include decorative wood elements and a projecting porch. The roof is front gabled with bargeboards, brackets, decorative vents, and exposed rafter tails, surfaced with composition shingle. Related features include an attached garage. Alterations: side addition, rear addition, and conversion of single-family to multi-family.

110. 4136 Ibis Street

APN: 4443821300

Non-contributor

c. 1914

A two-story single-family residence with no identifiable architectural style. It has an irregular plan and its cladding is smooth stucco and stacked stone. Details include a stoop. The roof is hipped and pent with open eaves and exposed rafter tails, surfaced with composition shingle. Related features include an attached garage. Alterations: completely altered.

PERMITS ARE ISSUED FOR NEW COTTAGES


Among permits issued by the city building department yesterday afternoon was one to Nat Sebastian for a flat building and garage at 3611 Park Row. La Jolla, to cost \$15,000.

Other permits were issued yesterday and this morning as follows:

To N. Z. Thornhill for M. Lainson 5-room cottage at 3776 Pioneer place rooms at 3766 Kite, to cost \$5000; to rooms at 3766Kite, to cost \$5000; to W. J. Calloway, 3 rooms at 273. Lincoln, to cost \$3500; to Charlotte Orr, 6 roms at 1349 Park Row, to cost \$2500; to J. C. Fraas, 5 rooms at 4073 Hhirtieth, to cost \$4500; to J. S. Graves, 5 rooms at 4128 Ibis, to cost \$5000.

San Diego Evening Tribune September 16, 1920

ACCUSTOURS ASSESSOR AND ISSOC OCCALIFORNIA EXTERIOR FOOD LIBERTINE OF BUILDING RESCRIPTION OF BUILDING DESCRIPTION OF BUILDING RODULTION ARE CONSTRUCTION FOR A STATE OF THE STATE OF	cou	JNTY	AS	SESSO	R		RES.	IDF	VTI2	v I	BU	II.DII	NG F	REC	OR	D									PA	RGEL _	9-	10	3-7	16			
DESCRIPTION OF BUILDING STRUCTURAL EXTERIOR ROOP LURYING ROOM AND FINISH DETAIL	SAN DI	EGO C	0.	CALIFO	RNIA		*		•								BIS	<u>.</u>						-	e u		4	44	Z — .	38,	2 -/	2	SHFF1
ELASS ASSAULT CONSTRUCTION STRUCTURAL EXTERIOR ROOF LIGHTING AIRCRAFT WITHIN AIRCRAFT CONSTRUCTION CONSTRUCTION STRUCTURAL STREET AIRCRAFT WITHIN AIRCRAFT CONSTRUCTION RECORD STRUCTURAL STREET AIRCRAFT CONSTRUCTION RECORD STRUCTURAL STREET AIRCRAFT CONSTRUCTION RECORD STRUCTURAL STREET CONSTRUCTION RECORD STRUCTURAL STRUCTUR											_ A							-04	W.C.						13/	CE /							SALLY
1.50	CLASS	SWADE	100	NETRIK	TION	STE	CHCTURA	77	FYTER	IOR	$\overline{}$			KIP						DITI	ION		_		R	OOM A	ND F	INIS	SH DE	TAIL			
Second Substitute Substit	D6.0+	2	۲		,,,,,,	_		_			۲,			tch						_		POOMS			\$ F	LOOR F	INISE	1 76		INT	ERIOR	F	NISH
Above 5-Standard Cascerte Risks Standard Cascerte Risks Carl Go Fee				Sub-Stance	derd x			6.			٦,					_	$\overline{}$	_			_		В	1 2				<u>- L</u>				_	
Statist Special State 16.6 Shingle Carriers Art Ar	ARCHIT	ECTURE	x					/	Siding	Mr _X es	"1			3			-	_		_	mid.	All	Ш	<u>× </u>		4. wo.	G	10	F,	PL	LPT.	PL	+PT.
USE Design FOUNDATION Alobe Sonie	- ,	\$4	╀		ndard	_		_		,	+			-	,			<u>~</u> !	Wall Uni	7 (1)	<u> </u>	Fet Hell		-	+		_	╁	-	—			
Use Design Foundation Acobe Soke X Ref. Y/SE Sol. Sol. Sol. Getter Sol. Sol. Sol. Getter Sol. Sol. Sol. Getter Sol. Sol. Sol. Getter Sol. Sol. Sol. Sol. Getter Sol. S			+	Special				30.	Shinale		-			→ ×	_			Χ,	Floor Un	it ti	1		H	1	H	CARCT	\vdash	╢					
X Simple X Concerner X Picco Post 1 1 2 3 5 5 5 5 5 5 5 5 5			1	OUNDAT	ION	_					٦,					+-+-				\rightarrow	-			7.		,							
Diplies Paris 2	× Single			Cancrete		_			8 8 B.	7.8								_ (Central ·	"													
Apart Reged			1		d			25			_	1		-				4					Н	3	Н			-	_				
First Piers Concrete Floor WINDOWS Tile K Sint Date Medical Concrete Floor K Zink K K Zi			+			_						+			Poor Y	QS/d.	Spent	+	031 B			Bed	H		H		-	-					
Motor			+		\rightarrow	_		77		OW.S	+			- x	Sink	Y	\dashv	ť	on Deri	er		 	Н	-	\vdash	-		-				-	
			+	, , , , ,		-	increie i loc				ent		im				\dashv	_		М-В.	.T. U.		Н	\dashv	\vdash			\top					
CONSTRUCTION RECORD EFFEC APPR NORMAL % GOOD RATING E.G. A.F.P.		-	t			Ins	ulated Ceil					Compo). <i>j</i>				Auto.	×	Firepla	ce													
Parmit No. For Amount Dole YEAR Agr No. No		Unifs	L	Light H	leavy	Ins	ulated Wa	//s X				Сопро	Shingle				_	Ţ				Drain 8d	Mo	terial	601	201	Lgin:	-8	Ft.	Splash	: FOX	m	1
No. For Name Note No	CON	ISTRU	CTI	ON REC	ORD		EFFEC.	APP	, NC	RMA	1L	% G(OD		RAT	ING											ATH						
RETIRENT 1970 1975 1975 25 30 Rec 60 A A A A A A A A A A A A A A A A A A			_	Amount	م	ate	YEAR	YEA	Age			Table	%	Cond								FI. No.	L,										
REMORE 1920 1975 197 30 80 00 A A A A A A A A A A A A A A A A		FOF	-				 		+ -		10			2																			
1925 1959 23 30 16 to 59 16 to 59 1925 192		PEm		-,				100	7 3 2	7 3	0	1260	60	7	<u>4</u>	-	A	F	. e	- 6	_	7 - 7	300	7 37 6	2 1	- Litera		۲	<i>p</i> -0	+-	-	+	Acom
1922 1365 13		V. ~			/_	-3-	 ' ' 	 		- 1	0	R-60	₹5	 	+^-			T		\top					1		\vdash	+		1		_	
1970 49 9 1925 1974978 19749										~	4	R6s.	49	Α	Α	A	A	1	<u>G</u> /	1	Α												
Approiser & Date			_		\perp					19	ĵ		44		-			f		7						SPE							
Appraiser & Date C C COMPUTATION 74/LE Appraiser & Date C C C C C C C C C		ļ	_				1925	197	1978	+	_			G	14	-	A_	1	_ -	- /	<u> </u>												
Approiser & Date C		-			-		 	-						 	 -	ļ. —	 -	╀	10/4	+			_					_			x 130	F F E	·T
Approiser & Date		1				~	<u>. </u>		- 					/00	MOI	ITAT	CION			!_		1 / /	,ner	747				,,3,10	- Tasme				
Unit Area Cost Cost Cost Cost Cost Cost Cost Cost	400	raicar	_	Data		-36					+				W / C	,,,,,		÷	7				г							—			
RES 1355 1.70 10433 . 8.30 11246 . 860 11653 1240 14042 CAR II 116 115 540 . 280 605 2.30 . 497 480 1037 C.C.P. SHL 88 5.80 487 . 400 336 3.20 119 A.C. 170 . 170 . 280 . 480 C. P. 350 . 350 . 350 . 350 . 380 ELAT 45800 40 80 . 40 80 . 35 . 157 . 157 TOTAL 12040 . 12181 . 13206 . 16213 NORMAL % GOOD 60 . 59 . 49 . 49 . 49 . 49 . 49 . 49 . 49			<u> </u>			PUR	2/2 ~~ 4	EBIC	war- ?		7 7 .	Unit			Vuni	7			9 00	<i>ii</i> –	т.		1	Init		-	Un	74-1	_		Dais		
CAR II 116 7.57 540 . 280 605 2.30, 497 480 1037 C.C.P. SKL 88 5.80 48 7 . 400 336 3.20 149. A.C. 170 . 170 . 280 480 A.C. 170 . 170 . 280 480 A.C. 170 . 170 . 280 480 ELAT 45800 40 80 . 40 70 35 157 157 TOTAL 12060 . 12787 13206 162/3 NORMAL % 6000 60 . 59 49 49 44 R.C.L.ND 7240 BB 07 7544 64 781 7/35			+-		Cost						- 1	Cost	\ C03	<u>'</u>	$\overline{}$			_	Co	st	-	Cost	1	ost	-	COST	Čö	8 t	Co	37	Cos		Cost
C.C. P. 944 84 5.80 487 - 400 336 320 149 249 249 249 249 249 260 260 260 260 260 260 260 260 260 260	RES	· •	<u> </u>	355		-		. 8.	0 11	241	<u>6]</u>	8.60	116	5-3	194	6	1409	72	ւ		$oxed{oxed}$		匚		L_								
A.C., 170 . 170 . 280 . 480	GAR	<u> </u>		716	7.5	,	540	. 2.8	0	60.	ز [ک	.30,	4	97	48	0 1	103	2		<u></u>			Ι.	_				I					
A.C., 170 . 170 . 280 . 480	CC.P.	344		· 84	5.80)	487	. 40	ه	330	6	3.20	ン	69	. '		26	7	1						-							\top	
TOTAL 1200 40 80 1320 1320 1320 1320 1320 1320 1320 132	AC.	,	Ī						1.		7					\top	101	,					Γ									1	
TOTAL 12960 40 80 40 80 35 157 157 157 157 157 157 157 157 157 15	20			4		_		<u> </u>	 .							_//-			-		\vdash		┢		 							- -	
TOTAL 12P60 . 12787 13206 16213 NORMAL % GOOD 60 . 59 49 49 44 R.C.L.N.D 7240 BH OF 7544 64701 7/35	, <u>, , , , , , , , , , , , , , , , , , </u>		1	260	V.C			· ,	_		_					_/∖	_		-		+		┢		\vdash			-				+	
TOTAL 12960 12787 13206 16215 NORMAL % GOOD 60 59 49 49 49 7240 80 05 7544 6470 7/35	ELAT		- 4	50				7	0	66	-	.34	<u>-</u>	3/		<u> X</u>	15	_	_		\vdash		-									- -	
TOTAL 12960 12787 13206 16215 NORMAL % GOOD 60 59 49 49 49 7240 80 05 7544 6470 7/35			+	₩		+		<u> </u>	+		4					- /	ackslash		+		╀	·	ļ.—		<u> </u>							-	
NORMAL % GOOD 60. 59 49. 49. 44. 44. A.			\perp			\bot					1					/			_						<u> </u>								
NORMAL % GOOD 60. 59 49. 49. 44. 44. A.			\perp			\perp					\perp					ot	__						L										
NORMAL % GOOD 60. 59 49. 49. 44. 44. A.							ì				1				/		1																
NORMAL % GOOD 60. 59 49. 49. 44. 44. A.			Т			Т					Т				7		/													-			
NORMAL % GOOD 60. 59 49. 49. 44. 44. A.	TOTAL					1:	2040		/.5	78-	,		14.5	96	7	1/	(2)	₹-	1														
R.C.L.N.D 7240 BH OF 7544 6470 7/35	NO			200		_/_9		-/4/07			;+-				+								-										
								011		27	-			7.																	٠		
			_	الإـــــا	—· · , ·				W-7	247	4		64_	10		_//			<u> </u>														



a SMA	PΕ	C	NSTA	ľU	CTIO	N	5	TR	UCT	URA	L		ΕX	TERI	OR		R
+2 10		\neg	Light				X	Fra	me			X	St	ucca a	1.7		Flot
G EBI	१।		Sub-St	ġ,	ndard		X		8 x X	~-/	6.				بعر	×	Gabl
TECTUR	Έ	ĸ	Standa	ro	,			She	athin	9		X	Sic	ding "	Manly	X	Нір
•			Abore-	St	andar	ď		Con	crete	Bloc	k				`		Shea
Stories			Special					8.8	В.	T. 6	G.						Cut
YPE								Bric	c k				SA	ingle			Dorn
Desig	70	F	OUND	A	TION			Ado	be				Sh	oke		×	Roft
'e	×	×	Cancre	te			×	Flor	or Joi	st:			8.	8 8.	T. & G.		Gutte
/e			Reinfo	r¢	ed		×	157:	γ×̈́	<u>6"-</u>	75						
ex			Brick					2**	- x	*_	**		81	ick			5hin
tment			Wood					Sub-Floor					St		Shok		
Court			Piers					Concrete Floor					W		7//e		
,/													D.,	# X (Tile	
								Insu	lated	Cei/	ings		Me	etal So.	sh		Com
/ Unit	's		Light		Heavy			Insu	ilatea	Wal	//3	×	Se	reens		\times	Comp
NSTR	JC	TI	ON R	E	COR	D	EFFEC.				4	PPR. NORMAL			RMAL	9	6 G
ermit For		-	Amo		,,		Dat.	e	YE			A		Age	Remain' Life	9	Table
						10	<u>7</u> ¬	0									
RET	101	20	۲.			1	91	0	19	V S	14	25	7	3√	30		260
						-			19:	. <	19		9	3-3	30	1	260
					ī				19:		19	165	7	43	24	7	863
		\neg				-						7		48	19		Rbo
									19:	25	14			778	1	T	
				-			-						7			T	

Uptown Community Plan Area

Historic Resources Survey Report







Prepared by City of San Diego Planning Department

> Final Document November 2016

Potential Historic Districts Appendix D

		ARN	OLD AND C	HOATE'	S HISTORIC DISTR	ICT	
	CON	TRII	BUTING AND	NON-CO	ONTRIBUTING RES	OURCES	
				STATUS			
APN	NUM	DIR	STREET	CODE	STYLE	DESCRIPTION	DATE
44331036	1219		Hunter St	7R			c.1985
44331005	1220		Hunter St	5D3	Prairie	Minimally Altered	1922
44438309	4066		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1916
44438310	4070		Ibis St	7R	Craftsman Bungalow	Heavily Altered	1918
44438311	4078		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1918
44438312	4086		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1912
44438313	4096		Ibis St	7R	Craftsman Bungalow	Heavily Altered	c.1910
44438209	4102		Ibis St	5D3	Victorian Vernacular	Minimally Altered	c.1905
44439505	4109		Ibis St	5D3	Spanish Colonial Revival	Unaltered	1926
44438210	4114		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1914
44439504	4117		Ibis St	5D3	Spanish Colonial Revival	Minimally Altered	1926
44438211	4124		Ibis St	5D3	Craftsman Bungalow	Heavily Altered	1914
44439503	4125		Ibis St	5D3	Spanish Colonial Revival	Minimally Altered	c.1930
44438212	4128		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1925
44439502	4135		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1914
44438213	4136		Ibis St	7R	No Longer Apparent	Altered Beyond	1914
4442021402	41.44		Ibis St	5D3		Recognition Minimally Altered	1922
4443821402	4144		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	
44439501 44439108	4145 4152		Ibis St	5D3	Craftsman Bungalow Craftsman Bungalow	Minimally Altered	1914 1918
44439100	4132		1015 51	3ט3	Craftsman Bungalow	Millimany Anered	1910
44439109	4164		Ibis St	5D3	w/Classical elements	Minimally Altered	c.1915
					Craftsman/Swiss Chalet		
44439202	4171		Ibis St	5D3	Bungalow	Minimally Altered	1912
44439113	4176		Ibis St	5D3	Queen Anne Free	Minimally Altered	c.1900
			Controlled Street Toronto.		Classic/Contemporary	_	
44439201	4179		Ibis St	7R	Ranch	Heavily Altered	1960
44426409	4220		Ibis St	7R	Ranch	Minimally Altered	1951
44426309	4227		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1915
44426410	4230		Ibis St	5D3	Craftsman Bungalow	Unaltered	1923
44426310	4233		Ibis St	7R	No Longer Apparent	Altered Beyond	1956
44426412	4236		Ibis St	5D3	Mission Revival	Recognition Minimally Altered	1926
	4251		Ibis St		Craftsman Bungalow	Minimally Altered	1920
44426205	4251		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1911
44426204	4201		1015 51	5D3	Cransman Bungalow	Altered Beyond	1911
44426107	4268		Ibis St	7R	No Longer Apparent	Recognition	1940
44426203	4269		Ibis St	5D3	Mission Revival	Minimally Altered	1928
44426108	4270		Ibis St	5D3	Craftsman Bungalow	Minimally Altered	1919
20100	1270		1013 51		Victorian	Transfer of	1717
44426109	4276		Ibis St	5D3	Vernacular/transitional	Heavily Altered	c.1900
					Craftsman Bungalow	,	
44426202	4277		Ibis St	5D3	Minimal Traditional	Unaltered	1937
44368410	4020		Ingalls St	7R	Vernacular Bungalow	Heavily Altered	1920
44368411	4024		Ingalls St	5D3	Craftsman Bungalow	Minimally Altered	c.1915
					Victorian		
44368303	4027		Ingalls St	5D3	Vernacular/transitional	Minimally Altered	c.1905
					Craftsman Bungalow		
44368412	4028		Ingalls St	5D3	Craftsman Bungalow	Minimally Altered	c.1915



453 Vernon Way El Cajon, CA 92020 619.448.9900 Lic #528441

4/11/24

Mr. David Potter 4128 Ibis Street San Diego, CA 92103

Re: Forensic Inspection - Presence Of Original Stucco Underneath Non-Original Wood Clapboard

Dear Mr. Potter:

At your request, I conducted a site visit of your home, located at 4128 lbis Street, San Diego, to determine whether original construction material exists underneath the wood clapboard along the northeast elevation.

In terms of my experience, I've been licensed and operating since 1988 when I started Burgio Stucco and have completed over 16,000 projects. I specialize in residential projects, lath and stucco of exterior homes and re-stucco of historical homes for historical designation and was the past president of the APLC (Associated Plastering and Lathing Contractors). As you know, your home was designed in the Craftsman architectural style.

I understand that it was built in 1920 by its original owner, J.S. Graves. While most of the exterior is composed of stucco, horizontal clapboard siding exists along the northeast elevation. I further understand that historical documentation strongly suggests that the clapboard was added to the residence around 1950. However, forensic inspection of the area was necessary to confirm or dispel this belief.

During my site visit, I carefully pulled a clapboard upward to reveal the presence of rather smooth stucco underneath (See Photographs #1-4). Overall, while the stucco was found to have been cracked, the damage appears to be minimal and can easily be repaired through patching efforts or a re-stuccoing of the entire affected area.

Based upon the above, in my professional opinion, I believe that the stucco exterior underneath the clapboard is original, and that the wood siding was added in later years as a way to defer maintenance, and/or change the original appearance of the home based upon the taste of the property owner at that time.

If you have any questions regarding my site inspection or which to discuss proposed restorative work, please contact me at your convenience.

Sincerely,

Paul Burgio

Paul Burgio

President, Burgio Stucco, Inc.

