



AIRPORT BULLETIN

MONTGOMERY FIELD RUNWAY 5/23, TAXIWAY GOLF CONSTRUCTION PROJECT

May 29, 2015

There will be a major construction project taking place at Montgomery Field beginning the week of **June 8** which will involve rehabilitating the crosswind runway, 5/23, and the parallel taxiway Golf. The project will be phased to reduce the impact to aircraft operations as much as possible; however, operational limitations will exist, including:

- Runway 5/23 will be closed continuously until February 2016.
- Runway 10R/28L will be closed during certain phases for takeoffs and landings, but available as a taxiway.
- Taxiway Golf will be constructed in phases, requiring alternate taxi routes using temporary by-passes.
- Runway 10L/28R will remain open during the project.
- The project will not impact the ILS to Runway 28R.
- Touch and goes on Runway 10L/28R will be allowed at the discretion of ATC.
- Taxiway Charlie will be closed north of Runway 10L/28R.
- Portions of Taxiways Foxtrot and Hotel will be closed during certain phases, requiring alternate taxi routes.
- There will be a significant amount of construction personnel and equipment on and near Taxiway Golf.

Pilots are encouraged to check NOTAM's and listen carefully to ATIS prior to flying during the scheduled construction period, or contact Airport Operations at (858) 573-1440.

City of San Diego, Airports Division
3750 John J Montgomery Drive, San Diego, CA 92123
(858) 573-1440

