

PHOTO- LOG FORM

Project: City of San Diego MSWSMP
 Location: Nestor Creek, Map 134 from MSWSMP Appx B Biology Maps
 Date: 11/12/2010
 Photographer: Amy Mattson *Post-Maintenance Condition
 Team members:

Photo #	Time	Photo Point ID	Photo Pt. Description & Location	Bearing to Subject	Subject Description
1	10:27	1	32.584981 N 117.096055 W	East	Looking upstream from access pt.
2	10:28	2	" "	West	Looking downstream from access pt.
3	10:33	3	32.584921 N 117.095692 W	West	West end of concrete channel North of Palm Ave
4	10:34	4	" "	East	Looking upstream at area to be dewatered for maint.
5	10:40	5	32.584555 N 117.094761 W	West	Looking downstream from Thermal Ave
6	10:41	6	32.584317 N 117.094761 W	North	" "
7	10:40	7	" "	South	Looking upstream toward Palm Ave from Thermal Ave
12	10:48	12	32.583403 N 117.094766 W	East	Looking east at concrete channel south of Palm, along 18th St
13	10:51	13	32.583025 N 117.092880 W	West	Looking west from Saturn Blvd south of Palm Ave.

General Notes or Comments (weather, cloud cover, time of sunrise and sunset, other pertinent information): Photos document post-maintenance condition of concrete-lined reach of Nestor Creek north + south of Palm Avenue. Clear & sunny; mid-day.

POST-MAINTENANCE SITE PHOTOS Map 134_ Nestor Creek_111210_AM



PHOTO NOTES:

Looking east/upstream from access point for maintenance north of Palm Avenue. Vegetation was driven over to provide access to the concrete portions of the channel.

PHOTO NOTES:

Looking west/downstream from access point for maintenance north of Palm Avenue.



PHOTO NOTES:

Looking west/downstream at beginning of maintenance area for the concrete channel north of Palm Avenue. Standing water is present.

PHOTO NOTES:

Looking east/upstream at maintenance area for the concrete channel north of Palm Avenue. Standing water is present.

POST-MAINTENANCE SITE PHOTOS Map 134_ Nestor Creek_111210_AM



PHOTO NOTES:
 Looking west/downstream at maintenance area for the concrete channel north of Palm Avenue. Accumulated sediment has been removed.

PHOTO NOTES:
 Looking north/downstream at maintenance area for the concrete channel north of Palm Avenue. Freshwater marsh and accumulated sediment has been removed.



PHOTO NOTES:
 Looking south/upstream at maintenance area for the concrete channel north of Palm Avenue. Freshwater marsh and southern willow scrub have been removed.

PHOTO NOTES:
 Looking east/upstream at maintenance area for the concrete channel south of Palm Avenue. Accumulated sediment has been removed.

POST-MAINTENANCE SITE PHOTOS Map 134_ Nestor Creek_111210_AM

	
<p>PHOTO NOTES: Looking west at the concrete channel from Saturn Boulevard. Accumulated sediment has been removed.</p>	<p>PHOTO NOTES:</p>

<p>PHOTO NOTES:</p>	<p>PHOTO NOTES:</p>