SR #	Creation Dt/Tm	Last Update Dt / ID	
3017312	10/03/07 09:33	10/03/07 09:33	D25

SR Comments

'ER 1603, PAGED 1874...SD

3017312	10/03/07 09:09	10/03/07 09:09	D25

SR Comments

ALSO PAGED 1630 (OCA 1994)....SD

3017312	10/03/07 09:08	10/03/07 09:08	D25

SR Comments

PAGED 1603...SD

3017312	10/03/07 09:03	10/03/07 09:04	ROG

SR Comments

NOTE: THIS IS WHERE LAND IS SINKING NEED CREWS ASAP



C12S
LA JOLLA
2738
2733
2720
2715
5801
2701
5785
5775
5765
5755
2691
5782
5770
5758
5795
5746
5736
5828
5812
5844
5835
5819
5777
5761
5753
5741
5731
5723
5748
5734
5713
5720
5691
5706
5695
5678
5668
5658
5675
5665
5648
5655
5645
5628
5635
5633
5638
5632
5692
5682
5672
5662
5644
5702
5726
5715
5703
5688
5746
5762
5776
5785
5735
5726
5714
5688
5655
5638
8334
8333
8330
8324
8323
8322
8316
8315
8312
8314
8313
8307
8308
48
50
42
41
40
24
25
26
27
28
33
34
35
36
421
209121032061
22742133214357032264
22345719577057292224
20315749578057392047
22042173575921632214
22442123215321132254
208121152071
216221522191
220622072132
21392279207922972151
22942102207521122177
22842261208322432163
2127222422252242
217221422182
55645536552455405558
55465412540454205552
55165435544554055508
54685485543654955460
54365452546854445428
54445475211954655452
54765425545554155484

San Diego MWWD Facility Information Sheet

FSN 8315

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
171	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8315	12	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	01/02/2008	AVAIL	ROW	12 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
8446	01/02/2007	C - Cleaned	721	Kirkendall, Brian		(SYSTEM: completed before window)	None	None	None	Yes
6918	04/05/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	Light	None	No
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	None	None	Yes
4114	10/27/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	None	None	Yes
200402700	02/03/2004	F - Foamed	2,001	Gayman, Scott						No
1901	11/10/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED¿NO FINDINGS INDICATED.	None	None	None	No
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	Light	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
01/02/2007	Maintenance	Kirkendall, Brian	(SYSTEM: completed before window)
04/05/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	

10/27/2004	Maintenance	Ceasar, Felton	
02/03/2004	Maintenance	Gayman, Scott	
11/10/2003	Maintenance	Owens, Doug	RELINED¿NO FINDINGS INDICATED.
07/19/2002	Maintenance	Ortiz, Gabriel	
09/13/1999	Stoppage/SSO		STORM DRAIN Large root ball in main caused blockage which caused overflow

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6918	04/05/2006	745	Carlos Gomez-Tagle	Cleaned			Light Sludge.
5538	07/31/2005	718	Corey Nellis	Cleaned			Clear.
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/27/2004	752	Felton Ceasar	Cleaned			Clear.
	02/03/2004			Root Foamed			Foamed by Contractor
1901	11/10/2003	741	Doug Owens	Cleaned			RELINED¿NO FINDINGS INDICATED.
1901	11/10/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/20/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/20/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/20/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR. LS.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

San Diego MWWD Facility Information Sheet

FSN 8315

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
171	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8315	12	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	01/02/2008	AVAIL	ROW	12 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
8446	01/02/2007	C - Cleaned	721	Kirkendall, Brian		(SYSTEM: completed before window)	None	None	None	Yes
6918	04/05/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	Light	None	No
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	None	None	Yes
4114	10/27/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	None	None	Yes
200402700	02/03/2004	F - Foamed	2,001	Gayman, Scott						No
1901	11/10/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED¿NO FINDINGS INDICATED.	None	None	None	No
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	Light	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
01/02/2007	Maintenance	Kirkendall, Brian	(SYSTEM: completed before window)
04/05/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	

10/27/2004	Maintenance	Ceasar, Felton	
02/03/2004	Maintenance	Gayman, Scott	
11/10/2003	Maintenance	Owens, Doug	RELINED¿NO FINDINGS INDICATED.
07/19/2002	Maintenance	Ortiz, Gabriel	
09/13/1999	Stoppage/SSO		STORM DRAIN Large root ball in main caused blockage which caused overflow

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6918	04/05/2006	745	Carlos Gomez-Tagle	Cleaned			Light Sludge.
5538	07/31/2005	718	Corey Nellis	Cleaned			Clear.
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/27/2004	752	Felton Ceasar	Cleaned			Clear.
	02/03/2004			Root Foamed			Foamed by Contractor
1901	11/10/2003	741	Doug Owens	Cleaned			RELINED¿NO FINDINGS INDICATED.
1901	11/10/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/20/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/20/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/20/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR. LS.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

San Diego MWWD Facility Information Sheet

FSN 8316

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
225	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8316	6	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	08/03/2007	OPEN	ROW	6 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
9553		NV - Not Visite	741	Owens, Doug						No
8446	01/02/2007	C - Cleaned	721	Kirkendall, Brian		(SYSTEM: completed before window)	None	None	None	Yes
6918	04/05/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	Light	None	No
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	None	None	Yes
4114	10/27/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	None	None	Yes
200402700	02/01/2004	EX - Expired	2,001	Gayman, Scott		RI Past Due				No
1901	11/03/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED.	None	None	None	Yes
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	Light	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
08/03/2007	Schedule Change	Rodriguez, Salvador	FREQUENCY FROM 12 TO 6
01/02/2007	Maintenance	Kirkendall, Brian	(SYSTEM: completed before window)

04/05/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	
10/27/2004	Maintenance	Ceasar, Felton	
02/01/2004	Maintenance	Gayman, Scott	RI Past Due
11/03/2003	Maintenance	Owens, Doug	RELINED.
07/19/2002	Maintenance	Ortiz, Gabriel	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
6918	04/05/2006	745	Carlos Gomez-Tagle	Cleaned			Light Sludge.
5538	07/31/2005	718	Corey Nellis	Cleaned			Clear.
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/27/2004	752	Felton Ceasar	Cleaned			Clear.
1901	11/03/2003	741	Doug Owens	Cleaned			Clear. RELINED.
1901	11/03/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/24/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/24/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/24/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR. LS.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

San Diego MWWD Facility Information Sheet

FSN 8322

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
300	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8322	6	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	01/25/2008	AVAIL	ROW	6 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
9294	07/25/2007	C - Cleaned	721	Kirkendall, Brian			None	Light	None	No
8256	12/03/2006	C - Cleaned	718	Nellis, Corey		Unable tyo pass with full size slead	None	Light	None	No
7352	06/22/2006	C - Cleaned	753	Harvey, Stanley	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER! *NOTE: 5731 DESER' VIEW DR. TOILET MAY OVERFLOW¿USE LOW PRESSURE!*		None	None	None	Yes
6424	01/10/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	None	None	Yes
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	Heavy	None	No
4114	10/22/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	None	None	Yes
200402700	02/01/2004	EX - Expired	2,001	Gayman, Scott		RI Past Due				No
1901	11/03/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED.	None	None	None	Yes
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	None	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
07/25/2007	Maintenance	Kirkendall, Brian	
01/23/2007	Schedule Change		FREQUENCY FROM 6 TO 12
12/03/2006	Maintenance	Nellis, Corey	Unable tyo pass with full size slead
06/22/2006	Maintenance	Harvey, Stanley	
01/10/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	
10/22/2004	Maintenance	Ceasar, Felton	
02/01/2004	Maintenance	Gayman, Scott	RI Past Due
11/03/2003	Maintenance	Owens, Doug	RELINED.
07/19/2002	Maintenance	Ortiz, Gabriel	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
7352	06/22/2006	753	Stanley Harvey	Cleaned			Clear.
6424	01/10/2006	745	Carlos Gomez-Tagle	Cleaned			Clear.
5538	07/31/2005	718	Corey Nellis	Cleaned			Heavy Sludge.
5538	07/31/2005	718	Corey Nellis	Sched Change	6	6	Accepted
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/22/2004	752	Felton Ceasar	Cleaned			Clear.
1901	11/03/2003	741	Doug Owens	Cleaned			Clear. RELINED.
1901	11/03/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/19/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/19/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/19/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

San Diego MWWD Facility Information Sheet

FSN 8323

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
126	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8323	6	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	01/25/2008	AVAIL	ROW	6 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
9294	07/25/2007	C - Cleaned	721	Kirkendall, Brian			None	Light	None	No
8256	12/03/2006	C - Cleaned	718	Nellis, Corey		No full size slead	None	None	None	Yes
7352	06/22/2006	C - Cleaned	753	Harvey, Stanley	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	None	None	Yes
6424	01/10/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	None	None	Yes
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	Heavy	None	No
4114	10/22/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMIS LINER!		None	None	None	Yes
200402700	02/01/2004	EX - Expired	2,001	Gayman, Scott		RI Past Due				No
1901	11/03/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED.	None	None	None	Yes
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	None	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS

07/25/2007	Maintenance	Kirkendall, Brian	
01/23/2007	Schedule Change		FREQUENCY FROM 6 TO 12
12/03/2006	Maintenance	Nellis, Corey	No full size slead
06/22/2006	Maintenance	Harvey, Stanley	
01/10/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	
10/22/2004	Maintenance	Ceasar, Felton	
02/01/2004	Maintenance	Gayman, Scott	RI Past Due
11/03/2003	Maintenance	Owens, Doug	RELINED.
07/19/2002	Maintenance	Ortiz, Gabriel	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
				Root Foam Aborted			RI Past Due
7352	06/22/2006	753	Stanley Harvey	Cleaned			Clear.
6424	01/10/2006	745	Carlos Gomez-Tagle	Cleaned			Clear.
5538	07/31/2005	718	Corey Nellis	Cleaned			Heavy Sludge.
5538	07/31/2005	718	Corey Nellis	Sched Change	6	6	Accepted
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/22/2004	752	Felton Ceasar	Cleaned			Clear.
1901	11/03/2003	741	Doug Owens	Cleaned			Clear. RELINED.
1901	11/03/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/21/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/21/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/21/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

San Diego MWWD Facility Information Sheet

FSN 8312

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
279	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8312	12	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	01/02/2008	AVAIL	ROW	12 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
8446	01/02/2007	C - Cleaned	721	Kirkendall, Brian		(SYSTEM: completed before window)	None	None	Light	No
6918	04/05/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	Light	None	No
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	None	None	Yes
4114	10/27/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI! LINER!		None	None	None	Yes
200402700	02/03/2004	F - Foamed	2,001	Gayman, Scott						No
1901	11/10/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED¿NO FINDINGS INDICATED.	None	None	None	No
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	Light	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
01/02/2007	Maintenance	Kirkendall, Brian	(SYSTEM: completed before window)
04/05/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	

10/27/2004	Maintenance	Ceasar, Felton	
02/03/2004	Maintenance	Gayman, Scott	
11/10/2003	Maintenance	Owens, Doug	RELINED¿NO FINDINGS INDICATED.
07/19/2002	Maintenance	Ortiz, Gabriel	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6918	04/05/2006	745	Carlos Gomez-Tagle	Cleaned			Light Sludge.
5538	07/31/2005	718	Corey Nellis	Cleaned			Clear.
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/27/2004	752	Felton Ceasar	Cleaned			Clear.
	02/03/2004			Root Foamed			Foamed by Contractor
1901	11/10/2003	741	Doug Owens	Cleaned			RELINED¿NO FINDINGS INDICATED.
1901	11/10/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/18/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/18/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/18/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR. LS.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

Wastewater Collection Division

Revised - Standby Schedule (please see asterisk in bold*)

October 05, 2007 through October 11, 2007

Rev 1 10/04/07	NAME	TITLE	PAGER	TELEPHONE	UNIT
DUTY SUPERVISOR	**Mike Bedard**	**GWUS**	**8794**	**619-980-8609**	**353**
EQUIPMENT OPERATOR II	Jon Barnes	EOII	2814	619-952-9722	660
ENVIRONMENTAL	Laura Ball	Planner		619-980-1282	
ELECTRICIAN	Craig Brewster	ELECT.	8823	858-627-0557	818
CONSTRUCTION	Larry Cooper	WUS	6885	619-985-8642	661
	Mark Jones		9361	619-787-5909	
	Kevin Wilson		7609	619-459-5078	
CONSTRUCTION	Dean Campbell	WUS	9179	619-980-9382	662
	Derrick Harris		8852	619-823-0714	
	Joe Campbell		8552	951-978-3194	
TRENCH COMP/TEST	Anthony Scira			c. 619-980-0883	
				h. 619-479-8501	
SEWER PUMPS	Sylvester Boadilla	ETII	8532	619-517-4511	761
	Felipe Ramirez	ET1	8538	619-286-1507	
FLUSHING /ROD CREW	Doug Owens	EOI	6929	619-461-4136	741
	Debbie Camacho			619-269-6148	
TV CREW	**Alberto Mejia**	WUS	**8374***	**619-980-1442***	949
	Brain Dantzler		8554	619-287-1816	
	Michelle Moran		8195	619-726-7867	
NON-RIGHT-OF-WAY	John Collingwood	EOII		619-980-1695	516
	Henry Manriquez		2831	619-980-1718	
	Clarence Scott		7073	619-756-4243	
MICRO BIOLOGY LAB	Aaron Russel	BIO		619-838-3805	
MICRO BIOLOGY LAB	Rumana Shahzad	Lab Tech	7737	619-985-9295	
NAVY PUBLIC WORKS CENTER	**Duty Desk**				
SPACE & NAVAL WARFARE SYSTEMS DUTY COMMANDER		**(call to gain access)**		**619-524-7004**	
CITY OF LA MESA PUBLIC WORKS-24 HOUR EMERGENCY #: 469-6111(DAYTIME-STEVE MAURER)					
PROBLEMS WITH PUMP STATIONS, CALL COMC (614-4551)					
STATION 38 EMERGENCY #: (619) 527-7660					

(1) Deputy Director-Wastewater Collection*
(1) Assist. Deputy Director-Wastewater Collection*
(1) Deputy Director -Services and Contracts*
(3) GWUS/Wastewater Collection*
(9) SWUS/Wastewater Collection*
(1) Plant Processing Control Supvr*
(1) Rich Grunow-Environmental Planner*
(1) O&M/Gerald Schreckengost *
(1) Local 127 - MS 127
(1)STA 38 (FAX 77478 or #13)
(1) Rose Canyon (FAX 19967 or #10)
(2) Chollas Bulletin Boards MS 43
(2) Front Office Bulletin Board
(11) WWC Electricians

(1) Metropolitan Wastewater/Director *
(1) Metropolitan Wastewater/Assist. Director*
(1) Deputy Director/Water Production/Mark Stone*
(2) Payroll Specialist/Wastewater Collection*
(1) Sr Civil Engineer - Isam Hireish*
(1) COMC*Gerald Schreckengost
(1) Security Desk (MOC II)
(1) Anna Rodriguez-Engineering fax #78098
(1) Micro-Biology Lab-Ricardo Amador*
(1) J. Cordova/A. Stoecker Superintendant Point Loma Treatment Plant*
(1) SAMS* - Larry Sherry, Rae Brown
(1) Keith Strehle*
*Groupwise

Code ED-Extended Day NH-Not Home N-Refused S-Sick O-No Answer SBC-Standby Crew
W-Working on a job A-Will report to work
Caller should use these codes to log responses to all calls

San Diego MWWD Facility Information Sheet

FSN 8306

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
320	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8306	12	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	11/05/2007	OPEN	ROW	12 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
9553		NV - Not Visite	741	Owens, Doug						No
8157	11/05/2006	C - Cleaned	718	Nellis, Corey			None	None	Light	No
6266	12/01/2005	C - Cleaned	758	Jordan, Alberto			None	None	Light	No
4623	02/16/2005	C - Cleaned	750	Scott, Clarence			None	None	None	Yes
2992	02/24/2004	C - Cleaned	677	Hauer, Matt			None	Medium	None	No
1642	04/16/2003	C - Cleaned	752	Ceasar, Felton			None	None	None	Yes
112	03/16/2002	C - Cleaned	721	Beasley, Tim		Some sludge	None	Light	None	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
01/23/2007	Schedule Change		FREQUENCY FROM 12 TO 24
11/05/2006	Maintenance	Nellis, Corey	
12/01/2005	Maintenance	Jordan, Alberto	
02/16/2005	Maintenance	Scott, Clarence	
02/24/2004	Maintenance	Hauer, Matt	
04/16/2003	Maintenance	Ceasar, Felton	

03/16/2002	Maintenance	Beasley, Tim	Some sludge

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6266	12/01/2005	758	Alberto Jordan	Cleaned			Light Roots.
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4623	02/16/2005	750	Clarence Scott	Cleaned			Clear.
2992	02/24/2004	677	Matt Hauer	Cleaned			Medium Sludge.
1642	04/16/2003	752	Clarence Scott	Cleaned			Clear.
	08/08/2002			Sched Change	60	12	Schedule Changed by Jun Mejia
112	03/16/2002	721	Tim Beasley	Sched Change	99	60	Accepted.
112	03/16/2002	721	Tim Beasley	Sched Change	AREA	FLUSH	Accepted.
112	03/16/2002	721	Tim Beasley	Cleaned			LS. Some sludge

San Diego MWWD Facility Information Sheet

FSN 8307

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
317	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8307	6	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW_TYPE	RULE
1	FLUSH	01/25/2008	AVAIL	ROW	6 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
9294	07/25/2007	C - Cleaned	721	Kirkendall, Brian			None	None	None	Yes
8446	01/02/2007	C - Cleaned	721	Kirkendall, Brian			None	None	None	Yes
7498	07/28/2006	C - Cleaned	753	Harvey, Stanley			None	None	None	Yes
6918	04/05/2006	C - Cleaned	745	Gomez-Tagle, Carlos			None	None	None	Yes
6266	12/01/2005	C - Cleaned	758	Jordan, Alberto			None	None	Heavy	No
4623	02/16/2005	C - Cleaned	750	Scott, Clarence			None	Light	None	No
2992	02/24/2004	C - Cleaned	677	Hauer, Matt			None	Medium	None	No
1642	04/16/2003	C - Cleaned	752	Ceasar, Felton			None	None	None	Yes
112	03/16/2002	C - Cleaned	721	Beasley, Tim		Clean some roots	None	None	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
07/25/2007	Maintenance	Kirkendall, Brian	
01/02/2007	Maintenance	Kirkendall, Brian	
07/28/2006	Maintenance	Harvey, Stanley	
04/05/2006	Maintenance	Gomez-Tagle, Carlos	

12/01/2005	Maintenance	Jordan, Alberto	
02/16/2005	Maintenance	Scott, Clarence	
02/24/2004	Maintenance	Hauer, Matt	
04/16/2003	Maintenance	Ceasar, Felton	
03/16/2002	Maintenance	Beasley, Tim	Clean some roots

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6918	04/05/2006	745	Carlos Gomez-Tagle	Cleaned			Clear.
6266	12/01/2005	758	Alberto Jordan	Cleaned			Heavy Roots.
6266	12/01/2005	758	Alberto Jordan	Sched Change	6	6	Accepted
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4623	02/16/2005	750	Clarence Scott	Cleaned			Light Sludge.
2992	02/24/2004	677	Matt Hauer	Cleaned			Medium Sludge.
1642	04/16/2003	752	Clarence Scott	Cleaned			Clear.
	08/08/2002			Sched Change	60	12	Schedule Changed by Jun Mejia
112	03/16/2002	721	Tim Beasley	Sched Change	99	60	Accepted.
112	03/16/2002	721	Tim Beasley	Sched Change	AREA	FLUSH	Accepted.
112	03/16/2002	721	Tim Beasley	Cleaned			LR. Clean some roots

San Diego MWWD Facility Information Sheet

FSN 8308

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
200	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8308	60	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW_TYPE	RULE
1	FLUSH	05/14/2009	AVAIL	ROW	60 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
3390	05/14/2004	C - Cleaned	718	Nellis, Corey			None	None	Light	No
112	03/16/2002	C - Cleaned	721	Beasley, Tim			None	None	None	Yes

Facility Event History

Date	Activity	Crew Leader	REMARKS
05/14/2004	Maintenance	Nellis, Corey	
03/16/2002	Maintenance	Beasley, Tim	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	07/24/2004		ADMIN	Sched Change	05/14/2006	5/14/2009	On 1/21/2004 this main was rescheduled from 120 MO to 60 MO to comply with EPA Guidelines. Due to the fact PSTools programming had not been updated to support this change, main was rescheduled to 24 month schedule in error.
	07/24/2004		ADMIN	Sched Change	24	60	On 1/21/2004 this main was rescheduled from 120 MO to 60 MO to comply with EPA Guidelines. Due to the fact PSTools programming had not been updated to support this change, main was rescheduled to 24 month schedule in error.
3390	05/14/2004	718	Corey Nellis	Sched Change	60	24	Accepted.
3390	05/14/2004	718	Corey Nellis	Cleaned			Light Roots.
	01/21/2004		RESCHEDULE	Sched Change	3/16/2012	1/1/2004	Reschedule pipe from 3/16/2012 to 1/1/2004 to level load the schedule.
	01/21/2004		RESCHEDULE	Sched Change	120	60	Reschedule pipe from 120 MO to 60 MO to comply with EPA Guidelines.
112	03/16/2002	721	Tim Beasley	Sched Change	99	120	Accepted.
112	03/16/2002	721	Tim Beasley	Sched Change	AREA	FLUSH	Accepted.
112	03/16/2002	721	Tim Beasley	Cleaned			Clear.

San Diego MWWD Facility Information Sheet

FSN 8330

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
350	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8330	12	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	12/03/2007	OPEN	ROW	12 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
9553		NV - Not Visite	741	Owens, Doug						No
8256	12/03/2006	C - Cleaned	718	Nellis, Corey			Light	Medium	None	No
6524	02/19/2006	C - Cleaned	719	System		REMOVED HEAVY ROCKS	None	Heavy	None	No
3175	04/13/2004	C - Cleaned	725	Rodriguez, Eddie		MEDIUM DEBRIS	None	Heavy	None	No
112	03/14/2002	C - Cleaned	721	Beasley, Tim			None	None	None	Yes

Facility Event History

Date	Activity	Crew Leader	REMARKS
12/03/2006	Maintenance	Nellis, Corey	
02/19/2006	Maintenance	System	REMOVED HEAVY ROCKS
04/13/2004	Maintenance	Rodriguez, Eddie	MEDIUM DEBRIS
03/14/2002	Maintenance	Beasley, Tim	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6524	02/19/2006	719	Greg Siaumau	Cleaned			Heavy Sludge. REMOVED HEAVY ROCKS
6524	02/19/2006	719	Greg Siaumau	Sched Change	12	12	Accepted
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
3175	04/13/2004	725	Eddie Rodriguez	Cleaned			Heavy Sludge. MEDIUM DEBRIS
3175	04/13/2004	725	Eddie Rodriguez	Sched Change	60	24	Accepted.
	01/21/2004		RESCHEDULE	Sched Change	3/14/2012	9/1/2004	Reschedule pipe from 3/14/2012 to 9/1/2004 to level load the schedule.
	01/21/2004		RESCHEDULE	Sched Change	120	60	Reschedule pipe from 120 MO to 60 MO to comply with EPA Guidelines.
112	03/14/2002	721	Tim Beasley	Sched Change	99	120	Accepted.
112	03/14/2002	721	Tim Beasley	Sched Change	AREA	FLUSH	Accepted.
112	03/14/2002	721	Tim Beasley	Cleaned			Clear.

San Diego MWWD Facility Information Sheet

FSN 8313

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
151	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8313	12	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	01/02/2008	AVAIL	ROW	12 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
8446	01/02/2007	C - Cleaned	721	Kirkendall, Brian		(SYSTEM: completed before window)	None	None	None	Yes
6918	04/05/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI LINER!		None	None	None	Yes
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI LINER!		None	None	None	Yes
4114	10/27/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI LINER!		None	None	None	Yes
200402700	02/03/2004	F - Foamed	2,001	Gayman, Scott						No
1901	11/10/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED¿NO FINDINGS INDICATED.	None	None	None	No
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	Light	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
01/02/2007	Maintenance	Kirkendall, Brian	(SYSTEM: completed before window)
04/05/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	

10/27/2004	Maintenance	Ceasar, Felton	
02/03/2004	Maintenance	Gayman, Scott	
11/10/2003	Maintenance	Owens, Doug	RELINED¿NO FINDINGS INDICATED.
07/19/2002	Maintenance	Ortiz, Gabriel	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6918	04/05/2006	745	Carlos Gomez-Tagle	Cleaned			Clear.
6918	04/05/2006	745	Carlos Gomez-Tagle	Sched Change	24	24	Accepted
5538	07/31/2005	718	Corey Nellis	Cleaned			Clear.
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/27/2004	752	Felton Ceasar	Cleaned			Clear.
	02/03/2004			Root Foamed			Foamed by Contractor
1901	11/10/2003	741	Doug Owens	Cleaned			RELINED¿NO FINDINGS INDICATED.
1901	11/10/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/25/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/25/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/25/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR. LS.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

San Diego MWWD Facility Information Sheet

FSN 8314

Sewer Main Info

LENGTH	DIAM_SIZE	MATL_CD
218	8	VC

Maintenance Calendar

FACILITY_NM	FREQUENCY	STATUS	SCHEDULETYPE	COMMENTS
Pipe FSN# 8314	12	Available	Cycle Frequency	

SEQ	MAINTENANCE_TYPE	SCHEDULED_DT	STATUS	CREW TYPE	RULE
1	FLUSH	01/02/2008	AVAIL	ROW	12 Month (Cleaning)

Maintenance Request History

MRN	Date	Activity	Unit #	Crew Leader	SCHEDULE_NOTES	REMARKS	Grease	Sludge	Roots	IsClear
8446	01/02/2007	C - Cleaned	721	Kirkendall, Brian		(SYSTEM: completed before window)	None	None	None	Yes
6918	04/05/2006	C - Cleaned	745	Gomez-Tagle, Carlos	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI: LINER!		None	None	None	Yes
5538	07/31/2005	C - Cleaned	718	Nellis, Corey	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI: LINER!		None	None	None	Yes
4114	10/27/2004	C - Cleaned	752	Ceasar, Felton	MUST FLUSH! LINED PIPE. RODDING WILL COMPROMI: LINER!		None	None	None	Yes
200402700	02/03/2004	F - Foamed	2,001	Gayman, Scott						No
1901	11/10/2003	C - Cleaned	741	Owens, Doug	ROOT TREATMENT.	RELINED¿NO FINDINGS INDICATED.	None	None	None	No
453	07/19/2002	C - Cleaned	750	Ortiz, Gabriel	ROOT TREATMENT.		None	Light	Light	No

Facility Event History

Date	Activity	Crew Leader	REMARKS
01/02/2007	Maintenance	Kirkendall, Brian	(SYSTEM: completed before window)
04/05/2006	Maintenance	Gomez-Tagle, Carlos	
07/31/2005	Maintenance	Nellis, Corey	

10/27/2004	Maintenance	Ceasar, Felton	
02/03/2004	Maintenance	Gayman, Scott	
11/10/2003	Maintenance	Owens, Doug	RELINED¿NO FINDINGS INDICATED.
07/19/2002	Maintenance	Ortiz, Gabriel	

Facility Event History - Archive

MR # / SR #	Date	Unit #	Crew Leader	ACTION	OLD	NEW	COMMENTS_FINDINGS
6918	04/05/2006	745	Carlos Gomez-Tagle	Cleaned			Clear.
6918	04/05/2006	745	Carlos Gomez-Tagle	Sched Change	24	24	Accepted
5538	07/31/2005	718	Corey Nellis	Cleaned			Clear.
	06/07/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
	03/14/2005			Sched Change	YES	YES	Updated from latest SWIFT Update
4114	10/27/2004	752	Felton Ceasar	Cleaned			Clear.
	02/03/2004			Root Foamed			Foamed by Contractor
1901	11/10/2003	741	Doug Owens	Sched Change	12	12	RI Default Frequency Accepted
1901	11/10/2003	741	Doug Owens	Cleaned			RELINED¿NO FINDINGS INDICATED.
	10/09/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/25/2003.Maintenance schedule set to 24 Mo. and next PM date adjusted until end of warranty period.
	10/08/2003		Phase A CIP	Sched Change	ROD	FLUSH	Main lined on 2/25/2003. MUST FLUSH! LINED PIPE. RODDING WILL COMPROMISE LINER!
	10/08/2003		Phase A CIP	Sched Change	YES	NO	Main lined on 2/25/2003. No requirement to continue ROOT I.
	08/08/2002			Sched Change	ROD	ROD_RI	Rooti Schedule Changed by Jun Mejia
453	07/19/2002	750	Gabriel Ortiz	Cleaned			LR. LS.
	04/15/2002			Sched Change	ROOTI	ROD	Schedule changed by planner. These ROOTI records had no corresponding ROD schedule.
	04/15/2002			Sched Change	6	12	Schedule changed by planner to 12 month frequency.

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint
TELEVISE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description

Water/Sewer: S

SR #	WO #	Status	Gen Dt	Prty
3016113	8	CMP	10/01/07	2

Fac Type	Fac Seq #
MAIN	8307

Cross Street Name

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946		1248A2

Job Description
TELEVISE FOR PIPE INTEGRITY

Special Instructions
ENVIRONMENTALLY SENSITIVE AREA. PERMITS MAY BE REQUIRED. CONTACT YOUR SUPERVISOR FOR INSTRUCTIONS.

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
10/3/2007 08:43:00	10/3/2007 09:32:04	METRO WASTE WATER DEPT	8203	3	1

Service Request Comments

Work Order Comments
AT 302' WATER LEVEL HAS INCREASED AND CAMERA WEWNT UNDERWATER. WAS ABLE TO SEE MH#25.

Tabular Report of PLR C12S-026 X **for** City of SD

Work Order 3016113	***Contract***	***Video*** cd	***Setup*** 14
Facility 8307	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 10/03/2007

Street Name 5715 soledad mtn. rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 318.0 ***Ft***	***From*** C12S-026 ***Depth*** 8.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-025 ***Depth*** ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note tv for pipe integrity
Location note on st.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-026
00000	0.0		WL	Water level				1	
	3.0		CB	Break in Connection		10			
	3.0		CR	Roots from lateral	S	10			
	38.9		CN	Service Connection		02			
	61.6		CN	Service Connection		11			
	98.7		RJ	Roots at joint	S				
	111.0		CN	Service Connection		02			
	133.7		CN	Service Connection		11			
	173.1		CN	Service Connection		02			
	209.6		CN	Service Connection		10			
	249.0		CN	Service Connection		02			
	284.8		CN	Service Connection		11			
	302.9		WL	Water level				0040	
	309.0		CUB	Camera Submerged Begin					
	318.0		MH	Manhole/Node					C12S-025
	318.0		FH	Finish of Surveys					end

318.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 45	***Mean Defect*** 9	***Peak*** 25	***Mean Pipe*** 0.1

Notes

At 302' water level has an increase and cam. went under water, was able to see m/h 25.

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego Phone: 858-654-4467 Fax:

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	1	CMP	07/25/07	1

Cross Street Name

Fac Type	Fac Seq #
MAIN	8306

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946		1248A2

Job Description

TV MAIN TO ACCESS CONDITION

Special Instructions

TV SUROUNDING AREA NEAR 5715 SOLEDAD.MTN. RD

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/30/2007 14:09:38	7/30/2007 14:09:39	METRO WASTE WATER DEPT	8202	1	0.1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

Work Order Comments

WRONG FSN WAS GIVEN, SHOULD READ FSN 8306 & SUROUNDING AREAS. THAT FSN WAS TV'D ON 7-26-07 AS WELL AS 7 OTHER FSN'S, IN THE AREA.

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint
TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**
5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	2	CMP	07/26/07	1

Cross Street Name

Fac Type	Fac Seq #
MAIN	8306

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description
TV MAIN TO ACCESS CONDITION.

Special Instructions
TV SUROUNDING AREA NEAR 5715 SOLEDAD MT. RD.

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 09:53:24	7/26/2007 09:53:25	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

THIS MAIN IS CLEAR W/ ROOTS INSIDE 3 LATERALS.

Comments	Creation Dt/Tm	
THIS MAIN IS CLEAR W/ ROOTS INSIDE 3 LATERALS.	07/26/07 [illegible]	
	Last Update Dt/Tm	
	07/26/07 [illegible]	UPLOA

Tabular Report of PLR C12S-024 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 16
Facility 8306	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 315.0 ***Ft***	***From*** C12S-024 ***Depth*** 20.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-025 ***Depth*** ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note tv to assess condition
Location note on soledad mtn. rd.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-024
00000	0.0		WL	Water level				3	
	33.0		CN	Service Connection		03			
	49.1		CN	Service Connection		10			
	108.4		CN	Service Connection		02			
	115.1		RJ	Roots at joint	S				
	117.6		CN	Service Connection		10			
	117.6		CR	Roots from lateral	M	10			
	146.0		DE	Debris	S				
	183.8		CN	Service Connection		11			
	183.8		CR	Roots from lateral	S	11			
	186.7		CN	Service Connection		02			
	186.7		CR	Roots from lateral	L	02			
	249.4		CN	Service Connection		10			
	268.3		DE	Debris	S				
	268.5		CN	Service Connection		02			
	304.7		CN	Service Connection		10			
	315.0		MH	Manhole/Node					C12S-025
	315.0		FH	Finish of Surveys					END

315.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 270	***Mean Defect*** 38.6	***Peak*** 75	***Mean Pipe*** 0.9

Notes

This main is clear, 3 laterals have roots from them.

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego ***Phone:*** ***Fax:***

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	3	CMP	07/26/07	1

Fac Type	Fac Seq #
MAIN	8316

Cross Street Name

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description

PIPE INTEGRITY / EXTRA SECTION.

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 13:33:02	7/26/2007 13:33:02	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

THIS EXTRA SECTION HAS SOME DEBRIS BOTTOM OF MAIN @ 4'. SOME SMALL GREASE ON WALLS. CAMERA WENT UNDERWATER FOR 10'. A DIAMETER CHANGE @ 157' WAS TO TIGHT FOR CAMERA TO PASS, AND WAS NOT ABLE TO DO A REVERSE SET-UP DUE TO MAIN DROPS INTO MH#35, NOT ABLE TO GET CAMERA INTO MH#35 GOING U/S.

Comments	Creation Date
THIS EXTRA SECTION HAS SOME DEBRIS BOTTOM OF MAIN @ 4'. SOME SMALL GREASE ON WALLS. CAMERA WENT UNDERWATER FOR 10'. A DIAMETER CHANGE @ 157' WAS TO TIGHT FOR CAMERA TO PASS, AND WAS NOT ABLE TO DO A REVERSE SET-UP DUE TO MAIN DROPS INTO MH#35, NOT ABLE TO GET CAMERA INTO MH#35 GOING U/S.	07/26/07 12:38
	Last Update Date
	07/26/07 15:12

Tabular Report of PLR C12S-040 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 27
Facility 8316	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 225.0 ***Ft***	***From*** C12S-040	***Depth*** 15.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-035	***Depth*** ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down	
Lining Plastic	***Year laid***	***Pre-clean***	***Last Cleaned***

General note Extra section
Location note on desert view dr.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-040
00000	0.0		WL	Water level				10	
	4.2		DE	Debris	M				
	33.4		CN	Service Connection		02			
	61.9		DEG	Debris (Grease)	S				ON WALLS
	68.0		WL	Water level				0035	
	73.0		CN	Service Connection		11			
	123.3		CUB	Camera Submerged Begin					
	133.9		CUE	Camera Submerged End					
	156.1		DC	Diameter of sewer changes				07.5	
	157.5		GO	General observation					TOO TIGHT FOR CAM.
	157.6		SA	Survey abandoned					

157.6 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 125	***Mean Defect*** 20.8	***Peak*** 75	***Mean Pipe*** 0.8

Notes

Extra section some debris on the bottom @ 4' some grease on the walls (S) , Cam. went under water for 10', a dim. change @ 157' is too tight for the cam. to pass and unable to do rev. setup due to main dropes into m/h 35 and can not get cam. up into this fsn going up/s.

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	4	CMP	07/26/07	1

Cross Street Name

Fac Type	Fac Seq #
MAIN	8322

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description

PIPE INTEGRITY / EXTRA SECTION.

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 13:05:00	7/26/2007 13:09:25	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

THIS EXTRA SECTION OF PIPE HAS A LOT OF FLOW, AND IS CLEAR.

Comments	Creation Dt/Tm	
THIS EXTRA SECTION OF PIPE HAS A LOT OF FLOW, AND IS CLEAR.	07/26/07 13:09	
	Last Update Dt / ID	
	07/26/07 15:12	UPDOT

Tabular Report of PLR C12S-041 X **for** **Ciyt of SD**

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 26
Facility 8322	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 300.0 ***Ft***	***From*** C12S-041 ***Depth*** 15.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-040 ***Depth*** ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining Plastic	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note Extra section
Location note on desert view dr.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-041
00000	0.0		WL	Water level				8	
	8.9		CN	Service Connection		09			
	88.9		CN	Service Connection		09			
	98.1		CN	Service Connection		02			
	167.9		CN	Service Connection		03			
	210.8		CN	Service Connection		02			
	247.1		CN	Service Connection		10			
	300.0		MH	Manhole/Node					C12S-040
	300.0		FH	Finish of Surveys					END

300.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0

Notes

Extra section main has lots of flow, but clear

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego ***Phone:*** ***Fax:***

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	5	CMP	07/26/07	1

Fac Type	Fac Seq #
MAIN	8323

Cross Street Name

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description

PIPE INTEGRITY / EXTRA SECTION.

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 12:56:10	7/26/2007 12:56:10	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

CAMERA WENT UNDERWATER FOR 10', SOME SMALL GREASE.

Tabular Report of PLR C12S-042 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 25
Facility 8323	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 127.0 ***Ft***	***From*** C12S-042 ***Depth*** 10.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-041 ***Depth*** ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining Plastic	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note Extra section
Location note on desert view dr.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-042
00000	0.0		WL	Water level				5	
	36.1		DEG	Debris (Grease)	S				ON TOPS
	39.1		CUB	Camera Submerged Begin					
	51.1		CUE	Camera Submerged End					
	53.8		CN	Service Connection		09			
	56.5		CN	Service Connection		03			
	122.7		CN	Service Connection		02			
	127.0		MH	Manhole/Node					C12S-041
	127.0		FH	Finish of Surveys					END

127.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 50	***Mean Defect*** 12.5	***Peak*** 50	***Mean Pipe*** 0.4

Notes

Extra section cam. went under water for 10' some grease(S).

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego ***Phone:*** ***Fax:***

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	6	CMP	07/26/07	1

Cross Street Name

Fac Type	Fac Seq #
MAIN	8317

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description

PIPE INTEGRITY / EXTRA SECTION

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 12:27:49	7/26/2007 12:27:49	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

EXTRA SECTION HAS LOTS OF SMALL - LARGE ROOTS AT JOINTS.

Tabular Report of PLR C12S-035 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 24
Facility 8317	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 60.0 ***Ft***	***From*** C12S-035 ***Depth*** 25.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-056 ***Depth*** ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining Plastic	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note Extra section
Location note on desert view dr.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-035
00000	0.0		WL	Water level				5	
	10.3		RJ	Roots at joint	S				
	27.1		RJ	Roots at joint	S				
	27.6		RJ	Roots at joint	S				
	34.9		RJ	Roots at joint	S				
	34.9		RJ	Roots at joint	S				
	48.3		RJ	Roots at joint	M				
	51.5		RJ	Roots at joint	L				
	54.2		RJ	Roots at joint	M				
	58.7		R	Roots	M				IN M/H
	60.0		MH	Manhole/Node					C12S-056
	60.0		FH	Finish of Surveys					END

60.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 450	***Mean Defect*** 45	***Peak*** 100	***Mean Pipe*** 7.5

Notes

Extra section Lots of roots at joints (S,M,L)

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint
TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**
5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	7	CMP	07/26/07	1

Cross Street Name

Fac Type	Fac Seq #
MAIN	8312

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description
PIPE INTEGRITY / EXTRA SECTION.

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 11:48:00	7/26/2007 12:23:39	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

THIS EXTRA SECTION MAIN IS LINED AND HAS JOINTSNW/ ROOTS FROM THEM SMALL THRU MED. CAMERA FLPPPED OVER AND A REVERASE SET-UP WAS DONE TO COMPLETE SURVEY. REVERSE FOUND THIS 8" VC MAIN LINED, MADE A DIAMETER CHANGE AT SPOTS TO BE 7.5"AND ROOTS AT JOINTS (SM). CAMERA FLIPPED @ 158'.

Tabular Report of PLR C12S-032 X **for** Clyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 22
Facility 8312	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 279.0 ***Ft***	***From*** C12S-032 ***Depth*** 12.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-035 ***Depth*** 25.00 ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining Plastic	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note extra sections
Location note on soledad mtn. rd.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-032
00000	0.0		WL	Water level				3	
	54.0		RJ	Roots at joint	M				
	121.1		CN	Service Connection		02			
	124.2		RJ	Roots at joint	S				
	125.6		RJ	Roots at joint	S				
	128.3		SA	Survey abandoned					CAM. FLIPPED

128.3 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 125	***Mean Defect*** 31.3	***Peak*** 75	***Mean Pipe*** 1

Notes

Extra section main is lined and has joints w/ roots from them (S,M).

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



Tabular Report of PLR C12S-032 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 23
Facility 8312	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 279.0 ***Ft***	***From*** C12S-035 ***Depth*** 25.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-032 ***Depth*** 12.00 ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Up
Lining Plastic	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note Reverse set up on sheet:22
Location note on soledad mtn. rd.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-035
00000	0.0		WL	Water level				3	
	6.5		LL	Bend in pipe left					
	11.4		LC	Lining Defect	S				
	86.6		DC	Diameter of sewer changes				07.5	
	129.0		CN	Service Connection		09			
	156.0		RJ	Roots at joint	S				
	158.4		DC	Diameter of sewer changes				07.5	
	158.4		SA	Survey abandoned					CSAM. FLIPPED

158.4 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 50	***Mean Defect*** 25	***Peak*** 50	***Mean Pipe*** 0.3
Service:	***Total*** 25	***Mean Defect*** 12.5	***Peak*** 25	***Mean Pipe*** 0.2

Notes

Found repairs on this 8" vc lined main made diameter change in spots to be 7.5" and roots at joints (S), cam. flipped @ 158'.

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego ***Phone:*** ***Fax:***

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	8	CMP	07/26/07	1

Cross Street Name

Fac Type	Fac Seq #
MAIN	8311

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description

PIPE INTEGRITY / EXTRA SECTION.

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 11:34:00	7/26/2007 11:45:53	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

THIS EXTRA SECTION OF MAIN IS LINED, @ 127.3' IS A LATERAL W/ ROOTS FROM IT (LRG.) WHICH MADE THE CAMERA FLIP. REVERSE SET-UP FOUND MAIN CLEAR UP UNTIL REACHING ROOTS THAT STOPPED CAMERA GOING D/S.

Tabular Report of PLR C12S-384 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 20
Facility 8311	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 156.0 ***Ft***	***From*** C12S-384 ***Depth*** 12.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-032 ***Depth*** ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining Plastic	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note extra sections
Location note on soledad mtn. rd.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-384
00000	0.0		WL	Water level				3	
	11.7		CN	Service Connection		03			
	51.3		CN	Service Connection		10			
	113.4		CN	Service Connection		03			
	127.3		CN	Service Connection		03			
	127.3		CR	Roots from lateral	L	03			
	128.5		SA	Survey abandoned					CAM. FLIPPED

128.5 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 75	***Mean Defect*** 37.5	***Peak*** 75	***Mean Pipe*** 0.6

Notes

Extra section this main is lined @ 127.3' is a lateral w/ roots from it (L) that made cam. flip.

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego Phone: Fax:

Tabular Report of PLR C12S-384 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 21
Facility 8311	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 156.0 ***Ft***	***From*** C12S-032 ***Depth*** ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-384 ***Depth*** 12.00 ***Ft***
Material Vitrified clay	***Joint Spacing*** ***Ft***	***Direction*** Up
Lining Plastic	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note Reverse set up on sheet:20
Location note on soledad mtn. rd.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-032
00000	0.0		WL	Water level				3	
	11.5		CN	Service Connection		09			
	28.5		CN	Service Connection		02			
	28.5		CR	Roots from lateral	L	02			
	29.5		R	Roots	L				ROOTS AHEAD
	30.0		SA	Survey abandoned					CAN NOT PASS

30.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 175	***Mean Defect*** 58.3	***Peak*** 100	***Mean Pipe*** 5.8

Notes

Tved for rev. set up found 2 laterals w/ roots from them (L)

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego ***Phone:*** ***Fax:***

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	9	CMP	07/26/07	1

Cross Street Name

Fac Type	Fac Seq #
MAIN	5185137

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description

PIPE INTEGRITY / EXTRA SECTION.

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 11:21:41	7/26/2007 11:21:41	METRO WASTE WATER DEPT	8202	3	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

TV'D THIS EXTRA SECTION GOING D/S, FOUND BELL JOINTS @ MATERIAL CHANGES. THE LAST JOINT (BELL) @ 101' CAMERA COULD NOT PASS. DID A REVERSE SET-UP AND WAS AGAIN STOPPED BY A BELL JOINT @ 51'. SURVEY WAS ABANDONED.

Tabular Report of PLR C12S-029 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 18
Facility 5185137	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 254.0 ***Ft***	***From*** C12S-029 ***Depth*** 15.00 ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-384 ***Depth*** ***Ft***
Material Polyvinly chloride	***Joint Spacing*** ***Ft***	***Direction*** Down
Lining	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note extra sections tv to assess condition
Location note on soledad mtn. rd.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-029
00000	0.0		WL	Water level				1	
	3.5		RJ	Roots at joint	L				
	4.5		RJ	Roots at joint	L				
	5.0		CN	Service Connection		03			
	28.6		MC	Material of sewer changes					TO VC
	34.4		MC	Material of sewer changes					BACK TO PVC
	37.9		LL	Bend in pipe left					
	62.4		CN	Service Connection		03			
	93.1		MC	Material of sewer changes					TO VC
	98.3		GO	General observation					BELL JOINT
	100.5		MC	Material of sewer changes					TO PVC
	101.0		SA	Survey abandoned					CAM CAN NOT PASS

101.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 200	***Mean Defect*** 66.7	***Peak*** 100	***Mean Pipe*** 2

Notes

Extra section tved d/s found bell joints @ materical changed and at 101' the cam. would not pass.

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego Phone: Fax:

Tabular Report of PLR C12S-029 X **for** Ciyt of SD

Work Order 3000622	***Contract***	***Video*** cd	***Setup*** 19
Facility 5185137	***Operator*** parker	***Van Ref*** 303005	***Surveyed On*** 07/26/2007

Street Name 5715 soledad mtn rd. ***City*** san diego
Location type Road carriageway
Surface Chip seal road
Survey purpose Specific problems on sewer system related to structural ***Weather*** Dry

Pipe Use Sanitary	***Sched length*** 254.0 ***Ft***	***From*** C12S-384 ***Depth*** ***Ft***
Shape Circular	***Size*** 8 ***by*** ***ins***	***To*** C12S-029 ***Depth*** 15.00 ***Ft***
Material Polyvinly chloride	***Joint Spacing*** ***Ft***	***Direction*** Up
Lining	***Year laid***	***Pre-clean*** ***Last Cleaned***

General note Reverse set up on sheet:18
Location note on soledad mtn. rd.

Structural Service Constructional
Miscellaneous Hydraulic

Video	Count	CD	Code		Sev	Fr	To	Value	Remarks
00000	0.0		ST	Start of Survey					
00000	0.0		MH	Manhole/Node					C12S-384
00000	0.0		WL	Water level				1	
	23.5		JD	Joint Displaced	S				
	50.3		MC	Material of sewer changes					TRO VC
	51.0		SA	Survey abandoned					CAN NOT PASS

51.0 Ft ***Total Length Surveyed***

Scores

Structural:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0
Service:	***Total*** 0	***Mean Defect*** 0	***Peak*** 0	***Mean Pipe*** 0

Notes

Rev. set up another bell joint stopped cam.

Clock references: Clock references are given clockwise ie from 10 o'clock to 2 o'clock = 1002. The upper part of a pipe is 0903 and the lower half is 0309. See Illustration below



City of San Diego ***Phone:*** ***Fax:***

SWIM Workorder

Printed on: 10/4/2007

Nature of Complaint

TELEVISE
UNSCHEDULED MAINTENANCE

Street #	Fr	Predir	Street Name	Sfx	Suite #	Juris
5715			SOLEDAD MTN	RD		SD

Intersection

Location Description | **Water/Sewer**

5715 SOLEDAD MAOUNTAIN ROAD (CORRECT ADDRESS) | S

SR #	WO #	Status	Gen Dt	Prty
3000622	10	CMP	07/26/07	1

Fac Type	Fac Seq #
MAIN	8307

Cross Street Name

Requestor Name	Area	Phone #	Contact
			N

☐ Complete
☐ Sketch

ES Service Area	Service Area	Field Book Pg	Grid
W	RC	C12S	

Radio#	Orig Radio#	Thos Bros Pg
946	946	1248A2

Job Description

PIPE INTEGRITY / EXTRA SECTION.

Special Instructions

Work Cd	Work Code Desc	Action Code	Action Code Desc
TV	TV INSPECT	TV03	TELEVISED MAIN COND ASSESS

Motive Equipment Used

Equip Nbr	Hours

Rental Equipment Used

Equipment Type	Operated	Hours
	◯ Yes ◯ No	
	◯ Yes ◯ No	
	◯ Yes ◯ No	

Start Date/Time	End Date/Time	Department	Job Order Number	Employees	Hours
7/26/2007 11:16:07	7/26/2007 11:16:08	METRO WASTE WATER DEPT	8202	2	1

Service Request Comments

PER 946 REQ FLUSHER CREW TO FLUSH FSN#8307 ON 8"VC MAIN, CAN HOLD..PAGED 8794..JKL

PGED 758..JKL

PER 758, ASSISTED IN FLUSHING MAIN FOR CITY PROTECTION....MF

Work Order Comments

THIS EXTRA SECTION HAS A LATERAL W/ ROOTS FROM IT (LRG.) AND FROM AROUND THE TAP (SM.). ALSO A CIRCULAR CRACK AT A JOINT NEAR THE D/E MH.