HILLMANN
CONSULTING

PHASE I ENVIRONMENTAL SITE ASSESSMENT



MAKING A BETTER FUTURE FOR ALL THE COMMUNITIES WE TOUCH

7020 Airway Road

San Diego, California 92154

PREPARED FOR:

JPI REAL ESTATE ACQUISITION II, LLC
12250 EL CAMINO REAL, SUITE 380
SAN DIEGO, CALIFORNIA 92130

HILLMANN PROJECT NUMBER: C3-9535
MAY 1, 2023

Your Property. Our Priority

Environmental Health & Safety | Due Diligence & Remediation Services | Construction Services

HILLMANN
CONSULTING

May 1, 2023

Mr. Conner Kloeppel
JPI Real Estate Acquisition II, LLC
12250 El Camino Real, Suite 380
San Diego, California 92130

RE: Phase I Environmental Site Assessment
7020 Airway Road
San Diego, California 92154
Hillmann Project No: C3-9535

Dear Mr. Conner Kloeppel:

Hillmann Consulting LLC has completed a Phase I Environmental Site Assessment at the above referenced site. This assessment was performed in conformance with the scope and limitations of ASTM E1527-21, which is the latest version of the E1527 standard published by the ASTM.

We appreciate the opportunity to provide environmental consulting services. If you have any questions concerning this report, or if we can assist you in any other matter, please contact our office at 714-634-9500.

Sincerely,

Hillmann Consulting LLC

Stephen Bartlett
Senior Project Manager

Ryan Terwilliger
West Coast Operations Manager

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY 2
1.1 Summary of Project Details 2
1.2 Findings Summary Table 3
1.3 Findings, Opinions and Conclusions 3
1.4 Business Environmental Risks / Non-ASTM Scope 6
2.0 INTRODUCTION 7
2.1 Purpose and Scope 7
2.2 Property Location/Legal Description 10
2.3 Data Gaps 10
2.4 ESA Report Component Dates/Viability 11
2.5 User Reliance 11
2.6 Significant Assumptions 11
2.7 General Limitations and Exceptions 12
3.0 USER PROVIDED INFORMATION 15
3.1 Prior Environmental Reports/Documentation 15
3.2 User Responsibilities 15
4.0 RECORDS REVIEW 18
4.1 Environmental Information 18
4.2 Historical Research 26
5.0 INTERVIEWS 32
5.1 Interviews with Owners, Operators and Occupants 32
5.2 Interviews with State and/or Local Government Officials 33
6.0 SITE RECONNAISSANCE 34
6.1 Methodology and Limiting Conditions 34
6.2 General Site Setting 34
6.3 Site Features and Conditions 36
7.0 BUSINESS ENVIRONMENTAL RISKS 38
7.1 Asbestos-Containing Material (ACM) 38
7.2 Lead-Based Paint 38
7.3 Radon 38
7.4 Mold/Microbial Damage 38
7.5 NWI Mapped Wetlands 39
7.6 Lead in Drinking Water 39
8.0 REFERENCES 40

APPENDIX A	Site Diagram/Vicinity Map
APPENDIX B	Site Photographs
APPENDIX C	Questionnaires / User Provided Information
APPENDIX D	Regulatory Records Documentation
APPENDIX E	Historical Records Documentation
APPENDIX F	Other Documents / Lab Results
APPENDIX G	Project Personnel Qualifications

LIST OF ACRONYMS/ABBREVIATIONS

Hillmann may use the following abbreviations and acronyms for common terminology described in our report. Not all abbreviations or acronyms may be applicable to this report:

AOC	-Area of Concern
AST	-Above Ground Storage Tank
ASTM	-American Society for Testing Materials
BER	-Business Environmental Risk
CERCLA	-Comprehensive Environmental Response Compensation and Liability Act
CERCLIS	-Comprehensive Environmental Response Compensation and Liability Information System
CESQG	-Conditionally Exempt Small Quantity Generator
COC	-Chemicals of Concern
CORRACTS	-Corrective Action Sites
CREC	-Controlled Recognized Environmental Condition
DEC	-Department of Environmental Conservation
DEP	-Department of Environmental Protection
DHS	-Department of Health Services
DNPL	-Delisted National Priority List
DOB	-Department of Buildings
DOH	-Department of Health
DOT	-Department of Transportation
EPA	-Environmental Protection Agency
ERNS	-Emergency Response Notification System
FD	-Fire Department
FOI/FOIA/FOIL	-Freedom of Information / Freedom of Information Act / Freedom of Information Letter
HVAC	-Heating Ventilation & Air Conditioning
HREC	-Historical Recognized Environmental Condition
IAQ	-Indoor Air Quality
ISRA	-Industrial Site Recovery Act
LBP	-Lead-Based Paint
LCP	-Lead-Containing Paint
LQG	-Large Quantity Generator
LTANK	-Leaking Storage Tank
LUST	-Leaking Underground Storage Tank
SDS/MSDS	-Safety Data Sheet / Material Safety Data Sheet
NA	-Not Applicable
NFA	-No Further Action
NFRAP	-No Further Remedial Actions Planned
NPDES	-National Pollutant Discharge Elimination System
NPL	-National Priorities List
OPRA	-Open Public Records Act
PAH	-Polycyclic Aromatic Hydrocarbon
PCE	-Perchloroethylene
RAO	-Response Action Outcome
RCRA	-Resource Conservation and Recovery Act
RCRIS	-Resource Conservation and Recovery Information System
REC	-Recognized Environmental Concern
SDG	-Significant Data Gap
SEMS	-Superfund Enterprise Management System
SRP	-Site Remediation Program
SQG	-Small Quantity Generator
SVOC	-Semi-Volatile Organic Compound
TCE	-Trichloroethylene
TSDF	-Treatment Storage and/or Disposal Facility
UST	-Underground Storage Tank
VEC	-Vapor Encroachment Condition
VOC	-Volatile Organic Compound

1.0 EXECUTIVE SUMMARY

Hillmann Consulting LLC (Hillmann) has performed a Phase I Environmental Site Assessment (ESA) of 7020 Airway Road, San Diego, California (the Subject Property in accordance with our contracted scope of work and the ASTM Standard Practice E 1527-21 for Phase I Environmental Site Assessments and All Appropriate Inquiries (AAI) Final Rule 40 CFR Part 312. This section contains a summary of findings, opinions and conclusions made by this assessment. However, this section, alone, does not constitute the complete assessment. The report must be read in its entirety.

1.1 Summary of Project Details

Primary Street Address:	7020 Airway Road				
City:	San Diego	County:	San Diego	State:	California
Tax ID/Parcel Number:	646-100-77-00				
Property Owner:	Paez Joseph Jr				
Zoning Designation:	Agricultural				
Approx. Property Area:	37.79-acre				
Buildings:	None				
Approx. Building Size:	NA				
Approx. Year Built:	NA				
Commercial Occupants:	NA				
Current Use:	Vacant land				
Site Visit Personnel:	Jason Norton				
Site Contact/Company:	Conner Kloeppel / JPI				
Site Escort/Company:	Unescorted				
Inspection Date:	April 19, 2023				
Weather Conditions:	65° F / Sunny				

1.2 Findings Summary Table

Assessment Subject	No REC	REC	CREC	HREC	SDG	Rpt. Ref.
Regulatory Records Review:	✔					4.1
Historical Records Review:	✔					4.2
Bulk Petroleum Storage:	✔					6.3
On-Site Operations:	✔					6.3
On-Site Haz-Mat Storage/Use/Spills:	✔					6.3
Transformers/Hydraulic Systems:	✔					6.3
Waste Discharges:	✔					6.3
Interviews:	✔					5.0
Adjoining/Surrounding Area:	✔					4.0 6.2
Prior Env. Reports/User Provided Info:	✔					3.0

1.3 Findings, Opinions and Conclusions

Recognized Environmental Conditions & Significant Data Gaps

Hillmann has performed a Phase I Environmental Site Assessment in accordance with the scope and limitations of ASTM Practice E 1527-21 of the Subject Property as described in Section 2.2 of this report. Any additions to, exceptions to, or deletions from this practice are also described in Section 2 of this report. This assessment has revealed the following recognized environmental conditions (RECs), controlled recognized environmental conditions (CRECs) and/or significant data gaps (SDGs) in connection with the Subject Property:

RECOGNIZED ENVIRONMENTAL CONDITIONS
No RECs were identified.
CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS
No CRECs were identified.
SIGNIFICANT DATA GAPS
No SDGs were identified.
RECOMMENDATIONS
None identified.

Historical Recognized Environmental Conditions (HRECs)

If identified, *historical recognized environmental conditions* (HRECs) in connection with the Subject Property are described below:

HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS
No HRECs were identified.

De Minimis and Other Environmental Conditions

If identified, *de minimis* and other environmental conditions are described below:

OTHER ENVIRONMENTAL CONDITIONS / DE MINIMIS CONDITIONS
The Subject Property was historically utilized as agricultural land from at least 1949 to 1996. Hillmann reviewed a prior Phase I Environmental Site Assessment conducted by C. Young Associates and dated July 2022, which indicated that Limited Soil Sampling was conducted due to the historical agricultural usage of the Subject Property. A total of fifty (50) discrete soil samples were composited into thirteen (13) composite samples and analyzed for organochlorine pesticides (OCPs) using EPA Method 8081A. Additionally, a total of thirteen (13) of the fifty (50) discrete samples were analyzed for arsenic in accordance with EPA Method 6010. Laboratory analysis indicated arsenic levels consistent with naturally occurring background concentrations ranging between 2.0 milligrams per kilogram (mg/kg) to 5.14 mg/kg, OCPs 4,4-DDD, DDE and DDT were detected, but concentrations were below the residential human health risk-based screening levels. However, toxaphene was detected in twelve (12) out of the thirteen (13) composite samples ranging from 726 µg/kg to 2,470 µg/kg. The toxaphene screening levels are above the residential human health risk-based screening level of 510 micrograms per kilogram (µg/kg). No information was available to suggest that pesticides applied at the Subject Property were not applied applied in a legal manner, therefore the historic usage of pesticides at the Subject Property can be considered a Business Environmental Risk (BER) rather than a REC. Given the prior soil sampling data indicating elevated levels of pesticides throughout the Subject Property, the contaminated soil will likely need to be either removed or encapsulated prior to redevelopment. Therefore, this is considered to be a Business Environmental Risk (BER) in connection with the Subject Property.

Environmental Professional Statement

I/We declare that, to the best of my professional knowledge and belief, I/we meet the definition of Environmental professional as defined in § 312.10 of 40 C.F.R. 312. I/we have the specific qualifications based on education, training and experience to assess a property of the nature, history and setting of the subject property. I/We have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 C.F.R. Part 312.



Ryan Terwilliger

Environmental Professional

1.4 Business Environmental Risks / Non-ASTM Scope

Hillmann has performed a limited review of the following potential Business Environmental Risks (BER), also known as "Non-ASTM Scope concerns", in accordance with the contracted scope of work scope for this assessment. BER is defined by ASTM E1527-21 as "*a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice.*" The following is a summary of findings for the limited review of potential BERs, where applicable, as per the contracted scope of work and limitations outlined in Section 2. For a more detailed discussion of the findings and contracted scope of work, please see the referenced report section.

Subject	Findings	Not Appl.	Rpt. Ref.
Asbestos		✔	7.1
Lead Paint		✔	7.2
Radon	Property is located in the USEPA radon designation Zone 3 or 'low risk' area for radon.		7.3
Mold/ Microbial Damage		✔	7.4
NWI Wetlands	A review of NWI Wetlands Mapper did not indicate regulated wetland areas on the Subject Property.		7.5
Lead in Drinking Water	No potable water services were present at the Subject Property.		7.6

2.0 INTRODUCTION

2.1 Purpose and Scope

This assessment was conducted utilizing generally accepted Phase I ESA industry standards in accordance with the ASTM Standard Practice E 1527-21. The ASTM describes these methodologies as representing good commercial and customary practice for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. § 9601) and petroleum products. This practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner or bona fide prospective purchaser limitations on CERCLA liability ("landowner liability protections," or "LLPs"): that is, the practice that constitutes all appropriate inquiries into the previous ownership and uses of the Subject Property consistent with good commercial and customary practice as defined at 42 U.S.C. §9601(35) (B). The goal of the processes established by ASTM E1527-21 is to identify *recognized environmental conditions* in connection with the Subject Property.

The term *recognized environmental condition* (REC) is defined by ASTM E1527-21 as "*(1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.*"

The term *controlled recognized environmental condition* (CREC) is a type of recognized environmental condition and defined by ASTM E1527-21 as a "*recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations).*"

The term *historical recognized environmental condition* (HREC) is defined as a "*previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations).*" The ASTM E1527-21 standard has clarified that a historical recognized environmental condition is not a recognized environmental condition.

The term *de minimis condition* is defined by the ASTM, "*...a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.*" A condition determined to be a de minimis condition is not REC nor a CREC.

The chief components of this assessment are generally described as follows:

- A non-invasive visual reconnaissance of the Subject Property and adjoining properties in accordance with ASTM guidelines for evidence of RECs.

- Interviews of past and present owners and occupants and state and local government officials, seeking information related to the potential presence of RECs at the Subject Property.

- A review of standard physical record sources for available topographic, geologic and groundwater data.

- A review of standard historical record sources, such as fire insurance maps, city directories, aerial photographs, prior reports and interviews, etc., to determine prior uses of the Subject Property from the present, back to the Subject Property's first developed use, or back to 1940, whichever is earlier.

- A review of standard environmental record sources including federal and state environmental databases, and additional environmental record sources, to identify potential regulatory concerns with the Subject Property, adjoining properties and properties located within the surrounding area.

An evaluation of environmental or other regulatory compliance matters is excluded from the scope of this assessment.

These methodologies are described as representing good commercial and customary practice for conducting an Environmental Site Assessment of a property for the purpose of identifying recognized environmental conditions.

Business Environmental Risks/Non-ASTM Scope Considerations

In accordance with our contract agreement, Hillmann may have addressed the following potential environmental subject matters that are outside of the requirements of the ASTM E1527-21 standard:

- Asbestos-Containing Materials (ACM): A cursory non-intrusive visual screening for the presence of suspect ACM within the accessed areas of buildings built prior to 1990 on the Subject Property. If the Subject Property contains buildings built in 1990 or later, the contracted scope of work excludes a cursory non-intrusive visual screening or any other level of evaluation for suspect ACM; however, the exclusion for buildings built ≥1990 should not be interpreted to suggest that any such buildings are free of ACM or would not warrant evaluation of building materials for ACM prior to disturbance. It is emphasized that this cursory non-intrusive visual screening does not constitute an asbestos survey/ inspection of the premises. An asbestos survey/inspection should be sought by the report User(s) if a greater certainty is desired regarding ACM and potential asbestos hazards at the Subject Property. Furthermore, a review of regulatory compliance matters pertaining to asbestos is excluded from the scope of work.

- Lead-Based Paint (LBP): A cursory non-intrusive visual screening of the condition of painted surfaces in the accessed areas of residential buildings/units built prior to 1980 on the Subject Property. If the Subject Property contains buildings built in 1980 or later, the contracted scope of work excludes any cursory non-intrusive visual screening or other level of evaluation for suspect LPB; however, the scope of work exclusion for building built ≥1980 should not be interpreted to suggest that any such buildings are free of LPB or other lead hazards. It is emphasized that this cursory non-intrusive visual screening does not constitute a comprehensive survey for LBP or potential lead hazards. A comprehensive inspection should be sought by the report User(s) if more certainty is desired regarding LBP at the Subject Property. Furthermore, a review of regulatory compliance matters pertaining to lead-based paint is excluded from the scope of work.

- USEPA Designated Radon Potential: Review of general non-site specific data published by the USEPA regarding the Radon Zone classification for the area of the Subject Property.

- Mold/Microbial Damage: A cursory non-intrusive visual screening within the accessed areas of buildings on the Subject Property for evidence of systemic microbial problems, including visible mold growth, water damaged building materials or musty odors. It is emphasized that this cursory non-intrusive visual screening does not constitute a comprehensive survey for moisture/mold/microbial damage. A more comprehensive inspection should be sought by the report User(s) if more certainty is desired regarding the potential for moisture/mold/microbial damages at the Subject Property.

- NWI Wetlands: The Subject Property has been reviewed for jurisdictional wetlands using the National Wetlands Inventory-Wetland Mapper to determine whether mapped federal wetlands have been indicated on the Subject Property. Any further evaluation or legal delineation of regulated wetlands areas is excluded from the scope of work. It is also emphasized that a field delineation of regulated wetlands by a qualified professional

would be warranted to more fully determine the presence or absence of regulated wetlands at the Subject Property.

- Lead in Drinking Water: Review of the potential for elevated levels of lead in the drinking water by determining the source of the drinking water supply and a review of available testing or compliance data reports.

2.2 Property Location/Legal Description

Property location and legal description details are described as follows:

Primary Street Address:	7020 Airway Road				
City:	San Diego	County:	San Diego	State:	California
Tax ID/Parcel Number:	646-100-77-00				
Approx. Land Area:	37.79-acre				
Apprx. Latitude/Longitude:	North 32.5624890 degrees/West 116.986240 degrees				
Additional Details (if appl.)	N/A				
Property Owner:	Paez Joseph Jr				
Zoning Designation:	Agricultural				

2.3 Data Gaps

A *data gap* is defined by the ASTM as a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. A data gap is only significant if other information and/or professional experience raises reasonable concerns involving the data gap and the ability to determine the presence or absence of recognized environmental conditions. The following table summarizes data gaps encountered during the assessment as well as a discussion of their significance.

Data Gap:	Significant (Yes/No)?	Discussion
Historical records data failure	No	The date and/or type of the first developed use of the Subject Property was not determined. Records gaps exceeding five years were encountered; however, no significant site use changes are suspected during these intervals.
Response to agency records requests not received as of date of report.	No	Any additional information indicative of a REC will be forwarded upon receipt.

2.4 ESA Report Component Dates/Viability

The ASTM E1527-21 standard states that an environmental site assessment (ESA) is presumed to be viable when it is conducted within 180 days prior to the date of acquisition of the Subject Property (or, for transactions not involving an acquisition such as a lease or refinance, the date of the intended transaction). Specifically, all of the following components must be conducted or updated within 180 days prior to the date of acquisition or prior to the date of the transaction. The following table summarizes the component completion dates:

ESA Component	Completion Date
Interviews:	April 24, 2023
Env. Lien Search:	(excluded from scope)
Government Records Review:	April 11, 2023
Visual Inspections:	April 19, 2023
Env. Professional Declaration:	May 1, 2023

2.5 User Reliance

This report is for the exclusive use of JPI Real Estate Acquisition II, LLC and additional relying entities, if any, named on the front cover. No additional individuals or entities shall be permitted to rely upon any data, interpretation, reports or other information or documentation contained in this report, without first obtaining the consent of JPI Real Estate Acquisition II, LLC; and without obtaining written consent from Hillmann in the form of a reliance agreement/letter.

Hillmann may, in its sole discretion, withhold its consent to additional reliance and/or Hillmann may condition consent for reliance upon payment of a fee or other conditions.

2.6 Significant Assumptions

The following significant assumptions are made:

- The site operations at the time of the site visit are assumed to reflect typical site conditions relative to potential environmental conditions and that no concealment of environmental conditions or releases by site owners or occupants has occurred. Likewise, it is assumed that no areas of the Subject Property with potential environmental concerns or RECs were concealed or otherwise not reported, intentionally or unknowingly, by the Subject Property owners/occupants and/or site escort at the time of the site visit.

- For the purpose of estimating the approximate direction of groundwater flow in the absence of site-specific groundwater data, unless indicated otherwise, an assumption has been made that the gradient of groundwater flow follows the surface topography of the Subject Property and immediate surrounding area.

2.7 General Limitations and Exceptions

Limitations

The report turnaround time specified by the contract agreement for this assessment may present a limitation to the availability of pertinent regulatory agency records. Such limitations, if encountered, would be further specified in Section 4.1.

Significant limitations related to the condition or accessibility of the Subject Property at the time of the site reconnaissance, if encountered, are reported in Section 6.1.

Other Exceptions or Deletions

No other exceptions or deletions from the ASTM Standard E 1527-21 are reported.

Special Terms and Conditions

This Phase I Environmental Site Assessment has been prepared using reasonable efforts in each phase of its work to identify recognized environmental conditions associated with hazardous substances, wastes and petroleum products at the Subject Property. Findings within this report are based on information collected from observations made on the day of the site reconnaissance and from reasonably ascertainable information obtained from governing public agencies and private sources.

This report is not definitive and should not be assumed to be a complete or specific definition of the conditions above or below grade. Information in this report is not intended to be used as a construction document and should not be used for demolition, renovation, site development, redevelopment, or other construction purposes. No representation or warranty is made that the past or current operations at the Subject Property are, or have been, in compliance with all applicable federal, state and local laws, regulations and codes.

Findings, conclusions and recommendations presented in this report are based on visual observations of the Subject Property, interviews conducted, the records reviewed, information provided by the Client, and/or a review of readily available and supplied drawings and documents.

No warranty or guarantee is made of the accuracy or completeness of information that was obtained from ostensibly knowledgeable individuals, regulatory agency representatives or other secondary sources, including information obtained during the assessment, whether written, graphic or verbal, provided by the Subject Property contact(s) or as shown on any documents reviewed or received from the Subject Property contact, owner or agent, or government agency source. Independent verification of the accuracy or completeness of all information reviewed or received during the course of this assessment is not made and excluded from the scope of work for this assessment.

Regardless of the findings stated in this report, Hillmann is not responsible for consequences or conditions arising from facts that were concealed, withheld or not fully disclosed at the time the assessment was conducted.

This report does not warrant against future operations or conditions, nor does it warrant against operations or conditions present of a type or at a location not investigated.

The regulatory database report provided is based on an evaluation of the data collected and compiled by a contracted data research company. Hillmann can neither warrant nor guarantee the accuracy or completeness of the information obtained from the regulatory database report provider during the course of this assessment.

Subsurface conditions may differ from the conditions implied by the surface observations and can only be reliably evaluated through intrusive techniques.

Reasonable efforts have been made during this assessment to identify aboveground and underground storage tanks and ancillary equipment. Reasonable efforts are limited to information gained from visual observation of largely unobstructed areas, recorded database information held in public record and available information gathered from interviews. Such methods may not identify surficial and subsurface features that may have been hidden from view due to parked automobiles and other vehicles, snow cover, vegetative growth, pavement, construction or debris pile storage or incorrect information from sources.

No guarantee, explicit or implied, is made that the records pertaining to historical ownership or occupancy which were reviewed represent a comprehensive or precise delineation of past Property ownership or tenancy for legal purposes.

The ASTM E1527-21 standard states that recommendations are not required to be included in a Phase I ESA report; however, further that recommendations are an additional service that may be useful in the User's analysis of landowner liability protections or business environmental risks; and that the User should consider whether recommendations for additional inquiries or other services are desired.

Recommended response actions offered in Section 1.3, if any, are provided as an option to the Client, and may have taken into account the Client's relation to the Subject Property and/or their intended purpose of this assessment. If included, it is not intended by Hillmann to represent the only course(s) of action, or inaction, to take. Furthermore, it is emphasized that additional response actions may become advisable depending on the outcome of the initial action(s) taken. Hillmann advises that Client and any additional authorized relying parties as specified on the report Cover and Section 2.5, or via letter of reliance extension, undertake consultation with legal counsel familiar with environmental and real estate law would be beneficial to the decision making process for the type and timing of a response action to identified RECs or Business Environmental Risks, if any.

Due to the limited nature of our review of potential Business Environmental Risks, the User(s) of the report should consider whether to take additional action(s) to further define, properly manage and/or mitigate potential BERs.

The User(s) assumes responsibility for business decisions that it makes utilizing information in the report provided by Hillmann. Hillmann shall not be responsible for any conclusions, interpretations and/or decisions of the User(s).

In the event of any conflict between the terms and conditions of this report and the terms and conditions of the consulting services agreement for this project, the consulting services agreement shall control.

3.0 USER PROVIDED INFORMATION

The term “User” is defined by ASTM as the party seeking to use Practice E1527 to complete an environmental site assessment of the Subject Property; specifically, the entity or entities named on the front cover to which the report has been addressed.

3.1 Prior Environmental Reports/Documentation

The following prior environmental reports/documentation was provided:

Phase I Environmental Site Assessment, Paez Property (APN 646-100-77-00), Airway Road and Cactus Road, San Diego, California 92154; prepared by C Young Associates and dated July 8, 2022. Below is the summary of the findings.

- *"With the exception of the prevalence of the OCP Toxaphene in shallow topsoil at the Site, no features and/or conditions indicating the presence or likely presence of hazardous substances and/or petroleum products that potentially have a significant impact to the Site were identified at the Site during the completion of this Phase I ESA. However, being that the pesticides appear to have been legally applied and are not the result of an accidental spill or release, this is not considered to be a “recognized environmental condition” in connection with the Site. However, it is considered to be a business environmental risk to be handled during future development activities by way of selective grading and soil management. This is considered a common practice and condition at development projects in the general locale of the Site."*

- *"This Phase I ESA has revealed no evidence of “recognized environmental conditions,” “controlled recognized environmental conditions” or “historical recognized environmental conditions” in connection with the Site. Additional assessment at the Site is not considered to be warranted at this time."*

3.2 User Responsibilities

In order to qualify for Landowner Liability Protections (LLPs) offered by federal regulations, the User must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. The User should provide the following information to the environmental professional (Hillmann). Failure to conduct these inquiries could result in a determination that “all appropriate inquiries” is not complete. To assist the report User to meet these requirements, Hillmann has provided a questionnaire of inquiries (User Questionnaire) specified in 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31 with instructions to complete and return to Hillmann. A completed questionnaire was received by Hillmann. The following is a summary of the User's responses:

Question:	Yes/No:	Detail:
1. Search of Land Title and Judicial Records: Has the User performed a search of land title records and judicial records for environmental liens and/or Activity and Use Limitations (AULs) filed or recorded against the Subject Property?	No	
1.a. If yes to Question 1: Did the search identify any environmental liens or Activity and Use Limitations (AUL), such as engineering controls, land use restrictions or institutional controls that are in place at the Subject Property and/or have been filed or recorded against the Subject Property under federal, tribal, state or local law?	No	
1.b. If yes to Question 1: Has the User provided the result of the search of land title and judicial records to Hillmann?	NA	
2. Specialized knowledge or experience of the person seeking to qualify for the LLP: Do you have any specialized knowledge or experience related to the Subject Property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the Subject Property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	No	
3. Relationship of the purchase price to the fair market value of the Subject Property if it were not contaminated: Does the purchase price being paid for this property reasonably reflect the fair market value of the Subject Property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the Subject Property?	Yes	
4. Commonly Known or Reasonably Ascertainable Information: Are you aware of commonly known or reasonably ascertainable information about the Subject Property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example:		
4.a. Do you know the past uses of the Subject Property?	No	
4.b. Do you know of specific chemicals that are present or were once present at the Subject Property?	No	

4.c. Do you know of spills or other chemical releases that have taken place at the Subject Property?	No	
4.d. Do you know of any environmental cleanups that have taken place at the Subject Property?	No	
5. The degree of obviousness of the presence or likely presence of contamination at the Subject Property, and the ability to detect the contamination by appropriate investigation: Based on your knowledge and experience related to the Subject Property are there any obvious indicators that point to the presence or likely presence of releases at the Subject Property?	No	
6. Litigation, Administrative Proceedings, Government Notices: As the User of this ESA, do you have knowledge of (1) any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the Subject Property; (2) any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on or from the Subject Property; and (3) any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.	No	
7. User's Reason/Purpose for Performing Phase I ESA:	Hillmann understands that the assessment is being prepared in connection with a prospective real estate transaction involving the Subject Property.	

4.0 RECORDS REVIEW

4.1 Environmental Information

Physical Setting

Source	Discussion
USGS 7.5 minute Topo Map:	The Subject Property lies at an elevation of approximately 510 feet above mean sea level. An interpretation of topographic contour lines as well as a review of the EDR Geocheck-General Topographic Gradient suggested terrain sloping downward towards the west. There is no closest down gradient body of water.
USDA Soil Data: (EDR GeoCheck)	The soil type at the Subject Property is classified as "Stockpan". This soil type is described as having gravelly clay loam texture, with slow infiltration rates and high water table.
Geologic Data: (EDR GeoCheck)	The geologic formation in the vicinity of the Property is described as Cenozoic Era, Tertiary System, and Pliocene Series.
Prior Env. Reports: (Section 3.2)	Prior environmental reports reviewed as part of this assessment, as detailed in Section 3.1, did not provide additional pertinent detail of physical setting data.
Additional Sources/ Data:	No additional physical setting sources or data was obtained.
Groundwater Flow Discussion:	Based on a review of the above information as well as observation of the site, the direction of shallow groundwater flow at the site is inferred to be towards the west.

Federal, State and Tribal Environmental Record Sources

Standard government records were obtained and reviewed primarily via a third-party regulatory database report, titled EDR Radius Map™ Report, prepared by Environmental Data Resources of Shelton, CT. The report provided government records from the standard environmental resources and within minimum search distances specified by Section 8.2.2-Table 2 of the ASTM E1527-21; and were reviewed for the purpose of identifying potential RECs in connection with the Subject Property. Additional detail of the source and significance of the regulatory databases can be found in the regulatory database report in Appendix E. Hillmann has also included discussion of records pertaining to the Subject Property from other government record sources not specifically listed under Table 2, as applicable.

Reported distances for adjoining property listings, if applicable, are approximate and indicative of the presence of a public roadway or right-of-way between the adjoining site and Property.

The reported gradients have been estimated based on a number of factors including but not necessarily limited to field observation, review of topographic maps, database listing details and/or site specific geo-technical data.

Limited analysis of the details of on-site, adjoining and vicinity database sites was conducted to identify potential sources of sub-surface vapor encroachment. This review was based on elements of the ASTM "Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions" (ASTM E 2600-15); and also on elements of "Methodology for Identifying the Area of Concern Around a Property Potentially Impacted by Vapor Migration from Nearby Contaminated Sources" (Buonicore, 2011-S-103-AWMA). Vicinity database sites pertaining to non-petroleum product releases within 1,760 feet of the Subject Property in the up-gradient direction, 365 feet of the Subject Property in the cross gradient direction and 100 feet of the Subject Property in the down gradient direction; and vicinity database sites pertaining to petroleum product releases within 528 feet of the Subject Property in the up-gradient direction, 165 feet of the Subject Property in the cross gradient direction and 100 feet of the Subject Property in the down gradient direction were reviewed to identify active contamination sites with the potential to affect subsurface vapor conditions at the Subject Property. The potential for vapor encroachment was considered in assessing whether or not a REC exists in connection with the Subject Property when reviewing applicable sites within those distances.

Regulatory database sites with active petroleum or non-petroleum releases that are considered to constitute a vapor encroachment condition (VEC) to the Subject Property, if any, are identified and discussed in this section.

The EDR Radius Map report is attached in Appendix D.

Subject Property Listings

The following listings of the Subject Property were identified:

Name/Address:	No Subject Property listings.
Database(s):	
Data Discussion:	
REC Discussion:	
VEC Discussion:	

Adjoining Property Listings

The following adjoining property listings were identified.

Name/Address:	Irma Tatum / 1812 Cactus Road

Database(s):	RCRA-NoNGen/NLR
Dist./Dir./Gradient:	0 feet; Northwest; Down-gradient
Details:	The RCRA-NoNGen/NLR listing indicated the site currently does not produce hazardous waste, with no violations noted.
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.
VEC Discussion:	Based on the available data, a VEC is not suspected.

Name/Address:	Yvette Alcaraz / 1942 Cactus Road
Database(s):	RCRA-NoNGen/NLR
Dist./Dir./Gradient:	0 feet; West; Down-gradient
Details:	The RCRA-NoNGen/NLR listing indicated the site currently does not produce hazardous waste, with no violations noted.
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.
VEC Discussion:	Based on the available data, a VEC is not suspected.

Name/Address:	Tripp Salvage Landfill - Sesi Property - Aka Tripp / 1890 Cactus Road
Database(s):	CPS-SLIC, DEED, CERS
Dist./Dir./Gradient:	0 feet; West; Down-gradient
Details:	The site is listed on two (2) CPS-SLIC listing databases. One (1) CPS-SLIC listing indicated a No Further Action as of October 17, 2017. Based on the review of GeoTracker documents part of Tripp Salvage Landfill was utilized for dismantling automobile waste from 1968 to 1977, and it was estimated waste extends to a depth of approximately 65 feet. Groundwater samples collected in 1998 indicated elevated levels for VOCs, SVOCs, and metals. The site is listed on a "Land Use Covenant" since 2015 due to historical on-site operations. An additional CPS-SLIC listing was listed on-site, with a No Further Action as of June 11, 2012. Based on the review of the GeoTracker documents the CPS-SLIC case was opened due to dumping of debris at the site was, which was later categorized as hazardous waste. However, based on the regulatory oversight, down-gradient position and no further action letters, the listings do not indicate a REC in connection with the Subject Property.
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.
VEC Discussion:	Based on the available data, a VEC is not suspected.

Name/Address:	Otay Canyon Ranch / 2440 Cactus Road
Database(s):	CPS-SLIC
Dist./Dir./Gradient:	600 feet; West; Down-gradient

Details:	The CPS-SLIC listing indicated the site is listed on a Open - Site Assessment as of July 22, 2014. Based on the review of GeoTracker documents the site was part of a larger operation and the closest APN located to the Subject Property was noted as APN 646-100-20. Soil samples collected on the Subject Property indicated elevated concentrations of 4,4'-DDD, 4,4'-DDE, 4,4'-DDT, and toxaphene. The site had ongoing remedial activities under DEH oversight, including a Soil Management work completed in concurrent with grading and construction activities. The activities included cleaning and preparation of the northern and southern areas for development. A Soil Management Closure Report was conducted in September 2022. Confirmation soil samples collected from throughout the site indicated that remaining soils were suitable for residential and commercial development. The site is currently in the process of receiving a No Further Action letter from DTSC and RWQCB. The latest document on GeoTracker dated January 2023 concluded that the "*DTSC concurs with the waterboard and does not object to the issuance of NFA based on the information provided for this site.*" A No Further Action letter is anticipated to be received by the end of 2023. However, based on clean-up activities, regulatory oversight, and down-gradient position relative to the Subject Property, this is not considered to be in a REC.
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.
VEC Discussion:	Based on the available data, a VEC is not suspected.

Surrounding Area Findings

The following is a discussion of non-adjoining sites identified as located within the ASTM specified search distance surrounding the Subject Property. In order to keep this discussion informative and concise, discussion(s) is/are provided of the listed site(s) for each database category that appears most likely to impact the Subject Property based on distance, area topography and/or regulatory status. Listings of sites within the applicable search distances not specifically discussed below were reviewed and concluded not to be RECs in connection with the Subject Property or VECs based on various factors including distance, area topography, known or inferred groundwater flow direction and/or regulatory status.

Federal - NPL

ASTM Search Distance:	1-mile	Number of listings within ASTM Search Distance:	0
Notable Listing:	None		
Dist/Dir/Gradient:			
Details:			
REC Discussion:			
VEC Discussion:			

Federal - Delisted NPL

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	0
Notable Listing:	None		
Dist/Dir/Gradient:			
Details:			
REC Discussion:			
VEC Discussion:			

Federal - SEMS

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	0
Notable Listing:	None		
Dist/Dir/Gradient:			
Details:			
REC Discussion:			
VEC Discussion:			

Federal - SEMS Archive

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	0
Notable Listing:	None		
Dist/Dir/Gradient:			
Details:			
REC Discussion:			
VEC Discussion:			

Federal - CORRACTS

ASTM Search Distance:	1-mile	Number of listings within ASTM Search Distance:	0
Notable Listing:	None		
Dist/Dir/Gradient:			
Details:			
REC Discussion:			
VEC Discussion:			

Federal - RCRA-TSD

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	0
Notable Listing:	None		
Dist/Dir/Gradient:			
Details:			
REC Discussion:			
VEC Discussion:			

State/Tribal - Superfund & Hazardous Waste Sites

ASTM Search Distance:	1-mile	Number of listings within ASTM Search Distance:	3
Notable Listing:	Britannia Boulevard / 2133-2201 Britannia		
Dist/Dir/Gradient:	1,699 feet; east-southeast; down-gradient		
Details:	The ENVROSTOR listing indicated a "Certified O&M - Land Use Restrictions Only" with a "Voluntary Cleanup" site type status indicating the site was listed on a Land Use Restriction as of December 17, 2010.		
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.		
VEC Discussion:	Based on the available data, a VEC is not suspected.		

State/Tribal - Landfill / Solid Waste Disposal

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	1
Notable Listing:	Cactus Road - Aka Tripp Salvage / 1700-1902 Cactus Road		
Dist/Dir/Gradient:	501 feet; north-northwest; down-gradient		
Details:	The SWF/LF listing indicated a "Solid Waste Disposal Site," with a "Closed" operational status, and no violations noted. The salvage yard was redeveloped with Highway 905 since 2010 to present.		
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.		
VEC Discussion:	Based on the available data, a VEC is not suspected.		

State/Tribal - Leaking Storage Tanks

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	8
Notable Listing:	The City of San Diego - Brownfield / 1424 Continental Street		
Dist/Dir/Gradient:	1,718 feet; north; up-gradient		

Details:	The LUST listing indicated a "Preliminary site assessment underway" site status, which indicating soil at the site was contaminated with gasoline from a leaking UST; however, no further pertinent information was provided regarding the spill.
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.
VEC Discussion:	Based on the available data, a VEC is not suspected.

State/Tribal - Voluntary Cleanup Sites

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	1
Notable Listing:	Britannia Boulevard / 2133-2201 Britannia		
Dist/Dir/Gradient:	1,699 feet; east-southeast; down-gradient		
Details:	The VCP listing indicated a "Certified O&M - Land Use Restrictions Only" with a "Voluntary Cleanup" site type status indicating the site is listed on a Land Use Restriction as of December 17, 2010.		
REC Discussion:	Based on the details provided above, a REC is not suspected in connection with the Subject Property.		
VEC Discussion:	Based on the available data, a VEC is not suspected.		

State/Tribal - Brownfields

ASTM Search Distance:	1/2-mile	Number of listings within ASTM Search Distance:	0
Notable Listing:	None		
Dist/Dir/Gradient:			
Details:			
REC Discussion:			
VEC Discussion:			

Unmapped/Orphan List Sites

Hillmann has also reviewed a list of unmapped sites (a.k.a. “Orphan List” sites) indicated by the database report. Unmapped sites that were identified as falling within an applicable specific search distance or warranting discussion have either been discussed in the preceding tables or are detailed below:

Notable Listing(s):	None
Database(s):	
Dist/Dir/Gradient:	
Details:	

REC Discussion:	
VEC Discussion:	

Additional Environmental Record Sources

Requests have been submitted to local, municipal and state agencies for pertinent records pertaining to the Subject Property, particularly with regard to potential environmental concerns such as petroleum storage tanks, storage and usage of hazardous substances and petroleum products, and/or known or suspected environmental contamination. Where applicable, internet research of government environmental regulatory databases was also conducted, as well as a general cursory internet search of the Subject Property address, for information indicative of a REC. The following table summarizes the findings of the research:

Source	Type of Request	Outcome
EPA MyProperty	Online search	Hillmann searched online for records pertaining to the Property. No records pertaining to the property were found.
EPA Envirofacts	Online search	Hillmann searched online for records pertaining to the Property. No records pertaining to the property were found.
CA DTSC Envirostor database (www.envirostor.dtsc.ca.gov/public/)	Online search	Hillmann searched online for records pertaining to the Property. No records pertaining to the property were found.
CA GeoTracker database (geotracker.waterboards.ca.gov/)	Online search	Hillmann searched online for records pertaining to the Property. No records pertaining to the property were found.
CA DTSC	FOI request	A response was received stating that no records were found.
Regional Water Quality Control Board (RWQCB)	FOI request	No response was received prior to report issuance.
San Diego Co. CUPA	FOI request	A response was received stating that no records were found.
San Diego Air Quality Management District (SCAQMD)	FOI request	A response was received stating that no records were found.
City of San Diego	FOI request	No response was received prior to report issuance.

4.2 Historical Research

Historical records have been compiled and analyzed for historical property information and developing a history of previous uses of the Subject Property, adjoining properties and surrounding area. These records were reviewed for the purpose of identifying the likelihood of past uses having led to RECs in connection with the Subject Property.

The historical record sources listed below have been sought with the objective to document past uses of the Subject Property from the present back to the Subject Property's first developed use, or back to 1940, whichever is earlier. The term "developed use" includes agricultural use, placement of fill dirt and other uses that do not involve structures. Hillmann has sought to review historical records in minimum intervals of five years.

Fire Insurance Maps

A Certified Sanborn Map Report was obtained from EDR for a review of published historical fire insurance maps for the Subject Property and surrounding area. The following is a summary of site uses and notable details depicted by the available maps:

Year(s)	Subject Property	Adjoining Properties
	(none identified)	

A copy of the Certified Sanborn Map Report is attached in Appendix E.

City Directories

An EDR City Directory Abstract report was reviewed for data of prior occupants of the Subject Property's street address. The following is a generalized summary of the findings of city directory research for past occupants of the Subject Property.

Subject Property Use(s) / Occupant(s)	Years
(none identified)	

The EDR City Directory Abstract report was also reviewed for listings of prior occupants of the adjoining properties. The following is a generalized summary of the findings of city directory research for past occupants of the adjoining properties:

Adjoining Property Use(s) / Occupant(s)	Years
(none identified)	

A copy of the EDR City Directory report is attached in Appendix E.

Historical Topographic Maps

Historical topographic maps of the Property and vicinity obtained from an EDR Historical Topographic Map report (as attached in Appendix E) have been reviewed. The following interpretation of land usage was made by review of the maps:

Year(s)	Subject Property	Adjoining Properties
1903	No structures or significant features were depicted.	No structures or significant features were depicted.
1943	No structures or significant features were depicted.	A pond is depicted to the northwest; a structure to the south
1953, 1955	No structures or significant features were depicted.	A pond is depicted to the northwest; a structure with a reservoir to the south and southeast
1971, 1975	No structures or significant features were depicted.	A pond is depicted to the northwest; a structure with a reservoir to the south-southeast; multiple purple structures to the west indicating building development
1991	No structures or significant features were depicted.	Shrubland is depicted to the northwest; structures to the northwest and south
1996	No structures or significant features were depicted.	A stream is depicted to the northwest; two (2) structures to the west
2012	No structures or significant features were depicted.	A stream is depicted to the northwest; reservoir to the southeast
2015, 2018	No structures or significant features were depicted.	A pond is depicted to the northwest; Highway 905 to the north; reservoir to the southeast

If obtained, copies of historical aerial photographs have been included in Appendix E.

Historical Aerial Photographs

Historical aerial photographs of the Property and vicinity obtained from an EDR Aerial Photo Decade Package report, as attached in Appendix E, were reviewed. The following interpretation of land usage was made by review of the aerial photographs:

Year(s)	Subject Property	Adjoining Properties
1949, 1953	Agricultural land; orchards to the northwest	Agricultural land; pond to the northwest
1964	Agricultural land; orchards to the northwest	Agricultural land, with farmshed structures to the south and west

Year(s)	Subject Property	Adjoining Properties
1966	Agricultural land	Agricultural land, with farmshed structures to the south and west
1971, 1979, 1985	Agricultural land	Agricultural land, with multiple structures are adjacent to the west
1989, 1990, 1994, 1996	Agricultural land	Agricultural land, with multiple structures are adjacent to the west; scrapyard to the north
2002, 2005	Undeveloped land	Scrapyard to the northwest; junkyard to the west
2009	Undeveloped land	The scrapyard that was adjacent to the northwest appears to have ceased operations; junkyard to the west
2012, 2016	Undeveloped land	Highway 905 is developed to the north; junkyard to the west
2020	Undeveloped land	Highway 905 is developed to the north; junkyard to the west; grading activities to the southeast

If obtained, copies of historical aerial photographs have been included in Appendix E.

EDR High-Risk Historical Records

The EDR Radius Map™ report, which is discussed in greater detail in Section 4.1 and attached in Appendix D, provided a search of proprietary databases of potential historical high-risk uses at or in the vicinity of the Subject Property. These databases include EDR Hist Cleaner – a database of property addresses with records of historical occupancy by suspected cleaners businesses; EDR Hist Auto – a database of property addresses with records of historical occupancy by potential automotive gas/filling stations and repair facilities; and EDR MGP- a proprietary database of sites historically occupied by manufactured gas plants and related facilities.

EDR Database	On-site Listings	Adjoining/Off-site Listings
EDR Hist Cleaner: (on-site/adjoining only)	None	None
EDR Hist Auto: (on-site/adjoining only)	None	None
EDR MGP: (1-mile distance)	None	None

Petroleum/Natural Gas Well Review

The historical record sources and the California Geologic Energy Management Division (CalGEM) online mapping application were reviewed for records of petroleum and/or natural gas wells at the Subject Property. No record of any historical petroleum/natural gas wells at or adjoining the Property was identified.

Additional Historical Data

Where applicable, the following additional pertinent historical data was obtained:

Interviews/ Anecdotal:	The following additional pertinent historical data was obtained: Mr. Paez, Subject Property Owner, indicated on the Owner Questionnaire that trash and some tires were dumped on-site, and the trash was hauled away. There are power polls that SDG&E left onsite, and they were called to remove them.
Local Gov't Records:	No additional pertinent historical data was obtained.
Prior Env. Reports:	Not applicable; no prior reports were provided.
Site Observations:	Indications of historic uses of the Subject Property or adjoining properties were not observed during the site reconnaissance.
Other Sources:	No additional pertinent historical data was obtained.

Summary of Identified Historical Uses

The following table presents a summary of the types and approximate date ranges of identified prior uses of the Subject Property:

Date Range	Subject Property Use(s)
1949 to 1996	Agricultural land
1949 to 1964	Orchards
1996 to 2020	Undeveloped land

The following table presents a summary of the types of identified prior uses of the adjoining properties:

Date Range	Adjoining Property Use(s)
1949 to 1996	Agricultural land
1989 to 2005	Scrapyard
1996 to 2020	Junkyard - landfill

Historical Records Data Failure

The ASTM E1527-21 standard defines data failure as failure to achieve the historical research objective even after reviewing the standard historical sources that are reasonably ascertainable and likely to be useful. The objective is to identify all obvious uses of the Subject Property from the present, back to the Subject Property's first developed use, or back to 1940, whichever is earlier. Furthermore, records of historical use/conditions were sought in intervals no less than approximately five years, unless the Subject Property conditions appear unchanged over a longer interval. In encountered, data failure and its significance as a data gap is discussed below:

Objective	Met?	Detail	Significant?
First developed use/ date determined?	No	The earliest documented use of the Property was agricultural land circa 1949.	No
Record sources at 5-year intervals back to 1940 or first developed use?	No	Historical record gaps exceeding five years were encountered. However, significant site-use changes or undiscovered site uses appear unlikely to have occurred during the record gaps.	No
All obvious prior uses identified?	Yes	See Summary of Identified Past Uses of this section.	N/A

Please refer to Section 2.3 for additional discussion of data gaps and their significance to the findings of the assessment.

Historical Uses REC Discussion

The Subject Property was historically utilized as agricultural land from at least 1949 to 1996. Hillmann reviewed a prior Phase I Environmental Site Assessment conducted by C. Young Associates and dated July 2022, which indicated that Limited Soil Sampling was conducted due to the historical agricultural usage of the Subject Property. A total of fifty (50) discrete soil samples were composited into thirteen (13) composite samples and analyzed for organochlorine pesticides (OCPs) using EPA Method 8081A. Additionally, a total of thirteen (13) of the fifty (50) discrete samples were analyzed for arsenic in accordance with EPA Method 6010. Laboratory analysis indicated arsenic levels consistent with naturally occurring background concentrations ranging between 2.0 milligrams per kilogram (mg/kg) to 5.14 mg/kg, OCPs 4,4-DDD, DDE and DDT were detected, but concentrations were below the residential human health risk-based screening levels. However, toxaphene was detected in twelve (12) out of the thirteen (13) composite samples ranging from 726 µg/kg to 2,470 µg/kg. The toxaphene screening levels are above the residential human health risk-based screening level of 510 micrograms per kilogram (µg/kg).

No information was available to suggest that pesticides applied at the Subject Property were not applied applied in a legal manner, therefore the historic usage of pesticides at the Subject Property can be considered a Business Environmental Risk (BER) rather than a REC. Given the prior soil sampling data indicating elevated levels of pesticides throughout the Subject Property, the contaminated soil will likely need to be either removed or encapsulated prior to redevelopment.

Therefore, this is considered to be a Business Environmental Risk (BER) in connection with the Subject Property.

5.0 INTERVIEWS

5.1 Interviews with Owners, Operators and Occupants

Property Owner

Property Owner	Contact Name	Affiliation	Interview Type	Date
Paez Joseph Jr	Joe Paez	Owner	Questionnaire	04/24/23
An environmental questionnaire for information pertinent to the assessment was forwarded via email and completed and attached in Appendix C. Pertinent information, where applicable, is referenced in the appropriate sections of this report.				

Key Site Manager/Operator

Name	Company/Title	Yrs @ Site	Interview Type	Date
(none)	NA			
A knowledgeable site representative was not identified or made available for interview.				

Occupant(s)

Name	Company/Title	Yrs @ Site	Interview Type	Date
(none)	NA			
No occupant interviews were conducted.				

Prior Owners/Operators/Occupant(s)

Name	Company/Title	Yrs @ Site	Interview Type	Date
(none)	NA			
No interviews of prior owners, operators or occupants were conducted.				

Neighboring Property Owner(s)/Occupant(s)

Name	Company/Title	Yrs @ Site	Interview Type	Date
(none)	NA			
The Subject Property was not an abandoned property with evidence of unauthorized uses or uncontrolled access; therefore, interviews with adjoining or nearby property owners or occupants were not conducted.				

5.2 Interviews with State and/or Local Government Officials

State and/or local governmental officials have been interviewed to obtain information of potential RECs in connection with the Subject Property. Many government agencies and their officials require submittal of written request for records in order to respond. The details in Section 4.1 list the various state and local government agencies contacted as part of this assessment, and the outcome of each inquiry. In addition, the details of regulatory database research in Section 4.1 may have included detail of interviews with officials pertinent to government records review and identification of RECs.

Additional interview of government officials not previously detailed in Sections 4.1 are discussed below, if applicable.

Name	Agency Name/Title	Interview Type
(none)	NA	
Interview Outcome/Findings:		
No additional local/state government officials were interviewed.		

6.0 SITE RECONNAISSANCE

6.1 Methodology and Limiting Conditions

A site reconnaissance was conducted to collect information and make observations to help identify RECs in connection with the Subject Property. This included visual and/or physical observations of the Subject Property and its structures, adjoining properties as viewed from the Subject Property boundaries and the surrounding area based on visual observations from adjoining public thoroughfares and accessed Subject Property structures. Subject property building exteriors were observed at ground level, unless otherwise indicated. Where applicable, building interiors were accessed and observed to the extent they were made safely accessible with the cooperation of the site escort.

Site Inspection Personnel:	Jason Norton
Property Escort/ Company:	Unescorted/
Inspection Date:	April 19, 2023
Weather Conditions:	65° F / Sunny

Significant Inaccessible Areas

No significant areas of the Subject Property inaccessible at the time of the inspection were noted.

Significant Limiting Site Conditions

No significant limiting site conditions were noted at the time of the site reconnaissance.

6.2 General Site Setting

Site and Vicinity Characteristics

Abutting Roadways:	Airway Road to the south; Continental Street to the southeast; Cactus Road to the southwest
Current Property Use:	Vacant land
Evidence of Past Property Uses:	None observed
Evidence of Past Adjoining Property Uses:	None observed

Surrounding Area Uses:	light-industrial

Current Adjoining Property Uses

Dir	Street Address	Description
N	NA	Highway 905
SE	7231 Colchester Ct	Silo Apartments
S	Airway Road	Undeveloped land
W	1938 Cactus Road	Scrap Yard and single-family residences
NW	1812 Cactus Road	Single-family residence

Topographic Characteristics

Terrain:	Gently to moderately sloping
Direction of Downward Slope:	West
On-site Water Bodies:	None observed
Other Significant Features:	None observed

General Description of Structures and Improvements

Buildings:	None
Approx. Building Size:	NA OR NA
Approx. Year Built:	NA
Number of Stories:	NA
Subgrade Levels:	NA
Exterior Ground Cover:	Natural groundcover
Ancillary Structures:	None
Sources of Heating and Cooling:	NA
Potable Water/Sewage Disposal:	No potable water or sewer services were present at the Subject Property.

6.3 Site Features and Conditions

Storage/Usage of Hazardous Substances and Petroleum Products

The following approximate number of containers, and general description of their contents, capacity, container types and storage conditions, were observed to be stored and/or used at the Subject Property:

Occupant	Substance	Qty/Container Type	Storage Conditions
	(none)		

Bulk Petroleum/Hazardous Material Storage Tanks

If identified or suspected, storage tanks for bulk petroleum or hazardous material storage are described as follows:

AST/UST	Product	Capacity	Construction	Year Installed	Status	Location/Notes
						No storage tanks were identified.

Strong, Pungent or Noxious Odors and their Sources

No strong, pungent or noxious odors were noted at the Subject Property.

Standing Surface Water/Pools & Sumps

No standing water, pools or sumps containing liquids likely to be hazardous substances or petroleum products were noted.

Drums, Totes and Intermediate Bulk Containers

No hazardous substance or petroleum product drums were noted.

Unidentified Substance Containers

No unidentified substance containers suspected of containing hazardous substance or petroleum product were noted.

PCBs in Oil Filled Electrical/Hydraulic Equipment

No oil-filled electrical or hydraulic equipment was identified at the Subject Property.

It is noted that identification of PCB containing fluorescent light ballasts, caulk, paint, or other materials located inside and are part of the building or structure is outside of the scope of the ASTM E1527-21 standard and this assessment.

Stains or Corrosion on Floors, Walls or Ceilings

No stains or corrosion of floors, walls or ceilings, excluding any staining from water, were noted.

Drains and Sumps

No buildings were present at the Subject Property.

Pits/Ponds/Lagoons

No pits, ponds or lagoons were identified in connection with waste treatment or disposal.

Stained Soil, Pavement/Stressed Vegetation

No stained soil, pavement or stressed vegetation was observed.

On-Site Solid Waste Disposal/Fill Material

No evidence of on-site disposal of trash, construction debris, demolition debris or other solid waste was observed.

Waste Water

No sanitary sewer discharges were identified at the Subject Property.

Septic Systems/Cesspools

No septic systems or cesspools were identified at the Subject Property.

Wells

No wells (including any dry wells, irrigation wells, injection wells, abandoned wells, or other wells) were identified at the Subject Property.

Railroad Spurs

No railroad spurs were identified on the Subject Property.

7.0 BUSINESS ENVIRONMENTAL RISKS

In accordance with the contract agreement for this assessment, Hillmann has performed cursory reviews of several potential Business Environmental Risks (also known as “Non-Scope Considerations”). The ASTM E1527-21 standard defines the term business environmental risk (BER) as, “a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice.”

7.1 Asbestos-Containing Material (ACM)

The contracted scope of work included a cursory visual screening of the accessed portions of buildings at the Subject Property built prior to 1990 for suspect asbestos containing materials (ACM). The information provided in this section, where applicable, is limited to identification of potential suspect materials in the readily accessible and observed areas of the building, and their general condition. This is not intended to be a comprehensive survey for the presence of ACM, and no testing has been conducted.

No buildings were present at the Subject Property.

7.2 Lead-Based Paint

The contracted scope of work included a cursory visual screening of the condition of painted surfaces in the accessed areas of residential buildings/units built prior to 1980. This is not intended to constitute a comprehensive survey for LBP or potential lead hazards, and no testing has been conducted.

No residential buildings were present at the Subject Property.

7.3 Radon

Data compiled by the USEPA, as summarized by the regulatory database report, indicated that the Subject Property is located in an area classified as Zone 3 or 'low risk'. area for radon. Radon testing was not included in the scope of this assessment.

7.4 Mold/Microbial Damage

The contracted scope of work included a cursory visual screening of the accessed areas of the building for evidence of significant damage to building materials and finishes as result of moisture intrusion and/or mold/microbial growth.

Given the absence of building structures at the Property, mold/microbial growth is not considered to be a significant environmental concern.

7.5 NWI Mapped Wetlands

The National Wetlands Inventory online Wetland Mapper was reviewed for indications of jurisdictional wetlands at or immediately adjoining the Subject Property. The scope of work for this assessment excluded a visual determination of regulated wetlands at the Subject Property. It is emphasized that, regardless of the data reviewed via the NWI Wetlands Mapper, a field delineation of regulated wetlands by a qualified professional would be warranted to determine the presence or absence of regulated wetlands at the Subject Property.

A review of NWI Wetlands Mapper did not indicate regulated wetland areas on the Subject Property.

7.6 Lead in Drinking Water

The scope of work for this assessment included a review of the potential for elevated levels of lead in drinking water by determining the source of the drinking water supply and a review of available compliance or testing data.

No potable water services were present at the Subject Property.

8.0 REFERENCES

ASTM International, “Designation E1527-21 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process”; ASTM, West Conshohocken, PA, 2021.

ASTM International, “Designation E2600-15-Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transaction”, ASTM, West Conshohocken, PA, 2015.

United States Environmental Protection Agency (USEPA), “EPA Map of Radon Zones by U.S. County, EPA 402/F19/004”, www.epa.gov/radon/epa-map-radon-zones, 2019

U.S. Fish and Wildlife Service – National Wetlands Inventory, “Wetlands Mapper”, fwsprimary.wim.usgs.gov/wetlands/apps/wetlands-mapper/ 2023

Environmental Data Resources Inc. (EDR), “The EDR Radius Map™ Report with GeoCheck®”, EDR, Sheldon, CT, 2023.

EDR, “The EDR-City Directory Abstract”, EDR, Sheldon, CT, 2023.

EDR, “The EDR Aerial Photo Decade Package”, EDR, Sheldon, CT, 2023.

EDR, “Certified Sanborn Map Report”, EDR, Sheldon, CT, 2023.


EDR, “EDR Historical Topo Map Report with QuadMatch™”, EDR, Sheldon, CT, 2023.

Buonicore A., “Methodology for Identifying the Area of Concern Around a Property Potentially Impacted by Vapor Migration from Nearby Contaminated Sources, Paper 2011-A301-AWMA”, The Buonicore Group, Milford, CT, 2011.

Phase I Environmental Site Assessment, Paez Property (APN 646-100-77-00), Airway Road and Cactus Road, San Diego, California 92154; C Young Associates July 2022.

APPENDIX A

Site Diagram/Vicinity Map



HILLMANN CONSULTING

Site Location Map

7020 Airway Road
San Diego, California 92154

SCALE: (Not to scale)

PROJECT No: C3-9535

N



HILLMANN CONSULTING

Site Diagram

7020 Airway Road
San Diego, California 92154

SCALE: (Not to scale)

PROJECT No: C3-9535

N

APPENDIX B

Site Photographs

SITE PHOTOGRAPHS



1. View from South-West corner of Property near Airport Road



2. View from North-West corner of Property near 905 Freeway



3. View from North-East corner of Property near 905 Freeway



4. View from South-East corner of Property near Airport Rd



5. View from East Side of Property near Continental Rd



6. View from South-Side of Property near Airport Rd

7020 Airway Road
San Diego, California

Project No.	C3-9535

HILLMANN
CONSULTING

SITE PHOTOGRAPHS



7. View from West Side of Property near Cactus Rd



8. On-going Construction to the East of Property



9. On-going Construction to the West of Property



10. Possible Ponding at North-West Corner due to Slope of Property

APPENDIX C

Questionnaires / User Provided Information

ASTM E 1527-21/AAI - USER QUESTIONNAIRE

Instructions: This form should be completed by a representative of the USER of the Phase I ESA report and returned to Hillmann via email or in-person. **The report USER is the entity on whose behalf the assessment is being prepared and that will be relying on the report for liability protections.**

In order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "Brownfields Amendments"),188 the USER must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. The user should provide the following information to the environmental professional. Failure to conduct these inquiries could result in a determination that "all appropriate inquiries" is not complete. Please complete the following questionnaire and provide any of the referenced information (if available) to Hillmann.

USER Company Name:	JPI	**USER Mailing Address:**	11988 El Camino Real Suite 200 San Diego, CA 92130
Respondent Name & Email Address:	Conner Kloeppel Conner.kloeppel@jpi.com	**Date of Completion:**	4/20/23

Property Address:	Address: NEC of Airway Road & Cactus Road, San Diego, CA 92154	**YES**	**NO**	**DETAIL (optional):**
Search of Land Title Records and AULs: Has the User performed a review of land title records and judicial records for environmental liens and Activity and Use Limitations (AULs) filed or recorded against the property?			X	
If yes to the above question: Did the review identify any environmental liens or Activity and Use Limitations (AUL), such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law?			X	
Specialized knowledge or experience of the person seeking to qualify for the LLP: Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?			X	
Relationship of the purchase price to the fair market value of the property if it were not contaminated: Does the purchase price being paid for this property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?		X		

Property Address:		YES	NO	DETAIL (optional):
Commonly Known or Reasonably Ascertainable Information: Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? **ANSWER BELOW**				
- Do you know the past uses of the property?			X	
- Do you know of specific chemicals that are present or were once present at the property?			X	
- Do you know of spills or other chemical releases that have taken place at the property?			X	
- Do you know of any environmental cleanups that have taken place at the property?			X	
The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation: Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property?			X	
Litigation/Administrative Proceedings/Government Notices As the User of this ESA, do you have knowledge of (1) any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the property; (2) any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on or from the property; and (3) any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.			X	
User's Reason for performing Phase I ESA:	Due Diligence			

Additional Details, if applicable:

HILLMANN
CONSULTING

PHASE I ESA - ENVIRONMENTAL QUESTIONNAIRE

Instructions: This questionnaire should be completed by the property owner, or representative(s) designated by the owner as being most knowledgeable of the physical characteristics, site use history and environmental condition of the subject property. Please complete, sign at bottom of page 5, and return to Hillmann via email, or in person during the site inspection. ***Hillmann contact name:*** _____ ***Email:*** _____ ***@hillmannconsulting.com***

Document Request/Environmental Report Disclosure: Copies of existing environmental reports and other documents pertinent to the environmental condition of the Property are requested for review. This includes, but is not necessarily limited to, the following types of documents.

- Environmental assessments (Phase I ESA, Transaction screen ESA, Preliminary Assessments, etc.)
- Subsurface or water testing: (Phase II, site investigation, subsurface testing, drinking water, groundwater monitoring, etc.)
- Site remediation documents, and any associated regulatory correspondences
- Petroleum storage tank testing/closure reports, and any associated regulatory documents.
- Building survey/inspection/testing reports for asbestos, lead, mold or radon; any associated O&M documents
- Environmental permits/registrations/certifications (bulk petroleum, waste discharge, emissions, potable wells, etc.).
- Environmental/health/fire code regulatory violations or citations

Property Details			
Street address(es) City, ST ZIP:	Cactus & airway, San Diego, Ca. 92154	Property ownership entity and primary contact person: (name/company/ph#/email):	Joe Paez, Jr. 619-885-1601, joseph@bcsproduce.com
Tax ID: (block/lot or APN)		Contact's affiliation to owner: (if other than the owner)	
Property size: (acres or SF)	approx. 39 acres	Questionnaire completed by: (if different than above)	
Total bldg. area:	I don't know	No. of years at, or familiar, with the Property:	since 2002
Number of residential units If residential:		No. of years-current ownership:	20 yearsn/a
Date(s) of bldg construction:		Prior owner name/contact info: (if owned <5 yrs)	

Current Non-Residential Occupants & Type of Use (For facilities with ≥ 10 non-residential occupants, please provide a copy of the latest rent roll in lieu of completing the table below)			
Occupant Name:	**Type of Use:**	**NAICS # (if known)**	**Appx # yrs at Property**
n/a			

Your Property. Our Priority.

Making a better future for all the communities we touch.

www.HillmannConsulting.com

HILLMANN
CONSULTING

Utilities and Services:									
Type	**Yes**	**No**	**NA**	**Name of Provider**	**Type**	**Yes**	**No**	**NA**	**Name of Provider**
Water:				OnAll I don't know	**Fuel Oil:**				
Sewer:					**HVAC Maint:**				
Power:					**Elev Maint:**				
Nat Gas:					**Septic Maint:**				
Pest Control:					**Pool Maint:**				

Please answer each question. Check "D/K" for "Don't Know". Additional space for comments/details is provided on Page 5.

Previous Environmental Investigations				
1.	Have any previous environmental investigations (see list on Page 1) been performed at the Property? *If YES, please briefly elaborate below and forward copies of the report(s).* what ever was done, Tim Winslow sent it to the buyer.	yes		
		Yes	**No**	**D/K**
Property & Adjoining Usage				
2.	To the best of your knowledge, is the Property or any adjoining property currently occupied or formerly occupied for industrial purposes? *If YES, please elaborate below:*	**Property:**		
				x
		Yes	**No**	**D/K**
		Adj. Property:		
				x
		Yes	**No**	**D/K**
3.	Is the property or any adjoining property currently used, or have they ever been used, as a gasoline filling station, dry cleaning facility, automotive service/repair shop, auto body repair shop, commercial printing facility, photo development laboratory shop, junkyard, landfill, or as a waste treatment, storage disposal, recycling or processing facility? *If YES, please elaborate below:*	**Property:**		
				x
		Yes	**No**	**D/K**
		Adj. Property:		
				x
		Yes	**No**	**D/K**
4.	Have any hazardous substances or petroleum products, unidentified waste materials, tires, automotive or industrial batteries, or any other waste materials been dumped above grade, buried and/or burned on the property?	X		
		Yes	**No**	**D/K**
Bulk Storage Tanks				
5.	Are there currently, or have there been previously, any registered or unregistered above ground or underground storage tanks located at the Property? *If YES, please provide number, size, age of tanks, permits, closure reports, regulatory agency correspondence, and related information.*	**Currently:**		
				x
		Yes	**No**	**D/K**
		Previously:		
				x
		Yes	**No**	**D/K**
6.	Are there currently, or have there been previously, any vent pipes, or access ways indicating a fill pipe protruding from the ground on the property or adjacent to any structure located on the property? *If YES, please elaborate below:*	**Currently:**		
				x
		Yes	**No**	**D/K**
		Previously:		
				x
		Yes	**No**	**D/K**
7.	Are there currently, or have there been previously, any leakage of hazardous substances or petroleum products from above ground or underground storage tank systems at the Property? *If YES, please elaborate below:*	**Currently:**		
				x
		Yes	**No**	**D/K**
		Previously:		
				x
		Yes	**No**	**D/K**

HILLMANN
CONSULTING

Spills, Releases, Wastes		
8.	Are there currently, or have there been previously, any waste discharges on or adjacent to the property, other than storm water or into a municipal sanitary sewer system? *If YES, please elaborate below.*	**Currently:** Yes: ; No: ; D/K: x **Previously:** Yes: ; No: ; D/K: x
9.	Are there currently, or have there been previous, any septic systems, dry wells or leach fields on the property? *If YES, please elaborate below.*	**Currently:** Yes: ; No: ; D/K: x **Previously:** Yes: ; No: ; D/K: x
10.	Are there currently, or have there been previously, any flooring, drains or walls located within the facility that are, or have been, stained by substances (or, in the case of drains, used for) other than water or are emanating foul odors? *If YES, please elaborate below.*	**Currently:** Yes: ; No: ; D/K: x **Previously:** Yes: ; No: ; D/K: x
11.	Are there currently, or have there been previously, any spills or releases of hazardous substances or petroleum products within the building(s) or on the exterior of the Property? *If YES, please elaborate below.*	**Currently:** Yes: ; No: ; D/K: x **Previously:** Yes: ; No: ; D/K: x
12.	Has any non-native and/or contaminated fill material been deposited on the Property? *If YES, please elaborate below.*	Yes: ; No: ; D/K: x
13.	Have any current or former property occupants generated hazardous wastes or other wastes (such as waste oil, or medical wastes) that required non-conventional storage, handling and/or disposal methods? *If YES, please indicate type of waste and the name of the waste handling contractor.*	Yes: ; No: ; D/K: x
Transformers/Hydraulic Equipment		
14.	Are any power transformers, capacitors, oil-filled switchgear or hydraulic equipment present at the Property? *If YES, please elaborate below; and indicate approximate age and ownership.*	Yes: ; No: x; D/K:
15.	If hydraulic equipment is present, indicate approximate age of equipment & ownership:	
Regulatory Disclosure		
16.	Have there been any environmental liens or governmental notification or involvement relating to past or current use or disposal of hazardous substances with respect to the property of any facility or structure located on the property? *If YES, please elaborate below.*	Yes: ; No: ; D/K: x
17.	If the property is served by a private well or non-public water system, have contaminants been identified in the well or system that exceed guidelines applicable to the water system, or has the well been designated as contaminated by any government environmental/health agency? *(If YES, please elaborate below. If not applicable, please check* NO*)*	Yes: ; No: ; D/K: X

HILLMANN
CONSULTING

18.	Is there any environmental litigation, administrative action or cleanup action involving the property related to a release or threatened release of any hazardous substance or petroleum product? *If YES, please elaborate below:*			x
		Yes	No	D/K
19.	Are you aware of testing of any environmental media (soil, groundwater, surface water, etc.) at the property which identified levels of contaminants in excess of regulatory standards and/or cleanup guidelines? *If YES, please elaborate below:*			X
		Yes	No	D/K
Additional Environmental/Building Conditions				
20.a.	Has testing of building materials for asbestos ever been conducted at the Property? *If YES, please forward a copy of test results and/or survey reports:*			x
		Yes	No	D/K
20.b.	Are any asbestos containing materials known to be present at the Property? *If YES, please elaborate*:			X
		Yes	No	D/K
20.c.	Is there an Asbestos Operations & Maintenance (O&M) program in place? *If YES, please forward a copy.*			x
		Yes	No	D/K
21.a.	Has lead paint testing/risk assessment ever been conducted at the Property? *If YES, please forward a copy of test results.*			x
		Yes	No	D/K
21.b.	Is lead-based paint known to be present at the Property? *If YES, please elaborate:*			x
		Yes	No	D/K
21.c.	Is there a lead paint Operations & Maintenance (O&M) (or equivalent) program in place? *If YES, please forward a copy.*			x
		Yes	No	D/K
21.d.	For any residential buildings built prior to 1987, has any testing for lead in drinking water been performed? *If YES, please provide a copy of all test results.*			x
		Yes	No	D/K
21.e.	If Yes to 23.d., has any lead testing of drinking water indicated results exceeding 15 parts per billion (or microgram per liter)? *If YES, please elaborate and forward documentation of any mitigation performed to reduce lead concentration in drinking water.*			x
		Yes	No	D/K
22.a.	Has radon testing ever been conducted at the Property? *If YES, please forward a copy of test results.*			x
		Yes	No	D/K
22.b.	Are there any radon mitigations systems at the Property? *If YES, please provide details of the systems including the most recent service records.*			x
		Yes	No	D/K
23.a.	Are there any problems with water intrusion, water damaged surfaces or excessive mold growth within the buildings? *If YES, please elaborate:*			X
		Yes	No	D/K
23.b.	Is there a Moisture Control (or Mold Management) Program in place *If YES, please forward a copy.*			x
		Yes	No	D/K
24.a.	Are any pest control, pesticides or herbicides products utilized or applied at the Property? *If YES, please elaborate.*			X
		Yes	No	D/K
24.b.	If Yes to 24.a., are all products applied by licensed pest control contractor? *If YES, provide company name and any applicable license #s if available. If NO, please describe what products are utilized, who applies them and/or how they are applied or utilized.*			x
		Yes	No	D/K

HILLMANN
CONSULTING

Additional Details/Comments:
For any questions that warrant further elaboration, please use the following space as necessary, and/or provide documentation along with the completed questionnaire:
On question #4, trash and some tires were dumped on the site, a couple of years ago and we hauled the trash away. There are a couple of power polls that SDG&E left, we have called them to pick them up.

Certification

I, Joe Paez, Jr., state to the best of my knowledge, information and belief, that all of the facts stated in response to the questions and requests for information contained in this Environmental Questionnaire are true.

Signature:	Date: 4/24/2023
Title: owner	
On behalf of: _____ (name of entity)	

CUSHMAN & WAKEFIELD

DUE DILIGENCE

Table of Contents

ENGINEERING/ARCHITECTURE

2	Environmental Site Assessment - Phase 1, Enecotech Project 1877-001, April 9, 2002	Click Here
43	Environmental Risk Management, 07549422R, April 13, 2002	Click Here
106	Phase 1 ESA, ColRich, C Young, July 8, 2022	Click Here
627	Phase 1 ESA Questionnaire, Owner, C Yong June 30, 2022	Click Here
629	Biological Resources, Alden Environmental, Inc, June 21, 2022	Click Here
636	Biological Resources Letter Report, REC, January 21, 2021	Click Here
654	Biological Resources Letter Report, REC, October 30, 2019	Click Here
737	Groundwurk Proposal, Meyers Research , May 26, 2017	Click Here
744	Geotechnical Study, AGS, ColRich, July 2, 2022	Click Here
779	EPOCA Public Improvement Plans, December 15, 2020	Click Here

PLANS

805	ALTA, Project Design Consultants	Click Here
806	Tentative Map For Central Village, Landmark	Click Here
811	Concept Site Plan, M. W. Steele	Click Here
812	Overall Floor Plans, Floreo	Click Here

TAXES

814	Tax Statement 2020-2021	Click Here
815	Tax Statement 2021-2022	Click Here

MISCELLANEOUS

816	CYA - Request For No Further Action	Click Here
817	Letter of Permission for Offsite Grading/Improvements, April 6, 2022	Click Here
818	Letter of Permission for Offsite Grading/Improvements, January 21, 2009	Click Here
821	Sewer Easement Grant Deed, November 21, 2009	Click Here
825	Public Street Easement, February 9, 2021	Click Here
829	EPOCA Report, August 21, 2022	Click Here
916	Street Vacation Request, Murphy Development, February 3, 2014	Click Here
925	Development Services Department Invoice, August 10, 2021	Click Here
926	United Site Fence Contract	Click Here

PHASE I
ENVIRONMENTAL SITE ASSESSMENT
AIRWAY ROAD AND CACTUS ROAD
SAN DIEGO, CALIFORNIA 92154

APRIL 9, 2002

ENECOTECH PROJECT #1877-001

PREPARED BY:

ENECOTECH SOUTHWEST, INC.
6160 FAIRMOUNT AVENUE, SUITE A
SAN DIEGO, CALIFORNIA 92120

PREPARED FOR:

BCS PRODUCE COMPANY, INC.
7558 PANASONIC WAY
SAN DIEGO, CALIFORNIA 92173

PREPARED BY:

Melissa Novak

MELISSA NOVAK
STAFF SCIENTIST

REVIEWED BY:

REGISTERED ENVIRONMENTAL ASSESSOR I
TERRY D. FARLEY
No. 07480
Expires: 2002
STATE OF CALIFORNIA

TERRY FARLEY, REA 7480
PROJECT SCIENTIST

Recycled Paper

EnecoTech
STRATEGIES FOR ENVIRONMENTAL RESPONSIBILITY

TABLE OF CONTENTS

Section		*Page*
EXECUTIVE SUMMARY		1
1.0	**INTRODUCTION**	2
	PURPOSE OF THE ASSESSMENT	2
	SCOPE OF WORK	2
	SPECIAL TERMS AND CONDITIONS	3
	SIGNIFICANT ASSUMPTIONS	3
	LIMITING CONDITIONS AND EXCEPTIONS TO THE ASTM STANDARD	3
2.0	**LIMITATIONS**	3
3.0	**SITE DESCRIPTION**	4
	GENERAL	4
	PROPERTY USES	5
	USER PROVIDED INFORMATION	5
4.0	**ENVIRONMENTAL RECORDS REVIEW**	5
	ORPHAN SITES	6
	NATIONAL PRIORITIES LIST (NPL)	6
	COMPREHENSIVE ENVIRONMENTAL RESPONSE, COMPENSATION AND LIABILITY ACT INFORMATION SYSTEM (CERCLIS)	6
	NO FURTHER REMEDIAL ACTION PROGRAM (NFRAP)	6
	STATE HAZARDOUS WASTE SITES (CAL-SITES)	7
	SOLID WASTE SITES	7
	RESOURCE CONSERVATION AND RECOVERY ACT (RCRA)	7
	LEAKING UNDERGROUND STORAGE TANKS (LUSTS)	8
	REGISTERED USTS	8
	EMERGENCY RESPONSE NOTIFICATION SYSTEM (ERNS)	8
	OTHER REGULATORY RECORDS	8
5.0	**TOPOGRAPHY AND HYDROGEOLOGIC SETTING**	9
6.0	**HISTORICAL USE INFORMATION**	9
	TOPOGRAPHIC MAPS	9
	AERIAL PHOTOGRAPHS	9
	SANBORN MAP REVIEW	10
	CITY DIRECTORY REVIEW	10
	PROPERTY TAX INFORMATION	11
	PREVIOUS INVESTIGATIONS	11
	OTHER HISTORICAL SOURCES	11

TABLE OF CONTENTS
(Continued)

Section		*Page*
7.0	**SITE RECONNAISSANCE**	11
	ONSITE CONDITIONS	12
	ADJOINING PROPERTIES	12
8.0	**INTERVIEWS**	13
9.0	**FINDINGS**	13
10.0	**OPINIONS**	13
11.0	**CONCLUSIONS**	14
12.0	**ADDITIONAL SERVICES**	14
13.0	**REFERENCES**	14

LIST OF APPENDICES

APPENDIX A - FIGURES
APPENDIX B - HISTORICAL USE INFORMATION
APPENDIX C - REGULATORY RECORDS SEARCH
APPENDIX D - INTERVIEW DOCUMENTATION
APPENDIX E - PHOTOGRAPHIC DOCUMENTATION
APPENDIX F - ENECOTECH RESUMES

EXECUTIVE SUMMARY

Please note that this executive summary does not fully present the findings and opinions of this Phase I Environmental Site Assessment (ESA). EnecoTech Southwest, Inc. (EnecoTech) urges you to read the entire report and contact us with any questions or concerns you may have.

FINDINGS

There were no indications of onsite environmental concern from our records review and interviews. Historic information indicates the subject site has been in agricultural use since the 1920s.

Offsite environmental concerns include one Solid Waste Disposal/Landfill Site and one LUST site within the ASTM search radii.

OPINIONS

It is EnecoTech's opinion that no onsite or offsite concerns would impact the subject site.

CONCLUSIONS

EnecoTech has performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E1527-00 of the subject site located at Airway Road and Cactus Road in San Diego, California. Any exceptions to, or deletions from, this practice are described in the Introduction of this report. Based on the findings of this Phase I ESA for the subject site, the following conclusions were possible:

This assessment has revealed no evidence of recognized environmental concerns in connection with the subject site except one Solid Waste Disposal/Landfill Site and one LUST site within the ASTM search radii.

1.0 INTRODUCTION

PURPOSE OF THE ASSESSMENT

This report presents the results of a Phase I Environmental Site Assessment (Phase I ESA) performed by EnecoTech Southwest, Inc. (EnecoTech) for the subject site located at the intersection of Airway Road and Cactus Road in San Diego, California. EnecoTech was authorized to perform this work on March 25, 2002, by BCS Produce Company, Incorporated (Client).

The goal of the Phase I ESA (Phase I) is to determine recognized environmental conditions associated with the subject property in accordance with American Society of Testing Materials (ASTM) Practice E1527-00. "Recognized environmental conditions" means the presence or likely presence of any hazardous substances (or petroleum products) on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term "recognized environmental conditions" is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not recognized environmental conditions.

SCOPE OF WORK

The scope of this Phase I ESA consisted of a preliminary evaluation of the subject site for conditions of environmental concern. The assessment of the subject site was conducted in April 2002 and consisted of:

- Review of property use through interviews and historical records;
- Search of state and federal environmental agency records;
- Interview with a representative or the current owner;
- Site reconnaissance of the subject site and adjoining properties (to the extent allowable);
- Review of regulatory agency database report (EDR);
- Review of historical aerial photographs;
- Review of City Directories;
- Review of the geologic, hydrogeologic, hydrologic, and topographic conditions; and,
- Report of findings.

This investigation was not an audit for regulatory compliance, structural or geotechnical conditions, and the following items of possible environmental concern are outside of the scope of work of this Phase I ESA:

- Asbestos containing materials;
- Radon;
- Lead-based paint;
- Wetlands;
- Regulatory compliance;
- Cultural and historic resources;
- Industrial hygiene;
- Health and safety;
- Ecological resources;

- Endangered species, and,
- Indoor air quality

SPECIAL TERMS AND CONDITIONS

It is EnecoTech's understanding that this report is to be used and distributed exclusively for purposes connected with purchase of the subject site. This report of findings was prepared for the exclusive use of BCS Produce Company, Incorporated. The contents of this report may not be copied, provided, or otherwise communicated to any party other than those associated with BCS Produce Company, Incorporated without the express written consent of EnecoTech.

SIGNIFICANT ASSUMPTIONS

Groundwater flow is assumed to be in the general direction of surface topography, which for the subject site is to the west-northwest.

Recognized potential environmental conditions include the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. The term includes hazardous substances and petroleum products under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not recognized environmental conditions.

Business environmental risk includes risks that can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel or commercial real estate, not necessarily limited to those environmental issues required to be investigated in any standard Phase I environmental assessment. It is EnecoTech's understanding that this report is to be used and distributed exclusively for the purpose of a real estate transaction of the subject site.

LIMITING CONDITIONS AND EXCEPTIONS TO THE ASTM STANDARD

- There were no limiting conditions or exceptions upon investigation of the subject site.

2.0 LIMITATIONS

No environmental assessment or investigation is infallible. Some uncertainty will always exist concerning the presence or absence of potentially adverse conditions at a particular property, irrespective of the rigor of the investigation. Accordingly, EnecoTech offers no warranty that adverse environmental conditions, other than those identified in this report, do not exist at the subject site or may not exist there in the future.

This report is a professional opinion based on findings derived from a review of regulatory records and historical sources, comments made by interviewees, and from site reconnaissance.

The findings and opinions conveyed in this report are based partially on information obtained from a variety of sources enumerated in the report and which EnecoTech believes are reliable. Nonetheless, EnecoTech cannot and does not guarantee the authenticity or reliability of the information it has relied upon.

BCS Produce Company, Incorporated (Client) is herewith advised that the CONDITIONS OBSERVED BY ENECOTECH ARE SUBJECT TO CHANGE. Certain indicators of the presence of hazardous materials may have been latent at the time of the site reconnaissance and may subsequently have become discernable. In a similar manner, the research effort conducted for an ESA is limited. Accordingly, it is possible that EnecoTech's research, while appropriate for an ESA, failed to indicate the existence of important information sources. Assuming such sources actually exist, their information could not have been considered in the formulation of EnecoTech's findings and opinions.

EnecoTech has performed these services in a manner consistent with the level of care and skill ordinarily exercised by members of the environmental risk assessment profession practicing contemporaneously under similar conditions in the area of the project.

Conclusions regarding the condition of the subject site do not represent a warranty. If additional information becomes available concerning this site after the date of this report, EnecoTech is under no obligation to revise the conclusions and recommendations of this report.

An effort has been made to obtain information based on readily available sources and a site reconnaissance. No other warranty, expressed or implied, is given.

3.0 SITE DESCRIPTION

GENERAL

Location and Legal Description - The subject site is located on the northeast intersection of Airway Road and Cactus Road, south of Otay Mesa/State Highway 905 in the City of San Diego, California. The subject site is identified by the County of San Diego Assessor's Office as APN 646-100-31 with the legal description of "Exc rds south ½ of west ½ of northeast ¼ of Section 33, Township 18, Range 1W".

Site and Vicinity Characteristics - The subject site is located within an agricultural and commercial area in the southern portion of the City of San Diego, California. The subject site consists of a rectangular shaped, approximate 40.79 acre parcel bound by commercial and agricultural properties to the north, Airway Road to the south, agricultural property to the east, and Cactus Road to the west.

Descriptions of Structures, Roads and Other Improvements on the Site - The subject site consists of a rectangular shaped, approximate 40.79 acre parcel of land. The parcel is a recently tilled area used for agriculture and is currently un-maintained vegetation. There are no structures or roads on the subject site.

Information Provided by the Client Regarding Environmental Liens or Specialized Knowledge or Experience – The Client reported no specialized information or known liens to EnecoTech.

PROPERTY USES

The following information on property uses represents a summary of information obtained during the records review, interviews, and site reconnaissance. This summary is presented in an effort to establish familiarity with the history of the subject site and surrounding area prior to the presentation of more specific information. For additional detail, refer to the other appropriate sections of the report.

Subject Property - Current and Past Uses (to the extent identified) – Refer to the Site Maps in Appendix A for approximate locations of adjoining properties and to the Historical Use Information Section for additional information.

Mr. Curtis J. Corn is the current owner of the subject site. Historical research indicates that the subject site has been used for agricultural purposes since 1928.

Adjoining Properties - Current and Past Uses (to the extent identified) - Refer to the Site Maps in Appendix A for approximate locations of adjoining properties and to the Historical Use Information Section for additional information.

The adjacent properties to the west are agricultural and residential properties. Adjacent properties to the north are commercial (Cactus Recycling Center) and agricultural, and the adjacent properties to the east and south are agricultural. Historical research indicates the area has been used for agricultural purposes since 1928. Aerial photographs indicate the adjoining property to the south had a residential structure from 1928 until 1977. Aerial photographs indicate the adjoining property to the north was commercial since 1928, and adjoining properties to the west were residential since 1982.

USER PROVIDED INFORMATION

Title records, information regarding environmental liens, activity use limitations, specialized knowledge, or valuation reduction for environmental issues were not provided by the Client. Mr. Curtis J. Corn is the current owner of the subject site. The Otay Water District provides water services for the subject site. San Diego Gas & Electric (SDG&E) provides electrical and natural gas services to the subject site area, but no services are provided to the subject site.

This Phase I ESA has been performed for BCS Produce Company, Incorporated to be used for the purchase of the property.

4.0 ENVIRONMENTAL RECORDS REVIEW

Environmental records from the State of California and USEPA were obtained for EnecoTech by Environmental Data Resources (EDR). The state and federal database and minimum search radii requirements of ASTM E1527-00 were satisfied. The County of San Diego, Department of Environmental Health (DEH) did not have records regarding the subject site. Refer to Appendix C for the state and federal environmental records documentation.

- The subject site was not identified by the environmental records search as having recognized environmental conditions.

- The adjoining properties were not identified by the environmental records search as having recognized environmental conditions.

- The following were identified within the appropriate search radii:

  1. One Solid Waste Facility/Landfill Site within 0.5 mile of the subject site.
  2. One LUST site within 0.5 mile of the subject site.

ORPHAN SITES

The EDR report included information on 39 "orphan" facilities that were not mapped due to poor or inadequate addresses. EnecoTech has made reasonable effort to reconcile this information utilizing resources currently available to EnecoTech. EnecoTech exercised professional judgement in an attempt to evaluate whether or not the orphan sites are located within the approximate minimum search distances.

The listed orphan facilities were not located within the appropriate search radii that were either: A) located beyond the approximate minimum search distances; B) not located in the anticipated upgradient direction; or, C) EnecoTech could not accurately determine their locations. Therefore, these remaining orphan facilities were not identified as potential environmental concerns.

NATIONAL PRIORITIES LIST (NPL)

NPL sites have been identified by the government for priority remedial actions under the Superfund Program.

- The search revealed no NPL sites within approximately 1.0 mile of the subject site.

COMPREHENSIVE ENVIRONMENTAL RESPONSE, COMPENSATION AND LIABILITY ACT INFORMATION SYSTEM (CERCLIS)

CERCLIS is the database compilation of sites, which USEPA has investigated or is currently investigating for a release or a threatened release of hazardous substances pursuant to the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980.

- The search revealed no CERCLIS facilities located within approximately 0.5 mile of the subject site.

NO FURTHER REMEDIAL ACTION PROGRAM (NFRAP)

NFRAP is the database compilation of sites that, upon initial investigation, contamination was not significant, contamination was quickly removed, or contamination was not significant enough for consideration to list on the NPL.

- The search revealed neither the subject site nor adjoining sites were identified as NFRAP facilities.

STATE HAZARDOUS WASTE SITES (CAL-SITES)

State Hazardous Waste site records are the state's equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent to Superfund) are identified along with sites where potential responsible parties will pay for environmental cleanup.

- The search revealed no Cal-Sites within approximately 1.0 mile of the subject site.

SOLID WASTE SITES

Solid waste site records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Section 2004 criteria for solid waste landfills or disposal sites.

- The search revealed one solid waste facility/landfill site within approximately 0.5 mile of the subject site.

    1. The site listed as "Cactus Road- AKA Tripp Salvage" is approximately 0.5 mile north of the subject site. According to the regulatory agency database reviewed, the operator's status is closed and the regulation status is listed as unpermitted.

RESOURCE CONSERVATION AND RECOVERY ACT (RCRA)

The RCRA listing is a compilation by USEPA of reporting facilities that generate, store, transport, treat, or dispose of hazardous waste.

- The search revealed no small or large quantity RCRA generator sites within approximately 0.25 mile of the subject site.

- The search revealed no RCRA treatment, storage, and/or disposal sites within approximately 0.5 mile of the subject site.

- The search revealed no RCRA corrective action sites (CORRACTS) within approximately 1.0 mile of the subject site.

- The search revealed that the subject site was not listed as a RCRA site.

LEAKING UNDERGROUND STORAGE TANKS (LUSTS)

The search revealed one LUST site.

- Brown Field Airport is approximately 0.5 mile north of the subject site. According to the regulatory agency database reported by EDR, the site is listed due to 23 unauthorized reported leaks of diesel, gasoline, and boiler fuel, all of which were discovered during tank closure. There are 18 leaks that affected the soil and 5 leaks that affected the groundwater. Preliminary site assessment is underway for 20 of the LUST cases and three cases that the regulatory agency deemed that remedial action has been completed or was unnecessary.

REGISTERED USTS

This is a listing of registered USTs.

- The search revealed no registered UST sites within 0.25 mile of the subject site.
- The search revealed that the subject site was not listed as a registered UST site.
- The search revealed no registered UST sites adjoining the subject site.

EMERGENCY RESPONSE NOTIFICATION SYSTEM (ERNS)

The ERNS is a federal database containing information on reported releases of oil and hazardous substances. This database is a compilation of information from spill reports made to federal authorities including the USEPA, United States Coast Guard, the National Response Center, and the Department of Transportation.

- The search revealed that the subject site was not listed as an ERNS facility.

OTHER REGULATORY RECORDS

Additionally, EDR provided information from other record sources. The subject site was not identified on the following databases:

- FINDS
- RAATS
- HMIRS
- PADS
- TRIS
- NPL Liens
- TSCA

5.0 Topography and Hydrogeologic Setting

General Topographic Setting - The topography of the subject site is flat and level with a slight downgradient slope to the west-northwest. The north adjacent property slopes toward the south, the south adjacent property is flat, the east adjacent property slopes slightly toward the east, and the west adjacent property slopes toward the west.

Surface Water - Surface water bodies were not observed on the subject site. Surface water streams including swales and surface gradient near the subject site apparently flow in a west-northwesterly direction toward Cactus Road.

Borings or Well Logs – No monitoring wells (indicative of potential groundwater contamination) were located on the subject site or nearby properties during site reconnaissance.

Geologic Deposits - According to the California Division of Mines & Geology topographic map of the National City, Imperial Beach, and Otay Mesa Quadrangles, Southern San Diego Metropolitan Area, California, the surface formation for the subject site area consists of Linda Vista Formation. The Linda Vista Formation consists of near shore marine and non-marine sediments. The sediments are composed of moderate reddish-brown interbedded sandstone and conglomerate.

Groundwater Flow/Depth - No published groundwater flow or depth information was readily available, and local geologic conditions do not allow us to estimate groundwater flow with a high degree of confidence. Therefore, the groundwater flow direction is considered to be uncertain. EnecoTech assumes groundwater flow to be in the general direction of surface topography. Review of the 7.5 minute USGS topographic map of the Otay Mesa Quadrangle indicates the surface topography slopes downgradient to the west-northwest.

6.0 HISTORICAL USE INFORMATION

TOPOGRAPHIC MAPS

EnecoTech reviewed the most current topographic map available for the subject site is the 7.5 minute USGS topographic map, Otay Mesa Quadrangle. This map was produced by the United States Department of Interior Geological Survey, dated 1967 and photo-revised in 1971. Review of the topographic map indicates the subject site was developed and no obvious landfills, mining activity, or quarries were identified within approximately 1.0 mile of the subject site.

AERIAL PHOTOGRAPHS

On March 29, 2002, EnecoTech reviewed historical aerial photos from the County of San Diego Cartographic Services and Mapquest.com to supplement information obtained from the historical topographic map information. This review yielded the following relevant information.

1928	EnecoTech observed the subject site was cultivated with a small tree grove to the north. The north adjacent property had a commercial structure off Cactus and agricultural to the east. The south adjacent property was agricultural with a single-family residential structure. The east and west adjacent properties were undeveloped.
1945	The subject site and adjacent properties appeared to be undeveloped. (Poor photograph quality.)
1953	Half of the subject site appears to be cultivated and the other half is undeveloped. The north adjacent property is mostly undeveloped with a small grove of trees. The south adjacent property appears the same as in 1928. The east and west adjacent properties appear undeveloped.
1964	The subject site and surrounding properties are occupied by agricultural land, and the south adjacent property also has a single-family residence.
1966	The subject site and surrounding properties are occupied by agricultural land, and the south adjacent property also has a single-family residence on part of the land.
1971	The subject site and surrounding properties appear similar to the 1966 aerial photograph.
1977	The subject site and surrounding properties appear similar to the 1966 aerial photograph.
1982	The subject site is agricultural. The north adjacent property has a commercial structure with agricultural land to the east. The south and east adjacent properties are agricultural land. The west adjacent property has three single-family residences.
1987	The subject and surrounding properties appear similar to the 1982 aerial photograph except the west adjacent property has five single-family residences.
1995	The subject site and surrounding properties are similar to the 1987 aerial photograph except the commercial structure on the north adjacent property appears to be the current improvements.
2002	The subject site and surrounding properties are occupied by the current improvements.

SANBORN MAP REVIEW

No Sanborn Maps were available as provided by EDR.

CITY DIRECTORY REVIEW

Available San Diego city directories from the main San Diego City Public Library were reviewed by EnecoTech. The directories were reviewed between the years 1926 and 2002 in five-year increments. The following information was found as listed in the city directories for the subject site and adjacent properties:

- The subject site and the south and east adjacent properties were not listed in any of the City Directories reviewed.

- Airway and Cactus Roads were not listed in the San Diego City or Suburban City Directories between 1926 and 1987.
- 1703 Cactus Road, the adjacent property north of the subject site, was not listed from 1926 to 1987. The adjacent northern property was listed as a business property from the year 1992 until the year 2002.
- 1938 Cactus Road, the adjacent property west of the subject site, was listed as a business property in 1992 and a residential property in 1997 and 2002.
- 1940 Cactus Road, the adjacent property west of the subject site, was listed as residential property in 1992, 1997, and 2002.
- 1942 Cactus Road, the adjacent property to the west, was listed as a business/residential property between 1992 and 2002.
- 1950 Cactus Road, the adjacent property west of the subject site, was listed as residential property in 1992, 1997, and 2002.

PROPERTY TAX INFORMATION

On April 4, 2002, EnecoTech conducted a telephone interview with the County Assessor's Office. According to their records:

- The current owner of the subject site is Curtis J. Corn located at 4429 Loma Paseo, Bonita, California.
- The subject site consists of approximately 40.79 acres used for agriculture, with no structures on the site. The subject site, as reported by the County of San Diego Assessor's Office, is identified as APN 646-100-31 with the legal description of "Exc rds south ½ of west ½ of northeast ¼ of Section 33, Township 18, Range 1W".

PREVIOUS INVESTIGATIONS

No previous investigations were provided to EnecoTech.

OTHER HISTORICAL SOURCES

No other historical sources were reviewed for this environmental site assessment.

7.0 SITE RECONNAISSANCE

Melissa Novak of EnecoTech conducted a site reconnaissance of the subject site and observed the exterior of adjoining properties on March 29, 2002. Observations of the subject site and adjacent properties on this date are summarized in this section. Photographs of the subject site and surrounding areas are presented in Appendix E. A discussion of the subject site and nearby properties was previously presented in the Site Description section of this report.

The site reconnaissance indicated:

Site Setting

The subject site consists of open, recently tilled, agricultural land. The parcel of land consists of approximately 40.79 acres.

ONSITE CONDITIONS

- The subject site had a small amount of construction debris along the southern boundary off Airway Road. Other miscellaneous debris was scattered intermittently on the subject site. None of the debris appeared to be of a hazardous nature.

- No evidence of hazardous waste generation, storage, or disposal was observed on the site during EnecoTech's site reconnaissance.

- Electrical service is provided by pole-mounted transformers. Three transformers were identified along the subject site boundaries, one along Cactus Road, and two along Airway Road. No leaks or stains were observed in the area of the transformers. SDG&E identified the transformers as not containing PCBs and are not an environmental concern.

- The following conditions were not observed onsite:

  - Stained soils and/or pavement;
  - Sheen or iridescence on surface water;
  - Unusual corrosion;
  - Unusual odors;
  - Aboveground storage tanks;
  - Underground storage tanks;
  - Landfilling;
  - Unusual mounds or piles/irregular depressions;
  - Large areas of earthen fill;
  - Spills or releases;
  - Storage, treatment, and/or disposal of hazardous substances and/or petroleum products;
  - Oil, gas, or water wells;
  - Septic systems and cesspools;
  - Hydraulic lifts/elevators with underground components;
  - Parts washers; or,
  - PCB-containing devices.

ADJOINING PROPERTIES

EnecoTech performed visual reconnaissance of the adjoining properties from the site and public thoroughfare areas. The relevant observations, to the extent identified, were as follows:

- The north adjacent property is an operating recycling center that appeared to recycle metals and PVC piping.

- The south adjacent property had debris items including discarded construction materials, 5-gallon buckets, broken fiberglass, and one 55-gallon drum that appeared empty scattered along the northern perimeter. None of the materials appeared to be of a hazardous nature.

- The east adjacent property had construction debris and a discarded 35-gallon drum that appeared empty.

- No environmental concerns were identified for the west adjacent property.

8.0 INTERVIEWS

EnecoTech contacted the parties listed below for information on the subject site. Other information provided to EnecoTech via telephone correspondence regarding the subject site has been presented in Appendix D.

Owner - EnecoTech conducted a telephone interview with the current owner, Mr. Curtis J. Corn. The owner did not identify any environmental concerns on the subject site or adjoining properties per EnecoTech's telephone correspondences.

Local Environmental/Health Department – On April 9, 2002, EnecoTech received notice from the County of San Diego, DEH that there are no records concerning the subject site.

Local Fire Department – EnecoTech requested information from the City of San Diego Fire Department regarding potential hazardous substance usage, UST's, and hazardous substance spills associated with the subject site. A response from the Fire Department had not been received for inclusion with this report.

9.0 FINDINGS

This section presents EnecoTech's findings based on the records review, interviews, and site reconnaissance.

There were no indications of onsite environmental concern from our records review and interviews. Historic information indicates the subject site has been in agricultural use since the 1920s.

Offsite environmental concerns include one Solid Waste Disposal/Landfill Site and one LUST site within the ASTM search radii.

10.0 OPINIONS

It is EnecoTech's opinion that no onsite or offsite concerns would impact the subject site.

11.0 CONCLUSIONS

EnecoTech has performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E1527-00 of the subject site located at the intersection of Cactus Road and Airway Road in San Diego, California. Any exceptions to, or deletions from, this practice are described in the Introduction of this report. Based on the findings of this Phase I ESA for the subject site, the following conclusions were possible:

This assessment has revealed no evidence of recognized environmental concerns in connection with the subject site except one Solid Waste Disposal/Landfill Site and one LUST site within the ASTM search radii.

12.0 ADDITIONAL SERVICES

No additional services were provided within the scope of work.

13.0 REFERENCES

California Division of Mines & Geology, Map Sheet 29 (1977). Geology of National City, Imperial Beach, and Otay Mesa Quadrangles, Southern San Diego Metropolitan Area, California.

County of San Diego Department of Cartographic Services (1995-1996). Aerial Foto-Map Book, Aerial Fotobank, Inc., San Diego, California 92121.

County of San Diego Department of Cartographic Services (1987, 1982, 1977, 1971, 1966, 1964. 1953, 1945, and 1928). San Diego County aerial photographs. County of San Diego Department of Cartographic Services, Ruffin Road Annex, San Diego, California.

Environmental Data Resources, Inc. (2002). The EDR Radius Map. Environmental Data resources, Inc. Southport, Connecticut 06490.

Frye & Smith Official San Diego City and County Directory (1927 and 1937), Frye & Smith Publishing, San Diego, California

Haines San Diego City and Suburban Criss-Cross Directory (1972 and 1977), Haines & Company, North Canton, Ohio

Haines Criss-Cross Directory – South San Diego County, California (1982, 1987, 1992 – 1993, 1997 – 1998, and 2002), Haines & Company, North Canton, Ohio

Polk's San Diego City Directory (1947 – 1948, 1952, 1957, 1962, and 1967), R.L. Polk & Company, Dallas Texas

Polk's San Diego Suburban Directory (1947 – 1948, 1952, 1957, 1962, and 1967), R.L. Polk & Company, Dallas Texas

Real Estate Atlas of San Diego County – Volume 3 (1972, and 1977)

San Diego (California) City Directory (1932 and 1942), San Diego Directory County Publishing, San Diego, California


San Diego (California) Suburban Directory (1932 and 1942), San Diego Directory County Publishing, San Diego, California

San Diego City and County Directory (1926), San Diego Directory County Publishing, San Diego, California

United States Geologic Survey (USGS) (1967 and photo-revised 1975). USGS topographic map of the Otay Mesa Quadrangle. USGS Denver, Colorado 80225.

APPENDIX A

FIGURES



Reference Thomas Bros.

EnecoTech
STRATEGIES FOR ENVIRONMENTAL RESPONSIBILITIES


BCS PRODUCE COMPANY, INC.

INTERSECTION OF CACTUS & AIRWAY ROADS
SAN DIEGO, CALIFORNIA

SITE LOCATION MAP

File No.:	ACAD File No.:	Date:	Rev.:
02-01877-001	FIG1	4/2002	

Drawn By:	Design By:	Checked By:	Approved By:	Figure. No.:
		TF	TF	1



EnecoTech
STRATEGIES FOR ENVIRONMENTAL RESPONSIBILITY

Project: BCS PRODUCE COMPANY, INC.	SITE PLAN
INTERSECTION OF CACTUS & AIRWAY ROADS SAN DIEGO, CA	

File No.:	02-01877-001	ACAD File No.:	SP402	Date:	4/02	REV.:	
Drawn By:	MJL	Design By:	TF	Checked By:	TF	Approved By:	TF	Figure No.:	2

APPENDIX B

HISTORICAL USE INFORMATION

Environmental Data Resources, Inc.

"Linking Technology with Tradition"

Sanborn® Map Report

Ship to: Melissa Novak
EnecoTech Southwest, Inc.
6160 Fairmount
San Diego, CA 92120

1114553CMK 619-299-0033

Order Date: 4/3/2002 **Completion Date:** 04/03/2002
Inquiry #: 754942.3S
P.O. #: 02-01877-001
Site Name: BCS Produce Company, Inc.
Address: Airway Road/Cactus Road
City/State: San Diego, CA 92154
Cross Streets:

This document reports that the largest and most complete collection of Sanborn fire insurance maps has been reviewed based on client-supplied information, and fire insurance maps depicting the target property at the specified address were not identified.

NO COVERAGE

All maps provided pursuant to a Sanborn® Map Report are currently reproducible of fire insurance maps owned or licensed by Environmental Data Resources, Inc. NO WARRANTY, EXPRESSED OR IMPLIED IS MADE WHATSOEVER. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, WARRANTIES AS TO ACCURACY, VALIDITY, COMPLETENESS, SUITABILITY, CONDITION, QUALITY, MERCHANTABILITY, OR FITNESS FOR A PARTICULAR USE OR PURPOSE WITH RESPECT TO THE REPORT, THE MAPS, THE INFORMATION CONTAINED THEREIN, OR THE RESULTS OF A SEARCH OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. Environmental Data Resources, Inc. assumes no liability to any party for any loss or damage whether arising out of errors or omissions, negligence, accident or any other cause. In no event shall Environmental Data Resources, Inc., its affiliates or agents, be liable to anyone for special, incidental, consequential or exemplary damages.

Copyright 2002, Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format of any map of Environmental Data Resources, Inc. (whether obtained as a result of a search or otherwise) may be prohibited without prior written permission from Environmental Data Resources, Inc. Sanborn and Sanborn Map are registered trademarks of Environmental Data Resources, Inc.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

LOS ANGELES COUNTY:

List of Solid Waste Facilities
Source: La County Department of Public Works
Telephone: 818-458-5185

Date of Government Version: 11/09/99
Database Release Frequency: Varies

Date of Last EDR Contact: 02/20/02
Date of Next Scheduled EDR Contact: 05/20/02

City of El Segundo Underground Storage Tank
Source: City of El Segundo Fire Department
Telephone: 310-607-2239

Date of Government Version: 03/01/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/18/02
Date of Next Scheduled EDR Contact: 05/20/02

City of Long Beach Underground Storage Tank
Source: City of Long Beach Fire Department
Telephone: 562-570-2543

Date of Government Version: 10/01/99
Database Release Frequency: Annually

Date of Last EDR Contact: 02/25/02
Date of Next Scheduled EDR Contact: 05/27/02

City of Torrance Underground Storage Tank
Source: City of Torrance Fire Department
Telephone: 310-618-2973

Date of Government Version: 11/01/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/18/02
Date of Next Scheduled EDR Contact: 05/20/02

City of Los Angeles Landfills
Source: Engineering & Construction Division
Telephone: 213-473-7869

Date of Government Version: 08/31/99
Database Release Frequency: Varies

Date of Last EDR Contact: 02/18/02
Date of Next Scheduled EDR Contact: 05/20/02

HMS: Street Number List
Source: Department of Public Works
Telephone: 626-458-3517
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 11/29/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/18/02
Date of Next Scheduled EDR Contact: 05/20/02

Site Mitigation List
Source: Community Health Services
Telephone: 323-890-7806
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 01/11/01
Database Release Frequency: Annually

Date of Last EDR Contact: 02/18/02
Date of Next Scheduled EDR Contact: 05/20/02

San Gabriel Valley Areas of Concern
Source: EPA Region 9
Telephone: 415-744-2407
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

Date of Government Version: 12/31/98
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 06/29/99
Date of Next Scheduled EDR Contact: N/A

MARIN COUNTY:

Underground Storage Tank Sites
Source: Public Works Department Waste Management
Telephone: 415-499-6647
Currently permitted USTs in Marin County.

Date of Government Version: 03/05/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/04/02
Date of Next Scheduled EDR Contact: 05/06/02

NAPA COUNTY:

Sites With Reported Contamination
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269

Date of Government Version: 10/01/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/02/02
Date of Next Scheduled EDR Contact: 04/01/02

Closed and Operating Underground Storage Tank Sites
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269

Date of Government Version: 10/01/01
Database Release Frequency: Annually

Date of Last EDR Contact: 01/02/02
Date of Next Scheduled EDR Contact: 04/01/02

ORANGE COUNTY:

List of Underground Storage Tank Cleanups
Source: Health Care Agency
Telephone: 714-834-3446
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 11/27/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/12/02
Date of Next Scheduled EDR Contact: 06/10/02

List of Underground Storage Tank Facilities
Source: Health Care Agency
Telephone: 714-834-3446
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 11/27/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/12/02
Date of Next Scheduled EDR Contact: 06/10/02

List of Industrial Site Cleanups
Source: Health Care Agency
Telephone: 714-834-3446
Petroleum and non-petroleum spills.

Date of Government Version: 10/24/00
Database Release Frequency: Annually

Date of Last EDR Contact: 03/12/02
Date of Next Scheduled EDR Contact: 06/10/02

PLACER COUNTY:

Master List of Facilities
Source: Placer County Health and Human Services
Telephone: 530-889-7312
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 01/31/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/02/02
Date of Next Scheduled EDR Contact: 03/25/02

RIVERSIDE COUNTY:

Listing of Underground Tank Cleanup Sites
Source: Department of Public Health
Telephone: 909-358-5055
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 09/05/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/21/02
Date of Next Scheduled EDR Contact: 04/22/02

Underground Storage Tank Tank List
Source: Health Services Agency
Telephone: 909-358-5055

Date of Government Version: 08/01/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/21/02
Date of Next Scheduled EDR Contact: 04/22/02

SACRAMENTO COUNTY:

CS - Contaminated Sites
Source: Sacramento County Environmental Management
Telephone: 916-875-8406

Date of Government Version: 01/15/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/04/02
Date of Next Scheduled EDR Contact: 05/06/02

ML - Regulatory Compliance Master List
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 11/21/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/04/02
Date of Next Scheduled EDR Contact: 05/06/02

SAN BERNARDINO COUNTY:

Hazardous Material Permits
Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/12/02
Date of Next Scheduled EDR Contact: 06/10/02

SAN DIEGO COUNTY:

Solid Waste Facilities
Source: Department of Health Services
Telephone: 619-338-2209
San Diego County Solid Waste Facilities.

Date of Government Version: 08/01/00
Database Release Frequency: Varies

Date of Last EDR Contact: 02/25/02
Date of Next Scheduled EDR Contact: 05/27/02

Hazardous Materials Management Division Database
Source: Hazardous Materials Management Division
Telephone: 619-338-2268
The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 12/25/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

SAN FRANCISCO COUNTY:

Local Oversite Facilities
Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920

Date of Government Version: 03/01/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/12/02
Date of Next Scheduled EDR Contact: 06/10/02

Underground Storage Tank Information
Source: Department of Public Health
Telephone: 415-252-3920

Date of Government Version: 12/01/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/12/02
Date of Next Scheduled EDR Contact: 06/10/02

SAN MATEO COUNTY:

Fuel Leak List
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921

Date of Government Version: 12/06/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/28/02
Date of Next Scheduled EDR Contact: 04/29/02

Business Inventory
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 05/15/01
Database Release Frequency: Annually

Date of Last EDR Contact: 01/15/02
Date of Next Scheduled EDR Contact: 04/15/02

SANTA CLARA COUNTY:

Fuel Leak Site Activity Report
Source: Santa Clara Valley Water District
Telephone: 408-265-2600

Date of Government Version: 01/03/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/04/02
Date of Next Scheduled EDR Contact: 04/01/02

Hazardous Material Facilities
Source: City of San Jose Fire Department
Telephone: 408-277-4659

Date of Government Version: 06/13/00
Database Release Frequency: Annually

Date of Last EDR Contact: 03/12/02
Date of Next Scheduled EDR Contact: 06/10/02

SOLANO COUNTY:

Leaking Underground Storage Tanks
Source: Solano County Department of Environmental Management
Telephone: 707-421-6770

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/18/02
Date of Next Scheduled EDR Contact: 06/17/02

Underground Storage Tanks
Source: Solano County Department of Environmental Management
Telephone: 707-421-6770

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/18/02
Date of Next Scheduled EDR Contact: 06/17/02

SONOMA COUNTY:

Leaking Underground Storage Tank Sites
Source: Department of Health Services
Telephone: 707-565-6565

Date of Government Version: 11/29/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/29/02
Date of Next Scheduled EDR Contact: 04/29/02

SUTTER COUNTY:

Underground Storage Tanks
Source: Sutter County Department of Agriculture
Telephone: 530-822-7500

Date of Government Version: 07/01/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

VENTURA COUNTY:

Inventory of Illegal Abandoned and Inactive Sites
Source: Environmental Health Division
Telephone: 805-654-2813
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 04/02/01
Database Release Frequency: Annually

Date of Last EDR Contact: 02/25/02
Date of Next Scheduled EDR Contact: 05/27/02

Listing of Underground Tank Cleanup Sites
Source: Environmental Health Division
Telephone: 805-654-2813
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/24/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/18/02
Date of Next Scheduled EDR Contact: 06/17/02

Underground Tank Closed Sites List
Source: Environmental Health Division
Telephone: 805-654-2813
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 05/24/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/15/02
Date of Next Scheduled EDR Contact: 04/15/02

Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 11/06/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/18/02
Date of Next Scheduled EDR Contact: 06/17/02

YOLO COUNTY:

Underground Storage Tank Comprehensive Facility Report
Source: Yolo County Department of Health
Telephone: 530-666-8646

Date of Government Version: 11/20/01
Database Release Frequency: Annually

Date of Last EDR Contact: 01/21/02
Date of Next Scheduled EDR Contact: 04/22/02

California Regional Water Quality Control Board (RWQCB) LUST Records

LUST REG 1: Active Toxic Site Investigation
Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-576-2220
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/01
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 02/25/02
Date of Next Scheduled EDR Contact: 05/27/02

LUST REG 2: Fuel Leak List
Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457

Date of Government Version: 12/01/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/28/02
Date of Next Scheduled EDR Contact: 04/15/02

LUST REG 3: Leaking Underground Storage Tank Database
Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147

Date of Government Version: 11/19/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/18/02
Date of Next Scheduled EDR Contact: 05/20/02

LUST REG 4: Underground Storage Tank Leak List
Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-266-6600
Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 08/09/01
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 01/02/02
Date of Next Scheduled EDR Contact: 04/01/02

LUST REG 5: Leaking Underground Storage Tank Database
Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-255-3125

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

LUST REG 6L: Leaking Underground Storage Tank Case Listing
Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 916-542-5424

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

LUST REG 6V: Leaking Underground Storage Tank Case Listing
Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-346-7491

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

LUST REG 7: Leaking Underground Storage Tank Case Listing
Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-346-7491

Date of Government Version: 01/23/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/02/02
Date of Next Scheduled EDR Contact: 04/01/02

LUST REG 8: Leaking Underground Storage Tanks
Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4498
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 07/23/01
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 02/12/02
Date of Next Scheduled EDR Contact: 05/13/02

LUST REG 9: Leaking Underground Storage Tank Report
Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/01
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 01/21/02
Date of Next Scheduled EDR Contact: 04/22/02

California Regional Water Quality Control Board (RWQCB) SLIC Records

SLIC REG 1: Active Toxic Site Investigations
Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220

Date of Government Version: 02/01/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 03/01/02
Date of Next Scheduled EDR Contact: 05/27/02

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Any contaminated site that impacts groundwater or has the potential to impact groundwater.

Date of Government Version: 12/01/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/28/02
Date of Next Scheduled EDR Contact: 04/15/02

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Any contaminated site that impacts groundwater or has the potential to impact groundwater.

Date of Government Version: 02/19/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/18/02
Date of Next Scheduled EDR Contact: 05/20/02

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Any contaminated site that impacts groundwater or has the potential to impact groundwater.

Date of Government Version: 09/13/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/28/02
Date of Next Scheduled EDR Contact: 04/29/02

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-855-3075
Unregulated sites that impact groundwater or have the potential to impact groundwater.

Date of Government Version: 01/02/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583

Date of Government Version: 07/19/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-3298

Date of Government Version: 07/31/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/08/02
Date of Next Scheduled EDR Contact: 04/08/02

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980

Date of Government Version: 03/01/02
Database Release Frequency: Annually

Date of Last EDR Contact: 03/04/02
Date of Next Scheduled EDR Contact: 06/03/02

EDR PROPRIETARY HISTORICAL DATABASES

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Oil/Gas Pipelines/Electrical Transmission Lines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 1999 from the U.S. Fish and Wildlife Service.

GEOCHECK® - PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

BCS PRODUCE COMPANY, INC.
AIRWAY ROAD/CACTUS ROAD
SAN DIEGO, CA 92154

TARGET PROPERTY COORDINATES

Latitude (North):	32.561001 - 32° 33' 39.6"
Longitude (West):	116.987602 - 116° 59' 15.4"
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	501164.1
UTM Y (Meters):	3602431.5

EDR's GeoCheck Physical Setting Source Addendum has been developed to assist the environmental professional with the collection of physical setting source information in accordance with ASTM 1527-00, Section 7.2.3. Section 7.2.3 requires that a current USGS 7.5 Minute Topographic Map (or equivalent, such as the USGS Digital Elevation Model) be reviewed. It also requires that one or more additional physical setting sources be sought when (1) conditions have been identified in which hazardous substances or petroleum products are likely to migrate to or from the property, and (2) more information than is provided in the current USGS 7.5 Minute Topographic Map (or equivalent) is generally obtained, pursuant to local good commercial or customary practice, to assess the impact of migration of recognized environmental conditions in connection with the property. Such additional physical setting sources generally include information about the topographic, hydrologic, hydrogeologic, and geologic characteristics of a site, and wells in the area.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata. EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

USGS TOPOGRAPHIC MAP ASSOCIATED WITH THIS SITE

Target Property: 2432116-E8 OTAY MESA, CA MX02
Source: USGS 7.5 min quad index

GENERAL TOPOGRAPHIC GRADIENT AT TARGET PROPERTY

Target Property: General SW

Source: General Topographic Gradient has been determined from the USGS 1 Degree Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
SAN DIEGO, CA	Not Available

Flood Plain Panel at Target Property: Not Reported

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
OTAY MESA	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Site-Specific Hydrogeological Data*:

Search Radius:	2.0 miles
Status:	Not found

AQUIFLOW®

Search Radius: 2.000 Miles.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Cenozoic
System:	Tertiary
Series:	Pliocene
Code:	Tp *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

* ©1998 Site-specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: gravelly - clay loam
loam
clay
clay loam
coarse sand
cobbly - loam

Surficial Soil Types: gravelly - clay loam
loam
clay
clay loam
coarse sand
cobbly - loam

Shallow Soil Types: very cobbly - clay

Deeper Soil Types: stratified
weathered bedrock
coarse sand
cobbly - loam

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

According to ASTM E 1527-00, Section 7.2.2, "one or more additional state or local sources of environmental records may be checked, in the discretion of the environmental professional, to enhance and supplement federal and state sources... Factors to consider in determining which local or additional state records, if any, should be checked include (1) whether they are reasonably ascertainable, (2) whether they are sufficiently useful, accurate, and complete in light of the objective of the records review (see 7.1.1), and (3) whether they are obtained, pursuant to local, good commercial or customary practice." One of the record sources listed in Section 7.2.2 is water well information. Water well information can be used to assist the environmental professional in assessing sources that may impact groundwater flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 0754942.2r



- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Airports
- (W) Water Wells
- (P) Public Water Supply Wells
- Groundwater Flow Direction
- (GI) Indeterminate Groundwater Flow at Location
- (GV) Groundwater Flow Varies at Location
- Cluster of Multiple Icons
- Earthquake epicenter, Richter 5 or greater
- (HD) Closest Hydrogeological Data
- Oil, gas or related wells

TARGET PROPERTY:	BCS Produce Company, Inc.	CUSTOMER:	EnecoTech Southwest, Inc.
ADDRESS:	Airway Road/Cactus Road	CONTACT:	Melissa Novak
CITY/STATE/ZIP:	San Diego CA 92154	INQUIRY #:	0754942.2r
LAT/LONG:	32.5610 / 116.9876	DATE:	April 03, 2002 10:09 am

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for SAN DIEGO County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

SAN DIEGO COUNTY, CA

Number of sites tested: 30

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.677 pCi/L	100%	0%	0%
Living Area - 2nd Floor	0.400 pCi/L	100%	0%	0%
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 1999 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the national Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STATE RECORDS

California Drinking Water Quality Database
Source: Department of Health Services
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations for District 2 and 6
Source: Department of Conservation
Telephone: 916-323-1779

RADON

Area Radon Information: The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones: Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

APPENDIX C

REGULATORY RECORDS SEARCH

The EDR Radius Map
with GeoCheck®

BCS Produce Company, Inc.
Airway Road/Cactus Road
San Diego, CA 92154

Inquiry Number: 0754942.2r

April 03, 2002

Environmental Data Resources, Inc.

***The* Source For Environmental Risk Management Data**

3530 Post Road
Southport, Connecticut 06490

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	37
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-6
Physical Setting Source Map Findings	A-7
Physical Setting Source Records Searched	A-8

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer
Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.

Entire contents copyright 2001 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and the edr logos are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

TARGET PROPERTY INFORMATION

ADDRESS

AIRWAY ROAD/CACTUS ROAD
SAN DIEGO, CA 92154

COORDINATES

Latitude (North):	32.561000 - 32° 33' 39.6"
Longitude (West):	116.987600 - 116° 59' 15.4"
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	501164.1
UTM Y (Meters):	3602431.5

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property:	2432116-E8 OTAY MESA, CA MX02
Source:	USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM STANDARD

NPL---------- National Priority List
Proposed NPL---------- Proposed National Priority List Sites
CERCLIS---------- Comprehensive Environmental Response, Compensation, and Liability Information System
CERC-NFRAP---------- CERCLIS No Further Remedial Action Planned
CORRACTS---------- Corrective Action Report
RCRIS-TSD---------- Resource Conservation and Recovery Information System
RCRIS-LQG---------- Resource Conservation and Recovery Information System
RCRIS-SQG---------- Resource Conservation and Recovery Information System
ERNS---------- Emergency Response Notification System

STATE ASTM STANDARD

AWP---------- Annual Workplan Sites
Cal-Sites---------- Calsites Database
Toxic Pits---------- Toxic Pits Cleanup Act Sites
WMUDS/SWAT---------- Waste Management Unit Database

EXECUTIVE SUMMARY

LUST..... Leaking Underground Storage Tank Information System
CA BOND EXP. PLAN..... Bond Expenditure Plan
UST..... List of Underground Storage Tank Facilities
CA FID UST..... Facility Inventory Database
HIST UST..... Hazardous Substance Storage Container Database

FEDERAL ASTM SUPPLEMENTAL

CONSENT..... Superfund (CERCLA) Consent Decrees
ROD..... Records Of Decision
Delisted NPL..... National Priority List Deletions
FINDS..... Facility Index System/Facility Identification Initiative Program Summary Report
HMIRS..... Hazardous Materials Information Reporting System
MLTS..... Material Licensing Tracking System
MINES..... Mines Master Index File
NPL Liens..... Federal Superfund Liens
PADS..... PCB Activity Database System
RAATS..... RCRA Administrative Action Tracking System
TRIS..... Toxic Chemical Release Inventory System
TSCA..... Toxic Substances Control Act
FTTS..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

STATE OR LOCAL ASTM SUPPLEMENTAL

AST..... Aboveground Petroleum Storage Tank Facilities
CLEANERS..... Cleaner Facilities
CA WDS..... Waste Discharge System
DEED..... List of Deed Restrictions
CA SLIC..... Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
HAZNET..... Hazardous Waste Information System
SAN DIEGO CO. HMMD..... Hazardous Materials Management Division Database

EDR PROPRIETARY HISTORICAL DATABASES

Coal Gas..... Former Manufactured Gas (Coal Gas) Sites

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS 1 degree Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. EDR's definition of a site with an elevation equal to the target property includes a tolerance of +/- 10 feet. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property (by more than 10 feet). Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STATE ASTM STANDARD

CHMIRS: The California Hazardous Material Incident Report System contains information on reported hazardous material incidents, i.e., accidental releases or spills. The source is the California Office of Emergency Services.

A review of the CHMIRS list, as provided by EDR, and dated 12/31/1994 has revealed that there is 1 CHMIRS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
Not reported	1400 CACTUS RD	1/4 - 1/2 N	1	6

CORTESE: This database identifies public drinking water wells with detectable levels of contamination, hazardous substance sites selected for remedial action, sites with known toxic material identified through the abandoned site assessment program, sites with USTs having a reportable release and all solid waste disposal facilities from which there is known migration. The source is the California Environmental Protection Agency/Office of Emergency Information.

A review of the Cortese list, as provided by EDR, has revealed that there are 2 Cortese sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
BROWN FIELD AIRPORT	*1424 CONTINENTAL ST*	*1/2 - 1 N*	*3*	*7*
PIPER RANCH BUSINESS PARK	*6464 OTAY MESA RD*	*1/2 - 1 NW*	*4*	*34*

NOTIFY 65: Notify 65 records contain facility notifications about any release that could impact drinking water and thereby expose the public to a potential health risk. The data come from the State Water Resources Control Board's Proposition 65 database.

A review of the Notify 65 list, as provided by EDR, has revealed that there is 1 Notify 65 site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
CORNER OF OTAY MESA & HERITAGE	ROAD	1/2 - 1 NW	5	36

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.


A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
CACTUS ROAD- AKA TRIPP SALVAGE	1812 CACTUS ROAD (APN 6	1/4 - 1/2 N	2	6

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
SWEETWATER UNION HS DIST/HS #12 PROPOSED	Cal-Sites
DENNERY RANCH	Cal-Sites
SAN DIEGO INTERNAT'L AIRPORT	Toxic Pits
38TH AND QUINCE STREET BURNASH SITE	SWF/LF
MURPHY-SHEPARD CANYON LANDFILL	SWF/LF
MURRAY CANYON BURNSITE	SWF/LF
MURRAY RIDGE BURNSITE	SWF/LF
FAIRMOUNT BURNSITE	SWF/LF
SAN YSIDRO BURNSITE	SWF/LF
SUNSHINE SUMMIT BURNSITE	SWF/LF
MTS-PORT DISTRICT SITE	SWF/LF
S.H. PERLMUTTER	SWF/LF
OTAY TRUCK STOP	SWF/LF
MONTGOMERY DEMOLITION LANDFILL	SWF/LF
MURRAY CANYON LANDFILL	SWF/LF
BELL JR HIGH SLF/SWEETWATER II	SWF/LF
KELLY STREET BURNSITE	SWF/LF
ARIZONA STREET SLF	SWF/LF
FEDERAL BOULEVARD BURNSITE	SWF/LF
SD CONVENTION CENTER	SWF/LF
ROSE CANYON	SWF/LF
OLD MCRD REFUSE DISPOSAL/BURN AREA	SWF/LF
INS SHOOTING RANGE (CAYS)	SWF/LF
BALBOA PARK NURSERY	SWF/LF
CITY FARM DUMP	SWF/LF
BALBOA PARK NURSERY	SWF/LF
CAMP MATTHEWS	SWF/LF
INS SHOOTING RANGE (CAYS)	SWF/LF
CITY FARM DUMP	SWF/LF
SUBASE OLD REFUSE DISPOSAL	SWF/LF
DEXTER CANYON DISPOSAL SITE	SWF/LF
MISSION VALLEY DISPOSAL AREA	SWF/LF
TOURMALINE BEACH BURNSITE	SWF/LF
TOURMALINE BEACH BURNSITE	SWF/LF
BALBOA PARK LANDFILL	SWF/LF
SAN CLEMENTE CYN DISPOSAL SITE	SWF/LF
NELSON & SLOAN (CAYS)	SWF/LF
KUSI TV MCKINNON BROADCASTING	HAZNET
COUNTY OF SAN DIEGO PUBLIC WORKS	HAZNET

OVERVIEW MAP - 0754942.2r - EnecoTech Southwest, Inc.




0 1/4 1/2 1 Miles

- ☆ Target Property
- ▲ Sites at elevations higher than or equal to the target property
- ◆ Sites at elevations lower than the target property
- Coal Gasification Sites
- National Priority List Sites
- Landfill Sites
- Power transmission lines
- Oil & Gas pipelines
- Wetlands
- Areas of Concern

N

TARGET PROPERTY:	BCS Produce Company, Inc.	CUSTOMER:	EnecoTech Southwest, Inc.
ADDRESS:	Airway Road/Cactus Road	CONTACT:	Melissa Novak
CITY/STATE/ZIP:	San Diego CA 92154	INQUIRY #:	0754942.2r
LAT/LONG:	32.5610 / 116.9876	DATE:	April 03, 2002 10:09 am

DETAIL MAP - 0754942.2r - EnecoTech Southwest, Inc.



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Coal Gasification Sites
- Sensitive Receptors
- National Priority List Sites
- Landfill Sites
- Power transmission lines
- Oil & Gas pipelines
- Wetlands
- Areas of Concern

TARGET PROPERTY:	BCS Produce Company, Inc.	CUSTOMER:	EnecoTech Southwest, Inc.
ADDRESS:	Airway Road/Cactus Road	CONTACT:	Melissa Novak
CITY/STATE/ZIP:	San Diago CA 92154	INQUIRY #:	0754942.2r
LAT/LONG:	32.5610 / 116.9876	DATE:	April 03, 2002 10:09 am

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL ASTM STANDARD								
NPL		1.000	0	0	0	0	NR	0
Proposed NPL		1.000	0	0	0	0	NR	0
CERCLIS		0.500	0	0	0	NR	NR	0
CERC-NFRAP		0.250	0	0	NR	NR	NR	0
CORRACTS		1.000	0	0	0	0	NR	0
RCRIS-TSD		0.500	0	0	0	NR	NR	0
RCRIS Lg. Quan. Gen.		0.250	0	0	NR	NR	NR	0
RCRIS Sm. Quan. Gen.		0.250	0	0	NR	NR	NR	0
ERNS		TP	NR	NR	NR	NR	NR	0
STATE ASTM STANDARD								
AWP		1.000	0	0	0	0	NR	0
Cal-Sites		1.000	0	0	0	0	NR	0
CHMIRS		1.000	0	0	1	0	NR	1
Cortese		1.000	0	0	0	2	NR	2
Notify 65		1.000	0	0	0	1	NR	1
Toxic Pits		1.000	0	0	0	0	NR	0
State Landfill		0.500	0	0	1	NR	NR	1
WMUDS/SWAT		0.500	0	0	0	NR	NR	0
LUST		0.500	0	0	0	NR	NR	0
CA Bond Exp. Plan		1.000	0	0	0	0	NR	0
UST		0.250	0	0	NR	NR	NR	0
CA FID UST		0.250	0	0	NR	NR	NR	0
HIST UST		0.250	0	0	NR	NR	NR	0
FEDERAL ASTM SUPPLEMENTAL								
CONSENT		1.000	0	0	0	0	NR	0
ROD		1.000	0	0	0	0	NR	0
Delisted NPL		1.000	0	0	0	0	NR	0
FINDS		TP	NR	NR	NR	NR	NR	0
HMIRS		TP	NR	NR	NR	NR	NR	0
MLTS		TP	NR	NR	NR	NR	NR	0
MINES		0.250	0	0	NR	NR	NR	0
NPL Liens		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
FTTS		TP	NR	NR	NR	NR	NR	0
STATE OR LOCAL ASTM SUPPLEMENTAL								
AST		TP	NR	NR	NR	NR	NR	0
CLEANERS		0.250	0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CA WDS		TP	NR	NR	NR	NR	NR	0
DEED		TP	NR	NR	NR	NR	NR	0
CA SLIC		0.500	0	0	0	NR	NR	0
HAZNET		0.250	0	0	NR	NR	NR	0
San Diego Co. HMMD		TP	NR	NR	NR	NR	NR	0
EDR PROPRIETARY HISTORICAL DATABASES								
Coal Gas		1.000	0	0	0	0	NR	0

AQUIFLOW - see EDR Physical Setting Source Addendum

TP = Target Property

NR = Not Requested at this Search Distance

- Sites may be listed in more than one database

Coal Gas Site Search: No site was found in a search of Real Property Scan's ENVIROHAZ database.

1
North
1/4-1/2
2217
Higher

1400 CACTUS RD
SAN DIEGO, CA

CHMIRS **S100216077**
N/A

CHMIRS:

OES Control Number:	8801895	DOT ID:	Not reported
DOT Hazard Class:	Not Reported		
Chemical Name:	POLYETHYLENE		
Extent of Release:	Not reported		
CAS Number:	Not reported	Quantity Released:	10000
Environmental Contamination:	Air	Property Use:	Agricultural
Incident Date:	18-JUN-88	Date Completed:	18-JUN-88

2
North
1/4-1/2
2571
Higher

CACTUS ROAD- AKA TRIPP SALVAGE
1812 CACTUS ROAD (APN 64610049-59-70)
SAN YSIDRO (IN SAN DIEGO), CA

SWF/LF **S101669413**
N/A

LF:

Facility ID:	37-CR-0011
Operator:	Tripp,fred/Martinez,jose (County Of Sd)
Operator Phone:	Not reported
Operator Addr:	5555 Overland Drive
	San Diego, CA 92123
Owner:	Sesi Et Al
Owner Address:	Not reported
	1415 Coker Way
	El Cajon
Owner Telephone:	Not reported
Activity:	Solid Waste Disposal Site
Operator's Status:	Closed
Regulation Status:	Unpermitted
Region:	STATE
Lat/Long:	33 / -117
Permit Date:	Not reported
Accepted Waste:	
Permitted Throughput with Units:	0
Permitted Throughput with Units:	0
Permitted Throughput with Units:	0
Actual Throughput with Units:	Not reported
Actual Capacity with Units:	0
Permitted Capacity with Units:	0
Remaining Capacity with Units:	Not reported
Permitted Total Acreage:	0
Inspection Frequency:	Quarterly
Landuse Name:	Not reported
GIS Source:	Place
Permit Status:	Not reported
Category:	Disposal
Unit Number:	01
Last Waste Tire Inspection Count :	0
Last Waste Tire Inspection Date:	0
Original Waste Tire Count:	Not reported

CACTUS ROAD- AKA TRIPP SALVAGE (Continued) S101669413

Original Waste Tire Count Date:	Not reported
Closure Date:	/ /
Closure Type:	Not reported
Disposal Acreage:	0
Remaining Capacity:	0

3 **BROWN FIELD AIRPORT** LUST 1000437555
North **1424 CONTINENTAL ST** HIST UST N/A
1/2-1 **SAN DIEGO, CA 92073** Cortese
2656 SAN DIEGO CO. HMMD
Higher

State LUST:

Cross Street:	Not reported		
Qty Leaked:	Not reported		
Case Number	9UT2989		
Reg Board:	San Diego Region		
Chemical:	Diesel		
Lead Agency:	Local Agency		
Local Agency :	37000		
Case Type:	Soil only		
Status:	Preliminary site assessment underway		
County:	San Diego		
Review Date:	3/17/1989	Confirm Leak:	3/17/1989
Workplan:	3/31/1989	Prelim Assess:	3/31/1989
Pollution Char:	Not reported	Remed Plan:	Not reported
Remed Action:	Not reported	Monitoring:	Not reported
Close Date:	Not reported		
Release Date:	3/30/1989		
Cleanup Fund Id :	Not reported		
Discover Date :	3/17/1989		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	3/28/1993		
Funding:	Not reported		
Staff Initials:	ELS		
How Discovered:	Tank Closure		
How Stopped:	Close Tank		
Interim :	Yes		
Leak Cause:	Unknown		
Leak Source:	Unknown		
MTBE Date :	Not reported		
Max MTBE GW :	Not reported		
MTBE Tested:	Not Required to be Tested.		
Priority:	2B		
Local Case # :	H10618-003		
Beneficial:	MUN		
Staff :	SJP		
GW Qualifies :	Not reported		
Max MTBE Soil :	Not reported		
Soil Qualifies :	Not reported		
Hydr Basin #:	911.12		
Operator :	CITY OF SAN DIEGO		
Oversight Prgm:	Local Oversight Program UST		
Oversight Prgm :	LOP		
Review Date :	3/30/1993		
Stop Date :	3/17/1989		
Work Suspended :	Not reported		
Responsible Party	CITY OF SAN DIEGO		

BROWN FIELD AIRPORT (Continued) 1000437555

RP Address: 4950 MURPHY CANYON RD 92123-4325
Global Id: T0607301154
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 38903.900136331521744680610565
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Cross Street: SIKORSKY
Qty Leaked: Not reported
Case Number 9UT1811
Reg Board: San Diego Region
Chemical: Premium Gasoline
Lead Agency: Local Agency
Local Agency : 37000
Case Type: Soil only
Status: Preliminary site assessment underway
County: San Diego
Review Date: 10/19/1990
Workplan: 10/19/1990
Pollution Char: Not reported
Remed Action: Not reported
Close Date: Not reported
Release Date: 10/10/1990
Cleanup Fund Id : Not reported
Discover Date : 10/10/1990
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 12/5/1990
Funding: Not reported
Staff Initials: ELS
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Priority: 2B
Local Case # : H10618-017
Beneficial: MUN
Staff : SJP
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: 911.12
Operator : CITY OF SAN DIEGO
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 3/17/1992
Stop Date : 10/10/1990
Work Suspended : Not reported

Confirm Leak: 10/19/1990
Prelim Assess: 10/19/1990
Remed Plan: Not reported
Monitoring: Not reported

BROWN FIELD AIRPORT (Continued) **1000437555**

Responsible Party: CITY OF SAN DIEGO
RP Address: 4950 MURPHY CANYON RD 92123-4325
Global Id: T0607300600
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 38903.900136331521744680610565
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Cross Street: STEARMAN ST
Qty Leaked: Not reported
Case Number: 9UT2393
Reg Board: San Diego Region
Chemical: Diesel
Lead Agency: Local Agency
Local Agency : 37000
Case Type: Soil only
Status: Preliminary site assessment underway
County: San Diego
Review Date: Not reported
Workplan: 5/31/1989
Pollution Char: Not reported
Remed Action: Not reported
Close Date: Not reported
Release Date: 4/6/1989
Cleanup Fund Id : Not reported
Discover Date : 3/17/1989
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 3/28/1993
Funding: Not reported
Staff Initials: ELS
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: 2B
Local Case # : H10618-007
Beneficial: MUN
Staff : SJP
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: 911.12
Operator : CITY OF SAN DIEGO
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 6/9/1993
Stop Date : 3/17/1989

Confirm Leak: Not reported
Prelim Assess: 5/31/1989
Remed Plan: Not reported
Monitoring: Not reported

BROWN FIELD AIRPORT (Continued) **1000437555**

Work Suspended :Not reported
Responsible PartyCITY OF SAN DIEGO
RP Address: 4950 MURPHY CANYON RD 92123-4325
Global Id: T0607301159
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 38903.900136331521744680610565
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Cross Street: BOEING ST
Qty Leaked: Not reported
Case Number 9UT2398
Reg Board: San Diego Region
Chemical: Diesel
Lead Agency: Local Agency
Local Agency : 37000
Case Type: Soil only
Status: Preliminary site assessment underway
County: San Diego
Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)
Review Date: 4/14/1989
Confirm Leak: 4/14/1989
Workplan: 6/23/1989
Prelim Assess: 6/23/1989
Pollution Char: Not reported
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: Not reported
Release Date: 5/4/1989
Cleanup Fund Id : Not reported
Discover Date : 4/14/1989
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 3/28/1993
Funding: Not reported
Staff Initials: ELS
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: 2B
Local Case # : H10618-012
Beneficial: MUN
Staff : SJP
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: 911.12
Operator : CITY OF SAN DIEGO
Oversight Prgm: Local Oversight Program UST

BROWN FIELD AIRPORT (Continued) **1000437555**

Oversight Prgm : LOP
Review Date : 3/30/1993
Stop Date : 4/14/1989
Work Suspended : Not reported
Responsible Party CITY OF SAN DIEGO
RP Address: 4950 MURPHY CANYON RD 92123-4325
Global Id: T0607301164
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 38903.900136331521744680610585
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Cross Street: Not reported
Qty Leaked: Not reported
Case Number 9UT1933
Reg Board: San Diego Region
Chemical: Boiler Fuel
Lead Agency: Local Agency
Local Agency : 37000
Case Type: Aquifer affected
Status: Preliminary site assessment underway
County: San Diego
Review Date: 12/6/1990
Workplan: 12/6/1990
Pollution Char: Not reported
Remed Action: Not reported
Close Date: Not reported
Release Date: 12/6/1990
Cleanup Fund Id : Not reported
Discover Date : 12/6/1990
Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 4/4/1991
Funding: Not reported
Staff Initials: ELS
How Discovered: Tank Closure
How Stopped: Close Tank
Interim : Yes
Leak Cause: Unknown
Leak Source: Unknown
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: 2B
Local Case # : H10618-020
Beneficial: MUN
Staff : SJP
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: 911.12
Operator : CITY OF SAN DIEGO
Oversight Prgm: Local Oversight Program UST

Confirm Leak: 12/6/1990
Prelim Assess: 12/6/1990
Remed Plan: Not reported
Monitoring: Not reported

BROWN FIELD AIRPORT (Continued) 1000437555

Oversight Prgm : LOP
Review Date : 3/17/1992
Stop Date : 12/6/1990
Work Suspended :Not reported
Responsible PartyCITY OF SAN DIEGO
RP Address: 4950 MURPHY CANYON RD 92123-4325
Global Id: T0607300712
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 38903.900136331521744680610565
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 9:

Case Number:	9UT1467	Release Date:	06/23/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	06/23/1989	How Found:	Tank Closure
Date Stopped:	06/23/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-015
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		

Interim Remedial Actions: Yes
Beneficial Use: MUN
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported
NPDES Number: Not reported

BROWN FIELD AIRPORT (Continued) 1000437555

Case Number:	9UT1796	Release Date:	10/12/1990
Local Agency:	37000		
Substance:	12033	Qty Leaked:	0
Date Found:	10/12/1990	How Found:	Tank Closure
Date Stopped:	10/12/1990	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Aquifer affected		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-019
Basin Number:	911.12	Gwater Depth:	UNK
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT1797	Release Date:	10/12/1990
Local Agency:	37000		
Substance:	12033	Qty Leaked:	0
Date Found:	10/12/1990	How Found:	Tank Closure
Date Stopped:	10/12/1990	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Aquifer affected		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-018
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	Not reported		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) **1000437555**

Case Number:	9UT1811	Release Date:	10/10/1990
Local Agency:	37000		
Substance:	12033	Qty Leaked:	0
Date Found:	10/10/1990	How Found:	Tank Closure
Date Stopped:	10/10/1990	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-017
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT1812	Release Date:	10/10/1990
Local Agency:	37000		
Substance:	12033	Qty Leaked:	0
Date Found:	10/10/1990	How Found:	Tank Closure
Date Stopped:	10/10/1990	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	10/19/90	Submit Workplan:	10/19/90
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-016
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) **1000437555**

Case Number:	9UT1933	Release Date:	12/06/1990
Local Agency:	37000		
Substance:	09	Qty Leaked:	0
Date Found:	12/06/1990	How Found:	Tank Closure
Date Stopped:	12/06/1990	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Aquifer affected		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-020
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:		Yes	
Beneficial Use:		MUN	
Cleanup and Abatement order Number:		Not reported	
Waste Discharge Requirement Number:		Not reported	
NPDES Number:		Not reported	

Case Number:	9UT1942	Release Date:	04/19/1991
Local Agency:	37000		
Substance:	12034	Qty Leaked:	0
Date Found:	04/19/1991	How Found:	Tank Closure
Date Stopped:	04/19/1991	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Aquifer affected		
Confirm Date:	5/16/91	Submit Workplan:	5/16/91
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-023
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	Not reported		
Interim Remedial Actions:		Yes	
Beneficial Use:		MUN	
Cleanup and Abatement order Number:		Not reported	
Waste Discharge Requirement Number:		Not reported	
NPDES Number:		Not reported	

BROWN FIELD AIRPORT (Continued) 1000437555

Case Number:	9UT1992	Release Date:	04/19/1991
Local Agency:	37000		
Substance:	12037	Qty Leaked:	Not reported
Date Found:	04/19/1991	How Found:	Tank Closure
Date Stopped:	04/19/1991	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-022
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT2388	Release Date:	03/30/1989
Local Agency:	37000		
Substance:	8006619	Qty Leaked:	0
Date Found:	03/17/1989	How Found:	Tank Closure
Date Stopped:	03/17/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-002
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) 1000437555

Case Number:	9UT2389	Release Date:	03/30/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	0
Date Found:	03/17/1989	How Found:	Tank Closure
Date Stopped:	03/17/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-003
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT2390	Release Date:	03/30/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	03/17/1989	How Found:	Tank Closure
Date Stopped:	03/17/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-004
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) **1000437555**

Case Number:	9UT2391	Release Date:	03/30/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	03/17/1989	How Found:	Tank Closure
Date Stopped:	03/17/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-005
Basin Number:	911.12	Gwater Depth:	400+
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT2392	Release Date:	04/06/1989
Local Agency:	37000		
Substance:	12035	Qty Leaked:	0
Date Found:	03/17/1989	How Found:	Tank Closure
Date Stopped:	03/17/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-006
Basin Number:	911.12	Gwater Depth:	440+
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) **1000437555**

Case Number:	9UT2393	Release Date:	04/06/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	03/17/1989	How Found:	Tank Closure
Date Stopped:	03/17/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-007
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT2394	Release Date:	05/04/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	04/14/1989	How Found:	Tank Closure
Date Stopped:	04/14/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-008
Basin Number:	911.12	Gwater Depth:	440+
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) 1000437555

Case Number:	9UT2395	Release Date:	05/04/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	04/14/1989	How Found:	Tank Closure
Date Stopped:	04/14/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-009
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT2396	Release Date:	05/04/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	04/14/1989	How Found:	Tank Closure
Date Stopped:	04/14/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-010
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) **1000437555**

Case Number:	9UT2397	Release Date:	05/04/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	04/14/1989	How Found:	Tank Closure
Date Stopped:	04/14/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-011
Basin Number:	911.12	Gwater Depth:	440'
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT2398	Release Date:	05/04/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	04/14/1989	How Found:	Tank Closure
Date Stopped:	04/14/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-012
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) 1000437555

Case Number:	9UT2399	Release Date:	05/04/1989
Local Agency:	37000		
Substance:	12034	Qty Leaked:	Not reported
Date Found:	04/14/1989	How Found:	Tank Closure
Date Stopped:	04/14/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Preliminary site assessment underway		
Case Type:	Soil only		
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	Not reported	Closed Date:	Not reported
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-013
Basin Number:	911.12	Gwater Depth:	440+
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUN		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT2400	Release Date:	05/04/1989
Local Agency:	37000		
Substance:	61	Qty Leaked:	Not reported
Date Found:	04/14/1989	How Found:	Tank Closure
Date Stopped:	04/14/1989	How Stopped:	Close Tank
Source:	Unknown	Cause:	Unknown
Lead Agency:	Local Agency		
Status:	Signed off, remedial action completed or deemed unnecessary		
Case Type:	Soil only		
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	8/16/99	Closed Date:	8/16/99
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-014
Basin Number:	911.12	Gwater Depth:	5-45
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	MUNBU		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

BROWN FIELD AIRPORT (Continued) 1000437555

Case Number:	9UT692	Release Date:	04/21/1987
Local Agency:	37000		
Substance:	12033	Qty Leaked:	0
Date Found:	04/16/1987	How Found:	Tank Closure
Date Stopped:	04/16/1987	How Stopped:	Close Tank
Source:	Tank	Cause:	Overfill
Lead Agency:	Local Agency		
Status:	Signed off, remedial action completed or deemed unnecessary		
Case Type:	Soil only		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	4/21/87	Closed Date:	4/21/87
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H19053-001
Basin Number:	911.12	Gwater Depth:	300
File Dispn:	File discarded, case closed		
Interim Remedial Actions:	Yes		
Beneficial Use:	Not reported		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

Case Number:	9UT712	Release Date:	02/23/1987
Local Agency:	37000		
Substance:	0	Qty Leaked:	0
Date Found:	02/06/1987	How Found:	Tank Closure
Date Stopped:	02/06/1987	How Stopped:	Close Tank
Source:	Tank	Cause:	Corrosion
Lead Agency:	Local Agency		
Status:	Signed off, remedial action completed or deemed unnecessary		
Case Type:	Aquifer affected		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	3/4/87	Closed Date:	3/4/87
Enforce Type:	Not reported		
Enforce Date:	Not reported		
Pilot Program:	LOP	Local Case:	H10618-001
Basin Number:	911.12	Gwater Depth:	<10
File Dispn:	File archived, case closed and file moved to storage		
Interim Remedial Actions:	Yes		
Beneficial Use:	Not reported		
Cleanup and Abatement order Number:	Not reported		
Waste Discharge Requirement Number:	Not reported		
NPDES Number:	Not reported		

The CA State LUST database contains 18 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id:	9UT3904
Region:	CORTESE
Reg By:	Leaking Underground Storage Tanks

Reg Id: 9UT692

BROWN FIELD AIRPORT (Continued) **1000437555**

Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT712
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1796
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1797
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1812
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1811
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1467
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1992
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1933
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT1942
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2390
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2388
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2389
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2391
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2392
Region: CORTESE

BROWN FIELD AIRPORT (Continued) 1000437555

Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2393
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2394
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2395
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2396
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2397
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2398
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2399
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Reg Id: 9UT2400
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

HMMD:

Facility ID:	H10618		
Inactive Indicator:	Active	Business Code:	Not reported
SIC:	Not reported	Permit Expiration:	00/00
Owner:	SAN DIEGO GEN SVCS DEPT CITY	2nd Name:	Not reported
		Business Phone:	(619)690-8355
Mailing Address:	SAN DIEGO CA 92173, 1708		
Corporate Code:	20	Fire Dept District:	SAN DIEGO FD
Census Tract #:	10007	EPA ID:	CAD981988587
Inspection Date:	04/26/1994 0:00:00	Reinspection Date:	04/95
Inspector Name:	TRAINOR	Gas Station:	Not reported
Facility Contact:	MIKE TUSSY/OPERATIONS MANAGER	Delinquent Flag:	Not Delinquent
Property Owner:	SAN DIEGO GEN SVCS DEPT CITY		
PO Address:	SAN DIEGO CA 92073		
Tank Owner:	CITY OF SAN DIEGO		
TO Address:	SAN DIEGO CA 92073		
Last Update:	04/19/1999 0:00:00		
Last Delinquent Letter:	08/07/1994 0:00:00		

BROWN FIELD AIRPORT (Continued) 1000437555

Last Letter Type: 30
Violation Notice Issued: Not reported
Map Code/Business Plan on File: Not reported
Business Plan Acceptance Date: 11/22/88
Reinspection Date Y2K Compatible: Apr 1995

HMMD DISCLOSURE INVENTORY:
Chemical Name: Not reported
Item Number: Not reported
Stored at 1 Time: Not reported
Measurement Units: Not reported
Storage Method: Not reported
Carcinogen: No
Annual Qty String: Not reported
Quantity Stored At One Time: Not reported
Annual Quantity String: Not reported
Material Safety Data Sheet: Not reported
1st Hazard Category: Not reported
2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: T001
Capacity (Gal): 565.00
Waste or Product: Product
Tank ID Number: C1338-1
Tank Exempt: No
Tank Contents: DIESEL

Tank Number: T002
Capacity (Gal): 550.00
Waste or Product: Product
Tank ID Number: C1338-2
Tank Exempt: No
Tank Contents: DIESEL

Tank Number: T003
Capacity (Gal): 550.00
Waste or Product: Product
Tank ID Number: C1338-3
Tank Exempt: No
Tank Contents: DIESEL

Tank Number: T005
Capacity (Gal): 10000.00
Waste or Product: Product
Tank ID Number: C1338-5
Tank Exempt: No
Tank Contents: REGULAR UNLEADED

Tank Number: T008
Capacity (Gal): 50000.00
Waste or Product: Product
Tank ID Number: C1338-8
Tank Exempt: No
Tank Contents: AVIATION FUEL

Tank Number: T009
Capacity (Gal): 50000.00
Waste or Product: Product
Tank ID Number: C1338-9
Tank Exempt: No
Tank Contents: AVIATION FUEL

Tank Number: T012
Capacity (Gal): 50000.00
Waste or Product: Product
Tank ID Number: C1338-12
Tank Exempt: No
Tank Contents: AVIATION FUEL

Tank Number: T013
Capacity (Gal): 25000.00
Waste or Product: Product
Tank ID Number: C1338-13
Tank Exempt: No
Tank Contents: AVIATION FUEL

Tank Number: T014
Capacity (Gal): 25000.00
Waste or Product: Product
Tank ID Number: C1338-14
Tank Exempt: No
Tank Contents: AVIATION FUEL

Tank Number: T015
Capacity (Gal): 220000.00
Waste or Product: Product
Tank ID Number: C1338-15
Tank Exempt: No
Tank Contents: DIESEL

BROWN FIELD AIRPORT (Continued) 1000437555

Tank Number: T016
Capacity (Gal): 220000.00
Waste or Product: Product
Tank ID Number: 1338-16
Tank Exempt: No
Tank Contents: DIESEL

Tank Number: T017
Capacity (Gal): 220000.00
Waste or Product: Product
Tank ID Number: C1338-17
Tank Exempt: No
Tank Contents: DIESEL

Tank Number: T018
Capacity (Gal): 1.00
Waste or Product: Product
Tank ID Number: C1338-18
Tank Exempt: No
Tank Contents: REGULAR UNLEADED

Tank Number: T019
Capacity (Gal): 1.00
Waste or Product: Product
Tank ID Number: C1338-19
Tank Exempt: No
Tank Contents: LEADED

Tank Number: T020
Capacity (Gal): 500.00
Waste or Product: Product
Tank ID Number: C1338-20
Tank Exempt: No
Tank Contents: DIESEL

Tank Number: T021
Capacity (Gal): 1.00
Waste or Product: Waste
Tank ID Number: C1338-21
Tank Exempt: No
Tank Contents: WASTE OIL

Tank Number: T022
Capacity (Gal): 10000.00
Waste or Product: Product
Tank ID Number: C1338-22
Tank Exempt: No
Tank Contents: REGULAR UNLEADED

Tank Number: T023
Capacity (Gal): 5000.00
Waste or Product: Product
Tank ID Number: C1338-23
Tank Exempt: No
Tank Contents: DIESEL

Tank Number: T024
Capacity (Gal): 500.00
Waste or Product: Product
Tank ID Number: C1338-28
Tank Exempt: No
Tank Contents: PLUS UNLEADED

Tank Number: T025
Capacity (Gal): 500.00
Waste or Product: Product
Tank ID Number: C1338-25
Tank Exempt: No
Tank Contents: PLUS UNLEADED

Tank Number: T026
Capacity (Gal): 500.00
Waste or Product: Product
Tank ID Number: C1338-26
Tank Exempt: No
Tank Contents: PLUS UNLEADED

Tank Number: T027
Capacity (Gal): 250.00
Waste or Product: Waste
Tank ID Number: 1338-27
Tank Exempt: No
Tank Contents: WASTE OIL

Tank Number: T028
Capacity (Gal): 1.00
Waste or Product: Not reported
Tank ID Number: 1338-28
Tank Exempt: No
Tank Contents: SEE FILE FOR CONTENTS

Tank Number: T029
Capacity (Gal): 550.00
Waste or Product: Not reported
Tank ID Number: 1338-29
Tank Exempt: No
Tank Contents: SEE FILE FOR CONTENTS

BROWN FIELD AIRPORT (Continued) **1000437555**

Tank Number: T030 Tank ID Number: 1338-30
Capacity (Gal): 550.00 Tank Exempt: No
Waste or Product: Waste Tank Contents: WASTE OIL

Tank Number: T031 Tank ID Number: 1338-31
Capacity (Gal): 1500.00 Tank Exempt: No
Waste or Product: Not reported Tank Contents: SEE FILE FOR CONTENTS

Tank Number: T032 Tank ID Number: 1338-32
Capacity (Gal): 1.00 Tank Exempt: No
Waste or Product: Not reported Tank Contents: SEE FILE FOR CONTENTS

Tank Number: T033 Tank ID Number: 1338-38
Capacity (Gal): 1.00 Tank Exempt: No
Waste or Product: Not reported Tank Contents: SEE FILE FOR CONTENTS

Tank Number: T034 Tank ID Number: 1338-34
Capacity (Gal): 2200.00 Tank Exempt: No
Waste or Product: Not reported Tank Contents: SEE FILE FOR CONTENTS

Tank Number: T035 Tank ID Number: 1338-35
Capacity (Gal): 1400.00 Tank Exempt: No
Waste or Product: Not reported Tank Contents: SEE FILE FOR CONTENTS

Tank Number: T038 Tank ID Number: AT2060
Capacity (Gal): 800.00 Tank Exempt: No
Waste or Product: Waste Tank Contents: GASOLINE & WASTE OIL

Tank Number: T039 Tank ID Number: AT2060
Capacity (Gal): 1600.00 Tank Exempt: No
Waste or Product: Waste Tank Contents: GASOLINE & WASTE OIL

Tank Number: T040 Tank ID Number: AT3066
Capacity (Gal): 550.00 Tank Exempt: No
Waste or Product: Product Tank Contents: DIESEL

HMMD WASTE STREAMS:
Inspection Date: Not reported Waste Item #: Not reported
Waste Code: Not reported Waste Name: Not reported
Qnty at Inspection: Not reported Annual Quantity: Not reported
Measurement Unit: Not reported
Treatment Method: Not reported Storage Method: Not reported
Waste Description: Not reported Haz Waste Hauler: Not reported
Carcinogen: No Annual Qty String: Not reported
Quantity String: Not reported

HMMD VIOLATIONS:
Inspection Date: 02/28/1990 0:00:00 Occurrences: 01
Waste Code: 211
Type of Violation: HALOGENATED SOLVENTS
Violation Description: GENERATOR HAS NOT RETAINED A COPY OF EACH MANIFEST FOR 3 YEARS FROM THE DATE OF TRANSPORT
CCR 66492 (A)

Inspection Date: 05/05/1992 0:00:00 Occurrences: 01
Waste Code: Not reported
Type of Violation: GENERAL VIOLATION

BROWN FIELD AIRPORT (Continued) **1000437555**

Violation Description: OPERATOR OF THE UNDERGROUND STORAGE TANK HAS NOT ENTERED INTO A WRITTEN CONTRACT WITH TANK OWNER AND NOTIFIED THE HMMD HSC 25293(B)

Inspection Date: 05/05/1992 0:00:00 Occurrences: 01
Waste Code: Not reported
Type of Violation: GENERAL VIOLATION
Violation Description: BUSINESS PLAN HAS NOT BEEN COMPLETED/UPDATED AND/OR MAINTAINED ON SITE HSC 25503.5, 25504, 25505

Inspection Date: 05/05/1992 0:00:00 Occurrences: 01
Waste Code: Not reported
Type of Violation: GENERAL VIOLATION
Violation Description: OWNER/OPERATOR HAS NOT HAD MONITORING EQUIPMENT TESTED ANNUALLY AS REQUIRED. 23CCR 2630, 2641 (J)

HMMD ENVIRONMENTAL ASSESSMENT INFORMATION:
Case Status Date: 10/19/1990 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 017
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 10/10/1990 0:00:00
Lead Agency: Not reported

Case Status Date: 04/16/1999 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 024
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 03/25/1999 0:00:00
Lead Agency: Not reported

Case Status Date: 05/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 013
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/14/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 07/19/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 015
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 06/25/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 08/16/1999 0:00:00
Case Type: TANK, RELEASE
Case Status: CLOSED
Release Occurrance Number: 014
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/14/1989 0:00:00
Lead Agency: Not reported

BROWN FIELD AIRPORT (Continued) 1000437555

Case Status Date: 10/12/1990 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 018
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 10/12/1990 0:00:00
Lead Agency: Not reported

Case Status Date: 10/22/1990 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 019
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 10/12/1990 0:00:00
Lead Agency: Not reported

Case Status Date: 12/03/1990 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 020
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 12/06/1990 0:00:00
Lead Agency: Not reported

Case Status Date: 05/29/1991 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 023
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/19/1991 0:00:00
Lead Agency: Not reported

Case Status Date: 06/23/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 012
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/14/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 04/17/1991 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 022
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/17/1991 0:00:00
Lead Agency: Not reported

Case Status Date: 03/04/1987 0:00:00
Case Type: TANK, RELEASE
Case Status: CLOSED
Release Occurrence Number: 001
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 02/09/1987 0:00:00
Lead Agency: Not reported

BROWN FIELD AIRPORT (Continued) 1000437555

Case Status Date: 05/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 011
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/14/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 10/23/1990 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 016
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 10/10/1990 0:00:00
Lead Agency: Not reported

Case Status Date: 03/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 002
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 03/17/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 03/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 003
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 03/17/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 03/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 004
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 03/17/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 05/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 006
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 03/17/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 05/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 007
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 03/17/1989 0:00:00
Lead Agency: Not reported

BROWN FIELD AIRPORT (Continued) 1000437555

Case Status Date: 05/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 008
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/14/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 05/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 009
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/14/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 05/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 010
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 04/14/1989 0:00:00
Lead Agency: Not reported

Case Status Date: 03/31/1989 0:00:00
Case Type: TANK, RELEASE
Case Status: OPEN
Release Occurrence Number: 005
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Date Release Began: 03/17/1989 0:00:00
Lead Agency: Not reported

Additional detail may be available for this site. Please contact your EDR Account Executive for more information

Facility ID: H28639
Inactive Indicator: Active
SIC: Not reported
Owner: ALC SANDALL, LLC

Mailing Address: SAN YSIDRO
CA
92173, 1708

Corporate Code: 20
Census Tract #: 10007
Inspection Date: 08/16/2001 0:00:00
Inspector Name: MCCULLOUGH
Facility Contact: GEORGE SUNDBERG
Property Owner: CITY OF SAN DIEGO
PO Address: SAN YSIDRO
CA
92173, 1708
Tank Owner: CITY OF SAN DIEGO
TO Address: SAN YSIDRO
CA
92173, 1708

Business Code: FUEL-DISPENSE NO REPAIR
Permit Expiration: 04/30
2nd Name: Not reported
Business Phone: (619)661-1121

Fire Dept District: SAN DIEGO FD
EPA ID: CAD981988587
Reinspection Date: 10/02
Gas Station: Not reported
Delinquent Flag: Not Delinquent

BROWN FIELD AIRPORT (Continued) 1000437555

Last Update: 09/28/2001 0:00:00
Last Delinquent Letter: Not reported
Last Letter Type: Not reported
Violation Notice Issued: Not reported
Map Code/Business Plan on File: Not reported
Business Plan Acceptance Date: 08/31/98
ReInspection Date Y2K Compatible: Oct 2002

HMMD DISCLOSURE INVENTORY:
Chemical Name: AVIATION GAS
Item Number: D002
Stored at 1 Time: 10000.00
Measurement Units: 0000300000
Storage Method: Not reported
Carcinogen: Yes
Annual Qty String: 0000010000
Quantity Stored At One Time: 8006-61-9
Annual Quantity String: 300000.00
Material Safety Data Sheet: A
1st Hazard Category: Not reported
2nd Hazard Category: FIRE HAZARD

Chemical Name: JET A; JET FUEL
Item Number: D001
Stored at 1 Time: 12000.00
Measurement Units: 0000300000
Storage Method: Not reported
Carcinogen: Yes
Annual Qty String: 0000012000
Quantity Stored At One Time: 8008-20-6
Annual Quantity String: 300000.00
Material Safety Data Sheet: A
1st Hazard Category: Not reported
2nd Hazard Category: FIRE HAZARD

HMMD UNDERGROUND TANKS:
Tank Number: T001
Tank ID Number: 1
Capacity (Gal): 12000.00
Tank Exempt: No
Waste or Product: Product
Tank Contents: AVIATION FUEL

Tank Number: T002
Tank ID Number: 2
Capacity (Gal): 12000.00
Tank Exempt: No
Waste or Product: Product
Tank Contents: JP4 JET FUEL

HMMD WASTE STREAMS:
Inspection Date: 08/16/2001 0:00:00
Waste Item #: W001
Waste Code: 331.00
Waste Name: OFF-SPEC,AGED,SURPLUS ORGANICS
Qnty at Inspection: 45.00
Annual Quantity: 90.00
Measurement Unit: GAL
Treatment Method: RECYCLE
Storage Method: METAL DRUMS 6-110 GALLONS
Waste Description: OFF SPEC AVGAS & JET FUEL
Haz Waste Hauler: ASBURY ENVIR. SERVICES
Carcinogen: No
Annual Qty String: 0000000090
Quantity String: 0000000045

HMMD VIOLATIONS:
Inspection Date: 06/02/2000 0:00:00
Occurrences: 01
Waste Code: Not reported
Type of Violation: GENERAL VIOLATION
Violation Description: HAZARDOUS WASTE CONTAINERS ARE MISSING LABELS, ACCUMULATION DATE AND/OR ARE IMPROPERLY LABELED CCR 66262.34

Inspection Date: 06/02/2000 0:00:00
Occurrences: 01

BROWN FIELD AIRPORT (Continued) 1000437555

Waste Code: Not reported
Type of Violation: GENERAL VIOLATION
Violation Description: HAZARDOUS MATERIALS HANDLER HAS NOT OBTAINED A VALID SAN DIEGO COUNTY HEALTH PERMIT.
SDCC 68.1105

HMMD ENVIRONMENTAL ASSESSMENT INFORMATION:
Case Status Date: Not reported
Case Type: Not reported
Case Status: Not reported
Release Occurrence Number: Not reported
Historical Name: Not reported
Date Release Began: Not reported
Lead Agency: Not reported

Additional detail may be available for this site. Please contact your EDR Account Executive for more information

UST HIST:

Facility ID:	28709		
Tank Num:	1	Container Num:	01
Tank Capacity:	550	Year Installed:	1981
Tank Used for:	PRODUCT		
Type of Fuel:	DIESEL	Tank Construction:	1 inches
Leak Detection:	Pressure Test		
Contact Name:	E.W. ALLEN	Telephone:	(619) 690-9369
Total Tanks:	1	Region:	STATE
Facility Type:	2	Other Type:	EMERG. GENERATOR

4
NW
1/2-1
3449
Higher

PIPER RANCH BUSINESS PARK LUST S104160603
6464 OTAY MESA RD Cortese N/A
CHULA VISTA, CA 92173

State LUST:

Cross Street:	Not reported		
Qty Leaked:	Not reported		
Case Number	9UT3356		
Reg Board:	San Diego Region		
Chemical:	Gasoline		
Lead Agency:	Local Agency		
Local Agency :	37000		
Case Type:	Soil only		
Status:	Signed off, remedial action completed or deemed unnecessary		
County:	San Diego		
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site		
Review Date:	Not reported	Confirm Leak:	Not reported
Workplan:	9/27/1994	Prelim Assess:	9/27/1994
Pollution Char:	Not reported	Remed Plan:	Not reported
Remed Action:	Not reported	Monitoring:	Not reported
Close Date:	2/21/1995		
Release Date:	9/24/1994		
Cleanup Fund Id :	Not reported		
Discover Date :	8/29/1988		
Enforcement Dt :	9/28/1994		
Enf Type:	Not reported		
Enter Date :	2/18/1997		
Funding:	Not reported		

PIPER RANCH BUSINESS PARK (Continued) **S104160603**

Staff Initials: RVR
How Discovered: Not reported
How Stopped: Not reported
Interim : Not reported
Leak Cause: Not reported
Leak Source: Not reported
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Priority: Low priority. Priority ranking can change over time.
Local Case # : H26521-002
Beneficial: MUN
Staff : CQC
GW Qualifies : Not reported
Max MTBE Soil : Not reported
Soil Qualifies : Not reported
Hydr Basin #: 911.12
Operator : Not reported
Oversight Prgm: Local Oversight Program UST
Oversight Prgm : LOP
Review Date : 2/18/1997
Stop Date : 9/24/1994
Work Suspended :Not reported
Responsible PartyTCW REALTY ADVISORS
RP Address: 865 S. FIGUERO ST 90017
Global Id: T0607302117
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 37673.189933615889774606945737
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

PIPER RANCH BUSINESS PARK (Continued) **S104160603**

LUST Region 9:

Case Number:	9UT3356	Release Date:	09/24/1994
Local Agency:	37000		
Substance:	8006619	Qty Leaked:	0
Date Found:	08/29/1988	How Found:	Not reported
Date Stopped:	09/24/1994	How Stopped:	Not reported
Source:	Not reported	Cause:	Not reported
Lead Agency:	Local Agency		
Status:	Signed off, remedial action completed or deemed unnecessary		
Case Type:	Soil only		
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site		
Confirm Date:	Not reported	Submit Workplan:	Not reported
Prelim Assess:	Not reported	Desc Pollution:	Not reported
Remed Plan:	Not reported	Remed Action:	Not reported
Began Monitor:	2/21/95	Closed Date:	2/21/95
Enforce Type:	SEL		
Enforce Date:	9/28/94		
Pilot Program:	LOP	Local Case:	H26521-002
Basin Number:	911.12	Gwater Depth:	Not reported
File Dispn:	Administratively opened on database, however no file physically exists		

Interim Remedial Actions: Not reported
Beneficial Use: MUN
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported
NPDES Number: Not reported

CORTESE:
Reg Id: 9UT3356
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

5
NW
1/2-1
3877
Higher

CORNER OF OTAY MESA & HERITAGE ROAD
SAN DIEGO, CA

Notify 65 **S100178041**
N/A

NOTIFY 65:
Date Reported: Not reported Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Incident Description: Not Reported

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
SAN DIEGO	S105003820	38TH AND QUINCE STREET BURNASH SITE	38TH STREET AND QUINCE		SWF/LF	37-CR-0114
SAN DIEGO	S105155685	MURPHY-SHEPARD CANYON LANDFILL	TB 46-A6		SWF/LF	
SAN DIEGO	S101669411	MURRAY CANYON BURNSITE	TB 53-D4 ADJ MURRAY RIDGE PK		SWF/LF	37-CR-0051
SAN DIEGO	S105155664	MURRAY RIDGE BURNSITE	TB 53-D4 ADJ MURRAY RIDGE PK		SWF/LF	
SAN DIEGO	S105155658	FAIRMOUNT BURNSITE	TB 60-C5 FAIRMONT/FEDERAL		SWF/LF	
SAN DIEGO	S105155672	SAN YSIDRO BURNSITE	TB 72-B6 OTAY MESA RD		SWF/LF	
SAN DIEGO	S105003819	SUNSHINE SUMMIT BURNSITE	35150 HWY 79		SWF/LF	37-CR-0112
SAN DIEGO	S105155662	MTS-PORT DISTRICT SITE	8TH-12TH ALONG HARBOR DR		SWF/LF	
SAN DIEGO	S100734157	KUSI TV MCKINNON BROADCASTING	12197 ROUTE 94		HAZNET	CAC001383040
SAN DIEGO	S102066317	S.H. PERLMUTTER	ADJ. TO OTAY LF		SWF/LF	37-CR-0058
SAN DIEGO	S105155683	OTAY TRUCK STOP	8490 AVENIDA DE LA FUENTA		SWF/LF	
SAN DIEGO	S105155681	MONTGOMERY DEMOLITION LANDFILL	3800 BLK CALLE FORTUNADA		SWF/LF	
SAN DIEGO	S105155663	MURRAY CANYON LANDFILL	2400 BLK ADMIRAL BAKER ROAD		SWF/LF	
SAN DIEGO	S105155575	BELL JR HIGH SLF/SWEETWATER II	7300 BLOCK PARADISE VALLEY RD		SWF/LF	37-CR-0088
SAN DIEGO	S105155659	KELLY STREET BURNSITE	5500 BLOCK KELLY ST		SWF/LF	
SAN DIEGO	S105155649	ARIZONA STREET SLF	SOUTH END OF ARIZONA STREET		SWF/LF	
SAN DIEGO	S102066290	FEDERAL BOULEVARD BURNSITE	FEDERAL BOULEVARD		SWF/LF	37-CR-0025
SAN DIEGO	S105155674	SD CONVENTION CENTER	HARBOR BLVD		SWF/LF	
SAN DIEGO	S100676406	SAN DIEGO INTERNAT'L AIRPORT	LINDBERGH-FIRE FIGHT.TEST AREA		Toxic Pits	
SAN DIEGO	S105155669	ROSE CANYON	NAS MIRAMAR		SWF/LF	
SAN DIEGO	S105155667	OLD MCRD REFUSE DISPOSAL/BURN AREA	NAVAL TRAINING CENTER		SWF/LF	
SAN DIEGO	S104384595	SWEETWATER UNION HS DIST/HS #12 PROPOSED	S. OF INTER. 905 / E. OF OTAY MESA RD.	92154	Cal-Sites	37010003
SAN DIEGO	S102066294	INS SHOOTING RANGE (CAYS)	8400 E. OF HERITAGE RD		SWF/LF	37-CR-0032
SAN DIEGO	S102066272	BALBOA PARK NURSERY	500' E OF NAVAL HOSPITAL / 400' S OF UPAS		SWF/LF	37-CR-0005
SAN DIEGO	S102066273	CITY FARM DUMP	1500' SOUTH OF PAC.HWY/LA JOLLACYN		SWF/LF	37-CR-0014
SAN DIEGO	S105155650	BALBOA PARK NURSERY	E OF NAVAL HOSPITAL		SWF/LF	
SAN DIEGO	S105155652	CAMP MATTHEWS	E OF JOHN J HOPKINS		SWF/LF	
SAN DIEGO	S105155658	INS SHOOTING RANGE (CAYS)	E. OF HERITAGE RD		SWF/LF	
SAN DIEGO	S103679463	COUNTY OF SAN DIEGO PUBLIC WORKS	OLD HWY 395 KEYES CANYON CREEK		HAZNET	CAC001236488
SAN DIEGO	S103770864	DENNERY RANCH	OTAY VALLEY ROAD / I-805	92154	Cal-Sites	37650001
SAN DIEGO	S105155653	CITY FARM DUMP	PAC. HWY/LA JOLLA CYN		SWF/LF	
SAN DIEGO	S105155676	SUBASE OLD REFUSE DISPOSAL	POINT LOMA NVL CMPLX		SWF/LF	
SAN DIEGO	S105155655	DEXTER CANYON DISPOSAL SITE	SAN VINCENT RESERVOIR		SWF/LF	
SAN DIEGO	S105155660	MISSION VALLEY DISPOSAL AREA	TEXAS ST/HWY 8		SWF/LF	
SAN DIEGO	S102066304	TOURMALINE BEACH BURNSITE	TOURMALINE ST		SWF/LF	37-CR-0080
SAN DIEGO	S105155678	TOURMALINE BEACH BURNSITE	TOURMALINE STREET		SWF/LF	
SAN DIEGO	S105155651	BALBOA PARK LANDFILL	UPAS/FLORIDA CANYON		SWF/LF	
SAN DIEGO	S105155670	SAN CLEMENTE CYN DISPOSAL SITE	VEGAS STREET		SWF/LF	
SAN DIEGO	S105155666	NELSON & SLOAN (CAYS)	WILLOW/CMNO DLA PLZA		SWF/LF	

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

NPL: National Priority List
Source: EPA
Telephone: N/A
National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/29/02
Date Made Active at EDR: 02/25/02
Database Release Frequency: Semi-Annually
Date of Data Arrival at EDR: 02/04/02
Elapsed ASTM days: 21
Date of Last EDR Contact: 02/04/02

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 6
Telephone: 214-655-6659

EPA Region 8
Telephone: 303-312-6774

Proposed NPL: Proposed National Priority List Sites
Source: EPA
Telephone: N/A

Date of Government Version: 01/17/02
Date Made Active at EDR: 02/25/02
Database Release Frequency: Semi-Annually
Date of Data Arrival at EDR: 02/04/02
Elapsed ASTM days: 21
Date of Last EDR Contact: 02/04/02

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System
Source: EPA
Telephone: 703-413-0223
CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/21/01
Date Made Active at EDR: 02/04/02
Database Release Frequency: Quarterly
Date of Data Arrival at EDR: 12/26/01
Elapsed ASTM days: 40
Date of Last EDR Contact: 12/26/01

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned
Source: EPA
Telephone: 703-413-0223
As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

Date of Government Version: 11/21/01
Date Made Active at EDR: 02/04/02
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 12/26/01
Elapsed ASTM days: 40
Date of Last EDR Contact: 12/16/01

CORRACTS: Corrective Action Report
Source: EPA
Telephone: 800-424-9346
CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 11/14/01
Date Made Active at EDR: 01/14/02
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 11/14/01
Elapsed ASTM days: 61
Date of Last EDR Contact: 03/11/02

RCRIS: Resource Conservation and Recovery Information System
Source: EPA/NTIS
Telephone: 800-424-9346
Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 06/21/00
Date Made Active at EDR: 07/31/00
Database Release Frequency: Varies

Date of Data Arrival at EDR: 07/10/00
Elapsed ASTM days: 21
Date of Last EDR Contact: 01/14/02

ERNS: Emergency Response Notification System
Source: EPA/NTIS
Telephone: 202-260-2342
Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 08/08/00
Date Made Active at EDR: 09/06/00
Database Release Frequency: Varies

Date of Data Arrival at EDR: 08/11/00
Elapsed ASTM days: 26
Date of Last EDR Contact: 02/01/02

FEDERAL ASTM SUPPLEMENTAL RECORDS

BRS: Biennial Reporting System
Source: EPA/NTIS
Telephone: 800-424-9346
The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/99
Database Release Frequency: Biennially

Date of Last EDR Contact: 03/18/02
Date of Next Scheduled EDR Contact: 06/17/02

CONSENT: Superfund (CERCLA) Consent Decrees
Source: EPA Regional Offices
Telephone: Varies
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: N/A
Database Release Frequency: Varies

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

ROD: Records Of Decision
Source: NTIS
Telephone: 703-416-0223
Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 09/30/00
Database Release Frequency: Annually

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

DELISTED NPL: National Priority List Deletions
Source: EPA
Telephone: N/A
The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/29/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/04/02
Date of Next Scheduled EDR Contact: 05/06/02

FINDS: Facility Index System/Facility Identification Initiative Program Summary Report
Source: EPA
Telephone: N/A
Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 10/29/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

HMIRS: Hazardous Materials Information Reporting System
Source: U.S. Department of Transportation
Telephone: 202-366-4526
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/30/01
Database Release Frequency: Annually

Date of Last EDR Contact: 01/21/02
Date of Next Scheduled EDR Contact: 04/22/02

MLTS: Material Licensing Tracking System
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/25/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

MINES: Mines Master Index File
Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959

Date of Government Version: 12/14/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/02/02
Date of Next Scheduled EDR Contact: 04/01/02

NPL LIENS: Federal Superfund Liens
Source: EPA
Telephone: 205-564-4267
Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 02/26/02
Date of Next Scheduled EDR Contact: 05/27/02

PADS: PCB Activity Database System
Source: EPA
Telephone: 202-260-3936
PCB Activity Database. PADS identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/30/01
Database Release Frequency: Annually

Date of Last EDR Contact: 02/12/02
Date of Next Scheduled EDR Contact: 05/13/02

RAATS: RCRA Administrative Action Tracking System
Source: EPA
Telephone: 202-564-4104
RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/95
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 03/11/02
Date of Next Scheduled EDR Contact: 06/10/02

TRIS: Toxic Chemical Release Inventory System
Source: EPA
Telephone: 202-260-1531
Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/99
Database Release Frequency: Annually

Date of Last EDR Contact: 12/26/01
Date of Next Scheduled EDR Contact: 03/25/02

TSCA: Toxic Substances Control Act
Source: EPA
Telephone: 202-260-5521
Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/98
Database Release Frequency: Every 4 Years

Date of Last EDR Contact: 01/22/02
Date of Next Scheduled EDR Contact: 04/22/02

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-564-2501
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/11/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 12/26/01
Date of Next Scheduled EDR Contact: 03/25/02

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
Source: EPA
Telephone: 202-564-2501

Date of Government Version: 01/14/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 12/26/01
Date of Next Scheduled EDR Contact: 03/25/02

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STATE OF CALIFORNIA ASTM STANDARD RECORDS

AWP: Annual Workplan Sites
Source: California Environmental Protection Agency
Telephone: 916-323-3400
Known Hazardous Waste Sites. California DTSC's Annual Workplan (AWP), formerly BEP, identifies known hazardous substance sites targeted for cleanup.

Date of Government Version: 11/08/00
Date Made Active at EDR: 03/02/01
Database Release Frequency: Annually

Date of Data Arrival at EDR: 01/31/01
Elapsed ASTM days: 30
Date of Last EDR Contact: 02/04/02

CAL-SITES: Calsites Database
Source: Department of Toxic Substance Control
Telephone: 916-323-3400
The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database.

Date of Government Version: 10/01/00
Date Made Active at EDR: 11/22/00
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 10/30/00
Elapsed ASTM days: 23
Date of Last EDR Contact: 01/07/02

CHMIRS: California Hazardous Material Incident Report System
Source: Office of Emergency Services
Telephone: 916-845-8400
California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 12/31/94
Date Made Active at EDR: 04/24/95
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 03/13/95
Elapsed ASTM days: 42
Date of Last EDR Contact: 03/01/02

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
Source: CAL EPA/Office of Emergency Information
Telephone: 916-445-6532
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 04/01/01
Date Made Active at EDR: 07/26/01
Database Release Frequency: Varies

Date of Data Arrival at EDR: 05/29/01
Elapsed ASTM days: 58
Date of Last EDR Contact: 01/28/02

NOTIFY 65: Proposition 65 Records
Source: State Water Resources Control Board
Telephone: 916-445-3846
Proposition 65 Notification Records. NOTIFY 65 contains facility notifications about any release which could impact drinking water and thereby expose the public to a potential health risk.

Date of Government Version: 10/21/93
Date Made Active at EDR: 11/19/93
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 11/01/93
Elapsed ASTM days: 18
Date of Last EDR Contact: 01/21/02

TOXIC PITS: Toxic Pits Cleanup Act Sites
Source: State Water Resources Control Board
Telephone: 916-227-4364
Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/95
Date Made Active at EDR: 09/26/95
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 08/30/95
Elapsed ASTM days: 27
Date of Last EDR Contact: 02/04/02

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

SWF/LF (SWIS): Solid Waste Information System
Source: Integrated Waste Management Board
Telephone: 916-341-6320
Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/17/01
Date Made Active at EDR: 01/15/02
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 12/17/01
Elapsed ASTM days: 29
Date of Last EDR Contact: 03/18/02

WMUDS/SWAT: Waste Management Unit Database
Source: State Water Resources Control Board
Telephone: 916-227-4448
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/00
Date Made Active at EDR: 05/10/00
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 04/10/00
Elapsed ASTM days: 30
Date of Last EDR Contact: 03/12/02

LUST: Leaking Underground Storage Tank Information System
Source: State Water Resources Control Board
Telephone: 916-341-5740
Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 01/17/02
Date Made Active at EDR: 02/12/02
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 01/21/02
Elapsed ASTM days: 22
Date of Last EDR Contact: 01/21/02

CA BOND EXP. PLAN: Bond Expenditure Plan
Source: Department of Health Services
Telephone: 916-255-2118
Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/89
Date Made Active at EDR: 08/02/94
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 07/27/94
Elapsed ASTM days: 6
Date of Last EDR Contact: 05/31/94

CA UST:

UST: Active UST Facilities
Source: SWRCB
Telephone: 916-341-5700
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 01/17/02
Date Made Active at EDR: 02/12/02
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 01/21/02
Elapsed ASTM days: 22
Date of Last EDR Contact: 01/21/02

CA FID UST: Facility Inventory Database
Source: California Environmental Protection Agency
Telephone: 916-445-6532
The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/94
Date Made Active at EDR: 09/29/95
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 09/05/95
Elapsed ASTM days: 24
Date of Last EDR Contact: 12/28/98

HIST UST: Hazardous Substance Storage Container Database
Source: State Water Resources Control Board
Telephone: 916-341-5700
The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/90
Date Made Active at EDR: 02/12/91
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 01/25/91
Elapsed ASTM days: 18
Date of Last EDR Contact: 07/26/01

STATE OF CALIFORNIA ASTM SUPPLEMENTAL RECORDS

AST: Aboveground Petroleum Storage Tank Facilities
Source: State Water Resources Control Board
Telephone: 916-227-4382
Registered Aboveground Storage Tanks.

Date of Government Version: 02/27/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/04/02
Date of Next Scheduled EDR Contact: 05/06/02

CLEANERS: Cleaner Facilities
Source: Department of Toxic Substance Control
Telephone: 916-225-0873
A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 07/27/01
Database Release Frequency: Annually

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

CA WDS: Waste Discharge System
Source: State Water Resources Control Board
Telephone: 916-657-1571
Sites which have been issued waste discharge requirements.

Date of Government Version: 07/19/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/19/02
Date of Next Scheduled EDR Contact: 06/24/02

DEED: List of Deed Restrictions
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes.

Date of Government Version: 02/11/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/19/02
Date of Next Scheduled EDR Contact: 04/08/02

HAZNET: Hazardous Waste Information System
Source: California Environmental Protection Agency
Telephone: 916-255-1136
Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method.

Date of Government Version: 12/31/00
Database Release Frequency: Annually

Date of Last EDR Contact: 02/12/02
Date of Next Scheduled EDR Contact: 05/13/02

LOCAL RECORDS

ALAMEDA COUNTY:

Local Oversight Program Listing of UGT Cleanup Sites
Source: Alameda County Environmental Health Services
Telephone: 510-567-6700

Date of Government Version: 07/01/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/28/02
Date of Next Scheduled EDR Contact: 04/29/02

Underground Tanks
Source: Alameda County Environmental Health Services
Telephone: 510-567-6700

Date of Government Version: 12/01/00
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/28/02
Date of Next Scheduled EDR Contact: 04/29/02

CONTRA COSTA COUNTY:

Site List
Source: Contra Costa Health Services Department
Telephone: 925-646-2286
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 09/01/00
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 03/04/02
Date of Next Scheduled EDR Contact: 06/03/02

FRESNO COUNTY:

CUPA Resources List
Source: Dept. of Community Health
Telephone: 559-445-3271
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 01/02/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/12/02
Date of Next Scheduled EDR Contact: 05/13/02

KERN COUNTY:

Underground Storage Tank Sites & Tanks Listing
Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Kern County Sites and Tanks Listing.

Date of Government Version: 12/20/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/04/02
Date of Next Scheduled EDR Contact: 06/03/02

APPENDIX D

INTERVIEW DOCUMENTATION

BCS Produce Company, Inc.
Phase 1 - (1877-001) Phone Notes
by Melissa Novak

Date	Phone # and Contact	Notes
4/4/02	SD County Assessor's Office 236-3771	Legal Description: "Exc rds south 1/2 of west 1/2 of northeast 1/4 of Section 33, Township 18, Range 1W. Current Owner: Curtis J. Corn - 4429 Loma Paseo, Bonita, CA 91902
	Curtis Corn- 479-7390	He said that he believes he has owned the property since 1979. (During my site visit I ask a resident at one of the western, adjacent properties (1938 Cactus Rd) how long she had lived there. She said since 1972 and that the property to the south of her's (1942 Cactus Rd) had been different businesses since she had lived there. The last she said was some sort of automobile sales business.) I asked if the western residences were there ar far as he remembers. He said yes, that they were built before he bought the property. I asked if he remembers there ever being buildings on the property adjacent to the south - just across Airway Road. He said no, that it had always been agricultural. I asked if he remembers a "R&R AG (Agriculture?) Chemical company near where the recycling center is? He said that they sold fertilizer.
4/8/02	Connie Flagg - 619-533-4466 "Fire Prevention"	Maricela Barba no longer does Env Assessments. She transferred me to Connie Flagg. I asked if they were able to research a property without an address - agricultural props. She said that it would be good to include a copy of Thomas Bros intersection highlighted.
	Hal Larsen - SDGE Tranformers 858-650-4133	Doesn't do PCB info anymore. Gave me another number but it was out of service. I called him back to try to get any other info he may have, he said he would call me back. He called back and said there was a fellow, Jeff Harris, at the Special investigations desk that could probably help.
4/9/02	Jeff Harris - SDGE 858-636-7500	(Returned my call from yesterday.) He said that they have a general letter they send out that basically says there are basically no transformers with PCBs any more and that if we wanted to have them tested it would cost money. I asked him to fax and mail the letter.

APPENDIX E

PHOTOGRAPHIC DOCUMENTATION



Photo 1: Subject site looking southwest (Intersection of Cactus & Airway Roads).



Photo 2: Subject site looking north-towards Brown Field Municipal Airport.

Project Name: BCS Produce Co. Inc. Project No.: 02-01877-001



Photo 3: Small amount of construction debris along the southern perimeter of the subject site.



Photo 4: Cactus Recycling adjacent to the north of the subject site.

Project Name: BCS Produce Co. Inc. Project No.: 02-01877-001



Photo 5: Agricultural land adjacent to the north of the subject site.



Photo 6: Agricultural land adjacent to the east of the subject site.



Photo 7: Agricultural land adjacent to the south of the subject site; note, Small amount of debris along perimeter.



Photo 8: Agricultural land adjacent to the west of the subject site.



Photo 9: Single Family residences adjacent to the west of the subject site.

APPENDIX F

ENECOTECH RESUMES

Terry Farley, REA
Project Scientist

EDUCATION	M. S. Environmental Management, West Coast University B. S. Wildlife Management, University of Minnesota
EXPERIENCE	14 years
CERTIFICATIONS	Registered Environmental Assessor, California OSHA 40-hour HAZWOPER AHERA – Asbestos Building Inspector

WORK HISTORY		
	EnecoTech Southwest, Inc.	Project Scientist
	Project Resources Inc.	Project Engineer
	County of San Diego	Insect Detection Specialist
	National Marine Fisheries Service	Biological Technician

QUALIFICATIONS SUMMARY

Mr. Farley has experience in managing and performing a variety of environmental projects including site assessments and site investigations. In addition to fieldwork, Mr. Farley has experience in costing, budgeting, interaction with regulatory agencies, and preparing proposals, corrective action plans, and work plans.

Additional professional experience includes Phase I Site Assessments, Environmental Baseline Surveys (ASTM 6008), Physical Needs Assessments, and Phase II Subsurface Investigations, identification of agricultural pests, public contact, and technical writing. His experience also includes performing marine mammal population assessments; food habit studies and monitoring marine mammal involvement in commercial fishing operations; and, natural resources management (fisheries, wildlife, botany, mapping).

PROJECT EXPERIENCE

As Project Scientist, Mr. Farley is project manager for several sites throughout Southern California ensuring regulatory compliance, scheduling of monitoring activities, preparation and submittal of work plans, proposals, corrective action plans, and engaging subcontractors.

Mr. Farley has collected soil and groundwater samples, installed monitoring wells, completed boring logs, retrieved soil and groundwater samples for submittal under standard chain of custody procedures, reviewed laboratory analysis, and submitted reports to regulatory agencies.

He is program manager for environmental, health, and safety audits and training at various sites. Audits have included compliance with environmental regulations and health and safety codes. Training has included environmental compliance, personal protective equipment (PPE), fire safety, respirator fit tests, and forklift operations.

Mr. Farley manages all Phase I Environmental Site Assessments for the San Diego office including proposals, scheduling, review, and oftentimes follow up. Phase I's are performed in compliance with ASTM E1527-00 guidelines and individual client requirements.

Mr. Farley has performed Limited Phase II subsurface investigations of dry cleaning, gas station, and other operations. He served as project coordinator for site visits with onsite personnel and subcontractors, production of health and safety plans, sampling protocols and chain of custody procedures, collection and logging of samples, submittal of samples to certified laboratory for analysis, identification of soil characteristics, and analysis of laboratory results. Mr. Farley has presented results and recommended additional sampling and characterization of the site, when indicated.

Performed a phase I environmental assessment of manufacturing facility with on-going remedial activities due to groundwater contamination with PCE and TCE, from an unknown source. Reviewed groundwater monitoring results, corrective action plan, remedial activities, and historic information. Interviewed consultant and regulatory agencies.

PUBLICATION

Geographic Variation in Dorsal Fin Color Pattern of Common Dolphins (*Delphinus Delphis*). National Marine Fisheries Service (LJ-95-002)

Melissa Novak
Staff Scientist

EDUCATION

M. S. Environmental Management, National University, San Diego, California
Extended Studies – Environmental Regulation Compliance (Federal and CA State), Environmental Economics, UST and AST, Chemical Analysis, Hazardous Materials Business Plans, CalARP, DOT CFR Title 49, CalOSHA CCR Title 8, Emergency Action Plans
B. S. Computer Science, National University, San Diego, California
Extended Studies – Systems design and analysis, Programming in C, C++ and Visual Basic, Windows NT, 3.x, 95, 98, and MSDOS operating systems, Microsoft Office 97, also Visio and PowerPoint layouts
A. S. Technical Illustration, San Diego City College, San Diego, California
Extended Studies – Engineering Drafting, Architectural Design, Graphic Art

TRAINING

OSHA 40-Hour HAZWOPER Training
BNSF Railroad Safety Training

WORK HISTORY

EnecoTech Southwest, Inc.	Staff Scientist
	Safety Committee Chairperson
Continental DataGraphics	Systems Analyst, Sr. Data Analyst

QUALIFICATIONS SUMMARY

Melissa Novak has experience that ranges from Hazardous Materials compliance issues to Health and Safety projects. Her abilities include developing business plans, emergency action plans, and site inspections. Using OSHA guidelines, she has conducted building inspections and implemented compliance corrective actions in a cost effective manner.

PROJECT EXPERIENCE

Project overseeing of monitoring well installations. Monitoring wells were established for petroleum waste product sampling and testing. Overseeing tasks include permit processing, site assessment deciphering, contractor coordination, and regulatory agency correspondence.

Development of Integrated Compliance Plans that include Emergency Response procedures, Hazardous Materials handling and safety, and Site History reports.

Project responsibilities include completing California State UST Fund Applications and Reimbursement Requests that involve spreadsheet analysis and research into agency authorization of clean up projects. Direct communications with clients and government representatives to investigate clean up procedure methods and approvals.



Phase I Environmental Site Assessment

Paez Property (APN 646-100-77-00)
Airway Road and Cactus Road
San Diego, California 92154

July 8, 2022

Prepared for:
SARE Investments, LLC
c/o ColRich
444 W. Beech Street, Suite 300
San Diego, CA 92101

Prepared by:

1042 Skylark Drive
La Jolla, CA 92037
(858) 945-7029
www.cyaforensics.com

C YOUNG ASSOCIATES
1042 Skylark Drive
La Jolla, CA 92037
(858) 945-7029
www.cyaforensics.com

July 8, 2022

Jason Shepard
SARE Investments, LLC
c/o ColRich
444 W. Beech Street, Suite 300
San Diego, CA 92101


Subject: Phase I Environmental Site Assessment
Paez Property (APN 646-100-77-00)
Airway Road and Cactus Road
San Diego, California 92154

Dear Mr. Shepard:

C Young Associates has completed the contracted environmental consulting services for the above referenced project. The services were performed in accordance with our proposal and agreement for this assignment. The Phase I Environmental Site Assessment has been performed in accordance with ASTM International (ASTM) Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM Designation E1527-13 and Title 40 of the Code of Federal Regulations (40 CFR) Part 312. Soil sampling and analysis was also completed concurrently with this Phase I ESA. We appreciate the opportunity to be of service to you on this project. Please contact us if you have any questions or comments regarding this report or if we can be of further assistance.

Sincerely,

C Young Associates



Colin P. Young, CIH
Principal



Daniel Weis, R.E.H.S. - Associate Environmental Scientist

TABLE OF CONTENTS

1.0 INTRODUCTION 1

1.1 Purpose 1
1.2 Scope of the Assessment 1
1.3 Limitations and Exceptions 2
1.4 Special Terms and Conditions 3
1.5 Limiting Conditions and Deviations 3
1.6 Data Failure and Data Gaps 3
1.7 Reliance 3

2.0 SITE DESCRIPTION 5

2.1 Location and Legal Description 5
2.2 Site and Vicinity Characteristics 5
2.3 Current Use of the Site 5
2.4 Description of Site Improvements 5
2.5 Utilities 5
2.6 Description of Adjoining Properties 6
2.7 Summary Relative to Environmental Concerns 6

3.0 PHYSICAL SETTING 7

3.1 Topography 7
3.2 Hydrology 7
3.3 Geology 7
3.4 Hydrogeology 8
3.5 Oil and Gas Exploration 8
3.6 Summary Relative to Environmental Concerns 8

4.0 USER PROVIDED INFORMATION 9

4.1 Title Records 9
4.2 Environmental Liens 9
4.3 Activity and Use Limitations 9
4.4 Specialized or Actual Knowledge or Experience 9
4.5 Commonly Known or Reasonably Ascertainable Information 9
4.6 Valuation Reduction for Environmental Issues 10
4.7 Owner, Property Manager, and Occupant Information 10
4.8 Reason for Performing Phase I ESA 10
4.9 Proceedings Involving the Site 10
4.10 Other Provided Documents 10
4.11 Summary Relative to Environmental Concerns 10

5.0 REGULATORY RECORDS REVIEW 11

5.1 Standard ASTM Regulatory Database Search 11
5.2 Non-ASTM Regulatory Database Search 14
5.3 Regulatory Agency File Reviews 14
5.4 Summary Relative to Environmental Concerns 15

6.0 HISTORICAL RESOURCE REVIEW 16
6.1 Aerial Photographs 16
6.2 Topographic Maps 16
6.3 Other Historical Sources 17
6.4 Summary Relative to Environmental Concerns 17
7.0 SITE RECONAISSANCE 18
7.1 Methodology and Limiting Conditions 18
7.2 Current General Site and Vicinity Characteristics 18
7.3 Indications of Past Site and Vicinity Uses 18
7.4 Site-Specific Observations 18
7.5 Summary Relative to Environmental Concerns 19
8.0 INTERVIEWS 20
8.1 Site Owner 20
8.2 Key Site Manager 20
8.3 Current Occupants 20
8.4 Local Government Official 20
8.5 Other Parties 20
8.6 Summary Relative to Environmental Concerns 20
9.0 ADDITIONAL SERVICES – NON-SCOPE ASTM CONSIDERATIONS 21
10.0 FINDINGS AND OPINIONS 23
11.0 CONCLUSIONS AND RECOMMENDATIONS 24
12.0 ENVIRONMENTAL PROFESSIONAL STATEMENT 25
13.0 ASSUMPTIONS 26
14.0 DEFINITIONS 27
15.0 REFERENCES 29
15.1 Documents, Plans and Reports 29
15.2 Personal Communications 29
15.3 Agencies Consulted 29

FIGURES

Figure 1 Vicinity Map
Figure 2 Topographic Map
Figure 3 Site Plan

APPENDICES

Appendix A Regulatory Database Report
Appendix B Historical Resources
Appendix C Photographs
Appendix D Environmental Questionnaires
Appendix E Soil Sample Locations and Analytical Laboratory Report
Appendix F Qualifications

1.0 INTRODUCTION

This report presents the methods and findings of a Phase I Environmental Site Assessment (Phase I ESA) of the Paez property located on the north side of Airway Road between Cactus Road and Continental Street in the community of Otay Mesa, City of San Diego, California (Site). This Phase I ESA was performed in conformance with the contract/agreement for this assignment and the scope and limitations of ASTM Standard Practice E1527-13 and U.S. Environmental Protection Agency (EPA) Standards and Practices for All Appropriate Inquiries (AAI) as published in Title 40 of the Code of Federal Regulations Part 312 (40 CFR 312). EPA promulgated the AAI rule that became effective in November 2006 and has indicated that the ASTM E1527 practice is consistent with the requirements of AAI and may be used to comply with the provisions of the AAI rule. Soil sampling and analysis has also been completed concurrently with this Phase I ESA due to the historical agricultural activity of the Site.

1.1 Purpose

The purpose of the ASTM E1527 practice (framework for this Phase I ESA) is to define good commercial and customary practice in the U.S. for conducting a Phase I ESA of a parcel of real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA, Title 42 U.S. Code [42 U.S.C.] Section 9601) and petroleum products. As such, this practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA liability (hereinafter, the "landowner liability protections," or "LLPs"); i.e., the practice that constitutes AAI's into the previous ownership and uses of a property consistent with good commercial and customary practice as defined in 42 U.S.C. Section 9601(35)(B).

In defining a standard of good commercial and customary practice for conducting this Phase I ESA, the goal of the processes established by the ASTM E1527 practice is to identify, to the extent feasible, *recognized environmental conditions*. The term "recognized environmental conditions" is defined as the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment, or; (3) under conditions that pose a material threat of a future release to the environment. In addition, *controlled recognized environmental conditions*, *historical recognized environmental conditions* and/or *de minimis conditions*, if identified during the completion of the assessment, are discussed herein. Definitions of these terms and other key terminology relevant to the practice are included in Section 14.0 of this report.

1.2 Scope of the Assessment

In general terms, this Phase I ESA included the acquisition of readily available/accessible and practically reviewable regulatory records and historical information, a site reconnaissance, interviews and preparation of this written report of findings. A more

detailed description of the four primary components of the Phase I ESA is presented below.

Records Review - A review of Federal, State, Tribal, and local standard ASTM and non-ASTM regulatory databases for a myriad of environmental identifiers including, but not limited to: properties with underground storage tanks (USTs); properties with leaking USTs; properties that have reported spills/releases that did not occur from a leaking UST, and; businesses that utilize hazardous materials and/or generate hazardous waste and hazardous waste disposal locations. The regulatory review may also include public records requests with one or more Federal, State, Tribal and/or local agencies. A review of historical sources is also completed to help ascertain previous land uses of the property in question and in the surrounding area.

Site Reconnaissance - A Site inspection and viewing of adjacent and surrounding properties for conditions that could be "recognized environmental conditions."

Interviews - Interviews with present and past owners, operators and/or occupants of a property and local government officials.

Reporting - Evaluation of the information gathered during the completion of the Phase I ESA and the subsequent preparation of a written report. As stated previously, soil sampling and analysis has also been completed concurrent with this Phase I ESA. The sampling work was completed in accordance with the California Department of Toxic Substances Control's (DTSC) Interim Guidance for Sampling Agricultural Properties (Third Revision).

1.3 Limitations and Exceptions

Concerns regarding liability under the CERCLA and analogous State laws have been a primary driver for Phase I ESA assignments in commercial real estate transactions. While the ASTM E1527 practice can be used in many contexts, a familiarity with CERCLA and its potential LLPs is critical in understanding and applying the ASTM E1527 practice. We advise consultation with legal counsel if further inquiry or information is desired.

AAI represents the minimum level of inquiry necessary to support the LLPs. However, it is important to understand that additional inquiry ultimately may be necessary or desirable for legal as well as business reasons depending upon the outcome of this inquiry and the particular risk tolerances of a given user. For example, additional inquiry may assist a user of a Phase I ESA in determining whether he or she would have continuing obligations in the event he or she acquires a given property and may also assist the user in defining the scope of future steps to be taken to satisfy such obligations. In addition, a user may be concerned about business environmental risks or non-scope ASTM considerations that do not fall within the definition of a "recognized environmental condition." In addition, this Phase I ESA did not include subsurface or other invasive exploration. Users are also cautioned that Federal, State, Tribal and local laws may impose environmental assessment obligations that are beyond the scope of the ASTM E1527 practice.

The evaluation, opinion and conclusions presented herein are based solely on visual observations and regulatory, historical and personal knowledge related information that existed at the time our assessment was completed. The use of the gathered information

is exclusively for the purposes outlined in this report and only for the Site. Our firm can make no warranty, express or implied, except that the services conducted were performed in accordance with generally accepted environmental assessment practices applicable at the time and location of the assessment and that the conclusions of the assessment have been based in part on professional judgment/experience, an interpretation of readily available data and the standard of care normally followed by similar professionals practicing in a similar locale and under similar circumstances. Any opinions presented cannot apply to Site changes of which our firm is unaware and has not had the opportunity to evaluate. In addition, this report cannot feasibly include any evaluation of undocumented activities at the Site or on adjacent or nearby properties. Lastly, a Phase I ESA meeting or exceeding this practice and completed less than 180 days prior to the date of an acquisition or completed transaction is presumed to be valid.

1.4 Special Terms and Conditions

This Phase I ESA was prepared in accordance with the terms and conditions of the contract/agreement for the work as executed between our firm and the client to whom this report is addressed. There are no other special terms and conditions established between our firm and the client pertinent to the findings of this Phase I ESA or methodology used to complete this Phase I ESA. In addition, our firm has no final or other vested interest in the Site or adjacent/surrounding properties, or in any entity that owns or occupies the Site or adjacent/surrounding properties.

1.5 Limiting Conditions and Deviations

There were no significant limiting conditions that would inhibit our ability to identify "recognized environmental conditions" noted during the completion of this Phase I ESA. In addition, there were no deviations from the ASTM E1527 standard noted during the completion of this Phase I ESA. Any limiting conditions that are not considered to be ones that would inhibit our ability to identify "recognized environmental conditions" at the Site are referenced in applicable sections of this report.

1.6 Data Failure and Data Gaps

No instances of data failure were encountered during the completion of this Phase I ESA. In addition, no data gaps of significance (i.e., those that would inhibit our ability to identify "recognized environmental conditions") were identified during the completion of this Phase I ESA. Any data gaps that are not considered to be ones that would inhibit our ability to identify "recognized environmental conditions" at the Site are referenced in applicable sections of this report.

1.7 Reliance

This report has been prepared for the exclusive use of the client to which our firm has contracted with to complete this Phase I ESA. This report may not be relied upon by any other person or entity without the written consent of both our firm and our client. The scope of services performed for this Phase I ESA may not be appropriate to satisfy the specific needs of other users, and any use or reuse of this document would be at the sole

risk of said users. Any other party seeking liability protection under CERCLA must take independent action to accomplish its objective.

2.0 SITE DESCRIPTION

2.1 Location and Legal Description

The Site has no reported physical address and is identified by San Diego County Assessor's Parcel Number (APN) 646-100-77-00. The Site comprises 40 acres and is located adjacent to and north of Airway Road, east of Cactus Road, west of Continental Street and south of the Otay Mesa Freeway (State Route 905). A Vicinity Map is included as Figure 1. A Site Plan is included as Figure 2.

2.2 Site and Vicinity Characteristics

The Site and the surrounding vicinity are situated in an area of the community of Otay Mesa that consists primarily of vacant land, agricultural land, new development and commercial development with some scattered residences and public roadways. Additional details pertaining to the Site and its adjoining properties are provided in the sections below.

2.3 Current Use of the Site

The Site is presently vacant and undeveloped tilled land.

2.4 Description of Site Improvements

There are no habitable improvements present at the Site. It is possible that remnants of former utility systems or other subsurface features associated with historical agricultural activities are present.

2.5 Utilities

Utilities that provide service in the surrounding area are noted below along with their municipal provider where applicable. If certain utility systems are not provided by public agencies or entities, they are noted as privately maintained.

Utility	Provider (Where Applicable)
Potable Water	Otay Water District
Sewage Maintenance	Otay Water District
Electrical	San Diego Gas and Electric
Natural Gas	San Diego Gas and Electric
Solid Waste Disposal	City of San Diego

2.6 Description of Adjoining Properties

Adjoining properties are defined as any real property or properties, the border of which is contiguous or partially contiguous with that of the subject Site or that would be contiguous or partially contiguous with the subject Site but for a street, road, or other public thoroughfare separating them. To the extent feasible, our firm performed a visual inspection of adjoining properties from the Site boundaries and along public right of ways. We did not encroach onto adjoining private property during the completion of this Phase I ESA. The following table identifies the adjoining property uses:

Direction	Adjoining Property Use
North	State Route 905 and related highway easements
South	Airway Road and vacant land
East	Residential properties currently under construction
West	Cactus Road then vacant graded land (future EPOCA/Lumina development), a residential property and a junkyard

2.7 Summary Relative to Environmental Concerns

No “recognized environmental conditions” in connection with the land use of, and improvements at, the Site are noted. In addition, the land uses of adjoining properties and properties in the vicinity of the Site do not represent “recognized environmental conditions” that are of direct environmental concern to the Site.

3.0 PHYSICAL SETTING

3.1 Topography

The Site is depicted on the U.S. Geological Survey (USGS) topographic map for the Otay Mesa, California 7.5-minute quadrangle (1996). The Site is shown on the map as being situated at an elevation of approximately 500 feet above mean sea level (msl). The Site is relatively flat and level. Adjoining and surrounding roadways are depicted on the map. A Topographic Map is included as Figure 3.

3.2 Hydrology

According to the Water Quality Control Plan for the San Diego Basin (Region 9), published by the California Regional Water Quality Control Board, the Site is situated within the Otay or Tijuana Hydrologic Unit. A portion of a drainage is present in the northern area of the Site. Significant infiltration of precipitation can be expected at the Site due to its unimproved nature. Any excess surface water would appear to flow as surface runoff to surrounding areas of lower elevation. The Site does not appear to receive significant drainage from off-Site properties.

3.3 Geology

General geologic information pertaining to the Site is presented in the table below.

Geologic Consideration	Details
California Geomorphic Province	Peninsular Ranges
Mapped Soils or Formation	Alluvium, Pleistocene marine and non-marine terrace deposits and the Otay Formation
Description of Soils or Formation	Alluvium - poorly consolidated clay, silt, sand, and gravel Terrace deposits - Thick, stiff, moist, dark brown to olive silty or sandy clay and dense to very dense interbedded reddish brown sandy course gravel and gravelly sands with some silt and clay and interbedded massive cobble layers Otay Formation - Dense to very dense, light olive to gray-brown, interbedded clayey siltstones and silty fine-grained sandstones The Site is also underlain by varying amounts of compacted fill material placed during recent grading activities and derived by the soils noted above.
Distance/Direction to Mapped Faults	No known faults are mapped on the Site. Please refer to the project geotechnical report for additional information

3.4 Hydrogeology

General hydrogeologic information pertaining to the Site is presented in the table below.

Hydrogeologic Consideration	Details
Groundwater Basin or Unit	Otay or Tijuana Hydrologic Unit
Beneficial Uses	Municipal, agricultural and industrial supply purposes
Estimated Depth to Groundwater	Estimated at greater than 100 feet
Estimated Flow of Groundwater	West to southwest
Known Site or Regional Groundwater Contamination Issues	None reported

3.5 Oil and Gas Exploration

According to online resources provided by the California Department of Conservation, Geologic Energy Management Division, there are no oil, gas or geothermal wells located on the Site or its adjacent properties.

3.6 Summary Relative to Environmental Concerns

No “recognized environmental conditions” associated with Site *Physical Setting* considerations are noted. In addition, *Physical Setting* considerations related to the adjoining properties and properties in the vicinity of the Site do not represent “recognized environmental conditions” that are of direct environmental concern to the Site.

4.0 USER PROVIDED INFORMATION

The user of this report (ColRich) was interviewed during the completion of this Phase I ESA. The questions posed during the interview are defined by the ASTM E1527 practice. The client also provided our firm with any land title records and judicial records that may be available for the Site as part of the required evaluation for environmental liens and activity and use limitations (AULs) in connection with the subject property of a Phase I ESA. As stated in the ASTM E1527 practice, it is the responsibility of the user of the report to provide any available records pertaining to environmental liens and AULs that may exist in connection with a given property. Any land title and judicial recorded provided to our firm are discussed below. If such information is not discussed in the sections below, it was not provided by the user of the report.

In addition to the contact information obtained, the user of the report was also asked if they are aware of other useful documents that may exist and if so whether copies can be provided to the environmental professional within reasonable time and cost constraints. A list of typical useful documents is included in Section 10.8.1 of the ASTM E1527 practice and include but are not limited to environmental assessment reports, compliance audits and permits, registrations for tank and other aboveground or underground systems, safety plans, spill prevention and other facility related plans and geological/geotechnical studies and environmental governmental agency notices and/or correspondence.

4.1 Title Records

Our firm was provided with a preliminary title report for the Site prepared by First American Title Company, dated May 20, 2022. No environmentally related liens, deed restrictions or activity and use limitations pertaining to the Site were noted in the title report.

4.2 Environmental Liens

The client is unaware of environmental liens in connection with the Site.

4.3 Activity and Use Limitations

The client is unaware of AULs in connection with the Site.

4.4 Specialized or Actual Knowledge or Experience

The client is unaware of specialized knowledge, actual knowledge or experience that is material to “recognized environmental conditions” in connection with the Site.

4.5 Commonly Known or Reasonably Ascertainable Information

The client is unaware of commonly known or reasonably ascertainable information within the local community that is material to “recognized environmental conditions” in connection with the Site.

4.6 Valuation Reduction for Environmental Issues

The client is unaware of information pertaining to an undervalued purchase price of the Site relative to the estimated fair market value of the Site due to the presence of contamination.

4.7 Owner, Property Manager, and Occupant Information

The Site is currently owned and managed by Joseph Paez, Jr. The Site is currently vacant with no known occupants.

4.8 Reason for Performing Phase I ESA

The client has commissioned this Phase I ESA as part of a proposed purchase and future development of the Site. The Phase I ESA is also being completed to assist the client in complying with 40 CFR 312.

4.9 Proceedings Involving the Site

The client is unaware of pending, threatened, or past litigation and administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the Site. The client is also unaware of notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products in connection with the Site.

4.10 Other Provided Documents

No prior environmental reports pertaining to the Site were provided to CYA.

4.11 Summary Relative to Environmental Concerns

No “recognized environmental conditions” associated with the *User Provided Information* are noted.

5.0 REGULATORY RECORDS REVIEW

Our firm commissioned the preparation of a regulatory database report from Environmental Risk Information Services (ERIS) as part of the regulatory records review. ERIS searches a myriad of Federal, State and local government environmental databases during the preparation of their deliverables. Certain databases are specifically required by the ASTM E1527 practice and are referenced as "standard ASTM regulatory databases." Such databases are searched to at least the minimum search distance around a given property or properties as defined in the practice. Other regulatory databases are also searched that are not specifically referenced in ASTM E1527. Such databases are referenced as "non-ASTM regulatory databases" and are searched as varying radii around a given property as selected by ERIS.

Descriptions of each database searched and the dates that the regulatory databases were last updated by the applicable agencies are included in the ERIS report. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of an updates. ERIS updates databases in accordance with ASTM E1527 which states that government information from non-governmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public.

Our firm also reviewed unplottable sites listed in the database report by cross-referencing reasonably ascertainable information pertaining to such properties that may include facility names, street names, zip codes or other information. Unplottable sites are ones that cannot be formally mapped or geocoded due to various reasons, including limited geographic information. Any unplottable sites that we identify within the specified search radii have been evaluated as part of the preparation of this report. A copy of the regulatory database report is included in Appendix A.

5.1 Standard ASTM Regulatory Database Search

The tables below present the standard Federal, State, Tribal and local ASTM databases that were searched by ERIS including the search distances from the Site. Below the tables are descriptions of any listings for the Site that may appear in the databases. In addition, a discussion of adjoining properties or properties in the Site vicinity that are listed in one or more regulatory databases that in our professional judgment and opinion have the potential to adversely impact the Site due to current or former releases of hazardous substances and/or petroleum products that occurred at said properties is presented. This practice of discussing only properties of potential environmental concern to the Site is noted in ASTM E1527 which states that the environmental professional may make statements applicable to multiple properties listed in regulatory databases that are not likely to have current or former releases of hazardous substances and/or petroleum products with the potential to migrate to the a given subject property. Our professional judgment and opinions discussed herein are based on several factors including the nature of the regulatory database listings, distance of the off-Site listed properties from the Site,

orientation of the listed properties relative to the Site, interpreted the direction of groundwater flow and/or regulatory case status information for the various properties as described in the databases.

The following Federal standard ASTM databases were searched:

Standard Environmental Record Source Name	ERIS Regulatory Database Identification	Search Distance From Site (Miles)
National Priorities List (NPL) Site List	NPL – Proposed NPL – Superfund Record of Decision (ROD)	1.0
Delisted NPL Site List	Deleted NPL	0.5
Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) List	CERCLIS - SEMS – SEMS Archive – ODI – IODI – CERCLIS LIENS – SEMS LIENS	0.5
CERCLIS List	CERCLIS LIENS – SEMS LIENS	Site
CERCLIS No Further Remedial Action Planned (NFRAP) Site List	CERCLIS NFRAP	0.5
Resource Conservation and Recovery Act (RCRA) Corrective Action Sites (CORRACTS) Facilities List	RCRA CORRACTS	1.0
RCRA Non-CORRACTS Treatment, Storage and Disposal (TSD) Facilities List	RCRA TSD	0.5
RCRA Generators List	RCRA LQG – RCRA SQG – RCRA CESQG – RCRA NON-GEN – BULK TERMINAL – REFN – FEMA Underground Storage Tank (UST)	0.25
Institutional Control/Engineering Control Registries	FED ENG – FED INST – FED Brownfields	0.5
Emergency Response Notification System (ERNS) List	ERNS – ERNS 1982 to 1986 – ERNS 1987 to 1989	Site

Site – The Site is not listed on any of the standard Federal ASTM regulatory databases.

Adjoining Properties – Two adjoining properties are listed on the RCRA Non-Gen standard Federal ASTM regulatory database. The properties are identified as Yvette Alcaraz (1942 Cactus Road and adjoining to the west) and Dantzlet & Barnhart Properties/Charles Tatum (1812 Cactus Road and adjoining to the west-northwest). Both properties have no reported violations or reports of releases in the database listings. These properties are not considered to have the potential to adversely impact the Site.

Other Properties – There are multiple listings mapped in the surrounding area on the Federal databases. These properties are not considered to have the potential to adversely impact the Site.

The following State, Tribal and local standard ASTM databases were searched:

Standard Environmental Record Sources Name	ERIS Regulatory Database Identification	Search Distance From Site (Miles)
Equivalent NPL	RESPONSE	1.0
Equivalent CERCLIS	ENVIROSTOR – DELISTED ENVS – HWP - HHSS	0.5
Landfill and/or Solid Waste Disposal Site Lists	SWF/LF – LDS – SWAT – SWRCB SWF – SANDIEGO SWF	0.5
Leaking Storage Tank Lists	LUST – DELISTED LST – UST CLOSURE – CLEANUP SITES – INDIAN LUST – DELISTED ILST – SAN DIEGO LOP – SAN DIEGO SAM	0.5
Registered Storage Tank Lists	UST – AST – DELISTED TNK – CERS TANK – DELISTED CTNK – HIST TANK – INDIAN UST – DELISTED IUST – DELISTED COUNTY – SAN DIEGO UST	Site and Adjoining Properties
Institutional Control/Engineering Control Registries	LUR – HLUR - DEED	Site
Voluntary Cleanup Sites	VCP	0.5
Brownfield Sites	Not Applicable – No Database Exists	0.5

Site – The Site is not listed on any of the State, Tribal or local ASTM regulatory databases.

Adjoining Properties – One adjoining property is listed on multiple databases including SAM SAN DIEGO, CLEANUP SITES, HAZ SAN DIEGO, LOP SAN DIEGO and DEED. The property is identified as the Tripp Landfill (Cactus Road and adjoining to the west-northwest). This former landfill is located across Cactus Road and historically operated by accepting auto shredder related waste. In addition, municipal waste was delivered to and burned at the former facility. Multiple phases of environmental assessment and remedial work (i.e., grading and capping) have occurred over the decades and the former landfill was subsequently issued a certificate of completion by the State of California. Given the distance and orientation of this property from the Site and depth to groundwater in the area, this property is not considered to be a significant environmental concern to the Site.

Other Properties – There are multiple listings mapped in the surrounding area on the State, Tribal or local databases. These properties are not considered to have the potential to adversely impact the Site.

5.2 Non-ASTM Regulatory Database Search

A myriad of non-ASTM regulatory databases was searched by ERIS as noted in the regulatory database report.

Site – The Site is not listed on any of the non-ASTM regulatory databases.

Adjoining Properties – Four adjoining properties are listed on one or more of the non-ASTM databases as noted below.

- San Diego Fire and Rescue (1950 Cactus Road and adjoining to the west). This location appears on the CHMIRS database. In October 2021, several containers of paints, adhesives and sealants fell from a truck on to Cactus Road. The issue was rectified.

- Otay Auto Transport (1938 Cactus Road and adjoining to the west-northwest). This property is listed on the HAZNET database with an EPA ID# of CAL000395792. No additional details are provided. The business is also referenced on the HAZ SAN DIEGO database with an ID of DEH2016-HUPFP-002285. This ID was suspended in 2018. Several administrative related violations and some pertaining to the storage of hazardous wastes were noted. However, no releases have been reported. This property is also listed on the FINDS/FRS database for stormwater related considerations.

- Harry Singh and Son/NRC (Cactus and Airway Road and adjoining to the southwest). The business is referenced on the HAZ SAN DIEGO database with an ID of DEH2002-HUPFP-199071. No releases were reported. This property is also listed on the CHMIRS database for a report of abandoned drums in a field that was subsequently removed.

- Dantzlet & Barnhart Properties/Charles Tatum (1812 Cactus Road and adjoining to the northwest). This property is listed on the HAZ SAN DIEGO database under an ID of DEH2002-HUPFP-134129 and no releases reported. The property is also listed on the FINDS/FRS database with no details provided and on the HAZNET database for generating contaminated soil resulting from a property cleanup.

These properties are not considered to have the potential to adversely impact the Site.

Other Properties – There are multiple listings mapped in the surrounding area on the non-ASTM databases. These properties are not considered to have the potential to adversely impact the Site.

5.3 Regulatory Agency File Reviews

If a property being assessed under a Phase I ESA or any of the adjoining properties are identified on one or more of the above referenced standard environmental record sources, pertinent regulatory files and/or records associated with such listings should be reviewed

to assist the environmental professional in evaluating if “recognized environmental conditions” existing at a given subject property in connection with any listings. However, if in the environmental professional’s opinion, such a review is not warranted, file reviews need not be conducted if the environmental professional provides justification for not doing so.

CYA completed a records search with the County of San Diego DEH and the San Diego RWQCB pertaining to the Site and no records were identified. We also have substantial knowledge pertaining to the EPOCA/LUMINA new development occurring to the west of the Site across Cactus Road. A removal action of impacted soil was removed from a former reservoir area at this property. In addition, agricultural soils containing organochlorine pesticides (OCPs) were managed by burial in deep fill areas at the property. The EPOCA/LUMINA property is not considered to be an environmental concern to the Site.

5.4 Summary Relative to Environmental Concerns

No “recognized environmental conditions” associated with *Regulatory Records* reviews are noted. In addition, regulatory resources related to the adjoining properties and properties in the vicinity of the Site do not represent “recognized environmental conditions” that are of direct environmental concern to the Site.

6.0 HISTORICAL RESOURCE REVIEW

The objective of consulting historical sources is to develop a history of the previous uses of a property and surrounding area, in order to help identify the likelihood of past uses having led to "recognized environmental conditions" in connection with a given property. The goal of the historical research is to identify all obvious uses of a subject property from the present, back to the property's first developed use, or back to 1940, whichever is earlier. The environmental professional exercises professional judgment in reviewing only as many of the standard historical sources referenced in ASTM E1527 that are deemed necessary, are reasonably ascertainable and are likely to be useful. Historical resources reviewed during the completion of this Phase I ESA are referenced below. Copies are included in Appendix B.

6.1 Aerial Photographs

We reviewed historical aerial photographs ranging in date from 1928 to 2020 provided by ERIS. From 1928 to 1994, evidence of agricultural activity at the Site is visible (i.e. crop patterns). In 1994 and 1996, a few structures are visible in the northwest corner of the Site. Beginning in 1996, the Site is predominantly vacant and undeveloped. Some structures (appear to be temporary) are present along the western Site boundary between 2005 and 2010. Adjoining properties have historically primarily included vacant and agricultural land. Some residential and commercial (i.e., junkyard) activity has been present to the west across Cactus Road.

As stated above, the Site was historically used for agricultural activities. During historical agricultural activities throughout the State of California, OCPs were commonly and legally applied during the normal course of agricultural operations. These compounds have since been banned from production and use in the U.S. Section 105215 of the California Health and Safety Code discusses the regulatory reporting of incidents that pertain to pesticide spills and accidental releases of pesticide products. No information has been revealed that would lead CYA to believe that an accidental spill or release of pesticide products has occurred at the Site. In addition, neither stressed vegetation nor evidence of the storage of OCP based chemical products was observed on the Site during the Site reconnaissance or based on regulatory and historical research reviews. As such, the historical agricultural use of the Site is not considered to be a "recognized environmental condition" in connection with the Site. However, it should be noted that the potential for residual agricultural chemicals in shallow soils is still of interest relative to Site development constraints and costs. As such, soil sampling and analysis was completed concurrently with this Phase I ESA. Please refer to Section 9.0 for information pertaining to soil sampling completed at the Site.

6.2 Topographic Maps

We reviewed topographic maps ranging in date from 1943 to 2021 provided by ERIS. The Site is depicted as vacant on each of the maps. A pond is mapped near the northwest corner of the Site on some of the maps. Reservoirs and ponds are also mapped on some adjoining properties. Adjoining properties are primarily depicted as vacant with some

scattered structures present in some years. Cactus Road and Airway Road are also depicted.

6.3 Other Historical Sources

Other historical sources are referenced in the ASTM E1527 practice as any source or sources other than the standard historical sources referenced in the practice that are credible to a reasonable person and that identify past uses of a subject property. This category includes, but is not limited to miscellaneous maps, newspaper archives, internet sites, community organizations, local libraries, historical societies, current owners or occupants of neighboring properties, or records in the files and/or personal knowledge of the property owner and/or occupants. No historical sources other than the standard sources described above were deemed necessary and useful to assist in identifying "recognized environmental conditions."

6.4 Summary Relative to Environmental Concerns

No "recognized environmental conditions" associated with *Historical Resources* reviewed are noted. In addition, *Historical Resources* related to the adjoining properties and properties in the vicinity of the Site do not represent "recognized environmental conditions" that are of direct environmental concern to the Site.

7.0 SITE RECONAISSANCE

The objective of the Site reconnaissance is to obtain information indicating the likelihood of identifying "recognized environmental conditions" in connection with a subject property. The Site visit for our assessment was completed by Colin Young on June 28, 2022. Mr. Young was unescorted during the inspection.

7.1 Methodology and Limiting Conditions

The Site reconnaissance consisted of observing visible areas of the Site and walking publicly accessible areas surrounding the Site. No significant limiting conditions were noted during the reconnaissance. Select photographs of the Site obtained during the Site reconnaissance are included in Appendix C.

7.2 Current General Site and Vicinity Characteristics

The Site and the surrounding vicinity are situated in an area of the community of Otay Mesa that consists primarily of vacant land, agricultural land, new development, and commercial development with some scattered residences and public roadways. The Site is currently vacant and tilled land.

7.3 Indications of Past Site and Vicinity Uses

There are no material differences between the current and past uses of the Site, adjoining properties and the surrounding area that were visually and/or physically observed during the Site reconnaissance that pertain to "recognized environmental conditions."

7.4 Site-Specific Observations

We examined the Site for the features and conditions noted in the table below.

Feature or Condition	Details
General Description of Structures	There are no habitable improvements present at the Site. The Site is tilled.
Drains and Sumps	None observed.
Heating/Cooling Systems	None observed.
Potable Water Supply	Municipal (Otay Water District)
Roads	None observed.
Septic Systems / Sewage Disposal System	None observed.
Wastewater and Stormwater Discharges	None observed.
Wells	None observed.
Drums	None observed.
Electrical or Hydraulic Equipment Known to Contain	None observed.

Feature or Condition	Details
PCBs or Likely to Contain PCBs	
Hazardous Substances and Petroleum Products in Connection with Identified Uses	None observed.
Hazardous Substance and Petroleum Products Not Necessarily in Connection With Identified Uses	None observed.
Odors	None noted.
Pits, Ponds or Lagoons	None observed.
Pools of Liquid	None observed.
Solid Waste (Including Fill Material)	None observed.
Stained Soil or Pavement	None observed.
Stains or Corrosion	None observed.
Storage Tanks	None observed.
Stressed Vegetation	None observed.
Unidentified Substance Containers	None observed.

7.5 Summary Relative to Environmental Concerns

No “recognized environmental conditions” associated with the current use of the Site were noted during the *Site Reconnaissance*. In addition, no current uses of the adjoining properties or properties in the surrounding area that were visually and/or physically observed during the *Site Reconnaissance* were noted as being relevant to “recognized environmental conditions” that are of direct environmental concern to the Site.

8.0 INTERVIEWS

The designated Site owner representative and Key Site Manager is Joseph Paez, Jr. Mr. Paez completed an environmental questionnaire pertaining to the Site. Questionnaires completed by Mr. Paez and the client are included in Appendix D. No other persons knowledgeable of the Site were interviewed during the completion of this Phase I ESA.

8.1 Site Owner

The Site owner is unaware of environmental concerns in connection with the Site.

8.2 Key Site Manager

The Site owner is also considered to be the Key Site Manager. Please refer to Section 8.1 above.

8.3 Current Occupants

The Site is vacant with no known occupants.

8.4 Local Government Official

During the preparation of this Phase I ESA, public records clerks of the County of San Diego DEH and the SD-RWQCB were contacted by our firm regarding the Site. Representatives of these agencies indicated that public records requests should be conducted in order to obtain information known by the agencies regarding the Site. Public records requests were completed by our firm as described in Section 5.3.

8.5 Other Parties

Interviews with other persons were not conducted during the preparation of this Phase I ESA. As stated in the ASTM E1527 practice, interviews with past owners, operators, and occupants of a subject property who are likely to have material information regarding the potential for contamination at a given property shall be conducted to the extent that they have been identified and that the information likely to be obtained is not duplicative of information already obtained from other sources. Interviews with persons with past association with the Site were not deemed warranted during the completion of this Phase I ESA.

8.6 Summary Relative to Environmental Concerns

No “recognized environmental conditions” associated with the *Interviews* completed during the assessment are noted.

9.0 ADDITIONAL SERVICES – NON-SCOPE ASTM CONSIDERATIONS

With the exception of soil sampling and analysis, no additional services were completed by our firm during the preparation of this Phase I ESA. Several non-scope ASTM considerations referenced in Section 13 of the ASTM E1527 practice were considered, but deemed not relevant or substantive to the objectives of this assessment. Listed considerations in the practice include asbestos-containing building materials, biological agents, cultural and historic resources, ecological resources, endangered species, health and safety, indoor air quality (unrelated to releases of hazardous substances or petroleum products into the environment), industrial hygiene, lead-based paint, lead in drinking water, mold, radon, regulatory compliance and wetlands. No implication is intended by the practice as to the relative importance of inquiry into such non-scope considerations, and the list of considerations is not intended to be all-inclusive. An evaluation of one or more of the non-scope considerations was not requested of our firm as part of the scope of services for this assessment. Therefore, no findings, opinions and conclusions of this Phase I ESA are based on said non-scope ASTM considerations.

In consideration of the Site's agricultural use history, CYA conducted surface soil sampling at the Site concurrent with the completion of this Phase I ESA. The sampling was performed in conformance with the California Department of Toxic Substances Control's (DTSC) *Interim Guidance for Sampling Agricultural Properties (Third Revision)*. In consideration of the site's 40 acre size, the following was performed:

- Sampling only needed to be obtained from the surface (i.e., a depth of ≤6 inches). Guidelines for a 40-acre site dictated the acquisition of 50 discrete soil samples. Each sample location was plotted on a sampling plan. Deeper samples were not obtained at this time but may be performed to support grading activities at a later date.
- The 50 "discrete" soil samples were composited into 13 composite samples and analyzed for organochlorine pesticides (OCPs) using EPA Method 8081A. A total of 11 four-point composites and two three-point composites were generated by the /analytical laboratory and analyzed. Thirteen (13) of the 50 "discrete" samples were also analyzed for arsenic in accordance with EPA Method 6010.

Laboratory results were as follows:

- Total arsenic concentrations were unremarkable and consistent with naturally occurring concentrations of this element in southern California soils. Detections ranged from 2.0 milligrams per kilogram (mg/kg) to 5.14 mg/kg.
- The OCPs 4,4-DDD, DDE and DDT were prevalent in the composite samples but at concentrations below residential human health risk based screening levels.
- One unremarkable and trace concentration of the OCP Dieldrin was detected in one of the soil samples.
- Toxaphene is prevalent at the Site above the residential human health risk based screening level of 510 micrograms per kilogram (µg/kg). Twelve (12) of the 13

composite soil samples contained toxaphene above this target concentration. Detections ranged from 726 µg/kg to 2,470 µg/kg.

Appendix D includes a sampling location plan and the analytical laboratory report.

The sampling services summarized above were performed in accordance with practices and standards generally accepted by environmental scientists practicing in this industry. No other warranty, either express or implied, is made. The results and conclusions presented are based on a limited sampling program and do not purport to identify any and all sources or locations of subsurface impacts that may exist at the Site. Subsurface conditions at a given location may not be representative of conditions in other areas on the Site. In addition, conditions may change at any particular location as a function of time in response to natural conditions, chemical reactions, and other factors. Our conclusions regarding the condition of the Site does not represent a warranty that all areas of the Site are similar to those sampled. We are not responsible for the conclusions, opinions, or recommendations made by others based on this information. In addition, geologic interpretation was not within the scope of the sampling and analysis completed for the Site.

10.0 FINDINGS AND OPINIONS

With the exception of the prevalence of the OCP Toxaphene in shallow topsoil at the Site, no features and/or conditions indicating the presence or likely presence of hazardous substances and/or petroleum products that potentially have a significant impact to the Site were identified at the Site during the completion of this Phase I ESA. However, being that the pesticides appear to have been legally applied and are not the result of an accidental spill or release, this is not considered to be a “recognized environmental condition” in connection with the Site. However, it is considered to be a business environmental risk to be handled during future development activities by way of selective grading and soil management. This is considered a common practice and condition at development projects in the general locale of the Site.

11.0 CONCLUSIONS AND RECOMMENDATIONS


This Phase I ESA has revealed no evidence of “recognized environmental conditions,” “controlled recognized environmental conditions” or “historical recognized environmental conditions” in connection with the Site. Additional assessment at the Site is not considered to be warranted at this time.

12.0 ENVIRONMENTAL PROFESSIONAL STATEMENT

We declare that, to the best of my professional knowledge and belief, we meet the definition of environmental professional as defined in Section 312.10 of 40 CFR. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Site. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312. Qualifications of personnel involved with the completion of this report are included in Appendix E.



Colin P. Young, CIH
Principal



Daniel Weis, R.E.H.S.
Associates Environmental Scientist

13.0 ASSUMPTIONS

No Phase I ESA effort can eliminate uncertainty regarding the potential for “recognized environmental conditions” to exist in connection with a given property. Performance of the ASTM E1527 practice may reduce such uncertainty but in no way should the findings and report be misconstrued as insurance or a guarantee regarding the potential for “recognized environmental conditions” in connection with a given property. The ASTM E1527 practice recognizes reasonable limits of time and cost relative to the completion of a Phase I ESA.

During the completion of this ESA, our firm relied on certain information obtained from secondary sources, including but not limited to the user of the report, government agencies, historical research business entities, environmental databases and interviews with one or more persons. The sources obtained and/or consulted are assumed to be reliable. However, our firm cannot warrant or guarantee that the information provided by these other sources is wholly accurate or complete. Our firm is not responsible for any misrepresentations or false statements that may be provided by others or the lack of pertinent/relevant information that should have been provided/disclosed by others and we assume no responsibility for any consequence as a result of such omissions or withheld information.

Accuracy and completeness of records varies among information sources, including from governmental agencies. As a result, there is a possibility that even with the proper application of the methodologies presented in ASTM E1527, conditions may exist that could not be identified within the scope of this Phase I ESA or which were not reasonably identifiable from the available information. In addition, any responses received from Federal, State, Tribal, and local regulatory agency secondary sources of information after the issuance of this report may change certain findings and conclusions of this report.

Estimations and opinions regarding the potential for off-Site properties to adversely impact a given subject property is one of the key components of a Phase I ESA. In most cases, recent property-specific or adjacent-property specific measured groundwater data or other hydrogeological information is not reasonably ascertainable. In the absence of such data, reasonable assumptions regarding the depth and flow of groundwater are made based on various sources including comparisons to surface elevations, land topography and available hydrogeological on the State of California Geotracker database. In addition, estimations and opinions regarding potential impacts from off-Site locations may be based on certain assumptions that a hazardous substance or petroleum product may not migrate laterally within unsaturated soil for a substantial distance and that contaminants that have reached saturated soil and groundwater may attenuate over time and/or may decrease in concentration relative to distance from its source. While any interpretations presented herein may be effective in reducing uncertainty regarding potential impacts to a subject property from off-Site locations, in no way should the findings and report be misconstrued as insurance or a guarantee regarding the potential for such impacts to occur. Greater certainty regarding subsurface conditions at a given property can only be achieved by way of a subsurface sampling effort of one or more media.

14.0 DEFINITIONS

Definitions of key terminology relevant to the ASTM E1527 practice are presented below.

Recognized Environmental Condition - The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment.

Controlled Recognized Environmental Condition - A recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

Data Failure - A failure to achieve the historical research objectives as outlined in the ASTM E1527 practice even after reviewing the standard historical sources that are reasonably ascertainable and likely to be useful. Data failure is one type of data gap.

Data Gap - A lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. Data gaps may result from incompleteness in any of the activities required by the ASTM E1527 practice, including, but not limited to site reconnaissance (for example, an inability to conduct the site visit), and interviews (for example, an inability to interview the key site manager, regulatory officials, etc.). Data gaps are only considered to be significant if they affect the ability of the environmental professional to identify recognized environmental conditions.

***De Minimis* Condition** - A condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be *de minimis* conditions are not “recognized environmental conditions” nor “controlled recognized environmental conditions.”

Environment - (A) the navigable waters, the waters of the contiguous zone, and the ocean waters of which the natural resources are under the exclusive management authority of the United States under the Magnuson-Stevens Fishery Conservation and Management Act [16 U.S.C. §§ 1801 et seq.], and (B) any other surface water, groundwater, drinking water supply, land surface or subsurface strata, or ambient air within the United States or under the jurisdiction of the United States.

Good Faith - The absence of any intention to seek an unfair advantage or to defraud another party; an honest and sincere intention to fulfill one’s obligations in the conduct or transaction concerned.

Hazardous Substance - Includes hazardous substances designated under section 311 of the Clean Water Act (CWA) or Section 102 of CERCLA, any toxic pollutant listed under Section 307(a) of the CWA, any waste that has been listed as a RCRA hazardous waste or possesses a RCRA hazardous waste characteristic, any substance that is identified as a hazardous pollutant under Section 112 of the Clean Air Act (CAA), and any imminently hazardous chemical that EPA has taken action pursuant to Section 7 of the Toxic Substances Control Act (TSCA).

Historical Recognized Environmental Condition - A past release of any hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property in question to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

Petroleum Exclusion – While the definition of a CERCLA hazardous substance specifically excludes petroleum products and crude oil, the EPA has determined that the petroleum exclusion applies to petroleum products such as gasoline and other fuels containing lead, benzene or other hazardous substances that are normally added during the refining process. Notwithstanding the existence of the petroleum exclusion, petroleum products are included within the scope of the ASTM E1527 practice for multiple reasons. Petroleum products have historically been widely used at commercial properties. In addition, other federal and state laws may impose liability for releases or spills of petroleum products.

Reasonably Ascertainable Information - Information that is (1) publicly available, (2) obtainable from its source within reasonable time and cost constraints and (3) practically reviewable.

Release or Threatened Release - Spilling, leaking, pumping, pouring, emitting, emptying, discharging, injecting, escaping, leaching, dumping or disposing into the environment (including the abandonment or discarding of barrels, containers and other closed receptacles containing any hazardous substance, or pollutant or contaminant).

15.0 REFERENCES

Sources of information consulted during the completion of our Phase I ESA are noted in the sections below.

15.1 Documents, Plans and Reports

- All Appropriate Inquiry" as necessary to satisfy the defenses available under 42 U.S.C. §§ 9607(b)(3), 9607(r)(1), and 9607(q), relying on definitions provided at 42 U.S.C. §§ 9601(35)(B); and as further explained in 40 CFR §§ 312.1 – 312.31.
- ASTM International, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process," ASTM Designation E 1527-13, Published November 2013.
- California Geological Survey, 2002, California Geomorphic Provinces Note 36, Electronic Copy, Revised December.
- California State Water Resources Control Board, Water Quality Control Plan for the San Diego River Basin (9), California, Published 2008.
- ERIS Regulatory Database Report
- USGS topographic map, Otay Mesa, California Quadrangle (2010).
- Aerial Photographs and Topographic Maps - ERIS

15.2 Personal Communications

- Public Records Clerk – County of San Diego
- Public Records Clerk – SD-RWQCB

15.3 Agencies Consulted

- California Department of Conservation, Geologic Energy Management Division (CalGEM)
- County of San Diego DEH
- SD-RWQCB

FIGURES

FIGURE 1
VICINITY MAP



Figure 1 - Vicinity Map

Paez Property
County of San Diego Assessor's Parcel Number
646-100-77-00
San Diego, California

N

Prepared by:

C Young Associates
1042 Skylark Drive
La Jolla, CA 92037

FIGURE 2
SITE PLAN



Figure 2 - Site Plan

Paez Property
County of San Diego Assessor's Parcel Number
646-100-77-00
San Diego, California

N

Prepared by:

C Young Associates
1042 Skylark Drive
La Jolla, CA 92037

FIGURE 3
TOPOGRAPHIC MAP




Figure 3 - Topographic Map

Paez Property
County of San Diego Assessor's Parcel Number
646-100-77-00
San Diego, California

N

Prepared by:

C Young Associates
1042 Skylark Drive
La Jolla, CA 92037

APPENDICES

APPENDIX A
REGULATORY DATABASE REPORT

ERIS

DATABASE REPORT

Project Property:	*APN 646-100-77-00* *APN 646-100-77-00* *San Diego CA*
Project No:	
Report Type:	*Database Report*
Order No:	*22062300084*
Requested by:	*C Young Associates*
Date Completed:	*June 24, 2022*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....9
Executive Summary: Site Report Summary - Surrounding Properties.....10
Executive Summary: Summary by Data Source.....23
Map.....40
Aerial.....43
Topographic Map.....44
Detail Report.....45
Unplottable Summary.....349
Unplottable Report.....350
Appendix: Database Descriptions.....351
Definitions.....367

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*APN 646-100-77-00* *APN 646-100-77-00 San Diego CA*
Project No:		
Coordinates:		
	Latitude:	*32.5624841*
	Longitude:	*-116.98622804*
	UTM Northing:	*3,602,785.67*
	UTM Easting:	*501,292.83*
	UTM Zone:	*11S*
Elevation:		*509 FT*

Order Information:

Order No:	*22062300084*
Date Requested:	*June 23, 2022*
Requested by:	*C Young Associates*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (with Project Boundaries)*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Topographic Map	*Topographic Maps*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
DOE FUSRAP	Y	1	0	0	0	0	0	0
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	0	-	0
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	0	**1**	-	-	**1**
RCRA SQG	Y	0.25	0	0	**2**	-	-	**2**
RCRA VSQG	Y	0.25	0	0	0	-	-	0
RCRA NON GEN	Y	0.25	0	**5**	**17**	-	-	**22**
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
FRP	Y	0.25	0	0	0	-	-	0
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
RESPONSE	Y	1	0	0	0	0	0	0
ENVIROSTOR	Y	1	0	0	0	**1**	**3**	**4**
DELISTED ENVS	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	**1**	0	**1**	-	**2**
SWRCB SWF	Y	0.5	0	0	0	0	-	0
WMUD	Y	0.5	0	0	0	**3**	-	**3**
HWP	Y	1	0	0	0	0	0	0
SWAT	Y	0.5	0	0	0	0	-	0
C&D DEBRIS RECY	Y	0.5	0	0	0	**1**	-	**1**
RECYCLING	Y	0.5	0	0	0	0	-	0
PROCESSORS	Y	0.5	0	0	0	0	-	0
CONTAINER RECY	Y	0.5	0	0	0	0	-	0
LDS	Y	0.5	0	0	0	**1**	-	**1**
LUST	Y	0.5	0	0	0	**1**	-	**1**
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	0	**2**	-	-	**2**
UST CLOSURE	Y	0.5	0	0	0	0	-	0
HHSS	Y	0.25	0	0	0	-	-	0
UST SWEEPS	Y	0.25	0	0	0	-	-	0
AST	Y	0.25	0	**1**	**1**	-	-	**2**
AST SWRCB	Y	0.25	0	0	0	-	-	0
TANK OIL GAS	Y	0.25	0	0	0	-	-	0
DELISTED TNK	Y	0.25	0	0	**1**	-	-	**1**
CERS TANK	Y	0.25	0	**1**	**2**	-	-	**3**
DELISTED CTNK	Y	0.25	0	0	0	-	-	0
HIST TANK	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
LUR	Y	0.5	0	0	0	1	-	1
CALSITES	Y	0.5	0	0	0	0	-	0
HLUR	Y	0.5	0	0	0	0	-	0
DEED	Y	0.5	0	1	0	0	-	1
VCP	Y	0.5	0	0	0	1	-	1
CLEANUP SITES	Y	0.5	0	2	1	5	-	8
DELISTED CLEANUP	Y	0.5	0	0	0	0	-	0
DELISTED COUNTY	Y	0.25	0	0	0	-	-	0
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED ILST	Y	0.5	0	0	0	0	-	0
DELISTED IUST	Y	0.25	0	0	0	-	-	0
County								
SWF SANDIEGO	Y	0.5	0	0	0	0	-	0
LOP SANDIEGO	Y	0.5	0	1	0	12	-	13
HAZ SANDIEGO	Y	0.25	0	13	48	-	-	61
UST SANDIEGO	Y	0.25	0	0	2	-	-	2
SAM SANDIEGO	Y	0.5	0	1	1	3	-	5
Additional Environmental Records								
Federal								
FINDS/FRS	Y	PO	0	2	-	-	-	2
TRIS	Y	PO	0	-	-	-	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
ERNS PFAS	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	**1**	**1**
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
URANIUM	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	0	-	-	-	-	0
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
State								
DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DRYC GRANT	Y	0.25	0	0	0	-	-	0
PFAS	Y	0.5	0	0	0	0	-	0
PFAS GW	Y	0.5	0	0	0	0	-	0
HWSS CLEANUP	Y	0.5	0	0	0	0	-	0
TOXIC PITS	Y	1	0	0	0	0	0	0
DTSC HWF	Y	0.5	0	0	0	0	-	0
INSP COMP ENF	Y	1	0	0	0	0	0	0
SCH	Y	1	0	0	0	0	**1**	**1**
CHMIRS	Y	PO	0	**2**	-	-	-	**2**
HIST CHMIRS	Y	PO	0	-	-	-	-	0
HAZNET	Y	PO	0	**4**	-	-	-	**4**
HIST MANIFEST	Y	PO	0	-	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
HW TRANSPORT	Y	0.125	0	0	-	-	-	0
WASTE TIRE	Y	PO	0	-	-	-	-	0
MEDICAL WASTE	Y	0.25	0	0	0	-	-	0
HIST CORTESE	Y	0.5	0	0	0	0	-	0
CDO/CAO	Y	0.5	0	0	0	**2**	-	**2**
CERS HAZ	Y	0.125	0	**1**	-	-	-	**1**
DELISTED HAZ	Y	0.5	0	0	0	**1**	-	**1**
GEOTRACKER	Y	0.125	0	0	-	-	-	0
MINE	Y	1	0	0	0	0	0	0
LIEN	Y	PO	0	-	-	-	-	0
WASTE DISCHG	Y	0.25	0	0	0	-	-	0
EMISSIONS	Y	0.25	0	0	**1**	-	-	**1**
CDL	Y	0.125	0	0	-	-	-	0

Tribal ***No Tribal additional environmental record sources available for this State.***

County ***No County additional environmental databases were selected to be included in the search.***

Total:	*0*	***35***	***79***	***33***	***5***	***152***

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	CHMIRS	San Diego Fire And Rescue	1950 Cactus Road San Diego CA 92154 ***Notified Date:*** 10/16/2021 18:46	W	0.01 / 40.24	-8	45
2	HAZNET	OTAY AUTO TRANSPORT & STORAGE	1938 CACTUS RD SAN DIEGO CA 92154	WNW	0.01 / 61.40	-11	46
2	HAZ SANDIEGO	OTAY AUTO TRANSPORT (SAN DIEGO)	1938 Cactus RD, San Diego, CA 92154 San Diego CA 0	WNW	0.01 / 61.40	-11	47
2	FINDS/FRS	OTAY AUTO TRANSPORT	1938 CACTUS ROAD SAN DIEGO CA 92154 ***Registry ID:*** 110070086028	WNW	0.01 / 61.40	-11	49
3	RCRA NON GEN	YVETTE ALCARAZ	1942 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID:*** CAC003145547	W	0.01 / 65.49	-9	50
4	HAZ SANDIEGO	HARRY SINGH & SON	CACTUS & AIRWAY RD, SAN DIEGO, 92173- CA	SW	0.01 / 66.19	2	51
4	CHMIRS	NRC	Airway Rd & Cactus Ave Otay CA ***Notified Date:*** 3/10/200411:15:03 AM	SW	0.01 / 66.19	2	51
5	SAM SANDIEGO	TRIP LANDFILL/CACTUS RD PROPER	0 W CACTUS RD San Diego CA	WNW	0.02 / 79.30	-15	51
5	CLEANUP SITES	TRIP LANDFILL/CACTUS RD PROPER	NONE W CACTUS S OTAY MESA R SAN DIEGO CA 92173 ***Status*** **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE	WNW	0.02 / 79.30	-15	52
5	HAZ SANDIEGO	TRIP LANDFILL/CACTUS RD PROPER	0 W CACTUS S OTAY MESA R, SAN YSIDRO, CA 92173 SAN YSIDRO CA 92173	WNW	0.02 / 79.30	-15	54
5	CLEANUP SITES	TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA TRIPP SALVAGE LANDFILL	1890 CACTUS ROAD SAN DIEGO CA 92154 ***Status*** **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE	WNW	0.02 / 79.30	-15	56

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
5	LOP SANDIEGO	TRIP LANDFILL/CACTUS RD PROPER	0 W CACTUS RD, SAN YSIDRO, CA 92173 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1991-LSAM-H32115-001 | Completed	WNW	0.02 / 79.30	-15	61
5	DEED	TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA Tripp Salvage Landfill	1890 CACTUS ROAD SAN DIEGO CA 92154	WNW	0.02 / 79.30	-15	61
6	HAZ SANDIEGO	DANTZLER & BARNHART PROPERTY'S	1812 CACTUS RD CA 0	NW	0.02 / 80.67	-13	62
6	HAZNET	CHARLES TATUM	1812 CACTUS RD SAN DIEGO CA 921548105	NW	0.02 / 80.67	-13	63
6	HAZNET	CHARLES TATUM	1812 CACTUS RD SAN DIEGO CA 921540000	NW	0.02 / 80.67	-13	63
6	HAZNET	TATUM CHARLES EIRMA TRUST	1812 CACTUS RD SAN DIEGO CA 921548105	NW	0.02 / 80.67	-13	64
6	RCRA NON GEN	IRMA TATUM	1812 CACTUS RD. SAN DIEGO CA 92154 ***EPA Handler ID:*** CAC003026135	NW	0.02 / 80.67	-13	65
6	FINDS/FRS	IRMA TATUM	1812 CACTUS RD. SAN DIEGO CA 92154 ***Registry ID:*** 110070657576	NW	0.02 / 80.67	-13	66
7	AST	ASSOCIATED READY MIXED CONCRETE	1696 CACTUS RD, SAN DIEGO, CA 92154- CA	NW	0.07 / 358.82	-4	66
7	HAZ SANDIEGO	AT&T WIRELESS #333	1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.07 / 358.82	-4	66
7	HAZ SANDIEGO	NEXTEL CELL SITE CA 5807	1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.07 / 358.82	-4	68
7	HAZ SANDIEGO	AT&T MOBILITY - SD 0333	1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.07 / 358.82	-4	69
7	HAZ SANDIEGO	ASSOCIATED READY MIXED CONCRETE, INC	1696 CACTUS RD SAN DIEGO CA 92154	NW	0.07 / 358.82	-4	70

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
7	CERS TANK	ASSOCIATED READY MIXED CONCRETE INC	1696 CACTUS RD SAN DIEGO CA 92154 ***Site ID:*** 93697	NW	0.07 / 358.82	-4	91
7	RCRA NON GEN	ASSOCIATED READY MIXED CONCRETE INC #62	1696 CACTUS RD SAN DIEGO CA 92154 ***EPA Handler ID:*** CAL000270953	NW	0.07 / 358.82	-4	99
8	HAZ SANDIEGO	CACTUS RECYCLING, INC.	1703 CACTUS RD CA 0	NNW	0.08 / 422.63	-3	100
8	HAZ SANDIEGO	R&R AG CHEM INC	1703 CACTUS RD, SAN YSIDRO, 92173-2209 CA	NNW	0.08 / 422.63	-3	101
8	RCRA NON GEN	CALTRANS	1703 CACTUS RD SAN DIEGO CA 92154 ***EPA Handler ID:*** CAP000199299	NNW	0.08 / 422.63	-3	101
9	SWF/LF	Cactus Road- AKA Tripp Salvage	1700-1902 Cactus Road San Diego CA 92154 ***Act Opl Status*** | ***Activity:*** Closed | Solid Waste Disposal Site	NNW	0.10 / 548.10	-2	103
10	HAZ SANDIEGO	ENERGY LABS, INC.	1695 CACTUS RD SAN DIEGO CA 92154	NNW	0.12 / 614.77	-2	104
10	HAZ SANDIEGO	SKS INC	1695 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NNW	0.12 / 614.77	-2	107
10	CERS HAZ	ENERGY LABS, INC.	1695 CACTUS RD SAN DIEGO CA 92154	NNW	0.12 / 614.77	-2	108
11	HAZ SANDIEGO	GM TIRES & ROAD SERVICE, INC	1690 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NNW	0.12 / 652.20	-2	111
11	RCRA NON GEN	SUNSET CAR RENTAL LLC	1690 CACTUS RD SAN DIEGO CA 92154-8101 ***EPA Handler ID:*** CAL000367120	NNW	0.12 / 652.20	-2	112
12	DELISTED TNK	AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154	NNW	0.16 / 821.59	1	113
12	HAZ SANDIEGO	AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154	NNW	0.16 / 821.59	1	114

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
12	UST	AT&T California - D3179	1670 Cactus Rd San Diego CA 92154 ***Facility ID:*** 37-000-129788	NNW	0.16 / 821.59	1	117
12	RCRA LQG	PACIFIC BELL DBA AT&T OF CA	1670 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID:*** CAR000286229	NNW	0.16 / 821.59	1	117
12	CERS TANK	AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154 ***Site ID:*** 433548	NNW	0.16 / 821.59	1	146
12	RCRA NON GEN	PACIFIC BELL TELEPHONE CO DBA AT&T CALIF	1670 CACTUS RD OTAY MESA CA 92173-2210 ***EPA Handler ID:*** CAL000116895	NNW	0.16 / 821.59	1	152
12	UST SANDIEGO	AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154 ***Record ID*** | ***Permit Status:*** DEH2002-HUPFP-129788 | Permit Renewed	NNW	0.16 / 821.59	1	153
13	HAZ SANDIEGO	HM INT'L COSMETICS, INC	6965 CAMINO MAQUILADORA, SUITE# E, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.17 / 908.25	-3	153
13	HAZ SANDIEGO	CAVAZOS TRANSPORTATION & REGISTRATION	6965 CAMINO MAQUILADORA CA 0	NW	0.17 / 908.25	-3	154
13	HAZ SANDIEGO	H & J PRECISION TOOLS, INC	6965 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.17 / 908.25	-3	155
14	RCRA SQG	T K OF SAN DIEGO	6975 CAMINO MAQUILLADORA SAN DIEGO CA 92173 ***EPA Handler ID:*** CAD982460347	NW	0.17 / 915.11	-3	157
14	HAZ SANDIEGO	PINNACLE INDUSTRIAL SUPPLY, INC; PINNACLE INDUSTRIAL SUPPLY, INC	6975 CAMINO MAQUILADORA, SAN DiEGO, CA 92154 SAN DiEGO CA 92154; 0	NW	0.17 / 915.11	-3	159
14	HAZ SANDIEGO	THERMO KING OF SAN DIEGO	6975 CAMINO MAQUILADORA, SAN DIEGO, 92173-3504 CA	NW	0.17 / 915.11	-3	163

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
14	RCRA NON GEN	PINNACLE INDUSTRIAL SUPPLY INC	6975 CAMINO MAQUILADORA SAN DIEGO CA 92154-7504 ***EPA Handler ID:*** CAL000355386	NW	0.17 / 915.11	-3	163
14	RCRA NON GEN	BORDER RECAPPING LLC DBA BORDER TIRE	6975 CAMINO MAQUILADORA SAN DIEGO CA 92154 ***EPA Handler ID:*** CAL000466847	NW	0.17 / 915.11	-3	165
15	HAZ SANDIEGO	OFFICE 2000	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.19 / 997.03	-4	166
15	HAZ SANDIEGO	GM WHOLESALE & ROAD SERVICE TIRES, INC	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.19 / 997.03	-4	167
15	HAZ SANDIEGO	SUPER SPICE COMPANY	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.19 / 997.03	-4	168
15	HAZ SANDIEGO	LCA EXPORT	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.19 / 997.03	-4	169
16	SAM SANDIEGO	MARTINEZ RANCH	2160 CACTUS RD San Diego CA	SW	0.20 / 1,050.50	0	170
16	CLEANUP SITES	MARTINEZ RANCH	2160 CACTUS RD SAN DIEGO CA 92154	SW	0.20 / 1,050.50	0	171
			Status **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED	CLEANUP PROGRAM SITE			
16	AST	MARTINEZ RANCH	2160 CACTUS RD SAN DIEGO CA 92154	SW	0.20 / 1,050.50	0	173
16	HAZ SANDIEGO	MARTINEZ RANCH	2160 CACTUS, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	SW	0.20 / 1,050.50	0	173
16	HAZ SANDIEGO	MARTINEZ RANCH	2160 CACTUS RD CA 0	SW	0.20 / 1,050.50	0	174
17	HAZ SANDIEGO	Verizon Wireless: Mesa de Otay	2175 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	S	0.21 / 1,083.84	-3	176
17	HAZ SANDIEGO	AZULEE AUTO RECON	2175 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	S	0.21 / 1,083.84	-3	177

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
17	HAZ SANDIEGO	ADESA SAN DIEGO	2175 CACTUS RD SAN YSIDRO CA 92173	S	0.21 / 1,083.84	-3	178
17	RCRA NON GEN	ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO	2175 CACTUS RD SAN DIEGO CA 92154-8002 ***EPA Handler ID:*** CAL000346874	S	0.21 / 1,083.84	-3	203
17	RCRA NON GEN	DIRECT RECONDITIONING, LLC	2175 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID:*** CAL000429226	S	0.21 / 1,083.84	-3	204
18	HAZ SANDIEGO	GLOBAL EXPORT TRANSPORT	6935 CAMINO MAQUILADORA CA 0	NW	0.22 / 1,185.81	-5	205
18	HAZ SANDIEGO	INALERT DISTRIBUTION OF CA	6935 CAMINO MAQUILADORA CA 0	NW	0.22 / 1,185.81	-5	206
18	HAZ SANDIEGO	PLANTRONICS INC	6935 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.22 / 1,185.81	-5	207
18	HAZ SANDIEGO	PRO DESIGN FURNITURE	6935 CAMINO MAQUILADORA CA 0	NW	0.22 / 1,185.81	-5	208
18	RCRA NON GEN	MENDEOLA TRANSAXLES INC.	6935 CAMINO MAQUILADORA SUITE B SAN DIEGO CA 92154 ***EPA Handler ID:*** CAC003079987	NW	0.22 / 1,185.81	-5	209
18	RCRA NON GEN	MENDEOLA TRANSAXLES INC	6935 CAMINO MAQUILADORA SAN DIEGO CA 92154 ***EPA Handler ID:*** CAL000456162	NW	0.22 / 1,185.81	-5	210
18	RCRA NON GEN	MENDEOLA TRANSAXLES INC	6935 CAMINO MAQUILADORA SAN DIEGO CA 92154 ***EPA Handler ID:*** CAC003158330	NW	0.22 / 1,185.81	-5	211
19	HAZ SANDIEGO	1605 CACTUS, INC DBA: CALI-MART/ CHEVRON	1605 CACTUS RD, SAN DIEGO, 92154 CA	NNW	0.23 / 1,204.75	3	212
19	HAZ SANDIEGO	Noil USA Inc.	1605 CACTUS RD SAN DIEGO CA 92154	NNW	0.23 / 1,204.75	3	213

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
19	UST SANDIEGO	Noil USA Inc.	1605 CACTUS RD SAN DIEGO CA 92154 ***Record ID*** **|** ***Permit Status:*** DEH2012-HUPFP-216147 | Permit Renewed	NNW	0.23 / 1,204.75	3	223
19	UST	Noil USA Inc.	1605 Cactus Rd San Diego CA 92154 ***Facility ID:*** 37-000-216147	NNW	0.23 / 1,204.75	3	224
19	EMISSIONS	OTAY MESA MOBIL	1605 CACTUS ROAD SAN DIEGO CA 92037	NNW	0.23 / 1,204.75	3	224
19	CERS TANK	Noil USA Inc.	1605 CACTUS RD SAN DIEGO CA 92154 ***Site ID:*** 6166	NNW	0.23 / 1,204.75	3	230
19	RCRA NON GEN	NOIL USA INC	1605 CACTUS RD SAN DIEGO CA 92154 ***EPA Handler ID:*** CAL000418575	NNW	0.23 / 1,204.75	3	244
20	RCRA NON GEN	M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA	6950 CAMINO MAQUILADORA STE C SAN DIEGO CA 92154 ***EPA Handler ID:*** CAR000217547	NW	0.23 / 1,235.24	0	245
20	HAZ SANDIEGO	M.RIOS TRUCKING	6950 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.23 / 1,235.24	0	250
20	HAZ SANDIEGO	PRECISION EQUIPMENT	6950 CAMINO MAQUILADORA #C, SAN DIEGO, 92173- CA	NW	0.23 / 1,235.24	0	251
20	HAZ SANDIEGO	M RIOS TRUCKING, INC	6950 CAMINO MAQUILADORA, SAN YSIDRO CA 92173 CA	NW	0.23 / 1,235.24	0	251
20	HAZ SANDIEGO	AERODESIGN PRODUCTS, INC	6950 CAMINO MAQUILADORA, SUITE# D-E, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.23 / 1,235.24	0	251
20	HAZ SANDIEGO	AP MOTORSPORTS	6950 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.23 / 1,235.24	0	252
20	RCRA NON GEN	NAHUM LLC	6950 CAMINO MAQUILADORA SUITE B SAN DIEGO CA 92154 ***EPA Handler ID:*** CAC002988639	NW	0.23 / 1,235.24	0	253

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
21	HAZ SANDIEGO	F & S TOWING	2230 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	SSW	0.24 / 1,280.79	-1	254
21	RCRA SQG	LUMINA I	2230 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID:*** CAP000318428	SSW	0.24 / 1,280.79	-1	255
22	HAZ SANDIEGO	OTAY MESA TENT ONLY	6960 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	1	257
22	HAZ SANDIEGO	SANCHEZ TRUCK REPAIR	6960 CAMINO MAQUILADORA CA 0	NW	0.25 / 1,293.96	1	258
22	HAZ SANDIEGO	baja auto parts #2	6960 CAMINO MAQUILADORA E SAN DIEGO CA 92154	NW	0.25 / 1,293.96	1	259
22	HAZ SANDIEGO	PRECISE LIFT SYSTEMS	6960 CAMINO MAQUILADORA CA 0	NW	0.25 / 1,293.96	1	263
22	HAZ SANDIEGO	BAJA AUTO PARTS #2	6960 CAMINO MAQUILADORA, SUITE# L, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.25 / 1,293.96	1	265
22	HAZ SANDIEGO	OTAY ENGINE REBUILDERS	6960 CAMINO MAQUILADORA, SAN DIEGO, 92173- CA	NW	0.25 / 1,293.96	1	266
22	HAZ SANDIEGO	905 SMOG & AUTO REPAIR	6960 CAMINO MAQUILADORA, SUITE# G, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	1	266
22	HAZ SANDIEGO	JVS GENERAL AUTO REPAIR	6960 CAMINO MAQUILADORA #K, SAN DIEGO, 92173- CA	NW	0.25 / 1,293.96	1	273
22	HAZ SANDIEGO	CYCLONE LIFT INC	6960 CAMINO MAQUILADORA CA 0	NW	0.25 / 1,293.96	1	273
22	HAZ SANDIEGO	PAYLESS REGISTRATION SERVICE, INC.	6960 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	1	274

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
22	HAZ SANDIEGO	EAGLE SCIENTIFIC PRODUCTS	6960 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	1	275
22	RCRA NON GEN	905 SMOG & AUTO REPAIR	6960 CAMINO MAQUILADORA STE G SAN DIEGO CA 92154 ***EPA Handler ID:*** CAL000297004	NW	0.25 / 1,293.96	1	276
22	RCRA NON GEN	BAJA AUTO PARTS #2	6960 CAMINO MAQUILADORA STE E SAN DIEGO CA 92154 ***EPA Handler ID:*** CAL000403322	NW	0.25 / 1,293.96	1	278
22	RCRA NON GEN	JOSE GRACIA	6960 CAMINO MAQUILADORA SUITE B SAN DIEGO CA 92154 ***EPA Handler ID:*** CAC003069222	NW	0.25 / 1,293.96	1	279
23	HAZ SANDIEGO	SMOG EXPRESS	6930 CAMINO MAQUILADORA, SUITE# A, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.25 / 1,294.15	0	280
23	HAZ SANDIEGO	I-MACH INDUSTRIAL MACHINERY & PARTS	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	0	281
23	HAZ SANDIEGO	ECO STONE, INC	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	0	282
23	HAZ SANDIEGO	LARSON IRRIGATION, INC.	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	0	283
23	HAZ SANDIEGO	BORDER TRANSMISSIONS	6930 CAMINO MAQUILADORA #D, SAN DIEGO, 92173- CA	NW	0.25 / 1,294.15	0	284
23	HAZ SANDIEGO	NEW WORLD MOLDING	6930 CAM MAQUILADORA CA 0	NW	0.25 / 1,294.15	0	284
23	HAZ SANDIEGO	JD ELECTRIC & INDUSTRIAL SUPPLY	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	0	285

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
23	HAZ SANDIEGO	OTAY CARPET OUTLET INC	6930 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	0	287
23	HAZ SANDIEGO	ASERET FREIGHT FORWARDING	6930 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	0	288
23	HAZ SANDIEGO	Battery and Components Inc dba Commercial Battery	6930 CAMINO MAQUILADORA K & L SAN DIEGO CA 92154	NW	0.25 / 1,294.15	0	289
23	RCRA NON GEN	OTAY HYDRAULICS LLC	6930 CAMINO MAQUILADORA STE F SAN DIEGO CA 92154-7513 ***EPA Handler ID:*** CAL000398978	NW	0.25 / 1,294.15	0	293
23	RCRA NON GEN	MEDOSA, INC.	6930 CAMINO MAQUILADORA SUITE L SAN DIEGO CA 92154 ***EPA Handler ID:*** CAR000206656	NW	0.25 / 1,294.15	0	294
23	RCRA NON GEN	BATTERY & COMPONENTS, INC.	6930 CAMINO MAQUILADORA SUITE K SAN DIEGO CA 92154 ***EPA Handler ID:*** CAR000306688	NW	0.25 / 1,294.15	0	296
24	CLEANUP SITES	OTAY MESA ROAD WIDENING	NONE OTAY MESA RD SAN DIEGO CA 92173	NNW	0.25 / 1,331.16	2	297
			Status **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE				
25	LDS	BARNHART AND DANTZLER PROPERTY	900 CACTUS ROAD SAN DIEGO CA 92154	NNW	0.26 / 1,383.61	1	300
25	CDO/CAO	Tripp Salvage Landfill	900 Cactus Rd San Ysidro CA 91973	NNW	0.26 / 1,383.61	1	302
25	CDO/CAO	SESI Tripp Salvage	900 Cactus Rd San Ysidro CA 91973	NNW	0.26 / 1,383.61	1	303
25	WMUD	BARNHARDT-DANTZLER-TRIPP SALVA	900 CACTUS RD SAN YSIDRO CA 91973	NNW	0.26 / 1,383.61	1	305
25	WMUD	TRIPP SALVAGE LANDFILL	900 CACTUS RD SAN YSIDRO CA 91973	NNW	0.26 / 1,383.61	1	306
25	WMUD	SESI TRIPP SALVAGE	900 CACTUS RD SAN YSIDRO CA 91973	NNW	0.26 / 1,383.61	1	308

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
26	SAM SANDIEGO	U S BORDER PATROL/BROWN FIELD	7060 BOEING ST San Diego CA	NNW	0.28 / 1,468.25	5	309
26	CLEANUP SITES	U S BORDER PATROL/BROWN FIELD	7060 BOEING ST SAN DIEGO CA 921731728	NNW	0.28 / 1,468.25	5	309
			Status **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE				
27	LOP SANDIEGO	U S BORDER PATROL/BROWN FIELD	7060 BOEING ST, SAN YSIDRO, CA 92173-1728 SAN YSIDRO CA	NNW	0.28 / 1,491.90	5	311
			Record ID **|** ***Record Status:*** DEH1987-LSAM-H21496-001 | Completed				
28	DELISTED HAZ	STEELCASE, INC	7510 AIRWAY RD SAN DIEGO CA 92154	E	0.32 / 1,676.21	-8	312
29	VCP	BRITANNIA BOULEVARD PROPERTY	2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154	ESE	0.32 / 1,698.04	-10	312
			Estor/EPA ID **|** ***Cleanup Status:*** 37070001 | CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010				
29	LUR	BRITANNIA BOULEVARD PROPERTY	2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154	ESE	0.32 / 1,698.04	-10	317
			Estor/EPA ID **|** ***Cleanup Status:*** 37070001 | CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010				
29	ENVIROSTOR	BRITANNIA BOULEVARD PROPERTY	2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154	ESE	0.32 / 1,698.04	-10	323
			Estor/EPA ID **|** ***Cleanup Status:*** 37070001 | CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010				
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	N	0.34 / 1,818.29	9	328
			Record ID **|** ***Record Status:*** DEH1987-LSAM-H10618-001 | Completed				
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	N	0.34 / 1,818.29	9	328
			Record ID **|** ***Record Status:*** DEH1990-LSAM-H10618-018 | Completed				
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	N	0.34 / 1,818.29	9	329
			Record ID **|** ***Record Status:*** DEH1989-LSAM-H10618-007 | Completed				
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	N	0.34 / 1,818.29	9	329
			Record ID **|** ***Record Status:*** DEH1989-LSAM-H10618-015 | Completed				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1999-LSAM-H10618-024 | Completed	N	0.34 / 1,818.29	9	329
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1989-LSAM-H10618-004 | Completed	N	0.34 / 1,818.29	9	329
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1989-LSAM-H10618-014 | Completed	N	0.34 / 1,818.29	9	330
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1989-LSAM-H10618-008 | Completed	N	0.34 / 1,818.29	9	330
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1990-LSAM-H10618-019 | Completed	N	0.34 / 1,818.29	9	330
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1990-LSAM-H10618-020 | Completed	N	0.34 / 1,818.29	9	331
30	LOP SANDIEGO	SDCTY-GEN SER, BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status:*** DEH1991-LSAM-H10618-023 | Completed	N	0.34 / 1,818.29	9	331
31	SWF/LF	Ins Shooting Range (Cays)	NW 1/4 S27, T18S, R1W, SB merid. San Diego CA 92173	W	0.39 / 2,071.63	-23	331
32	CLEANUP SITES	PIPER RANCH BUS PARK	6464 OTAY MESA ROAD CHULA VISTA CA 92173 ***Status*** **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE	NW	0.44 / 2,331.03	0	332
32	LUST	PIPER RANCH BUS PARK	6464 OTAY MESA ROAD CHULA VISTA CA 92173 ***Global ID*** **|** ***Status*** **|** ***Status Date:*** T0607302117 | COMPLETED - CASE CLOSED | 1995-02-21 00:00:00	NW	0.44 / 2,331.03	0	334
33	SAM SANDIEGO	2380 BRITANNIA BLVD., SAN DIEGO	2380 BRITANNIA San Diego CA	SE	0.46 / 2,451.68	-31	336
33	CLEANUP SITES	BRITANNIA 40 OTAY	2380 BRITANNIA SAN DIEGO CA 92154 ***Status*** **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE	SE	0.46 / 2,451.68	-31	337
33	C&D DEBRIS RECY	INSURANCE AUTO AUCTIONS	2380 BRITANNIA BLVD SAN DIEGO CA 92154	SE	0.46 / 2,451.68	-31	339

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
34	CLEANUP SITES	OTAY CANYON RANCH	2440 CACTUS ROAD SAN DIEGO CA 92154	SSW	0.47 / 2,497.08	-39	339
			Status* | *Site Facility Type: OPEN - SITE ASSESSMENT | CLEANUP PROGRAM SITE				
34	SAM SANDIEGO	Otay Canyon Ranch	2440 CACTUS RD San Diego CA	SSW	0.47 / 2,497.08	-39	344
35	ENVIROSTOR	BROWN FIELD NAAS	EAST OF CHULA VISTA CA	NW	0.57 / 3,025.10	12	345
			Estor/EPA ID* | *Cleanup Status: 80000947 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005				
35	FUDS	BROWN FIELD NAVAL AUXILIARY AIR STATION	EAST OF CHULA VISTA CA	NW	0.57 / 3,025.10	12	345
			FUDS Property No: J09CA7278				
36	ENVIROSTOR	HONEYWELL, INC.	2055 DUBLIN DRIVE SAN DIEGO CA 92173	E	0.59 / 3,126.37	-7	346
			Estor/EPA ID* | *Cleanup Status: 71003124 | NO FURTHER ACTION AS OF 2/22/2017				
37	SCH	OCEAN VIEW HILLS MID SCH/INTERIM HOUSING	4919 DEL SOL BOULEVARD SAN DIEGO CA 92154	WNW	0.83 / 4,365.70	9	346
			Estor/EPA ID* | *Cleanup Status: 37020003 | NO ACTION REQUIRED AS OF 4/15/2004				
37	ENVIROSTOR	OCEAN VIEW HILLS MID SCH/INTERIM HOUSING	4919 DEL SOL BOULEVARD SAN DIEGO CA 92154	WNW	0.83 / 4,365.70	9	347
			Estor/EPA ID* | *Cleanup Status: 37020003 | NO ACTION REQUIRED AS OF 4/15/2004				

Executive Summary: Summary by Data Source

Standard

Federal

RCRA LQG - RCRA Generator List

A search of the RCRA LQG database, dated Apr 11, 2022 has found that there are 1 RCRA LQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PACIFIC BELL DBA AT&T OF CA	1670 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID**: CAR000286229*	NNW	0.16 / 821.59	12

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Apr 11, 2022 has found that there are 2 RCRA SQG site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
T K OF SAN DIEGO	6975 CAMINO MAQUILLADORA SAN DIEGO CA 92173 ***EPA Handler ID**: CAD982460347*	NW	0.17 / 915.11	14
LUMINA I	2230 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID**: CAP000318428*	SSW	0.24 / 1,280.79	21

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Apr 11, 2022 has found that there are 22 RCRA NON GEN site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PACIFIC BELL TELEPHONE CO DBA AT&T CALIF	1670 CACTUS RD OTAY MESA CA 92173-2210 ***EPA Handler ID**: CAL000116895*	NNW	0.16 / 821.59	12
NOIL USA INC	1605 CACTUS RD SAN DIEGO CA 92154 ***EPA Handler ID**: CAL000418575*	NNW	0.23 / 1,204.75	19
JOSE GRACIA	6960 CAMINO MAQUILADORA SUITE B SAN DIEGO CA 92154 ***EPA Handler ID**: CAC003069222*	NW	0.25 / 1,293.96	22
BAJA AUTO PARTS #2	6960 CAMINO MAQUILADORA STE E SAN DIEGO CA 92154	NW	0.25 / 1,293.96	22

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID**: CAL000403322*			
905 SMOG & AUTO REPAIR	6960 CAMINO MAQUILADORA STE G SAN DIEGO CA 92154 ***EPA Handler ID**: CAL000297004*	NW	0.25 / 1,293.96	22

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
YVETTE ALCARAZ	1942 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID**: CAC003145547*	W	0.01 / 65.49	3
IRMA TATUM	1812 CACTUS RD. SAN DIEGO CA 92154 ***EPA Handler ID**: CAC003026135*	NW	0.02 / 80.67	6
ASSOCIATED READY MIXED CONCRETE INC #62	1696 CACTUS RD SAN DIEGO CA 92154 ***EPA Handler ID**: CAL000270953*	NW	0.07 / 358.82	7
CALTRANS	1703 CACTUS RD SAN DIEGO CA 92154 ***EPA Handler ID**: CAP000199299*	NNW	0.08 / 422.63	8
SUNSET CAR RENTAL LLC	1690 CACTUS RD SAN DIEGO CA 92154-8101 ***EPA Handler ID**: CAL000367120*	NNW	0.12 / 652.20	11
PINNACLE INDUSTRIAL SUPPLY INC	6975 CAMINO MAQUILADORA SAN DIEGO CA 92154-7504 ***EPA Handler ID**: CAL000355386*	NW	0.17 / 915.11	14
BORDER RECAPPING LLC DBA BORDER TIRE	6975 CAMINO MAQUILADORA SAN DIEGO CA 92154 ***EPA Handler ID**: CAL000466847*	NW	0.17 / 915.11	14
ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO	2175 CACTUS RD SAN DIEGO CA 92154-8002 ***EPA Handler ID**: CAL000346874*	S	0.21 / 1,083.84	17
DIRECT RECONDITIONING, LLC	2175 CACTUS ROAD SAN DIEGO CA 92154 ***EPA Handler ID**: CAL000429226*	S	0.21 / 1,083.84	17
MENDEOLA TRANSAXLES INC.	6935 CAMINO MAQUILADORA SUITE B SAN DIEGO CA 92154 ***EPA Handler ID**: CAC003079987*	NW	0.22 / 1,185.81	18
MENDEOLA TRANSAXLES INC	6935 CAMINO MAQUILADORA SAN DIEGO CA 92154 ***EPA Handler ID**: CAL000456162*	NW	0.22 / 1,185.81	18

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MENDEOLA TRANSAXLES INC	6935 CAMINO MAQUILADORA SAN DIEGO CA 92154 ***EPA Handler ID**: CAC003158330*	NW	0.22 / 1,185.81	18
M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA	6950 CAMINO MAQUILADORA STE C SAN DIEGO CA 92154 ***EPA Handler ID**: CAR000217547*	NW	0.23 / 1,235.24	20
NAHUM LLC	6950 CAMINO MAQUILADORA SUITE B SAN DIEGO CA 92154 ***EPA Handler ID**: CAC002988639*	NW	0.23 / 1,235.24	20
MEDOSA, INC.	6930 CAMINO MAQUILADORA SUITE L SAN DIEGO CA 92154 ***EPA Handler ID**: CAR000206656*	NW	0.25 / 1,294.15	23
OTAY HYDRAULICS LLC	6930 CAMINO MAQUILADORA STE F SAN DIEGO CA 92154-7513 ***EPA Handler ID**: CAL000398978*	NW	0.25 / 1,294.15	23
BATTERY & COMPONENTS, INC.	6930 CAMINO MAQUILADORA SUITE K SAN DIEGO CA 92154 ***EPA Handler ID**: CAR000306688*	NW	0.25 / 1,294.15	23

State

ENVIROSTOR - EnviroStor Database

A search of the ENVIROSTOR database, dated May 30, 2022 has found that there are 4 ENVIROSTOR site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BROWN FIELD NAAS	EAST OF CHULA VISTA CA ***Estor/EPA ID**	**Cleanup Status**: 80000947 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*	NW	0.57 / 3,025.10	35
OCEAN VIEW HILLS MID SCH/INTERIM HOUSING	4919 DEL SOL BOULEVARD SAN DIEGO CA 92154 ***Estor/EPA ID**	**Cleanup Status**: 37020003 | NO ACTION REQUIRED AS OF 4/15/2004*	WNW	0.83 / 4,365.70	37

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BRITANNIA BOULEVARD PROPERTY	2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154 ***Estor/EPA ID**	**Cleanup Status**: 37070001 | CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010*	ESE	0.32 / 1,698.04	29
HONEYWELL, INC.	2055 DUBLIN DRIVE SAN DIEGO CA 92173 ***Estor/EPA ID**	**Cleanup Status**: 71003124 | NO FURTHER ACTION AS OF 2/22/2017*	E	0.59 / 3,126.37	36

SWF/LF - Solid Waste Information System (SWIS)

A search of the SWF/LF database, dated Feb 2, 2022 has found that there are 2 SWF/LF site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Cactus Road- AKA Tripp Salvage	1700-1902 Cactus Road San Diego CA 92154	NNW	0.10 / 548.10	9
	Act Opl Status **|** ***Activity****: Closed*	*Solid Waste Disposal Site*		
Ins Shooting Range (Cays)	NW 1/4 S27, T18S, R1W, SB merid. San Diego CA 92173	W	0.39 / 2,071.63	31

WMUD - Waste Management Unit Database

A search of the WMUD database, dated Jan 1, 2000 has found that there are 3 WMUD site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SESI TRIPP SALVAGE	900 CACTUS RD SAN YSIDRO CA 91973	NNW	0.26 / 1,383.61	25
BARNHARDT-DANTZLER-TRIPP SALVA	900 CACTUS RD SAN YSIDRO CA 91973	NNW	0.26 / 1,383.61	25
TRIPP SALVAGE LANDFILL	900 CACTUS RD SAN YSIDRO CA 91973	NNW	0.26 / 1,383.61	25

C&D DEBRIS RECY - Construction and Demolition Debris Recyclers

A search of the C&D DEBRIS RECY database, dated Jun 20, 2018 has found that there are 1 C&D DEBRIS RECY site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
INSURANCE AUTO AUCTIONS	2380 BRITANNIA BLVD SAN DIEGO CA 92154	SE	0.46 / 2,451.68	33

LDS - Land Disposal Sites

A search of the LDS database, dated Feb 15, 2022 has found that there are 1 LDS site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BARNHART AND DANTZLER PROPERTY	900 CACTUS ROAD SAN DIEGO CA 92154	NNW	0.26 / 1,383.61	25

LUST - Leaking Underground Fuel Tank Reports

A search of the LUST database, dated Feb 15, 2022 has found that there are 1 LUST site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PIPER RANCH BUS PARK	6464 OTAY MESA ROAD CHULA VISTA CA 92173	NW	0.44 / 2,331.03	32
	Global ID **|** ***Status*** **|** ***Status Date***: *T0607302117 | COMPLETED - CASE CLOSED | 1995-02-21 00:00:00*			

UST - Permitted Underground Storage Tank (UST) in GeoTracker

A search of the UST database, dated Apr 25, 2022 has found that there are 2 UST site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
AT&T California - D3179	1670 Cactus Rd San Diego CA 92154	NNW	0.16 / 821.59	12
	Facility ID: *37-000-129788*			
Noil USA Inc.	1605 Cactus Rd San Diego CA 92154	NNW	0.23 / 1,204.75	19
	Facility ID: *37-000-216147*			

AST - Aboveground Storage Tanks

A search of the AST database, dated Aug 31, 2009 has found that there are 2 AST site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MARTINEZ RANCH	2160 CACTUS RD SAN DIEGO CA 92154	SW	0.20 / 1,050.50	16

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ASSOCIATED READY MIXED CONCRETE	1696 CACTUS RD, SAN DIEGO, CA 92154- CA	NW	0.07 / 358.82	7

DELISTED TNK - Delisted Storage Tanks

A search of the DELISTED TNK database, dated May 25, 2022 has found that there are 1 DELISTED TNK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154	NNW	0.16 / 821.59	12

CERS TANK - California Environmental Reporting System (CERS) Tanks

A search of the CERS TANK database, dated Apr 5, 2022 has found that there are 3 CERS TANK site(s) within approximately 0.25

miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154 ***Site ID**: 433548*	NNW	0.16 / 821.59	12
Noil USA Inc.	1605 CACTUS RD SAN DIEGO CA 92154 ***Site ID**: 6166*	NNW	0.23 / 1,204.75	19

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ASSOCIATED READY MIXED CONCRETE INC	1696 CACTUS RD SAN DIEGO CA 92154 ***Site ID**: 93697*	NW	0.07 / 358.82	7

LUR - Site Mitigation and Brownfields Reuse Program Facility Sites with Land Use Restrictions

A search of the LUR database, dated May 30, 2022 has found that there are 1 LUR site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BRITANNIA BOULEVARD PROPERTY	2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154 ***Estor/EPA ID**	**Cleanup Status**: 37070001 | CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010*	ESE	0.32 / 1,698.04	29

DEED - Deed Restrictions and Land Use Restrictions

A search of the DEED database, dated Feb 15, 2022 has found that there are 1 DEED site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA Tripp Salvage Landfill	1890 CACTUS ROAD SAN DIEGO CA 92154	WNW	0.02 / 79.30	5

VCP - Voluntary Cleanup Program

A search of the VCP database, dated May 30, 2022 has found that there are 1 VCP site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BRITANNIA BOULEVARD PROPERTY	2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154 ***Estor/EPA ID**	**Cleanup Status**: 37070001 | CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010*	ESE	0.32 / 1,698.04	29

CLEANUP SITES - GeoTracker Cleanup Program Sites

A search of the CLEANUP SITES database, dated Feb 15, 2022 has found that there are 8 CLEANUP SITES site(s) within

approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MARTINEZ RANCH	2160 CACTUS RD SAN DIEGO CA 92154	SW	0.20 / 1,050.50	16
	Status **|** ***Site Facility Type****: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
OTAY MESA ROAD WIDENING	NONE OTAY MESA RD SAN DIEGO CA 92173	NNW	0.25 / 1,331.16	24
	Status **|** ***Site Facility Type****: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
U S BORDER PATROL/BROWN FIELD	7060 BOEING ST SAN DIEGO CA 921731728	NNW	0.28 / 1,468.25	26
	Status **|** ***Site Facility Type****: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
PIPER RANCH BUS PARK	6464 OTAY MESA ROAD CHULA VISTA CA 92173	NW	0.44 / 2,331.03	32
	Status **|** ***Site Facility Type****: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA TRIPP SALVAGE LANDFILL	1890 CACTUS ROAD SAN DIEGO CA 92154	WNW	0.02 / 79.30	5
	Status **|** ***Site Facility Type****: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
TRIP LANDFILL/CACTUS RD PROPER	NONE W CACTUS S OTAY MESA R SAN DIEGO CA 92173	WNW	0.02 / 79.30	5
	Status **|** ***Site Facility Type****: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
BRITANNIA 40 OTAY	2380 BRITANNIA SAN DIEGO CA 92154	SE	0.46 / 2,451.68	33
	Status **|** ***Site Facility Type****: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
OTAY CANYON RANCH	2440 CACTUS ROAD SAN DIEGO CA 92154	SSW	0.47 / 2,497.08	34
	Status **|** ***Site Facility Type****: OPEN - SITE ASSESSMENT | CLEANUP PROGRAM SITE*			

County

LOP SANDIEGO - San Diego County - Local Oversight Program List

A search of the LOP SANDIEGO database, dated Jun 15, 2020 has found that there are 13 LOP SANDIEGO site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
U S BORDER PATROL/BROWN FIELD	7060 BOEING ST, SAN YSIDRO, CA 92173-1728 SAN YSIDRO CA ***Record ID*** **|** ***Record Status****: DEH1987-LSAM-H21496-001 | Completed*	NNW	0.28 / 1,491.90	27
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	N	0.34 / 1,818.29	30

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Record ID **|** ***Record Status***: *DEH1989-LSAM-H10618-014* | *Completed*			
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1989-LSAM-H10618-008* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1990-LSAM-H10618-019* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1990-LSAM-H10618-020* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1991-LSAM-H10618-023* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1987-LSAM-H10618-001* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1989-LSAM-H10618-004* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1999-LSAM-H10618-024* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1989-LSAM-H10618-015* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1989-LSAM-H10618-007* | *Completed*	N	0.34 / 1,818.29	30
SDCTY-GEN SER,BROWN FIELD	1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1990-LSAM-H10618-018* | *Completed*	N	0.34 / 1,818.29	30

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TRIP LANDFILL/CACTUS RD PROPER	0 W CACTUS RD, SAN YSIDRO, CA 92173 SAN YSIDRO CA ***Record ID*** **|** ***Record Status***: *DEH1991-LSAM-H32115-001* | *Completed*	WNW	0.02 / 79.30	5

HAZ SANDIEGO - San Diego County - Hazardous Materials Management Division Database

A search of the HAZ SANDIEGO database, dated May 1, 2022 has found that there are 61 HAZ SANDIEGO site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
HARRY SINGH & SON	CACTUS & AIRWAY RD, SAN DIEGO, 92173- CA	SW	0.01 / 66.19	4
AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154	NNW	0.16 / 821.59	12
MARTINEZ RANCH	2160 CACTUS, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	SW	0.20 / 1,050.50	16
MARTINEZ RANCH	2160 CACTUS RD CA 0	SW	0.20 / 1,050.50	16
1605 CACTUS, INC DBA: CALI-MART/ CHEVRON	1605 CACTUS RD, SAN DIEGO, 92154 CA	NNW	0.23 / 1,204.75	19
Noil USA Inc.	1605 CACTUS RD SAN DIEGO CA 92154	NNW	0.23 / 1,204.75	19
OTAY MESA TENT ONLY	6960 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	22
SANCHEZ TRUCK REPAIR	6960 CAMINO MAQUILADORA CA 0	NW	0.25 / 1,293.96	22
baja auto parts #2	6960 CAMINO MAQUILADORA E SAN DIEGO CA 92154	NW	0.25 / 1,293.96	22
PRECISE LIFT SYSTEMS	6960 CAMINO MAQUILADORA CA 0	NW	0.25 / 1,293.96	22
BAJA AUTO PARTS #2	6960 CAMINO MAQUILADORA, SUITE# L, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.25 / 1,293.96	22
OTAY ENGINE REBUILDERS	6960 CAMINO MAQUILADORA, SAN DIEGO, 92173- CA	NW	0.25 / 1,293.96	22
905 SMOG & AUTO REPAIR	6960 CAMINO MAQUILADORA, SUITE# G, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	22

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
JVS GENERAL AUTO REPAIR	6960 CAMINO MAQUILADORA #K, SAN DIEGO, 92173- CA	NW	0.25 / 1,293.96	22
CYCLONE LIFT INC	6960 CAMINO MAQUILADORA CA 0	NW	0.25 / 1,293.96	22
PAYLESS REGISTRATION SERVICE, INC.	6960 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	22
EAGLE SCIENTIFIC PRODUCTS	6960 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,293.96	22

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OTAY AUTO TRANSPORT (SAN DIEGO)	1938 Cactus RD, San Diego, CA 92154 San Diego CA 0	WNW	0.01 / 61.40	2
TRIP LANDFILL/CACTUS RD PROPER	0 W CACTUS S OTAY MESA R, SAN YSIDRO, CA 92173 SAN YSIDRO CA 92173	WNW	0.02 / 79.30	5
DANTZLER & BARNHART PROPERTY'S	1812 CACTUS RD CA 0	NW	0.02 / 80.67	6
AT&T WIRELESS #333	1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.07 / 358.82	7
NEXTEL CELL SITE CA 5807	1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.07 / 358.82	7
AT&T MOBILITY - SD 0333	1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.07 / 358.82	7
ASSOCIATED READY MIXED CONCRETE, INC	1696 CACTUS RD SAN DIEGO CA 92154	NW	0.07 / 358.82	7
CACTUS RECYCLING, INC.	1703 CACTUS RD CA 0	NNW	0.08 / 422.63	8

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
R&R AG CHEM INC	1703 CACTUS RD, SAN YSIDRO, 92173-2209 CA	NNW	0.08 / 422.63	8
ENERGY LABS, INC.	1695 CACTUS RD SAN DIEGO CA 92154	NNW	0.12 / 614.77	10
SKS INC	1695 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NNW	0.12 / 614.77	10
GM TIRES & ROAD SERVICE, INC	1690 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NNW	0.12 / 652.20	11
HM INT'L COSMETICS, INC	6965 CAMINO MAQUILADORA, SUITE# E, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.17 / 908.25	13
CAVAZOS TRANSPORTATION & REGISTRATION	6965 CAMINO MAQUILADORA CA 0	NW	0.17 / 908.25	13
H & J PRECISION TOOLS, INC	6965 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.17 / 908.25	13
PINNACLE INDUSTRIAL SUPPLY, INC; PINNACLE INDUSTRIAL SUPPLY, INC	6975 CAMINO MAQUILADORA, SAN DiEGO, CA 92154 SAN DiEGO CA 92154; 0	NW	0.17 / 915.11	14
THERMO KING OF SAN DIEGO	6975 CAMINO MAQUILADORA, SAN DIEGO, 92173-3504 CA	NW	0.17 / 915.11	14
OFFICE 2000	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.19 / 997.03	15
GM WHOLESALE & ROAD SERVICE TIRES, INC	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.19 / 997.03	15
SUPER SPICE COMPANY	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.19 / 997.03	15
LCA EXPORT	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.19 / 997.03	15

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Verizon Wireless: Mesa de Otay	2175 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	S	0.21 / 1,083.84	17
AZULEE AUTO RECON	2175 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	S	0.21 / 1,083.84	17
ADESA SAN DIEGO	2175 CACTUS RD SAN YSIDRO CA 92173	S	0.21 / 1,083.84	17
GLOBAL EXPORT TRANSPORT	6935 CAMINO MAQUILADORA CA 0	NW	0.22 / 1,185.81	18
INALERT DISTRIBUTION OF CA	6935 CAMINO MAQUILADORA CA 0	NW	0.22 / 1,185.81	18
PLANTRONICS INC	6935 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.22 / 1,185.81	18
PRO DESIGN FURNITURE	6935 CAMINO MAQUILADORA CA 0	NW	0.22 / 1,185.81	18
M.RIOS TRUCKING	6950 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.23 / 1,235.24	20
PRECISION EQUIPMENT	6950 CAMINO MAQUILADORA #C, SAN DIEGO, 92173- CA	NW	0.23 / 1,235.24	20
M RIOS TRUCKING, INC	6950 CAMINO MAQUILADORA, SAN YSIDRO CA 92173 CA	NW	0.23 / 1,235.24	20
AERODESIGN PRODUCTS, INC	6950 CAMINO MAQUILADORA, SUITE# D-E, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.23 / 1,235.24	20
AP MOTORSPORTS	6950 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.23 / 1,235.24	20
F & S TOWING	2230 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	SSW	0.24 / 1,280.79	21

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BORDER TRANSMISSIONS	6930 CAMINO MAQUILADORA #D, SAN DIEGO, 92173- CA	NW	0.25 / 1,294.15	23
NEW WORLD MOLDING	6930 CAM MAQUILADORA CA 0	NW	0.25 / 1,294.15	23
JD ELECTRIC & INDUSTRIAL SUPPLY	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	23
OTAY CARPET OUTLET INC	6930 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	23
ASERET FREIGHT FORWARDING	6930 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	23
Battery and Components Inc dba Commercial Battery	6930 CAMINO MAQUILADORA K & L SAN DIEGO CA 92154	NW	0.25 / 1,294.15	23
SMOG EXPRESS	6930 CAMINO MAQUILADORA, SUITE# A, SAN DIEGO, CA 92154 SAN DIEGO CA 0	NW	0.25 / 1,294.15	23
I-MACH INDUSTRIAL MACHINERY & PARTS	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	23
ECO STONE, INC	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	23
LARSON IRRIGATION, INC.	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	NW	0.25 / 1,294.15	23

UST SANDIEGO - San Diego County - UST List

A search of the UST SANDIEGO database, dated Apr 25, 2022 has found that there are 2 UST SANDIEGO site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
AT&T California - D3179	1670 CACTUS RD SAN DIEGO CA 92154	NNW	0.16 / 821.59	12

Record ID **|** ***Permit Status****: DEH2002-HUPFP-129788 | Permit Renewed*

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Noil USA Inc.	1605 CACTUS RD SAN DIEGO CA 92154	NNW	0.23 / 1,204.75	19
	Record ID **|** ***Permit Status***: *DEH2012-HUPFP-216147 | Permit Renewed*			

SAM SANDIEGO - San Diego County - Site Assessment and Mitigation Investigation Sites

A search of the SAM SANDIEGO database, dated Jun 30, 2020 has found that there are 5 SAM SANDIEGO site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MARTINEZ RANCH	2160 CACTUS RD San Diego CA	SW	0.20 / 1,050.50	16
U S BORDER PATROL/BROWN FIELD	7060 BOEING ST San Diego CA	NNW	0.28 / 1,468.25	26

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TRIP LANDFILL/CACTUS RD PROPER	0 W CACTUS RD San Diego CA	WNW	0.02 / 79.30	5
2380 BRITANNIA BLVD., SAN DIEGO	2380 BRITANNIA San Diego CA	SE	0.46 / 2,451.68	33
Otay Canyon Ranch	2440 CACTUS RD San Diego CA	SSW	0.47 / 2,497.08	34

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Nov 2, 2020 has found that there are 2 FINDS/FRS site(s) within approximately 0.02 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OTAY AUTO TRANSPORT	1938 CACTUS ROAD SAN DIEGO CA 92154	WNW	0.01 / 61.40	2
	Registry ID: *110070086028*			
IRMA TATUM	1812 CACTUS RD. SAN DIEGO CA 92154	NW	0.02 / 80.67	6
	Registry ID: *110070657576*			

FUDS - Formerly Used Defense Sites

A search of the FUDS database, dated May 26, 2021 has found that there are 1 FUDS site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BROWN FIELD NAVAL AUXILIARY AIR STATION	EAST OF CHULA VISTA CA	NW	0.57 / 3,025.10	35
	***FUDS Property No**: J09CA7278*			

State

SCH - School Property Evaluation Program Sites

A search of the SCH database, dated May 30, 2022 has found that there are 1 SCH site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
OCEAN VIEW HILLS MID SCH/INTERIM HOUSING	4919 DEL SOL BOULEVARD SAN DIEGO CA 92154	WNW	0.83 / 4,365.70	37
	***Estor/EPA ID**	**Cleanup Status**: 37020003 | NO ACTION REQUIRED AS OF 4/15/2004*		

CHMIRS - California Hazardous Material Incident Report System (CHMIRS)

A search of the CHMIRS database, dated Feb 8, 2022 has found that there are 2 CHMIRS site(s) within approximately 0.02 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NRC	Airway Rd & Cactus Ave Otay CA	SW	0.01 / 66.19	4
	***Notified Date**: 3/10/200411:15:03 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
San Diego Fire And Rescue	1950 Cactus Road San Diego CA 92154	W	0.01 / 40.24	1
	***Notified Date**: 10/16/2021 18:46*			

HAZNET - Hazardous Waste Manifest Data

A search of the HAZNET database, dated Oct 24, 2016 has found that there are 4 HAZNET site(s) within approximately 0.02 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OTAY AUTO TRANSPORT & STORAGE	1938 CACTUS RD SAN DIEGO CA 92154	WNW	0.01 / 61.40	2
TATUM CHARLES EIRMA TRUST	1812 CACTUS RD SAN DIEGO CA 921548105	NW	0.02 / 80.67	6

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CHARLES TATUM	1812 CACTUS RD SAN DIEGO CA 921548105	NW	0.02 / 80.67	6
CHARLES TATUM	1812 CACTUS RD SAN DIEGO CA 921540000	NW	0.02 / 80.67	6

CDO/CAO - Cease and Desist Orders and Cleanup and Abatement Orders

A search of the CDO/CAO database, dated Dec 6, 2021 has found that there are 2 CDO/CAO site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SESI Tripp Salvage	900 Cactus Rd San Ysidro CA 91973	NNW	0.26 / 1,383.61	25
Tripp Salvage Landfill	900 Cactus Rd San Ysidro CA 91973	NNW	0.26 / 1,383.61	25

CERS HAZ - California Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the CERS HAZ database, dated Apr 5, 2022 has found that there are 1 CERS HAZ site(s) within approximately 0.12 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ENERGY LABS, INC.	1695 CACTUS RD SAN DIEGO CA 92154	NNW	0.12 / 614.77	10

DELISTED HAZ - Delisted Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the DELISTED HAZ database, dated Nov 29, 2018 has found that there are 1 DELISTED HAZ site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
STEELCASE, INC	7510 AIRWAY RD SAN DIEGO CA 92154	E	0.32 / 1,676.21	28

EMISSIONS - Toxic Pollutant Emissions Facilities

A search of the EMISSIONS database, dated Dec 31, 2019 has found that there are 1 EMISSIONS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
OTAY MESA MOBIL	1605 CACTUS ROAD SAN DIEGO CA 92037	NNW	0.23 / 1,204.75	19

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key



Map: 1.0 Mile Radius


Order Number: 22062300084

Address: APN 646-100-77-00, San Diego, CA

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Eris Areas with Higher Elevation
- Eris Areas with Same Elevation
- Eris Areas with Lower Elevation
- Eris Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 22062300084

Address: APN 646-100-77-00, San Diego, CA

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Eris Areas with Higher Elevation
- Eris Areas with Same Elevation
- Eris Areas with Lower Elevation
- Eris Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius


Order Number: 22062300084

Address: APN 646-100-77-00, San Diego, CA

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Eris Areas with Higher Elevation
- Eris Areas with Same Elevation
- Eris Areas with Lower Elevation
- Eris Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.




Aerial Year: 2022

Order Number: 22062300084

Address: APN 646-100-77-00, San Diego, CA

Source: ESRI World Imagery

© ERIS Information Inc.



Topographic Map

Year: 2015

Order Number: 22062300084

Address: APN 646-100-77-00, CA

Quadrangle(s): Imperial Beach, CA; Otay Mesa, CA

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 1	W	0.01 / 40.24	501.37 / -8	San Diego Fire And Rescue 1950 Cactus Road San Diego CA 92154	CHMIRS

Control No: '21-5757
County: San Diego County
Year: 2021
URL:
Notified Date: 10/16/2021 18:46
Notified Date Time:

Spill Report View

Amount 1:
Amount 2:
Amount 3:
Type: OTHER
Water:
On Scene:
Other on Scene:
Other Notified:
Document Title: SPILL Report
Spill Site: Merchant/Business
Cause Desc for Other:
Person Notifying Cal OES:
Creation Date: 10/16/2021 06:46 PM
Received By:
Admin Agency:
Admin Agency 2:
Additional County:
Phone No:
Ext:
Pag Cell:

Hazardous Materials Spill Report

Contained: Stopped, Not contained
Date : 10/16/2021
Time: 1846
Incident Date: 10/16/2021
Incident Time: 1200
Water Involved: Yes
Waterway: Storm drain
Drink Wtr Impact: No
Detail for Other:
UPRR Rim No:
DOG Unit:
RWQCB Unit: 9
1 Substance: Hazardous Materials - Vehicle
1 Qty: =
1 Amount : 200
1 Measure: N/A
1 Type: OTHER
1 Other: Paint, Adhesives, and Sealants, etc.
1 Pipeline: No
1 Ves >= 300 Tons: No
Incident Location: 1950 Cactus Road
Additional County:
Injuries: No
Fatality: No
Evacuation: No
Known Impact:
Name:
Agency: San Diego Fire And Rescue
Phone:
Ext:
Pag Cell:
Control Cal OES: 21-5757
Control NRC:
Received By:
Cleanup By: Responsible Party
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

PRS Name:
PRS Agency:
PRS Phone:
PRS Ext:
PRS Pag Cell:
Sec Agency:
Admin Agency: San Diego County Health Services Department
Admin Agency 2:
Notification Info:
Notification List:
On Scene: Fire Dept.
Other on Scene:
Other Notified: None
Header Unknown: SAN DIEGO COUNTY APCD
Incident Desc:
Site: Merchant/Business
Reported Cause: Other
Description for Other : Fire
R R Crssing < 50 Ft:
Description: A large fire destroyed an estimated 200 vehicles at a wrecking yard. The San Diego Fire-Rescue Department crews, along with the Chula Vista and Imperial Beach fire departments and Cal Fire San Diego, responded to the site, south of State Route 905. The fire started near two businesses; an auto repair shop and a vehicle storage facility. The cause of the fire has not been determined. During the fire fighting efforts, an estimated 500,000 gallons of water was used to extinguish the fire. An unknown amount of the water and debris entered an on-site storm drain that leads to the Pacific Ocean. No injuries were reported. An investigation is ongoing and the cleanup is pending.

California Hazardous Material Incident Report System (2021)

Incident Date:	10/16/2021	**DOG No:**	
Time:	1200	**A2 Substance:**	
Spill Site:	Merchant/Business	**A2 Quantity:**	
Site:	Storm drain	**A2 Measure:**	
Contained:	Stopped,Not contained	**A2 Type:**	
Water:	Yes	**A2 Other:**	
Water Way:	Storm drain	**A2 Pipeline:**	No
Injuries Yes No:	No	**A2 Vessel 300 Tons:**	No
Injuries No:		**A3 Substance:**	
Fatals Yes No:	No	**A3 Quantity:**	
Fatals No:		**A3 Measure:**	
Evacs Yes No:	No	**A3 Type:**	
Evacs No:		**A3 Other:**	
Cleanup:	Responsible Party	**A3 Pipeline:**	No
Cause:	Other	**A3 Vessel 300 Tons:**	No
A1 Substance:	Hazardous Materials - Vehicle	**Cause Other:**	Fire
A1 Other:	Paint, Adhesives, and Sealants, etc.	**Drnkng Wtr Impacted:**	No
A1 Quantity:	200	**Known Impact:**	
A1 Measure:	N/A	**City:**	San Diego
A1 Type:	OTHER	**County:**	San Diego County
A1 Pipeline:	No	**ZIP:**	92154
A1 Vessel 300 Tons:	No		

Admin Agency: San Diego County Health Services Department
Notification Area: AA/CUPA,DTSC,RWQCB,US EPA,USFWS,DFW-OSPR,AIR RESOURCES BD,COASTAL COM,CDPH-D.O., LANDS,PARKS & REC,USCG,Co/WP,Co/Hlth,Co/E-Hlth
Description: A large fire destroyed an estimated 200 vehicles at a wrecking yard. The San Diego Fire-Rescue Department crews, along with the Chula Vista and Imperial Beach fire departments and Cal Fire San Diego, responded to the site, south of State Route 905. The fire started near two businesses; an auto repair shop and a vehicle storage facility. The cause of the fire has not been determined. During the fire fighting efforts, an estimated 500,000 gallons of water was used to extinguish the fire. An unknown amount of the water and debris entered an on-site storm drain that leads to the Pacific Ocean. No injuries were reported. An investigation is ongoing and the cleanup is pending.
Location: 1950 Cactus Road

2	1 of 3	WNW	0.01 / 61.40	498.23 / -11	**OTAY AUTO TRANSPORT & STORAGE** **1938 CACTUS RD** **SAN DIEGO CA 92154**	HAZNET

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SIC Code:	9999	**Mailing City:**	SAN DIEGO
NAICS Code:	99999	**Mailing State:**	CA
EPA ID:	CAL000395792	**Mailing Zip:**	92154
Create Date:	4/14/2014 4:08:08 PM	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	MANUEL RAMIREZ
Inact Date:	6/30/2014	**Owner Addr 1:**	1938 CACTUS RD
County Code:	37	**Owner Addr 2:**	
County Name:	San Diego	**Owner City:**	SAN DIEGO
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	1938 CACTUS RD	**Owner Zip:**	92154
Mailing Addr 2:		**Owner Phone:**	6192402273
Owner Fax:			

Contact Information

--	--
Contact Name:	MANUEL RAMIREZ
Street Address 1:	1938 CACTUS RD
Street Address 2:	
City:	SAN DIEGO
State:	CA
Zip:	92154
Phone:	6192402273
--	--

2	2 of 3	WNW	0.01 / 61.40	498.23 / -11	**OTAY AUTO TRANSPORT (SAN DIEGO)** **1938 Cactus RD, San Diego, CA 92154** **San Diego CA 0**	**HAZ SANDIEGO**

Record ID:	DEH2016-HUPFP-002285	**GIS Record ID:**	DEH2016-HUPFP-002285
Facility Name:		**GIS Facility City:**	San Diego
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	0
Facility Latitude:		**GIS Fac Longitude:**	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	OTAY AUTO TRANSPORT (SAN DIEGO)		
GIS Facility Address:	1938 Cactus RD, San Diego, CA 92154		
Tank Owner Name:			

Hazardous Materials Inspection Violations

Container Tank ID:		**Inspection No:**	5431202
Facility ID No:	37-000-002285	**Inspection Type:**	Routine
ID:	39860	**Inspection Date:**	05/19/2014 02:52:00 PM
UST ID:		**Compliance Date:**	03/10/2016 12:00:00 AM
Permit Status:	Permit Suspended	**Last Updated:**	10/25/2018 04:26:38 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	HMD0226 Did not accumulate waste in a container or tank. (40 CFR 262.34(d)(2).) 22 CCR 66262.34(d)(2)		

Container Tank ID:		**Inspection No:**	5431202
Facility ID No:	37-000-002285	**Inspection Type:**	Routine
ID:	39864	**Inspection Date:**	05/19/2014 02:52:00 PM
UST ID:		**Compliance Date:**	01/21/2016 12:00:00 AM
Permit Status:	Permit Suspended	**Last Updated:**	10/25/2018 04:26:38 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Minor		
Violation Code:	1010002 HMBP not submitted to the CUPA in CERS. HSC 25508(a)(1)(A); HSC 25404(e)(4); 27 CCR 15188(a), (d)		

Container Tank ID:		**Inspection No:**	5431202
Facility ID No:	37-000-002285	**Inspection Type:**	Routine

ID:	39862	**Inspection Date:**	05/19/2014 02:52:00 PM
UST ID:		**Compliance Date:**	03/10/2016 12:00:00 AM
Permit Status:	Permit Suspended	**Last Updated:**	10/25/2018 04:26:38 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	3010010 Failed to maintain uniform hazardous waste manifest, consolidated manifest, or bills of lading copies for 3 years. HSC 25160.2(b)(3), 25185(a)(4); 22 CCR 66262.40(a)		

Container Tank ID:		**Inspection No:**	5431202
Facility ID No:	37-000-002285	**Inspection Type:**	Routine
ID:	39863	**Inspection Date:**	05/19/2014 02:52:00 PM
UST ID:		**Compliance Date:**	01/21/2016 12:00:00 AM
Permit Status:	Permit Suspended	**Last Updated:**	10/25/2018 04:26:38 AM
Active Permit:	false	**NOV:**	true
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905		

Container Tank ID:		**Inspection No:**	5431202
Facility ID No:	37-000-002285	**Inspection Type:**	Routine
ID:	39861	**Inspection Date:**	05/19/2014 02:52:00 PM
UST ID:		**Compliance Date:**	03/10/2016 12:00:00 AM
Permit Status:	Permit Suspended	**Last Updated:**	10/25/2018 04:26:38 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	3030017 Failed to properly close hazardous waste container(s). (40 CFR 262.34(d)(2); 265.173.) 22 CCR 66262.34(d)(2)		

Container Tank ID:		**Inspection No:**	5431202
Facility ID No:	37-000-002285	**Inspection Type:**	Routine
ID:	39859	**Inspection Date:**	05/19/2014 02:52:00 PM
UST ID:		**Compliance Date:**	03/10/2016 12:00:00 AM
Permit Status:	Permit Suspended	**Last Updated:**	10/25/2018 04:26:38 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	3030007 Failed to properly label/date hazardous waste container and/or tank. 22 CCR 66262.34(f)		

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:	10503400	**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Permit Suspended	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:	No	**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	0
SIC Code:		**X Coord:**	0
NAICS Code:		**Y Coord:**	0
Disclose Qty Haz Mat:		**Kiva Per Typ:**	
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334159.4933
UST Facility:		**Point Y:**	1785374.8833
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Y	**Side:**	
Recycle100:		**X Map Coord:**	-116.98837565140082
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.56284519335829

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:	1938 Cactus Rd	**Bill Code 3:**	
Parcel No:		**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	1938 Cactus RD		
Business Type:	Not Applicable		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record address		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

2	3 of 3	WNW	0.01 / 61.40	498.23 / -11	OTAY AUTO TRANSPORT 1938 CACTUS ROAD SAN DIEGO CA 92154	FINDS/FRS

Registry ID:	110070086028
FIPS Code:	06073
HUC Code:	
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	07-AUG-17
Update Date:	
Interest Types:	ICIS-NPDES UNPERMITTED
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	
Census Block Code:	
EPA Region Code:	09
County Name:	SAN DIEGO COUNTY
US/Mexico Border Ind:	
Latitude:	
Longitude:	
Reference Point:	
Coord Collection Method:	
Accuracy Value:	
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070086028
Program Acronyms:	

NPDES:CAW445071

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of 1	W	0.01 / 65.49	499.72 / -9	YVETTE ALCARAZ 1942 CACTUS ROAD SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID: CAC003145547
Gen Status Universe: No Report
Contact Name: YVETTE ALCARAZ
Contact Address: 1942 CACTUS ROAD , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext: 619-496-1226
Contact Email: TERRI.KLICKA@NORTH-STATE.COM
Contact Country:
County Name: SAN DIEGO
EPA Region: 09
Land Type:
Receive Date: 20211027
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20211027
Handler Name: YVETTE ALCARAZ
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: YVETTE ALCARAZ
Date Became Current:
Date Ended Current:
Phone: 619-496-1226
Source Type: Implementer
Street No:
Street 1: 1942 CACTUS ROAD
Street 2:
City: SAN DIEGO
State: CA
Country:
Zip Code: 92154

Owner/Operator Ind: Current Owner
Type: Other
Street No:
Street 1: 1942 CACTUS ROAD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	YVETTE ALCARAZ	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-496-1226	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

---

4 | **1 of 2** | **SW** | **0.01 / 66.19** | **510.59 / 2** | **HARRY SINGH & SON**
CACTUS & AIRWAY RD, SAN DIEGO, 92173-
CA

HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-199071	**GIS Record ID:**	
Facility Name:	HARRY SINGH & SON	**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	
Facility ZipCode:		**GIS Fac Latitude:**	
Facility Latitude:		**GIS Fac Longitude:**	
Facility Longitude:			
Facility Address:	CACTUS & AIRWAY RD, SAN DIEGO, 92173-		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

---

4 | **2 of 2** | **SW** | **0.01 / 66.19** | **510.59 / 2** | **NRC**
Airway Rd & Cactus Ave
Otay CA

CHMIRS

Control No:	04-1340	**Notified Date:**	3/10/200411:15:03 AM
County:	San Diego County	**Notified Date Time:**	
Year:	2004		
URL:			

California Hazardous Material Incident Report System (as of 1997 to 2005)

Contained:	Unknown	**Bbls:**	0
Substance:	Unknown Material	**Cups:**	0
Incident Date:	3/9/200412:00:00 AM	**Cu Ft:**	0
No of Injuries:	0	**Gals:**	0.000000
No of Fatals:	0	**Grams:**	0
No of Evacs:	0	**Lbs:**	0
Cleanup:	Unknown	**Liters:**	0
Water:		**Oz:**	0
Water Way:		**Pts:**	0
City:	Otay	**Qts:**	0
County:	San Diego County	**Sheen:**	0
ZIP:		**Tons:**	0
Site:	Road,Other	**Unknown:**	0
Admin Agency:	San Diego County Health Services Dept.		
Location:	Airway Rd & Cactus Ave		
Description:	Per NRC FAX: The caller stated that there are several abandoned drums in a field.		

---

5 | **1 of 6** | **WNW** | **0.02 / 79.30** | **494.24 / -15** | **TRIP LANDFILL/CACTUS RD PROPER**
0 W CACTUS RD
San Diego CA

SAM SANDIEGO

Record ID:	DEH1991-LSAM-H32115-001	**Primary Parcel:**	YES
Record ID (DEH Lyr):	DEH1991-LSAM-H32115-001	**Primary Address:**	YES
ID:	2532	**Address Type:**	ALIAS
Object ID:	2530	**Street String:**	0 W CACTUS RD
SWRCB Global ID:	T0608106121	**Community:**	San Diego
Feature ID:	6461006900	**Zip Code:**	92173
Parcel No:	646-100-69-00	**Zip Community:**	92154
Case No:	H32115-001	**Jurisdiction:**	SAN DIEGO
H No:	H32115	**Census Tract:**	100.15
KIVA per Tp per No:	6SAM H32115	**GT Global ID:**	T0608106121

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Status:	Completed	**GT RB Case No:**	
Historical Name:	TRIP LANDFILL	**GT Status:**	Completed - Case Closed
Record Name:	TRIP LANDFILL/CACTUS RD PROPER	**GT Status Date:**	6/10/2012 8:00 PM
Project Name:	TRIP LANDFILL/CACTUS RD PROPER	**GT Case Type:**	Cleanup Program Site
Record Status:	Completed	**GT Lead Agency:**	SAN DIEGO COUNTY LOP
Record Type:	SAM Investigation	**GT CUF Case:**	NO
Record Alias:	SAM Investigation	**GT County:**	San Diego
Date:	11/07/1991	**GT Longitude:**	-116.98956614
Per Type:	LWQD	**GT Latitude:**	32.56322004
DEH Permit Owner:		**Agency Name:**	COSD
Fire Agency:	SAN DIEGO	**Lead Agency:**	DEH/SAM
Point X:	6333943.53015172	**Lead Agcy Date:**	11/6/1991 7:00 PM
Point Y:	1785428.7299803	**Opened Date:**	11/6/1991 7:00 PM
Latitude GS84:	32.56296	**ThomasBros Map Gd:**	1351 D 2
Longitude GS84:	-116.9890888	**Funding:**	N - Non-Billable
Watershed Basin:	911.12	**BOS District:**	1
Water Purveyor:	SAN DIEGO	**Short Notes:**	

Address: 0 W CACTUS RD, SAN YSIDRO CA 92173
Case Type:
Geo SRC: Mapped to XY from previous SAM Layer
Record Type (DEH Lyr): LUEG-DEH/LWQD/SAM Investigation/NA
Source File: Citizen Access DEH Site Assessment and Mitigation Investigation Sites; San Diego Site Assessment and Mitigation Investigation Sites

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	2 of 6	WNW	0.02 / 79.30	494.24 / -15	TRIP LANDFILL/CACTUS RD PROPER NONE W CACTUS S OTAY MESA R SAN DIEGO CA 92173	CLEANUP SITES

Global ID:	T0608106121	**Latitude:**	32.5632200393743
Status:	COMPLETED - CASE CLOSED	**Longitude:**	-116.989566137573
Status Date:	6/11/2012	**County:**	SAN DIEGO

Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:		**Potential COC:**	
Local Case No:	H32115-001	**How Discovered:**	
Begin Date:	11/7/1991	**Stop Method:**	Other Means
Lead Agency:	SAN DIEGO COUNTY LOP	**Stop Description:**	OTHER MEANS
Local Agency:	SAN DIEGO COUNTY LOP	**Case Worker:**	VAP
CUF Case:	NO	**Military DoD Site:**	No
CalEnvScreen Score:	66-70%	**Leak Reported Dt:**	1991-11-07 00:00:00
EPA Region:	9	**No Further Action Dt:**	2012-06-11 00:00:00
Qty Rlsd Gallons:			

Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community:
Coordinate Source: Google Map Move
Discharge Cause: Other
Discharge Source:
File Location: Local Agency
Site History:

This case was opened in November 1991; it involved the dumping of debris at a site that was later determined to be hazardous debris. This case was transferred in 1996 to the LEA as a Site Designation Case - Solid Waste Information System (SWIS) 37CR0011; therefore, the SAM case can be administratively closed.

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2012-06-11 00:00:00
Action: Closure/No Further Action Letter

Action Type: Other
Date: 1991-11-07 00:00:00
Action: Leak Stopped

Action Type: Other
Date: 1991-11-07 00:00:00
Action: Leak Began

Action Type: Other
Date: 1991-11-07 00:00:00
Action: Leak Reported

Action Type: Other
Date: 1991-11-07 00:00:00
Action: Leak Discovery

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2012-06-11 00:00:00

Status: Open - Site Assessment
Status Date: 1991-11-07 00:00:00

Status: Open - Case Begin Date
Status Date: 1991-11-07 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: Voluntary Assistance Program (VAP)
Phone No:
Organization Name: SAN DIEGO COUNTY LOP
Email: deh.sam@sdcounty.ca.gov
Address: P.O. Box 129261
City: SAN DIEGO

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608106121
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 6/11/2012
Potential COC: ,
Potential Media of Concern: SOIL
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: H32115-001
CASEWORKER: Voluntary Assistance Program (VAP)
SAN DIEGO RWQCB (REGION 9)
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608106121&tabname=regulatoryhistory
Site History:

This case was opened in November 1991; it involved the dumping of debris at a site that was later determined to be hazardous debris. This case was transferred in 1996 to the LEA as a Site Designation Case - Solid Waste Information System (SWIS) 37CR0011; therefore, the SAM case can be administratively closed.

Sites from GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions ***Action Date:*** 6/11/2012
Action: Closure/No Further Action Letter ***Received Issue Date:*** 6/11/2012
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608106121&enforcement_id=6124486&temptable=ENFORCEMENT
Title Description Comments:

Administrative Closure Memo

Action Type: Leak Action ***Action Date:*** 11/7/1991
Action: Leak Stopped ***Received Issue Date:***
Doc Link:
Title Description Comments:

Action Type: Leak Action ***Action Date:*** 11/7/1991
Action: Leak Reported ***Received Issue Date:***
Doc Link:
Title Description Comments:

Action Type: Leak Action ***Action Date:*** 11/7/1991
Action: Leak Discovery ***Received Issue Date:***
Doc Link:
Title Description Comments:

Action Type: Leak Action ***Action Date:*** 11/7/1991
Action: Leak Began ***Received Issue Date:***
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Documents

Document Type: Site Documents ***Submitted:***
Document Date: 6/11/2012 ***Submitted By:*** ELLEN BEACON (REGULATOR)
Size :
Title: ADMINISTRATIVE CLOSURE MEMO
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608106121&enforcement_id=6124486
Type: CLOSURE/NO FURTHER ACTION LETTER

Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 6/11/2012

Status: Open - Case Begin Date
Date: 11/7/1991

Status: Open - Site Assessment
Date: 11/7/1991

5	3 of 6	WNW	0.02 / 79.30	494.24 / -15	TRIP LANDFILL/CACTUS RD PROPER 0 W CACTUS S OTAY MESA R, SAN YSIDRO, CA 92173 SAN YSIDRO CA 92173	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-132115	**GIS Record ID:**	DEH2002-HUPFP-132115
Facility Name:		**GIS Facility City:**	SAN YSIDRO
Facility City:		**GIS Facility ZipCode:**	92173
Facility ZipCode:		**GIS Fac Latitude:**	32.56296
Facility Latitude:		**GIS Fac Longitude:**	-116.9890888
Facility Longitude:			
Facility Address:			
GIS Facility Name:	TRIP LANDFILL/CACTUS RD PROPER		
GIS Facility Address:	0 W CACTUS S OTAY MESA R, SAN YSIDRO, CA 92173		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461006900
SIC Code:		**X Coord:**	6333941.324
NAICS Code:		**Y Coord:**	1785383.63
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 132115
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333941.32412
UST Facility:		**Point Y:**	1785383.63
Total No USTs:		**Lat GS84:**	32.56296
No of Tanks:		**Lon GS84:**	-116.9890888
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.98908389807217
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56286498381347
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-100-69-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	0 W CACTUS S OTAY MESA R		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	4 of 6	WNW	0.02 / 79.30	494.24 / -15	TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA TRIPP SALVAGE LANDFILL 1890 CACTUS ROAD SAN DIEGO CA 92154	CLEANUP SITES

Global ID: SL209274202
Status: COMPLETED - CASE CLOSED
Status Date: 10/17/2017
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download
Latitude: 32.5636422854041
Longitude: -116.989181041717
County: SAN DIEGO

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 2092700
Local Case No:
Begin Date: 5/1/1997
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Local Agency:
CUF Case: NO
CalEnvScreen Score: 56-60%
EPA Region: 9
Qty Rlsd Gallons:
Potential Media of Concern: Other Groundwater (uses other than drinking water), Soil
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community:
Coordinate Source: Google Map Move
Discharge Cause:
Discharge Source:
File Location: Regional Board
Site History:

Potential COC: Copper, Lead, Zinc
How Discovered: * RPR
Stop Method:
Stop Description:
Case Worker:
Military DoD Site: No
Leak Reported Dt: 1965-01-02 00:00:00
No Further Action Dt: 2017-10-17 00:00:00

Part of Tripp Salvage Landfill. Automobile dismantling waste was placed on the Sesi Property from approximately 1968 to 1977, and burn ash-contaminated soil was placed in on the property in 1987. This material was covered with fill from other landfills in the area. It is estimated that the waste extends to a depth of approximately 65 feet. Groundwater samples collected from this property in 1998 reportedly contained VOCs, SVOCs, and metals. A Revegetation Plan prepared 2006 proposed excavation of a portion of the waste and placement of a soil cap over the remaining waste. According to the County LEA, soil cap design and associated grading plans have been submitted to City of San Diego for review but the cap has not yet been constructed. On September 25, 1996, the County of San Diego Department of Environmental Health (DEH) was designated by the California Environmental Protection Agency (CalEPA) Site Designation Committee as the Administering Agency for the Sesi Group / Tripp Salvage Landfill.

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2017-10-17 00:00:00
Action: Closure/No Further Action Letter - #96-18

Action Type: RESPONSE
Date: 2017-08-15 00:00:00
Action: Request for Closure

Action Type: ENFORCEMENT
Date: 2015-11-19 00:00:00
Action: Deed Restriction / Land Use Restriction / Covenant - #2015-0608139

Action Type: REMEDIATION
Date: 2013-12-01 00:00:00
Action: Capping

Action Type: RESPONSE
Date: 2013-10-16 00:00:00
Action: Other Report / Document

Action Type: RESPONSE

Date: 2012-10-11 00:00:00
Action: Site Investigation Workplan

Action Type: RESPONSE
Date: 2011-05-01 00:00:00
Action: Other Workplan

Action Type: ENFORCEMENT
Date: 2008-08-21 00:00:00
Action: Cost Recovery Agreement / N. of Reimbursement

Action Type: ENFORCEMENT
Date: 2005-04-27 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 1996-09-25 00:00:00
Action: AB 2061 - Designation - #96-18

Action Type: Other
Date: 1965-01-02 00:00:00
Action: Leak Reported

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2017-10-17 00:00:00

Status: Open - Eligible for Closure
Status Date: 2017-08-07 00:00:00

Status: Open - Inactive
Status Date: 2009-06-25 00:00:00

Status: Open - Remediation
Status Date: 2002-08-01 00:00:00

Status: Open - Case Begin Date
Status Date: 1997-05-01 00:00:00

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=SL209274202
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 10/17/2017
Potential COC: COPPER, LEAD, ZINC
Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER), SOIL
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL
LAND USE COVENANT
Future Land Use: SENSITIVE USE
Cleanup Oversight Agencies: SAN DIEGO RWQCB (REGION 9) (LEAD) - CASE #: 2092700
SAN DIEGO COUNTY LOP
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=SL209274202&tabname=regulatoryhistory

Site History:

Part of Tripp Salvage Landfill. Automobile dismantling waste was placed on the Sesi Property from approximately 1968 to 1977, and burn ash-contaminated soil was placed in on the property in 1987. This material was covered with fill from other landfills in the area. It is estimated that the waste extends to a depth of approximately 65 feet. Groundwater samples collected from this property in 1998 reportedly contained VOCs, SVOCs, and metals. A Revegetation Plan prepared 2006 proposed excavation of a portion of the waste and placement of a soil cap over the remaining waste. According to the County LEA, soil cap design and associated grading plans have been submitted to City of San Diego for review but the cap has not yet been constructed.

On September 25, 1996, the County of San Diego Department of Environmental Health (DEH) was designated by the California Environmental Protection Agency (CalEPA) Site Designation
Committee as the Administering Agency for the Sesi Group / Tripp Salvage Landfill.

Sites from GeoTracker Search - Cleanup Action Report

Action Type: CAPPING ***Begin Date:*** 12/1/2013
Phase: ***End Date:*** 6/12/2014
Description:
Contaminant Mass Removed:

Sites from GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions ***Action Date:*** 10/17/2017
Action: Closure/No Further Action Letter - #96-18 ***Received Issue Date:*** 10/17/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6366329&temptable=ENFORCEMENT
Title Description Comments:

CERTIFICATE OF COMPLETION

Action Type: Response Requested - Other ***Action Date:*** 8/15/2017
Action: Request for Closure ***Received Issue Date:*** 8/15/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL209274202&doc_id=5933444
Title Description Comments:

DEH Notice of Intent to Issue Certificate of Completion

Action Type: Other Regulatory Actions ***Action Date:*** 11/19/2015
Action: Deed Restriction / Land Use Restriction / Covenant - #2015-0608139 ***Received Issue Date:*** 11/19/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6366327&temptable=ENFORCEMENT
Title Description Comments:

Action Type: Cleanup Action ***Action Date:*** 12/1/2013
Action: Capping ***Received Issue Date:***
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other ***Action Date:*** 10/16/2013
Action: Other Report / Document ***Received Issue Date:*** 10/16/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL209274202&doc_id=6094730
Title Description Comments:

Approval of the Cactus Road - AKA Tripp Salvage Disposal Site Remediation Project, Facility No. 37-CR-001

Action Type: Response Requested - Workplans ***Action Date:*** 10/11/2012
Action: Site Investigation Workplan ***Received Issue Date:*** 10/11/2012
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL209274202&doc_id=6094729
Title Description Comments:

Updated Hazardous Material Technical Study - Otay Mesa Community Plan Update

Action Type: Response Requested - Workplans **Action Date:** 5/1/2011
Action: Other Workplan **Received Issue Date:** 5/1/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL209274202&doc_id=6094728
Title Description Comments:

Revised Soil Management Plan Sewer Force Main Installation - Cactus Road at SR-905, San Diego, CA

Action Type: Agreements **Action Date:** 8/21/2008
Action: Cost Recovery Agreement / N. of Reimbursement **Received Issue Date:** 8/21/2008
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6220970&temptable=ENFORCEMENT
Title Description Comments:

Annual Estimation for Site Cleanup Cost Recovery Program - SESI Group Property

Action Type: Other Regulatory Actions **Action Date:** 4/27/2005
Action: Staff Letter **Received Issue Date:** 4/27/2005
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6220971&temptable=ENFORCEMENT
Title Description Comments:

NEW REGULATIONS - ELECTRONIC SUBMITTAL OF INFORMATION

Action Type: Other Regulatory Actions **Action Date:** 9/25/1996
Action: AB 2061 - Designation - #96-18 **Received Issue Date:** 9/25/1996
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6339252&temptable=ENFORCEMENT
Title Description Comments:

CalEPA Site Designation Committee Resolution No. 96-18

Action Type: Leak Action **Action Date:** 1/2/1965
Action: Leak Reported **Received Issue Date:**
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Deed Restrictions

Date Recorded: 11/19/2015
Site Management Requirements: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL, LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3665352940/Deed%20Restriction.pdf

Sites from GeoTracker Search - Documents

Document Type: Site Documents **Submitted:**
Document Date: 10/17/2017 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: CERTIFICATE OF COMPLETION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6366329
Type: CLOSURE/NO FURTHER ACTION LETTER

Document Type: Site Documents **Submitted:**
Document Date: 8/15/2017 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: DEH NOTICE OF INTENT TO ISSUE CERTIFICATE OF COMPLETION - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&document_id=5933444
Type: REQUEST FOR CLOSURE

Document Type: Site Documents **Submitted:**

Document Date: 11/19/2015 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6366327
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT

Document Type: Site Documents **Submitted:**
Document Date: 10/16/2013 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: APPROVAL OF THE CACTUS ROAD - AKA TRIPP SALVAGE DISPOSAL SITE REMEDIATION PROJECT, FACILITY NO. 37-CR-001
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&document_id=6094730
Type: OTHER REPORT / DOCUMENT

Document Type: Site Documents **Submitted:**
Document Date: 10/11/2012 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: UPDATED HAZARDOUS MATERIAL TECHNICAL STUDY - OTAY MESA COMMUNITY PLAN UPDATE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&document_id=6094729
Type: SITE INVESTIGATION WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 5/1/2011 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: REVISED SOIL MANAGEMENT PLAN SEWER FORCE MAIN INSTALLATION - CACTUS ROAD AT SR-905, SAN DIEGO, CA
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&document_id=6094728
Type: OTHER WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 8/21/2008 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: ANNUAL ESTIMATION FOR SITE CLEANUP COST RECOVERY PROGRAM - SESI GROUP PROPERTY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6220970
Type: COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT

Document Type: Site Documents **Submitted:**
Document Date: 4/27/2006 **Submitted By:** (REGULATOR)
Size : 23 KB
Title: NEW REGULATIONS - ELECTRONIC SUBMITTAL OF INFORMATION
Title Link: https://geotracker.waterboards.ca.gov/site_documents/1836262345/Sesi%20Group%2Epdf
Type: LETTER

Document Type: Site Documents **Submitted:**
Document Date: 8/9/2005 **Submitted By:** JOHN ODERMATT (REGULATOR)
Size : 42 KB
Title: 1997 ADDITION TO SLIC REIMBURSEMENT LIST
Title Link: https://geotracker.waterboards.ca.gov/site_documents/6809635758/sesislic%2Epdf
Type:

Document Type: Site Documents **Submitted:**
Document Date: 4/27/2005 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: NEW REGULATIONS - ELECTRONIC SUBMITTAL OF INFORMATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6220971
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 9/25/1996 **Submitted By:** JOHN P. ANDERSON (REGULATOR)
Size :
Title: CALEPA SITE DESIGNATION COMMITTEE RESOLUTION NO. 96-18
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6339252
Type: AB 2061 - DESIGNATION

Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 10/17/2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Status: Open - Eligible for Closure
Date: 8/7/2017

Status: Open - Inactive
Date: 6/25/2009

Status: Open - Remediation
Date: 8/1/2002

Status: Open - Case Begin Date
Date: 5/1/1997

Sites from GeoTracker Search - Related Cases

Identifier: L10007631848
Status: COMPLETED - CASE CLOSED
Association: Related Global ID
Description:
Project Name: BARNHART AND DANTZLER PROPERTY
Project Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=L10007631848
Address: 900 CACTUS ROAD
City: SAN DIEGO

5	5 of 6	WNW	0.02 / 79.30	494.24 / -15	TRIP LANDFILL/CACTUS RD PROPER 0 W CACTUS RD, SAN YSIDRO, CA 92173 SAN YSIDRO CA	LOP SANDIEGO

SWRCB Global ID: T0608106121
Record ID: DEH1991-LSAM-H32115-001
Record Status: Completed
Opened Date: 11/7/1991
Case Type:
Historical Name: TRIP LANDFILL
Lead Agency: DEH/SAM
Lead Agency Date: 11/7/1991
Funding: N - Non-Billable
Fire Agency: SAN DIEGO
Water Purveyor: SAN DIEGO
File Case Type: CASES WITH NO CASE TYPE
Parcel No: 646-100-69-00
Census Tract: 100.15
Zip Code 2: 92154
Community: San Diego
Jurisdiction: SAN DIEGO
Watershed Basin No: 911.12
Latitude GS 84: 32.5629600
Longitude GS 84: -116.9890888
X Map Coord: 6333941.324
Y Map Coord: 1785383.630

5	6 of 6	WNW	0.02 / 79.30	494.24 / -15	TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA Tripp Salvage Landfill 1890 CACTUS ROAD SAN DIEGO CA 92154	DEED

Global ID: SL209274202
Site Type: Cleanup Program Site
Status: Completed - Case Closed
Status Date: 10/17/2017
County: San Diego
Latitude: 32.5636422854041
Longitude: -116.989181041717
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=SL209274202

Regulatory Activities GeoTracker Download

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant - #2015-0608139
Action Date: 11/19/2015

Sites from GeoTracker Search - Regulatory Activities

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Action: Deed Restriction / Land Use Restriction / Covenant - #2015-0608139
Action Type: Other Regulatory Actions
Action Date: 11/19/2015
Received Issue Date: 11/19/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL209274202&enforcement_id=6366327&temptable=ENFORCEMENT
Title Description Comments:

Sites from GeoTracker Search - Deed Restrictions

Date Recorded: 11/19/2015
Site Management Requirements: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL, LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3665352940/Deed%20Restriction.pdf

---

6	1 of 6	NW	0.02 / 80.67	495.59 / -13	DANTZLER & BARNHART PROPERTY'S 1812 CACTUS RD CA 0	HAZ SANDIEGO

Record ID: DEH2002-HUPFP-134129
Facility Name:
Facility City:
Facility ZipCode:
Facility Latitude:
Facility Longitude:
Facility Address:
GIS Facility Name: DANTZLER & BARNHART PROPERTY'S
GIS Facility Address: 1812 CACTUS RD
Tank Owner Name:

GIS Record ID: DEH2002-HUPFP-134129
GIS Facility City:
GIS Facility ZipCode: 0
GIS Fac Latitude: 32.5643336
GIS Fac Longitude: -116.9890314

HMD Permits Map Data

GIS Facility ID:
GIS CERS ID:
GIS Record Type: LUEG-DEH/HMD/UPFP/Facility
Per Type:
Per Sub Type:
Per Cat:
Record Status: Completed
HW Tier:
LRG QTY MW Gener:
EPA ID No:
RMP CAL ARP:
Tank Owner:
SIC Code:
NAICS Code:
Disclose Qty Haz Mat:
Exp Date:
Own/Operate USTs :
UST Facility:
Total No USTs:
No of Tanks:
Own Oper APS: N
Tot APSA Cap: 0
Capacity LR:
Haz Waste G:
Recycle100:
Onsite Haz Waste Tre:
RCRA LRG Qty:
Haz Wst Coll Site:
Accept Offs:
Universal Waste Han:
Toxic Gas:

Status:
ER Contact:
ER Con Work Ph:
Census Tract:
Parcel Zip:
Community:
Jurisdiction:
Basin No:
BOS Dist:
Tbpg Grid:
Insp Dist:
Feature ID: 6461004800
X Coord: 6333952.661
Y Coord: 1785907.43
Kiva Per Typ: HK07 134129
Agency Name: COSD
Point X: 6333952.66104
Point Y: 1785907.43014
Lat GS84: 32.5643336
Lon GS84: -116.9890314
Loc Name:
Score:
Match Type:
Side:
X Map Coord: -116.98905915504038
Y Map Coord: 32.564304774675485
User Fld:
Addr Type:
ARC Address:
ARC City:
ARC Zipcode:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-100-48-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	1812 CACTUS RD		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

6	2 of 6	NW	0.02 / 80.67	495.59 / -13	**CHARLES TATUM** **1812 CACTUS RD** **SAN DIEGO CA 921548105**	HAZNET

SIC Code:		**Mailing City:**	IMPERIAL BEACH
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC002684332	**Mailing Zip:**	919320000
Create Date:	1/23/2012	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	CHARLES TATUM
Inact Date:	7/22/2012	**Owner Addr 1:**	737 HOLLY AVE
County Code:	37	**Owner Addr 2:**	
County Name:	San Diego	**Owner City:**	IMPERIAL BEACH
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	737 HOLLY AVE	**Owner Zip:**	919320000
Mailing Addr 2:		**Owner Phone:**	6194103877
Owner Fax:			

Contact Information

--	--
Contact Name:	CHARLES TATUM
Street Address 1:	737 HOLLY AVE
Street Address 2:	
City:	IMPERIAL BEACH
State:	CA
Zip:	919320000
Phone:	6194103877
--	--

6	3 of 6	NW	0.02 / 80.67	495.59 / -13	**CHARLES TATUM** **1812 CACTUS RD** **SAN DIEGO CA 921540000**	HAZNET

SIC Code:		**Mailing City:**	IMPERIAL BEACH
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC002427239	**Mailing Zip:**	919320000
Create Date:	1/9/2002	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	CHARLES TATUM
Inact Date:	9/10/2002	**Owner Addr 1:**	737 HOLLY AVE
County Code:	37	**Owner Addr 2:**	
County Name:	San Diego	**Owner City:**	IMPERIAL BEACH
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	737 HOLLY AVE	**Owner Zip:**	919320000
Mailing Addr 2:		**Owner Phone:**	6195759599
Owner Fax:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Information	
--	--
Contact Name:	ED WARDOE/AMERICAN INTEGRATED
Street Address 1:	PO BOX 92316
Street Address 2:	
City:	LONG BEACH
State:	CA
Zip:	908090000
Phone:	3232498442
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAC002427239
Generator County Code:	37
Generator County:	San Diego
TSD EPA ID:	CAT000646117
TSD County Code:	16
TSD County:	Kings
State Waste Code:	611
State Waste Code Desc.:	Contaminated soil from site clean-up
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	23.5984
Year:	2002
--	--

6	*4 of 6*	*NW*	*0.02 / 80.67*	*495.59 / -13*	***TATUM CHARLES EIRMA TRUST*** ***1812 CACTUS RD*** ***SAN DIEGO CA 921548105***	***HAZNET***

SIC Code:		***Mailing City:***	IMPERIAL BEACH
NAICS Code:		***Mailing State:***	CA
EPA ID:	CAC002667242	***Mailing Zip:***	919320000
Create Date:	5/18/2011	***Region Code:***	4
Fac Act Ind:	No	***Owner Name:***	TATUM CHARLES EIRMA TRUST
Inact Date:	11/15/2011	***Owner Addr 1:***	737 HOLLY AVE
County Code:	37	***Owner Addr 2:***	
County Name:	San Diego	***Owner City:***	IMPERIAL BEACH
Mail Name:		***Owner State:***	CA
Mailing Addr 1:	737 HOLLY AVE	***Owner Zip:***	919320000
Mailing Addr 2:		***Owner Phone:***	6194103877
Owner Fax:			

Contact Information	
--	--
Contact Name:	CARLES TATUM
Street Address 1:	737 HOLLY AVE
Street Address 2:	
City:	IMPERIAL BEACH
State:	CA
Zip:	919320000
Phone:	6194103877
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAC002667242
Generator County Code:	37
Generator County:	San Diego
TSD EPA ID:	NVT33001000
TSD County Code:	
TSD County:	
State Waste Code:	611
State Waste Code Desc.:	Contaminated soil from site clean-up
Method Code:	H132
Method Description:	LANDFILL OR SURFACE IMPOUNDMENT THAT WILL BE CLOSED AS LANDFILL(TO INCLUDE ON-SITE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TREATMENT AND/OR STABILIZATION)
Tons: 254.88
Year: 2011
-- --

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	5 of 6	NW	0.02 / 80.67	495.59 / -13	IRMA TATUM 1812 CACTUS RD. SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID: CAC003026135
Gen Status Universe: No Report
Contact Name: IRMA TATUM
Contact Address: 1812 CACTUS RD. , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext: 619-805-6998
Contact Email: IBCINDY91932@YAHOO.COM
Contact Country:
County Name: SAN DIEGO
EPA Region: 09
Land Type:
Receive Date: 20190726
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20190726
Handler Name: IRMA TATUM
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: IRMA TATUM
Date Became Current:
Date Ended Current:
Phone: 619-805-6998
Street No:
Street 1: 1812 CACTUS RD.
Street 2:
City: SAN DIEGO
State: CA
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type:	Implementer	**Zip Code:**	92154		
Owner/Operator Ind:	Current Operator	**Street No:**			
Type:	Other	**Street 1:**	1812 CACTUS RD.		
Name:	IRMA TATUM	**Street 2:**			
Date Became Current:		**City:**	SAN DIEGO		
Date Ended Current:		**State:**	CA		
Phone:	619-805-6998	**Country:**			
Source Type:	Implementer	**Zip Code:**	92154		

6	6 of 6	NW	0.02 / 80.67	495.59 / -13	IRMA TATUM 1812 CACTUS RD. SAN DIEGO CA 92154	FINDS/FRS

Registry ID:	110070657576
FIPS Code:	06073
HUC Code:	
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	26-NOV-19
Update Date:	
Interest Types:	UNSPECIFIED UNIVERSE
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	
Census Block Code:	
EPA Region Code:	09
County Name:	SAN DIEGO
US/Mexico Border Ind:	
Latitude:	
Longitude:	
Reference Point:	
Coord Collection Method:	
Accuracy Value:	
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070657576
Program Acronyms:	

RCRAINFO:CAC003026135

7	1 of 7	NW	0.07 / 358.82	505.43 / -4	ASSOCIATED READY MIXED CONCRETE 1696 CACTUS RD, SAN DIEGO, CA 92154- CA	AST

Total Capacity(Gal):	12805	**Owner Name:**	ASSOCIATED READY MIXED CONCRETE, INC
CUPA:	San Diego	**County:**	San Diego

7	2 of 7	NW	0.07 / 358.82	505.43 / -4	AT&T WIRELESS #333 1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 0	HAZ SANDIEGO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Record ID:	DEH2002-HUPFP-100510	**GIS Record ID:**	DEH2002-HUPFP-100510
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	0
Facility Latitude:		**GIS Fac Longitude:**	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	AT&T WIRELESS #333		
GIS Facility Address:	1708 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tler:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	0
SIC Code:		**X Coord:**	0
NAICS Code:		**Y Coord:**	0
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK18 100510
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334165.78889
UST Facility:		**Point Y:**	1786284.65642
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.98837612926346
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56534566308832
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-20-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	1708 CACTUS RD		
Business Type:	One (1) Waste Item or One (1) Inventory		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record address		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	3 of 7	NW	0.07 / 358.82	505.43 / -4	NEXTEL CELL SITE CA 5807 1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2009-HUPFP-211177	**GIS Record ID:**	DEH2009-HUPFP-211177
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.565382
Facility Latitude:		**GIS Fac Longitude:**	-116.9889421
Facility Longitude:			
Facility Address:			
GIS Facility Name:	NEXTEL CELL SITE CA 5807		
GIS Facility Address:	1708 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461903000
SIC Code:		**X Coord:**	6333991.488
NAICS Code:		**Y Coord:**	1786299.111
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 211177
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333991.48806
UST Facility:		**Point Y:**	1786299.11111
Total No USTs:		**Lat GS84:**	32.565382
No of Tanks:		**Lon GS84:**	-116.9889421
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.98894215303889
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56538199548504
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-30-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	1708 CACTUS RD		
Business Type:	Public Utilities-Not Fleet Fuel Facility		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hirt Flag:						
Frhmbp Report Filename:						
Frhmbp Sitemap Filename:						
7	4 of 7	NW	0.07 / 358.82	505.43 / -4	AT&T MOBILITY - SD 0333 1708 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 0	HAZ SANDIEGO

Record ID:	DEH2005-HUPFP-204895	GIS Record ID:	DEH2005-HUPFP-204895
Facility Name:		GIS Facility City:	SAN DIEGO
Facility City:		GIS Facility ZipCode:	0
Facility ZipCode:		GIS Fac Latitude:	0
Facility Latitude:		GIS Fac Longitude:	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	AT&T MOBILITY - SD 0333		
GIS Facility Address:	1708 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		Status:	
GIS CERS ID:		ER Contact:	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	ER Con Work Ph:	
Per Type:		Census Tract:	
Per Sub Type:		Parcel Zip:	
Per Cat:		Community:	
Record Status:	Completed	Jurisdiction:	
HW Tier:		Basin No:	
LRG QTY MW Gener:		BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	0
SIC Code:		X Coord:	0
NAICS Code:		Y Coord:	0
Disclose Qty Haz Mat:		Kiva Per Typ:	HK18 204895
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6334165.78889
UST Facility:		Point Y:	1786284.65642
Total No USTs:		Lat GS84:	0
No of Tanks:		Lon GS84:	0
Own Oper APS:	N	Loc Name:	
Tot APSA Cap:	0	Score:	
Capacity LR:		Match Type:	
Haz Waste G:		Side:	
Recycle100:		X Map Coord:	-116.98837612926346
Onsite Haz Waste Tre:		Y Map Coord:	32.56534566308832
RCRA LRG Qty:		User Fld:	
Haz Wst Coll Site:		Addr Type:	
Accept Offs:		ARC Address:	
Universal Waste Han:		ARC City:	
Toxic Gas:		ARC Zipcode:	
Hazmat EHS:		ARC State:	
Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:		Bill Code 3:	
Parcel No:	646-190-20-00	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	1708 CACTUS RD		
Business Type:	One (1) Waste Item or One (1) Inventory		
Bill Code:			
ER Con Name:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ER Con Title:						
Water Purv:						
Fire Agency:						
Geo SRC:		Mapped to record address				
Match Addr:						
Hirt Flag:						
Frhmbp Report Filename:						
Frhmbp Sitemap Filename:						

7	5 of 7	NW	0.07 / 358.82	505.43 / -4	ASSOCIATED READY MIXED CONCRETE, INC 1696 CACTUS RD SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-102446	GIS Record ID:	DEH2002-HUPFP-102446
Facility Name:	ASSOCIATED READY MIXED CONCRETE, INC	GIS Facility City:	SAN DIEGO
Facility City:	SAN DIEGO	GIS Facility ZipCode:	92154
Facility ZipCode:	92154	GIS Fac Latitude:	32.565661
Facility Latitude:	32.56615480409957	GIS Fac Longitude:	-116.9906707
Facility Longitude:	-116.98825304362099		
Facility Address:	1696 CACTUS RD		
GIS Facility Name:	ASSOCIATED READY MIXED CONCRETE, INC		
GIS Facility Address:	1696 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

Hazardous Materials Facility Data

CERS ID:	10394077	Onsite H Waste Trtmt:	false
Facility ID No:	37-000-102446	Haz Mat on Site:	true
EPA ID No:	CAL000270953	Haz Waste Generator:	true
Active Permit:	true	Own/Oper Under:	false
Permit Status:	Permit Renewed	Own/Oper Above:	true
Bus. Phone:	619-661-7555	Recycle:	false
Bus. Fax:	0	RCRA Large Qty Gen:	false
Last Updated:	03/09/2022 12:44:27 AM	HHW Collection:	false
New Georeferenced Column:	(32.56615480409957, -116.98825304362099)		
Mailing Address:	4621 TELLER AVE # 130, NEWPORT, CA 92660		

Hazardous Waste and Materials

ID:	254369	Permit Status:	Permit Renewed
Child Record ID:	DEH2019-HCHEM-0237041	Active Permit:	true
CAS No:		Haz Material Type:	Mixture
Last Updated:	02/25/2020 01:35:46 AM	Trade Secret:	false
Chemical Name:	EUCON X15 - Mid Range Water Reducing Admixture		
Common Name Inventory:	EUCON X15 - Mid Range Water Reducing Admixture		

ID:	254370	Permit Status:	Permit Renewed
Child Record ID:	DEH2019-HCHEM-0237042	Active Permit:	true
CAS No:		Haz Material Type:	Mixture
Last Updated:	02/25/2020 01:35:46 AM	Trade Secret:	false
Chemical Name:	EUCON NW - Water Reducing Admixture		
Common Name Inventory:	EUCON NW - Water Reducing Admixture		

ID:	282097	Permit Status:	Permit Renewed
Child Record ID:	DEH2020-HCHEM-0248655	Active Permit:	true
CAS No:		Haz Material Type:	Mixture
Last Updated:	06/10/2020 01:12:58 AM	Trade Secret:	false
Chemical Name:	Automotive Wash		
Common Name Inventory:	Tristar All-Brite		

ID:	216520	Permit Status:	Permit Renewed
Child Record ID:	DEH2019-HCHEM-0216222	Active Permit:	true
CAS No:		Haz Material Type:	Mixture
Last Updated:	04/10/2019 12:46:26 AM	Trade Secret:	false

Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name Inventory: EUCON X15 - Mid Range Water Reducing Admixture

ID: 2694 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130531 **Active Permit:** true
CAS No: 64742-54-7 **Haz Material Type:** Pure
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name Inventory: Chevron Rando HD ISO 68

ID: 474031 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323156 **Active Permit:** true
CAS No: 107-21-1 **Haz Material Type:** Pure
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 474033 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323158 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Water Reducer
Common Name Inventory: Plastol

ID: 474039 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0290157 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/09/2022 12:44:29 AM **Trade Secret:** false
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL

ID: 216518 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216220 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110

ID: 228212 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223339 **Active Permit:** true
CAS No: 1305-78-8 **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash

ID: 282096 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248654 **Active Permit:** true
CAS No: 65996-61-4 **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Pulp, cellulose
Common Name Inventory: Used Rags

ID: 474020 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323145 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110/130

ID: 474023 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323148 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 282083 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248641 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture

Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110

ID: 393525 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290071 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 228215 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223342 **Active Permit:** true
CAS No: 107-21-1 **Haz Material Type:** Pure
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 2700 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130537 **Active Permit:** true
CAS No: 74-86-2 **Haz Material Type:** Pure
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: Acetylene
Common Name Inventory: Acetylene

ID: 130440 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168995 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 393519 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290065 **Active Permit:** true
CAS No: 107-21-1 **Haz Material Type:** Pure
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 393522 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290068 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Highly Refined Mineral Oil
Common Name Inventory: Gear Oil

ID: 130433 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168988 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: IN10-330
Common Name Inventory: Color-Crete Granular Black 330

ID: 393509 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290055 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name Inventory: EUCON NW - Water Reducing Admixture

ID: 254374 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237046 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 130452 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0169007 **Active Permit:** true

CAS No: 7782-44-7 **Haz Material Type:** Pure
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: Oxygen
Common Name Inventory: Oxygen

ID: 130435 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168990 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110

ID: 2687 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130524 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name Inventory: EUCON NW - Water Reducing Admixture

ID: 393513 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290059 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 474036 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323161 **Active Permit:** true
CAS No: 74-86-2 **Haz Material Type:** Pure
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Acetylene
Common Name Inventory: Acetylene

ID: 228219 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0193080 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL

ID: 393523 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290069 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Water Reducer
Common Name Inventory: Plastol

ID: 282090 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248648 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement

ID: 228203 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223330 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name Inventory: EUCON X15 - Mid Range Water Reducing Admixture

ID: 228205 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223332 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA

ID: 254376 **Permit Status:** Permit Renewed

Child Record ID: DEH2019-HCHEM-0237048 **Active Permit:** true
CAS No: 64742-54-7 **Haz Material Type:** Pure
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name Inventory: Chevron Rando HD ISO 68

ID: 254386 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237058 **Active Permit:** true
CAS No: 74-86-2 **Haz Material Type:** Pure
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Acetylene
Common Name Inventory: Acetylene

ID: 216528 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216230 **Active Permit:** true
CAS No: 64742-54-7 **Haz Material Type:** Pure
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name Inventory: Chevron Rando HD ISO 68

ID: 254371 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237043 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA

ID: 254385 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237057 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 393512 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290058 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 282102 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248660 **Active Permit:** true
CAS No: 74-86-2 **Haz Material Type:** Pure
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Acetylene
Common Name Inventory: Acetylene

ID: 228210 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223337 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement

ID: 282085 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248643 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name Inventory: EUCON NW - Water Reducing Admixture

ID: 228208 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223335 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 2685 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130522 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: IN10 920
Common Name Inventory: Color-Crete Granular Yellow 920

ID: 2693 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130530 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement

ID: 393527 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290073 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: Used Oil Filters (Drained)

ID: 393528 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290074 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: Eucon BCN

ID: 282101 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248659 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 282093 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248651 **Active Permit:** true
CAS No: 64742-65-0 **Haz Material Type:** Pure
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40

ID: 130439 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168994 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA

ID: 2689 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130526 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 228216 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223343 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 393514 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290060 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement

ID: 130442 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168997 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 282104 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0219661 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 06/10/2020 01:13:00 AM **Trade Secret:** false
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL

ID: 2686 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130523 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name Inventory: EUCON X15 - Mid Range Water Reducing Admixture

ID: 2696 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130533 **Active Permit:** true
CAS No: 64742-65-0 **Haz Material Type:** Pure
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40

ID: 228213 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223340 **Active Permit:** true
CAS No: 64742-65-0 **Haz Material Type:** Pure
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40

ID: 474022 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323147 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA

ID: 130446 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0169001 **Active Permit:** true
CAS No: 1305-78-8 **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash

ID: 216516 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216218 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: IN10-330
Common Name Inventory: Color-Crete Granular Black 330

ID: 2684 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130521 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110

ID: 474027 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323152 **Active Permit:** true
CAS No: 64742-54-7 **Haz Material Type:** Pure
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Petroleum Hydrocarbon Distillate

Common Name Inventory: Chevron Rando HD ISO 68

ID: 474037
Child Record ID: DEH2022-HCHEM-0323162
CAS No:
Last Updated: 03/09/2022 12:44:28 AM
Chemical Name:
Common Name Inventory: Eucon BCN
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 216527
Child Record ID: DEH2019-HCHEM-0216229
CAS No:
Last Updated: 04/10/2019 12:46:26 AM
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 254382
Child Record ID: DEH2019-HCHEM-0237054
CAS No:
Last Updated: 02/25/2020 01:35:46 AM
Chemical Name: Automotive Wash
Common Name Inventory: Tristar All-Brite
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 393515
Child Record ID: DEH2021-HCHEM-0290061
CAS No: 64742-54-7
Last Updated: 06/29/2021 02:34:22 AM
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name Inventory: Chevron Rando HD ISO 68
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 393517
Child Record ID: DEH2021-HCHEM-0290063
CAS No: 64742-65-0
Last Updated: 06/29/2021 02:34:22 AM
Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 393524
Child Record ID: DEH2021-HCHEM-0290070
CAS No: 7782-44-7
Last Updated: 06/29/2021 02:34:22 AM
Chemical Name: Oxygen
Common Name Inventory: Oxygen
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 393530
Child Record ID: DEH2021-HWAST-0259006
CAS No:
Last Updated: 06/29/2021 02:34:22 AM
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type:
Trade Secret: false

ID: 2683
Child Record ID: DEH2017-HCHEM-0130520
CAS No:
Last Updated: 10/24/2017 12:01:32 AM
Chemical Name: IN10-130
Common Name Inventory: Color-Crete Granular Red 130
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 282092
Child Record ID: DEH2020-HCHEM-0248650
CAS No: 1305-78-8
Last Updated: 06/10/2020 01:12:58 AM
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 282084
Child Record ID: DEH2020-HCHEM-0248642
CAS No:
Last Updated: 06/10/2020 01:12:58 AM
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name Inventory: EUCON X15 - Mid Range Water Reducing Admixture

ID: 282099 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248657 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Water Reducer
Common Name Inventory: Plastol

ID: 216531 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216233 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 254375 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237047 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement

ID: 254380 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237052 **Active Permit:** true
CAS No: 107-21-1 **Haz Material Type:** Pure
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 393511 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290057 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 228207 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223334 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 254372 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237044 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 254389 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0208476 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2020 01:35:47 AM **Trade Secret:** false
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL

ID: 254377 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237049 **Active Permit:** true
CAS No: 1305-78-8 **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash

ID: 216532 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216234 **Active Permit:** true
CAS No: 107-21-1 **Haz Material Type:** Pure

Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 254388 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237060 **Active Permit:** true
CAS No: 7782-44-7 **Haz Material Type:** Pure
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Oxygen
Common Name Inventory: Oxygen

ID: 228211 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223338 **Active Permit:** true
CAS No: 64742-54-7 **Haz Material Type:** Pure
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name Inventory: Chevron Rando HD ISO 68

ID: 393526 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290072 **Active Permit:** true
CAS No: 74-86-2 **Haz Material Type:** Pure
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Acetylene
Common Name Inventory: Acetylene

ID: 2691 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130528 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 2682 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130519 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: IN10-330
Common Name Inventory: Color-Crete Granular Black 330

ID: 2690 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130527 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 474040 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0290158 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/09/2022 12:44:29 AM **Trade Secret:** false
Chemical Name: Pulp, cellulose
Common Name Inventory: Used Rags

ID: 216523 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216225 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 216525 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216227 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 216526 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216228 **Active Permit:** true

CAS No: 7647-01-0 **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: HYDROCLORIC ACID, HCL
Common Name Inventory: DISSOLVE

ID: 228218 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223345 **Active Permit:** true
CAS No: 7782-44-7 **Haz Material Type:** Pure
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: Oxygen
Common Name Inventory: Oxygen

ID: 2701 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130538 **Active Permit:** true
CAS No: 7782-44-7 **Haz Material Type:** Pure
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: Oxygen
Common Name Inventory: Oxygen

ID: 130436 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168991 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: IN10 920
Common Name Inventory: Color-Crete Granular Yellow 920

ID: 130437 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168992 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name Inventory: EUCON X15 - Mid Range Water Reducing Admixture

ID: 216522 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216224 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA

ID: 228201 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223328 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: IN10-130
Common Name Inventory: Color-Crete Granular Red 130

ID: 474024 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323149 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 393521 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290067 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Automotive Wash
Common Name Inventory: Tristar All-Brite

ID: 2697 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130534 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 2688 **Permit Status:** Permit Renewed

Child Record ID: DEH2017-HCHEM-0130525
CAS No:
Last Updated: 10/24/2017 12:01:32 AM
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 2692
Child Record ID: DEH2017-HCHEM-0130529
CAS No: 7647-01-0
Last Updated: 10/24/2017 12:01:32 AM
Chemical Name: HYDROCLORIC ACID, HCL
Common Name Inventory: DISSOLVE
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 130450
Child Record ID: DEH2018-HCHEM-0169005
CAS No: 68476-34-6
Last Updated: 10/25/2018 04:00:42 PM
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 130451
Child Record ID: DEH2018-HCHEM-0169006
CAS No: 74-86-2
Last Updated: 10/25/2018 04:00:42 PM
Chemical Name: Acetylene
Common Name Inventory: Acetylene
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 130453
Child Record ID: DEH2018-HWAST-0143060
CAS No:
Last Updated: 10/25/2018 04:00:42 PM
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type:
Trade Secret: false

ID: 393516
Child Record ID: DEH2021-HCHEM-0290062
CAS No: 1305-78-8
Last Updated: 06/29/2021 02:34:22 AM
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 393510
Child Record ID: DEH2021-HCHEM-0290056
CAS No:
Last Updated: 06/29/2021 02:34:22 AM
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 254383
Child Record ID: DEH2019-HCHEM-0237055
CAS No:
Last Updated: 02/25/2020 01:35:46 AM
Chemical Name: Highly Refined Mineral Oil
Common Name Inventory: Gear Oil
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 254384
Child Record ID: DEH2019-HCHEM-0237056
CAS No:
Last Updated: 02/25/2020 01:35:46 AM
Chemical Name: Water Reducer
Common Name Inventory: Plastol
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 2695
Child Record ID: DEH2017-HCHEM-0130532
CAS No: 1305-78-8
Last Updated: 10/24/2017 12:01:32 AM
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 2699 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130536 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 474029 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323154 **Active Permit:** true
CAS No: 64742-65-0 **Haz Material Type:** Pure
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40

ID: 474030 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323155 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 216529 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216231 **Active Permit:** true
CAS No: 1305-78-8 **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash

ID: 216530 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216232 **Active Permit:** true
CAS No: 64742-65-0 **Haz Material Type:** Pure
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40

ID: 2702 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0109018 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL

ID: 216517 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216219 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: IN10-130
Common Name Inventory: Color-Crete Granular Red 130

ID: 216519 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216221 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: IN10 920
Common Name Inventory: Color-Crete Granular Yellow 920

ID: 130444 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168999 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement

ID: 474021 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323146 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name Inventory: EUCON NW - Water Reducing Admixture

ID: 393508 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290054 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110/130

ID: 282103 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248661 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: Used Oil Filters (Drained)

ID: 282100 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248658 **Active Permit:** true
CAS No: 7782-44-7 **Haz Material Type:** Pure
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Oxygen
Common Name Inventory: Oxygen

ID: 282087 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248645 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 2698 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0130535 **Active Permit:** true
CAS No: 107-21-1 **Haz Material Type:** Pure
Last Updated: 10/24/2017 12:01:32 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 228217 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223344 **Active Permit:** true
CAS No: 74-86-2 **Haz Material Type:** Pure
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: Acetylene
Common Name Inventory: Acetylene

ID: 130441 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168996 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 130438 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168993 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name Inventory: EUCON NW - Water Reducing Admixture

ID: 216521 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216223 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name Inventory: EUCON NW - Water Reducing Admixture

ID: 216533 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216235 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2

Common Name Inventory: Diesel Fuel No. 2

ID: 216535 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216237 **Active Permit:** true
CAS No: 7782-44-7 **Haz Material Type:** Pure
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: Oxygen
Common Name Inventory: Oxygen

ID: 393518 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290064 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 228204 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223331 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name Inventory: EUCON NW - Water Reducing Admixture

ID: 393529 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290075 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: Eucon SPC

ID: 254379 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237051 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 282095 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248653 **Active Permit:** true
CAS No: 107-21-1 **Haz Material Type:** Pure
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 282086 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248644 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: EUCON NCA
Common Name Inventory: EUCON NCA

ID: 282088 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248646 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 130448 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0169003 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 130447 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0169002 **Active Permit:** true
CAS No: 64742-65-0 **Haz Material Type:** Pure
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false

Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40

ID: 216534 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216236 **Active Permit:** true
CAS No: 74-86-2 **Haz Material Type:** Pure
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: Acetylene
Common Name Inventory: Acetylene

ID: 216524 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0216226 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 04/10/2019 12:46:26 AM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 216536 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0186474 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 04/10/2019 12:46:29 AM **Trade Secret:** false
Chemical Name: WASTE OIL
Common Name Inventory: WASTE OIL

ID: 474028 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323153 **Active Permit:** true
CAS No: 1305-78-8 **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Type F Flyash
Common Name Inventory: Headwaters Flyash

ID: 474032 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323157 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Automotive Wash
Common Name Inventory: Tristar All-Brite

ID: 474035 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323160 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 474041 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0290159 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/09/2022 12:44:29 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: Used Oil Filters (Drained)

ID: 474038 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323163 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: Eucon SPC

ID: 474025 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323150 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 282091 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248649 **Active Permit:** true
CAS No: 64742-54-7 **Haz Material Type:** Pure

Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name Inventory: Chevron Rando HD ISO 68

ID: 228209 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223336 **Active Permit:** true
CAS No: 7647-01-0 **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: HYDROCLORIC ACID, HCL
Common Name Inventory: DISSOLVE

ID: 254373 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237045 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name Inventory: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ID: 254381 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237053 **Active Permit:** true
CAS No: 65996-61-4 **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: Pulp, cellulose
Common Name Inventory: Used Rags

ID: 254387 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237059 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: Used Oil Filters (Drained)

ID: 254368 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237040 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110

ID: 228202 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223329 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: IN10-110
Common Name Inventory: Color-Crete Granular Red 110

ID: 228206 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223333 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name Inventory: EUCON SRA - Shrinking Reducing Admixture

ID: 282089 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248647 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: EUCON DS
Common Name Inventory: EUCON DS

ID: 130434 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168989 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: IN10-130
Common Name Inventory: Color-Crete Granular Red 130

ID: 130449 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0169004 **Active Permit:** true

CAS No: 107-21-1 **Haz Material Type:** Pure
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT

ID: 474026 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323151 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: CEMENT
Common Name Inventory: Cal Portland Cement

ID: 474034 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0323159 **Active Permit:** true
CAS No: 7782-44-7 **Haz Material Type:** Pure
Last Updated: 03/09/2022 12:44:28 AM **Trade Secret:** false
Chemical Name: Oxygen
Common Name Inventory: Oxygen

ID: 130443 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0168998 **Active Permit:** true
CAS No: 7647-01-0 **Haz Material Type:** Mixture
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: HYDROCLORIC ACID, HCL
Common Name Inventory: DISSOLVE

ID: 282094 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248652 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 130445 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0169000 **Active Permit:** true
CAS No: 64742-54-7 **Haz Material Type:** Pure
Last Updated: 10/25/2018 04:00:42 PM **Trade Secret:** false
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name Inventory: Chevron Rando HD ISO 68

ID: 228214 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0223341 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/03/2019 03:27:57 AM **Trade Secret:** false
Chemical Name: Eucon ABS
Common Name Inventory: Eucon ABS

ID: 393520 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0290066 **Active Permit:** true
CAS No: 65996-61-4 **Haz Material Type:** Mixture
Last Updated: 06/29/2021 02:34:22 AM **Trade Secret:** false
Chemical Name: Pulp, cellulose
Common Name Inventory: Used Rags

ID: 282098 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0248656 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 06/10/2020 01:12:58 AM **Trade Secret:** false
Chemical Name: Highly Refined Mineral Oil
Common Name Inventory: Gear Oil

ID: 254378 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0237050 **Active Permit:** true
CAS No: 64742-65-0 **Haz Material Type:** Pure
Last Updated: 02/25/2020 01:35:46 AM **Trade Secret:** false
Chemical Name: MOTOR OIL
Common Name Inventory: Chevron Delo 400 LE SAE 15W-40

Hazardous Materials Inspection Violations

Container Tank ID:
Facility ID No: 37-000-102446
ID: 1231
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 4384906
Inspection Type: Routine
Inspection Date: 02/20/2015 12:00:00 AM
Compliance Date: 03/13/2015 12:00:00 AM
Last Updated: 03/09/2022 12:44:25 AM
NOV: false
Program Element: Aboveground Petroleum Storage Act
Violation Classification: Class II
Violation Code: 4010019 Failure to predict the extent of a discharge that could result from equipment failure within the SPCC plan; 40 CFR 1 112.7(b); HSC 6.67 25270.4.5(a).

Container Tank ID:
Facility ID No: 37-000-102446
ID: 1223
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 4384906
Inspection Type: Routine
Inspection Date: 02/20/2015 12:00:00 AM
Compliance Date: 02/21/2015 12:00:00 AM
Last Updated: 03/09/2022 12:44:25 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3030017 Failure to properly close hazardous waste containers when not in active use.; 22 CCR 12 66262.34(d)(2); 40 CFR 1 265.173.

Container Tank ID:
Facility ID No: 37-000-102446
ID: 1222
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 4384906
Inspection Type: Routine
Inspection Date: 02/20/2015 12:00:00 AM
Compliance Date: 02/21/2015 12:00:00 AM
Last Updated: 03/09/2022 12:44:25 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3030004 Failure to properly handle, manage, label, and recycle used oil and fuel filters.; 22 CCR 16 66266.130.

Container Tank ID:
Facility ID No: 37-000-102446
ID: 1235
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 4384906
Inspection Type: Routine
Inspection Date: 02/20/2015 12:00:00 AM
Compliance Date: 05/11/2015 12:00:00 AM
Last Updated: 03/09/2022 12:44:25 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010007 Failure to submit a revised business plan upon a substantial change in the handler's operations; HSC 6.95 25508.1(f)

Container Tank ID:
Facility ID No: 37-000-102446
ID: 45826
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 6124791
Inspection Type: Routine
Inspection Date: 07/26/2019 12:00:00 AM
Compliance Date: 07/30/2019 12:00:00 AM
Last Updated: 03/09/2022 12:44:25 AM
NOV: false
Program Element: Aboveground Petroleum Storage Act
Violation Classification: Class II
Violation Code: 4010023 Failed to conduct annual discharge prevention briefings to ensure understanding of SPCC plan. (40 CFR 112.7(f)(3).) HSC 25270.4.5(a)

Container Tank ID:
Facility ID No: 37-000-102446
ID: 1229
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 4384906
Inspection Type: Routine
Inspection Date: 02/20/2015 12:00:00 AM
Compliance Date: 03/28/2015 12:00:00 AM
Last Updated: 03/09/2022 12:44:25 AM
NOV: false
Program Element: Aboveground Petroleum Storage Act
Violation Classification: Class II
Violation Code: 4030015 Failure to integrity test aboveground tanks by such methods as hydrostatic, nondestructive, etc.; 40 CFR 1 112.8(c)(6); HSC 6.67 25270.4.5(a).

Container Tank ID:
Facility ID No: 37-000-102446
Inspection No: 5611660
Inspection Type: Routine

ID: 1234 **Inspection Date:** 03/08/2017 02:53:00 PM
UST ID: **Compliance Date:** 03/10/2017 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/09/2022 12:44:25 AM
Active Permit: true **NOV:** false
Program Element: Aboveground Petroleum Storage Act
Violation Classification: Class II
Violation Code: 4020001 Failed to train oil-handling personnel on operation/maintenance of equipment to prevent discharges; discharge procedure protocols; applicable laws, rules, and regulations; general facility operations; AND the contents of the SPCC Plan. (40 CFR 112.7(f)(1).) HSC 25270.4.5(a)

Container Tank ID: **Inspection No:** 4384906
Facility ID No: 37-000-102446 **Inspection Type:** Routine
ID: 1226 **Inspection Date:** 02/20/2015 12:00:00 AM
UST ID: **Compliance Date:** 03/06/2015 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/09/2022 12:44:25 AM
Active Permit: true **NOV:** false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3030007 Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.; 22 CCR 12 66262.34(f).

Container Tank ID: **Inspection No:** 4384906
Facility ID No: 37-000-102446 **Inspection Type:** Routine
ID: 1228 **Inspection Date:** 02/20/2015 12:00:00 AM
UST ID: **Compliance Date:** 03/13/2015 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/09/2022 12:44:25 AM
Active Permit: true **NOV:** false
Program Element: Aboveground Petroleum Storage Act
Violation Classification: Class II
Violation Code: 4010023 Failure to schedule and conduct spill prevention briefings at least once a year.; 40 CFR 1 112.7(f)(3); HSC 6.67 25270.4.5(a).

Container Tank ID: **Inspection No:** 5611660
Facility ID No: 37-000-102446 **Inspection Type:** Routine
ID: 1233 **Inspection Date:** 03/08/2017 02:53:00 PM
UST ID: **Compliance Date:** 03/10/2017 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/09/2022 12:44:25 AM
Active Permit: true **NOV:** false
Program Element: Aboveground Petroleum Storage Act
Violation Classification: Class II
Violation Code: 4010021 Failed to address in SPCC plan/maintain complete records of: inspections, tests/procedures for 3 years. (40 CFR 112.7(e), 112.8(c)(6).) HSC 25270.4.5(a)

Container Tank ID: **Inspection No:** 4384906
Facility ID No: 37-000-102446 **Inspection Type:** Routine
ID: 1227 **Inspection Date:** 02/20/2015 12:00:00 AM
UST ID: **Compliance Date:** 03/13/2015 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/09/2022 12:44:25 AM
Active Permit: true **NOV:** false
Program Element: Aboveground Petroleum Storage Act
Violation Classification: Class II
Violation Code: 4020001 Employee training requirements - Failure to provide training regarding: 40 CFR 1 112.7(f)(1); HSC 6.67 25270.4.5(a).

Container Tank ID: **Inspection No:** 4384906
Facility ID No: 37-000-102446 **Inspection Type:** Routine
ID: 1224 **Inspection Date:** 02/20/2015 12:00:00 AM
UST ID: **Compliance Date:** 03/05/2015 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/09/2022 12:44:25 AM
Active Permit: true **NOV:** false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: HMD0224 Empty cont not managed. Failed to mark date on empty container larger than 5 gallons &/or manage it within one year. 22CCR 66261.7(e) & (f).

Container Tank ID: **Inspection No:** 4384906
Facility ID No: 37-000-102446 **Inspection Type:** Routine
ID: 1225 **Inspection Date:** 02/20/2015 12:00:00 AM

UST ID:		**Compliance Date:**	03/13/2015 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/09/2022 12:44:25 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3020001 Failure to ensure employees are familiar with the handling and compliance of hazardous waste regulations and emergency response. 22 CCR 12 66262.34(d)(2); 40 CFR 1 262.34(d)(5)(iii)		

Container Tank ID:		**Inspection No:**	5611660
Facility ID No:	37-000-102446	**Inspection Type:**	Routine
ID:	1232	**Inspection Date:**	03/08/2017 02:53:00 PM
UST ID:		**Compliance Date:**	03/10/2017 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/09/2022 12:44:25 AM
Active Permit:	true	**NOV:**	false
Program Element:	Aboveground Petroleum Storage Act		
Violation Classification:	Class II		
Violation Code:	4010023 Failed to conduct annual discharge prevention briefings to ensure understanding of SPCC plan. (40 CFR 112.7(f)(3).) HSC 25270.4.5(a)		

Container Tank ID:		**Inspection No:**	6124791
Facility ID No:	37-000-102446	**Inspection Type:**	Routine
ID:	45827	**Inspection Date:**	07/26/2019 12:00:00 AM
UST ID:		**Compliance Date:**	08/20/2019 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/09/2022 12:44:25 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010006 Failed to update HMBP in CERS within 30 days of a substantial change to any portion of the HMBP, including inventory changes or facility information. HSC 25508.1(a-f); 19 CCR 2654(d); SDCC 68.904(c)(6)		

Container Tank ID:		**Inspection No:**	4384906
Facility ID No:	37-000-102446	**Inspection Type:**	Routine
ID:	1230	**Inspection Date:**	02/20/2015 12:00:00 AM
UST ID:		**Compliance Date:**	03/06/2015 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/09/2022 12:44:25 AM
Active Permit:	true	**NOV:**	false
Program Element:	Aboveground Petroleum Storage Act		
Violation Classification:	Class II		
Violation Code:	4010015 Failure to have an adequate facility diagram, or no facility diagram included within the SPCC plan; 40 CFR 1 112.7(a)(3); HSC 6.67 25270.4.5(a).		

Container Tank ID:		**Inspection No:**	6124791
Facility ID No:	37-000-102446	**Inspection Type:**	Routine
ID:	45825	**Inspection Date:**	07/26/2019 12:00:00 AM
UST ID:		**Compliance Date:**	08/02/2019 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/09/2022 12:44:25 AM
Active Permit:	true	**NOV:**	false
Program Element:	Aboveground Petroleum Storage Act		
Violation Classification:	Class II		
Violation Code:	4010009 Failed to perform and properly document a five-year review of the SPCC Plan. (40 CFR 112.5(b).) HSC 25270.4.5(a)		

HMD Permits Map Data

GIS Facility ID:	37-000-102446	**Status:**	
GIS CERS ID:	10394077	**ER Contact:**	714-272-1900
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	619-661-7555
Per Type:		**Census Tract:**	100.15
Per Sub Type:		**Parcel Zip:**	92154
Per Cat:		**Community:**	San Diego
Record Status:	Permit Renewed	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAL000270953	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HS015
Tank Owner:		**Feature ID:**	6461903200
SIC Code:	3273	**X Coord:**	6333586.818
NAICS Code:		**Y Coord:**	1786430.291

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	HK07 102446
Exp Date:	6/29/2020	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333586.818
UST Facility:		**Point Y:**	1786430.29100001
Total No USTs:		**Lat GS84:**	32.565661
No of Tanks:		**Lon GS84:**	-116.9906707
Own Oper APS:	Y	**Loc Name:**	
Tot APSA Cap:	13460	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Y	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.99025852828306
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.56573463047276
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:	N	**ARC Address:**	
Universal Waste Han:	N	**ARC City:**	
Toxic Gas:	No	**ARC Zipcode:**	
Hazmat EHS:	N	**ARC State:**	
Hazmat Rad:	No	**ARC APN:**	
Haz Waste Rad:	N	**Zip:**	
Haz Waste EHS:	N	**Farm Nursery:**	
Full Name:	ASSOCIATED READY MIXED CONCRETE, INC	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	949-253-2800	**Bill Code 2:**	Not Applicable
Site Address:	1696 CACTUS RD	**Bill Code 3:**	Not Applicable
Parcel No:	646-190-32-00	**Univ Waste Gen Type:**	

Record Ali:	Unified Program Facility Permit
Address:	1696 CACTUS RD
Business Type:	Contractors-Street, Painting, Roofers, Building
Bill Code:	Not Applicable
ER Con Name:	JIM PARKER
ER Con Title:	PLANT MANAGER
Water Purv:	OTAY WATER IMP DIST C-SEWER
Fire Agency:	SAN DIEGO
Geo SRC:	Mapped to record APN/Parcel XY center
Match Addr:	
Hirt Flag:	Yes
Frhmbp Report Filename:	HMBP102446.pdf
Frhmbp Sitemap Filename:	MAP_102446.pdf

7	*6 of 7*	*NW*	*0.07 / 358.82*	*505.43 / -4*	***ASSOCIATED READY MIXED CONCRETE INC 1696 CACTUS RD SAN DIEGO CA 92154***	***CERS TANK***

Site ID:	93697	**Latitude:**	32.565734
Longitude:	-116.990257		

Regulated Programs

EI ID:	10394077
EI Description:	Hazardous Waste Generator
EI ID:	10394077
EI Description:	Aboveground Petroleum Storage
EI ID:	10394077
EI Description:	Chemical Storage Facilities
EI ID:	9215WSSCTD1696C
EI Description:	Toxic Release Inventory

Violations

Violation Date:	02/20/2015	**Violation Source:**	CERS

Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 25508.1(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(f)
Violation Notes:

Returned to compliance on 05/11/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to electronically update the business plan within 30 days of a substantial change.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/06/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to have an adequate facility diagram, or no facility diagram included within the SPCC plan.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to schedule and conduct spill prevention briefings at least once a year.

Violations

Violation Date: 07/26/2019 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Notes:

Returned to compliance on 07/30/2019. Inspection Sequence ID:6124791

Violation Description:

Failure to include in the SPCC plan an adequate description of employee training. Training shall address, at a minimum: operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules, and regulations; general facility operations; content of the facility SPCC plan; and annual discharge prevention briefings for oil-handling personnel to assure adequate understanding of the SPCC plan.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 03/06/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 07/26/2019 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)
Violation Notes:

Returned to compliance on 08/20/2019. Inspection Sequence ID:6124791

Violation Description:

Failure to electronically update business plan within 30 days of any one of the following events:
A 100 percent or more increase in the quantity of a previously disclosed material.
Any handling of a previously undisclosed hazardous materials at or above reportable quantities.
A change of business address, business ownership, or business name.
A substantial change in the handler's operations that requires modification to any portion of the business plan.

Violations

Violation Date: 07/26/2019 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Notes:

Returned to compliance on 08/02/2019. Inspection Sequence ID:6124791

Violation Description:

Failure to complete a review and evaluation of the SPCC Plan at least once every five years, document the completion of the review, and sign a statement as to whether the SPCC Plan will be amended.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Notes:

Returned to compliance on 02/21/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to properly close hazardous waste containers when not in active use.

Violations

Violation Date: 03/08/2017 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/10/2017.

Violation Description:

Failure to include in the SPCC plan and document discharge prevention briefings for oil-handling personnel at least once a year, including, but not limited to, known discharges, failures, and malfunctioning components.

Violations

Violation Date: 03/08/2017 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/10/2017.

Violation Description:

Failure to comply with one or more of the following requirements:

1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector.

2. Keep written procedures and records of inspections and integrity tests for at least three years.

3. Keep comparison records.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: 40 CFR 1 262.34(d)(5)(iii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(iii)
Violation Notes:

Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to ensure employees are familiar with the handling and compliance of hazardous waste regulations and emergency response.

Violations

Violation Date: 03/08/2017 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/10/2017.

Violation Description:

Failure to provide the following training to all oil-handling personnel:

1. Operation and maintenance of equipment to prevent discharges.

2. Discharge procedure protocols.

3. Applicable pollution control laws, rules, and regulations.

4. General facility operations.

5. Contents of the SPCC Plan.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130

Violation Notes:

Returned to compliance on 02/21/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to properly handle, manage, label, and recycle used oil and fuel filters.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections
Violation Notes:

Returned to compliance on 03/05/2015. Inspection Sequence ID:4384906;Violation:HMD0224 Empty cont not managed. Failed to mark date on empty container larger than 5 gallons &/or manage it within one year. 22CCR 66261.7(e) & (f).

Violation Description:

Haz Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to predict the extent of a discharge that could result from equipment failure within the SPCC plan.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to provide training regarding:
1. The operation and maintenance of equipment to prevent discharges.
2. Discharge procedure protocols.
3. Applicable pollution control laws, rules, and regulations.
4. General facility operations. AND
5. The contents of the SPCC Plan.

Violations

Violation Date: 02/20/2015 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 03/28/2015. Inspection Sequence ID:4384906

Violation Description:

Failure to integrity test aboveground tanks by such methods as hydrostatic, nondestructive, etc.

Evaluations

Eval Date: 02/20/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:4384906; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/26/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Inspector: Chavarin Yvonne Inspection ID:6124791; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/08/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:5611660; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/26/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Chavarin Yvonne Inspection ID:6124791; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/20/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:4384906; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/08/2017
Violations Found: No

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:5611660; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/20/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:4384906; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/08/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:5611660; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/26/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Chavarin Yvonne Inspection ID:6124791; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 4621 TELLER AVE # 130
City: NEWPORT
State: CA
Country:
Zip Code: 92660
Phone:

Affil Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title:
Address: PO Box 129261
City: San Diego
State: CA
Country:
Zip Code: 92112-9261
Phone: (858) 505-6880

Affil Type Desc: Operator

Entity Name:	ASSOCIATED READY MIXED CONCRETE, INC
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(619) 661-7555

Affil Type Desc:	Document Preparer
Entity Name:	Windell Jones, Jr
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Identification Signer
Entity Name:	ALEX NICHOLS
Entity Title:	Director, Development & Compliance
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Parent Corporation
Entity Name:	A&A READY MIXED CONCRETE, INC
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Public Contact
Entity Name:	Alex Nichols
Entity Title:	
Address:	4621 TELLER AVENUE, SUITE 130
City:	NEWPORT BEACH
State:	CA
Country:	
Zip Code:	92154
Phone:	9492532800

Affil Type Desc:	Company Official
Entity Name:	Alexander Nichols
Entity Title:	Director of Development and Compliance
Address:	4621 TELLER AVENUE, SUITE 130
City:	NEWPORT BEACH
State:	CA
Country:	
Zip Code:	92154
Phone:	

Affil Type Desc:	Parent Company
Entity Name:	CAILLIER INVESTMENTS, INC
Entity Title:	
Address:	4621 TELLER AVENUE, SUITE 130
City:	NEWPORT BEACH
State:	CA
Country:	
Zip Code:	92154
Phone:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Environmental Contact
Entity Name: Alex Nichols
Entity Title:
Address: 4621 TELLER AV #130
City: NEWPORT BEACH
State: CA
Country:
Zip Code: 92660
Phone:

Affil Type Desc: Legal Owner
Entity Name: ASSOCIATED READY MIXED CONCRETE, INC
Entity Title:
Address: 4621 TELLER AVE 130
City: NEWPORT BEACH
State: CA
Country: United States
Zip Code: 92660
Phone: (949) 253-2800

Affil Type Desc: Technical Contact
Entity Name: Alex Nichols
Entity Title:
Address: 4621 TELLER AVENUE, SUITE 130
City: NEWPORT BEACH
State: CA
Country:
Zip Code: 92154
Phone: 9492532800

Coordinates

Env Int Type Code: HWG
Program ID: 10394077
Latitude: 32.565730
Longitude: -116.990260
Coord Name:
Ref Point Type Desc: Center of a facility or station.

7	7 of 7	NW	0.07 / 358.82	505.43 / -4	ASSOCIATED READY MIXED CONCRETE INC #62 1696 CACTUS RD SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID: CAL000270953
Gen Status Universe: No Report
Contact Name: MIKE COOK
Contact Address: 3250 E. 70TH ST. , , LONG BEACH , CA, 90805-1821 ,
Contact Phone No and Ext: 562-790-3650
Contact Email: MCOOK@ASSOCRMC.COM
Contact Country:
County Name: SAN DIEGO
EPA Region: 09
Land Type:
Receive Date: 20030529
Location Latitude: 32.565348
Location Longitude: -116.990735

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20030529
Handler Name:	ASSOCIATED READY MIXED CONCRETE INC #62
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	3250 E. 70TH ST.
Name:	MIKE COOK	**Street 2:**	
Date Became Current:		**City:**	LONG BEACH
Date Ended Current:		**State:**	CA
Phone:	562-790-3650	**Country:**	
Source Type:	Implementer	**Zip Code:**	90805-1821

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	4621 TELLER AVE #130
Name:	KURT AND RANDY CAILLIER	**Street 2:**	
Date Became Current:		**City:**	NEWPORT BEACH
Date Ended Current:		**State:**	CA
Phone:	949-253-2800	**Country:**	
Source Type:	Implementer	**Zip Code:**	90805-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	1 of 3	NNW	0.08 / 422.63	505.63 / -3	CACTUS RECYCLING, INC. 1703 CACTUS RD CA 0	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-134580	**GIS Record ID:**	DEH2002-HUPFP-134580
Facility Name:		**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	0
Facility Latitude:		**GIS Fac Longitude:**	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	CACTUS RECYCLING, INC.		
GIS Facility Address:	1703 CACTUS RD		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

LRG QTY MW Gener:		BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	0
SIC Code:		X Coord:	0
NAICS Code:		Y Coord:	0
Disclose Qty Haz Mat:		Kiva Per Typ:	HK07 134580
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6334168.93575
UST Facility:		Point Y:	1786547.08925
Total No USTs:		Lat GS84:	0
No of Tanks:		Lon GS84:	0
Own Oper APS:	N	Loc Name:	
Tot APSA Cap:	0	Score:	
Capacity LR:		Match Type:	
Haz Waste G:	Yes	Side:	
Recycle100:		X Map Coord:	-116.98837194749115
Onsite Haz Waste Tre:		Y Map Coord:	32.56606697380987
RCRA LRG Qty:		User Fld:	
Haz Wst Coll Site:		Addr Type:	
Accept Offs:		ARC Address:	
Universal Waste Han:		ARC City:	
Toxic Gas:		ARC Zipcode:	
Hazmat EHS:		ARC State:	
Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:		Bill Code 3:	
Parcel No:	646-101-14-00	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	1703 CACTUS RD		
Business Type:	Wrecking/Scrap Yards		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record address		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

8	2 of 3	NNW	0.08 / 422.63	505.63 / -3	R&R AG CHEM INC 1703 CACTUS RD, SAN YSIDRO, 92173-2209 CA	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-110861	GIS Record ID:	
Facility Name:	R&R AG CHEM INC	GIS Facility City:	
Facility City:		GIS Facility ZipCode:	
Facility ZipCode:		GIS Fac Latitude:	
Facility Latitude:		GIS Fac Longitude:	
Facility Longitude:			
Facility Address:	1703 CACTUS RD, SAN YSIDRO, 92173-2209		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

8	3 of 3	NNW	0.08 / 422.63	505.63 / -3	CALTRANS 1703 CACTUS RD SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID:	CAP000199299

Gen Status Universe:	No Report
Contact Name:	SANDRA L DURBIN
Contact Address:	4050 TAYLOR ST , MS 310 , SAN DIEGO , CA, 92110 , US
Contact Phone No and Ext:	619-302-4685
Contact Email:	SANDRA.DURBIN@DOT.CA.GOV
Contact Country:	US
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	State
Receive Date:	20090622
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20090622
Handler Name:	CALTRANS
Source Type:	Temporary
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20090317
Handler Name:	CALTRANS
Source Type:	Temporary
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street 1:**	
Name:	JANUS CORP	**Street 2:**	
Date Became Current:	20081031	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Temporary	**Zip Code:**	
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	4050 TAYLOR ST
Name:	CALTRANS DISTRICT 11	**Street 2:**	
Date Became Current:	20080619	**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:		**Country:**	US
Source Type:	Temporary	**Zip Code:**	92110

Historical Handler Details

Receive Dt:	20090317
Generator Code Description:	Large Quantity Generator
Handler Name:	CALTRANS

---

9 | ***1 of 1*** | ***NNW*** | ***0.10 / 548.10*** | ***506.80 / -2*** | ***Cactus Road- AKA Tripp Salvage
1700-1902 Cactus Road
San Diego CA 92154*** | ***SWF/LF***

SWIS No:	37-CR-0011	**Latitude:**	32.56392
EPA Fed Registry ID:		**Longitude:**	-116.98903
Site Operational Status:	Closed	**County:**	San Diego
Regulatory Status:	Unpermitted	**Site ZIP:**	92154
Site is Archived:	No	**ARB District:**	San Diego
Absorbed on:		**SWRCB Region:**	San Diego
Absorbed by:		**Site Point of Contact:**	Abel Martinez-Centeno
Site Inert Debris Eng Fill:	No		
Closed Illegal Aband:	Yes		
Closed Illegal Aband Cat:	C1		
Finance Assuran Responsible:	No		
Incorporated City:	San Diego		
Local Government:	San Diego		
Reporting Agency Legal Name:	City of San Diego		
Reporting Agency Department:	Development Services Department		
Enforcing Agency Legal Name:	City of San Diego		
Enforcing Agency Department:	Development Services Department		

Site Owners

Site Type:	Disposal Only	**Contact Name:**	
Owner Name:	Sesi Group	**Contact First Name:**	
Owner Address:	Sesi Salim-APN:646-100-4900 & 7300 747 Vista Grande Rd.	**Contact Last Name:**	
Owner City:	El Cajon	**Contact Title:**	
Owner State:	CA	**Contact Email:**	
Owner ZIP Code:	92019	**Started On:**	
Owner Phone:	(619) 588-7882		
Site Type:	Disposal Only	**Contact Name:**	
Owner Name:	Sesi Group	**Contact First Name:**	
Owner Address:	Dr. Jabir Adamo-APN:646-100-4900 & 7300 2129 Furner St.	**Contact Last Name:**	
Owner City:	El Cajon	**Contact Title:**	
Owner State:	CA	**Contact Email:**	
Owner ZIP Code:	92020	**Started On:**	
Owner Phone:	(619) 933-5696		
Site Type:	Disposal Only	**Contact Name:**	
Owner Name:	CalTrans- District 11	**Contact First Name:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Address: Owen A. Chung 4050 Taylor St. MS 242
Owner City: San Diego
Owner State: CA
Owner ZIP Code: 92110
Owner Phone: (619) 688-3153
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Type: Disposal Only
Owner Name: Opper & Varco LLP
Owner Address: Richard Opper-APN:646-100-4900 & 7300 225 Broadway St., Suite 1900
Owner City: San Diego
Owner State: CA
Owner ZIP Code: 92101
Owner Phone: (619) 231-5858
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Type: Disposal Only
Owner Name: Charles E. & Irma J. Tatum
Owner Address: APN: 646-100-4800 737 Holly Ave.
Owner City: Imperial
Owner State: CA
Owner ZIP Code: 91932
Owner Phone: (619) 575-9599
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Activities (Search Result)

ID:
Act Opl Status: Closed
Site Name: Cactus Road- AKA Tripp Salvage
Activity: Solid Waste Disposal Site
Act Regulatory Stat: Unpermitted
Activity Category: Disposal

Extra Details

EPA Fed Reg ID:
Regulatory Status: Unpermitted
Operational Status: Closed
Is Archived: No
Fin Assuran Resp: No
Closed Illegal Aband: Yes
Inert Debris Eng Fill: No
Site Name: Cactus Road- AKA Tripp Salvage
Enforc Agncy Dept: Development Services Department
Enforc Agency:
Absorbed By:
Absorbed On:
Local Government: San Diego
Enforc Agncy Lgl Nm: City of San Diego
Point of Contact: Abel Martinez-Centeno
County: San Diego

Site Activities (Export)

WDR No:
WDR Landfill Class:
Act is Archived: No
Act Opl Status: Closed
Act Regulatory Stat: Unpermitted
Activity Category: Disposal
Act Classification: Solid Waste Disposal Site
Cease Operation:
Cease Operation Tp:
Insp Frequency: Annual
Incorporated City: San Diego
Site Point of Contact: Abel Martinez-Centeno
Activity: Solid Waste Disposal Site
Max Permitted Throughput:
Throughput UOM:
Remaining Capacity:
Remaining Cap Dt:
Max Permit Cap:
Capacity UOM:
Total Acreage: 0.00
Disposal Acreage: 0.00
Permitted Elev :
Permitted Elev Tp:
Permitted Depth:
Permitted Depth Tp:
Site Name: Cactus Road- AKA Tripp Salvage

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	1 of 3	NNW	0.12 / 614.77	506.99 / -2	ENERGY LABS, INC. 1695 CACTUS RD SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID: DEH2006-HUPFP-207570
GIS Record ID: DEH2006-HUPFP-207570

Facility Name:	ENERGY LABS, INC.	**GIS Facility City:**	SAN DIEGO
Facility City:	SAN DIEGO	**GIS Facility ZipCode:**	92154
Facility ZipCode:	92154	**GIS Fac Latitude:**	32.5658794
Facility Latitude:	32.56618390134834	**GIS Fac Longitude:**	-116.987819
Facility Longitude:	-116.98838254434625		
Facility Address:	1695 CACTUS RD		
GIS Facility Name:	ENERGY LABS, INC.		
GIS Facility Address:	1695 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

Hazardous Materials Facility Data

CERS ID:	10394488	**Onsite H Waste Trtmt:**	false
Facility ID No:	37-000-207570	**Haz Mat on Site:**	true
EPA ID No:	CAL000316781	**Haz Waste Generator:**	false
Active Permit:	true	**Own/Oper Under:**	false
Permit Status:	Permit Renewed	**Own/Oper Above:**	false
Bus. Phone:	6196710404	**Recycle:**	false
Bus. Fax:	0	**RCRA Large Qty Gen:**	false
Last Updated:	02/15/2022 02:32:11 AM	**HHW Collection:**	false
New Georeferenced Column:	(32.56618390134834, -116.98838254434625)		
Mailing Address:	1695 CACTUS ROAD, SAN DIEGO, CA 92154		

Hazardous Waste and Materials

ID:	183756	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2018-HCHEM-0196864	**Active Permit:**	true
CAS No:	74-98-6	**Haz Material Type:**	Pure
Last Updated:	01/24/2019 02:35:04 AM	**Trade Secret:**	false
Chemical Name:	Propane		
Common Name Inventory:	Liquefied Petroleum Gas (lpg)		

ID:	223299	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2019-HCHEM-0217257	**Active Permit:**	true
CAS No:	74-98-6	**Haz Material Type:**	Pure
Last Updated:	11/13/2019 03:50:18 AM	**Trade Secret:**	false
Chemical Name:	Propane		
Common Name Inventory:	Liquefied Petroleum Gas (lpg)		

ID:	273770	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2019-HCHEM-0239986	**Active Permit:**	true
CAS No:	74-98-6	**Haz Material Type:**	Pure
Last Updated:	02/15/2022 02:32:11 AM	**Trade Secret:**	false
Chemical Name:	Propane		
Common Name Inventory:	Liquefied Petroleum Gas (lpg)		

ID:	96315	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2017-HCHEM-0141739	**Active Permit:**	true
CAS No:	74-98-6	**Haz Material Type:**	Pure
Last Updated:	01/23/2018 02:31:59 AM	**Trade Secret:**	false
Chemical Name:	Propane		
Common Name Inventory:	Liquefied Petroleum Gas (lpg)		

ID:	42606	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2016-HCHEM-0120505	**Active Permit:**	true
CAS No:	74-98-6	**Haz Material Type:**	Pure
Last Updated:	01/25/2017 02:34:58 AM	**Trade Secret:**	false
Chemical Name:	Propane		
Common Name Inventory:	Liquefied Petroleum Gas (lpg)		

Hazardous Materials Inspection Violations

Container Tank ID:		**Inspection No:**	4099942
Facility ID No:	37-000-207570	**Inspection Type:**	Routine
ID:	22489	**Inspection Date:**	08/31/2015 02:12:00 PM

UST ID:		**Compliance Date:**	12/01/2015 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/15/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	CLASS II		
Violation Code:	1010002 HMBP not submitted to the CUPA in CERS. HSC 25508(a)(1)(A); HSC 25404(e)(4); 27 CCR 15188(a), (d)		

Container Tank ID:		**Inspection No:**	4099942
Facility ID No:	37-000-207570	**Inspection Type:**	Routine
ID:	22488	**Inspection Date:**	08/31/2015 02:12:00 PM
UST ID:		**Compliance Date:**	01/11/2016 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/15/2022 12:00:00 AM
Active Permit:	true	**NOV:**	true
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	CLASS I		
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905		

Container Tank ID:		**Inspection No:**	6260197
Facility ID No:	37-000-207570	**Inspection Type:**	Routine
ID:	50054	**Inspection Date:**	11/12/2019 12:00:00 AM
UST ID:		**Compliance Date:**	12/19/2019 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/15/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Minor		
Violation Code:	1010017 HMBP not readily available to facility personnel or the CUPA. HSC 25505(c)		

Container Tank ID:		**Inspection No:**	6260197
Facility ID No:	37-000-207570	**Inspection Type:**	Routine
ID:	50055	**Inspection Date:**	11/12/2019 12:00:00 AM
UST ID:		**Compliance Date:**	12/10/2019 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/15/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Minor		
Violation Code:	1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)		

HMD Permits Map Data

GIS Facility ID:	37-000-207570	**Status:**	
GIS CERS ID:	10394488	**ER Contact:**	6196710404
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	6196710100
Per Type:		**Census Tract:**	100.15
Per Sub Type:		**Parcel Zip:**	92154
Per Cat:		**Community:**	San Diego
Record Status:	Permit Renewed	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAL000316781	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HS015
Tank Owner:		**Feature ID:**	6462700900
SIC Code:		**X Coord:**	6334338.991
NAICS Code:		**Y Coord:**	1786489.668
Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	HK07 207570
Exp Date:	2/27/2021	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334338.99100001
UST Facility:		**Point Y:**	1786489.668
Total No USTs:		**Lat GS84:**	32.5658794
No of Tanks:		**Lon GS84:**	-116.987819
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	N	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.98781871232288
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.56591247066637

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:	N	**ARC State:**	
Hazmat Rad:	No	**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:	RAY IRANI	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	6196710404	**Bill Code 2:**	Not Applicable
Site Address:	1695 CACTUS RD	**Bill Code 3:**	Not Applicable
Parcel No:	646-270-09-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	1695 CACTUS RD		
Business Type:	Contractors-Street, Painting, Roofers, Building		
Bill Code:	Not Applicable		
ER Con Name:	LUIS KIM		
ER Con Title:	WAREHOUSE MANAGER		
Water Purv:	SAN DIEGO		
Fire Agency:	SAN DIEGO		
Geo SRC:	Mapped to record APN/Parcel XY center		
Match Addr:			
Hirt Flag:	No		
Frhmbp Report Filename:	HMBP207570.pdf		
Frhmbp Sitemap Filename:	MAP_207570.pdf		

10	2 of 3	NNW	0.12 / 614.77	506.99 / -2	**SKS INC** **1695 CACTUS RD, SAN DIEGO, CA 92154** **SAN DIEGO CA 92154**	**HAZ SANDIEGO**

Record ID:	DEH2002-HUPFP-139108	**GIS Record ID:**	DEH2002-HUPFP-139108
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5658794
Facility Latitude:		**GIS Fac Longitude:**	-116.987819
Facility Longitude:			
Facility Address:			
GIS Facility Name:	SKS INC		
GIS Facility Address:	1695 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6462700900
SIC Code:		**X Coord:**	6334338.991
NAICS Code:		**Y Coord:**	1786489.668
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 139108
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334338.99097
UST Facility:		**Point Y:**	1786489.66815
Total No USTs:		**Lat GS84:**	32.5658794
No of Tanks:		**Lon GS84:**	-116.987819
Own Oper APS:	N	**Loc Name:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.98781871232288
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56591247066637
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-270-09-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	1695 CACTUS RD		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

10	3 of 3	NNW	0.12 / 614.77	506.99 / -2	ENERGY LABS, INC. 1695 CACTUS RD SAN DIEGO CA 92154	CERS HAZ

Site ID:	134160
Latitude:	32.56588
Longitude:	-116.987816
County:	

Regulated Programs

EI ID:	10394488	**EI Description:**	Chemical Storage Facilities

Violations

Violation Date:	08/31/2015	**Violation Source:**	CERS
Violation Program:	HMRRP	**Violation Division:**	San Diego County Department of Env Health
Citation:	HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple		
Violation Notes:			

Returned to compliance on 01/11/2016. Inspection Sequence ID:4099942;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date:	08/31/2015	**Violation Source:**	CERS
Violation Program:	HMRRP	**Violation Division:**	San Diego County Department of Env Health

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Notes:

Returned to compliance on 12/01/2015. Inspection Sequence ID:4099942

Violation Description:

Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 11/12/2019 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 25505(c) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(c)
Violation Notes:

Returned to compliance on 12/19/2019. Inspection Sequence ID:6260197

Violation Description:

Failure to have a business plan readily available to personnel of the business or the unified program facility with responsibilities for emergency response or training.

Violations

Violation Date: 11/12/2019 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 12/10/2019. Inspection Sequence ID:6260197

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Evaluations

Eval Date: 08/31/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Eivaz Chantal Inspection ID:4099942; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/12/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Cervantes Diego Inspection ID:6260197; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/12/2017

Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Campanella Luke Inspection ID:5730502; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Operator
Entity Name: LUIS A KIM
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (619) 664-9303

Affil Type Desc: Identification Signer
Entity Name: LUIS KIM
Entity Title: WAREHOUSE MANAGER
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: RAY IRANI
Entity Title:
Address: 1695 CACTUS ROAD
City: SAN DIEGO
State: CA
Country: United States
Zip Code: 92154
Phone: (619) 671-0404

Affil Type Desc: Document Preparer
Entity Name: LUIS A KIM
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Energy Labs Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title:
Address: PO Box 129261
City: San Diego

State:	CA
Country:	
Zip Code:	92112-9261
Phone:	(858) 505-6880
Affil Type Desc:	Environmental Contact
Entity Name:	Luis Kim
Entity Title:	
Address:	1695 CACTUS ROAD
City:	SAN DIEGO
State:	CA
Country:	
Zip Code:	92154
Phone:	
Affil Type Desc:	Property Owner
Entity Name:	RAY IRANI
Entity Title:	
Address:	1695 CACTUS RD
City:	SAN DIEGO
State:	CA
Country:	United States
Zip Code:	92154
Phone:	(310) 466-9429
Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	1695 CACTUS ROAD
City:	SAN DIEGO
State:	CA
Country:	
Zip Code:	92154
Phone:	

Coordinates

Env Int Type Code:	HMBP	**Longitude:**	-116.987820
Program ID:	10394488	**Coord Name:**	
Latitude:	32.565880	**Ref Point Type Desc:**	Center of a facility or station.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	1 of 2	NNW	0.12 / 652.20	506.83 / -2	GM TIRES & ROAD SERVICE, INC 1690 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2009-HUPFP-210591	**GIS Record ID:**	DEH2009-HUPFP-210591
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.566194
Facility Latitude:		**GIS Fac Longitude:**	-116.9888197
Facility Longitude:			
Facility Address:			
GIS Facility Name:	GM TIRES & ROAD SERVICE, INC		
GIS Facility Address:	1690 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

HW Tier:		Basin No:	
LRG QTY MW Gener:		BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	6461901000
SIC Code:		X Coord:	6334030.918
NAICS Code:		Y Coord:	1786601.676
Disclose Qty Haz Mat:		Kiva Per Typ:	HK07 210591
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6334030.9181
UST Facility:		Point Y:	1786601.67613
Total No USTs:		Lat GS84:	32.566194
No of Tanks:		Lon GS84:	-116.9888197
Own Oper APS:	N	Loc Name:	
Tot APSA Cap:	0	Score:	
Capacity LR:		Match Type:	
Haz Waste G:		Side:	
Recycle100:		X Map Coord:	-116.98882114157902
Onsite Haz Waste Tre:		Y Map Coord:	32.56621430883802
RCRA LRG Qty:		User Fld:	
Haz Wst Coll Site:		Addr Type:	
Accept Offs:		ARC Address:	
Universal Waste Han:		ARC City:	
Toxic Gas:		ARC Zipcode:	
Hazmat EHS:		ARC State:	
Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:		Bill Code 3:	
Parcel No:	646-190-10-00	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	1690 CACTUS RD		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

11	2 of 2	NNW	0.12 / 652.20	506.83 / -2	SUNSET CAR RENTAL LLC 1690 CACTUS RD SAN DIEGO CA 92154-8101	RCRA NON GEN

EPA Handler ID:	CAL000367120
Gen Status Universe:	No Report
Contact Name:	DARIO PIAGENTINI
Contact Address:	1690 CACTUS RD , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext:	619-250-1784
Contact Email:	DARIO@NICOMUSA.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20110902
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20110902
Handler Name:	SUNSET CAR RENTAL LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	1690 CACTUS RD
Name:	SUNSET CAR RENTAL LLC	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-270-2355	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154-8101
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	1690 CACTUS RD
Name:	DARIO PIAGENTINI	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-250-1784	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	1 of 7	NNW	0.16 / 821.59	509.79 / 1	**AT&T California - D3179** **1670 CACTUS RD** **SAN DIEGO CA 92154**	**DELISTED TNK**

Delisted San Diego County - UST List

Record ID:	DEH2002-HUPFP-129788	**Haz. Waste Gen:**	false
CERS ID:	10394128	**Recycle:**	false
Permit Status:	Permit Renewed	**Onsite Haz Wt Trt:**	false
Active Permit:	true	**RCRA Large Qty Gen:**	false
Facility Type UST:		**HHW Collection:**	false
Business Phone:	(800) 566-9347	**Last Updated:**	09/23/2020 12:48:00 AM
Business Fax:	0.0	**Atoms:**	
Facility ID:	37-000-129788	**ZIP Codes:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

EPA ID No:	CAL000116895	**Latitude:**	
Haz. Mat. On-Site:	true	**Longitude:**	
Own or Operate UG:	true	**Original Source:**	USSD
Own or Operate AG:	false	**Record Date:**	09-DEC-2020
Mailing Address:	308 S. Akard St., 17th Floor, Dallas, TX 75202		
New Georeferenced:	(32.56651937112131, -116.98824891711917)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	2 of 7	NNW	0.16 / 821.59	509.79 / 1	AT&T California - D3179 1670 CACTUS RD SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-129788	**GIS Record ID:**	DEH2002-HUPFP-129788
Facility Name:	AT&T California - D3179	**GIS Facility City:**	SAN DIEGO
Facility City:	SAN DIEGO	**GIS Facility ZipCode:**	92154
Facility ZipCode:	92154	**GIS Fac Latitude:**	32.5665652
Facility Latitude:		**GIS Fac Longitude:**	-116.9888181
Facility Longitude:			
Facility Address:	1670 CACTUS RD		
GIS Facility Name:	AT&T California - D3179		
GIS Facility Address:	1670 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

Hazardous Materials Facility Data

CERS ID:	10394128	**Onsite H Waste Trtmt:**	false
Facility ID No:	37-000-129788	**Haz Mat on Site:**	true
EPA ID No:	CAL000116895	**Haz Waste Generator:**	true
Active Permit:	true	**Own/Oper Under:**	true
Permit Status:	Permit Renewed	**Own/Oper Above:**	false
Bus. Phone:	(800) 566-9347	**Recycle:**	false
Bus. Fax:	0	**RCRA Large Qty Gen:**	false
Last Updated:	01/26/2022 02:32:41 AM	**HHW Collection:**	false
New Georeferenced Column:			
Mailing Address:	308 S. Akard St., 17th Floor, Dallas, TX 75202		

Hazardous Waste and Materials

ID:	196960	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2019-HCHEM-0208655	**Active Permit:**	true
CAS No:	68476-34-6	**Haz Material Type:**	Pure
Last Updated:	08/17/2019 12:38:45 AM	**Trade Secret:**	false
Chemical Name:	Diesel Fuel No. 2		
Common Name Inventory:	Diesel Fuel No. 2		

ID:	18487	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2017-HCHEM-0129403	**Active Permit:**	true
CAS No:	68476-34-6	**Haz Material Type:**	Pure
Last Updated:	01/18/2018 11:44:44 AM	**Trade Secret:**	false
Chemical Name:	Diesel Fuel No. 2		
Common Name Inventory:	Diesel Fuel No. 2		

ID:	404790	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2021-HWAST-0255939	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	01/26/2022 02:32:41 AM	**Trade Secret:**	false
Chemical Name:			
Common Name Inventory:	Engine maintenance fluids		

ID:	134204	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2018-HCHEM-0169031	**Active Permit:**	true
CAS No:		**Haz Material Type:**	Mixture
Last Updated:	10/20/2018 12:35:25 AM	**Trade Secret:**	false
Chemical Name:	Lead Acid Batteries		
Common Name Inventory:	Lead Acid Batteries		

ID:	18486	**Permit Status:**	Permit Renewed

Child Record ID: DEH2017-HCHEM-0129402
CAS No:
Last Updated: 01/18/2018 11:44:44 AM
Chemical Name: Lead Acid Batteries
Common Name Inventory: Lead Acid Batteries
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 134205
Child Record ID: DEH2018-HCHEM-0169032
CAS No: 68476-34-6
Last Updated: 10/20/2018 12:35:25 AM
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 196959
Child Record ID: DEH2019-HCHEM-0208654
CAS No:
Last Updated: 08/17/2019 12:38:45 AM
Chemical Name: Lead Acid Batteries
Common Name Inventory: Lead Acid Batteries
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 404789
Child Record ID: DEH2021-HCHEM-0286992
CAS No: 68476-34-6
Last Updated: 01/26/2022 02:32:41 AM
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 404788
Child Record ID: DEH2021-HCHEM-0286991
CAS No:
Last Updated: 01/26/2022 02:32:41 AM
Chemical Name: Lead Acid Batteries
Common Name Inventory: Lead Acid Batteries
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

Hazardous Materials Inspection Violations

Container Tank ID:
Facility ID No: 37-000-129788
ID: 10033
UST ID: 28476
Permit Status: Permit Renewed
Active Permit: true
Program Element: Underground Storage Tank
Violation Classification: Class II
Violation Code: 2030036 (TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. 7. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. 8. Inspected within 30 days after a repair to the overfill prevention equipment. 9. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 10. Inspected by a certified UST service technician. 11. Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)
Inspection No: 6057811
Inspection Type: Routine
Inspection Date: 12/06/2018 02:52:56 PM
Compliance Date: 12/06/2018 12:00:00 AM
Last Updated: 01/26/2022 12:00:00 AM
NOV: false

HMD Permits Map Data

GIS Facility ID: 37-000-129788
GIS CERS ID: 10394128
GIS Record Type: LUEG-DEH/HMD/UPFP/Facility
Per Type:
Per Sub Type:
Status:
ER Contact: (800) 566-9347
ER Con Work Ph: (800) 566-9347
Census Tract: 100.15
Parcel Zip: 92154

Per Cat:		**Community:**	San Diego
Record Status:	Permit Renewed	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAL000116895	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HT206
Tank Owner:	8	**Feature ID:**	6461900900
SIC Code:	4813	**X Coord:**	6334030.91753614
NAICS Code:	517311	**Y Coord:**	1786601.67605696
Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	HK07 129788
Exp Date:	1/30/2021	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334030.91753615
UST Facility:	Other	**Point Y:**	1786601.67605697
Total No USTs:	1	**Lat GS84:**	32.5665652
No of Tanks:		**Lon GS84:**	-116.9888181
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	N	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.98882114370865
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.56621430882523
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:	N	**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:	N	**ARC State:**	
Hazmat Rad:	No	**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:	Pacific Bell Telephone Company dba AT&T California	**Indian or Territory:**	N
Email Perm:		**County ID:**	
Phone Perm:	(214) 464-1712	**Bill Code 2:**	Not Applicable
Site Address:	1670 Cactus Rd	**Bill Code 3:**	Not Applicable
Parcel No:	646-190-09-00	**Univ Waste Gen Type:**	

Record Ali:	Unified Program Facility Permit
Address:	1670 CACTUS RD
Business Type:	UST - Non Retail - No Repair Service
Bill Code:	Not Applicable
ER Con Name:	AT&T EH&S Hotline - Option #1
ER Con Title:	Environmental Site Manager
Water Purv:	OTAY WATER IMP DIST C-SEWER
Fire Agency:	SAN DIEGO
Geo SRC:	Mapped to record APN/Parcel XY center
Match Addr:	
Hirt Flag:	No
Frhmbp Report Filename:	HMBP129788.pdf
Frhmbp Sitemap Filename:	MAP_129788.pdf

HMD Facility Data

ID:	29488	**Tank Status:**	Active
Record ID:	DEH2002-HUPFP-129788	**Tank Contents:**	Diesel
Facility ID No:	37-000-129788	**Tank Use:**	05
Tank ID No:	28476	**Type of Tank:**	Double Wall
Permit Status:	Permit Renewed	**Piping System Type:**	Conventional Suction
Active Permit:	true	**Last Updated:**	01/26/2022 02:32:41 AM
Tank Owner Name:	AT&T California		
Facility Type Ust Facility:	Other		
Tank Capacity in Galons:	4030		
Date Ust Permanently Closed:			

HMD Facility Data

ID:	8931	**Tank Status:**	SEE FILE
Record ID:	DEH2002-HUPFP-129788	**Tank Contents:**	Diesel

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID No:	37-000-129788	**Tank Use:**	Emergency Generator Fuel
Tank ID No:	D3179U001	**Type of Tank:**	Double Wall
Permit Status:	Permit Renewed	**Piping System Type:**	Conventional Suction
Active Permit:	true	**Last Updated:**	04/28/2018 02:09:07 AM
Tank Owner Name:	AT&T California		
Facility Type Ust Facility:	Other		
Tank Capacity in Galons:	4000		
Date Ust Permanently Closed:	04/27/2018 12:00:00 AM		

12	3 of 7	NNW	0.16 / 821.59	509.79 / 1	**AT&T California - D3179** **1670 Cactus Rd** **San Diego CA 92154**	UST

Facility ID:	37-000-129788	**Latitude:**	
CERS ID:	10394128	**Longitude:**	
County:	San Diego		
Permitting Agency:	San Diego County Department of Environmental Health		
Note:	Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.gov/search		
Site Facility Type:	PERMITTED UNDERGROUND STORAGE TANK (UST)		

12	4 of 7	NNW	0.16 / 821.59	509.79 / 1	**PACIFIC BELL DBA AT&T OF CA** **1670 CACTUS ROAD** **SAN DIEGO CA 92154**	RCRA LQG

EPA Handler ID:	CAR000286229
Gen Status Universe:	Large Quantity Generator
Contact Name:	MICHAEL JOHNSTON
Contact Address:	1670 , CACTUS ROAD , , SAN DIEGO , CA, 92154 , US
Contact Phone No and Ext:	619-204-9861
Contact Email:	
Contact Country:	US
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	Private
Receive Date:	20180702
Location Latitude:	32.566775
Location Longitude:	-116.98831

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	Yes
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180702
Handler Name: PACIFIC BELL DBA AT&T OF CA
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: U190
Waste Code Description: 1,3-ISOBENZOFURANDIONE (OR) PHTHALIC ANHYDRIDE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: K032
Waste Code Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHLORDANE.

Hazardous Waste Code: P190
Waste Code Description: CARBAMIC ACID, METHYL-, 3-METHYLPHENYL ESTER (OR) METOLCARB

Hazardous Waste Code: P191
Waste Code Description: CARBAMIC ACID, DIMETHYL-, 1-[(DIMETHYL-AMINO)CARBONYL]- 5-METHYL-1H- PYRAZOL-3-YL ESTER (OR) DIMETILAN

Hazardous Waste Code: U042
Waste Code Description: 2-CHLOROETHYL VINYL ETHER (OR) ETHENE, (2-CHLOROETHOXY)-

Hazardous Waste Code: U168
Waste Code Description: 2-NAPTHALENAMINE (OR) BETA-NAPHTHYLAMINE

Hazardous Waste Code: U177
Waste Code Description: N-NITROSO-N-METHYLUREA (OR) UREA, N-METHYL-N-NITROSO-

Hazardous Waste Code: U243
Waste Code Description: 1-PROPENE, 1,1,2,3,3,3-HEXACHLORO- (OR) HEXACHLOROPROPENE

Hazardous Waste Code: F021
Waste Code Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF PENTACHLOROPHENOL, OR OF INTERMEDIATES USED TO PRODUCE DERIVATIVES.

Hazardous Waste Code: F028
Waste Code Description: RESIDUES RESULTING FROM THE INCINERATION OR THERMAL TREATMENT OF SOIL CONTAMINATED WITH EPA HAZARDOUS WASTE NOS. F020, F021, F022, F023, F026, AND F027.

Hazardous Waste Code: K001
Waste Code Description: BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATERS FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Hazardous Waste Code: K061
Waste Code Description: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Hazardous Waste Code: K125
Waste Code Description: FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Hazardous Waste Code: P095
Waste Code Description: CARBONIC DICHLORIDE (OR) PHOSGENE

Hazardous Waste Code:	U093
Waste Code Description:	BENZENAMINE, N,N-DIMETHYL-4-(PHENYLAZO)- (OR) P-DIMETHYLAMINOAZOBENZENE
Hazardous Waste Code:	U170
Waste Code Description:	P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-
Hazardous Waste Code:	U222
Waste Code Description:	BENZENAMINE, 2-METHYL-, HYDROCHLORIDE (OR) O-TOLUIDINE HYDROCHLORIDE
Hazardous Waste Code:	F006
Waste Code Description:	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
Hazardous Waste Code:	F022
Waste Code Description:	WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENES UNDER ALKALINE CONDITIONS.
Hazardous Waste Code:	F025
Waste Code Description:	CONDENSED LIGHT ENDS, SPENT FILTERS AND FILTER AIDS, AND SPENT DESICCANT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION.
Hazardous Waste Code:	K030
Waste Code Description:	COLUMN BOTTOMS OR HEAVY ENDS FROM THE COMBINED PRODUCTION OF TRICHLOROETHYLENE AND PERCHLOROETHYLENE.
Hazardous Waste Code:	K095
Waste Code Description:	DISTILLATION BOTTOMS FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.
Hazardous Waste Code:	K098
Waste Code Description:	UNTREATED PROCESS WASTEWATER FROM THE PRODUCTION OF TOXAPHENE.
Hazardous Waste Code:	U030
Waste Code Description:	4-BROMOPHENYL PHENYL ETHER (OR) BENZENE, 1-BROMO-4-PHENOXY-
Hazardous Waste Code:	P110
Waste Code Description:	PLUMBANE, TETRAETHYL- (OR) TETRAETHYL LEAD
Hazardous Waste Code:	U121
Waste Code Description:	METHANE, TRICHLOROFLUORO- (OR) TRICHLOROMONOFLUOROMETHANE
Hazardous Waste Code:	U135
Waste Code Description:	HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	D042
Waste Code Description:	2,4,6-TRICHLOROPHENOL
Hazardous Waste Code:	F008
Waste Code Description:	PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.
Hazardous Waste Code:	K123
Waste Code Description:	PROCESS WASTEWATER (INCLUDING SUPERNATES, FILTRATES, AND WASHWATERS) FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.
Hazardous Waste Code:	K147
Waste Code Description:	TAR STORAGE RESIDUES FROM COAL TAR REFINING.
Hazardous Waste Code:	K181

Waste Code Description:	Nonwastewaters from the production of dyes and/or pigments.
Hazardous Waste Code:	P027
Waste Code Description:	3-CHLOROPROPIONITRILE (OR) PROPANENITRILE, 3-CHLORO-
Hazardous Waste Code:	P060
Waste Code Description:	1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5BETA, 8BETA, 8ABETA)- (OR) ISODRIN
Hazardous Waste Code:	U410
Waste Code Description:	ETHANIMIDOTHIOIC ACID, N,N'-[THIOBIS[(METHYLIMINO)CARBONYLOXY]]BIS-, DIMETHYL ESTER (OR) THIODICARB
Hazardous Waste Code:	U239
Waste Code Description:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)
Hazardous Waste Code:	U210
Waste Code Description:	ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE
Hazardous Waste Code:	D036
Waste Code Description:	NITROBENZENE
Hazardous Waste Code:	K141
Waste Code Description:	PROCESS RESIDUES FROM THE RECOVERY OF COAL TAR, INCLUDING, BUT NOT LIMITED TO, TAR COLLECTING SUMP RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL. THIS LISTING DOES NOT INCLUDE K087 (DECANTER TANK SLUDGE FROM COKING OPERATIONS).
Hazardous Waste Code:	P009
Waste Code Description:	AMMONIUM PICRATE (R) (OR) PHENOL, 2,4,6-TRINITRO-, AMMONIUM SALT (R)
Hazardous Waste Code:	P042
Waste Code Description:	1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE
Hazardous Waste Code:	P048
Waste Code Description:	2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-
Hazardous Waste Code:	P070
Waste Code Description:	ALDICARB (OR) PROPANAL, 2-METHYL-2-(METHYLTHIO)-, O-[(METHYLAMINO)CARBONYL]OXIME
Hazardous Waste Code:	P076
Waste Code Description:	NITRIC OXIDE (OR) NITROGEN OXIDE NO
Hazardous Waste Code:	P102
Waste Code Description:	2-PROPYN-1-OL (OR) PROPARGYL ALCOHOL
Hazardous Waste Code:	U049
Waste Code Description:	4-CHLORO-O-TOLUIDINE, HYDROCHLORIDE (OR) BENZENAMINE, 4-CHLORO-2-METHYL-, HYDROCHLORIDE
Hazardous Waste Code:	U120
Waste Code Description:	FLUORANTHENE
Hazardous Waste Code:	U169
Waste Code Description:	BENZENE, NITRO- (OR) NITROBENZENE (I,T)
Hazardous Waste Code:	U194
Waste Code Description:	1-PROPANAMINE (I,T) (OR) N-PROPYLAMINE (I,T)
Hazardous Waste Code:	D027
Waste Code Description:	1,4-DICHLOROBENZENE
Hazardous Waste Code:	K047
Waste Code Description:	PINK/RED WATER FROM TNT OPERATIONS.
Hazardous Waste Code:	K117
Waste Code Description:	WASTEWATER FROM THE REACTOR VENT GAS SCRUBBER IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Hazardous Waste Code: P103
Waste Code Description: SELENOUREA

Hazardous Waste Code: P113
Waste Code Description: THALLIC OXIDE (OR) THALLIUM OXIDE TL2O3

Hazardous Waste Code: P198
Waste Code Description: METHANIMIDAMIDE, N,N-DIMETHYL-N'-[3-[[(METHYLAMINO)-CARBONYL]OXY]PHENYL]-, MONOHYDROCHLORIDE (OR) FORMETANATE HYDROCHLORIDE

Hazardous Waste Code: U014
Waste Code Description: AURAMINE (OR) BENZENAMINE, 4,4'-CARBONIMIDOYLBIS[N,N-DIMETHYL-

Hazardous Waste Code: U039
Waste Code Description: P-CHLORO-M-CRESOL (OR) PHENOL, 4-CHLORO-3-METHYL-

Hazardous Waste Code: U102
Waste Code Description: 1,2-BENZENEDICARBOXYLIC ACID, DIMETHYL ESTER (OR) DIMETHYL PHTHALATE

Hazardous Waste Code: U189
Waste Code Description: PHOSPHORUS SULFIDE (R) (OR) SULFUR PHOSPHIDE (R)

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: K025
Waste Code Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF NITROBENZENE BY THE NITRATION OF BENZENE.

Hazardous Waste Code: P067
Waste Code Description: 1,2-PROPYLENIMINE (OR) AZIRIDINE, 2-METHYL-

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U378
Waste Code Description: CARBAMODITHIOIC ACID, (HYDROXYMETHYL) METHYL-, MONOPOTASSIUM SALT (OR) POTASSIUM N-HYDROXYMETHYL- N-METHYLDI-THIOCARBAMATE

Hazardous Waste Code: F024
Waste Code Description: PROCESS WASTES INCLUDING, BUT NOT LIMITED TO, DISTILLATION RESIDUES, HEAVY ENDS, TARS, AND REACTOR CLEAN-OUT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION. (THIS LISTING DOES NOT INCLUDE WASTEWATERS, WASTEWATER TREATMENT SLUDGE, SPENT CATALYSTS, AND WASTES LISTED IN SECTIONS 261.31. OR 261.32)

Hazardous Waste Code: K029
Waste Code Description: WASTE FROM THE PRODUCT STEAM STRIPPER IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Hazardous Waste Code: K083
Waste Code Description: DISTILLATION BOTTOMS FROM ANILINE PRODUCTION.

Hazardous Waste Code: P036
Waste Code Description: ARSONOUS DICHLORIDE, PHENYL- (OR) DICHLOROPHENYLARSINE

Hazardous Waste Code: P084
Waste Code Description: N-NITROSOMETHYLVINYLAMINE (OR) VINYLAMINE, N-METHYL-N-NITROSO-

Hazardous Waste Code: P205
Waste Code Description: ZINC, BIS(DIMETHYLCARBAMODITHIOATO-S,S')-, (OR) ZIRAM

Hazardous Waste Code: U082
Waste Code Description: 2,6-DICHLOROPHENOL (OR) PHENOL, 2,6-DICHLORO-

Hazardous Waste Code: U083
Waste Code Description: PROPANE, 1,2-DICHLORO- (OR) PROPYLENE DICHLORIDE

Hazardous Waste Code: U155
Waste Code Description: 1,2-ETHANEDIAMINE, N,N-DIMETHYL-N'-2-PYRIDINYL-N'-(2-THIENYLMETHYL)- (OR) METHAPYRILENE

Hazardous Waste Code: K094
Waste Code Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM ORTHO-XYLENE.

Hazardous Waste Code: K034
Waste Code Description: FILTER SOLIDS FROM THE FILTRATION OF HEXACHLOROCYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Hazardous Waste Code: F032
Waste Code Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT CURRENTLY USE, OR HAVE PREVIOUSLY USED, CHLOROPHENOLIC FORMULATIONS [EXCEPT POTENTIALLY CROSS-CONTAMINATED WASTES THAT HAVE HAD THE F032 WASTE CODE DELETED IN ACCORDANCE WITH SECTION 261.35 (I.E., THE NEWLY PROMULGATED EQUIPMENT CLEANING OR REPLACEMENT STANDARDS), AND WHERE THE GENERATOR DOES NOT RESUME OR INITIATE USE OF CHLOROPHENOLIC FORMULATIONS]. (THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.)

Hazardous Waste Code: K112
Waste Code Description: REACTION BY-PRODUCT WATER FROM THE DRYING COLUMN IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Hazardous Waste Code: D025
Waste Code Description: P-CRESOL

Hazardous Waste Code: F039
Waste Code Description: LEACHATE RESULTING FROM THE TREATMENT, STORAGE, OR DISPOSAL OF WASTES CLASSIFIED BY MORE THAN ONE WASTE CODE UNDER SUBPART D, OR FROM A MIXTURE OF WASTES CLASSIFIED UNDER SUBPARTS C AND D OF THIS PART. (LEACHATE RESULTING FROM THE MANAGEMENT OF ONE OR MORE OF THE FOLLOWING EPA HAZARDOUS WASTES AND NO OTHER HAZARDOUS WASTES RETAINS ITS HAZARDOUS WASTE CODE(S): F020, F021, F022, F023, F026, F027, AND/OR F028.)

Hazardous Waste Code: K051
Waste Code Description: API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Hazardous Waste Code: U103
Waste Code Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Hazardous Waste Code: U158
Waste Code Description: 4,4'-METHYLENEBIS(2-CHLOROANILINE) (OR) BENZENAMINE, 4,4'-METHYLENEBIS[2-CHLORO-

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: U367
Waste Code Description: 7-BENZOFURANOL, 2,3-DIHYDRO-2,2-DIMETHYL- (OR) CARBOFURAN PHENOL

Hazardous Waste Code: P006
Waste Code Description: ALUMINUM PHOSPHIDE (R,T)

Hazardous Waste Code: P068
Waste Code Description: HYDRAZINE, METHYL- (OR) METHYL HYDRAZINE

Hazardous Waste Code: P199
Waste Code Description: METHIOCARB (OR) MEXACARBATE (OR) PHENOL, (3,5-DIMETHYL-4-(METHYLTHIO)-, METHYLCARBAMATE

Hazardous Waste Code: U235
Waste Code Description: 1-PROPANOL, 2,3-DIBROMO-, PHOSPHATE (3:1) (OR) TRIS(2,3,-DIBROMOPROPYL) PHOSPHATE

Hazardous Waste Code: K159
Waste Code Description: ORGANICS FROM THE TREATMENT OF THIOCARBAMATE WASTES.

Hazardous Waste Code:	U132
Waste Code Description:	HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-
Hazardous Waste Code:	U237
Waste Code Description:	2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]- (OR) URACIL MUSTARD
Hazardous Waste Code:	U404
Waste Code Description:	ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE
Hazardous Waste Code:	P008
Waste Code Description:	4-AMINOPYRIDINE (OR) 4-PYRIDINAMINE
Hazardous Waste Code:	P057
Waste Code Description:	ACETAMIDE, 2-FLUORO- (OR) FLUOROACETAMIDE
Hazardous Waste Code:	U018
Waste Code Description:	BENZ[A]ANTHRACENE
Hazardous Waste Code:	U038
Waste Code Description:	BENZENEACETIC ACID, 4-CHLORO-ALPHA-(4-CHLOROPHENYL)-ALPHA-HYDROXY-, ETHYL ESTER (OR) CHLOROBENZILATE
Hazardous Waste Code:	U050
Waste Code Description:	CHRYSENE
Hazardous Waste Code:	U088
Waste Code Description:	1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE
Hazardous Waste Code:	K015
Waste Code Description:	STILL BOTTOMS FROM THE DISTILLATION OF BENZYL CHLORIDE.
Hazardous Waste Code:	K111
Waste Code Description:	PRODUCT WASHWATERS FROM THE PRODUCTION OF DINITROTOLUENE VIA NITRATION OF TOLUENE.
Hazardous Waste Code:	P038
Waste Code Description:	ARSINE, DIETHYL- (OR) DIETHYLARSINE
Hazardous Waste Code:	U017
Waste Code Description:	BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-
Hazardous Waste Code:	U027
Waste Code Description:	DICHLOROISOPROPYL ETHER (OR) PROPANE, 2,2'-OXYBIS[2-CHLORO-
Hazardous Waste Code:	U057
Waste Code Description:	CYCLOHEXANONE (I)
Hazardous Waste Code:	U156
Waste Code Description:	CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)
Hazardous Waste Code:	K020
Waste Code Description:	HEAVY ENDS FROM THE DISTILLATION OF VINYL CHLORIDE IN VINYL CHLORIDE MONOMER PRODUCTION.
Hazardous Waste Code:	U196
Waste Code Description:	PYRIDINE
Hazardous Waste Code:	D004
Waste Code Description:	ARSENIC
Hazardous Waste Code:	F012
Waste Code Description:	QUENCHING WASTEWATER TREATMENT SLUDGES FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.
Hazardous Waste Code:	F035
Waste Code Description:	WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE INORGANIC PRESERVATIVES CONTAINING ARSENIC OR CHROMIUM. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Hazardous Waste Code:	K038
Waste Code Description:	WASTEWATER FROM THE WASHING AND STRIPPING OF PHORATE PRODUCTION.
Hazardous Waste Code:	P041
Waste Code Description:	DIETHYL-P-NITROPHENYL PHOSPHATE (OR) PHOSPHORIC ACID, DIETHYL 4-NITROPHENYL ESTER
Hazardous Waste Code:	P054
Waste Code Description:	AZIRIDINE (OR) ETHYLENEIMINE
Hazardous Waste Code:	P115
Waste Code Description:	SULFURIC ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SULFATE
Hazardous Waste Code:	U022
Waste Code Description:	BENZO[A]PYRENE
Hazardous Waste Code:	U053
Waste Code Description:	2-BUTENAL (OR) CROTONALDEHYDE
Hazardous Waste Code:	U066
Waste Code Description:	1,2-DIBROMO-3-CHLOROPROPANE (OR) PROPANE, 1,2-DIBROMO-3-CHLORO-
Hazardous Waste Code:	U073
Waste Code Description:	[1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DICHLORO- (OR) 3,3'-DICHLOROBENZIDINE
Hazardous Waste Code:	U163
Waste Code Description:	GUANIDINE, N-METHYL-N'-NITRO-N-NITROSO- (OR) MNNG
Hazardous Waste Code:	U193
Waste Code Description:	1,2-OXATHIOLANE, 2,2-DIOXIDE (OR) 1,3-PROPANE SULTONE
Hazardous Waste Code:	K004
Waste Code Description:	WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF ZINC YELLOW PIGMENTS.
Hazardous Waste Code:	K073
Waste Code Description:	CHLORINATED HYDROCARBON WASTE FROM THE PURIFICATION STEP OF THE DIAPHRAGM CELL PROCESS USING GRAPHITE ANODES IN CHLORINE PRODUCTION.
Hazardous Waste Code:	K086
Waste Code Description:	SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.
Hazardous Waste Code:	P058
Waste Code Description:	ACETIC ACID, FLUORO-, SODIUM SALT (OR) FLUOROACETIC ACID, SODIUM SALT
Hazardous Waste Code:	U183
Waste Code Description:	BENZENE, PENTACHLORO- (OR) PENTACHLOROBENZENE
Hazardous Waste Code:	U217
Waste Code Description:	NITRIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) NITRATE
Hazardous Waste Code:	U206
Waste Code Description:	D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN
Hazardous Waste Code:	U201
Waste Code Description:	1,3-BENZENEDIOL (OR) RESORCINOL
Hazardous Waste Code:	D015
Waste Code Description:	TOXAPHENE (C10 H10 CL8, TECHNICAL CHLORINATED CAMPHENE, 67-69 PERCENT CHLORINE)
Hazardous Waste Code:	D033
Waste Code Description:	HEXACHLOROBUTADIENE
Hazardous Waste Code:	F003
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE

SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P114
Waste Code Description: SELENIOUS ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SELENITE

Hazardous Waste Code: U008
Waste Code Description: 2-PROPENOIC ACID (I) (OR) ACRYLIC ACID (I)

Hazardous Waste Code: U020
Waste Code Description: BENZENESULFONIC ACID CHLORIDE (C,R) (OR) BENZENESULFONYL CHLORIDE (C,R)

Hazardous Waste Code: U080
Waste Code Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Hazardous Waste Code: U085
Waste Code Description: 1,2:3,4-DIEPOXYBUTANE (I,T) (OR) 2,2'-BIOXIRANE

Hazardous Waste Code: U130
Waste Code Description: 1,3-CYCLOPENTADIENE, 1,2,3,4,5,5-HEXACHLORO- (OR) HEXACHLOROCYCLOPENTADIENE

Hazardous Waste Code: U147
Waste Code Description: 2,5-FURANDIONE (OR) MALEIC ANHYDRIDE

Hazardous Waste Code: K113
Waste Code Description: CONDENSED LIQUID LIGHT ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: K041
Waste Code Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF TOXAPHENE.

Hazardous Waste Code: K050
Waste Code Description: HEAT EXCHANGER BUNDLE CLEANING SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Hazardous Waste Code: K158
Waste Code Description: BAG HOUSE DUSTS AND FILTER/SEPARATION SOLIDS FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Hazardous Waste Code: P020
Waste Code Description: DINOSEB (OR) PHENOL, 2-(1-METHYLPROPYL)-4,6-DINITRO-

Hazardous Waste Code: P026
Waste Code Description: 1-(O-CHLOROPHENYL)THIOUREA (OR) THIOUREA, (2-CHLOROPHENYL)-

Hazardous Waste Code: P192
Waste Code Description: ISOLAN (OR) CARBAMIC ACID, DIMETHYL-, 3-METHY-L-(1-METHYLETHYL)-1H- PYRAZOL-5-YL ESTER

Hazardous Waste Code: U186
Waste Code Description: 1,3-PENTADIENE (I) (OR) 1-METHYLBUTADIENE (I)

Hazardous Waste Code: U215
Waste Code Description: CARBONIC ACID, DITHALLIUM(1+) SALT (OR) THALLIUM(I) CARBONATE

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: U236
Waste Code Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO-4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Hazardous Waste Code:	K157
Waste Code Description:	WASTEWATERS (INCLUDING SCRUBBER WATERS, CONDENSER WATERS, WASHWATERS, AND SEPARATION WATERS) FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.
Hazardous Waste Code:	K116
Waste Code Description:	ORGANIC CONDENSATE FROM THE SOLVENT RECOVERY COLUMN IN THE PRODUCTION OF TOLUENE DIISOCYANATE VIA PHOSGENATION OF TOLUENEDIAMINE.
Hazardous Waste Code:	K036
Waste Code Description:	STILL BOTTOMS FROM TOLUENE RECLAMATION DISTILLATION IN THE PRODUCTION OF DISULFOTON.
Hazardous Waste Code:	U353
Waste Code Description:	BENZENAMINE, 4-METHYL- (OR) P-TOLUIDINE
Hazardous Waste Code:	U280
Waste Code Description:	BARBAN (OR) CARBAMIC ACID, (3-CHLOROPHENYL)-, 4-CHLORO-2-BUTYNYL ESTER
Hazardous Waste Code:	U249
Waste Code Description:	ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	D026
Waste Code Description:	CRESOL
Hazardous Waste Code:	D029
Waste Code Description:	1,1-DICHLOROETHYLENE
Hazardous Waste Code:	K023
Waste Code Description:	DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.
Hazardous Waste Code:	K060
Waste Code Description:	AMMONIA STILL LIME SLUDGE FROM COKING OPERATIONS.
Hazardous Waste Code:	K107
Waste Code Description:	COLUMN BOTTOMS FROM PRODUCT SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE (UDMH) FROM CARBOXYLIC ACID HYDRAZIDES.
Hazardous Waste Code:	K150
Waste Code Description:	ORGANIC RESIDULES EXCLUDING SPENT CARBON ADSORBENT, FROM THE SPENT CHLORINE GAS AND HYDROCHLORIC ACID RECOVERY PROCESSES ASSOCIATED WITH THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.
Hazardous Waste Code:	P033
Waste Code Description:	CYANOGEN CHLORIDE (OR) CYANOGEN CHLORIDE (CN)CL
Hazardous Waste Code:	P043
Waste Code Description:	DIISOPROPYLFLUOROPHOSPHATE (DFP) (OR) PHOSPHOROFLUORIDIC ACID, BIS(1-METHYLETHYL) ESTER
Hazardous Waste Code:	U078
Waste Code Description:	1,1-DICHLOROETHYLENE (OR) ETHENE, 1,1-DICHLORO-
Hazardous Waste Code:	U084
Waste Code Description:	1,3-DICHLOROPROPENE (OR) 1-PROPENE, 1,3-DICHLORO-
Hazardous Waste Code:	U119
Waste Code Description:	ETHYL METHANESULFONATE (OR) METHANESULFONIC ACID, ETHYL ESTER
Hazardous Waste Code:	U171
Waste Code Description:	2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)
Hazardous Waste Code:	P064
Waste Code Description:	METHANE, ISOCYANATO- (OR) METHYL ISOCYANATE
Hazardous Waste Code:	P123
Waste Code Description:	TOXAPHENE

Hazardous Waste Code: U012
Waste Code Description: ANILINE (I,T) (OR) BENZENAMINE (I,T)

Hazardous Waste Code: U052
Waste Code Description: CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-

Hazardous Waste Code: U067
Waste Code Description: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

Hazardous Waste Code: K101
Waste Code Description: DISTILLATION TAR RESIDUES FROM THE DISTILLATION OF ANILINE-BASED COMPOUNDS IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Hazardous Waste Code: K176
Waste Code Description: BAGHOUSE FILTERS FROM THE PRODUCTION OF ANTIMONY OXIDE, INCLUDING FILTERS FROM THE PRODUCTION OF INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Hazardous Waste Code: U099
Waste Code Description: 1,2-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Hazardous Waste Code: U395
Waste Code Description: DIETHYLENE GLYCOL, DICARBAMATE (OR) ETHANOL, 2,2'-OXYBIS-, DICARBAMATE

Hazardous Waste Code: P097
Waste Code Description: FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

Hazardous Waste Code: U089
Waste Code Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Hazardous Waste Code: P050
Waste Code Description: 6,9-METHANO-2,4,3-BENZODIOXATHIEPIN,6,7,8,9,10,10-HEXACHLORO-1,5,5A,6,9,9A-HEXAHYDRO-,3-OXIDE (OR) ENDOSULFAN

Hazardous Waste Code: P011
Waste Code Description: ARSENIC OXIDE AS2O5 (OR) ARSENIC PENTOXIDE

Hazardous Waste Code: U106
Waste Code Description: 2,6-DINITROTOLUENE (OR) BENZENE, 2-METHYL-1,3-DINITRO-

Hazardous Waste Code: U167
Waste Code Description: 1-NAPTHALENAMINE (OR) ALPHA-NAPHTHYLAMINE

Hazardous Waste Code: U172
Waste Code Description: 1-BUTANAMINE, N-BUTYL-N-NITROSO- (OR) N-NITROSODI-N-BUTYLAMINE

Hazardous Waste Code: U364
Waste Code Description: BENDIOCARB PHENOL (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-

Hazardous Waste Code: U211
Waste Code Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Hazardous Waste Code: F023
Waste Code Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- AND TETRACHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE WASTES FROM EQUIPMENT USED ONLY FOR THE PRODUCTION OR USE OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)

Hazardous Waste Code: F026
Waste Code Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENE UNDER ALKALINE CONDITIONS.

Hazardous Waste Code: K156

Waste Code Description:	ORGANIC WASTE (INCLUDING HEAVY ENDS, STILL BOTTOMS, LIGHT ENDS, SPENT SOLVENTS, FILTRATES, AND DECANTATES) FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.
Hazardous Waste Code:	P003
Waste Code Description:	2-PROPENAL (OR) ACROLEIN
Hazardous Waste Code:	P039
Waste Code Description:	DISULFOTON (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[2-(ETHYLTHIO)ETHYL] ESTER
Hazardous Waste Code:	P062
Waste Code Description:	HEXAETHYL TETRAPHOSPHATE (OR) TETRAPHOSPHORIC ACID, HEXAETHYL ESTER
Hazardous Waste Code:	U149
Waste Code Description:	MALONONITRILE (OR) PROPANEDINITRILE
Hazardous Waste Code:	U221
Waste Code Description:	BENZENEDIAMINE, AR-METHYL- (OR) TOLUENEDIAMINE
Hazardous Waste Code:	D010
Waste Code Description:	SELENIUM
Hazardous Waste Code:	U024
Waste Code Description:	DICHLOROMETHOXY ETHANE (OR) ETHANE, 1,1'-[METHYLENEBIS(OXY)]BIS[2-CHLORO-
Hazardous Waste Code:	U074
Waste Code Description:	1,4-DICHLORO-2-BUTENE (I,T) (OR) 2-BUTENE, 1,4-DICHLORO- (I,T)
Hazardous Waste Code:	U138
Waste Code Description:	METHANE, IODO- (OR) METHYL IODIDE
Hazardous Waste Code:	K017
Waste Code Description:	HEAVY ENDS (STILL BOTTOMS) FROM THE PURIFICATION COLUMN IN THE PRODUCTION OF EPICHLOROHYDRIN.
Hazardous Waste Code:	K100
Waste Code Description:	WASTE LEACHING SOLUTION FROM ACID LEACHING OF EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.
Hazardous Waste Code:	P028
Waste Code Description:	BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE
Hazardous Waste Code:	U005
Waste Code Description:	2-ACETYLAMINOFLUORENE (OR) ACETAMIDE, N-9H-FLUOREN-2-YL
Hazardous Waste Code:	U134
Waste Code Description:	HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)
Hazardous Waste Code:	U136
Waste Code Description:	ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID
Hazardous Waste Code:	U176
Waste Code Description:	N-NITROSO-N-ETHYLUREA (OR) UREA, N-ETHYL-N-NITROSO-
Hazardous Waste Code:	U238
Waste Code Description:	CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)
Hazardous Waste Code:	U191
Waste Code Description:	2-PICOLINE (OR) PYRIDINE, 2-METHYL-
Hazardous Waste Code:	D020
Waste Code Description:	CHLORDANE
Hazardous Waste Code:	K007
Waste Code Description:	WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF IRON BLUE PIGMENTS.
Hazardous Waste Code:	U208
Waste Code Description:	1,1,1,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,1,2-TETRACHLORO-
Hazardous Waste Code:	K019

Waste Code Description:	HEAVY ENDS FROM THE DISTILLATION OF ETHYLENE DICHLORIDE IN ETHYLENE DICHLORIDE PRODUCTION.
Hazardous Waste Code:	K087
Waste Code Description:	DECANTER TANK TAR SLUDGE FROM COKING OPERATIONS.
Hazardous Waste Code:	U076
Waste Code Description:	ETHANE, 1,1-DICHLORO- (OR) ETHYLIDENE DICHLORIDE
Hazardous Waste Code:	U141
Waste Code Description:	1,3-BENZODIOXOLE, 5-(1-PROPENYL)- (OR) ISOSAFROLE
Hazardous Waste Code:	D023
Waste Code Description:	O-CRESOL
Hazardous Waste Code:	K048
Waste Code Description:	DISSOLVED AIR FLOTATION (DAF) FLOAT FROM THE PETROLEUM REFINING INDUSTRY.
Hazardous Waste Code:	K109
Waste Code Description:	SPENT FILTER CARTRIDGES FROM PRODUCT PURIFICATION FROM THE PRODUCT OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.
Hazardous Waste Code:	P024
Waste Code Description:	BENZENAMINE, 4-CHLORO- (OR) P-CHLORANILINE
Hazardous Waste Code:	P074
Waste Code Description:	NICKEL CYANIDE (OR) NICKEL CYANIDE NI(CN)2
Hazardous Waste Code:	P081
Waste Code Description:	1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)
Hazardous Waste Code:	P088
Waste Code Description:	7-OXABICYCLO[2.2.1]HEPTANE-2,3-DICARBOXYLIC ACID (OR) ENDOTHALL
Hazardous Waste Code:	P203
Waste Code Description:	ALDICARB SULFONE (OR) PROPANAL, 2-METHYL-2-(METHYL-SULFONYL)-, O-[(METHYLAMINO) CARBONYL] OXIME
Hazardous Waste Code:	U055
Waste Code Description:	BENZENE, (1-METHYLETHYL)- (I) (OR) CUMENE (I)
Hazardous Waste Code:	U062
Waste Code Description:	CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3-DICHLORO-2-PROPENYL) ESTER (OR) DIALLATE
Hazardous Waste Code:	U069
Waste Code Description:	1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE
Hazardous Waste Code:	U480
Waste Code Description:	2,4,6, TRIBROMPHENOL (I.E.; DISCARDED COMMERCIAL CHEMICAL PRODUCTS, OFF-SPECIFICATION SPECIES, CONTAINER RESIDUES, AND SPILL RESIDUES THEREOF)
Hazardous Waste Code:	D016
Waste Code Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Hazardous Waste Code:	K096
Waste Code Description:	HEAVY ENDS FROM THE HEAVY ENDS COLUMN FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.
Hazardous Waste Code:	P085
Waste Code Description:	DIPHOSPHORAMIDE, OCTAMETHYL- (OR) OCTAMETHYLPYROPHOSPHORAMIDE
Hazardous Waste Code:	P101
Waste Code Description:	ETHYL CYANIDE (OR) PROPANENITRILE
Hazardous Waste Code:	K044
Waste Code Description:	WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING AND PROCESSING OF EXPLOSIVES.
Hazardous Waste Code:	K108
Waste Code Description:	CONDENSED COLUMN OVERHEADS FROM PRODUCT SEPARATION AND CONDENSED REACTOR VENT

GASES FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Hazardous Waste Code: K131
Waste Code Description: WASTEWATER FROM THE REACTOR AND SPENT SULFURIC ACID FROM THE ACID DRYER FROM THE PRODUCTION OF METHYL BROMIDE.

Hazardous Waste Code: P094
Waste Code Description: PHORATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[(ETHYLTHIO)METHYL] ESTER

Hazardous Waste Code: P116
Waste Code Description: HYDRAZINECARBOTHIOAMIDE (OR) THIOSEMICARBAZIDE

Hazardous Waste Code: U105
Waste Code Description: 2,4-DINITROTOLUENE (OR) BENZENE, 1-METHYL-2,4-DINITRO-

Hazardous Waste Code: U108
Waste Code Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Hazardous Waste Code: U187
Waste Code Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Hazardous Waste Code: U373
Waste Code Description: CARBAMIC ACID, PHENYL-, 1-METHYLETHYL ESTER (OR) PROPHAM

Hazardous Waste Code: U227
Waste Code Description: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

Hazardous Waste Code: U219
Waste Code Description: THIOUREA

Hazardous Waste Code: U218
Waste Code Description: ETHANETHIOAMIDE (OR) THIOACETAMIDE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: K002
Waste Code Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME YELLOW AND ORANGE PIGMENTS.

Hazardous Waste Code: K046
Waste Code Description: WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING, FORMULATION, AND LOADING OF LEAD-BASED INITIATING COMPOUNDS.

Hazardous Waste Code: K171
Waste Code Description: SPENT HYDROTREATING CATALYST FROM PETROLEUM REFINING OPERATIONS,INCLUDING GUARD BEDS USED TO DESULFURIZE FEEDS TO OTHER CATALYTIC REACTORS (THIS LISTING DOES NOT INCLUDE INERT SUPPORT MEDIA)

Hazardous Waste Code: P065
Waste Code Description: FULMINIC ACID, MERCURY(2+) SALT (R,T) (OR) MERCURY FULMINATE (R,T)

Hazardous Waste Code: P108
Waste Code Description: STRYCHNIDIN-10-ONE, & SALTS (OR) STRYCHNINE, & SALTS

Hazardous Waste Code: U009
Waste Code Description: 2-PROPENENITRILE (OR) ACRYLONITRILE

Hazardous Waste Code: U071
Waste Code Description: BENZENE, 1,3-DICHLORO- (OR) M-DICHLOROBENZENE

Hazardous Waste Code: K010
Waste Code Description: DISTILLATION SIDE CUTS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.

Hazardous Waste Code: K069
Waste Code Description: EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.

Hazardous Waste Code: P023
Waste Code Description: ACETALDEHYDE, CHLORO- (OR) CHLOROACETALDEHYDE

Hazardous Waste Code:	P037
Waste Code Description:	2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2AALPHA, 3BETA, 6BETA, 6AALPHA, 7BETA, 7AALPHA)- (OR) DIELDRIN
Hazardous Waste Code:	P189
Waste Code Description:	CARBAMIC ACID, [(DIBUTYLAMINO)-THIO]METHYL-, 2,3-DIHYDRO-2,2-DIMETHYL -7-BENZOFURANYL ESTER (OR) CARBOSULFAN
Hazardous Waste Code:	U002
Waste Code Description:	2-PROPANONE (I) (OR) ACETONE (I)
Hazardous Waste Code:	U004
Waste Code Description:	ACETOPHENONE (OR) ETHANONE, 1-PHENYL-
Hazardous Waste Code:	U016
Waste Code Description:	BENZ[C]ACRIDINE
Hazardous Waste Code:	U028
Waste Code Description:	1,2-BENZENEDICARBOXYLIC ACID, BIS(2-ETHYLHEXYL) ESTER (OR) DIETHYLHEXYL PHTHALATE
Hazardous Waste Code:	U036
Waste Code Description:	4,7-METHANO-1H-INDENE, 1,2,4,5,6,7,8,8-OCTACHLORO-2,3,3A,4,7,7A-HEXAHYDRO- (OR) CHLORDANE, ALPHA & GAMMA ISOMERS
Hazardous Waste Code:	U077
Waste Code Description:	ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE
Hazardous Waste Code:	U144
Waste Code Description:	ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE
Hazardous Waste Code:	U150
Waste Code Description:	L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN
Hazardous Waste Code:	U192
Waste Code Description:	BENZAMIDE, 3,5-DICHLORO-N-(1,1-DIMETHYL-2-PROPYNYL)- (OR) PRONAMIDE
Hazardous Waste Code:	U081
Waste Code Description:	2,4-DICHLOROPHENOL (OR) PHENOL, 2,4-DICHLORO-
Hazardous Waste Code:	U205
Waste Code Description:	SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)
Hazardous Waste Code:	U372
Waste Code Description:	CARBAMIC ACID, 1H-BENZIMIDAZOL-2-YL, METHYL ESTER (OR) CARBENDAZIM
Hazardous Waste Code:	U278
Waste Code Description:	BENDIOCARB (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-, METHYL CARBAMATE
Hazardous Waste Code:	D035
Waste Code Description:	METHYL ETHYL KETONE
Hazardous Waste Code:	K110
Waste Code Description:	CONDENSED COLUMN OVERHEADS FROM INTERMEDIATE SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.
Hazardous Waste Code:	K142
Waste Code Description:	TANK STORAGE RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR FROM THE RECOVERY OF COKE BY-PRODUCTS FROM COAL.
Hazardous Waste Code:	K170
Waste Code Description:	CLARIFIED SLURRY OIL TANK SEDIMENT AND/OR IN-LINE FILTER/SEPARATION SOLIDS FROM PETROLEUM REFINING OPERATIONS
Hazardous Waste Code:	P031
Waste Code Description:	CYANOGEN (OR) ETHANEDINITRILE
Hazardous Waste Code:	U097
Waste Code Description:	CARBAMIC CHLORIDE, DIMETHYL- (OR) DIMETHYLCARBAMOYL CHLORIDE

Hazardous Waste Code:	U143
Waste Code Description:	2-BUTENOIC ACID, 2-METHYL-, 7-[[2,3-DIHYDROXY-2-(1-METHOXYETHYL)-3-METHYL-1-OXOBUTOXY] METHYL]-2,3,5,7A-TETRAHYDRO-1H-PYRROLIZIN-1-YL ESTER, [1S-[1ALPHA(Z), 7(2S*,3R*), 7AALPHA]]- (OR) LASIOCARPINE
Hazardous Waste Code:	U161
Waste Code Description:	4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-
Hazardous Waste Code:	K126
Waste Code Description:	BAGHOUSE DUST AND FLOOR SWEEPINGS IN MILLING AND PACKAGING OPERATIONS FROM PRODUCTION OR FORMULATION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.
Hazardous Waste Code:	K132
Waste Code Description:	SPENT ABSORBENT AND WASTEWATER SEPARATOR SOLIDS FROM THE PRODUCTION OF METHYL BROMIDE.
Hazardous Waste Code:	D041
Waste Code Description:	2,4,5-TRICHLOROPHENOL
Hazardous Waste Code:	D003
Waste Code Description:	REACTIVE WASTE
Hazardous Waste Code:	U142
Waste Code Description:	1,3,4-METHENO-2H-CYCLOBUTA[CD]PENTALEN-2-ONE, 1,1A,3,3A,4,5,5,5A,5B,6- DECACHLOROOCTAHYDRO- (OR) KEPONE
Hazardous Waste Code:	U035
Waste Code Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL
Hazardous Waste Code:	P096
Waste Code Description:	HYDROGEN PHOSPHIDE (OR) PHOSPHINE
Hazardous Waste Code:	P004
Waste Code Description:	1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5ALPHA, 8ALPHA, 8ABETA)- (OR) ALDRIN
Hazardous Waste Code:	P104
Waste Code Description:	SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)
Hazardous Waste Code:	U128
Waste Code Description:	1,3-BUTADIENE, 1,1,2,3,4,4-HEXACHLORO- (OR) HEXACHLOROBUTADIENE
Hazardous Waste Code:	P128
Waste Code Description:	PHENOL, 4-(DIMETHYLAMINO)-3,5-DIMETHYL-, METHYLCARBAMATE (ESTER)
Hazardous Waste Code:	LABP
Waste Code Description:	LAB PACK
Hazardous Waste Code:	F004
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	K008
Waste Code Description:	OVEN RESIDUE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS.
Hazardous Waste Code:	K093
Waste Code Description:	DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM ORTHO-XYLENE.
Hazardous Waste Code:	K175
Waste Code Description:	WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF VINYL CHLORIDE MONOMER..
Hazardous Waste Code:	P111
Waste Code Description:	DIPHOSPHORIC ACID, TETRAETHYL ESTER (OR) TETRAETHYL PYROPHOSPHATE

Hazardous Waste Code: P112
Waste Code Description: METHANE, TETRANITRO- (R) (OR) TETRANITROMETHANE (R)

Hazardous Waste Code: U151
Waste Code Description: MERCURY

Hazardous Waste Code: U157
Waste Code Description: 3-METHYLCHOLANTHRENE (OR) BENZ[J]ACEANTHRYLENE, 1,2-DIHYDRO-3-METHYL-

Hazardous Waste Code: U160
Waste Code Description: 2-BUTANONE, PEROXIDE (R,T) (OR) METHYL ETHYL KETONE PEROXIDE (R,T)

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: K006
Waste Code Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS (ANHYDROUS AND HYDRATED).

Hazardous Waste Code: D013
Waste Code Description: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D012
Waste Code Description: ENDRIN (1,2,3,4,10,10-HEXACHLORO-1,7-EPOXY-1,4,4A,5,6,7,8,8A-OCTAHYDRO-1,4-ENDO, ENDO-5,8-DIMETH-ANO-NAPHTHALENE)

Hazardous Waste Code: U248
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: U112
Waste Code Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Hazardous Waste Code: U185
Waste Code Description: BENZENE, PENTACHLORONITRO- (OR) PENTACHLORONITROBENZENE (PCNB)

Hazardous Waste Code: K099
Waste Code Description: UNTREATED WASTEWATER FROM THE PRODUCTION OF 2,4-D.

Hazardous Waste Code: F038
Waste Code Description: PETROLEUM REFINERY SECONDARY (EMULSIFIED) OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE AND/OR FLOAT GENERATED FROM THE PHYSICAL AND/OR CHEMICAL SEPARATION OF OIL/WATER/SOLIDS IN PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH WASTES INCLUDE, BUT ARE NOT LIMITED TO, ALL SLUDGES AND FLOATS GENERATED IN INDUCED AIR FLOTATION (IAF) UNITS, TANKS AND IMPOUNDMENTS, AND ALL SLUDGES GENERATED IN DAF UNITS. SLUDGES GENERATED IN STORMWATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND F037, K048, AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Hazardous Waste Code: D031
Waste Code Description: HEPTACHLOR (AND ITS EPOXIDE)

Hazardous Waste Code: U203
Waste Code Description: 1,3-BENZODIOXOLE, 5-(2-PROPENYL)- (OR) SAFROLE

Hazardous Waste Code: U032
Waste Code Description: CALCIUM CHROMATE (OR) CHROMIC ACID H2CRO4, CALCIUM SALT

Hazardous Waste Code: U079
Waste Code Description: 1,2-DICHLOROETHYLENE (OR) ETHENE, 1,2-DICHLORO-,(E)-

Hazardous Waste Code: U117
Waste Code Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Hazardous Waste Code: U125
Waste Code Description: 2-FURANCARBOXALDEHYDE (I) (OR) FURFURAL (I)

Hazardous Waste Code: U068
Waste Code Description: METHANE, DIBROMO- (OR) METHYLENE BROMIDE

Hazardous Waste Code: P014
Waste Code Description: BENZENETHIOL (OR) THIOPHENOL

Hazardous Waste Code: U207
Waste Code Description: 1,2,4,5-TETRACHLOROBENZENE (OR) BENZENE, 1,2,4,5-TETRACHLORO-

Hazardous Waste Code: P017
Waste Code Description: 2-PROPANONE, 1-BROMO- (OR) BROMOACETONE

Hazardous Waste Code: P194
Waste Code Description: ETHANIMIDOTHIOC ACID, 2-(DIMETHYLAMINO)-N-[[(METHYLAMINO) CARBONYL]OXY]-2-OXO-, METHYL ESTER (OR) OXAMYL

Hazardous Waste Code: P022
Waste Code Description: CARBON DISULFIDE

Hazardous Waste Code: P122
Waste Code Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 10% (R,T)

Hazardous Waste Code: U244
Waste Code Description: THIOPEROXYDICARBONIC DIAMIDE [(H2N)C(S)]2S2, TETRAMETHYL- (OR) THIRAM

Hazardous Waste Code: U328
Waste Code Description: BENZENAMINE, 2-METHYL- (OR) O-TOLUIDINE

Hazardous Waste Code: U409
Waste Code Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Hazardous Waste Code: U359
Waste Code Description: ETHANOL, 2-ETHOXY- (OR) ETHYLENE GLYCOL MONOETHYL ETHER

Hazardous Waste Code: U197
Waste Code Description: 2,5-CYCLOHEXADIENE-1,4-DIONE (OR) P-BENZOQUINONE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D037
Waste Code Description: PENTACHLOROPHENOL

Hazardous Waste Code: K084
Waste Code Description: WASTEWATER TREATMENT SLUDGES GENERATED DURING THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Hazardous Waste Code: P007
Waste Code Description: 3(2H)-ISOXAZOLONE, 5-(AMINOMETHYL)- (OR) 5-(AMINOMETHYL)-3-ISOXAZOLOL

Hazardous Waste Code: U031
Waste Code Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Hazardous Waste Code: U094
Waste Code Description: 7,12-DIMETHYLBENZ[A]ANTHRACENE (OR) BENZ[A]ANTHRACENE, 7,12-DIMETHYL-

Hazardous Waste Code: U118
Waste Code Description: 2-PROPENOIC ACID, 2-METHYL-, ETHYL ESTER (OR) ETHYL METHACRYLATE

Hazardous Waste Code: U152
Waste Code Description: 2-PROPENENITRILE, 2-METHYL- (I,T) (OR) METHACRYLONITRILE (I,T)

Hazardous Waste Code: U225
Waste Code Description: BROMOFORM (OR) METHANE, TRIBROMO-

Hazardous Waste Code: U216
Waste Code Description: THALLIUM CHLORIDE TLCL (OR) THALLIUM(I) CHLORIDE

Hazardous Waste Code: U209
Waste Code Description: 1,1,2,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,2,2-TETRACHLORO-

Hazardous Waste Code: P005
Waste Code Description: 2-PROPEN-1-OL (OR) ALLYL ALCOHOL

Hazardous Waste Code: U023
Waste Code Description: BENZENE, (TRICHLOROMETHYL)- (OR) BENZOTRICHLORIDE (C,R,T)

Hazardous Waste Code: U043
Waste Code Description: ETHENE, CHLORO- (OR) VINYL CHLORIDE

Hazardous Waste Code: U116
Waste Code Description: 2-IMIDAZOLIDINETHIONE (OR) ETHYLENETHIOUREA

Hazardous Waste Code: K024
Waste Code Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.

Hazardous Waste Code: K106
Waste Code Description: WASTEWATER TREATMENT SLUDGE FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION.

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: D014
Waste Code Description: METHOXYCHLOR (1,1,1-TRICHLORO-2,2-BIS [P-METHOXYPHENYL] ETHANE)

Hazardous Waste Code: K018
Waste Code Description: HEAVY ENDS FROM THE FRACTIONATION COLUMN IN ETHYL CHLORIDE PRODUCTION.

Hazardous Waste Code: K088
Waste Code Description: SPENT POTLINERS FROM PRIMARY ALUMINUM REDUCTION.

Hazardous Waste Code: P089
Waste Code Description: PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL-O-(4-NITROPHENYL) ESTER

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Hazardous Waste Code: U047
Waste Code Description: BETA-CHLORONAPHTHALENE (OR) NAPHTHALENE, 2-CHLORO-

Hazardous Waste Code: U075
Waste Code Description: DICHLORODIFLUOROMETHANE (OR) METHANE, DICHLORODIFLUORO-

Hazardous Waste Code: K145
Waste Code Description: RESIDUES FROM NAPHTHALENE COLLECTION AND RECOVERY OPERATIONS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Hazardous Waste Code: P093
Waste Code Description: PHENYLTHIOUREA (OR) THIOUREA, PHENYL-

Hazardous Waste Code: P121
Waste Code Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Hazardous Waste Code: K103
Waste Code Description: PROCESS RESIDUES FROM ANILINE EXTRACTION FROM THE PRODUCTION OF ANILINE.

Hazardous Waste Code: K104
Waste Code Description: COMBINED WASTEWATERS GENERATED FROM NITROBENZENE/ANILINE PRODUCTION.

Hazardous Waste Code: F037

Waste Code Description:	PETROLEUM REFINERY PRIMARY OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE GENERATED FROM THE GRAVITATIONAL SEPARATION OF OIL/WATER/SOLIDS DURING THE STORAGE OR TREATMENT OF PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH SLUDGES INCLUDE, BUT ARE NOT LIMITED TO, THOSE GENERATED IN OIL/WATER/SOLIDS SEPARATORS; TANKS AND IMPOUNDMENTS; DITCHES AND OTHER CONVEYANCES; SUMPS; AND STORM WATER UNITS RECEIVING DRY WEATHER FLOW. SLUDGES GENERATED IN STORM WATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.
Hazardous Waste Code:	U110
Waste Code Description:	1-PROPANIMINE, N-PROPYL-(I) (OR) DIPROPYLAMINE (I)
Hazardous Waste Code:	U115
Waste Code Description:	ETHYLENE OXIDE (I,T) (OR) OXIRANE (I,T)
Hazardous Waste Code:	U051
Waste Code Description:	CREOSOTE
Hazardous Waste Code:	K144
Waste Code Description:	WASTEWATER SUMP RESIDUES FROM LIGHT OIL REFINING, INCLUDING, BUT NOT LIMITED TO, INTERCEPTING OR CONTAMINATION SUMP SLUDGES FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.
Hazardous Waste Code:	P066
Waste Code Description:	ETHANIMIDOTHIOIC ACID, N-[[(METHYLAMINO)CARBONYL]OXY]-, METHYL ESTER (OR) METHOMYL
Hazardous Waste Code:	P196
Waste Code Description:	MANGANESE DIMETHYLDITHIOCARBAMATE (OR) MANGANESE, BIS(DIMETHYLCARBAMODITHIOATO-S,S') -,
Hazardous Waste Code:	P013
Waste Code Description:	BARIUM CYANIDE
Hazardous Waste Code:	K014
Waste Code Description:	BOTTOMS FROM THE ACETONITRILE PURIFICATION COLUMN IN THE PRODUCTION OF ACRYLONITRILE.
Hazardous Waste Code:	P021
Waste Code Description:	CALCIUM CYANIDE (OR) CALCIUM CYANIDE CA(CN)2
Hazardous Waste Code:	P045
Waste Code Description:	2-BUTANONE, 3,3-DIMETHYL-1-(METHYLTHIO)-, O-[METHYLAMINO)CARBONYL] OXIME (OR) THIOFANOX
Hazardous Waste Code:	P047
Waste Code Description:	4,6-DINITRO-O-CRESOL, & SALTS (OR) PHENOL, 2-METHYL-4,6-DINITRO-, & SALTS
Hazardous Waste Code:	P098
Waste Code Description:	POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)
Hazardous Waste Code:	P118
Waste Code Description:	METHANETHIOL, TRICHLORO- (OR) TRICHLOROMETHANETHIOL
Hazardous Waste Code:	P119
Waste Code Description:	AMMONIUM VANADATE (OR) VANADIC ACID, AMMONIUM SALT
Hazardous Waste Code:	U037
Waste Code Description:	BENZENE, CHLORO- (OR) CHLOROBENZENE
Hazardous Waste Code:	U146
Waste Code Description:	LEAD SUBACETATE (OR) LEAD, BIS(ACETATO-O)TETRAHYDROXYTRI-
Hazardous Waste Code:	U178
Waste Code Description:	CARBAMIC ACID, METHYLNITROSO-, ETHYL ESTER (OR) N-NITROSO-N-METHYLURETHANE
Hazardous Waste Code:	U240
Waste Code Description:	2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: F019
Waste Code Description: WASTEWATER TREATMENT SLUDGES FROM THE CHEMICAL CONVERSION COATING OF ALUMINUM, EXCEPT FROM ZIRCONIUM PHOSPHATING IN ALUMINUM CAN WASHING WHEN SUCH PHOSPHATING IS AN EXCLUSIVE CONVERSION COATING PROCESS.

Hazardous Waste Code: K035
Waste Code Description: WASTEWATER TREATMENT SLUDGES GENERATED IN THE PRODUCTION OF CREOSOTE.

Hazardous Waste Code: K043
Waste Code Description: 2,6-DICHLOROPHENOL WASTE FROM THE PRODUCTION OF 2,4-D.

Hazardous Waste Code: K052
Waste Code Description: TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY.

Hazardous Waste Code: K115
Waste Code Description: HEAVY ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: U015
Waste Code Description: AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)

Hazardous Waste Code: U041
Waste Code Description: EPICHLOROHYDRIN (OR) OXIRANE, (CHLOROMETHYL)-

Hazardous Waste Code: U101
Waste Code Description: 2,4-DIMETHYLPHENOL (OR) PHENOL, 2,4-DIMETHYL-

Hazardous Waste Code: K033
Waste Code Description: WASTEWATER AND SCRUB WATER FROM THE CHLORINATION OF CYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Hazardous Waste Code: D030
Waste Code Description: 2,4-DINITROTOLUENE

Hazardous Waste Code: K021
Waste Code Description: AQUEOUS SPENT ANTIMONY CATALYST WASTE FROM FLUOROMETHANE PRODUCTION.

Hazardous Waste Code: K105
Waste Code Description: SEPARATED AQUEOUS STREAM FROM THE REACTOR PRODUCT WASHING STEP IN THE PRODUCTION OF CHLOROBENZENES.

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code: K037
Waste Code Description: WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF DISULFOTON.

Hazardous Waste Code: U058
Waste Code Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Hazardous Waste Code: U164
Waste Code Description: 4(1H)-PYRIMIDINONE, 2,3-DIHYDRO-6-METHYL-2-THIOXO- (OR) METHYLTHIOURACIL

Hazardous Waste Code: U048
Waste Code Description: O-CHLOROPHENOL (OR) PHENOL, 2-CHLORO-

Hazardous Waste Code: U019
Waste Code Description: BENZENE (I,T)

Hazardous Waste Code: U098
Waste Code Description: 1,1-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,1-DIMETHYL-

Hazardous Waste Code: U001
Waste Code Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Hazardous Waste Code: P127
Waste Code Description: 7-BENZOFURANOL, 2,3-DIHYDRO-2,2-DIMETHYL-, METHYLCARBAMATE (OR) CARBOFURAN

Hazardous Waste Code: U034
Waste Code Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Hazardous Waste Code: U029
Waste Code Description: METHANE, BROMO- (OR) METHYL BROMIDE

Hazardous Waste Code: U131
Waste Code Description: ETHANE, HEXACHLORO- (OR) HEXACHLOROETHANE

Hazardous Waste Code: P059
Waste Code Description: 4,7-METHANO-1H-INDENE, 1,4,5,6,7,8,8-HEPTACHLORO-3A,4,7,7A-TETRAHYDRO- (OR) HEPTACHLOR

Hazardous Waste Code: U006
Waste Code Description: ACETYL CHLORIDE (C,R,T)

Hazardous Waste Code: U246
Waste Code Description: CYANOGEN BROMIDE (CN)BR

Hazardous Waste Code: D032
Waste Code Description: HEXACHLOROBENZENE

Hazardous Waste Code: D043
Waste Code Description: VINYL CHLORIDE

Hazardous Waste Code: F009
Waste Code Description: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Hazardous Waste Code: K003
Waste Code Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF MOLYBDATE ORANGE PIGMENTS.

Hazardous Waste Code: K042
Waste Code Description: HEAVY ENDS OR DISTILLATION RESIDUES FROM THE DISTILLATION OF TETRACHLOROBENZENE IN THE PRODUCTION OF 2,4,5-T.

Hazardous Waste Code: K062
Waste Code Description: SPENT PICKLE LIQUOR FROM STEEL FINISHING OPERATIONS OF PLANTS THAT PRODUCE IRON OR STEEL.

Hazardous Waste Code: K114
Waste Code Description: VICINALS FROM THE PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Hazardous Waste Code: P002
Waste Code Description: 1-ACETYL-2-THIOUREA (OR) ACETAMIDE, N-(AMINOTHIOXOMETHYL)-

Hazardous Waste Code: P188
Waste Code Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Hazardous Waste Code: U059
Waste Code Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL) OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Hazardous Waste Code: U109
Waste Code Description: 1,2-DIPHENYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Hazardous Waste Code: U129
Waste Code Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Hazardous Waste Code:	U184
Waste Code Description:	ETHANE, PENTACHLORO- (OR) PENTACHLOROETHANE
Hazardous Waste Code:	U279
Waste Code Description:	CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	F010
Waste Code Description:	QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.
Hazardous Waste Code:	K039
Waste Code Description:	FILTER CAKE FROM THE FILTRATION OF DIETHYLPHOSPHORODITHIOIC ACID IN THE PRODUCTION OF PHORATE.
Hazardous Waste Code:	K143
Waste Code Description:	PROCESS RESIDUES FROM THE RECOVERY OF LIGHT OIL, INCLUDING, BUT NOT LIMITED TO, THOSE GENERATED IN STILLS, DECANTERS, AND WASH OIL RECOVERY UNITS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.
Hazardous Waste Code:	K148
Waste Code Description:	RESIDUES FROM COAL TAR DISTILLATION, INCLUDING, BUT NOT LIMITED TO, STILL BOTTOMS.
Hazardous Waste Code:	P087
Waste Code Description:	OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE
Hazardous Waste Code:	P099
Waste Code Description:	ARGENTATE (1-), BIS(CYANO-C)-, POTASSIUM (OR) POTASSIUM SILVER CYANIDE
Hazardous Waste Code:	P120
Waste Code Description:	VANADIUM OXIDE V2O5 (OR) VANADIUM PENTOXIDE
Hazardous Waste Code:	U007
Waste Code Description:	2-PROPENAMIDE (OR) ACRYLAMIDE
Hazardous Waste Code:	U010
Waste Code Description:	AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C
Hazardous Waste Code:	U090
Waste Code Description:	1,3-BENZODIOXOLE, 5-PROPYL- (OR) DIHYDROSAFROLE
Hazardous Waste Code:	U092
Waste Code Description:	DIMETHYLAMINE (I) (OR) METHANAMINE, N-METHYL- (I)
Hazardous Waste Code:	U173
Waste Code Description:	ETHANOL, 2,2'-(NITROSOIMINO)BIS- (OR) N-NITROSODIETHANOLAMINE
Hazardous Waste Code:	U180
Waste Code Description:	N-NITROSOPYRROLIDINE (OR) PYRROLIDINE, 1-NITROSO-
Hazardous Waste Code:	U234
Waste Code Description:	1,3,5-TRINITROBENZENE (R,T) (OR) BENZENE, 1,3,5-TRINITRO-
Hazardous Waste Code:	U228
Waste Code Description:	ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE
Hazardous Waste Code:	U214
Waste Code Description:	ACETIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) ACETATE
Hazardous Waste Code:	D017
Waste Code Description:	2,4,5-TP SILVEX (2,4,5-TRICHLOROPHENOXYPROPIONIC ACID)
Hazardous Waste Code:	D021
Waste Code Description:	CHLOROBENZENE

Hazardous Waste Code:	K178
Waste Code Description:	RESIDUES FROM MANUFACTURING AND MANUFACTURING-SITE STORAGE OF FERRIC CHLORIDE FROM ACIDS FORMED DURING THE PRODUCTION OF TITANIUM DIOXIDE USING THE CHLORIDE-ILMENITE PROCESS.
Hazardous Waste Code:	P010
Waste Code Description:	ARSENIC ACID H3ASO4
Hazardous Waste Code:	P016
Waste Code Description:	DICHLOROMETHYL ETHER (OR) METHANE, OXYBIS[CHLORO-
Hazardous Waste Code:	P044
Waste Code Description:	DIMETHOATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIMETHYL S-[2-(METHYLAMINO)-2-OXOETHYL] ESTER
Hazardous Waste Code:	P049
Waste Code Description:	DITHIOBIURET (OR) THIOIMIDODICARBONIC DIAMIDE [(H2N)C(S)]2NH
Hazardous Waste Code:	P063
Waste Code Description:	HYDROCYANIC ACID (OR) HYDROGEN CYANIDE
Hazardous Waste Code:	P072
Waste Code Description:	ALPHA-NAPHTHYLTHIOUREA (OR) THIOUREA, 1-NAPHTHALENYL-
Hazardous Waste Code:	U070
Waste Code Description:	BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE
Hazardous Waste Code:	U114
Waste Code Description:	CARBAMODITHIOIC ACID, 1,2-ETHANEDIYLBIS-, SALTS & ESTERS (OR) ETHYLENEBISDITHIOCARBAMIC ACID, SALTS & ESTERS
Hazardous Waste Code:	U200
Waste Code Description:	RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL) OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-
Hazardous Waste Code:	D019
Waste Code Description:	CARBON TETRACHLORIDE
Hazardous Waste Code:	P075
Waste Code Description:	NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS
Hazardous Waste Code:	P077
Waste Code Description:	BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE
Hazardous Waste Code:	U061
Waste Code Description:	BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDT
Hazardous Waste Code:	U140
Waste Code Description:	1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)
Hazardous Waste Code:	P105
Waste Code Description:	SODIUM AZIDE
Hazardous Waste Code:	P109
Waste Code Description:	TETRAETHYLDITHIOPYROPHOSPHATE (OR) THIODIPHOSPHORIC ACID, TETRAETHYL ESTER
Hazardous Waste Code:	U387
Waste Code Description:	CARBAMOTHIOIC ACID, DIPROPYL-, S-(PHENYLMETHYL) ESTER (OR) PROSULFOCARB
Hazardous Waste Code:	P015
Waste Code Description:	BERYLLIUM
Hazardous Waste Code:	U003
Waste Code Description:	ACETONITRILE (I,T)
Hazardous Waste Code:	U411
Waste Code Description:	PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR
Hazardous Waste Code:	P082

Waste Code Description:	METHANIMINE, N-METHYL-N-NITROSO- (OR) N-NITROSODIMETHYLAMINE
Hazardous Waste Code:	U213
Waste Code Description:	FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)
Hazardous Waste Code:	U021
Waste Code Description:	[1,1'-BIPHENYL]-4,4'-DIAMINE (OR) BENZIDINE
Hazardous Waste Code:	U033
Waste Code Description:	CARBON OXYFLUORIDE (R,T) (OR) CARBONIC DIFLUORIDE
Hazardous Waste Code:	U064
Waste Code Description:	BENZO[RST]PENTAPHENE (OR) DIBENZO[A,I]PYRENE
Hazardous Waste Code:	U086
Waste Code Description:	HYDRAZINE, 1,2-DIETHYL- (OR) N,N'-DIETHYLHYDRAZINE
Hazardous Waste Code:	U126
Waste Code Description:	GLYCIDYLALDEHYDE (OR) OXIRANECARBOXYALDEHYDE
Hazardous Waste Code:	K009
Waste Code Description:	DISTILLATION BOTTOMS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.
Hazardous Waste Code:	U226
Waste Code Description:	ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM
Hazardous Waste Code:	D024
Waste Code Description:	M-CRESOL
Hazardous Waste Code:	F027
Waste Code Description:	DISCARDED UNUSED FORMULATIONS CONTAINING TRI-, TETRA-, OR PENTACHLOROPHENOL OR DISCARDED UNUSED FORMULATIONS CONTAINING COMPOUNDS DERIVED FROM THESE CHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE FORMULATIONS CONTAINING HEXACHLOROPHENE SYNTHESIZED FROM PREPURIFIED 2,4,5-TRICHLOROPHENOL AS THE SOLE COMPONENT.)
Hazardous Waste Code:	K011
Waste Code Description:	BOTTOM STREAM FROM THE WASTEWATER STRIPPER IN THE PRODUCTION OF ACRYLONITRILE.
Hazardous Waste Code:	K022
Waste Code Description:	DISTILLATION BOTTOM TARS FROM THE PRODUCTION OF PHENOL/ACETONE FROM CUMENE.
Hazardous Waste Code:	K071
Waste Code Description:	BRINE PURIFICATION MUDS FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION, IN WHICH SEPARATELY PREPURIFIED BRINE IS NOT USED.
Hazardous Waste Code:	K169
Waste Code Description:	CRUDE OIL STORAGE TANK SEDIMENT FROM PETROLEUM REFINING OPERATIONS
Hazardous Waste Code:	U223
Waste Code Description:	BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T) (OR) TOLUENE DIISOCYANATE (R,T)
Hazardous Waste Code:	D009
Waste Code Description:	MERCURY
Hazardous Waste Code:	F020
Waste Code Description:	WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- OR TETRACHLOROPHENOL OR OF INTERMEDIATES USED TO PRODUCE THEIR PESTICIDE DERIVATIVES. (THIS LISTING DOES NOT INCLUDE WASTES FROM THE PRODUCTION OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)
Hazardous Waste Code:	K028
Waste Code Description:	SPENT CATALYST FROM THE HYDROCHLORINATOR REACTOR IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.
Hazardous Waste Code:	K149
Waste Code Description:	DISTILLATION BOTTOMS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES,

RING-CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS. [THIS WASTE DOES NOT INCLUDE STILL BOTTOMS FROM THE DISTILLATION OF BENZOYL CHLORIDE]

Hazardous Waste Code: P040
Waste Code Description: O,O-DIETHYL O-PYRAZINYL PHOSPHOROTHIOATE (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL O-PYRAZINYL ESTER

Hazardous Waste Code: U025
Waste Code Description: DICHLOROETHYL ETHER (OR) ETHANE, 1,1'-OXYBIS[2-CHLORO-

Hazardous Waste Code: U091
Waste Code Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHOXY- (OR) 3,3'-DIMETHOXYBENZIDINE

Hazardous Waste Code: U174
Waste Code Description: ETHANAMINE, N-ETHYL-N-NITROSO- (OR) N-NITROSODIETHYLAMINE

Hazardous Waste Code: U389
Waste Code Description: CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3,3-TRICHLORO-2-PROPENYL) ESTER (OR) TRIALLATE

Hazardous Waste Code: D028
Waste Code Description: 1,2-DICHLOROETHANE

Hazardous Waste Code: K124
Waste Code Description: REACTOR VENT SCRUBBER WATER FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Hazardous Waste Code: K151
Waste Code Description: WASTEWATER TREATMENT SLUDGES, EXCLUDING NEUTRALIZATION AND BIOLOGICAL SLUDGES, GENERATED DURING THE TREATMENT OF WASTEWATERS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.

Hazardous Waste Code: K172
Waste Code Description: SPENT HYDROREFINING CATALYST FROM PETROLEUM REFINING OPERATIONS, INCLUDING GUARD BEDS USED TO DESULFURIZE FEEDS TO OTHER CATALYTIC REACTORS (THIS LISTING DOES NOT INCLUDE INERT SUPPORT MEDIA)

Hazardous Waste Code: P018
Waste Code Description: BRUCINE (OR) STRYCHNIDIN-10-ONE, 2,3-DIMETHOXY-

Hazardous Waste Code: P034
Waste Code Description: 2-CYCLOHEXYL-4,6-DINITROPHENOL (OR) PHENOL, 2-CYCLOHEXYL-4,6-DINITRO-

Hazardous Waste Code: U011
Waste Code Description: 1H-1,2,4-TRIAZOL-3-AMINE (OR) AMITROLE

Hazardous Waste Code: U111
Waste Code Description: 1-PROPANAMINE, N-NITROSO-N-PROPYL- (OR) DI-N-PROPYLNITROSAMINE

Hazardous Waste Code: P073
Waste Code Description: NICKEL CARBONYL (OR) NICKEL CARBONYL NI(CO)4, (T-4)-

Hazardous Waste Code: U181
Waste Code Description: 5-NITRO-O-TOLUIDINE (OR) BENZENAMINE, 2-METHYL-5-NITRO

Hazardous Waste Code: P051
Waste Code Description: 2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2ABETA, 3ALPHA, 6ALPHA, 6ABETA, 7BETA, 7AALPHA)- & METABOLITES (OR) ENDRIN (OR) ENDRIN, & METABOLITES

Hazardous Waste Code: P185
Waste Code Description: 1,3-DITHIOLANE-2-CARBOXALDEHYDE, 2,4-DIMETHYL-, O- [(METHYLAMINO)-CARBONYL]OXIME (OR) TIRPATE

Hazardous Waste Code: K177
Waste Code Description: SLAG FROM THE PRODUCTION OF ANTIMONY OXIDE THAT IS SPECULATIVELY ACCUMULATED OR DISPOSED,INCLUDING SLAG FROM THE PRODUCTION OF INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Hazardous Waste Code:	U394
Waste Code Description:	A2213 (OR) ETHANIMIDOTHIOIC ACID, 2-(DIMETHYLAMINO)-N-HYDROXY-2-OXO-, METHYL ESTER
Hazardous Waste Code:	U247
Waste Code Description:	BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-METHOXY- (OR) METHOXYCHLOR
Hazardous Waste Code:	K174
Waste Code Description:	WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF ETHLYENE DICHLORIDE OR VINYL CHLORIDE
Hazardous Waste Code:	P078
Waste Code Description:	NITROGEN DIOXIDE (OR) NITROGEN OXIDE NO2
Hazardous Waste Code:	P092
Waste Code Description:	MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE
Hazardous Waste Code:	K013
Waste Code Description:	BOTTOM STREAM FROM THE ACETONITRILE COLUMN IN THE PRODUCTION OF ACRYLONITRILE.
Hazardous Waste Code:	K085
Waste Code Description:	DISTILLATION OR FRACTIONATION COLUMN BOTTOMS FROM THE PRODUCTION OF CHLOROBENZENES.
Hazardous Waste Code:	K016
Waste Code Description:	HEAVY ENDS OR DISTILLATION RESIDUES FROM THE PRODUCTION OF CARBON TETRACHLORIDE.
Hazardous Waste Code:	K040
Waste Code Description:	WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF PHORATE.
Hazardous Waste Code:	K049
Waste Code Description:	SLOP OIL EMULSION SOLIDS FROM THE PETROLEUM REFINING INDUSTRY.
Hazardous Waste Code:	D034
Waste Code Description:	HEXACHLOROETHANE
Hazardous Waste Code:	K097
Waste Code Description:	VACUUM STRIPPER DISCHARGE FROM THE CHLORDANE CHLORINATOR IN THE PRODUCTION OF CHLORDANE.
Hazardous Waste Code:	U148
Waste Code Description:	3,6-PYRIDAZINEDIONE, 1,2-DIHYDRO- (OR) MALEIC HYDRAZIDE
Hazardous Waste Code:	U107
Waste Code Description:	1,2-BENZENEDICARBOXYLIC ACID, DIOCTYL ESTER (OR) DI-N-OCTYL PHTHALATE
Hazardous Waste Code:	U044
Waste Code Description:	CHLOROFORM (OR) METHANE, TRICHLORO-
Hazardous Waste Code:	U063
Waste Code Description:	DIBENZ[A,H]ANTHRACENE
Hazardous Waste Code:	U087
Waste Code Description:	O,O-DIETHYL S-METHYL DITHIOPHOSPHATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-METHYL ESTER
Hazardous Waste Code:	U046
Waste Code Description:	CHLOROMETHYL METHYL ETHER (OR) METHANE, CHLOROMETHOXY-
Hazardous Waste Code:	D039
Waste Code Description:	TETRACHLOROETHYLENE
Hazardous Waste Code:	K031
Waste Code Description:	BY-PRODUCT SALTS GENERATED IN THE PRODUCTION OF MSMA AND CACODYLIC ACID.
Hazardous Waste Code:	K102
Waste Code Description:	RESIDUE FROM THE USE OF ACTIVATED CARBON FOR DECOLORIZATION IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Hazardous Waste Code:	K136
Waste Code Description:	STILL BOTTOMS FROM THE PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.
Hazardous Waste Code:	U123
Waste Code Description:	FORMIC ACID (C,T)
Hazardous Waste Code:	U124
Waste Code Description:	FURAN (I) (OR) FURFURAN (I)
Hazardous Waste Code:	U159
Waste Code Description:	2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)
Hazardous Waste Code:	U162
Waste Code Description:	2-PROPENOIC ACID, 2-METHYL-, METHYL ESTER (I,T) (OR) METHYL METHACRYLATE (I,T)
Hazardous Waste Code:	U166
Waste Code Description:	1,4-NAPHTHALENEDIONE (OR) 1,4-NAPHTHOQUINONE
Hazardous Waste Code:	U182
Waste Code Description:	1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE
Hazardous Waste Code:	F007
Waste Code Description:	SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.
Hazardous Waste Code:	P071
Waste Code Description:	METHYL PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O,-DIMETHYL O-(4-NITROPHENYL) ESTER
Hazardous Waste Code:	P197
Waste Code Description:	FORMPARANATE (OR) METHANIMIDAMIDE, N,N-DIMETHYL-N'-[2-METHYL-4-[[(METHYLAMINO)CARBONYL] OXY]PHENYL]
Hazardous Waste Code:	U045
Waste Code Description:	METHANE, CHLORO- (I,T) (OR) METHYL CHLORIDE (I,T)
Hazardous Waste Code:	U060
Waste Code Description:	BENZENE, 1,1'-(2,2-DICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDD
Hazardous Waste Code:	U072
Waste Code Description:	BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE
Hazardous Waste Code:	U145
Waste Code Description:	LEAD PHOSPHATE (OR) PHOSPHORIC ACID, LEAD(2+) SALT (2:3)
Hazardous Waste Code:	U271
Waste Code Description:	BENOMYL (OR) CARBAMIC ACID, [1-[(BUTYLAMINO)CARBONYL]-1H-BENZIMIDAZOL-2-YL]-, METHYL ESTER
Hazardous Waste Code:	F034
Waste Code Description:	WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE CREOSOTE FORMULATIONS. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.
Hazardous Waste Code:	K005
Waste Code Description:	WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME GREEN PIGMENTS.
Hazardous Waste Code:	P201
Waste Code Description:	PHENOL, 3-METHYL-5-(1-METHYLETHYL)-, METHYL CARBAMATE (OR) PROMECARB
Hazardous Waste Code:	U026
Waste Code Description:	CHLORNAPHAZIN (OR) NAPHTHALENAMINE, N,N'-BIS(2-CHLOROETHYL)-
Hazardous Waste Code:	U113
Waste Code Description:	2-PROPENOIC ACID, ETHYL ESTER (I) (OR) ETHYL ACRYLATE (I)
Hazardous Waste Code:	U137
Waste Code Description:	INDENO[1,2,3-CD]PYRENE

Hazardous Waste Code:	U153
Waste Code Description:	METHANETHIOL (I,T) (OR) THIOMETHANOL (I,T)
Hazardous Waste Code:	121
Waste Code Description:	Alkaline solution (pH >12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)
Hazardous Waste Code:	F011
Waste Code Description:	SPENT CYANIDE SOLUTIONS FROM SLAT BATH POT CLEANING FROM METAL HEAT TREATING OPERATIONS.
Hazardous Waste Code:	K026
Waste Code Description:	STRIPPING STILL TAILS FROM THE PRODUCTION OF METHYL ETHYL PYRIDINES.
Hazardous Waste Code:	K045
Waste Code Description:	SPENT CARBON FROM THE TREATMENT OF WASTEWATER CONTAINING EXPLOSIVES.
Hazardous Waste Code:	P056
Waste Code Description:	FLUORINE
Hazardous Waste Code:	P069
Waste Code Description:	2-METHYLLACTONITRILE (OR) PROPANENITRILE, 2-HYDROXY-2-METHYL-
Hazardous Waste Code:	P202
Waste Code Description:	M-CUMENYL METHYLCARBAMATE (OR) 3-ISOPROPYLPHENYL N-METHYLCARBAMATE (OR) PHENOL, 3-(1-METHYLETHYL)-, METHYL CARBAMATE
Hazardous Waste Code:	P204
Waste Code Description:	PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-
Hazardous Waste Code:	U095
Waste Code Description:	[1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHYL- (OR) 3,3'-DIMETHYLBENZIDINE
Hazardous Waste Code:	U188
Waste Code Description:	PHENOL
Hazardous Waste Code:	U204
Waste Code Description:	SELENIOUS ACID (OR) SELENIUM DIOXIDE
Hazardous Waste Code:	F005
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	K027
Waste Code Description:	CENTRIFUGE AND DISTILLATION RESIDUES FROM TOLUENE DIISOCYANATE PRODUCTION.
Hazardous Waste Code:	K161
Waste Code Description:	PURIFICATION SOLIDS (INCLUDING FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS), BAG HOUSE DUST AND FLOOR SWEEPINGS FROM THE PRODUCTION OF DITHIOCARBAMATE ACIDS AND THEIR SALTS. (THIS LISTING DOES NOT INCLUDE K125 OR K126).
Hazardous Waste Code:	P029
Waste Code Description:	COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)
Hazardous Waste Code:	P124
Waste Code Description:	ACTINOMYCIN D
Hazardous Waste Code:	U127
Waste Code Description:	BENZENE, HEXACHLORO- (OR) HEXACHLOROBENZENE
Hazardous Waste Code:	U133
Waste Code Description:	HYDRAZINE (R,T)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: K118
Waste Code Description: SPENT ADSORBENT SOLIDS FROM PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: U056
Waste Code Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Hazardous Waste Code: U096
Waste Code Description: ALPHA,ALPHA-DIMETHYLBENZYLHYDROPEROXIDE (R) (OR) HYDROPEROXIDE, 1-METHYL-1-PHENYLETHYL- (R)

Hazardous Waste Code: U179
Waste Code Description: N-NITROSOPIPERIDINE (OR) PIPERIDINE, 1-NITROSO-

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	1670
Type:	Private	**Street 1:**	CACTUS ROAD
Name:	PACIFIC BELL AT&T OF CA	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	92154
Owner/Operator Ind:	Current Operator	**Street No:**	1670
Type:	Private	**Street 1:**	CACTUS ROAD
Name:	PACIFIC BELL AT&T OF CA	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	92154

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	5 of 7	NNW	0.16 / 821.59	509.79 / 1	AT&T California - D3179 1670 CACTUS RD SAN DIEGO CA 92154	CERS TANK

Site ID: 433548
Latitude: 32.566996
Longitude: -116.988364

Regulated Programs

EI ID: 10394128
EI Description: Underground Storage Tank

EI ID: 10394128
EI Description: Chemical Storage Facilities

EI ID: 10394128
EI Description: Hazardous Waste Generator

Violations

Violation Date: 12/06/2018
Violation Source: CERS
Violation Program: UST
Violation Division: San Diego County Department of Env Health
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Notes:

Returned to compliance on 12/06/2018. Inspection Sequence ID:6057811;Tank ID:28476;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equip

Violation Description:

Failure to comply with one or more of the following overfill prevention equipment requirements:
Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or
Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or
Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or
Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.

Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018.

For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter.

For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter.

Inspected within 30 days after a repair to the overfill prevention equipment.

Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Inspected by a certified UST service technician.

Maintain records of overfill prevention equipment inspection for 36 months.

Evaluations

Eval Date: 01/28/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:4088730; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/08/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Chavarin Yvonne Inspection ID:6828190; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/05/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Campanella Luke Inspection ID:5799648; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/06/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Chavarin Yvonne Inspection ID:6057811; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/08/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Chavarin Yvonne Inspection ID:6828190; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/21/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:5221674; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/13/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Zmily Zanalee Inspection ID:6388957; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/06/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Chavarin Yvonne Inspection ID:6057811; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/09/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Ayala Anthony Inspection ID:6559133; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/21/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:5221674; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/21/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:5221674; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/28/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Drummond Rafaela Inspection ID:4088730; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/05/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Campanella Luke Inspection ID:5799648; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/05/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Campanella Luke Inspection ID:5799648; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/09/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval Notes:

Inspector: Drummond Rafaela Inspection ID:5571682; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/09/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Ayala Anthony Inspection ID:6559133; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: UST Tank Owner
Entity Name: Pacific Bell Telephone Company dba AT&T California
Entity Title:
Address: 308 S. Akard St., 17th Floor
City: Dallas
State: TX
Country: United States
Zip Code: 75202
Phone: (800) 566-9347

Affil Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title:
Address: PO Box 129261
City: San Diego
State: CA
Country:
Zip Code: 92112-9261
Phone: (858) 505-6880

Affil Type Desc: Identification Signer
Entity Name: Jeremy McGrue
Entity Title: National EPCRA Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: UST Tank Operator
Entity Name: Pacific Bell Telephone Company dba AT&T California
Entity Title:
Address: 308 S. Akard St., 17th Floor
City: Dallas
State: TX
Country: United States
Zip Code: 75202
Phone: (800) 566-9347

Affil Type Desc: UST Permit Applicant
Entity Name: Sarah Bullock
Entity Title: Authorized Agent to AT&T
Address:
City:
State:
Country:
Zip Code:
Phone: (800) 566-9347

Affil Type Desc:	Legal Owner
Entity Name:	Pacific Bell Telephone Company dba AT&T California
Entity Title:	
Address:	308 S. Akard St., 17th Floor
City:	Dallas
State:	TX
Country:	United States
Zip Code:	75202
Phone:	(214) 464-1712

Affil Type Desc:	Environmental Contact
Entity Name:	AT&T EH&S Hotline - Option #1
Entity Title:	
Address:	308 S. Akard St., 17th Floor
City:	Dallas
State:	TX
Country:	
Zip Code:	75202
Phone:	

Affil Type Desc:	Operator
Entity Name:	AT&T California
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(800) 566-9347

Affil Type Desc:	Document Preparer
Entity Name:	Peter Burnell, Sigma Consultants, Inc.
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	UST Property Owner Name
Entity Name:	Pacific Bell Telephone Company dba AT&T California
Entity Title:	
Address:	308 S. Akard St., 17th Floor
City:	Dallas
State:	TX
Country:	United States
Zip Code:	75202
Phone:	(800) 566-9347

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	308 S. Akard St., 17th Floor
City:	Dallas
State:	TX
Country:	
Zip Code:	75202
Phone:	

Affil Type Desc:	Parent Corporation
Entity Name:	Pacific Bell Telephone Company dba AT&T California
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Phone:						
12	6 of 7	NNW	0.16 / 821.59	509.79 / 1	PACIFIC BELL TELEPHONE CO DBA AT&T CALIF 1670 CACTUS RD OTAY MESA CA 92173-2210	RCRA NON GEN

EPA Handler ID: CAL000116895
Gen Status Universe: No Report
Contact Name: DERONICA LAMB
Contact Address: 308 S. AKARD ST. , 17TH FLOOR , DALLAS , TX, 75202 ,
Contact Phone No and Ext: 214-741-0464
Contact Email: EHSRRC@LIST.ATT.COM
Contact Country:
County Name: SAN DIEGO
EPA Region: 09
Land Type:
Receive Date: 19940914
Location Latitude: 32.566995
Location Longitude: -116.988366

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940914
Handler Name: PACIFIC BELL TELEPHONE CO DBA AT&T CALIF
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: AT&T K SASAKI DDS
Date Became Current:
Date Ended Current:
Phone: 214-741-0464
Source Type: Implementer

Street No:
Street 1: 308 S. AKARD ST.
Street 2: 17TH FLOOR
City: DALLAS
State: TX
Country:
Zip Code: 75202-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	308 S. AKARD ST.
Name:	DERONICA LAMB	**Street 2:**	17TH FLOOR
Date Became Current:		**City:**	DALLAS
Date Ended Current:		**State:**	TX
Phone:	214-741-0464	**Country:**	
Source Type:	Implementer	**Zip Code:**	75202

12	7 of 7	NNW	0.16 / 821.59	509.79 / 1	**AT&T California - D3179** **1670 CACTUS RD** **SAN DIEGO CA 92154**	**UST** **SANDIEGO**

Facility ID:	37-000-129788	**RCRA Large Qty. Gen:**	false
Record ID:	DEH2002-HUPFP-129788	**HHW Collection:**	false
CERS ID:	10394128	**Recycle:**	false
EPA ID No:	CAL000116895	**Own or Operate UG:**	true
Permit Status:	Permit Renewed	**Own or Operate AG:**	false
Active Permit:	true	**Business Phone:**	(800) 566-9347
Haz. Mat. On-Site:	true	**Business Fax:**	0
Haz. Waste Gen:	true	**Last Updated:**	2022 Jan 26 02:32:41 AM
Onsite Haz Wt Trt:	false		
Mailing Address:	308 S. Akard St., 17th Floor, Dallas, TX 75202		

Tank Information

Tank ID:	D3179U001	**Tank Capacity in Gal:**	4000
Tank Status:	SEE FILE	**Tank Contents:**	Diesel
Permit Status:	Permit Renewed	**Tank Use:**	Emergency Generator Fuel
Active Permit:	true	**Piping Sys Type:**	Conventional Suction
Dt UST Perm Closed:	2018 Apr 27 12:00:00 AM	**Fac Type (UST Fac):**	Other
Type of Tank:	Double Wall	**Last Updated:**	2018 Apr 28 02:09:07 AM
Tank Owner Name:	AT&T California		

Tank ID:	28476	**Tank Capacity in Gal:**	4030
Tank Status:	Active	**Tank Contents:**	Diesel
Permit Status:	Permit Renewed	**Tank Use:**	05
Active Permit:	true	**Piping Sys Type:**	Conventional Suction
Dt UST Perm Closed:		**Fac Type (UST Fac):**	Other
Type of Tank:	Double Wall	**Last Updated:**	2022 Jan 26 02:32:41 AM
Tank Owner Name:	AT&T California		

13	1 of 3	NW	0.17 / 908.25	505.85 / -3	**HM INT'L COSMETICS, INC** **6965 CAMINO MAQUILADORA,** **SUITE# E, SAN DIEGO, CA 92154** **SAN DIEGO CA 92154**	**HAZ** **SANDIEGO**

Record ID:	DEH2010-HUPFP-213109	**GIS Record ID:**	DEH2010-HUPFP-213109
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5663929
Facility Latitude:		**GIS Fac Longitude:**	-116.9899909
Facility Longitude:			
Facility Address:			
GIS Facility Name:	HM INT'L COSMETICS, INC		
GIS Facility Address:	6965 CAMINO MAQUILADORA, SUITE# E, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902500
SIC Code:		**X Coord:**	6333671.621
NAICS Code:		**Y Coord:**	1786686.492
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 213109
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333671.62092
UST Facility:		**Point Y:**	1786686.4919
Total No USTs:		**Lat GS84:**	32.5663929
No of Tanks:		**Lon GS84:**	-116.9899909
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.98998920140822
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56644040694037
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-25-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6965 CAMINO MAQUILADORA, SUITE# E		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
13	2 of 3	NW	0.17 / 908.25	505.85 / -3	CAVAZOS TRANSPORTATION & REGISTRATION 6965 CAMINO MAQUILADORA CA 0	HAZ SANDIEGO

Record ID:	DEH2010-HUPFP-212543	**GIS Record ID:**	DEH2010-HUPFP-212543
Facility Name:		**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	32.5663929
Facility Latitude:		**GIS Fac Longitude:**	-116.9899909
Facility Longitude:			
Facility Address:			
GIS Facility Name:	CAVAZOS TRANSPORTATION & REGISTRATION		
GIS Facility Address:	6965 CAMINO MAQUILADORA		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

GIS CERS ID:		ER Contact:	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	ER Con Work Ph:	
Per Type:		Census Tract:	
Per Sub Type:		Parcel Zip:	
Per Cat:		Community:	
Record Status:	Completed	Jurisdiction:	
HW Tier:		Basin No:	
LRG QTY MW Gener:		BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	6461902500
SIC Code:		X Coord:	6333671.621
NAICS Code:		Y Coord:	1786686.492
Disclose Qty Haz Mat:		Kiva Per Typ:	HK07 212543
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6333671.62092
UST Facility:		Point Y:	1786686.4919
Total No USTs:		Lat GS84:	32.5663929
No of Tanks:		Lon GS84:	-116.9899909
Own Oper APS:		Loc Name:	
Tot APSA Cap:	0	Score:	
Capacity LR:		Match Type:	
Haz Waste G:		Side:	
Recycle100:		X Map Coord:	-116.98998920140822
Onsite Haz Waste Tre:		Y Map Coord:	32.56644040694037
RCRA LRG Qty:		User Fld:	
Haz Wst Coll Site:		Addr Type:	
Accept Offs:		ARC Address:	
Universal Waste Han:		ARC City:	
Toxic Gas:		ARC Zipcode:	
Hazmat EHS:		ARC State:	
Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:		Bill Code 3:	
Parcel No:	646-190-25-00	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	6965 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

13	3 of 3	NW	0.17 / 908.25	505.85 / -3	H & J PRECISION TOOLS, INC 6965 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	HAZ SANDIEGO

Record ID:	DEH2006-HUPFP-206249	GIS Record ID:	DEH2006-HUPFP-206249
Facility Name:		GIS Facility City:	SAN DIEGO
Facility City:		GIS Facility ZipCode:	0
Facility ZipCode:		GIS Fac Latitude:	0
Facility Latitude:		GIS Fac Longitude:	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	H & J PRECISION TOOLS, INC		
GIS Facility Address:	6965 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

Hazardous Materials Inspection Violations

Container Tank ID:		***Inspection No:***	4112317
Facility ID No:	37-000-206249	***Inspection Type:***	Routine
ID:	20987	***Inspection Date:***	10/01/2015 03:35:00 PM
UST ID:		***Compliance Date:***	10/07/2015 12:00:00 AM
Permit Status:	Permit Suspended	***Last Updated:***	06/06/2019 12:00:00 AM
Active Permit:	false	***NOV:***	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Minor		
Violation Code:	1020002 Initial and/or annual employee training not conducted for hazardous materials management and/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4)		

HMD Permits Map Data

GIS Facility ID:		***Status:***	
GIS CERS ID:	10394401	***ER Contact:***	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	***ER Con Work Ph:***	
Per Type:		***Census Tract:***	
Per Sub Type:		***Parcel Zip:***	
Per Cat:		***Community:***	
Record Status:	Permit Suspended	***Jurisdiction:***	
HW Tier:		***Basin No:***	
LRG QTY MW Gener:	No	***BOS Dist:***	
EPA ID No:		***Tbpg Grid:***	
RMP CAL ARP:		***Insp Dist:***	
Tank Owner:		***Feature ID:***	6461902500
SIC Code:		***X Coord:***	6333671.621
NAICS Code:		***Y Coord:***	1786686.492
Disclose Qty Haz Mat:		***Kiva Per Typ:***	HK18 206249
Exp Date:		***Agency Name:***	COSD
Own/Operate USTs :		***Point X:***	6333671.62092
UST Facility:		***Point Y:***	1786686.4919
Total No USTs:		***Lat GS84:***	0
No of Tanks:		***Lon GS84:***	0
Own Oper APS:		***Loc Name:***	
Tot APSA Cap:	0	***Score:***	
Capacity LR:		***Match Type:***	
Haz Waste G:	N	***Side:***	
Recycle100:		***X Map Coord:***	-116.98998920140822
Onsite Haz Waste Tre:	N	***Y Map Coord:***	32.56644040694037
RCRA LRG Qty:	N	***User Fld:***	
Haz Wst Coll Site:		***Addr Type:***	
Accept Offs:		***ARC Address:***	
Universal Waste Han:		***ARC City:***	
Toxic Gas:		***ARC Zipcode:***	
Hazmat EHS:		***ARC State:***	
Hazmat Rad:		***ARC APN:***	
Haz Waste Rad:		***Zip:***	
Haz Waste EHS:		***Farm Nursery:***	
Full Name:		***Indian or Territory:***	
Email Perm:		***County ID:***	
Phone Perm:		***Bill Code 2:***	
Site Address:	6965 Camino Maquiladora	***Bill Code 3:***	
Parcel No:	646-190-25-00	***Univ Waste Gen Type:***	
Record Ali:	Unified Program Facility Permit		
Address:	6965 CAMINO MAQUILADORA		
Business Type:	Contractors-Street, Painting, Roofers, Building		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Frhmbp Report Filename:						
Frhmbp Sitemap Filename:						
14	1 of 5	NW	0.17 / 915.11	505.92 / -3	T K OF SAN DIEGO 6975 CAMINO MAQUILLADORA SAN DIEGO CA 92173	RCRA SQG

EPA Handler ID: CAD982460347
Gen Status Universe: Small Quantity Generator
Contact Name:
Contact Address: US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: SAN DIEGO
EPA Region: 09
Land Type:
Receive Date: 19960901
Location Latitude: 32.566829
Location Longitude: -116.989556

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Apr, 2022.

Violation Details

Found Violation: Yes
Citation: FR - 262.10-12.A
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19930211
Scheduled Compliance Date:
Return to Compliance: Unverifiable
Actual Return to Compl: 19940426
Violation Responsible Agency: State

Violation Details

Found Violation: Yes
Citation: FR - 262.10-12.A
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19920204
Scheduled Compliance Date:
Return to Compliance: Unverifiable
Actual Return to Compl: 19930211
Violation Responsible Agency: State

Violation Details

Found Violation: Yes
Citation: FR - 262.10-12.A
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19940426
Scheduled Compliance Date:
Return to Compliance: Not Resolvable
Actual Return to Compl: 19990426
Violation Responsible Agency: State

Evaluation Details

Evaluation Start Date: 19920204
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19930211
Evaluation Agency: State Contractor/Grantee

Evaluation Start Date: 19940426
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19990426
Evaluation Agency: State Contractor/Grantee

Evaluation Start Date: 19930211
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19940426
Evaluation Agency: State Contractor/Grantee

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19901023
Handler Name: T K OF SAN DIEGO
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960901
Handler Name: T K OF SAN DIEGO
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: NOT REQUIRED
Date Became Current:
Date Ended Current:
Phone: 415-555-1212
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: ME
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	HAMMAN INVESTMENT	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	ME
Phone:	415-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Historical Handler Details

Receive Dt:	19901023
Generator Code Description:	Large Quantity Generator
Handler Name:	T K OF SAN DIEGO

14	2 of 5	NW	0.17 / 915.11	505.92 / -3	**PINNACLE INDUSTRIAL SUPPLY, INC; PINNACLE INDUSTRIAL SUPPLY, INC** **6975 CAMINO MAQUILADORA,** **SAN DiEGO, CA 92154** **SAN DiEGO CA 92154; 0**	**HAZ SANDIEGO**

Record ID:	DEH2006-HUPFP-206248	**GIS Record ID:**	DEH2006-HUPFP-206248
Facility Name:		**GIS Facility City:**	SAN DiEGO
Facility City:		**GIS Facility ZipCode:**	92154; 0
Facility ZipCode:		**GIS Fac Latitude:**	32.566392; 0
Facility Latitude:		**GIS Fac Longitude:**	-116.9894996; 0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	PINNACLE INDUSTRIAL SUPPLY, INC; PINNACLE INDUSTRIAL SUPPLY, INC		
GIS Facility Address:	6975 CAMINO MAQUILADORA, SAN DiEGO, CA 92154		
Tank Owner Name:			

Hazardous Waste and Materials

ID:	40135	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2015-HCHEM-0066387	**Active Permit:**	true
CAS No:	68476-85-7	**Haz Material Type:**	Pure
Last Updated:	05/18/2016 02:32:16 AM	**Trade Secret:**	false
Chemical Name:	PROPANE		
Common Name Inventory:	PROPANE		

ID:	94981	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2017-HWAST-0111929	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	01/17/2019 01:21:02 AM	**Trade Secret:**	false
Chemical Name:	WASTE 223 UNSPEC OIL CONTAINING WASTE		
Common Name Inventory:	OILY ABSORBENT		

ID:	454289	**Permit Status:**	Issued
Child Record ID:	DEH2021-HCHEM-0309496	**Active Permit:**	true
CAS No:	74-86-2	**Haz Material Type:**	Pure
Last Updated:	11/08/2021 07:26:17 AM	**Trade Secret:**	false
Chemical Name:	Acetylene		
Common Name Inventory:	Acetylene		

ID:	454290	**Permit Status:**	Issued
Child Record ID:	DEH2021-HCHEM-0309497	**Active Permit:**	true
CAS No:	7782-44-7	**Haz Material Type:**	Pure
Last Updated:	11/08/2021 07:26:17 AM	**Trade Secret:**	false
Chemical Name:	Oxygen		
Common Name Inventory:	Oxygen Gas		

ID:	454288	**Permit Status:**	Issued
Child Record ID:	DEH2021-HCHEM-0309495	**Active Permit:**	true

CAS No: 74-98-6 **Haz Material Type:** Pure
Last Updated: 11/08/2021 07:26:17 AM **Trade Secret:** false
Chemical Name: Propane
Common Name Inventory: Propane

ID: 94980 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0133760 **Active Permit:** true
CAS No: 68476-85-7 **Haz Material Type:** Pure
Last Updated: 01/17/2019 01:21:02 AM **Trade Secret:** false
Chemical Name: PROPANE
Common Name Inventory: PROPANE

ID: 40136 **Permit Status:** Permit Renewed
Child Record ID: DEH2015-HCHEM-0066388 **Active Permit:** true
CAS No: 64742-53-6 **Haz Material Type:** Mixture
Last Updated: 05/18/2016 02:32:16 AM **Trade Secret:** false
Chemical Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Common Name Inventory: OILY ABSORBENT

Hazardous Materials Inspection Violations

Container Tank ID: **Inspection No:** 6815989
Facility ID No: 37-000-206248 **Inspection Type:** Initial Inspection
ID: 57706 **Inspection Date:** 10/29/2021 12:00:00 AM
UST ID: **Compliance Date:**
Permit Status: Expired **Last Updated:** 01/14/2022 12:51:24 AM
Active Permit: false **NOV:**
Program Element: Hazardous Waste Generator
Violation Classification:
Violation Code: HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS AND LQGS

Container Tank ID: **Inspection No:** 4099147
Facility ID No: 37-000-206248 **Inspection Type:** Routine
ID: 20985 **Inspection Date:** 05/18/2015 12:00:00 AM
UST ID: **Compliance Date:** 05/18/2015 12:00:00 AM
Permit Status: Expired **Last Updated:** 01/14/2022 12:51:24 AM
Active Permit: false **NOV:** false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010008 Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date. For facilities with invenntory that exceed EPCRA thresholds; failure to submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages HSC 6.95 25508.2 / 19 CCR 4 2729.5(c)

Container Tank ID: **Inspection No:** 6815989
Facility ID No: 37-000-206248 **Inspection Type:** Initial Inspection
ID: 57707 **Inspection Date:** 10/29/2021 12:00:00 AM
UST ID: **Compliance Date:** 11/16/2021 12:00:00 AM
Permit Status: Expired **Last Updated:** 01/14/2022 12:51:24 AM
Active Permit: false **NOV:** false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3010002 Failed to obtain &/or maintain an active EPA ID Number. 22 CCR 66262.12(a)

Container Tank ID: **Inspection No:** 4099147
Facility ID No: 37-000-206248 **Inspection Type:** Routine
ID: 20986 **Inspection Date:** 05/18/2015 12:00:00 AM
UST ID: **Compliance Date:** 05/18/2015 12:00:00 AM
Permit Status: Expired **Last Updated:** 01/14/2022 12:51:24 AM
Active Permit: false **NOV:** false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Minor
Violation Code: 1010006 Failure to update hazardous material inventory within 30 days when one of the following occurs: A 100 percent or more increase in the quantity of a previously disclosed material; Any handling of a previously undisclosed hazardous materials; A change of business address, business ownership, or business name; HSC 6.95 25508.1(a)/(b)/(c)/(d)/(e).

Container Tank ID: **Inspection No:** 4099147
Facility ID No: 37-000-206248 **Inspection Type:** Routine

ID:	20984	**Inspection Date:**	05/18/2015 12:00:00 AM
UST ID:		**Compliance Date:**	05/18/2015 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	01/14/2022 12:51:24 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010002 Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; HSC 6.95 25508(a) 1A		

Container Tank ID:		**Inspection No:**	6139395
Facility ID No:	37-000-206248	**Inspection Type:**	Routine
ID:	47430	**Inspection Date:**	07/31/2019 12:00:00 AM
UST ID:		**Compliance Date:**	08/21/2019 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	01/14/2022 12:51:24 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	3030017 Failed to properly close hazardous waste container(s). 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2), 265.173		

Container Tank ID:		**Inspection No:**	4099147
Facility ID No:	37-000-206248	**Inspection Type:**	Routine
ID:	20983	**Inspection Date:**	05/18/2015 12:00:00 AM
UST ID:		**Compliance Date:**	05/18/2015 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	01/14/2022 12:51:24 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Minor		
Violation Code:	1010003 Owner/Operator failed to complete and/or submit the Business Activities Page and/or Business Owner Operator Identification Page; 19 CCR 4 2729.2(a)(1).		

Container Tank ID:		**Inspection No:**	6815989
Facility ID No:	37-000-206248	**Inspection Type:**	Initial Inspection
ID:	57708	**Inspection Date:**	10/29/2021 12:00:00 AM
UST ID:		**Compliance Date:**	11/16/2021 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	01/14/2022 12:51:24 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)		

Container Tank ID:		**Inspection No:**	6815989
Facility ID No:	37-000-206248	**Inspection Type:**	Initial Inspection
ID:	57705	**Inspection Date:**	10/29/2021 12:00:00 AM
UST ID:		**Compliance Date:**	
Permit Status:	Expired	**Last Updated:**	01/14/2022 12:51:24 AM
Active Permit:	false	**NOV:**	
Program Element:	Hazardous Waste Generator		
Violation Classification:			
Violation Code:	HMD0001 RECORD KEEPING/OPERATIONAL REQUIREMENTS		

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:	10395226	**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Permit Suspended	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:	No	**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461901100
SIC Code:		**X Coord:**	6333823.154

NAICS Code:		**Y Coord:**	1786685.084
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 206248
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333823.15408
UST Facility:		**Point Y:**	1786685.08409
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Y	**Side:**	
Recycle100:		**X Map Coord:**	-116.98949736383479
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.5664394926005
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:	6975 CAMINO MAQUILADORA	**Bill Code 3:**	
Parcel No:	646-190-11-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6975 CAMINO MAQUILADORA		
Business Type:	Contractors-Street, Painting, Roofers, Building		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

GIS Facility ID:	37-000-206248	**Status:**	
GIS CERS ID:	10395226	**ER Contact:**	619-770-8970
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	619-710-4255
Per Type:		**Census Tract:**	100.15
Per Sub Type:		**Parcel Zip:**	92154
Per Cat:		**Community:**	San Diego
Record Status:	Permit Renewed	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAL000355386	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HS015
Tank Owner:		**Feature ID:**	6461901100
SIC Code:	0000	**X Coord:**	6333823.154
NAICS Code:		**Y Coord:**	1786685.084
Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	HK07 206248
Exp Date:	5/30/2020	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333823.154
UST Facility:		**Point Y:**	1786685.08400001
Total No USTs:		**Lat GS84:**	32.566392
No of Tanks:		**Lon GS84:**	-116.9894996
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Y	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.98949736383479
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.5664394926005
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:	No	**ARC Zipcode:**	
Hazmat EHS:	N	**ARC State:**	
Hazmat Rad:	No	**ARC APN:**	
Haz Waste Rad:	N	**Zip:**	
Haz Waste EHS:	N	**Farm Nursery:**	
Full Name:	Pinnacle Industrial Supply	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	619-710-4255	**Bill Code 2:**	Not Applicable
Site Address:	6975 CAMINO MAQUILADORA	**Bill Code 3:**	Not Applicable
Parcel No:	646-190-11-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6975 CAMINO MAQUILADORA		
Business Type:	Contractors-Street, Painting, Roofers, Building		
Bill Code:	Not Applicable		
ER Con Name:	DAN HALECKY		
ER Con Title:	PRESIDENT		
Water Purv:	SAN DIEGO		
Fire Agency:	SAN DIEGO		
Geo SRC:	Mapped to record APN/Parcel XY center		
Match Addr:			
Hirt Flag:	No		
Frhmbp Report Filename:	HMBP206248.pdf		
Frhmbp Sitemap Filename:			

14	3 of 5	NW	0.17 / 915.11	505.92 / -3	THERMO KING OF SAN DIEGO 6975 CAMINO MAQUILADORA, SAN DIEGO, 92173-3504 CA	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-129980	**GIS Record ID:**	
Facility Name:	THERMO KING OF SAN DIEGO	**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	
Facility ZipCode:		**GIS Fac Latitude:**	
Facility Latitude:		**GIS Fac Longitude:**	
Facility Longitude:			
Facility Address:	6975 CAMINO MAQUILADORA, SAN DIEGO, 92173-3504		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

14	4 of 5	NW	0.17 / 915.11	505.92 / -3	PINNACLE INDUSTRIAL SUPPLY INC 6975 CAMINO MAQUILADORA SAN DIEGO CA 92154-7504	RCRA NON GEN

EPA Handler ID:	CAL000355386
Gen Status Universe:	No Report
Contact Name:	BRIAN CHIN
Contact Address:	1612 , PACIFIC RIM CT , , SAN DIEGO , CA, 92154 , US
Contact Phone No and Ext:	619-710-4255
Contact Email:	BCHIN@PINNACLECA.COM
Contact Country:	US
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	Other
Receive Date:	20210825
Location Latitude:	32.566829
Location Longitude:	-116.989556

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20100803
Handler Name:	PINNACLE INDUSTRIAL SUPPLY
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20210825
Handler Name:	PINNACLE INDUSTRIAL SUPPLY INC
Source Type:	Deactivation
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	1612
Type:	Other	***Street 1:***	PACIFIC RIM CT
Name:	PINNACLE INDUSTRIAL SUPPLY	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	619-710-4255	***Country:***	US
Source Type:	Deactivation	***Zip Code:***	92154
Owner/Operator Ind:	Current Operator	***Street No:***	1612
Type:	Other	***Street 1:***	PACIFIC RIM CT
Name:	PINNACLE INDUSTRIAL SUPPLY	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	619-710-4255	***Country:***	US
Source Type:	Deactivation	***Zip Code:***	92154
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	6975 CAMINO MAQUILADORA
Name:	PINNACLE INDUSTRIAL SUPPLY	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	619-710-4255	***Country:***	
Source Type:	Implementer	***Zip Code:***	92154-7504
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	6975 CAMINO MAQUILADORA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	BRIAN CHIN	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-710-4255	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

Historical Handler Details

Receive Dt:	20100803
Generator Code Description:	Not a Generator, Verified
Handler Name:	PINNACLE INDUSTRIAL SUPPLY

14	*5 of 5*	*NW*	*0.17 / 915.11*	*505.92 / -3*	***BORDER RECAPPING LLC DBA BORDER TIRE 6975 CAMINO MAQUILADORA SAN DIEGO CA 92154***	***RCRA NON GEN***

EPA Handler ID:	CAL000466847
Gen Status Universe:	No Report
Contact Name:	MARIO HERNANDEZ
Contact Address:	6975 CAMINO MAQUILADORA , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext:	619-671-0570
Contact Email:	MARIO.HERNANDEZ@BORDER-TIRE.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20211117
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20211117
Handler Name:	BORDER RECAPPING LLC DBA BORDER TIRE
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	6975 CAMINO MAQUILADORA
Name:	MARIO HERNANDEZ	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	619-671-0570	***Country:***	
Source Type:	Implementer	***Zip Code:***	92154

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	3590 W PICACHO AVE
Name:	BORDER RECAPPING LLC	***Street 2:***	
Date Became Current:		***City:***	LAS CRUCES
Date Ended Current:		***State:***	NM
Phone:	575-636-3355	***Country:***	
Source Type:	Implementer	***Zip Code:***	88007

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	1 of 4	NW	0.19 / 997.03	504.65 / -4	OFFICE 2000 6955 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2011-HUPFP-213421	***GIS Record ID:***	DEH2011-HUPFP-213421
Facility Name:		***GIS Facility City:***	SAN DIEGO
Facility City:		***GIS Facility ZipCode:***	92154
Facility ZipCode:		***GIS Fac Latitude:***	32.5663931
Facility Latitude:		***GIS Fac Longitude:***	-116.9905162
Facility Longitude:			
Facility Address:			
GIS Facility Name:	OFFICE 2000		
GIS Facility Address:	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		***Status:***	
GIS CERS ID:		***ER Contact:***	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	***ER Con Work Ph:***	
Per Type:		***Census Tract:***	
Per Sub Type:		***Parcel Zip:***	
Per Cat:		***Community:***	
Record Status:	Completed	***Jurisdiction:***	
HW Tier:		***Basin No:***	
LRG QTY MW Gener:		***BOS Dist:***	
EPA ID No:		***Tbpg Grid:***	
RMP CAL ARP:		***Insp Dist:***	
Tank Owner:		***Feature ID:***	6461902400
SIC Code:		***X Coord:***	6333510.115
NAICS Code:		***Y Coord:***	1786688.416
Disclose Qty Haz Mat:		***Kiva Per Typ:***	HK07 213421
Exp Date:		***Agency Name:***	COSD
Own/Operate USTs :		***Point X:***	6333510.11501
UST Facility:		***Point Y:***	1786688.41611
Total No USTs:		***Lat GS84:***	32.5663931
No of Tanks:		***Lon GS84:***	-116.9905162
Own Oper APS:		***Loc Name:***	
Tot APSA Cap:	0	***Score:***	
Capacity LR:		***Match Type:***	
Haz Waste G:		***Side:***	
Recycle100:		***X Map Coord:***	-116.99051341773303
Onsite Haz Waste Tre:		***Y Map Coord:***	32.566442543898695
RCRA LRG Qty:		***User Fld:***	
Haz Wst Coll Site:		***Addr Type:***	
Accept Offs:		***ARC Address:***	
Universal Waste Han:		***ARC City:***	
Toxic Gas:		***ARC Zipcode:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-24-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6955 CAM MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

15	2 of 4	NW	0.19 / 997.03	504.65 / -4	**GM WHOLESALE & ROAD SERVICE TIRES, INC** **6955 CAM MAQUILADORA, SAN DIEGO, CA 92154** **SAN DIEGO CA 92154**	**HAZ SANDIEGO**

Record ID:	DEH2006-HUPFP-206242	**GIS Record ID:**	DEH2006-HUPFP-206242
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5663931
Facility Latitude:		**GIS Fac Longitude:**	-116.9905162
Facility Longitude:			
Facility Address:			
GIS Facility Name:	GM WHOLESALE & ROAD SERVICE TIRES, INC		
GIS Facility Address:	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902400
SIC Code:		**X Coord:**	6333510.115
NAICS Code:		**Y Coord:**	1786688.416
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK18 206242
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333510.11501
UST Facility:		**Point Y:**	1786688.41611
Total No USTs:		**Lat GS84:**	32.5663931
No of Tanks:		**Lon GS84:**	-116.9905162
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99051341773303

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Onsite Haz Waste Tre:		**Y Map Coord:**	32.566442543898695
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-24-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6955 CAM MAQUILADORA		
Business Type:	One (1) Waste Item or One (1) Inventory		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

15	3 of 4	NW	0.19 / 997.03	504.65 / -4	**SUPER SPICE COMPANY** **6955 CAM MAQUILADORA, SAN DIEGO, CA 92154** **SAN DIEGO CA 92154**	**HAZ SANDIEGO**

Record ID:	DEH2006-HUPFP-206244	**GIS Record ID:**	DEH2006-HUPFP-206244
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5663931
Facility Latitude:		**GIS Fac Longitude:**	-116.9905162
Facility Longitude:			
Facility Address:			
GIS Facility Name:	SUPER SPICE COMPANY		
GIS Facility Address:	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902400
SIC Code:		**X Coord:**	6333510.115
NAICS Code:		**Y Coord:**	1786688.416
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK18 206244
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333510.11501
UST Facility:		**Point Y:**	1786688.41611
Total No USTs:		**Lat GS84:**	32.5663931
No of Tanks:		**Lon GS84:**	-116.9905162

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99051341773303
Onsite Haz Waste Tre:		**Y Map Coord:**	32.566442543898695
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-24-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6955 CAM MAQUILADORA		
Business Type:	One (1) Waste Item or One (1) Inventory		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

15	4 of 4	NW	0.19 / 997.03	504.65 / -4	**LCA EXPORT** **6955 CAM MAQUILADORA, SAN DIEGO, CA 92154** **SAN DIEGO CA 0**	**HAZ SANDIEGO**

Record ID:	DEH2006-HUPFP-206243	**GIS Record ID:**	DEH2006-HUPFP-206243
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	0
Facility Latitude:		**GIS Fac Longitude:**	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	LCA EXPORT		
GIS Facility Address:	6955 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:	10394398	**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Permit Suspended	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:	No	**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902400
SIC Code:		**X Coord:**	6333510.115
NAICS Code:		**Y Coord:**	1786688.416
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK18 206243

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333510.11501
UST Facility:		**Point Y:**	1786688.41611
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99051341773303
Onsite Haz Waste Tre:		**Y Map Coord:**	32.566442543898695
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-24-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6955 CAM MAQUILADORA		
Business Type:	Not Applicable		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	1 of 5	SW	0.20 / 1,050.50	509.40 / 0	MARTINEZ RANCH 2160 CACTUS RD San Diego CA	SAM SANDIEGO

Record ID:	DEH2004-LSAM-H99064-001	**Primary Parcel:**	YES
Record ID (DEH Lyr):	DEH2004-LSAM-H99064-001	**Primary Address:**	YES
ID:	5590	**Address Type:**	ALIAS
Object ID:	5586	**Street String:**	2160 CACTUS RD
SWRCB Global ID:	T06019770242	**Community:**	San Diego
Feature ID:	6461002000	**Zip Code:**	
Parcel No:	646-100-20-00	**Zip Community:**	92154
Case No:	H99064-001	**Jurisdiction:**	SAN DIEGO
H No:	H99064	**Census Tract:**	100.15
KIVA per Tp per No:	6SAM H99064	**GT Global ID:**	T06019770242
Status:	Completed	**GT RB Case No:**	
Historical Name:	MARTINEZ RANCH	**GT Status:**	Completed - Case Closed
Record Name:	MARTINEZ RANCH	**GT Status Date:**	10/28/2012 8:00 PM
Project Name:	MARTINEZ RANCH	**GT Case Type:**	Cleanup Program Site
Record Status:	Completed	**GT Lead Agency:**	SAN DIEGO COUNTY LOP
Record Type:	SAM Investigation	**GT CUF Case:**	NO
Record Alias:	SAM Investigation	**GT County:**	San Diego
Date:	11/05/2004	**GT Longitude:**	-116.989567
Per Type:	LWQD	**GT Latitude:**	32.559274
DEH Permit Owner:		**Agency Name:**	COSD
Fire Agency:	SAN DIEGO	**Lead Agency:**	DEH/SAM
Point X:	6333700.94861589	**Lead Agcy Date:**	11/8/2004 7:00 PM
Point Y:	1782887.48867173	**Opened Date:**	11/4/2004 7:00 PM
Latitude GS84:	32.5591297	**ThomasBros Map Gd:**	1351 D 3
Longitude GS84:	-116.9895249	**Funding:**	XV - Non-Billable VAP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Watershed Basin: 911.12
BOS District: 1
Water Purveyor: SAN DIEGO
Short Notes:
Address: 2160 CACTUS RD
Case Type: VAP - Voluntary Assistance Program
Geo SRC: Mapped to XY from previous SAM Layer
Record Type (DEH Lyr): LUEG-DEH/LWQD/SAM Investigation/NA
Source File: Citizen Access DEH Site Assessment and Mitigation Investigation Sites; San Diego Site Assessment and Mitigation Investigation Sites

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	2 of 5	SW	0.20 / 1,050.50	509.40 / 0	MARTINEZ RANCH 2160 CACTUS RD SAN DIEGO CA 92154	CLEANUP SITES

Global ID: T06019770242
Latitude: 32.559274
Status: COMPLETED - CASE CLOSED
Longitude: -116.989567
Status Date: 10/29/2012
County: SAN DIEGO
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:
Potential COC:
Local Case No: H99064-001
How Discovered:
Begin Date: 11/5/2004
Stop Method:
Lead Agency: SAN DIEGO COUNTY LOP
Stop Description:
Local Agency: SAN DIEGO COUNTY LOP
Case Worker: SW
CUF Case: NO
Military DoD Site: No
CalEnvScreen Score: 66-70%
Leak Reported Dt:
EPA Region: 9
No Further Action Dt: 2012-10-29 00:00:00
Qty Rlsd Gallons:
Potential Media of Concern:
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community:
Coordinate Source: Manual Entry on Screens
Discharge Cause:
Discharge Source:
File Location: Local Agency
Site History:

Refer to "Site Maps/Documents" for Admin Closure Memo

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2013-09-10 00:00:00
Action: Letter - Notice

Action Type: ENFORCEMENT
Date: 2012-10-29 00:00:00
Action: Closure/No Further Action Letter

Action Type: ENFORCEMENT
Date: 2012-07-23 00:00:00
Action: Letter - Notice

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2012-10-29 00:00:00

Status: Open - Site Assessment

Status Date: 2004-11-05 00:00:00

Status: Open - Inactive
Status Date: 2004-11-05 00:00:00

Status: Open - Case Begin Date
Status Date: 2004-11-05 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: SCOTT WELDON
Phone No:
Organization Name: SAN DIEGO COUNTY LOP
Email: scott.weldon@sdcounty.ca.gov
Address: P.O. Box 129261
City: San Diego

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T06019770242
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 10/29/2012
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: H99064-001
CASEWORKER: SCOTT WELDON
SAN DIEGO RWQCB (REGION 9)
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T06019770242&tabname=regulatoryhistory
Site History:

Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

Refer to "Site Maps/Documents" for Admin Closure Memo

Sites from GeoTracker Search - Regulatory Activities

Action Type: Notices
Action: Letter - Notice
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T06019770242&enforcement_id=6174604&temptable=ENFORCEMENT
Title Description Comments:

Action Date: 9/10/2013
Received Issue Date: 9/10/2013

Letter notifying the City of San Diego POlanning Dept.

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T06019770242&enforcement_id=6141314&temptable=ENFORCEMENT
Title Description Comments:

Action Date: 10/29/2012
Received Issue Date: 10/29/2012

Administrative Closure Memo

Action Type: Notices
Action Date: 7/23/2012
Action: Letter - Notice
Received Issue Date: 7/23/2012
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T06019770242&enforcement_id=6136973&temptable=ENFORCEMENT
Title Description Comments:

Withdra Request.

Sites from GeoTracker Search - Documents

Document Type: Site Documents
Submitted:
Document Date: 9/10/2013
Submitted By: NASSER SIONIT (REGULATOR)
Size :
Title: LETTER NOTIFYING THE CITY OF SAN DIEGO POLANNING DEPT.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T06019770242&enforcement_id=6174604
Type: LETTER - NOTICE

Document Type: Site Documents
Submitted:
Document Date: 10/29/2012
Submitted By: ELLEN BEACON (REGULATOR)
Size :
Title: ADMINISTRATIVE CLOSURE MEMO
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T06019770242&enforcement_id=6141314
Type: CLOSURE/NO FURTHER ACTION LETTER

Document Type: Site Documents
Submitted:
Document Date: 7/23/2012
Submitted By: NASSER SIONIT (REGULATOR)
Size :
Title: WITHDRA REQUEST.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T06019770242&enforcement_id=6136973
Type: LETTER - NOTICE

Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 10/29/2012

Status: Open - Inactive
Date: 11/5/2004

Status: Open - Site Assessment
Date: 11/5/2004

Status: Open - Case Begin Date
Date: 11/5/2004

---

16 | ***3 of 5*** | ***SW*** | ***0.20 / 1,050.50*** | ***509.40 / 0*** | ***MARTINEZ RANCH***
2160 CACTUS RD
SAN DIEGO CA 92154 | ***AST***

Total Capacity(Gal): 2610
Owner Name: MARTINEZ RANCH
CUPA: San Diego
County: San Diego

---

16 | ***4 of 5*** | ***SW*** | ***0.20 / 1,050.50*** | ***509.40 / 0*** | ***MARTINEZ RANCH***
2160 CACTUS, SAN DIEGO, CA 92154
SAN DIEGO CA 92154 | ***HAZ SANDIEGO***

Record ID: DEH2010-HUPFP-211670
GIS Record ID: DEH2010-HUPFP-211670
Facility Name:
GIS Facility City: SAN DIEGO
Facility City:
GIS Facility ZipCode: 92154
Facility ZipCode:
GIS Fac Latitude: 32.5591297

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Latitude:		**GIS Fac Longitude:**	-116.9895249
Facility Longitude:			
Facility Address:			
GIS Facility Name:	MARTINEZ RANCH		
GIS Facility Address:	2160 CACTUS, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461002000
SIC Code:		**X Coord:**	6333783.207
NAICS Code:		**Y Coord:**	1784078.355
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 211670
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333783.20698
UST Facility:		**Point Y:**	1784078.35506
Total No USTs:		**Lat GS84:**	32.5591297
No of Tanks:		**Lon GS84:**	-116.9895249
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.98956700307573
Onsite Haz Waste Tre:		**Y Map Coord:**	32.559274590841106
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-100-20-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	2160 CACTUS		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	5 of 5	SW	0.20 / 1,050.50	509.40 / 0	MARTINEZ RANCH 2160 CACTUS RD CA 0	HAZ SANDIEGO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Record ID:	DEH2002-HUPFP-199064	**GIS Record ID:**	DEH2002-HUPFP-199064
Facility Name:		**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	32.5591297
Facility Latitude:		**GIS Fac Longitude:**	-116.9895249
Facility Longitude:			
Facility Address:			
GIS Facility Name:	MARTINEZ RANCH		
GIS Facility Address:	2160 CACTUS RD		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tler:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461002000
SIC Code:		**X Coord:**	6333783.207
NAICS Code:		**Y Coord:**	1784078.355
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 199064
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333783.20698
UST Facility:		**Point Y:**	1784078.35506
Total No USTs:		**Lat GS84:**	32.5591297
No of Tanks:		**Lon GS84:**	-116.9895249
Own Oper APS:	Y	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.98956700307573
Onsite Haz Waste Tre:		**Y Map Coord:**	32.559274590841106
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-100-20-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	2160 CACTUS RD		
Business Type:	Agriculture Site Inspect By Dept AWM		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	1 of 5	S	0.21 / 1,083.84	506.14 / -3	Verizon Wireless: Mesa de Otay 2175 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID: DEH2012-HUPFP-217292
Facility Name:
Facility City:
Facility ZipCode:
Facility Latitude:
Facility Longitude:
Facility Address:
GIS Facility Name: Verizon Wireless: Mesa de Otay
GIS Facility Address: 2175 CACTUS RD, SAN DIEGO, CA 92154
Tank Owner Name:

GIS Record ID: DEH2012-HUPFP-217292
GIS Facility City: SAN DIEGO
GIS Facility ZipCode: 92154
GIS Fac Latitude: 32.5580757
GIS Fac Longitude: -116.986175

Hazardous Waste and Materials

ID: 143271
Child Record ID: DEH2018-HCHEM-0168292
CAS No: 68476-34-6
Last Updated: 02/03/2018 01:26:08 AM
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 63176
Child Record ID: DEH2016-HCHEM-0124371
CAS No:
Last Updated: 10/31/2017 02:34:01 AM
Chemical Name:
Common Name Inventory: Lead Acid Batteries

Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 143272
Child Record ID: DEH2018-HCHEM-0168293
CAS No:
Last Updated: 02/03/2018 01:26:08 AM
Chemical Name:
Common Name Inventory: Lead Acid Batteries

Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Mixture
Trade Secret: false

ID: 63175
Child Record ID: DEH2016-HCHEM-0124370
CAS No: 68476-34-6
Last Updated: 10/31/2017 02:34:01 AM
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

HMD Permits Map Data

GIS Facility ID: 37-000-217292
GIS CERS ID: 10163485
GIS Record Type: LUEG-DEH/HMD/UPFP/Facility
Per Type:
Per Sub Type:
Per Cat:
Record Status: Permit Renewed
HW Tier: Not Applicable
LRG QTY MW Gener: No
EPA ID No:
RMP CAL ARP: Not Applicable
Tank Owner:
SIC Code: 4812
NAICS Code: 517210
Disclose Qty Haz Mat: Y
Exp Date: 11/29/2020
Own/Operate USTs :
UST Facility:
Total No USTs:

Status:
ER Contact: (800) 264-6620
ER Con Work Ph: (800) 264-6620
Census Tract: 100.15
Parcel Zip: 92154
Community: San Diego
Jurisdiction: SAN DIEGO
Basin No: 911.12
BOS Dist: 1
Tbpg Grid:
Insp Dist: HPC064
Feature ID:
X Coord: 6334841.536
Y Coord: 1783612.218
Kiva Per Typ: HK07 217292
Agency Name: COSD
Point X: 6334841.536
Point Y: 1783612.21799999
Lat GS84: 32.5580757

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

No of Tanks:		**Lon GS84:**	-116.986175
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	N	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.98612176434442
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.55801408085075
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:	N	**ARC Address:**	
Universal Waste Han:	N	**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:	N	**ARC State:**	
Hazmat Rad:	No	**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:	Verizon Wireless	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	(949) 286-7000	**Bill Code 2:**	Not Applicable
Site Address:	2175 Cactus Rd	**Bill Code 3:**	Not Applicable
Parcel No:		**Univ Waste Gen Type:**	

Record Ali:	Unified Program Facility Permit
Address:	2175 CACTUS RD
Business Type:	Cellular Site
Bill Code:	Not Applicable
ER Con Name:	Verizon Wireless Network Operations Center
ER Con Title:	N/A
Water Purv:	OTAY WATER IMP DIST C-SEWER
Fire Agency:	SAN DIEGO
Geo SRC:	Mapped to record APN/Parcel XY center
Match Addr:	
Hirt Flag:	No
Frhmbp Report Filename:	HMBP217292.pdf
Frhmbp Sitemap Filename:	MAP_217292.pdf

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	2 of 5	S	0.21 / 1,083.84	506.14 / -3	AZULEE AUTO RECON 2175 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2004-HUPFP-203300	**GIS Record ID:**	DEH2004-HUPFP-203300
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5580757
Facility Latitude:		**GIS Fac Longitude:**	-116.986175
Facility Longitude:			
Facility Address:			
GIS Facility Name:	AZULEE AUTO RECON		
GIS Facility Address:	2175 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461000900
SIC Code:		**X Coord:**	6334841.536
NAICS Code:		**Y Coord:**	1783612.218

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK18 203300
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334841.5359
UST Facility:		**Point Y:**	1783612.21787
Total No USTs:		**Lat GS84:**	32.5580757
No of Tanks:		**Lon GS84:**	-116.986175
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.98612176434442
Onsite Haz Waste Tre:		**Y Map Coord:**	32.55801408085075
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-100-09-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	2175 CACTUS RD		
Business Type:	One (1) Waste Item or One (1) Inventory		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

17	3 of 5	S	0.21 / 1,083.84	506.14 / -3	**ADESA SAN DIEGO** **2175 CACTUS RD** **SAN YSIDRO CA 92173**	**HAZ SANDIEGO**

Record ID:	DEH2002-HUPFP-129754	**GIS Record ID:**	DEH2002-HUPFP-129754
Facility Name:	ADESA SAN DIEGO	**GIS Facility City:**	SAN YSIDRO
Facility City:	SAN YSIDRO	**GIS Facility ZipCode:**	92173
Facility ZipCode:	92173	**GIS Fac Latitude:**	32.5481623
Facility Latitude:		**GIS Fac Longitude:**	-116.9872576
Facility Longitude:			
Facility Address:	2175 CACTUS RD		
GIS Facility Name:	ADESA SAN DIEGO		
GIS Facility Address:	2175 CACTUS RD, SAN YSIDRO, CA 92173		
Tank Owner Name:			

Hazardous Materials Facility Data

CERS ID:	10395157	**Onsite H Waste Trtmt:**	false
Facility ID No:	37-000-129754	**Haz Mat on Site:**	true
EPA ID No:	CAL000346874	**Haz Waste Generator:**	true
Active Permit:	true	**Own/Oper Under:**	false
Permit Status:	Permit Renewed	**Own/Oper Above:**	false
Bus. Phone:	619-661-5565	**Recycle:**	false
Bus. Fax:	0	**RCRA Large Qty Gen:**	false
Last Updated:	02/25/2022 12:55:04 AM	**HHW Collection:**	false
New Georeferenced Column:			
Mailing Address:	2175 CACTUS RD, SAN DIEGO, CA 92154		

Hazardous Waste and Materials

ID: 234407 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227285 ***Active Permit:*** true
CAS No: ***Haz Material Type:*** Mixture
Last Updated: 08/02/2019 12:45:11 AM ***Trade Secret:*** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 341570 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273579 ***Active Permit:*** true
CAS No: 74-98-6 ***Haz Material Type:*** Mixture
Last Updated: 09/01/2020 02:32:56 AM ***Trade Secret:*** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 256105 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234659 ***Active Permit:*** true
CAS No: ***Haz Material Type:*** Mixture
Last Updated: 10/26/2019 01:31:02 AM ***Trade Secret:*** false
Chemical Name:
Common Name Inventory: STINGER 737 ALL CLEAN

ID: 84175 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144041 ***Active Permit:*** true
CAS No: ***Haz Material Type:*** Mixture
Last Updated: 08/30/2017 02:30:57 AM ***Trade Secret:*** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 166720 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2018-HWAST-0160928 ***Active Permit:*** true
CAS No: ***Haz Material Type:***
Last Updated: 07/27/2018 02:31:02 AM ***Trade Secret:*** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 84173 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144039 ***Active Permit:*** true
CAS No: ***Haz Material Type:*** Mixture
Last Updated: 08/30/2017 02:30:57 AM ***Trade Secret:*** false
Chemical Name:
Common Name Inventory: STINGER 822 SHOW ROOM SHINE

ID: 166709 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186029 ***Active Permit:*** true
CAS No: 74-98-6 ***Haz Material Type:*** Mixture
Last Updated: 07/27/2018 02:31:02 AM ***Trade Secret:*** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 256103 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234657 ***Active Permit:*** true
CAS No: ***Haz Material Type:*** Mixture
Last Updated: 10/26/2019 01:31:02 AM ***Trade Secret:*** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 475185 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321114 ***Active Permit:*** true
CAS No: ***Haz Material Type:*** Mixture
Last Updated: 02/25/2022 12:55:05 AM ***Trade Secret:*** false
Chemical Name:
Common Name Inventory: STINGER 771 SILICONE MULTIPURPOSE LUBRICANT

ID: 475189 ***Permit Status:*** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321118 ***Active Permit:*** true

CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 737 ALL CLEAN

ID: 467989 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307336 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 822 SHOWROOM SHINE

ID: 467998 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274697 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MEDICAL WASTE (SHARPS/USED NEEDLES)

ID: 84177 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144043 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name: Liquified petroleum gas
Common Name Inventory: PROPANE

ID: 166717 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160925 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 84168 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144034 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 759 WHEEL BRIGHTENER

ID: 234424 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196981 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 234413 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227291 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 772 PREMIUM SILICONE MULTIPURPOSE LUBRICANT

ID: 18452 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116600 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER PREMIUM VOC

ID: 18455 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HWAST-0097779 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/15/2016 12:35:35 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 114281 **Permit Status:** Permit Renewed

Child Record ID: DEH2017-HCHEM-0157958 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 84176 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144042 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 166729 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160937 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (CAR CLEANING MATERIALS)

ID: 341577 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273586 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 114283 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157960 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 LACQUER THINNER

ID: 114311 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133524 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC WASTE (HOUSEHOLD WASTE)

ID: 341567 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273576 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 166710 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186030 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 268618 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243056 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 737 ALL CLEAN

ID: 166707 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186027 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 763 SPECIALTY ADHESIVE REMOVER

ID: 475196 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288352 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 475199 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288355 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 268630 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213970 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 268632 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213972 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 234414 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227292 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 234430 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196987 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 341585 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242384 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 234410 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227288 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 166721 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160929 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 166722 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160930 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 467981 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307328 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 114284 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157961 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 822 SHOWROOM SHINE

ID: 166711 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186031 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 234406 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227284 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 234408 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227286 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name: Liquified petroleum gas
Common Name Inventory: PROPANE

ID: 268629 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213969 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MEDICAL WASTE (SHARPS/USED NEEDLES)

ID: 114298 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133511 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 114295 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157972 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: PRR 2085B COMPLIANT CLEANING SOLVENT

ID: 256106 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234660 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 772 PREMIUM SILICONE MULTIPURPOSE LUBRICANT

ID: 341575 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273584 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:

Common Name Inventory: STINGER 822 SHOWROOM SHINE

ID: 114305 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133518 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 341572 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273581 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 114282 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157959 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 84172 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144038 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 LACQUER THINNER

ID: 256102 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234656 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 256108 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234662 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 475193 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321122 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 234418 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196975 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 234421 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196978 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 256109 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204851 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false

Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 84169 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144035 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 715 QUICK GLASS

ID: 84171 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144037 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 234409 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227287 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 256112 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204854 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 256098 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234652 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 467991 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307338 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 166718 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160926 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 166731 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160939 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 475187 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321116 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 234402 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227280 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture

Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 234403 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227281 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 234420 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196977 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 341580 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242379 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 268620 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243058 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 341581 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242380 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 114306 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133519 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 475188 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321117 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 268627 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213967 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 114287 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157964 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 114291 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157968 **Active Permit:** true

CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 763 SPECIALTY ADHESIVE REMOVER

ID: 268616 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243054 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 268613 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243051 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 475197 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288353 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 341583 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242382 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 166724 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160932 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 268614 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243052 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 771 SILICONE MULTIPURPOSE LUBRICANT

ID: 166714 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186034 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 912 PREMIUM VOC DRESSING

ID: 256117 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204859 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (CAR CLEANING MATERIALS)

ID: 234428 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196985 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (CAR CLEANING MATERIALS)

ID: 18451 **Permit Status:** Permit Renewed

Child Record ID: DEH2016-HCHEM-0116599 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER SHOW ROOM SHINE

ID: 114296 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133509 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 341576 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273585 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 114300 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133513 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 114290 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157967 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 475186 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321115 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 475192 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321121 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 234404 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227282 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 771 SILICONE MULTIPURPOSE LUBRICANT

ID: 166706 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186026 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 467996 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274695 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 166708 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186028 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 715 QUICK GLASS

ID: 341582 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242381 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 341569 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273578 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 771 SILICONE MULTIPURPOSE LUBRICANT

ID: 166716 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186036 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 166719 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160927 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 114299 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133512 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 467994 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274693 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 467999 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274698 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 114297 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133510 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 475190 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321119 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 772 PREMIUM SILICONE MULTIPURPOSE LUBRICANT

ID: 256099 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234653 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 467986 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307333 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 468000 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274699 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (AUTOMOTIVE FLUIDS)

ID: 475200 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288356 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MEDICAL WASTE (SHARPS/USED NEEDLES)

ID: 467987 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307334 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 737 ALL CLEAN

ID: 341579 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242378 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 234417 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196974 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 234429 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196986 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 166728 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160936 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (HOUSEHOLD WASTE)

ID: 166730 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160938 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:

Common Name Inventory: MOTOR OIL (USED)

ID: 84174 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144040 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 912 PREMIUM VOC DRESSING

ID: 166713 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186033 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name: Liquified petroleum gas
Common Name Inventory: PROPANE

ID: 84170 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0144036 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 18453 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116601 **Active Permit:** true
CAS No: **Haz Material Type:** Pure
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 18454 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116602 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 234422 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196979 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 114286 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157963 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 114292 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157969 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 905 PREMIUM DRESSING

ID: 268628 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213968 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 341586 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242385 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false

Chemical Name:
Common Name Inventory: MISC HAZ WASTE (CAR CLEANING MATERIALS)

ID: 475191 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321120 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 822 SHOWROOM SHINE

ID: 475195 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288351 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 475198 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288354 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 256104 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234658 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 256114 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204856 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 467997 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274696 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 256107 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234661 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 256115 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204857 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MEDICAL WASTE (SHARPS/USED NEEDLES)

ID: 268621 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243059 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL

ID: 268624 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213964 **Active Permit:** true
CAS No: **Haz Material Type:**

Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 256110 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204852 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 256111 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204853 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 256116 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204858 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 166715 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186035 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 166723 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160931 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 467993 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274692 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 234416 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196973 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 114307 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133520 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: SHARPS (USED NEEDLES)

ID: 234427 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196984 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (HOUSEHOLD WASTE)

ID: 114285 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157962 **Active Permit:** true

CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name: Liquified petroleum gas
Common Name Inventory: PROPANE

ID: 268622 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243060 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 822 SHOWROOM SHINE

ID: 114289 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157966 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 705 WASH N WAX

ID: 475183 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321112 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 84179 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0122833 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (WASTE)

ID: 166712 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186032 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 822 SHOWROOM SHINE

ID: 467983 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307330 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 771 SILICONE MULTIPURPOSE LUBRICANT

ID: 467990 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307337 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 467995 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274694 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 468001 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274700 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 234426 **Permit Status:** Permit Renewed

Child Record ID: DEH2019-HWAST-0196983 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 18447 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116595 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER QUICK GLASS

ID: 114308 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133521 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 18449 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116597 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER BLUE POWER DEGREASER

ID: 114301 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133514 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 114288 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157965 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 341571 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273580 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 268623 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213963 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 256100 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234654 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 771 SILICONE MULTIPURPOSE LUBRICANT

ID: 467982 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307329 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 475202 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288358 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (AUTOMOTIVE FLUIDS)

ID: 256101 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0234655 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 10/26/2019 01:31:02 AM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 256118 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204860 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 475184 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0321113 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/25/2022 12:55:05 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 475194 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288350 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 475201 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288357 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 467985 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307332 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 736 BLUE POWER DEGREASER

ID: 467988 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307335 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 772 PREMIUM SILICONE MULTIPURPOSE LUBRICANT

ID: 467984 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0307331 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 166727 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160935 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: BONDO AND SANDING DUST (WASTE)

ID: 166726 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160934 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MEDICAL WASTE (SHARPS-USED NEEDLES)

ID: 166705 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186025 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 234419 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196976 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: AEROSOLS (WASTE)

ID: 234405 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227283 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 341584 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242383 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MEDICAL WASTE (SHARPS/USED NEEDLES)

ID: 234412 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227290 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 737 ALL CLEAN

ID: 18446 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116594 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER WHEEL BRIGHTENER

ID: 18448 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116596 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Pure
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 18450 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0116598 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/15/2016 12:35:34 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER LACQUER THINNER

ID: 341587 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242386 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:

Common Name Inventory: MOTOR OIL (USED)

ID: 114303 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133516 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 341574 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273583 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 772 PREMIUM SILICONE MULTIPURPOSE LUBRICANT

ID: 114293 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157970 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 906 SUPER PLUS DRESSING

ID: 268617 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243055 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 256113 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0204855 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/26/2019 01:31:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 268615 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243053 **Active Permit:** true
CAS No: 74-98-6 **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name: Liquefied petroleum gas
Common Name Inventory: PROPANE

ID: 268612 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243050 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 510 HEAVY DUTY TIRE & WHEEL

ID: 268619 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0243057 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 01/16/2020 03:32:54 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 772 PREMIUM SILICONE MULTIPURPOSE LUBRICANT

ID: 268625 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213965 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 268626 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213966 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false

Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 84178 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0122832 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/30/2017 02:30:57 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 475203 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0288359 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 12:55:06 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MOTOR OIL (USED)

ID: 166725 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0160933 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/27/2018 02:31:02 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (SOLIDS)

ID: 467992 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0274691 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/04/2022 02:32:14 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 234415 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227293 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name: Gasoline
Common Name Inventory: GASOLINE

ID: 234423 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196980 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: WASTE PAINT RELATED MATERIAL (LIQUID)

ID: 234425 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0196982 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 08/02/2019 12:45:12 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MEDICAL WASTE (SHARPS/USED NEEDLES)

ID: 234411 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0227289 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 08/02/2019 12:45:11 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 761 (765) LACQUER THINNER

ID: 114304 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133517 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: OILY ABSORBENT (WASTE)

ID: 114310 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133523 **Active Permit:** true
CAS No: **Haz Material Type:**

Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: UNIVERSAL WASTE LIQUIDS

ID: 268631 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0213971 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 01/16/2020 03:32:55 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC HAZ WASTE (CAR CLEANING MATERIALS)

ID: 341578 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0242377 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: ANTIFREEZE (USED)

ID: 114294 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157971 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: PRR 1720B COMPLIANT WATERBORNE CLEANING SOLUTION

ID: 341568 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273577 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 718 CRYSTAL CLEAR RTU

ID: 341573 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0273582 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 09/01/2020 02:32:56 AM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 737 ALL CLEAN

ID: 114309 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133522 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FLUORESCENT BULBS (WASTE)

ID: 114302 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133515 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: FILTERS, PAPER (USED)

ID: 114280 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0157957 **Active Permit:** true
CAS No: **Haz Material Type:** Mixture
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: STINGER 715 QUICK GLASS

ID: 114312 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HWAST-0133525 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/24/2017 12:18:22 PM **Trade Secret:** false
Chemical Name:
Common Name Inventory: MISC WASTE (CAR CLEANING MATERIALS)

Hazardous Materials Inspection Violations

Container Tank ID:
Facility ID No: 37-000-129754
ID: 9996
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5703279
Inspection Type: Routine
Inspection Date: 08/01/2017 04:08:00 PM
Compliance Date: 08/31/2017 12:00:00 AM
Last Updated: 02/25/2022 12:55:01 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Minor
Violation Code: 1010005 Site map not submitted in CERS or not sufficient. HSC 25505(a)(2); 25508(a)(1)(A); 25508.1(f); 19 CCR 2652(a)(3)

Container Tank ID:
Facility ID No: 37-000-129754
ID: 9998
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5703279
Inspection Type: Routine
Inspection Date: 08/01/2017 04:08:00 PM
Compliance Date: 08/29/2017 12:00:00 AM
Last Updated: 02/25/2022 12:55:01 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Minor
Violation Code: 1020002 Initial &/or annual employee training not conducted for hazardous materials management &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Container Tank ID:
Facility ID No: 37-000-129754
ID: 9991
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5703279
Inspection Type: Routine
Inspection Date: 08/01/2017 04:08:00 PM
Compliance Date: 08/07/2017 12:00:00 AM
Last Updated: 02/25/2022 12:55:01 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3030005 Failed to make a proper waste determination. 22 CCR 66262.11, 66262.40(c)

Container Tank ID:
Facility ID No: 37-000-129754
ID: 9997
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5703279
Inspection Type: Routine
Inspection Date: 08/01/2017 04:08:00 PM
Compliance Date: 08/31/2017 12:00:00 AM
Last Updated: 02/25/2022 12:55:01 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Minor
Violation Code: 1010004 Chemical inventory incomplete or not submitted in CERS. HSC 25505(a)(1); 25507(a); 25508(a)(1)(A); 25508.1(a-b); 19 CCR 2654 (a) or (d)

Container Tank ID:
Facility ID No: 37-000-129754
ID: 9994
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5703279
Inspection Type: Routine
Inspection Date: 08/01/2017 04:08:00 PM
Compliance Date: 08/29/2017 12:00:00 AM
Last Updated: 02/25/2022 12:55:01 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3020001 Failure to ensure employees are trained on hazardous waste regulations related to proper waste handling and emergency response procedures. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(5)(iii)

Container Tank ID:
Facility ID No: 37-000-129754
ID: 9995
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5703279
Inspection Type: Routine
Inspection Date: 08/01/2017 04:08:00 PM
Compliance Date: 08/04/2017 12:00:00 AM
Last Updated: 02/25/2022 12:55:01 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3030030 Failed to maintain &/or operate facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(4), 265.31

Container Tank ID:
Facility ID No: 37-000-129754
Inspection No: 5703279
Inspection Type: Routine

ID:	9993	**Inspection Date:**	08/01/2017 04:08:00 PM
UST ID:		**Compliance Date:**	08/31/2017 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/25/2022 12:55:01 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	3030010 Accumulated waste too long (>180 or 270 days) or (>90 days). HSC 25201(a); 22 CCR 66262.34(d); 40 CFR 262.34(e) and (f)		

Container Tank ID:		**Inspection No:**	5703279
Facility ID No:	37-000-129754	**Inspection Type:**	Routine
ID:	9992	**Inspection Date:**	08/01/2017 04:08:00 PM
UST ID:		**Compliance Date:**	08/07/2017 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/25/2022 12:55:01 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3030006 Failed to determine if a hazardous waste is restricted or prohibited from land disposal. 22 CCR 66268.7 (a)		

HMD Permits Map Data

GIS Facility ID:	37-000-129754	**Status:**	
GIS CERS ID:	10395157	**ER Contact:**	619-723-4919
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	619-661-8544
Per Type:		**Census Tract:**	100.15
Per Sub Type:		**Parcel Zip:**	92154
Per Cat:		**Community:**	San Diego
Record Status:	Permit Renewed	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAL000346874	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HS015
Tank Owner:		**Feature ID:**	6670506200
SIC Code:	5012	**X Coord:**	6334466.221
NAICS Code:	423110	**Y Coord:**	1780030.199
Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	HK07 129754
Exp Date:	8/30/2020	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334466.221
UST Facility:		**Point Y:**	1780030.19900002
Total No USTs:		**Lat GS84:**	32.5481623
No of Tanks:		**Lon GS84:**	-116.9872576
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Y	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.98725754606484
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.54816226773029
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:	N	**ARC City:**	
Toxic Gas:	No	**ARC Zipcode:**	
Hazmat EHS:	N	**ARC State:**	
Hazmat Rad:	No	**ARC APN:**	
Haz Waste Rad:	N	**Zip:**	
Haz Waste EHS:	N	**Farm Nursery:**	
Full Name:	ADESA CALIFORNIA LLC	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	800-923-3725	**Bill Code 2:**	Not Applicable
Site Address:	2175 Cactus Rd	**Bill Code 3:**	Not Applicable
Parcel No:	667-050-62-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	2175 CACTUS RD		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:	Not Applicable		
ER Con Name:	James George		
ER Con Title:	Safety Coordinator		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Purv:	SAN DIEGO
Fire Agency:	SAN DIEGO
Geo SRC:	Mapped to record APN/Parcel XY center
Match Addr:	
Hirt Flag:	No
Frhmbp Report Filename:	HMBP129754.pdf
Frhmbp Sitemap Filename:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	4 of 5	S	0.21 / 1,083.84	506.14 / -3	ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO 2175 CACTUS RD SAN DIEGO CA 92154-8002	RCRA NON GEN

EPA Handler ID:	CAL000346874
Gen Status Universe:	No Report
Contact Name:	JAMES WALKER
Contact Address:	13085 HAMILTON CROSSING BLVD , , CARMEL , IN, 46032 ,
Contact Phone No and Ext:	317-843-4739
Contact Email:	JAMES.WALKER@KARAUCTIONSERVICES.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20090930
Location Latitude:	32.558039
Location Longitude:	-116.98837

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20090930
Handler Name:	ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	13085 HAMILTON CROSSING BLVD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	JAMES WALKER	**Street 2:**	
Date Became Current:		**City:**	CARMEL
Date Ended Current:		**State:**	IN
Phone:	317-843-4739	**Country:**	
Source Type:	Implementer	**Zip Code:**	46032
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	13085 HAMILTON CROSSING BLVD
Name:	ADESA CALIFORINA LLC	**Street 2:**	
Date Became Current:		**City:**	CARMEL
Date Ended Current:		**State:**	IN
Phone:	800-923-3725	**Country:**	
Source Type:	Implementer	**Zip Code:**	46032-0000

17	5 of 5	S	0.21 / 1,083.84	506.14 / -3	**DIRECT RECONDITIONING, LLC** **2175 CACTUS ROAD** **SAN DIEGO CA 92154**	**RCRA NON GEN**

EPA Handler ID:	CAL000429226
Gen Status Universe:	No Report
Contact Name:	BRIAN NUTTER
Contact Address:	2175 CACTUS ROAD , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext:	615-364-1396
Contact Email:	BNUTTER@DIRECTAUCTIONSERVICES.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20170717
Location Latitude:	32.558039
Location Longitude:	-116.98837

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20170717
Handler Name:	DIRECT RECONDITIONING, LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	2175 CACTUS ROAD
Name:	BRIAN NUTTER	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	615-364-1396	***Country:***	
Source Type:	Implementer	***Zip Code:***	92154
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	1041 KENDRA'S RUN
Name:	DAVID NUTTER	***Street 2:***	
Date Became Current:		***City:***	GALLATIN
Date Ended Current:		***State:***	TN
Phone:	665-594-3886	***Country:***	
Source Type:	Implementer	***Zip Code:***	37066

18	*1 of 7*	*NW*	*0.22 / 1,185.81*	*504.23 / -5*	***GLOBAL EXPORT TRANSPORT*** ***6935 CAMINO MAQUILADORA*** ***CA 0***	***HAZ SANDIEGO***

Record ID:	DEH2010-HUPFP-212997	***GIS Record ID:***	DEH2010-HUPFP-212997
Facility Name:		***GIS Facility City:***	
Facility City:		***GIS Facility ZipCode:***	0
Facility ZipCode:		***GIS Fac Latitude:***	32.5663932
Facility Latitude:		***GIS Fac Longitude:***	-116.991281
Facility Longitude:			
Facility Address:			
GIS Facility Name:	GLOBAL EXPORT TRANSPORT		
GIS Facility Address:	6935 CAMINO MAQUILADORA		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		***Status:***	
GIS CERS ID:		***ER Contact:***	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	***ER Con Work Ph:***	
Per Type:		***Census Tract:***	
Per Sub Type:		***Parcel Zip:***	
Per Cat:		***Community:***	
Record Status:	Completed	***Jurisdiction:***	
HW Tier:		***Basin No:***	
LRG QTY MW Gener:		***BOS Dist:***	
EPA ID No:		***Tbpg Grid:***	
RMP CAL ARP:		***Insp Dist:***	
Tank Owner:		***Feature ID:***	6461902300
SIC Code:		***X Coord:***	6333274.654
NAICS Code:		***Y Coord:***	1786690.736
Disclose Qty Haz Mat:		***Kiva Per Typ:***	HK07 212997
Exp Date:		***Agency Name:***	COSD
Own/Operate USTs :		***Point X:***	6333274.65386
UST Facility:		***Point Y:***	1786690.73599
Total No USTs:		***Lat GS84:***	32.5663932
No of Tanks:		***Lon GS84:***	-116.991281
Own Oper APS:		***Loc Name:***	
Tot APSA Cap:	0	***Score:***	
Capacity LR:		***Match Type:***	
Haz Waste G:		***Side:***	
Recycle100:		***X Map Coord:***	-116.99127766699759
Onsite Haz Waste Tre:		***Y Map Coord:***	32.5664443212312
RCRA LRG Qty:		***User Fld:***	
Haz Wst Coll Site:		***Addr Type:***	
Accept Offs:		***ARC Address:***	
Universal Waste Han:		***ARC City:***	
Toxic Gas:		***ARC Zipcode:***	
Hazmat EHS:		***ARC State:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:		Bill Code 3:	
Parcel No:	646-190-23-00	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	6935 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

18	2 of 7	NW	0.22 / 1,185.81	504.23 / -5	INALERT DISTRIBUTION OF CA 6935 CAMINO MAQUILADORA CA 0	HAZ SANDIEGO

Record ID:	DEH2010-HUPFP-213147	GIS Record ID:	DEH2010-HUPFP-213147
Facility Name:		GIS Facility City:	
Facility City:		GIS Facility ZipCode:	0
Facility ZipCode:		GIS Fac Latitude:	32.5663932
Facility Latitude:		GIS Fac Longitude:	-116.991281
Facility Longitude:			
Facility Address:			
GIS Facility Name:	INALERT DISTRIBUTION OF CA		
GIS Facility Address:	6935 CAMINO MAQUILADORA		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		Status:	
GIS CERS ID:		ER Contact:	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	ER Con Work Ph:	
Per Type:		Census Tract:	
Per Sub Type:		Parcel Zip:	
Per Cat:		Community:	
Record Status:	Completed	Jurisdiction:	
HW Tier:		Basin No:	
LRG QTY MW Gener:		BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	6461902300
SIC Code:		X Coord:	6333274.654
NAICS Code:		Y Coord:	1786690.736
Disclose Qty Haz Mat:		Kiva Per Typ:	HK07 213147
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6333274.65386
UST Facility:		Point Y:	1786690.73599
Total No USTs:		Lat GS84:	32.5663932
No of Tanks:		Lon GS84:	-116.991281
Own Oper APS:		Loc Name:	
Tot APSA Cap:	0	Score:	
Capacity LR:		Match Type:	
Haz Waste G:		Side:	
Recycle100:		X Map Coord:	-116.99127766699759
Onsite Haz Waste Tre:		Y Map Coord:	32.5664443212312
RCRA LRG Qty:		User Fld:	
Haz Wst Coll Site:		Addr Type:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-23-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6935 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	3 of 7	NW	0.22 / 1,185.81	504.23 / -5	PLANTRONICS INC 6935 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	HAZ SANDIEGO

Record ID:	DEH2006-HUPFP-206239	**GIS Record ID:**	DEH2006-HUPFP-206239
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	0
Facility Latitude:		**GIS Fac Longitude:**	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	PLANTRONICS INC		
GIS Facility Address:	6935 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:	10394395	**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Permit Suspended	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:	No	**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902300
SIC Code:		**X Coord:**	6333274.654
NAICS Code:		**Y Coord:**	1786690.736
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK18 206239
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333274.65386
UST Facility:		**Point Y:**	1786690.73599
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Haz Waste G:		Side:	
Recycle100:		X Map Coord:	-116.99127766699759
Onsite Haz Waste Tre:		Y Map Coord:	32.5664443212312
RCRA LRG Qty:		User Fld:	
Haz Wst Coll Site:		Addr Type:	
Accept Offs:		ARC Address:	
Universal Waste Han:		ARC City:	
Toxic Gas:		ARC Zipcode:	
Hazmat EHS:		ARC State:	
Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:		Bill Code 3:	
Parcel No:	646-190-23-00	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	6935 CAM MAQUILADORA		
Business Type:	Not Applicable		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

18	4 of 7	NW	0.22 / 1,185.81	504.23 / -5	PRO DESIGN FURNITURE 6935 CAMINO MAQUILADORA CA 0	HAZ SANDIEGO

Record ID:	DEH2011-HUPFP-213400	GIS Record ID:	DEH2011-HUPFP-213400
Facility Name:		GIS Facility City:	
Facility City:		GIS Facility ZipCode:	0
Facility ZipCode:		GIS Fac Latitude:	32.5663932
Facility Latitude:		GIS Fac Longitude:	-116.991281
Facility Longitude:			
Facility Address:			
GIS Facility Name:	PRO DESIGN FURNITURE		
GIS Facility Address:	6935 CAMINO MAQUILADORA		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		Status:	
GIS CERS ID:		ER Contact:	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	ER Con Work Ph:	
Per Type:		Census Tract:	
Per Sub Type:		Parcel Zip:	
Per Cat:		Community:	
Record Status:	Completed	Jurisdiction:	
HW Tier:		Basin No:	
LRG QTY MW Gener:		BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	6461902300
SIC Code:		X Coord:	6333274.654
NAICS Code:		Y Coord:	1786690.736
Disclose Qty Haz Mat:		Kiva Per Typ:	HK07 213400
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6333274.65386
UST Facility:		Point Y:	1786690.73599
Total No USTs:		Lat GS84:	32.5663932

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

No of Tanks:		**Lon GS84:**	-116.991281
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99127766699759
Onsite Haz Waste Tre:		**Y Map Coord:**	32.5664443212312
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-23-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6935 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

18	*5 of 7*	*NW*	*0.22 / 1,185.81*	*504.23 / -5*	***MENDEOLA TRANSAXLES INC.*** ***6935 CAMINO MAQUILADORA*** ***SUITE B*** ***SAN DIEGO CA 92154***	***RCRA NON GEN***

EPA Handler ID:	CAC003079987
Gen Status Universe:	No Report
Contact Name:	IAN KIRKLAND
Contact Address:	6935 CAMINO MAQUILADORA , SUITE B , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext:	619-947-6534
Contact Email:	IAN@MENDEOLATRANSAXLES.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20200819
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200819
Handler Name:	MENDEOLA TRANSAXLES INC.
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	6935 CAMINO MAQUILADORA
Name:	MIKE MENDEOLA	**Street 2:**	SUITE B
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-947-6534	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	6935 CAMINO MAQUILADORA
Name:	IAN KIRKLAND	**Street 2:**	SUITE B
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-947-6534	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	6 of 7	NW	0.22 / 1,185.81	504.23 / -5	MENDEOLA TRANSAXLES INC 6935 CAMINO MAQUILADORA SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID:	CAL000456162
Gen Status Universe:	No Report
Contact Name:	MARILYN MENDEOLA
Contact Address:	6935 CAMINO MAQUILADORA , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext:	619-947-6534
Contact Email:	MARILYN@MENDEOLATRANSAXLES.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20200811
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200811
Handler Name:	MENDEOLA TRANSAXLES INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	6935 CAMINO MAQUILADORA
Name:	MARILYN MENDEOLA	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-947-6534	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	432 STONERIDGE COURT
Name:	MENDEOLA TRANSAXLES INC	**Street 2:**	
Date Became Current:		**City:**	BONITA
Date Ended Current:		**State:**	CA
Phone:	619-947-6534	**Country:**	
Source Type:	Implementer	**Zip Code:**	91902

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	7 of 7	NW	0.22 / 1,185.81	504.23 / -5	MENDEOLA TRANSAXLES INC 6935 CAMINO MAQUILADORA SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID:	CAC003158330
Gen Status Universe:	No Report
Contact Name:	IAN KIRKLAND
Contact Address:	432 STONERIDGE COURT , , BONITA , CA, 91902 ,
Contact Phone No and Ext:	619-947-6534
Contact Email:	MARILYN@MENDEOLATRANSAXLES.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20220124
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20220124
Handler Name:	MENDEOLA TRANSAXLES INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	432 STONERIDGE COURT
Name:	IAN KIRKLAND	***Street 2:***	
Date Became Current:		***City:***	BONITA
Date Ended Current:		***State:***	CA
Phone:	619-947-6534	***Country:***	
Source Type:	Implementer	***Zip Code:***	91902

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	6935 CAMINO MAQUILADORA
Name:	MICHAEL MENDEOLA	***Street 2:***	SUITE B
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	619-947-6534	***Country:***	
Source Type:	Implementer	***Zip Code:***	92154

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	*1 of 7*	*NNW*	*0.23 / 1,204.75*	*511.89 / 3*	***1605 CACTUS, INC DBA: CALI-MART/ CHEVRON*** ***1605 CACTUS RD, SAN DIEGO, 92154*** ***CA***	***HAZ SANDIEGO***

Record ID:	DEH2002-HUPFP-102237	***GIS Record ID:***	
Facility Name:	1605 CACTUS, INC DBA: CALI-MART/ CHEVRON	***GIS Facility City:***	
Facility City:		***GIS Facility ZipCode:***	
Facility ZipCode:		***GIS Fac Latitude:***	
Facility Latitude:		***GIS Fac Longitude:***	
Facility Longitude:			
Facility Address:	1605 CACTUS RD, SAN DIEGO, 92154		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	2 of 7	NNW	0.23 / 1,204.75	511.89 / 3	Noil USA Inc. 1605 CACTUS RD SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2012-HUPFP-216147	**GIS Record ID:**	DEH2012-HUPFP-216147
Facility Name:	Noil USA Inc.	**GIS Facility City:**	SAN DIEGO
Facility City:	SAN DIEGO	**GIS Facility ZipCode:**	92154
Facility ZipCode:	92154	**GIS Fac Latitude:**	32.5676381
Facility Latitude:	32.567950006953666	**GIS Fac Longitude:**	-116.9877202
Facility Longitude:	-116.9882327478551		
Facility Address:	1605 CACTUS RD		
GIS Facility Name:	Noil USA Inc.		
GIS Facility Address:	1605 CACTUS RD, SAN DIEGO, CA 92154		
Tank Owner Name:			

Hazardous Materials Facility Data

CERS ID:	10395283	**Onsite H Waste Trtmt:**	false
Facility ID No:	37-000-216147	**Haz Mat on Site:**	true
EPA ID No:	CAL000418575	**Haz Waste Generator:**	true
Active Permit:	true	**Own/Oper Under:**	true
Permit Status:	Permit Renewed	**Own/Oper Above:**	false
Bus. Phone:	619-500-5601	**Recycle:**	false
Bus. Fax:	0	**RCRA Large Qty Gen:**	false
Last Updated:	04/14/2022 01:29:56 AM	**HHW Collection:**	false
New Georeferenced Column:	(32.567950006953666, -116.9882327478551)		
Mailing Address:	1605 CACTUS RD, SAN DIEGO, CA 92154		

Hazardous Waste and Materials

ID:	60152	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2016-HWAST-0088254	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	03/24/2018 02:33:44 AM	**Trade Secret:**	false
Chemical Name:	Waste Clean-up, Test Water		
Common Name Inventory:	Waste Clean-up, Test Water		

ID:	169632	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2018-HWAST-0161630	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	11/10/2018 12:40:08 AM	**Trade Secret:**	false
Chemical Name:	Waste Absorbent & Spent Dispenser Fuel Filters		
Common Name Inventory:	Waste Absorbent & Spent Dispenser Fuel Filters		

ID:	224897	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2019-HCHEM-0217836	**Active Permit:**	true
CAS No:	86290-81-5	**Haz Material Type:**	Pure
Last Updated:	02/25/2020 02:36:47 AM	**Trade Secret:**	false
Chemical Name:	Supreme Unleaded Gasoline		
Common Name Inventory:	Supreme Unleaded Gasoline		

ID:	391982	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2021-HWAST-0256682	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	02/25/2022 02:32:19 AM	**Trade Secret:**	false
Chemical Name:	Waste Absorbent & Spent Dispenser Fuel Filters		
Common Name Inventory:	Waste Absorbent & Spent Dispenser Fuel Filters		

ID:	487798	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2022-HWAST-0293922	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	04/14/2022 01:29:56 AM	**Trade Secret:**	false
Chemical Name:	Waste Clean-up, Test Water		
Common Name Inventory:	Waste Clean-up, Test Water		

ID:	60149	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2016-HCHEM-0107005	**Active Permit:**	true

CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 03/24/2018 02:33:44 AM **Trade Secret:** false
Chemical Name: Supreme Unleaded Gasoline
Common Name Inventory: Supreme Unleaded Gasoline

ID: 391981 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0288091 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 02/25/2022 02:32:19 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 169629 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186741 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 11/10/2018 12:40:07 AM **Trade Secret:** false
Chemical Name: Regular Unleaded Gasoline
Common Name Inventory: Regular Unleaded Gasoline

ID: 332302 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0240484 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 07/25/2020 01:01:02 AM **Trade Secret:** false
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name Inventory: Waste Absorbent & Spent Dispenser Fuel Filters

ID: 332301 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0270378 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 07/25/2020 01:01:02 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 224898 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0217837 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 02/25/2020 02:36:47 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 224899 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0187874 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2020 02:36:47 AM **Trade Secret:** false
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name Inventory: Waste Absorbent & Spent Dispenser Fuel Filters

ID: 169633 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0161631 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 11/10/2018 12:40:08 AM **Trade Secret:** false
Chemical Name: Waste Clean-up, Test Water
Common Name Inventory: Waste Clean-up, Test Water

ID: 391983 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0256683 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2022 02:32:19 AM **Trade Secret:** false
Chemical Name: Waste Clean-up, Test Water
Common Name Inventory: Waste Clean-up, Test Water

ID: 487795 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0327026 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 04/14/2022 01:29:56 AM **Trade Secret:** false
Chemical Name: Unleaded Gasoline
Common Name Inventory: Unleaded Gasoline

ID: 391980 **Permit Status:** Permit Renewed

Child Record ID: DEH2021-HCHEM-0288090 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 02/25/2022 02:32:19 AM **Trade Secret:** false
Chemical Name: Unleaded Gasoline
Common Name Inventory: Unleaded Gasoline

ID: 487796 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HCHEM-0327027 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 04/14/2022 01:29:56 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 60150 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0107006 **Active Permit:** true
CAS No: 68476-34-6 **Haz Material Type:** Pure
Last Updated: 03/24/2018 02:33:44 AM **Trade Secret:** false
Chemical Name: Diesel Fuel No. 2
Common Name Inventory: Diesel Fuel No. 2

ID: 224900 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0187875 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/25/2020 02:36:47 AM **Trade Secret:** false
Chemical Name: Waste Clean-up, Test Water
Common Name Inventory: Waste Clean-up, Test Water

ID: 60151 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HWAST-0088253 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/24/2018 02:33:44 AM **Trade Secret:** false
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name Inventory: Waste Absorbent & Spent Dispenser Fuel Filters

ID: 332300 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0270377 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 07/25/2020 01:01:02 AM **Trade Secret:** false
Chemical Name: Supreme Unleaded Gasoline
Common Name Inventory: Supreme Unleaded Gasoline

ID: 224896 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0217835 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 02/25/2020 02:36:47 AM **Trade Secret:** false
Chemical Name: Regular Unleaded Gasoline
Common Name Inventory: Regular Unleaded Gasoline

ID: 487797 **Permit Status:** Permit Renewed
Child Record ID: DEH2022-HWAST-0293921 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 04/14/2022 01:29:56 AM **Trade Secret:** false
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name Inventory: Waste Absorbent & Spent Dispenser Fuel Filters

ID: 332299 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HCHEM-0270376 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 07/25/2020 01:01:02 AM **Trade Secret:** false
Chemical Name: Regular Unleaded Gasoline
Common Name Inventory: Regular Unleaded Gasoline

ID: 169630 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HCHEM-0186742 **Active Permit:** true
CAS No: 86290-81-5 **Haz Material Type:** Pure
Last Updated: 11/10/2018 12:40:07 AM **Trade Secret:** false
Chemical Name: Supreme Unleaded Gasoline
Common Name Inventory: Supreme Unleaded Gasoline

ID:	169631	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2018-HCHEM-0186743	**Active Permit:**	true
CAS No:	68476-34-6	**Haz Material Type:**	Pure
Last Updated:	11/10/2018 12:40:07 AM	**Trade Secret:**	false
Chemical Name:	Diesel Fuel No. 2		
Common Name Inventory:	Diesel Fuel No. 2		

ID:	60148	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2016-HCHEM-0107004	**Active Permit:**	true
CAS No:	86290-81-5	**Haz Material Type:**	Pure
Last Updated:	03/24/2018 02:33:44 AM	**Trade Secret:**	false
Chemical Name:	Regular Unleaded Gasoline		
Common Name Inventory:	Regular Unleaded Gasoline		

ID:	332303	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2020-HWAST-0240485	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	07/25/2020 01:01:02 AM	**Trade Secret:**	false
Chemical Name:	Waste Clean-up, Test Water		
Common Name Inventory:	Waste Clean-up, Test Water		

Hazardous Materials Inspection Violations

Container Tank ID:		**Inspection No:**	6903785
Facility ID No:	37-000-216147	**Inspection Type:**	Routine
ID:	62010	**Inspection Date:**	04/13/2022 12:00:00 AM
UST ID:		**Compliance Date:**	
Permit Status:	Permit Renewed	**Last Updated:**	04/14/2022 01:29:56 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3030010 Failed to properly dispose of hazardous waste within 180 days (or 270 days if waste is transported over 200 miles). 22 CCR 66262.34(d); HSC 6.5 25123.3(h)(1)		

Container Tank ID:		**Inspection No:**	5874620
Facility ID No:	37-000-216147	**Inspection Type:**	Routine
ID:	34448	**Inspection Date:**	04/26/2018 12:00:00 AM
UST ID:		**Compliance Date:**	06/21/2018 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	04/14/2022 01:29:56 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)		

Container Tank ID:		**Inspection No:**	5409617
Facility ID No:	37-000-216147	**Inspection Type:**	Routine
ID:	34447	**Inspection Date:**	04/27/2016 12:05:00 PM
UST ID:		**Compliance Date:**	12/01/2017 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	04/14/2022 01:29:56 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class I		
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905		

Container Tank ID:		**Inspection No:**	5409617
Facility ID No:	37-000-216147	**Inspection Type:**	Routine
ID:	34446	**Inspection Date:**	04/27/2016 12:05:00 PM
UST ID:		**Compliance Date:**	04/27/2016 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	04/14/2022 01:29:56 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class I		
Violation Code:	1010001 HMBP not established/ implemented. HSC 25505(a) and 25507(a)		

Container Tank ID:		**Inspection No:**	5409617
Facility ID No:	37-000-216147	**Inspection Type:**	Routine
ID:	34439	**Inspection Date:**	04/27/2016 12:05:00 PM

UST ID:
Compliance Date: 04/26/2017 12:00:00 AM
Permit Status: Permit Renewed
Last Updated: 04/14/2022 01:29:56 AM
Active Permit: true
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3030010 Accumulated waste too long (>180 or 270 days) (>90 days for an acutely hazardous waste). (40 CFR 262.34(e) and (f).) HSC 25201(a); 22 CCR 66262.34(d)

Container Tank ID:
Inspection No: 4280322
Facility ID No: 37-000-216147
Inspection Type: Routine
ID: 34431
Inspection Date: 04/08/2013 12:00:00 AM
UST ID: 87
Compliance Date: 05/29/2014 12:00:00 AM
Permit Status: Permit Renewed
Last Updated: 04/14/2022 01:29:56 AM
Active Permit: true
NOV: false
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030025 Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).

Container Tank ID:
Inspection No: 4280322
Facility ID No: 37-000-216147
Inspection Type: Routine
ID: 34432
Inspection Date: 04/08/2013 12:00:00 AM
UST ID: 87
Compliance Date: 06/01/2013 12:00:00 AM
Permit Status: Permit Renewed
Last Updated: 04/14/2022 01:29:56 AM
Active Permit: true
NOV: false
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030036 Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 16 2635(b)(2), 2665.

Container Tank ID:
Inspection No: 6903785
Facility ID No: 37-000-216147
Inspection Type: Routine
ID: 62006
Inspection Date: 04/13/2022 12:00:00 AM
UST ID: 32548
Compliance Date:
Permit Status: Permit Renewed
Last Updated: 04/14/2022 01:29:56 AM
Active Permit: true
NOV: false
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030035 Failure to operate the UST system to prevent unauthorized releases including leaks, spills, and/or overfills. HSC 25292.1(a)

Container Tank ID:
Inspection No: 6903785
Facility ID No: 37-000-216147
Inspection Type: Routine
ID: 62007
Inspection Date: 04/13/2022 12:00:00 AM
UST ID: 16201
Compliance Date: 04/13/2022 12:00:00 AM
Permit Status: Permit Renewed
Last Updated: 04/14/2022 01:29:56 AM
Active Permit: true
NOV: false
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030025 (TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch within an hour and restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)

Container Tank ID:
Inspection No: 6903785
Facility ID No: 37-000-216147
Inspection Type: Routine
ID: 62005
Inspection Date: 04/13/2022 12:00:00 AM
UST ID:
Compliance Date:
Permit Status: Permit Renewed
Last Updated: 04/14/2022 01:29:56 AM
Active Permit: true
NOV:
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: HMD0000 UST PRESSURIZED PIPING (DW) REQUIREMENTS

Container Tank ID:
Facility ID No: 37-000-216147
ID: 34438
UST ID: 16204
Permit Status: Permit Renewed
Active Permit: true
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030025 (RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)

Inspection No: 5646866
Inspection Type: Routine
Inspection Date: 04/27/2017 09:11:00 PM
Compliance Date: 04/26/2018 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false

Container Tank ID:
Facility ID No: 37-000-216147
ID: 34430
UST ID: 8791
Permit Status: Permit Renewed
Active Permit: true
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030048 Failure to comply with one or more of the following: conduct secondary containment testing, within six months of installation and every 36 months thereafter, conducted in accordance with proper practices, protocols, or test methods. 23 CCR 16 2637

Inspection No: 4280322
Inspection Type: Routine
Inspection Date: 04/08/2013 12:00:00 AM
Compliance Date: 04/18/2014 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false

Container Tank ID:
Facility ID No: 37-000-216147
ID: 34436
UST ID: 16204
Permit Status: Permit Renewed
Active Permit: true
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030062 (RD) Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak. HSC 25299(a)(9)

Inspection No: 5646866
Inspection Type: Routine
Inspection Date: 04/27/2017 09:11:00 PM
Compliance Date: 04/27/2017 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: true

Container Tank ID:
Facility ID No: 37-000-216147
ID: 62008
UST ID: 16202
Permit Status: Permit Renewed
Active Permit: true
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Inspection No: 6903785
Inspection Type: Routine
Inspection Date: 04/13/2022 12:00:00 AM
Compliance Date: 04/13/2022 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false

Container Tank ID:
Facility ID No: 37-000-216147
ID: 45028
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3030010 Accumulated waste too long (>180 or 270 days) or (>90 days). HSC 25201(a), 25123.3(h)(1); 22 CCR 66262.34(d); 40 CFR 262.34(e) and/or (f)

Inspection No: 6135413
Inspection Type: Routine
Inspection Date: 04/23/2019 12:00:00 AM
Compliance Date: 05/20/2019 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false

Container Tank ID:
Facility ID No: 37-000-216147
ID: 34433
UST ID: 91
Permit Status: Permit Renewed
Active Permit: true

Inspection No: 5166669
Inspection Type: Routine
Inspection Date: 04/28/2015 12:00:00 AM
Compliance Date: 04/28/2015 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false

Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030026 Failure of line leak detector to detect a leak and/or failure of audible and visual alarm. 23 CCR 16 2636(f)(2), 2666.

Container Tank ID:
Facility ID No: 37-000-216147
ID: 45024
UST ID: 32548
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 6135413
Inspection Type: Routine
Inspection Date: 04/23/2019 12:00:00 AM
Compliance Date: 05/20/2019 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030013 (TCR 12) Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR, 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days. 23CCR 2716 (a-e)

Container Tank ID:
Facility ID No: 37-000-216147
ID: 34442
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5646866
Inspection Type: Routine
Inspection Date: 04/27/2017 09:11:00 PM
Compliance Date: 05/17/2019 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: true
Program Element: Hazardous Waste Generator
Violation Classification: Class I
Violation Code: HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. HSC 25404.1; SDCC 68.905

Container Tank ID:
Facility ID No: 37-000-216147
ID: 34445
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 5076286
Inspection Type: Routine
Inspection Date: 04/28/2014 02:20:00 PM
Compliance Date: 06/03/2014 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010001 Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; 19 CCR 4 2729.1 (a); HSC 6.95 25503.5(a).

Container Tank ID:
Facility ID No: 37-000-216147
ID: 45027
UST ID:
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 6135413
Inspection Type: Routine
Inspection Date: 04/23/2019 12:00:00 AM
Compliance Date: 05/20/2019 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3030017 Failed to properly close hazardous waste container(s). 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2), 265.173

Container Tank ID:
Facility ID No: 37-000-216147
ID: 45025
UST ID: 32548
Permit Status: Permit Renewed
Active Permit: true
Inspection No: 6135413
Inspection Type: Routine
Inspection Date: 04/23/2019 12:00:00 AM
Compliance Date: 05/14/2019 12:00:00 AM
Last Updated: 04/14/2022 01:29:56 AM
NOV: false
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2030036 (TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m

before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. 7. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. 8. Inspected within 30 days after a repair to the overfill prevention equipment. 9. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 10. Inspected by a certified UST service technician. 11. Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)

Container Tank ID: ***Inspection No:*** 5409617
Facility ID No: 37-000-216147 ***Inspection Type:*** Routine
ID: 34434 ***Inspection Date:*** 04/27/2016 12:05:00 PM
UST ID: 16202 ***Compliance Date:*** 04/27/2016 12:00:00 AM
Permit Status: Permit Renewed ***Last Updated:*** 04/14/2022 01:29:56 AM
Active Permit: true ***NOV:*** false
Program Element: Underground Storage Tank
Violation Classification: Class I
Violation Code: 2030025 (RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)

Container Tank ID: ***Inspection No:*** 5874620
Facility ID No: 37-000-216147 ***Inspection Type:*** Routine
ID: 34443 ***Inspection Date:*** 04/26/2018 12:00:00 AM
UST ID: ***Compliance Date:*** 04/23/2019 12:00:00 AM
Permit Status: Permit Renewed ***Last Updated:*** 04/14/2022 01:29:56 AM
Active Permit: true ***NOV:*** false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3010002 Failed to obtain &/or maintain an active EPA ID Number. 22 CCR 66262.12(a)

Container Tank ID: ***Inspection No:*** 6903785
Facility ID No: 37-000-216147 ***Inspection Type:*** Routine
ID: 62009 ***Inspection Date:*** 04/13/2022 12:00:00 AM
UST ID: ***Compliance Date:***
Permit Status: Permit Renewed ***Last Updated:*** 04/14/2022 01:29:56 AM
Active Permit: true ***NOV:***
Program Element: Hazardous Waste Generator
Violation Classification:
Violation Code: HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS ONLY

Container Tank ID: ***Inspection No:*** 6903785
Facility ID No: 37-000-216147 ***Inspection Type:*** Routine
ID: 62004 ***Inspection Date:*** 04/13/2022 12:00:00 AM
UST ID: ***Compliance Date:***
Permit Status: Permit Renewed ***Last Updated:*** 04/14/2022 01:29:56 AM
Active Permit: true ***NOV:***
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: HMD0000 UST TANK (DW/SW) - REQUIREMENT

Container Tank ID: ***Inspection No:*** 4280322
Facility ID No: 37-000-216147 ***Inspection Type:*** Routine
ID: 34444 ***Inspection Date:*** 04/08/2013 12:00:00 AM
UST ID: ***Compliance Date:*** 04/28/2014 12:00:00 AM
Permit Status: Permit Renewed ***Last Updated:*** 04/14/2022 01:29:56 AM
Active Permit: true ***NOV:*** false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010005 Failure to complete and/or submit an annotated site map if required by CUPA; 19 CCR 4 2729.2(a)(3).

Container Tank ID: ***Inspection No:*** 6135413
Facility ID No: 37-000-216147 ***Inspection Type:*** Routine
ID: 45023 ***Inspection Date:*** 04/23/2019 12:00:00 AM
UST ID: 32548 ***Compliance Date:*** 04/09/2020 12:00:00 AM
Permit Status: Permit Renewed ***Last Updated:*** 04/14/2022 01:29:56 AM

Active Permit: true **NOV:** false
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Container Tank ID: **Inspection No:** 5646866
Facility ID No: 37-000-216147 **Inspection Type:** Routine
ID: 34440 **Inspection Date:** 04/27/2017 09:11:00 PM
UST ID: **Compliance Date:**
Permit Status: Permit Renewed **Last Updated:** 04/14/2022 01:29:56 AM
Active Permit: true **NOV:**
Program Element: Hazardous Waste Generator
Violation Classification:
Violation Code: HMD0001 RECORD KEEPING/OPERATIONAL REQUIREMENTS

Container Tank ID: **Inspection No:** 6135413
Facility ID No: 37-000-216147 **Inspection Type:** Routine
ID: 45026 **Inspection Date:** 04/23/2019 12:00:00 AM
UST ID: **Compliance Date:** 05/20/2019 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 04/14/2022 01:29:56 AM
Active Permit: true **NOV:** false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3030007 Failed to properly label/date hazardous waste container &/or tank. 22 CCR 66262.34(f)

Container Tank ID: **Inspection No:** 5409617
Facility ID No: 37-000-216147 **Inspection Type:** Routine
ID: 34435 **Inspection Date:** 04/27/2016 12:05:00 PM
UST ID: 32548 **Compliance Date:** 04/27/2016 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 04/14/2022 01:29:56 AM
Active Permit: true **NOV:** false
Program Element: Underground Storage Tank
Violation Classification: Class II
Violation Code: 2030036 (RP) Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity; and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 2635(b)(2), 2665

Container Tank ID: **Inspection No:** 5646866
Facility ID No: 37-000-216147 **Inspection Type:** Routine
ID: 34441 **Inspection Date:** 04/27/2017 09:11:00 PM
UST ID: **Compliance Date:**
Permit Status: Permit Renewed **Last Updated:** 04/14/2022 01:29:56 AM
Active Permit: true **NOV:**
Program Element: Hazardous Waste Generator
Violation Classification:
Violation Code: HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS AND LQGS

Container Tank ID: **Inspection No:** 5646866
Facility ID No: 37-000-216147 **Inspection Type:** Routine
ID: 34437 **Inspection Date:** 04/27/2017 09:11:00 PM
UST ID: **Compliance Date:**
Permit Status: Permit Renewed **Last Updated:** 04/14/2022 01:29:56 AM
Active Permit: true **NOV:**
Program Element: Underground Storage Tank
Violation Classification:
Violation Code: 2010007 Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance. HSC 25292.2, 25299.30-25299.34; 23 CCR 2711; 2808.1, 2809-2809.2

HMD Permits Map Data

GIS Facility ID:	37-000-216147	***Status:***	
GIS CERS ID:	10395283	***ER Contact:***	213-688-5601
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	***ER Con Work Ph:***	619-500-5601
Per Type:		***Census Tract:***	100.15
Per Sub Type:		***Parcel Zip:***	92154
Per Cat:		***Community:***	San Diego
Record Status:	Permit Renewed	***Jurisdiction:***	SAN DIEGO
HW Tier:	Not Applicable	***Basin No:***	911.12
LRG QTY MW Gener:	No	***BOS Dist:***	1
EPA ID No:	CAL000418575	***Tbpg Grid:***	
RMP CAL ARP:	Not Applicable	***Insp Dist:***	HT204
Tank Owner:	8	***Feature ID:***	6462701100
SIC Code:	5541	***X Coord:***	6334373.354
NAICS Code:		***Y Coord:***	1787130.563
Disclose Qty Haz Mat:	Y	***Kiva Per Typ:***	HK07 216147
Exp Date:	3/30/2021	***Agency Name:***	COSD
Own/Operate USTs :		***Point X:***	6334373.35400002
UST Facility:	Motor Vehicle Fueling	***Point Y:***	1787130.56299999
Total No USTs:	5	***Lat GS84:***	32.5676381
No of Tanks:		***Lon GS84:***	-116.9877202
Own Oper APS:	N	***Loc Name:***	
Tot APSA Cap:	0	***Score:***	
Capacity LR:		***Match Type:***	
Haz Waste G:	Y	***Side:***	
Recycle100:	N	***X Map Coord:***	-116.9877219038061
Onsite Haz Waste Tre:	N	***Y Map Coord:***	32.56767452279591
RCRA LRG Qty:	N	***User Fld:***	
Haz Wst Coll Site:	N	***Addr Type:***	
Accept Offs:	N	***ARC Address:***	
Universal Waste Han:	N	***ARC City:***	
Toxic Gas:	No	***ARC Zipcode:***	
Hazmat EHS:	N	***ARC State:***	
Hazmat Rad:	No	***ARC APN:***	
Haz Waste Rad:	N	***Zip:***	
Haz Waste EHS:	N	***Farm Nursery:***	
Full Name:	Noil Holdings, LLC	***Indian or Territory:***	N
Email Perm:		***County ID:***	
Phone Perm:	213-688-5466	***Bill Code 2:***	Not Applicable
Site Address:	1605 Cactus Rd	***Bill Code 3:***	Not Applicable
Parcel No:	646-270-11-00	***Univ Waste Gen Type:***	

Record Ali:	Unified Program Facility Permit
Address:	1605 CACTUS RD
Business Type:	UST - Retail Site - No Repair Service
Bill Code:	Not Applicable
ER Con Name:	Levon Termendzhyan
ER Con Title:	President
Water Purv:	OTAY WATER IMP DIST C-SEWER
Fire Agency:	SAN DIEGO
Geo SRC:	Mapped to record APN/Parcel XY center
Match Addr:	
Hirt Flag:	Yes
Frhmbp Report Filename:	HMBP216147.pdf
Frhmbp Sitemap Filename:	MAP_216147.pdf

HMD Facility Data

ID:	6837	***Tank Status:***	Active
Record ID:	DEH2012-HUPFP-216147	***Tank Contents:***	Diesel
Facility ID No:	37-000-216147	***Tank Use:***	1a
Tank ID No:	32548	***Type of Tank:***	Double Wall
Permit Status:	Permit Renewed	***Piping System Type:***	Pressure
Active Permit:	true	***Last Updated:***	04/14/2022 01:29:56 AM
Tank Owner Name:	Noil USA Inc.		

Facility Type Ust Facility:	Motor Vehicle Fueling
Tank Capacity in Galons:	5000

Date Ust Permanently Closed:

HMD Facility Data

ID: 6834
Record ID: DEH2012-HUPFP-216147
Facility ID No: 37-000-216147
Tank ID No: 16202
Permit Status: Permit Renewed
Active Permit: true
Tank Owner Name: Noil USA Inc.
Facility Type Ust Facility: Motor Vehicle Fueling
Tank Capacity in Galons: 15000
Date Ust Permanently Closed:

Tank Status: Active
Tank Contents: Premium Unleaded
Tank Use: 1a
Type of Tank: Double Wall
Piping System Type: Pressure
Last Updated: 04/14/2022 01:29:56 AM

HMD Facility Data

ID: 6836
Record ID: DEH2012-HUPFP-216147
Facility ID No: 37-000-216147
Tank ID No: 16204
Permit Status: Permit Renewed
Active Permit: true
Tank Owner Name: Noil USA Inc.
Facility Type Ust Facility: Motor Vehicle Fueling
Tank Capacity in Galons: 15000
Date Ust Permanently Closed:

Tank Status: Active
Tank Contents: Diesel
Tank Use: 1a
Type of Tank: Double Wall
Piping System Type: Pressure
Last Updated: 04/14/2022 01:29:56 AM

HMD Facility Data

ID: 6833
Record ID: DEH2012-HUPFP-216147
Facility ID No: 37-000-216147
Tank ID No: 16201
Permit Status: Permit Renewed
Active Permit: true
Tank Owner Name: Noil USA Inc.
Facility Type Ust Facility: Motor Vehicle Fueling
Tank Capacity in Galons: 20000
Date Ust Permanently Closed:

Tank Status: Active
Tank Contents: Regular Unleaded
Tank Use: 1a
Type of Tank: Double Wall
Piping System Type: Pressure
Last Updated: 04/14/2022 01:29:56 AM

HMD Facility Data

ID: 6835
Record ID: DEH2012-HUPFP-216147
Facility ID No: 37-000-216147
Tank ID No: 16203
Permit Status: Permit Renewed
Active Permit: true
Tank Owner Name: Noil USA Inc.
Facility Type Ust Facility: Motor Vehicle Fueling
Tank Capacity in Galons: 20000
Date Ust Permanently Closed:

Tank Status: Active
Tank Contents: Diesel
Tank Use: 1a
Type of Tank: Double Wall
Piping System Type: Pressure
Last Updated: 04/14/2022 01:29:56 AM

---

19 | ***3 of 7*** | ***NNW*** | ***0.23 / 1,204.75*** | ***511.89 / 3*** | ***Noil USA Inc.*** ***1605 CACTUS RD*** ***SAN DIEGO CA 92154*** | ***UST*** ***SANDIEGO***

Facility ID: 37-000-216147
Record ID: DEH2012-HUPFP-216147
CERS ID: 10395283
EPA ID No: CAL000418575
Permit Status: Permit Renewed

RCRA Large Qty. Gen: false
HHW Collection: false
Recycle: false
Own or Operate UG: true
Own or Operate AG: false

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Active Permit:	true	**Business Phone:**	619-500-5601
Haz. Mat. On-Site:	true	**Business Fax:**	0
Haz. Waste Gen:	true	**Last Updated:**	2022 Apr 14 01:29:56 AM
Onsite Haz Wt Trt:	false		
Mailing Address:	1605 CACTUS RD, SAN DIEGO, CA 92154		

Tank Information

Tank ID:	32548	**Tank Capacity in Gal:**	5000
Tank Status:	Active	**Tank Contents:**	Diesel
Permit Status:	Permit Renewed	**Tank Use:**	1a
Active Permit:	true	**Piping Sys Type:**	Pressure
Dt UST Perm Closed:		**Fac Type (UST Fac):**	Motor Vehicle Fueling
Type of Tank:	Double Wall	**Last Updated:**	2022 Apr 14 01:29:56 AM
Tank Owner Name:	Noil USA Inc.		

Tank ID:	16202	**Tank Capacity in Gal:**	15000
Tank Status:	Active	**Tank Contents:**	Premium Unleaded
Permit Status:	Permit Renewed	**Tank Use:**	1a
Active Permit:	true	**Piping Sys Type:**	Pressure
Dt UST Perm Closed:		**Fac Type (UST Fac):**	Motor Vehicle Fueling
Type of Tank:	Double Wall	**Last Updated:**	2022 Apr 14 01:29:56 AM
Tank Owner Name:	Noil USA Inc.		

Tank ID:	16203	**Tank Capacity in Gal:**	20000
Tank Status:	Active	**Tank Contents:**	Diesel
Permit Status:	Permit Renewed	**Tank Use:**	1a
Active Permit:	true	**Piping Sys Type:**	Pressure
Dt UST Perm Closed:		**Fac Type (UST Fac):**	Motor Vehicle Fueling
Type of Tank:	Double Wall	**Last Updated:**	2022 Apr 14 01:29:56 AM
Tank Owner Name:	Noil USA Inc.		

Tank ID:	16201	**Tank Capacity in Gal:**	20000
Tank Status:	Active	**Tank Contents:**	Regular Unleaded
Permit Status:	Permit Renewed	**Tank Use:**	1a
Active Permit:	true	**Piping Sys Type:**	Pressure
Dt UST Perm Closed:		**Fac Type (UST Fac):**	Motor Vehicle Fueling
Type of Tank:	Double Wall	**Last Updated:**	2022 Apr 14 01:29:56 AM
Tank Owner Name:	Noil USA Inc.		

19	*4 of 7*	*NNW*	*0.23 / 1,204.75*	*511.89 / 3*	***Noil USA Inc.*** ***1605 Cactus Rd*** ***San Diego CA 92154***	***UST***

Facility ID:	37-000-216147	**Latitude:**	
CERS ID:	10395283	**Longitude:**	
County:	San Diego		
Permitting Agency:	San Diego County Department of Environmental Health		
Note:	Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.gov/search		
Site Facility Type:	PERMITTED UNDERGROUND STORAGE TANK (UST)		

19	*5 of 7*	*NNW*	*0.23 / 1,204.75*	*511.89 / 3*	***OTAY MESA MOBIL*** ***1605 CACTUS ROAD*** ***SAN DIEGO CA 92037***	***EMISSIONS***

2004 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2004 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2005 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2005 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2006 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2006 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	

Air Basin: SD
District: SD
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CERR Code:

2007 Criteria Data

Facility ID: 7954
Facility SIC Code: 5541
CO: 37
Air Basin: SD
District: SD
COID: SD
DISN: SAN DIEGO COUNTY APCD
CHAPIS:
CERR Code:
TOGT: 4.48
ROGT: 4.48
COT:
NOXT:
SOXT:
PMT:
PM10T:

2007 Toxic Data

Facility ID: 7954
Facility SIC Code: 5541
CO: 37
Air Basin: SD
District: SD
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SD
DISN: SAN DIEGO COUNTY APCD
CHAPIS:
CERR Code:

2008 Criteria Data

Facility ID: 7954
Facility SIC Code: 5541
CO: 37
Air Basin: SD
District: SD
COID: SD
DISN: SAN DIEGO COUNTY APCD
CHAPIS:
CERR Code:
TOGT: 4.48
ROGT: 4.48
COT:
NOXT:
SOXT:
PMT:
PM10T:

2008 Toxic Data

Facility ID: 7954
Facility SIC Code: 5541
CO: 37
Air Basin: SD
District: SD
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SD
DISN: SAN DIEGO COUNTY APCD
CHAPIS:
CERR Code:

2009 Criteria Data

Facility ID: 7954
Facility SIC Code: 5541
CO: 37
Air Basin: SD
District: SD
COID: SD
DISN: SAN DIEGO COUNTY APCD
CHAPIS:
CERR Code:
TOGT: 4.48
ROGT: 4.48
COT:
NOXT:
SOXT:
PMT:
PM10T:

2009 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2010 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2011 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2011 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2012 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2012 Toxic Data

Facility ID:	7954	***COID:***	SD

Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2013 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2013 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2014 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2014 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2015 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	

DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2015 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2016 Criteria Data

Facility ID:	7954	***CERR CODE:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2016 Toxic Data

Facility ID:	7954	***TS:***	
Facility SIC Code:	5541	***HRA:***	
CERR CODE:		***CH Index:***	
COID:	SD	***AH Index:***	
CO:	37	***Air Basin:***	SD
DISN:	SAN DIEGO COUNTY APCD	***District:***	SD
CHAPIS:			

2017 Criteria Data

Facility ID:	7954	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	4.48
CO:	37	***ROGT:***	4.48
Air Basin:	SD	***COT:***	
District:	SD	***NOXT:***	
COID:	SD	***SOXT:***	
DISN:	SAN DIEGO COUNTY APCD	***PMT:***	
CHAPIS:		***PM10T:***	

2017 Toxic Data

Facility ID:	7954	***COID:***	SD
Facility SIC Code:	5541	***DISN:***	SAN DIEGO COUNTY APCD
CO:	37	***CHAPIS:***	
Air Basin:	SD	***CERR Code:***	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	7954	***CERR Code:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility SIC Code:	5541	**TOGT:**	4.48
CO:	37	**ROGT:**	4.48
Air Basin:	SD	**COT:**	
District:	SD	**NOXT:**	
COID:	SD	**SOXT:**	
DISN:	SAN DIEGO COUNTY APCD	**PMT:**	
CHAPIS:		**PM10T:**	

2018 Toxic Data

Facility ID:	7954	**COID:**	SD
Facility SIC Code:	5541	**DISN:**	SAN DIEGO COUNTY APCD
CO:	37	**CHAPIS:**	
Air Basin:	SD	**CERR Code:**	
District:	SD		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	37	**CHAPIS:**	
Air Basin:	SD	**CERR Code:**	
Facility ID:	7954	**ROGT:**	4.48
District:	SD	**COT:**	
Facility SIC Code:	5541	**NOXT:**	
CO ID:	SD	**SOXT:**	
DISN:	SAN DIEGO COUNTY APCD		
PM10T:			
TOGT:	4.48		
PMT:			

2019 Toxic Data

CO:	37	**CHAPIS:**	
Air Basin:	SD	**CERR Code:**	
Faccility ID:	7954	**TS:**	
District:	SD	**Health Risk Asmt:**	
Facility SIC Code:	5541	**NonCncrChrnicHazInd :**	
COID:	SD	**NonCncrActeHazInd:**	
DISN:	SAN DIEGO COUNTY APCD		

19	6 of 7	NNW	0.23 / 1,204.75	511.89 / 3	**Noil USA Inc.** **1605 CACTUS RD** **SAN DIEGO CA 92154**	CERS TANK

Site ID:	6166	**Latitude:**	32.567638
Longitude:	-116.987717		

Regulated Programs

EI ID:	10395283
EI Description:	Underground Storage Tank
EI ID:	10395283
EI Description:	Hazardous Waste Generator
EI ID:	10395283
EI Description:	Chemical Storage Facilities

Violations

Violation Date: 04/27/2016 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Notes:

Returned to compliance on 04/27/2016. Inspection Sequence ID:5409617;Tank ID:16202;Violation Description:(RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)

Violation Description:

Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs.

Violations

Violation Date: 04/23/2019 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 04/27/2016 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507
Violation Notes:

Returned to compliance on 04/27/2016. Inspection Sequence ID:5409617

Violation Description:

Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 04/26/2018 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Notes:

Returned to compliance on 04/23/2019. Inspection Sequence ID:5874620

Violation Description:

Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.

Violations

Violation Date: 04/27/2016 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Notes:

Returned to compliance on 04/27/2016. Inspection Sequence ID:5409617;Tank ID:32548,16201,16202,16203,16204;Violation Description:(RP) Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity; and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 2635(b)(2), 2665

Violation Description:

Failure of the overfill prevention system to meet one of the following requirements:
1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or
2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or
3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or
4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.

Violations

Violation Date: 04/27/2017 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Notes:

Returned to compliance on 04/30/2017. Inspection Sequence ID:5646866;Tank ID:32548,16201,16202,16203,16204;Violation Description:Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance. HSC 25292.2, 25299.30-25299.34; 23 CCR 2711; 2808.1, 2809-2809.2

Violation Description:

Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.

Violations

Violation Date: 04/08/2013 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: 19 CCR 4 2729.2(a)(3) - California Code of Regulations, Title 19, Chapter 4, Section(s) 2729.2(a)(3)
Violation Notes:

Returned to compliance on 04/28/2014. Inspection Sequence ID:4280322

Violation Description:

Failure to complete and/or submit an annotated site map if required by CUPA.

Violations

Violation Date: 04/23/2019 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Notes:

Returned to compliance on 04/09/2020. Inspection Sequence ID:6135413;Tank ID:32548,16203,16204;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Violation Description:

"Failure to meet one or more of the following requirements:

Install or maintain a liquid-tight spill container.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill container.

Be resistant to galvanic corrosion.

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Tested by a certified UST service technician.

Maintain records of spill containment testing for 36 months.

"

Violations

Violation Date: 04/08/2013 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2637 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2637
Violation Notes:

Returned to compliance on 04/18/2014. Inspection Sequence ID:4280322;Tank ID:8791;Violation Description:Failure to comply with one or more of the following: conduct secondary containment testing, within six months of installation and every 36 months thereafter, conducted in accordance with proper practices, protocols, or test methods. 23 CCR 16 2637

Violation Description:

Failure to comply with one or more of the following: conduct secondary containment testing, within six months of installation and every 36 months thereafter, conducted in accordance with proper practices, protocols, or test methods.

Violations

Violation Date: 04/23/2019 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Notes:

Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413

Violation Description:

Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met:
(1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms.

(2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f).

(3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.

Violations

Violation Date: 04/23/2019 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Notes:

Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413

Violation Description:

Failure to meet the following container management requirements:

(a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste.
(b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.

Violations

Violation Date: 04/23/2019 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Notes:

Returned to compliance on 05/14/2019. Inspection Sequence ID:6135413;Tank ID:32548,16201,16202,16203,16204;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the o

Violation Description:

Failure to comply with one or more of the following overfill prevention equipment requirements:
Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or
Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or
Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or
Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.

Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018.

For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter.

For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter.

Inspected within 30 days after a repair to the overfill prevention equipment.

Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Inspected by a certified UST service technician.

Maintain records of overfill prevention equipment inspection for 36 months.

Violations

Violation Date: 04/08/2013 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Notes:

Returned to compliance on 06/01/2014. Inspection Sequence ID:4280322;Tank ID:87,91,03,03;Violation Description:Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).

Violation Description:

Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs.

Violations

Violation Date: 04/27/2016 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 12/01/2017. Inspection Sequence ID:5409617;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 04/27/2017 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.7 25299(a)(9) - California Health and Safety Code, Chapter 6.7, Section(s) 25299(a)(9)
Violation Notes:

Returned to compliance on 04/27/2017. Inspection Sequence ID:5646866;Tank ID:16204;Violation Description:(RD) Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak. HSC 25299(a)(9)

Violation Description:

Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak.

Violations

Violation Date: 04/27/2017 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Notes:

Returned to compliance on 04/26/2018. Inspection Sequence ID:5646866;Tank ID:16204;Violation Description:(RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)

Violation Description:

Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements:Monitor at least hourly.Be capable of detecting a release of 3.0 gallons per hour at 10 p.s.i.g.
Restrict or shut off the flow of product through the piping when a leak is detected.

Violations

Violation Date: 04/27/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 05/17/2019. Inspection Sequence ID:5646866;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. HSC 25404.1; SDCC 68.905

Violation Description:

Hazardous Waste Generator Program - Administration/Documentation - General

Violations

Violation Date: 04/26/2018 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 06/21/2018. Inspection Sequence ID:5874620

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 04/28/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Diego County Department of Env Health
Citation: HSC 6.95 25503.5(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25503.5(a)
Violation Notes:

Returned to compliance on 06/03/2014.

Violation Description:

Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Violations

Violation Date: 04/28/2015 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2666(c) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2666(c)
Violation Notes:

Returned to compliance on 04/28/2015.

Violation Description:

Failure of line leak detector to detect a leak and/or failure of audible and visual alarm.

Violations

Violation Date: 04/23/2019 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** San Diego County Department of Env Health
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Notes:

Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413;Tank ID:32548,16201,16202,16203,16204;Violation Description:(TCR 12) Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR, 2715(c). For designated

Violation Description:

For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements:
Be performed by an ICC certified DO.
Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy.
Inspect for the presence of liquid/debris in spill containers.
Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly.
Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit.
Check that all testing and maintenance has been completed and documented.
Verify that all facility employees have been trained in accordance with 23 CCR 2715(c).
For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.

Violations

Violation Date: 04/08/2013 **Violation Source:** CERS
Violation Program: UST **Violation Division:** San Diego County Department of Env Health
Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Notes:

Returned to compliance on 06/01/2013. Inspection Sequence ID:4280322;Tank ID:87 ,91,03,03;Violation Description:Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 16 2635(b)(2), 2665.

Violation Description:

Failure of the overfill prevention system to meet one of the following requirements:
1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or
2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or
3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or
4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.

Violations

Violation Date: 04/27/2016 **Violation Source:** CERS
Violation Program: HW **Violation Division:** San Diego County Department of Env Health
Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Notes:

Returned to compliance on 04/26/2017. Inspection Sequence ID:5409617

Violation Description:

Failure to dispose of hazardous waste within 180 days (or 270 if waste is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.

Evaluations

Eval Date: 04/08/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:4280322; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/26/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:5874620; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5409617; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/20/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

"No On-site Inspection" Inspector: Kiener Michael Inspection ID:6408429; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5646866; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:6611027; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/26/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:5874620; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5409617; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/28/2015

Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5166669; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/29/2013
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5168302; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5646866; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:6611027; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/29/2013
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5168302; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/08/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:4280322; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/23/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:6135413; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/28/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5166669; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/28/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5076286; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5409617; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5646866; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/27/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:6611027; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/26/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:5874620; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/28/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5166669; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/23/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:6135413; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/23/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Inspector: Kiener Michael Inspection ID:6135413; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/29/2013
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Inspector: Archer Veronica Inspection ID:5168302; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/28/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval Notes:

Inspector: Archer Veronica Inspection ID:5076286; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Identification Signer
Entity Name: Levon Termendzhyan
Entity Title: President
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Noil Holdings, LLC
Entity Title:
Address: 1605 CACTUS RD
City: SAN DIEGO
State: CA
Country: United States
Zip Code: 92154
Phone: (213) 688-5466

Affil Type Desc: Parent Corporation
Entity Name: Noil USA Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: UST Tank Owner
Entity Name: Noil Holdings, LLC
Entity Title:
Address: 4251 23rd St.
City: San Diego
State: CA
Country: United States
Zip Code: 92154
Phone: (213) 688-5466

Affil Type Desc: UST Tank Operator
Entity Name: Noil USA Inc.
Entity Title:
Address: 1605 Cactus Rd.
City: San Diego
State: CA
Country: United States
Zip Code: 92154
Phone: (213) 688-5466

Affil Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title:
Address: PO Box 129261
City: San Diego
State: CA
Country:
Zip Code: 92112-9261
Phone: (858) 505-6880

Affil Type Desc: Document Preparer

Entity Name:	Sam Stevenson
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	UST Property Owner Name
Entity Name:	Noil Holdings, LLC
Entity Title:	
Address:	1605 Cactus Rd.
City:	San Diego
State:	CA
Country:	United States
Zip Code:	92154
Phone:	(213) 688-5466

Affil Type Desc:	UST Permit Applicant
Entity Name:	Levon Termendezhyan
Entity Title:	President
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(213) 688-5466

Affil Type Desc:	Environmental Contact
Entity Name:	Levon Termendzhyan
Entity Title:	
Address:	1605 CACTUS RD
City:	SAN DIEGO
State:	CA
Country:	
Zip Code:	92154
Phone:	

Affil Type Desc:	Property Owner
Entity Name:	Noil Holdings, LLC
Entity Title:	
Address:	1605 CACTUS RD
City:	SAN DIEGO
State:	CA
Country:	United States
Zip Code:	92154
Phone:	(213) 688-5466

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	1605 CACTUS RD
City:	San Diego
State:	CA
Country:	
Zip Code:	92154
Phone:	

Affil Type Desc:	Operator
Entity Name:	Noil USA Inc.
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(213) 688-5601

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	7 of 7	NNW	0.23 / 1,204.75	511.89 / 3	NOIL USA INC 1605 CACTUS RD SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID: CAL000418575
Gen Status Universe: No Report
Contact Name: HAROLD HEKIMYAN
Contact Address: 1605 CACTUS RD , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext: 626-238-8787
Contact Email: JACK@NOILUSA.COM
Contact Country:
County Name: SAN DIEGO
EPA Region: 09
Land Type:
Receive Date: 20160630
Location Latitude: 32.567625
Location Longitude: -116.987508

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20160630
Handler Name: NOIL USA INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: LEVON TERMENDZHYAN
Date Became Current:
Date Ended Current:
Phone: 954-609-1442
Source Type: Implementer
Street No:
Street 1: 1605 CACTUS RD
Street 2:
City: SAN DIEGO
State: CA
Country:
Zip Code: 92154

Owner/Operator Ind: Current Operator
Type: Other
Name: HAROLD HEKIMYAN
Street No:
Street 1: 1605 CACTUS RD
Street 2:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	626-238-8787	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

20	1 of 7	NW	0.23 / 1,235.24	508.73 / 0	**M RIOS TRUCKING INC DBA** **MIGUEL RIOS ROSA** **6950 CAMINO MAQUILADORA** **STE C** **SAN DIEGO CA 92154**	**RCRA NON GEN**

EPA Handler ID:	CAR000217547
Gen Status Universe:	No Report
Contact Name:	MIGUEL RIOS ROSA
Contact Address:	6950 CAMINO MAQUILADORA , STE C , SAN DIEGO , CA, 92154 , US
Contact Phone No and Ext:	619-661-0271
Contact Email:	MRIOSTRUCKING@SBCGLOBAL.NET
Contact Country:	US
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	Private
Receive Date:	20131113
Location Latitude:	32.566894
Location Longitude:	-116.99005

Violation/Evaluation Summary

Note:	VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Apr, 2022.

Violation Details

Found Violation:	Yes
Citation:	
Violation Short Description:	State Statute or Regulation
Violation Type:	XXS
Violation Determined Date:	20190304
Scheduled Compliance Date:	
Return to Compliance:	Documented
Actual Return to Compl:	20190422
Violation Responsible Agency:	State

Enforcement Details

Enforcement Type:	120
Enforcement Type Description:	WRITTEN INFORMAL
Enforcement Action Date:	20190304
Enf Disposition Status:	
Disposition Status Date:	
Enforcement Lead Agency:	State
Proposed Penalty Amount:	
Final Amount:	
Paid Amount:	

Enforcement Type:	125
Enforcement Type Description:	
Enforcement Action Date:	20190405
Enf Disposition Status:	
Disposition Status Date:	
Enforcement Lead Agency:	State
Proposed Penalty Amount:	
Final Amount:	
Paid Amount:	

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Transporters - General
Violation Type: 263.A
Violation Determined Date: 20131018
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20131023
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 125
Enforcement Type Description:
Enforcement Action Date: 20131216
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20131018
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Transporters - Manifest System and Recordkeeping
Violation Type: 263.B
Violation Determined Date: 20190304
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20190422
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 125
Enforcement Type Description:
Enforcement Action Date: 20190405
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20190304
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:

Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: State Statute or Regulation
Violation Type: XXS
Violation Determined Date: 20131018
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20131023
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 125
Enforcement Type Description:
Enforcement Action Date: 20131216
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20131018
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Transporters - Manifest System and Recordkeeping
Violation Type: 263.B
Violation Determined Date: 20131018
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20131023
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20131018
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Enforcement Type: 125
Enforcement Type Description:
Enforcement Action Date: 20131216

Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20190304
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: State Statute or Regulation
Return to Compliance Date: 20190422
Evaluation Agency: State

Evaluation Start Date: 20131018
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: State Statute or Regulation
Return to Compliance Date: 20131023
Evaluation Agency: State

Evaluation Start Date: 20190304
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Transporters - Manifest System and Recordkeeping
Return to Compliance Date: 20190422
Evaluation Agency: State

Evaluation Start Date: 20131018
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Transporters - Manifest System and Recordkeeping
Return to Compliance Date: 20131023
Evaluation Agency: State

Evaluation Start Date: 20131018
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Transporters - General
Return to Compliance Date: 20131023
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: Yes
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20110411
Handler Name: M RIOS TRUCKING DBA MIGUEL RIOS ROSA
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: 132
Waste Code Description: Aqueous solution w/metals (< restricted levels and see waste code 121 for a list of metals)

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20131113
Handler Name: M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: 132
Waste Code Description: Aqueous solution w/metals (< restricted levels and see waste code 121 for a list of metals)

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: MIGUEL RIOS
Date Became Current: 20030801
Date Ended Current:
Phone: 619-661-0271
Source Type: Notification
Street No:
Street 1: 6950 CAMINO MAQUILADORA
Street 2: STE C
City: SAN DIEGO
State: CA
Country: US
Zip Code: 92154

Owner/Operator Ind: Current Operator
Type: Private
Name: MIGUEL RIOS
Date Became Current: 20030801
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: MIGUEL RIOS
Date Became Current: 20030801
Date Ended Current:
Phone: 619-661-0271
Source Type: Notification
Street No:
Street 1: 6950 CAMINO MAQUILADORAS
Street 2: STE C
City: SAN DIEGO
State: CA
Country: US
Zip Code: 92154

Historical Handler Details

Receive Dt: 20110411
Generator Code Description: Not a Generator, Verified
Handler Name: M RIOS TRUCKING DBA MIGUEL RIOS ROSA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	2 of 7	NW	0.23 / 1,235.24	508.73 / 0	M.RIOS TRUCKING 6950 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2011-HUPFP-213382	**GIS Record ID:**	DEH2011-HUPFP-213382
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5674512
Facility Latitude:		**GIS Fac Longitude:**	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	M.RIOS TRUCKING		
GIS Facility Address:	6950 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902707
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 213382
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90813
UST Facility:		**Point Y:**	1787076.88613
Total No USTs:		**Lat GS84:**	32.5674512
No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-07	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6950 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Geo SRC:		Mapped to record APN/parcel center XY				
Match Addr:						
Hirt Flag:						
Frhmbp Report Filename:						
Frhmbp Sitemap Filename:						
20	3 of 7	NW	0.23 / 1,235.24	508.73 / 0	PRECISION EQUIPMENT 6950 CAMINO MAQUILADORA #C, SAN DIEGO, 92173- CA	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-132832	GIS Record ID:	
Facility Name:	PRECISION EQUIPMENT	GIS Facility City:	
Facility City:		GIS Facility ZipCode:	
Facility ZipCode:		GIS Fac Latitude:	
Facility Latitude:		GIS Fac Longitude:	
Facility Longitude:			
Facility Address:	6950 CAMINO MAQUILADORA #C, SAN DIEGO, 92173-		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	4 of 7	NW	0.23 / 1,235.24	508.73 / 0	M RIOS TRUCKING, INC 6950 CAMINO MAQUILADORA, SAN YSIDRO CA 92173 CA	HAZ SANDIEGO

Record ID:	DEH2007-HUPFP-208623	GIS Record ID:	
Facility Name:	M RIOS TRUCKING, INC	GIS Facility City:	
Facility City:		GIS Facility ZipCode:	
Facility ZipCode:		GIS Fac Latitude:	
Facility Latitude:		GIS Fac Longitude:	
Facility Longitude:			
Facility Address:	6950 CAMINO MAQUILADORA, SAN YSIDRO CA 92173		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	5 of 7	NW	0.23 / 1,235.24	508.73 / 0	AERODESIGN PRODUCTS, INC 6950 CAMINO MAQUILADORA, SUITE# D-E, SAN DIEGO, CA 92154 SAN DIEGO CA 0	HAZ SANDIEGO

Record ID:	DEH2006-HUPFP-206287	GIS Record ID:	DEH2006-HUPFP-206287
Facility Name:		GIS Facility City:	SAN DIEGO
Facility City:		GIS Facility ZipCode:	0
Facility ZipCode:		GIS Fac Latitude:	0
Facility Latitude:		GIS Fac Longitude:	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	AERODESIGN PRODUCTS, INC		
GIS Facility Address:	6950 CAMINO MAQUILADORA, SUITE# D-E, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		Status:	
GIS CERS ID:	10394410	ER Contact:	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	ER Con Work Ph:	
Per Type:		Census Tract:	
Per Sub Type:		Parcel Zip:	
Per Cat:		Community:	
Record Status:	Permit Suspended	Jurisdiction:	
HW Tier:		Basin No:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

LRG QTY MW Gener:	No	BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	0
SIC Code:		X Coord:	0
NAICS Code:		Y Coord:	0
Disclose Qty Haz Mat:		Kiva Per Typ:	HK18 206287
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6333598.29889
UST Facility:		Point Y:	1786851.49748
Total No USTs:		Lat GS84:	0
No of Tanks:		Lon GS84:	0
Own Oper APS:		Loc Name:	
Tot APSA Cap:	0	Score:	
Capacity LR:		Match Type:	
Haz Waste G:	N	Side:	
Recycle100:		X Map Coord:	-116.99023097217436
Onsite Haz Waste Tre:	N	Y Map Coord:	32.566892464591156
RCRA LRG Qty:	N	User Fld:	
Haz Wst Coll Site:		Addr Type:	
Accept Offs:		ARC Address:	
Universal Waste Han:		ARC City:	
Toxic Gas:		ARC Zipcode:	
Hazmat EHS:		ARC State:	
Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:	6754 Calle De Linea Ste 111	Bill Code 3:	
Parcel No:	646-190-27-20	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	6950 CAMINO MAQUILADORA, SUITE# D-E		
Business Type:	Not Applicable		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record address		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

20	6 of 7	NW	0.23 / 1,235.24	508.73 / 0	AP MOTORSPORTS 6950 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 0	HAZ SANDIEGO

Record ID:	DEH2006-HUPFP-206288	GIS Record ID:	DEH2006-HUPFP-206288
Facility Name:		GIS Facility City:	SAN DIEGO
Facility City:		GIS Facility ZipCode:	0
Facility ZipCode:		GIS Fac Latitude:	0
Facility Latitude:		GIS Fac Longitude:	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	AP MOTORSPORTS		
GIS Facility Address:	6950 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		Status:	
GIS CERS ID:		ER Contact:	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	ER Con Work Ph:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tler:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	0
SIC Code:		**X Coord:**	0
NAICS Code:		**Y Coord:**	0
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 206288
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333598.29889
UST Facility:		**Point Y:**	1786851.49748
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.99023097217436
Onsite Haz Waste Tre:		**Y Map Coord:**	32.566892464591156
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-20	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6950 CAM MAQUILADORA		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record address		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

20	7 of 7	NW	0.23 / 1,235.24	508.73 / 0	**NAHUM LLC** **6950 CAMINO MAQUILADORA** **SUITE B** **SAN DIEGO CA 92154**	**RCRA NON GEN**

EPA Handler ID:	CAC002988639
Gen Status Universe:	No Report
Contact Name:	JOY LANHAM
Contact Address:	3636 4 AVE. , SUITE 300 , SAN DIEGO , CA, 92103 ,
Contact Phone No and Ext:	619-295-8376
Contact Email:	JLANHAM@IHAPARTNERS.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20181109
Location Latitude:	32.566894

Location Longitude: -116.99005

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20181109
Handler Name:	NAHUM LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	3636 4 AVE.
Name:	NAHUM LLC	**Street 2:**	SUITE 300
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-295-8376	**Country:**	
Source Type:	Implementer	**Zip Code:**	92103

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	3636 4 AVE.
Name:	JOY LANHAM	**Street 2:**	SUITE 300
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-295-8376	**Country:**	
Source Type:	Implementer	**Zip Code:**	92103

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	1 of 2	SSW	0.24 / 1,280.79	508.05 / -1	F & S TOWING 2230 CACTUS RD, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2009-HUPFP-211526	**GIS Record ID:**	DEH2009-HUPFP-211526
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5574452
Facility Latitude:		**GIS Fac Longitude:**	-116.9887606
Facility Longitude:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Address:
GIS Facility Name: F & S TOWING
GIS Facility Address: 2230 CACTUS RD, SAN DIEGO, CA 92154
Tank Owner Name:

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461003700
SIC Code:		**X Coord:**	6334015.698
NAICS Code:		**Y Coord:**	1783410.301
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 211526
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6334015.69799
UST Facility:		**Point Y:**	1783410.30095
Total No USTs:		**Lat GS84:**	32.5574452
No of Tanks:		**Lon GS84:**	-116.9887606
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.98879714594024
Onsite Haz Waste Tre:		**Y Map Coord:**	32.55744309550072
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-100-37-00	**Univ Waste Gen Type:**	

Record Ali: Unified Program Facility Permit
Address: 2230 CACTUS RD
Business Type: Machine Shops/Metal Working Activities
Bill Code:
ER Con Name:
ER Con Title:
Water Purv:
Fire Agency:
Geo SRC: Mapped to record APN/parcel center XY
Match Addr:
Hirt Flag:
Frhmbp Report Filename:
Frhmbp Sitemap Filename:

21	2 of 2	SSW	0.24 / 1,280.79	508.05 / -1	**LUMINA I** **2230 CACTUS ROAD** **SAN DIEGO CA 92154**	RCRA SQG

EPA Handler ID: CAP000318428
Gen Status Universe: Small Quantity Generator

Contact Name:	JASON SHEPARD
Contact Address:	444 , WEST BEECH STREET , , SAN DIEGO , CA, 92101 , US
Contact Phone No and Ext:	858-490-2326
Contact Email:	JSHEPARD@COLRICH.COM
Contact Country:	US
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	Private
Receive Date:	20210127
Location Latitude:	32.560688
Location Longitude:	-116.990748

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20210127
Handler Name:	LUMINA I
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code:	223
Waste Code Description:	Unspecified oil-containing waste
Hazardous Waste Code:	221
Waste Code Description:	Waste oil and mixed oil
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	352
Waste Code Description:	Other organic solids
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	331
Waste Code Description:	Off-specification, aged, or surplus organics

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	444 WEST BEECH STREET, STE. 300
Name:	CR LUMINA GROUP, LLC	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	92101

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	444 WEST BEECH STREET, STE. 300
Name:	CR LUMINA GROUP, LLC, C/O COLRICH	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	92101

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	1 of 14	NW	0.25 / 1,293.96	510.06 / 1	***OTAY MESA TENT ONLY 6960 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154***	***HAZ SANDIEGO***

Record ID:	DEH2011-HUPFP-213419	***GIS Record ID:***	DEH2011-HUPFP-213419
Facility Name:		***GIS Facility City:***	SAN DIEGO
Facility City:		***GIS Facility ZipCode:***	92154
Facility ZipCode:		***GIS Fac Latitude:***	32.5674512
Facility Latitude:		***GIS Fac Longitude:***	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	OTAY MESA TENT ONLY		
GIS Facility Address:	6960 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		***Status:***	
GIS CERS ID:		***ER Contact:***	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	***ER Con Work Ph:***	
Per Type:		***Census Tract:***	
Per Sub Type:		***Parcel Zip:***	
Per Cat:		***Community:***	
Record Status:	Completed	***Jurisdiction:***	
HW Tier:		***Basin No:***	
LRG QTY MW Gener:		***BOS Dist:***	
EPA ID No:		***Tbpg Grid:***	
RMP CAL ARP:		***Insp Dist:***	
Tank Owner:		***Feature ID:***	6461902713
SIC Code:		***X Coord:***	6333602.908
NAICS Code:		***Y Coord:***	1787076.886
Disclose Qty Haz Mat:		***Kiva Per Typ:***	HK07 213419
Exp Date:		***Agency Name:***	COSD
Own/Operate USTs :		***Point X:***	6333602.90813
UST Facility:		***Point Y:***	1787076.88613
Total No USTs:		***Lat GS84:***	32.5674512
No of Tanks:		***Lon GS84:***	-116.9902239
Own Oper APS:		***Loc Name:***	
Tot APSA Cap:	0	***Score:***	
Capacity LR:		***Match Type:***	
Haz Waste G:		***Side:***	
Recycle100:		***X Map Coord:***	-116.99022120601873
Onsite Haz Waste Tre:		***Y Map Coord:***	32.56751199463001
RCRA LRG Qty:		***User Fld:***	
Haz Wst Coll Site:		***Addr Type:***	
Accept Offs:		***ARC Address:***	
Universal Waste Han:		***ARC City:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-13	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAM MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

22	2 of 14	NW	0.25 / 1,293.96	510.06 / 1	**SANCHEZ TRUCK REPAIR** **6960 CAMINO MAQUILADORA** **CA 0**	**HAZ SANDIEGO**

Record ID:	DEH2002-HUPFP-132775	**GIS Record ID:**	DEH2002-HUPFP-132775
Facility Name:		**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	32.5674512
Facility Latitude:		**GIS Fac Longitude:**	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	SANCHEZ TRUCK REPAIR		
GIS Facility Address:	6960 CAMINO MAQUILADORA		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902709
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 132775
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90813
UST Facility:		**Point Y:**	1787076.88613
Total No USTs:		**Lat GS84:**	32.5674512
No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56751199463001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-09	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

22	3 of 14	NW	0.25 / 1,293.96	510.06 / 1	**baja auto parts #2** **6960 CAMINO MAQUILADORA E** **SAN DIEGO CA 92154**	**HAZ SANDIEGO**

Record ID:	DEH2014-HUPFP-000515	**GIS Record ID:**	DEH2014-HUPFP-000515
Facility Name:	baja auto parts #2	**GIS Facility City:**	SAN DIEGO
Facility City:	SAN DIEGO	**GIS Facility ZipCode:**	92154
Facility ZipCode:	92154	**GIS Fac Latitude:**	32.5674512
Facility Latitude:	32.566914511519066	**GIS Fac Longitude:**	-116.9902239
Facility Longitude:	-116.98921357772875		
Facility Address:	6960 CAMINO MAQUILADORA E		
GIS Facility Name:	baja auto parts #2		
GIS Facility Address:	6960 CAMINO MAQUILADORA, SUITE# E, SAN DIEGO, CA 92154		
Tank Owner Name:			

Hazardous Materials Facility Data

CERS ID:	10449733	**Onsite H Waste Trtmt:**	false
Facility ID No:	37-000-000515	**Haz Mat on Site:**	true
EPA ID No:	CAL000403322	**Haz Waste Generator:**	true
Active Permit:	true	**Own/Oper Under:**	false
Permit Status:	Permit Renewed	**Own/Oper Above:**	false
Bus. Phone:	6197100777	**Recycle:**	false
Bus. Fax:	0	**RCRA Large Qty Gen:**	false
Last Updated:	03/31/2022 02:31:37 AM	**HHW Collection:**	false
New Georeferenced Column:	(32.566914511519066, -116.98921357772875)		
Mailing Address:	6960 camino maquiladora #e, san diego, CA 92154		

Hazardous Waste and Materials

ID:	431107	**Permit Status:**	Permit Renewed
Child Record ID:	DEH2021-HWAST-0270828	**Active Permit:**	true
CAS No:		**Haz Material Type:**	
Last Updated:	03/31/2022 02:31:37 AM	**Trade Secret:**	false
Chemical Name:	paper filters/absorbent		
Common Name Inventory:	paper filters/absorbent		

ID:	302066	**Permit Status:**	Permit Renewed

Child Record ID: DEH2020-HWAST-0227932 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/03/2021 02:41:12 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: Ethylene Glycol

ID: 63878 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HWAST-0102292 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/21/2018 02:32:45 AM **Trade Secret:** false
Chemical Name: Lubricating oils, used
Common Name Inventory: Used lubricating oils

ID: 189318 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0171038 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/27/2018 12:37:12 AM **Trade Secret:** false
Chemical Name: Lubricating oils, used
Common Name Inventory: Used lubricating oils

ID: 431106 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0270827 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/31/2022 02:31:37 AM **Trade Secret:** false
Chemical Name: Lubricating oils, used
Common Name Inventory: Used lubricating oils

ID: 302067 **Permit Status:** Permit Renewed
Child Record ID: DEH2020-HWAST-0227933 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/03/2021 02:41:12 AM **Trade Secret:** false
Chemical Name: Lubricating oils, used
Common Name Inventory: Used lubricating oils

ID: 189317 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0171037 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/27/2018 12:37:12 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: Ethylene Glycol

ID: 63875 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HWAST-0102289 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/21/2018 02:32:45 AM **Trade Secret:** false
Chemical Name: SANDBLAST WASTE
Common Name Inventory: SANDBLAST WASTE

ID: 415826 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0262175 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 06/11/2021 01:56:04 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: Ethylene Glycol

ID: 415827 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0262176 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 06/11/2021 01:56:04 AM **Trade Secret:** false
Chemical Name: Lubricating oils, used
Common Name Inventory: Used lubricating oils

ID: 215452 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0181577 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/17/2020 05:00:45 PM **Trade Secret:** false
Chemical Name: Lubricating oils, used
Common Name Inventory: Used lubricating oils

ID: 63876 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HWAST-0102290 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/21/2018 02:32:45 AM **Trade Secret:** false
Chemical Name: Waste Petroleum Spirits
Common Name Inventory: Waste Petroleum Spirits

ID: 189316 **Permit Status:** Permit Renewed
Child Record ID: DEH2018-HWAST-0171036 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 10/27/2018 12:37:12 AM **Trade Secret:** false
Chemical Name: SANDBLAST WASTE
Common Name Inventory: SANDBLAST WASTE

ID: 63877 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HWAST-0102291 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/21/2018 02:32:45 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: Ethylene Glycol

ID: 215451 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HWAST-0181576 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/17/2020 05:00:45 PM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: Ethylene Glycol

ID: 63874 **Permit Status:** Permit Renewed
Child Record ID: DEH2016-HCHEM-0122298 **Active Permit:** true
CAS No: 64475-85-0 **Haz Material Type:** Pure
Last Updated: 03/21/2018 02:32:45 AM **Trade Secret:** false
Chemical Name: Petroleum spirits
Common Name Inventory: Petroleum spirits

ID: 431105 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HWAST-0270826 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 03/31/2022 02:31:37 AM **Trade Secret:** false
Chemical Name: Ethylene Glycol
Common Name Inventory: Ethylene Glycol

Hazardous Materials Inspection Violations

Container Tank ID: **Inspection No:** 5176180
Facility ID No: 37-000-000515 **Inspection Type:** Routine
ID: 37422 **Inspection Date:** 12/11/2014 03:16:00 PM
UST ID: **Compliance Date:** 12/11/2014 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/31/2022 12:00:00 AM
Active Permit: true **NOV:** false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010008 Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date. For facilities with invenntory that exceed EPCRA thresholds; failure to submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages HSC 6.95 25508.2 / 19 CCR 4 2729.5(c)

Container Tank ID: **Inspection No:** 5176180
Facility ID No: 37-000-000515 **Inspection Type:** Routine
ID: 37419 **Inspection Date:** 12/11/2014 03:16:00 PM
UST ID: **Compliance Date:** 12/11/2014 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 03/31/2022 12:00:00 AM
Active Permit: true **NOV:** false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010005 Failure to complete and/or submit an annotated site map if required by CUPA; HSC 6.95 25505(a)2.

Container Tank ID: **Inspection No:** 6060102
Facility ID No: 37-000-000515 **Inspection Type:** Routine

ID:	43398	**Inspection Date:**	01/14/2019 12:00:00 AM
UST ID:		**Compliance Date:**	02/04/2019 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/31/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Minor		
Violation Code:	1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)		

Container Tank ID:		**Inspection No:**	5176180
Facility ID No:	37-000-000515	**Inspection Type:**	Routine
ID:	37417	**Inspection Date:**	12/11/2014 03:16:00 PM
UST ID:		**Compliance Date:**	05/01/2015 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/31/2022 12:00:00 AM
Active Permit:	true	**NOV:**	true
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class I		
Violation Code:	HMD0131 No Unified Program Facility (UPF) permit not obtained for the generation of hazardous waste. SDCC 68.905.		

Container Tank ID:		**Inspection No:**	6601006
Facility ID No:	37-000-000515	**Inspection Type:**	Routine
ID:	54866	**Inspection Date:**	05/25/2021 12:00:00 AM
UST ID:		**Compliance Date:**	06/07/2021 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/31/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3030010 Accumulated waste too long (>180 or 270 days) or (>90 days). HSC 25201(a), 25123.3(h)(1); 22 CCR 66262.34 (b), 66262.34(d); 40 CFR 262.34(e) and/or (f)		

Container Tank ID:		**Inspection No:**	5176180
Facility ID No:	37-000-000515	**Inspection Type:**	Routine
ID:	37418	**Inspection Date:**	12/11/2014 03:16:00 PM
UST ID:		**Compliance Date:**	02/18/2015 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/31/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	3030010 Failure to dispose of hazardous waste within 180 days (or 270 if waste is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.; 22 CCR 12 66262.34(d).		

Container Tank ID:		**Inspection No:**	5176180
Facility ID No:	37-000-000515	**Inspection Type:**	Routine
ID:	37421	**Inspection Date:**	12/11/2014 03:16:00 PM
UST ID:		**Compliance Date:**	12/11/2014 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/31/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010002 Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; HSC 6.95 25508(a) 1A		

Container Tank ID:		**Inspection No:**	5176180
Facility ID No:	37-000-000515	**Inspection Type:**	Routine
ID:	37416	**Inspection Date:**	12/11/2014 03:16:00 PM
UST ID:		**Compliance Date:**	12/26/2014 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/31/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Minor		
Violation Code:	3010002 Failure to obtain and/or maintain an Active EPA ID.; 22 CCR 12 66262.12.		

Container Tank ID:		**Inspection No:**	5176180
Facility ID No:	37-000-000515	**Inspection Type:**	Routine
ID:	37420	**Inspection Date:**	12/11/2014 03:16:00 PM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

UST ID:		**Compliance Date:**	05/01/2015 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	03/31/2022 12:00:00 AM
Active Permit:	true	**NOV:**	true
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class I		
Violation Code:	HMD1001 Unified Program Facility (UPF) permit was not obtained for the handling of hazardous materials; SDCC 68.905.		

HMD Permits Map Data

GIS Facility ID:	37-000-000515	**Status:**	
GIS CERS ID:	10449733	**ER Contact:**	6197100777
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	6197100777
Per Type:		**Census Tract:**	100.15
Per Sub Type:		**Parcel Zip:**	92154
Per Cat:		**Community:**	San Diego
Record Status:	Permit Renewed	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAL000403322	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HS015
Tank Owner:		**Feature ID:**	6461902716
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	
Exp Date:	3/30/2021	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90799999
UST Facility:		**Point Y:**	1787076.88600001
Total No USTs:		**Lat GS84:**	32.5674512
No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Y	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:	N	**ARC Address:**	
Universal Waste Han:	N	**ARC City:**	
Toxic Gas:	No	**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:	N	**Zip:**	
Haz Waste EHS:	N	**Farm Nursery:**	
Full Name:	manuel de leon	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	6197100777	**Bill Code 2:**	Not Applicable
Site Address:	6960 Camino Maquiladora Ste E	**Bill Code 3:**	Not Applicable
Parcel No:	646-190-27-16	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA, SUITE# E		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:	Not Applicable		
ER Con Name:	manuel de leon		
ER Con Title:	owner		
Water Purv:	OTAY WATER IMP DIST C-SEWER		
Fire Agency:	SAN DIEGO		
Geo SRC:	Mapped to record APN/Parcel XY center		
Match Addr:			
Hirt Flag:	No		
Frhmbp Report Filename:	HMBP000515.pdf		
Frhmbp Sitemap Filename:	MAP_000515.jpg		

22	*4 of 14*	*NW*	*0.25 / 1,293.96*	*510.06 / 1*	***PRECISE LIFT SYSTEMS 6960 CAMINO MAQUILADORA CA 0***	***HAZ SANDIEGO***

Record ID:	DEH2003-HUPFP-202526	**GIS Record ID:**	DEH2003-HUPFP-202526
Facility Name:		**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	32.5674512
Facility Latitude:		**GIS Fac Longitude:**	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	PRECISE LIFT SYSTEMS		
GIS Facility Address:	6960 CAMINO MAQUILADORA		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902709
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 202526
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90813
UST Facility:		**Point Y:**	1787076.88613
Total No USTs:		**Lat GS84:**	32.5674512
No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-09	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	5 of 14	NW	0.25 / 1,293.96	510.06 / 1	BAJA AUTO PARTS #2 6960 CAMINO MAQUILADORA, SUITE# L, SAN DIEGO, CA 92154 SAN DIEGO CA 0	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-200186	**GIS Record ID:**	DEH2002-HUPFP-200186
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	0
Facility Latitude:		**GIS Fac Longitude:**	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	BAJA AUTO PARTS #2		
GIS Facility Address:	6960 CAMINO MAQUILADORA, SUITE# L, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Permit Suspended	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902709
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 200186
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90813
UST Facility:		**Point Y:**	1787076.88613
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-09	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA, SUITE# L		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Match Addr:						
Hirt Flag:						
Frhmbp Report Filename:						
Frhmbp Sitemap Filename:						
22	6 of 14	NW	0.25 / 1,293.96	510.06 / 1	OTAY ENGINE REBUILDERS 6960 CAMINO MAQUILADORA, SAN DIEGO, 92173- CA	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-134481	GIS Record ID:	
Facility Name:	OTAY ENGINE REBUILDERS	GIS Facility City:	
Facility City:		GIS Facility ZipCode:	
Facility ZipCode:		GIS Fac Latitude:	
Facility Latitude:		GIS Fac Longitude:	
Facility Longitude:			
Facility Address:	6960 CAMINO MAQUILADORA, SAN DIEGO, 92173-		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	7 of 14	NW	0.25 / 1,293.96	510.06 / 1	905 SMOG & AUTO REPAIR 6960 CAMINO MAQUILADORA, SUITE# G, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2006-HUPFP-206286	GIS Record ID:	DEH2006-HUPFP-206286
Facility Name:		GIS Facility City:	SAN DIEGO
Facility City:		GIS Facility ZipCode:	92154
Facility ZipCode:		GIS Fac Latitude:	32.5674512
Facility Latitude:		GIS Fac Longitude:	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	905 SMOG & AUTO REPAIR		
GIS Facility Address:	6960 CAMINO MAQUILADORA, SUITE# G, SAN DIEGO, CA 92154		
Tank Owner Name:			

Hazardous Waste and Materials

ID:	138830	Permit Status:	Permit Renewed
Child Record ID:	DEH2016-HWAST-0102473	Active Permit:	true
CAS No:		Haz Material Type:	
Last Updated:	03/13/2018 12:44:47 AM	Trade Secret:	false
Chemical Name:	WASTE 342 ORGANIC LIQUIDS W/METALS		
Common Name Inventory:	ANTIFREEZE		

ID:	138829	Permit Status:	Permit Renewed
Child Record ID:	DEH2016-HWAST-0102472	Active Permit:	true
CAS No:		Haz Material Type:	
Last Updated:	03/13/2018 12:44:47 AM	Trade Secret:	false
Chemical Name:	WASTE 221 WASTE OIL & MIXED OIL		
Common Name Inventory:	USED OIL		

Hazardous Materials Inspection Violations

Container Tank ID:		Inspection No:	6392419
Facility ID No:	37-000-206286	Inspection Type:	Routine
ID:	51782	Inspection Date:	01/31/2020 12:00:00 AM
UST ID:		Compliance Date:	05/21/2021 12:00:00 AM
Permit Status:	Expired	Last Updated:	10/09/2021 01:31:53 AM
Active Permit:	false	NOV:	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3030010 Accumulated waste too long (>180 or 270 days) or (>90 days). HSC 25201(a), 25123.3(h)(1); 22 CCR 66262.34(d); 40 CFR 262.34(e) and/or (f)		

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21020
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 5564961
Inspection Type: Routine
Inspection Date: 12/09/2016 12:12:00 PM
Compliance Date: 02/27/2018 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3020001 Failed to ensure employees are trained for hazardous waste handling, compliance with regulations, and emergency response procedures. (40 CFR 262.34(d)(5)(iii).) 22 CCR 66262.34(d)(2)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 55851
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6772308
Inspection Type: Re-inspection
Inspection Date: 07/16/2021 12:00:00 AM
Compliance Date:
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Waste Generator
Violation Classification: Class I
Violation Code: HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1

Container Tank ID:
Facility ID No: 37-000-206286
ID: 54789
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6571037
Inspection Type: Re-inspection
Inspection Date: 05/21/2021 12:00:00 AM
Compliance Date: 07/16/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class I
Violation Code: HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1

Container Tank ID:
Facility ID No: 37-000-206286
ID: 55854
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6772308
Inspection Type: Re-inspection
Inspection Date: 07/16/2021 12:00:00 AM
Compliance Date: 09/08/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Waste Generator
Violation Classification: Class I
Violation Code: 3010010 Failed to maintain copies of Uniform Hazardous Waste Manifest, consolidated manifest, or Bills of Lading for 3 years. HSC 25160.2(b)(3), 25185(a)(4); 22 CCR 66262.40(a), 66262.23(a)(3)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21017
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 4350440
Inspection Type: Routine
Inspection Date: 12/12/2014 12:00:00 AM
Compliance Date: 12/30/2014 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3030010 Failure to dispose of hazardous waste within 180 days (or 270 if waste is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.; 22 CCR 12 66262.34(d).

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21018
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 5564961
Inspection Type: Routine
Inspection Date: 12/09/2016 12:12:00 PM
Compliance Date: 12/09/2016 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3010002 Failed to obtain and/or maintain an active EPA ID. 22 CCR 66262.12

Container Tank ID:
Facility ID No: 37-000-206286
Inspection No: 4350440
Inspection Type: Routine

ID:	21015	**Inspection Date:**	12/12/2014 12:00:00 AM
UST ID:		**Compliance Date:**	01/06/2015 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3010002 Failure to obtain and/or maintain an Active EPA ID.; 22 CCR 12 66262.12.		

Container Tank ID:		**Inspection No:**	5915311
Facility ID No:	37-000-206286	**Inspection Type:**	Routine
ID:	21022	**Inspection Date:**	02/27/2018 02:58:00 PM
UST ID:		**Compliance Date:**	02/28/2018 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	true
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class I		
Violation Code:	HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.905		

Container Tank ID:		**Inspection No:**	4350440
Facility ID No:	37-000-206286	**Inspection Type:**	Routine
ID:	21026	**Inspection Date:**	12/12/2014 12:00:00 AM
UST ID:		**Compliance Date:**	12/12/2014 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010008 Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date. For facilities with invenntory that exceed EPCRA thresholds; failure to submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages HSC 6.95 25508.2 / 19 CCR 4 2729.5(c)		

Container Tank ID:		**Inspection No:**	6772308
Facility ID No:	37-000-206286	**Inspection Type:**	Re-inspection
ID:	55852	**Inspection Date:**	07/16/2021 12:00:00 AM
UST ID:		**Compliance Date:**	07/16/2021 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)		

Container Tank ID:		**Inspection No:**	6772308
Facility ID No:	37-000-206286	**Inspection Type:**	Re-inspection
ID:	55850	**Inspection Date:**	07/16/2021 12:00:00 AM
UST ID:		**Compliance Date:**	07/27/2021 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3010002 Failed to obtain &/or maintain an active EPA ID Number. 22 CCR 66262.12(a)		

Container Tank ID:		**Inspection No:**	5564961
Facility ID No:	37-000-206286	**Inspection Type:**	Routine
ID:	21019	**Inspection Date:**	12/09/2016 12:12:00 PM
UST ID:		**Compliance Date:**	12/09/2016 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	false
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class II		
Violation Code:	3030019 Failed to inspect hazardous waste storage area at least weekly. (40 CFR 262.34(d)(2); 265.174.) 22 CCR 66262.34(d)(2)		

Container Tank ID:		**Inspection No:**	6392419
Facility ID No:	37-000-206286	**Inspection Type:**	Routine
ID:	51783	**Inspection Date:**	01/31/2020 12:00:00 AM
UST ID:		**Compliance Date:**	05/21/2021 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	false

Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3010010 Failed to maintain copies of Uniform Hazardous Waste Manifest, consolidated manifest, or Bills of Lading for 3 years. HSC 25160.2(b)(3), 25185(a)(4); 22 CCR 66262.40(a), 66262.23(a)(3)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21029
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 5915311
Inspection Type: Routine
Inspection Date: 02/27/2018 02:58:00 PM
Compliance Date: 03/12/2018 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class I
Violation Code: 1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21016
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 4350440
Inspection Type: Routine
Inspection Date: 12/12/2014 12:00:00 AM
Compliance Date: 01/06/2015 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3020001 Failure to ensure employees are familiar with the handling and compliance of hazardous waste regulations and emergency response. 22 CCR 12 66262.34(d)(2); 40 CFR 1 262.34(d)(5)(iii)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 54790
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6571037
Inspection Type: Re-inspection
Inspection Date: 05/21/2021 12:00:00 AM
Compliance Date: 07/16/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21025
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 4350440
Inspection Type: Routine
Inspection Date: 12/12/2014 12:00:00 AM
Compliance Date: 12/12/2014 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010002 Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; HSC 6.95 25508(a) 1A

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21024
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 4350440
Inspection Type: Routine
Inspection Date: 12/12/2014 12:00:00 AM
Compliance Date: 12/12/2014 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010001 Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; HSC 6.95 25507(a).

Container Tank ID:
Facility ID No: 37-000-206286
ID: 51781
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6392419
Inspection Type: Routine
Inspection Date: 01/31/2020 12:00:00 AM
Compliance Date: 05/21/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Waste Generator

Violation Classification: Class I
Violation Code: HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1

Container Tank ID:
Facility ID No: 37-000-206286
ID: 54787
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6571037
Inspection Type: Re-inspection
Inspection Date: 05/21/2021 12:00:00 AM
Compliance Date: 07/16/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Waste Generator
Violation Classification: Class I
Violation Code: 3030010 Accumulated waste too long (>180 or 270 days) or (>90 days). HSC 25201(a), 25123.3(h)(1); 22 CCR 66262.34 (b), 66262.34(d); 40 CFR 262.34(e) and/or (f)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 51785
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6392419
Inspection Type: Routine
Inspection Date: 01/31/2020 12:00:00 AM
Compliance Date: 05/21/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class I
Violation Code: HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21027
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 5564961
Inspection Type: Routine
Inspection Date: 12/09/2016 12:12:00 PM
Compliance Date: 12/09/2016 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508.2

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21023
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 5915311
Inspection Type: Routine
Inspection Date: 02/27/2018 02:58:00 PM
Compliance Date: 03/09/2018 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Minor
Violation Code: 3010010 Failed to maintain copies of Uniform Hazardous Waste Manifest, consolidated manifest, or Bills of Lading for 3 years. HSC 25160.2(b)(3), 25185(a)(4); 22 CCR 66262.40(a), 66262.23(a)(3)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 51784
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6392419
Inspection Type: Routine
Inspection Date: 01/31/2020 12:00:00 AM
Compliance Date: 01/31/2020 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 55853
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6772308
Inspection Type: Re-inspection
Inspection Date: 07/16/2021 12:00:00 AM
Compliance Date: 08/25/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Waste Generator
Violation Classification: Class I
Violation Code: 3030010 Accumulated waste too long (>180 or 270 days) or (>90 days). HSC 25201(a), 25123.3(h)(1); 22 CCR 66262.34 (b), 66262.34(d); 40 CFR 262.34(e) and/or (f)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 21030
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 5915311
Inspection Type: Routine
Inspection Date: 02/27/2018 02:58:00 PM
Compliance Date: 03/08/2018 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class I
Violation Code: 1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 51786
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6392419
Inspection Type: Routine
Inspection Date: 01/31/2020 12:00:00 AM
Compliance Date: 05/21/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 54788
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6571037
Inspection Type: Re-inspection
Inspection Date: 05/21/2021 12:00:00 AM
Compliance Date: 07/16/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: false
Program Element: Hazardous Waste Generator
Violation Classification: Class II
Violation Code: 3010010 Failed to maintain copies of Uniform Hazardous Waste Manifest, consolidated manifest, or Bills of Lading for 3 years. HSC 25160.2(b)(3), 25185(a)(4); 22 CCR 66262.40(a), 66262.23(a)(3)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 55855
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6772308
Inspection Type: Re-inspection
Inspection Date: 07/16/2021 12:00:00 AM
Compliance Date:
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class I
Violation Code: HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1

Container Tank ID:
Facility ID No: 37-000-206286
ID: 55856
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6772308
Inspection Type: Re-inspection
Inspection Date: 07/16/2021 12:00:00 AM
Compliance Date: 09/08/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class I
Violation Code: 1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Container Tank ID:
Facility ID No: 37-000-206286
ID: 54786
UST ID:
Permit Status: Expired
Active Permit: false
Inspection No: 6571037
Inspection Type: Re-inspection
Inspection Date: 05/21/2021 12:00:00 AM
Compliance Date: 07/16/2021 12:00:00 AM
Last Updated: 10/09/2021 01:31:53 AM
NOV: true
Program Element: Hazardous Waste Generator
Violation Classification: Class I
Violation Code: HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1

Container Tank ID:		**Inspection No:**	5915311
Facility ID No:	37-000-206286	**Inspection Type:**	Routine
ID:	21028	**Inspection Date:**	02/27/2018 02:58:00 PM
UST ID:		**Compliance Date:**	02/28/2018 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	true
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class I		
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907		

Container Tank ID:		**Inspection No:**	5915311
Facility ID No:	37-000-206286	**Inspection Type:**	Routine
ID:	21021	**Inspection Date:**	02/27/2018 02:58:00 PM
UST ID:		**Compliance Date:**	02/28/2018 12:00:00 AM
Permit Status:	Expired	**Last Updated:**	10/09/2021 01:31:53 AM
Active Permit:	false	**NOV:**	true
Program Element:	Hazardous Waste Generator		
Violation Classification:	Class I		
Violation Code:	3010002 Failed to obtain &/or maintain an active EPA ID Number. 22 CCR 66262.12(a)		

HMD Permits Map Data

GIS Facility ID:	37-000-206286	**Status:**	
GIS CERS ID:	10394407	**ER Contact:**	6196214530
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	6196214530
Per Type:		**Census Tract:**	100.15
Per Sub Type:		**Parcel Zip:**	92154
Per Cat:		**Community:**	San Diego
Record Status:	Expired	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAL000297004	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HS015
Tank Owner:		**Feature ID:**	6461902709
SIC Code:	0000	**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	HK07 206286
Exp Date:	5/30/2018	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90799999
UST Facility:		**Point Y:**	1787076.88600001
Total No USTs:		**Lat GS84:**	32.5674512
No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Y	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:	N	**ARC Address:**	
Universal Waste Han:	N	**ARC City:**	
Toxic Gas:	No	**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:	N	**Zip:**	
Haz Waste EHS:	N	**Farm Nursery:**	
Full Name:	miguel carranza	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	619-661-8008	**Bill Code 2:**	Not Applicable
Site Address:	6960 CAMINO MAQUILADORA	**Bill Code 3:**	Not Applicable
Parcel No:	646-190-27-09	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA, SUITE# G		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:	Not Applicable		
ER Con Name:	MIGUEL CARRANZA		
ER Con Title:	OWNER		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Purv:	SAN DIEGO
Fire Agency:	SAN DIEGO
Geo SRC:	Mapped to record APN/Parcel XY center
Match Addr:	
Hirt Flag:	No
Frhmbp Report Filename:	HMBP206286.pdf
Frhmbp Sitemap Filename:	MAP_206286.pdf

22	8 of 14	NW	0.25 / 1,293.96	510.06 / 1	JVS GENERAL AUTO REPAIR 6960 CAMINO MAQUILADORA #K, SAN DIEGO, 92173- CA	HAZ SANDIEGO

Record ID:	DEH2002-HUPFP-133485	**GIS Record ID:**	
Facility Name:	JVS GENERAL AUTO REPAIR	**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	
Facility ZipCode:		**GIS Fac Latitude:**	
Facility Latitude:		**GIS Fac Longitude:**	
Facility Longitude:			
Facility Address:	6960 CAMINO MAQUILADORA #K, SAN DIEGO, 92173-		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

22	9 of 14	NW	0.25 / 1,293.96	510.06 / 1	CYCLONE LIFT INC 6960 CAMINO MAQUILADORA CA 0	HAZ SANDIEGO

Record ID:	DEH2005-HUPFP-205698	**GIS Record ID:**	DEH2005-HUPFP-205698
Facility Name:		**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	32.5674512
Facility Latitude:		**GIS Fac Longitude:**	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	CYCLONE LIFT INC		
GIS Facility Address:	6960 CAMINO MAQUILADORA		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902709
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 205698
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90813
UST Facility:		**Point Y:**	1787076.88613
Total No USTs:		**Lat GS84:**	32.5674512
No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.99022120601873

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Onsite Haz Waste Tre:		**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-09	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

22	*10 of 14*	*NW*	*0.25 / 1,293.96*	*510.06 / 1*	***PAYLESS REGISTRATION SERVICE, INC.*** ***6960 CAMINO MAQUILADORA,*** ***SAN DIEGO, CA 92154*** ***SAN DIEGO CA 92154***	***HAZ SANDIEGO***

Record ID:	DEH2011-HUPFP-213394	**GIS Record ID:**	DEH2011-HUPFP-213394
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5674512
Facility Latitude:		**GIS Fac Longitude:**	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	PAYLESS REGISTRATION SERVICE, INC.		
GIS Facility Address:	6960 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902726
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 213394
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90813
UST Facility:		**Point Y:**	1787076.88613
Total No USTs:		**Lat GS84:**	32.5674512

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-26	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

22	11 of 14	NW	0.25 / 1,293.96	510.06 / 1	EAGLE SCIENTIFIC PRODUCTS 6960 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2010-HUPFP-212943	**GIS Record ID:**	DEH2010-HUPFP-212943
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.5674512
Facility Latitude:		**GIS Fac Longitude:**	-116.9902239
Facility Longitude:			
Facility Address:			
GIS Facility Name:	EAGLE SCIENTIFIC PRODUCTS		
GIS Facility Address:	6960 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902726
SIC Code:		**X Coord:**	6333602.908
NAICS Code:		**Y Coord:**	1787076.886

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 212943
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333602.90813
UST Facility:		**Point Y:**	1787076.88613
Total No USTs:		**Lat GS84:**	32.5674512
No of Tanks:		**Lon GS84:**	-116.9902239
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99022120601873
Onsite Haz Waste Tre:		**Y Map Coord:**	32.56751199463001
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-27-26	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6960 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

22	*12 of 14*	*NW*	*0.25 / 1,293.96*	*510.06 / 1*	***905 SMOG & AUTO REPAIR*** ***6960 CAMINO MAQUILADORA*** ***STE G*** ***SAN DIEGO CA 92154***	***RCRA NON GEN***

EPA Handler ID:	CAL000297004
Gen Status Universe:	No Report
Contact Name:	MIGUEL CARRANZA
Contact Address:	2750 , SPARTA RD STE 14 , , CHULA VISTA , CA, 91915 , US
Contact Phone No and Ext:	619-621-4530
Contact Email:	MICAR625@GMAIL.COM
Contact Country:	US
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20210521
Location Latitude:	32.566894
Location Longitude:	-116.99005

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20210521
Handler Name:	905 SMOG & AUTO REPAIR
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20050728
Handler Name:	905 SMOG & AUTO REPAIR
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	6960
Type:	Other	***Street 1:***	CAMINO MAQUILADORA STE G
Name:	MICAR INTERNATIONAL INC	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	619-621-4530	***Country:***	US
Source Type:	Implementer	***Zip Code:***	92154

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	6960 CAMINO MAQUILADORA STE G
Name:	MICAR INTERNATIONAL INC	***Street 2:***	
Date Became Current:		***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA
Phone:	619-621-4530	***Country:***	
Source Type:	Implementer	***Zip Code:***	92154

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	2750 SPARTA RD STE 14
Name:	MIGUEL CARRANZA	***Street 2:***	
Date Became Current:		***City:***	CHULA VISTA
Date Ended Current:		***State:***	CA
Phone:	619-621-4530	***Country:***	
Source Type:	Implementer	***Zip Code:***	91915

Owner/Operator Ind:	Current Operator	***Street No:***	2750
Type:	Other	***Street 1:***	SPARTA RD STE 14
Name:	MIGUEL CARRANZA	***Street 2:***	
Date Became Current:		***City:***	CHULA VISTA
Date Ended Current:		***State:***	CA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone: 619-621-4530 **Country:** US
Source Type: Implementer **Zip Code:** 91915

Historical Handler Details

Receive Dt: 20050728
Generator Code Description: Not a Generator, Verified
Handler Name: 905 SMOG & AUTO REPAIR

22	13 of 14	NW	0.25 / 1,293.96	510.06 / 1	**BAJA AUTO PARTS #2** **6960 CAMINO MAQUILADORA** **STE E** **SAN DIEGO CA 92154**	RCRA NON GEN

EPA Handler ID: CAL000403322
Gen Status Universe: No Report
Contact Name: MANUEL DE LEON
Contact Address: 6960 CAMINO MAQUILADORA STE E , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext: 619-710-0777
Contact Email: BAJAAUTOPARTS2@GMAIL.COM
Contact Country:
County Name: SAN DIEGO
EPA Region: 09
Land Type:
Receive Date: 20141226
Location Latitude: 32.566894
Location Longitude: -116.99005

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20141226
Handler Name: BAJA AUTO PARTS #2
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	6960 CAMINO MAQUILADORA STE E
Name:	MANUEL DE LEON	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-710-0777	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	6960 CAMINO MAQUILADORA STE E
Name:	MANUEL DE LEON	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-710-0777	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

22	14 of 14	NW	0.25 / 1,293.96	510.06 / 1	**JOSE GRACIA** **6960 CAMINO MAQUILADORA** **SUITE B** **SAN DIEGO CA 92154**	**RCRA NON GEN**

EPA Handler ID:	CAC003069222
Gen Status Universe:	No Report
Contact Name:	JOSE GRACIA
Contact Address:	6960 CAMINO MAQUILADORA SUITE B , , SAN DIEGO , CA, 92154 ,
Contact Phone No and Ext:	619-278-1456
Contact Email:	HEAVYTRUCKSERVICE01@GMAIL.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20200602
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200602
Handler Name:	JOSE GRACIA
Source Type:	Implementer
Federal Waste Generator Code:	N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	6960 CAMINO MAQUILDORA SUITE B
Name:	JOSE GRACIA	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-278-1456	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	6960 CAMINO MAQUILADORA SUITE B
Name:	JOSE GRACIA	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-278-1456	**Country:**	
Source Type:	Implementer	**Zip Code:**	92154

---

23 | 1 of 13 | NW | 0.25 / 1,294.15 | 508.63 / 0 | **SMOG EXPRESS**
6930 CAMINO MAQUILADORA,
SUITE# A, SAN DIEGO, CA 92154
SAN DIEGO CA 0 | **HAZ SANDIEGO**

Record ID:	DEH2006-HUPFP-206250	**GIS Record ID:**	DEH2006-HUPFP-206250
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	0
Facility Latitude:		**GIS Fac Longitude:**	0
Facility Longitude:			
Facility Address:			
GIS Facility Name:	SMOG EXPRESS		
GIS Facility Address:	6930 CAMINO MAQUILADORA, SUITE# A, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Permit Suspended	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902600
SIC Code:		**X Coord:**	6333303.853
NAICS Code:		**Y Coord:**	1787083.602
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 206250
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333303.85295
UST Facility:		**Point Y:**	1787083.602
Total No USTs:		**Lat GS84:**	0
No of Tanks:		**Lon GS84:**	0
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:	Yes	**Side:**	
Recycle100:		**X Map Coord:**	-116.99119196467954
Onsite Haz Waste Tre:		**Y Map Coord:**	32.567524613076586
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-26-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6930 CAMINO MAQUILADORA, SUITE# A		
Business Type:	Auto Repair, General - Waste USTs Only		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

23	2 of 13	NW	0.25 / 1,294.15	508.63 / 0	**I-MACH INDUSTRIAL MACHINERY & PARTS** **6930 CAMINO MAQUILADORA,** **SAN DIEGO, CA 92154** **SAN DIEGO CA 92154**	**HAZ SANDIEGO**

Record ID:	DEH2010-HUPFP-213148	**GIS Record ID:**	DEH2010-HUPFP-213148
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.567464
Facility Latitude:		**GIS Fac Longitude:**	-116.9911944
Facility Longitude:			
Facility Address:			
GIS Facility Name:	I-MACH INDUSTRIAL MACHINERY & PARTS		
GIS Facility Address:	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902600
SIC Code:		**X Coord:**	6333303.853
NAICS Code:		**Y Coord:**	1787083.602
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 213148
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333303.85295
UST Facility:		**Point Y:**	1787083.602
Total No USTs:		**Lat GS84:**	32.567464
No of Tanks:		**Lon GS84:**	-116.9911944
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99119196467954
Onsite Haz Waste Tre:		**Y Map Coord:**	32.567524613076586
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-26-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6930 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

23	3 of 13	NW	0.25 / 1,294.15	508.63 / 0	**ECO STONE, INC** **6930 CAMINO MAQUILADORA,** **SAN DIEGO, CA 92154** **SAN DIEGO CA 92154**	**HAZ SANDIEGO**

Record ID:	DEH2010-HUPFP-212942	**GIS Record ID:**	DEH2010-HUPFP-212942
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.567464
Facility Latitude:		**GIS Fac Longitude:**	-116.9911944
Facility Longitude:			
Facility Address:			
GIS Facility Name:	ECO STONE, INC		
GIS Facility Address:	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902600
SIC Code:		**X Coord:**	6333303.853
NAICS Code:		**Y Coord:**	1787083.602
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 212942
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333303.85295

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

UST Facility:		**Point Y:**	1787083.602
Total No USTs:		**Lat GS84:**	32.567464
No of Tanks:		**Lon GS84:**	-116.9911944
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99119196467954
Onsite Haz Waste Tre:		**Y Map Coord:**	32.567524613076586
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-26-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6930 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

23	4 of 13	NW	0.25 / 1,294.15	508.63 / 0	**LARSON IRRIGATION, INC.** **6930 CAMINO MAQUILADORA,** **SAN DIEGO, CA 92154** **SAN DIEGO CA 92154**	**HAZ SANDIEGO**

Record ID:	DEH2002-HUPFP-133769	**GIS Record ID:**	DEH2002-HUPFP-133769
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.567464
Facility Latitude:		**GIS Fac Longitude:**	-116.9911944
Facility Longitude:			
Facility Address:			
GIS Facility Name:	LARSON IRRIGATION, INC.		
GIS Facility Address:	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902600

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SIC Code:		**X Coord:**	6333303.853
NAICS Code:		**Y Coord:**	1787083.602
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 133769
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333303.85295
UST Facility:		**Point Y:**	1787083.602
Total No USTs:		**Lat GS84:**	32.567464
No of Tanks:		**Lon GS84:**	-116.9911944
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99119196467954
Onsite Haz Waste Tre:		**Y Map Coord:**	32.567524613076586
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-26-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6930 CAMINO MAQUILADORA		
Business Type:	Farming, General - Dairies, Nurseries, Etc		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

23	5 of 13	NW	0.25 / 1,294.15	508.63 / 0	**BORDER TRANSMISSIONS** **6930 CAMINO MAQUILADORA #D,** **SAN DIEGO, 92173-** **CA**	**HAZ SANDIEGO**

Record ID:	DEH2002-HUPFP-134054	**GIS Record ID:**	
Facility Name:	BORDER TRANSMISSIONS	**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	
Facility ZipCode:		**GIS Fac Latitude:**	
Facility Latitude:		**GIS Fac Longitude:**	
Facility Longitude:			
Facility Address:	6930 CAMINO MAQUILADORA #D, SAN DIEGO, 92173-		
GIS Facility Name:			
GIS Facility Address:			
Tank Owner Name:			

23	6 of 13	NW	0.25 / 1,294.15	508.63 / 0	**NEW WORLD MOLDING** **6930 CAM MAQUILADORA** **CA 0**	**HAZ SANDIEGO**

Record ID:	DEH2011-HUPFP-213328	**GIS Record ID:**	DEH2011-HUPFP-213328
Facility Name:		**GIS Facility City:**	
Facility City:		**GIS Facility ZipCode:**	0
Facility ZipCode:		**GIS Fac Latitude:**	32.567464
Facility Latitude:		**GIS Fac Longitude:**	-116.9911944

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Longitude:
Facility Address:
GIS Facility Name: NEW WORLD MOLDING
GIS Facility Address: 6930 CAM MAQUILADORA
Tank Owner Name:

HMD Permits Map Data

GIS Facility ID:
GIS CERS ID:
GIS Record Type: LUEG-DEH/HMD/UPFP/Facility
Per Type:
Per Sub Type:
Per Cat:
Record Status: Completed
HW Tler:
LRG QTY MW Gener:
EPA ID No:
RMP CAL ARP:
Tank Owner:
SIC Code:
NAICS Code:
Disclose Qty Haz Mat:
Exp Date:
Own/Operate USTs :
UST Facility:
Total No USTs:
No of Tanks:
Own Oper APS:
Tot APSA Cap: 0
Capacity LR:
Haz Waste G:
Recycle100:
Onsite Haz Waste Tre:
RCRA LRG Qty:
Haz Wst Coll Site:
Accept Offs:
Universal Waste Han:
Toxic Gas:
Hazmat EHS:
Hazmat Rad:
Haz Waste Rad:
Haz Waste EHS:
Full Name:
Email Perm:
Phone Perm:
Site Address:
Parcel No: 646-190-26-00
Record Ali: Unified Program Facility Permit
Address: 6930 CAM MAQUILADORA
Business Type:
Bill Code:
ER Con Name:
ER Con Title:
Water Purv:
Fire Agency:
Geo SRC: Mapped to record APN/parcel center XY
Match Addr:
Hirt Flag:
Frhmbp Report Filename:
Frhmbp Sitemap Filename:

Status:
ER Contact:
ER Con Work Ph:
Census Tract:
Parcel Zip:
Community:
Jurisdiction:
Basin No:
BOS Dist:
Tbpg Grid:
Insp Dist:
Feature ID: 6461902600
X Coord: 6333303.853
Y Coord: 1787083.602
Kiva Per Typ: HK07 213328
Agency Name: COSD
Point X: 6333303.85295
Point Y: 1787083.602
Lat GS84: 32.567464
Lon GS84: -116.9911944
Loc Name:
Score:
Match Type:
Side:
X Map Coord: -116.99119196467954
Y Map Coord: 32.567524613076586
User Fld:
Addr Type:
ARC Address:
ARC City:
ARC Zipcode:
ARC State:
ARC APN:
Zip:
Farm Nursery:
Indian or Territory:
County ID:
Bill Code 2:
Bill Code 3:
Univ Waste Gen Type:

23	7 of 13	NW	0.25 / 1,294.15	508.63 / 0	JD ELECTRIC & INDUSTRIAL SUPPLY 6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2010-HUPFP-213175	**GIS Record ID:**	DEH2010-HUPFP-213175
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.567464
Facility Latitude:		**GIS Fac Longitude:**	-116.9911944
Facility Longitude:			
Facility Address:			
GIS Facility Name:	JD ELECTRIC & INDUSTRIAL SUPPLY		
GIS Facility Address:	6930 CAMINO MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902600
SIC Code:		**X Coord:**	6333303.853
NAICS Code:		**Y Coord:**	1787083.602
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK07 213175
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333303.85295
UST Facility:		**Point Y:**	1787083.602
Total No USTs:		**Lat GS84:**	32.567464
No of Tanks:		**Lon GS84:**	-116.9911944
Own Oper APS:		**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99119196467954
Onsite Haz Waste Tre:		**Y Map Coord:**	32.567524613076586
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-26-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6930 CAMINO MAQUILADORA		
Business Type:			
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		
Match Addr:			
Hirt Flag:			
Frhmbp Report Filename:			
Frhmbp Sitemap Filename:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	8 of 13	NW	0.25 / 1,294.15	508.63 / 0	OTAY CARPET OUTLET INC 6930 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2006-HUPFP-206262	**GIS Record ID:**	DEH2006-HUPFP-206262
Facility Name:		**GIS Facility City:**	SAN DIEGO
Facility City:		**GIS Facility ZipCode:**	92154
Facility ZipCode:		**GIS Fac Latitude:**	32.567464
Facility Latitude:		**GIS Fac Longitude:**	-116.9911944
Facility Longitude:			
Facility Address:			
GIS Facility Name:	OTAY CARPET OUTLET INC		
GIS Facility Address:	6930 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		**Status:**	
GIS CERS ID:		**ER Contact:**	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	
Per Type:		**Census Tract:**	
Per Sub Type:		**Parcel Zip:**	
Per Cat:		**Community:**	
Record Status:	Completed	**Jurisdiction:**	
HW Tier:		**Basin No:**	
LRG QTY MW Gener:		**BOS Dist:**	
EPA ID No:		**Tbpg Grid:**	
RMP CAL ARP:		**Insp Dist:**	
Tank Owner:		**Feature ID:**	6461902600
SIC Code:		**X Coord:**	6333303.853
NAICS Code:		**Y Coord:**	1787083.602
Disclose Qty Haz Mat:		**Kiva Per Typ:**	HK18 206262
Exp Date:		**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333303.85295
UST Facility:		**Point Y:**	1787083.602
Total No USTs:		**Lat GS84:**	32.567464
No of Tanks:		**Lon GS84:**	-116.9911944
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	
Haz Waste G:		**Side:**	
Recycle100:		**X Map Coord:**	-116.99119196467954
Onsite Haz Waste Tre:		**Y Map Coord:**	32.567524613076586
RCRA LRG Qty:		**User Fld:**	
Haz Wst Coll Site:		**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:		**ARC Zipcode:**	
Hazmat EHS:		**ARC State:**	
Hazmat Rad:		**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:		**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:		**Bill Code 2:**	
Site Address:		**Bill Code 3:**	
Parcel No:	646-190-26-00	**Univ Waste Gen Type:**	
Record Ali:	Unified Program Facility Permit		
Address:	6930 CAM MAQUILADORA		
Business Type:	One (1) Waste Item or One (1) Inventory		
Bill Code:			
ER Con Name:			
ER Con Title:			
Water Purv:			
Fire Agency:			
Geo SRC:	Mapped to record APN/parcel center XY		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Match Addr:						
Hirt Flag:						
Frhmbp Report Filename:						
Frhmbp Sitemap Filename:						
23	9 of 13	NW	0.25 / 1,294.15	508.63 / 0	ASERET FREIGHT FORWARDING 6930 CAM MAQUILADORA, SAN DIEGO, CA 92154 SAN DIEGO CA 92154	HAZ SANDIEGO

Record ID:	DEH2006-HUPFP-206261	GIS Record ID:	DEH2006-HUPFP-206261
Facility Name:		GIS Facility City:	SAN DIEGO
Facility City:		GIS Facility ZipCode:	92154
Facility ZipCode:		GIS Fac Latitude:	32.567464
Facility Latitude:		GIS Fac Longitude:	-116.9911944
Facility Longitude:			
Facility Address:			
GIS Facility Name:	ASERET FREIGHT FORWARDING		
GIS Facility Address:	6930 CAM MAQUILADORA, SAN DIEGO, CA 92154		
Tank Owner Name:			

HMD Permits Map Data

GIS Facility ID:		Status:	
GIS CERS ID:		ER Contact:	
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	ER Con Work Ph:	
Per Type:		Census Tract:	
Per Sub Type:		Parcel Zip:	
Per Cat:		Community:	
Record Status:	Completed	Jurisdiction:	
HW Tier:		Basin No:	
LRG QTY MW Gener:		BOS Dist:	
EPA ID No:		Tbpg Grid:	
RMP CAL ARP:		Insp Dist:	
Tank Owner:		Feature ID:	6461902600
SIC Code:		X Coord:	6333303.853
NAICS Code:		Y Coord:	1787083.602
Disclose Qty Haz Mat:		Kiva Per Typ:	HK07 206261
Exp Date:		Agency Name:	COSD
Own/Operate USTs :		Point X:	6333303.85295
UST Facility:		Point Y:	1787083.602
Total No USTs:		Lat GS84:	32.567464
No of Tanks:		Lon GS84:	-116.9911944
Own Oper APS:	N	Loc Name:	
Tot APSA Cap:	0	Score:	
Capacity LR:		Match Type:	
Haz Waste G:		Side:	
Recycle100:		X Map Coord:	-116.99119196467954
Onsite Haz Waste Tre:		Y Map Coord:	32.567524613076586
RCRA LRG Qty:		User Fld:	
Haz Wst Coll Site:		Addr Type:	
Accept Offs:		ARC Address:	
Universal Waste Han:		ARC City:	
Toxic Gas:		ARC Zipcode:	
Hazmat EHS:		ARC State:	
Hazmat Rad:		ARC APN:	
Haz Waste Rad:		Zip:	
Haz Waste EHS:		Farm Nursery:	
Full Name:		Indian or Territory:	
Email Perm:		County ID:	
Phone Perm:		Bill Code 2:	
Site Address:		Bill Code 3:	
Parcel No:	646-190-26-00	Univ Waste Gen Type:	
Record Ali:	Unified Program Facility Permit		
Address:	6930 CAM MAQUILADORA		
Business Type:	Contractors-Street, Painting, Roofers, Building		
Bill Code:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ER Con Name:
ER Con Title:
Water Purv:
Fire Agency:
Geo SRC: Mapped to record APN/parcel center XY
Match Addr:
Hirt Flag:
Frhmbp Report Filename:
Frhmbp Sitemap Filename:

23	10 of 13	NW	0.25 / 1,294.15	508.63 / 0	**Battery and Components Inc dba Commercial Battery** **6930 CAMINO MAQUILADORA K & L** **SAN DIEGO CA 92154**	HAZ SANDIEGO

Record ID: DEH2002-HUPFP-135952
Facility Name: Battery and Components Inc dba Commercial Battery
Facility City: SAN DIEGO
Facility ZipCode: 92154
Facility Latitude:
Facility Longitude:
Facility Address: 6930 CAMINO MAQUILADORA K & L
GIS Facility Name: Battery and Components Inc dba Commercial Battery
GIS Facility Address: 6930 CAMINO MAQUILADORA, SUITE# K & L, SAN DIEGO, CA 92154
Tank Owner Name:
GIS Record ID: DEH2002-HUPFP-135952
GIS Facility City: SAN DIEGO
GIS Facility ZipCode: 92154
GIS Fac Latitude: 32.567464
GIS Fac Longitude: -116.9911944

Hazardous Materials Facility Data

CERS ID: 10198822
Facility ID No: 37-000-135952
EPA ID No: CAR000206656
Active Permit: true
Permit Status: Permit Renewed
Bus. Phone: 619-661-0380
Bus. Fax: 0
Last Updated: 02/08/2022 02:30:51 AM
New Georeferenced Column:
Mailing Address: 6930 CAMINO MAQUILADORA # K/L, SAN DIEGO, CA 92154
Onsite H Waste Trtmt: false
Haz Mat on Site: true
Haz Waste Generator: false
Own/Oper Under: false
Own/Oper Above: false
Recycle: false
RCRA Large Qty Gen: false
HHW Collection: false

Hazardous Waste and Materials

ID: 384451
Child Record ID: DEH2021-HCHEM-0286793
CAS No: 7439-92-1
Last Updated: 02/08/2022 02:30:51 AM
Chemical Name: Lead
Common Name Inventory: Lead
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 384445
Child Record ID: DEH2021-HCHEM-0286787
CAS No: 68476-85-7
Last Updated: 02/08/2022 02:30:51 AM
Chemical Name: PROPANE
Common Name Inventory: Liquid Propane Gas
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 304269
Child Record ID: DEH2019-HCHEM-0235298
CAS No: 497-19-8
Last Updated: 04/28/2020 02:31:04 AM
Chemical Name: Sodium Carbonate
Common Name Inventory: Soda Ash
Permit Status: Permit Renewed
Active Permit: true
Haz Material Type: Pure
Trade Secret: false

ID: 384446
Child Record ID: DEH2021-HCHEM-0286788
Permit Status: Permit Renewed
Active Permit: true

CAS No: 7440-70-2 **Haz Material Type:** Pure
Last Updated: 02/08/2022 02:30:51 AM **Trade Secret:** false
Chemical Name: Calcium
Common Name Inventory: Cal Grid II

ID: 22214 **Permit Status:** Permit Renewed
Child Record ID: DEH2002-HWAST-661290 **Active Permit:** true
CAS No: **Haz Material Type:**
Last Updated: 02/02/2017 02:32:00 AM **Trade Secret:** false
Chemical Name: WASTE 444 USED BATTERIES
Common Name Inventory: EXIDE

ID: 384452 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0286794 **Active Permit:** true
CAS No: 7440-31-5 **Haz Material Type:** Pure
Last Updated: 02/08/2022 02:30:51 AM **Trade Secret:** false
Chemical Name: Tin
Common Name Inventory: Tin

ID: 304265 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0235294 **Active Permit:** true
CAS No: 7440-70-2 **Haz Material Type:** Pure
Last Updated: 04/28/2020 02:31:04 AM **Trade Secret:** false
Chemical Name: Calcium
Common Name Inventory: Cal Grid II

ID: 304266 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0235295 **Active Permit:** true
CAS No: 7782-49-2 **Haz Material Type:** Pure
Last Updated: 04/28/2020 02:31:04 AM **Trade Secret:** false
Chemical Name: Selenium
Common Name Inventory: Selenmetall pellets

ID: 304270 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0235299 **Active Permit:** true
CAS No: 7439-92-1 **Haz Material Type:** Pure
Last Updated: 04/28/2020 02:31:04 AM **Trade Secret:** false
Chemical Name: Lead
Common Name Inventory: Lead

ID: 304264 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0235293 **Active Permit:** true
CAS No: 68476-85-7 **Haz Material Type:** Pure
Last Updated: 04/28/2020 02:31:04 AM **Trade Secret:** false
Chemical Name: PROPANE
Common Name Inventory: Liquid Propane Gas

ID: 304271 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0235300 **Active Permit:** true
CAS No: 7440-31-5 **Haz Material Type:** Pure
Last Updated: 04/28/2020 02:31:04 AM **Trade Secret:** false
Chemical Name: Tin
Common Name Inventory: Tin

ID: 384449 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0286791 **Active Permit:** true
CAS No: 7727-43-7 **Haz Material Type:** Pure
Last Updated: 02/08/2022 02:30:51 AM **Trade Secret:** false
Chemical Name: Barium Sulfate
Common Name Inventory: Negative Expander

ID: 114672 **Permit Status:** Permit Renewed
Child Record ID: DEH2017-HCHEM-0162232 **Active Permit:** true
CAS No: 68476-85-7 **Haz Material Type:** Pure
Last Updated: 08/17/2019 02:53:54 AM **Trade Secret:** false
Chemical Name: PROPANE
Common Name Inventory: Liquid Propane Gas

ID: 384448 **Permit Status:** Permit Renewed

Child Record ID: DEH2021-HCHEM-0286790 **Active Permit:** true
CAS No: 1344-09-8 **Haz Material Type:** Mixture
Last Updated: 02/08/2022 02:30:51 AM **Trade Secret:** false
Chemical Name: Silicic acid, sodium salt
Common Name Inventory: Sodium silicate mixture 680108

ID: 304267 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0235296 **Active Permit:** true
CAS No: 1344-09-8 **Haz Material Type:** Mixture
Last Updated: 04/28/2020 02:31:04 AM **Trade Secret:** false
Chemical Name: Silicic acid, sodium salt
Common Name Inventory: Sodium silicate mixture 680108

ID: 22213 **Permit Status:** Permit Renewed
Child Record ID: DEH2002-HCHEM-661292 **Active Permit:** true
CAS No: 68476-85-7 **Haz Material Type:** Mixture
Last Updated: 02/02/2017 02:32:00 AM **Trade Secret:** false
Chemical Name: PROPANE
Common Name Inventory:

ID: 384447 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0286789 **Active Permit:** true
CAS No: 7782-49-2 **Haz Material Type:** Pure
Last Updated: 02/08/2022 02:30:51 AM **Trade Secret:** false
Chemical Name: Selenium
Common Name Inventory: Selenmetall pellets

ID: 384450 **Permit Status:** Permit Renewed
Child Record ID: DEH2021-HCHEM-0286792 **Active Permit:** true
CAS No: 497-19-8 **Haz Material Type:** Pure
Last Updated: 02/08/2022 02:30:51 AM **Trade Secret:** false
Chemical Name: Sodium Carbonate
Common Name Inventory: Soda Ash

ID: 304268 **Permit Status:** Permit Renewed
Child Record ID: DEH2019-HCHEM-0235297 **Active Permit:** true
CAS No: 7727-43-7 **Haz Material Type:** Pure
Last Updated: 04/28/2020 02:31:04 AM **Trade Secret:** false
Chemical Name: Barium Sulfate
Common Name Inventory: Negative Expander

Hazardous Materials Inspection Violations

Container Tank ID: **Inspection No:** 5645834
Facility ID No: 37-000-135952 **Inspection Type:** Routine
ID: 12134 **Inspection Date:** 04/06/2017 05:08:00 PM
UST ID: **Compliance Date:** 04/12/2018 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 02/08/2022 12:00:00 AM
Active Permit: true **NOV:** false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Minor
Violation Code: 1020002 Initial and/or annual employee training not conducted for hazardous materials management and/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4)

Container Tank ID: **Inspection No:** 6141022
Facility ID No: 37-000-135952 **Inspection Type:** Routine
ID: 46753 **Inspection Date:** 08/16/2019 12:00:00 AM
UST ID: **Compliance Date:** 10/17/2019 12:00:00 AM
Permit Status: Permit Renewed **Last Updated:** 02/08/2022 12:00:00 AM
Active Permit: true **NOV:** false
Program Element: Hazardous Materials Release Response Plans
Violation Classification: Class II
Violation Code: 1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Container Tank ID: **Inspection No:** 4350605
Facility ID No: 37-000-135952 **Inspection Type:** Routine

ID:	12133	**Inspection Date:**	03/16/2015 12:00:00 AM
UST ID:		**Compliance Date:**	09/21/2016 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/08/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010008 Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date. For facilities with invenntory that exceed EPCRA thresholds; failure to submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages HSC 6.95 25508.2 / 19 CCR 4 2729.5(c)		

Container Tank ID:		**Inspection No:**	6141022
Facility ID No:	37-000-135952	**Inspection Type:**	Routine
ID:	46751	**Inspection Date:**	08/16/2019 12:00:00 AM
UST ID:		**Compliance Date:**	12/18/2019 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/08/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)		

Container Tank ID:		**Inspection No:**	4350605
Facility ID No:	37-000-135952	**Inspection Type:**	Routine
ID:	12132	**Inspection Date:**	03/16/2015 12:00:00 AM
UST ID:		**Compliance Date:**	09/21/2016 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/08/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010007 Failure to submit a revised business plan upon a substantial change in the handler's operations; HSC 6.95 25508.1(f)		

Container Tank ID:		**Inspection No:**	6141022
Facility ID No:	37-000-135952	**Inspection Type:**	Routine
ID:	46752	**Inspection Date:**	08/16/2019 12:00:00 AM
UST ID:		**Compliance Date:**	10/17/2019 12:00:00 AM
Permit Status:	Permit Renewed	**Last Updated:**	02/08/2022 12:00:00 AM
Active Permit:	true	**NOV:**	false
Program Element:	Hazardous Materials Release Response Plans		
Violation Classification:	Class II		
Violation Code:	1010004 Chemical inventory incomplete or not submitted in CERS. HSC 25505(a)(1); 25507(a); 25508.1(a-b); 19 CCR 2654 (a) or (d)		

HMD Permits Map Data

GIS Facility ID:	37-000-135952	**Status:**	
GIS CERS ID:	10198822	**ER Contact:**	619-479-2264
GIS Record Type:	LUEG-DEH/HMD/UPFP/Facility	**ER Con Work Ph:**	661-0380
Per Type:		**Census Tract:**	100.15
Per Sub Type:		**Parcel Zip:**	92154
Per Cat:		**Community:**	San Diego
Record Status:	Permit Renewed	**Jurisdiction:**	SAN DIEGO
HW Tier:	Not Applicable	**Basin No:**	911.12
LRG QTY MW Gener:	No	**BOS Dist:**	1
EPA ID No:	CAR000206656	**Tbpg Grid:**	
RMP CAL ARP:	Not Applicable	**Insp Dist:**	HS015
Tank Owner:		**Feature ID:**	6461902600
SIC Code:		**X Coord:**	6333303.853
NAICS Code:		**Y Coord:**	1787083.602
Disclose Qty Haz Mat:	Y	**Kiva Per Typ:**	HK07 135952
Exp Date:	2/27/2021	**Agency Name:**	COSD
Own/Operate USTs :		**Point X:**	6333303.85300002
UST Facility:		**Point Y:**	1787083.602
Total No USTs:		**Lat GS84:**	32.567464
No of Tanks:		**Lon GS84:**	-116.9911944
Own Oper APS:	N	**Loc Name:**	
Tot APSA Cap:	0	**Score:**	
Capacity LR:		**Match Type:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Haz Waste G:	N	**Side:**	
Recycle100:	N	**X Map Coord:**	-116.99119196467954
Onsite Haz Waste Tre:	N	**Y Map Coord:**	32.567524613076586
RCRA LRG Qty:	N	**User Fld:**	
Haz Wst Coll Site:	N	**Addr Type:**	
Accept Offs:		**ARC Address:**	
Universal Waste Han:		**ARC City:**	
Toxic Gas:	No	**ARC Zipcode:**	
Hazmat EHS:	N	**ARC State:**	
Hazmat Rad:	No	**ARC APN:**	
Haz Waste Rad:		**Zip:**	
Haz Waste EHS:		**Farm Nursery:**	
Full Name:	RAMON CASTANARES	**Indian or Territory:**	
Email Perm:		**County ID:**	
Phone Perm:	619-479-2264	**Bill Code 2:**	Not Applicable
Site Address:	6930 Camino Maquiladora Ste K/L	**Bill Code 3:**	Not Applicable
Parcel No:	646-190-26-00	**Univ Waste Gen Type:**	

Record Ali:	Unified Program Facility Permit
Address:	6930 CAMINO MAQUILADORA, SUITE# K & L
Business Type:	Contractors-Street, Painting, Roofers, Building
Bill Code:	Not Applicable
ER Con Name:	RAMON CASTANARES
ER Con Title:	OWNER
Water Purv:	SAN DIEGO
Fire Agency:	SAN DIEGO
Geo SRC:	Mapped to record APN/Parcel XY center
Match Addr:	
Hirt Flag:	No
Frhmbp Report Filename:	HMBP135952.pdf
Frhmbp Sitemap Filename:	MAP_135952.pdf

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	11 of 13	NW	0.25 / 1,294.15	508.63 / 0	OTAY HYDRAULICS LLC 6930 CAMINO MAQUILADORA STE F SAN DIEGO CA 92154-7513	RCRA NON GEN

EPA Handler ID:	CAL000398978
Gen Status Universe:	No Report
Contact Name:	JOSE HINOJSA/OWNER
Contact Address:	6930 CAMINO MAQUILADORA STE F , , SAN DIEGO , CA, 92154-7513 ,
Contact Phone No and Ext:	619-690-7577
Contact Email:	CYNTHIA.OTAYHYDRAULICS@GMAIL.COM
Contact Country:	
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	
Receive Date:	20140721
Location Latitude:	32.566922
Location Longitude:	-116.991399

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140721
Handler Name: OTAY HYDRAULICS LLC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: JOSE HINOJSA/OWNER
Date Became Current:
Date Ended Current:
Phone: 619-690-7577
Source Type: Implementer
Street No:
Street 1: 6930 CAMINO MAQUILADORA STE F
Street 2:
City: SAN DIEGO
State: CA
Country:
Zip Code: 92154-7513

Owner/Operator Ind: Current Owner
Type: Other
Name: OTAY HYDRAULICS LLC
Date Became Current:
Date Ended Current:
Phone: 619-271-6651
Source Type: Implementer
Street No:
Street 1: 6930 CAMINO MAQUILADORA STE F
Street 2:
City: SAN DIEGO
State: CA
Country:
Zip Code: 92154-7513

23	12 of 13	NW	0.25 / 1,294.15	508.63 / 0	MEDOSA, INC. 6930 CAMINO MAQUILADORA SUITE L SAN DIEGO CA 92154	RCRA NON GEN

EPA Handler ID: CAR000206656
Gen Status Universe: No Report
Contact Name: JULIO C BORRAZ
Contact Address: 6930 , CAMINO MAQUILADORA SUITE L , , SAN DIEGO , CA, 92154 , US
Contact Phone No and Ext: 619-661-0399
Contact Email: MEDOSAINC@AOL.COM
Contact Country: US
County Name: SAN DIEGO
EPA Region: 09
Land Type: Private
Receive Date: 20200108
Location Latitude: 32.567412
Location Longitude: -117.004425

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20100324
Handler Name:	BATTERY & COMPONENTS INC. DBA COMMERCIAL BATTERY
Source Type:	Notification
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Waste Code Details

Hazardous Waste Code:	132
Waste Code Description:	Aqueous solution w/metals (< restricted levels and see waste code 121 for a list of metals)
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20200108
Handler Name:	MEDOSA, INC.
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Waste Code Details

Hazardous Waste Code:	792
Waste Code Description:	Liquids with pH < 2 with metals
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	172
Waste Code Description:	Metal dust (see 121) and machining waste

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	6930 CAMINO MAQUILADORAS
Name:	RAMON CASTANARES	***Street 2:***	STE K AND L
Date Became Current:	19821119	***City:***	SAN DIEGO
Date Ended Current:		***State:***	CA

Phone:	619-661-0380	**Country:**	US
Source Type:	Notification	**Zip Code:**	92154
Owner/Operator Ind:	Current Operator	**Street No:**	6930
Type:	Private	**Street 1:**	CAMINO MAQUILADORA SUITE L
Name:	MEDOSA, INC.	**Street 2:**	
Date Became Current:	20190901	**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-661-0399	**Country:**	US
Source Type:	Notification	**Zip Code:**	92154
Owner/Operator Ind:	Current Owner	**Street No:**	1000
Type:	Private	**Street 1:**	PIONEER WAY
Name:	HAMANN COMPANIES	**Street 2:**	
Date Became Current:	19950815	**City:**	EL CAJON
Date Ended Current:		**State:**	CA
Phone:	619-440-7424	**Country:**	US
Source Type:	Notification	**Zip Code:**	92020
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	ARTURO ZURITA	**Street 2:**	
Date Became Current:	19821119	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Notification	**Zip Code:**	

Historical Handler Details

Receive Dt:	20100324
Generator Code Description:	Large Quantity Generator
Handler Name:	BATTERY & COMPONENTS INC. DBA COMMERCIAL BATTERY

23	*13 of 13*	*NW*	*0.25 / 1,294.15*	*508.63 / 0*	***BATTERY & COMPONENTS, INC.*** ***6930 CAMINO MAQUILADORA*** ***SUITE K*** ***SAN DIEGO CA 92154***	***RCRA NON GEN***

EPA Handler ID:	CAR000306688
Gen Status Universe:	No Report
Contact Name:	ARTURO ZURITA
Contact Address:	6930 , CAMINO MAQUILADORA SUITE K , , SAN DIEGO , CA, 92154 , US
Contact Phone No and Ext:	619-661-0380
Contact Email:	MEDOSAINC02@AOL.COM
Contact Country:	US
County Name:	SAN DIEGO
EPA Region:	09
Land Type:	Private
Receive Date:	20200331
Location Latitude:	32.567412
Location Longitude:	-117.004425

Violation/Evaluation Summary

Note:	NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No

Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200331
Handler Name:	BATTERY & COMPONENTS, INC.
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	792
Waste Code Description:	Liquids with pH < 2 with metals
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	172
Waste Code Description:	Metal dust (see 121) and machining waste

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	1000
Type:	Private	**Street 1:**	PIONEER WAY
Name:	HAMANN COMPANIES	**Street 2:**	
Date Became Current:	19950815	**City:**	EL CAJON
Date Ended Current:		**State:**	CA
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	92020
Owner/Operator Ind:	Current Operator	**Street No:**	6930
Type:	Private	**Street 1:**	CAMINO MAQUILADORA SUITE K
Name:	BATTERY & COMPONENTS, INC.	**Street 2:**	
Date Became Current:	20191001	**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	619-661-0380	**Country:**	US
Source Type:	Notification	**Zip Code:**	92154

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	1 of 1	NNW	0.25 / 1,331.16	511.33 / 2	OTAY MESA ROAD WIDENING NONE OTAY MESA RD SAN DIEGO CA 92173	CLEANUP SITES

Global ID:	T0608166754	**Latitude:**	32.5680299
Status:	COMPLETED - CASE CLOSED	**Longitude:**	-116.9883048
Status Date:	8/15/2012	**County:**	SAN DIEGO
Site Facility Type:	CLEANUP PROGRAM SITE		
Data Source:	Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download		

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:
Local Case No: H36821-001
Begin Date: 4/16/1997
Lead Agency: SAN DIEGO COUNTY LOP
Local Agency: SAN DIEGO COUNTY LOP
CUF Case: NO
CalEnvScreen Score: 66-70%
EPA Region: 9
Qty Rlsd Gallons:
Potential COC:
How Discovered:
Stop Method: Other Means
Stop Description: OTHER MEANS
Case Worker: VAP
Military DoD Site: No
Leak Reported Dt: 1997-04-16 00:00:00
No Further Action Dt: 2012-08-15 00:00:00
Potential Media of Concern: Aquifer used for drinking water supply
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community:
Coordinate Source:
Discharge Cause: Other
Discharge Source: Other
File Location: Local Agency
Site History:

Please refer to "Site Maps/Documents' tab for Closure Memo

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2012-08-15 00:00:00
Action: Closure/No Further Action Letter

Action Type: Other
Date: 1997-04-16 00:00:00
Action: Leak Began

Action Type: Other
Date: 1997-04-16 00:00:00
Action: Leak Reported

Action Type: Other
Date: 1997-04-16 00:00:00
Action: Leak Stopped

Action Type: Other
Date: 1997-04-16 00:00:00
Action: Leak Discovery

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2012-08-15 00:00:00

Status: Open - Remediation
Status Date: 1997-07-01 00:00:00

Status: Open - Case Begin Date
Status Date: 1997-04-16 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: Voluntary Assistance Program (VAP)
Phone No:
Organization Name: SAN DIEGO COUNTY LOP
Email: deh.sam@sdcounty.ca.gov
Address: P.O. Box 129261
City: SAN DIEGO

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608166754
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 8/15/2012
Potential COC: ,
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: H36821-001
CASEWORKER: Voluntary Assistance Program (VAP)
SAN DIEGO RWQCB (REGION 9)
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608166754&tabname=regulatoryhistory
Site History:

Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

Please refer to "Site Maps/Documents' tab for Closure Memo

Sites from GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608166754&enforcement_id=6134851&temptable=ENFORCEMENT
Title Description Comments:

Action Date: 8/15/2012
Received Issue Date: 8/15/2012

Administrative Closure Memo

Action Type: Leak Action
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Date: 4/16/1997
Received Issue Date:

Action Type: Leak Action
Action: Leak Stopped
Doc Link:
Title Description Comments:

Action Date: 4/16/1997
Received Issue Date:

Action Type: Leak Action
Action: Leak Began
Doc Link:
Title Description Comments:

Action Date: 4/16/1997
Received Issue Date:

Action Type: Leak Action
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Date: 4/16/1997
Received Issue Date:

Sites from GeoTracker Search - Documents

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Document Type: Site Documents
Document Date: 8/15/2012
Size :
Title: ADMINISTRATIVE CLOSURE MEMO
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608166754&enforcement_id=6134851
Type: CLOSURE/NO FURTHER ACTION LETTER
Submitted:
Submitted By: ELLEN BEACON (REGULATOR)

Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 8/15/2012

Status: Open - Remediation
Date: 7/1/1997

Status: Open - Case Begin Date
Date: 4/16/1997

25	1 of 6	NNW	0.26 / 1,383.61	510.27 / 1	**BARNHART AND DANTZLER PROPERTY** **900 CACTUS ROAD** **SAN DIEGO CA 92154**	LDS

Global ID: L10007631848
County: San Diego
Latitude: 32.5643147827013
Longitude: -116.989387338623

LDS Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 9 000254N97
Loc Case No:
Status: Completed - Case Closed
Status Date: 1/1/2003
Begin Date:
Case Type: Land Disposal Site
Qty Released Gallons:
Cal Enviroscreen: 56-60%
CUF Case: NO
Potential COC: Lead, Other Metal
Potential Media of Concern: Soil
How Discovered:
How Discovered Description:
Stop Method:
Stop Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community:
Discharge Cause:
Coordinate Source: Google Map Move
Discharge Source:
Site History:
EPA Region: 9
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Caseworker:
Local Agency:
File Location: Local Agency
Military DoD Site: No
Leak Reported Dt:
No Further Action Dt: 2003-01-01 00:00:00

Part of the Tripp Salvage Landfill. Automobile dismantling waste was placed on the Barnhart and Dantzler Property from approximately 1968 to 1977. This material was covered with fill from other landfills in the area. It is estimated that the waste extends to a depth of approximately 65 feet. Groundwater samples collected from this property in 1998 reportedly contained VOCs, SVOCs, and metals. Total area containing waste is approximately 1.1 acres, and an asphalt cap was constructed over the areal extent of the waste in 2001. The County LEA issued "no further action" letter in 2003 for this property.

LDS Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action: Other Report / Document
Date: 2013-10-16 00:00:00
Action Type: RESPONSE

Action: Other Workplan
Date: 2012-10-11 00:00:00

Action Type: RESPONSE

LDS Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2003-01-01 00:00:00

LDS Sites from GeoTracker Search - Regulatory Profile (as of Oct 20, 2021)

Site Facility Name: BARNHART AND DANTZLER PROPERTY
Site Facility Type: LAND DISPOSAL SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
Potential COC: LEAD, OTHER METAL
WDR Place Type:
Wdr File No:
Wdr Order No:
Address: 900 CACTUS ROAD
City: SAN DIEGO
Zip: 92154
County: SAN DIEGO
Cuf Claim No:
CUF Priority Assig:
CUF Amount Paid:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=L10007631848
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 1/1/2003
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=L10007631848&tabname=regulatoryhistory
Potential Media of Concern: SOIL
User Defined Beneficial Use:
DWR GW Sub Basin:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Facility Type: TITLE 27 - MUNICIPAL SOLID WASTE LANDFILL
Composting Method:
Gndwater Monitoring Frequen:
Cleanup Oversight Agencies: SAN DIEGO RWQCB (REGION 9) (LEAD) - CASE #: 9 000038N90
SAN DIEGO RWQCB (REGION 9) - CASE #: 9 000254N97
SAN DIEGO RWQCB (REGION 9) - CASE #: 2092600
File Location: LOCAL AGENCY
Site History:

Part of the Tripp Salvage Landfill. Automobile dismantling waste was placed on the Barnhart and Dantzler Property from approximately 1968 to 1977. This material was covered with fill from other landfills in the area. It is estimated that the waste extends to a depth of approximately 65 feet. Groundwater samples collected from this property in 1998 reportedly contained VOCs, SVOCs, and metals. Total area containing waste is approximately 1.1 acres, and an asphalt cap was constructed over the areal extent of the waste in 2001. The County LEA issued "no further action" letter in 2003 for this property.

LDS Sites from GeoTracker Search - Cleanup Status History (as of Oct 20, 2021)

Status: Completed - Case Closed
Date: 1/1/2003

LDS Sites from GeoTracker Search - Regulatory Activities (as of Oct 20, 2021)

Action Type: Response Requested - Workplans
Action: Other Workplan
Action Date: 10/11/2012
Received Issue Date: 10/11/2012
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10007631848&doc_id=5816539
Title Description Comment: Otay Mesa Community Plan Update - Updated Hazardous Materials Technical Study

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date: 10/16/2013
Received Issue Date: 10/16/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10007631848&doc_id=5816538
Title Description Comment: Approval of the Cactus Road - AKA Tripp Salvage Disposal Site Remediation Project

LDS Sites from GeoTracker Search - Documents (as of Oct 20, 2021)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Document Type:	Site Documents	**Size:**	
Document Date:	10/16/2013	**Submitted By:**	JOHN P. ANDERSON (REGULATOR)
Type:	OTHER REPORT / DOCUMENT	**Submitted:**	
Title:	APPROVAL OF THE CACTUS ROAD - AKA TRIPP SALVAGE DISPOSAL SITE REMEDIATION PROJECT		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=L10007631848&document_id=5816538		

Document Type:	Site Documents	**Size:**	
Document Date:	10/11/2012	**Submitted By:**	JOHN P. ANDERSON (REGULATOR)
Type:	OTHER WORKPLAN	**Submitted:**	
Title:	OTAY MESA COMMUNITY PLAN UPDATE - UPDATED HAZARDOUS MATERIALS TECHNICAL STUDY		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=L10007631848&document_id=5816539		

LDS Sites from GeoTracker Search - Related Cases (as of Oct 20, 2021)

Identifier:	SL209274202	**Address:**	1890 CACTUS ROAD
Project Name:	SESI PROPERTY - AKA Tripp Salvage Landfill	**City:**	SAN DIEGO
Status:	COMPLETED - CASE CLOSED	**Association:**	Related Global ID
Description:			
Project Link:	https://geotracker.waterboards.ca.gov/profile_report?global_id=SL209274202		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	2 of 6	NNW	0.26 / 1,383.61	510.27 / 1	**Tripp Salvage Landfill** **900 Cactus Rd** **San Ysidro CA 91973**	CDO/CAO

Facility ID:	266502	**Design Flow:**	
Facility Type:	All other facilities	**Complexity:**	
Status:	Never Active	**Pretreatment:**	
Status Date:	2/20/2013	**Fee Code:**	
Place Type:	Facility	**SIC Code 1:**	9511
Place Sub Type:		**SIC Desc 1:**	Air and Water Resource and Solid Waste Management
Agency Type:	County Agency	**SIC Code 2:**	
No of Agencies:	1	**SIC Desc 2:**	
Program:	LNDISP	**SIC Code 3:**	
No of Programs:	1	**SIC Desc 3:**	
WD ID:	9 000255N97	**NAICS Code 1:**	
Reg Measure ID:	161633	**NAICS Desc 1:**	
Region 1:	9	**NAICS Code 2:**	
Order No:		**NAICS Desc 2:**	
NPDES No Cano:		**NAICS Code 3:**	
Major Minor:		**NAICS Desc 3:**	
NPDES Type:		**No of Places:**	3
Reclamation:		**Staff Assigned:**	Brian McDaniel
Dredge Fill Fee:		**Place County:**	San Diego
A301H:		**Place Latitude:**	
Effective Date:		**Place Longitude:**	
Region:	9	**Source of Facility:**	Reg Meas
Agency Name:	Signal Landmark Inc Morrism		
Status 1:	Active		
Facility Waste Type:			
Facility Waste Type 3:			
Facility Waste Type 4:			
Facility Waste Type 2:			
Title:	Enforcement - 9 000255N97		
Description:	UNKNOWN		
Threat to Water Quality:			
Reg Measure Type:	Unregulated		
Program 1:	LNDISP		
No of Programs 1:	1		
Enforcement ID EID:	220520		
Order Resolution No:	LT961211		
Enforcement Action Type:	Clean-up and Abatement Order		
Effective Date 1:	12/11/1996		
Year Effective:			
Adoption Issuance Date:			
Achieve Date:			
Year Effective2:			

ACL Issuance Date:	
EPL Issuance Date:	
Latest Milestone Completion Da:	
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability Amount:	0
Project Amount:	0
Application Fee Amt Received:	
Liability Paid:	0
Project Completed:	0
Total Paid Completed Amount:	0
Agency Issuing Enf:	
Date of Oldest Violation Linke:	
Rank 1 Violations:	0
Rank 2 Violations:	0
Rank 3 Violations:	0
Unclassified Violations:	0
Atox Violations No:	0
Expiration Review Date:	
Termination Date:	
WDR Review Amend:	
WDR Review Revise Renew:	
WDR Review Resc Ind:	
WDR Review No Action Required:	
WDR Review Pending:	
WDR Review Planned:	
Status Enrollee:	No
Individual General:	I
No of Staff Assigned:	1
Supervisor:	David Barker
No of Supervisors:	1
Direction Voice:	Passive
Region 2:	9
Assigned Staff:	
No of Assigned Staff:	
Supervisor2:	
No of Supervisors 1:	

Program Category:	LNDISP	Tot No of VIO Linked :	0
Program Category 1:	LNDISP	Ctox Violations No:	0
Late Report VIO No:	0	Dfcnt Monitor VIO No:	0
OEV VIO No:	0	Dfcnt Report VIO No:	0
Other Codes VIO No:	0	Enfcmt Act VIO No:	0
Permit Condit VIO No:	0	Fees Violations No:	0
Pretreatment VIO No:	0	Groundwater VIO No:	0
SSO Violations No:	0	Hydro Mod VIO No:	0
Surface Wtr VIO No:	0	Effluent MMP Serious:	0
SWPPP Violations No:	0	Chronic MMP:	0
Total MMP VIO No:	0	Report MMP Serious:	0
Priority Violations:	0	Economic Benefit:	
BMP Violations No:	0	Staff Cost:	
Cat1 Violations No:	0	Max Pot Liability:	
Cat2 Violations No:	0	Termination Date 1:	
Reporting F to Notify VIO No:	0		
Unauthorized Discharge VIO No:	0		
Basin Plan Prohibition VIO:	0		

25	3 of 6	NNW	0.26 / 1,383.61	510.27 / 1	SESI Tripp Salvage 900 Cactus Rd San Ysidro CA 91973	CDO/CAO

Facility ID:	256370	Design Flow:	
Facility Type:	Solid Waste Class II - designated wastes	Complexity:	
Status:	Never Active	Pretreatment:	
Status Date:	2/20/2013	Fee Code:	

Place Type:	Waste Management Unit	**SIC Code 1:**	4953
Place Sub Type:	Land fill	**SIC Desc 1:**	Refuse Systems
Agency Type:	Privately-Owned Business	**SIC Code 2:**	
No of Agencies:	1	**SIC Desc 2:**	
Program:	LNDISP	**SIC Code 3:**	
No of Programs:	1	**SIC Desc 3:**	
WD ID:	9 000254N97	**NAICS Code 1:**	
Reg Measure ID:	161632	**NAICS Desc 1:**	
Region 1:		**NAICS Code 2:**	
Order No:		**NAICS Desc 2:**	
NPDES No Cano:		**NAICS Code 3:**	
Major Minor:		**NAICS Desc 3:**	
NPDES Type:		**No of Places:**	1
Reclamation:		**Staff Assigned:**	Brian McDaniel
Dredge Fill Fee:		**Place County:**	San Diego
A301H:		**Place Latitude:**	
Effective Date:		**Place Longitude:**	
Region:	9	**Source of Facility:**	Reg Meas
Agency Name:	Sesi, Salim D		
Status 1:	Active		
Facility Waste Type:			
Facility Waste Type 3:			
Facility Waste Type 4:			
Facility Waste Type 2:			
Title:	Enforcement - 9 000254N97		
Description:	UNKNOWN		
Threat to Water Quality:			
Reg Measure Type:	Unregulated		
Program 1:	LNDISP		
No of Programs 1:	1		
Enforcement ID EID:	220521		
Order Resolution No:	LT961211		
Enforcement Action Type:	Clean-up and Abatement Order		
Effective Date 1:	12/11/1996		
Year Effective:			
Adoption Issuance Date:			
Achieve Date:			
Year Effective2:			
ACL Issuance Date:			
EPL Issuance Date:			
Latest Milestone Completion Da:			
Total Assessment Amount:	0		
Initial Assessed Amount:	0		
Liability Amount:	0		
Project Amount:	0		
Application Fee Amt Received:			
Liability Paid:	0		
Project Completed:	0		
Total Paid Completed Amount:	0		
Agency Issuing Enf:			
Date of Oldest Violation Linke:			
Rank 1 Violations:	0		
Rank 2 Violations:	0		
Rank 3 Violations:	0		
Unclassified Violations:	0		
Atox Violations No:	0		
Expiration Review Date:			
Termination Date:			
WDR Review Amend:			
WDR Review Revise Renew:			
WDR Review Resc Ind:			
WDR Review No Action Required:			
WDR Review Pending:			
WDR Review Planned:			
Status Enrollee:	No		
Individual General:	I		
No of Staff Assigned:	1		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Supervisor:	
No of Supervisors:	
Direction Voice:	Passive
Region 2:	9
Assigned Staff:	
No of Assigned Staff:	
Supervisor2:	
No of Supervisors 1:	

Program Category:	LNDISP	Tot No of VIO Linked :	0
Program Category 1:	LNDISP	Ctox Violations No:	0
Late Report VIO No:	0	Dfcnt Monitor VIO No:	0
OEV VIO No:	0	Dfcnt Report VIO No:	0
Other Codes VIO No:	0	Enfcmt Act VIO No:	0
Permit Condit VIO No:	0	Fees Violations No:	0
Pretreatment VIO No:	0	Groundwater VIO No:	0
SSO Violations No:	0	Hydro Mod VIO No:	0
Surface Wtr VIO No:	0	Effluent MMP Serious:	0
SWPPP Violations No:	0	Chronic MMP:	0
Total MMP VIO No:	0	Report MMP Serious:	0
Priority Violations:	0	Economic Benefit:	
BMP Violations No:	0	Staff Cost:	
Cat1 Violations No:	0	Max Pot Liability:	
Cat2 Violations No:	0	Termination Date 1:	
Reporting F to Notify VIO No:	0		
Unauthorized Discharge VIO No:	0		
Basin Plan Prohibition VIO:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	4 of 6	NNW	0.26 / 1,383.61	510.27 / 1	BARNHARDT-DANTZLER-TRIPP SALVA 900 CACTUS RD SAN YSIDRO CA 91973	WMUD

Wmu ID No:	9 000255N97	Npid:	
Wds ID No:	9 000255N97	Rptf:	
Swis ID No:		Sic1:	4953
Reg ID No:		Sic2:	
Edit Date:		Swat Anms:	
Last Edit:		Swat Fnms:	
Region:	9	Atyp:	CO
County:	37	Anms:	SIGNAL LANDMARK, INC MORRISM
Wds:	TRUE	Adep:	
Msw:		A Street:	345 CALIFORNIA ST
Superorder:		A City:	SAN FRANCISCO CA
Sc15:	TRUE	A Zip:	94104
Swat:	FALSE	A County:	BARRY SANDALS
Tpca:	FALSE	Afon:	4156777000
Rcra:	FALSE	Lnms:	
Dod:		Ldep:	
Rbpo:	BKM	L Street:	
Openpub:		L City:	
Waste List:		L State:	
Tot Wmus:	1	L Zip:	
Secrange:		L County:	
Basemer:		Lfon:	
Fcnt:		Ttwq:	
Fdep:		Toxi:	N
F State:	CA	Cplx:	
Ffon:		Wdrs:	A
Ftyp:	SW2	Wtp1:	DCNSOIL
Tonnage:		Wtp2:	
Fac Comment:			

WMU Details

Wmu ID:	9 000255N97-01	G Monitor:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Edit Date:		**S Monitor:**	
Last Edit:		**V Monitor:**	
Wmu Type:		**G Back:**	
Wmu Name:	BARNHARDT-DANTZLER-TRIPP SALVA	**S Back:**	
Wmustatus:		**V Back:**	
Wmu Size:		**G Nonback:**	
Listed:		**S Nonback:**	
Printed:		**V Nonback:**	
Msw:		**G Date:**	
Superorder:		**S Date:**	
Sc15:	TRUE	**V Date:**	
Swat:	FALSE	**Perm Test:**	
Tpca:	FALSE	**Gw Depth:**	
Rcra:	FALSE	**Precip:**	
Dod:		**Site Alt:**	
Old Class:		**Site Alta:**	
Old Waste:		**Line Alt:**	
Old First:		**Line Alta:**	
New Class:		**Lcrs Alt:**	
New Waste:		**Lcrs Alta:**	
New First:		**Composite:**	
Stat Date:		**Line Des:**	
Cap Year:		**Liner1:**	
Closeplan:		**Line1 Type:**	
Township:		**Liner2:**	
Fault Name:		**Line2 Type:**	
Fault Distance:		**Liner3:**	
Withquake:		**Line3 Type:**	
Type Op:			
Gen Com1:			
Gen Com2:			
Gen Com3:			
Gen Com4:			
Formation:			
Form Type:			
Form Permit:			
Form Com1:			
Form Com2:			
Form Com3:			
Form Com4:			
Liner Com:			
Lcrs:			
Lcrs Type:			
Lcrs Des:			
Cons Com1:			
Cons Com2:			
Cons Com3:			
Cons Com4:			

25	5 of 6	NNW	0.26 / 1,383.61	510.27 / 1	**TRIPP SALVAGE LANDFILL** **900 CACTUS RD** **SAN YSIDRO CA 91973**	WMUD

Wmu ID No:	9 000038N90	**Npid:**	
Wds ID No:	9 000038N90	**Rptf:**	
Swis ID No:		**Sic1:**	9511
Reg ID No:		**Sic2:**	
Edit Date:		**Swat Anms:**	TRIPP SALVAGE
Last Edit:		**Swat Fnms:**	AUTO SHREDDER WASTE DISPOSAL
Region:	9	**Atyp:**	PR
County:	37	**Anms:**	FRED L TRIPP
Wds:	TRUE	**Adep:**	
Msw:	FALSE	**A Street:**	900 CACTUS RD
Superorder:		**A City:**	SAN YSIDRO CA
Sc15:	TRUE	**A Zip:**	91973
Swat:	TRUE	**A County:**	MR. KYRIAKOS
Tpca:	FALSE	**Afon:**	
Rcra:	FALSE	**Lnms:**	UNKNOWN

Dod:		**Ldep:**	
Rbpo:	CAT	**L Street:**	
Openpub:	FALSE	**L City:**	
Waste List:		**L State:**	
Tot Wmus:	1	**L Zip:**	
Secrange:		**L County:**	
Basemer:		**Lfon:**	
Fcnt:		**Ttwq:**	
Fdep:		**Toxi:**	
F State:	CA	**Cplx:**	
Ffon:		**Wdrs:**	A
Ftyp:	OTH	**Wtp1:**	NSLDWST
Tonnage:	0	**Wtp2:**	
Fac Comment:			

WMU Details

Wmu ID:	9 000038N90-01	**G Monitor:**	FALSE
Edit Date:	23-May-1995	**S Monitor:**	FALSE
Last Edit:	JHMJHMJHM	**V Monitor:**	FALSE
Wmu Type:	WASTE PILE	**G Back:**	0
Wmu Name:	TRIPP SALVAGE LANDFILL	**S Back:**	0
Wmustatus:	CEASE DISCHARGE	**V Back:**	0
Wmu Size:		**G Nonback:**	0
Listed:		**S Nonback:**	0
Printed:		**V Nonback:**	0
Msw:	FALSE	**G Date:**	
Superorder:		**S Date:**	
Sc15:	TRUE	**V Date:**	
Swat:	TRUE	**Perm Test:**	
Tpca:	FALSE	**Gw Depth:**	0
Rcra:	FALSE	**Precip:**	10
Dod:	FALSE	**Site Alt:**	FALSE
Old Class:		**Site Alta:**	FALSE
Old Waste:		**Line Alt:**	FALSE
Old First:		**Line Alta:**	FALSE
New Class:	UNK	**Lcrs Alt:**	FALSE
New Waste:		**Lcrs Alta:**	FALSE
New First:		**Composite:**	
Stat Date:		**Line Des:**	FALSE
Cap Year:		**Liner1:**	FALSE
Closeplan:	FALSE	**Line1 Type:**	
Township:		**Liner2:**	FALSE
Fault Name:	UNKNOWN	**Line2 Type:**	
Fault Distance:		**Liner3:**	FALSE
Withquake:	FALSE	**Line3 Type:**	
Type Op:			
Gen Com1:			
Gen Com2:			
Gen Com3:			
Gen Com4:			
Formation:	UNKNOWN		
Form Type:	UNKNOWN		
Form Permit:	UNKNOWN		
Form Com1:			
Form Com2:			
Form Com3:			
Form Com4:			
Liner Com:			
Lcrs:	FALSE		
Lcrs Type:			
Lcrs Des:	FALSE		
Cons Com1:			
Cons Com2:			
Cons Com3:			
Cons Com4:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	6 of 6	NNW	0.26 / 1,383.61	510.27 / 1	SESI TRIPP SALVAGE 900 CACTUS RD SAN YSIDRO CA 91973	WMUD

Wmu ID No:	9 000254N97	**Npid:**	
Wds ID No:	9 000254N97	**Rptf:**	
Swis ID No:		**Sic1:**	4953
Reg ID No:		**Sic2:**	
Edit Date:		**Swat Anms:**	
Last Edit:		**Swat Fnms:**	
Region:	9	**Atyp:**	SD
County:	37	**Anms:**	MCKENNA+CUNEO CO. "SESI GROUP"
Wds:	TRUE	**Adep:**	
Msw:		**A Street:**	750 B ST, STE 3200
Superorder:		**A City:**	SAN DIEGO CA
Sc15:	TRUE	**A Zip:**	92101
Swat:	FALSE	**A County:**	RICHARD OPPEN
Tpca:	FALSE	**Afon:**	6195955400
Rcra:	FALSE	**Lnms:**	
Dod:		**Ldep:**	
Rbpo:	BKM	**L Street:**	
Openpub:		**L City:**	
Waste List:		**L State:**	
Tot Wmus:	1	**L Zip:**	
Secrange:		**L County:**	
Basemer:		**Lfon:**	
Fcnt:		**Ttwq:**	
Fdep:		**Toxi:**	N
F State:	CA	**Cplx:**	
Ffon:		**Wdrs:**	A
Ftyp:	SW2	**Wtp1:**	DCNSOIL
Tonnage:		**Wtp2:**	
Fac Comment:			

WMU Details

Wmu ID:	9 000254N97-01	**G Monitor:**	
Edit Date:		**S Monitor:**	
Last Edit:		**V Monitor:**	
Wmu Type:		**G Back:**	
Wmu Name:	SESI- TRIPP SALVAGE	**S Back:**	
Wmustatus:		**V Back:**	
Wmu Size:		**G Nonback:**	
Listed:		**S Nonback:**	
Printed:		**V Nonback:**	
Msw:		**G Date:**	
Superorder:		**S Date:**	
Sc15:	TRUE	**V Date:**	
Swat:	FALSE	**Perm Test:**	
Tpca:	FALSE	**Gw Depth:**	
Rcra:	FALSE	**Precip:**	
Dod:		**Site Alt:**	
Old Class:		**Site Alta:**	
Old Waste:		**Line Alt:**	
Old First:		**Line Alta:**	
New Class:		**Lcrs Alt:**	
New Waste:		**Lcrs Alta:**	
New First:		**Composite:**	
Stat Date:		**Line Des:**	
Cap Year:		**Liner1:**	
Closeplan:		**Line1 Type:**	
Township:		**Liner2:**	
Fault Name:		**Line2 Type:**	
Fault Distance:		**Liner3:**	
Withquake:		**Line3 Type:**	
Type Op:			
Gen Com1:			
Gen Com2:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Gen Com3:
Gen Com4:
Formation:
Form Type:
Form Permit:
Form Com1:
Form Com2:
Form Com3:
Form Com4:
Liner Com:
Lcrs:
Lcrs Type:
Lcrs Des:
Cons Com1:
Cons Com2:
Cons Com3:
Cons Com4:

---

26 | **1 of 2** | **NNW** | **0.28 / 1,468.25** | **513.88 / 5** | **U S BORDER PATROL/BROWN FIELD**
7060 BOEING ST
San Diego CA

SAM
SANDIEGO

Record ID:	DEH1987-LSAM-H21496-001	**Primary Parcel:**	YES
Record ID (DEH Lyr):	DEH1987-LSAM-H21496-001	**Primary Address:**	YES
ID:	924	**Address Type:**	ALIAS
Object ID:	923	**Street String:**	7060 BOEING ST
SWRCB Global ID:	T0608177377	**Community:**	San Diego
Feature ID:	6460500300	**Zip Code:**	92173-1728
Parcel No:	646-050-03-00	**Zip Community:**	92154
Case No:	H21496-001	**Jurisdiction:**	SAN DIEGO
H No:	H21496	**Census Tract:**	100.14
KIVA per Tp per No:	6SAM H21496	**GT Global ID:**	T0608177377
Status:	Completed	**GT RB Case No:**	
Historical Name:	U S BORDER PATROL/BROWN FIELD	**GT Status:**	Completed - Case Closed
Record Name:	U S BORDER PATROL/BROWN FIELD	**GT Status Date:**	6/30/1987 8:00 PM
Project Name:	U S BORDER PATROL/BROWN FIELD	**GT Case Type:**	Cleanup Program Site
Record Status:	Completed	**GT Lead Agency:**	SAN DIEGO COUNTY LOP
Record Type:	SAM Investigation	**GT CUF Case:**	NO
Record Alias:	SAM Investigation	**GT County:**	San Diego
Date:	02/19/1987	**GT Longitude:**	-116.988442
Per Type:	LWQD	**GT Latitude:**	32.568371
DEH Permit Owner:		**Agency Name:**	COSD
Fire Agency:	SAN DIEGO	**Lead Agency:**	DEH/SAM
Point X:	6333932.4950688	**Lead Agcy Date:**	2/18/1987 7:00 PM
Point Y:	1787452.70395073	**Opened Date:**	2/18/1987 7:00 PM
Latitude GS84:	32.5753625	**ThomasBros Map Gd:**	1351 E 1
Longitude GS84:	-116.9834182	**Funding:**	N - Non-Billable
Watershed Basin:	910.2	**BOS District:**	1
Water Purveyor:	SAN DIEGO	**Short Notes:**	

Address: 7060 BOEING ST, SAN YSIDRO CA 921731728
Case Type:
Geo SRC: Mapped to XY from previous SAM Layer
Record Type (DEH Lyr): LUEG-DEH/LWQD/SAM Investigation/NA
Source File: Citizen Access DEH Site Assessment and Mitigation Investigation Sites; San Diego Site Assessment and Mitigation Investigation Sites

---

26 | **2 of 2** | **NNW** | **0.28 / 1,468.25** | **513.88 / 5** | **U S BORDER PATROL/BROWN FIELD**
7060 BOEING ST
SAN DIEGO CA 921731728

CLEANUP
SITES

Global ID:	T0608177377	**Latitude:**	32.568371
Status:	COMPLETED - CASE CLOSED	**Longitude:**	-116.988442
Status Date:	7/1/1987	**County:**	SAN DIEGO
Site Facility Type:	CLEANUP PROGRAM SITE		

Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:
Local Case No: H21496-001
Begin Date: 2/19/1987
Lead Agency: SAN DIEGO COUNTY LOP
Local Agency: SAN DIEGO COUNTY LOP
CUF Case: NO
CalEnvScreen Score: 56-60%
EPA Region: 9
Qty Rlsd Gallons:
Potential Media of Concern: Under Investigation
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community: Severely Disadvantaged Community
Coordinate Source: Google Geocode
Discharge Cause:
Discharge Source:
File Location: Local Agency
Site History:

Potential COC: Gasoline
How Discovered:
Stop Method:
Stop Description:
Case Worker: KH
Military DoD Site: No
Leak Reported Dt: 1987-02-19 00:00:00
No Further Action Dt: 1987-07-01 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: Other
Date: 1987-02-19 00:00:00
Action: Leak Discovery

Action Type: Other
Date: 1987-02-19 00:00:00
Action: Leak Began

Action Type: Other
Date: 1987-02-19 00:00:00
Action: Leak Reported

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 1987-07-01 00:00:00

Status: Open - Case Begin Date
Status Date: 1987-02-19 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: KEVIN HEATON
Phone No:
Organization Name: SAN DIEGO COUNTY LOP
Email: kevin.heaton@sdcounty.ca.gov

Address: P.O. Box 129261
City: San Diego

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: LOCAL AGENCY

Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608177377
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 7/1/1987
Potential COC: GASOLINE
Potential Media of Concern: UNDER INVESTIGATION
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: H21496-001
CASEWORKER: KEVIN HEATON
SAN DIEGO RWQCB (REGION 9)
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608177377&tabname=regulatoryhistory
Site History:

No site history available

Sites from GeoTracker Search - Regulatory Activities

Action Type: Leak Action
Action: Leak Began
Action Date: 2/19/1987
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Discovery
Action Date: 2/19/1987
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Reported
Action Date: 2/19/1987
Received Issue Date:
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 7/1/1987

Status: Open - Case Begin Date
Date: 2/19/1987

27	1 of 1	NNW	0.28 / 1,491.90	513.83 / 5	**U S BORDER PATROL/BROWN FIELD** **7060 BOEING ST, SAN YSIDRO, CA 92173-1728** **SAN YSIDRO CA**	LOP SANDIEGO

SWRCB Global ID: T0608177377
Record ID: DEH1987-LSAM-H21496-001
Record Status: Completed
Opened Date: 2/19/1987
Case Type: FIT - Failed Integrity Test
Historical Name: U S BORDER PATROL/BROWN FIELD
Lead Agency: DEH/SAM
Lead Agency Date: 2/19/1987
Funding: N - Non-Billable
Fire Agency: SAN DIEGO
Parcel No: 646-050-03-00
Census Tract: 100.14
Zip Code 2: 92154
Community: San Diego
Jurisdiction: SAN DIEGO
Watershed Basin No: 910.2
Latitude GS 84: 32.5753625
Longitude GS 84: -116.9834182
X Map Coord: 6334469.504
Y Map Coord: 1789750.822

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Water Purveyor:		SAN DIEGO				
File Case Type:		FAILED INTEGRITY TESTS (CLOSED)				
28	1 of 1	E	0.32 / 1,676.21	501.18 / -8	STEELCASE, INC 7510 AIRWAY RD SAN DIEGO CA 92154	DELISTED HAZ
Siteid:		157115				
Latitude:		32.561195				
Longitude:		-116.978722				
Original Source:		CHAZ				
Record Date:		20-OCT-2017				
29	1 of 3	ESE	0.32 / 1,698.04	499.25 / -10	BRITANNIA BOULEVARD PROPERTY 2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154	VCP

Estor/EPA ID:	37070001	**Permit Renewal Lead:**	
Site Code:	401185	**Project Manager:**	
Nat Priority List:	NO	**Supervisor:**	PATRICK HSIEH
Acres:	19 ACRES	**Public Partici Spclst:**	
Special Program:	VOLUNTARY AGREEMENT - PROSPECTIVE PURCHASER PROGRAM	**Census Tract:**	6073010015
Funding:	SITE PROPONENT	**County:**	SAN DIEGO
Assembly District:	80	**Latitude:**	32.5602
Senate District:	40	**Longitude:**	-116.9786
School District:			

APN: 646-110-20, 646-110-20
Cleanup Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
Site Type: VOLUNTARY AGREEMENT
Office: CLEANUP CYPRESS
Past Use that Caused Contam: DISTRIBUTOR - CHEMICAL
Potential Media Affected: SOIL
Potential Contamin of Concern:

CHLOROFORM

Site History:

The property is located at the southeast corner of Britannia Boulevard and Airway Road, in San Diego, California. The property consists of a multi-tenant commercial/industrial business park on a sub-division consisting of eight parcels totaling approximately 19 acres. From 1930 through 2000, the property was used historically for agriculture purposes and pesticides and herbicides were routinely applied to soils.

In a PEA report completed in November 2002, 4,4'-DDD, 4,4'-DDE, 4,4'-DDT, and toxaphene were detected in soil samples collected at the site. Based on the final risk evaluation in the report, toxaphene exceeded appropriate risk levels for unrestricted use.

In October 2003, DTSC and Chiquita Frupac Incorporated signed a Land Use Covenant (LUC), restricting the property to commercial/industrial use. DTSC conducts annual inspections at the site to assure compliance with LUC provisions.

Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY - LAND USE RESTRICTIONS
Program Type: VOLUNTARY CLEANUP
CalEnviroScreen Score: 55-60%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=37070001

Land Use Restrictions

Site Management Requirements: ASPHALT COVER NOT TO BE DISTURBED WITHOUT APPROVAL
CHECK FOR CRACKS IN FOUNDATION
DAY CARE CENTER PROHIBITED
ELDER CARE CENTER PROHIBITED

HOSPITAL USE PROHIBITED
NOTIFY AFTER CHANGE OF PROPERTY OWNER
NOTIFY PRIOR TO CHANGE IN LAND USE
NOTIFY PRIOR TO DEVELOPMENT
RAISING OF FOOD PROHIBITED
RESIDENCE USE PROHIBITED

Title: Deed Restriction / Land Use Covenant
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&global_id=37070001&enforcement_id=5005224
Date Recorded: 11/4/2003

Site Management Requirements: NONE SPECIFIED
Title: LUC Annual Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/view_document?docurl=/public/deliverable_documents/7756010293/Annual%20LUC%20Inspection%20Rpt%2E%2020160912%20%2DBritannia%20Property%2Epdf
Date Recorded: 9/12/2016

Completed Activities

Title: Cost Estimate Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60343804
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/26/2013
Comments:

Title: FY 2017 - 2018 Annual Cost Est. Ltr.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60420474
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 2/15/2018
Comments:

Title: 2018 - 2019 Annual Cost Est.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60441493
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/5/2018
Comments:

Title: Voluntary Cleanup Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5004760
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Standard Voluntary Agreement
Date Completed: 9/30/2002
Comments: A Voluntary Cleanup Agreement (VCA) was signed on 9/30/02 to conduct a Preliminary Endangerment Assessment (PEA).

Title: Annual Site inspection report Sept. 22, 2011
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60281807
Area Name:
Area Link:
Sub Area:
Sub Area Link:

Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/27/2011
Comments: Completed.

Title: Annual Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403461
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/2/2015
Comments: 2016 Annual Cost Estimate

Title: Site visit Form for deed rest.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6011415
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/4/2007
Comments: A site visit was conducted by DTSC on 8/29/07, the site remains capped and the restrictions still apply. A covenant to restrict the property was executed on 3/26/2004 between DTSC and Otay Crossing, Inc. The following restrictions apply to the site: Not to be used as a residence, including mobile home or factory home built housing, a hospital for humans, a public school for person under 21 years of age, a day care center for children, convalescent homes, or any use that include full-time human habitation.

Title: LUC Annual Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403304
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Date Completed: 9/12/2016
Comments: Annual LUC Inspection Completed on August 16, 2016

Title: Alert Notice Responses
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60284012
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 11/14/2011
Comments:

Title: Annual Cost Estimate 2012
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60281037
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/10/2011
Comments:

Title: Annual LUR Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6017266
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/25/2009
Comments: Annual Land Use Restriction Inspection completed.

Title: 2017 Annual LUC Site Inspection Report

Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60438466
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 11/28/2017
Comments: LUC inspection conducted on 20171116

Title: Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60475330
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 6/21/2021
Comments:

Title: Site Visit
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60370427
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/12/2014
Comments: Completed.

Title: Annual Cost Estimate Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60385472
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/3/2014
Comments:

Title: Prospective Purchaser Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5005223
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Prospective Purchaser Agreement
Date Completed: 3/26/2004
Comments:

Title: Annual Deed/LUC Site Visit
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6011555
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/4/2008
Comments:

Title: Preliminary Endangerment Assessment Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=5005226
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 8/28/2002
Comments: DTSC reviewed and approved the PEA with a recommendation for a Deed Restriction of the land to be used for commercial/ industrial use only.

Title: Annual Cost Estimate 2013
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60312467
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/9/2012
Comments:

Title: Deed Restriction / Land Use Covenant
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5005224
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Date Completed: 11/4/2003
Comments: DEED - RESTR: A deed restriction was recorded with San Diego County Recorder's Office on Nov. 4, 2003. The deed restriction restricted sensitive land use (residential, hospital, day care, school, and any use that includes full-time human habitation).

Title: 2019 - 2020 Annual Cost Est.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60459081
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/20/2019
Comments:

Title: 2020 - 2021 Annual Cost Est. Ltr.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60472381
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/9/2020
Comments:

Title: Annual Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60370408
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/9/2012
Comments:

Title: 2019 - Annual LUC Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60463012
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 1/14/2020
Comments:

Title: Annual Cost Estimate - FY 2021/2022
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60489364
Area Name:
Area Link:
Sub Area:
Sub Area Link:

Document Type: Annual Oversight Cost Estimate
Date Completed: 12/24/2021
Comments:

Title: Annual inspection report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60258023
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/10/2010
Comments: Completed.

Title: 2018 - Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60417221
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 1/14/2020
Comments:

Title: Annual Cost Estimate (FY 2016 - 2017)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403514
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/22/2016
Comments: FY 2016 - 2017 Cost Est. Completed 11-22-2016

Title: Site Visit Form for Deed Restrictions
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6009885
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 8/25/2006
Comments:

29	2 of 3	ESE	0.32 / 1,698.04	499.25 / -10	**BRITANNIA BOULEVARD PROPERTY** **2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD &** **7577 AIRWAY ROAD** **OTAY MESA CA 92154**	LUR

Estor/EPA ID: 37070001
Site Code: 401185
Nat Priority List: NO
Acres: 19 ACRES
Special Program: VOLUNTARY AGREEMENT - PROSPECTIVE PURCHASER PROGRAM
Funding: SITE PROPONENT
Assembly District: 80
Senate District: 40
School District:
Permit Renewal Lead:
Project Manager:
Supervisor: PATRICK HSIEH
Public Partici Spclst:
Census Tract: 6073010015
County: SAN DIEGO
Latitude: 32.5602
Longitude: -116.9786
APN: 646-110-20, 646-110-20
Cleanup Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
Site Type: VOLUNTARY AGREEMENT
Office: CLEANUP CYPRESS
Past Use that Caused Contam: DISTRIBUTOR - CHEMICAL
Potential Media Affected: SOIL

Potential Contamin of Concern:

CHLOROFORM

Site History:

The property is located at the southeast corner of Britannia Boulevard and Airway Road, in San Diego, California. The property consists of a multi-tenant commercial/industrial business park on a sub-division consisting of eight parcels totaling approximately 19 acres. From 1930 through 2000, the property was used historically for agriculture purposes and pesticides and herbicides were routinely applied to soils.

In a PEA report completed in November 2002, 4,4'-DDD, 4,4'-DDE, 4,4'-DDT, and toxaphene were detected in soil samples collected at the site. Based on the final risk evaluation in the report, toxaphene exceeded appropriate risk levels for unrestricted use.

In October 2003, DTSC and Chiquita Frupac Incorporated signed a Land Use Covenant (LUC), restricting the property to commercial/industrial use. DTSC conducts annual inspections at the site to assure compliance with LUC provisions.

Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY - LAND USE RESTRICTIONS
Program Type: VOLUNTARY CLEANUP
CalEnviroScreen Score: 55-60%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=37070001

Land Use Restrictions

Site Management Requirements: ASPHALT COVER NOT TO BE DISTURBED WITHOUT APPROVAL
CHECK FOR CRACKS IN FOUNDATION
DAY CARE CENTER PROHIBITED
ELDER CARE CENTER PROHIBITED
HOSPITAL USE PROHIBITED
NOTIFY AFTER CHANGE OF PROPERTY OWNER
NOTIFY PRIOR TO CHANGE IN LAND USE
NOTIFY PRIOR TO DEVELOPMENT
RAISING OF FOOD PROHIBITED
RESIDENCE USE PROHIBITED
Title: Deed Restriction / Land Use Covenant
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&global_id=37070001&enforcement_id=5005224
Date Recorded: 11/4/2003

Site Management Requirements: NONE SPECIFIED
Title: LUC Annual Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/view_document?docurl=/public/deliverable_documents/7756010293/Annual%20LUC%20Inspection%20Rpt%2E%2020160912%20%2DBritannia%20Property%2Epdf
Date Recorded: 9/12/2016

Completed Activities

Title: Annual Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403461
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/2/2015
Comments: 2016 Annual Cost Estimate

Title: Annual Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60370408
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/9/2012
Comments:

Title: Annual inspection report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60258023
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/10/2010
Comments: Completed.

Title: 2019 - 2020 Annual Cost Est.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60459081
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/20/2019
Comments:

Title: Annual Cost Estimate - FY 2021/2022
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60489364
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/24/2021
Comments:

Title: Site Visit
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60370427
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/12/2014
Comments: Completed.

Title: Annual Deed/LUC Site Visit
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6011555
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/4/2008
Comments:

Title: Preliminary Endangerment Assessment Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=5005226
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 8/28/2002
Comments: DTSC reviewed and approved the PEA with a recommendation for a Deed Restriction of the land to be used for commercial/ industrial use only.

Title: Alert Notice Responses
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60284012
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence

Date Completed: 11/14/2011
Comments:

Title: Annual Cost Estimate Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60385472
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/3/2014
Comments:

Title: 2020 - 2021 Annual Cost Est. Ltr.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60472381
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/9/2020
Comments:

Title: FY 2017 - 2018 Annual Cost Est. Ltr.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60420474
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 2/15/2018
Comments:

Title: Annual Cost Estimate 2012
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60281037
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/10/2011
Comments:

Title: 2018 - 2019 Annual Cost Est.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60441493
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/5/2018
Comments:

Title: Site visit Form for deed rest.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6011415
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/4/2007
Comments: A site visit was conducted by DTSC on 8/29/07, the site remains capped and the restrictions still apply. A covenant to restrict the property was executed on 3/26/2004 between DTSC and Otay Crossing, Inc. The following restrictions apply to the site: Not to be used as a residence, including mobile home or factory home built housing, a hospital for humans, a public school for person under 21 years of age, a day care center for children, convalescent homes, or any use that include full-time human habitation.

Title: Prospective Purchaser Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5005223

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Prospective Purchaser Agreement
Date Completed: 3/26/2004
Comments:

Title: Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60475330
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 6/21/2021
Comments:

Title: LUC Annual Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403304
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Date Completed: 9/12/2016
Comments: Annual LUC Inspection Completed on August 16, 2016

Title: Annual Site inspection report Sept. 22, 2011
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60281807
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/27/2011
Comments: Completed.

Title: Annual Cost Estimate 2013
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60312467
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/9/2012
Comments:

Title: 2019 - Annual LUC Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60463012
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 1/14/2020
Comments:

Title: Deed Restriction / Land Use Covenant
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5005224
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Date Completed: 11/4/2003
Comments: DEED - RESTR: A deed restriction was recorded with San Diego County Recorder's Office on Nov. 4, 2003. The deed restriction restricted sensitive land use (residential, hospital, day care, school, and any use that includes full-time human habitation).

Title: Annual Cost Estimate (FY 2016 - 2017)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403514
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/22/2016
Comments: FY 2016 - 2017 Cost Est. Completed 11-22-2016

Title: Site Visit Form for Deed Restrictions
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6009885
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 8/25/2006
Comments:

Title: 2018 - Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60417221
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 1/14/2020
Comments:

Title: Voluntary Cleanup Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5004760
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Standard Voluntary Agreement
Date Completed: 9/30/2002
Comments: A Voluntary Cleanup Agreement (VCA) was signed on 9/30/02 to conduct a Preliminary Endangerment Assessment (PEA).

Title: Cost Estimate Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60343804
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/26/2013
Comments:

Title: Annual LUR Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6017266
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/25/2009
Comments: Annual Land Use Restriction Inspection completed.

Title: 2017 Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60438466
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Completed: 11/28/2017
Comments: LUC inspection conducted on 20171116

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
29	3 of 3	ESE	0.32 / 1,698.04	499.25 / -10	BRITANNIA BOULEVARD PROPERTY 2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD OTAY MESA CA 92154	ENVIROSTOR

Estor/EPA ID: 37070001
Site Code: 401185
Nat Priority List: NO
APN: 646-110-20, 646-110-20
Census Tract: 6073010015
Site Type: VOLUNTARY AGREEMENT
Address Description: 2133, 2155, 2177, 2189, 2195, 2199, 2201 BRITANNIA BOULEVARD & 7577 AIRWAY ROAD
Office: CLEANUP CYPRESS
Special Program: VOLUNTARY AGREEMENT - PROSPECTIVE PURCHASER PROGRAM
Funding: SITE PROPONENT
Assembly District: 80
Senate District: 40
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN DIEGO
Latitude: 32.5602
Longitude: -116.9786
Acres: 19 ACRES
Supervisor: PATRICK HSIEH
Cleanup Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY AS OF 12/17/2010
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: DISTRIBUTOR - CHEMICAL
Potential Media Affected: SOIL
Potential Contamin of Concern:

CHLOROFORM

Site History:

The property is located at the southeast corner of Britannia Boulevard and Airway Road, in San Diego, California. The property consists of a multi-tenant commercial/industrial business park on a sub-division consisting of eight parcels totaling approximately 19 acres. From 1930 through 2000, the property was used historically for agriculture purposes and pesticides and herbicides were routinely applied to soils.

In a PEA report completed in November 2002, 4,4'-DDD, 4,4'-DDE, 4,4'-DDT, and toxaphene were detected in soil samples collected at the site. Based on the final risk evaluation in the report, toxaphene exceeded appropriate risk levels for unrestricted use.

In October 2003, DTSC and Chiquita Frupac Incorporated signed a Land Use Covenant (LUC), restricting the property to commercial/industrial use. DTSC conducts annual inspections at the site to assure compliance with LUC provisions.

Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY - LAND USE RESTRICTIONS
Program Type: VOLUNTARY CLEANUP
CalEnviroScreen Score: 55-60%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=37070001

Land Use Restrictions

Site Management Requirements:
ASPHALT COVER NOT TO BE DISTURBED WITHOUT APPROVAL
CHECK FOR CRACKS IN FOUNDATION
DAY CARE CENTER PROHIBITED
ELDER CARE CENTER PROHIBITED
HOSPITAL USE PROHIBITED
NOTIFY AFTER CHANGE OF PROPERTY OWNER
NOTIFY PRIOR TO CHANGE IN LAND USE
NOTIFY PRIOR TO DEVELOPMENT
RAISING OF FOOD PROHIBITED
RESIDENCE USE PROHIBITED
Title: Deed Restriction / Land Use Covenant
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?cmd=radocuments&global_id=37070001&enforcement_id=5005224
Date Recorded: 11/4/2003

Site Management NONE SPECIFIED

Requirements:
Title: LUC Annual Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/view_document?docurl=/public/deliverable_documents/7756010293/Annual%20LUC%20Inspection%20Rpt%2E%2020160912%20%2DBritannia%20Property%2Epdf
Date Recorded: 9/12/2016

Completed Activities

Title: 2017 Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60438466
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 11/28/2017
Comments: LUC inspection conducted on 20171116

Title: 2019 - 2020 Annual Cost Est.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60459081
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/20/2019
Comments:

Title: 2018 - Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60417221
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 1/14/2020
Comments:

Title: Annual Cost Estimate (FY 2016 - 2017)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403514
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/22/2016
Comments: FY 2016 - 2017 Cost Est. Completed 11-22-2016

Title: Annual Site inspection report Sept. 22, 2011
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60281807
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/27/2011
Comments: Completed.

Title: Annual Cost Estimate Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60385472
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/3/2014
Comments:

Title: Deed Restriction / Land Use Covenant
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5005224
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Date Completed: 11/4/2003
Comments: DEED - RESTR: A deed restriction was recorded with San Diego County Recorder's Office on Nov. 4, 2003. The deed restriction restricted sensitive land use (residential, hospital, day care, school, and any use that includes full-time human habitation).

Title: Prospective Purchaser Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5005223
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Prospective Purchaser Agreement
Date Completed: 3/26/2004
Comments:

Title: 2018 - 2019 Annual Cost Est.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60441493
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/5/2018
Comments:

Title: Annual Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403461
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/2/2015
Comments: 2016 Annual Cost Estimate

Title: FY 2017 - 2018 Annual Cost Est. Ltr.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60420474
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 2/15/2018
Comments:

Title: Preliminary Endangerment Assessment Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=5005226
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 8/28/2002
Comments: DTSC reviewed and approved the PEA with a recommendation for a Deed Restriction of the land to be used for commercial/ industrial use only.

Title: Alert Notice Responses
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60284012
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Correspondence
Date Completed: 11/14/2011
Comments:

Title: Annual Cost Estimate 2013
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60312467
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/9/2012
Comments:

Title: Annual Deed/LUC Site Visit
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6011555
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/4/2008
Comments:

Title: Annual LUC Site Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60475330
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 6/21/2021
Comments:

Title: 2020 - 2021 Annual Cost Est. Ltr.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60472381
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/9/2020
Comments:

Title: Annual Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60370408
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/9/2012
Comments:

Title: Annual LUR Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6017266
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/25/2009
Comments: Annual Land Use Restriction Inspection completed.

Title: Cost Estimate Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60343804
Area Name:
Area Link:

Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 11/26/2013
Comments:

Title: Site Visit
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60370427
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/12/2014
Comments: Completed.

Title: Annual Cost Estimate 2012
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60281037
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/10/2011
Comments:

Title: LUC Annual Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60403304
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Date Completed: 9/12/2016
Comments: Annual LUC Inspection Completed on August 16, 2016

Title: Site Visit Form for Deed Restrictions
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6009885
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 8/25/2006
Comments:

Title: Site visit Form for deed rest.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=6011415
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 9/4/2007
Comments: A site visit was conducted by DTSC on 8/29/07, the site remains capped and the restrictions still apply. A covenant to restrict the property was executed on 3/26/2004 between DTSC and Otay Crossing, Inc. The following restrictions apply to the site: Not to be used as a residence, including mobile home or factory home built housing, a hospital for humans, a public school for person under 21 years of age, a day care center for children, convalescent homes, or any use that include full-time human habitation.

Title: Voluntary Cleanup Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=5004760
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Standard Voluntary Agreement
Date Completed: 9/30/2002
Comments: A Voluntary Cleanup Agreement (VCA) was signed on 9/30/02 to conduct a Preliminary Endangerment

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Assessment (PEA).

Title: 2019 - Annual LUC Inspection Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&doc_id=60463012
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction Monitoring Report
Date Completed: 1/14/2020
Comments:

Title: Annual Cost Estimate - FY 2021/2022
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60489364
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/24/2021
Comments:

Title: Annual inspection report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=37070001&enforcement_id=60258023
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction - Site Inspection/Visit
Date Completed: 11/10/2010
Comments: Completed.

30	*1 of 11*	*N*	*0.34 / 1,818.29*	*517.48 / 9*	***SDCTY-GEN SER,BROWN FIELD*** ***1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708*** ***SAN YSIDRO CA***	***LOP*** ***SANDIEGO***

SWRCB Global ID: T0607302978
Record ID: DEH1987-LSAM-H10618-001
Record Status: Completed
Opened Date: 2/9/1987
Case Type: LOP - Local Oversight Program
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Lead Agency: DEH/SAM
Lead Agency Date: 2/9/1987
Funding: F - LOP Federal Fund
Fire Agency: SAN DIEGO
Water Purveyor: SAN DIEGO
File Case Type: CLOSED OR TRANSFERRED LOP CASES

Parcel No: 646-050-03-00
Census Tract: 100.14
Zip Code 2: 92154
Community: San Diego
Jurisdiction: SAN DIEGO
Watershed Basin No: 910.2
Latitude GS 84: 32.5753625
Longitude GS 84: -116.9834182
X Map Coord: 6334469.504
Y Map Coord: 1789750.822

30	*2 of 11*	*N*	*0.34 / 1,818.29*	*517.48 / 9*	***SDCTY-GEN SER,BROWN FIELD*** ***1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708*** ***SAN YSIDRO CA***	***LOP*** ***SANDIEGO***

SWRCB Global ID: T0607300589
Record ID: DEH1990-LSAM-H10618-018
Record Status: Completed
Opened Date: 10/22/1990
Case Type: LOP - Local Oversight Program
Historical Name: CITY OF SAN DIEGO-BROWN FIELD
Lead Agency: DEH/SAM
Lead Agency Date: 10/12/1990
Funding: S - LOP State Fund
Fire Agency: SAN DIEGO
Water Purveyor: SAN DIEGO

Parcel No: 646-050-03-00
Census Tract: 100.14
Zip Code 2: 92154
Community: San Diego
Jurisdiction: SAN DIEGO
Watershed Basin No: 910.2
Latitude GS 84: 32.5753625
Longitude GS 84: -116.9834182
X Map Coord: 6334469.504
Y Map Coord: 1789750.822

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
File Case Type:		CLOSED OR TRANSFERRED LOP CASES				
30	3 of 11	N	0.34 / 1,818.29	517.48 / 9	SDCTY-GEN SER,BROWN FIELD 1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	LOP SANDIEGO

SWRCB Global ID:	T0607301159	Parcel No:	646-050-03-00
Record ID:	DEH1989-LSAM-H10618-007	Census Tract:	100.14
Record Status:	Completed	Zip Code 2:	92154
Opened Date:	3/17/1989	Community:	San Diego
Case Type:	LOP - Local Oversight Program	Jurisdiction:	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD TANK 28	Watershed Basin No:	910.2
Lead Agency:	DEH/SAM	Latitude GS 84:	32.5753625
Lead Agency Date:	4/6/1989	Longitude GS 84:	-116.9834182
Funding:	F - LOP Federal Fund	X Map Coord:	6334469.504
Fire Agency:	SAN DIEGO	Y Map Coord:	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	4 of 11	N	0.34 / 1,818.29	517.48 / 9	SDCTY-GEN SER,BROWN FIELD 1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	LOP SANDIEGO

SWRCB Global ID:	T0607300288	Parcel No:	646-050-03-00
Record ID:	DEH1989-LSAM-H10618-015	Census Tract:	100.14
Record Status:	Completed	Zip Code 2:	92154
Opened Date:	6/23/1989	Community:	San Diego
Case Type:	LOP - Local Oversight Program	Jurisdiction:	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD TANK 34	Watershed Basin No:	910.2
Lead Agency:	DEH/SAM	Latitude GS 84:	32.5753625
Lead Agency Date:	6/23/1989	Longitude GS 84:	-116.9834182
Funding:	F - LOP Federal Fund	X Map Coord:	6334469.504
Fire Agency:	SAN DIEGO	Y Map Coord:	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	5 of 11	N	0.34 / 1,818.29	517.48 / 9	SDCTY-GEN SER,BROWN FIELD 1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	LOP SANDIEGO

SWRCB Global ID:	T0607302664	Parcel No:	646-050-03-00
Record ID:	DEH1999-LSAM-H10618-024	Census Tract:	100.14
Record Status:	Completed	Zip Code 2:	92154
Opened Date:	3/25/1999	Community:	San Diego
Case Type:	LOP - Local Oversight Program	Jurisdiction:	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD	Watershed Basin No:	910.2
Lead Agency:	DEH/SAM	Latitude GS 84:	32.5753625
Lead Agency Date:	4/16/1999	Longitude GS 84:	-116.9834182
Funding:	S - LOP State Fund	X Map Coord:	6334469.504
Fire Agency:	SAN DIEGO	Y Map Coord:	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	6 of 11	N	0.34 / 1,818.29	517.48 / 9	SDCTY-GEN SER,BROWN FIELD 1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708	LOP SANDIEGO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					SAN YSIDRO CA	

SWRCB Global ID:	T0607301156	**Parcel No:**	646-050-03-00
Record ID:	DEH1989-LSAM-H10618-004	**Census Tract:**	100.14
Record Status:	Completed	**Zip Code 2:**	92154
Opened Date:	3/17/1989	**Community:**	San Diego
Case Type:	LOP - Local Oversight Program	**Jurisdiction:**	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD TANK 20	**Watershed Basin No:**	910.2
Lead Agency:	DEH/SAM	**Latitude GS 84:**	32.5753625
Lead Agency Date:	3/31/1989	**Longitude GS 84:**	-116.9834182
Funding:	F - LOP Federal Fund	**X Map Coord:**	6334469.504
Fire Agency:	SAN DIEGO	**Y Map Coord:**	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	7 of 11	N	0.34 / 1,818.29	517.48 / 9	SDCTY-GEN SER,BROWN FIELD 1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	LOP SANDIEGO

SWRCB Global ID:	T0607301167	**Parcel No:**	646-050-03-00
Record ID:	DEH1989-LSAM-H10618-014	**Census Tract:**	100.14
Record Status:	Completed	**Zip Code 2:**	92154
Opened Date:	4/14/1989	**Community:**	San Diego
Case Type:	LOP - Local Oversight Program	**Jurisdiction:**	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD	**Watershed Basin No:**	910.2
Lead Agency:	DEH/SAM	**Latitude GS 84:**	32.5753625
Lead Agency Date:	5/4/1989	**Longitude GS 84:**	-116.9834182
Funding:	F - LOP Federal Fund	**X Map Coord:**	6334469.504
Fire Agency:	SAN DIEGO	**Y Map Coord:**	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	8 of 11	N	0.34 / 1,818.29	517.48 / 9	SDCTY-GEN SER,BROWN FIELD 1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	LOP SANDIEGO

SWRCB Global ID:	T0607301160	**Parcel No:**	646-050-03-00
Record ID:	DEH1989-LSAM-H10618-008	**Census Tract:**	100.14
Record Status:	Completed	**Zip Code 2:**	92154
Opened Date:	4/14/1989	**Community:**	San Diego
Case Type:	LOP - Local Oversight Program	**Jurisdiction:**	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD TANK 18	**Watershed Basin No:**	910.2
Lead Agency:	DEH/SAM	**Latitude GS 84:**	32.5753625
Lead Agency Date:	5/4/1989	**Longitude GS 84:**	-116.9834182
Funding:	F - LOP Federal Fund	**X Map Coord:**	6334469.504
Fire Agency:	SAN DIEGO	**Y Map Coord:**	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	9 of 11	N	0.34 / 1,818.29	517.48 / 9	SDCTY-GEN SER,BROWN FIELD 1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708 SAN YSIDRO CA	LOP SANDIEGO

SWRCB Global ID:	T0607300588	**Parcel No:**	646-050-03-00
Record ID:	DEH1990-LSAM-H10618-019	**Census Tract:**	100.14
Record Status:	Completed	**Zip Code 2:**	92154
Opened Date:	10/22/1990	**Community:**	San Diego
Case Type:	LOP - Local Oversight Program	**Jurisdiction:**	SAN DIEGO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Historical Name:	CITY OF SAN DIEGO-BROWN FIELD	**Watershed Basin No:**	910.2
Lead Agency:	DEH/SAM	**Latitude GS 84:**	32.5753625
Lead Agency Date:	10/12/1990	**Longitude GS 84:**	-116.9834182
Funding:	S - LOP State Fund	**X Map Coord:**	6334469.504
Fire Agency:	SAN DIEGO	**Y Map Coord:**	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

30	10 of 11	N	0.34 / 1,818.29	517.48 / 9	**SDCTY-GEN SER,BROWN FIELD** **1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708** **SAN YSIDRO CA**	**LOP SANDIEGO**

SWRCB Global ID:	T0607300712	**Parcel No:**	646-050-03-00
Record ID:	DEH1990-LSAM-H10618-020	**Census Tract:**	100.14
Record Status:	Completed	**Zip Code 2:**	92154
Opened Date:	12/7/1990	**Community:**	San Diego
Case Type:	LOP - Local Oversight Program	**Jurisdiction:**	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD TANK 1	**Watershed Basin No:**	910.2
Lead Agency:	DEH/SAM	**Latitude GS 84:**	32.5753625
Lead Agency Date:	12/6/1990	**Longitude GS 84:**	-116.9834182
Funding:	F - LOP Federal Fund	**X Map Coord:**	6334469.504
Fire Agency:	SAN DIEGO	**Y Map Coord:**	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

30	11 of 11	N	0.34 / 1,818.29	517.48 / 9	**SDCTY-GEN SER,BROWN FIELD** **1424 CONTINENTAL ST, SAN YSIDRO, CA 92173-1708** **SAN YSIDRO CA**	**LOP SANDIEGO**

SWRCB Global ID:	T0607300719	**Parcel No:**	646-050-03-00
Record ID:	DEH1991-LSAM-H10618-023	**Census Tract:**	100.14
Record Status:	Completed	**Zip Code 2:**	92154
Opened Date:	4/19/1991	**Community:**	San Diego
Case Type:	LOP - Local Oversight Program	**Jurisdiction:**	SAN DIEGO
Historical Name:	CITY OF SAN DIEGO-BROWN FIELD	**Watershed Basin No:**	910.2
Lead Agency:	DEH/SAM	**Latitude GS 84:**	32.5753625
Lead Agency Date:	4/19/1991	**Longitude GS 84:**	-116.9834182
Funding:	S - LOP State Fund	**X Map Coord:**	6334469.504
Fire Agency:	SAN DIEGO	**Y Map Coord:**	1789750.822
Water Purveyor:	SAN DIEGO		
File Case Type:	CLOSED OR TRANSFERRED LOP CASES		

31	1 of 1	W	0.39 / 2,071.63	485.76 / -23	**Ins Shooting Range (Cays)** **NW 1/4 S27, T18S, R1W, SB merid.** **San Diego CA 92173**	**SWF/LF**

SWIS No:	37-CR-0032	**Latitude:**	32.56333
EPA Fed Registry ID:		**Longitude:**	-116.995
Site Operational Status:	Clean Closed	**County:**	San Diego
Regulatory Status:	Pre-regulation	**Site ZIP:**	92173
Site is Archived:	Yes	**ARB District:**	San Diego
Absorbed on:		**SWRCB Region:**	San Diego
Absorbed by:		**Site Point of Contact:**	Abel Martinez-Centeno
Site Inert Debris Eng Fill:	No		
Closed Illegal Aband:	Yes		
Closed Illegal Aband Cat:	D		
Finance Assuran Responsible:	No		
Incorporated City:	San Diego		
Local Government:	San Diego		
Reporting Agency Legal Name:	City of San Diego		

Reporting Agency Department: Development Services Department
Enforcing Agency Legal Name: City of San Diego
Enforcing Agency Department: Development Services Department

Site Owners

Site Type: Disposal Only
Owner Name: Department Of Navy
Owner Address: 5280 4th St Spc Command
Owner City: Dahlgren
Owner State: VA
Owner ZIP Code: 22448-5202
Owner Phone:
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Operators

Site Type: Disposal Only
Operator Name: Department Of Navy
Operator Address: 5280 4th St Spc Command
Operator City: Dahlgren
Operator State: VA
Operator ZIP Code: 22448-5202
Operator Phone:
Is Archived: Yes
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started on:

Extra Details

EPA Fed Reg ID:
Regulatory Status: Pre-regulation
Operational Status: Clean Closed
Is Archived: Yes
Fin Assuran Resp: No
Closed Illegal Aband: Yes
Inert Debris Eng Fill: No
Site Name: Ins Shooting Range (Cays)
Enforc Agncy Dept: Development Services Department
Enforc Agency:
Absorbed By:
Absorbed On:
Local Government: San Diego
Enforc Agncy Lgl Nm: City of San Diego
Point of Contact: Abel Martinez-Centeno
County: San Diego

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	1 of 2	NW	0.44 / 2,331.03	509.07 / 0	PIPER RANCH BUS PARK 6464 OTAY MESA ROAD CHULA VISTA CA 92173	CLEANUP SITES

Global ID: T0608115400
Status: COMPLETED - CASE CLOSED
Status Date: 2/28/1996
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download
Latitude: 32.568841780256
Longitude: -116.995026707161
County: SAN DIEGO

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:
Local Case No: H26521-001
Begin Date: 6/22/1988
Lead Agency: SAN DIEGO COUNTY LOP
Local Agency: SAN DIEGO COUNTY LOP
CUF Case: NO
CalEnvScreen Score: 36-40%
EPA Region: 9
Qty Rlsd Gallons:
Potential Media of Concern:
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community:
Coordinate Source: Google Map Move
Potential COC:
How Discovered:
Stop Method:
Stop Description:
Case Worker: VAP
Military DoD Site: No
Leak Reported Dt:
No Further Action Dt: 1996-02-28 00:00:00

Discharge Cause:
Discharge Source:
File Location: Local Agency
Site History:

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 1996-02-28 00:00:00
Action: Closure/No Further Action Letter

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 1996-02-28 00:00:00

Status: Open - Case Begin Date
Status Date: 1988-06-22 00:00:00

Status: Open - Site Assessment
Status Date: 1988-06-22 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: Voluntary Assistance Program (VAP)
Phone No:
Organization Name: SAN DIEGO COUNTY LOP
Email: deh.sam@sdcounty.ca.gov
Address: P.O. Box 129261
City: SAN DIEGO

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0608115400
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 2/28/1996
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: H26521-001
CASEWORKER: Voluntary Assistance Program (VAP)
SAN DIEGO RWQCB (REGION 9)
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0608115400&tabname=regulatoryhistory
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:
Site History:

No site history available

Sites from GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action Date: 2/28/1996
Action: Closure/No Further Action Letter
Received Issue Date: 2/28/1996
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608115400&enforcement_id=6136856&temptable=ENFORCEMENT
Title Description Comments:

Closure/No further Action

Sites from GeoTracker Search - Documents

Document Type: Site Documents
Submitted:
Document Date: 2/28/1996
Submitted By: ELLEN BEACON (REGULATOR)
Size :
Title: CLOSURE/NO FURTHER ACTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0608115400&enforcement_id=6136856
Type: CLOSURE/NO FURTHER ACTION LETTER

Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 2/28/1996

Status: Open - Site Assessment
Date: 6/22/1988

Status: Open - Case Begin Date
Date: 6/22/1988

32	2 of 2	NW	0.44 / 2,331.03	509.07 / 0	PIPER RANCH BUS PARK 6464 OTAY MESA ROAD CHULA VISTA CA 92173	LUST

Global ID: T0607302117
County: SAN DIEGO
Status: COMPLETED - CASE CLOSED
Latitude: 32.5688820599091
Status Date: 1995-02-21 00:00:00
Longitude: -116.995745840445
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 9UT3356
Potential COC: Gasoline
Local Case No: H26521-002
How Discovered:
Begin Date: 8/29/1988
Stop Method:
Lead Agency: SAN DIEGO COUNTY LOP
Stop Description:
Local Agency:
Case Worker:
CUF Case: NO
Military DoD Site: No
CalEnvScreen Score: 56-60%
Leak Reported Dt: 1994-09-24 00:00:00
EPA Region: 9
No Further Action Dt: 1995-02-21 00:00:00
Qty Rlsd Gallons:
Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community: Severely Disadvantaged Community
Coordinate Source: Google Map Move
Discharge Cause:
Discharge Source:
File Location: Local Agency
Site History:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date : 9/28/1994
Action: Notice of Responsibility

Action Type: Other
Date : 9/24/1994
Action: Leak Reported

Action Type: Other
Date : 9/24/1994
Action: Leak Stopped

Action Type: Other
Date : 8/29/1988
Action: Leak Discovery

Action Type: Other
Date : 8/29/1988
Action: Leak Began

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2/21/1995

Status: Open - Case Begin Date
Status Date: 8/29/1988

LUST Sites from GeoTracker Search - Regulatory Profile

Site Facility Name: PIPER RANCH BUS PARK
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig:
CUF Amount Paid:
Potential COC: GASOLINE
Facility Type:
Composting Method:
Address: 6464 OTAY MESA ROAD
City: CHULA VISTA
Zip: 92173
County: SAN DIEGO
CUF Claim:
File Location: LOCAL AGENCY
Designated Beneficial Use: MUN, AGR, IND
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0607302117
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 2/21/1995
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0607302117&tabname=regulatoryhistory
Potential Media of Concern: SOIL
User Defined Beneficial Use:
DWR GW Sub Basin:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: H26521-002
SAN DIEGO RWQCB (REGION 9) - CASE #: 9UT3356
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 2/21/1995

Status: Open - Case Begin Date
Date : 8/29/1988

Sites from GeoTracker Search - Regulatory Activities

Action Type: Notices
Action Date: 9/28/1994
Received Issue Date: 9/28/1994
Action: Notice of Responsibility
Doc Link:
Title Description Comments:

NOTICE OF REIMBURSEMENT / LOCAL

Action Type: Leak Action
Action Date: 8/29/1988
Received Issue Date:
Action: Leak Began
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 8/29/1988
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 9/24/1994
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 9/24/1994
Received Issue Date:
Action: Leak Stopped
Doc Link:
Title Description Comments:

33	*1 of 3*	*SE*	*0.46 / 2,451.68*	*477.72 / -31*	***2380 BRITANNIA BLVD., SAN DIEGO 2380 BRITANNIA San Diego CA***	***SAM SANDIEGO***

Record ID:	DEH2009-LSAM-H39739-001	***Primary Parcel:***	YES
Record ID (DEH Lyr):	DEH2009-LSAM-H39739-001	***Primary Address:***	YES
ID:	6063	***Address Type:***	ALIAS
Object ID:	6059	***Street String:***	2380 BRITANNIA
SWRCB Global ID:	T10000001097	***Community:***	San Diego
Feature ID:	6461001000	***Zip Code:***	
Parcel No:	646-100-10-00	***Zip Community:***	92154
Case No:	H39739-001	***Jurisdiction:***	SAN DIEGO
H No:	H39739	***Census Tract:***	100.15
KIVA per Tp per No:	6SAM H39739	***GT Global ID:***	T10000001097
Status:	Completed	***GT RB Case No:***	
Historical Name:	BRITANNIA 40 OTAY	***GT Status:***	Completed - Case Closed
Record Name:	2380 BRITANNIA BLVD., SAN DIEGO	***GT Status Date:***	6/15/2009 8:00 PM
Project Name:	2380 BRITANNIA BLVD., SAN DIEGO	***GT Case Type:***	Cleanup Program Site
Record Status:	Completed	***GT Lead Agency:***	SAN DIEGO COUNTY LOP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Record Type:	SAM Investigation	**GT CUF Case:**	NO
Record Alias:	SAM Investigation	**GT County:**	San Diego
Date:	04/15/2009	**GT Longitude:**	-116.97971821
Per Type:	LWQD	**GT Latitude:**	32.55491614
DEH Permit Owner:		**Agency Name:**	COSD
Fire Agency:	SAN DIEGO	**Lead Agency:**	DEH/SAM
Point X:	6336806.84069805	**Lead Agcy Date:**	4/14/2009 8:00 PM
Point Y:	1782471.13878265	**Opened Date:**	4/14/2009 8:00 PM
Latitude GS84:	32.5570712	**ThomasBros Map Gd:**	1351 E 3
Longitude GS84:	-116.9820543	**Funding:**	V - Private - VAP
Watershed Basin:	911.12	**BOS District:**	1
Water Purveyor:	SAN DIEGO	**Short Notes:**	
Address:	2380 BRITANNIA		
Case Type:	VAP - Voluntary Assistance Program		
Geo SRC:	Mapped to GeoTracker Lat/Lon		
Record Type (DEH Lyr):	LUEG-DEH/LWQD/SAM Investigation/NA		
Source File:	Citizen Access DEH Site Assessment and Mitigation Investigation Sites; San Diego Site Assessment and Mitigation Investigation Sites		

33	2 of 3	SE	0.46 / 2,451.68	477.72 / -31	**BRITANNIA 40 OTAY** **2380 BRITANNIA** **SAN DIEGO CA 92154**	**CLEANUP SITES**

Global ID:	T10000001097	**Latitude:**	32.5549161382447
Status:	COMPLETED - CASE CLOSED	**Longitude:**	-116.979718208313
Status Date:	6/16/2009	**County:**	SAN DIEGO
Site Facility Type:	CLEANUP PROGRAM SITE		
Data Source:	Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download		

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:		**Potential COC:**	
Local Case No:	H39739-001	**How Discovered:**	
Begin Date:	5/6/2009	**Stop Method:**	
Lead Agency:	SAN DIEGO COUNTY LOP	**Stop Description:**	
Local Agency:	SAN DIEGO COUNTY LOP	**Case Worker:**	EB
CUF Case:	NO	**Military DoD Site:**	No
CalEnvScreen Score:	66-70%	**Leak Reported Dt:**	
EPA Region:	9	**No Further Action Dt:**	2009-06-16 00:00:00
Qty Rlsd Gallons:			
Potential Media of Concern:			
How Discovered Description:			
Calwater Watershed Name:	Tijuana - Tijuana Valley - Water Tanks (911.12)		
DWR GW Subbasin Name:			
Disadvantaged Community:			
Coordinate Source:	Manual Entry on Screens		
Discharge Cause:			
Discharge Source:			
File Location:			
Site History:			

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type:	ENFORCEMENT
Date:	2009-05-07 00:00:00
Action:	Notification - Public Notice of Case Closure

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	2009-06-16 00:00:00
Status:	Open - Site Assessment

Status Date: 2009-05-06 00:00:00

Status: Open - Case Begin Date
Status Date: 2009-05-06 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: Ellen Beacon
Phone No:
Organization Name: SAN DIEGO COUNTY LOP
Email: ellen.beacon@sdcounty.ca.gov
Address: P.O. Box 129261
City: San Diego

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location:
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000001097
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 6/16/2009
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: H39739-001
CASEWORKER: Ellen Beacon
SAN DIEGO RWQCB (REGION 9)
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000001097&tabname=regulatoryhistory
Site History:

Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

No site history available

Sites from GeoTracker Search - Regulatory Activities

Action Type: Notices
Action: Notification - Public Notice of Case Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001097&enforcement_id=6014145&temptable=ENFORCEMENT
Title Description Comments:
Action Date: 5/7/2009
Received Issue Date: 5/7/2009

Case Closure Letter

Sites from GeoTracker Search - Documents

Document Type: Site Documents
Document Date: 5/7/2009
Size :
Title: CASE CLOSURE LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001097&enforcement_id=6014145
Type: NOTIFICATION - PUBLIC NOTICE OF CASE CLOSURE
Submitted:
Submitted By: ELLEN BEACON (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 6/16/2009

Status: Open - Site Assessment
Date: 5/6/2009

Status: Open - Case Begin Date
Date: 5/6/2009

33	3 of 3	SE	0.46 / 2,451.68	477.72 / -31	INSURANCE AUTO AUCTIONS 2380 BRITANNIA BLVD SAN DIEGO CA 92154	C&D DEBRIS RECY

County: SAN DIEGO

Activity Type: SCRAP METAL PROCESSING
Phone No: (619) 710-2866

34	1 of 2	SSW	0.47 / 2,497.08	470.30 / -39	OTAY CANYON RANCH 2440 CACTUS ROAD SAN DIEGO CA 92154	CLEANUP SITES

Global ID: T10000006065
Status: OPEN - SITE ASSESSMENT
Status Date: 7/22/2014
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download
Latitude: 32.5615024475569
Longitude: -116.989670278296
County: SAN DIEGO

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No:
Local Case No: DEH2014-LSAM-000254
Begin Date: 7/22/2014
Lead Agency: SAN DIEGO COUNTY LOP
Local Agency: SAN DIEGO COUNTY LOP
CUF Case: NO
CalEnvScreen Score: 66-70%
EPA Region: 9
Qty Rlsd Gallons:
Potential Media of Concern:
How Discovered Description:
Calwater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
DWR GW Subbasin Name:
Disadvantaged Community:
Coordinate Source: Google Map Move
Discharge Cause:
Discharge Source:
File Location: Local Agency
Site History:
Potential COC:
How Discovered:
Stop Method:
Stop Description:
Case Worker: EM
Military DoD Site: No
Leak Reported Dt:
No Further Action Dt:

This is a new VAP case. This section will be updated as data is recieved.

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2017-05-23 00:00:00
Action: Technical Correspondence / Assistance / Other

Action Type: RESPONSE
Date: 2017-05-20 00:00:00
Action: Removal Action Work Plan - Regulator Responded

Action Type: ENFORCEMENT
Date: 2016-10-25 00:00:00
Action: Technical Correspondence / Assistance / Other

Action Type: ENFORCEMENT
Date: 2016-07-08 00:00:00
Action: Cost Recovery Agreement / N. of Reimbursement

Action Type: ENFORCEMENT
Date: 2016-05-27 00:00:00
Action: Meeting

Action Type: ENFORCEMENT
Date: 2016-05-27 00:00:00
Action: Cost Recovery Agreement / N. of Reimbursement

Action Type: ENFORCEMENT
Date: 2016-04-06 00:00:00
Action: Meeting

Action Type: RESPONSE
Date: 2015-05-19 00:00:00
Action: Soil and Water Investigation Report

Action Type: RESPONSE
Date: 2014-08-22 00:00:00
Action: Site Assessment Report - Regulator Responded

Action Type: ENFORCEMENT
Date: 2014-07-30 00:00:00
Action: Letter - Notice

Action Type: ENFORCEMENT
Date: 2014-07-17 00:00:00
Action: Cost Recovery Agreement / N. of Reimbursement

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Open - Case Begin Date
Status Date: 2014-07-22 00:00:00

Status: Open - Site Assessment
Status Date: 2014-07-22 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: EWAN MOFFAT
Phone No:
Organization Name: SAN DIEGO COUNTY LOP
Email: ewan.moffat@sdcounty.ca.gov
Address: P.O. Box 129261
City: San Diego

Cleanup Program Sites from GeoTracker Search - Regulatory Profile

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply
Project Oversight Agencies:
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000006065
Cleanup Status Detail: OPEN - SITE ASSESSMENT AS OF 7/22/2014
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Frequen:
DWR GW Sub Basin:
CalWater Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN DIEGO COUNTY LOP (LEAD) - CASE #: DEH2014-LSAM-000254
CASEWORKER: EWAN MOFFAT
SAN DIEGO RWQCB (REGION 9)
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000006065&tabname=regulatoryhistory
Site History:

This is a new VAP case. This section will be updated as data is recieved.

Sites from GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action Date: 5/23/2017
Action: Technical Correspondence / Assistance / Other
Received Issue Date: 5/23/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6320746&temptable=ENFORCEMENT
Title Description Comments:

DEH Approval of Soil Management Plan

Action Type: Response Requested - Workplans
Action Date: 5/20/2017
Action: Removal Action Work Plan - Regulator Responded
Received Issue Date: 5/20/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006065&doc_id=5920573
Title Description Comments:

Soil Management Plan

Action Type: Other Regulatory Actions
Action Date: 10/25/2016
Action: Technical Correspondence / Assistance / Other
Received Issue Date: 10/25/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6301830&temptable=ENFORCEMENT
Title Description Comments:

DEH Response to Site Assessment Reports

Action Type: Agreements
Action Date: 7/8/2016
Action: Cost Recovery Agreement / N. of Reimbursement
Received Issue Date: 7/8/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6291937&temptable=ENFORCEMENT
Title Description Comments:

Updated Voluntary Assistance Program Application

Action Type: Other Regulatory Actions
Action Date: 5/27/2016
Action: Meeting
Received Issue Date: 5/27/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6286189&temptable=ENFORCEMENT
Title Description Comments:

Meeting Sign-In Sheet. Parcels have been added to project. DEH will review existing data and a new meeting will be scheduled to discuss Property Mitigation Plan.

Action Type: Agreements ***Action Date:*** 5/27/2016
Action: Cost Recovery Agreement / N. of Reimbursement ***Received Issue Date:*** 5/27/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6286131&temptable=ENFORCEMENT
Title Description Comments:

VAP Application - Additional Parcel

Action Type: Other Regulatory Actions ***Action Date:*** 4/6/2016
Action: Meeting ***Received Issue Date:*** 4/6/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6281556&temptable=ENFORCEMENT
Title Description Comments:

Meeting Sign-In Sheet Meeting to discuss Phase II Report and recommendations. Environmental consultant CYA will get development plans to DEH prior to DEH response.

Action Type: Response Requested - Reports ***Action Date:*** 5/19/2015
Action: Soil and Water Investigation Report ***Received Issue Date:*** 5/19/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006065&doc_id=5885968
Title Description Comments:

Phase II Soil Sampling, 1902 Cactus Road

Action Type: Response Requested - Reports ***Action Date:*** 8/22/2014
Action: Site Assessment Report - Regulator Responded ***Received Issue Date:*** 8/22/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000006065&doc_id=5816275
Title Description Comments:

Phase I Environmental Site Assessment and Phase II Soil Sampling

Action Type: Notices ***Action Date:*** 7/30/2014
Action: Letter - Notice ***Received Issue Date:*** 7/30/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6217450&temptable=ENFORCEMENT
Title Description Comments:

SB-1248 DTSC's Response

Action Type: Agreements ***Action Date:*** 7/17/2014
Action: Cost Recovery Agreement / N. of Reimbursement ***Received Issue Date:*** 7/17/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6213606&temptable=ENFORCEMENT
Title Description Comments:

VAP Application, six parcels, three owners

Sites from GeoTracker Search - Documents

Document Type: Site Documents ***Submitted:***
Document Date: 2/25/2021* ***Submitted By:*** COLIN P. YOUNG, CIH (AUTH_RP)
Size : 14,013 KB
Title: SOIL MANAGEMENT PLAN - REVISION 1
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2118843793/T10000006065.PDF
Type: REMOVAL ACTION WORK PLAN

Document Type: Site Documents ***Submitted:***
Document Date: 5/23/2017 ***Submitted By:*** JAMES CLAY (REGULATOR)
Size :
Title: DEH APPROVAL OF SOIL MANAGEMENT PLAN

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6320746
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER

Document Type: Site Documents **Submitted:**
Document Date: 5/19/2017 **Submitted By:** COLIN P. YOUNG, CIH (AUTH_RP)
Size : 6,096 KB
Title: SOIL MANAGEMENT PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8994284272/T10000006065.PDF
Type: REMOVAL ACTION WORK PLAN

Document Type: Site Documents **Submitted:**
Document Date: 4/7/2017 **Submitted By:** COLIN P. YOUNG, CIH (AUTH_RP)
Size : 7,231 KB
Title: SOIL MANAGEMENT PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9704383552/T10000006065.PDF
Type: REMOVAL ACTION WORK PLAN

Document Type: Site Documents **Submitted:**
Document Date: 10/25/2016 **Submitted By:** JAMES CLAY (REGULATOR)
Size :
Title: DEH RESPONSE TO SITE ASSESSMENT REPORTS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6301830
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER

Document Type: Site Documents **Submitted:**
Document Date: 7/8/2016 **Submitted By:** JAMES CLAY (REGULATOR)
Size :
Title: UPDATED VOLUNTARY ASSISTANCE PROGRAM APPLICATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6291937
Type: COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT

Document Type: Site Documents **Submitted:**
Document Date: 5/27/2016 **Submitted By:** JAMES CLAY (REGULATOR)
Size :
Title: MEETING SIGN-IN SHEET. PARCELS HAVE BEEN ADDED TO PROJECT. DEH WILL REVIEW EXISTING DATA AND A NEW MEETING WILL BE SCHEDULED TO DISCUSS PROPERTY MITIGATION PLAN.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6286189
Type: MEETING

Document Type: Site Documents **Submitted:**
Document Date: 5/27/2016 **Submitted By:** JAMES CLAY (REGULATOR)
Size :
Title: VAP APPLICATION - ADDITIONAL PARCEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6286131
Type: COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT

Document Type: Site Documents **Submitted:**
Document Date: 4/6/2016 **Submitted By:** JAMES CLAY (REGULATOR)
Size :
Title: MEETING SIGN-IN SHEET
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6281556
Type: MEETING

Document Type: Site Documents **Submitted:**
Document Date: 4/14/2015 **Submitted By:** KEITH ETCHELLS (AUTH_RP)
Size : 4,912 KB
Title: PHASE II SOIL SAMPLING, 1902 CACTUS ROAD
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6368048131/T10000006065.PDF
Type: SOIL AND WATER INVESTIGATION REPORT

Document Type: Site Documents **Submitted:**
Document Date: 8/22/2014 **Submitted By:** CAROL A. FENNER (REGULATOR)
Size :
Title: PHASE I ENVIRONMENTAL SITE ASSESSMENT AND PHASE II SOIL SAMPLING - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&document_id=5816275
Type: SITE ASSESSMENT REPORT

Document Type: Site Documents **Submitted:**
Document Date: 7/30/2014 **Submitted By:** NASSER SIONIT (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Size :
Title: SB-1248 DTSC'S RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6217450
Type: LETTER - NOTICE

Document Type: Site Documents
Document Date: 7/17/2014
Submitted:
Submitted By: LAURIE APECECHEA (REGULATOR)
Size :
Title: VAP APPLICATION, SIX PARCELS, THREE OWNERS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000006065&enforcement_id=6213606
Type: COST RECOVERY AGREEMENT / N. OF REIMBURSEMENT

Document Type: Site Documents
Document Date: 7/12/2013
Submitted:
Submitted By: KEITH ETCHELLS (AUTH_RP)
Size : 60,416 KB
Title: PHASE I ENVIRONMENTAL SITE ASSESSMENT AND PHASE II SOIL SAMPLING
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7715537369/T10000006065.PDF
Type: SITE ASSESSMENT REPORT

Sites from GeoTracker Search - Cleanup Status History

Status: Open - Site Assessment
Date: 7/22/2014

Status: Open - Case Begin Date
Date: 7/22/2014

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	2 of 2	SSW	0.47 / 2,497.08	470.30 / -39	Otay Canyon Ranch 2440 CACTUS RD San Diego CA	SAM SANDIEGO

Record ID:	DEH2014-LSAM-000254	**Primary Parcel:**	YES
Record ID (DEH Lyr):	DEH2014-LSAM-000254	**Primary Address:**	YES
ID:	6636	**Address Type:**	MASTER
Object ID:	6576	**Street String:**	2440 CACTUS RD
SWRCB Global ID:	T10000006065	**Community:**	San Diego
Feature ID:	6461001700	**Zip Code:**	92154-8007
Parcel No:	646-100-17-00	**Zip Community:**	92154
Case No:		**Jurisdiction:**	SAN DIEGO
H No:		**Census Tract:**	100.15
KIVA per Tp per No:		**GT Global ID:**	T10000006065
Status:	Open	**GT RB Case No:**	
Historical Name:	Otay Canyon Ranch	**GT Status:**	Open - Site Assessment
Record Name:	Otay Canyon Ranch	**GT Status Date:**	7/21/2014 8:00 PM
Project Name:	Otay Canyon Ranch	**GT Case Type:**	Cleanup Program Site
Record Status:	Open	**GT Lead Agency:**	SAN DIEGO COUNTY LOP
Record Type:	SAM Investigation	**GT CUF Case:**	NO
Record Alias:	SAM Investigation	**GT County:**	San Diego
Date:	07/22/2014	**GT Longitude:**	-116.98967028
Per Type:	LWQD	**GT Latitude:**	32.56150245
DEH Permit Owner:	Rita Mahoney	**Agency Name:**	COSD
Fire Agency:	SAN DIEGO	**Lead Agency:**	DEH/SAM
Point X:	6333760.77789256	**Lead Agcy Date:**	7/21/2014 8:00 PM
Point Y:	1784887.41085298	**Opened Date:**	7/21/2014 8:00 PM
Latitude GS84:	32.5545986	**ThomasBros Map Gd:**	1351 D 3
Longitude GS84:	-116.9916679	**Funding:**	V - Private - VAP
Watershed Basin:	911.12	**BOS District:**	1
Water Purveyor:	SAN DIEGO	**Short Notes:**	

Address: 2440 CACTUS RD, SAN DIEGO CA 921548007
Case Type: VAP - Voluntary Assistance Program
Geo SRC: Mapped to Geotracker Lat/Lon
Record Type (DEH Lyr): LUEG-DEH/LWQD/SAM Investigation/NA
Source File: Citizen Access DEH Site Assessment and Mitigation Investigation Sites; San Diego Site Assessment and Mitigation Investigation Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	1 of 2	NW	0.57 / 3,025.10	521.29 / 12	BROWN FIELD NAAS EAST OF CHULA VISTA CA	ENVIROSTOR

Estor/EPA ID:	80000947	**Assembly District:**	80
Site Code:		**Senate District:**	40
Nat Priority List:	NO	**Permit Renewal Lead:**	
APN:	NONE SPECIFIED	**Public Partici Spclst:**	
Census Tract:	6073010014	**Project Manager:**	
Site Type:	FUDS	**County:**	SAN DIEGO
Address Description:		**Latitude:**	32.5708333333333
Office:	CLEANUP CYPRESS	**Longitude:**	-116.994444444444
Special Program:		**Acres:**	NONE SPECIFIED
Funding:	DERA	**Supervisor:**	DOUGLAS BAUTISTA

Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION
Program Type: MILITARY EVALUATION
CalEnviroScreen Score: 55-60%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000947

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	2 of 2	NW	0.57 / 3,025.10	521.29 / 12	BROWN FIELD NAVAL AUXILIARY AIR STATION EAST OF CHULA VISTA CA	FUDS

FUDS Property No: J09CA7278
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=53561
FUDS INST ID: CA99799FA24900
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 51
EPA Region: 09
County: SAN DIEGO
Latitude: 32.57083333
Longitude: -116.99444444
Fiscal year: 2019
USACE Division: SPD
USACE District: Los Angeles District (SPL)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: N/A

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
36	1 of 1	E	0.59 / 3,126.37	502.24 / -7	HONEYWELL, INC. 2055 DUBLIN DRIVE SAN DIEGO CA 92173	ENVIROSTOR

Estor/EPA ID: 71003124
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6073010015
Site Type: TIERED PERMIT
Address Description: 2055 DUBLIN DRIVE
Office: CLEANUP CYPRESS
Special Program:
Funding:
Assembly District: 80
Senate District: 40
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN DIEGO
Latitude: 32.561574
Longitude: -116.973934
Acres: 0 ACRES
Supervisor: ROBERT SENGA
Cleanup Status: NO FURTHER ACTION AS OF 2/22/2017
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: NO FURTHER ACTION
Program Type: TIERED PERMIT
CalEnviroScreen Score: 55-60%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71003124

Completed Activities

Title: Phase I Environmental Assessment
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=71003124&enforcement_id=60423902
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase I Verification
Date Completed: 8/16/1996
Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
37	1 of 2	WNW	0.83 / 4,365.70	518.03 / 9	OCEAN VIEW HILLS MID SCH/INTERIM HOUSING 4919 DEL SOL BOULEVARD SAN DIEGO CA 92154	SCH

Estor/EPA ID: 37020003
Site Code: 404525
Nat Priority List: NO
Acres: 37 ACRES
Special Program:
Funding: SCHOOL DISTRICT
Assembly District: 80
Senate District: 40
Permit Renewal Lead:
Project Manager:
Supervisor: YOLANDA GARZA
Public Partici Spclst:
Census Tract: 6073010014
County: SAN DIEGO
Latitude: 32.5711
Longitude: -117
School District: SAN YSIDRO ELEMENTARY SCHOOL DISTRICT
APN: NONE SPECIFIED
Cleanup Status: NO ACTION REQUIRED AS OF 4/15/2004
Cleanup Oversight Agencies: DTSC - LEAD AGENCY
Site Type: SCHOOL
Office: SOUTHERN CALIFORNIA SCHOOLS & BROWNFIELDS OUTREACH
Past Use that Caused Contam: AGRICULTURAL - LIVESTOCK
Potential Media Affected: NO MEDIA AFFECTED
Potential Contamin of Concern:

NO CONTAMINANTS FOUND

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SITE HISTORY:

Historically used for grazing. Currently an existing school on a portion of the site (portables only).

Status: NO ACTION REQUIRED
Program Type: SCHOOL EVALUATION
CalEnviroScreen Score: 55-60%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=37020003

Completed Activities

Title: Phase 1
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1
Date Completed: 4/15/2004
Comments:

Title: * Site Visit - Site Inspections/visit
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Inspections/Visit (Non LUR)
Date Completed: 4/15/2004
Comments:

37	*2 of 2*	*WNW*	*0.83 / 4,365.70*	*518.03 / 9*	***OCEAN VIEW HILLS MID SCH/INTERIM HOUSING 4919 DEL SOL BOULEVARD SAN DIEGO CA 92154***	***ENVIROSTOR***

Estor/EPA ID: 37020003
Site Code: 404525
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6073010014
Site Type: SCHOOL
Address Description: 4919 DEL SOL BOULEVARD
Office: SOUTHERN CALIFORNIA SCHOOLS & BROWNFIELDS OUTREACH
Special Program:
Funding: SCHOOL DISTRICT
Assembly District: 80
Senate District: 40
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN DIEGO
Latitude: 32.5711
Longitude: -117
Acres: 37 ACRES
Supervisor: YOLANDA GARZA
Cleanup Status: NO ACTION REQUIRED AS OF 4/15/2004
Cleanup Oversight Agencies: DTSC - LEAD AGENCY
School District: SAN YSIDRO ELEMENTARY SCHOOL DISTRICT
Past Use that Caused Contam: AGRICULTURAL - LIVESTOCK
Potential Media Affected: NO MEDIA AFFECTED
Potential Contamin of Concern:

NO CONTAMINANTS FOUND

Site History:

Historically used for grazing. Currently an existing school on a portion of the site (portables only).

Status: NO ACTION REQUIRED
Program Type: SCHOOL EVALUATION
CalEnviroScreen Score: 55-60%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=37020003

Completed Activities

Title: * Site Visit - Site Inspections/visit
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Inspections/Visit (Non LUR)
Date Completed: 4/15/2004
Comments:

Title: Phase 1
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1
Date Completed: 4/15/2004
Comments:

Unplottable Summary

Total: 0 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID

No unplottable records were found that may be relevant for the search criteria.

Unplottable Report

No unplottable records were found that may be relevant for the search criteria.

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

Formerly Utilized Sites Remedial Action Program: DOE FUSRAP

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

National Priority List: NPL

Sites on the United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. The NPL, which EPA is required to update at least once a year, is based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

National Priority List - Proposed: PROPOSED NPL

Sites proposed - by the EPA, the state agency, or concerned citizens - for addition to the NPL due to contamination by hazardous waste and identified by the Environmental Protection Agency (EPA) as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

Deleted NPL: DELETED NPL

Sites deleted from the United States Environmental Protection Agency (EPA)'s National Priorities List. The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

SEMS List 8R Active Site Inventory: SEMS

The Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted.

Government Publication Date: Apr 27, 2022

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

SEMS List 8R Archive Sites: SEMS ARCHIVE

The Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time.

Government Publication Date: Apr 27, 2022

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Apr 11, 2022

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites listed as treatment, storage and/or disposal facilities of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Government Publication Date: Apr 11, 2022

RCRA Generator List: RCRA LQG

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Apr 11, 2022

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Apr 11, 2022

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Apr 11, 2022

RCRA Non-Generators: RCRA NON GEN

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Apr 11, 2022

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Apr 11, 2022

Federal Engineering Controls-ECs: FED ENG

Engineering controls (ECs) encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Dec 30, 2021

Federal Institutional Controls- ICs: FED INST

Institutional controls are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's (United States Environmental Protection Agency) expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site.

Government Publication Date: Dec 30, 2021

Land Use Control Information System: LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Institutional Control Boundaries at NPL sites: NPL IC

Boundaries of Institutional Control areas at sites on the United States Environmental Protection Agency (EPA)'s National Priorities List, or Proposed or Deleted, made available by the EPA's Shared Enterprise Geodata and Services (SEGS). United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy.

Government Publication Date: Mar 30, 2022

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Dec 31, 2021

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Aug 20, 2021

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

List of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

List of petroleum refineries from the U.S. Energy Information Administration (EIA) Refinery Capacity Report. Includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year located in the 50 States, the District of Columbia, Puerto Rico, the Virgin Islands, Guam, and other U.S. possessions. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

List of petroleum product and crude oil rail terminals made available by the U.S. Energy Information Administration (EIA). Includes operable bulk petroleum product terminals located in the 50 States and the District of Columbia with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil that were active between 2017 and 2018. Petroleum product terminals comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

LIEN on Property: SEMS LIEN

The EPA Superfund Enterprise Management System (SEMS) provides LIEN information on properties under the EPA Superfund Program.

Government Publication Date: Apr 27, 2022

Superfund Decision Documents: SUPERFUND ROD

This database contains a listing of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD), along with other associated memos and files. This information is maintained and made available by the US EPA (Environmental Protection Agency).

Government Publication Date: May 3, 2022

State

State Response Sites: RESPONSE

A list of identified confirmed release sites where the Department of Toxic Substances Control (DTSC) is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk. This database is state equivalent NPL.

Government Publication Date: May 30, 2022

EnviroStor Database: ENVIROSTOR

The EnviroStor Data Management System is made available by the Department of Toxic Substances Control (DTSC). Includes Corrective Action sites, Tiered Permit sites, Historical Sites and Evaluation/Investigation sites. This database is state equivalent CERCLIS.

Government Publication Date: May 30, 2022

Delisted State Response Sites: DELISTED ENVS

Sites removed from the list of State Response Sites made available by the EnviroStor Data Management System, Department of Toxic Substances Control (DTSC).

Government Publication Date: May 30, 2022

Solid Waste Information System (SWIS): SWF/LF

The Solid Waste Information System (SWIS) database made available by the Department of Resources Recycling and Recovery (CalRecycle) contains information on solid waste facilities, operations, and disposal sites throughout the State of California. The types of facilities found in this database include landfills, transfer stations, material recovery facilities, composting sites, transformation facilities, waste tire sites, and closed disposal sites.

Government Publication Date: Feb 2, 2022

Solid Waste Disposal Sites with Waste Constituents Above Hazardous Waste Levels: SWRCB SWF

This is a list of solid waste disposal sites identified by California State Water Resources Control Board with waste constituents above hazardous waste levels outside the waste management unit.

Government Publication Date: Sep 20, 2006

Waste Management Unit Database: WMUD

The Waste Management Unit Database System tracks and inventories waste management units. CCR Title 27 contains criteria stating that Waste Management Units are classified according to their ability to contain wastes. Containment shall be determined by geology, hydrology, topography, climatology, and other factors relating to the ability of the Unit to protect water quality. Water Code Section 13273.1 requires that operators submit a water quality solid waste assessment test (SWAT) report to address leak status. The WMUDS was last updated by the State Water Resources control board in 2000.

Government Publication Date: Jan 1, 2000

EnviroStor Hazardous Waste Facilities: HWP

A list of hazardous waste facilities including permitted, post-closure and historical facilities found in the Department of Toxic Substances Control (DTSC) EnviroStor database.

Government Publication Date: May 30, 2022

Sites Listed in the Solid Waste Assessment Test (SWAT) Program Report: SWAT

In a 1993 Memorandum of Understanding, the State Water Resources Control Board (SWRCB) agreed to submit a comprehensive report on the Solid Waste Assessment Test (SWAT) Program to the California Integrated Waste Management Board (CIWMB). This report summarizes the work completed to date on the SWAT Program, and addresses both the impacts that leakage from solid waste disposal sites (SWDS) may have upon waters of the State and the actions taken to address such leakage.

Government Publication Date: Dec 31, 1995

Construction and Demolition Debris Recyclers: C&D DEBRIS RECY

This listing of Construction and Demolition Debris Recyclers is maintained by the California Intergrated Waste Management Board-common C&D materials include lumber, drywall, metals, masonry (brick, concrete, etc.), carpet, plastic, pipe, rocks, dirt, paper, cardboard, or green waste related to land development.

Government Publication Date: Jun 20, 2018

Recycling Centers: RECYCLING

This list of Certified Recycling Centers that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Apr 12, 2022

Listing of Certified Processors: PROCESSORS

This list of Certified Processors that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Apr 12, 2022

Listing of Certified Dropoff, Collection, and Community Service Programs: CONTAINER RECY

This list of Certified Dropoff, Collection, and Community Service Programs (non-buyback) operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Apr 12, 2022

Land Disposal Sites: LDS

Land Disposal Sites in GeoTracker, the State Water Resources Control Board (SWRCB)'s data management system. The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units. Waste management units include waste piles, surface impoundments, and landfills.

Government Publication Date: Feb 15, 2022

Leaking Underground Fuel Tank Reports: LUST

List of Leaking Underground Storage Tanks within the Cleanup Sites data in GeoTracker database. GeoTracker is the State Water Resources Control Board's (SWRCB) data management system for managing sites that impact groundwater, especially those that require groundwater cleanup (Underground Storage Tanks, Department of Defense and Site Cleanup Program) as well as permitted facilities such as operating Underground Storage Tanks. The Leak Prevention Program that overlooks LUST sites is the SWRCB in California's Environmental Protection Agency.

Government Publication Date: Feb 15, 2022

Delisted Leaking Storage Tanks: DELISTED LST

List of Leaking Underground Storage Tanks (LUST) cleanup sites removed from GeoTracker, the State Water Resources Control Board (SWRCB)'s database system, as well as sites removed from the SWRCB's list of UST Case closures.

Government Publication Date: Feb 15, 2022

Permitted Underground Storage Tank (UST) in GeoTracker: UST

List of Permitted Underground Storage Tank (UST) sites made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA).

Government Publication Date: Apr 25, 2022

Proposed Closure of Underground Storage Tank Cases: UST CLOSURE

List of UST cases that are being considered for closure by either the California Environmental Protection Agency, State Water Resources Control Board or the Executive Director that have been posted for a 60-day public comment period.

Government Publication Date: May 5, 2021

Historical Hazardous Substance Storage Information Database: HHSS

The Historical Hazardous Substance Storage database contains information collected in the 1980s from facilities that stored hazardous substances. The information was originally collected on paper forms, was later transferred to microfiche, and recently indexed as a searchable database. When using this database, please be aware that it is based upon self-reported information submitted by facilities which has not been independently verified. It is unlikely that every facility responded to the survey and the database should not be expected to be a complete inventory of all facilities that were operating at that time. This database is maintained by the California State Water Resources Control Board's (SWRCB) Geotracker.

Government Publication Date: Aug 27, 2015

Statewide Environmental Evaluation and Planning System: UST SWEEPS

The Statewide Environmental Evaluation and Planning System (SWEEPS) is a historical listing of active and inactive underground storage tanks made available by the California State Water Resources Control Board (SWRCB).

Government Publication Date: Oct 1, 1994

Aboveground Storage Tanks: AST

A statewide list from 2009 of aboveground storage tanks (ASTs) made available by the Cal FIRE Office of the State Fire Marshal (OSFM). This list is no longer maintained or updated by the Cal FIRE OSFM.

Government Publication Date: Aug 31, 2009

SWRCB Historical Aboveground Storage Tanks: AST SWRCB

A list of aboveground storage tanks made available by the California State Water Resources Control Board (SWRCB). Effective January 1, 2008, the Certified Unified Program Agencies (CUPAs) are vested with the responsibility and authority to implement the Aboveground Petroleum Storage Act (APSA).

Government Publication Date: Dec 1, 2007

Oil and Gas Facility Tanks: TANK OIL GAS

Locations of oil and gas tanks that fall under the jurisdiction of the Geologic Energy Management Division of the California Department of Conservation (CalGEM) (CCR 1760). CalGEM was formerly the Division of Oil, Gas, and Geothermal Resources (DOGGR).

Government Publication Date: Apr 4, 2022

Delisted Storage Tanks: DELISTED TNK

This database contains a list of storage tank sites that were removed by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA) and the Cal FIRE Office of State Fire Marshal (OSFM).

Government Publication Date: May 25, 2022

California Environmental Reporting System (CERS) Tanks: CERS TANK

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: Apr 5, 2022

Delisted California Environmental Reporting System (CERS) Tanks: DELISTED CTNK

This database contains a list of Aboveground Petroleum Storage and Underground Storage Tank sites that were removed from in the California Environmental Protection Agency (CalEPA) Regulated Site Portal.

Government Publication Date: Apr 5, 2022

Historical Hazardous Substance Storage Container Information - Facility Summary: HIST TANK

The State Water Resources Control Board maintained the Hazardous Substance Storage Containers listing and inventory in th 1980s. This facility summary lists historic tank sites where the following container types were present: farm motor vehicle fuel tanks; waste tanks; sumps; pits, ponds, lagoons, and others; and all other product tanks. This set, published in May 1988, lists facility and owner information, as well as the number of containers. This data is historic and will not be updated.

Government Publication Date: May 27, 1988

Site Mitigation and Brownfields Reuse Program Facility Sites with Land Use Restrictions: LUR

The Department of Toxic Substances Control (DTSC) Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents land use restrictions that are active. Some sites have multiple land use restrictions.

Government Publication Date: May 30, 2022

CALSITES Database: CALSITES

This historical database was maintained by the Department of Toxic Substance Control (DTSC) for more than a decade. CALSITES contains information on Brownfield properties with confirmed or potential hazardous contamination. In 2006, DTSC introduced EnviroStor as the latest Brownfields site database.

Government Publication Date: May 1, 2004

Hazardous Waste Management Program Facility Sites with Deed / Land Use Restrictions: HLUR

The Department of Toxic Substances Control (DTSC) Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Government Publication Date: Feb 18, 2021

Deed Restrictions and Land Use Restrictions: DEED

List of Deed Restrictions, Land Use Restrictions and Covenants in GeoTracker made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency. A deed restriction (land use covenant) may be required to facilitate the remediation of past environmental contamination and to protect human health and the environment by reducing the risk of exposure to residual hazardous materials.

Government Publication Date: Feb 15, 2022

Voluntary Cleanup Program: VCP

List of sites in the Voluntary Cleanup Program made available by the Department of Toxic Substances and Control (DTSC). The Voluntary Cleanup Program was designed to respond to lower priority sites. Under the Voluntary Cleanup Program, DTSC enters site-specific agreements with project proponents for DTSC oversight of site assessment, investigation, and/or removal or remediation activities, and the project proponents agree to pay DTSC's reasonable costs for those services.

Government Publication Date: May 30, 2022

GeoTracker Cleanup Program Sites: CLEANUP SITES

A list of Cleanup Program sites in the state of California made available by The State Water Resources Control Board (SWRCB) of the California Environmental Protection Agency (EPA). SWRCB tracks leaking underground storage tank cleanups as well as other water board cleanups.

Government Publication Date: Feb 15, 2022

Delisted Cleanup Program Sites: DELISTED CLEANUP

A list of Cleanup Program sites which were once included - and have since been removed from - the list of Cleanup Program Sites in GeoTracker. GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Government Publication Date: Feb 15, 2022

Delisted County Records: DELISTED COUNTY

Records removed from county or CUPA databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: May 26, 2022

Tribal

Leaking Underground Storage Tanks (LUSTs) on Indian Lands: INDIAN LUST
LUSTs on Tribal/Indian Lands in Region 9, which includes California.
Government Publication Date: Oct 12, 2021

Underground Storage Tanks (USTs) on Indian Lands: INDIAN UST
USTs on Tribal/Indian Lands in Region 9, which includes California.
Government Publication Date: Oct 12, 2021

Delisted Tribal Leaking Storage Tanks: DELISTED ILST
Leaking Underground Storage Tank facilities which have been removed from the Regional Tribal LUST lists made available by the EPA.
Government Publication Date: Jan 31, 2022

Delisted Tribal Underground Storage Tanks: DELISTED IUST
Underground Storage Tank facilities which have been removed from the Regional Tribal UST lists made available by the EPA.
Government Publication Date: Oct 13, 2021

County

San Diego County - Solid Waste Facility List: SWF SANDIEGO
This list of open and closed Solid Waste Facilities is made available by the County of San Diego Department of Environmental Health and Quality's (DEHQ) agency files and map service. The County of San Diego DEHQ Solid Waste Local Enforcement Agency (LEA) is certified by the California Department of Resources Recycling and Recovery to enforce state solid waste laws and regulations in San Diego County, excluding the City of San Diego.
Government Publication Date: Dec 7, 2021

San Diego County - Local Oversight Program List: LOP SANDIEGO
A list of Underground Storage Tank (UST) release sites in the County of San Diego. This list is made available by San Diego County Department of Environmental Health.
Government Publication Date: Jun 15, 2020

San Diego County - Hazardous Materials Management Division Database: HAZ SANDIEGO
A list of facilities with Unified Program Facility Permit in San Diego County. This list has been made available by County of San Diego Environmental Health.
Government Publication Date: May 1, 2022

San Diego County - UST List: UST SANDIEGO
A list of registered Underground Storage Tanks in the County of San Diego. The list is made available by the San Diego County Hazardous Materials Division.
Government Publication Date: Apr 25, 2022

San Diego County - Site Assessment and Mitigation Investigation Sites: SAM SANDIEGO
List of sites which have undergone a Site Assessment and Mitigation investigation. This list is made available by the County of San Diego Department of Environmental Health.
Government Publication Date: Jun 30, 2020

Additional Environmental Record Sources

Federal

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the Environmental Protection Agency (US EPA).
Government Publication Date: Nov 2, 2020

Toxics Release Inventory (TRI) Program: TRIS

The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U. S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment.
Government Publication Date: Aug 24, 2021

Perfluorinated Alkyl Substances (PFAS) Releases: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment.
Government Publication Date: Aug 24, 2021

PFOA/PFOS Contaminated Sites: PFAS NPL

List of National Priorities List (NPL) and related Superfund Alternative Agreement (SAA) sites where PFOA or PFOS contaminants have been found in water and/or soil. The site listing is provided by the Federal Environmental Protection Agency (EPA).
Government Publication Date: Apr 15, 2022

Perfluorinated Alkyl Substances (PFAS) Water Quality: PFAS WATER

The Water Quality Portal (WQP) is a cooperative service sponsored by the United States Geological Survey (USGS), the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC). This listing includes records from the Water Quality Portal where the characteristic (environmental measurement) is in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances.
Government Publication Date: Jul 20, 2020

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents, and this is cited in the tracker. Disclaimer: The source conveys this database undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Limited location details are available with this data. Access the following for the most current informations https://pfasproject.com/pfas-contamination-site-tr acker/
Government Publication Date: Dec 12, 2019

National Response Center PFAS Spills: ERNS PFAS

National Response Center (NRC) calls from 1990 to the most recent complete calendar year where there is indication of Aqueous Film Forming Foam (AFFF) usage. NRC calls may reference AFFF usage in the "Material Involved" or "Incident Description" fields. Data made available by the US Environmental Protection Agency (EPA). Disclaimer: dataset may include initial or misidentified incident data not yet validated or investigated by a federal/state response agency.
Government Publication Date: Feb 23, 2022

Hazardous Materials Information Reporting System: HMIRS

US DOT - Department of Transportation Pipeline and Hazardous Materials Safety Administration (PHMSA) Incidents Reports Database taken from Hazmat Intelligence Portal, U.S. Department of Transportation.
Government Publication Date: Sep 1, 2020

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department") provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.
Government Publication Date: Nov 22, 2021

Toxic Substances Control Act: TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI).

Government Publication Date: Apr 11, 2019

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the cleanup process, the Environmental Protection Agency (EPA) conducts a search to find the potentially responsible parties (PRPs). EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site.

Government Publication Date: Mar 30, 2022

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) is a system that provides information for the Federal Enforcement and Compliance (FE&C) and the National Pollutant Discharge Elimination System (NPDES) programs. The FE&C component supports the Environmental Protection Agency's (EPA) Civil Enforcement and Compliance program activities. These activities include Compliance Assistance, Compliance Monitoring and Enforcement. The NPDES program supports tracking of NPDES permits, limits, discharge monitoring data and other program reports.

Government Publication Date: Apr 30, 2022

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) online search. The Environmental Protection Agency (EPA) tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: May 5, 2021

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).

Government Publication Date: May 5, 2021

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DoD) is responsible for an environmental restoration. This list is published by the U.S. Army Corps of Engineers.

Government Publication Date: May 26, 2021

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

A list of flagged pipeline incidents made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types.

Government Publication Date: Jul 7, 2020

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) contains mine identification numbers issued by the Department of Labor Mine Safety and Health Administration (MSHA) for mines active or opened since 1971. Note that addresses may or may not correspond with the physical location of the mine itself.

Government Publication Date: Feb 1, 2022

Surface Mining Control and Reclamation Act Sites: SMCRA

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by the Office of Surface Mining Reclamation and Enforcement (OSMRE) to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of Abandoned Mine Land (AML) impacts, as well as information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Government Publication Date: Dec 18, 2020

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

Uranium Mill Tailings Radiation Control Act Sites: URANIUM

The Legacy Management Office of the Department of Energy (DOE) manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The L.M. Office manages this database of sites registered under the Uranium Mill Tailings Control Act (UMTRCA).

Government Publication Date: Mar 4, 2017

Alternative Fueling Stations: ALT FUELS

List of alternative fueling stations made available by the US Department of Energy's Office of Energy Efficiency & Renewable Energy. Includes Biodiesel stations, Ethanol (E85) stations, Liquefied Petroleum Gas (Propane) stations, Ethanol (E85) stations, Natural Gas stations, Hydrogen stations, and Electric Vehicle Supply Equipment (EVSE). The National Renewable Energy Laboratory (NREL) obtains information about new stations from trade media, Clean Cities coordinators, a Submit New Station form on the Station Locator website, and through collaborating with infrastructure equipment and fuel providers, original equipment manufacturers (OEMs), and industry groups.

Government Publication Date: May 16, 2022

Superfunds Consent Decrees: CONSENT DECREES

A list of Superfund consent decrees made available by the Department of Justice, Environment & Natural Resources Division (ENRD).

Government Publication Date: May 18, 2022

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

List of active EPA-registered foreign and domestic pesticide-producing and device-producing establishments based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that facilities producing pesticides, active ingredients, or devices be registered. The list of establishments is made available by the EPA.

Government Publication Date: Mar 30, 2022

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: Jan 20, 2022

State

Dry Cleaning Facilities: DRYCLEANERS

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial, linen supply, commercial laundry, dry cleaning and pressing machines - Coin Operated Laundry and Dry Cleaning. This is provided by the Department of Toxic Substance Control.

Government Publication Date: Dec 20, 2021

Delisted Drycleaners: DELISTED DRYCLEANERS

Sites removed from the list of drycleaner related facilities that have EPA ID numbers, made available by the California Department of Toxic Substance Control.

Government Publication Date: Feb 28, 2020

Non-Toxic Dry Cleaning Incentive Program: DRYC GRANT

A list of grant recipients of the Non-Toxic Dry Cleaning Incentive Program made available by the California Air Resources Board (CARB). The program provides grants to eligible dry cleaning businesses to assist them in transitioning away from PERC machines to alternative non-toxic and non-smog forming technologies.

Government Publication Date: Feb 28, 2020

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

List of sites from the State Water Resources Control Board (SWRCB)'s GeoTracker at which one or more of the potential contaminants of concern are in the PFAS Master List of PFAS Substances made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Feb 15, 2022

PFOA/PFOS Groundwater: PFAS GW

A list of water wells from the Groundwater Ambient Monitoring and Assessment Program (GAMA) Groundwater Information System with the groundwater chemical perfluorooctanoic acid (PFOA) (NL = 0.014 UG/L) or perfluorooctanoic sulfonate (PFOS) (NL = 0.013 UG/L). The GAMA Groundwater Information System search is made available by California Water Boards.

Government Publication Date: Apr 27, 2022

Hazardous Waste and Substances Site List - Site Cleanup: HWSS CLEANUP

The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements in providing information about the location of hazardous materials release sites. This list is published by California Department of Toxic Substance Control.

Government Publication Date: May 20, 2021

Toxic Pit Cleanup Act Sites: TOXIC PITS

The Toxic Pits Cleanup Act (TPCA) list identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. This list was maintained by the State Water Resources Control Board (SWRCB), is not longer maintained, and updates are not planned.

Government Publication Date: Jul 1, 1995

List of Hazardous Waste Facilities Subject to Corrective Action: DTSC HWF

This is a list of hazardous waste facilities identified in Health and Safety Code (HSC) § 25187.5. These facilities are those where Department of Toxic Substances Control (DTSC) has taken or contracted for corrective action because a facility owner/operator has failed to comply with a date for taking corrective action in an order issued under HSC § 25187, or because DTSC determined that immediate corrective action was necessary to abate an imminent or substantial endangerment.

Government Publication Date: Jul 18, 2016

EnviroStor Inspection, Compliance, and Enforcement: INSP COMP ENF

A list of permitted facilities with inspections and enforcements tracked in the Department of Toxic Substance Control (DTSC) EnviroStor.

Government Publication Date: Apr 29, 2021

School Property Evaluation Program Sites: SCH

A list of sites registered with The Department of Toxic Substances Control (DTSC) School Property Evaluation and Cleanup (SPEC) Division. SPEC is responsible for assessing, investigating and cleaning up proposed school sites. The Division ensures that selected properties are free of contamination or, if the properties were previously contaminated, that they have been cleaned up to a level that protects the students and staff who will occupy the new school.

Government Publication Date: May 30, 2022

California Hazardous Material Incident Report System (CHMIRS): CHMIRS

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS). This list has been made available by the California Office of Emergency Services (OES).

Government Publication Date: Feb 8, 2022

Historical California Hazardous Material Incident Report System (CHMIRS): HIST CHMIRS

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS) prior to 1993. This list has been made available by the California Office of Emergency Services (OES).

Government Publication Date: Jan 1, 1993

Hazardous Waste Manifest Data: HAZNET

A list of hazardous waste manifests received each year by Department of Toxic Substances Control (DTSC). The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.

Government Publication Date: Oct 24, 2016

Historical Hazardous Waste Manifest Data: HIST MANIFEST

A list of historic hazardous waste manifests received by the Department of Toxic Substances Control (DTSC) from year the 1980 to 1992. The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.

Government Publication Date: Dec 31, 1992

DTSC Registered Hazardous Waste Transporters: HW TRANSPORT

The California Department of Toxic Substances Control (DTSC) maintains this list of Registered Hazardous Waste Transporters.

Government Publication Date: Oct 19, 2020

Registered Waste Tire Haulers: WASTE TIRE

This list of registered waste tire haulers is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Apr 12, 2022

California Medical Waste Management Program Facility List: MEDICAL WASTE

This list of Medical Waste Management Program Facilities is maintained by the California Department of Public Health. The Medical Waste Management Program (MWMP) regulates the generation, handling, storage, treatment, and disposal of medical waste by providing oversight for the implementation of the Medical Waste Management Act (MWMA). The MWMP permits and inspects all medical waste off-site treatment facilities, medical waste transporters, and medical waste transfer stations. This list contains transporters, treatment, and transfer facilities.

Government Publication Date: Dec 31, 2020

Historical Cortese List: HIST CORTESE

List of sites which were once included on the Cortese list. The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements for providing information about the location of hazardous sites.

Government Publication Date: Nov 13, 2008

Cease and Desist Orders and Cleanup and Abatement Orders: CDO/CAO

The California Environment Protection Agency "Cortese List" of active Cease and Desist Orders (CDO) and Cleanup and Abatement Orders (CAO). This list contains many CDOs and CAOs that do NOT concern the discharge of wastes that are hazardous materials. Many of the listed orders concern, as examples, discharges of domestic sewage, food processing wastes, or sediment that do not contain hazardous materials, but the Water Boards' database does not distinguish between these types of orders.

Government Publication Date: Dec 6, 2021

California Environmental Reporting System (CERS) Hazardous Waste Sites: CERS HAZ

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: Apr 5, 2022

Delisted Environmental Reporting System (CERS) Hazardous Waste Sites: DELISTED HAZ

This database contains a list of sites that were removed from the California Environmental Protection Agency (CalEPA) in the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator.

Government Publication Date: Nov 29, 2018

Sites in GeoTracker: GEOTRACKER

GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater. This is a list of sites in GeoTracker that aren't otherwise categorized as LUST, Land Disposal Sites (LDS), Cleanup Sites, or sites having Waste Discharge Requirements (WDR). This listing includes program types such as Underground Injection Control (UIC), Confined Animal Facilities (CAF), Irrigated Lands Regulatory Program, plans, and non-case information.

Government Publication Date: Feb 15, 2022

Mines Listing: MINE

This list includes mine site locations extracted from the Mines Online database, maintained by the California Department of Conservation. Mines Online (MOL) is an interactive web map designed with GIS features that provide information such as the mine name, mine status, commodity sold, location, and other mine specific data. Please note: Mine location information is provided to assist experts in determining the location of mine operators in accordance with California Civil Code section 1103.4 and reflects information reported by mine operators in annual reports provided under Public Resources Code section 2207. While the Division of Mine Reclamation (DMR) attempts to populate MOL with accurate location information, the DMR cannot guarantee the accuracy of operator reported location information.

Government Publication Date: Dec 17, 2021

Recorded Environmental Cleanup Liens: LIEN

The California Department of Toxic Substance Control (DTSC) maintains this list of liens placed upon real properties. A lien is utilized by the DTSC to obtain reimbursement from responsible parties for costs associated with the remediation of contaminated properties.

Government Publication Date: May 4, 2022

Waste Discharge Requirements: WASTE DISCHG

List of sites in California State Water Resources Control Board (SWRCB) Waste Discharge Requirements (WDRs) Program in California, made available by the SWRCB via GeoTracker. The WDR program regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Government Publication Date: Feb 15, 2022

Toxic Pollutant Emissions Facilities: EMISSIONS

A list of criteria and toxic pollutant emissions data for facilities in California made available by the California Environmental Protection Agency - Air Resources Board (ARB). Risk data may be based on previous inventory submittals. The toxics data are submitted to the ARB by the local air districts as requirement of the Air Toxics "Hot Spots" Program. This program requires emission inventory updates every four years.

Government Publication Date: Dec 31, 2019

Clandestine Drug Lab Sites: CDL

The Department of Toxic Substances Control (DTSC) maintains a listing of drug lab sites. DTSC is responsible for removal and disposal of hazardous substances discovered by law enforcement officials while investigating illegal/clandestine drug laboratories.

Government Publication Date: Jan 19, 2021

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental databases were selected to be included in the search.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX B
HISTORICAL RESOURCES

ERIS

HISTORICAL AERIALS

Project Property: APN 646-100-77-00
APN 646-100-77-00
San Diego CA

Project No:

Requested By: C Young Associates


Order No: 22062300084

Date Completed: June 24,2022

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
2020	United States Department of Agriculture	1" = 500'	
2018	United States Department of Agriculture	1" = 500'	
2016	United States Department of Agriculture	1" = 500'	
2014	United States Department of Agriculture	1" = 500'	
2012	United States Department of Agriculture	1" = 500'	
2010	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2005	United States Department of Agriculture	1" = 500'	
2002	United States Geological Survey	1" = 500'	
1996	United States Geological Survey	1" = 500'	
1994	United States Geological Survey	1" = 500'	
1985	United States Geological Survey	1" = 500'	
1981	United States Geological Survey	1" = 500'	
1976	PRIVATE	1" = 500'	
1971	United States Geological Survey	1" = 500'	
1966	United States Geological Survey	1" = 500'	
1958	FAIRCHILD	1" = 500'	
1953	Agricultural Stabilization & Conserv. Service	1" = 500'	
1949	Agricultural Stabilization & Conserv. Service	1" = 500'	
1928	County of San Diego	1" = 500'	




Year: 2020
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 2018
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 2016
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 2014
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 2012
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 2010
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS




Year: 2005
Source: USDA
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS




Year: 2002
Source: USGS
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS




Year: 1996
Source: USGS
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 1994
Source: USGS
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 1985
Source: USGS
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 1981
Source: USGS
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 1976
Source: PRIVATE
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS



Year: 1971
Source: USGS
Scale: 1" = 500'
Comment:

Address: APN 646-100-77-00, San Diego, CA
Approx Center: -116.98622804,32.5624841

Order No: 22062300084

ERIS