CITY OF SAN DIEGO HISTORICAL RESOURCES BOARD

DESIGN ASSISTANCE SUBCOMMITTEE

Wednesday, March 7, 2012, at 4:00 PM 5th Floor Large Conference Room City Operations Building, Development Services Department 1222 First Avenue, San Diego, CA

MEETING NOTES

1. ATTENDANCE

Subcommittee Members		Gail Garbini; Linda Marrone; Ann Woods
	Recusals	N/A
City Staff		
	HRB	Kelley Stanco; Jodie Brown; Cathy Winterrowd
Guests		
	Item 3A	Bob Bauer, Terry Buis
	Item 3B	Tony Crisafi, Ed Sutton
	Item 3C	Randy Cramer, Marie Burke Lia
	Other	Bruce Coons, SOHO

- 2. Public Comment (on matters not on the agenda): None
- 3. Project Reviews

• <u>ITEM 3A</u>:

Listings: HRB Site #528 Address: 7890 Torrey Lane Historic Name: Dr. Harold C. & Frieda Daum Urey/Russell Forester House Significance: Architecture (Custom Residential Ranch); Master Architect Russell Forrester Mills Act Status: Yes PTS #: N/A Project Contact: Bob Bauer, Annette and Terry Buis Treatment: Rehabilitation Project Scope: This project proposes an addition of 720.5 SF to an existing single family residence at the rear of the principle structure. Conversion of the exisitng master bedroom into a sitting area for a new master bedroom. Conversion of the existing master bathroom into an internal laundry room. Provide a new master bath and walk-in closet. Install one factory fabricated gas-only fireplace in the new bedroom area. Remodel an existing bedroom with a total remodel of 550 SF. Replace three existing windows and two exterior single light doors, with equivalent wood framed units in the original residence.

Existing Square Feet: 3,126 Additional Square Feet: 721 Total Proposed Square Feet: 3,847 Prior DAS Review: N/A

<u>Staff Presentation</u>: The property owner is proposing to construct an addition of 720.5SF at the rear of the house. They are also proposing to convert the existing master bedroom into a sitting area for a new master bedroom. They are also proposing to convert the existing master bathroom into an internal laundry, providing a new master bath and walk-in closet. They are also proposing to install a gas fireplace and replace two windows and two doors.

<u>Applicant Presentation</u>: There are two main reasons that we are proposing to modify this house. The house does not have an internal laundry which is currently located in a breezeway. There is also an existing drainage problem; the closet area and the rear wall of the bedroom have water intrusion problems. We are proposing to elevate a concrete slab at the rear of the building to help the problem. There is also a storage issue. They will be adding storage to the house. Based on a perspective view there is little visibility from the street given that the house sits up from the street.

Public Comment:

Name	Comments
Coons	Are portions of the existing house being removed? (the
	back wall that has the issue with water intrusion) Are
	windows and doors being replaced? (the windows and
	doors in the two bedrooms are being replaced with dual
	glazing to address a fire issue)

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
Marrone- Having trouble visualizing it.	Applicant provided site plan which
What is the relationship to the street?	shows the house is elevated from the
	street behind the detached garage.
Garbini-Is there a dog run?	It is a walkway to get access to the
	rear of the property to clear out
	vegetation
Marrone-On the rear side it is raised 6" but	Yes
it is set back?	
Marrone- There is a 1968 addition, is that	Yes
part of the historic designation?	
Woods-Are there any other views of the	Not really, from the other houses
house from public right-of-ways above?	above but not from the public-right-of-
	way
Garbini-What were staff concerns with the	Staff did not discuss the project with
project?	the applicant prior to their submittal to

Subcommittee-member Issue or Question	Applicant's Response
	DAS. Plans were also simultaneously
	submitted to the city for review.
Woods-Would you be able to see the	No.
chimney from the front of the house? I	
have concerns about it.	

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Woods	Uncertain about the addition. Concerned about the metal chimney addition.
Garbini	Would like to see the property, is it possible to go out to the site? Would like to visit the site and would like to have reduced copies of what was already seen and have them PDF'ed to me.
Marrone	It is setback and seems to be within the Secretary of the Interior's Standards.

Staff Comment:

Staff Member	Comments
Stanco	It is possible for the subcommittee members to go out to
	the site individually to view the site and the applicant can
	come back to DAS next month or the month after.

Recommended Modifications: The DAS subcommittee members would like to have a copy of the plans available for their review and would like to make a site visit to the property to put the plans into perspective. The applicant has been asked to come back to DAS at the next available meeting to continue to discuss the proposed addition.

Consensus:

Consistent with the Standards

Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

• ITEM 3B:

Listings: HRB Site #520 Address: 333 Dunemere Drive Historic Name: Casa de la Paz / The Dunes Significance: Cultural Landscape; Historical Person (Philip Barber); Architecture (Spanish Eclectic); Master Builder (Philip Barber) Mills Act Status: Yes PTS #: 273017 Project Contact: Tony Crisafi, John and Victoria Miller

Treatment: Rehabilitation

<u>Project Scope</u>: Remodel and addition to the existing guest house over the 2-car garage. The remodel consists of revising the existing one bedroom guest house layout to a new configuration. The addition consists of a new 2 car garage on the first floor adjacent to the existing structure with a new 1 bedroom addition above. The addition will be connected to the existing guest house via an enclosed "bridge" over the external staircase to the second floor. There is also a proposed addition at the rear of the existing guest house accommodate a new bedroom.

Existing Square Feet: 1,192 Additional Square Feet: 1,150 Total Proposed Square Feet: 2,342 Prior DAS Review: N/A

<u>Staff Presentation</u>: The new design retains the staircase and constructs the new addition as an adjacent structure connected to the existing garage through an enclosed hallway at the second floor over the existing stairway. The design also includes demolition of the rear façade of the existing garage at the ground floor, and demolition of nearly the entire rear façade at the second floor. The garage and second floor above will be extended back toward the property line. Staff is concerned about the extent of demolition at the rear façade, primarily at the second floor, and is seeking input from DAS on this aspect of the project scope.

<u>Applicant Presentation</u>: The garage originally had three bays when it was relocated and turned 90 degrees and then relocated 100' away. We are proposing to remodel the interior space of the existing garage which would require demolition of the rear wall on the garage to accommodate a new bedroom. We would maintain the external staircase, but it would become an internal staircase. We have made some modifications to the new structure to change the look and we have stepped back the new addition. The two windows on the side would be impacted and half of the existing porch. We would also like to remove the decorative tile that is non historic on the garage.

Name	Comments	
Coons	Explain the bump-out. (The building will serve as a guest	
	house for the grandchildren and children. The way the	
	windows are currently configured will not accommodate	
	the internal space needed to fit everything; which	
	required them to bump out to the back.	
Coons	What was the house designated under? (A,B,C,D). If	
	you allow the addition, it is not reversible and you would	
	be releasing them from that Standard.	
Moomjian	There are a number of window modifications on the main	
	house already.	

Public Comment:

Subcommittee-member Issue or Question	Applicant's Response
Marrone: Will the existing staircase and	The windows will remain and door
porch still be there?	opening.
Marrone: Because they were moving an	Yes, try to discourage large sections of
original wall is that why staff is concerned?	demolition.
Garbini-Were there windows there before?	Yes, No
Their views are not any different?	
Garbini: From the other property, they	Yes
would have a view of the addition if there	
were no vegetation?	
Garbini: What is between the fence line and	There is just a small strip of land
the rear of the building?	where there is just some storage/tile
Marrone-Is Tom Sheppard associated with	He is associated with an addition to
the property?	the main house

<u>Q&A</u>:

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Garbini	It appears that the proposed addition is consistent with
	the Standards.
Marrone	It is at the rear of the property and will not have an
	impact on the view from the public right of way. It is
	good that staff requested that the staircase be saved and a
	portion of the balcony will remain. I feel that it is a
	modest addition and will not impact the view for the
	public.
Woods	Defer to Linda, but I am comfortable with it

Staff Comment: None

<u>Recommended Modifications</u>: The proposed addition appears to be consistent with the Secretary of the Interior's Standards as proposed.

Consensus:

 \blacksquare Consistent with the Standards

Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

• <u>ITEM 3C</u>:

<u>Listings</u>: N/A <u>Address</u>: 2550 5th Avenue <u>Historic Name</u>: Mr. A's <u>Significance</u>: N/A <u>Mills Act Status</u>: N/A <u>PTS #</u>: 266533 <u>Project Contact</u>: Carrier Johnson + Culture; Alessio Investment Co. <u>Treatment</u>: Rehabilitation <u>Project Scope</u>: Replace the exterior metal panels on the tower portion of the building. <u>Existing Square Feet</u>: N/A <u>Additional Square Feet</u>: N/A <u>Total Proposed Square Feet</u>: N/A <u>Prior DAS Review</u>: N/A

<u>Staff Presentation</u>: This is not designated, but came to staff through the Over-45 process to replace the metal panels on the exterior of the tower portion of the building. Staff has identified the building as potentially historic. With the initial review staff determined that the replacement of the exterior panels was not consistent with the Secretary of the Interior's Standards. The applicant has informed staff that there are some issues with the existing panels; staff does not have an issue with replacement, but the pattern should be replicated. The proposed replacement does not replicate the existing pattern.

<u>Applicant Presentation</u>: The building was constructed in 1964. We are only proposing work on the tower portion of the building which is essentially the same on all sides. The panels were painted about 3-4 years ago. The paint is peeling, but we would like to fix them. Panels are made of stamped steel with porcelain enamel, which is technology that was used in the 50s and 60s but is no longer manufactured. When the panels were made in 1964 they were made of 6 pieces with a line down the middle so they would not warp or bend. There is a failure on the connection points which makes repair infeasible. It is not economically feasible to replicate the panels or to have them cleaned. We would like to install a single panel with a Kynar finish. The technology today allows for one flat piece without the need for the cross-members. All you would see is a flat surface.

Name	Comments
Coons	The panels are a character defining feature of the
	building. This building should go through the whole
	review and be taken to the board for a determination. It
	is easy to clean and you can still put porcelain on any
	surface. It is very easy to clean this surface with select
	products and re-fabricate those that need to be replaced.
	(CA Sheet Metal told the applicant that they could not
	replicate the panels)

Public Comment:

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
Garbini-The architecture is so streamline	Not a simple matter of cleaning the
that the panels are very character defining.	panels. They would have to remove

Subcommittee-member Issue or Question	Applicant's Response
If the panels are smooth then the look will	the panels to remove the paint and not
change. I would recommend that they not be	sure how it was originally painted.
removed but cleaned. I also think that it	Believe that it was the technology at
should go to the Historical Resources Board	the time and was not a design feature.
for review.	
Marrone-Would it be helpful to bring info	Yes we could bring more technical
to staff to see other ways to restore the	information to staff.
panels.	
Marrone-Could you research other options-	Yes.
to remove is labor intensive	

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Garbini	I understand that at the time that it was the only way to
	manufacture the panels. That may be the case it still
	becomes a character defining feature.
Marrone	Agree. If this was a historic building, they would have to
	maintain the appearance.
Woods	Echoes the look of the lower portion of the building.
	Impacts the character of the building. Should go to the
	Historical Resources Board.

Staff Comment: None

<u>Recommended Modifications</u>: If the building is considered architecturally significant, the panels appear to be a character-defining feature, and that replacing the panels with new panels that did not replicate the pattern would significantly alter the character and appearance of the building. If the existing panels cannot be retained or accurately replaced, the DAS recommended HRB review of the building to determine significance.

Consensus:

Consistent with the Standards

Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

 \blacksquare Inconsistent with the Standards

4. Adjourned at 5:19 PM

The next regularly-scheduled Subcommittee Meeting will be on April 4, 2012 at 4:00 PM.

For more information, please contact Jodie Brown at <u>JDBrown@sandiego.gov</u> or 619.533.6300