



Mitigation Assignments By Project 2015



Habitat	Tier	Impact	Ratio	Mitigation Acreage	Mitigation Location*
10325 Roselle Street Emergency					
Diegan Coastal Sage Scrub (DCSS)	II	0.0010	0:1	0	No mitigation required for temporary impacts below the Significance Threshold
Disturbed Habitat (DHAB)	IV	0.0120	0:1	0	Tier IV Impacts do not Require Mitigation
0.0130					
Avenida Playa Veracruz - East Shepherd Canyon Water Main Emergency					
Diegan Coastal Sage Scrub (DCSS)	II	0.0080	0:1	0	No mitigation required for temporary impacts below the Significance Threshold
Non-Native Grassland (NNG)	IIIB	0.0190	0:1	0	No mitigation required for temporary impacts below the Significance Threshold
Non-Native Vegetation (NNV)	IV	0.0040	0:1	0	Tier IV Impacts do not Require Mitigation
0.0310					
Dakota Canyon Manhole Repairs - Emergency					
Waters of the U.S.	W	0.0006	1:1	0.006	Rose Canyon Mitigation Site
0.0006					
Dove Canyon Pipe Encasement					
Non-Vegetated Channel (NVC)	W	0.0005	1:1	0.005	San Diego River Wetland Creation Site
0.0005					
Hinson Place Emergency Sewer Repair					
Disturbed Habitat (DHAB)	IV	0.0090	0:1	0	Tier IV Impacts do not Require Mitigation
0.0090					
Mission Valley Canyon Sewer Lateral Repair					
Diegan Coastal Sage Scrub (DCSS)	II	0.0006	1:1	0.006	Lake Murray Mitigation Site
0.0006					
Murphy Canyon MH114 Locate and Raise					
Southern Willow Scrub (SWS)	W	0.0140	2:1	0.028	San Diego River/Rancho Mission Wetlands Mitigation Sites
0.0140					
Murphy Creek MH 111 Emergency					
Non-Vegetated Channel (NVC)	W	0.0010	0:1	0	Temporary impacts to un-vegetated channel do not require mitigation
0.0010					
Nobel Drive MH97 Emergency					
Mule Fat Scrub (MFS)	W	0.0047	2:1	0.0094	Rose Canyon Mitigation Site
0.0047					
Pump Station 45 Pipe Repair Emergency					

Diegan Coastal Sage Scrub (DCSS)	II	0.0120	1:1	0.012	Canyon View Uplands
Disturbed Habitat (DHAB)	IV	0.0030	0:1		Tier IV Impacts do not Require Mitigation

0.0150

Sorrento Valley Water Main Leak Emergency

Disturbed Wetland (DWET)	W	0.0180	0:1	0	Area previously impacted by MTS project
Southern Willow Scrub (SWS)	W	0.0090	3:1	0	Construction not Complete. Mitigation not yet assigned.

0.0270

South Chollas LTA

Diegan Coastal Sage Scrub (DCSS)	II	0.3630	1:1	0.363	Marron Valley Cornerstone Lands
Disturbed Habitat (DHAB)	IV	0.0770	0:1	0	Tier IV Impacts do not Require Mitigation
Non-Native Vegetation (NNV)	IV	0.0030	0:1	0	Tier IV Impacts do not Require Mitigation

0.4430

* All Habitat Mitigation is within the MHPA