CITY OF SAN DIEGO HISTORICAL RESOURCES BOARD

DESIGN ASSISTANCE SUBCOMMITTEE

Wednesday, June 7, 2017, at 4:00 PM 5th Floor Large Conference Room City Operations Building, Development Services Department 1222 First Avenue, San Diego, CA

MEETING NOTES

1. ATTENDANCE

Subcommittee Members	Todd Pitman; Ann Woods; Matt Winter
Recusals	
City Staff	
HRB	Jodie Brown; Camille Pekarek
CCDC	Aaron Hollister; Brad Richter
Guests	
Item 3A	Sonya Sparks; TJ Sparks; Benetta Buell-Wilson
Item 3B	Justin Mandelbaum; David Mandelbaum; Marie Huff;
	David Schroedl;
Item 3C	Gulla Jonsdottirai; Elie Samaha; Marsha Sewell
Other	Amie Hayes; Bruce Coons, SOHO

- 2. Public Comment (on matters not on the agenda)
- 3. Project Reviews

• <u>ITEM 3A</u>:

Listings: N/A Address: 4357 Argos Drive Historic Name: N/A Significance: N/A Mills Act Status: No PTS #: Project Contact: Benetta Buell-Wilson; Kiley Wallace Treatment: Restoration Project Scope: The owners wish to restore this house and looking for guidance on stucco, roof repair and replacement of the non-historic windows. Existing Square Feet: 1,836 SF Additional Square Feet: 0 Total Proposed Square Feet: 1,836 SF

Prior DAS Review: No

<u>Staff Presentation</u>: This property is not currently designated. The property owner would like to do some restoration work on the property in order to have it designated at a later date. They have specific questions for DAS members.

<u>Applicant Presentation</u>: The property is a 1926 Tudor Revival in Kensington. It has quite a bit of deferred maintenance. We have questions about stucco, asphalt shingles, and some window replacement. We would like to restore the windows back to wood double hung windows. We would like to know if it is OK to use acrylic stucco with integral color. The roof is currently asphalt shingles, and we would like to know if it is OK to replace the shingles with a similar product? Also, there are currently bay windows on the house and we would like to restore the original double hung windows.

Public Comment:

None

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
The roof shingles in asphalt is not an issue.	
I think there is little concern over the use of	
acrylic stucco.	
If the windows match the original in the	
original opening per the studs there is no	
issue.	

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Pitman	There are no stucco issues or window issues with what is
	proposed.

Staff Comment:

None

Recommended Modifications:

None

Consensus:

X Consistent with the Standards

Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

• <u>ITEM 3B</u>:

Listings: HRB Site #1125, CR Address: 7727 Lookout Historic Name: George and Marion Cottrell/Cliff May House Significance: C, D Mills Act Status: No PTS #: Project Contact: Justin Mandelbaum; Lisa Kriedeman <u>Treatment</u>: Rehabilitation Project Scope: Review of the conceptual re-design of the initial plan to develop Parcel 4 located to the north of the designated house. Proposed design seeks to preserve the viewshed from the historical structure. <u>Existing Square Feet</u>: 2,400 Additional Square Feet: 3,000 <u>Total Proposed Square Feet</u>: 5,400 <u>Prior DAS Review</u>: 12.2.2015

<u>Staff Presentation</u>: This project is a re-design of a property located adjacent to a designated resource. The project proposes to construct 3 new houses on lots adjacent to the designated resource. In the previous version, there was a one story portion that allowed visibility from the historic resource. This re-design still allows for visibility but re-designs the space.

<u>Applicant Presentation</u>: The new design extends the patio of the historic house out over the proposed new construction. The lot slopes down allowing for the living room, dining room, kitchen and garage to sit below the patio.

Public Comment:

Name	Comments
Bruce Coons	This design seems better than the last one.

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
It was the view from the resource out that	Yes.
was significant?	
There will be an easement to maintain that	Yes.
Cliff May patio?	
What is the roof past the patio?	There will be no roof, just the patio.
So there will be an actual easement, so they	No.
can't build anything in the future?	
What's the difference?	The previous design blocked other
	views. The living area was also
	impacted by the other design.

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Pitman	It appears to be consistent with the Standards.

Staff Comment:

None

Recommended Modifications:

None

Consensus:

X Consistent with the Standards

Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

• <u>ITEM 3C</u>:

<u>Listings</u>: Non-contributor <u>Address</u>: 701 5th Avenue <u>Historic Name</u>: Gaslamp Historic District <u>Significance</u>: <u>Mills Act Status</u>: No <u>PTS #</u>: <u>Project Contact</u>: Samaha Elie; Gulla Jonsdottir <u>Treatment</u>: Rehabilitation <u>Project Scope</u>: Renovate the existing Gaslamp Theatre constructed in 1997. New uses will include ground level restaurants; a new theatre and a roof top deck. <u>Existing Square Feet</u>: 66,180 <u>Additional Square Feet</u>: 66,180 <u>Prior DAS Review</u>: 7.6.2016

<u>Staff Presentation</u>: The proposed project will re-design the exterior of a non-contributing resource within the Gaslamp. The original building was a movie theater and the proposed use will be a luxury theater with restaurants at the ground floor.

<u>Applicant Presentation</u>: This theater is associated with the Grauman Theater in Los Angeles. We will be providing 8 luxury theaters and three restaurants on the ground floor. The exterior of the building will be re-branded to reference the Grauman Theater. There exterior will be painted white. Exterior drapes will be added to the 5th Avenue side. The ground floor will be opened up for access to the restaurants.

Name	Comments
Marsha Sewell	How will you be comply with the land use ordinance?
	The sign does not comply with the PDO.
Bruce Coons	I was not fond of the previous building. I did like the
	stone. Per the Standards, you should match the cornice,
	rhythm of the openings, etc. Prior buildings built to
	respect the lots. I am not telling you to replicate, but you
	should respect the design. The corner appears to be
	primarily signage. I am not aware of any ordinance that
	will allow it. The colors are regulated but should relate to
	the surrounding. Concentrate on rhythm on the bays—
	they should be more open on the 1 st floor. (There are
	brace frames, so we are limited.) Transoms should be
	used and the cornice behind the drapes should be
	maintained.

Public Comment:

<u>Q&A</u>:

Subcommittee-member Issue or Question	Applicant's Response
Glad to see you open up the south façade.	
Great. Minor revisions. It will help to	
activate the street.	
I think the building is terrible. It minimizes	
the other building. The tower is a little	
heavy handed. There should be a quieter	
way to convey.	
The tower is the biggest change. The mass	We could lower this 3'-4'.
got bigger as it is now squared off. This	
element could be improved.	
A blade sign would be better.	The blade is for signage. We would
	not do the dragon as a blade sign.
The cornice should be visible.	The drapes can be placed below the
	cornice.

Subcommittee Discussion and Comment:

Subcommittee-member	Comments
Pitman	The drapes should be more open to make the windows
	behind them more visible. The marble should be Carrera
	marble. The height of the tower should be reduced. The
	hand and foot imprints are fine at the interior and the
	exterior.

Staff Comment:

None

Recommended Modifications:

Open up the drapes and place them below the cornice. Reduce the height of the tower. Use Carrera marble at the exterior.

Consensus:

Consistent with the Standards

X Consistent with the Standards if modified as noted

Inconsistent with the Standards and needs revision and additional review

Inconsistent with the Standards but is the best feasible alternative

Inconsistent with the Standards

4. Adjourned at 5.45 PM

The next regularly-scheduled Subcommittee Meeting will be on July 5, 2017 at 4:00 PM.

For more information, please contact Jodie Brown at JDBrown@sandiego.gov or 619.533.6300