



SAN YSIDRO

Focus Areas and Existing Conditions



SAN YSIDRO

Recommended Improvement Areas



SAN YSIDRO

Improvement Details

Improvement Area	Concerns	Recommendations	Potential Improvements
SY-1: Via San Ysidro / I-5 Northbound Ramp Intersection Improvements	<ul style="list-style-type: none"> History of pedestrian related accidents Vehicles do not yield to pedestrians 	Improve pedestrian safety at freeway ramps.	<ul style="list-style-type: none"> Install traffic signal at I-5 NB on/off ramps.
SY-2: Calle Primera Walkability Improvements	<ul style="list-style-type: none"> Missing or incomplete sidewalk on north side from Via San Ysidro to Willow St. No pedestrian lighting along sidewalk near pedestrian bridge. 	Construct new sidewalk along north side of Calle Primera to improve access to transit and access to existing pedestrian bridge	<ul style="list-style-type: none"> Install sidewalk (1,000 LF)* Install ADA compliant curb ramps at Via San Ysidro / Calle Primera Install pedestrian scale lighting near access to pedestrian bridge
SY-3: Beyer Boulevard Corridor Enhancements	<ul style="list-style-type: none"> Parking occurs on west side of Beyer Boulevard Pedestrians cross 4 lanes of traffic from parked cars to the residential units High traffic speeds result in uncomfortable walking condition on Limited access across trolley tracks splits San Ysidro community 	Evaluate the feasibility of reducing Beyer Boulevard from 4 lanes to 2 lanes, integrate pedestrian and bicycle enhancements, and improve connectivity within the community	<ul style="list-style-type: none"> The San Ysidro Mobility Plan has identified corridor improvements for Beyer Boulevard including a road diet project Evaluate the feasibility of constructing a pedestrian overpass over trolley tracks, near Del Sur / Beyer Boulevard* Install traffic signal at Beyer Blvd. / Smythe Ave.* Modify driveway at Border Patrol location to reduce crossing distance and remove obstructions
SY-4: Beyer Boulevard Walkability Improvements (W Park Avenue to Otay Mesa Road)	<ul style="list-style-type: none"> Missing or incomplete sidewalks at Beyer / North Street lights at intersections only resulting in dark sidewalks Missing or incomplete sidewalks on southside near Otay Mesa Road Existing school zone signs do not comply with current standards 	Install missing sidewalks and pedestrian scale street lights to improve walkability.	<ul style="list-style-type: none"> Install sidewalk on northwest corner at Beyer / North Install pedestrian scale street lights from North to Otay Mesa Road Install sidewalks from I-805 overcrossing to Otay Mesa Road on south side of Beyer Boulevard

*Consistent with San Ysidro Community Planning Group recommendations



SAN YSIDRO

Improvement Details

Improvement Area	Concerns	Recommendations	Potential Improvements
SY-5: Smythe Avenue Connection Improvements	<ul style="list-style-type: none"> • Unsignalized intersection near railroad tracks. • High pedestrian volume as this is the only railroad crossing on Beyer Boulevard. • Lack of connectivity at San Ysidro Boulevard • Numerous sidewalk obstructions that restrict accessibility (utility poles) • School signage out of date 	Improve connectivity in San Ysidro across trolley tracks and improve pedestrian safety and visibility	<ul style="list-style-type: none"> • Install new traffic signal at Smythe Ave. / Beyer Blvd.* • Install curb extensions to narrow crossing distance (at new signal) • Install ADA compliant curb ramps, marked crosswalks and countdown timers at new signal • Install enhanced marked crosswalk at W. San Ysidro Boulevard / Smythe Avenue* • Reconstruct sidewalks to remove obstructions along corridor • Replace school signage with a new CA-MUTCD sign
SY-6: Seaward Avenue and R/R tracks Sidewalk Project	<ul style="list-style-type: none"> • No pedestrian lighting along path fronting R/R tracks • Missing or incomplete sidewalks on Seaward Avenue 	Improve pedestrian safety along rail ROW by installing pedestrian scale lighting and completing sidewalks to improve connectivity	<ul style="list-style-type: none"> • Install sidewalk from railroad tracks to 162 West Seaward on the south side of the street • Install pedestrian scale lighting along sidewalk fronting railroad tracks from West Seaward Avenue to South Vista Avenue
SY-7: Sunset Lane Walkability Improvements	<ul style="list-style-type: none"> • Sunset Elementary School fronts Sunset Lane • Existing school signs do not meet current MUTCD standards • Sidewalk obstructions on north side of street restrict accessibility • Traffic calming speed humps and striping are deteriorating 	Improve pedestrian safety by reducing traffic speeds and improving visibility of pedestrians	<ul style="list-style-type: none"> • Install CA-MUTCD compliant signage • Repair existing sidewalk and remove existing obstructions on north side of the street • Replace existing marked crosswalks with highly reflective paint and enhanced features • Replace one midblock speed hump with a speed table (adjacent to staff parking lot)

*Consistent with San Ysidro Community Planning Group recommendations



SAN YSIDRO

Improvement Details

Improvement Area	Concerns	Recommendations	Potential Improvements
SY-8: E and W Park Avenue Corridor Enhancements	<ul style="list-style-type: none"> • Recreational uses between East and West Park • Sidewalk along tennis courts too narrow • Ballards near intersection indicate issues 	Improve walkability through implementation of traffic calming and through wider sidewalks	<ul style="list-style-type: none"> • Widen sidewalks through restricted area • Install curb extension at intersections and speed tables midblock to reduce speeds • Install ADA compliant curb ramps at intersection
SY-9: E. Beyer Boulevard Walkability Improvements	<ul style="list-style-type: none"> • School crosswalk faded and difficult to see • No street lights makes corridor dark at night • No more crossing at end of existing pedestrian bridge 	Improve visibility of pedestrians and school children through lighting and signage and traffic calming	<ul style="list-style-type: none"> • Install a raised enhanced crosswalk at existing marked school crosswalk including overhead "Flashing Yellow" lights or hawk signal • Install street lights on E. Beyer Boulevard from I-805 Pedestrian bridge to Filoi Avenue • Install ADA compliant curb ramps at Pedestrian Bridge and enhance crosswalk • Install a raised crosswalk at the I-805 Pedestrian Bridge access at E. Beyer Boulevard
SY-10: Otay Mesa Road Connectivity Improvements	<ul style="list-style-type: none"> • Children are walking in the street between San Ysidro High School and the community due to lack of existing sidewalk 	Improve walkability, safety, and connectivity from San Ysidro community to local high school	<ul style="list-style-type: none"> • Install sidewalk on one side of the road to improve connectivity* • Install street lights on Otay Mesa Road between Hawken Drive and San Ysidro High School • Install ADA compliant curb ramps at all intersections along the corridor

*Consistent with San Ysidro Community Planning Group recommendations

