


**Barrio Logan Community Plan Area**  
San Diego, CA 92113

Inquiry Number: 2230960.1s  
June 03, 2008

**EDR DataMap™**

**Area Study**



440 Wheelers Farms Road  
Milford, CT 06461  
Toll Free: 800.352.0050  
[www.edrnet.com](http://www.edrnet.com)

***Thank you for your business.***  
Please contact EDR at 1-800-352-0050  
with any questions or comments.

**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2006 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

## TARGET PROPERTY INFORMATION

### ADDRESS

SAN DIEGO, CA 92113  
SAN DIEGO, CA 92113

## DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records within the requested search area for the following databases:

### FEDERAL RECORDS

**NPL**..... National Priority List  
**Proposed NPL**..... Proposed National Priority List Sites  
**Delisted NPL**..... National Priority List Deletions  
**US ENG CONTROLS**..... Engineering Controls Sites List  
**US INST CONTROL**..... Sites with Institutional Controls  
**US CDL**..... Clandestine Drug Labs  
**FUDS**..... Formerly Used Defense Sites  
**LUCIS**..... Land Use Control Information System  
**CONSENT**..... Superfund (CERCLA) Consent Decrees  
**ROD**..... Records Of Decision  
**UMTRA**..... Uranium Mill Tailings Sites  
**ODI**..... Open Dump Inventory  
**DEBRIS REGION 9**..... Torres Martinez Reservation Illegal Dump Site Locations  
**MINES**..... Mines Master Index File  
**MLTS**..... Material Licensing Tracking System  
**RADINFO**..... Radiation Information Database  
**RAATS**..... RCRA Administrative Action Tracking System

### STATE AND LOCAL RECORDS

**Toxic Pits**..... Toxic Pits Cleanup Act Sites  
**CA FID UST**..... Facility Inventory Database  
**LIENS**..... Environmental Liens Listing  
**DEED**..... Deed Restriction Listing  
**CDL**..... Clandestine Drug Labs

### TRIBAL RECORDS

**INDIAN RESERV**..... Indian Reservations  
**INDIAN ODI**..... Report on the Status of Open Dumps on Indian Lands  
**INDIAN LUST**..... Leaking Underground Storage Tanks on Indian Land  
**INDIAN UST**..... Underground Storage Tanks on Indian Land

## SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

## EXECUTIVE SUMMARY

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

### FEDERAL RECORDS

**NPL LIENS:** This database contains a list of federal Superfund liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens. The source of this database is the U.S. EPA.

A review of the NPL LIENS list, as provided by EDR, and dated 10/15/1991 has revealed that there are 2 NPL LIENS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
RIGEL STREET DRUM		94	2023
RIGEL STREET DRUM (AMMENDED -		94	2057

**CERCLIS:** The Comprehensive Environmental Response, Compensation and Liability Information System contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the CERCLIS list, as provided by EDR, and dated 04/08/2008 has revealed that there are 2 CERCLIS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b><i>MASTER PLATING</i></b>	<b><i>2109 NEWTON AVE</i></b>	<b><i>63</i></b>	<b><i>1351</i></b>
SAN DIEGO PUBLIC WORKS CENTER	SAN DIEGO NAVAL STATION	107	2442

**CERC-NFRAP:** Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 12/03/2007 has revealed that there are 16 CERC-NFRAP sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
HEAVY EQUIPMENT LOT	1475 J ST	15	87
ALLEN, WILLIS M.	1902 NATIONAL AVE.	37	460
<b><i>PACIFIC TREATMENT</i></b>	<b><i>1668 NATIONAL AVENUE</i></b>	<b><i>37</i></b>	<b><i>628</i></b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
SUPERIOR CRANE AND RIGGING, IN	1779 MAIN STREET	55	988
PROLINE PAINT STORE	2646 MAIN ST.	59	1067
<b>BARRIO SENIOR VILLAS</b>	<b>2330 NEWTON AVE</b>	<b>59</b>	<b>1181</b>
<b>PACIFIC TREATMENT CORP</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1448</b>
<b>CLEANING DYNAMICS CORP</b>	<b>2146 MAIN ST</b>	<b>69</b>	<b>1477</b>
KELCO DIVISION OF MERCK & CO.,	2145 EAST BELT	79	1648
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAY FRONT STREET</b>	<b>79</b>	<b>1682</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
<b>NATIONAL STEEL AND SHIPBUILDIN</b>	<b>2798 EAST HARBOR DRIVE</b>	<b>92</b>	<b>1959</b>
<b>RIGEL STREET DRUM SITE</b>	<b>1620 RIGEL ST</b>	<b>94</b>	<b>2048</b>
ARNHART ELECTRIC	3520 MAIN ST	101	2068
<b>SAN DIEGO GALVANIZING INCORPOR</b>	<b>3586 DALBERGIA STREET</b>	<b>104</b>	<b>2404</b>

**LIENS 2:** A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

A review of the LIENS 2 list, as provided by EDR, and dated 02/08/2008 has revealed that there is 1 LIENS 2 site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>RIGEL STREET DRUM SITE</b>	<b>1620 RIGEL ST</b>	<b>94</b>	<b>2048</b>

**CORRACTS:** CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 03/26/2008 has revealed that there are 3 CORRACTS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>PACIFIC TREATMENT</b>	<b>1668 NATIONAL AVENUE</b>	<b>37</b>	<b>628</b>
<b>PACIFIC TREATMENT CORP</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1448</b>
<b>USNAVY SAN DIEGO NAVAL STN PWC</b>	<b>32ND ST AND HARBOR DR</b>	<b>115</b>	<b>2506</b>

**RCRA-TSDF:** RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-TSDF list, as provided by EDR, and dated 03/06/2008 has revealed that there are

## EXECUTIVE SUMMARY

3 RCRA-TSDF sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>PACIFIC TREATMENT</b>	<b>1668 NATIONAL AVENUE</b>	<b>37</b>	<b>628</b>
<b>PACIFIC TREATMENT CORP</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1448</b>
<b>USNAVY SAN DIEGO NAVAL STN PWC</b>	<b>32ND ST AND HARBOR DR</b>	<b>115</b>	<b>2506</b>

**RCRA-LQG:** RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/06/2008 has revealed that there are 13 RCRA-LQG sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
Not reported	1620 NEWTON AVE.	37	596
Not reported	1531 NATIONAL AVENUE	37	675
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
Not reported	1995 BAYFRONT STREET	68	1382
<b>PACIFIC SHIP (BAE SYSTEMS)</b>	<b>2205 E BELT ST</b>	<b>79</b>	<b>1623</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>1401 SAMPSON ST</b>	<b>79</b>	<b>1628</b>
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAY FRONT STREET</b>	<b>79</b>	<b>1682</b>
CONTINENTAL MARTIME NASSCO	1995 BAY FRONT ST	79	1694
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>NATIONAL STEEL AND SHIPBUILDIN</b>	<b>2798 EAST HARBOR DRIVE</b>	<b>92</b>	<b>1959</b>
<b>PACIFIC SHIP REPAIR &amp; FABRICATI</b>	<b>1625 RIGEL STREET</b>	<b>94</b>	<b>2023</b>
32ND STREET NAVAL STATION	3600 SURFACE NAVY BOULE	101	2098
<b>USNAVY SAN DIEGO NAVAL STN PWC</b>	<b>32ND ST AND HARBOR DR</b>	<b>115</b>	<b>2506</b>

**RCRA-SQG:** RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/06/2008 has revealed that there are 93 RCRA-SQG sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SHELL SEERVICE STATION</b>	<b>1619 G STREET</b>	<b>5</b>	<b>7</b>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
<b>PACIFIC MARINE SHEET METAL COR</b>	<b>410 15TH ST</b>	<b>15</b>	<b>99</b>
<b>SDG &amp; E SERVICE BUILD</b>	<b>114 TENTH AVENUE</b>	<b>21</b>	<b>164</b>
<b>SAN DIEGO TRANSIT CORP</b>	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>CAL LINEN SUPPLY</b>	<b>101 16TH ST</b>	<b>24</b>	<b>307</b>
<b>CONTINENTAL BAKING COMPANY</b>	<b>1301 IMPERIAL AVE</b>	<b>28</b>	<b>354</b>
<b>NATIONAL BRAKE SERVICE INC</b>	<b>2040 IMPERIAL AVE</b>	<b>29</b>	<b>369</b>
<b>OCEAN HABITABILITY INC</b>	<b>1844 IMPERIAL AVE</b>	<b>29</b>	<b>377</b>
<b>WILSON &amp; HAMPTON REFINISHING I</b>	<b>1835 IMPERIAL AVENUE</b>	<b>29</b>	<b>379</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>ELMERS FOREIGN AUTO WRECKING</b>	<b>1935 NATIONAL AVE</b>	<b>37</b>	<b>445</b>
<b>ACE RADIATOR</b>	<b>1854 NATIONAL AVE</b>	<b>37</b>	<b>478</b>
<b>TRIAD ENVIRONMENTAL SYSTEMS</b>	<b>1775 NATIONAL AVENUE</b>	<b>37</b>	<b>517</b>
<b>ANGEL VILLEGAS</b>	<b>1025A SIGSBEE</b>	<b>37</b>	<b>546</b>
<b>SAN DIEGO SAW AND KNIFE WORKS</b>	<b>1765 LOGAN AVE</b>	<b>37</b>	<b>578</b>
<b>PACIFIC TREATMENT</b>	<b>1668 NATIONAL AVENUE</b>	<b>37</b>	<b>628</b>
<b>SAN DIEGO TROLLEY INC</b>	<b>1535 NEWTON AVE</b>	<b>37</b>	<b>647</b>
<b>HILL BROTHERS CHEMICAL CO</b>	<b>1680 LOGAN AVENUE</b>	<b>37</b>	<b>663</b>
<b>MR PARTS OPS DIVISION</b>	<b>16 15TH ST</b>	<b>37</b>	<b>729</b>
<b>SAN DIEGO USD SAN DIEGO CITY S</b>	<b>1826 IRVING ST</b>	<b>42</b>	<b>784</b>
<b>KRASNE'S INC</b>	<b>2222 COMMERCIAL ST</b>	<b>42</b>	<b>786</b>
<b>PORT OF SAN DIEGO DIST MAINT F</b>	<b>825 EAST HARBOR DRIVE</b>	<b>45</b>	<b>794</b>
<b>DANNYS PAINT &amp; BODY SHOP</b>	<b>1866 KEARNEY AVENUE</b>	<b>50</b>	<b>804</b>
<b>NASSCO WAREHOUSE</b>	<b>1699 MAIN ST</b>	<b>53</b>	<b>835</b>
<b>PACIFIC RIGGING LOFT</b>	<b>1694 MAIN ST</b>	<b>53</b>	<b>838</b>
<b>CP KELCO</b>	<b>1343 CEASAR CHAVEZ PKWY</b>	<b>55</b>	<b>873</b>
<b>BURLINGTON NORHTERN AND SANTA</b>	<b>1342 CESAR E CHAVEZ PKW</b>	<b>55</b>	<b>874</b>
<b>RANKIN INDUSTRIES INC</b>	<b>1991 MAIN ST</b>	<b>55</b>	<b>880</b>
<b>CALTRANS CORONADO BRIDGE MT ST</b>	<b>1120 DEWEY STREET</b>	<b>55</b>	<b>932</b>
<b>SAN DIEGO CITY REDEVELOPMENT A</b>	<b>1901 MAIN STREET</b>	<b>55</b>	<b>952</b>
<b>ROMANS TRUCKING PAINTING</b>	<b>1941 NEWTON AVE</b>	<b>55</b>	<b>963</b>
<b>AVION DYNAMICS CORP</b>	<b>1827 MAIN STREET</b>	<b>55</b>	<b>974</b>
<b>FRYER KNOWLES INC</b>	<b>1858 NEWTON AVE</b>	<b>55</b>	<b>983</b>
<b>NORTH AMERICAN TERMINAL INC</b>	<b>1090 WATER ST</b>	<b>57</b>	<b>1003</b>
<b>SAN DIEGO TRANSMISSION</b>	<b>1127 S 27TH ST</b>	<b>59</b>	<b>1127</b>
<b>FMC CORP</b>	<b>2393 NEWTON AVE</b>	<b>59</b>	<b>1140</b>
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
<b>PROPULSION CONTROLS ENGINEERIN</b>	<b>2255 NATIONAL AVE</b>	<b>59</b>	<b>1245</b>
<b>SAN DIEGO EXPRESS</b>	<b>2635 LOGON ST</b>	<b>59</b>	<b>1254</b>
<b>MIMS PLATING</b>	<b>2169-B NATIONAL AVE</b>	<b>59</b>	<b>1267</b>
<b>DIEGO AND SON PRINTING INC</b>	<b>2104 NATIONAL AVE</b>	<b>59</b>	<b>1288</b>
<b>CROWLEY MARINE SERVICE INC</b>	<b>1843 WATER ST</b>	<b>61</b>	<b>1303</b>
<b>CARLSON &amp; BEAULOYE MACHINE SHO</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1332</b>
<b>MASTER PLATING</b>	<b>2109 NEWTON AVE</b>	<b>63</b>	<b>1354</b>
<b>SAN DIEGO USA MEMORIAL JUNIOR</b>	<b>2850 LOGAN AVENUE</b>	<b>64</b>	<b>1366</b>
<b>CALIFORNIA MARINE CLEANING INC</b>	<b>905 S 33RD ST</b>	<b>67</b>	<b>1373</b>
<b>BUMBLE BEE SEAFOODS</b>	<b>1995 BAYFRONT</b>	<b>68</b>	<b>1387</b>
<b>SOUTHBAY SANDBLASTING AND TANK</b>	<b>1995 BAYFRONT ST PIER 1</b>	<b>68</b>	<b>1413</b>
<b>CP KELCO</b>	<b>2025 EAST HARBOR DRIVE</b>	<b>68</b>	<b>1434</b>
<b>PACIFIC TREATMENT CORP</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1448</b>
<b>CLEANING DYNAMICS CORP</b>	<b>2146 MAIN ST</b>	<b>69</b>	<b>1477</b>
<b>SDG&amp;E TANKS 801 &amp; 802</b>	<b>2141 MAIN ST</b>	<b>69</b>	<b>1491</b>
<b>COOL RADIATOR SHOP</b>	<b>3362 NATIONAL AVE</b>	<b>71</b>	<b>1504</b>
<b>SUNSHINE TRUCK WORKS</b>	<b>3361 NATIONAL AVE</b>	<b>71</b>	<b>1508</b>
<b>SOUTHERN CALIFORNIA PLATING</b>	<b>3261 NATIONAL AVE.</b>	<b>73</b>	<b>1539</b>
<b>CAL SOFT WATER SERVICE INC</b>	<b>3094 NATIONAL AVE</b>	<b>74</b>	<b>1558</b>
<b>A&amp;A AUTO &amp; TRUCK ELEC</b>	<b>3005 NATIONAL AVE</b>	<b>75</b>	<b>1565</b>
<b>HOLSUM BAKING CO</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1570</b>
<b>TRICK TRUX INC</b>	<b>2380 MAIN ST</b>	<b>78</b>	<b>1589</b>
<b>SAN DIEGO EXPRESS INC</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1594</b>
<b>SOUTHWEST REGIONAL MAINTENANCE</b>	<b>2205 EAST BELT ST.</b>	<b>79</b>	<b>1618</b>
<b>PACIFIC SHIP REPAIR AND FABRIC</b>	<b>2205 E BELT ST</b>	<b>79</b>	<b>1626</b>
<b>SAN DIEGO GAS &amp; ELECTRIC - SIL</b>	<b>1348 SAMPSON STREET</b>	<b>79</b>	<b>1670</b>
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAYFRONT STREET</b>	<b>79</b>	<b>1696</b>
<b>TEXACO SERVICE STATION</b>	<b>1145 SOUTH 28TH STREET</b>	<b>80</b>	<b>1720</b>
<b>CHEVRON SAN DIEGO TERMINAL 100</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1783</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>ATLANTIC RICHFIELD CO SAN DIEG</b>	<b>2295 E. HARBOR DRIVE</b>	<b>84</b>	<b>1812</b>
<b>ADVANCED SURFACE TECHNOLOGY IN</b>	<b>3134 MAIN ST</b>	<b>86</b>	<b>1825</b>
<b>ADVANCED SURFACE TECHNOLOGY</b>	<b>3134 MAIN ST</b>	<b>86</b>	<b>1826</b>
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
<b>S S HOWELL LYKES EXPRESS VAN B</b>	<b>HARBOR DR AND 28 ST CSS</b>	<b>92</b>	<b>2004</b>
PROPULSION CONTROLS ENGINEERIN	1620 RIGEL ST	94	2045
PIER 13	NAVAL STN 32ND ST	101	2085
<b>NAVAL COATING INC</b>	<b>32ND ST NAVAL STATION</b>	<b>101</b>	<b>2088</b>
<b>BAE SYSTEMS MES</b>	<b>32ND ST NAVAL STATION</b>	<b>101</b>	<b>2091</b>
APPLIED ENERGY LLC 32ND ST NAV	BLDG 3427 SURFACE NAVY	101	2102
<b>SOUTHBAY SANDBLAST AND TANK CL</b>	<b>32ND ST NAS PIERS</b>	<b>101</b>	<b>2110</b>
<b>NAVAL STATION SAN DIEGO 32 ST</b>	<b>PIER 14</b>	<b>101</b>	<b>2113</b>
<b>ANFEL'S AUTO BODY</b>	<b>3814 ACACIA ST</b>	<b>102</b>	<b>2180</b>
<b>SANCHEZ AUTO BODY</b>	<b>3746 MAIN STREET #B</b>	<b>104</b>	<b>2217</b>
<b>DOOR-MAN</b>	<b>3738 MAIN ST</b>	<b>104</b>	<b>2227</b>
<b>SALSCO, INC</b>	<b>3722 MAIN ST</b>	<b>104</b>	<b>2236</b>
<b>GOLDEN WHEELS</b>	<b>3698 1/2 MAIN ST</b>	<b>104</b>	<b>2253</b>
<b>ATC VANCOM</b>	<b>3683 DALBERGIA ST</b>	<b>104</b>	<b>2302</b>
<b>SOUTHBAY SANDBLAST &amp; TANK CLEA</b>	<b>3589 DALBERGIA ST</b>	<b>104</b>	<b>2357</b>
<b>CHAPMANS DIESEL SALES AND SVC</b>	<b>3561 DALBERGIA ST</b>	<b>104</b>	<b>2371</b>
<b>ARAMARK UNIFORM SERVICES</b>	<b>3554 DALBERGIA</b>	<b>104</b>	<b>2384</b>
<b>SAN DIEGO GALVANIZING INCORPOR</b>	<b>3586 DALBERGIA STREET</b>	<b>104</b>	<b>2404</b>
<b>NAVY EXCHANGE SVC STA</b>	<b>32ND ST &amp; HARBOR DR</b>	<b>106</b>	<b>2424</b>
<b>USNAVY EXCHANGE SERVICE STATIO</b>	<b>32ND &amp; HARBOR DR NAVAL</b>	<b>106</b>	<b>2427</b>
<b>CAMPBELL INDUSTRIES</b>	<b>32ND ST AND HARBOR DR</b>	<b>106</b>	<b>2440</b>
<b>EARL SCHEIB OF CALIF INC</b>	<b>111 NATIONAL CITY BLVD</b>	<b>109</b>	<b>2445</b>
<b>SHELL SVC STN</b>	<b>3890 DIVISION</b>	<b>109</b>	<b>2468</b>

**RCRA-CESQG:** RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/06/2008 has revealed that there are 3 RCRA-CESQG sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>PERFORMANCE CONTRACTING, INC</b>	<b>2015 MAIN ST</b>	<b>55</b>	<b>854</b>
<b>PACIFIC TANK CLEANING SVCS INC</b>	<b>2734 MAIN ST</b>	<b>88</b>	<b>1894</b>
MAJOR SCIENTIFIC INDUSTRIES	3557 DALBERGIA ST	104	2375

**RCRA-NonGen:** RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 03/06/2008 has revealed that there



## EXECUTIVE SUMMARY

are 22 RCRA-NonGen sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>ARCWELL CORP</b>	<b>510 16TH STREET</b>	<b>15</b>	<b>117</b>
<b>BALLPARK INFRASTRUCTURE SITE</b>	<b>K ST AND IMPERIAL BORDE</b>	<b>21</b>	<b>246</b>
<b>AZTEC OIL</b>	<b>1921 NATIONAL AVE</b>	<b>37</b>	<b>456</b>
<b>SUNBELT DISTRIBUTING CHEMICAL</b>	<b>1625 NEWTON ST</b>	<b>37</b>	<b>590</b>
<b>SUNBELT PAINT &amp; BODY</b>	<b>1712 LOGAN AVE</b>	<b>37</b>	<b>645</b>
<b>QUALITY CABINET &amp; FIXTURE CO.</b>	<b>939 S 16TH ST</b>	<b>37</b>	<b>692</b>
<b>PEPPER INDUSTRIES INC</b>	<b>1501 NATIONAL AVE</b>	<b>37</b>	<b>695</b>
<b>CORROSION ENGINEERING SVCS</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>897</b>
<b>COASTAL TRANSPORT CO INC</b>	<b>2351 E HARBOR BLVD DR</b>	<b>59</b>	<b>1018</b>
<b>BAY DECKING COMPANY INCORPORAT</b>	<b>2685 BOSTON ST.</b>	<b>59</b>	<b>1109</b>
<b>BARRIO SENIOR VILLAS</b>	<b>2330 NEWTON AVE</b>	<b>59</b>	<b>1181</b>
<b>B&amp;C MARINE ENTERPRISES INC</b>	<b>2255 NATIONAL AVE</b>	<b>59</b>	<b>1242</b>
<b>NRC ENVIRONMENTAL SVCS INC</b>	<b>1839 WATER ST</b>	<b>61</b>	<b>1306</b>
<b>BAY DECKING COMPANY INC</b>	<b>1995 BAY FRONT ST</b>	<b>68</b>	<b>1381</b>
<b>MARINE BARGE SERVICES INC</b>	<b>2146 MAIN ST</b>	<b>69</b>	<b>1475</b>
MARINE BARGE SERVICES INC	2146 MAIN ST	69	1484
<b>PHD CORP</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1591</b>
<b>ISP ALGINATES INCORPORATED</b>	<b>2145 E. BELT STREET</b>	<b>79</b>	<b>1665</b>
<b>PROPULSION CONTROLS ENGINEERIN</b>	<b>1304 S SAMPSON ST</b>	<b>79</b>	<b>1700</b>
<b>CALIFORNIA MARINE CLEANING</b>	<b>2970 MAIN ST</b>	<b>87</b>	<b>1858</b>
<b>NAVAL COATING INC</b>	<b>1505 RIGEL ST</b>	<b>90</b>	<b>1932</b>
<b>SOUTH BAY SANDBLASTING AND TAN</b>	<b>1920 UNA ST</b>	<b>104</b>	<b>2337</b>

**ERNS:** The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 12/31/2007 has revealed that there are 41 ERNS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
16TH & NEWTON	16TH & NEWTON	37	624
1680 LOGAN AVE	1680 LOGAN AVE	37	663
1444 CROSBY ST. (FUELING DOCK)	1444 CROSBY ST. (FUELIN	55	907
1342 CROSBY	1342 CROSBY	55	908
1880 HARBOR DRIVE	1880 HARBOR DRIVE	55	932
2351 HARBOR DRIVE	2351 HARBOR DRIVE	84	1788
15 @ 115	15 @ 115	85	1818
HARBOR DR & 28TH ST BERTH 2	HARBOR DR & 28TH ST BER	92	1957
28 & HARBOR DRIVE	28 & HARBOR DRIVE	92	1958
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1976
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1976
2800 HARBOR DR.	2800 HARBOR DR.	92	1981
2800 HARBOR DR.	2800 HARBOR DR.	92	1987
2800 HARBOR DR.	2800 HARBOR DR.	92	1987
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1987
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1987
2800 HARBOR DR.	2800 HARBOR DR.	92	1988
2800 HARBOR DR.	2800 HARBOR DR.	92	1988
2800 HARBOR DR.	2800 HARBOR DR.	92	1988
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1988
2798 HARBOR DR.	2798 HARBOR DR.	92	1988
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1989

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
2798 HARBOR DR.	2798 HARBOR DR.	92	1989
28TH / HARBOR DRIVE	28TH / HARBOR DRIVE	92	1989
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1989
2800 HARBOR DR.	2800 HARBOR DR.	92	1990
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1996
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1996
2798 HARBOR DR	2798 HARBOR DR	92	1996
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1996
2798 HARBOR DRIVE	2798 HARBOR DRIVE	92	1996
2798 HARBOR DR.	2798 HARBOR DR.	92	1997
2798 HARBOR DR	2798 HARBOR DR	92	1998
2798 E. HARBOR DRIVE	2798 E. HARBOR DRIVE	92	2002
2800 HARBOUR DR	2800 HARBOUR DR	92	2002
28TH STREEET AND HARBOR DR.	28TH STREEET AND HARBOR	92	2002
28TH ST AND HARBOR DR	28TH ST AND HARBOR DR	92	2002
NASSCO HARBOR DRIVE	NASSCO HARBOR DRIVE	92	2006
NASSCO SHIP YARD BERTH NO. 6	NASSCO SHIP YARD BERTH	92	2006
NASSCO SHIP YARD BERTH 4	NASSCO SHIP YARD BERTH	92	2006
NASSCO PIER DIRECTLY ACROSS FR	NASSCO PIER DIRECTLY AC	92	2006

**HMIRS:** The Hazardous Materials Incident Report System contains hazardous material spill incidents reported to the Department of Transportation. The source of this database is the U.S. EPA.

A review of the HMIRS list, as provided by EDR, and dated 12/31/2007 has revealed that there is 1 HMIRS site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
Not reported	1342 CROSBY STREET	55	907

Department of Transportation, Office of Pipeline Safety Incident and Accident data.

A review of the DOT OPS list, as provided by EDR, and dated 02/14/2008 has revealed that there is 1 DOT OPS site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
Not reported	2116 NEWTON AVENUE	63	1349

**US BROWNFIELDS:** The EPA's listing of Brownfields properties addressed by Cooperative Agreement Recipients and Brownfields properties addressed by Targeted Brownfields Assessments

A review of the US BROWNFIELDS list, as provided by EDR, and dated 04/01/2008 has revealed that there is 1 US BROWNFIELDS site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
MASTER PLATING	2109 NEWTON AVENUE	101	2083

## EXECUTIVE SUMMARY

**DOD:** Consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

A review of the DOD list, as provided by EDR, and dated 12/31/2005 has revealed that there is 1 DOD site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
SAN DIEGO NAVAL STATION		0	3

**TRIS:** The Toxic Chemical Release Inventory System identifies facilities that release toxic chemicals to the air, water, and land in reportable quantities under SARA Title III, Section 313. The source of this database is the U.S. EPA.

A review of the TRIS list, as provided by EDR, and dated 12/31/2006 has revealed that there are 5 TRIS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>ISP ALGINATES INCORPORATED</b>	<b>2145 EAST BELT STREET</b>	<b>79</b>	<b>1659</b>
CHEVRON SAN DIEGO TERMINAL	2351 E HARBOR DR	84	1773
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR</b>	<b>84</b>	<b>1793</b>
<b>NATIONAL STEEL AND SHIPBUILDIN</b>	<b>2798 EAST HARBOR DRIVE</b>	<b>92</b>	<b>1959</b>
<b>SAN DIEGO GALVANIZING INCORPOR</b>	<b>3586 DALBERGIA STREET</b>	<b>104</b>	<b>2404</b>

**TSCA:** The Toxic Substances Control Act identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. The United States Environmental Protection Agency has no current plan to update and/or re-issue this database.

A review of the TSCA list, as provided by EDR, and dated 12/31/2002 has revealed that there are 3 TSCA sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
LIQUID CARBONIC INDUSTRIES COR	2205 NEWTON AVE	63	1319
AMERIGAS	2205 NEWTON AVE	63	1319
PRAXAIR, INC.	2205 NEWTON AVENU	63	1326

**FTTS:** FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act) over the previous five years. To maintain currency, EDR contacts the Agency on a quarterly basis.

A review of the FTTS list, as provided by EDR, and dated 04/11/2008 has revealed that there are 4 FTTS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>PROLINE PAINT PROFESSIONAL FIN</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1066</b>
<b>SHERWIN WILLIAMS (PRO-LINE PAI</b>	<b>2646 MAIN STREET</b>	<b>59</b>	<b>1067</b>
<b>PAKAN INC (MASTER PLATING)</b>	<b>2109 NEWTON AVE</b>	<b>63</b>	<b>1351</b>
<b>PACIFIC SHIP REPAIR AND FABRIC</b>	<b>1625 RIGEL AVENUE</b>	<b>94</b>	<b>2044</b>

## EXECUTIVE SUMMARY

**HIST FTTS:** A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

A review of the HIST FTTS list, as provided by EDR, and dated 10/19/2006 has revealed that there are 5 HIST FTTS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<i>PROLINE PAINT PROFESSIONAL FIN</i>	<i>2646 MAIN ST</i>	<i>59</i>	<i>1066</i>
<i>SHERWIN WILLIAMS (PRO-LINE PAI</i>	<i>2646 MAIN STREET</i>	<i>59</i>	<i>1067</i>
<i>PAKAN INC (MASTER PLATING)</i>	<i>2109 NEWTON AVE</i>	<i>63</i>	<i>1351</i>
<i>TELEDYNE RYAN AERONAUTICAL</i>	<i>2701 HARBOR DR</i>	<i>91</i>	<i>1934</i>
<i>PACIFIC SHIP REPAIR AND FABRIC</i>	<i>1625 RIGEL AVENUE</i>	<i>94</i>	<i>2044</i>

**SSTS:** Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

A review of the SSTS list, as provided by EDR, and dated 12/31/2006 has revealed that there are 2 SSTS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
PRO-LINE PAINT COMPANY	2646 MAIN STREET	59	1069
SHERWIN-WILLIAMS CO	2646 MAIN ST	59	1074

**ICIS:** The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 02/28/2008 has revealed that there is 1 ICIS site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
MASTER PLATING	2109 NEWTON AVE	63	1361

**PADS:** The PCB Activity Database identifies generators, transporters, commercial storers and/or brokers and disposers of PCBs who are required to notify the United States Environmental Protection Agency of such activities. The source of this database is the U.S. EPA.

A review of the PADS list, as provided by EDR, and dated 12/04/2007 has revealed that there are 3 PADS sites within the searched area.

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
A TO Z	3202 MAIN ST	86	1819
<b>USNAVY SAN DIEGO NAVAL STN PWC</b>	<b>32ND ST AND HARBOR DR</b>	<b>115</b>	<b>2506</b>

**FINDS:** The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 04/03/2008 has revealed that there are 119 FINDS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SHELL SEERVIC SERVICE STATION</b>	<b>1619 G STREET</b>	<b>5</b>	<b>7</b>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
<b>PACIFIC MARINE SHEET METAL CORP</b>	<b>410 15TH ST</b>	<b>15</b>	<b>99</b>
<b>ARCWELL CORP</b>	<b>510 16TH STREET</b>	<b>15</b>	<b>117</b>
<b>BALLPARK INFRASTRUCTURE SITE</b>	<b>K ST AND IMPERIAL BORDE</b>	<b>21</b>	<b>246</b>
<b>SAN DIEGO TRANSIT CORP</b>	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>CAL LINEN SUPPLY</b>	<b>101 16TH ST</b>	<b>24</b>	<b>307</b>
<b>CONTINENTAL BAKING COMPANY</b>	<b>1301 IMPERIAL AVE</b>	<b>28</b>	<b>354</b>
<b>NATIONAL BRAKE SERVICE INC</b>	<b>2040 IMPERIAL AVE</b>	<b>29</b>	<b>369</b>
<b>OCEAN HABITABILITY INC</b>	<b>1844 IMPERIAL AVE</b>	<b>29</b>	<b>377</b>
<b>WILSON &amp; HAMPTON REFINISHING I</b>	<b>1835 IMPERIAL AVENUE</b>	<b>29</b>	<b>379</b>
<b>ELMERS FOREIGN AUTO WRECKING</b>	<b>1935 NATIONAL AVE</b>	<b>37</b>	<b>445</b>
<b>AZTEC OIL</b>	<b>1921 NATIONAL AVE</b>	<b>37</b>	<b>456</b>
<b>ACE RADIATOR</b>	<b>1854 NATIONAL AVE</b>	<b>37</b>	<b>478</b>
<b>TRIAD ENVIRONMENTAL SYSTEMS</b>	<b>1775 NATIONAL AVENUE</b>	<b>37</b>	<b>517</b>
<b>ANGEL VILLEGAS</b>	<b>1025A SIGSBEE</b>	<b>37</b>	<b>546</b>
<b>SAN DIEGO SAW AND KNIFE WORKS</b>	<b>1765 LOGAN AVE</b>	<b>37</b>	<b>578</b>
<b>SUNBELT DISTRIBUTING CHEMICAL</b>	<b>1625 NEWTON ST</b>	<b>37</b>	<b>590</b>
<b>PACIFIC TREATMENT</b>	<b>1668 NATIONAL AVENUE</b>	<b>37</b>	<b>628</b>
<b>SUNBELT PAINT &amp; BODY</b>	<b>1712 LOGAN AVE</b>	<b>37</b>	<b>645</b>
<b>SAN DIEGO TROLLEY INC</b>	<b>1535 NEWTON AVE</b>	<b>37</b>	<b>647</b>
<b>HILL BROTHERS CHEMICAL CO</b>	<b>1680 LOGAN AVENUE</b>	<b>37</b>	<b>663</b>
<b>QUALITY CABINET &amp; FIXTURE CO.</b>	<b>939 S 16TH ST</b>	<b>37</b>	<b>692</b>
<b>PEPPER INDUSTRIES INC</b>	<b>1501 NATIONAL AVE</b>	<b>37</b>	<b>695</b>
<b>MR PARTS OPS DIVISION</b>	<b>16 15TH ST</b>	<b>37</b>	<b>729</b>
<b>SAN DIEGO USD SAN DIEGO CITY S</b>	<b>1826 IRVING ST</b>	<b>42</b>	<b>784</b>
<b>PORT OF SAN DIEGO DIST MAINT F</b>	<b>825 EAST HARBOR DRIVE</b>	<b>45</b>	<b>794</b>
<b>DANNYS PAINT &amp; BODY SHOP</b>	<b>1866 KEARNEY AVENUE</b>	<b>50</b>	<b>804</b>
<b>NASSCO WAREHOUSE</b>	<b>1699 MAIN ST</b>	<b>53</b>	<b>837</b>
<b>PACIFIC RIGGING LOFT</b>	<b>1694 MAIN ST</b>	<b>53</b>	<b>838</b>
<b>PERFORMANCE CONTRACTING, INC</b>	<b>2015 MAIN ST</b>	<b>55</b>	<b>854</b>
<b>BURLINGTON NORHTERN AND SANTA</b>	<b>1342 CESAR E CHAVEZ PKW</b>	<b>55</b>	<b>874</b>
<b>RANKIN INDUSTRIES INC</b>	<b>1991 MAIN ST</b>	<b>55</b>	<b>880</b>
<b>CORROSION ENGINEERING SVCS</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>897</b>
<b>CALTRANS CORONADO BRIDGE MT ST</b>	<b>1120 DEWEY STREET</b>	<b>55</b>	<b>932</b>
<b>CALTRANS DISTRICT 11-CORONADO</b>	<b>1995 NEWTON AVE</b>	<b>55</b>	<b>941</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>SAN DIEGO CITY REDEVELOPMENT A</b>	<b>1901 MAIN STREET</b>	<b>55</b>	<b>952</b>
<b>ROMANS TRUCKING PAINTING</b>	<b>1941 NEWTON AVE</b>	<b>55</b>	<b>963</b>
<b>AVION DYNAMICS CORP</b>	<b>1827 MAIN STREET</b>	<b>55</b>	<b>974</b>
<b>FRYER KNOWLES INC</b>	<b>1858 NEWTON AVE</b>	<b>55</b>	<b>983</b>
PERKINS ELEMENTARY	1770 MAIN STREET	55	991
Not reported	1110 BEARDSLEY STREET,	55	999
<b>NORTH AMERICAN TERMINAL INC</b>	<b>1090 WATER ST</b>	<b>57</b>	<b>1003</b>
<b>COASTAL TRANSPORT CO INC</b>	<b>2351 E HARBOR BLVD DR</b>	<b>59</b>	<b>1018</b>
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
<b>BAY DECKING COMPANY INCORPORAT</b>	<b>2685 BOSTON ST.</b>	<b>59</b>	<b>1109</b>
<b>SAN DIEGO TRANSMISSION</b>	<b>1127 S 27TH ST</b>	<b>59</b>	<b>1127</b>
<b>FMC CORP</b>	<b>2393 NEWTON AVE</b>	<b>59</b>	<b>1140</b>
<b>BARRIO SENIOR VILLAS</b>	<b>2330 NEWTON AVE</b>	<b>59</b>	<b>1181</b>
NORTH STAR PROPELLERS INC	2285 NEWTON AVENUE	59	1194
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
<b>B&amp;C MARINE ENTERPRISES INC</b>	<b>2255 NATIONAL AVE</b>	<b>59</b>	<b>1242</b>
<b>PROPULSION CONTROLS ENGINEERIN</b>	<b>2255 NATIONAL AVE</b>	<b>59</b>	<b>1245</b>
<b>SAN DIEGO EXPRESS</b>	<b>2635 LOGON ST</b>	<b>59</b>	<b>1254</b>
<b>MIMS PLATING</b>	<b>2169-B NATIONAL AVE</b>	<b>59</b>	<b>1267</b>
<b>DIEGO AND SON PRINTING INC</b>	<b>2104 NATIONAL AVE</b>	<b>59</b>	<b>1288</b>
<b>CROWLEY MARINE SERVICE INC</b>	<b>1843 WATER ST</b>	<b>61</b>	<b>1303</b>
<b>CARLSON &amp; BEAULOYE MACHINE SHO</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1332</b>
<b>MASTER PLATING</b>	<b>2109 NEWTON AVE</b>	<b>63</b>	<b>1354</b>
<b>SAN DIEGO USA MEMORIAL JUNIOR</b>	<b>2850 LOGAN AVENUE</b>	<b>64</b>	<b>1366</b>
<b>CALIFORNIA MARINE CLEANING INC</b>	<b>905 S 33RD ST</b>	<b>67</b>	<b>1373</b>
<b>BAY DECKING COMPANY INC</b>	<b>1995 BAY FRONT ST</b>	<b>68</b>	<b>1381</b>
<b>BUMBLE BEE SEAFOODS</b>	<b>1995 BAYFRONT</b>	<b>68</b>	<b>1387</b>
<b>SOUTHBAY SANDBLASTING AND TANK</b>	<b>1995 BAYFRONT ST PIER 1</b>	<b>68</b>	<b>1413</b>
<b>CP KELCO</b>	<b>2025 EAST HARBOR DRIVE</b>	<b>68</b>	<b>1434</b>
<b>PACIFIC TREATMENT CORP</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1448</b>
<b>MARINE BARGE SERVICES INC</b>	<b>2146 MAIN ST</b>	<b>69</b>	<b>1475</b>
<b>CLEANING DYNAMICS CORP</b>	<b>2146 MAIN ST</b>	<b>69</b>	<b>1477</b>
<b>SDG&amp;E TANKS 801 &amp; 802</b>	<b>2141 MAIN ST</b>	<b>69</b>	<b>1491</b>
<b>COOL RADIATOR SHOP</b>	<b>3362 NATIONAL AVE</b>	<b>71</b>	<b>1504</b>
<b>SUNSHINE TRUCK WORKS</b>	<b>3361 NATIONAL AVE</b>	<b>71</b>	<b>1508</b>
<b>SOUTHERN CALIFORNIA PLATING</b>	<b>3261 NATIONAL AVE.</b>	<b>73</b>	<b>1539</b>
<b>CAL SOFT WATER SERVICE INC</b>	<b>3094 NATIONAL AVE</b>	<b>74</b>	<b>1558</b>
<b>A&amp;A AUTO &amp; TRUCK ELEC</b>	<b>3005 NATIONAL AVE</b>	<b>75</b>	<b>1565</b>
<b>HOLSUM BAKING CO</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1570</b>
<b>TRICK TRUX INC</b>	<b>2380 MAIN ST</b>	<b>78</b>	<b>1589</b>
<b>PHD CORP</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1591</b>
<b>SOUTHWEST REGIONAL MAINTENANCE</b>	<b>2205 EAST BELT ST.</b>	<b>79</b>	<b>1618</b>
<b>PACIFIC SHIP (BAE SYSTEMS)</b>	<b>2205 E BELT ST</b>	<b>79</b>	<b>1623</b>
<b>SAN DIEGO GAS &amp; ELECTRIC - SIL</b>	<b>1348 SAMPSON STREET</b>	<b>79</b>	<b>1670</b>
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAYFRONT STREET</b>	<b>79</b>	<b>1696</b>
<b>PROPULSION CONTROLS ENGINEERIN</b>	<b>1304 S SAMPSON ST</b>	<b>79</b>	<b>1700</b>
<b>TEXACO SERVICE STATION</b>	<b>1145 SOUTH 28TH STREET</b>	<b>80</b>	<b>1720</b>
TEXACO #120520	1145 28TH ST S	80	1740
<b>ATLANTIC RICHFIELD CO SAN DIEG</b>	<b>2295 E. HARBOR DRIVE</b>	<b>84</b>	<b>1812</b>
VALVOLINE INSTANT OIL CHANGE	32ND & MAIN #3456	86	1818
<b>ADVANCED SURFACE TECHNOLOGY IN</b>	<b>3134 MAIN ST</b>	<b>86</b>	<b>1825</b>
GRAPHIC SOLUTIONS	2926 MAIN ST	87	1853
<b>CALIFORNIA MARINE CLEANING</b>	<b>2970 MAIN ST</b>	<b>87</b>	<b>1858</b>
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
<b>PACIFIC TANK CLEANING SVCS INC</b>	<b>2734 MAIN ST</b>	<b>88</b>	<b>1894</b>
<b>NAVAL COATING INC</b>	<b>1505 RIGEL ST</b>	<b>90</b>	<b>1932</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
PACIFIC SHIP REPAIR AND FABRIC	2798 HARBOR DR	92	1987
NATIONAL STEEL AND SHIPBUILDIN	2798 EAST HARBOR DRIVE	92	1997
<b>S S HOWELL LYKES EXPRESS VAN B</b>	<b>HARBOR DR AND 28 ST CSS</b>	<b>92</b>	<b>2004</b>
<b>PACIFIC SHIP REPAIR &amp; FABRICATI</b>	<b>1625 RIGEL STREET</b>	<b>94</b>	<b>2023</b>
PROPULSION CONTROLS ENGINEERIN	1620 RIGEL ST	94	2045
<b>NAVAL COATING INC</b>	<b>32ND ST NAVAL STATION</b>	<b>101</b>	<b>2088</b>
<b>BAE SYSTEMS MES</b>	<b>32ND ST NAVAL STATION</b>	<b>101</b>	<b>2091</b>
<b>SOUTHBAY SANDBLAST AND TANK CL</b>	<b>32ND ST NAS PIERS</b>	<b>101</b>	<b>2110</b>
<b>WATSON LAMINATES INC</b>	<b>3388 MAIN ST</b>	<b>101</b>	<b>2171</b>
<b>ANFEL'S AUTO BODY</b>	<b>3814 ACACIA ST</b>	<b>102</b>	<b>2180</b>
<b>G&amp;M OIL / MAIN STREET</b>	<b>3774 MAIN ST</b>	<b>104</b>	<b>2186</b>
<b>CENTRAL MARBLE SUPPLY</b>	<b>3754 MAIN ST</b>	<b>104</b>	<b>2206</b>
CENTRAL MARBLE SUPPLY MARBLE W	3754 MAIN STREET UNIT B	104	2212
<b>SANCHEZ AUTO BODY</b>	<b>3746 MAIN STREET #B</b>	<b>104</b>	<b>2217</b>
<b>DOOR-MAN</b>	<b>3738 MAIN ST</b>	<b>104</b>	<b>2227</b>
<b>SALSCO, INC</b>	<b>3722 MAIN ST</b>	<b>104</b>	<b>2236</b>
<b>GOLDEN WHEELS</b>	<b>3698 1/2 MAIN ST</b>	<b>104</b>	<b>2253</b>
<b>ATC VANCOM</b>	<b>3683 DALBERGIA ST</b>	<b>104</b>	<b>2302</b>
<b>SOUTH BAY SANDBLASTING AND TAN</b>	<b>1920 UNA ST</b>	<b>104</b>	<b>2337</b>
<b>SOUTHBAY SANDBLAST &amp; TANK CLEA</b>	<b>3589 DALBERGIA ST</b>	<b>104</b>	<b>2357</b>
<b>CHAPMANS DIESEL SALES AND SVC</b>	<b>3561 DALBERGIA ST</b>	<b>104</b>	<b>2371</b>
<b>MAJOR SCIENTIFIC INDUSTRIES</b>	<b>3557 DALBERGIA ST</b>	<b>104</b>	<b>2377</b>
ARATEX SERVICES, INC.	3554 DALBERGIA STREET	104	2404
<b>SAN DIEGO GALVANIZING INCORPOR</b>	<b>3586 DALBERGIA STREET</b>	<b>104</b>	<b>2404</b>
<b>CAMPBELL INDUSTRIES</b>	<b>32ND ST AND HARBOR DR</b>	<b>106</b>	<b>2440</b>
<b>EARL SCHEIB OF CALIF INC</b>	<b>111 NATIONAL CITY BLVD</b>	<b>109</b>	<b>2445</b>
<b>SHELL SVC STN</b>	<b>3890 DIVISION</b>	<b>109</b>	<b>2468</b>

### STATE AND LOCAL RECORDS

**HIST Cal-Sites:** Formerly known as ASPIS, this database contains both known and potential hazardous substance sites. The source is the California Department of Toxic Substance Control. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

A review of the HIST Cal-Sites list, as provided by EDR, and dated 08/08/2005 has revealed that there is 1 HIST Cal-Sites site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SAN DIEGO NAVAL STATION - SITE</b>	<b>SAN DIEGO BAY, 113 NAVA</b>	<b>101</b>	<b>2143</b>

**CA BOND EXP. PLAN:** Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

A review of the CA BOND EXP. PLAN list, as provided by EDR, and dated 01/01/1989 has revealed that there is 1 CA BOND EXP. PLAN site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
SAN DIEGO NAVAL STATION	P. O. BOX 113 NAVAL BAS	101	2086

## EXECUTIVE SUMMARY

**SCH:** This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category. depending on the level of threat to public health and safety or the. environment they pose.

A review of the SCH list, as provided by EDR, and dated 02/26/2008 has revealed that there are 7 SCH sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>BURBANK ELEMENTARY EXPANSION</b>	<b>2146 JULIAN AVENUE</b>	<b>56</b>	<b>999</b>
<b>LAURA G. RODRIGUEZ ELEMENTARY</b>	<b>32ND STREET/GREELY AVEN</b>	<b>60</b>	<b>1295</b>
<b>MEMORIAL AREA MIDDLE SCHOOL AL</b>	<b>43RD STREET/LOGAN AVENU</b>	<b>65</b>	<b>1368</b>
<b>KENNEDY/KNOX SCHOOL SITE NO. 1</b>	<b>DOMINION STREET/LOGAN A</b>	<b>66</b>	<b>1370</b>
<b>KENNEDY/KNOX SCHOOL SITE NO. 2</b>	<b>43RD STREET/KEELER AVEN</b>	<b>81</b>	<b>1742</b>
<b>MEMORIAL AREA MIDDLE SCHOOL AL</b>	<b>4103 BETA STREET</b>	<b>96</b>	<b>2057</b>
<b>OFFICE OF EDUCATION BUILDING</b>	<b>NATIONAL CITY BOULEVARD</b>	<b>113</b>	<b>2486</b>

**SWF/LF:** The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.

A review of the SWF/LF list, as provided by EDR, and dated 03/10/2008 has revealed that there are 3 SWF/LF sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
8TH AVENUE TIDELAND DUMP	50 8TH AVENUE	45	789
BALBOA PARK NURSERY	500' E OF NAVAL HOSPITA	101	2084
EDCO TRANSFER STATION	3660 DALBERGIA STREET	104	2326

**CA WDS:** California Water Resources Control Board - Waste Discharge System.

A review of the CA WDS list, as provided by EDR, and dated 06/19/2007 has revealed that there are 15 CA WDS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SAN DIEGO TRANSIT CORP</b>	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>MINI TRUCK</b>	<b>1700 NEWTON AV</b>	<b>37</b>	<b>539</b>
<b>SAN DIEGO TROLLEY INC</b>	<b>1535 NEWTON AVE</b>	<b>37</b>	<b>647</b>
AMERICAN & FOREIGN AUTO W.	1615 LOGAN AVE	37	702
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
<b>SANTA FE INTERMODAL</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>908</b>
CORONADO TOLL BRIDGE MAINT FAC	1995 NEWTON AVE	55	936
IMS RECYCLING SERVICES	2740 BOSTON AVE	59	1119
<b>IMS RECYCLING SERVICES</b>	<b>2731 NEWTON AV</b>	<b>59</b>	<b>1151</b>
<b>ADVANCED METAL FORMING, INC.</b>	<b>2618 NATIONAL AV</b>	<b>59</b>	<b>1206</b>
A TO Z AUTO DISMANTLING	1249 SO. 32ND STREET	83	1749
CHEVRON SAN DIEGO TERMINAL	2351 EAST HARBOR DR.	84	1789
IMS RECYCLING SERVICES	1345 SO. 27TH ST.	88	1884
SUNDANCE STAGE LINES	3762 MAIN ST	104	2189
<b>SANI-TAINER INC</b>	<b>3660 DALBERGIA ST</b>	<b>104</b>	<b>2329</b>



## EXECUTIVE SUMMARY

**WMUDS/SWAT:** The Waste Management Unit Database System is used for program tracking and inventory of waste management units. The source is the State Water Resources Control Board.

A review of the WMUDS/SWAT list, as provided by EDR, and dated 04/01/2000 has revealed that there are 22 WMUDS/SWAT sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
POINT LOMA NAVAL COMPLEX	SITE # 4 IAS	101	2087
NAVAL STATION	SITE # 3 IAS	101	2126
POINT LOMA NAVAL COMPLEX	SITE # 6 IAS	101	2127
POINT LOMA NAVAL COMPLEX	SITE # 7 IAS	101	2128
POINT LOMA NAVAL COMPLEX	SITE # 13 IAS	101	2129
NAVAL STATION	SITE # 1 IAS	101	2130
NAVAL TRAINING CENTER	SITE # 1 IAS	101	2131
NAVAL STATION	SITE # 4 IAS	101	2132
POINT LOMA NAVAL COMPLEX	SITE # 5 IAS	101	2133
POINT LOMA NAVAL COMPLEX	SITE # 2 IAS	101	2134
POINT LOMA NAVAL COMPLEX	SITE # 8 IAS	101	2135
POINT LOMA NAVAL COMPLEX	SITE # 3 IAS	101	2136
POINT LOMA NAVAL COMPLEX	SITE # 12 IAS	101	2137
POINT LOMA NAVAL COMPLEX	SITE # 16 IAS	101	2138
POINT LOMA NAVAL COMPLEX	SITE # 9 IAS	101	2139
POINT LOMA NAVAL COMPLEX	SITE # 10 IAS	101	2140
POINT LOMA NAVAL COMPLEX	SITE # 17 IAS	101	2141
POINT LOMA NAVAL COMPLEX	SITE # 14 IAS	101	2142
POINT LOMA NAVAL COMPLEX	SITE # 15 IAS	101	2146
NAVAL TRAINING CENTER	SITE # 2 IAS	101	2147
NAVAL TRAINING CENTER	SITE # 3 IAS	101	2148
NAVAL STATION SAN DIEGO	SITE # 6 IAS	101	2149

**Cortese:** The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites). This listing is no longer updated by the state agency.

A review of the Cortese list, as provided by EDR, and dated 04/01/2001 has revealed that there are 127 Cortese sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
<b>SHELL OIL PRODUCTS COMPANY</b>	<b>1619 G ST</b>	<b>5</b>	<b>16</b>
<b>HAWTHORNE RENT-IT SERVICE</b>	<b>1473 G ST</b>	<b>6</b>	<b>27</b>
<b>JAMES' DETAIL SHOP</b>	<b>544 11TH ST</b>	<b>8</b>	<b>45</b>
<b>FSE INC</b>	<b>1238-1258 MARKET ST</b>	<b>8</b>	<b>49</b>
<b>YELLOW CAB CO OF SAN DIEGO INC</b>	<b>639 13TH ST</b>	<b>8</b>	<b>52</b>
<b>UNOCAL SERVICE STATION</b>	<b>1606 MARKET ST</b>	<b>10</b>	<b>69</b>
<b>ECONO AUTO REPAIR/GAS</b>	<b>400 16TH ST</b>	<b>15</b>	<b>88</b>
<b>PACIFIC MARINE SHEET METAL COR</b>	<b>410 15TH ST</b>	<b>15</b>	<b>99</b>
<b>VICTOR'S USED TIRES</b>	<b>405 16TH ST</b>	<b>15</b>	<b>106</b>
<b>ARCWELL CORP</b>	<b>510 16TH STREET</b>	<b>15</b>	<b>117</b>
<b>EAST VILLAGE RDA (535-353)</b>	<b>318 9TH</b>	<b>17</b>	<b>131</b>
<b>A-1 QUALITY TRANSMISSIONS</b>	<b>901 J ST</b>	<b>17</b>	<b>135</b>
<b>DONEV COMPANY</b>	<b>441 10TH AVE</b>	<b>17</b>	<b>141</b>
<b>SDG &amp; E SERVICE BUILD</b>	<b>114 TENTH AVENUE</b>	<b>21</b>	<b>164</b>
<b>SOUTHWEST HARDWARE</b>	<b>944 K ST</b>	<b>21</b>	<b>254</b>
<b>CITY OF SAN DIEGO</b>	<b>330 12TH AVE</b>	<b>21</b>	<b>262</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>CENTRAL POLICE STATION</b>	<b>320 12TH AVE</b>	<b>21</b>	<b>269</b>
<b>CARNATION DAIRY COMPANY</b>	<b>354 11TH AVE</b>	<b>21</b>	<b>274</b>
<b>SAN DIEGO TRANSIT CORP</b>	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>CALIF. INDUSTR. &amp; LINEN SUPPLY</b>	<b>101 16TH ST</b>	<b>24</b>	<b>316</b>
<b>FRED'S AUTO BODY &amp; PAINT</b>	<b>301 16TH ST</b>	<b>24</b>	<b>319</b>
<b>COTINENTAL BAKING COMP</b>	<b>171 14TH ST</b>	<b>27</b>	<b>327</b>
<b>INTERSTATE BRANDS CORP.</b>	<b>1401 IMPERIAL AVE</b>	<b>28</b>	<b>341</b>
<b>SQUIRES BELT MATERIAL</b>	<b>149 12TH AVE</b>	<b>28</b>	<b>359</b>
<b>VITAGOLD BRANDS COOP AT0726</b>	<b>2121 IMPERIAL AV</b>	<b>29</b>	<b>366</b>
<b>FIRST CHOICE</b>	<b>24 21ST ST</b>	<b>29</b>	<b>382</b>
<b>SDG&amp;E</b>	<b>45 9TH</b>	<b>30</b>	<b>394</b>
<b>MARATHON LAND &amp; CATTLE</b>	<b>2682 IMPERIAL AVE</b>	<b>32</b>	<b>405</b>
<b>IMPERIAL AVE. APARTMENTS</b>	<b>2701 IMPERIAL AVE</b>	<b>32</b>	<b>413</b>
<b>THRIFTY #96</b>	<b>2502 IMPERIAL AVE</b>	<b>34</b>	<b>418</b>
<b>ARCO FACILITY NO. 9560</b>	<b>2502 IMPERIAL AV</b>	<b>34</b>	<b>419</b>
<b>THRIFTY OIL STATION #96</b>	<b>2502 IMPERIAL AVE</b>	<b>34</b>	<b>424</b>
<b>EL GUERO TIRE SHOP</b>	<b>2401 IMPERIAL AVE</b>	<b>36</b>	<b>435</b>
<b>BILL ALLEN/ ELMER'S AUTO</b>	<b>1902 NATIONAL AVE</b>	<b>37</b>	<b>462</b>
<b>BETTENCOURT AUTO BODY</b>	<b>1865 NATIONAL AVE</b>	<b>37</b>	<b>476</b>
<b>MOBIL SERVICE STATION</b>	<b>1879 LOGAN AVE</b>	<b>37</b>	<b>506</b>
<b>THE DIESEL CENTER</b>	<b>1792 NATIONAL AVE</b>	<b>37</b>	<b>527</b>
<b>TROPIC ICE CREAM</b>	<b>1776 NATIONAL AVE</b>	<b>37</b>	<b>533</b>
<b>SAN DIEGO SAW AND KNIFE WORKS</b>	<b>1765 LOGAN AVE</b>	<b>37</b>	<b>578</b>
<b>ACTION CLEANING</b>	<b>1604 NEWTON AVE</b>	<b>37</b>	<b>617</b>
<b>GRAYBILL TERMINALS</b>	<b>1531 NATIONAL AVE</b>	<b>37</b>	<b>684</b>
<b>HUGHES ATTORNEY SERVICES</b>	<b>1643 LOGAN AVE</b>	<b>37</b>	<b>691</b>
<b>HERTZ - PENSKE TRUCK LEASING</b>	<b>1402 COMMERCIAL ST</b>	<b>37</b>	<b>723</b>
<b>ST. VINCENT DEPAUL</b>	<b>16 15TH ST</b>	<b>37</b>	<b>732</b>
<b>EL DORADO SANDBLASTING</b>	<b>2694 COMMERCIAL ST</b>	<b>40</b>	<b>756</b>
<b>ELDORADO SAND BLASTING</b>	<b>2675 COMMERCIAL ST</b>	<b>40</b>	<b>767</b>
<b>SDUSD MAINTENANCE</b>	<b>1826 IRVING AVE</b>	<b>42</b>	<b>774</b>
<b>SAN DIEGO CITY SCHOOLS</b>	<b>1826 IRVINE AVE</b>	<b>42</b>	<b>785</b>
<b>PORT DISTRICT MAINTENANCE</b>	<b>825 HARBOR</b>	<b>45</b>	<b>797</b>
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
<b>YOUNG'S MARKET COMPANY</b>	<b>1709 MAIN ST S</b>	<b>53</b>	<b>834</b>
<b>P&amp;L KNEPP TRUCKING</b>	<b>2001 MAIN ST</b>	<b>55</b>	<b>864</b>
<b>A.O. REED</b>	<b>1990 MAIN ST</b>	<b>55</b>	<b>884</b>
<b>MAAC PRO ECT, SDG&amp;E</b>	<b>2043 NEWTON AVE</b>	<b>55</b>	<b>892</b>
<b>TUNA CLIPPER</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>899</b>
<b>SANTA FE INTERMODAL</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>908</b>
<b>SANTA FE RAILWAY</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>920</b>
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
<b>IMS RECYCLING</b>	<b>2740 BOSTON AVE</b>	<b>59</b>	<b>1125</b>
<b>JVM SPA COVERS</b>	<b>2777 NEWTON AVE</b>	<b>59</b>	<b>1147</b>
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
<b>KARVON ELECTRIC</b>	<b>2635 LOGAN AVE</b>	<b>59</b>	<b>1253</b>
<b>CITY OF S.D. PARKING LOT</b>	<b>2183 NATIONAL AVE</b>	<b>59</b>	<b>1265</b>
<b>S D UNIFIED SCHOOL DISTRICT</b>	<b>3550 LOGAN AV</b>	<b>62</b>	<b>1314</b>
<b>CARLSON AND BEAULOYE</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1330</b>
<b>CORROSION ENGG SVC, INC.</b>	<b>1995 BAY FRONT ST</b>	<b>68</b>	<b>1384</b>
<b>CONTINENTAL MARITIME</b>	<b>1995 BAY FRONT ST</b>	<b>68</b>	<b>1389</b>
<b>CLEANING DYNAMICS</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1461</b>
<b>TANK #801 &amp; #802 *</b>	<b>2141 MAIN ST</b>	<b>69</b>	<b>1485</b>
<b>PORT OF SAN DIEGO</b>	<b>1875 WATER ST</b>	<b>70</b>	<b>1498</b>
<b>ADAMS COMMERCIAL PROPERTY</b>	<b>3369 NATIONAL AVE</b>	<b>71</b>	<b>1514</b>
<b>U.S.A. PETROLEUM</b>	<b>3502 NATIONAL AVE</b>	<b>72</b>	<b>1515</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>USA PETROLEUM STA. #50</b>	<b>3502 NATIONAL AVE</b>	<b>72</b>	<b>1527</b>
<b>AMERICAN FORKLIFT</b>	<b>3485 NATIONAL AVE</b>	<b>72</b>	<b>1534</b>
<b>SOUTHERN CALIFORNIA PLATING CO</b>	<b>3261 NATIONAL AV</b>	<b>73</b>	<b>1543</b>
<b>HOLSUM BAKING CO</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1570</b>
<b>SAN DIEGO EXPRESS INC.,</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1593</b>
<b>SAN DIEGO MUSEUM OF ART</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1606</b>
<b>ISP ALGINATES INCORPORATED</b>	<b>2145 EAST BELT STREET</b>	<b>79</b>	<b>1659</b>
<b>SILVERGATE POWER PLANT</b>	<b>1348 SAMPSON ST</b>	<b>79</b>	<b>1674</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>TEXACO SERVICE STATION</b>	<b>1145 28TH ST S</b>	<b>80</b>	<b>1740</b>
<b>ATALS FENCE COMPANY</b>	<b>1211 32ND ST S</b>	<b>83</b>	<b>1753</b>
<b>ATLAS FENCE COMPANY</b>	<b>1211 32ND ST S</b>	<b>83</b>	<b>1754</b>
<b>CHEVRON SERVICE STATION</b>	<b>2351 HARBOR DR E</b>	<b>84</b>	<b>1768</b>
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1794</b>
<b>ARCO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1816</b>
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
<b>THE SICKLES GROUP</b>	<b>2795 MAIN ST</b>	<b>88</b>	<b>1886</b>
<b>MARKEL OHNSON</b>	<b>2697 MAIN ST</b>	<b>88</b>	<b>1904</b>
<b>GIOLZETTI AND LULUE</b>	<b>2694 MAIN ST</b>	<b>88</b>	<b>1914</b>
<b>BILL LEONG'S IMPORT/EXPORT</b>	<b>1531 RIGEL ST</b>	<b>90</b>	<b>1928</b>
<b>TRIPLE A SOUTH</b>	<b>3350 MAIN ST</b>	<b>94</b>	<b>2012</b>
<b>BABYLAND DIAPER SERVICE</b>	<b>3348 MAIN ST</b>	<b>94</b>	<b>2013</b>
<b>NEX GAS 28TH ST</b>	<b>28ND ST</b>	<b>100</b>	<b>2066</b>
<b>ARATEX SERVICES</b>	<b>3504 MAIN ST</b>	<b>101</b>	<b>2078</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 3300 32ND ST</b>	<b>101</b>	<b>2095</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 332 32ND ST</b>	<b>101</b>	<b>2114</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 209 32ND ST</b>	<b>101</b>	<b>2115</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 3356 32ND ST</b>	<b>101</b>	<b>2117</b>
<b>NAVAL STATION FTC, FFS-12</b>	<b>BLDG 171 32ND ST</b>	<b>101</b>	<b>2118</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 3162 32ND ST</b>	<b>101</b>	<b>2118</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 265 32ND ST</b>	<b>101</b>	<b>2119</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 132 32ND ST</b>	<b>101</b>	<b>2120</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 129 32ND ST</b>	<b>101</b>	<b>2121</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 254 32ND ST</b>	<b>101</b>	<b>2124</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 273 32ND ST</b>	<b>101</b>	<b>2125</b>
<b>SAN DIEGO NAVAL STATION</b>	<b>SAN DIEGO BAY 113 NAVAL</b>	<b>101</b>	<b>2146</b>
<b>SAN DIEGO NAVAL STATION -</b>	<b>SAN DIEGO BAY 113 NAVAL</b>	<b>101</b>	<b>2146</b>
<b>AMERICAN LINEN</b>	<b>3460 MAIN ST</b>	<b>101</b>	<b>2152</b>
<b>AMERICAN UNIFORM &amp; TOWEL SUPPLY</b>	<b>3440 MAIN ST</b>	<b>101</b>	<b>2158</b>
<b>AMERICAN LINEN SUPPLY</b>	<b>3410 MAIN ST</b>	<b>101</b>	<b>2164</b>
<b>SUNDANCE STAGE LINES</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2200</b>
<b>ESPARZA'S USED TIRES</b>	<b>3698 MAIN ST</b>	<b>104</b>	<b>2257</b>
<b>BAY CITIES SERVICES</b>	<b>3683 DALBERGIA</b>	<b>104</b>	<b>2322</b>
<b>ARAMARK UNIFORM SERVICES</b>	<b>3554 DALBERGIA</b>	<b>104</b>	<b>2384</b>
<b>ARATEX SERVICES INC.</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2400</b>
<b>SOVEREIGN CONST-GEN DYNAM/CONV</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2416</b>
<b>ONE TEN LIQUOR</b>	<b>110 NATIONAL CITY BLVD</b>	<b>109</b>	<b>2448</b>
<b>MOBIL OIL STATION #18-FF9</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2455</b>
<b>MOBIL SERVICE STATION #18-FF9</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2461</b>
<b>DIVISION SHELL SERVICE</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2470</b>
<b>SHELL SERVICE STATION</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2481</b>
<b>SDGE STN A, BLOCK 148 UST</b>	<b>114 10TH AVE/900 L</b>	<b>110</b>	<b>2482</b>
<b>CHEVRON STAT. #98225</b>	<b>105 8TH ST W</b>	<b>114</b>	<b>2489</b>
<b>THRIFTY #103</b>	<b>801 ROOSEVELT AVE</b>	<b>114</b>	<b>2491</b>

## EXECUTIVE SUMMARY

**SWRCY:** A listing of recycling facilities in California.

A review of the SWRCY list, as provided by EDR, and dated 04/07/2008 has revealed that there are 5 SWRCY sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
TIME RECYCLING CENTER	412 CESAR E CHAVEZ PKWY	44	789
J & R RECYCLING	3374 NATIONAL AVE	71	1514
NATIONAL RECYCLING CENTER	3008 NATIONAL AVE	75	1565
A TO Z AUTO INC	3202 MAIN ST	86	1819
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>

**LUST:** The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.

A review of the LUST list, as provided by EDR, and dated 04/08/2008 has revealed that there are 264 LUST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SHELL SEERVICE STATION</b>	<b>1619 G STREET</b>	<b>5</b>	<b>7</b>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
Facility Status: Case Closed			
<b>SHELL OIL PRODUCTS COMPANY</b>	<b>1619 G ST</b>	<b>5</b>	<b>16</b>
Facility Status: Remediation Plan			
Facility Status: Remediation Plan			
<b>HAWTHORNE RENT-IT SERVICE</b>	<b>1473 G ST</b>	<b>6</b>	<b>27</b>
Facility Status: Preliminary site assessment underway			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>ROAD RUNNERS</b>	<b>544 11TH AV</b>	<b>8</b>	<b>42</b>
Facility Status: Case Closed			
<b>JAMES' DETAIL SHOP</b>	<b>544 11TH ST</b>	<b>8</b>	<b>45</b>
<b>WESTERN PACIFIC HOUSING</b>	<b>1147 MARKET ST</b>	<b>8</b>	<b>46</b>
Facility Status: Case Closed			
<b>ISLAND VILLAGE APARTMENTS</b>	<b>1213 MARKET ST</b>	<b>8</b>	<b>48</b>
Facility Status: Remediation Plan			
<b>FSE INC</b>	<b>1238-1258 MARKET ST</b>	<b>8</b>	<b>49</b>
<b>YELLOW CAB CO OF SAN DIEGOINC</b>	<b>639 13TH ST</b>	<b>8</b>	<b>52</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>UNOCAL SERVICE STATION</b>	<b>1606 MARKET ST</b>	<b>10</b>	<b>69</b>
<b>UNOCAL SERV STN #0364-30319</b>	<b>1606 MARKET ST</b>	<b>10</b>	<b>70</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>ADT PROPERTY HOLDINGS INC</b>	<b>1416 MARKET ST</b>	<b>11</b>	<b>80</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<b>PARKSIDE, FORMER E. VIL. COMM</b>	<b>505 13TH ST</b>	<b>14</b>	<b>86</b>
Facility Status: Preliminary site assessment underway			

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>ECONO AUTO REPAIR/GAS</b> Facility Status: Case Closed	<b>400 16TH ST</b>	<b>15</b>	<b>88</b>
<b>JOHN HANSEN HOUSE MOVING</b> Facility Status: Remedial action (cleanup) Underway	<b>405 15TH ST</b>	<b>15</b>	<b>96</b>
<b>JOHN HANSEN HOUSE MOVING</b> Facility Status: Remediation Plan	<b>405 15TH</b>	<b>15</b>	<b>98</b>
<b>PACIFIC MARINE SHEET METAL COR</b> Facility Status: Case Closed	<b>410 15TH ST</b>	<b>15</b>	<b>99</b>
<b>VICTOR'S USED TIRES</b> Facility Status: Case Closed	<b>405 16TH ST</b>	<b>15</b>	<b>106</b>
<b>MOTOR WORKS INC</b> Facility Status: Case Closed	<b>1490 ISLAND AV</b>	<b>15</b>	<b>111</b>
<b>BARTOLINI TRUST</b> <b>ARCWELL CORP</b> Facility Status: Remediation Plan Facility Status: Remediation Plan	<b>1460 ISLAND AVE</b> <b>510 16TH STREET</b>	<b>15</b> <b>15</b>	<b>115</b> <b>117</b>
<b>SHERMAN HEIGHTS FAMILY HLTH CT</b> Facility Status: Preliminary site assessment underway	<b>450 24TH ST</b>	<b>16</b>	<b>126</b>
<b>EAST VILLAGE RDA (535-353-08)</b> <b>MONTERREY PROVISION CO INC</b> Facility Status: Case Closed Facility Status: Case Closed	<b>318 9TH AVE</b> <b>318 09TH AV</b>	<b>17</b> <b>17</b>	<b>130</b> <b>131</b>
<b>A-1 QUALITY TRANSMISSIONS</b> <b>BIG TOW</b> Facility Status: Case Closed	<b>901 J ST</b> <b>901 J ST</b>	<b>17</b> <b>17</b>	<b>135</b> <b>136</b>
<b>DOS AMIGOS PROPERTY</b> Facility Status: Case Closed	<b>405 10TH AV</b>	<b>17</b>	<b>138</b>
<b>DONEV COMPANY</b> <b>DONEV COMPANY</b> Facility Status: Case Closed	<b>441 10TH AVE</b> <b>441 10TH AV</b>	<b>17</b> <b>17</b>	<b>141</b> <b>142</b>
<b>CONTINENTAL CLEANERS</b> Facility Status: Case Closed	<b>450 10TH AV</b>	<b>17</b>	<b>146</b>
<b>12TH &amp; ISLAND</b> Facility Status: Case Closed	<b>443 12TH AV</b>	<b>18</b>	<b>152</b>
<b>ALLAN COMPANY</b> Facility Status: Case Closed	<b>415 14TH ST</b>	<b>19</b>	<b>153</b>
SDG&E STATION A, TANK 1801 <b>SDGE STA A BL 148 FUELING FAC</b> Facility Status: Case Closed Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>114 10TH AVE</b> <b>114 10TH AV</b>	<b>21</b> <b>21</b>	<b>158</b> <b>159</b>
<b>SDG &amp; E SERVICE BUILD</b> Facility Status: Pollution Characterization	<b>114 TENTH AVENUE</b>	<b>21</b>	<b>164</b>
SAN DIEGO GAS & ELEC TANK #1702 SAN DIEGO GAS & ELEC TANK #202 <b>EAST VILLAGE RDA</b> Facility Status: Case Closed Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>114 10TH AVE W</b> <b>114 10TH AVE W</b> <b>200 10TH AV</b>	<b>21</b> <b>21</b> <b>21</b>	<b>170</b> <b>171</b> <b>171</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SDG&amp;E/STATION A BLOCK 135</b> Facility Status: Case Closed	<b>250 10TH AV</b>	<b>21</b>	<b>241</b>
<b>BALL PARK</b> Facility Status: Preliminary site assessment underway	<b>175 11TH AV</b>	<b>21</b>	<b>244</b>
STATION A TANK 203 BLOCK 150	175 11TH AVE	21	245
<b>BALLPARK INFRASTRUCTURE SITE</b>	<b>K ST AND IMPERIAL BORDE</b>	<b>21</b>	<b>246</b>
<b>SOUTHWEST MARINE HARDWARE</b> Facility Status: Case Closed	<b>944 K ST</b>	<b>21</b>	<b>250</b>
<b>SOUTHWEST HARDWARE</b>	<b>944 K ST</b>	<b>21</b>	<b>254</b>
ALTA E. OLIVER TRUST PROPERTY	312 11TH AVE	21	255
<b>ATLAS FIRE EQUIPMENT CO</b> Facility Status: Remediation Plan Facility Status: Case Closed	<b>312 11TH AV</b>	<b>21</b>	<b>256</b>
<b>LIBRARY TOWER</b> Facility Status: Preliminary site assessment underway	<b>325 12TH AV</b>	<b>21</b>	<b>260</b>
<b>SDCTY-POLICE REPAIR FACILITY</b> Facility Status: Preliminary site assessment underway	<b>300 12TH AV</b>	<b>21</b>	<b>261</b>
<b>CITY OF SAN DIEGO</b>	<b>330 12TH AVE</b>	<b>21</b>	<b>262</b>
<b>SD CITY POLICE</b> Facility Status: Preliminary site assessment underway Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>330 12TH AV</b>	<b>21</b>	<b>263</b>
<b>CENTRAL POLICE STATION</b>	<b>320 12TH AVE</b>	<b>21</b>	<b>269</b>
<b>A.W. COGGESHALL</b> Facility Status: Case Closed	<b>354 11TH AV</b>	<b>21</b>	<b>270</b>
<b>CARNATION DAIRY COMPANY</b>	<b>354 11TH AVE</b>	<b>21</b>	<b>274</b>
<b>SAN DIEGO TRANSIT CORP</b> Facility Status: Remediation Plan Facility Status: Remediation Plan	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>BREITBARD PROPERTIES LLC</b> Facility Status: Remediation Plan	<b>101 16TH ST</b>	<b>24</b>	<b>310</b>
<b>CALIF.Industr. &amp; LINEN SUPPLY</b>	<b>101 16TH ST</b>	<b>24</b>	<b>316</b>
<b>FRED'S AUTO BODY &amp; PAINT</b>	<b>301 16TH ST</b>	<b>24</b>	<b>319</b>
<b>ROY'S AUTO REPAIR</b> Facility Status: Case Closed	<b>301 16TH ST</b>	<b>24</b>	<b>322</b>
<b>COTINENTAL BAKING COMP</b> Facility Status: Case Closed Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>171 14TH ST</b>	<b>27</b>	<b>327</b>
<b>TRIANGLE PROPERTY</b> Facility Status: Preliminary site assessment underway	<b>65 13TH ST</b>	<b>28</b>	<b>338</b>
SAN DIEGO GAS & ELECTRIC Facility Status: Leak being confirmed	NONE 14TH ST / IMPERI	28	339
<b>INTERSTATE BRANDS CORP.</b>	<b>1401 IMPERIAL AVE</b>	<b>28</b>	<b>341</b>
<b>INTERSTATE BRANDS CORP.</b> Facility Status: Case Closed Facility Status: Case Closed	<b>1401 IMPERIAL AV</b>	<b>28</b>	<b>342</b>
<b>SDG &amp; E PROPERTY</b> Facility Status: Preliminary site assessment underway	<b>0 IMPERIAL AV</b>	<b>28</b>	<b>347</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SQUIRES BELT MATERIAL CO</b> Facility Status: Case Closed	<b>149 12TH AV</b>	<b>28</b>	<b>355</b>
<b>SQUIRES BELT MATERIAL</b>	<b>149 12TH AVE</b>	<b>28</b>	<b>359</b>
<b>VITAGOLD COOPERATIVE ASSOC.</b>	<b>2121 IMPERIAL AVE</b>	<b>29</b>	<b>364</b>
<b>VITAGOLD BRANDS COOP AT0726</b> Facility Status: Case Closed	<b>2121 IMPERIAL AV</b>	<b>29</b>	<b>366</b>
<b>UNIVERSAL RADIATOR SHOP</b> Facility Status: Preliminary site assessment underway Facility Status: Preliminary site assessment underway	<b>2005 IMPERIAL AV</b>	<b>29</b>	<b>375</b>
<b>FIRST CHOICE</b> Facility Status: Case Closed	<b>24 21ST ST</b>	<b>29</b>	<b>382</b>
<b>CITY OF SAN DIEGO</b> Facility Status: Remedial action (cleanup) Underway	<b>800 HARBOR DR</b>	<b>30</b>	<b>387</b>
<b>MTDB LEASEHOLD</b> Facility Status: Case Closed	<b>93 08TH AV</b>	<b>30</b>	<b>390</b>
SDG&E STATION A, BLK 157	45 9TH AVE	30	393
<b>PLANT PRODUCTS &amp; SUPPLY CO</b> Facility Status: Case Closed Facility Status: Case Closed	<b>822 IMPERIAL AV</b>	<b>30</b>	<b>394</b>
EV RDA LOP (535-562-03)	822 IMPERIAL AVE	30	398
<b>CITY OF SAN DIEGO</b> Facility Status: Case Closed Facility Status: Case Closed	<b>800 IMPERIAL AV</b>	<b>30</b>	<b>399</b>
<b>MARATHON LAND &amp; CATTLE</b>	<b>2682 IMPERIAL AVE</b>	<b>32</b>	<b>405</b>
<b>MARATHON LAND &amp; CATILE</b> Facility Status: Case Closed	<b>2682 IMPERIAL AV</b>	<b>32</b>	<b>407</b>
<b>IMPERIAL AVENUE APARTMENTS</b> Facility Status: Preliminary site assessment underway	<b>2701 IMPERIAL AV</b>	<b>32</b>	<b>410</b>
<b>IMPERIAL AVE. APARTMENTS</b>	<b>2701 IMPERIAL AVE</b>	<b>32</b>	<b>413</b>
<b>CAMPBELL'S SHIPYARD</b> Facility Status: Remedial action (cleanup) Underway	<b>501 HARBOR DR</b>	<b>33</b>	<b>414</b>
THRIFTY SERVICE STATION #96	2502 IMPERIAL AVE	34	417
<b>THRIFTY #96</b>	<b>2502 IMPERIAL AVE</b>	<b>34</b>	<b>418</b>
<b>THRIFTY OIL STATION #96</b>	<b>2502 IMPERIAL AVE</b>	<b>34</b>	<b>424</b>
ARCO PRODUCTS COMPANY #9560	2502 IMPERIAL AVE	34	427
<b>ARCO 9560</b> Facility Status: Case Closed Facility Status: Preliminary site assessment underway <i>*Additional key fields are available in the Map Findings section</i>	<b>2502 IMPERIAL AV</b>	<b>34</b>	<b>427</b>
<b>EL GUERO TIRE SHOP</b>	<b>2401 IMPERIAL AVE</b>	<b>36</b>	<b>435</b>
<b>EL GUERO TIRE SHOP &amp; REPAIR</b>	<b>2401 IMPERIAL AV</b>	<b>36</b>	<b>436</b>
<b>BILL ALLEN/ELMER'S AUTO</b> Facility Status: Case Closed	<b>1902 NATIONAL AVE</b>	<b>37</b>	<b>462</b>
<b>URBAN CORPS OF SAN DIEGO</b> Facility Status: Case Closed	<b>1864 NATIONAL AV</b>	<b>37</b>	<b>473</b>
<b>BETTENCOURT AUTO BODY</b>	<b>1865 NATIONAL AVE</b>	<b>37</b>	<b>476</b>
<b>FRASER'S BOILER SERVICE, INC.</b> Facility Status: Case Closed	<b>1746 NEWTON AV</b>	<b>37</b>	<b>493</b>
<b>D'ARCH ENTERPRISES</b> Facility Status: Case Closed	<b>1879 LOGAN AV</b>	<b>37</b>	<b>500</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MOBIL SERVICE STATION</b>	<b>1879 LOGAN AVE</b>	<b>37</b>	<b>506</b>
<b>LOGAN HEIGHTS FAMILY HEALTH CT</b> Facility Status: Case Closed	<b>1809 NATIONAL AV</b>	<b>37</b>	<b>510</b>
<b>YE OLDE TOWN PUMP</b> Facility Status: Case Closed	<b>1792 NATIONAL AV</b>	<b>37</b>	<b>522</b>
<b>THE DIESEL CENTER</b>	<b>1792 NATIONAL AVE</b>	<b>37</b>	<b>527</b>
<b>TROPIC ICE CREAM CO</b> Facility Status: Case Closed	<b>1776 NATIONAL AV</b>	<b>37</b>	<b>529</b>
<b>TROPIC ICE CREAM</b>	<b>1776 NATIONAL AVE</b>	<b>37</b>	<b>533</b>
SUPER WELDING OF SO. CA., INC. Facility Status: Case Closed	1702 NATIONAL AV	37	574
<b>SAN DIEGO SAW AND KNIFE WORKS</b> Facility Status: Preliminary site assessment underway Facility Status: Case Closed	<b>1765 LOGAN AVE</b>	<b>37</b>	<b>578</b>
<b>ACTION CLEANING</b>	<b>1604 NEWTON AVE</b>	<b>37</b>	<b>617</b>
<b>ACTION CLEANING</b> Facility Status: Case Closed	<b>1604 NEWTON AV</b>	<b>37</b>	<b>618</b>
<b>CENTER CITY TOWING</b> Facility Status: Preliminary site assessment underway	<b>1668 NATIONAL AV</b>	<b>37</b>	<b>634</b>
<b>SAN DIEGO TROLLEY, INC</b> Facility Status: Case Closed Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>1535 NEWTON AV</b>	<b>37</b>	<b>650</b>
<b>CENTRAL MEAT &amp; PROVISION CO</b> Facility Status: Case Closed	<b>1603 NATIONAL AVE</b>	<b>37</b>	<b>671</b>
<b>GRAYBILL TERMINALS CO</b> Facility Status: Case Closed Facility Status: Case Closed	<b>1531 NATIONAL AV</b>	<b>37</b>	<b>676</b>
<b>GRAYBILL TERMINALS</b>	<b>1531 NATIONAL AVE</b>	<b>37</b>	<b>684</b>
<b>HUGHES ATTORNEY SERVICE INC</b> Facility Status: Case Closed	<b>1643 LOGAN AV</b>	<b>37</b>	<b>689</b>
<b>HUGHES ATTORNEY SERVICES</b>	<b>1643 LOGAN AVE</b>	<b>37</b>	<b>691</b>
<b>PEPPER INDUSTRIES INC</b> Facility Status: Case Closed	<b>1501 NATIONAL AVE</b>	<b>37</b>	<b>695</b>
<b>LUIS AUTO SERVICES</b> Facility Status: Case Closed	<b>1603 LOGAN AV</b>	<b>37</b>	<b>704</b>
<b>RELIABLE PIPE SUPPLY</b> Facility Status: Case Closed	<b>1430 NATIONAL AV</b>	<b>37</b>	<b>707</b>
<b>PENSKE TRUCK LEASING INC</b> Facility Status: Remediation Plan	<b>1402 COMMERCIAL ST</b>	<b>37</b>	<b>714</b>
<b>HERTZ - PENSKE TRUCK LEASING</b>	<b>1402 COMMERCIAL ST</b>	<b>37</b>	<b>723</b>
<b>ST. VINCENT DEPAUL</b> Facility Status: Case Closed Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>16 15TH ST</b>	<b>37</b>	<b>732</b>
<b>CATELLUS DEVELOPMENT PROPERTY</b> Facility Status: Case Closed	<b>702 HARBOR DR</b>	<b>39</b>	<b>752</b>
<b>EL DORADO SANDBLASTING</b>	<b>2694 COMMERCIAL ST</b>	<b>40</b>	<b>756</b>
<b>EL DORADO SANDBLASTING CO</b> Facility Status: Case Closed Facility Status: Case Closed	<b>2694 COMMERCIAL ST</b>	<b>40</b>	<b>759</b>



## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>ELDORADO SAND BLASTING</b>	<b>2675 COMMERCIAL ST</b>	<b>40</b>	<b>767</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<b>SDUSD MAINTENANCE</b>	<b>1826 IRVING AVE</b>	<b>42</b>	<b>774</b>
<b>SDUSD - MAINTENANCE</b>	<b>1826 IRVING AV</b>	<b>42</b>	<b>778</b>
Facility Status: Preliminary site assessment underway			
Facility Status: Preliminary site assessment underway			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>SAN DIEGO CITY SCHOOLS</b>	<b>1826 IRVINE AVE</b>	<b>42</b>	<b>785</b>
<b>SD PORT DISTRICT MAINT DEPT</b>	<b>825 E HARBOR DR</b>	<b>45</b>	<b>790</b>
Facility Status: Case Closed			
<b>PORT OF SAN DIEGO DIST MAINT F</b>	<b>825 EAST HARBOR DRIVE</b>	<b>45</b>	<b>794</b>
<b>RALSTON PURINA/VAN CAMP</b>	<b>1025 E HARBOR DR</b>	<b>49</b>	<b>800</b>
Facility Status: Case Closed			
RALSTON PURINA COMPANY	1025 HARBOR DR E	49	803
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
Facility Status: Case Closed			
<b>YOUNGS MARKET CO</b>	<b>1709 MAIN ST</b>	<b>53</b>	<b>831</b>
Facility Status: Case Closed			
<b>YOUNG'S MARKET COMPANY</b>	<b>1709 MAIN ST S</b>	<b>53</b>	<b>834</b>
<b>JR GAS AND MINI MART</b>	<b>505 S 30TH ST</b>	<b>54</b>	<b>839</b>
Facility Status: Case Closed			
<b>P&amp;L KNEPP TRUCKING</b>	<b>2001 MAIN ST</b>	<b>55</b>	<b>864</b>
Facility Status: Case Closed			
<b>A.O. REED</b>	<b>1990 MAIN ST</b>	<b>55</b>	<b>884</b>
<b>A O REED</b>	<b>1990 MAIN ST</b>	<b>55</b>	<b>885</b>
Facility Status: Case Closed			
<b>MAAC PRO ECT, SDG&amp;E</b>	<b>2043 NEWTON AVE</b>	<b>55</b>	<b>892</b>
<b>SDG &amp; E</b>	<b>2043 NEWTON AV</b>	<b>55</b>	<b>893</b>
Facility Status: Case Closed			
<b>TUNA CLIPPER</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>899</b>
<b>TUNA CLIPPER MARINE</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>899</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<b>SANTA FE INTERMODAL</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>908</b>
Facility Status: Preliminary site assessment underway			
Facility Status: Preliminary site assessment underway			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>SANTA FE RAILWAY</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>920</b>
<b>MERCADO COMMERCIAL CENTER</b>	<b>1920 MAIN ST</b>	<b>55</b>	<b>934</b>
Facility Status: Case Closed			
<b>A.E.P. CORP.</b>	<b>1901 MAIN ST</b>	<b>55</b>	<b>949</b>
Facility Status: Case Closed			
<b>JOHNSON TRUCK REPAIR &amp; PAINT</b>	<b>1931 NEWTON AV</b>	<b>55</b>	<b>968</b>
Facility Status: Preliminary site assessment underway			
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
Facility Status: Case Closed			
<b>I M S RECYCLING SVC IRON DEPT</b>	<b>2740 BOSTON AV</b>	<b>59</b>	<b>1121</b>
Facility Status: Case Closed			

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>IMS RECYCLING</b>	<b>2740 BOSTON AVE</b>	<b>59</b>	<b>1125</b>
<b>MEDLAND CONTROLS INC</b> Facility Status: Case Closed	<b>2393 NEWTON AV</b>	<b>59</b>	<b>1134</b>
<b>UNION ELECTRIC MOTOR SERVICE</b> Facility Status: Case Closed	<b>2777 NEWTON AV</b>	<b>59</b>	<b>1142</b>
<b>JVM SPA COVERS</b>	<b>2777 NEWTON AVE</b>	<b>59</b>	<b>1147</b>
<b>FORDS &amp; FOREIGN AUTO PARTS</b> Facility Status: Case Closed	<b>2335 NEWTON AV</b>	<b>59</b>	<b>1179</b>
<b>BARRIO STATION INC</b> Facility Status: Case Closed Facility Status: Case Closed	<b>2320 NEWTON AV</b>	<b>59</b>	<b>1185</b>
<b>ABC CONSTRUCTION CO</b> Facility Status: Remediation Plan Facility Status: Case Closed	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
<b>KARVON ELECTRIC</b>	<b>2635 LOGAN AVE</b>	<b>59</b>	<b>1253</b>
<b>SAN DIEGO EXPRESS</b> Facility Status: Case Closed	<b>2635 LOGON ST</b>	<b>59</b>	<b>1254</b>
<b>CALIFORNIA METAL FORMING</b> Facility Status: Case Closed	<b>2183 NATIONAL AV</b>	<b>59</b>	<b>1262</b>
<b>CITY OF S.D. PARKING LOT</b>	<b>2183 NATIONAL AVE</b>	<b>59</b>	<b>1265</b>
<b>FREIGHT HANDLERS INC</b> Facility Status: Case Closed Facility Status: Case Closed	<b>1790 WATER ST</b>	<b>61</b>	<b>1308</b>
<b>S D UNIFIED SCHOOL DISTRICT</b> Facility Status: Case Closed	<b>3550 LOGAN AV</b>	<b>62</b>	<b>1314</b>
<b>BANDINI UNIOR HIGH SCHOOL</b>	<b>3550 LOGAN AVE</b>	<b>62</b>	<b>1317</b>
<b>PRAXAIR DISTRIBUTION INC.</b> Facility Status: Post remedial action monitoring	<b>2205 NEWTON AV</b>	<b>63</b>	<b>1319</b>
<b>CARLSON AND BEAULOYE</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1330</b>
<b>CARLSON &amp; BEAULOYE MACHINE SHO</b> Facility Status: Case Closed	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1332</b>
<b>CONTINENTAL MARITIME OF S D</b> Facility Status: Case Closed Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>1995 BAYFRONT ST</b>	<b>68</b>	<b>1389</b>
<b>CP KELCO</b> Facility Status: Case Closed Facility Status: Preliminary site assessment underway <i>*Additional key fields are available in the Map Findings section</i>	<b>2025 HARBOR DR</b>	<b>68</b>	<b>1414</b>
<b>CLEANING DYNAMICS</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1461</b>
<b>AMERICAN KELP</b> Facility Status: Remediation Plan	<b>2190 MAIN ST</b>	<b>69</b>	<b>1468</b>
<b>TANK #801 &amp; #802 *</b> Facility Status: Case Closed	<b>2141 MAIN ST</b>	<b>69</b>	<b>1485</b>
<b>PORT OF SAN DIEGO</b> Facility Status: Case Closed	<b>1875 WATER ST</b>	<b>70</b>	<b>1498</b>
<b>MARTINEZ AUTO REPAIR</b> Facility Status: Case Closed	<b>3369 NATIONAL AV</b>	<b>71</b>	<b>1511</b>
<b>ADAMS COMMERCIAL PROPERTY</b>	<b>3369 NATIONAL AVE</b>	<b>71</b>	<b>1514</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>U.S.A. PETROLEUM</b>	<b>3502 NATIONAL AVE</b>	<b>72</b>	<b>1515</b>
<b>USA GASOLINE CORP #50</b>	<b>3502 NATIONAL AV</b>	<b>72</b>	<b>1516</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>USA PETROLEUM STA. #50</b>	<b>3502 NATIONAL AVE</b>	<b>72</b>	<b>1527</b>
<b>AMERICAN FORKLIFT/J MAGRE</b>	<b>3485 NATIONAL AV</b>	<b>72</b>	<b>1529</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>AMERICAN FORKLIFT</b>	<b>3485 NATIONAL AVE</b>	<b>72</b>	<b>1534</b>
<b>GENERAL AUTO REPAIR</b>	<b>3451 NATIONAL AV</b>	<b>72</b>	<b>1536</b>
Facility Status: Case Closed			
<b>CAL SOFT WATER SERVICE INC</b>	<b>3094 NATIONAL AVE</b>	<b>74</b>	<b>1558</b>
Facility Status: Case Closed			
<b>FORMER FORNACA BAKERY</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1568</b>
<b>HOLSUM BAKING CO</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1570</b>
Facility Status: Case Closed			
<b>AUTOZONE #5674</b>	<b>2865 NATIONAL AV</b>	<b>77</b>	<b>1576</b>
Facility Status: Case Closed			
<b>DORMANS TIRE CO</b>	<b>2385 MAIN ST</b>	<b>78</b>	<b>1580</b>
Facility Status: Case Closed			
<b>SAN DIEGO EXPRESS INC.,</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1593</b>
<b>SAN DIEGO EXPRESS INC</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1594</b>
Facility Status: Case Closed			
<b>SOUTHWEST MARINE</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1602</b>
Facility Status: Case Closed			
<b>SAN DIEGO MUSEUM OF ART</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1606</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<b>ISP ALGINATES</b>	<b>2145 E BELT ST</b>	<b>79</b>	<b>1637</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>ISP ALGINATES INCORPORATED</b>	<b>2145 EAST BELT STREET</b>	<b>79</b>	<b>1659</b>
<b>SILVERGATE POWER PLANT</b>	<b>1348 SAMPSON ST</b>	<b>79</b>	<b>1674</b>
Facility Status: Preliminary site assessment underway			
Facility Status: Preliminary site assessment underway			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAY FRONT STREET</b>	<b>79</b>	<b>1682</b>
Facility Status: Leak being confirmed			
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>TEXACO MARKETING</b>	<b>1145 S 28TH ST</b>	<b>80</b>	<b>1723</b>
Facility Status: Case Closed			
Facility Status: Preliminary site assessment underway			
<b>TEXACO SERVICE STATION</b>	<b>1145 28TH ST S</b>	<b>80</b>	<b>1740</b>
<b>SAN DIEGO HOUSING COMMISSION</b>	<b>2883 BOSTON AV</b>	<b>82</b>	<b>1746</b>
<b>ATLAS FENCE COMPANY</b>	<b>1211 32ND ST S</b>	<b>83</b>	<b>1753</b>
<b>ATLAS FENCE COMPANY</b>	<b>1211 32ND ST S</b>	<b>83</b>	<b>1754</b>
<b>ALCORN FENCE COMPANY DBA ATLAS</b>	<b>1211 S 32ND ST</b>	<b>83</b>	<b>1757</b>
Facility Status: Case Closed			
Facility Status: Case Closed			

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>CHEVRON SERVICE STATION</b>	<b>2351 HARBOR DR E</b>	<b>84</b>	<b>1768</b>
<b>CHEVRON USA INC.</b>	<b>2351 HARBOR DR</b>	<b>84</b>	<b>1772</b>
Facility Status: Case Closed			
<b>CHEVRON USA INC.</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1773</b>
Facility Status: Remediation Plan			
Facility Status: Preliminary site assessment underway			
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1794</b>
Facility Status: Remedial action (cleanup) Underway			
Facility Status: Remedial action (cleanup) Underway			
*Additional key fields are available in the Map Findings section			
ARCO GAS TERMINAL	2295 HARBOR DR E	84	1814
<b>ARCO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1816</b>
<b>ARC CASTLE ELECTRONICS</b>	<b>3106 MAIN ST</b>	<b>86</b>	<b>1837</b>
Facility Status: Case Closed			
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
Facility Status: Case Closed			
<b>THE SICKLES GROUP</b>	<b>2795 MAIN ST</b>	<b>88</b>	<b>1886</b>
Facility Status: Case Closed			
<b>MARKEL OHNSON</b>	<b>2697 MAIN ST</b>	<b>88</b>	<b>1904</b>
Facility Status: Case Closed			
<b>GIOLZETTI AND LULUE</b>	<b>2694 MAIN ST</b>	<b>88</b>	<b>1914</b>
Facility Status: Case Closed			
<b>BILL LEONG'S IMPORT/EXPORT</b>	<b>1531 RIGEL ST</b>	<b>90</b>	<b>1928</b>
Facility Status: Case Closed			
<b>US COAST GUARD AIR STATION</b>	<b>2710 HARBOR DR</b>	<b>91</b>	<b>1936</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
*Additional key fields are available in the Map Findings section			
<b>TRIPLE A SOUTH</b>	<b>3350 MAIN ST</b>	<b>94</b>	<b>2012</b>
<b>BABYLAND DIAPER SERVICE</b>	<b>3348 MAIN ST</b>	<b>94</b>	<b>2013</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<b>AEROSPACE COATINGS &amp; TECH</b>	<b>1610 RIGEL ST</b>	<b>94</b>	<b>2052</b>
Facility Status: Case Closed			
PUBLIC WORKS CENTER	BLDG 132 32ND ST	97	2060
CO FLEET TRAINING CENTER	32ND ST	99	2065
<b>ARATEX SERVICES</b>	<b>3504 MAIN ST</b>	<b>101</b>	<b>2078</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 3300 32ND ST</b>	<b>101</b>	<b>2095</b>
NAVAL STATION SAN DIEGO	BLDG 322/65 32ND ST	101	2096
NAVAL STATION SAN DIEGO	BLDG 223 32ND ST	101	2097
<b>APPLIED ENERGY AT NAVSTA</b>	<b>3970 SURFACE NAVY B-342</b>	<b>101</b>	<b>2100</b>
Facility Status: Case Closed			
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 332 32ND ST</b>	<b>101</b>	<b>2114</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 209 32ND ST</b>	<b>101</b>	<b>2115</b>
NAVAL STATION SAN DIEGO	BLDG 3403 32ND ST	101	2116
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 3356 32ND ST</b>	<b>101</b>	<b>2117</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 3162 32ND ST</b>	<b>101</b>	<b>2118</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 265 32ND ST</b>	<b>101</b>	<b>2119</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
NAVAL STATION SAN DIEGO	TANK 270 32ND ST	101	2119
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 132 32ND ST</b>	<b>101</b>	<b>2120</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 129 32ND ST</b>	<b>101</b>	<b>2121</b>
NAVAL STATION SAN DIEGO	TANK 259 / 268 32ND S	101	2122
NAVAL STATION SAN DIEGO	BLDG 271 32ND ST	101	2123
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 254 32ND ST</b>	<b>101</b>	<b>2124</b>
<b>NAVAL STATION SAN DIEGO</b>	<b>BLDG 273 32ND ST</b>	<b>101</b>	<b>2125</b>
<b>AMERICAN LINEN</b>	<b>3460 MAIN ST</b>	<b>101</b>	<b>2152</b>
Facility Status: Case Closed			
<b>AMERICAN UNIFORM &amp; TOWEL SUPPLY</b>	<b>3440 MAIN ST</b>	<b>101</b>	<b>2158</b>
Facility Status: Case Closed			
<b>AMERICAN LINEN SUPPLY</b>	<b>3410 MAIN ST</b>	<b>101</b>	<b>2164</b>
Facility Status: Case Closed			
<b>SUNDANCE STAGE LINES INC</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2189</b>
Facility Status: Case Closed			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>SUNDANCE STAGE LINES</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2200</b>
<b>ESPARZA'S USED TIRES</b>	<b>3698 MAIN ST</b>	<b>104</b>	<b>2257</b>
Facility Status: Remediation Plan			
<b>TRANS TECH TRANSMISSIONS</b>	<b>3644 MAIN ST</b>	<b>104</b>	<b>2276</b>
Facility Status: Case Closed			
<b>C AND B AUTO REPAIR</b>	<b>3683 DALBERGIA ST</b>	<b>104</b>	<b>2305</b>
Facility Status: Remedial action (cleanup) Underway			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>BAY CITIES SERVICES</b>	<b>3683 DALBERGIA</b>	<b>104</b>	<b>2322</b>
<b>CHICKS ELECTRIC</b>	<b>3592 MAIN ST</b>	<b>104</b>	<b>2323</b>
Facility Status: Case Closed			
<b>ARAMARK UNIFORM SERVICES</b>	<b>3554 DALBERGIA</b>	<b>104</b>	<b>2384</b>
<b>ARAMARK UNIFORM SERVICE INC</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2388</b>
Facility Status: Preliminary site assessment underway			
Facility Status: Case Closed			
<i>*Additional key fields are available in the Map Findings section</i>			
<b>ARATEX SERVICES INC.</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2400</b>
<b>GENERAL DYNAMICS CONVAIR</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2418</b>
Facility Status: Case Closed			
<b>NAVY EXCHANGE SVC STA</b>	<b>32ND ST &amp; HARBOR DR</b>	<b>106</b>	<b>2424</b>
FIRE FIGHTER TRAINING FACILITY	32ND ST	108	2443
NEW BLDG #P-235	P-235 FLEASWTRACENPAC	108	2443
EAST OF BLDG #2	E BLDG #2 FLEASWTRACENP	108	2444
<b>ONE TEN LIQUOR</b>	<b>110 NATIONAL CITY BLVD</b>	<b>109</b>	<b>2448</b>
<b>ONE TEN LIQUOR STORE</b>	<b>110 NATIONAL CITY BL</b>	<b>109</b>	<b>2449</b>
Facility Status: Remediation Plan			
<b>NATIONAL MOBIL SERVICE STATION</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2450</b>
Facility Status: Remediation Plan			
Facility Status: Case Closed			
<b>MOBIL OIL STATION #18-FF9</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2455</b>
<b>MOBIL SERVICE STATION #18-FF9</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2461</b>
<b>SHELL STATION</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2464</b>
Facility Status: Leak being confirmed			

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>DIVISION SHELL SERVICE</b> Facility Status: Case Closed Facility Status: Case Closed	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2470</b>
<b>SHELL SERVICE STATION</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2481</b>
<b>HOLIDAY INN SAN DIEGO SOUTH BA</b> Facility Status: Case Closed	<b>700 NATIONAL CITY BL</b>	<b>112</b>	<b>2483</b>
<b>CHEVRON STAT. #98225</b>	<b>105 8TH ST W</b>	<b>114</b>	<b>2489</b>
<b>THRIFTY #103</b>	<b>801 ROOSEVELT AVE</b>	<b>114</b>	<b>2491</b>
<b>ARCO FACILITY NO. 9565</b> Facility Status: Remediation Plan Facility Status: Case Closed <i>*Additional key fields are available in the Map Findings section</i>	<b>801 ROOSEVELT AV</b>	<b>114</b>	<b>2494</b>
<b>CHEVRON #98225</b> Facility Status: Remedial action (cleanup) Underway	<b>105 W 08TH ST</b>	<b>114</b>	<b>2502</b>

**SLIC:** SLIC Region comes from the California Regional Water Quality Control Board.

A review of the SLIC list, as provided by EDR, and dated 04/08/2008 has revealed that there are 9 SLIC sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
GRAYBILL TERMINALS	1531 NATIONAL AVENUE	37	676
SAINT VINCENT DE PAUL VILLAGE	15TH / 16TH STREETS	37	739
Not reported	2699 COMMERCIAL ST.	40	755
JANKOVICH & SONS INC	920 GULL STREET	51	812
SAN DIEGO GAS AND ELECTRIC Facility Status: Case Open	1348 SAMPSON STREET	79	1669
SOLAR TURBINES Facility Status: Feasibility Study for Remedial Action Plan	2201 HARBOR DR	79	1704
CHEVRON PIPELINE RUPTURE	BELT STREET / SICARD ST	89	1924
<b>TELEDYNE RYAN AERONAUTICAL</b> Facility Status: Pollution Characterization	<b>2701 HARBOR DR</b>	<b>91</b>	<b>1934</b>
<b>Not reported</b>	<b>HARBOR DRIVE AND 28TH S</b>	<b>92</b>	<b>1953</b>

**UST:** The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, and dated 04/08/2008 has revealed that there are 16 UST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>YELLOW CAB CO OF SAN DIEGO INC</b>	<b>639 13TH ST</b>	<b>8</b>	<b>52</b>
<b>UNOCAL SERV STN #0364-30319</b>	<b>1606 MARKET ST</b>	<b>10</b>	<b>70</b>
<b>BIG TOW</b>	<b>901 J ST</b>	<b>17</b>	<b>136</b>
<b>BREITBARD PROPERTIES LLC</b>	<b>101 16TH ST</b>	<b>24</b>	<b>310</b>
<b>PENSKE TRUCK LEASING INC</b>	<b>1402 COMMERCIAL ST</b>	<b>37</b>	<b>714</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>JR GAS AND MINI MART</b>	<b>505 S 30TH ST</b>	<b>54</b>	<b>839</b>
<b>ISP ALGINATES INCORPORATED</b>	<b>2145 E. BELT STREET</b>	<b>79</b>	<b>1665</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>TEXACO MARKETING</b>	<b>1145 S 28TH ST</b>	<b>80</b>	<b>1723</b>
<b>CHEVRON USA INC.</b>	<b>2351 HARBOR DR</b>	<b>84</b>	<b>1772</b>
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR</b>	<b>84</b>	<b>1793</b>
USN-NAVSTA/NEX ANNEX	BLD G 3156-28TH ST	101	2088
USN-NAVSTA/PWC GAS STATION	BLD G 305	101	2095
<b>SUNDANCE STAGE LINES INC</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2189</b>
<b>GENERAL DYNAMICS CONVAIR</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2418</b>
<b>NATIONAL MOBIL SERVICE STATION</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2450</b>

### HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 65 HIST UST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>HAWTHORNE RENT-IT SERVICE</b>	<b>1473 G ST</b>	<b>6</b>	<b>27</b>
<b>YELLOW CAB CO OF SAN DIEGO INC</b>	<b>639 13TH ST</b>	<b>8</b>	<b>52</b>
<b>CALIFORNIA LINEN SUPPLY</b>	<b>101 16TH ST</b>	<b>24</b>	<b>304</b>
ARCWEL CORP	229 16TH ST	24	316
ENGINEERING DEPT.	171 14TH ST	27	334
GARAGE/ITT CBC	171 14TH ST	27	334
SAN DIEGO	1300 L ST	27	337
WONDER BREAD THRIFT STORE	1304 IMPERIAL AVE	28	354
ARCWEL CORP	2031 COMMERCIAL ST	29	360
SAN DIEGO VAN & STORAGE CO.	1944 COMMERCIAL ST	29	363
ALL FRESH PRODUCTS, INC.	40 20TH ST	29	363
SOUTHWEST COACHES, INC.	1902 NATIONAL AVE	37	461
AVISE INC.	1841 NATIONAL AVE	37	483
<b>FRASER'S BOILER SERVICE, INC.</b>	<b>1746 NEWTON AVE</b>	<b>37</b>	<b>492</b>
MOBIL STATION #139	1879 LOGAN AVE	37	509
DIESEL CENTER	1792 NATIONAL AVE	37	527
LUBE EQUIP. PUMP SERV. CO.	178K LOGAN AVE.	37	554
<b>SUNBELT DISTRIBUTING CHEMICAL</b>	<b>1625 NEWTON ST</b>	<b>37</b>	<b>590</b>
<b>PACIFIC TREATMENT</b>	<b>1668 NATIONAL AVENUE</b>	<b>37</b>	<b>628</b>
<b>RADFORD OVERHEAD DOORS INC</b>	<b>1659 NATIONAL AVE</b>	<b>37</b>	<b>639</b>
CENTRAL MEAT AND PROVISION COM	1603 NATIONAL AVE	37	670
GRAYBILL TERMINALS	1531 NATIONAL AVE	37	684
B&L MASONRY, INC.	#9 17TH ST.	37	729
DEWITT TRANSFER AND STORAGE	16 15TH ST	37	731
SAN DIEGO TRANSIT CORPORATION	100-16TH STREET	37	749
SCHOOL	1826 IRVING AVE	42	777
WEBER MILBROOK PLANT	1955 JULIAN AVE	52	829
INTERSTATE BRANDS CORPORATION	1955 JULIAN AVE	52	829
YOUNG'S MARKET CO.	1709 MAIN ST	53	834
PRODUCE WAREHOUSE	2001 MAIN ST	55	871
<b>TUNA CLIPPER MARINE</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>899</b>
<b>A.E.P. CORP.</b>	<b>1901 MAIN ST</b>	<b>55</b>	<b>949</b>
SAN DIEGO GLASS & PAINT COMPAN	1827 MAIN ST	55	978
SAN DIEGO COATINGS	2646 MAIN ST	59	1024
IMS RECYCLING SERVICES, INC.	2740 BOSTON AVE. SCALE	59	1150

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
PACIFIC MOLASSES COMPANY	1750 WATER ST	61	1314
<b>BUMBLE BEE SEAFOODS</b>	<b>1995 BAYFRONT</b>	<b>68</b>	<b>1387</b>
MAIN STREET YARD	2141 MAIN ST	69	1485
<b>CAL SOFT WATER SERVICE INC</b>	<b>3094 NATIONAL AVE</b>	<b>74</b>	<b>1558</b>
LEASEWAY TRANSPORTATION	2304 MAIN ST	78	1590
<b>PHD CORP</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1591</b>
WILLIG FREIGHT LINES	2286 MAIN ST	78	1614
SOUTHWEST MARINE, INC.	2205 E BELT ST	79	1623
<b>MERCK &amp; COMPANY</b>	<b>2145 E BELT ST</b>	<b>79</b>	<b>1649</b>
SILVER GATE POWER PLANT	1348 SAMPSON ST	79	1669
<b>TEXACO REFINING &amp; MARKETING</b>	<b>1145 S 28TH ST</b>	<b>80</b>	<b>1734</b>
<b>ALCORN FENCE COMPANY DBA ATLAS</b>	<b>1211 S 32ND ST</b>	<b>83</b>	<b>1757</b>
<b>CHEVRON SAN DIEGO TERMINAL 100</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1783</b>
SAN DIEGO PIPELINE COMPANY HAR	2295 HARBOR DR	84	1815
<b>ADVANCED SURFACE TECHNOLOGY</b>	<b>3134 MAIN ST</b>	<b>86</b>	<b>1826</b>
MARKEL-JOHNSON POULTRY CO., IN	2697 MAIN ST	88	1904
EDDIE'S VOLKSWAGEN & FOREIGN R	2694 MAIN ST	88	1913
<b>NATIONAL STEEL AND SHIPBUILDIN</b>	<b>2798 EAST HARBOR DRIVE</b>	<b>92</b>	<b>1959</b>
TRIPLE "A" SOUTH	PO BOX 13097	94	2050
AMERICAN LINEN SERV.	3460 MAIN ST	101	2156
AMERICAN UNIFORM	3440 MAIN STRET	101	2158
AMERICAN COVERALL SUPPLY	3440 MAIN ST	101	2163
AMERICAN LINEN SUPPLY	3410 MAIN ST	101	2170
<b>TRANSTECH TRANSMISSIONS</b>	<b>3644 MAIN ST</b>	<b>104</b>	<b>2279</b>
BAY CITIES SERVICES, INC	3683 DALBERGIA ST # 367	104	2322
<b>NAVY EXCHANGE SVC STA</b>	<b>32ND ST &amp; HARBOR DR</b>	<b>106</b>	<b>2424</b>
<b>USNAVY EXCHANGE SERVICE STATIO</b>	<b>32ND &amp; HARBOR DR NAVAL</b>	<b>106</b>	<b>2427</b>
WILLIAM TABER	10 OSBORN ST	109	2463
KENNETH L RUSSEL	3890 DIVISION ST	109	2467

**AST:** The Aboveground Storage Tank database contains registered ASTs. The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the AST list, as provided by EDR, and dated 11/01/2007 has revealed that there are 5 AST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>CP KELCO</b>	<b>2025 EAST HARBOR DRIVE</b>	<b>68</b>	<b>1434</b>
SAN DIEGO TERMINAL	2351 E. HARBOR DR.	84	1771
SAN DIEGO TERMINAL	2295 E. HARBOR DR.	84	1816
<b>NAVAL STATION SAN DIEGO 32 ST</b>	<b>PIER 14</b>	<b>101</b>	<b>2113</b>
NAVAL STATION CENTRAL STEAM PL	213 WARD RD.	101	2125



## EXECUTIVE SUMMARY

**SWEEPS UST:** Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 99 SWEEPS UST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
<b>SHELL OIL PRODUCTS COMPANY</b>	<b>1619 G ST</b>	<b>5</b>	<b>16</b>
<b>HAWTHORNE RENT-IT SERVICE</b>	<b>1473 G ST</b>	<b>6</b>	<b>27</b>
<b>ECONO AUTO REPAIR/GAS</b>	<b>400 16TH ST</b>	<b>15</b>	<b>88</b>
<b>VICTOR'S USED TIRES</b>	<b>405 16TH ST</b>	<b>15</b>	<b>106</b>
<b>EAST VILLAGE RDA (535-353-08)</b>	<b>318 9TH AVE</b>	<b>17</b>	<b>130</b>
<b>SOUTHWEST MARINE HARDWARE</b>	<b>944 K ST</b>	<b>21</b>	<b>250</b>
<b>SAN DIEGO TRANSIT CORP</b>	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>CALIFORNIA LINEN SUPPLY</b>	<b>101 16TH ST</b>	<b>24</b>	<b>304</b>
<b>SAN DIEGO EXPRESS</b>	<b>229 16TH ST</b>	<b>24</b>	<b>317</b>
<b>US SPRINT</b>	<b>1402 E K ST</b>	<b>25</b>	<b>326</b>
<b>KING TRANSPORTATION</b>	<b>1300 L ST</b>	<b>27</b>	<b>335</b>
<b>INTERSTATE BRANDS CORP.</b>	<b>1401 IMPERIAL AVE</b>	<b>28</b>	<b>341</b>
<b>CONTINENTAL BAKING CO</b>	<b>1304 IMPERIAL AVE</b>	<b>28</b>	<b>353</b>
<b>SQUIRES BELT MATERIAL</b>	<b>149 12TH AVE</b>	<b>28</b>	<b>359</b>
<b>SAN DIEGO VAN &amp; STORAGE CO</b>	<b>1944 COMMERCIAL ST</b>	<b>29</b>	<b>361</b>
<b>VITAGOLD COOPERATIVE ASSOC.</b>	<b>2121 IMPERIAL AVE</b>	<b>29</b>	<b>364</b>
<b>STANDARD MEAT CO INC</b>	<b>101 19TH ST</b>	<b>29</b>	<b>385</b>
<b>MARATHON LAND &amp; CATTLE</b>	<b>2682 IMPERIAL AVE</b>	<b>32</b>	<b>405</b>
<b>THRIFTY OIL STATION #96</b>	<b>2502 IMPERIAL AVE</b>	<b>34</b>	<b>424</b>
<b>ULTRACRAFT</b>	<b>9 17TH ST</b>	<b>35</b>	<b>433</b>
<b>EL GUERO TIRE SHOP</b>	<b>2401 IMPERIAL AVE</b>	<b>36</b>	<b>435</b>
<b>BILL ALLEN/ELMER'S AUTO</b>	<b>1902 NATIONAL AVE</b>	<b>37</b>	<b>462</b>
<b>MAURICIO AND SONS INC</b>	<b>1864 NATIONAL AVE</b>	<b>37</b>	<b>477</b>
<b>FRASER'S BOILER SERVICE, INC.</b>	<b>1746 NEWTON AVE</b>	<b>37</b>	<b>492</b>
<b>MOBIL SERVICE STATION</b>	<b>1879 LOGAN AVE</b>	<b>37</b>	<b>506</b>
<b>THE DIESEL CENTER</b>	<b>1792 NATIONAL AVE</b>	<b>37</b>	<b>527</b>
<b>TROPIC ICE CREAM</b>	<b>1776 NATIONAL AVE</b>	<b>37</b>	<b>533</b>
<b>LUBE EQUIPMENT &amp; PUMP SERVICE</b>	<b>1785 LOGAN AVE</b>	<b>37</b>	<b>557</b>
<b>SUNBELT DISTRIBUTING CHEMICAL</b>	<b>1625 NEWTON ST</b>	<b>37</b>	<b>590</b>
<b>RADFORD OVERHEAD DOORS INC</b>	<b>1659 NATIONAL AVE</b>	<b>37</b>	<b>639</b>
<b>CENTRAL MEAT &amp; PROVISION CO</b>	<b>1603 NATIONAL AVE</b>	<b>37</b>	<b>671</b>
<b>GRAYBILL TERMINALS CO</b>	<b>1531 NATIONAL AVE</b>	<b>37</b>	<b>681</b>
<b>RELIABLE PIPE SUPPLY</b>	<b>1430 NATIONAL AVE</b>	<b>37</b>	<b>713</b>
<b>HERTZ - PENSKE TRUCK LEASING</b>	<b>1402 COMMERCIAL ST</b>	<b>37</b>	<b>723</b>
<b>ST. VINCENT DEPAUL</b>	<b>16 15TH ST</b>	<b>37</b>	<b>732</b>
<b>SAINT VINCENT DE PAUL</b>	<b>1501 IMPERIAL AVE</b>	<b>37</b>	<b>739</b>
<b>SDUSD MAINTENANCE</b>	<b>1826 IRVING AVE</b>	<b>42</b>	<b>774</b>
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
<b>YOUNGS MARKET CO</b>	<b>1709 MAIN ST</b>	<b>53</b>	<b>831</b>
<b>JR GAS AND MINI MART</b>	<b>505 S 30TH ST</b>	<b>54</b>	<b>839</b>
<b>P&amp;L KNEPP TRUCKING</b>	<b>2001 MAIN ST</b>	<b>55</b>	<b>864</b>
<b>A O REED</b>	<b>1990 MAIN ST</b>	<b>55</b>	<b>885</b>
<b>TUNA CLIPPER MARINE</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>899</b>
<b>SANTA FE RAILWAY</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>920</b>
<b>A.E.P. CORP.</b>	<b>1901 MAIN ST</b>	<b>55</b>	<b>949</b>
<b>NEPTUNE OIL COMPANY</b>	<b>1950 NEWTON AVE</b>	<b>55</b>	<b>962</b>
<b>AVION DYNAMICS CORP</b>	<b>1827 MAIN STREET</b>	<b>55</b>	<b>974</b>
<b>SUPERIOR CRANE AND RIGGING</b>	<b>1779 MAIN ST</b>	<b>55</b>	<b>989</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>NORTH AMERICAN TERMINAL INC</b>	<b>1090 WATER ST</b>	<b>57</b>	<b>1003</b>
<b>PROLINE PAINTS AT0098</b>	<b>2647 MAIN ST</b>	<b>59</b>	<b>1022</b>
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
<b>IMS RECYCLING</b>	<b>2740 BOSTON AVE</b>	<b>59</b>	<b>1125</b>
<b>JVM SPA COVERS</b>	<b>2777 NEWTON AVE</b>	<b>59</b>	<b>1147</b>
<b>JESUS TRANSPORTATION</b>	<b>2691 NEWTON AVE</b>	<b>59</b>	<b>1168</b>
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
<b>KARVON ELECTRIC</b>	<b>2635 LOGAN AVE</b>	<b>59</b>	<b>1253</b>
<b>CITY OF S.D. PARKING LOT</b>	<b>2183 NATIONAL AVE</b>	<b>59</b>	<b>1265</b>
<b>FORMER PACIFIC MOLASSES SITE</b>	<b>1750 WATER ST</b>	<b>61</b>	<b>1312</b>
<b>BANDINI UNIOR HIGH SCHOOL</b>	<b>3550 LOGAN AVE</b>	<b>62</b>	<b>1317</b>
<b>CITY OF SAN DIEGO</b>	<b>2184 NEWTON AVE</b>	<b>63</b>	<b>1330</b>
<b>CARLSON AND BEAULOYE</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1330</b>
<b>CONTINENTAL MARITIME OF S D</b>	<b>1995 BAYFRONT ST</b>	<b>68</b>	<b>1389</b>
<b>SHREVE &amp; HAYS</b>	<b>2191 MAIN ST</b>	<b>69</b>	<b>1473</b>
<b>TANK #801 &amp; #802 *</b>	<b>2141 MAIN ST</b>	<b>69</b>	<b>1485</b>
<b>USA PETROLEUM STA. #50</b>	<b>3502 NATIONAL AVE</b>	<b>72</b>	<b>1527</b>
<b>AMERICAN FORKLIFT</b>	<b>3485 NATIONAL AVE</b>	<b>72</b>	<b>1534</b>
<b>CAL SOFT WATER SERVICE INC</b>	<b>3094 NATIONAL AVE</b>	<b>74</b>	<b>1558</b>
<b>FORMER FORNACA BAKERY</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1568</b>
<b>GAS QUIK</b>	<b>2865 NATIONAL AVE</b>	<b>77</b>	<b>1574</b>
<b>DORMANS TIRE CO</b>	<b>2385 MAIN ST</b>	<b>78</b>	<b>1580</b>
<b>SAN DIEGO EXPRESS INC</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1594</b>
<b>DORMAN/DAPPER TIRE</b>	<b>2301 MAIN ST</b>	<b>78</b>	<b>1600</b>
<b>SAN DIEGO MUSEUM OF ART</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1606</b>
<b>SOUTHWEST MARINE</b>	<b>1401 SAMPSON ST</b>	<b>79</b>	<b>1631</b>
<b>MERCK &amp; COMPANY</b>	<b>2145 E BELT ST</b>	<b>79</b>	<b>1649</b>
<b>SILVERGATE POWER PLANT</b>	<b>1348 SAMPSON ST</b>	<b>79</b>	<b>1674</b>
<b>S D UNIFIED PORT DIST AT0192</b>	<b>2025 BELT ST</b>	<b>79</b>	<b>1718</b>
<b>TEXACO REFINING &amp; MARKETING</b>	<b>1145 S 28TH ST</b>	<b>80</b>	<b>1734</b>
<b>ALCORN FENCE COMPANY DBA ATLAS</b>	<b>1211 S 32ND ST</b>	<b>83</b>	<b>1757</b>
<b>CHEVRON USA INC.</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1773</b>
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1794</b>
<b>ADVANCED SURFACE TECHNOLOGY</b>	<b>3134 MAIN ST</b>	<b>86</b>	<b>1826</b>
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
<b>THE SICKLES GROUP</b>	<b>2795 MAIN ST</b>	<b>88</b>	<b>1886</b>
<b>MARKEL OHNSON</b>	<b>2697 MAIN ST</b>	<b>88</b>	<b>1904</b>
<b>GIOLZETTI AND LULUE</b>	<b>2694 MAIN ST</b>	<b>88</b>	<b>1914</b>
<b>US COAST GUARD AIR STATION</b>	<b>2710 HARBOR DR</b>	<b>91</b>	<b>1936</b>
<b>BABYLAND DIAPER SERVICE</b>	<b>3348 MAIN ST</b>	<b>94</b>	<b>2013</b>
<b>PACIFIC SHIP REPAIR&amp; FABRICATI</b>	<b>1625 RIGEL STREET</b>	<b>94</b>	<b>2023</b>
<b>AMRICAN UNIFORM &amp; TOWEL SUPPLY</b>	<b>3440 MAIN ST</b>	<b>101</b>	<b>2158</b>
<b>AMERICAN LINEN SUPPLY</b>	<b>3410 S MAIN ST</b>	<b>101</b>	<b>2170</b>
<b>SUNDANCE STAGE LINES INC</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2189</b>
<b>HIGH GEAR TRANSMISSION &amp; AUTO</b>	<b>3683 DALBERGIA ST</b>	<b>104</b>	<b>2312</b>
<b>ARATEX SERVICES INC.</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2400</b>
<b>GENERAL DYNAMICS CONVAIR</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2418</b>
<b>NATIONAL MOBIL SERVICE STATION</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2450</b>
<b>DIVISION SHELL SERVICE</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2470</b>
<b>THRIFTY #103</b>	<b>801 ROOSEVELT AVE</b>	<b>114</b>	<b>2491</b>

## EXECUTIVE SUMMARY

**CHMIRS:** The California Hazardous Material Incident Report System contains information on reported hazardous material incidents, i.e., accidental releases or spills. The source is the California Office of Emergency Services.

A review of the CHMIRS list, as provided by EDR, and dated 12/31/2005 has revealed that there are 38 CHMIRS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
Not reported	1023 SIGSBEE	37	567
Not reported	1680 LOGAN AVENUE	37	665
Date Completed: 09-OCT-91			
Not reported	1444 CROSBY ST.	55	906
Date Completed: 20-JAN-89			
<b>SANTA FE INTERMODAL</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>908</b>
Not reported	2646 MAIN ST.	59	1068
Date Completed: 05-SEP-89			
Not reported	2635 BOSTON AV	59	1105
Date Completed: 28-MAR-88			
Not reported	2156 NATIONAL AV	59	1270
Not reported	2171 LOGAN AV	59	1291
Not reported	2159 LOGAN AVE.	59	1292
Not reported	2154 LOGAN AVENUE	59	1294
Not reported	2186 NEWTON ST	63	1327
Date Completed: 04-FEB-88			
<b>CORROSION ENGN SVC, INC.</b>	<b>1995 BAY FRONT ST</b>	<b>68</b>	<b>1384</b>
Not reported	2040 E. HARBOR DR.	68	1442
Not reported	1100 SICARD (IN ALLEY)	78	1614
Date Completed: 21-JAN-88			
<b>Not reported</b>	<b>2295 BELT STREET</b>	<b>79</b>	<b>1615</b>
Date Completed: 11-FEB-90			
<b>Not reported</b>	<b>2145 EAST BELT STREET</b>	<b>79</b>	<b>1655</b>
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAY FRONT STREET</b>	<b>79</b>	<b>1682</b>
Not reported	2851 BOSTON AVE	82	1745
Not reported	N/B I-5 AT I-15	85	1817
Date Completed: 13-DEC-88			
Not reported	3150 MAIN ST.	86	1824
Not reported	1345 S. 27TH ST.	88	1871
Not reported	1300 SOUTH 28TH STREET	88	1885
<b>Not reported</b>	<b>HARBOR DRIVE AND 28TH S</b>	<b>92</b>	<b>1953</b>
Not reported	28TH ST / HARBOR DR, BE	92	1956
Not reported	HARBOR DRIVE / 28TH S	92	1958
<b>NATIONAL STEEL AND SHIPBUILDIN</b>	<b>2798 EAST HARBOR DRIVE</b>	<b>92</b>	<b>1959</b>
Not reported	28TH ST / HARBOR DR	92	1969
Not reported	2800 HARBOR DRIVE	92	1972
Date Completed: 01-JUN-91			
Not reported	2798 HARBOR DR.	92	1977
Not reported	2798 HARBOR DRIVE	92	1981
Not reported	28TH / HARBOR	92	1990
<b>NASSCO SHIPYARD</b>	<b>2798 HARBOR DR</b>	<b>92</b>	<b>1991</b>
Not reported	2798 HARBOR DR.	92	1998
Not reported	NASSCO SHIP YARD 2798 H	92	2002
<b>FRASER'S BOILER SERV INC @ NAV</b>	<b>32ND ST NAVAL STATION</b>	<b>98</b>	<b>2060</b>
Not reported	3713 DALVERGIA ST.	104	2292
<b>USNAVY EXCHANGE SERVICE STATIO</b>	<b>32ND &amp; HARBOR DR NAVAL</b>	<b>106</b>	<b>2427</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<i>Not reported</i>	<b>1211 MCKINLEY AVE</b>	<b>117</b>	<b>2553</b>

**Notify 65:** Notify 65 records contain facility notifications about any release that could impact drinking water and thereby expose the public to a potential health risk. The data come from the State Water Resources Control Board's Proposition 65 database.

A review of the Notify 65 list, as provided by EDR, and dated 10/21/1993 has revealed that there are 24 Notify 65 sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
Not reported	1110 "C" STREET	1	3
Not reported	1110 "C" STREET	1	3
Not reported	1110 "C" STREET	1	3
Not reported	11TH / "C" STREET	1	4
Not reported	15TH / BROADWAY	2	4
Not reported	15TH / BROADWAY	2	4
Not reported	515 27TH STREET	13	86
Not reported	333 24TH ST	22	275
Not reported	2682 IMPERIAL AVENUE	32	407
Not reported	1025 SIGSBEE ST.	37	561
Not reported	1640 NEWTON AVE	37	569
Not reported	1702 NATIONAL AVE	37	573
Not reported	3758 GILLET ST.	38	752
28TH AND WEBSTER AVENUE		47	800
Not reported	3020 WEBSTER.	48	800
SUN ROAD MARINA	955 HARBOR DR	49	804
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
Not reported	920 SO. 33RD ST.	67	1373
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
ON GROUND	3654 BETA ST	95	2057
<b>FRASER'S BOILER SERV INC @ NAV</b>	<b>32ND ST NAVAL STATION</b>	<b>98</b>	<b>2060</b>
24TH ST MARINE TERMINAL	FOOT OF 24TH ST	98	2065
PUMP STATION 2	PUMP STATION 2	101	2114
<b>NATIONAL LINEN SERVICE</b>	<b>3410 MAIN STREET</b>	<b>101</b>	<b>2169</b>

**VCP:** Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

A review of the VCP list, as provided by EDR, and dated 02/26/2008 has revealed that there is 1 VCP site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>STUDIO 15</b>	<b>70 15TH STREET</b>	<b>37</b>	<b>745</b>

## EXECUTIVE SUMMARY

**DRYCLEANERS:** A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaners' agents; linen supply; coin-operated laundries and cleaning; drycleaning plants except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

A review of the DRYCLEANERS list, as provided by EDR, and dated 07/31/2007 has revealed that there are 7 DRYCLEANERS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>CARLOS CLEANERS</b>	<b>1694 NATIONAL AVE</b>	<b>37</b>	<b>587</b>
<b>CARLOS CLEANERS</b>	<b>1686 NATIONAL AVE</b>	<b>37</b>	<b>607</b>
<b>CALIFORNIA CARPET CLEANERS INT</b>	<b>3356 NATIONAL AVE</b>	<b>71</b>	<b>1503</b>
<b>L C EMBROIDERY &amp; CLEANERS</b>	<b>3280 MAIN ST STE 6</b>	<b>93</b>	<b>2007</b>
<b>AMERICAN LINEN SUPPLY</b>	<b>3410 MAIN ST</b>	<b>101</b>	<b>2164</b>
<b>ARAMARK UNIFORM SERVICE INC</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2388</b>
<b>ARATEX SERVICES INC.</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2400</b>

**WIP:** Well Investigation Program case in the San Gabriel and San Fernando Valley area.

A review of the WIP list, as provided by EDR, and dated 02/26/2008 has revealed that there is 1 WIP site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>INTERSTATE BRANDS CORPORATION</b> Facility Status: Historical	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>

**San Diego Co. HMMD:** The Hazardous Materials Management Division Database comes from the Hazardous Materials Management Division.

A review of the San Diego Co. HMMD list, as provided by EDR, and dated 05/16/2005 has revealed that there are 355 San Diego Co. HMMD sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
<b>SHELL OIL PRODUCTS COMPANY</b>	<b>1619 G ST</b>	<b>5</b>	<b>16</b>
<b>HAWTHORNE RENT-IT SERVICE</b>	<b>1473 G ST</b>	<b>6</b>	<b>27</b>
<b>ROAD RUNNERS</b>	<b>544 11TH AV</b>	<b>8</b>	<b>42</b>
<b>YELLOW CAB CO OF SAN DIEGO INC</b>	<b>639 13TH ST</b>	<b>8</b>	<b>52</b>
<b>UNOCAL SERV STN #0364-30319</b>	<b>1606 MARKET ST</b>	<b>10</b>	<b>70</b>
<b>ADT PROPERTY HOLDINGS INC</b>	<b>1416 MARKET ST</b>	<b>11</b>	<b>80</b>
<b>ECONO AUTO REPAIR/GAS</b>	<b>400 16TH ST</b>	<b>15</b>	<b>88</b>
<b>VICTOR'S USED TIRES</b>	<b>405 16TH ST</b>	<b>15</b>	<b>106</b>
<b>MOTOR WORKS INC</b>	<b>1490 ISLAND AV</b>	<b>15</b>	<b>111</b>
<b>ARCWELL CORP</b>	<b>510 16TH STREET</b>	<b>15</b>	<b>117</b>
<b>SHERMAN HEIGHTS FAMILY HLTH CT</b>	<b>450 24TH ST</b>	<b>16</b>	<b>126</b>
<b>MONTERREY PROVISION CO INC</b>	<b>318 09TH AV</b>	<b>17</b>	<b>131</b>
<b>DONEV COMPANY</b>	<b>441 10TH AV</b>	<b>17</b>	<b>142</b>
<b>CONTINENTAL CLEANERS</b>	<b>450 10TH AV</b>	<b>17</b>	<b>146</b>
<b>ALLAN COMPANY</b>	<b>415 14TH ST</b>	<b>19</b>	<b>153</b>
<b>SDGE STA A BL 148 FUELING FAC</b>	<b>114 10TH AV</b>	<b>21</b>	<b>159</b>
<b>EAST VILLAGE RDA</b>	<b>200 10TH AV</b>	<b>21</b>	<b>171</b>
<b>SDG&amp;E/STATION A BLOCK 135</b>	<b>250 10TH AV</b>	<b>21</b>	<b>241</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SOUTHWEST MARINE HARDWARE</b>	<b>944 K ST</b>	<b>21</b>	<b>250</b>
<b>ATLAS FIRE EQUIPMENT CO</b>	<b>312 11TH AV</b>	<b>21</b>	<b>256</b>
<b>A.W. COGGESHALL</b>	<b>354 11TH AV</b>	<b>21</b>	<b>270</b>
<b>SAN DIEGO TRANSIT CORP</b>	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>BREITBARD PROPERTIES LLC</b>	<b>101 16TH ST</b>	<b>24</b>	<b>310</b>
<b>SAN DIEGO EXPRESS</b>	<b>229 16TH ST</b>	<b>24</b>	<b>317</b>
<b>FRED'S AUTO BODY &amp; PAINT</b>	<b>301 16TH ST</b>	<b>24</b>	<b>319</b>
<b>ROY'S AUTO REPAIR</b>	<b>301 16TH ST</b>	<b>24</b>	<b>322</b>
<b>COTINENTAL BAKING COMP</b>	<b>171 14TH ST</b>	<b>27</b>	<b>327</b>
<b>KING TRANSPORTATION</b>	<b>1300 L ST</b>	<b>27</b>	<b>335</b>
<b>INTERSTATE BRANDS CORP.</b>	<b>1401 IMPERIAL AV</b>	<b>28</b>	<b>342</b>
<b>METROPOLITAN TRANSIT DEV BOARD</b>	<b>1255 IMPERIAL AV</b>	<b>28</b>	<b>348</b>
<b>SQUIRES BELT MATERIAL CO</b>	<b>149 12TH AV</b>	<b>28</b>	<b>355</b>
<b>SAN DIEGO VAN &amp; STORAGE CO</b>	<b>1944 COMMERCIAL ST</b>	<b>29</b>	<b>361</b>
<b>VITAGOLD BRANDS COOP AT0726</b>	<b>2121 IMPERIAL AV</b>	<b>29</b>	<b>366</b>
<b>NATIONAL BRAKE SERVICE INC</b>	<b>2040 IMPERIAL AVE</b>	<b>29</b>	<b>369</b>
<b>FIRST CHOICE</b>	<b>24 21ST ST</b>	<b>29</b>	<b>382</b>
<b>STANDARD MEAT CO INC</b>	<b>101 19TH ST</b>	<b>29</b>	<b>385</b>
<b>CITY OF SAN DIEGO</b>	<b>800 HARBOR DR</b>	<b>30</b>	<b>387</b>
<b>MTDB LEASEHOLD</b>	<b>93 08TH AV</b>	<b>30</b>	<b>390</b>
<b>PLANT PRODUCTS &amp; SUPPLY CO</b>	<b>822 IMPERIAL AV</b>	<b>30</b>	<b>394</b>
<b>CITY OF SAN DIEGO</b>	<b>800 IMPERIAL AV</b>	<b>30</b>	<b>399</b>
<b>MARATHON LAND &amp; CATILE</b>	<b>2682 IMPERIAL AV</b>	<b>32</b>	<b>407</b>
<b>IMPERIAL AVENUE APARTMENTS</b>	<b>2701 IMPERIAL AV</b>	<b>32</b>	<b>410</b>
<b>ARCO FACILITY NO. 9560</b>	<b>2502 IMPERIAL AV</b>	<b>34</b>	<b>419</b>
<b>ULTRACRAFT</b>	<b>9 17TH ST</b>	<b>35</b>	<b>433</b>
<b>EL GUERO TIRE SHOP &amp; REPAIR</b>	<b>2401 IMPERIAL AV</b>	<b>36</b>	<b>436</b>
<b>NO NAME-FOUND ON TOP OF FILES</b>	<b>1955 NATIONAL AV</b>	<b>37</b>	<b>442</b>
<b>M &amp; M RECYCLING</b>	<b>1937 NATIONAL AV</b>	<b>37</b>	<b>444</b>
<b>ELMERS FOREIGN AUTO WRECKING</b>	<b>1935 NATIONAL AVE</b>	<b>37</b>	<b>445</b>
<b>ASTRO PAK</b>	<b>1936 NATIONAL AV</b>	<b>37</b>	<b>448</b>
<b>PETROLEUM RECYCLING CORP</b>	<b>1921 NATIONAL AV</b>	<b>37</b>	<b>455</b>
<b>GEORGE GONZALEZ</b>	<b>1902 NATIONAL AV</b>	<b>37</b>	<b>466</b>
<b>C/C WELDING</b>	<b>1901 NATIONAL AV</b>	<b>37</b>	<b>470</b>
<b>A &amp; D AUTOBODY AND FRAME</b>	<b>1868 NATIONAL AV</b>	<b>37</b>	<b>472</b>
<b>URBAN CORPS OF SAN DIEGO</b>	<b>1864 NATIONAL AV</b>	<b>37</b>	<b>473</b>
<b>ACE RADIATOR</b>	<b>1854 NATIONAL AVE</b>	<b>37</b>	<b>478</b>
<b>RICARDO'S FLEET SERVICE</b>	<b>1841 NATIONAL AV</b>	<b>37</b>	<b>484</b>
<b>ACE RADIATOR SERVICE</b>	<b>1836 NATIONAL AV</b>	<b>37</b>	<b>487</b>
<b>FRASER'S BOILER SERVICE, INC.</b>	<b>1746 NEWTON AV</b>	<b>37</b>	<b>493</b>
<b>D'ARCH ENTERPRISES</b>	<b>1879 LOGAN AV</b>	<b>37</b>	<b>500</b>
<b>CROSBY SQUARE CHIROPRACTIC</b>	<b>1879 LOGAN AV</b>	<b>37</b>	<b>505</b>
<b>LOGAN HEIGHTS FAMILY HEALTH CT</b>	<b>1809 NATIONAL AV</b>	<b>37</b>	<b>510</b>
<b>TRIAD ENVIRONMENTAL SYSTEMS</b>	<b>1775 NATIONAL AVENUE</b>	<b>37</b>	<b>517</b>
<b>TRIAD ENVIRONMENTAL SYSTEMS</b>	<b>1775 NATIONAL AV</b>	<b>37</b>	<b>520</b>
<b>YE OLDE TOWN PUMP</b>	<b>1792 NATIONAL AV</b>	<b>37</b>	<b>522</b>
<b>TROPIC ICE CREAM CO</b>	<b>1776 NATIONAL AV</b>	<b>37</b>	<b>529</b>
<b>CEMENT CUTTING INC</b>	<b>1845 LOGAN AV</b>	<b>37</b>	<b>535</b>
<b>MINI TRUCK</b>	<b>1700 NEWTON AV</b>	<b>37</b>	<b>539</b>
<b>KAMAN INDUSTRIAL TECHNOLOGIES</b>	<b>1675 NEWTON AV</b>	<b>37</b>	<b>548</b>
<b>BEECO SAN DIEGO AUTO RECYCLING</b>	<b>1674 NEWTON AV</b>	<b>37</b>	<b>550</b>
<b>FRASERS BOILER</b>	<b>1735 NATIONAL AV</b>	<b>37</b>	<b>552</b>
<b>NORTHWEST PUMP &amp; EQUIPMENT SER</b>	<b>1785 LOGAN AV</b>	<b>37</b>	<b>555</b>
<b>LUBE EQUIPMENT &amp; PUMP SERVICE</b>	<b>1785 LOGAN AV</b>	<b>37</b>	<b>559</b>
<b>GEORGES TRANSMISSION</b>	<b>1025 SIGSBEE ST</b>	<b>37</b>	<b>561</b>
<b>ACME AUTO BODY</b>	<b>1025 SIGSBEE ST</b>	<b>37</b>	<b>566</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
NATIONAL TRANSMISSION	1709 NATIONAL AV	37	569
SUPER WELDING OF SO. CA INC.	1702 NATIONAL AV	37	575
<b>SAN DIEGO SAW AND KNIFE WORKS</b>	<b>1765 LOGAN AVE</b>	<b>37</b>	<b>578</b>
BARRETT ENGINEERED PUMPS	1695 NATIONAL AV	37	587
SUNBELT CHEMICAL	1625 NEWTON AV	37	592
ROBERT & GAIL LICHTER	1625 NEWTON AV	37	594
<b>ACTION CLEANING CORP</b>	<b>1620 NEWTON AV</b>	<b>37</b>	<b>596</b>
CARLOS CLEANERS	1686 NATIONAL AV	37	609
MARINE & RESTAURANT FABRICATOR	1616 NEWTON AV	37	613
<b>ACTION CLEANING</b>	<b>1604 NEWTON AV</b>	<b>37</b>	<b>618</b>
MARTINEZ GARAGE & TOWING	1604 NEWTON AV	37	623
SAN DIEGO TROLLEY	1601 NEWTON AV	37	625
<b>CENTER CITY TOWING</b>	<b>1668 NATIONAL AV</b>	<b>37</b>	<b>634</b>
YALE COMBS	1668 NATIONAL AV	37	638
RADFORD OVERHEAD DOORS INC	1659 NATIONAL AV	37	640
REFRIGERATION SUPPLIES DIST	1721 LOGAN AV	37	641
SUNBELT DISTRIBUTING	1712 LOGAN AV	37	644
<b>SAN DIEGO TROLLEY, INC</b>	<b>1535 NEWTON AV</b>	<b>37</b>	<b>650</b>
HILL BROTHERS CHEMICAL CO	1680 LOGAN AV	37	661
QUALITY REFRIGERATION CO, INC	1680 LOGAN AV	37	666
CLEANING DYNAMICS COMPANY	1606 NATIONAL AV	37	668
<b>CENTRAL MEAT &amp; PROVISION CO</b>	<b>1603 NATIONAL AVE</b>	<b>37</b>	<b>671</b>
<b>GRAYBILL TERMINALS CO</b>	<b>1531 NATIONAL AV</b>	<b>37</b>	<b>676</b>
TEEN HEALTH CENTER	1643 LOGAN AV	37	685
HUGHES ATTORNEY SERVICE INC	1643 LOGAN AV	37	687
QUALITY CABINET & FIXTURES CO	939 S 16TH ST	37	693
<b>PEPPER INDUSTRIES INC</b>	<b>1501 NATIONAL AVE</b>	<b>37</b>	<b>695</b>
HENRYS TRANSMISSION SHOP	1603 LOGAN AV	37	699
AMERICAN & FOREIGN AUTO RECYCL	1615 LOGAN AV	37	705
<b>RELIABLE PIPE SUPPLY</b>	<b>1430 NATIONAL AV</b>	<b>37</b>	<b>707</b>
<b>PENSKE TRUCK LEASING INC</b>	<b>1402 COMMERCIAL ST</b>	<b>37</b>	<b>714</b>
<b>G E O AUTO DISMANTLING</b>	<b>1610 COMMERCIAL ST</b>	<b>37</b>	<b>725</b>
<b>ST. VINCENT DEPAUL</b>	<b>16 15TH ST</b>	<b>37</b>	<b>732</b>
<b>SAINT VINCENT DE PAUL</b>	<b>1501 IMPERIAL AV</b>	<b>37</b>	<b>740</b>
<b>CATELLUS DEVELOPMENT PROPERTY</b>	<b>702 HARBOR DR</b>	<b>39</b>	<b>752</b>
<b>EL DORADO SANDBLASTING CO</b>	<b>2694 COMMERCIAL ST</b>	<b>40</b>	<b>759</b>
<b>ELDORADO SAND BLASTING</b>	<b>2675 COMMERCIAL ST</b>	<b>40</b>	<b>767</b>
<b>SDUSD - MAINTENANCE</b>	<b>1826 IRVING AV</b>	<b>42</b>	<b>778</b>
<b>SD PORT DISTRICT MAINT DEPT</b>	<b>825 E HARBOR DR</b>	<b>45</b>	<b>790</b>
<b>RALSTON PURINA/VAN CAMP</b>	<b>1025 E HARBOR DR</b>	<b>49</b>	<b>800</b>
<b>DANNYS PAINT &amp; BODY SHOP</b>	<b>1866 KEARNEY AVENUE</b>	<b>50</b>	<b>804</b>
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
<b>YOUNGS MARKET CO</b>	<b>1709 MAIN ST</b>	<b>53</b>	<b>831</b>
<b>JR GAS AND MINI MART</b>	<b>505 S 30TH ST</b>	<b>54</b>	<b>839</b>
ADVANCE DIESEL INJECTION INC	2049 MAIN ST	55	850
<b>PERFORMANCE CONTRACTING GROUP</b>	<b>2015 MAIN ST</b>	<b>55</b>	<b>851</b>
LOOMIS MAINTENANCE GARAGE	2007 MAIN ST	55	855
NATIONAL PETROLEUM,INC	2005 MAIN ST	55	857
<b>P&amp;L KNEPP TRUCKING</b>	<b>2001 MAIN ST</b>	<b>55</b>	<b>864</b>
TUM YETO, INC	1995 MAIN ST	55	878
<b>RANKIN INDUSTRIES INC</b>	<b>1991 MAIN ST</b>	<b>55</b>	<b>880</b>
<b>A O REED</b>	<b>1990 MAIN ST</b>	<b>55</b>	<b>885</b>
OIL FILTER SERVICE INC	1987 MAIN ST	55	889
UNION ELECTRIC MOTOR SERVICE	2046 NEWTON AV	55	890
<b>SDG &amp; E</b>	<b>2043 NEWTON AV</b>	<b>55</b>	<b>893</b>
MARINE PUMP SERVICE	1977 MAIN ST	55	896

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
CORROSION ENGRG,POWDER COATING	1444 CROSBY ST	55	904
<b>SANTA FE INTERMODAL</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>908</b>
ACME AWING & CANVUS COMPANY	1961 MAIN ST	55	925
ABREST WELDING AND FABRICATION	1212 CROSBY ST	55	927
CROSBY ST CORRIDOR	1200 CROSBY ST	55	929
KIB MOTORS	1950 MAIN ST	55	930
<b>MERCADO COMMERCIAL CENTER</b>	<b>1920 MAIN ST</b>	<b>55</b>	<b>934</b>
CALTRANS/CORONADO BRIDGE	1995 NEWTON ST	55	937
<b>NATIONAL PUMP &amp; INJECTOR</b>	<b>1901 MAIN ST</b>	<b>55</b>	<b>945</b>
<b>A.E.P. CORP.</b>	<b>1901 MAIN ST</b>	<b>55</b>	<b>949</b>
CHAMPION CONSTRUCTION CO.	1969 NEWTON AV	55	954
NO NAME-FOUND ON TOP OF FILES	1960 NEWTON AV	55	956
LUNA TRANSMISSIONS	1957 NEWTON AV	55	958
NEPTUNE OIL COMPANY	1950 NEWTON AV	55	961
<b>ROMANS TRUCKING PAINTING</b>	<b>1941 NEWTON AVE</b>	<b>55</b>	<b>963</b>
<b>JOHNSON TRUCK REPAIR &amp; PAINT</b>	<b>1931 NEWTON AV</b>	<b>55</b>	<b>968</b>
CENTER CITY TOWING	1911 NEWTON AV	55	971
<b>EMM, ELECTRICAL MOTOR MACHINE</b>	<b>1837 MAIN ST</b>	<b>55</b>	<b>972</b>
<b>AVION DYNAMICS CORP</b>	<b>1827 MAIN STREET</b>	<b>55</b>	<b>974</b>
CALIFORNIA WATER CONDITIONING	1884 NEWTON AV	55	978
<b>QUALITY REFRIGERATION CO.</b>	<b>1815 MAIN ST</b>	<b>55</b>	<b>980</b>
<b>FRYER KNOWLES INC</b>	<b>1858 NEWTON AVE</b>	<b>55</b>	<b>983</b>
<b>SUPERIOR CRANE AND RIGGING</b>	<b>1779 MAIN ST</b>	<b>55</b>	<b>989</b>
WEST MARINE DIESEL	1835 NEWTON AV	55	993
SAN DIEGO EXPRESS PRINTING	1805 NEWTON AV	55	995
<b>NORTH AMERICAN TERMINAL INC</b>	<b>1090 WATER ST</b>	<b>57</b>	<b>1003</b>
NANDO'S GARAGE	2078 LOGAN AV	58	1014
SANDEZ ORNAMENTAL IRON WORKS	2060 LOGAN AV	58	1016
<b>OIL FILTER SERVICE, INC.</b>	<b>2636 MAIN ST</b>	<b>59</b>	<b>1020</b>
<b>PROLINE PAINTS AT0098</b>	<b>2647 MAIN ST</b>	<b>59</b>	<b>1022</b>
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
SHERWIN-WILLIAMS - STORE# 8227	2640 MAIN ST	59	1091
<b>EPSILON AIR CONDITIONING &amp; REF</b>	<b>2640 MAIN ST</b>	<b>59</b>	<b>1094</b>
JONES STUDIO	2602 MAIN ST	59	1097
WESTERN BAY SHEET METAL/MARINE	1221 S 26TH ST	59	1099
SAN DIEGO HOUSING COMMISSION	2650 BOSTON AV	59	1102
BELAIR CORP	2645 BOSTON ST	59	1103
SAN DIEGO HOUSING COMMISSION	2627 BOSTON AV	59	1106
ANDYS A&R	2627 BOSTON AV	59	1108
BAY DECKING COMPANY INC	2685 BOSTON ST	59	1112
WESTECH	2675 BOSTON AV	59	1114
TARANTINO WHOLESALE FOODS	2707 BOSTON AV	59	1116
ASTON AUTO CENTRE	2727 BOSTON AV	59	1118
<b>I M S RECYCLING SVC IRON DEPT</b>	<b>2740 BOSTON AV</b>	<b>59</b>	<b>1121</b>
<b>IMS RECYCLING</b>	<b>2740 BOSTON AVE</b>	<b>59</b>	<b>1125</b>
<b>SAN DIEGO TRANSMISSION</b>	<b>1127 S 27TH ST</b>	<b>59</b>	<b>1127</b>
<b>ADVANCED WOOD FINISHING</b>	<b>1127 S 27TH ST</b>	<b>59</b>	<b>1132</b>
<b>MEDLAND CONTROLS INC</b>	<b>2393 NEWTON AV</b>	<b>59</b>	<b>1134</b>
ALLIED REFRIGERATION INC	2393 NEWTON AV	59	1138
<b>UNION ELECTRIC MOTOR SERVICE</b>	<b>2777 NEWTON AV</b>	<b>59</b>	<b>1142</b>
<b>IMS RECYCLING SERVICES</b>	<b>2731 NEWTON AV</b>	<b>59</b>	<b>1151</b>
PACIFIC PEBBLES	2709 NEWTON AV	59	1157
FARRELL COURIER SERVICE INC	2691 NEWTON AV	59	1162
J&J AUTO BODY	2691 NEWTON AV	59	1164
CANDY'S AUTO BODY LLC	2691 NEWTON AV	59	1169
HOWELL SERVICE	2681 NEWTON AV	59	1170



## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
HYTECH METAL FORMING	2676 NEWTON AV	59	1172
GARCIA AUTO REPAIR	2340 NEWTON AV	59	1175
<b>FORDS &amp; FOREIGN AUTO PARTS</b>	<b>2335 NEWTON AV</b>	<b>59</b>	<b>1179</b>
<b>BARRIO STATION INC</b>	<b>2320 NEWTON AV</b>	<b>59</b>	<b>1185</b>
<b>NORTH STAR PROPELLERS, INC</b>	<b>2317 NEWTON AV</b>	<b>59</b>	<b>1189</b>
<b>NORTH STAR PROPELLERS INC.</b>	<b>2285 NEWTON AV</b>	<b>59</b>	<b>1194</b>
SICARD AUTO REPAIR	1025 SICARD ST	59	1204
<b>ADVANCED METAL FORMING, INC.</b>	<b>2618 NATIONAL AV</b>	<b>59</b>	<b>1206</b>
L & M SAW WORKS INC	2670 NATIONAL AV	59	1210
HANSSON INDUSTRIAL & TRUCK	2619 NATIONAL AV	59	1211
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
LUIS COMANJA AUTO SERVICE	2295 NATIONAL AV	59	1222
WESTERN STEEL	2292 NATIONAL AV	59	1224
ANGELS AUTO REPAIR	2276 NATIONAL AV	59	1228
ALL WRENCH AUTO	925 S 26TH ST	59	1230
<b>ACE MUFFLER SHOP</b>	<b>2260 NATIONAL AV</b>	<b>59</b>	<b>1231</b>
PROPULSION CONTROLS ENGRG	2255 NATIONAL AV	59	1236
B & C MARINE ENTERPRISE	2255 NATIONAL AV	59	1243
R & R AUTO TECH	2243 NATIONAL AV	59	1247
RESTORE AUTO BODY	2243 NATIONAL AV	59	1250
<b>SAN DIEGO EXPRESS</b>	<b>2635 LOGON ST</b>	<b>59</b>	<b>1254</b>
<b>SAN DIEGO AUTO EXPERT</b>	<b>2602 LOGAN AV</b>	<b>59</b>	<b>1258</b>
TANAKA MEDICAL CLINIC INC	2204 NATIONAL AV	59	1260
<b>CALIFORNIA METAL FORMING</b>	<b>2183 NATIONAL AV</b>	<b>59</b>	<b>1262</b>
PORT MEDICAL SERVICE,S.D.	2169 NATIONAL AV	59	1268
TREJO TOWING	2250 LOGAN AV	59	1271
RC AUTO ELECTRIC	2250 LOGAN AV	59	1273
PORKYLAND	2196 LOGAN AV	59	1278
AZTEC STEEL FABRICATORS	2183 LOGAN AV	59	1280
MAGANA AUTOMATIC TRANSMISSIONS	2134 NATIONAL AV	59	1281
DIEGO AND SON PRINTING	2104 NATIONAL AV	59	1285
<b>FREIGHT HANDLERS INC</b>	<b>1790 WATER ST</b>	<b>61</b>	<b>1308</b>
<b>FORMER PACIFIC MOLASSES SITE</b>	<b>1750 WATER ST</b>	<b>61</b>	<b>1312</b>
<b>S D UNIFIED SCHOOL DISTRICT</b>	<b>3550 LOGAN AV</b>	<b>62</b>	<b>1314</b>
<b>PRAXAIR DISTRIBUTION INC.</b>	<b>2205 NEWTON AV</b>	<b>63</b>	<b>1319</b>
CITY OF SAN DIEGO	2184 NEWTON AV	63	1328
<b>CARLSON &amp; BEAULOYE MACHINE SHO</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1332</b>
TRIMM WOODWORKING, INC	2130 NEWTON AV	63	1346
<b>MASTER PLATING</b>	<b>2109 NEWTON AVE</b>	<b>63</b>	<b>1354</b>
<b>CALIFORNIA MARINE CLEANING INC</b>	<b>905 S 33RD ST</b>	<b>67</b>	<b>1373</b>
<b>CORROSION ENGRG SVC, INC.</b>	<b>1995 BAY FRONT ST</b>	<b>68</b>	<b>1384</b>
<b>CONTINENTAL MARITIME OF S D</b>	<b>1995 BAYFRONT ST</b>	<b>68</b>	<b>1389</b>
<b>CP KELCO</b>	<b>2025 HARBOR DR</b>	<b>68</b>	<b>1414</b>
SUNSHINE TRUCK WORKS	2191 MAIN ST	69	1444
COMMERCIAL FLEET SERVICES	2191 MAIN ST	69	1445
CAR CONNECTION 2	2191 MAIN ST	69	1447
<b>GJS WAREHOUSE</b>	<b>2191 MAIN ST</b>	<b>69</b>	<b>1459</b>
<b>AMERICAN KELP</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1468</b>
COMMERCIAL FLEET SERVICE	2191 MAIN ST	69	1472
<b>SHREVE &amp; HAYS</b>	<b>2191 MAIN ST</b>	<b>69</b>	<b>1473</b>
<b>E.J. FERGUSON'S</b>	<b>2146 MAIN ST</b>	<b>69</b>	<b>1479</b>
<b>TANK #801 &amp; #802 *</b>	<b>2141 MAIN ST</b>	<b>69</b>	<b>1485</b>
<b>EARL INDUSTRIES, LLC</b>	<b>2102 MAIN ST</b>	<b>69</b>	<b>1493</b>
<b>PORT OF SAN DIEGO</b>	<b>1875 WATER ST</b>	<b>70</b>	<b>1498</b>
<b>COOL RADIATOR SHOP</b>	<b>3362 NATIONAL AVE</b>	<b>71</b>	<b>1504</b>
<b>SUNSHINE TRUCK WORKS</b>	<b>3361 NATIONAL AVE</b>	<b>71</b>	<b>1508</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>MARTINEZ AUTO REPAIR</b>	<b>3369 NATIONAL AV</b>	<b>71</b>	<b>1511</b>
<b>USA GASOLINE CORP #50</b>	<b>3502 NATIONAL AV</b>	<b>72</b>	<b>1516</b>
<b>AMERICAN FORKLIFT/J MAGRE</b>	<b>3485 NATIONAL AV</b>	<b>72</b>	<b>1529</b>
<b>GENERAL AUTO REPAIR</b>	<b>3451 NATIONAL AV</b>	<b>72</b>	<b>1536</b>
<b>SOUTHERN CALIFORNIA PLATING CO</b>	<b>3261 NATIONAL AV</b>	<b>73</b>	<b>1543</b>
<b>CAL SOFT WATER SERVICE INC</b>	<b>3094 NATIONAL AVE</b>	<b>74</b>	<b>1558</b>
<b>HOLSUM BAKING CO</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1570</b>
<b>AUTOZONE #5674</b>	<b>2865 NATIONAL AV</b>	<b>77</b>	<b>1576</b>
<b>DORMANS TIRE CO</b>	<b>2385 MAIN ST</b>	<b>78</b>	<b>1580</b>
<b>AMERICAN RIGGING &amp; SUPPLY CO</b>	<b>2380 MAIN ST</b>	<b>78</b>	<b>1583</b>
<b>SAN DIEGO EXPRESS INC</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1594</b>
<b>DORMAN/DAPPER TIRE</b>	<b>2301 MAIN ST</b>	<b>78</b>	<b>1600</b>
<b>SOUTHWEST MARINE</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1602</b>
<b>SAN DIEGO MUSEUM OF ART</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1606</b>
<b>SOUTHWEST MARINE</b>	<b>1401 SAMPSON ST</b>	<b>79</b>	<b>1631</b>
<b>SILVERGATE POWER PLANT</b>	<b>1348 SAMPSON ST</b>	<b>79</b>	<b>1674</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>S D UNIFIED PORT DIST AT0192</b>	<b>2025 BELT ST</b>	<b>79</b>	<b>1718</b>
<b>TEXACO MARKETING</b>	<b>1145 S 28TH ST</b>	<b>80</b>	<b>1723</b>
<b>SAN DIEGO HOUSING COMMISSION</b>	<b>2883 BOSTON AV</b>	<b>82</b>	<b>1746</b>
<b>MIGUEL'S AUTO SERVICE</b>	<b>1249 32ND ST</b>	<b>83</b>	<b>1750</b>
<b>ALCORN FENCE COMPANY DBA ATLAS</b>	<b>1211 S 32ND ST</b>	<b>83</b>	<b>1757</b>
<b>CHEVRON USA INC.</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1773</b>
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1794</b>
<b>A TO Z AUTO DISMANTLING</b>	<b>3202 MAIN ST</b>	<b>86</b>	<b>1819</b>
<b>ADVANCE DIESEL INJECTION</b>	<b>3134 MAIN ST</b>	<b>86</b>	<b>1829</b>
<b>S.A. HYDRAULIC SERVICE</b>	<b>3120 MAIN ST</b>	<b>86</b>	<b>1831</b>
<b>ARC CASTLE ELECTRIC</b>	<b>3106 MAIN ST</b>	<b>86</b>	<b>1839</b>
<b>DIESEL ELECTRIC EXCHANGE</b>	<b>2874 MAIN ST</b>	<b>87</b>	<b>1842</b>
<b>COAST INDUSTRIAL SYSTEMS</b>	<b>3004 MAIN ST</b>	<b>87</b>	<b>1844</b>
<b>B &amp; C DIVING &amp; CONST SOUTH INC</b>	<b>3004 MAIN ST</b>	<b>87</b>	<b>1847</b>
<b>FABRICATION ARTS</b>	<b>2926 MAIN ST</b>	<b>87</b>	<b>1849</b>
<b>GRAPHIC SOLUTIONS</b>	<b>2952 MAIN ST</b>	<b>87</b>	<b>1855</b>
<b>RPM WELDING</b>	<b>2970 MAIN ST</b>	<b>87</b>	<b>1859</b>
<b>ADVANCE ENG TECH SERV INC</b>	<b>3032 MAIN ST</b>	<b>87</b>	<b>1868</b>
<b>M D S ENGINEERING INC</b>	<b>3030 MAIN ST</b>	<b>87</b>	<b>1869</b>
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
<b>THE SICKLES GROUP</b>	<b>2795 MAIN ST</b>	<b>88</b>	<b>1886</b>
<b>VCA MAIN ST ANIMAL HOSPITAL</b>	<b>2773 MAIN ST</b>	<b>88</b>	<b>1891</b>
<b>PACIFIC TANK CLEANING SVCS INC</b>	<b>2734 MAIN ST</b>	<b>88</b>	<b>1894</b>
<b>BRITISH MOTORS</b>	<b>2720 MAIN ST</b>	<b>88</b>	<b>1899</b>
<b>MARKEL OHNSON</b>	<b>2697 MAIN ST</b>	<b>88</b>	<b>1904</b>
<b>VINCENT DESIGN</b>	<b>2694 MAIN ST</b>	<b>88</b>	<b>1910</b>
<b>ABLE AUTO WRECKING</b>	<b>2704 MAIN ST</b>	<b>88</b>	<b>1918</b>
<b>AMERICAN MARINE DECKING &amp; COAT</b>	<b>1531 RIGEL ST</b>	<b>90</b>	<b>1926</b>
<b>BILL LEONG'S IMPORT/EXPORT</b>	<b>1531 RIGEL ST</b>	<b>90</b>	<b>1928</b>
<b>U.S. COAST GUARD ACTIVITIES SA</b>	<b>2710 HARBOR DR</b>	<b>91</b>	<b>1942</b>
<b>NASSCO SHIPYARD</b>	<b>2798 HARBOR DR</b>	<b>92</b>	<b>1991</b>
<b>BUTLER BROTHERS CLEANERS</b>	<b>3280 MAIN ST</b>	<b>93</b>	<b>2009</b>
<b>BABYLAND DIAPER SERVICE</b>	<b>3348 MAIN ST</b>	<b>94</b>	<b>2013</b>
<b>PACIFIC SHIP REPAIR&amp; FABRICATI</b>	<b>1625 RIGEL STREET</b>	<b>94</b>	<b>2023</b>
<b>AEROSPACE COATINGS &amp; TECH</b>	<b>1610 RIGEL ST</b>	<b>94</b>	<b>2052</b>
<b>SLOAN ELECTRIC CO</b>	<b>3520 MAIN ST</b>	<b>101</b>	<b>2068</b>
<b>ARATEX SERVICES</b>	<b>3504 MAIN ST</b>	<b>101</b>	<b>2078</b>
<b>YYK ENTERPRISES INC</b>	<b>3460 W MAIN ST</b>	<b>101</b>	<b>2150</b>
<b>AMERICAN LINEN</b>	<b>3460 MAIN ST</b>	<b>101</b>	<b>2152</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>AMERICAN UNIFORM &amp; TOWEL SUPPLY</b>	<b>3440 MAIN ST</b>	<b>101</b>	<b>2158</b>
<b>AMERICAN LINEN SUPPLY</b>	<b>3410 MAIN ST</b>	<b>101</b>	<b>2164</b>
ALSCO AMERICAN LINEN SUPPLY CO	3410 MAIN ST	101	2168
WATSON LAMINATES, INC.	3388 MAIN ST	101	2174
YARA NORTH AMERICA, INC	1770 THOR ST	103	2181
<b>SUNDANCE STAGE LINES INC</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2189</b>
MARBLE WORKS OF SAN DIEGO	3754 MAIN ST	104	2203
K & R GRAPHICS	3754 MAIN ST	104	2208
SERGIO AUTO ELECTRIC, INC.	3746 MAIN ST	104	2213
SANCHEZ AUTO BODY	3746 MAIN ST	104	2222
PRO TRANSMISSION & AUTOMOTIVE	3738 MAIN ST	104	2224
<b>WELCHS TIRE CO</b>	<b>3724 MAIN ST</b>	<b>104</b>	<b>2229</b>
SALSCO INC	3722 MAIN ST	104	2233
MAIN AUTO REPAIR	3714 MAIN ST	104	2238
<b>CUCAMANGOS</b>	<b>3712 MAIN ST</b>	<b>104</b>	<b>2242</b>
G & A AUTO AIR	3708 MAIN ST	104	2247
<b>CUSTOM CNTR AUTO BODY &amp; PAINT</b>	<b>3708 MAIN ST</b>	<b>104</b>	<b>2249</b>
GOLDEN WHEELS	3698 MAIN ST	104	2251
<b>ESPARZA'S USED TIRES</b>	<b>3698 MAIN ST</b>	<b>104</b>	<b>2257</b>
COMPLETE WELDING OF SD	3676 MAIN ST	104	2263
PACIFIC MARINE PROPELLERS INC	3781 DALBERGIA ST	104	2265
MARINE & RESTAURANT FABRICATOR	3768 DALBERGIA ST	104	2268
MASTER MACHINE CORP	3763 DALBERGIA ST	104	2272
<b>DIMENSIONAL SILKSCREEN INC</b>	<b>3750 DALBERGIA ST</b>	<b>104</b>	<b>2274</b>
BC AUTOMOTIVE	3644 MAIN ST	104	2277
<b>TRANSTECH TRANSMISSIONS</b>	<b>3644 MAIN ST</b>	<b>104</b>	<b>2279</b>
DBA ALL TRANSMISSION PRODUCTS	3636 MAIN ST	104	2286
<b>INTERNATIONAL COMPOSITES</b>	<b>3715 DALBERGIA ST</b>	<b>104</b>	<b>2288</b>
SAN DIEGO COLLISION SPECIALIST	3713 DALBERGIA ST	104	2295
<b>VIC'S GO BATTERY</b>	<b>3616 MAIN ST</b>	<b>104</b>	<b>2298</b>
HIGH GEAR TRANSMISSION & AUTOM	3683 DALBERGIA ST	104	2303
<b>HIGH GEAR TRANSMISSION &amp; AUTO</b>	<b>3683 DALBERGIA ST</b>	<b>104</b>	<b>2312</b>
SAFIRO PORTABLE TOILETS	3683 DALBERGIA ST	104	2316
MC AUTO ELECTRIC	3683 DALBERGIA ST	104	2320
<b>CHICKS ELECTRIC</b>	<b>3592 MAIN ST</b>	<b>104</b>	<b>2323</b>
<b>SANI-TAINER INC</b>	<b>3660 DALBERGIA ST</b>	<b>104</b>	<b>2329</b>
FIBRE RESOURCES ULTD INC	3652 N DALBERGIA ST	104	2334
PAUL BROWN	3641 DALBERGIA ST	104	2336
<b>DECA FORKLIFT, INC</b>	<b>1920 UNA ST</b>	<b>104</b>	<b>2340</b>
AGUINAGA'S MOBIL SHOP	3625 DALBERGIA ST	104	2347
CRANK IT AUTO ELECTRIC	3625 DALBERGIA ST	104	2349
TINO'S IRON WORKS	1915 UNA ST	104	2351
<b>DECA FORKLIFT, INC.</b>	<b>3596 DALBERGIA ST</b>	<b>104</b>	<b>2353</b>
<b>SOUTH BAY SANDBLASTING</b>	<b>3589 DALBERGIA ST</b>	<b>104</b>	<b>2360</b>
SOUTH BAY SANDBLASTING	3577 DALBERGIA ST	104	2369
<b>CHAPMANS DIESEL SALES AND SVC</b>	<b>3561 DALBERGIA ST</b>	<b>104</b>	<b>2371</b>
<b>MAJOR SCIENTIFIC INDUSTRIES</b>	<b>3557 DALBERGIA ST</b>	<b>104</b>	<b>2377</b>
<b>ARAMARK UNIFORM SERVICE INC</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2388</b>
<b>SAN DIEGO GALVANIZING INCORPOR</b>	<b>3586 DALBERGIA STREET</b>	<b>104</b>	<b>2404</b>
<b>SOVEREIGN CONST-GEN DYNAM/CONV</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2416</b>
<b>GENERAL DYNAMICS CONVAIR</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2418</b>
<b>MOBIL OIL STATION #18-FF9</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2455</b>
<b>DIVISION SHELL SERVICE</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2470</b>
<b>HOLIDAY INN SAN DIEGO SOUTH BA</b>	<b>700 NATIONAL CITY BL</b>	<b>112</b>	<b>2483</b>
<b>ARCO FACILITY NO. 9565</b>	<b>801 ROOSEVELT AV</b>	<b>114</b>	<b>2494</b>
<b>CHEVRON #98225</b>	<b>105 W 08TH ST</b>	<b>114</b>	<b>2502</b>

## EXECUTIVE SUMMARY

**RESPONSE:** Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

A review of the RESPONSE list, as provided by EDR, and dated 02/26/2008 has revealed that there are 2 RESPONSE sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MCAS MIRAMAR</b>	<b>OFF OF MIRAMAR BOULEVAR</b>	<b>101</b>	<b>2103</b>
<b>SAN DIEGO NAVAL STATION - SITE</b>	<b>SAN DIEGO BAY, 113 NAVA</b>	<b>101</b>	<b>2143</b>

**HAZNET:** The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency

A review of the HAZNET list, as provided by EDR, and dated 12/31/2006 has revealed that there are 242 HAZNET sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
<b>HAWTHORNE RENT-IT SERVICE</b>	<b>1473 G ST</b>	<b>6</b>	<b>27</b>
<b>WESTERN PACIFIC HOUSING</b>	<b>1147 MARKET ST</b>	<b>8</b>	<b>46</b>
<b>ECONO AUTO REPAIR/GAS</b>	<b>400 16TH ST</b>	<b>15</b>	<b>88</b>
<b>PACIFIC MARINE SHEET METAL COR</b>	<b>410 15TH ST</b>	<b>15</b>	<b>99</b>
<b>BARTOLINI TRUST</b>	<b>1460 ISLAND AVE</b>	<b>15</b>	<b>115</b>
<b>SHERMAN HEIGHTS FAMILY HLTH CT</b>	<b>450 24TH ST</b>	<b>16</b>	<b>126</b>
<b>EAST VILLAGE RDA (535-353)</b>	<b>318 9TH</b>	<b>17</b>	<b>131</b>
<b>CONWAY TRUST &amp; DT SAN DIEGO LL</b>	<b>427 9TH AVE</b>	<b>17</b>	<b>139</b>
<b>ALLAN COMPANY</b>	<b>415 14TH ST</b>	<b>19</b>	<b>153</b>
<b>SDG &amp; E SERVICE BUILD</b>	<b>114 TENTH AVENUE</b>	<b>21</b>	<b>164</b>
<b>BALLPARK INFRASTRUCTURE SITE</b>	<b>K ST AND IMPERIAL BORDE</b>	<b>21</b>	<b>246</b>
<b>SOUTHWEST MARINE HARDWARE</b>	<b>944 K ST</b>	<b>21</b>	<b>250</b>
<b>DONALD C HARDER_INC</b>	<b>2580 K ST</b>	<b>23</b>	<b>275</b>
<b>CAL LINEN SUPPLY</b>	<b>101 16TH ST</b>	<b>24</b>	<b>307</b>
<b>FRED'S AUTO BODY &amp; PAINT</b>	<b>301 16TH ST</b>	<b>24</b>	<b>319</b>
<b>ROY'S AUTO REPAIR</b>	<b>301 16TH ST</b>	<b>24</b>	<b>322</b>
<b>CONTINENTAL BAKING CO</b>	<b>1304 IMPERIAL AVE</b>	<b>28</b>	<b>353</b>
<b>NATIONAL BRAKE SERVICE INC</b>	<b>2040 IMPERIAL AVE</b>	<b>29</b>	<b>369</b>
<b>WILSON &amp; HAMPTON REFINISHING I</b>	<b>1835 IMPERIAL AVENUE</b>	<b>29</b>	<b>379</b>
<b>ASTRO PAK CORPORATION</b>	<b>1936 NATIONAL AVENUE</b>	<b>37</b>	<b>453</b>
<b>AZTEC OIL</b>	<b>1921 NATIONAL AVE</b>	<b>37</b>	<b>456</b>
<b>SDCTY FIRE STATION 7</b>	<b>944 CESAR E CHAVEZ PKWY</b>	<b>37</b>	<b>478</b>
<b>ACE RADIATOR</b>	<b>1854 NATIONAL AVE</b>	<b>37</b>	<b>478</b>
<b>RICARDO'S FLEET SERVICE</b>	<b>1841 NATIONAL AVE</b>	<b>37</b>	<b>483</b>
<b>ACE RADIATOR</b>	<b>1836 NATIONAL AVE</b>	<b>37</b>	<b>489</b>
<b>FRASER'S BOILER SERVICE INC</b>	<b>1746 NEWTON AVE</b>	<b>37</b>	<b>490</b>
<b>CITY OF SAN DIEGO</b>	<b>1880 LOGAN AVE</b>	<b>37</b>	<b>500</b>
<b>LOGAN HEIGHTS FAMILY HEALTH CE</b>	<b>1809 NATIONAL AVE</b>	<b>37</b>	<b>514</b>
<b>TRIAD MARINE &amp; INDUSTRIAL CLEA</b>	<b>1775 NATIONAL AVE</b>	<b>37</b>	<b>515</b>
<b>MINI TRUCK DISMANTLING</b>	<b>1700 NEWTON AVE</b>	<b>37</b>	<b>538</b>
<b>CASTELLINI &amp; SONS INC</b>	<b>1827 LOGAN AVE</b>	<b>37</b>	<b>547</b>
<b>KAMAN IND TECH</b>	<b>1675 NEWTON</b>	<b>37</b>	<b>550</b>
<b>ACTION CLEANING</b>	<b>1668 NEWTON AVE</b>	<b>37</b>	<b>552</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
LUBE EQUIPMENT & PUMP SERVICE	1795 LOGAN AVE	37	554
<b>LUBE EQUIPMENT &amp; PUMP SERVICE</b>	<b>1785 LOGAN AVE</b>	<b>37</b>	<b>557</b>
FBI GARAGE	1637 NEWTON AVE	37	573
SIGSBEE ROW HOMES LLC	1702 NATIONAL AVE	37	573
<b>SAN DIEGO SAW AND KNIFE WORKS</b>	<b>1765 LOGAN AVE</b>	<b>37</b>	<b>578</b>
LOGAN INVESTMENT LLC	1765 LOGAN AVE	37	586
<b>CARLOS CLEANERS</b>	<b>1694 NATIONAL AVE</b>	<b>37</b>	<b>587</b>
US COAST GUARD	1620 NEWTON AVE	37	595
<b>ACTION CLEANING CORP</b>	<b>1620 NEWTON AV</b>	<b>37</b>	<b>596</b>
<b>CARLOS CLEANERS</b>	<b>1686 NATIONAL AVE</b>	<b>37</b>	<b>607</b>
MARINE & RESTURANT FABRICATORS	1616 NEWTON AVE	37	612
ACTION CLEANING PRODUCTS	1616 NEWTON AVE	37	616
<b>ACTION CLEANING</b>	<b>1604 NEWTON AVE</b>	<b>37</b>	<b>617</b>
METRO TRANSIT	1601 NEWTON AVE	37	624
SANDAG	1601 NEWTON AVE	37	625
<b>SAN DIEGO TROLLEY INC</b>	<b>1535 NEWTON AVE</b>	<b>37</b>	<b>647</b>
QUALITY REFRIGERATION CO	1680 LOGAN AVE	37	660
CENTRAL MEAT & PROVIDION COMPA	1603 NATIONAL AVENUE	37	670
<b>GRAYBILL TERMINALS CO</b>	<b>1531 NATIONAL AVE</b>	<b>37</b>	<b>681</b>
JAMES M HUGHES	1643 LOGAN AVE	37	690
GATEWAY HOUSING INVESTMENT LP	1637 LOGAN AVE	37	691
AMERICAN & FOREIGN AUTO WRECKI	1615 LOGAN AVE	37	702
GATEWAY ONE HOUSING INVESTORS	1603 LOGAN AVE	37	707
<b>RELIABLE PIPE SUPPLY</b>	<b>1430 NATIONAL AVE</b>	<b>37</b>	<b>713</b>
<b>G E O AUTO DISMANTLING</b>	<b>1610 COMMERCIAL ST</b>	<b>37</b>	<b>725</b>
<b>SAINT VINCENT DE PAUL</b>	<b>1501 IMPERIAL AVE</b>	<b>37</b>	<b>739</b>
<b>EL DORADO SANDBLASTING CO</b>	<b>2694 COMMERCIAL ST</b>	<b>40</b>	<b>759</b>
<b>PORT OF SAN DIEGO DIST MAINT F</b>	<b>825 EAST HARBOR DRIVE</b>	<b>45</b>	<b>794</b>
<b>DANNYS PAINT &amp; BODY SHOP</b>	<b>1866 KEARNEY AVENUE</b>	<b>50</b>	<b>804</b>
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
SEA MANAGEMENT	1202 SIGSBEE ST	53	835
<b>NASSCO WAREHOUSE</b>	<b>1699 MAIN ST</b>	<b>53</b>	<b>835</b>
<b>PERFORMANCE CONTRACTING GROUP</b>	<b>2015 MAIN ST</b>	<b>55</b>	<b>851</b>
NATIONAL PETROLEUM, INC.	2005 MAIN ST.	55	863
ATKINSON CONSTRUCTION	1997 MAIN ST	55	872
<b>BURLINGTON NORHTERN AND SANTA</b>	<b>1342 CESAR E CHAVEZ PKW</b>	<b>55</b>	<b>874</b>
<b>RANKIN INDUSTRIES INC</b>	<b>1991 MAIN ST</b>	<b>55</b>	<b>880</b>
<b>A O REED</b>	<b>1990 MAIN ST</b>	<b>55</b>	<b>885</b>
TUMYETO INC	1991 MAIN STREET	55	888
UNION ELECTRIC MOTOR SVC	2046 NEWTON AVE	55	892
<b>TUNA CLIPPER MARINE</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>899</b>
<b>SANTA FE INTERMODAL</b>	<b>1342 CROSBY ST</b>	<b>55</b>	<b>908</b>
BURLINGTON NORTHERN AND SANTA	1342 CROSBY ST	55	919
VEHICLE PROCESSING & DISTRIBUT	1300 CROSBY	55	922
<b>CALTRANS DISTRICT 11-CORONADO</b>	<b>1995 NEWTON AVE</b>	<b>55</b>	<b>941</b>
CALTRANS DISTRICT 11-CORONADO	1995 NEWTON AVE	55	942
NATIONAL PUMP & INJECTOR CORP	1901 MAIN ST	55	944
<b>NATIONAL PUMP &amp; INJECTOR</b>	<b>1901 MAIN ST</b>	<b>55</b>	<b>945</b>
CABINETRY DESIGN INC	1878 MAIN ST	55	956
REAL'S AUTO BODY	1957 NEWTON AVE	55	958
<b>ROMANS TRUCKING PAINTING</b>	<b>1941 NEWTON AVE</b>	<b>55</b>	<b>963</b>
COUNTY OF DIEGO-ENVIRO SERVICE	1931 NEWTON AVE	55	968
<b>EMM, ELECTRICAL MOTOR MACHINE</b>	<b>1837 MAIN ST</b>	<b>55</b>	<b>972</b>
<b>QUALITY REFRIGERATION CO.</b>	<b>1815 MAIN ST</b>	<b>55</b>	<b>980</b>
ORIENT ENGINES & PARTS INC	1805 MAIN ST	55	983
<b>FRYER KNOWLES INC</b>	<b>1858 NEWTON AVE</b>	<b>55</b>	<b>983</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
WEST MARINE DIESEL	1835 NEWTON AVE	55	992
SAN DIEGO EXPRESS PRINTING	1805 NEWTON AVENUE	55	999
<b>NORTH AMERICAN TERMINAL INC</b>	<b>1090 WATER ST</b>	<b>57</b>	<b>1003</b>
<b>OIL FILTER SERVICE, INC.</b>	<b>2636 MAIN ST</b>	<b>59</b>	<b>1020</b>
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
<b>EPSILON AIR CONDITIONING &amp; REF</b>	<b>2640 MAIN ST</b>	<b>59</b>	<b>1094</b>
EPSILON A/C & R A UNIT OF DIGI	2640 MAIN ST	59	1097
SHERWIN WILLIAMS #8227	2640 MAIN ST	59	1097
BAY DECKING CO., INC.	2685 BOSTON AVE	59	1111
IMS RECYCLING INC	2740 BOSTON AVE	59	1120
<b>ADVANCED WOOD FINISHING</b>	<b>1127 S 27TH ST</b>	<b>59</b>	<b>1132</b>
RESURGENCE PROP INC	2363-2393 NEWTON AVE	59	1141
<b>JVM SPA COVERS</b>	<b>2777 NEWTON AVE</b>	<b>59</b>	<b>1147</b>
IMS RECYCLING SERVICES	2740 NEWTON AVE	59	1149
<b>IMS RECYCLING SERVICES</b>	<b>2731 NEWTON AV</b>	<b>59</b>	<b>1151</b>
LIFE DECK-PACIFIC PEBBLES	2709 NEWTON	59	1161
CANDY'S AUTO BODY SHOP	2691 NEWTON AVE	59	1164
GARCIA AUTO REPAIR	2340 NEWTON AVE	59	1178
<b>BARRIO SENIOR VILLAS</b>	<b>2330 NEWTON AVE</b>	<b>59</b>	<b>1181</b>
<b>NORTH STAR PROPELLERS, INC</b>	<b>2317 NEWTON AV</b>	<b>59</b>	<b>1189</b>
NORTH STAR PROPELLERS INC	2285 NEWTON AVE	59	1201
NORTH STAR PROPELLER	2285 NEWTON AVE	59	1203
<b>ADVANCED METAL FORMING, INC.</b>	<b>2618 NATIONAL AV</b>	<b>59</b>	<b>1206</b>
CARLOS TRANSMISSION	2295 NATIONAL AVE	59	1224
WESTERN STEEL & METALS	2292 NATIONAL AVE	59	1227
TERESA'S TIRE SHOP	2276 NATIONAL AVENUE	59	1229
<b>ACE MUFFLER SHOP</b>	<b>2260 NATIONAL AV</b>	<b>59</b>	<b>1231</b>
ODACO INC	2255 NATIONAL AVE	59	1234
FRASER INC DBA OLYMPIC BOILER	2255 NATIONAL AVE	59	1235
INLAND WEST SYSTEMS, INC	2255 NATIONAL AVE	59	1241
<b>PROPULSION CONTROLS ENGINEERIN</b>	<b>2255 NATIONAL AVE</b>	<b>59</b>	<b>1245</b>
DBA BALLPARK COLLISION	2243 NATIONAL AVE	59	1249
<b>SAN DIEGO AUTO EXPERT</b>	<b>2602 LOGAN AV</b>	<b>59</b>	<b>1258</b>
R & C AUTO ELECTRIC	2250 LOGAN AVE	59	1278
DIEGO AND SONS PRINTING INC	2104 NATIONAL AVE	59	1284
<b>DIEGO AND SON PRINTING INC</b>	<b>2104 NATIONAL AVE</b>	<b>59</b>	<b>1288</b>
<b>CROWLEY MARINE SERVICE INC</b>	<b>1843 WATER ST</b>	<b>61</b>	<b>1303</b>
<b>NRC ENVIRONMENTAL SVCS INC</b>	<b>1839 WATER ST</b>	<b>61</b>	<b>1306</b>
PRAXAIR	2205 NEWTON AVE	63	1326
<b>CARLSON &amp; BEAULOYE MACHINE SHO</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1332</b>
TRIMM WOODWORKING INC	2130 NEWTON AVE	63	1349
<b>MASTER PLATING</b>	<b>2109 NEWTON AVE</b>	<b>63</b>	<b>1351</b>
<b>CALIFORNIA MARINE CLEANING INC</b>	<b>905 S 33RD ST</b>	<b>67</b>	<b>1373</b>
<b>CONTINENTAL MARITIME OF S D</b>	<b>1995 BAYFRONT ST</b>	<b>68</b>	<b>1389</b>
<b>CP KELCO</b>	<b>2025 EAST HARBOR DRIVE</b>	<b>68</b>	<b>1434</b>
<b>GJS WAREHOUSE</b>	<b>2191 MAIN ST</b>	<b>69</b>	<b>1459</b>
<b>CLEANING DYNAMICS</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1461</b>
SUNSHINE TRUCK & AUTO BODY	2191 MAIN ST #4	69	1475
<b>E.J. FERGUSON'S</b>	<b>2146 MAIN ST</b>	<b>69</b>	<b>1479</b>
<b>EARL INDUSTRIES, LLC</b>	<b>2102 MAIN ST</b>	<b>69</b>	<b>1493</b>
TRIMM WOODWORKING INC	2102 MAIN ST	69	1498
<b>COOL RADIATOR SHOP</b>	<b>3362 NATIONAL AVE</b>	<b>71</b>	<b>1504</b>
<b>SOUTHERN CALIFORNIA PLATING</b>	<b>3261 NATIONAL AVE.</b>	<b>73</b>	<b>1539</b>
<b>A&amp;A AUTO &amp; TRUCK ELEC</b>	<b>3005 NATIONAL AVE</b>	<b>75</b>	<b>1565</b>
<b>GAS QUIK</b>	<b>2865 NATIONAL AVE</b>	<b>77</b>	<b>1574</b>
<b>AMERICAN RIGGING &amp; SUPPLY CO</b>	<b>2380 MAIN ST</b>	<b>78</b>	<b>1583</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>SOUTHWEST REGIONAL MAINTENANCE</b>	<b>2205 EAST BELT ST.</b>	<b>79</b>	<b>1618</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>1401 SAMPSON ST</b>	<b>79</b>	<b>1628</b>
<b>MERCK &amp; COMPANY</b>	<b>2145 E BELT ST</b>	<b>79</b>	<b>1649</b>
<b>SAN DIEGO GAS &amp; ELECTRIC - SIL</b>	<b>1348 SAMPSON STREET</b>	<b>79</b>	<b>1670</b>
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAYFRONT STREET</b>	<b>79</b>	<b>1696</b>
<b>PROPULSION CONTROLS ENGINEERIN</b>	<b>1304 S SAMPSON ST</b>	<b>79</b>	<b>1700</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>TEXACO SERVICE STATION</b>	<b>1145 SOUTH 28TH STREET</b>	<b>80</b>	<b>1720</b>
<b>TEXACO REFINING &amp; MARKETING</b>	<b>1145 S 28TH ST</b>	<b>80</b>	<b>1734</b>
TEXACO REFINING AND MARKETING	1145 S 28TH ST	80	1739
<b>ATLAS FENCE COMPANY</b>	<b>1211 32ND ST S</b>	<b>83</b>	<b>1754</b>
ALCORN FENCE COMPANYDBA ATLAS	1211 S 32ND_ST	83	1767
<b>CHEVRON SAN DIEGO TERMINAL 100</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1783</b>
CHEVRON 1001252 SAN DIEGO	2351 EAST HARBOR DR	84	1791
SAN DIEGO PETROLEUM CORP	2351 E HARBOR BLVD	84	1792
CITY OF SAN DIEGO, TRANSPORTAT	3200 MAIN ST	86	1818
<b>A TO Z AUTO DISMANTLING</b>	<b>3202 MAIN ST</b>	<b>86</b>	<b>1819</b>
ABAMEX INC	3106 MAIN ST	86	1837
<b>CASINO ELECTRIC COMPANY INC</b>	<b>3106 MAIN STREET</b>	<b>86</b>	<b>1841</b>
<b>COAST INDUSTRIAL SYSTEMS</b>	<b>3004 MAIN ST</b>	<b>87</b>	<b>1844</b>
B & C DIVING	3004 MAIN STREET	87	1848
GRAPHIC SOLUTIONS DBA FABRICAT	2926 MAIN STREET	87	1854
<b>RPM WELDING</b>	<b>2970 MAIN ST</b>	<b>87</b>	<b>1859</b>
NAVY REGION SOUTHWEST	1345 S 27TH ST	88	1872
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
EVERINGHAM BROS BAIT CO	2750 MAIN ST	88	1893
<b>PACIFIC TANK CLEANING SVCS INC</b>	<b>2734 MAIN ST</b>	<b>88</b>	<b>1894</b>
<b>BRITISH MOTORS</b>	<b>2720 MAIN ST</b>	<b>88</b>	<b>1899</b>
<b>MARKEL OHNSON</b>	<b>2697 MAIN ST</b>	<b>88</b>	<b>1904</b>
<b>ABLE AUTO WRECKING</b>	<b>2704 MAIN ST</b>	<b>88</b>	<b>1918</b>
AMERICAN MARINE DECKING SYSTEM	1531 RIGEL STREET	90	1925
<b>BILL LEONG'S IMPORT/EXPORT</b>	<b>1531 RIGEL ST</b>	<b>90</b>	<b>1928</b>
US COAST GUARD SECTOR	2710 HARBOR DR	91	1935
<b>US COAST GUARD AIR STATION</b>	<b>2710 HARBOR DR</b>	<b>91</b>	<b>1936</b>
SS ALMERIA LYKES EX PRES MCKIN	HARBOR DR / 28TH ST	92	1957
NATIONAL STEEL AND SHIPBUILDIN	2798 EAST HARBOR DRIVE	92	1975
<b>S S HOWELL LYKES EXPRESS VAN B</b>	<b>HARBOR DR AND 28 ST CSS</b>	<b>92</b>	<b>2004</b>
<b>L C EMBROIDERY &amp; CLEANERS</b>	<b>3280 MAIN ST STE 6</b>	<b>93</b>	<b>2007</b>
PCE & BAYSIDE HARBOR PROPERTY	3348 MAIN ST	94	2023
<b>PACIFIC SHIP REPAIR &amp; FABRICATI</b>	<b>1625 RIGEL STREET</b>	<b>94</b>	<b>2023</b>
PLENUMS PLUS_INC	1620 RIGEL STREET	94	2047
A & B COPP INC	1620 RIGEL ST	94	2048
<b>FRASER'S BOILER SERV INC @ NAV</b>	<b>32ND ST NAVAL STATION</b>	<b>98</b>	<b>2060</b>
SLOAN ELECTRIC COMPANY	3520 MAIN ST	101	2066
<b>SLOAN ELECTRIC CO</b>	<b>3520 MAIN ST</b>	<b>101</b>	<b>2068</b>
FISCHBACH PROPERTIES	3520 MAIN ST	101	2076
<b>NAVAL COATING INC</b>	<b>32ND ST NAVAL STATION</b>	<b>101</b>	<b>2088</b>
<b>BAE SYSTEMS MES</b>	<b>32ND ST NAVAL STATION</b>	<b>101</b>	<b>2091</b>
<b>SOUTHBAY SANDBLAST AND TANK CL</b>	<b>32ND ST NAS PIERS</b>	<b>101</b>	<b>2110</b>
YYK ENTERPRISES INC	3460 MAIN STREET	101	2156
<b>NATIONAL LINEN SERVICE</b>	<b>3410 MAIN STREET</b>	<b>101</b>	<b>2169</b>
<b>WATSON LAMINATES INC</b>	<b>3388 MAIN ST</b>	<b>101</b>	<b>2171</b>
SUNDANCE STAGE LINES INC	3762 MAIN STREET	104	2198
<b>SUNDANCE STAGE LINES</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2200</b>
K&R GRAPHIX	3754 MAIN ST	104	2202
MARBLE WORKS	3754 MAIN ST, #B	104	2211

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
SERGIO'S AUTO ELECTRIC	3746 MAIN ST	104	2216
<b>SANCHEZ AUTO BODY</b>	<b>3746 MAIN STREET #B</b>	<b>104</b>	<b>2217</b>
THE BUMPER GUY INC	3746 MAIN ST	104	2224
<b>WELCHS TIRE CO</b>	<b>3724 MAIN ST</b>	<b>104</b>	<b>2229</b>
<b>CUCAMANGOS</b>	<b>3712 MAIN ST</b>	<b>104</b>	<b>2242</b>
BENNY AUTO BODY & PAINT	3712 MAIN ST.	104	2246
<b>CUSTOM CNTR AUTO BODY &amp; PAINT</b>	<b>3708 MAIN ST</b>	<b>104</b>	<b>2249</b>
<b>GOLDEN WHEELS</b>	<b>3698 1/2 MAIN ST</b>	<b>104</b>	<b>2253</b>
<b>ESPARZA'S USED TIRES</b>	<b>3698 MAIN ST</b>	<b>104</b>	<b>2257</b>
COMPLETE WELDING OF SAN DIEGO	3676 MAIN ST	104	2265
MARINE & RESTAURANT FABRICATOR	3768 DALBERGIA STREET	104	2271
<b>DIMENSIONAL SILKSCREEN INC</b>	<b>3750 DALBERGIA ST</b>	<b>104</b>	<b>2274</b>
<b>INTERNATIONAL COMPOSITES</b>	<b>3715 DALBERGIA ST</b>	<b>104</b>	<b>2288</b>
SAN DIEGO COLLISION SPECIALIST	3713 DILBERTIA ST	104	2294
ELITE AUTO BODY AND PAINT	3626 MAIN ST	104	2298
<b>VIC'S GO BATTERY</b>	<b>3616 MAIN ST</b>	<b>104</b>	<b>2298</b>
STEVE CAVADAIS	3683 DALBERGIA	104	2303
<b>CHICKS ELECTRIC</b>	<b>3592 MAIN ST</b>	<b>104</b>	<b>2323</b>
BAY CITIES SERVICES CO INC	3660 DALBERGIA ST	104	2327
<b>SANI-TAINER INC</b>	<b>3660 DALBERGIA ST</b>	<b>104</b>	<b>2329</b>
NATIONAL ORDINANCE COMPANY INC	3647 DALBERGIA ST	104	2335
<b>DECA FORKLIFT, INC</b>	<b>1920 UNA ST</b>	<b>104</b>	<b>2340</b>
JIM SALLEE	1915 UNA ST	104	2350
<b>DECA FORKLIFT, INC.</b>	<b>3596 DALBERGIA ST</b>	<b>104</b>	<b>2353</b>
<b>SOUTHBAY SANDBLAST &amp; TANK CLEA</b>	<b>3589 DALBERGIA ST</b>	<b>104</b>	<b>2357</b>
<b>SOUTH BAY SANDBLASTING</b>	<b>3589 DALBERGIA ST</b>	<b>104</b>	<b>2360</b>
<b>CHAPMANS DIESEL SALES AND SVC</b>	<b>3561 DALBERGIA ST</b>	<b>104</b>	<b>2371</b>
<b>MAJOR SCIENTIFIC INDUSTRIES</b>	<b>3557 DALBERGIA ST</b>	<b>104</b>	<b>2377</b>
<b>MAJOR SCIENTIFIC INDUSTRIES</b>	<b>3557 DALBERGIA ST</b>	<b>104</b>	<b>2377</b>
<b>ARAMARK UNIFORM SERVICE INC</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2388</b>
<b>ARATEX SERVICES INC.</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2400</b>
<b>SAN DIEGO GALVANIZING INCORPOR</b>	<b>3586 DALBERGIA STREET</b>	<b>104</b>	<b>2404</b>
<b>SOVEREIGN CONST-GEN DYNAM/CONV</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2416</b>
<b>CAMPBELL INDUSTRIES</b>	<b>32ND ST AND HARBOR DR</b>	<b>106</b>	<b>2440</b>
<b>EARL SCHEIB OF CALIF INC</b>	<b>111 NATIONAL CITY BLVD</b>	<b>109</b>	<b>2445</b>
<b>NATIONAL MOBIL SERVICE STATION</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2450</b>
<b>MOBIL OIL STATION #18-FF9</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2455</b>
<b>MOBIL SERVICE STATION #18-FF9</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2461</b>
<b>DIVISION SHELL SERVICE</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2470</b>
<b>USNAVY SAN DIEGO NAVAL STN PWC</b>	<b>32ND ST AND HARBOR DR</b>	<b>115</b>	<b>2506</b>

**AIRS:** Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies

A review of the AIRS list, as provided by EDR, and dated 12/31/2005 has revealed that there are 35 AIRS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SHELL OIL PRODUCTS COMPANY</b>	<b>1619 G ST</b>	<b>5</b>	<b>16</b>
<b>YELLOW CAB CO OF SAN DIEGO INC</b>	<b>639 13TH ST</b>	<b>8</b>	<b>52</b>
<b>CONTINENTAL CLEANERS</b>	<b>450 10TH AV</b>	<b>17</b>	<b>146</b>
<b>SD CITY POLICE</b>	<b>330 12TH AV</b>	<b>21</b>	<b>263</b>
<b>ARCO FACILITY NO. 9560</b>	<b>2502 IMPERIAL AV</b>	<b>34</b>	<b>419</b>



## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>EL DORADO SANDBLASTING</b>	<b>2694 COMMERCIAL ST</b>	<b>40</b>	<b>756</b>
<b>DANNYS PAINT &amp; BODY SHOP</b>	<b>1866 KEARNEY AVENUE</b>	<b>50</b>	<b>804</b>
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
<b>SHERWIN-WILLIAMS COMPANY THE</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1066</b>
<b>NORTH STAR PROPELLERS INC.</b>	<b>2285 NEWTON AV</b>	<b>59</b>	<b>1194</b>
<b>CARLSON &amp; BEAULOYE MACHINE SHO</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1332</b>
<b>CALIFORNIA WOOD DESI</b>	<b>2130 NEWTON AV</b>	<b>63</b>	<b>1348</b>
<b>MASTER PLATING</b>	<b>2109 NEWTON AVE</b>	<b>63</b>	<b>1354</b>
<b>PARTY HATS INC</b>	<b>2109 NEWTON AV</b>	<b>63</b>	<b>1365</b>
<b>SOUTHERN CALIFORNIA PLATING CO</b>	<b>3261 NATIONAL AV</b>	<b>73</b>	<b>1543</b>
<b>ISP ALGINATES INCORPORATED</b>	<b>2145 EAST BELT STREET</b>	<b>79</b>	<b>1659</b>
<b>BAE SYSTEMS SAN DIEGO SHIP REP</b>	<b>FOOT OF SAMSON STREET</b>	<b>79</b>	<b>1704</b>
<b>TEXACO SERVICE STATION</b>	<b>1145 28TH ST S</b>	<b>80</b>	<b>1740</b>
<b>CHEVRON SERVICE STATION</b>	<b>2351 HARBOR DR E</b>	<b>84</b>	<b>1768</b>
<b>CHEVRON USA INC</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1789</b>
<b>CHEVRON USA INC</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1792</b>
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1794</b>
<b>FABRICATION ARTS</b>	<b>2926 MAIN ST</b>	<b>87</b>	<b>1849</b>
<b>NATIONAL STEEL &amp; SHIPBUILDING</b>	<b>28TH ST / HARBOR DR</b>	<b>92</b>	<b>1984</b>
<b>NATL STEEL &amp; SHIPBUILDING A GE</b>	<b>28TH ST / HARBOR DR</b>	<b>92</b>	<b>1986</b>
<b>NATIONAL STEEL &amp; SHI</b>	<b>28TH ST / HARBOR DR</b>	<b>92</b>	<b>1989</b>
<b>NATIONAL STEEL &amp; SHIP</b>	<b>28TH ST / HARBOR DR</b>	<b>92</b>	<b>2001</b>
<b>PACIFIC SHIP REPAIR&amp; FABRICATI</b>	<b>1625 RIGEL STREET</b>	<b>94</b>	<b>2023</b>
<b>WATSON LAMINATES INC</b>	<b>3388 MAIN ST</b>	<b>101</b>	<b>2171</b>
<b>G&amp;M OIL / MAIN STREET</b>	<b>3774 MAIN ST</b>	<b>104</b>	<b>2186</b>
<b>CENTRAL MARBLE SUPPLY</b>	<b>3754 MAIN ST</b>	<b>104</b>	<b>2206</b>
<b>SANCHEZ AUTO BODY</b>	<b>3746 MAIN STREET #B</b>	<b>104</b>	<b>2217</b>
<b>SHELL STATION</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2464</b>
<b>ARCO FACILITY NO. 9565</b>	<b>801 ROOSEVELT AV</b>	<b>114</b>	<b>2494</b>

**SAN DIEGO CO. SAM:** The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

A review of the SAN DIEGO CO. SAM list, as provided by EDR, and dated 11/28/2007 has revealed that there are 158 SAN DIEGO CO. SAM sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MIKE RUDIN AUTOMOTIVE</b>	<b>1616 G ST</b>	<b>5</b>	<b>10</b>
<b>SHELL OIL PRODUCTS COMPANY</b>	<b>1619 G ST</b>	<b>5</b>	<b>16</b>
<b>HAWTHORNE RENT-IT SERVICE</b>	<b>1473 G ST</b>	<b>6</b>	<b>27</b>
<b>ROAD RUNNERS</b>	<b>544 11TH AV</b>	<b>8</b>	<b>42</b>
<b>WESTERN PACIFIC HOUSING</b>	<b>1147 MARKET ST</b>	<b>8</b>	<b>46</b>
<b>ISLAND VILLAGE APARTMENTS</b>	<b>1213 MARKET ST</b>	<b>8</b>	<b>48</b>
<b>FRMR YELLOW CAB/NEW EV II LLC</b>	<b>639 13TH ST</b>	<b>8</b>	<b>50</b>
<b>UNOCAL SERV STN #0364-30319</b>	<b>1606 MARKET ST</b>	<b>10</b>	<b>70</b>
<b>ADT PROPERTY HOLDINGS INC</b>	<b>1416 MARKET ST</b>	<b>11</b>	<b>80</b>
<b>PARKSIDE, FORMER E. VIL. COMM</b>	<b>505 13TH ST</b>	<b>14</b>	<b>86</b>
<b>ECONO AUTO REPAIR/GAS</b>	<b>400 16TH ST</b>	<b>15</b>	<b>88</b>
<b>JOHN HANSEN HOUSE MOVING</b>	<b>405 15TH ST</b>	<b>15</b>	<b>96</b>
<b>JOHN HANSEN HOUSE MOVING</b>	<b>405 15TH</b>	<b>15</b>	<b>98</b>
<b>VICTOR'S USED TIRES</b>	<b>405 16TH ST</b>	<b>15</b>	<b>106</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>MOTOR WORKS INC</b>	<b>1490 ISLAND AV</b>	<b>15</b>	<b>111</b>
<b>ARCWELL CORP</b>	<b>510 16TH STREET</b>	<b>15</b>	<b>117</b>
<b>MONTERREY PROVISION CO INC</b>	<b>318 09TH AV</b>	<b>17</b>	<b>131</b>
<b>BIG TOW</b>	<b>901 J ST</b>	<b>17</b>	<b>136</b>
<b>DOS AMIGOS PROPERTY</b>	<b>405 10TH AV</b>	<b>17</b>	<b>138</b>
<b>DONEV COMPANY</b>	<b>441 10TH AV</b>	<b>17</b>	<b>142</b>
<b>CONTINENTAL CLEANERS</b>	<b>450 10TH AV</b>	<b>17</b>	<b>146</b>
<b>12TH &amp; ISLAND</b>	<b>443 12TH AV</b>	<b>18</b>	<b>152</b>
<b>ALLAN COMPANY</b>	<b>415 14TH ST</b>	<b>19</b>	<b>153</b>
<b>SDGE STA A BL 148 FUELING FAC</b>	<b>114 10TH AV</b>	<b>21</b>	<b>159</b>
<b>EAST VILLAGE RDA</b>	<b>200 10TH AV</b>	<b>21</b>	<b>171</b>
<b>SDG&amp;E/STATION A BLOCK 135</b>	<b>250 10TH AV</b>	<b>21</b>	<b>241</b>
<b>BALL PARK</b>	<b>175 11TH AV</b>	<b>21</b>	<b>244</b>
<b>BALLPARK INFRASTRUCTURE SITE</b>	<b>K ST AND IMPERIAL BORDE</b>	<b>21</b>	<b>246</b>
<b>SOUTHWEST MARINE HARDWARE</b>	<b>944 K ST</b>	<b>21</b>	<b>250</b>
<b>ATLAS FIRE EQUIPMENT CO</b>	<b>312 11TH AV</b>	<b>21</b>	<b>256</b>
<b>LIBRARY TOWER</b>	<b>325 12TH AV</b>	<b>21</b>	<b>260</b>
<b>SDCTY-POLICE REPAIR FACILITY</b>	<b>300 12TH AV</b>	<b>21</b>	<b>261</b>
<b>SD CITY POLICE</b>	<b>330 12TH AV</b>	<b>21</b>	<b>263</b>
<b>A.W.COGGESHALL</b>	<b>354 11TH AV</b>	<b>21</b>	<b>275</b>
<b>SAN DIEGO TRANSIT CORP</b>	<b>100 16TH ST</b>	<b>24</b>	<b>277</b>
<b>BREITBARD PROPERTIES LLC</b>	<b>101 16TH ST</b>	<b>24</b>	<b>310</b>
<b>ROY'S AUTO REPAIR</b>	<b>301 16TH ST</b>	<b>24</b>	<b>322</b>
<b>COTINENTAL BAKING COMP</b>	<b>171 14TH ST</b>	<b>27</b>	<b>327</b>
<b>TRIANGLE PROPERTY</b>	<b>65 13TH ST</b>	<b>28</b>	<b>338</b>
<b>SAN DIEGO GAS &amp; ELECTRIC</b>	<b>14TH ST / IMPERIAL</b>	<b>28</b>	<b>340</b>
<b>INTERSTATE BRANDS CORP.</b>	<b>1401 IMPERIAL AV</b>	<b>28</b>	<b>342</b>
<b>SDG &amp; E PROPERTY</b>	<b>0 IMPERIAL AV</b>	<b>28</b>	<b>347</b>
<b>METROPOLITAN TRANSIT DEV BOARD</b>	<b>1255 IMPERIAL AV</b>	<b>28</b>	<b>348</b>
<b>SQUIRES BELT MATERIAL CO</b>	<b>149 12TH AV</b>	<b>28</b>	<b>355</b>
<b>VITAGOLD BRANDS COOP AT0726</b>	<b>2121 IMPERIAL AV</b>	<b>29</b>	<b>366</b>
<b>UNIVERSAL RADIATOR SHOP</b>	<b>2005 IMPERIAL AV</b>	<b>29</b>	<b>375</b>
<b>FIRST CHOICE</b>	<b>24 21ST ST</b>	<b>29</b>	<b>382</b>
<b>CITY OF SAN DIEGO</b>	<b>800 HARBOR DR</b>	<b>30</b>	<b>387</b>
<b>MTDB LEASEHOLD</b>	<b>93 08TH AV</b>	<b>30</b>	<b>390</b>
<b>PLANT PRODUCTS &amp; SUPPLY CO</b>	<b>822 IMPERIAL AV</b>	<b>30</b>	<b>394</b>
<b>CITY OF SAN DIEGO</b>	<b>800 IMPERIAL AV</b>	<b>30</b>	<b>399</b>
<b>MARATHON LAND &amp; CATILE</b>	<b>2682 IMPERIAL AV</b>	<b>32</b>	<b>407</b>
<b>IMPERIAL AVENUE APARTMENTS</b>	<b>2701 IMPERIAL AV</b>	<b>32</b>	<b>410</b>
<b>ARCO 9560</b>	<b>2502 IMPERIAL AV</b>	<b>34</b>	<b>427</b>
<b>EL GUERO TIRE SHOP &amp; REPAIR</b>	<b>2401 IMPERIAL AV</b>	<b>36</b>	<b>436</b>
<b>BILL ALLEN/ ELMER'S AUTO</b>	<b>1902 NATIONAL AVE</b>	<b>37</b>	<b>462</b>
<b>URBAN CORPS OF SAN DIEGO</b>	<b>1864 NATIONAL AV</b>	<b>37</b>	<b>473</b>
<b>FRASER'S BOILER SERVICE, INC.</b>	<b>1746 NEWTON AV</b>	<b>37</b>	<b>493</b>
<b>D'ARCH ENTERPRISES</b>	<b>1879 LOGAN AV</b>	<b>37</b>	<b>500</b>
<b>LOGAN HEIGHTS FAMILY HEALTH CT</b>	<b>1809 NATIONAL AV</b>	<b>37</b>	<b>510</b>
<b>YE OLDE TOWN PUMP</b>	<b>1792 NATIONAL AV</b>	<b>37</b>	<b>522</b>
<b>TROPIC ICE CREAM CO</b>	<b>1776 NATIONAL AV</b>	<b>37</b>	<b>529</b>
<b>SUPER WELDING OF SO. CA., INC.</b>	<b>1702 NATIONAL AV</b>	<b>37</b>	<b>573</b>
<b>SAN DIEGO SAW AND KNIFE WORKS</b>	<b>1765 LOGAN AVE</b>	<b>37</b>	<b>578</b>
<b>ACTION CLEANING</b>	<b>1604 NEWTON AV</b>	<b>37</b>	<b>618</b>
<b>CENTER CITY TOWING</b>	<b>1668 NATIONAL AV</b>	<b>37</b>	<b>634</b>
<b>SAN DIEGO TROLLEY, INC</b>	<b>1535 NEWTON AV</b>	<b>37</b>	<b>650</b>
<b>CENTRAL MEAT &amp; PROVISION CO</b>	<b>1603 NATIONAL AVE</b>	<b>37</b>	<b>671</b>
<b>GRAYBILL TERMINALS CO</b>	<b>1531 NATIONAL AV</b>	<b>37</b>	<b>676</b>
<b>HUGHES ATTORNEY SERVICE INC</b>	<b>1643 LOGAN AV</b>	<b>37</b>	<b>689</b>

## EXECUTIVE SUMMARY

Site	Address	Map ID	Page
<b>PEPPER INDUSTRIES INC</b>	<b>1501 NATIONAL AVE</b>	<b>37</b>	<b>695</b>
<b>LUIS AUTO SERVICES</b>	<b>1603 LOGAN AV</b>	<b>37</b>	<b>704</b>
<b>RELIABLE PIPE SUPPLY</b>	<b>1430 NATIONAL AV</b>	<b>37</b>	<b>707</b>
<b>PENSKE TRUCK LEASING INC</b>	<b>1402 COMMERCIAL ST</b>	<b>37</b>	<b>714</b>
ST.VINCENT DE PAUL	16 15TH ST	37	731
<b>SAINT VINCENT DE PAUL</b>	<b>1501 IMPERIAL AV</b>	<b>37</b>	<b>740</b>
STUDIO 15	70 15TH ST	37	744
<b>CATELLUS DEVELOPMENT PROPERTY</b>	<b>702 HARBOR DR</b>	<b>39</b>	<b>752</b>
<b>EL DORADO SANDBLASTING CO</b>	<b>2694 COMMERCIAL ST</b>	<b>40</b>	<b>759</b>
<b>ELDORADO SAND BLASTING</b>	<b>2675 COMMERCIAL ST</b>	<b>40</b>	<b>767</b>
<b>SDUSD - MAINTENANCE</b>	<b>1826 IRVING AV</b>	<b>42</b>	<b>778</b>
<b>SD PORT DISTRICT MAINT DEPT</b>	<b>825 E HARBOR DR</b>	<b>45</b>	<b>790</b>
<b>RALSTON PURINA/VAN CAMP</b>	<b>1025 E HARBOR DR</b>	<b>49</b>	<b>800</b>
<b>INTERSTATE BRANDS CORPORATION</b>	<b>1955 JULIAN AVE</b>	<b>52</b>	<b>813</b>
<b>YOUNGS MARKET CO</b>	<b>1709 MAIN ST</b>	<b>53</b>	<b>831</b>
<b>JR GAS AND MINI MART</b>	<b>505 S 30TH ST</b>	<b>54</b>	<b>839</b>
<b>P&amp;L KNEPP TRUCKING</b>	<b>2001 MAIN ST</b>	<b>55</b>	<b>864</b>
<b>A O REED</b>	<b>1990 MAIN ST</b>	<b>55</b>	<b>885</b>
<b>SDG &amp; E</b>	<b>2043 NEWTON AV</b>	<b>55</b>	<b>893</b>
<b>TUNA CLIPPER MARINE</b>	<b>1444 CROSBY ST</b>	<b>55</b>	<b>899</b>
<b>MERCADO COMMERCIAL CENTER</b>	<b>1920 MAIN ST</b>	<b>55</b>	<b>934</b>
FORMER NATIONAL PUMP AND	1901 MAIN ST	55	954
<b>JOHNSON TRUCK REPAIR &amp; PAINT</b>	<b>1931 NEWTON AV</b>	<b>55</b>	<b>968</b>
<b>THE SHERWIN-WILLIAMS CO., PRO-</b>	<b>2646 MAIN ST</b>	<b>59</b>	<b>1025</b>
<b>I M S RECYCLING SVC IRON DEPT</b>	<b>2740 BOSTON AV</b>	<b>59</b>	<b>1121</b>
<b>MEDLAND CONTROLS INC</b>	<b>2393 NEWTON AV</b>	<b>59</b>	<b>1134</b>
<b>UNION ELECTRIC MOTOR SERVICE</b>	<b>2777 NEWTON AV</b>	<b>59</b>	<b>1142</b>
<b>FORDS &amp; FOREIGN AUTO PARTS</b>	<b>2335 NEWTON AV</b>	<b>59</b>	<b>1179</b>
<b>BARRIO STATION INC</b>	<b>2320 NEWTON AV</b>	<b>59</b>	<b>1185</b>
<b>ABC CONSTRUCTION CO</b>	<b>2665 NATIONAL AVENUE</b>	<b>59</b>	<b>1213</b>
<b>SAN DIEGO EXPRESS</b>	<b>2635 LOGON ST</b>	<b>59</b>	<b>1254</b>
<b>CALIFORNIA METAL FORMING</b>	<b>2183 NATIONAL AV</b>	<b>59</b>	<b>1262</b>
<b>FREIGHT HANDLERS INC</b>	<b>1790 WATER ST</b>	<b>61</b>	<b>1308</b>
<b>S D UNIFIED SCHOOL DISTRICT</b>	<b>3550 LOGAN AV</b>	<b>62</b>	<b>1314</b>
PRAXAIR	2205 NEWTON AV	63	1326
<b>CARLSON &amp; BEAULOYE MACHINE SHO</b>	<b>2141 NEWTON AVE</b>	<b>63</b>	<b>1332</b>
<b>CP KELCO</b>	<b>2025 HARBOR DR</b>	<b>68</b>	<b>1414</b>
<b>AMERICAN KELP</b>	<b>2190 MAIN ST</b>	<b>69</b>	<b>1468</b>
<b>TANK #801 &amp; #802 *</b>	<b>2141 MAIN ST</b>	<b>69</b>	<b>1485</b>
<b>PORT OF SAN DIEGO</b>	<b>1875 WATER ST</b>	<b>70</b>	<b>1498</b>
<b>MARTINEZ AUTO REPAIR</b>	<b>3369 NATIONAL AV</b>	<b>71</b>	<b>1511</b>
<b>USA GASOLINE CORP #50</b>	<b>3502 NATIONAL AV</b>	<b>72</b>	<b>1516</b>
<b>AMERICAN FORKLIFT/J MAGRE</b>	<b>3485 NATIONAL AV</b>	<b>72</b>	<b>1529</b>
<b>GENERAL AUTO REPAIR</b>	<b>3451 NATIONAL AV</b>	<b>72</b>	<b>1536</b>
<b>CAL SOFT WATER SERVICE INC</b>	<b>3094 NATIONAL AVE</b>	<b>74</b>	<b>1558</b>
<b>HOLSUM BAKING CO</b>	<b>2828 NATIONAL AVE</b>	<b>76</b>	<b>1570</b>
<b>AUTOZONE #5674</b>	<b>2865 NATIONAL AV</b>	<b>77</b>	<b>1576</b>
<b>DORMANS TIRE CO</b>	<b>2385 MAIN ST</b>	<b>78</b>	<b>1580</b>
<b>SAN DIEGO EXPRESS INC</b>	<b>2304 MAIN ST</b>	<b>78</b>	<b>1594</b>
<b>SOUTHWEST MARINE</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1602</b>
<b>SAN DIEGO MUSEUM OF ART</b>	<b>2286 MAIN ST</b>	<b>78</b>	<b>1606</b>
SOUTHWEST MARINE INC	1427 W SAMPSON ST	79	1628
<b>ISP ALGINATES INCORPORATED</b>	<b>2145 E. BELT STREET</b>	<b>79</b>	<b>1665</b>
<b>SILVERGATE POWER PLANT</b>	<b>1348 SAMPSON ST</b>	<b>79</b>	<b>1674</b>
<b>CONTINENTAL MARITIME OF SAN DI</b>	<b>1995 BAY FRONT STREET</b>	<b>79</b>	<b>1682</b>
<b>TEXACO MARKETING</b>	<b>1145 S 28TH ST</b>	<b>80</b>	<b>1723</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>SAN DIEGO HOUSING COMMISSION</b>	<b>2883 BOSTON AV</b>	<b>82</b>	<b>1746</b>
<b>ALCORN FENCE COMPANY DBA ATLAS</b>	<b>1211 S 32ND ST</b>	<b>83</b>	<b>1757</b>
<b>CHEVRON USA INC.</b>	<b>2351 HARBOR DR</b>	<b>84</b>	<b>1772</b>
<b>CHEVRON USA INC.</b>	<b>2351 E HARBOR DR</b>	<b>84</b>	<b>1773</b>
<b>ARCO SAN DIEGO TERMINAL</b>	<b>2295 HARBOR DR E</b>	<b>84</b>	<b>1794</b>
<b>ARC CASTLE ELECTRONICS</b>	<b>3106 MAIN ST</b>	<b>86</b>	<b>1837</b>
<b>IMS RECYCLING SERVICES INC</b>	<b>1345 SOUTH 27TH ST</b>	<b>88</b>	<b>1873</b>
<b>THE SICKLES GROUP</b>	<b>2795 MAIN ST</b>	<b>88</b>	<b>1886</b>
<b>MARKEL OHNSON</b>	<b>2697 MAIN ST</b>	<b>88</b>	<b>1904</b>
<b>J J AUTO BODY</b>	<b>2694 MAIN ST</b>	<b>88</b>	<b>1914</b>
<b>BILL LEONG'S IMPORT/EXPORT</b>	<b>1531 RIGEL ST</b>	<b>90</b>	<b>1928</b>
<b>US COAST GUARD AIR STATION</b>	<b>2710 HARBOR DR</b>	<b>91</b>	<b>1936</b>
<b>BABYLAND DIAPER SERVICE</b>	<b>3348 MAIN ST</b>	<b>94</b>	<b>2013</b>
<b>AEROSPACE COATINGS &amp; TECH</b>	<b>1610 RIGEL ST</b>	<b>94</b>	<b>2052</b>
<b>ARATEX SERVICES</b>	<b>3504 MAIN ST</b>	<b>101</b>	<b>2078</b>
<b>APPLIED ENERGY AT NAVSTA</b>	<b>3970 SURFACE NAVY B-342</b>	<b>101</b>	<b>2100</b>
<b>AMERICAN LINEN</b>	<b>3460 MAIN ST</b>	<b>101</b>	<b>2152</b>
<b>AMRICAN UNIFORM &amp; TOWEL SUPPLY</b>	<b>3440 MAIN ST</b>	<b>101</b>	<b>2158</b>
<b>AMERICAN LINEN SUPPLY</b>	<b>3410 MAIN ST</b>	<b>101</b>	<b>2164</b>
<b>SUNDANCE STAGE LINES INC</b>	<b>3762 MAIN ST</b>	<b>104</b>	<b>2189</b>
<b>ESPARZA'S USED TIRES</b>	<b>3698 MAIN ST</b>	<b>104</b>	<b>2257</b>
<b>TRANS TECH TRANSMISSIONS</b>	<b>3644 MAIN ST</b>	<b>104</b>	<b>2276</b>
<b>C AND B AUTO REPAIR</b>	<b>3683 DALBERGIA ST</b>	<b>104</b>	<b>2305</b>
<b>CHICKS ELECTRIC</b>	<b>3592 MAIN ST</b>	<b>104</b>	<b>2323</b>
<b>ARAMARK UNIFORM SERVICE INC</b>	<b>3554 DALBERGIA ST</b>	<b>104</b>	<b>2388</b>
<b>GENERAL DYNAMICS CONVAIR</b>	<b>2980 HARBOR DR</b>	<b>105</b>	<b>2418</b>
<b>ONE TEN LIQUOR STORE</b>	<b>110 NATIONAL CITY BL</b>	<b>109</b>	<b>2449</b>
<b>NATIONAL MOBIL SERVICE STATION</b>	<b>10 OSBORN ST</b>	<b>109</b>	<b>2450</b>
<b>DIVISION SHELL SERVICE</b>	<b>3890 DIVISION ST</b>	<b>109</b>	<b>2470</b>
<b>HOLIDAY INN SAN DIEGO SOUTH BA</b>	<b>700 NATIONAL CITY BL</b>	<b>112</b>	<b>2483</b>
<b>ARCO FACILITY NO. 9565</b>	<b>801 ROOSEVELT AV</b>	<b>114</b>	<b>2494</b>
<b>CHEVRON #98225</b>	<b>105 W 08TH ST</b>	<b>114</b>	<b>2502</b>

**ENVIROSTOR:** The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifies sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 02/26/2008 has revealed that there are 46 ENVIROSTOR sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<b>5TH &amp; "E"</b> Facility Status: Refer: 1248 Local Agency	<b>525 "E" STREET</b>	<b>3</b>	<b>4</b>
<b>MIDAS MUFFLER(FORMER)</b> Facility Status: Refer: 1248 Local Agency	<b>668 SIXTH AVENUE</b>	<b>4</b>	<b>5</b>

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
NORTH BLOCK LOFTS Facility Status: Refer: 1248 Local Agency	735 6TH AVE.	4	6
11TH & "G" Facility Status: Refer: 1248 Local Agency	1122 "G" STREET	7	41
YELLOW CAB OF SAN DIEGO Facility Status: Refer: 1248 Local Agency	639 13 STREET	8	51
GOODWILL PROPERTY Facility Status: Refer: 1248 Local Agency	626-630 FRONT STREET	9	68
PACIFIC AIRMOTIVE Facility Status: Refer: Other Agency	544 7TH AVENUE	12	84
ISLAND AVE. AUTO SHOP Facility Status: Refer: 1248 Local Agency	1434-90 ISLAND AVENUE	15	116
<b>CONWAY TRUST &amp; DT SAN DIEGO LL</b> Facility Status: Refer: 1248 Local Agency	<b>427 9TH AVE</b>	<b>17</b>	<b>139</b>
CONTINENTAL CLEANERS Facility Status: Refer: 1248 Local Agency	450 10TH AVENUE	17	145
FISCHER PARCEL Facility Status: Refer: 1248 Local Agency	304 J STREET	20	157
SAN DIEGO GAS AND ELECTRIC STA Facility Status: Refer: 1248 Local Agency	250 10TH AVENUE	21	240
<b>DONALD C HARDER, INC</b> Facility Status: No Further Action	<b>2580 K ST</b>	<b>23</b>	<b>275</b>
CROWN BAY Facility Status: Refer: 1248 Local Agency	4TH / K	26	326
CAMACHO IRON WORKS Facility Status: Refer: 1248 Local Agency	3056 IMPERIAL AVENUE	31	403
<b>CAMPBELL'S SHIPYARD</b> Facility Status: Refer: Other Agency	<b>501 HARBOR DR</b>	<b>33</b>	<b>414</b>
TRIAD MARINE & INDUSTRIAL CLEA Facility Status: Refer: RCRA	1668 NATIONAL AVE.	37	627
GRAYBILL TERMINAL(FORMER) Facility Status: Refer: 1248 Local Agency	1551 NATIONAL AVENUE	37	684
<b>STUDIO 15</b> Facility Status: Active	<b>70 15TH STREET</b>	<b>37</b>	<b>745</b>
GIFFORD'S BARRELS Facility Status: Refer: Other Agency	2606 COMMERCIAL STREET	41	772
BRIDGE HOUSING Facility Status: Refer: RWQCB	1826 IRVING AVENUE	42	776
CONTROLS ENGINEERING MAINTENAN Facility Status: Refer: 1248 Local Agency	105 SOUTH 31ST STREET	43	788
MTDB LEASEHOLD Facility Status: Refer: 1248 Local Agency	93 8TH AVENUE	45	798
TOSCO IDLE PIPELINE Facility Status: Refer: 1248 Local Agency	8TH STREET/HARBOR AVE.	46	799
ALLIED TANK CLEANING CORP Facility Status: Refer: Other Agency	1883 EAST HARBOR DRIVE	55	924

## EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
NATIONAL PUMP INJECTOR(FORMER) Facility Status: Refer: 1248 Local Agency	1901 MAIN STREET	55	948
<b>BURBANK ELEMENTARY EXPANSION</b> Facility Status: Certified	<b>2146 JULIAN AVENUE</b>	<b>56</b>	<b>999</b>
AUGUST'S FOUNDRY Facility Status: Refer: Other Agency	2320 NEWTON AVENUE	59	1184
<b>LAURA G. RODRIGUEZ ELEMENTARY</b> Facility Status: Active	<b>32ND STREET/GREELY AVEN</b>	<b>60</b>	<b>1295</b>
<b>MEMORIAL AREA MIDDLE SCHOOL AL</b> Facility Status: Inactive - Action Required	<b>43RD STREET/LOGAN AVENU</b>	<b>65</b>	<b>1368</b>
<b>KENNEDY/KNOX SCHOOL SITE NO. 1</b> Facility Status: Inactive - Needs Evaluation	<b>DOMINION STREET/LOGAN A</b>	<b>66</b>	<b>1370</b>
CP KELCO Facility Status: Refer: 1248 Local Agency	2025 E. HARBOR DRIVE	68	1433
CLEANING DYNAMICS/PACIFIC TREA Facility Status: Refer: RCRA	2190 MAIN STREET	69	1466
<b>Not reported</b> Facility Status: Refer: 1248 Local Agency	<b>2295 BELT STREET</b>	<b>79</b>	<b>1615</b>
<b>Not reported</b> Facility Status: Refer: 1248 Local Agency	<b>2145 EAST BELT STREET</b>	<b>79</b>	<b>1655</b>
<b>KENNEDY/KNOX SCHOOL SITE NO. 2</b> Facility Status: Inactive - Needs Evaluation	<b>43RD STREET/KEELER AVEN</b>	<b>81</b>	<b>1742</b>
<b>CASINO ELECTRIC COMPANY INC</b> Facility Status: Refer: 1248 Local Agency	<b>3106 MAIN STREET</b>	<b>86</b>	<b>1841</b>
<b>MEMORIAL AREA MIDDLE SCHOOL AL</b> Facility Status: Inactive - Action Required	<b>4103 BETA STREET</b>	<b>96</b>	<b>2057</b>
<b>SLOAN ELECTRIC CO</b> Facility Status: Refer: Other Agency	<b>3520 MAIN ST</b>	<b>101</b>	<b>2068</b>
<b>MCAS MIRAMAR</b> Facility Status: Active	<b>OFF OF MIRAMAR BOULEVAR</b>	<b>101</b>	<b>2103</b>
<b>SAN DIEGO NAVAL STATION - SITE</b> Facility Status: Certified	<b>SAN DIEGO BAY, 113 NAVA</b>	<b>101</b>	<b>2143</b>
OLD SCHOOLHOUSE SQUARE Facility Status: Refer: 1248 Local Agency	550 E. 8TH STREET, SUIT	111	2482
<b>OFFICE OF EDUCATION BUILDING</b> Facility Status: Inactive - Action Required	<b>NATIONAL CITY BOULEVARD</b>	<b>113</b>	<b>2486</b>
EDUCATION VILLAGE Facility Status: Refer: 1248 Local Agency	801 ROOSEVELT AVE.	114	2490
COLONIAL FORD (FORMER) Facility Status: Refer: 1248 Local Agency	1401 NATIONAL CITY BLVD	116	2552
<b>Not reported</b> Facility Status: Refer: Other Agency	<b>1211 MCKINLEY AVE</b>	<b>117</b>	<b>2553</b>

## EXECUTIVE SUMMARY

**HAULERS:** A listing of registered waste tire haulers.

A review of the HAULERS list, as provided by EDR, and dated 04/28/2008 has revealed that there is 1 HAULERS site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
WELCHS TIRES, INC.	3724 MAIN STREET	104	2229

### **EDR PROPRIETARY RECORDS**

**Manufactured Gas Plants:** The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the Manufactured Gas Plants list, as provided by EDR, has revealed that there is 1 Manufactured Gas Plants site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
SAN DIEGO GAS WORKS	9TH STREET BTWN IMPERIA	30	390

## **EXECUTIVE SUMMARY**

Please refer to the end of the findings report for unmapped orphan sites due to poor or inadequate address information.



MAP FINDINGS SUMMARY

<u>Database</u>	<u>Total Plotted</u>
<b><u>FEDERAL RECORDS</u></b>	
NPL	0
Proposed NPL	0
Delisted NPL	0
NPL LIENS	2
CERCLIS	2
CERC-NFRAP	16
LIENS 2	1
CORRACTS	3
RCRA-TSDF	3
RCRA-LQG	13
RCRA-SQG	93
RCRA-CESQG	3
RCRA-NonGen	22
US ENG CONTROLS	0
US INST CONTROL	0
ERNS	41
HMIRS	1
DOT OPS	1
US CDL	0
US BROWNFIELDS	1
DOD	1
FUDS	0
LUCIS	0
CONSENT	0
ROD	0
UMTRA	0
ODI	0
DEBRIS REGION 9	0
MINES	0
TRIS	5
TSCA	3
FTTS	4
HIST FTTS	5
SSTS	2
ICIS	1
PADS	3
MLTS	0
RADINFO	0
FINDS	119
RAATS	0
<b><u>STATE AND LOCAL RECORDS</u></b>	
HIST Cal-Sites	1
CA BOND EXP. PLAN	1
SCH	7
Toxic Pits	0
SWF/LF	3

MAP FINDINGS SUMMARY

<u>Database</u>	<u>Total Plotted</u>
CA WDS	15
WMUDS/SWAT	22
Cortese	127
SWRCY	5
LUST	264
CA FID UST	0
SLIC	9
UST	16
HIST UST	65
AST	5
LIENS	0
SWEEPS UST	99
CHMIRS	38
Notify 65	24
DEED	0
VCP	1
DRYCLEANERS	7
WIP	1
CDL	0
San Diego Co. HMMD	355
RESPONSE	2
HAZNET	242
AIRS	35
SAN DIEGO CO. SAM	158
ENVIROSTOR	46
HAULERS	1

**TRIBAL RECORDS**

INDIAN RESERV	0
INDIAN ODI	0
INDIAN LUST	0
INDIAN UST	0

**EDR PROPRIETARY RECORDS**

Manufactured Gas Plants	1
-------------------------	---

**NOTES:**

Sites may be listed in more than one database

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**DOD Region**      **SAN DIEGO NAVAL STATION**      **DOD**      **CUSA145737**  
**SAN DIEGO NAVAL STATION (County), CA**      **N/A**

DOD:  
 Feature 1:      Navy DOD  
 Feature 2:      Not reported  
 Feature 3:      Not reported  
 URL:      Not reported  
 Name 1:      San Diego Naval Station  
 Name 2:      Not reported  
 Name 3:      Not reported  
 State:      CA  
 DOD Site:      Yes  
 Tile name:      CASAN\_DIEGO

**1**      **1110 "C" STREET**      **Notify 65**      **S100178277**  
**SAN DIEGO, CA**      **N/A**

Notify 65:  
 Date Reported:      Not reported  
 Staff Initials:      Not reported  
 Board File Number:      Not reported  
 Facility Type:      Not reported  
 Discharge Date:      Not reported  
 Incident Description:      Not reported

**1**      **1110 "C" STREET**      **Notify 65**      **S100178324**  
**SAN DIEGO, CA**      **N/A**

Notify 65:  
 Date Reported:      Not reported  
 Staff Initials:      Not reported  
 Board File Number:      Not reported  
 Facility Type:      Not reported  
 Discharge Date:      Not reported  
 Incident Description:      Not reported

**1**      **1110 "C" STREET**      **Notify 65**      **S100178341**  
**SAN DIEGO, CA**      **N/A**

Notify 65:  
 Date Reported:      Not reported  
 Staff Initials:      Not reported  
 Board File Number:      Not reported  
 Facility Type:      Not reported  
 Discharge Date:      Not reported  
 Incident Description:      Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site Database(s) EDR ID Number  
 EPA ID Number

1 **11TH / "C" STREET** **Notify 65** **S100178342**  
**SAN DIEGO, CA** **N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: Not reported

2 **15TH / BROADWAY** **Notify 65** **S100178406**  
**SAN DIEGO, CA** **N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: Not reported

2 **15TH / BROADWAY** **Notify 65** **S100178353**  
**SAN DIEGO, CA** **N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: Not reported

3 **5TH & "E"** **ENVIROSTOR** **S106893815**  
**525 "E" STREET** **N/A**  
**SAN DIEGO, CA 92101**

ENVIROSTOR:  
 Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000056  
 Site Code: Not reported  
 Assembly: 76  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-02-10 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**5TH & "E" (Continued)**

**S106893815**

Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37000056  
 Alias Type: Envirostor ID Number  
  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.  
  
 Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 02/10/00  
  
 Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported  
  
 Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

**4 MIDAS MUFFLER(FORMER)  
 668 SIXTH AVENUE  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106893866  
 N/A**

ENVIROSTOR:  
 Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37750011  
 Site Code: Not reported  
 Assembly: 76  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-04-24 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIDAS MUFFLER(FORMER) (Continued)**

**S106893866**

Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37750011  
 Alias Type: Envirostor ID Number  
  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.  
  
 Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 04/24/00  
  
 Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported  
  
 Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

**4 NORTH BLOCK LOFTS  
 735 6TH AVE.  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106797688  
 N/A**

ENVIROSTOR:  
 Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000036  
 Site Code: Not reported  
 Assembly: 76  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-05-30 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH BLOCK LOFTS (Continued)**

**S106797688**

Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37000036  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

**5 SHELL SEERRVICE STATION  
 1619 G STREET  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000288340  
 FINDS CAD981158645  
 LUST**

RCRA-SQG:  
 Date form received by agency: 09/08/2000  
 Facility name: SHELL SERVICE STATION  
 Facility address: 1619 G ST  
 S A P 135916  
 SAN DIEGO, CA 92101

EPA ID: CAD981158645  
 Mailing address: P O BOX 2099  
 HOUSTON, TX 772522099

Contact: SONDR A BIENVENU  
 Contact address: P O BOX 2099  
 HOUSTON, TX 772522099

Contact country: US  
 Contact telephone: (713) 241-5036  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL SEERRVICE STATION (Continued)**

**1000288340**

Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: EQUILON ENTERPRISE L L C  
 Owner/operator address: P O BOX 2099  
 HOUSTON, TX 77252  
 Owner/operator country: Not reported  
 Owner/operator telephone: (713) 241-5036  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:

Waste code: D000  
 Waste name: Not Defined

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHELL SEERRVICE STATION (Continued)**

**1000288340**

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018  
 Waste name: BENZENE  
 Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**LUST:**

Region: 9  
 Case Number: 9UT3948  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: 0  
 Date Found: 05/07/1999  
 How Found: Tank Closure  
 Date Stopped: 05/07/1999  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 07/13/1999  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H03160-002  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: Not reported  
 Release Date: 05/07/1999

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**SHELL SEERRVICE STATION (Continued)**

**1000288340**

Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**5 MIKE RUDIN AUTOMOTIVE**  
**1616 G ST**  
**SAN DIEGO, CA 92101**

**RCRA-SQG 1000818570**  
**FINDS CAD983644527**  
**HAZNET**  
**LUST**  
**Cortese**  
**San Diego Co. HMMD**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

**RCRA-SQG:**

Date form received by agency: 07/31/1992  
 Facility name: MIKE RUDIN AUTOMOTIVE  
 Facility address: 1616 G ST  
 SAN DIEGO, CA 92101  
 EPA ID: CAD983644527  
 Mailing address: G ST  
 SAN DIEGO, CA 92101  
 Contact: WAYNE CARROLL  
 Contact address: 1616 G ST  
 SAN DIEGO, CA 92101  
 Contact country: US  
 Contact telephone: (619) 234-7366  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: MIKE RUDIN  
 Owner/operator address: 1616 G ST  
 SAN DIEGO, CA 92101  
 Owner/operator country: Not reported  
 Owner/operator telephone: (609) 234-7366  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIKE RUDIN AUTOMOTIVE (Continued)**

**1000818570**

User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAL000058286  
 Contact: INACTIVE DUP NUM IN BLK LOGBK  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1616 G ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017335  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Not reported  
 Tons: 0.72  
 Facility County: Not reported

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300393  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1998-04-30 00:00:00  
 Discover Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MIKE RUDIN AUTOMOTIVE (Continued)**

**1000818570**

Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: DON CLARK  
 RP Address: 3732 GARDEN LANE  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H19682-001  
 Case Number: 9UT1573  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT1573  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 10/27/1989  
 How Found: Tank Closure  
 Date Stopped: 10/27/1989  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIKE RUDIN AUTOMOTIVE (Continued)**

**1000818570**

Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 11/15/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 01/25/1993  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 4/30/98  
 Pilot Program: LOP  
 Local Case: H19682-001  
 Basin Number: 908.21  
 Gwater Depth: 37'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 11/14/1989  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1616 G ST

San Diego Co. HMMID:  
 Facility ID: 119682  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1616 G ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 52  
 EPA ID: CAD983644527  
 Gas Station: Not reported  
 Inspection Date: 12/19/94  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: WAYNE CARROLL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIKE RUDIN AUTOMOTIVE (Continued)**

**1000818570**

Last Letter Type: Not reported  
 Property Owner: BROWN JAMES S REVOCABLE TRUST  
 Property Address: 3691 VIA MERCADO #12  
 Property City,St,Zip: 91941  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-7366

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/19/94  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1736  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/19/94  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 1737  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MIKE RUDIN AUTOMOTIVE (Continued)**

**1000818570**

Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 19682  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-019682-000001  
 Actv Date: Not reported  
 Capacity: 1250  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 19682  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-019682-000002  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 19682  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIKE RUDIN AUTOMOTIVE (Continued)**

**1000818570**

Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H19682-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 4/30/1998  
 Begandt: 10/27/1989

5

**SHELL OIL PRODUCTS COMPANY  
 1619 G ST  
 SAN DIEGO, CA 92101**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 AIRS  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S102769861  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607302278  
 Stop Date: 1997-05-23 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1998-07-07 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1997-05-23 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1997-05-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Unleaded Gasoline



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Contact Person: Not reported  
 Responsible Party: Marvin Katz  
 RP Address: 2266 WESTLAND AVE  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03160-001  
 Case Number: 9UT3510  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607399176  
 Stop Date: 1999-05-07 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2002-01-30 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1999-05-07 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-05-07 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: PAUL VIDAKOVICH  
 RP Address: 9966 SAN DIEGO MISSION  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03160-002  
 Case Number: 9UT3948  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT3510  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 05/23/1997  
 How Found: Other Means  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 05/23/1997  
 Desc Pollution: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H03160-001  
 Basin Number: 908.22  
 Gwater Depth: 35'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 05/27/1997  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: Not reported

**San Diego Co. HMMD:**

Facility ID: 103160  
 Inactive Indicator: Active  
 Business Code: 6HK29  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1619 G ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 52  
 EPA ID: CAD981158645  
 Gas Station: Not reported  
 Inspection Date: 07/21/03  
 Reinspection Date: Not reported  
 Inspector Name: RHANSEN  
 Violation Notice Issued: Not reported  
 Facility Contact: TAMI FAHEY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BAGDASAR AMAD E&MANAL  
 Property Address: 1619 G ST  
 Property City,St,Zip: 92101  
 Tank Owner: EQUILON ENTERPRISES LLC  
 Tank Address: P.O. BOX 4453  
 Tank City,St,Zip: Houston, TX 77210  
 Business Plan Acceptance Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 235-6742

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T005  
 Tank ID Number: 5  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T006  
 Tank ID Number: RT1227  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T007  
 Tank ID Number: RT1227  
 Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

Tank Number: T008  
 Tank ID Number: RT1227 PRE  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Tank Number: T009  
 Tank ID Number: 004  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 6023  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 6024  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 02/11/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3031  
 Occurrences: Not reported  
 Item Number: 1163  
 Violation Desc: FAILURE TO REPORT/RESPOND TO RELEASE

Inspection Date: 02/22/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2224  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/22/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2225  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/22/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 2226  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 02/22/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3030  
 Occurrences: Not reported  
 Item Number: 2227  
 Violation Desc: NO RELEASE RECORD LOG

**HMMD WASTE STREAMS:**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**EMI:**

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1227  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1227  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1227  
 Air District Name: SD  
 SIC Code: 5541

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003

Carbon Monoxide Emissions Tons/Yr: 37

Air Basin: SD

Facility ID: 1227

Air District Name: SD

SIC Code: 5541

Air District Name: SAN DIEGO COUNTY APCD

Community Health Air Pollution Info System: Not reported

Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 3

Reactive Organic Gases Tons/Yr: 3

Carbon Monoxide Emissions Tons/Yr: 0

NOX - Oxides of Nitrogen Tons/Yr: 0

SOX - Oxides of Sulphur Tons/Yr: 0

Particulate Matter Tons/Yr: 0

Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004

Carbon Monoxide Emissions Tons/Yr: 37

Air Basin: SD

Facility ID: 1227

Air District Name: SD

SIC Code: 5541

Air District Name: SAN DIEGO COUNTY APCD

Community Health Air Pollution Info System: Not reported

Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 3.024

Reactive Organic Gases Tons/Yr: 3.024

Carbon Monoxide Emissions Tons/Yr: 0

NOX - Oxides of Nitrogen Tons/Yr: 0

SOX - Oxides of Sulphur Tons/Yr: 0

Particulate Matter Tons/Yr: 0

Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005

Carbon Monoxide Emissions Tons/Yr: 37

Air Basin: SD

Facility ID: 1227

Air District Name: SD

SIC Code: 5541

Air District Name: SAN DIEGO COUNTY APCD

Community Health Air Pollution Info System: Not reported

Consolidated Emission Reporting Rule: Not reported

Total Organic Hydrocarbon Gases Tons/Yr: 3.024

Reactive Organic Gases Tons/Yr: 3.024

Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 3160  
 Number: Not reported  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000001  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 5

Status: Not reported  
 Comp Number: 3160  
 Number: Not reported  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3160  
 Number: Not reported  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000003  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Status: Not reported  
 Comp Number: 3160  
 Number: Not reported  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000004  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3160  
 Number: Not reported  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000005  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3160  
 Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000006  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 4

Status: A  
 Comp Number: 3160  
 Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000007  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3160  
 Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000008  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3160  
 Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003160-000009  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H03160-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 7/7/1998  
 Begandt: 5/23/1997

Case Number: H03160-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL OIL PRODUCTS COMPANY (Continued)**

**S102769861**

FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 1/30/2002  
 Begandt: 5/7/1999

6

**HAWTHORNE RENT-IT SERVICE  
 1473 G ST  
 SAN DIEGO, CA 92101**

**HAZNET 1000409862  
 LUST N/A  
 Cortese  
 San Diego Co. HMMD  
 HIST UST  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

HAZNET:

Gepaid: CAD981570898  
 Contact: JAMES T HAWTHORNE  
 Telephone: 6196747000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 708  
 Mailing City,St,Zip: SAN DIEGO, CA 921124125  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .2250  
 Facility County: San Diego

Gepaid: CAD981570898  
 Contact: JAMES T HAWTHORNE  
 Telephone: 6196747000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 708  
 Mailing City,St,Zip: SAN DIEGO, CA 921124125  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD981570898  
 Contact: JAMES T HAWTHORNE  
 Telephone: 6196747000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 708  
 Mailing City,St,Zip: SAN DIEGO, CA 921124125  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Transfer Station  
 Tons: .2917  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Gepaid: CAD981570898  
 Contact: JAMES T HAWTHORNE  
 Telephone: 6196747000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 708  
 Mailing City,St,Zip: SAN DIEGO, CA 921124125  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: 3.0000  
 Facility County: San Diego

Gepaid: CAD981570898  
 Contact: JAMES T HAWTHORNE  
 Telephone: 6196747000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 708  
 Mailing City,St,Zip: SAN DIEGO, CA 921124125  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .0750  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 44 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019760427  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2006-03-30 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Mary Pampuch  
 RP Address: 655 West Broadway, Suite 1450  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15607-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Tank  
 Global Id: T0607301435  
 Stop Date: 1994-02-09 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-05-11 00:00:00  
 Discover Date: 1994-02-07 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-02-09 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Paul Nieto  
 RP Address: 655 West Broadway, Ste. 1450  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15607-002  
 Case Number: 9UT2685  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Global Id: T0608194855  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-01-14 00:00:00  
 Discover Date: 1991-10-28 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-10-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15607-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

LUST:

Region: 9

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Case Number: 9UT2685  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 1000  
 Date Found: 02/10/1994  
 How Found: Tank Test  
 Date Stopped: 02/10/1994  
 How Stopped: Other Means  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 02/09/1994  
 Submit Workplan: 2/25/94  
 Prelim Assess: 03/02/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H15607-002  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 02/10/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 1473 G ST

**San Diego Co. HMMD:**

Facility ID: 115607  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 16945 CAMINO SAN BE  
 Mailing City,St,Zip: SAN DIEGO, CA 92127  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 52  
 EPA ID: CAD981570898



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Gas Station: Not reported  
 Inspection Date: 06/23/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: JEFF WOOD  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MCNITT PAUL H&WINONA  
 Property Address: 343 CASCADE RD  
 Property City,St,Zip: 92021  
 Tank Owner: HAWTHORNE RENT-IT SERVICE  
 Tank Address: 4200 KEARNY MESA RD  
 Tank City,St,Zip: San Diego, CA 92111  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 12/23/05  
 Facility Phone: 619-232-2084

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC03  
 Chemical Name: ACETYLENE NE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: DI05  
 Chemical Name: DIESEL  
 Case Number: 684-76-346  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OI04  
 Chemical Name: OIL: MOTOR, TRANSMISSION, HYDRAULIC  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Item Number: OX09  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: PR08  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: UN07  
 Chemical Name: UNLEADED GASOLINE  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ZE06  
 Chemical Name: ZEP DEGREASER WASH RACK  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 20  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 21  
 Waste or Product: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Tank Contents: DIESEL  
 Tank Number: T003  
 Tank ID Number: 22  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: 23  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 06/09/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 4435  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 06/09/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 4436  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 10/08/99  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 9155  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 04/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 4799  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 08/29/02  
 Waste Code: Not reported  
 Type of Violation: 6HR0001  
 Occurrences: Not reported  
 Item Number: 1370  
 Violation Desc: INSPECTION RECEIVED BUT NOT PROCESSED

Inspection Date: 06/23/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2491  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 06/23/04  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 2492  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

**HMMD WASTE STREAMS:**

Inspection Date: 06/23/04  
 Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE ANTIFREEZE  
 Carcinogen: No

Inspection Date: 06/23/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 12  
 Quantity String: 12  
 Annual Qty: 72  
 Annual Qty String: 72  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: PARTS WASHER-SYSTEM ONE  
 Carcinogen: No

Inspection Date: 06/23/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 250  
 Quantity String: 250  
 Annual Qty: 2500  
 Annual Qty String: 2500  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: FROM EQUIPMENT MAINTENANC  
 Carcinogen: No

Inspection Date: 06/23/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 1050  
 Quantity String: 1050

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Annual Qty: 1050  
 Annual Qty String: 1050  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: OILY ABSORBANTS  
 Carcinogen: No

Inspection Date: 06/23/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0539 NORTH STATE ENVIRONM  
 Waste Desc: USED FUEL FILTERS  
 Carcinogen: No

Inspection Date: 06/23/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qty at Inspection: 360  
 Quantity String: 360  
 Annual Qty: 720  
 Annual Qty String: 720  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: LEAD ACD BTTRS-POWER STRD  
 Carcinogen: No

Inspection Date: 06/23/04  
 Waste Item #: 860  
 Waste Code: 860  
 Waste Name: UNIVERSAL WASTE CRTS  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0539 NORTH STATE ENVIRONM  
 Waste Desc: USED AEROSOL CANS  
 Carcinogen: No

Inspection Date: 06/23/04  
 Waste Item #: 888  
 Waste Code: 888

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Waste Name: USED OIL FILTERS  
 Qty at Inspection: 600  
 Quantity String: 600  
 Annual Qty: 1200  
 Annual Qty String: 1200  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

HIST UST:

Region: STATE  
 Facility ID: 00000011098  
 Facility Type: Other  
 Other Type: EQUIPMENT RENTAL YAR  
 Total Tanks: 0008  
 Contact Name: TOM DUNCAN  
 Telephone: 6192322084  
 Owner Name: HAWTHORNE RENT-IT SERVICE  
 Owner Address: 4200 KEARNY MESA ROAD  
 Owner City,St,Zip: SAN DIEGO, CA 92111

Tank Num: 001  
 Container Num: 20  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 002  
 Container Num: 21  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 003  
 Container Num: 22  
 Year Installed: 1983  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: 06  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 004  
 Container Num: 23  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: WASTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 005  
 Container Num: 20  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 006  
 Container Num: 21  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 007  
 Container Num: 22  
 Year Installed: 1983  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: 06  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 008  
 Container Num: 23  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Visual

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 15607  
 Number: Not reported  
 Board Of Equalization: 44-021920  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015607-000004  
 Actv Date: Not reported  
 Capacity: 300  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Status: A  
 Comp Number: 15607  
 Number: 9  
 Board Of Equalization: 44-021920  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015607-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 3

Status: A  
 Comp Number: 15607  
 Number: 9  
 Board Of Equalization: 44-021920  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015607-000002  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 15607  
 Number: 9  
 Board Of Equalization: 44-021920  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015607-000003  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H15607-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HAWTHORNE RENT-IT SERVICE (Continued)**

**1000409862**

Date: 1/14/1992  
 Begandt: 10/28/1991

Case Number: H15607-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: POP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/11/2006  
 Begandt: 2/7/1994

Case Number: H15607-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 3/30/2006  
 Begandt: Not reported

7

**11TH & "G"  
 1122 "G" STREET  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106893821  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000063  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-04-24 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 11 & "G"  
 37000063  
 Alias Type: Envirostor ID Number  
 Alternate Name  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 04/24/00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**11TH & "G" (Continued)**

**S106893821**

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

8

**ROAD RUNNERS  
 544 11TH AV  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104749230  
 N/A**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300478  
 Stop Date: 1990-03-26 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-06-07 00:00:00  
 Discover Date: 1990-03-26 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-03-26 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ROAD RUNNERS (Continued)**

**S104749230**

Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: JIM MCCHESENEY  
 RP Address: 1337 MUIRLANDS VISTA WAY  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: PV  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H19859-001  
 Case Number: 9UT1663  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 119859  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1337 MUIRLANDS VIST  
 Mailing City,St,Zip: LA JOLLA, CA 92037  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 06/12/89  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ROAD RUNNERS (Continued)**

**S104749230**

Last Letter Type: Not reported  
 Property Owner: CITYMARK M2I LLC  
 Property Address: 701 B ST #1150  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ROAD RUNNERS (Continued)**

**S104749230**

SAN DIEGO CO. SAM:

Case Number: H19859-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/7/1993  
 Begandt: 3/26/1990

8

**JAMES' DETAIL SHOP  
 544 11TH ST  
 SAN DIEGO, CA 92101**

**LUST S102431868  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT1663  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 03/27/1990  
 How Found: Tank Closure  
 Date Stopped: 03/27/1990  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 03/27/1990  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 6/7/93  
 Pilot Program: LOP  
 Local Case: H19859-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 04/02/1990  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 544 11TH ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**8 WESTERN PACIFIC HOUSING  
 1147 MARKET ST  
 SAN DIEGO, CA 92101**

**HAZNET S105692342  
 LUST N/A  
 SAN DIEGO CO. SAM**

HAZNET:

Gepaid: CAC002553328  
 Contact: MICHAEL PLATZER  
 Telephone: 6192394434  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 528 5TH AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 0.91  
 Facility County: Not reported

Gepaid: CAC002553328  
 Contact: MICHAEL PLATZER  
 Telephone: 6192394434  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 528 5TH AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Recycler  
 Tons: 0.12  
 Facility County: Not reported

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608182805  
 Stop Date: 2002-02-11 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-05-07 00:00:00  
 Discover Date: 2002-02-11 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2002-02-11 00:00:00  
 Review Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**WESTERN PACIFIC HOUSING (Continued)**

**S105692342**

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13924-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H13924-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/7/2003  
 Begandt: 2/11/2002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**8 ISLAND VILLAGE APARTMENTS  
 1213 MARKET ST  
 SAN DIEGO, CA 92101**

**LUST S106874374  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0607360344  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2005-05-12 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2002-05-31 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2002-05-31 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Michael Galasso  
 RP Address: 710 West Ivy  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02862-001  
 Case Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISLAND VILLAGE APARTMENTS (Continued)**

**S106874374**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H02862-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Remedial Investigation  
 Date: 5/12/2005  
 Begandt: 5/31/2002

8

**FSE INC  
 1238-1258 MARKET ST  
 SAN DIEGO, CA 92101**

**LUST S102363532  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT3436  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 11/01/1996  
 How Found: Other Means  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 11/01/1996  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 4/29/97  
 Closed Date: 1/26/99  
 Pilot Program: LOP  
 Local Case: H36815-002  
 Basin Number: 908.21  
 Gwater Depth: 51.7  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FSE INC (Continued)**

**S102363532**

Release Date: 11/01/1996  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1238-1258 MARKET ST

8

**FRMR YELLOW CAB/NEW EV II LLC**  
**639 13TH ST**  
**SAN DIEGO, CA 92101**

**SAN DIEGO CO. SAM S108407058**  
**N/A**

SAN DIEGO CO. SAM:

Case Number: H04874-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/31/1996  
 Begandt: 5/30/1990

Case Number: H04874-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/31/1996  
 Begandt: 12/12/1991

Case Number: H04874-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/31/1996  
 Begandt: 11/23/1992

Case Number: H04874-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/22/2000  
 Begandt: 1/6/2000

Case Number: H04874-005  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 8/19/2003  
 Begandt: 8/19/2003

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**8 YELLOW CAB OF SAN DIEGO  
 639 13 STREET  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106893853  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37470002  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-02-01 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37470002  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 02/01/00

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**8 YELLOW CAB CO OF SAN DIEGO INC  
 639 13TH ST  
 SAN DIEGO, CA 92101**

**LUST 1000291256  
 Cortese N/A  
 UST  
 San Diego Co. HMMD  
 HIST UST  
 AIRS**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300818  
 Stop Date: 1990-07-09 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-01-31 00:00:00  
 Discover Date: 1990-05-30 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-06-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: ANTHONY PALMERI  
 RP Address: 639 13TH ST.  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: LS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Work Suspended: Not reported  
 Local Case #: H04874-001  
 Case Number: 9UT2048  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300966  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-01-31 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: TONY PALMERI  
 RP Address: 639 13TH ST.  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Staff Initials: LS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04874-002  
 Case Number: 9UT2199  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301077  
 Stop Date: 1992-11-23 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-01-31 00:00:00  
 Discover Date: 1992-11-23 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-11-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: TONY PALMERI  
 RP Address: 639 13TH ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: LS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04874-003  
 Case Number: 9UT2309  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607376944  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2003-08-19 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Robert G. Russell, Jr.  
 RP Address: 530 B Street, Ste. 2100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04874-005  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608115669  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-09-22 00:00:00  
 Discover Date: 2000-01-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-01-06 00:00:00  
 Review Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: WILLIAM PATCH  
 RP Address: 9191 TOWNE CENTRE DR #310  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JN  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04874-004  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT2048  
 Local Agency: San Diego  
 Substance: Regular Gasoline  
 Qty Leaked: 0  
 Date Found: 07/30/1991  
 How Found: Other Means  
 Date Stopped: 07/30/1991  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Confirm Date: 07/30/1991  
 Submit Workplan: 9/17/91  
 Prelim Assess: 08/27/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/31/96  
 Pilot Program: LOP  
 Local Case: H04874-001  
 Basin Number: 908.21  
 Gwater Depth: >10'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - ADMINISTRATIVE (CLOSURE/SB2004/ENFORCEMENT)  
 File Dispn: File discarded, case closed  
 Release Date: 07/30/1991  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported  
  
 Region: 9  
 Case Number: 9UT2199  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 12/12/1991  
 How Found: Other Means  
 Date Stopped: 12/12/1991  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
  
 Confirm Date: 12/12/1991  
 Submit Workplan: Not reported  
 Prelim Assess: 01/07/1991  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/31/96  
 Pilot Program: LOP  
 Local Case: H04874-002  
 Basin Number: 908.21  
 Gwater Depth: >10'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - ADMINISTRATIVE (CLOSURE/SB2004/ENFORCEMENT)  
 File Dispn: File discarded, case closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Release Date: 12/12/1991  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT2309  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 11/24/1992  
 How Found: Tank Closure  
 Date Stopped: 11/23/1992  
 How Stopped: Close Tank  
 Source: Piping  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: No Action Taken - no action has as yet been taken at the site  
 Confirm Date: 11/24/1992  
 Submit Workplan: 1/21/93  
 Prelim Assess: 07/15/1993  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/31/96  
 Pilot Program: LOP  
 Local Case: H04874-003  
 Basin Number: 908.21  
 Gwater Depth: >16'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - ADMINISTRATIVE (CLOSURE/SB2004/ENFORCEMENT)  
 File Disp: File discarded, case closed  
 Release Date: 11/24/1992  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 639 13TH ST

Region: CORTESE  
 Facility Addr2: 639 13TH ST

Region: CORTESE  
 Facility Addr2: 639 13TH ST

**UST:**

Local Agency: 37000  
 Facility ID: H04874

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

San Diego Co. HMMD:

Facility ID: 203855  
 Inactive Indicator: Active  
 Business Code: 6HK24  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 639 13TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 52  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/05/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: TONY PALMERI  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: P P D SAN DIEGO PROJECT OWNER  
 Property Address: C/O MARK CASSIDY  
 Property City,St,Zip: 89109  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/05/06  
 Facility Phone: 619-239-8061

HMMD DISCLOSURE INVENTORY:

Item Number: AC59  
 Chemical Name: ACETYLENE GAS  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR58  
 Chemical Name: ARGON/CO2 MIG MIX WELDING GAS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: CA60  
 Chemical Name: CARBON DIOXIDE GAS  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: OI71  
 Chemical Name: OILS, LUBRICATING  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX61  
 Chemical Name: OXYGEN GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 08/05/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: PAINT BOOTH FILTERS  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 212  
 Waste Code: 212  
 Waste Name: OXYGENATED SOLVENTS  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: BRAKE WASHER  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Carcinogen: No  
 Inspection Date: 08/05/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 5000  
 Annual Qty String: 5000  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: OILY ABSORBENT  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: ANTIFREEZE  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Storage Method: BOX  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED LEAD ACID BATTERIES  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 451  
 Waste Code: 451  
 Waste Name: DEGREASING SLUDGE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 3300  
 Annual Qty String: 3300  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: SUMP SLUDGE (2 SUMPS)  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 860  
 Waste Code: 860  
 Waste Name: UNIVERSAL WASTE CRTS  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: EMPTY AEROSOL CANS  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 5000



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Annual Qty String: 5000  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: Not reported  
 Carcinogen: No

**HIST UST:**

Region: STATE  
 Facility ID: 00000032997  
 Facility Type: Other  
 Other Type: TAXICAB  
 Total Tanks: 0008  
 Contact Name: R.A. MATTHEWS  
 Telephone: 6192398061  
 Owner Name: YELLOW CAB COMPANY OF SAN DIEG  
 Owner Address: 639 13TH STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00004000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 004  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00004000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: 10

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Tank Num: 005  
 Container Num: K  
 Year Installed: 1978  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 006  
 Container Num: 6  
 Year Installed: 1981  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 007  
 Container Num: 7  
 Year Installed: 1960  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 008  
 Container Num: 8  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: None

**EMI:**

Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	3415
Air District Name:	SD
SIC Code:	4121
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Facility ID: 3415  
 Air District Name: SD  
 SIC Code: 4121  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 3415  
 Air District Name: SD  
 SIC Code: 4121  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 3415  
 Air District Name: SD  
 SIC Code: 4121  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 3415  
 Air District Name: SD  
 SIC Code: 4121  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YELLOW CAB CO OF SAN DIEGOINC (Continued)**

**1000291256**

Total Organic Hydrocarbon Gases Tons/Yr:	0.187616016
Reactive Organic Gases Tons/Yr:	0.17304
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	3415
Air District Name:	SD
SIC Code:	4121
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.187616016
Reactive Organic Gases Tons/Yr:	.17304
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

9

**GOODWILL PROPERTY  
 626-630 FRONT STREET  
 SAN DIEGO, CA 92173**

**ENVIROSTOR S106893839  
 N/A**

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	So Cal - Cypress
Facility ID:	37000082
Site Code:	Not reported
Assembly:	79
Senate:	40
Special Program:	Not reported
Status:	Refer: 1248 Local Agency
Status Date:	2000-11-22 00:00:00
Restricted Use:	NO
Funding:	Not Applicable
Latitude:	0
Longitude:	0
Alias Name:	37000082
Alias Type:	Envirostor ID Number
APN:	NONE SPECIFIED
APN Description:	Not reported
Comments:	Not reported

Completed Info:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GOODWILL PROPERTY (Continued)**

**S106893839**

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

10

**UNOCAL SERVICE STATION  
 1606 MARKET ST  
 SAN DIEGO, CA 92101**

**LUST S102440247  
 Cortese N/A**

LUST:  
 Region: 9  
 Case Number: 9UT678  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: Not reported  
 Date Found: 02/23/1987  
 How Found: Tank Closure  
 Date Stopped: 02/23/1987  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 02/23/1987  
 Submit Workplan: Not reported  
 Prelim Assess: 02/27/1989  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/16/90  
 Pilot Program: LOP  
 Local Case: H05817-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERVICE STATION (Continued)**

**S102440247**

Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 02/23/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1606 MARKET ST

**10 UNOCAL SERV STN #0364-30319  
 1606 MARKET ST  
 SAN DIEGO, CA 92101**

**LUST U003942775  
 UST N/A  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302946  
 Stop Date: 1987-02-23 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1990-05-18 00:00:00  
 Discover Date: 1987-02-23 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-02-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: RICH GOSSETT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

RP Address: PO BOX 85176  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05817-001  
 Case Number: 9UT678  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608134329  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-11-13 00:00:00  
 Discover Date: 1992-08-26 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-11-13 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: MM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05817-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608162480  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-11-13 00:00:00  
 Discover Date: 1992-08-26 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-11-13 00:00:00



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: MM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05817-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H05817

San Diego Co. HMMD:

Facility ID: 105817  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: LIC DEPT DC36  
 Mailing Address: P O BOX 52085  
 Mailing City,St,Zip: PHOENIX, AZ 85072

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 52  
 EPA ID: CAL000046424  
 Gas Station: Not reported  
 Inspection Date: 04/28/03  
 Reinspection Date: Not reported  
 Inspector Name: RHANSEN  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS CUEN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MAHMOUDIAN KHASHAYAR&SHOLEH  
 Property Address: 1606 MARKET ST  
 Property City,St,Zip: 92101  
 Tank Owner: TOSCO MARKETING CO  
 Tank Address: 3550 N CENTRAL AV FT  
 Tank City,St,Zip: Phoenix, AZ 85012  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-4436

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 0364-34  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 10/14/98

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

Waste Code:	Not reported
Type of Violation:	6HV1003
Occurrences:	Not reported
Item Number:	8519
Violation Desc:	HMBP NOT AMENDED W/IN 30 DAYS
Inspection Date:	10/14/98
Waste Code:	Not reported
Type of Violation:	6HV1097
Occurrences:	Not reported
Item Number:	8520
Violation Desc:	HMBP: NO EMPLOYEE TRAINING PROGRAM
Inspection Date:	10/14/98
Waste Code:	Not reported
Type of Violation:	6HX3027
Occurrences:	Not reported
Item Number:	8521
Violation Desc:	UST MONITORING PROCEDURE NOT IMPLEMENTED
Inspection Date:	10/14/98
Waste Code:	Not reported
Type of Violation:	6HX3028
Occurrences:	Not reported
Item Number:	8522
Violation Desc:	UST RESPONSE PLAN NOT AVAILABLE
Inspection Date:	08/19/97
Waste Code:	Not reported
Type of Violation:	6HX3016
Occurrences:	Not reported
Item Number:	8377
Violation Desc:	DID NOT SUBMIT INTEGRITY TEST RESULTS TO
Inspection Date:	08/19/97
Waste Code:	Not reported
Type of Violation:	6HX3027
Occurrences:	Not reported
Item Number:	8378
Violation Desc:	UST MONITORING PROCEDURE NOT IMPLEMENTED
Inspection Date:	08/19/97
Waste Code:	Not reported
Type of Violation:	6HX3031
Occurrences:	Not reported
Item Number:	8379
Violation Desc:	FAILURE TO REPORT/RESPOND TO RELEASE
Inspection Date:	05/22/01
Waste Code:	Not reported
Type of Violation:	6HV0135
Occurrences:	Not reported
Item Number:	5856
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	05/22/01
Waste Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	5857
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	05/22/01
Waste Code:	Not reported
Type of Violation:	6HV0402
Occurrences:	Not reported
Item Number:	5858
Violation Desc:	TRAINING PROGRAM NOT ADEQUATE
Inspection Date:	05/22/01
Waste Code:	Not reported
Type of Violation:	6HX3011
Occurrences:	Not reported
Item Number:	5859
Violation Desc:	FAIL TO COMPLY WITH OP PERMIT CONDITIO
Inspection Date:	05/22/01
Waste Code:	Not reported
Type of Violation:	6HX3013
Occurrences:	Not reported
Item Number:	5860
Violation Desc:	NO FINANCIAL RESPOSIBILITY DOC
Inspection Date:	05/22/01
Waste Code:	Not reported
Type of Violation:	6HX3001
Occurrences:	Not reported
Item Number:	5861
Violation Desc:	UST RECORDS NOT MAINTAINED ONSITE
Inspection Date:	05/22/01
Waste Code:	Not reported
Type of Violation:	6HX3027
Occurrences:	Not reported
Item Number:	5862
Violation Desc:	UST MONITORING PROCEDURE NOT IMPLEMENTED
Inspection Date:	05/22/01
Waste Code:	Not reported
Type of Violation:	6HX3027
Occurrences:	Not reported
Item Number:	5863
Violation Desc:	UST MONITORING PROCEDURE NOT IMPLEMENTED
Inspection Date:	05/01/02
Waste Code:	Not reported
Type of Violation:	6HX3001
Occurrences:	Not reported
Item Number:	7617
Violation Desc:	UST RECORDS NOT MAINTAINED ONSITE
Inspection Date:	05/01/02
Waste Code:	Not reported
Type of Violation:	6HX3015

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

Occurrences: Not reported  
 Item Number: 7618  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 05/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 7619  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 05/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7620  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203020  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1606 MARKET ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 52  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 05/05/04  
 Reinspection Date: Not reported  
 Inspector Name: RHANSEN  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS CUEN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MAHMOUDIAN KHASHAYAR&SHOLEH  
 Property Address: 1606 MARKET ST  
 Property City,St,Zip: 92101  
 Tank Owner: K C MAHMOUDIAN  
 Tank Address: 1606 MARKET ST  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/05/05  
 Facility Phone: 619-234-4436

**HMMD DISCLOSURE INVENTORY:**

Item Number: PR61  
 Chemical Name: PREMIUM UNLEADED - T003 UNDERGROUND TANK 105817 T003  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: RE60  
 Chemical Name: REGULAR UNLEADED - T002 UNDERGROUND TANK 105817 T002  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T002  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 05/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1294  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

Inspection Date: 05/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1295  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 05/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3109  
 Occurrences: Not reported  
 Item Number: 1296  
 Violation Desc: MONITORING PLOT PLAN NOT SUBMITTED

Inspection Date: 05/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3114  
 Occurrences: Not reported  
 Item Number: 1297  
 Violation Desc: 2NDRY CONT TEST NOT DONE/SENT TO CUPA

Inspection Date: 05/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3255  
 Occurrences: Not reported  
 Item Number: 1298  
 Violation Desc: SPILL CONT NOT DRY & IN GOOD CONDITI

Inspection Date: 05/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3263  
 Occurrences: Not reported  
 Item Number: 1299  
 Violation Desc: MONITORING SYSTEM NOT FUNCTIONAL

**HMMD WASTE STREAMS:**

Inspection Date: 05/05/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 12  
 Quantity String: 12  
 Annual Qty: 12  
 Annual Qty String: 12  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: CAN  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: USED GASOLINE FILTERS  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H05817-001  
 Agency: DEH Site Assessment & Mitigation  
 Funding: **LOP - State Fund**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNOCAL SERV STN #0364-30319 (Continued)**

**U003942775**

FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/18/1990  
 Begandt: 2/23/1987

Case Number: H05817-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 11/13/1992  
 Begandt: 8/26/1992

Case Number: H05817-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 11/13/1992  
 Begandt: 8/26/1992

11

**ADT PROPERTY HOLDINGS INC**  
**1416 MARKET ST**  
**SAN DIEGO, CA 92101**

**SAN DIEGO CO. SAM**

**S108406936**  
**N/A**

SAN DIEGO CO. SAM:

Case Number: H09532-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/13/1994  
 Begandt: 5/4/1992

Case Number: H09532-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/16/2006  
 Begandt: Not reported

11

**ADT PROPERTY HOLDINGS INC**  
**1416 MARKET ST**  
**SAN DIEGO, CA 92101**

**LUST**  
**San Diego Co. HMMD**

**S104746788**  
**N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADT PROPERTY HOLDINGS INC (Continued)**

**S104746788**

Global Id: T0607399125  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-08-16 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: Robert G. Russell, Jr.  
 RP Address: 530 B Street, Ste. 2100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H09532-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ADT PROPERTY HOLDINGS INC (Continued)**

**S104746788**

Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608160540  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1994-01-13 00:00:00  
 Discover Date: 1992-05-04 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-05-04 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: STEVEN LEVINE  
 RP Address: 2255 GLADES RD, STE 421A  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H09532-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADT PROPERTY HOLDINGS INC (Continued)**

**S104746788**

Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 109532  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 5035  
 Mailing City,St,Zip: BOCA RATON, FL 33431  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 52  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: E V L L C  
 Property Address: C/O JIM RIVARD  
 Property City,St,Zip: 99202  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADT PROPERTY HOLDINGS INC (Continued)**

**S104746788**

Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

12

**PACIFIC AIRMOTIVE  
 544 7TH AVENUE  
 SAN DIEGO, CA 92101**

**ENVIROSTOR 1000250543  
 N/A**

**ENVIROSTOR:**

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37370118  
 Site Code: Not reported  
 Assembly: 76  
 Senate: 39  
 Special Program: \* RCRA 3012 - Past Haz Waste Disp Inven Site  
 Status: Refer: Other Agency  
 Status Date: 1995-08-21 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 32.7108333333333  
 Longitude: -117.158333333333  
 Alias Name: SUBSIDIARY OF PUREX CORP  
 37370118  
 CAD980636666  
 Alias Type: Alternate Name

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC AIRMOTIVE (Continued)**

**1000250543**

EPA Identification Number  
 Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: CALSITES VALIDATION PROGRAM CONFIRMS NFA FOR DTSC.FACILITY IDENTIFIED ID VIA EPA PRINTOUTFACILITY IDENTIFIED ID FROM ERRISSOURCE ACT: AIRCRAFT SERVING BUSINESS. SOLVENT CLEANING ON SITE. SUBMIT TO EPA PRELIM ASSESS DONE RCRA 3012

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 10/27/94

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 02/22/84

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 10/12/83

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 03/22/83

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 10198  
 Potential Description: \* UNSPECIFIED SOLVENT MIXTURES  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

13 **515 27TH STREET** **Notify 65** **S100178292**  
**SAN DIEGO, CA 92102** **N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92102-3164

14 **PARKSIDE, FORMER E. VIL. COMM** **SAN DIEGO CO. SAM** **S108540437**  
**505 13TH ST** **N/A**  
**SAN DIEGO, CA 92101**

SAN DIEGO CO. SAM:  
 Case Number: H39707-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 5/10/2007  
 Begandt: Not reported

14 **PARKSIDE, FORMER E. VIL. COMM CHURCH** **LUST** **S108536668**  
**505 13TH ST** **N/A**  
**SAN DIEGO, CA 92101**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: SLT19705653  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2007-05-10 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PARKSIDE, FORMER E. VIL. COMM CHURCH (Continued)**

**S108536668**

Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: Robert Henderson  
 RP Address: 625 Broadway, Suite 100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H39707-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**15 HEAVY EQUIPMENT LOT  
 1475 J ST  
 SAN DIEGO, CA 92101**

**CERC-NFRAP 1003877971  
 CAD982359598**

CERC-NFRAP:  
 Site ID: 0900066  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):  
 Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HEAVY EQUIPMENT LOT (Continued)**

**1003877971**

CERCLIS-NFRAP Assessment History:

Action:	DISCOVERY
Date Started:	Not reported
Date Completed:	12/01/1987
Priority Level:	Not reported
Action:	ARCHIVE SITE
Date Started:	Not reported
Date Completed:	09/06/1990
Priority Level:	Not reported
Action:	PRELIMINARY ASSESSMENT
Date Started:	Not reported
Date Completed:	09/06/1990
Priority Level:	NFRAP (No Further Remedial Action Planned)

**15**      **ECONO AUTO REPAIR/GAS**  
**400 16TH ST**  
**SAN DIEGO, CA 92101**

**HAZNET**      **S102861223**  
**LUST**          **N/A**  
**Cortese**  
**San Diego Co. HMMD**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

HAZNET:

Gepaid:	CAC002128256
Contact:	PAULA MILLFORD
Telephone:	6192323263
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	400 16TH ST
Mailing City,St,Zip:	SAN DIEGO, CA 921010000
Gen County:	San Diego
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	3.1066
Facility County:	San Diego

LUST:

Region:	STATE
Case Type:	Other ground water affected
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	NOR
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global Id:	T0607302562
Stop Date:	1998-12-14 00:00:00
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

Monitoring: Not reported  
 Close Date: 2002-05-15 00:00:00  
 Discover Date: 1998-12-14 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-12-28 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: SHEARN H PLATT  
 RP Address: 600 B STREET #2300  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03587-001  
 Case Number: 9UT3798  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT3798  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 12/14/1998  
 How Found: Tank Closure  
 Date Stopped: 12/14/1998  
 How Stopped: Close Tank

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: 12/28/1998  
 Submit Workplan: 1/6/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 1/2/99  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H03587-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 12/28/1998  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 400 16TH ST

**San Diego Co. HMMD:**

Facility ID: 103587  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 400 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000152632  
 Gas Station: Not reported  
 Inspection Date: 04/04/03  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: KABIR AMIR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WESTERN PACIFIC HOUSING INC  
 Property Address: 5790 FLEET ST #210  
 Property City,St,Zip: 92008  
 Tank Owner: RIMOLDIS PICCOS SERVICE INC  
 Tank Address: 400 16TH ST  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-3263

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: at4253  
 Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

Tank Number: T005  
 Tank ID Number: 5  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/12/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

Item Number: 8459  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/12/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8460  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/12/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 8461  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 10/12/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 8462  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 10/12/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 8463  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

Inspection Date: 02/04/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 2471  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 02/04/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2472  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/04/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 2473  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 02/04/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2474

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	6394
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HV0205
Occurrences:	Not reported
Item Number:	6395
Violation Desc:	WASTE CONTAINER: POOR CONDITION
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	6396
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HV0402
Occurrences:	Not reported
Item Number:	6397
Violation Desc:	TRAINING PROGRAM NOT ADEQUATE
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	6398
Violation Desc:	HMBP NOT ESTABLISHED/IMPLEMENTED.
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HX0108
Occurrences:	Not reported
Item Number:	6391
Violation Desc:	NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	6392
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	06/06/01
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	6393
Violation Desc:	WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

Inspection Date: 04/04/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 6421  
 Violation Desc: UPFP NOT OBTAINED for HAZWASTE

Inspection Date: 04/04/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6422  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 04/04/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 6423  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 04/04/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 6424  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 04/04/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 6425  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 04/04/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 6426  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

SWEEPS UST:

Status: Not reported  
 Comp Number: 3587  
 Number: Not reported  
 Board Of Equalization: 44-021898  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003587-000005  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 1

Status: A  
 Comp Number: 3587  
 Number: 9  
 Board Of Equalization: 44-021898  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003587-000001  
 Actv Date: Not reported  
 Capacity: 7500  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 4

Status: A  
 Comp Number: 3587  
 Number: 9  
 Board Of Equalization: 44-021898  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003587-000002  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3587  
 Number: 9  
 Board Of Equalization: 44-021898  
 Ref Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ECONO AUTO REPAIR/GAS (Continued)**

**S102861223**

Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003587-000003  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3587  
 Number: 9  
 Board Of Equalization: 44-021898  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003587-000004  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H03587-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/15/2002  
 Begandt: 12/14/1998

15

**JOHN HANSEN HOUSE MOVING  
 405 15TH ST  
 SAN DIEGO, CA 92101**

**LUST S107619821  
 SAN DIEGO CO. SAM N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019778236  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JOHN HANSEN HOUSE MOVING (Continued)**

**S107619821**

Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: 2005-06-06 00:00:00  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remedial action (cleanup) Underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Tim Adair  
 RP Address: 5790 Fleet Street, Ste. 200  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: 203184-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: 203184-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Remedial Action (Clean-Up)  
 Date: 6/6/2005

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

---

**JOHN HANSEN HOUSE MOVING (Continued)**

**S107619821**

Begandt: Not reported

15

**JOHN HANSEN HOUSE MOVING  
405 15TH  
SAN DIEGO, CA 92101**

**LUST S106875249  
SAN DIEGO CO. SAM N/A**

LUST:

Region:	STATE
Case Type:	Other ground water affected
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	NOR
How Discovered:	Not reported
How Stopped:	Close Tank
Leak Cause:	Other Cause
Leak Source:	Tank
Global Id:	T06019771011
Stop Date:	2004-04-02 00:00:00
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	2004-11-17 00:00:00
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	2004-04-02 00:00:00
Enforcement Dt:	Not reported
Release Date:	2004-04-02 00:00:00
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	37
Org Name:	Not reported
Reg Board:	San Diego Region
Status:	Remediation Plan
Chemical:	Gasoline
Contact Person:	Not reported
Responsible Party:	John Hansen
RP Address:	9822 1/2 Hawley Rd.
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	0
MTBE Fuel:	1
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Staff:	UNA
Staff Initials:	EM
Lead Agency:	Local Agency
Local Agency:	37000L
Hydr Basin #:	908.22
Beneficial:	REC-1,REC-2,WARM,WILD
Priority:	8
Cleanup Fund Id:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JOHN HANSEN HOUSE MOVING (Continued)**

**S106875249**

Work Suspended: Not reported  
 Local Case #: 203184-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: 203184-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 4/6/2004  
 Begandt: 4/2/2004

**15 PACIFIC MARINE SHEET METAL CORP  
 410 15TH ST  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000250117  
 FINDS CAD981388044  
 HAZNET  
 LUST  
 Cortese**

**RCRA-SQG:**

Date form received by agency: 09/01/1996  
 Facility name: PACIFIC MARINE SHEET METAL CORP  
 Facility address: 410 15TH ST  
 SAN DIEGO, CA 92101  
 EPA ID: CAD981388044  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC MARINE SHEET METAL CORP (Continued)**

**1000250117**

Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
  
 Owner/operator name: ALLEN WECKERLY  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 02/18/1986  
 Facility name: PACIFIC MARINE SHEET METAL CORP  
 Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: F - 262.30-34.C  
 Area of violation: Generators - General  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 04/12/2002  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 02/19/2002  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported  
  
 Regulation violated: F - GPP  
 Area of violation: Generators - Pre-transport  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 10/30/2001  
 Violation lead agency: EPA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC MARINE SHEET METAL CORP (Continued)**

**1000250117**

Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 279.20-24  
 Area of violation: Used Oil - Generators  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 04/12/2002  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 02/19/2002  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 262.30-34.C  
 Area of violation: Generators - General  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 04/12/2002  
 Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: 12/14/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 279.20-24  
 Area of violation: Used Oil - Generators  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 04/12/2002  
 Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: 12/14/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:  
 Evaluation date: 10/30/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Used Oil - Generators  
 Date achieved compliance: 04/12/2002  
 Evaluation lead agency: EPA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC MARINE SHEET METAL CORP (Continued)**

**1000250117**

Evaluation date: 10/30/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - Pre-transport  
 Date achieved compliance: 10/30/2001  
 Evaluation lead agency: EPA

Evaluation date: 10/30/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 04/12/2002  
 Evaluation lead agency: EPA

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD981388044  
 Contact: PACIFIC MARINE SHEET METAL COR  
 Telephone: 6192346746  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 410 15TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017535  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Liquids with chromium (VI) > 500 mg/l  
 Disposal Method: Not reported  
 Tons: .6880  
 Facility County: San Diego

Gepaid: CAD981388044  
 Contact: PACIFIC MARINE SHEET METAL COR  
 Telephone: 6192346746  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 410 15TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017535  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Liquids with chromium (VI) > 500 mg/l  
 Disposal Method: Recycler  
 Tons: .6880  
 Facility County: San Diego

Gepaid: CAD981388044

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC MARINE SHEET METAL CORP (Continued)**

1000250117

Contact: PACIFIC MARINE SHEET METAL COR  
 Telephone: 6192346746  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 410 15TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017535  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Recycler  
 Tons: .3500  
 Facility County: San Diego

Gepaid: CAD981388044  
 Contact: PACIFIC MARINE SHEET METAL COR  
 Telephone: 6192346746  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 410 15TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017535  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Not reported  
 Tons: .3500  
 Facility County: San Diego

Gepaid: CAD981388044  
 Contact: PACIFIC MARINE SHEET METAL COR  
 Telephone: 6192346746  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 410 15TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017535  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Treatment, Tank  
 Tons: .2293  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 91 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Tank Closure  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC MARINE SHEET METAL CORP (Continued)**

**1000250117**

Global Id: T0605902068  
 Stop Date: 9999-09-09 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2002-09-13 00:00:00  
 Discover Date: 1997-10-30 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1997-10-30 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 30  
 Org Name: Not reported  
 Reg Board: Santa Ana Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: RICK SWEENEY  
 RP Address: P O BOX 3165  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: VJB  
 Staff Initials: KC  
 Lead Agency: Local Agency  
 Local Agency: 30000L  
 Hydr Basin #: Not reported  
 Beneficial: MUN  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: 97UT046  
 Case Number: 083003033T  
 Qty Leaked: 0  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

LUST:

Region: 8



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC MARINE SHEET METAL CORP (Continued)**

**1000250117**

Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Tank Closure  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global ID: T0605902068  
 How Stopped Date: 9/9/9999  
 Review Date: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 9/13/2002  
 Discover Date: 10/30/1997  
 Enforcement Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifies: Not reported  
 Soil Qualifies: Not reported  
 Max MTBE GW: Not reported  
 Max MTBE Soil: Not reported  
 County: Orange  
 Operator: Not reported  
 Regional Board: 08  
 Facility Status: Case Closed  
 Substance: 12034  
 Facility Contact: Not reported  
 Interim: Not reported  
 Oversight Program: LUST  
 Latitude: 33.820922  
 Longitude: -117.8564674  
 MTBE Concentration: 0  
 MTBE Fuel: 0  
 MTBE Tested: NRQ  
 Staff: VJJ  
 Staff Initials: KC  
 Lead Agency: Local Agency  
 Local Agency: 30000L  
 Hydr Basin #: Not reported  
 Beneficial: MUN  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case Num: 97UT046  
 Case Number: 083003033T  
 Qty Leaked: 0  
 Abate Method: Not reported  
 MTBE Class: \*  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC MARINE SHEET METAL CORP (Continued)**

**1000250117**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported  
  
 Region: CORTESE  
 Facility Addr2: Not reported  
  
 Region: CORTESE  
 Facility Addr2: Not reported  
  
 Region: CORTESE  
 Facility Addr2: 410 GROVE AVE

15

**VICTOR'S USED TIRES  
 405 16TH ST  
 SAN DIEGO, CA 92101**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S102440914  
 N/A**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300787  
 Stop Date: 1991-07-18 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-01-24 00:00:00  
 Discover Date: 1991-07-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-07-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: SITE OPERATOR  
 RP Address: 424 17TH ST.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**VICTOR'S USED TIRES (Continued)**

**S102440914**

Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H22860-001  
 Case Number: 9UT2012  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT2012  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 07/18/1991  
 How Found: Other Means  
 Date Stopped: 07/18/1991  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 07/29/1991  
 Submit Workplan: 7/31/91  
 Prelim Assess: 12/23/1991  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H22860-001  
 Basin Number: 908.21  
 Gwater Depth: >13

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VICTOR'S USED TIRES (Continued)**

**S102440914**

Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 07/18/1991  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 405 16TH ST

**San Diego Co. HMMD:**

Facility ID: 122860  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 405-407 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 06/13/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ROGELIO MOSTACERO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STONECREEK HOMES INC  
 Property Address: 3555 ROSECRANS ST #2  
 Property City,St,Zip: 92110  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-9148

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**VICTOR'S USED TIRES (Continued)**

**S102440914**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT2331  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: AT2331  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: AT2331  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: 03/16/94  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0590  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/16/94  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 0591  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VICTOR'S USED TIRES (Continued)**

**S102440914**

Comp Number: 22860  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-022860-000001  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 22860  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-022860-000002  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 22860  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-022860-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 22860  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VICTOR'S USED TIRES (Continued)**

**S102440914**

Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H22860-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 1/24/2003  
 Begandt: 7/18/1991

15

**MOTOR WORKS INC**  
**1490 ISLAND AV**  
**SAN DIEGO, CA 92101**

**LUST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**S104750933**  
**N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Tank  
 Global Id: T0607399275  
 Stop Date: 1999-12-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-07-30 00:00:00  
 Discover Date: 1999-12-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-12-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOTOR WORKS INC (Continued)**

**S104750933**

Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: Sergio and Regina Bartolini Trust  
 RP Address: 465 Deer Path  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H26093-001  
 Case Number: 9UT4014  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 126093  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1490 ISLAND AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000050775  
 Gas Station: Not reported  
 Inspection Date: 07/28/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: SERGIO BARTOLINI  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MOTOR WORKS INC (Continued)**

**S104750933**

Property Owner: 15TH&ISLAND L P  
 Property Address: 405 VIA DEL NORTE  
 Property City,St,Zip: 92037  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/28/06  
 Facility Phone: 619-233-8875

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC69  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR68  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: AR72  
 Chemical Name: ARGON/CARBON DIOXIDE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: OX71  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOTOR WORKS INC (Continued)**

**S104750933**

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT4910  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/27/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4771  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/27/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4772  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 04/27/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4773  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 10/16/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0721  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 07/28/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 16  
 Quantity String: 16  
 Annual Qty: 176  
 Annual Qty String: 176  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: INVALID CODE  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: 8-WK SRVC TRM, 1 UNT  
 Carcinogen: No

Inspection Date: 07/28/04  
 Waste Item #: 491  
 Waste Code: 491  
 Waste Name: UNSPECIFIED SLUDGE W  
 Qnty at Inspection: 55

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOTOR WORKS INC (Continued)**

**S104750933**

Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2790 EVERGREEN ENVIRONMEN  
 Waste Desc: SMP SLG/MIX GREASE/OIL/MT  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H26093-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 7/30/2003  
 Begandt: 12/8/1999

15

**BARTOLINI TRUST**  
**1460 ISLAND AVE**  
**SAN DIEGO, CA 92101**

**HAZNET S104494709**  
**LUST N/A**

**HAZNET:**

Gepaid: CAC002566527  
 Contact: SERGIO BARTOLINI  
 Telephone: 6192338875  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1460 ISLAND AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 6.67  
 Facility County: San Diego

**LUST:**

Region: 9  
 Case Number: 9UT4014  
 Local Agency: San Diego  
 Substance: Crude Oil (Hazardous)  
 Qty Leaked: Not reported  
 Date Found: 12/15/1999  
 How Found: Subsurface Monitoring  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: / /

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARTOLINI TRUST (Continued)**

**S104494709**

Submit Workplan: 12/27/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H26093-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: NBUB/E  
 NPDES Number: Not reported  
 priority: Not reported  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 12/15/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

15

**ISLAND AVE. AUTO SHOP  
 1434-90 ISLAND AVENUE  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106893864  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37750008  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-02-01 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37750008  
 Alias Type: Envirostor ID Number  
  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISLAND AVE. AUTO SHOP (Continued)**

**S106893864**

Completed Date: 02/01/00

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

**15      ARCWELL CORP  
 510 16TH STREET  
 SAN DIEGO, CA 92101**

**FINDS    1000436165  
 LUST     CAD981429590  
 Cortese  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM  
 RCRA-NonGen**

FINDS:  
 Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607302935  
 Stop Date: 1988-07-11 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1988-07-11 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWELL CORP (Continued)**

**1000436165**

Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1988-07-11 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-07-11 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: Frank Hallford  
 RP Address: P.O. Box 25025  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01100-001  
 Case Number: 9UT668  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Spill  
 Leak Source: Tank

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWELL CORP (Continued)**

**1000436165**

Global Id: T0608112785  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1993-11-04 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1988-04-03 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-04-03 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: ATTN: FRANK HALLFORD  
 RP Address: 600 N BRAND BL, SUITE 300  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01100-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

LUST:

Region: 9

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWELL CORP (Continued)**

**1000436165**

Case Number: 9UT668  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 07/11/1988  
 How Found: Not reported  
 Date Stopped: 07/11/1988  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Pollution Characterization  
 Abate Method: Not reported  
 Confirm Date: 07/11/1988  
 Submit Workplan: Not reported  
 Prelim Assess: 03/25/1987  
 Desc Pollution: 4/19/94  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01100-001  
 Basin Number: 908.21  
 Gwater Depth: ~28  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - KNOWN HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 03/12/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 510 16TH ST

**San Diego Co. HMMD:**

Facility ID: 101100  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 510 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAD000058792



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWELL CORP (Continued)**

**1000436165**

Gas Station: Not reported  
 Inspection Date: 09/18/91  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RON WARREN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PUBLIC STORAGE PROPERTIES XIX  
 Property Address: C/O DEPT PT CA 21908  
 Property City,St,Zip: 91221  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 233-5291

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 001  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/04/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0027  
 Occurrences: Not reported  
 Item Number: 5825  
 Violation Desc: MANIFESTS NOT KEPT FOR 3 YEARS

Inspection Date: 11/04/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0027  
 Occurrences: Not reported  
 Item Number: 5826  
 Violation Desc: MANIFESTS NOT KEPT FOR 3 YEARS

Inspection Date: 11/04/85  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCWELL CORP (Continued)**

**1000436165**

Type of Violation:	6HX0027
Occurrences:	Not reported
Item Number:	5827
Violation Desc:	MANIFESTS NOT KEPT FOR 3 YEARS
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HX0027
Occurrences:	Not reported
Item Number:	5828
Violation Desc:	MANIFESTS NOT KEPT FOR 3 YEARS
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	5829
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	5830
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HX0042
Occurrences:	Not reported
Item Number:	5831
Violation Desc:	HAZWASTE CONT. NOT LABELED OR MARKED
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HX0042
Occurrences:	Not reported
Item Number:	5832
Violation Desc:	HAZWASTE CONT. NOT LABELED OR MARKED
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HX0043
Occurrences:	Not reported
Item Number:	5833
Violation Desc:	HAZWASTE CONT. NOT DATED WITH START DATE
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HX0043
Occurrences:	Not reported
Item Number:	5834
Violation Desc:	HAZWASTE CONT. NOT DATED WITH START DATE
Inspection Date:	11/04/85
Waste Code:	Not reported
Type of Violation:	6HX0034

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCWELL CORP (Continued)**

**1000436165**

Occurrences:	Not reported
Item Number:	5835
Violation Desc:	MANIFEST NOT DONE PRIOR TO TRANSPORT
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HV0499
Occurrences:	Not reported
Item Number:	6156
Violation Desc:	NO EMPLOYEE TRAINING FOR ER RESPONSE
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HX0069
Occurrences:	Not reported
Item Number:	6157
Violation Desc:	STORAGE OF WASTE FOR LONGER THAN 90 DAYS
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HX0042
Occurrences:	Not reported
Item Number:	6158
Violation Desc:	HAZWASTE CONT. NOT LABELED OR MARKED
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HX0043
Occurrences:	Not reported
Item Number:	6159
Violation Desc:	HAZWASTE CONT. NOT DATED WITH START DATE
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HV0207
Occurrences:	Not reported
Item Number:	6160
Violation Desc:	FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HX0023
Occurrences:	Not reported
Item Number:	6161
Violation Desc:	HAZWASTE DISPOSAL TO GROUND
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HX0022
Occurrences:	Not reported
Item Number:	6162
Violation Desc:	HAZWASTE DISPOSAL TO AIR
Inspection Date:	07/17/86
Waste Code:	Not reported
Type of Violation:	6HX0029
Occurrences:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCWELL CORP (Continued)**

**1000436165**

Item Number: 6163  
 Violation Desc: NO HAZARDOUS WASTE DETERMINATION

Inspection Date: 07/17/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0035  
 Occurrences: Not reported  
 Item Number: 6164  
 Violation Desc: HAZWASTE TO AN UNREGISTERED HAULER

Inspection Date: 09/18/91  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 8034  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 09/18/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 8035  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 09/18/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 8036  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 09/18/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8037  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/18/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0404  
 Occurrences: Not reported  
 Item Number: 8038  
 Violation Desc: SPILL CONTROL EQUIPMT NOT AVAILABLE

Inspection Date: 09/18/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 8039  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWELL CORP (Continued)**

**1000436165**

Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H01100-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 7/11/1988  
 Begandt: 7/11/1988

Case Number: H01100-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 11/4/1993  
 Begandt: 4/3/1988

**RCRA-NonGen:**

Date form received by agency: 05/13/1986  
 Facility name: ARCWELL CORP  
 Facility address: 510 16TH STREET  
 SAN DIEGO, CA 92101  
 EPA ID: CAD981429590  
 Mailing address: P O BOX 13428  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 510 SIXTEEN STREET  
 SAN DIEGO, CA 92101  
 Contact country: US  
 Contact telephone: (619) 233-5291  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWELL CORP (Continued)**

**1000436165**

Owner/Op end date: Not reported  
 Owner/operator name: STEVE PARKER  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

16

**SHERMAN HEIGHTS FAMILY HLTH CT  
 450 24TH ST  
 SAN DIEGO, CA 92102**

**HAZNET S104760625  
 LUST N/A  
 San Diego Co. HMMD**

HAZNET:

Gepaid: CAC001328456  
 Contact: SAN DIEGO USD  
 Telephone: 8586277255  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 4860 RUFFNER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921110000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .0750  
 Facility County: San Diego

Gepaid: CAC002606694  
 Contact: JOE KINKEAD/ASBESTOS INSPEC  
 Telephone: 8586277255  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 4860 RUFFNER ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERMAN HEIGHTS FAMILY HLTH CT (Continued)**

**S104760625**

Mailing City,St,Zip: SAN DIEGO, CA 921110000  
 Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: 25.28  
 Facility County: San Diego

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0619768165  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2008-03-29 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Tony Raso  
 RP Address: 4860 Ruffner Street  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: Not reported  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERMAN HEIGHTS FAMILY HLTH CT (Continued)**

**S104760625**

Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: 209017-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 154262  
 Inactive Indicator: Active  
 Business Code: 6HK10  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: LOGAN HEIGHTS FAMILY HEALTH CT  
 Mailing Address: 1809 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 47  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/10/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: NANCY BRYANT WALLIS/CLARA CABR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO UNIFIED SCHOOL DISTR  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/10/07  
 Facility Phone: 619-515-2435

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERMAN HEIGHTS FAMILY HLTH CT (Continued)**

**S104760625**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV4203  
 Occurrences: Not reported  
 Item Number: 3228  
 Violation Desc: MED WASTE STORAGE NOT SECURED

**HMMD WASTE STREAMS:**

Inspection Date: 08/10/04  
 Waste Item #: 901  
 Waste Code: 901  
 Waste Name: INFECTIOUS WASTE, GE  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 25  
 Annual Qty String: 25  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BAG  
 Haz Waste Hauler: 0303 BFI MEDICAL WASTE SY  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 08/10/04  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 50  
 Annual Qty String: 50  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: CARBOY  
 Haz Waste Hauler: 0303 BFI MEDICAL WASTE SY  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

17 EAST VILLAGE RDA (535-353-08)  
 318 9TH AVE  
 SAN DIEGO, CA 92101

LUST S103723453  
 SWEEPS UST N/A

LUST:

Region: 9  
 Case Number: 9UT3840  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 12/29/1998  
 How Found: Tank Closure  
 Date Stopped: 12/29/1998  
 How Stopped: Close Tank  
 Source: Piping  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 02/04/1999  
 Submit Workplan: 2/17/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 10/17/00  
 Pilot Program: LOP  
 Local Case: H21065-001  
 Basin Number: 908.21  
 Gwater Depth: >12'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: Not reported  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 02/02/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

SWEEPS UST:

Status: A  
 Comp Number: 21065  
 Number: 9  
 Board Of Equalization: 44-023415  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021065-000001  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: P

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EPA ID Number

**EAST VILLAGE RDA (535-353-08) (Continued)**

**S103723453**

Content: OTHER  
 Number Of Tanks: 1

**17 EAST VILLAGE RDA (535-353)  
 318 9TH  
 SAN DIEGO, CA**

**HAZNET S104160502  
 Cortese N/A**

HAZNET:  
 Gepaid: CAC001381608  
 Contact: RICHARD HERMAN  
 Telephone: 6192342222  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 318 9TH AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .5212  
 Facility County: San Diego

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

**17 MONTERREY PROVISION CO INC  
 318 09TH AV  
 SAN DIEGO, CA 92101**

**LUST S105032554  
 San Diego Co. HMMD N/A  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302598  
 Stop Date: 1998-12-29 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-10-19 00:00:00  
 Discover Date: 1998-12-29 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-02-02 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MONTERREY PROVISION CO INC (Continued)**

**S105032554**

MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: DOUG DODGEN  
 RP Address: 318 9TH AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21065-001  
 Case Number: 9UT3840  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Spill  
 Leak Source: Tank  
 Global Id: T0608192110  
 Stop Date: 2001-10-18 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MONTERREY PROVISION CO INC (Continued)**

**S105032554**

Monitoring: Not reported  
 Close Date: 2004-02-26 00:00:00  
 Discover Date: 2001-10-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-11-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Richard Herrman  
 RP Address: 5235 Lovelock Street  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21065-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 121065  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: DOUG DODGEN  
 Mailing Address: 5235 LOVELOCK ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92110

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MONTERREY PROVISION CO INC (Continued)**

**S105032554**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAL000047934  
 Gas Station: Not reported  
 Inspection Date: 08/03/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: GREG HERRMAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: RICHARD J HERRMAN  
 Tank Address: 318 09TH AV  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-2222

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1 DIESEL  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MONTERREY PROVISION CO INC (Continued)**

**S105032554**

Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H21065-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/19/2000  
 Begandt: 12/29/1998

Case Number: H21065-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/26/2004  
 Begandt: 10/18/2001

17

**A-1 QUALITY TRANSMISSIONS  
 901 J ST  
 SAN DIEGO, CA 92101**

**LUST S102423608  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT1717  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 05/31/1990  
 How Found: Tank Closure  
 Date Stopped: 08/04/1989  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Spill  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming), Enhanced Biodegradation - use of any available technology to promote bacterial decomposition of contaminants  
 Confirm Date: 05/31/1990  
 Submit Workplan: Not reported  
 Prelim Assess: / /

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A-1 QUALITY TRANSMISSIONS (Continued)**

**S102423608**

Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 10/15/91  
 Pilot Program: LOP  
 Local Case: H19916-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 05/31/1990  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 901 J ST

17

**BIG TOW**  
**901 J ST**  
**SAN DIEGO, CA 92101**

**LUST U003789554**  
**UST N/A**  
**SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300515  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-10-15 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BIG TOW (Continued)**

**U003789554**

Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: DEL MCGUE  
 RP Address: PO BOX X-1013  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H19916-001  
 Case Number: 9UT1717  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H19916

SAN DIEGO CO. SAM:

Case Number: H19916-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/15/1991  
 Begandt: 8/4/1989

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

17 **DOS AMIGOS PROPERTY**  
**405 10TH AV**  
**SAN DIEGO, CA 92101**

**LUST S106874906**  
**SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607334743  
 Stop Date: 2002-12-13 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-03-16 00:00:00  
 Discover Date: 2002-12-13 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2003-01-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Dos Amigos Distributors, Inc.  
 RP Address: 225 Broadway Ave., Ste. 1100  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H71103-001  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DOS AMIGOS PROPERTY (Continued)**

**S106874906**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H71103-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/16/2005  
 Begandt: 12/13/2002

17

**CONWAY TRUST & DT SAN DIEGO LLC**  
**427 9TH AVE**  
**SAN DIEGO, CA 92101**

**HAZNET S106893817**  
**ENVIROSTOR N/A**

**HAZNET:**

Gepaid: CAC002566835  
 Contact: GARY WATTS/INTRACORP  
 Telephone: 6197020332  
 Facility Addr2: Not reported  
 Mailing Name: INTRACORP  
 Mailing Address: 600 B ST. STE 1500  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Treatment, Tank  
 Tons: 0.41  
 Facility County: San Diego

Gepaid: CAC002566835  
 Contact: GARY WATTS/INTRACORP  
 Telephone: 6197020332  
 Facility Addr2: Not reported  
 Mailing Name: INTRACORP  
 Mailing Address: 600 B ST. STE 1500  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.05  
 Facility County: San Diego

Gepaid: CAC002571811  
 Contact: LOREN ADAMS  
 Telephone: 6197020330

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONWAY TRUST & DT SAN DIEGO LLC (Continued)**

**S106893817**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 600 B ST STE 1500  
 Mailing City,St,Zip: SAN FRANCISCO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: AZC951206114  
 TSD County: San Diego  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Not reported  
 Tons: 45.51  
 Facility County: San Diego

Gepaid: CAC002571811  
 Contact: LOREN ADAMS  
 Telephone: 6197020330  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 600 B ST STE 1500  
 Mailing City,St,Zip: SAN FRANCISCO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: AZC951206114  
 TSD County: San Diego  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Land Fill  
 Tons: 3306.3  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

**ENVIROSTOR:**

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: 1  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000058  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-02-25 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37000058  
 Alias Type: Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONWAY TRUST & DT SAN DIEGO LLC (Continued)**

**S106893817**

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 02/25/00

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

17

**DONEV COMPANY  
 441 10TH AVE  
 SAN DIEGO, CA 92101**

**LUST S103296811  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT3587  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 01/16/1998  
 How Found: Tank Closure  
 Date Stopped: 01/16/1998  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: 1/23/98  
 Prelim Assess: 10/22/1998  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 2/1/98  
 Closed Date: 6/23/98  
 Pilot Program: LOP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DONEV COMPANY (Continued)**

**S103296811**

Local Case: H37569-001  
 Basin Number: 908.20  
 Gwater Depth: 31.8  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 01/16/1998  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 441 10TH AVE

17

**DONEV COMPANY**  
**441 10TH AV**  
**SAN DIEGO, CA 92101**

**LUST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**S104756257**  
**N/A**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302355  
 Stop Date: 1998-01-16 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1998-06-23 00:00:00  
 Discover Date: 1998-01-16 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-01-22 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: C/O PETER J. HALL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DONEV COMPANY (Continued)**

**S104756257**

RP Address: 2104 EL AMIGO RD  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37569-001  
 Case Number: 9UT3587  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 137569  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 441 10TH STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: PETER HALL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DONEV COMPANY (Continued)**

**S104756257**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT3969  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H37569-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DONEV COMPANY (Continued)**

**S104756257**

FStatus: Closed Case  
 Date: 6/23/1998  
 Begandt: 1/16/1998

17

**CONTINENTAL CLEANERS  
 450 10TH AVENUE  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106797732  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37720028  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-02-21 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37720028  
 Alias Type: Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL CLEANERS (Continued)**

**S106797732**

Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

17

**CONTINENTAL CLEANERS**  
**450 10TH AV**  
**SAN DIEGO, CA 92101**

**LUST**  
**San Diego Co. HMMD**  
**AIRS**  
**SAN DIEGO CO. SAM**

**S105539550**  
**N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608161312  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-11-19 00:00:00  
 Discover Date: 1999-08-19 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-02-25 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL CLEANERS (Continued)**

**S105539550**

Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H11621-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 111621  
 Inactive Indicator: Active  
 Business Code: 6HK53  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ERIN KELLY KARNES TRUSTEE  
 Mailing Address: 450 10TH AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD981584188  
 Gas Station: Not reported  
 Inspection Date: 05/13/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: JEEF PHELPS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CONWAY ENTERPRISES L L C  
 Property Address: 11 NEWPORT CIR  
 Property City,St,Zip: 80906  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 11/13/05  
 Facility Phone: 619-232-3598

**HMMD DISCLOSURE INVENTORY:**

Item Number: FA11  
 Chemical Name: FABRICOL  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL CLEANERS (Continued)**

**S105539550**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: PE10  
 Chemical Name: PERCHLOROETHYLENE  
 Case Number: 127-18-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/30/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 0187  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 12/30/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 0188  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 05/16/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5240  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/31/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9331  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 08/31/01

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL CLEANERS (Continued)**

**S105539550**

Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9332  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 11/08/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4198  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/13/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1548  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 05/13/04  
 Waste Item #: 251  
 Waste Code: 251  
 Waste Name: STILL BOTTOMS W/HALO  
 Qnty at Inspection: 160  
 Quantity String: 160  
 Annual Qty: 675  
 Annual Qty String: 675  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1953 AA DISPOSAL  
 Waste Desc: STILL BOTTOMS OIL W/ PERC  
 Carcinogen: No

Inspection Date: 05/13/04  
 Waste Item #: 351  
 Waste Code: 351  
 Waste Name: ORGANIC SOLIDS WITH  
 Qnty at Inspection: 150  
 Quantity String: 150  
 Annual Qty: 1700  
 Annual Qty String: 1700  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1953 AA DISPOSAL  
 Waste Desc: CARTRIDGES (32/YEAR)  
 Carcinogen: No

**EMI:**

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL CLEANERS (Continued)**

**S105539550**

Facility ID: 6245  
 Air District Name: SD  
 SIC Code: 7216  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6245  
 Air District Name: SD  
 SIC Code: 7216  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6245  
 Air District Name: SD  
 SIC Code: 7216  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6245  
 Air District Name: SD  
 SIC Code: 7216  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL CLEANERS (Continued)**

**S105539550**

Total Organic Hydrocarbon Gases Tons/Yr: 1  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6245  
 Air District Name: SD  
 SIC Code: 7216  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6245  
 Air District Name: SD  
 SIC Code: 7216  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1.0395  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6245  
 Air District Name: SD  
 SIC Code: 7216  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL CLEANERS (Continued)**

**S105539550**

Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

SAN DIEGO CO. SAM:

Case Number: H11621-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 11/19/2003  
 Begandt: 8/19/1999

Case Number: H11621-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/7/2007  
 Begandt: 8/19/1999

18

**12TH & ISLAND  
 443 12TH AV  
 SAN DIEGO, CA 92101**

**LUST S105692917  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608124519  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-11-15 00:00:00  
 Discover Date: 2002-02-11 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2002-02-11 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**12TH & ISLAND (Continued)**

**S105692917**

Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Mike Platzer/Mike Ay  
 RP Address: 5790 Fleet Street, #210  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14943-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H14943-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 11/15/2005  
 Begandt: 2/11/2002

19

**ALLAN COMPANY**  
**415 14TH ST**  
**SAN DIEGO, CA 92101**

**HAZNET S104746969**  
**LUST N/A**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**HAZNET:**

Gepaid: CAC002283745  
 Contact: CCDC  
 Telephone: 6195337112  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 225 BROADWAY STE 110  
 Mailing City,St,Zip: SAN DIEGO, CA 921015074  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALLAN COMPANY (Continued)**

**S104746969**

Disposal Method: Recycler  
 Tons: 15.0120  
 Facility County: San Diego  
  
 Gepaid: CAC002283745  
 Contact: CCDC  
 Telephone: 6195337112  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 225 BROADWAY STE 110  
 Mailing City,St,Zip: SAN DIEGO, CA 921015074  
 Gen County: San Diego  
 TSD EPA ID: CAD980675276  
 TSD County: Kern  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Not reported  
 Tons: 212.3856  
 Facility County: San Diego

Gepaid: CAC002283745  
 Contact: CCDC  
 Telephone: 6195337112  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 225 BROADWAY STE 110  
 Mailing City,St,Zip: SAN DIEGO, CA 921015074  
 Gen County: San Diego  
 TSD EPA ID: CAD980675276  
 TSD County: Kern  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Land Fill  
 Tons: 4353.0620  
 Facility County: San Diego

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608113015  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-02-14 00:00:00  
 Discover Date: 1991-06-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-06-17 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALLAN COMPANY (Continued)**

**S104746969**

Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: STEVE YOUNG  
 RP Address: 14618 ARROW HWY.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10674-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMMD:

Facility ID: 110674  
 Inactive Indicator: Active  
 Business Code: 6HK32  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 415 14TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAL000049616

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALLAN COMPANY (Continued)**

**S104746969**

Gas Station: Not reported  
 Inspection Date: 02/16/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: EDWARD COOK  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CITY OF SAN DIEGO REDEVELOPMEN  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-231-9666

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALLAN COMPANY (Continued)**

**S104746969**

Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H10674-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/14/1992  
 Begandt: 6/17/1991

**20**

**FISCHER PARCEL  
 304 J STREET  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106893818  
 N/A**

**ENVIROSTOR:**

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000059  
 Site Code: Not reported  
 Assembly: 76  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-03-06 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37000059  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

**Completed Info:**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 03/06/00

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FISCHER PARCEL (Continued)**

**S106893818**

Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported  
 Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

21

**SDG&E STATION A, TANK 1801  
 114 10TH AVE  
 SAN DIEGO, CA 92101**

**LUST S104494715  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT4021  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: Not reported  
 Date Found: 11/15/1999  
 How Found: Tank Closure  
 Date Stopped: 11/15/1999  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Other Cause  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: / /  
 Submit Workplan: 1/12/00  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/10/00  
 Pilot Program: LOP  
 Local Case: H13946-003  
 Basin Number: 908.21  
 Gwater Depth: 10  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Disp: Administratively opened on database, however no file physically exists

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG&E STATION A, TANK 1801 (Continued)**

**S104494715**

Release Date: 11/15/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

21

**SDGE STA A BL 148 FUELING FAC  
 114 10TH AV  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S106064925  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302747  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-08-14 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDGE STA A BL 148 FUELING FAC (Continued)**

**S106064925**

Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13946-002  
 Case Number: 9UT440  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302748  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-08-19 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDGE STA A BL 148 FUELING FAC (Continued)**

**S106064925**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13946-001  
 Case Number: 9UT441  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607399223  
 Stop Date: 1999-11-15 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-05-17 00:00:00  
 Discover Date: 1999-05-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-05-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDGE STA A BL 148 FUELING FAC (Continued)**

**S106064925**

Contact Person: Not reported  
 Responsible Party: KEN ROWLAND  
 RP Address: P O BOX 3249  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13946-003  
 Case Number: 9UT4021  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 136431  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 1831  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: JACKIE SPARREY MCHUGH  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

**SDGE STA A BL 148 FUELING FAC (Continued)**

**S106064925**

Property Address: Not reported  
Property City,St,Zip: Not reported  
Tank Owner: Not reported  
Tank Address: Not reported  
Tank City,St,Zip: Not reported  
Business Plan Acceptance Date: Not reported  
Reinspection Date Y2K Compatible: Not reported  
Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
Chemical Name: Not reported  
Case Number: Not reported  
Quantity Stored At One Time: Not reported  
Quantity Stored at One Time: Not reported  
Annual Quantity String: Not reported  
Annual Quantity String: Not reported  
Measurement Units: Not reported  
Carcinogen: No  
1st Hazard Category: Not reported  
2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
Tank ID Number: Not reported  
Waste or Product: Not reported  
Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
Waste Code: Not reported  
Type of Violation: Not reported  
Occurrences: Not reported  
Item Number: Not reported  
Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
Waste Item #: Not reported  
Waste Code: Not reported  
Waste Name: Not reported  
Qty at Inspection: Not reported  
Quantity String: Not reported  
Annual Qty: Not reported  
Annual Qty String: Not reported  
Measurement Unit: Not reported  
Treatment Method: Not reported  
Storage Method: Not reported  
Haz Waste Hauler: Not reported  
Waste Desc: Not reported  
Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H13946-001  
Agency: DEH Site Assessment & Mitigation

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDGE STA A BL 148 FUELING FAC (Continued)**

**S106064925**

**Funding:** Private - VAP  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/19/1987  
 Begandt: 7/3/1986

Case Number: H13946-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** LOP - Federal Fund  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/14/1987  
 Begandt: 4/28/1987

Case Number: H13946-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** LOP - Federal Fund  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/17/2000  
 Begandt: 5/18/1999

21

**SDG & E SERVICE BUILD**  
**114 TENTH AVENUE**  
**SAN DIEGO, CA 92101**

**RCRA-SQG 1000100350**  
**HAZNET CAD981572076**  
**LUST**  
**Cortese**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: SDG & E SERVICE BUILD  
 Facility address: 114 TENTH AVENUE  
 SAN DIEGO, CA 92101  
 EPA ID: CAD981572076  
 Mailing address: PO BOX 1831  
 SAN DIEGO, CA 92112  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SDG & E SERVICE BUILD (Continued)**

**1000100350**

Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
  
 Owner/operator name: SAN DIEGO GAS & ELEC  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 08/30/1986  
 Facility name: SDG & E SERVICE BUILD  
 Classification: Large Quantity Generator

Violation Status: No violations found

HAZNET:

Gepaid: CAC001435512  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE STE 1200  
 Mailing City, St, Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: Not reported  
 Tons: .3000  
 Facility County: San Diego

Gepaid: CAC001435512  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SDG & E SERVICE BUILD (Continued)**

**1000100350**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE STE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 30.9972  
 Facility County: San Diego

Gepaid: CAC001435512  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE STE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus inorganics  
 Disposal Method: Transfer Station  
 Tons: .0750  
 Facility County: San Diego

Gepaid: CAC001435512  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE STE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAR000005454  
 TSD County: Sonoma  
 Waste Category: Polychlorinated biphenyls and material containing PCB's  
 Disposal Method: Not reported  
 Tons: .3750  
 Facility County: San Diego

Gepaid: CAC001435512  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE STE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .1500  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SDG & E SERVICE BUILD (Continued)**

**1000100350**

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

LUST:

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: FIRST  
 Enf Type: Not reported  
 Funding: SEL  
 How Discovered: Tank Closure  
 How Stopped: Not reported  
 Leak Cause: UNK  
 Leak Source: UNK  
 Global Id: T0605901964  
 Stop Date: 1996-04-27 00:00:00  
 Confirm Leak: 1996-04-27 00:00:00  
 Workplan: 1998-04-22 00:00:00  
 Prelim Assess: Not reported  
 Pollution Char: 2008-03-05 00:00:00  
 Remed Plan: 2002-08-22 00:00:00  
 Remed Action: 2007-11-21 00:00:00  
 Monitoring: 2005-07-19 00:00:00  
 Close Date: Not reported  
 Discover Date: 2002-06-05 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1996-04-29 00:00:00  
 Review Date: 2002-08-07 00:00:00  
 Enter Date: 2002-05-09 00:00:00  
 MTBE Date: 2005-12-06 00:00:00  
 GW Qualifier: =  
 Soil Qualifier: =  
 Max MTBE GW ppb: 930 (MAX)  
 Max MTBE Soil ppb: 0.57  
 County: 30  
 Org Name: Not reported  
 Reg Board: Santa Ana Region  
 Status: Pollution Characterization  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: TOSCO MARKETING COMPANY  
 RP Address: P.O. BOX 25376, SANTA ANA, CA 92626  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 29  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: NOM  
 Staff Initials: CC  
 Lead Agency: Regional Board  
 Local Agency: 30020  
 Hydr Basin #: COASTAL PLAIN OF ORA  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SDG & E SERVICE BUILD (Continued)**

**1000100350**

Case Number: 083002862T  
 Qty Leaked: Not reported  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Operator: ENAYAT FAZELI  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: MTBE DATE (REPORT 4/99)

**LUST:**

Region: 8  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: FIRST  
 Enf Type: SEL  
 Funding: Not reported  
 How Discovered: Tank Closure  
 How Stopped: Not reported  
 Leak Cause: UNK  
 Leak Source: UNK  
 Global ID: T0605901964  
 How Stopped Date: 4/27/1996  
 Review Date: 4/27/1996  
 Workplan: 4/22/1998  
 Prelim Assess: Not reported  
 Pollution Char: 4/26/1999  
 Remed Plan: 8/22/2002  
 Remed Action: 10/21/2004  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 6/5/2002  
 Enforcement Date: Not reported  
 Review Date: 8/7/2002  
 Enter Date: 5/9/2002  
 MTBE Date: 11/7/2002  
 GW Qualifies: =  
 Soil Qualifies: =  
 Max MTBE GW: 130000  
 Max MTBE Soil: 15000  
 County: Orange  
 Operator: Not reported  
 Regional Board: 08  
 Facility Status: Remedial action (cleanup) Underway  
 Substance: 12031  
 Facility Contact: Not reported  
 Interim: Not reported  
 Oversight Program: LUST  
 Latitude: 33.74523624  
 Longitude: -117.8854209  
 MTBE Concentration: 18  
 MTBE Fuel: 1  
 MTBE Tested: YES  
 Staff: NOM  
 Staff Initials: JB  
 Lead Agency: Regional Board



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG & E SERVICE BUILD (Continued)**

**1000100350**

Local Agency: Santa Ana, Orange County  
 Hydr Basin #: COASTAL PLAIN OF ORA  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case Num: Not reported  
 Case Number: 083002862T  
 Qty Leaked: Not reported  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 MTBE Class: \*  
 Summary: MTBE DATE (REPORT 4/99)

**LUST:**

Region: 9  
 Case Number: 9UT3457  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 05/21/1996  
 How Found: Not reported  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 06/10/1996  
 Desc Pollution: Not reported  
 Remed Plan: 02/17/1999  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 6/10/96  
 Closed Date: 6/28/00  
 Pilot Program: LOP  
 Local Case: H36431-001  
 Basin Number: 908.21  
 Gwater Depth: 14  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 2  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 05/21/1996  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG & E SERVICE BUILD (Continued)**

**1000100350**

Facility Addr2: Not reported  
 Region: CORTESE  
 Facility Addr2: Not reported  
 Region: CORTESE  
 Facility Addr2: 114 BRISTOL ST

21

**SAN DIEGO GAS &ELEC TANK #1702  
 114 10TH AVE W  
 SAN DIEGO, CA 92101**

**LUST S102436315  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT441  
 Local Agency: San Diego  
 Substance: 0  
 Qty Leaked: 0  
 Date Found: 06/24/1986  
 How Found: Tank Closure  
 Date Stopped: / /  
 How Stopped: Remove Contents  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 04/01/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 7/31/87  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 8/19/87  
 Pilot Program: LOP  
 Local Case: H13946-001  
 Basin Number: 908.22  
 Gwater Depth: 11'  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 06/26/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>21</b>	<b>SAN DIEGO GAS &amp; ELEC TANK #202</b> <b>114 10TH AVE W</b> <b>SAN DIEGO, CA 92101</b>	<b>LUST</b>	<b>S102436313</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

LUST:

Region:	9
Case Number:	9UT440
Local Agency:	San Diego
Substance:	0
Qty Leaked:	0
Date Found:	04/28/1987
How Found:	Not reported
Date Stopped:	/ /
How Stopped:	Not reported
Source:	Unknown
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Soil only
Status:	Case Closed
Abate Method:	Not reported
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	10/09/1986
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	7/1/87
Began Monitor:	Not reported
Enforce Type:	Not reported
Enforce Date:	Not reported
Closed Date:	8/14/87
Pilot Program:	LOP
Local Case:	H13946-002
Basin Number:	908.22
Gwater Depth:	14'
Beneficial Use:	Not reported
NPDES Number:	Not reported
priority:	3
File Dispn:	File discarded, case closed
Release Date:	04/24/1987
Interim Remedial Actions:	No
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

<b>21</b>	<b>EAST VILLAGE RDA</b> <b>200 10TH AV</b> <b>SAN DIEGO, CA 92101</b>	<b>LUST</b>	<b>S105539737</b> <b>N/A</b>
-----------	---	-------------	---------------------------------

**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Other Means
Leak Cause:	Other Cause
Leak Source:	Other Source
Global Id:	T06019730884
Stop Date:	2003-12-19 00:00:00
Confirm Leak:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-12-12 00:00:00  
 Discover Date: 2003-12-19 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2003-12-19 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: Sergio Sandoval  
 RP Address: 600 B Street, Ste. 1500  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-050  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T06019735701  
 Stop Date: 2004-02-02 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-07-23 00:00:00  
 Discover Date: 2004-02-02 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2004-02-02 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: David McCall  
 RP Address: 560 First Avenue  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-051  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T06019751936  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-08-25 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: David Alsbrook, Manager  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-053  
 Case Number: Not reported  
 Qty Leaked: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019754756  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2004-06-10 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Beneficial: Not reported  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-052  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Other Source  
 Global Id: T0607313974  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-11-06 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-044  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607316364  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2003-07-23 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Contact Person: Not reported  
 Responsible Party: Jim Chatfield  
 RP Address: 12680 High Bluff Dr.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-049  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Spill  
 Leak Source: Other Source  
 Global Id: T0607325882  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-12-13 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-047  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0607343445  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-03-14 00:00:00  
 Discover Date: 1998-10-08 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-045  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Piping  
 Global Id: T0607382884  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-07-21 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-046  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607393919  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-08-24 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-048  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608102930  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-05-15 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-028  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608103520  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-11-15 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-04-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTNG  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-005  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608104489  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-08-24 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-008  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608106803  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-03-18 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-09-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-021  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06081100838  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1998-10-08 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTNG  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Other Cause  
 Leak Source: Tank  
 Global Id: T0608112477  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-08-01 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-05-02 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-006  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Other Source  
 Global Id: T0608118231  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-08-08 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-010  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Leak Source: Other Source  
 Global Id: T0608119205  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2002-10-16 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-04-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-013  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608121620  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-08-15 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-05-19 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-009  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608122609  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-11-23 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTNG  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Work Suspended: Not reported  
 Local Case #: H37163-007  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608124740  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2002-03-03 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-07-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-017  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608125175  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-03-31 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-09-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Michael Uberuaga  
 RP Address: 225 BROADWAY, SUITE 1100

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-020  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608127828  
 Stop Date: 2000-03-27 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-06-25 00:00:00  
 Discover Date: 2000-03-27 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-03-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-025  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608128249  
 Stop Date: 2000-10-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-07-23 00:00:00  
 Discover Date: 2000-10-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-10-24 00:00:00  
 Review Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-027  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0608128850  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-08-24 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-036  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Other Cause  
 Leak Source: Tank

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Global Id: T0608138058  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-09-11 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-034  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608139488  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-02-09 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-015  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608140296  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-12-30 00:00:00  
 Discover Date: 2000-06-01 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-06-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Hydraulic Oil  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Local Case #: H37163-026  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608140620  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-02-26 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-04-13 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-004  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608141429  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-08-24 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-038  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608145775  
 Stop Date: 1999-11-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-09-18 00:00:00  
 Discover Date: 1999-11-20 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-11-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-023  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608146201  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-09-11 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-09-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-018  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608158243  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Monitoring: Not reported  
 Close Date: 2004-02-09 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-031  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608158247



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Stop Date: 2000-01-06 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-09-18 00:00:00  
 Discover Date: 2000-01-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-01-06 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-024  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608163055  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-08-03 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-041  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Spill  
 Leak Source: Other Source  
 Global Id: T0608166315  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-08-01 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-02-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608171842  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-02-26 00:00:00  
 Discover Date: 1999-11-16 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-11-16 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-022  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608174803  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-02-26 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-019  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608179688  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-02-09 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-032  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608179848  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-02-01 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-05-19 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-011  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608180309  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Close Date: 2005-12-12 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-043  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608180423  
 Stop Date: 1998-10-08 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-05-26 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-014  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608182633  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-11-23 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-039  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608185293  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-08-03 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-042  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608186488  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-08-24 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-037  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608186777  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-05-26 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTNG  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608187251  
 Stop Date: 2000-10-13 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-07-23 00:00:00  
 Discover Date: 2000-10-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-10-13 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-029  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608190812  
 Stop Date: 1999-05-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-08-08 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-05-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-012  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608193887  
 Stop Date: 1998-10-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-03-30 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-07-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-016  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608194608  
 Stop Date: Not reported  
 Confirm Leak: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-02-09 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK, MGR CNTRCTING  
 RP Address: 225 BROADWAY, SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-030  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608195630  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-09-18 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-035  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608195794  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-02-09 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-033  
 Case Number: Not reported  
 Qty Leaked: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Spill  
 Leak Source: Unknown  
 Global Id: T0608196703  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-11-18 00:00:00  
 Discover Date: 1998-10-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: David Allsbrook  
 RP Address: 225 Broadway Street, Suite 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37163-040  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 137163  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: CENTER CITY DEVLPMT CORP  
 Mailing Address: 255 BROADWAY 1100  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: DAVID ALLSBROOK, MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: CENTRE CITY DEVELOPMENT CORP.  
 Tank Address: 225 BROADWAY 1100  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: at4637  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: AT4609  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: AT4806  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: AT5007  
 Waste or Product: Not reported  
 Tank Contents: OTHER

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Case Number: H37163-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 10/8/1998  
 Begandt: 10/8/1998

Case Number: H37163-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/1/2003  
 Begandt: 10/8/1998

Case Number: H37163-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/26/2006  
 Begandt: 10/8/1998

Case Number: H37163-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/26/2004  
 Begandt: 10/8/1998

Case Number: H37163-005  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 11/15/2004  
 Begandt: 10/8/1998

Case Number: H37163-006  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/1/2003  
 Begandt: 10/8/1998

Case Number: H37163-007  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 11/23/2004  
 Begandt: 10/8/1998

Case Number: H37163-008

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/24/2004  
 Begandt: 10/8/1998

Case Number: H37163-009  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 8/15/2003  
 Begandt: 10/8/1998

Case Number: H37163-010  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 8/8/2003  
 Begandt: 10/8/1998

Case Number: H37163-011  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/1/2005  
 Begandt: 10/8/1998

Case Number: H37163-012  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 8/8/2003  
 Begandt: 10/8/1998

Case Number: H37163-013  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/16/2002  
 Begandt: 10/8/1998

Case Number: H37163-014  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/26/2006  
 Begandt: 10/8/1998

Case Number: H37163-015  
 Agency: DEH Site Assessment & Mitigation

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

**Funding:** Private - Site Designation  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/9/2004  
 Begandt: 10/8/1998

Case Number: H37163-016  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** Private - Site Designation  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/30/2004  
 Begandt: 10/8/1998

Case Number: H37163-017  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** Private - Site Designation  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/3/2002  
 Begandt: 10/8/1998

Case Number: H37163-018  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** Private - Site Designation  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/11/2003  
 Begandt: 10/8/1998

Case Number: H37163-019  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** Private - Site Designation  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/26/2004  
 Begandt: 10/8/1998

Case Number: H37163-020  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** Private - Site Designation  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/31/2004  
 Begandt: 10/8/1998

Case Number: H37163-021  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** Private - Site Designation  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/18/2005  
 Begandt: 10/8/1998

Case Number: H37163-022  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** Private - Site Designation

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/26/2004  
 Begandt: 11/16/1999

Case Number: H37163-023  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/18/2007  
 Begandt: 11/20/1999

Case Number: H37163-024  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/18/2007  
 Begandt: 1/6/2000

Case Number: H37163-025  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/25/2004  
 Begandt: 3/27/2000

Case Number: H37163-026  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/30/2003  
 Begandt: 6/1/2000

Case Number: H37163-027  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 7/23/2007  
 Begandt: 10/24/2000

Case Number: H37163-028  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/15/2006  
 Begandt: 10/8/1998

Case Number: H37163-029  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

FStatus: Closed Case  
 Date: 7/23/2007  
 Begandt: 10/24/2000

Case Number: H37163-030  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/9/2004  
 Begandt: 10/8/1998

Case Number: H37163-031  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/9/2004  
 Begandt: 10/8/1998

Case Number: H37163-032  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/9/2004  
 Begandt: 10/8/1998

Case Number: H37163-033  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/9/2004  
 Begandt: 10/8/1998

Case Number: H37163-034  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/11/2003  
 Begandt: 10/8/1998

Case Number: H37163-035  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/18/2007  
 Begandt: 4/5/2002

Case Number: H37163-036  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EAST VILLAGE RDA (Continued)**

**S105539737**

Date: 8/24/2004  
 Begandt: 10/8/1998

Case Number: H37163-037  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/24/2004  
 Begandt: 10/8/1998

Case Number: H37163-038  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/24/2004  
 Begandt: 10/8/1998

Case Number: H37163-039  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 11/23/2004  
 Begandt: 10/8/1998

Case Number: H37163-040  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 11/18/2004  
 Begandt: 10/8/1998

Case Number: H37163-041  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/3/2005  
 Begandt: 10/8/1998

Case Number: H37163-042  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/3/2005  
 Begandt: 10/8/1998

Case Number: H37163-043  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/12/2005

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Begandt: 10/8/1998

Case Number: H37163-044  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 11/6/2003  
 Begandt: 10/8/1998

Case Number: H37163-045  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/14/2006  
 Begandt: 10/8/1998

Case Number: H37163-046  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 7/21/2004  
 Begandt: 10/8/1998

Case Number: H37163-047  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Post Remedial Monitoring  
 Date: 8/4/2003  
 Begandt: 10/8/1998

Case Number: H37163-048  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/24/2004  
 Begandt: 11/24/1998

Case Number: H37163-049  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Remedial Investigation  
 Date: 7/23/2003  
 Begandt: Not reported

Case Number: H37163-050  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/12/2005  
 Begandt: 12/19/2003

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST VILLAGE RDA (Continued)**

**S105539737**

Case Number: H37163-051  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 7/23/2007  
 Begandt: 2/2/2004

Case Number: H37163-052  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 6/10/2004  
 Begandt: Not reported

Case Number: H37163-053  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/25/2004  
 Begandt: 10/8/1998

Case Number: H37163-054  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 11/6/2006  
 Begandt: Not reported

21

**SAN DIEGO GAS AND ELECTRIC STATION A**  
**250 10TH AVENUE**  
**SAN DIEGO, CA 92101**

**ENVIROSTOR S106893854**  
**N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37490035  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-06-14 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37490035



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GAS AND ELECTRIC STATION A (Continued)**

**S106893854**

Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

21

**SDG&E/STATION A BLOCK 135  
 250 10TH AV  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104757243  
 N/A**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608187072  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-06-20 00:00:00  
 Discover Date: 2000-05-18 00:00:00  
 Enforcement Dt: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG&E/STATION A BLOCK 135 (Continued)**

**S104757243**

Release Date: 2000-05-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: KEN ROWLAND  
 RP Address: P O BOX 3249  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H39133-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 139133  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG&E/STATION A BLOCK 135 (Continued)**

**S104757243**

EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG&E/STATION A BLOCK 135 (Continued)**

**S104757243**

Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H39133-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/20/2000  
 Begandt: 5/18/2000

21

**BALL PARK  
 175 11TH AV  
 SAN DIEGO, CA 92101**

**LUST S107619740  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019706650  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2005-11-16 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BALL PARK (Continued)**

**S107619740**

Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Sean Scholey/Roberta Correia  
 RP Address: 701 B Street, Suite 1400  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H39680-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H39680-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 11/16/2005  
 Begandt: Not reported

21

**STATION A TANK 203 BLOCK 150  
 175 11TH AVE  
 SAN DIEGO, CA 92101**

**LUST S104494729  
 N/A**

**LUST:**

Region: 9  
 Case Number: 9UT4039  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 03/10/2000  
 How Found: Tank Closure  
 Date Stopped: 03/10/2000  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**STATION A TANK 203 BLOCK 150 (Continued)**

**S104494729**

Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: / /  
 Submit Workplan: 3/17/00  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 6/16/00  
 Pilot Program: LOP  
 Local Case: H36432-002  
 Basin Number: 908.21  
 Gwater Depth: 10  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: 2  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 03/10/2000  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

21

**BALLPARK INFRASTRUCTURE SITE  
 K ST AND IMPERIAL BORDERED BY  
 SAN DIEGO, CA 92101**

**FINDS 1001967477  
 HAZNET CAR000069518  
 LUST  
 SAN DIEGO CO. SAM  
 RCRA-NonGen**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000069518  
 Contact: DERRICK ANDERSON  
 Telephone: 6195333147  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE SUITE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921014905  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BALLPARK INFRASTRUCTURE SITE (Continued)**

1001967477

Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 2.71  
 Facility County: Not reported

Gepaid: CAR000069518  
 Contact: DERRICK ANDERSON  
 Telephone: 6195333147  
 Facility Addr2: 10TH AVE AND 7TH AVE  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE SUITE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921014905  
 Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: San Diego  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Not reported  
 Tons: 14.15  
 Facility County: San Diego

Gepaid: CAR000069518  
 Contact: DERRICK ANDERSON  
 Telephone: 6195333147  
 Facility Addr2: 10TH AVE AND 7TH AVE  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE SUITE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921014905  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: San Diego  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.03  
 Facility County: San Diego

Gepaid: CAR000069518  
 Contact: DERRICK ANDERSON  
 Telephone: 6195333147  
 Facility Addr2: 10TH AVE AND 7TH AVE  
 Mailing Name: Not reported  
 Mailing Address: 1010 2ND AVE SUITE 1200  
 Mailing City,St,Zip: SAN DIEGO, CA 921014905  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.42  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BALLPARK INFRASTRUCTURE SITE (Continued)**

1001967477

Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608133149  
 Stop Date: 2002-02-28 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2002-02-28 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2002-02-28 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Not reported  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02733-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BALLPARK INFRASTRUCTURE SITE (Continued)**

**1001967477**

Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H02733-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Soils Only  
 FStatus: Remedial Action (Clean-Up)  
 Date: 2/28/2002  
 Begandt: 2/28/2002

**RCRA-NonGen:**

Date form received by agency: 04/04/2000  
 Facility name: BALLPARK INFRASTRUCTURE SITE  
 Facility address: K ST AND IMPERIAL BORDERED BY  
 10TH AVE AND 7TH AVE  
 SAN DIEGO, CA 92101  
 EPA ID: CAR000069518  
 Mailing address: 1010 2ND AVE SUITE 1200  
 THE CITY OF SAN DIEGO  
 SAN DIEGO, CA 92101 4905  
 Contact: ANDY CERIN  
 Contact address: 1010 2ND AVE SUITE 1200 THE CITY OF SAN DIEGO  
 SAN DIEGO, CA 92101 4905  
 Contact country: US  
 Contact telephone: 858-492-5003  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: CITY OF SAN DIEGO  
 Owner/operator address: 1010 2ND AVE SUITE 1200  
 SAN DIEGO, CA 92101  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 533-3147  
 Legal status: Municipal  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/0001  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BALLPARK INFRASTRUCTURE SITE (Continued)**

**1001967477**

User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D004  
 Waste name: ARSENIC

Violation Status: No violations found

21

**SOUTHWEST MARINE HARDWARE  
 944 K ST  
 SAN DIEGO, CA 92101**

**HAZNET S100727085  
 LUST N/A  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**HAZNET:**

Gepaid: CAL000020339  
 Contact: THOMPSON KEN  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 944 K ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017420  
 Gen County: San Diego  
 TSD EPA ID: CAD009452657  
 TSD County: San Mateo  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: .1167  
 Facility County: San Diego

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE HARDWARE (Continued)**

**S100727085**

Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300409  
 Stop Date: 1989-08-12 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-12-30 00:00:00  
 Discover Date: 1989-08-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-08-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: KEN THOMPSON  
 RP Address: 940 K ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05621-001  
 Case Number: 9UT1589  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST MARINE HARDWARE (Continued)**

**S100727085**

Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 105621  
 Inactive Indicator: Active  
 Business Code: 6HK33  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 944 K ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAL000020339  
 Gas Station: Not reported  
 Inspection Date: 02/26/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: KEN THOMPSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 233-4094

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE HARDWARE (Continued)**

**S100727085**

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SWEEPS UST:

Status: Not reported  
 Comp Number: 5621  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005621-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 5621  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE HARDWARE (Continued)**

**S100727085**

Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H05621-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/30/1992  
 Begandt: 8/12/1989

21

**SOUTHWEST HARDWARE  
 944 K ST  
 SAN DIEGO, CA 92101**

**LUST S102437923  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT1589  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 08/18/1989  
 How Found: Tank Closure  
 Date Stopped: 08/18/1989  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Spill  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 12/11/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 12/18/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/30/92  
 Pilot Program: LOP  
 Local Case: H05621-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 12/11/1989  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**SOUTHWEST HARDWARE (Continued)**

**S102437923**

Cortese:  
 Region:           CORTESE  
 Facility Addr2:   944 K ST

**21           ALTA E. OLIVER TRUST PROPERTY  
 312 11TH AVE  
 SAN DIEGO, CA 92101**

**LUST   S100729914  
 N/A**

LUST:  
 Region:           9  
 Case Number:     9UT3154  
 Local Agency:    San Diego  
 Substance:       Gasoline  
 Qty Leaked:      0  
 Date Found:      12/22/1995  
 How Found:       Other Means  
 Date Stopped:    02/23/1996  
 How Stopped:     Other Means  
 Source:           Unknown  
 Cause:            Unknown  
 Lead Agency:     Local Agency  
 Case Type:        Other ground water affected  
 Status:           Case Closed  
 Abate Method:    No Action Taken - no action has as yet been taken at the site  
 Confirm Date:    / /  
 Submit Workplan: 2/23/96  
 Prelim Assess:   03/15/1996  
 Desc Pollution:   Not reported  
 Remed Plan:      / /  
 Remed Action:    Not reported  
 Began Monitor:   Not reported  
 Enforce Type:    Not reported  
 Enforce Date:    Not reported  
 Closed Date:     4/12/99  
 Pilot Program:   LOP  
 Local Case:      H14646-001  
 Basin Number:    908.21  
 Gwater Depth:   25.6  
 Beneficial Use:   No Beneficial groundwater use  
 NPDES Number:   Not reported  
 priority:         2  
 File Dispn:      Administratively opened on database, however no file physically exists  
 Release Date:    12/22/1995  
 Interim Remedial Actions:           Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

21 ATLAS FIRE EQUIPMENT CO  
 312 11TH AV  
 SAN DIEGO, CA 92101

San Diego Co. HMMD  
 SAN DIEGO CO. SAM

LUST S105539583  
 N/A

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019710663  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2004-09-02 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Marvin Levin  
 RP Address: 1981 North Broadway, Suite 415  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14646-002  
 Case Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ATLAS FIRE EQUIPMENT CO (Continued)**

**S105539583**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301922  
 Stop Date: 1996-02-23 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1999-04-12 00:00:00  
 Discover Date: 1995-12-22 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1995-12-22 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: STANLEY CHAPMAN  
 RP Address: 312 11TH AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ATLAS FIRE EQUIPMENT CO (Continued)**

**S105539583**

Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14646-001  
 Case Number: 9UT3154  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 114646  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 312 11TH AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/01/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: GLENN TERADA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: 10TH&K L L C  
 Property Address: 1981 N BROADWAY #415  
 Property City,St,Zip: 94596  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-5745

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ATLAS FIRE EQUIPMENT CO (Continued)**

**S105539583**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H14646-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 4/12/1999  
 Begandt: 12/22/1995

Case Number: H14646-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Remedial Investigation  
 Date: 9/2/2004

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

---

**ATLAS FIRE EQUIPMENT CO (Continued)**

**S105539583**

Begandt: Not reported

21

**LIBRARY TOWER  
325 12TH AV  
SAN DIEGO, CA 92101**

**LUST S107619836  
SAN DIEGO CO. SAM N/A**

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global Id:	T06019712843
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	2006-03-28 00:00:00
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	Not reported
Enforcement Dt:	Not reported
Release Date:	Not reported
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	37
Org Name:	Not reported
Reg Board:	San Diego Region
Status:	Preliminary site assessment underway
Chemical:	Not reported
Contact Person:	Not reported
Responsible Party:	CW San Diego Towers, OLC, LLC
RP Address:	600 West Broadway, Ste. 250
Interim:	Not reported
Oversight Prgm:	LOCNL
MTBE Class:	*
MTBE Conc:	0
MTBE Fuel:	0
MTBE Tested:	Not Required to be Tested.
Staff:	UNA
Staff Initials:	TS
Lead Agency:	Local Agency
Local Agency:	37000L
Hydr Basin #:	Not reported
Beneficial:	Not reported
Priority:	7
Cleanup Fund Id:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LIBRARY TOWER (Continued)**

**S107619836**

Work Suspended: Not reported  
 Local Case #: H39674-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H39674-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 3/28/2006  
 Begandt: Not reported

21

**SDCTY-POLICE REPAIR FACILITY  
 300 12TH AV  
 SAN DIEGO, CA 92101**

**LUST S106915831  
 SAN DIEGO CO. SAM N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T06019737965  
 Stop Date: 2005-02-14 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2005-02-14 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2005-02-14 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2005-02-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDCTY-POLICE REPAIR FACILITY (Continued)**

**S106915831**

Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: Julie Ballesteros  
 RP Address: 1010 2nd Ave., Ste. 1400  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H12887-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H12887-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 2/11/2005  
 Begandt: Not reported

21

**CITY OF SAN DIEGO  
 330 12TH AVE  
 SAN DIEGO, CA 92101**

**LUST S102428064  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT1176  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: Not reported  
 Date Found: 07/13/1988  
 How Found: Tank Test  
 Date Stopped: 07/13/1988  
 How Stopped: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO (Continued)**

**S102428064**

Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 07/13/1988  
 Submit Workplan: 11/4/88  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/11/89  
 Pilot Program: LOP  
 Local Case: H12887-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 07/13/1988  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 330 12TH AVE

21

**SD CITY POLICE  
 330 12TH AV  
 SAN DIEGO, CA 92101**

**LUST S104747547  
 AIRS N/A  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Other Cause  
 Leak Source: Tank  
 Global Id: T06019705202  
 Stop Date: 2006-07-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2006-07-20 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD CITY POLICE (Continued)**

**S104747547**

Discover Date: 2006-07-20 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2006-08-03 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Craig Fergusson  
 RP Address: 9601 Ridgehaven Ct, #310  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H12887-004  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300149  
 Stop Date: 1988-07-13 00:00:00  
 Confirm Leak: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD CITY POLICE (Continued)**

**S104747547**

Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-01-11 00:00:00  
 Discover Date: 1988-07-13 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-07-13 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: PAUL GAGLIARDO  
 RP Address: 1010 SECOND ST, STE 444  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H12887-001  
 Case Number: 9UT1176  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD CITY POLICE (Continued)**

**S104747547**

How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Spill  
 Leak Source: Tank  
 Global Id: T0607301238  
 Stop Date: 1993-07-21 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1999-05-11 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1993-07-21 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1993-07-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: UST PROGRAM /TED OLSON  
 RP Address: 4950 MURPHY CANYON RD  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H12887-002  
 Case Number: 9UT2484  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD CITY POLICE (Continued)**

**S104747547**

Summary: Not reported

EMI:

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6242  
 Air District Name: SD  
 SIC Code: 9221  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6242  
 Air District Name: SD  
 SIC Code: 9221  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6242  
 Air District Name: SD  
 SIC Code: 9221  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD CITY POLICE (Continued)**

**S104747547**

Facility ID: 6242  
 Air District Name: SD  
 SIC Code: 9221  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6242  
 Air District Name: SD  
 SIC Code: 9221  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0.343404315  
 Reactive Organic Gases Tons/Yr: 0.316725  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6242  
 Air District Name: SD  
 SIC Code: 9221  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: .343404315  
 Reactive Organic Gases Tons/Yr: .316725  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

**SAN DIEGO CO. SAM:**

Case Number: H12887-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 12/7/2004  
 Begandt: 7/21/1993

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD CITY POLICE (Continued)**

**S104747547**

Case Number: H12887-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 8/6/2006  
 Begandt: 7/20/2006

Case Number: H12887-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/11/1989  
 Begandt: 7/13/1988

21

**CENTRAL POLICE STATION  
 320 12TH AVE  
 SAN DIEGO, CA 92101**

**LUST S101302193  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT2484  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 07/27/1993  
 How Found: Tank Test  
 Date Stopped: 07/21/1993  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 07/21/1993  
 Submit Workplan: Not reported  
 Prelim Assess: 07/21/1993  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H12887-002  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 07/29/1993  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTRAL POLICE STATION (Continued)**

**S101302193**

Cortese:  
 Region: CORTESE  
 Facility Addr2: 320 12TH AVE

21

**A.W. COGGESHALL  
 354 11TH AV  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD**

**S104745195  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303227  
 Stop Date: 1988-06-29 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1998-02-09 00:00:00  
 Discover Date: 1988-06-29 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-06-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: KIM FORD  
 RP Address: PO BOX 109  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A.W. COGGESHALL (Continued)**

**S104745195**

Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01037-001  
 Case Number: 9UT993  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 101037  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: CALIFORNIA FIRST BANK  
 Mailing Address: PO BOX 109  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/05/94  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: KIM FORD  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ICON L L C  
 Property Address: C/O RICHARD GARCIA  
 Property City,St,Zip: 94596  
 Tank Owner: A W COGGESTALL ESTATE  
 Tank Address: PO BOX 109  
 Tank City,St,Zip: -  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-230-4655

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**A.W. COGGESHALL (Continued)**

**S104745195**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 002  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: 003  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 06/29/88  
 Waste Code: Not reported  
 Type of Violation: 6HX3002  
 Occurrences: Not reported  
 Item Number: 6734  
 Violation Desc: UST OWNR-OPR W/O HEALTH PERMIT

Inspection Date: 06/29/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0084  
 Occurrences: Not reported  
 Item Number: 6735  
 Violation Desc: UST PRECISION TEST DATA NOT SENT TO HMMD

Inspection Date: 01/05/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3010  
 Occurrences: Not reported  
 Item Number: 0318  
 Violation Desc: PERMIT TO OPERATE APPLIC. NOT COMPLETED

Inspection Date: 01/05/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3012  
 Occurrences: Not reported  
 Item Number: 0319  
 Violation Desc: DIDN'T NOTIFY HMD OF UST CHANGES

Inspection Date: 01/05/94  
 Waste Code: Not reported  
 Type of Violation: 6HX0062



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**A.W. COGGESHALL (Continued)**

**S104745195**

Occurrences:	Not reported
Item Number:	0320
Violation Desc:	NO UST OWNER OPERATOR AGREEMENT
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HX3013
Occurrences:	Not reported
Item Number:	0321
Violation Desc:	NO FINANCIAL RESPOSIBILITY DOC
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HX3001
Occurrences:	Not reported
Item Number:	0322
Violation Desc:	UST RECORDS NOT MAINTAINED ONSITE
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HX3015
Occurrences:	Not reported
Item Number:	0323
Violation Desc:	ANNUAL INTEGRITY TEST NOT DONE
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HV3018
Occurrences:	Not reported
Item Number:	0324
Violation Desc:	IMPROPER INVENTORY RECONCILIATION
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HX3022
Occurrences:	Not reported
Item Number:	0325
Violation Desc:	GAUGING STICK IN POOR CONDITION
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HX3026
Occurrences:	Not reported
Item Number:	0326
Violation Desc:	MONITORING SYSTEM NOT FUNCTIONAL
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HX3027
Occurrences:	Not reported
Item Number:	0327
Violation Desc:	UST MONITORING PROCEDURE NOT IMPLEMENTED
Inspection Date:	01/05/94
Waste Code:	Not reported
Type of Violation:	6HX3028
Occurrences:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A.W. COGGESHALL (Continued)**

**S104745195**

Item Number: 0328  
 Violation Desc: UST RESPONSE PLAN NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

21

**CARNATION DAIRY COMPANY  
 354 11TH AVE  
 SAN DIEGO, CA 92101**

**LUST S102426362  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT993  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 06/29/1988  
 How Found: Tank Test  
 Date Stopped: 06/29/1988  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 06/29/1988  
 Submit Workplan: 9/19/88  
 Prelim Assess: 02/17/1989  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 8/3/88  
 Closed Date: 2/9/98  
 Pilot Program: LOP  
 Local Case: H01037-001  
 Basin Number: 908.21  
 Gwater Depth: 26'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EDR ID Number  
 EPA ID Number

**CARNATION DAIRY COMPANY (Continued)**

**S102426362**

File Dispn: File discarded, case closed  
 Release Date: 08/05/1988  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 354 11TH AVE

**21 A.W.COGGESHALL SAN DIEGO CO. SAM S108406933**  
**354 11TH AV N/A**  
**SAN DIEGO, CA 92101**

SAN DIEGO CO. SAM:  
 Case Number: H01037-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/9/1998  
 Begandt: 6/29/1988

**22 333 24TH ST Notify 65 S100178160**  
**SAN DIEGO, CA 92102 N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92102-2916

**23 DONALD C HARDER\_INC HAZNET 1000148760**  
**2580 K ST ENVIROSTOR N/A**  
**SAN DIEGO, CA 92102**

HAZNET:  
 Gepaid: CAC001021368  
 Contact: DONALD C HARDER  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2580 K ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .5629  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DONALD C HARDER\_INC (Continued)**

**1000148760**

Gepaid: CAC001021368  
 Contact: DONALD C HARDER  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2580 K ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Polymeric resin waste  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

**ENVIROSTOR:**

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37730138  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: \* CERC2  
 Status: No Further Action  
 Status Date: 1988-10-06 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 32.7083333333333  
 Longitude: -117.1394444444444  
 Alias Name: 37730138  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: CALSITES VALIDATION PROGRAM CONFIRMS NFA FOR DTSC."SITE SCREENING DONE NFA: UNDER CERCLA / SITE MITIGATION, BASED ON AVAILABLE INFORMATION"FACILITY IDENTIFIED VIA 1961 PHONE BOOKSITE SCREENING DONE PCB'S POSSIBLY USED ON SITE. WST DISP PRACTICES UNK"PRELIM ASSESS DONE THERE WERE NEVER ANY WASTE GENERATED ONSITE. CO. NEVER MFG OIL-TYPE TRANSFORMERS,NO RECORDS OF PCB ONSITE."

**Completed Info:**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 10/27/94  
  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DONALD C HARDER\_INC (Continued)**

**1000148760**

Completed Date: 03/10/89

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 06/28/88

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 06/14/87

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 12/01/82

Confirmed: 30386-NO  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: SOIL  
 Media Affected Desc: Soil

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30386  
 Potential Description: Methyl ethyl ketone (2-Butanone)  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: MANUFACTURING - INDUSTRIAL MACHINERY

24

**SAN DIEGO TRANSIT CORP  
 100 16TH ST  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000110674  
 FINDS CAD981448301  
 LUST  
 Cortese  
 San Diego Co. HMMD  
 CA WDS  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

RCRA-SQG:  
 Date form received by agency: 09/01/1996  
 Facility name: SAN DIEGO TRANSIT CORP  
 Facility address: 100 16TH ST  
 SAN DIEGO, CA 92101  
 EPA ID: CAD981448301  
 Mailing address: P O BOX 2511  
 SAN DIEGO, CA 92112  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: METROPOLITAN TRANSIT DEVELOPMENT BOARD  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 06/19/1991  
 Facility name: SAN DIEGO TRANSIT CORP  
 Classification: Large Quantity Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Date form received by agency: 03/04/1986  
 Facility name: SAN DIEGO TRANSIT CORP  
 Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 10/04/1993  
 Date achieved compliance: 10/04/1998  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 06/18/1992  
 Date achieved compliance: 10/04/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 11/19/1990  
 Date achieved compliance: 06/18/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/04/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 10/04/1998  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/18/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Area of violation: Generators - General  
 Date achieved compliance: 10/04/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 11/19/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/18/1992  
 Evaluation lead agency: State Contractor/Grantee

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Tank  
 Global Id: T0607301350  
 Stop Date: 1990-01-15 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2002-01-29 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1986-05-28 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-05-28 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Frank Toth, Facility Manager  
 RP Address: 1255 IMPERIAL AV #1000  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01049-001  
 Case Number: 9UT260  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607301954  
 Stop Date: 1994-05-17 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1995-11-15 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1994-05-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-05-17 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: RON DUPURIS  
 RP Address: 1255 IMPERIAL AV #1000  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01049-002  
 Case Number: 9UT3199  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT260  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 01/25/1990  
 How Found: Other Means  
 Date Stopped: / /  
 How Stopped: Remove Contents  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 01/26/1990  
 Submit Workplan: Not reported  
 Prelim Assess: 01/26/1990

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01049-001  
 Basin Number: 908.21  
 Gwater Depth: 15'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 05/28/1986  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported  
  
 Region: 9  
 Case Number: 9UT3199  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 05/17/1994  
 How Found: Not reported  
 Date Stopped: 05/17/1994  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Remedial action (cleanup) Underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 09/12/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 10/3/96  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01049-002  
 Basin Number: 908.21  
 Gwater Depth: 20'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - KNOWN HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 05/17/1994  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Cortese:

Region: CORTESE  
 Facility Addr2: 100 16TH ST

Region: CORTESE  
 Facility Addr2: 100 16TH ST

San Diego Co. HMMD:

Facility ID: 101049  
 Inactive Indicator: Active  
 Business Code: 6HK24  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: SAN DIEGO TRANSIT  
 Mailing Address: PO BOX 122511  
 Mailing City, St, Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD981448301  
 Gas Station: Not reported  
 Inspection Date: 08/12/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: FRANK TOTH  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO METROPOLITAN TRANSIT  
 Property Address: PUBLIC AGENCY  
 Property City, St, Zip: 00000  
 Tank Owner: SAN DIEGO TRANSIT CORP  
 Tank Address: 100 16TH ST  
 Tank City, St, Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/12/05  
 Facility Phone: 238-0100

HMMD DISCLOSURE INVENTORY:

Item Number: AC04  
 Chemical Name: ACTEYLENE 44-7  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AN96

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Chemical Name: ANTI-FREEZE CROWN CHEMICAL, ALSO STORED IN 55 GALLON DRUMS  
 Case Number: 107-21-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AR00  
 Chemical Name: ARGON/CO2 - MIG MIX  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: AU76  
 Chemical Name: AUTO TRANSMISSION FLUID UNDERGROUND TANK 101049 T023  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: CL06  
 Chemical Name: CLEANER: PETROLEUM DISTILLATE MIXTURE 'RIPPER', STORED IN TWO 500G POLY T  
 Case Number: 64742-88-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: CO97  
 Chemical Name: COMPRESSED NATURAL GAS  
 Case Number: 74-82-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: DI70  
 Chemical Name: DIESEL UNDERGROUND TANK 101049 T017 DIESEL  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: DI71  
 Chemical Name: DIESEL UNDERGROUND TANK 101049 T018 DIESEL  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: DI72  
 Chemical Name: DIESEL UNDERGROUND TANK 101049 T019 DIESEL  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: DO99  
 Chemical Name: DOUBLOON CLEANER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: FO07  
 Chemical Name: FORANE 22-CHLORODIFLUOROMETHANE  
 Case Number: 75-45-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: MO74  
 Chemical Name: MOTOR OIL UNDERGROUND TANK 101049 T021 MOTOR OIL  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: MO75  
 Chemical Name: MOTOR OIL UNDERGROUND TANK 101049 T022  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: NI09  
 Chemical Name: NITROGEN  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: OI05  
 Chemical Name: OIL: HOIST  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OI93  
 Chemical Name: OIL: LUBE, 30W; ALSO STORED IN55 GALLON DRUMS  
 Case Number: 8002-05-9

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OI02  
 Chemical Name: OIL: TELLUS HYDRAULIC OIL, TORQUE FLUID  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OI94  
 Chemical Name: OIL: TRANSMISSION; ALSO STORED IN 55 GALLON DRUMS  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OX08  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: R-01  
 Chemical Name: R-134A, 1,1,1,2 - TETRAFLUORO ETHANE  
 Case Number: 811-97-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Item Number: RE73  
 Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 101049 T020 REGULAR UNLEADED  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: SO95  
 Chemical Name: SODIUM HYPOCHLORITE  
 Case Number: 7681-52-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: SO77  
 Chemical Name: SOLVENT - SPECIFY TYPE UNDERGROUND TANK 101049 T024 COOLANT  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: TH03  
 Chemical Name: THERMATEX EP2-BEARING GREASE ALSO MARFAC EP2  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: VI98  
 Chemical Name: VIVID GLASS CLEANER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: A  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: B  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: C  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: D  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T005  
 Tank ID Number: E  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T006  
 Tank ID Number: F  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T007  
 Tank ID Number: G  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T008  
 Tank ID Number: H  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T009  
 Tank ID Number: I  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T010  
 Tank ID Number: J  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T011  
 Tank ID Number: K  
 Waste or Product: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Tank Contents: REGULAR UNLEADED

Tank Number: T012  
 Tank ID Number: L  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T013  
 Tank ID Number: M  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T014  
 Tank ID Number: N SOLVENT  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T015  
 Tank ID Number: O  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T016  
 Tank ID Number: P SUMP FOR  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T017  
 Tank ID Number: 001 DIESEL  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T018  
 Tank ID Number: 002 DIESEL  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T019  
 Tank ID Number: 003 DIESEL  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T020  
 Tank ID Number: 004 REGULA  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T021  
 Tank ID Number: 005 MOTOR  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T022  
 Tank ID Number: 007  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Tank Number: T023  
 Tank ID Number: 006  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T024  
 Tank ID Number: 008 COOLAN  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T025  
 Tank ID Number: AT 3850 DI  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 05/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7083  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 7084  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 05/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 7085  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 05/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 7086  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 05/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3031  
 Occurrences: Not reported  
 Item Number: 7087  
 Violation Desc: FAILURE TO REPORT/RESPOND TO RELEASE

Inspection Date: 05/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 7088  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Inspection Date: 08/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6127  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 6128  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 08/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6129  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 6130  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 08/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3031  
 Occurrences: Not reported  
 Item Number: 6131  
 Violation Desc: FAILURE TO REPORT/RESPOND TO RELEASE

Inspection Date: 06/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6856  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 06/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 6857  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 06/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6858  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 06/20/01

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Waste Code: Not reported  
 Type of Violation: 6HX3011  
 Occurrences: Not reported  
 Item Number: 6859  
 Violation Desc: FAIL TO COMPLY WITH OP PERMIT CONDITIO

Inspection Date: 06/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1789  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 06/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3109  
 Occurrences: Not reported  
 Item Number: 1790  
 Violation Desc: MONITORING PLOT PLAN NOT SUBMITTED

Inspection Date: 06/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3157  
 Occurrences: Not reported  
 Item Number: 1791  
 Violation Desc: FALSIFICATION OF RECORDS/TAMPER W/EQUIP

Inspection Date: 06/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3255  
 Occurrences: Not reported  
 Item Number: 1792  
 Violation Desc: SPILL CONT NOT DRY & IN GOOD CONDITI

Inspection Date: 06/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3255  
 Occurrences: Not reported  
 Item Number: 1793  
 Violation Desc: SPILL CONT NOT DRY & IN GOOD CONDITI

Inspection Date: 06/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 1794  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 06/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 1795  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 06/27/03  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Type of Violation:	6HV3401
Occurrences:	Not reported
Item Number:	1796
Violation Desc:	NO CONTIN. AUDIO&VISUAL ALARM W/+SHUT
Inspection Date:	06/27/03
Waste Code:	Not reported
Type of Violation:	6HV3401
Occurrences:	Not reported
Item Number:	1797
Violation Desc:	NO CONTIN. AUDIO&VISUAL ALARM W/+SHUT
Inspection Date:	06/27/03
Waste Code:	Not reported
Type of Violation:	6HV3402
Occurrences:	Not reported
Item Number:	1798
Violation Desc:	PUMP DOESN'T SHUT OFF IF MONITOR DISCONN
Inspection Date:	06/27/03
Waste Code:	Not reported
Type of Violation:	6HV3402
Occurrences:	Not reported
Item Number:	1799
Violation Desc:	PUMP DOESN'T SHUT OFF IF MONITOR DISCONN
Inspection Date:	08/12/04
Waste Code:	Not reported
Type of Violation:	6HV3255
Occurrences:	Not reported
Item Number:	3986
Violation Desc:	SPILL CONT NOT DRY & IN GOOD CONDITI
Inspection Date:	08/12/04
Waste Code:	Not reported
Type of Violation:	6HV3262
Occurrences:	Not reported
Item Number:	3987
Violation Desc:	SEC CONT PIPING DRAINAGE OBSTRUCTED
Inspection Date:	08/12/04
Waste Code:	Not reported
Type of Violation:	6HV3266
Occurrences:	Not reported
Item Number:	3988
Violation Desc:	DISP. CONT. NOT INSTALLED
Inspection Date:	08/12/04
Waste Code:	Not reported
Type of Violation:	6HV0304
Occurrences:	Not reported
Item Number:	3989
Violation Desc:	WASTE DETERMINATION NOT MADE
Inspection Date:	08/12/04
Waste Code:	Not reported
Type of Violation:	6HV1605

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Occurrences: Not reported  
 Item Number: 3990  
 Violation Desc: NO DAILY TANK INSPECTION/LOG

Inspection Date: 08/12/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3991  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 08/12/04  
 Waste Item #: 133  
 Waste Code: 133  
 Waste Name: AQUEOUS SOL'N W/ 10%  
 Qnty at Inspection: 4800  
 Quantity String: 4800  
 Annual Qty: 10000  
 Annual Qty String: 10000  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0063 UNITED PUMPING SERVI  
 Waste Desc: CLARIFIER SLUDGE  
 Carcinogen: No

Inspection Date: 08/12/04  
 Waste Item #: 134  
 Waste Code: 134  
 Waste Name: AQUEOUS SOL'N W/LESS  
 Qnty at Inspection: 24  
 Quantity String: 24  
 Annual Qty: 124  
 Annual Qty String: 124  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: AQUEOUS PARTS WASHER  
 Carcinogen: No

Inspection Date: 08/12/04  
 Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qnty at Inspection: 130  
 Quantity String: 130  
 Annual Qty: 360  
 Annual Qty String: 360  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE ANTIFREEZE  
 Carcinogen: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Inspection Date: 08/12/04  
 Waste Item #: 212  
 Waste Code: 212  
 Waste Name: OXYGENATED SOLVENTS  
 Qnty at Inspection: 6  
 Quantity String: 6  
 Annual Qty: 48  
 Annual Qty String: 48  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: MONOETHANOLAMINE PTS WSHR  
 Carcinogen: No

Inspection Date: 08/12/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 225  
 Quantity String: 225  
 Annual Qty: 1800  
 Annual Qty String: 1800  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: 16 UNITS  
 Carcinogen: No

Inspection Date: 08/12/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 1000  
 Quantity String: 1000  
 Annual Qty: 12025  
 Annual Qty String: 12025  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 08/12/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 4000  
 Quantity String: 4000  
 Annual Qty: 5700  
 Annual Qty String: 5700  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2804 ENVIROSERV

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Waste Desc: SPENT ABSORBANT  
 Carcinogen: No  
  
 Inspection Date: 08/12/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: FUEL FILTERS  
 Carcinogen: No

Inspection Date: 08/12/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 5000  
 Quantity String: 5000  
 Annual Qty: 36000  
 Annual Qty String: 36000  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: WASTE PILE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: SERVICED BI-WEEKLY  
 Carcinogen: No

Inspection Date: 08/12/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 1500  
 Quantity String: 1500  
 Annual Qty: 6900  
 Annual Qty String: 6900  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

CA WDS:

Facility ID: San Diego 371000449  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.

NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board

Subregion: 9

Facility Telephone: Not reported

Facility Contact: Not reported

Agency Name: METRO TRANSIT BOARD

Agency Address: 100 16TH ST

Agency City,St,Zip: SAN DIEGO 92101

Agency Contact: Not reported

Agency Telephone: Not reported

Agency Type: Private

SIC Code: 0

SIC Code 2: Not reported

Primary Waste: Not reported

Primary Waste Type: Not reported

Secondary Waste: Not reported

Secondary Waste Type: Not reported

Design Flow: 0

Baseline Flow: 0

Reclamation: Not reported

POTW: Not reported

Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

**SWEEPS UST:**

Status: A

Comp Number: 1049

Number: 9

Board Of Equalization: 44-021594

Ref Date: Not reported

Act Date: 06-26-92

Created Date: 02-29-88

Tank Status: A

Owner Tank Id: Not reported

Swrcb Tank Id: 37-000-001049-000001

Actv Date: Not reported

Capacity: 10000

Tank Use: M.V. FUEL

Stg: P

Content: OTHER

Number Of Tanks: 16

Status: A

Comp Number: 1049

Number: 9

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000003  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000004  
 Actv Date: Not reported  
 Capacity: 20000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Swrcb Tank Id: 37-000-001049-000005  
 Actv Date: Not reported  
 Capacity: 20000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000006  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000007  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: PETROLEUM  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000008  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Number Of Tanks:	Not reported
Status:	A
Comp Number:	1049
Number:	9
Board Of Equalization:	44-021594
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-001049-000009
Actv Date:	Not reported
Capacity:	7500
Tank Use:	OIL
Stg:	P
Content:	Not reported
Number Of Tanks:	Not reported
Status:	A
Comp Number:	1049
Number:	9
Board Of Equalization:	44-021594
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-001049-000010
Actv Date:	Not reported
Capacity:	550
Tank Use:	PETROLEUM
Stg:	W
Content:	Not reported
Number Of Tanks:	Not reported
Status:	A
Comp Number:	1049
Number:	9
Board Of Equalization:	44-021594
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-001049-000011
Actv Date:	Not reported
Capacity:	7500
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported
Status:	A
Comp Number:	1049
Number:	9
Board Of Equalization:	44-021594

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000012  
 Actv Date: Not reported  
 Capacity: 7500  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000013  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000014  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: CHEMICAL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000015

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORP (Continued)**

**1000110674**

Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 1049  
 Number: 9  
 Board Of Equalization: 44-021594  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001049-000016  
 Actv Date: Not reported  
 Capacity: 1200  
 Tank Use: CHEMICAL  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H01049-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 1/29/2002  
 Begandt: 5/28/1986

Case Number: H01049-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 1/29/2002  
 Begandt: 5/17/1994

24

**CALIFORNIA LINEN SUPPLY**  
**101 16TH ST**  
**SAN DIEGO, CA 92101**

**HIST UST U001572544**  
**SWEEPS UST N/A**

**HIST UST:**

Region: STATE  
 Facility ID: 00000066639  
 Facility Type: Other  
 Other Type: LAUNDRY  
 Total Tanks: 0002  
 Contact Name: DANNIE TORRES  
 Telephone: 6192327801  
 Owner Name: SERVICE CONTROL CORP.  
 Owner Address: 104 N. 14TH STREET  
 Owner City,St,Zip: PHOENIX, AZ 85034



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA LINEN SUPPLY (Continued)**

**U001572544**

Tank Num: 001  
 Container Num: #1  
 Year Installed: 1973  
 Tank Capacity: 00010000  
 Tank Used for: WASTE  
 Type of Fuel: 4  
 Tank Construction: Unkown inches  
 Leak Detection: None

Tank Num: 002  
 Container Num: #2  
 Year Installed: Not reported  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: None

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 2253  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000001  
 Actv Date: Not reported  
 Capacity: 3000  
 Tank Use: UNKNOWN  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 7

Status: Not reported  
 Comp Number: 2253  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000002  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: UNKNOWN  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2253  
 Number: Not reported  
 Board Of Equalization: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA LINEN SUPPLY (Continued)**

**U001572544**

Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000003  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: UNKNOWN  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2253  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000004  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2253  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000006  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2253  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000007

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA LINEN SUPPLY (Continued)**

**U001572544**

Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2253  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000008  
 Actv Date: Not reported  
 Capacity: 1250  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2253  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002253-000005  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 1

24

**CAL LINEN SUPPLY  
 101 16TH ST  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000818151  
 FINDS CAD041324385  
 HAZNET**

RCRA-SQG:  
 Date form received by agency: 09/01/1996  
 Facility name: CAL LINEN SUPPLY  
 Facility address: 101 16TH ST  
 SAN DIEGO, CA 92101  
 EPA ID: CAD041324385  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CAL LINEN SUPPLY (Continued)**

**1000818151**

Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: SERVICE CONTROL CORP  
 Owner/operator address: 4134 24TH ST STE A200  
 PHOENIX, AZ 85016  
 Owner/operator country: Not reported  
 Owner/operator telephone: (602) 957-4411  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:  
 U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:  
 Date form received by agency: 07/22/1992  
 Facility name: CAL LINEN SUPPLY  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**  
 Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:  
 Gepaid: CAD041324385

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CAL LINEN SUPPLY (Continued)**

**1000818151**

Contact: SERVICE CONTROL CORP  
 Telephone: 6029574411  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Recycler  
 Tons: 1.1259  
 Facility County: San Diego

Gepaid: CAD041324385  
 Contact: DEACT NON-DELIV. PER 95 FEES -  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 0.52  
 Facility County: San Diego

Gepaid: CAD041324385  
 Contact: SERVICE CONTROL CORP  
 Telephone: 6029574411  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Recycler  
 Tons: 2.3852  
 Facility County: San Diego

Gepaid: CAD041324385  
 Contact: SERVICE CONTROL CORP  
 Telephone: 6029574411  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Recycler  
 Tons: 2.085

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAL LINEN SUPPLY (Continued)**

**1000818151**

Facility County: San Diego  
 Gepaid: CAD041324385  
 Contact: DEACT NON-DELIV. PER 95 FEES -  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Not reported  
 Tons: 2.91  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

24

**BREITBARD PROPERTIES LLC**  
**101 16TH ST**  
**SAN DIEGO, CA 92101**

**LUST**  
**UST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**U003789070**  
**N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607302969  
 Stop Date: 1986-06-18 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1988-06-15 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1986-06-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-06-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BREITBARD PROPERTIES LLC (Continued)**

**U003789070**

Status: Remediation Plan  
 Chemical: Stoddard Solvent  
 Contact Person: Not reported  
 Responsible Party: Joan Breitbard Berg  
 RP Address: 964 Fifth Ave, Ste 314  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02253-001  
 Case Number: 9UT70  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**UST:**

Local Agency: 37000  
 Facility ID: H02253

**San Diego Co. HMMD:**

Facility ID: 102253  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: BREITBARD PROPERTIES LLC  
 Mailing Address: 964 5TH AV 314  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD041324385  
 Gas Station: Not reported  
 Inspection Date: 05/07/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BREITBARD PROPERTIES LLC (Continued)**

**U003789070**

Facility Contact: JOAN BERG  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BREITBARD PROPERTIES L L C  
 Property Address: 964 5TH AVE #314  
 Property City,St,Zip: 92101  
 Tank Owner: BREITBARD PROPERTIES LLC  
 Tank Address: 964 5TH AV 314  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/07/05  
 Facility Phone: 619-544-1458

**HMMD DISCLOSURE INVENTORY:**

Item Number: OT25  
 Chemical Name: OTHER - SPECIFY UNDERGROUND TANK 102253 T009 STODDARD SOLVENT/WATER  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT0247-1  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: AT0247-2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: AT0247-3  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: AT0560-1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T005  
 Tank ID Number: 5  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T006  
 Tank ID Number: AT 2320



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BREITBARD PROPERTIES LLC (Continued)**

**U003789070**

Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T007  
 Tank ID Number: AT2320  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T008  
 Tank ID Number: AT2320  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T009  
 Tank ID Number: RT1647 STO  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/20/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 8741  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 05/01/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5070  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 05/01/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3011  
 Occurrences: Not reported  
 Item Number: 5071  
 Violation Desc: FAIL TO COMPLY WITH OP PERMIT CONDITIO

Inspection Date: 05/01/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3013  
 Occurrences: Not reported  
 Item Number: 5072  
 Violation Desc: NO FINANCIAL RESPOSIBILITY DOC

Inspection Date: 05/01/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3029  
 Occurrences: Not reported  
 Item Number: 5073  
 Violation Desc: SPILL/OVERFILL PREVENTION NOT INSTALLED

Inspection Date: 04/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BREITBARD PROPERTIES LLC (Continued)**

**U003789070**

Occurrences:	Not reported
Item Number:	0392
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	0393
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	0394
Violation Desc:	HMBP NOT ESTABLISHED/IMPLEMENTED.
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	0395
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV1601
Occurrences:	Not reported
Item Number:	0396
Violation Desc:	HAZWASTE TANKS W/O P.E. ASSESSMENT
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV3105
Occurrences:	Not reported
Item Number:	0397
Violation Desc:	FINANCIAL RESPONSIBILITY EXPIRED
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV3107
Occurrences:	Not reported
Item Number:	0398
Violation Desc:	UST MONITORING PLAN NOT COMPLETE
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV3108
Occurrences:	Not reported
Item Number:	0399
Violation Desc:	UST EM RESPONSE PLAN NOT COMPLETE
Inspection Date:	04/07/04
Waste Code:	Not reported
Type of Violation:	6HV3111
Occurrences:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BREITBARD PROPERTIES LLC (Continued)**

**U003789070**

Item Number: 0400  
 Violation Desc: CONTIN MONITOR SYSTEM NOT CERT. YRLY

Inspection Date: 04/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3113  
 Occurrences: Not reported  
 Item Number: 0401  
 Violation Desc: 2NDRY CONT TEST NOT SENT TO CUPA

Inspection Date: 04/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3263  
 Occurrences: Not reported  
 Item Number: 0402  
 Violation Desc: MONITORING SYSTEM NOT FUNCTIONAL

Inspection Date: 04/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3403  
 Occurrences: Not reported  
 Item Number: 0403  
 Violation Desc: NO CONT AUDIO & VISUAL ALARM W/+SHUTOFF

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H02253-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 6/15/1988  
 Begandt: 6/18/1986

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**24 CALIF. INDUSTR. & LINEN SUPPLY  
 101 16TH ST  
 SAN DIEGO, CA 92101**

**LUST S101302199  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT70  
 Local Agency: San Diego  
 Substance: Stoddard Solvent  
 Qty Leaked: Not reported  
 Date Found: 06/18/1986  
 How Found: Tank Closure  
 Date Stopped: 06/18/1986  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Remedial action (cleanup) Underway  
 Abate Method: Not reported  
 Confirm Date: 06/18/1986  
 Submit Workplan: Not reported  
 Prelim Assess: 09/18/1986  
 Desc Pollution: Not reported  
 Remed Plan: 06/15/1988  
 Remed Action: 8/27/87  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 6/18/86  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H02253-001  
 Basin Number: 908.21  
 Gwater Depth: 13  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 06/18/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

**24 ARCWEL CORP  
 229 16TH ST  
 SAN DIEGO, CA 92101**

**HIST UST U001572533  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000018503  
 Facility Type: Other  
 Other Type: SHIP REPAIR  
 Total Tanks: 0001  
 Contact Name: DAND CHAPIN  
 Telephone: 6192335291

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWEL CORP (Continued)**

**U001572533**

Owner Name: ROBERT JADLOW  
 Owner Address: P.O. BOX 2245  
 Owner City,St,Zip: SAN DIEGO, CA 92112

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

24

**SAN DIEGO EXPRESS  
 229 16TH ST  
 SAN DIEGO, CA 92101**

**San Diego Co. HMMD  
 SWEEPS UST**

**S104749646  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 121013  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 229 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: JONES RICHARD&LAVONDA LEE REVO  
 Property Address: 1532 SHADOW KNOLLS D  
 Property City,St,Zip: 92020  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-5291

**HMMD DISCLOSURE INVENTORY:**  
 Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS (Continued)**

**S104749646**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21013  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021013-000001  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**SAN DIEGO EXPRESS (Continued)**

**S104749646**

Number Of Tanks: 1

**24 FRED'S AUTO BODY & PAINT**  
**301 16TH ST**  
**SAN DIEGO, CA 92101**

**HAZNET S102430453**  
**LUST N/A**  
**Cortese**  
**San Diego Co. HMMD**

HAZNET:

Gepaid: CAL000147728  
 Contact: ISMAEL GUILLEN/OWNER  
 Telephone: 6192371043  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 301 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: \*\*\*  
 Tons: Not reported  
 Facility County: Not reported

Gepaid: CAL000147728  
 Contact: ISMAEL GUILLEN/OWNER  
 Telephone: 6192371043  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 301 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Photochemicals/photoprocessing waste  
 Disposal Method: \*\*\*  
 Tons: 0.02  
 Facility County: Not reported

LUST:

Region: 9  
 Case Number: 9UT744  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 06/10/1987  
 How Found: Tank Closure  
 Date Stopped: 06/10/1987  
 How Stopped: Other Means  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 06/10/1987  
 Submit Workplan: Not reported  
 Prelim Assess: / /

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRED'S AUTO BODY & PAINT (Continued)**

**S102430453**

Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/11/89  
 Pilot Program: LOP  
 Local Case: H03741-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 06/10/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 301 16TH ST

San Diego Co. HMMD:

Facility ID: 203444  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 301 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 04/30/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: TOAN PHAM  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PHAM TOAN  
 Property Address: 4204 42ND ST  
 Property City,St,Zip: 92105  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FRED'S AUTO BODY & PAINT (Continued)**

**S102430453**

Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/30/06  
 Facility Phone: 619-708-3815

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 04/30/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 04/30/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: LBS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRED'S AUTO BODY & PAINT (Continued)**

**S102430453**

Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

24

**ROY'S AUTO REPAIR  
 301 16TH ST  
 SAN DIEGO, CA 92101**

**HAZNET  
 LUST**

**S104574413  
 N/A**

**San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

HAZNET:

Gepaid: CAD981664543  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 301 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 920110000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Recycler  
 Tons: 0.4586  
 Facility County: San Diego

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303006  
 Stop Date: 1987-06-10 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-01-11 00:00:00  
 Discover Date: 1987-06-10 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-06-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ROY'S AUTO REPAIR (Continued)**

**S104574413**

Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03741-001  
 Case Number: 9UT744  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 103741  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 301 16TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAC002295641  
 Gas Station: Not reported  
 Inspection Date: 04/08/03  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: ROY FONTENETT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ROY'S AUTO REPAIR (Continued)**

**S104574413**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PHAM TOAN  
 Property Address: 4204 42ND ST  
 Property City,St,Zip: 92105  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-6907

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/07/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6304  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/07/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6305  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 08/07/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 6306  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 09/22/00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ROY'S AUTO REPAIR (Continued)**

**S104574413**

Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 8447  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 09/22/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8448  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/22/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8449  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 1846  
 Violation Desc: NO TSDF SIGNED MANIFEST ONSITE

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1847  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H03741-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ROY'S AUTO REPAIR (Continued)**

**S104574413**

FStatus: Closed Case  
 Date: 1/11/1989  
 Begandt: 6/10/1987

25

**US SPRINT  
 1402 E K ST  
 SAN DIEGO, CA 92101**

**SWEEPS UST S106933852  
 N/A**

SWEEPS UST:

Status: A  
 Comp Number: 21041  
 Number: 9  
 Board Of Equalization: 44-023408  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021041-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 2

Status: A  
 Comp Number: 21041  
 Number: 9  
 Board Of Equalization: 44-023408  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021041-000002  
 Actv Date: Not reported  
 Capacity: 750  
 Tank Use: CHEMICAL  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

26

**CROWN BAY  
 4TH / K  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106893842  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CROWN BAY (Continued)**

**S106893842**

Division Branch: So Cal - Cypress  
 Facility ID: 37150007  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-02-01 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37150007  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 02/01/00

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

27

**COTINENTAL BAKING COMP  
 171 14TH ST  
 SAN DIEGO, CA 92101**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S102428404  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COTINENTAL BAKING COMP (Continued)**

**S102428404**

Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301392  
 Stop Date: 1994-01-04 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1999-06-17 00:00:00  
 Discover Date: 1994-01-04 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-01-04 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: PROPERTY TAX DEPT  
 RP Address: 2801 S TOWNE AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H32320-001  
 Case Number: 9UT2644  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COTINENTAL BAKING COMP (Continued)**

**S102428404**

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608173506  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-07-21 00:00:00  
 Discover Date: 1998-12-16 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-12-16 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: CS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: COMPLAINT  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H32320-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COTINENTAL BAKING COMP (Continued)**

**S102428404**

Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608191289  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1999-09-21 00:00:00  
 Discover Date: 1998-10-23 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-10-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: ATTN: STEPHEN SCHWARTZ  
 RP Address: 3049 RESEARCH DR  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: CS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1, REC-2, WARM, WILD  
 Priority: 7

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COTINENTAL BAKING COMP (Continued)**

**S102428404**

Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H32320-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT2644  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 01/04/1994  
 How Found: Tank Closure  
 Date Stopped: 01/04/1994  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: No Action Taken - no action has as yet been taken at the site  
 Confirm Date: 01/04/1994  
 Submit Workplan: Not reported  
 Prelim Assess: 01/04/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H32320-001  
 Basin Number: 908.21  
 Gwater Depth: >10'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/LOW - MINOR OR NO POTENTIAL WATER RESOURCE IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 01/06/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COTINENTAL BAKING COMP (Continued)**

**S102428404**

San Diego Co. HMMD:

Facility ID:	132320
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2801 S TOWNE AV
Mailing City,St,Zip:	POMONA, CA 91766
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	51
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	Not reported
Reinspection Date:	Not reported
Inspector Name:	Not reported
Violation Notice Issued:	Not reported
Facility Contact:	ED SHERLOCK
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	SINCLAIR ROBERT C&JACQUELINE T
Property Address:	258 KOLMAR ST
Property City,St,Zip:	92037
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-591-0451

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	T001
Tank ID Number:	AT3096
Waste or Product:	Not reported
Tank Contents:	DIESEL

HMMD VIOLATIONS:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**COTINENTAL BAKING COMP (Continued)**

**S102428404**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H32320-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 6/17/1999  
 Begandt: 1/4/1994

Case Number: H32320-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/21/1999  
 Begandt: 10/23/1998

Case Number: H32320-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Closed Case  
 Date: 7/21/2000  
 Begandt: 12/16/1998

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>27</b>	<b>ENGINEERING DEPT. 171 14TH ST SAN DIEGO, CA 92101</b>	<b>HIST UST</b>	<b>U001572559 N/A</b>
-----------	--	-----------------	---------------------------

HIST UST:

Region:	STATE
Facility ID:	00000044871
Facility Type:	Other
Other Type:	BAKERY
Total Tanks:	0001
Contact Name:	VIC CARLSON
Telephone:	6192337174
Owner Name:	ITT CONTINENTAL BAKING CO.
Owner Address:	171 14TH STREET
Owner City,St,Zip:	SAN DIEGO, CA 92101

Tank Num:	001
Container Num:	SDE 1
Year Installed:	Not reported
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

<b>27</b>	<b>GARAGE/ITT CBC 171 14TH ST SAN DIEGO, CA 92101</b>	<b>HIST UST</b>	<b>U001572564 N/A</b>
-----------	---	-----------------	---------------------------

HIST UST:

Region:	STATE
Facility ID:	00000061536
Facility Type:	Other
Other Type:	BAKERY
Total Tanks:	0002
Contact Name:	MITCH YOW
Telephone:	6192337174
Owner Name:	ITT CONTINENTAL BAKING COMPANY
Owner Address:	171 14TH ST.
Owner City,St,Zip:	SAN DIEGO, CA 92101

Tank Num:	001
Container Num:	SDG1
Year Installed:	1975
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

Tank Num:	002
Container Num:	SDS1
Year Installed:	Not reported
Tank Capacity:	00010000
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**27 KING TRANSPORTATION  
 1300 L ST  
 SAN DIEGO, CA 92101**

**San Diego Co. HMMD S104746203  
 SWEEPS UST N/A**

San Diego Co. HMMD:

Facility ID:	105584
Inactive Indicator:	Active
Business Code:	6HK28
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1300 L ST
Mailing City,St,Zip:	SAN DIEGO, CA 92101
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	51
EPA ID:	CAL000041844
Gas Station:	Not reported
Inspection Date:	10/09/95
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	STEVEN KING
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	CITY OF SAN DIEGO REDEVELOPMEN
Property Address:	PUBLIC AGENCY
Property City,St,Zip:	00000
Tank Owner:	JACK B KING
Tank Address:	1300 L ST
Tank City,St,Zip:	San Diego, CA 92101
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-239-6133

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	T001
Tank ID Number:	2
Waste or Product:	Not reported
Tank Contents:	DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KING TRANSPORTATION (Continued)**

**S104746203**

Tank Number: T002  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 5584  
 Number: Not reported  
 Board Of Equalization: 44-022242  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005584-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 5584  
 Number: Not reported  
 Board Of Equalization: 44-022242  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KING TRANSPORTATION (Continued)**

**S104746203**

Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005584-000002  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 5584  
 Number: 9  
 Board Of Equalization: 44-022242  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

27

**SAN DIEGO**  
**1300 L ST**  
**SAN DIEGO, CA 92101**

**HIST UST U001572599**  
**N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000057584  
 Facility Type: Other  
 Other Type: TRUCKING CO  
 Total Tanks: 0002  
 Contact Name: JACK B. KING  
 Telephone: 6192396133  
 Owner Name: JACK B KING  
 Owner Address: 1300 L. ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
 Container Num: 2  
 Year Installed: 1974  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 1  
 Year Installed: 1974  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO (Continued)**

**U001572599**

Leak Detection: Stock Inventor

28

**TRIANGLE PROPERTY  
 65 13TH ST  
 SAN DIEGO, CA 92113**

**LUST S106875120  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019703949  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2004-08-10 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Mr. Jarvie Worcester  
 RP Address: 600 B Street, Ste. 1500  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIANGLE PROPERTY (Continued)**

**S106875120**

Work Suspended: Not reported  
 Local Case #: H39657-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H39657-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 8/10/2004  
 Begandt: Not reported

28

**SAN DIEGO GAS & ELECTRIC  
 NONE 14TH ST / IMPERIAL  
 SAN DIEGO, CA 92101**

**LUST S106916416  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608102760  
 Stop Date: 1991-06-25 00:00:00  
 Confirm Leak: 1990-08-06 00:00:00  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1990-08-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-06-26 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GAS & ELECTRIC (Continued)**

**S106916416**

Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Leak being confirmed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H38963-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

28

**SAN DIEGO GAS & ELECTRIC  
 14TH ST / IMPERIAL  
 SAN DIEGO, CA 92101**

**SAN DIEGO CO. SAM**

**S108407217  
 N/A**

SAN DIEGO CO. SAM:

Case Number: H38963-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Leak Being Confirmed  
 Date: 6/25/1991  
 Begandt: 8/6/1990

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**28 INTERSTATE BRANDS CORP.  
 1401 IMPERIAL AVE  
 SAN DIEGO, CA 92101**

**LUST S100726527  
 Cortese N/A  
 SWEEPS UST**

**LUST:**

Region: 9  
 Case Number: 9UT3366  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 01/17/1997  
 How Found: Tank Closure  
 Date Stopped: 01/17/1997  
 How Stopped: Close Tank  
 Source: Piping  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 01/17/1997  
 Submit Workplan: Not reported  
 Prelim Assess: 01/28/1997  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 1/30/97  
 Closed Date: 12/23/97  
 Pilot Program: LOP  
 Local Case: H04087-002  
 Basin Number: 908.22  
 Gwater Depth: 10'  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 01/30/1997  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 1401 IMPERIAL AVE

**SWEEPS UST:**

Status: A  
 Comp Number: 4087  
 Number: 9  
 Board Of Equalization: 44-008489  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORP. (Continued)**

**S100726527**

Swrcb Tank Id: 37-000-004087-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 1

28

**INTERSTATE BRANDS CORP.  
 1401 IMPERIAL AV  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104745859  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302128  
 Stop Date: 1997-01-17 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-12-23 00:00:00  
 Discover Date: 1997-01-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1997-01-17 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID GRAVE  
 RP Address: P O BOX 419627  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: NS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORP. (Continued)**

**S104745859**

Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04087-002  
 Case Number: 9UT3366  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608152798  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-12-27 00:00:00  
 Discover Date: 1988-12-14 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-12-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORP. (Continued)**

**S104745859**

Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MV  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04087-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 104087  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 7706 TRADE ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92121  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000145794  
 Gas Station: Not reported  
 Inspection Date: 06/03/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: WILLIAM BARTEAU  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CITY OF SAND DIEGO REDEVELOPME  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: INTERSTATE BRANDS COPR.  
 Tank Address: 2801 S TOWNE AV



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORP. (Continued)**

**S104745859**

Tank City,St,Zip: Pomona, CA 91766  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 12/03/05  
 Facility Phone: 619-233-6817

**HMMD DISCLOSURE INVENTORY:**

Item Number: OI36  
 Chemical Name: OILS: MOTOR, HYDRAULIC, TRANSMISSION, LUBE, GREASE  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 001 UNLEAD  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 01/13/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 1780  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 05/01/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5078  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/09/02  
 Waste Code: Not reported  
 Type of Violation: 6HR0001  
 Occurrences: Not reported  
 Item Number: 0610  
 Violation Desc: INSPECTION RECEIVED BUT NOT PROCESSED

**HMMD WASTE STREAMS:**

Inspection Date: 06/03/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: LBS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORP. (Continued)**

**S104745859**

Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: SELF HAUL TO POMONA SITE  
 Carcinogen: No

Inspection Date: 06/03/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 16  
 Quantity String: 16  
 Annual Qty: 96  
 Annual Qty String: 96  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PARTS CLEANER - 8 WK  
 Carcinogen: No

Inspection Date: 06/03/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 530  
 Annual Qty String: 530  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 06/03/04  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE ANTIFREEZE  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H04087-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORP. (Continued)**

**S104745859**

FStatus: Closed Case  
 Date: 12/27/1989  
 Begandt: 12/14/1988  
  
 Case Number: H04087-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/23/1997  
 Begandt: 1/17/1997

28

**SDG & E PROPERTY  
 0 IMPERIAL AV  
 SAN DIEGO, CA 92101**

**LUST S107619913  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019791303  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2005-11-10 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Sean Scholey/ Roberta Correia  
 RP Address: 701 B Street, Suite 1400  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG & E PROPERTY (Continued)**

**S107619913**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H39679-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H39679-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 11/10/2005  
 Begandt: Not reported

28

**METROPOLITAN TRANSIT DEV BOARD  
 1255 IMPERIAL AV  
 SAN DIEGO, CA 92101**

**San Diego Co. HMMD S104751108  
 SAN DIEGO CO. SAM N/A**

**San Diego Co. HMMD:**

Facility ID: 126572  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 11TH & IMPERIAL AV  
 Mailing City, St, Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**METROPOLITAN TRANSIT DEV BOARD (Continued)**

**S104751108**

Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	SAN DIEGO REGIONAL BUILDING AU
Property Address:	PUBLIC AGENCY
Property City,St,Zip:	00000
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**METROPOLITAN TRANSIT DEV BOARD (Continued)**

**S104751108**

Carcinogen: No

Facility ID: 133352  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1255 IMPERIAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: LARRY MARSHALL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO REGIONAL BUILDING AU  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-338-2080

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**METROPOLITAN TRANSIT DEV BOARD (Continued)**

**S104751108**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 151398  
 Inactive Indicator: Active  
 Business Code: 6HK10  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1255 IMPERIAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 05/11/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: NANCY SCARDUZIO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO REGIONAL BUILDING AU  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**METROPOLITAN TRANSIT DEV BOARD (Continued)**

**S104751108**

Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-338-2170

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H26572-001  
 Agency: CA Regional Water Quality Control Board  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/14/1995  
 Begandt: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**28 CONTINENTAL BAKING CO  
 1304 IMPERIAL AVE  
 SAN DIEGO, CA 92101**

**HAZNET S102810252  
 SWEEPS UST N/A**

HAZNET:

Gepaid: CAL000018166  
 Contact: CONTINENTAL BAKING CO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1304 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Recycler  
 Tons: 1.2510  
 Facility County: San Diego

SWEEPS UST:

Status: Not reported  
 Comp Number: 28643  
 Number: Not reported  
 Board Of Equalization: 44-008489  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-028643-000002  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 1

Status: A  
 Comp Number: 28643  
 Number: 9  
 Board Of Equalization: 44-008489  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-028643-000001  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**28 WONDER BREAD THRIFT STORE  
 1304 IMPERIAL AVE  
 SAN DIEGO, CA 92101**

**HIST UST U001572619  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000061540  
 Facility Type: Other  
 Other Type: BAKERY  
 Total Tanks: 0001  
 Contact Name: MITCH YOW  
 Telephone: 6192337174  
 Owner Name: ITT CONTINENTAL BAKING COMPANY  
 Owner Address: 171 14TH ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
 Container Num: SDD1  
 Year Installed: 1982  
 Tank Capacity: 00012000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

**28 CONTINENTAL BAKING COMPANY  
 1301 IMPERIAL AVE  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000412852  
 FINDS CAD981435761**

RCRA-SQG:  
 Date form received by agency: 08/11/1986  
 Facility name: CONTINENTAL BAKING COMPANY  
 Facility address: 1301 IMPERIAL AVE  
 SAN DIEGO, CA 92101  
 EPA ID: CAD981435761  
 Mailing address: PO BOX 911  
 SAN DIEGO, CA 92101  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1301 IMPERIAL AVE  
 SAN DIEGO, CA 92101  
 Contact country: US  
 Contact telephone: (619) 233-7174  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: CONTINENTAL BAKING CO  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL BAKING COMPANY (Continued)**

**1000412852**

Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

28

**SQUIRES BELT MATERIAL CO**  
**149 12TH AV**  
**SAN DIEGO, CA 92101**

**LUST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**S104745505**  
**N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SQUIRES BELT MATERIAL CO (Continued)**

**S104745505**

Global Id: T0607302817  
 Stop Date: 1986-05-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-01-06 00:00:00  
 Discover Date: 1986-05-20 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-05-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: JOHN BENSON  
 RP Address: PO BOX 1097  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02585-001  
 Case Number: 9UT522  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:  
 Facility ID: 102585

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SQUIRES BELT MATERIAL CO (Continued)**

**S104745505**

Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P.O. BOX 121150  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000027964  
 Gas Station: Not reported  
 Inspection Date: 11/26/02  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: BRAD BENSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CITY OF SAN DIEGO REDEVELOPMEN  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: SQUIRES BELT MATERIAL  
 Tank Address: 149 12TH ST  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-8188

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL  
  
 Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SQUIRES BELT MATERIAL CO (Continued)**

**S104745505**

**HMMD VIOLATIONS:**

Inspection Date: 11/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 4636  
 Violation Desc: NO TSDF SIGNED MANIFEST ONSITE

Inspection Date: 08/16/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8692  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/16/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8693  
 Violation Desc: WASTE CONTAINER NOT CLOSED

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H02585-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 1/6/1989  
 Begandt: 5/20/1986

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**28 SQUIRES BELT MATERIAL  
 149 12TH AVE  
 SAN DIEGO, CA 92101**

**LUST S100725946  
 Cortese N/A  
 SWEEPS UST**

LUST:

Region: 9  
 Case Number: 9UT522  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 05/16/1986  
 How Found: Other Means  
 Date Stopped: 05/22/1986  
 How Stopped: Remove Contents  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Remove Free Product - remove floating product from water table  
 Confirm Date: 05/20/1986  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 8/31/87  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/6/89  
 Pilot Program: LOP  
 Local Case: H02585-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 2  
 File Dispn: File discarded, case closed  
 Release Date: 05/20/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 149 12TH AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 2585  
 Number: Not reported  
 Board Of Equalization: 44-021707  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002585-000001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SQUIRES BELT MATERIAL (Continued)**

**S100725946**

Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 2585  
 Number: Not reported  
 Board Of Equalization: 44-021707  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002585-000002  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2585  
 Number: 9  
 Board Of Equalization: 44-021707  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

29

**ARCWEL CORP  
 2031 COMMERCIAL ST  
 SAN DIEGO, CA 92101**

**HIST UST U001572534  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000018504  
 Facility Type: Other  
 Other Type: SHIP REPAIR  
 Total Tanks: 0001  
 Contact Name: DANA CHAPIN  
 Telephone: 6192335291  
 Owner Name: STEVEN A MILLER  
 Owner Address: 5348 FANUEL ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92109

Tank Num: 001



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCWEL CORP (Continued)**

**U001572534**

Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

29

**SAN DIEGO VAN & STORAGE CO  
 1944 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD  
 SWEEPS UST**

**S105034917  
 N/A**

San Diego Co. HMMD:

Facility ID: 115075  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1944 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 47  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/03/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ED DEBOLT/PRESIDENT  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DEBOLT DERRICK MCFARLAND PROPE  
 Property Address: 4300 BROOKS WAY  
 Property City,St,Zip: 92008  
 Tank Owner: SAN DIEGO VAN & STORAGE CO  
 Tank Address: 1944 COMMERCIAL ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 858-578-2000

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO VAN & STORAGE CO (Continued)**

**S105034917**

1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 15075  
 Number: Not reported  
 Board Of Equalization: 44-021887  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015075-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**29**      **SAN DIEGO VAN & STORAGE CO.**      **HIST UST**      **U001572993**  
**1944 COMMERCIAL ST**      **N/A**  
**SAN DIEGO, CA 92113**

HIST UST:  
 Region:                    STATE  
 Facility ID:                00000040751  
 Facility Type:             Other  
 Other Type:               MOVING & STORAGE  
 Total Tanks:              0001  
 Contact Name:            EDWIN C. DEBOLT  
 Telephone:                6195782000  
 Owner Name:              SAN DIEGO VAN & STORAGE CO  
 Owner Address:          1944 COMMERCIAL ST.  
 Owner City,St,Zip:      SAN DIEGO, CA 92113

Tank Num:                001  
 Container Num:          #1  
 Year Installed:          1960  
 Tank Capacity:          00002000  
 Tank Used for:          PRODUCT  
 Type of Fuel:            PREMIUM  
 Tank Construction:      Not reported  
 Leak Detection:         None

**29**      **ALL FRESH PRODUCTS, INC.**      **HIST UST**      **U001572621**  
**40 20TH ST**      **N/A**  
**SAN DIEGO, CA 92102**

HIST UST:  
 Region:                    STATE  
 Facility ID:                00000068702  
 Facility Type:             Other  
 Other Type:               WHOLESALE DISTRIBUTO  
 Total Tanks:              0001  
 Contact Name:            Not reported  
 Telephone:                6192321008  
 Owner Name:              ALL FRESH PRODUCTS, INC.  
 Owner Address:          40 20TH STREET  
 Owner City,St,Zip:      SAN DIEGO, CA 92102

Tank Num:                001  
 Container Num:          1  
 Year Installed:          Not reported  
 Tank Capacity:          00000550  
 Tank Used for:          WASTE  
 Type of Fuel:            2  
 Tank Construction:      Unkown centimeters  
 Leak Detection:         None

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**29 VITAGOLD COOPERATIVE ASSOC.  
 2121 IMPERIAL AVE  
 SAN DIEGO, CA 92102**

**LUST S100729615  
 SWEEPS UST N/A**

LUST:

Region: 9  
 Case Number: 9UT734  
 Local Agency: San Diego  
 Substance: 0  
 Qty Leaked: 0  
 Date Found: 05/22/1987  
 How Found: Not reported  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/22/87  
 Pilot Program: LOP  
 Local Case: H14028-001  
 Basin Number: 908.22  
 Gwater Depth: <10F  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 05/22/1987  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

SWEEPS UST:

Status: Not reported  
 Comp Number: 14028  
 Number: Not reported  
 Board Of Equalization: 44-022834  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014028-000001  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

VITAGOLD COOPERATIVE ASSOC. (Continued)

S100729615

Number Of Tanks:	5
Status:	Not reported
Comp Number:	14028
Number:	Not reported
Board Of Equalization:	44-022834
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-014028-000002
Actv Date:	Not reported
Capacity:	5000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	OTHER
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	14028
Number:	Not reported
Board Of Equalization:	44-022834
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-014028-000003
Actv Date:	Not reported
Capacity:	5000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	14028
Number:	Not reported
Board Of Equalization:	44-022834
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-014028-000004
Actv Date:	Not reported
Capacity:	1000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	14028
Number:	Not reported
Board Of Equalization:	44-022834

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

VITAGOLD COOPERATIVE ASSOC. (Continued)

S100729615

Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014028-000005  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

29

VITAGOLD BRANDS COOP AT0726  
 2121 IMPERIAL AV  
 SAN DIEGO, CA 92102

LUST  
 Cortese  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM

S104748057  
 N/A

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302996  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-12-22 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

VITAGOLD BRANDS COOP AT0726 (Continued)

S104748057

MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14028-001  
 Case Number: 9UT734  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:

Facility ID: 114028  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 135 S QUINCE ST  
 Mailing City,St,Zip: ESCONDIDO, CA 92025  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 47  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: IMPERIAL MARKET INVESTORS L L

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VITAGOLD BRANDS COOP AT0726 (Continued)**

**S104748057**

Property Address: C/O ALEX ZIRPOLO  
 Property City,St,Zip: 92101  
 Tank Owner: VITAGOLD BRANDS COOP ASSN  
 Tank Address: 2121 IMPERIAL AV  
 Tank City,St,Zip: San Diego, CA 92102  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: 002  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: 003  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: 004  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T005  
 Tank ID Number: 005  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

VITAGOLD BRANDS COOP AT0726 (Continued)

S104748057

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H14028-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/22/1987  
 Begandt: 5/22/1987

29

**NATIONAL BRAKE SERVICE INC**  
**2040 IMPERIAL AVE**  
**SAN DIEGO, CA 92102**

**RCRA-SQG 1000260502**  
**FINDS CAD981378359**  
**HAZNET**  
**San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: NATIONAL BRAKE SERVICE INC  
 Facility address: 2040 IMPERIAL AVE  
 SAN DIEGO, CA 92102  
 EPA ID: CAD981378359  
 Mailing address: P O BOX 335  
 LA MESA, CA 92041  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: STEPHEN HILL  
 Owner/operator address: NOT REQUIRED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL BRAKE SERVICE INC (Continued)**

**1000260502**

Owner/operator country: NOT REQUIRED, ME 99999  
 Owner/operator telephone: Not reported  
 Legal status: (415) 555-1212  
 Owner/Operator Type: Private  
 Owner/Op start date: Owner  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/31/1986  
 Facility name: NATIONAL BRAKE SERVICE INC  
 Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL BRAKE SERVICE INC (Continued)**

**1000260502**

HAZNET:

Gepaid: CAD981378359  
 Contact: NATIONAL BRAKE SERVICE INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 710662  
 Mailing City,St,Zip: SANTEE, CA 920720662  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Not reported  
 Tons: .3000  
 Facility County: San Diego

Gepaid: CAD981378359  
 Contact: NATIONAL BRAKE SERVICE INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 710662  
 Mailing City,St,Zip: SANTEE, CA 920720662  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .0150  
 Facility County: San Diego

Gepaid: CAD981378359  
 Contact: NATIONAL BRAKE SERVICE INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 710662  
 Mailing City,St,Zip: SANTEE, CA 920720662  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Transfer Station  
 Tons: .2000  
 Facility County: San Diego

Gepaid: CAD981378359  
 Contact: NATIONAL BRAKE SERVICE INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 710662  
 Mailing City,St,Zip: SANTEE, CA 920720662  
 Gen County: San Diego  
 TSD EPA ID: UTD991301748  
 TSD County: 99  
 Waste Category: Asbestos-containing waste

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL BRAKE SERVICE INC (Continued)**

**1000260502**

Disposal Method: Disposal, Land Fill  
 Tons: .6236  
 Facility County: San Diego  
  
 Gepaid: CAD981378359  
 Contact: NATIONAL BRAKE SERVICE INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 710662  
 Mailing City,St,Zip: SANTEE, CA 920720662  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Transfer Station  
 Tons: .0750  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 3 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 102416  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 710662  
 Mailing City,St,Zip: SANTEE, CA 92072  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 47  
 EPA ID: CAD981378359  
 Gas Station: Not reported  
 Inspection Date: 03/03/05  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: DAVID HILL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: HILL STEPHEN R  
 Property Address: P O BOX 710662  
 Property City,St,Zip: 92072  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/03/06  
 Facility Phone: 233-6296

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL BRAKE SERVICE INC (Continued)**

**1000260502**

HMMD DISCLOSURE INVENTORY:

Item Number: BR58  
 Chemical Name: BRAKE FLUID  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

HMMD VIOLATIONS:

Inspection Date: 08/09/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 7090  
 Violation Desc: NO TSDF SIGNED MANIFEST ONSITE

Inspection Date: 08/09/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7091  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/09/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 7092  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 01/11/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0853  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/11/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 0854  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 09/24/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL BRAKE SERVICE INC (Continued)**

**1000260502**

Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4354  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4355  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 4356  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 03/03/05  
 Waste Item #: 151  
 Waste Code: 151  
 Waste Name: ASBESTOS CONTAINING  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: FIBER DRUM  
 Haz Waste Hauler: 2640 LAIDLAW ENVIR. SERV.  
 Waste Desc: ASBESTOS/BEAD BLAST WASTE  
 Carcinogen: No

Inspection Date: 03/03/05  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 32  
 Quantity String: 32  
 Annual Qty: 480  
 Annual Qty String: 480  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 2986 INDUSTRIAL SOLVENT &  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 03/03/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

---

**NATIONAL BRAKE SERVICE INC (Continued)**

**1000260502**

Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: EXCESS OIL FROM AXLE  
 Carcinogen: No

29

**UNIVERSAL RADIATOR SHOP  
 2005 IMPERIAL AV  
 SAN DIEGO, CA 92102**

**LUST S105690927  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: SLT19728128  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2007-03-23 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Alejandra Morris  
 RP Address: 2005 Imperial Ave.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNIVERSAL RADIATOR SHOP (Continued)**

**S105690927**

Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13892-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608125637  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1994-01-13 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1990-04-27 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-04-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: MR. ALEX ZIRPOLO



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNIVERSAL RADIATOR SHOP (Continued)**

**S105690927**

RP Address: 2150 FIRST AVE  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13892-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H13892-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Preliminary Assessment  
 Date: 1/13/1994  
 Begandt: 4/27/1990

Case Number: H13892-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: XV**  
 FType: AX  
 FStatus: Preliminary Assessment  
 Date: 3/23/2007  
 Begandt: Not reported

29

**OCEAN HABITABILITY INC**  
**1844 IMPERIAL AVE**  
**SAN DIEGO, CA 92102**

**RCRA-SQG 1000150461**  
**FINDS CAD982018392**

**RCRA-SQG:**

Date form received by agency: 07/29/1987  
 Facility name: OCEAN HABITABILITY INC  
 Facility address: 1844 IMPERIAL AVE  
 SAN DIEGO, CA 92102  
 EPA ID: CAD982018392  
 Mailing address: IMPERIAL AVE  
 SAN DIEGO, CA 92102

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OCEAN HABITABILITY INC (Continued)**

**1000150461**

Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1844 IMPERIAL AVE  
 SAN DIEGO, CA 92102  
 Contact country: US  
 Contact telephone: (619) 232-0871  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: JERRY EISENHOWER  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OCEAN HABITABILITY INC (Continued)**

**1000150461**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

29

**WILSON & HAMPTON REFINISHING I  
 1835 IMPERIAL AVENUE  
 SAN DIEGO, CA 92102**

**RCRA-SQG 1000385035  
 FINDS CAD981686926  
 HAZNET**

RCRA-SQG:

Date form received by agency: 10/27/1986  
 Facility name: WILSON HAMPTON  
 Facility address: 1835 IMPERIAL AVE  
 SAN DIEGO, CA 92102  
 EPA ID: CAD981686926  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1835 IMPERIAL AVE  
 SAN DIEGO, CA 92102  
 Contact country: US  
 Contact telephone: (619) 234-3606  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: ROBT HAMPTON & E CLOWES JONES  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**WILSON & HAMPTON REFINISHING I (Continued)**

**1000385035**

Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD981686926  
 Contact: HRYHORI SPYCIA/DAVID R LINDEN  
 Telephone: 6192343606  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921023860  
 Gen County: San Diego  
 TSD EPA ID: CAT080013532  
 TSD County: 0  
 Waste Category: Latex waste  
 Disposal Method: Not reported  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD981686926  
 Contact: HRYHORI SPYCIA/DAVID R LINDEN  
 Telephone: 6192343606  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921023860  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**WILSON & HAMPTON REFINISHING I (Continued)**

**1000385035**

Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Recycler  
 Tons: .6880  
 Facility County: San Diego

Gepaid: CAD981686926  
 Contact: HRYHORI SPYCIA/DAVID R LINDEN  
 Telephone: 6192343606  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921023860  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons: 1.0633  
 Facility County: San Diego

Gepaid: CAD981686926  
 Contact: HRYHORI SPYCIA/DAVID R LINDEN  
 Telephone: 6192343606  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921023860  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Latex waste  
 Disposal Method: Recycler  
 Tons: .4378  
 Facility County: San Diego

Gepaid: CAD981686926  
 Contact: HRYHORI SPYCIA/DAVID R LINDEN  
 Telephone: 6192343606  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921023860  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Not reported  
 Tons: .2085  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 24 additional CA\_HAZNET: record(s) in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

29 **FIRST CHOICE**  
**24 21ST ST**  
**SAN DIEGO, CA 92104**

**LUST** **S102430001**  
**Cortese** **N/A**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300313  
 Stop Date: 1989-07-12 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1990-11-27 00:00:00  
 Discover Date: 1989-07-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-07-12 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: BERT BERNARDINI  
 RP Address: 24 21ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: AN  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H29231-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FIRST CHOICE (Continued)**

**S102430001**

Case Number: 9UT1492  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT1492  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 07/12/1989  
 How Found: Tank Closure  
 Date Stopped: 07/12/1989  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 07/12/1989  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 11/27/90  
 Pilot Program: LOP  
 Local Case: H29231-001  
 Basin Number: Not reported  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 07/12/1989  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 24 21ST ST

**San Diego Co. HMMD:**

Facility ID: 129231

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FIRST CHOICE (Continued)**

**S102430001**

Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 4476 KANSAS ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92116  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 47  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: BERT BERNARDINI  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAFARI INVESTMENTS L P  
 Property Address: 4805 POINT ALTO ST  
 Property City,St,Zip: 91941  
 Tank Owner: ALBERT BERNARDINI TRUST  
 Tank Address: 4476 KANSAS ST  
 Tank City,St,Zip: San Diego, CA 92116  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-670-4031

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FIRST CHOICE (Continued)**

**S102430001**

Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H29231-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 11/27/1990  
 Begandt: 7/12/1989

29

**STANDARD MEAT CO INC**  
**101 19TH ST**  
**SAN DIEGO, CA 92102**

**San Diego Co. HMMD**  
**SWEEPS UST**

**S104749679**  
**N/A**

San Diego Co. HMMD:

Facility ID: 121076  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 101 19TH ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92102  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 47  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/02/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: VINCENT NARES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**STANDARD MEAT CO INC (Continued)**

**S104749679**

Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: NARES VINCENT TRS  
 Property Address: 1517 CLOVE ST  
 Property City,St,Zip: 92106  
 Tank Owner: STANDARD MEAT CO INC  
 Tank Address: 101 19TH ST  
 Tank City,St,Zip: San Diego, CA 92102  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-6585

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**STANDARD MEAT CO INC (Continued)**

**S104749679**

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21076  
 Number: Not reported  
 Board Of Equalization: 44-023420  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021076-000001  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

30

**CITY OF SAN DIEGO  
 800 HARBOR DR  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104750830  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608119024  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: 1990-07-07 00:00:00  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remedial action (cleanup) Underway  
 Chemical: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO (Continued)**

**S104750830**

Contact Person: Not reported  
 Responsible Party: RICH GOSSETT  
 RP Address: PO BOX 85176  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H25938-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 125938  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: N CRNR 8TH & HARBOR  
 Mailing City, St, Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ATCHISON TOPEKA&SANTA FE RAILW

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO (Continued)**

**S104750830**

Property Address: CALIFORNIA STATE ASS  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H25938-001  
 Agency: DEH Site Assessment & Mitigation

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO (Continued)**

**S104750830**

**Funding:** Non Billable  
 FType: Complaint  
 FStatus: Remedial Action (Clean-Up)  
 Date: 7/7/1990  
 Begandt: 7/7/1990

**30 SAN DIEGO GAS WORKS  
 9TH STREET BTWN IMPERIAL AND COMMERCIAL  
 SAN DIEGO, CA 92101**

**Manufactured Gas Plants 1008407750  
 N/A**

Manufactured Gas Plants:  
 Alternate Name:CONSOLIDATED GAS AND ELECTRIC.

**30 MTDB LEASEHOLD  
 93 08TH AV  
 SAN DIEGO, CA 92101**

**LUST S104890821  
 San Diego Co. HMMD N/A  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608105248  
 Stop Date: 2001-04-06 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2002-11-26 00:00:00  
 Discover Date: 2001-03-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-03-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: GREG WEYL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MTDB LEASEHOLD (Continued)**

**S104890821**

RP Address: 2600 OLD CROW CYN RD #200  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H39423-001  
 Case Number: SOILS ONLY  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMMD:**

Facility ID: 139423  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 54  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MTDB LEASEHOLD (Continued)**

**S104890821**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H39423-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MTDB LEASEHOLD (Continued)**

**S104890821**

FStatus: Closed Case  
 Date: 11/26/2002  
 Begandt: 3/15/2001

**30**

**SDG&E STATION A, BLK 157  
 45 9TH AVE  
 SAN DIEGO, CA 92101**

**LUST S104735591  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT2695  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 12/02/1993  
 How Found: Tank Closure  
 Date Stopped: 12/02/1993  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Remove Free Product - remove floating product from water table  
 Confirm Date: 02/04/1994  
 Submit Workplan: 2/8/94  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: 02/17/1999  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/10/00  
 Pilot Program: LOP  
 Local Case: H32310-001  
 Basin Number: 908.21  
 Gwater Depth: 7'  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 01/11/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**30 SDG&E  
 45 9TH  
 SAN DIEGO, CA 92101**

**Cortese S103066326  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

**30 PLANT PRODUCTS & SUPPLY CO  
 822 IMPERIAL AV  
 SAN DIEGO, CA 92101**

**LUST S104748519  
 San Diego Co. HMD N/A  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607399047  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-02-24 00:00:00  
 Discover Date: 1999-06-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-06-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: EDWARD F PLANT  
 RP Address: 825 IMPERIAL AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PLANT PRODUCTS & SUPPLY CO (Continued)**

**S104748519**

Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15921-001  
 Case Number: 9UT3958  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607399240  
 Stop Date: 2000-04-18 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-02-24 00:00:00  
 Discover Date: 2000-04-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: C/O FREDERIC L GORDON  
 RP Address: 1230 COLUMBIA ST #700

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PLANT PRODUCTS & SUPPLY CO (Continued)**

**S104748519**

Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15921-002  
 Case Number: 9UT4047  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 115921  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 822 IMPERIAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAD98167461  
 Gas Station: Not reported  
 Inspection Date: 10/23/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: GEORGE LONGWORTH  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PLANT PRODUCTS & SUPPLY CO (Continued)**

**S104748519**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-236-1115

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: at4487  
 Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

Tank Number: T002  
 Tank ID Number: at4590  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: at4590  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PLANT PRODUCTS & SUPPLY CO (Continued)**

**S104748519**

Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H15921-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/24/2003  
 Begandt: 6/15/1999

Case Number: H15921-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/24/2003  
 Begandt: 4/18/2000

30

**EVRDA LOP (535-562-03)**  
**822 IMPERIAL AVE**  
**SAN DIEGO, CA 92101**

**LUST S104234306**  
**N/A**

LUST:

Region: 9  
 Case Number: 9UT3958  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 06/15/1999  
 How Found: Tank Closure  
 Date Stopped: 06/15/1999  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Remediation Plan  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: 8/24/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: 08/04/1999  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H15921-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EVRDA LOP (535-562-03) (Continued)**

**S104234306**

priority: Not reported  
 File Dispn: Not reported  
 Release Date: 06/15/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported  
  
 Region: 9  
 Case Number: 9UT4047  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: Not reported  
 Date Found: 04/18/2000  
 How Found: Tank Closure  
 Date Stopped: 04/18/2000  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: 5/2/00  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H15921-002  
 Basin Number: 908.21  
 Gwater Depth: 10  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: 2  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 04/18/2000  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

30

**CITY OF SAN DIEGO  
 800 IMPERIAL AV  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S105539636  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO (Continued)**

**S105539636**

Leak Source: Piping  
 Global Id: T0608150421  
 Stop Date: 1999-11-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-07-21 00:00:00  
 Discover Date: 1999-11-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-11-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: ATTN: RICHARD WILLIAMS  
 RP Address: 376 S VALENCIA AV  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H25929-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

CITY OF SAN DIEGO (Continued)

S105539636

Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Spill  
 Leak Source: Piping  
 Global Id: T0608169734  
 Stop Date: 1990-06-06 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-12-19 00:00:00  
 Discover Date: 1990-06-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-07-11 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: Mr. Rick Horn  
 RP Address: 276 Tank Farm Road  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H25929-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO (Continued)**

**S105539636**

Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 125929  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1010 2ND AV 0444  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: TED OLSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-533-3174

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO (Continued)**

**S105539636**

Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H25929-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/19/2003  
 Begandt: 6/6/1990

Case Number: H25929-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 7/21/2004  
 Begandt: 11/8/1999

31

**CAMACHO IRON WORKS  
 3056 IMPERIAL AVENUE  
 SAN DIEGO, CA 92102**

**ENVIROSTOR S106893848  
 N/A**

**ENVIROSTOR:**

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CAMACHO IRON WORKS (Continued)**

**S106893848**

Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37340139  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 34  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-02-10 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37340139  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

**Completed Info:**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 02/10/00

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

**Management:**

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**32 MARATHON LAND & CATTLE  
 2682 IMPERIAL AVE  
 SAN DIEGO, CA 92102**

**LUST S100733645  
 Cortese N/A  
 SWEEPS UST**

LUST:

Region: 9  
 Case Number: 9UT976  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 06/16/1988  
 How Found: Tank Closure  
 Date Stopped: 06/16/1988  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: 06/17/1988  
 Submit Workplan: Not reported  
 Prelim Assess: 09/19/1988  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 11/22/88  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 10/14/93  
 Pilot Program: LOP  
 Local Case: H26511-001  
 Basin Number: Not reported  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 06/20/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2682 IMPERIAL AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 26511  
 Number: Not reported  
 Board Of Equalization: 44-023684  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MARATHON LAND & CATTLE (Continued)**

**S100733645**

Swrcb Tank Id: 37-000-026511-000001  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 26511  
 Number: Not reported  
 Board Of Equalization: 44-023684  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-026511-000002  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 26511  
 Number: Not reported  
 Board Of Equalization: 44-023684  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-026511-000003  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 26511  
 Number: 9  
 Board Of Equalization: 44-023684  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARATHON LAND & CATTLE (Continued)**

**S100733645**

Number Of Tanks: Not reported

32

**2682 IMPERIAL AVENUE  
 SAN DIEGO, CA 92102**

**Notify 65 S100232868  
 N/A**

Notify 65:

Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92102-4002

32

**MARATHON LAND & CATILE  
 2682 IMPERIAL AV  
 SAN DIEGO, CA 92102**

**LUST S104751072  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303210  
 Stop Date: 1988-06-17 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-10-14 00:00:00  
 Discover Date: 1988-06-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-06-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: MR. MAN TRAN & NGUYEN HAO  
 RP Address: 3052 CLAIREMONT DR.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARATHON LAND & CATILE (Continued)**

**S104751072**

Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: LS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H26511-001  
 Case Number: 9UT976  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 126511  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3052 CLAIREMONT DR  
 Mailing City,St,Zip: SAN DIEGO, CA 92117  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 48  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE FURBY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TRAN MAN&NGUYEN HAO  
 Property Address: 2682 IMPERIAL AVE  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARATHON LAND & CATILE (Continued)**

**S104751072**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-276-4401

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARATHON LAND & CATILE (Continued)**

**S104751072**

Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H26511-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/14/1993  
 Begandt: 6/17/1988

32

**IMPERIAL AVENUE APARTMENTS  
 2701 IMPERIAL AV  
 SAN DIEGO, CA 92102**

**LUST S104755900**  
**San Diego Co. HMMD N/A**  
**SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607302696  
 Stop Date: 1999-06-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1999-06-25 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1999-06-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-06-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Maria Diaz  
 RP Address: 640 National City  
 Interim: Not reported  
 Oversight Prgm: LUST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMPERIAL AVENUE APARTMENTS (Continued)**

**S104755900**

MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: EM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H37003-001  
 Case Number: 9UT3936  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMMD:**

Facility ID: 137003  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 48  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DIAZ BERNARDO  
 Property Address: 640 NATIONAL CITY BL  
 Property City,St,Zip: 91950  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**IMPERIAL AVENUE APARTMENTS (Continued)**

**S104755900**

Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT4169  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: AT4169  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: AT4169  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T004  
 Tank ID Number: AT4169  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMPERIAL AVENUE APARTMENTS (Continued)**

**S104755900**

Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H37003-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 6/25/1999  
 Begandt: 6/24/1999

32

**IMPERIAL AVE. APARTMENTS  
 2701 IMPERIAL AVE  
 SAN DIEGO, CA 92102**

**LUST S104025595  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT3936  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 06/24/1999  
 How Found: Tank Closure  
 Date Stopped: 06/24/1999  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 06/25/1999  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H37003-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/LOW - MINOR OR NO POTENTIAL WATER RESOURCE IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 06/24/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMPERIAL AVE. APARTMENTS (Continued)**

**S104025595**

Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2701 IMPERIAL AVE

33

**CAMPBELL'S SHIPYARD  
 501 HARBOR DR  
 SAN DIEGO, CA 92112**

**LUST 1000345675  
 ENVIROSTOR N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: R  
 Funding: CAO  
 How Discovered: OM  
 How Stopped: Not reported  
 Leak Cause: Corrosion  
 Leak Source: Tank  
 Global Id: T0607391327  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: 2001-01-16 00:00:00  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: 2001-09-05 00:00:00  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2000-04-11 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-04-11 00:00:00  
 Review Date: 2000-12-19 00:00:00  
 Enter Date: 2001-01-30 00:00:00  
 MTBE Date: 2002-08-07 00:00:00  
 GW Qualifier: <  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: 10  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remedial action (cleanup) Underway  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: CAMPBELL'S SHIPYARD  
 RP Address: PO BOX 121870 SAN DIEGO, CA 92112  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: C  
 MTBE Conc: 1  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: TCA  
 Staff Initials: LS  
 Lead Agency: Regional Board

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CAMPBELL'S SHIPYARD (Continued)**

**1000345675**

Local Agency: 37000L  
 Hydr Basin #: SWEETWATER VALLEY (9)  
 Beneficial: NBU  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: No  
 Local Case #: H00417-003  
 Case Number: 9UT4109  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT4109  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 04/11/2000  
 How Found: Other Means  
 Date Stopped: / /  
 How Stopped: Other Means  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Regional Board  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 01/16/2001  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: UST  
 Local Case: H00417-003  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: NBU  
 NPDES Number: Not reported  
 priority: Not reported  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 04/11/2000  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CAMPBELL'S SHIPYARD (Continued)**

**1000345675**

ENVIROSTOR:

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37090001  
 Site Code: Not reported  
 Assembly: Not reported  
 Senate: Not reported  
 Special Program: Not reported  
 Status: Refer: Other Agency  
 Status Date: 1995-02-08 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 0  
 Longitude: 0  
 Alias Name: CAD008230047  
 37090001  
 Alias Type: Envirostor ID Number  
 EPA Identification Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DATABASE VALIDATION PROGRAM CONFIRMS NFA FOR DTSC.SITE SCREENING DONE  
 DHS ABANDONED SITE PROJECT: STRONG SOL- VENT ODOR EMANATED FROM  
 SITEPRELIM ASSESS DONE RCRA 3012: NFA - REGULATED BY LOCAL  
 AGENCIESSITE SCREENING DONE RCRA: HISTORICALLY DISPOSED TO SAN DIEGO  
 BAY

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 02/08/95  
  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 12/04/87  
  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 07/01/84  
  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 12/29/82  
  
 Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CAMPBELL'S SHIPYARD (Continued)**

**1000345675**

Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported  
 Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 10003, 10009  
 Potential Description: \* HALOGENATED SOLVENTS  
 Potential Description: \* HYDROCARBON SOLVENTS  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

34

**THRIFTY SERVICE STATION #96  
 2502 IMPERIAL AVE  
 SAN DIEGO, CA 92102**

**LUST S102439088  
 N/A**

LUST:  
 Region: 9  
 Case Number: 9UT691  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 03/02/1987  
 How Found: Not reported  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 6/15/87  
 Pilot Program: LOP  
 Local Case: H21069-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THRIFTY SERVICE STATION #96 (Continued)**

**S102439088**

Release Date: 03/02/1987  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

34

**THRIFTY #96  
 2502 IMPERIAL AVE  
 SAN DIEGO, CA 92102**

**LUST S102439013  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT2894  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 07/15/1994  
 How Found: Tank Closure  
 Date Stopped: 07/15/1994  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 09/01/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H21069-003  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/LOW - MINOR OR NO POTENTIAL WATER RESOURCE IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 07/15/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2502 IMPERIAL AVE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**34 ARCO FACILITY NO. 9560  
 2502 IMPERIAL AV  
 SAN DIEGO, CA 92102**

**Cortese  
 San Diego Co. HMMD  
 AIRS**

**S104749675  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:  
 Facility ID: 121069  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ENVIRONMENTAL COMPLIANCE  
 Mailing Address: PO BOX 6038  
 Mailing City,St,Zip: ARTESIA, CA 90702  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 48  
 EPA ID: CAL000225545  
 Gas Station: Not reported  
 Inspection Date: 02/17/04  
 Reinspection Date: Not reported  
 Inspector Name: RHANSEN  
 Violation Notice Issued: Not reported  
 Facility Contact: TAMMY LOVANO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ORKIN INC  
 Property Address: THRIFTY OIL CO  
 Property City,St,Zip: 90670  
 Tank Owner: BP WEST COAST PRODUCTS LLC  
 Tank Address: P.O. BOX 6038  
 Tank City,St,Zip: Artesia, CA 90702  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/17/05  
 Facility Phone: 619-702-4180

**HMMD DISCLOSURE INVENTORY:**

Item Number: CA40  
 Chemical Name: CARBON DIOXIDE LIQUID  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CRYOGENIC

Item Number: MI55  
 Chemical Name: MIDGRADE UNLEADED UNDERGROUND TANK 121069 T008 PLUS UNLEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9560 (Continued)**

**S104749675**

Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PR54  
 Chemical Name: PREMIUM UNLEADED UNDERGROUND TANK 121069 T007 SUPER UNLEADED  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: RE53  
 Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 121069 T006  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 096-1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: 096-2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 096-3  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T004  
 Tank ID Number: 096-10  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T005  
 Tank ID Number: 096-11

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO FACILITY NO. 9560 (Continued)**

**S104749675**

Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T006  
 Tank ID Number: 006  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T007  
 Tank ID Number: 007  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T008  
 Tank ID Number: 008  
 Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 2005  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2006  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 2007  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 2008  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 2009  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 02/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0135

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9560 (Continued)**

**S104749675**

Occurrences: Not reported  
 Item Number: 2083  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 2084  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 02/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3028  
 Occurrences: Not reported  
 Item Number: 2085  
 Violation Desc: UST RESPONSE PLAN NOT AVAILABLE

Inspection Date: 12/21/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3012  
 Occurrences: Not reported  
 Item Number: 2276  
 Violation Desc: DIDN'T NOTIFY HMD OF UST CHANGES

Inspection Date: 02/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3401  
 Occurrences: Not reported  
 Item Number: 7734  
 Violation Desc: NO CONTIN. AUDIO&VISUAL ALARM W/+SHUT

**HMMD WASTE STREAMS:**

Inspection Date: 02/17/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2997 BELSHIRE ENVIRONMENT  
 Waste Desc: USED FUEL FILTER  
 Carcinogen: No

**EMI:**

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1443  
 Air District Name: SD  
 SIC Code: 5541

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9560 (Continued)**

**S104749675**

Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4  
 Reactive Organic Gases Tons/Yr: 4  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1443  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4  
 Reactive Organic Gases Tons/Yr: 4  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1443  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4  
 Reactive Organic Gases Tons/Yr: 4  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1443  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4  
 Reactive Organic Gases Tons/Yr: 4  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9560 (Continued)**

**S104749675**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1443
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.5243586
Reactive Organic Gases Tons/Yr:	3.5243586
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1443
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.5243586
Reactive Organic Gases Tons/Yr:	3.5243586
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

34

**THRIFTY OIL STATION #96  
 2502 IMPERIAL AVE  
 SAN DIEGO, CA 92102**

**LUST S102439069  
 Cortese N/A  
 SWEEPS UST**

LUST:

Region:	9
Case Number:	9UT2547
Local Agency:	San Diego
Substance:	Waste Oil
Qty Leaked:	Not reported
Date Found:	03/14/1989
How Found:	Tank Closure
Date Stopped:	03/14/1989
How Stopped:	Close Tank
Source:	Unknown
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Soil only
Status:	Case Closed



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THRIFTY OIL STATION #96 (Continued)**

**S102439069**

Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 03/14/1989  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 8/1/89  
 Pilot Program: LOP  
 Local Case: H21069-002  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 03/14/1989  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2502 IMPERIAL AVE

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21069  
 Number: Not reported  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021069-000004  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 1

Status: A  
 Comp Number: 21069  
 Number: 9  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THRIFTY OIL STATION #96 (Continued)**

**S102439069**

Swrcb Tank Id: 37-000-021069-000001  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 4

Status: A  
 Comp Number: 21069  
 Number: 9  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021069-000002  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 21069  
 Number: 9  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021069-000003  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 21069  
 Number: 9  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021069-000005  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**THRIFTY OIL STATION #96 (Continued)**

**S102439069**

Number Of Tanks: Not reported

**34 ARCO PRODUCTS COMPANY #9560  
2502 IMPERIAL AVE  
SAN DIEGO, CA 92102**

**LUST S104234314  
N/A**

LUST:

Region:	9
Case Number:	9UT3972
Local Agency:	San Diego
Substance:	Gasoline
Qty Leaked:	0
Date Found:	08/24/1999
How Found:	Other Means
Date Stopped:	08/24/1999
How Stopped:	Other Means
Source:	Unknown
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Soil only
Status:	Preliminary site assessment underway
Abate Method:	Not reported
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	09/01/1999
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Enforce Type:	Not reported
Enforce Date:	Not reported
Closed Date:	Not reported
Pilot Program:	LOP
Local Case:	H21069-004
Basin Number:	908.22
Gwater Depth:	Not reported
Beneficial Use:	No Beneficial groundwater use
NPDES Number:	Not reported
priority:	LOP/LOW - LOW POTENTIAL HEALTH/SAFTY/ENVIRONMENTAL IMPACT
File Disp:	Not reported
Release Date:	08/24/1999
Interim Remedial Actions:	Not reported
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

**34 ARCO 9560  
2502 IMPERIAL AV  
SAN DIEGO, CA 92102**

**LUST S105690226  
SAN DIEGO CO. SAM N/A**

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO 9560 (Continued)**

**S105690226**

How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301292  
 Stop Date: 1989-03-14 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-08-01 00:00:00  
 Discover Date: 1989-03-14 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-03-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: PETER D'AMICO  
 RP Address: 13116 Imperial Highway  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21069-002  
 Case Number: 9UT2547  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO 9560 (Continued)**

**S105690226**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607301656  
 Stop Date: 1994-07-15 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1994-11-01 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1994-07-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-07-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: PETER D'AMICO  
 RP Address: 13116 Imperial Highway  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: KK  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21069-003  
 Case Number: 9UT2894  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO 9560 (Continued)**

**S105690226**

Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302961  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-06-24 00:00:00  
 Discover Date: 1987-03-04 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-03-04 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1, REC-2, WARM, WILD  
 Priority: 7

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO 9560 (Continued)**

**S105690226**

Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21069-001  
 Case Number: 9UT691  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607399192  
 Stop Date: 1999-08-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1999-09-01 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1999-08-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-08-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: MARTA BRUGERA-ZIRKLE  
 RP Address: 4 CENTERPOINTE DR  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO 9560 (Continued)**

**S105690226**

Staff: UNA  
 Staff Initials: KK  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21069-004  
 Case Number: 9UT3972  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H21069-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/24/1987  
 Begandt: 3/4/1987

Case Number: H21069-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/1/1989  
 Begandt: 3/14/1989

Case Number: H21069-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 9/1/1994  
 Begandt: 7/15/1994

Case Number: H21069-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 9/1/1999  
 Begandt: 8/24/1999



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**35**      **ULTRACRAFT**  
**9 17TH ST**  
**SAN DIEGO, CA 92101**

**San Diego Co. HMMD**      **S104746204**  
**SWEEPS UST**                      **N/A**

San Diego Co. HMMD:  
 Facility ID: 105588  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 9 17TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAL000187900  
 Gas Station: Not reported  
 Inspection Date: 02/28/00  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ALBERTO L. PEREO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: B & L MASONRY INC  
 Tank Address: 9 17TH ST  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-231-3635

HMMD DISCLOSURE INVENTORY:  
 Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:  
 Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ULTRACRAFT (Continued)**

**S104746204**

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 5588  
 Number: Not reported  
 Board Of Equalization: 44-022243  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005588-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 5588  
 Number: Not reported  
 Board Of Equalization: 44-022243  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ULTRACRAFT (Continued)**

**S104746204**

Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005588-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

**36**

**EL GUERO TIRE SHOP  
 2401 IMPERIAL AVE  
 SAN DIEGO, CA 92102**

**LUST  
 Cortese  
 SWEEPS UST**

**S102444743  
 N/A**

**LUST:**

Region: 9  
 Case Number: 9UT3182  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 07/10/1996  
 How Found: Not reported  
 Date Stopped: 07/10/1996  
 How Stopped: Not reported  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: 07/25/1996  
 Submit Workplan: 8/1/96  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H27463-001  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 07/10/1996  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2401 IMPERIAL AVE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL GUERO TIRE SHOP (Continued)**

**S102444743**

SWEEPS UST:

Status: A  
 Comp Number: 27463  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-027463-000001  
 Actv Date: Not reported  
 Capacity: 100  
 Tank Use: UNKNOWN  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: 2

Status: A  
 Comp Number: 27463  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-027463-000002  
 Actv Date: Not reported  
 Capacity: 100  
 Tank Use: UNKNOWN  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

36

**EL GUERO TIRE SHOP & REPAIR  
 2401 IMPERIAL AV  
 SAN DIEGO, CA 92102**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104751334  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: 13267R  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0607301948  
 Stop Date: 1996-07-10 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EL GUERO TIRE SHOP & REPAIR (Continued)**

**S104751334**

Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1996-07-10 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1996-07-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Not reported  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: RAMIRO & MARY MONTOGA  
 RP Address: 10895 UVALDE CT  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: CLP  
 Staff Initials: EM  
 Lead Agency: Regional Board  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H27463-001  
 Case Number: 9UT3182  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 127463  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 10895 UVALDE COURT  
 Mailing City,St,Zip: SAN DIEGO, CA 92124

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL GUERO TIRE SHOP & REPAIR (Continued)**

**S104751334**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 48  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/19/96  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RALPH ESPARZA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MONTOYA MARY  
 Property Address: 10895 UVALDE CT  
 Property City,St,Zip: 92124  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-5081

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT3654  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: AT3654  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: AT3654  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 05/18/94

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL GUERO TIRE SHOP & REPAIR (Continued)**

**S104751334**

Waste Code: Not reported  
 Type of Violation: 6HX3011  
 Occurrences: Not reported  
 Item Number: 0832  
 Violation Desc: FAIL TO COMPLY WITH OP PERMIT CONDITIO

Inspection Date: 05/18/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3013  
 Occurrences: Not reported  
 Item Number: 0833  
 Violation Desc: NO FINANCIAL RESPOSIBILITY DOC

Inspection Date: 05/18/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 0834  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 05/18/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 0835  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 05/18/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 0836  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 05/18/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 0837  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

Inspection Date: 06/26/95  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 2415  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 06/26/95  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 2416  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

**HMMD WASTE STREAMS:**

Inspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL GUERO TIRE SHOP & REPAIR (Continued)**

**S104751334**

Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203178  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2401 IMPERIAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92102  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 48  
 EPA ID: CAL000122080  
 Gas Station: Not reported  
 Inspection Date: 03/04/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: ENRIQUE SALAS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MONTOYA MARY  
 Property Address: 10895 UVALDE CT  
 Property City,St,Zip: 92124  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/04/05  
 Facility Phone: 619-239-6013

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL GUERO TIRE SHOP & REPAIR (Continued)**

**S104751334**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/04/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 9306  
 Violation Desc: UPFP NOT OBTAINED for HAZWASTE

Inspection Date: 03/04/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9307  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/04/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9308  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/04/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9309  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/04/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9310  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 03/04/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 9311  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: 03/04/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL GUERO TIRE SHOP & REPAIR (Continued)**

**S104751334**

Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 03/04/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H27463-001  
 Agency: CA Regional Water Quality Control Board  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 4/23/2004  
 Begandt: 7/10/1996

37

**NO NAME-FOUND ON TOP OF FILES  
 1955 NATIONAL AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD S106060055  
 N/A

San Diego Co. HMMD:

Facility ID: 102368  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NO NAME-FOUND ON TOP OF FILES (Continued)**

**S106060055**

EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	Not reported
Reinspection Date:	Not reported
Inspector Name:	Not reported
Violation Notice Issued:	Not reported
Facility Contact:	Not reported
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	Not reported
Property Address:	Not reported
Property City,St,Zip:	Not reported
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NO NAME-FOUND ON TOP OF FILES (Continued)**

**S106060055**

Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**M & M RECYCLING  
 1937 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104752770  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 131526  
 Inactive Indicator: Active  
 Business Code: 6HK32  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1937 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/07/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ADDIE HANKINS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-681-6564

HMMD DISCLOSURE INVENTORY:  
 Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**M & M RECYCLING (Continued)**

**S104752770**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**ELMERS FOREIGN AUTO WRECKING**  
**1935 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000595618**  
**FINDS CAD983595687**  
**San Diego Co. HMMD**

**RCRA-SQG:**

Date form received by agency: 07/24/1991  
 Facility name: ELMERS FOREIGN AUTO WRECKING  
 Facility address: 1935 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD983595687  
 Contact: JOHN ROSE  
 Contact address: 1935 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 232-1156  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELMERS FOREIGN AUTO WRECKING (Continued)**

**1000595618**

hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: JOHN ROSE JR  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELMERS FOREIGN AUTO WRECKING (Continued)**

**1000595618**

San Diego Co. HMMD:

Facility ID:	116479
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1935 NATIONAL AVE
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	Not reported
EPA ID:	CAD983595687
Gas Station:	Not reported
Inspection Date:	09/23/93
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	JOHN ROSE JR
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	Not reported
Property Address:	Not reported
Property City,St,Zip:	Not reported
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-234-8201

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

HMMD VIOLATIONS:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELMERS FOREIGN AUTO WRECKING (Continued)**

**1000595618**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**ASTRO PAK  
 1936 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748052  
 N/A**

San Diego Co. HMMD:

Facility ID: 114011  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1936 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000041792  
 Gas Station: Not reported  
 Inspection Date: 01/07/05  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: TONY COLLINS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ASTRO PAK CORPORATION  
 Property Address: 12201 PANGBORN AVE  
 Property City,St,Zip: 90241



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ASTRO PAK (Continued)**

**S104748052**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/07/06  
 Facility Phone: 619-231-1022

**HMMD DISCLOSURE INVENTORY:**

Item Number: AR75  
 Chemical Name: ARGON (LIQUID & GAS)  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: BR74  
 Chemical Name: BRULIN INDUSTRIAL DETERGENT  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HE76  
 Chemical Name: HELIUM  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: IS72  
 Chemical Name: ISOPROPYL ALCOHOL  
 Case Number: 67-63-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: KE77  
 Chemical Name: KEROSENE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ASTRO PAK (Continued)**

**S104748052**

Case Number: 8052-41-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: NI71  
 Chemical Name: NITROGEN (GAS & LIQUID)  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: PR95  
 Chemical Name: PROPANE PROPANE  
 Case Number: 68476-85-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: TR73  
 Chemical Name: TRICHLOROTRIFLUOROETHANE (FREON 113) 55 GAL & 5 GAL  
 Case Number: 76-13-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ASTRO PAK (Continued)**

**S104748052**

Occurrences: Not reported  
 Item Number: 0116  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/26/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 8901  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 09/26/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 8902  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4740  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/07/05  
 Waste Code: Not reported  
 Type of Violation: 6HV4205  
 Occurrences: Not reported  
 Item Number: 7423  
 Violation Desc: MED SOLID WASTE NOT SECURED TO DENY ACCE

**HMMD WASTE STREAMS:**

Inspection Date: 01/07/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 01/07/05  
 Waste Item #: 251  
 Waste Code: 251  
 Waste Name: STILL BOTTOMS W/HALO  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: GAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ASTRO PAK (Continued)**

**S104748052**

Treatment Method: 007 INCINERATION  
 Storage Method: CAN  
 Haz Waste Hauler: 1052 P F R ENVIRONMENTAL  
 Waste Desc: UNITED PUMPING SERVICE  
 Carcinogen: No

Inspection Date: 01/07/05  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 1052 P F R ENVIRONMENTAL  
 Waste Desc: ISOPROPYL ALCOHOL  
 Carcinogen: No

Facility ID: 203446  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1936 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ASTRO PAK CORPORATION  
 Property Address: 12201 PANGBORN AVE  
 Property City,St,Zip: 90241  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-231-1022

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ASTRO PAK (Continued)**

**S104748052**

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**ASTRO PAK CORPORATION  
 1936 NATIONAL AVENUE  
 SAN DIEGO, CA 92113**

**HAZNET S100930125  
 N/A**

**HAZNET:**

Gepaid: CAL000041792  
 Contact: DEAN DRESSLER CONTROLLER  
 Telephone: 5628033400  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 12201 PANGBORN AVE  
 Mailing City,St,Zip: DOWNEY, CA 902415612

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ASTRO PAK CORPORATION (Continued)**

**S100930125**

Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.05  
 Facility County: Not reported

Gepaid: CAL000041792  
 Contact: DEAN DRESSLER CONTROLLER  
 Telephone: 5628033400  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 12201 PANGBORN AVE  
 Mailing City,St,Zip: DOWNEY, CA 902415612  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: San Bernardino  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: 0.1  
 Facility County: Not reported

Gepaid: CAL000041792  
 Contact: ASTRO PAK CORPORATION  
 Telephone: 5628033400  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 12201 PANGBORN AVE  
 Mailing City,St,Zip: DOWNEY, CA 902415612  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2  
 Disposal Method: Treatment, Tank  
 Tons: 4.1700  
 Facility County: San Diego

Gepaid: CAL000041792  
 Contact: ASTRO PAK CORPORATION  
 Telephone: 5628033400  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 12201 PANGBORN AVE  
 Mailing City,St,Zip: DOWNEY, CA 902415612  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL000041792  
 Contact: ASTRO PAK CORPORATION  
 Telephone: 5628033400  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ASTRO PAK CORPORATION (Continued)**

**S100930125**

Mailing Name: Not reported  
 Mailing Address: 12201 PANGBORN AVE  
 Mailing City,St,Zip: DOWNEY, CA 902415612  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 21 additional CA\_HAZNET: record(s) in the EDR Site Report.

37

**PETROLEUM RECYCLING CORP  
 1921 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104749177  
 N/A**

San Diego Co. HMMD:

Facility ID: 119768  
 Inactive Indicator: Active  
 Business Code: 6HK78  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2651 WALNUT AV  
 Mailing City,St,Zip: SIGNAL HILL, CA 90806  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAD982028748  
 Gas Station: Not reported  
 Inspection Date: 11/01/91  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RICHARD NIELSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-226-1408

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PETROLEUM RECYCLING CORP (Continued)**

**S104749177**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**AZTEC OIL  
 1921 NATIONAL AVE  
 SAN DIEGO, CA 92120**

**FINDS 1000200668  
 HAZNET CAD982028748  
 RCRA-NonGen**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AZTEC OIL (Continued)**

**1000200668**

HAZNET:

Gepaid: CAD982028748  
 Contact: LOUIE RATAJESAK  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2651 WALNUT AVE  
 Mailing City,St,Zip: SIGNAL HILL, CA 921200000  
 Gen County: San Diego  
 TSD EPA ID: CAD982028748  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: 172.7005  
 Facility County: San Diego

Gepaid: CAD982028748  
 Contact: LOUIE RATAJESAK  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2651 WALNUT AVE  
 Mailing City,St,Zip: SIGNAL HILL, CA 921200000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Disposal, Other  
 Tons: 56.4676  
 Facility County: San Diego

Gepaid: CAD982028748  
 Contact: LOUIE RATAJESAK  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2651 WALNUT AVE  
 Mailing City,St,Zip: SIGNAL HILL, CA 921200000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: 10.8420  
 Facility County: San Diego

Gepaid: CAD982028748  
 Contact: LOUIE RATAJESAK  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2651 WALNUT AVE  
 Mailing City,St,Zip: SIGNAL HILL, CA 921200000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AZTEC OIL (Continued)**

**1000200668**

Disposal Method: Not reported  
 Tons: 27.1050  
 Facility County: San Diego

Gepaid: CAD982028748  
 Contact: LOUIE RATAJESAK  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2651 WALNUT AVE  
 Mailing City,St,Zip: SIGNAL HILL, CA 921200000  
 Gen County: San Diego  
 TSD EPA ID: CAD981696420  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: .4587  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

**RCRA-NonGen:**

Date form received by agency: 07/06/1987  
 Facility name: AZTEC OIL  
 Facility address: 1921 NATIONAL AVE  
 SAN DIEGO, CA 92120

EPA ID: CAD982028748  
 Mailing address: PO BOX 20783  
 SAN DIEGO, CA 92120

Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1921 NATIONAL AVE  
 SAN DIEGO, CA 92120

Contact country: US  
 Contact telephone: (619) 298-1610  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: RATAJESAK LOUIE  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AZTEC OIL (Continued)**

**1000200668**

Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Facility Has Received Notices of Violations:

Regulation violated: F - 262.30-34.C  
 Area of violation: Generators - General  
 Date violation determined: 06/28/1993  
 Date achieved compliance: 07/11/1993  
 Violation lead agency: State  
 Enforcement action: REFERRAL TO ATTORNEY GENERAL  
 Enforcement action date: 03/29/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 264.140-150.H  
 Area of violation: TSD - Financial Requirements  
 Date violation determined: 06/28/1993  
 Date achieved compliance: 07/11/1993  
 Violation lead agency: State  
 Enforcement action: REFERRAL TO ATTORNEY GENERAL  
 Enforcement action date: 03/29/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 06/16/1993  
 Evaluation: FINANCIAL RECORD REVIEW

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AZTEC OIL (Continued)**

**1000200668**

Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 05/17/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 07/11/1993  
 Evaluation lead agency: State

Evaluation date: 05/17/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - Financial Requirements  
 Date achieved compliance: 07/11/1993  
 Evaluation lead agency: State

37

**ALLEN, WILLIS M.  
 1902 NATIONAL AVE.  
 SAN DIEGO, CA 92113**

**CERC-NFRAP 1003879722  
 CAD983648890**

CERC-NFRAP:  
 Site ID: 0904583  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):  
 Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)  
  
 Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:  
 Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 09/23/1992  
 Priority Level: Not reported  
  
 Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 07/06/1993  
 Priority Level: Not reported  
  
 Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 07/06/1993  
 Priority Level: NFRAP (No Further Remedial Action Planned)

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37**      **SOUTHWEST COACHES, INC.**  
**1902 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**HIST UST**      **U001572996**  
**N/A**

HIST UST:

Region:                    STATE  
 Facility ID:                00000054293  
 Facility Type:             Other  
 Other Type:                PUBLIC TRANSPORTATIO  
 Total Tanks:              0004  
 Contact Name:             DAVID O'NEIL, SUPERVISOR  
 Telephone:                6192327579  
 Owner Name:               FRANK GINGLARDY AND EDGAR DICK  
 Owner Address:            1125 PRESIOCA STREET  
 Owner City,St,Zip:        SPRING VALLEY, CA 92077

Tank Num:                001  
 Container Num:            1  
 Year Installed:            Not reported  
 Tank Capacity:            00000000  
 Tank Used for:            PRODUCT  
 Type of Fuel:             DIESEL  
 Tank Construction:        Not reported  
 Leak Detection:            Pressure Test

Tank Num:                002  
 Container Num:            2  
 Year Installed:            Not reported  
 Tank Capacity:            00000000  
 Tank Used for:            PRODUCT  
 Type of Fuel:             DIESEL  
 Tank Construction:        Not reported  
 Leak Detection:            Pressure Test

Tank Num:                003  
 Container Num:            3  
 Year Installed:            Not reported  
 Tank Capacity:            00000000  
 Tank Used for:            PRODUCT  
 Type of Fuel:             DIESEL  
 Tank Construction:        Not reported  
 Leak Detection:            Pressure Test

Tank Num:                004  
 Container Num:            4  
 Year Installed:            Not reported  
 Tank Capacity:            00000000  
 Tank Used for:            PRODUCT  
 Type of Fuel:             DIESEL  
 Tank Construction:        Not reported  
 Leak Detection:            Pressure Test

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37 BILL ALLEN/ ELMER'S AUTO  
 1902 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S101302104  
 Cortese N/A  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: LFOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300643  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-05-02 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: WILLIS M ALLEN JR  
 RP Address: P.O. BOX 2570  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: ML  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10432-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BILL ALLEN/ ELMER'S AUTO (Continued)**

**S101302104**

Case Number: 9UT1858  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT1858  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 18000  
 Date Found: 11/08/1990  
 How Found: Other Means  
 Date Stopped: 11/08/1990  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 11/16/1990  
 Submit Workplan: 11/19/90  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: 09/24/1992  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/2/96  
 Pilot Program: LOP  
 Local Case: H10432-001  
 Basin Number: 908.22  
 Gwater Depth: 16'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - ADMINISTRATIVE (CLOSURE/SB2004/ENFORCEMENT)  
 File Dispn: File discarded, case closed  
 Release Date: 08/16/1993  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 1902 NATIONAL AVE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BILL ALLEN/ ELMER'S AUTO (Continued)**

**S101302104**

SWEEPS UST:

Status: Not reported  
 Comp Number: 10432  
 Number: Not reported  
 Board Of Equalization: 44-022454  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010432-000001  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 5

Status: Not reported  
 Comp Number: 10432  
 Number: Not reported  
 Board Of Equalization: 44-022454  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010432-000002  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 10432  
 Number: Not reported  
 Board Of Equalization: 44-022454  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010432-000003  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 10432  
 Number: Not reported  
 Board Of Equalization: 44-022454  
 Ref Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BILL ALLEN/ ELMER'S AUTO (Continued)**

**S101302104**

Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010432-000004  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 10432  
 Number: Not reported  
 Board Of Equalization: 44-022454  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010432-000005  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 10432  
 Number: 9  
 Board Of Equalization: 44-022454  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H10432-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/2/1996  
 Begandt: 11/16/1990

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37 GEORGE GONZALEZ  
 1902 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106060799  
 N/A**

San Diego Co. HMMD:

Facility ID:	110432
Inactive Indicator:	Active
Business Code:	6HK60
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	4650 ALDINE DR
Mailing City, St, Zip:	SAN DIEGO, CA 92115
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	03/14/02
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	AL SMITH/MANAGER
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	GOGRI MAHESH
Property Address:	404 MIWOK CT
Property City, St, Zip:	94539
Tank Owner:	EDGAR DICKERSON
Tank Address:	1902 NATIONAL AV
Tank City, St, Zip:	San Diego, CA 92113
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-571-8798

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	T001
Tank ID Number:	1
Waste or Product:	Not reported
Tank Contents:	DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GEORGE GONZALEZ (Continued)**

**S106060799**

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T005  
 Tank ID Number: 5  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/06/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0031  
 Occurrences: Not reported  
 Item Number: 6550  
 Violation Desc: NO HAZWASTE DISPOSAL RECEIPTS

Inspection Date: 01/06/88  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 6551  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 02/09/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0024  
 Occurrences: Not reported  
 Item Number: 7246  
 Violation Desc: HAZWASTE DISPOSAL TO UNAUTHORIZED POINT

Inspection Date: 02/09/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 7247  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 03/14/02  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 5611  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 03/14/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GEORGE GONZALEZ (Continued)**

**S106060799**

Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5612  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/14/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5613  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/14/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5614  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 03/14/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 5615  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 202972  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 4650 ALDINE DR  
 Mailing City,St,Zip: SAN DIEGO, CA 92115  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GEORGE GONZALEZ (Continued)**

**S106060799**

EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/23/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GOGRI MAHESH  
 Property Address: 404 MIWOK CT  
 Property City,St,Zip: 94539  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-571-8798

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/23/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 4307  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

Inspection Date: 09/23/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4308  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 09/23/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GEORGE GONZALEZ (Continued)**

**S106060799**

Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4309  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 09/23/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 4310  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**C/C WELDING  
 1901 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748600  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 116478  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1901 NATIONAL AV  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/13/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: SIMON CANTU  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**C/C WELDING (Continued)**

**S104748600**

Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-2585

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37 A & D AUTOBODY AND FRAME  
 1868 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104750848  
 N/A**

San Diego Co. HMMD:

Facility ID:	125961
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1868 NATIONAL AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	CAL00043245
Gas Station:	Not reported
Inspection Date:	07/24/92
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	HUGO ALVAREZ
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	SEGAWA JERRY
Property Address:	1864 NATIONAL AVE
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-232-8975

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A & D AUTOBODY AND FRAME (Continued)**

**S104750848**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**URBAN CORPS OF SAN DIEGO  
 1864 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104746214  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303098  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-02-12 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**URBAN CORPS OF SAN DIEGO (Continued)**

**S104746214**

Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05615-001  
 Case Number: 9UT851  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMMD:**

Facility ID: 105615  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1864 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAL000027724  
 Gas Station: Not reported  
 Inspection Date: 10/07/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**URBAN CORPS OF SAN DIEGO (Continued)**

**S104746214**

Facility Contact: LORI ORDILLE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SEGAWA JERRY  
 Property Address: 1864 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-235-0137

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT1038-2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: AT1038-1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**URBAN CORPS OF SAN DIEGO (Continued)**

**S104746214**

Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H05615-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/12/1988  
 Begandt: 11/25/1987

37

**BETTENCOURT AUTO BODY  
 1865 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S102425218  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT851  
 Local Agency: San Diego  
 Substance: 0  
 Qty Leaked: 0  
 Date Found: 11/18/1987  
 How Found: Tank Closure  
 Date Stopped: 11/18/1987  
 How Stopped: Remove Contents  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 12/07/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 2/12/88  
 Pilot Program: LOP  
 Local Case: H05615-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 11/23/1987

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BETTENCOURT AUTO BODY (Continued)**

**S102425218**

Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1865 NATIONAL AVE

37

**MAURICIO AND SONS INC  
 1864 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**SWEEPS UST**

**S106929218  
 N/A**

SWEEPS UST:  
 Status: Not reported  
 Comp Number: 5615  
 Number: Not reported  
 Board Of Equalization: 44-022252  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005615-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 5615  
 Number: Not reported  
 Board Of Equalization: 44-022252  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005615-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**37 SDCTY FIRE STATION 7 HAZNET S108220029**  
**944 CESAR E CHAVEZ PKWY N/A**  
**SAN DIEGO, CA 92113**

HAZNET:

Gepaid: CAL000290022  
 Contact: MIKE FLEMING FMO  
 Telephone: 8585731444  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3870 KEARNY VILLA RD  
 Mailing City,St,Zip: SAN DIEGO, CA 92123  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Transfer Station  
 Tons: 0.02  
 Facility County: Not reported

Gepaid: CAL000290022  
 Contact: MIKE FLEMING FMO  
 Telephone: 8585731444  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3870 KEARNY VILLA RD  
 Mailing City,St,Zip: SAN DIEGO, CA 92123  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Treatment, Incineration  
 Tons: 0.02  
 Facility County: San Diego

**37 ACE RADIATOR RCRA-SQG 1000129371**  
**1854 NATIONAL AVE FINDS CAD029098563**  
**SAN DIEGO, CA 92113 HAZNET**  
**San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: ACE RADIATOR  
 Facility address: 1854 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD029098563  
 Mailing address: NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR (Continued)**

**1000129371**

hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: DON N OLESON, INC  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD029098563

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR (Continued)**

**1000129371**

Contact: DON OLESON  
 Telephone: 7142338811  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1854 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals  
 (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt,  
 copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium,  
 vanadium, and zinc)  
 Disposal Method: Transfer Station  
 Tons: .2085  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 113567  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1854 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAD029098563  
 Gas Station: Not reported  
 Inspection Date: 12/01/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DON N OLESON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GINGLARDY FAMILY TRUST 12-14-8  
 Property Address: 8108 DORCHESTER ST  
 Property City,St,Zip: 91977  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-8811

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR (Continued)**

**1000129371**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 132437  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1601 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAL000003203  
 Gas Station: Not reported  
 Inspection Date: 10/09/91

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR (Continued)**

**1000129371**

Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: BILL BANER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GINGLARDY FAMILY TRUST 12-14-8  
 Property Address: 8108 DORCHESTER ST  
 Property City,St,Zip: 91977  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-7579

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR (Continued)**

**1000129371**

Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**RICARDO'S FLEET SERVICE  
 1841 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103547297  
 N/A**

HAZNET:

Gepaid: CAL000188849  
 Contact: THOMAS LUCIANO  
 Telephone: 6192348801  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1841 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.12  
 Facility County: San Diego

Gepaid: CAL000188849  
 Contact: T.LUCIANO/R GUERREA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1841 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 0.1042  
 Facility County: San Diego

37

**AVISE INC.  
 1841 NATIONAL AVE  
 SAN DIEGO, CA 92112**

**HIST UST U001572959  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000069082  
 Facility Type: Other  
 Other Type: FORMER CUSTOMER  
 Total Tanks: 0001  
 Contact Name: Not reported  
 Telephone: 7132415614  
 Owner Name: SHELL OIL COMPANY  
 Owner Address: 900 LOUISIANA STREET

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AVISE INC. (Continued)**

**U001572959**

Owner City,St,Zip: HOUSTON, TX 77001  
 Tank Num: 001  
 Container Num: 210201  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: WASTE  
 Type of Fuel: 2  
 Tank Construction: Unkown centimeters  
 Leak Detection: None

37

**RICARDO'S FLEET SERVICE  
 1841 NATIONAL AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104749029  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 119511  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1841 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000188849  
 Gas Station: Not reported  
 Inspection Date: 11/17/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: TOM LUCIANO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/17/05  
 Facility Phone: 619-234-8801

**HMMD DISCLOSURE INVENTORY:**

Item Number: OI09  
 Chemical Name: OIL; LUBRICATING  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**RICARDO'S FLEET SERVICE (Continued)**

**S104749029**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/08/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 8237  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5172  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0212  
 Occurrences: Not reported  
 Item Number: 5173  
 Violation Desc: INCOMPATIBLE WASTE NOT SEPARATED

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5174  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 5175  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 5176  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 11/17/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RICARDO'S FLEET SERVICE (Continued)**

**S104749029**

Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6141  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 11/17/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 440  
 Quantity String: 440  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 11/17/03  
 Waste Item #: 351  
 Waste Code: 351  
 Waste Name: ORGANIC SOLIDS WITH  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 CODE BLANK  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 11/17/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: INTERSTATE BATTERIES  
 Carcinogen: No

Inspection Date: 11/17/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 100

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RICARDO'S FLEET SERVICE (Continued)**

**S104749029**

Quantity String: 100  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: VORTEX  
 Carcinogen: No

37

**ACE RADIATOR SERVICE  
 1836 NATIONAL AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104749146  
 N/A**

San Diego Co. HMMD:

Facility ID: 119716  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1836 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000160453  
 Gas Station: Not reported  
 Inspection Date: 01/25/05  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: CHANEY SILVA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: OLESON DON N&DEETTE TRS  
 Property Address: 1836 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/25/06  
 Facility Phone: 619-233-8811

HMMD DISCLOSURE INVENTORY:

Item Number: AR16  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR SERVICE (Continued)**

**S104749146**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: HO17  
 Chemical Name: HOT TANK CLEANING SOLUTION  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 05/24/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 6048  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: 01/25/05  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 3871 THERMO FLUIDS INC.  
 Waste Desc: ANTIFREEZE - WASTE & RECY  
 Carcinogen: No

Inspection Date: 01/25/05  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 2400  
 Quantity String: 2400  
 Annual Qty: 4800  
 Annual Qty String: 4800



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR SERVICE (Continued)**

**S104749146**

Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1600 NATIONAL RESOURCES I  
 Waste Desc: SUMP SLUDGE/SANDBLST MEDI  
 Carcinogen: No

37

**ACE RADIATOR  
 1836 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100731004  
 N/A**

HAZNET:

Gepaid: CAL000160453  
 Contact: CHANEY L SILVA, PRESIDENT  
 Telephone: 6192338811  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1836 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 1  
 Facility County: Not reported

Gepaid: CAL000160453  
 Contact: DON OLESON  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1836 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD089446710  
 TSD County: Los Angeles  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Transfer Station  
 Tons: 1.1500  
 Facility County: San Diego

Gepaid: CAL000160453  
 Contact: DON OLESON  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1836 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 1  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE RADIATOR (Continued)**

**S100731004**

Gepaid: CAL000160453  
 Contact: DON OLESON  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1836 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 1.41  
 Facility County: Not reported

Gepaid: CAL000160453  
 Contact: CHANEY L SILVA, PRESIDENT  
 Telephone: 6192338811  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1836 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: 1.2  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 12 additional CA\_HAZNET: record(s) in the EDR Site Report.

37

**FRASER'S BOILER SERVICE INC**  
**1746 NEWTON AVE**  
**SAN DIEGO, CA 92113**

**HAZNET S100862505**  
**N/A**

HAZNET:

Gepaid: CAL000020343  
 Contact: FRASERS BOILER SERVICE INC  
 Telephone: 6192330195  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13186  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Liquids with lead > 500 mg/l  
 Disposal Method: Recycler  
 Tons: 1.3761  
 Facility County: San Diego

Gepaid: CAL000020343  
 Contact: FRASERS BOILER SERVICE INC  
 Telephone: 6192330195  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FRASER'S BOILER SERVICE INC (Continued)**

**S100862505**

Mailing Address: PO BOX 13186  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 1.8348  
 Facility County: San Diego

Gepaid: CAL000020343  
 Contact: FRASERS BOILER SERVICE INC  
 Telephone: 6192330195  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13186  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Recycler  
 Tons: .5212  
 Facility County: San Diego

Gepaid: CAL000020343  
 Contact: FRASERS BOILER SERVICE INC  
 Telephone: 6192330195  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13186  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAL080033681  
 TSD County: 0  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Not reported  
 Tons: .5212  
 Facility County: San Diego

Gepaid: CAL000020343  
 Contact: FRASERS BOILER SERVICE INC  
 Telephone: 6192330195  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13186  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .1251  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASER'S BOILER SERVICE INC (Continued)**

**S100862505**

[Click this hyperlink](#) while viewing on your computer to access  
 13 additional CA\_HAZNET: record(s) in the EDR Site Report.

37

**FRASER'S BOILER SERVICE, INC.  
 1746 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HIST UST  
 SWEEPS UST**

**U001572982  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000011524  
 Facility Type: Other  
 Other Type: GOV'T SHIP REPAIR  
 Total Tanks: 0001  
 Contact Name: Not reported  
 Telephone: 6192330195  
 Owner Name: FRASER'S BOILER SERVICE, INC.  
 Owner Address: 1746 NEWTON AVE.  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: #1  
 Year Installed: Not reported  
 Tank Capacity: 00000574  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Not reported

SWEEPS UST:

Status: Not reported  
 Comp Number: 16508  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-016508-000001  
 Actv Date: Not reported  
 Capacity: 574  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 16508  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASER'S BOILER SERVICE, INC. (Continued)**

**U001572982**

Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

37

**FRASER'S BOILER SERVICE, INC.  
 1746 NEWTON AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S105033343  
 N/A**

LUST:

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608138959  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1986-06-23 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASER'S BOILER SERVICE, INC. (Continued)**

**S105033343**

Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16508-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 116508  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1746 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000020343  
 Gas Station: Not reported  
 Inspection Date: 09/29/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ANDY MACIAS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: P O BOX 676007  
 Property City,St,Zip: 92067  
 Tank Owner: FRASER'S BOILER SERVICE, INC.  
 Tank Address: 1746 NEWTON AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/29/05  
 Facility Phone: 619-233-0195

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC06  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FRASER'S BOILER SERVICE, INC. (Continued)**

**S105033343**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR10  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: AR12  
 Chemical Name: ARGON/CO2/HELIUM  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CA13  
 Chemical Name: CARDON DIOXIDE  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CO05  
 Chemical Name: COMPRESSED OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASER'S BOILER SERVICE, INC. (Continued)**

**S105033343**

Item Number: NI11  
 Chemical Name: NITROGEN  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: PR07  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: #1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 11/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 9680  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 11/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 9681  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 03/08/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 2281  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 03/08/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FRASER'S BOILER SERVICE, INC. (Continued)**

**S105033343**

Item Number: 2282  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/08/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2283  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/08/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 2284  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5846  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 5847  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5848  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 5849  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5850  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 5851

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FRASER'S BOILER SERVICE, INC. (Continued)**

**S105033343**

Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

Inspection Date: 09/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 4470  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 09/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 4471  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 09/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4472  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 09/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 4473  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 09/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 4474  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 09/29/03  
 Waste Item #: 111  
 Waste Code: 111  
 Waste Name: ACID SOL'N WITH META  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: 5 GAL ACID DIP  
 Carcinogen: No

Inspection Date: 09/29/03  
 Waste Item #: 112  
 Waste Code: 112  
 Waste Name: ACID SOL'N W/OUT MET

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASER'S BOILER SERVICE, INC. (Continued)**

**S105033343**

Qty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 3635 KEM  
 Waste Desc: HYDROCHLORICE ACID  
 Carcinogen: No

Inspection Date: 09/29/03  
 Waste Item #: 172  
 Waste Code: 172  
 Waste Name: METAL DUST & MACHINI  
 Qty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: INVALID CODE  
 Haz Waste Hauler: 2091 PACIFIC TREATMENT CO  
 Waste Desc: SANDBLAST WASTE  
 Carcinogen: No

Inspection Date: 09/29/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 150  
 Quantity String: 150  
 Annual Qty: 160  
 Annual Qty String: 160  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: 2 DRUMS  
 Carcinogen: No

Inspection Date: 09/29/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qty at Inspection: 320  
 Quantity String: 320  
 Annual Qty: 320  
 Annual Qty String: 320  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 3635 KEM  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 09/29/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASER'S BOILER SERVICE, INC. (Continued)**

**S105033343**

Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 400  
 Quantity String: 400  
 Annual Qty: 250  
 Annual Qty String: 250  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H16508-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 6/23/1986  
 Begandt: 5/30/1986

37

**CITY OF SAN DIEGO  
 1880 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET S107139845  
 N/A**

**HAZNET:**

Gepaid: CAC002561474  
 Contact: DENNIS BRAND/ENVIRON INSPECTOR  
 Telephone: 8585731264  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 9601 RIDGEHEAVEN CT #320  
 Mailing City,St,Zip: SAN DIEGO, CA 92123  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: San Diego  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.25  
 Facility County: San Diego

37

**D'ARCH ENTERPRISES  
 1879 LOGAN AV  
 SAN DIEGO, CA 92113**

**LUST S104747229  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**D'ARCH ENTERPRISES (Continued)**

**S104747229**

Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303041  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-12-24 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H12222-001  
 Case Number: 9UT789  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**D'ARCH ENTERPRISES (Continued)**

**S104747229**

San Diego Co. HMMD:

Facility ID:	112222
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1037 BROADWAY A
Mailing City,St,Zip:	CHULA VISTA, CA 92101
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	12/15/87
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	Not reported
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	AYYAD ANDREW C&MAUREEN
Property Address:	1838 CHALCEDONY ST
Property City,St,Zip:	92109
Tank Owner:	E-Z SERVE OF CALIFORNIA INC
Tank Address:	P O BOX 3550
Tank City,St,Zip:	Ontario, CA 91761
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-234-0792

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	T001
Tank ID Number:	1
Waste or Product:	Not reported
Tank Contents:	LEADED
Tank Number:	T002
Tank ID Number:	2

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**D'ARCH ENTERPRISES (Continued)**

**S104747229**

Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T004  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T005  
 Tank ID Number: SUMP-EXEMP  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203351  
 Inactive Indicator: Active  
 Business Code: 6HK15  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1885 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**D'ARCH ENTERPRISES (Continued)**

**S104747229**

EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: AYYAD ANDREW C&MAUREEN  
 Property Address: 1838 CHALCEDONY ST  
 Property City,St,Zip: 92109  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-0096

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**D'ARCH ENTERPRISES (Continued)**

**S104747229**

Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H12222-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/24/1987  
 Begandt: 8/18/1987

37

**CROSBY SQUARE CHIROPRACTIC  
 1879 LOGAN AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S106066002  
 N/A**

San Diego Co. HMMD:

Facility ID: 139466  
 Inactive Indicator: Active  
 Business Code: 6HK15  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1879 LOGAN AV, # D  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/27/03  
 Reinspection Date: Not reported  
 Inspector Name: SESPIRIEH  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVEN RIGLER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: AYYAD ANDREW C&MAUREEN  
 Property Address: 1838 CHALCEDONY ST  
 Property City,St,Zip: 92109  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

**CROSBY SQUARE CHIROPRACTIC (Continued)**

**S106066002**

Facility Phone: 619-238-0096

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
Chemical Name: Not reported  
Case Number: Not reported  
Quantity Stored At One Time: Not reported  
Quantity Stored at One Time: Not reported  
Annual Quantity String: Not reported  
Annual Quantity String: Not reported  
Measurement Units: Not reported  
Carcinogen: No  
1st Hazard Category: Not reported  
2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
Tank ID Number: Not reported  
Waste or Product: Not reported  
Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
Waste Code: Not reported  
Type of Violation: Not reported  
Occurrences: Not reported  
Item Number: Not reported  
Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
Waste Item #: Not reported  
Waste Code: Not reported  
Waste Name: Not reported  
Qty at Inspection: Not reported  
Quantity String: Not reported  
Annual Qty: Not reported  
Annual Qty String: Not reported  
Measurement Unit: Not reported  
Treatment Method: Not reported  
Storage Method: Not reported  
Haz Waste Hauler: Not reported  
Waste Desc: Not reported  
Carcinogen: No

37

**MOBIL SERVICE STATION  
1879 LOGAN AVE  
SAN DIEGO, CA 92113**

**LUST S102433751  
Cortese N/A  
SWEEPS UST**

**LUST:**

Region: 9  
Case Number: 9UT789  
Local Agency: San Diego  
Substance: 0  
Qty Leaked: 0  
Date Found: 08/08/1987

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL SERVICE STATION (Continued)**

**S102433751**

How Found: Tank Closure  
 Date Stopped: 08/18/1987  
 How Stopped: Remove Contents  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 08/27/1987  
 Desc Pollution: Not reported  
 Remed Plan: 12/17/1987  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/24/87  
 Pilot Program: LOP  
 Local Case: H12222-001  
 Basin Number: 908.31  
 Gwater Depth: >8'  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 08/20/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 1879 LOGAN AVE

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 12222  
 Number: Not reported  
 Board Of Equalization: 44-017430  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012222-000001  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 4  
  
 Status: Not reported  
 Comp Number: 12222

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL SERVICE STATION (Continued)**

**S102433751**

Number: Not reported  
 Board Of Equalization: 44-017430  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012222-000002  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 12222  
 Number: Not reported  
 Board Of Equalization: 44-017430  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012222-000003  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 12222  
 Number: Not reported  
 Board Of Equalization: 44-017430  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012222-000004  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 12222  
 Number: 9  
 Board Of Equalization: 44-017430  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL SERVICE STATION (Continued)**

**S102433751**

Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012222-000005  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: CHEMICAL  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: 1

37

**MOBIL STATION #139  
 1879 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HIST UST U001572990  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000019540  
 Facility Type: Gas Station  
 Other Type: Not reported  
 Total Tanks: 0005  
 Contact Name: NGUYEN HUN DUE  
 Telephone: 6192340792  
 Owner Name: E-Z SERVE OF CALIFORNIA, INC.  
 Owner Address: P.O. BOX 3550  
 Owner City,St,Zip: ONTARIO, CA 91761

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: 1/4 inches  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: PREMIUM  
 Tank Construction: 1/4 inches  
 Leak Detection: Stock Inventor

Tank Num: 004  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00000550  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL STATION #139 (Continued)**

**U001572990**

Tank Construction: 12 gauge  
 Leak Detection: Not reported  
  
 Tank Num: 005  
 Container Num: 5  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Visual

37

**LOGAN HEIGHTS FAMILY HEALTH CT  
 1809 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104748251  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608106734  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-01-16 00:00:00  
 Discover Date: 1991-08-28 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-08-28 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: KATHY FLORES  
 RP Address: 1809 NATIONAL AV  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LOGAN HEIGHTS FAMILY HEALTH CT (Continued)**

**S104748251**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14412-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 114412  
 Inactive Indicator: Active  
 Business Code: 6HK58  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1809 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000098710  
 Gas Station: Not reported  
 Inspection Date: 05/17/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JANET ADAMIAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FAMILY HEALTH CENTERS OF SAN D  
 Property Address: 823 GATEWAY CENTER W  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/17/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LOGAN HEIGHTS FAMILY HEALTH CT (Continued)**

**S104748251**

Facility Phone: 619-234-8171

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/25/98  
 Waste Code: Not reported  
 Type of Violation: 6HX4104  
 Occurrences: Not reported  
 Item Number: 6888  
 Violation Desc: MED SOLID WSTE NOT IN LOCKED DUMPSTER

Inspection Date: 11/19/99  
 Waste Code: Not reported  
 Type of Violation: 6HX4113  
 Occurrences: Not reported  
 Item Number: 0478  
 Violation Desc: NO GENERATOR'S LABEL IN SHARPS & RED BAG

**HMMD WASTE STREAMS:**

Inspection Date: 05/17/04  
 Waste Item #: 541  
 Waste Code: 541  
 Waste Name: PHOTOCHEM/PHOTOPROC  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESS EQUIPMENT  
 Haz Waste Hauler: 4092 PATTERSON DENTAL SUP  
 Waste Desc: DENTAL CLINIC 2ND FLOOR  
 Carcinogen: No

Inspection Date: 05/17/04  
 Waste Item #: 860  
 Waste Code: 860  
 Waste Name: UNIVERSAL WASTE CRTS



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LOGAN HEIGHTS FAMILY HEALTH CT (Continued)**

**S104748251**

Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 3  
 Annual Qty String: 3  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 05/17/04  
 Waste Item #: 901  
 Waste Code: 901  
 Waste Name: INFECTIOUS WASTE, GE  
 Qty at Inspection: 75  
 Quantity String: 75  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BAG  
 Haz Waste Hauler: 3400 STERICYCLE INC.  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 05/17/04  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH  
 Qty at Inspection: 90  
 Quantity String: 90  
 Annual Qty: 5000  
 Annual Qty String: 5000  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BOX  
 Haz Waste Hauler: 3400 STERICYCLE INC.  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 05/17/04  
 Waste Item #: 905  
 Waste Code: 905  
 Waste Name: INFECTIOUS WASTE, LA  
 Qty at Inspection: 12  
 Quantity String: 12  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BOX  
 Haz Waste Hauler: 3400 STERICYCLE INC.  
 Waste Desc: CULTURE PLATES  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LOGAN HEIGHTS FAMILY HEALTH CT (Continued)**

**S104748251**

SAN DIEGO CO. SAM:

Case Number: H14412-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/16/1992  
 Begandt: 8/28/1991

37

**LOGAN HEIGHTS FAMILY HEALTH CENTER  
 1809 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103637153  
 N/A**

HAZNET:

Gepaid: CAL000098710  
 Contact: LOGAN HEIGHTS FAMILY HEALTH  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1809 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921132113  
 Gen County: San Diego  
 TSD EPA ID: CAD982049306  
 TSD County: San Diego  
 Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals  
 (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt,  
 copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium,  
 vanadium, and zinc)

Disposal Method: Recycler  
 Tons: .0050  
 Facility County: San Diego

Gepaid: CAL000098710  
 Contact: LOGAN HEIGHTS FAMILY HEALTH  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1809 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921132113  
 Gen County: San Diego  
 TSD EPA ID: CAD981402522  
 TSD County: Kern

Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals  
 (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt,  
 copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium,  
 vanadium, and zinc)

Disposal Method: Not reported  
 Tons: .0060  
 Facility County: San Diego

Gepaid: CAL000098710  
 Contact: LOGAN HEIGHTS FAMILY HEALTH  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1809 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921132113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LOGAN HEIGHTS FAMILY HEALTH CENTER (Continued)**

**S103637153**

Gen County: San Diego  
 TSD EPA ID: CAL920973155  
 TSD County: San Diego  
 Waste Category: Photochemicals/photoprocessing waste  
 Disposal Method: Recycler  
 Tons: .0458  
 Facility County: San Diego

Gepaid: CAL000098710  
 Contact: LOGAN HEIGHTS FAMILY HEALTH  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1809 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921132113  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .0025  
 Facility County: San Diego

Gepaid: CAL000098710  
 Contact: LOGAN HEIGHTS FAMILY HEALTH  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1809 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921132113  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: .0667  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

37

**TRIAD MARINE & INDUSTRIAL CLEANING CORP  
 1775 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100725198  
 N/A**

HAZNET:  
 Gepaid: CAD981965734  
 Contact: TRIAD MARINE AND INDUSTRIAL CL  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1775 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD MARINE & INDUSTRIAL CLEANING CORP (Continued)**

**S100725198**

Tons: .4587  
 Facility County: San Diego  
  
 Gepaid: CAD981965734  
 Contact: TRIAD MARINE AND INDUSTRIAL CL  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1775 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)  
 Disposal Method: Transfer Station  
 Tons: .4587  
 Facility County: San Diego

Gepaid: CAD981965734  
 Contact: TRIAD MARINE AND INDUSTRIAL CL  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1775 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 8.7570  
 Facility County: San Diego

Gepaid: CAD981965734  
 Contact: JOHN DRUMEL  
 Telephone: 6192392025  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1775 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)  
 Disposal Method: Recycler  
 Tons: 2.29  
 Facility County: Not reported

Gepaid: CAD981965734  
 Contact: JOHN DRUMEL  
 Telephone: 6192392025  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1775 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD MARINE & INDUSTRIAL CLEANING CORP (Continued)**

**S100725198**

Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Other  
 Tons: 0.1  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access 15 additional CA\_HAZNET: record(s) in the EDR Site Report.

37

**TRIAD ENVIRONMENTAL SYSTEMS  
 1775 NATIONAL AVENUE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000145166  
 FINDS CAD981965734  
 San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 11/06/2001  
 Facility name: TRIAD ENVIRONMENTAL SYSTEMS INC  
 Facility address: 1775 NATIONAL AVE  
 SAN DIEGO, CA 921131010  
 EPA ID: CAD981965734  
 Contact: MATT CARR  
 Contact address: 1775 NATIONAL AVE  
 SAN DIEGO, CA 921131010  
 Contact country: US  
 Contact telephone: (619) 239-2024  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: MATT CARR  
 Owner/operator address: 1775 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 239-2024  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD ENVIRONMENTAL SYSTEMS (Continued)**

**1000145166**

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 04/14/1990  
 Facility name: TRIAD ENVIRONMENTAL SYSTEMS INC  
 Site name: TRIAD MARINE  
 Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003  
 Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD ENVIRONMENTAL SYSTEMS (Continued)**

**1000145166**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

San Diego Co. HMMD:

Facility ID:	100123
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1775 NATIONAL AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	51
EPA ID:	CAD981965734
Gas Station:	Not reported
Inspection Date:	08/20/02
Reinspection Date:	Not reported
Inspector Name:	LWIRSCHE
Violation Notice Issued:	Not reported
Facility Contact:	PETE MORALES
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	R&H PROPERTIES L P
Property Address:	78273 BIRKDALE CT
Property City,St,Zip:	92253
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-239-2024

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD ENVIRONMENTAL SYSTEMS (Continued)**

**1000145166**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3374  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3375  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 04/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3373  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**TRIAD ENVIRONMENTAL SYSTEMS  
 1775 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106070853  
 N/A**

San Diego Co. HMMD:

Facility ID: 200750  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD ENVIRONMENTAL SYSTEMS (Continued)**

**S106070853**

2nd Name: Not reported  
 Mailing Address: 1775 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD981965734  
 Gas Station: Not reported  
 Inspection Date: 10/11/02  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-2024

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 2691  
 Violation Desc: HMBP NOT SUBMITTED TO HMD  
  
 Inspection Date: 09/27/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD ENVIRONMENTAL SYSTEMS (Continued)**

**S106070853**

Waste Code: Not reported  
 Type of Violation: 6HV1001  
 Occurrences: Not reported  
 Item Number: 2692  
 Violation Desc: NO UPF PERMIT FOR HAZMATS

Inspection Date: 09/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2693  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 09/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 2694  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 09/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 2695  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**YE OLDE TOWN PUMP  
 1792 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104745699  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YE OLDE TOWN PUMP (Continued)**

**S104745699**

Leak Source: Not reported  
 Global Id: T0607302843  
 Stop Date: 1988-11-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-09-12 00:00:00  
 Discover Date: 1988-11-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-11-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: FRITZ AHERN  
 RP Address: 5652 STRESEMANN ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: SP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03488-001  
 Case Number: 9UT554  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YE OLDE TOWN PUMP (Continued)**

**S104745699**

San Diego Co. HMMD:

Facility ID: 103488  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 931 PARAIISO AVE.  
 Mailing City,St,Zip: SPRING VALLEY, CA 91977  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000213957  
 Gas Station: Not reported  
 Inspection Date: 08/14/03  
 Reinspection Date: Not reported  
 Inspector Name: MNYAGA  
 Violation Notice Issued: Not reported  
 Facility Contact: DAGO ARIAS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: AHERN FRITZ C&SUSANA  
 Property Address: 418 3RD AVE  
 Property City,St,Zip: 92101  
 Tank Owner: SERGIO ESPARZA  
 Tank Address: 1792 NATIONAL AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/14/05  
 Facility Phone: 619-239-1684

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: T001  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: #2

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YE OLDE TOWN PUMP (Continued)**

**S104745699**

Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: #1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 12/02/88  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 6881  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 05/22/00  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 5371  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 05/22/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5372  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/28/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 0241  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 08/14/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 08/14/03  
 Waste Item #: 221  
 Waste Code: 221

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YE OLDE TOWN PUMP (Continued)**

**S104745699**

Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 08/14/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qty at Inspection: 150  
 Quantity String: 150  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 08/14/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H03488-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/12/1989  
 Begandt: 11/24/1988

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37 DIESEL CENTER  
 1792 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HIST UST U001572975  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000057816  
 Facility Type: Gas Station  
 Other Type: Not reported  
 Total Tanks: 0003  
 Contact Name: Not reported  
 Telephone: 6194535359  
 Owner Name: FRITZ AHERN  
 Owner Address: 5652 STRESEMANN  
 Owner City,St,Zip: SAN DIEGO, CA 92122

Tank Num: 001  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002  
 Container Num: #2  
 Year Installed: Not reported  
 Tank Capacity: 00000800  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 003  
 Container Num: #1  
 Year Installed: 1964  
 Tank Capacity: 00000800  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: None

**37 THE DIESEL CENTER  
 1792 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S102438868  
 Cortese N/A  
 SWEEPS UST**

LUST:

Region: 9  
 Case Number: 9UT554  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: 0  
 Date Found: 11/21/1986  
 How Found: Other Means  
 Date Stopped: 11/24/1988  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE DIESEL CENTER (Continued)**

**S102438868**

Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 11/24/1988  
 Submit Workplan: Not reported  
 Prelim Assess: 02/04/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 9/12/89  
 Pilot Program: LOP  
 Local Case: H03488-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 11/21/1986  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 1792 NATIONAL AVE

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 3488  
 Number: Not reported  
 Board Of Equalization: 44-021872  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003488-000001  
 Actv Date: Not reported  
 Capacity: 150  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 3488  
 Number: Not reported  
 Board Of Equalization: 44-021872  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE DIESEL CENTER (Continued)**

**S102438868**

Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003488-000002  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3488  
 Number: Not reported  
 Board Of Equalization: 44-021872  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003488-000003  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3488  
 Number: 9  
 Board Of Equalization: 44-021872  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

37

**TROPIC ICE CREAM CO  
 1776 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104745710  
 N/A**

LUST:

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TROPIC ICE CREAM CO (Continued)**

**S104745710**

Global Id: T0607300611  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-06-18 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: ATTN: MS. TAMARA HOWARD  
 RP Address: P.O. BOX X-1013  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: ML  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03524-001  
 Case Number: 9UT1822  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMID:  
 Facility ID: 103524

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TROPIC ICE CREAM CO (Continued)**

**S104745710**

Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1776 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/26/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MARK MATHEWSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WILLIAMS RICK TR  
 Property Address: P O BOX 1147  
 Property City,St,Zip: 91903  
 Tank Owner: HOWARD BROCKMAN  
 Tank Address: 1776 NATIONAL AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-5584

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED  
  
 Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TROPIC ICE CREAM CO (Continued)**

**S104745710**

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T004  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/26/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 7233  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 01/26/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0084  
 Occurrences: Not reported  
 Item Number: 7234  
 Violation Desc: UST PRECISION TEST DATA NOT SENT TO HMMD

Inspection Date: 11/28/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0031  
 Occurrences: Not reported  
 Item Number: 6878  
 Violation Desc: NO HAZWASTE DISPOSAL RECEIPTS

Inspection Date: 11/28/88  
 Waste Code: Not reported  
 Type of Violation: 6HX3002  
 Occurrences: Not reported  
 Item Number: 6879  
 Violation Desc: UST OWNR-OPR W/O HEALTH PERMIT

Inspection Date: 11/28/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0031  
 Occurrences: Not reported  
 Item Number: 6880  
 Violation Desc: NO HAZWASTE DISPOSAL RECEIPTS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TROPIC ICE CREAM CO (Continued)**

**S104745710**

Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H03524-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Drinking Water Aquifer Impacted  
 FStatus: Closed Case  
 Date: 6/18/1996  
 Begandt: 6/7/1990

37

**TROPIC ICE CREAM  
 1776 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S100233011  
 Cortese N/A  
 SWEEPS UST**

**LUST:**

Region: 9  
 Case Number: 9UT1822  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 06/07/1990  
 How Found: Other Means  
 Date Stopped: 06/07/1990  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: / /  
 Submit Workplan: 9/26/90  
 Prelim Assess: 10/23/1992  
 Desc Pollution: Not reported  
 Remed Plan: 10/24/1991  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 6/18/96  
 Pilot Program: LOP  
 Local Case: H03524-001  
 Basin Number: 908.22  
 Gwater Depth: 24'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - ADMINISTRATIVE (CLOSURE/SB2004/ENFORCEMENT)  
 File Dispn: File discarded, case closed  
 Release Date: 06/07/1990  
 Interim Remedial Actions: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TROPIC ICE CREAM (Continued)**

**S100233011**

Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1776 NATIONAL AVE

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 3524  
 Number: Not reported  
 Board Of Equalization: 44-021879  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003524-000001  
 Actv Date: Not reported  
 Capacity: 2500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 4

Status: Not reported  
 Comp Number: 3524  
 Number: Not reported  
 Board Of Equalization: 44-021879  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003524-000002  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3524  
 Number: Not reported  
 Board Of Equalization: 44-021879  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003524-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TROPIC ICE CREAM (Continued)**

**S100233011**

Content: LEADED  
 Number Of Tanks: Not reported  
  
 Status: Not reported  
 Comp Number: 3524  
 Number: Not reported  
 Board Of Equalization: 44-021879  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003524-000004  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

37

**CEMENT CUTTING INC  
 1845 LOGAN AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104745266  
 N/A**

San Diego Co. HMMD:

Facility ID: 101308  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1845 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000036110  
 Gas Station: Not reported  
 Inspection Date: 07/27/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: HAROLD GRAFTON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DOYLE DANIEL&JENNIFER M  
 Property Address: 2515 HORTON AVE  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CEMENT CUTTING INC (Continued)**

**S104745266**

Facility Phone: 619-231-1735

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 202697  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1845 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CEMENT CUTTING INC (Continued)**

**S104745266**

Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000234846  
 Gas Station: Not reported  
 Inspection Date: 11/12/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DANIEL DOYLE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DOYLE DANIEL&JENNIFER M  
 Property Address: 2515 HORTON AVE  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/12/05  
 Facility Phone: 619-233-7809

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 11/12/03  
 Waste Item #: 461  
 Waste Code: 461

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CEMENT CUTTING INC (Continued)**

**S104745266**

Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 15  
 Annual Qty String: 15  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: BOOTH FILTERS  
 Carcinogen: No

37

**MINI TRUCK DISMANTLING  
 1700 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100940129  
 N/A**

HAZNET:

Gepaid: CAL000037162  
 Contact: MARTINEZ MARION  
 Telephone: 6192333884  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1700 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131014  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: .4400  
 Facility County: San Diego

Gepaid: CAL000037162  
 Contact: MARTINEZ MARION  
 Telephone: 6192333884  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1700 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131014  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Organic liquids (nonsolvents) with halogens  
 Disposal Method: Transfer Station  
 Tons: .1100  
 Facility County: San Diego

Gepaid: CAL000037162  
 Contact: MARTINEZ MARION  
 Telephone: 6192333884  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1700 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131014  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MINI TRUCK DISMANTLING (Continued)**

**S100940129**

Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: .5500  
 Facility County: San Diego

Gepaid: CAL000037162  
 Contact: GINA THOLE OFFICE MANAGER  
 Telephone: 6192333884  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1700 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131014  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.30  
 Facility County: Not reported

Gepaid: CAL000037162  
 Contact: GINA THOLE OFFICE MANAGER  
 Telephone: 6192333884  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1700 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131014  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: 0.30  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 7 additional CA\_HAZNET: record(s) in the EDR Site Report.

37

**MINI TRUCK  
 1700 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104746993  
 CA WDS N/A**

San Diego Co. HMMD:  
 Facility ID: 110737  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1700 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000037162  
 Gas Station: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MINI TRUCK (Continued)**

**S104746993**

Inspection Date: 06/19/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MARION MARTINEZ-MOON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GUZMAN MARIA D L A  
 Property Address: 5711 ALBEMARLE ST  
 Property City,St,Zip: 92139  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 12/19/04  
 Facility Phone: 619-233-3884

**HMMD DISCLOSURE INVENTORY:**

Item Number: OX62  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/18/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 6582  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 02/03/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 2423  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 11/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0209

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MINI TRUCK (Continued)**

**S104746993**

Occurrences: Not reported  
 Item Number: 1465  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 11/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1466  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 11/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 1467  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1468  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 11/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0405  
 Occurrences: Not reported  
 Item Number: 1469  
 Violation Desc: AISLE SPACE IS OBSTRUCTED

**HMMD WASTE STREAMS:**

Inspection Date: 06/19/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 170  
 Annual Qty String: 170  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: CLEANING SOLVENTS  
 Carcinogen: No

Inspection Date: 06/19/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 4080  
 Annual Qty String: 4080  
 Measurement Unit: GAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MINI TRUCK (Continued)**

**S104746993**

Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE MOTOR OIL  
 Carcinogen: No

Inspection Date: 06/19/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 600  
 Quantity String: 600  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: CONTAMINATED ABSORBANT  
 Carcinogen: No

Inspection Date: 06/19/03  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE ANTIFREEZE  
 Carcinogen: No

Inspection Date: 06/19/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 155  
 Quantity String: 155  
 Annual Qty: 1860  
 Annual Qty String: 1860  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: SUNCOAST BATTERY  
 Carcinogen: No

Facility ID: 205320  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MINI TRUCK (Continued)**

**S104746993**

Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000037162  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GUZMAN MARIA D L A  
 Property Address: 5711 ALBEMARLE ST  
 Property City,St,Zip: 92139  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-3884

**HMMD DISCLOSURE INVENTORY:**

Item Number: OX37  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MINI TRUCK (Continued)**

**S104746993**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 170  
 Annual Qty String: 170  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: CLEANING SOLVENTS  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 4080  
 Annual Qty String: 4080  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE MOTOR OIL  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 600  
 Quantity String: 600  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: CONTAMINATED ABSORBANT  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MINI TRUCK (Continued)**

**S104746993**

Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE ANTIFREEZE  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 155  
 Quantity String: 155  
 Annual Qty: 1860  
 Annual Qty String: 1860  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: SUNCOAST BATTERY  
 Carcinogen: No

**CA WDS:**

Facility ID: San Diego 371010308  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.

Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.

NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board

Subregion: 9

Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: MARION MARTINEZ  
 Agency Address: 1700 NEWTON AVE  
 Agency City,St,Zip: SAN DIEGO 92113  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MINI TRUCK (Continued)**

**S104746993**

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

37

**ANGEL VILLEGAS  
 1025A SIGSBEE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000203794  
 FINDS CAD982499022**

RCRA-SQG:

Date form received by agency: 02/06/1990  
 Facility name: ANGEL VILLEGAS  
 Facility address: 1025A SIGSBEE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982499022  
 Mailing address: SIGSBEE  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1025A SIGSBEE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 234-0455  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: ANGEL VILLEGAS  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ANGEL VILLEGAS (Continued)**

**1000203794**

Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

37

**CASTELLINI & SONS INC  
 1827 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET S108744212  
 N/A**

**HAZNET:**

Gepaid: CAL000284797  
 Contact: PHILIP CASTELLINI  
 Telephone: 6192395817  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1827 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: KSD980633259  
 TSD County: 99  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: H06  
 Tons: 0.22  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37 KAMAN INDUSTRIAL TECHNOLOGIES  
 1675 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104754406  
 N/A**

San Diego Co. HMMD:

Facility ID: 134400  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1675 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000203498  
 Gas Station: Not reported  
 Inspection Date: 08/27/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: TONY RAHSAZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WINN FAMILY L P  
 Property Address: P O BOX 2487  
 Property City,St,Zip: 92021  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/27/05  
 Facility Phone: 619-233-5311

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**KAMAN INDUSTRIAL TECHNOLOGIES (Continued)**

**S104754406**

**HMMD VIOLATIONS:**

Inspection Date: 10/21/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 8758  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 10/21/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8759  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 08/29/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 8551  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 08/29/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8552  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5905  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 5906  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 5907  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 08/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3594  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KAMAN INDUSTRIAL TECHNOLOGIES (Continued)**

**S104754406**

HMMD WASTE STREAMS:

Inspection Date: 08/27/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 38  
 Annual Qty String: 38  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: ONE UNIT  
 Carcinogen: No

37

**KAMAN IND TECH  
 1675 NEWTON  
 SAN DIEGO, CA 92113**

**HAZNET S103635092  
 N/A**

HAZNET:

Gepaid: CAC001365624  
 Contact: KAMAN IND TECH  
 Telephone: 6192335311  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1675 NEWTON  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .0750  
 Facility County: San Diego

37

**BEECO SAN DIEGO AUTO RECYCLING  
 1674 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104746999  
 N/A**

San Diego Co. HMMD:

Facility ID: 110761  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1674 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BEECO SAN DIEGO AUTO RECYCLING (Continued)**

**S104746999**

Gas Station: Not reported  
 Inspection Date: 07/11/85  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: BOB BEEMAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BEEMAN MARIE TRUST 08-22-90  
 Property Address: 3553 BENTLEY DR  
 Property City,St,Zip: 91977  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-7441

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BEECO SAN DIEGO AUTO RECYCLING (Continued)**

**S104746999**

Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**ACTION CLEANING  
 1668 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103948655  
 N/A**

HAZNET:

Gepaid: CAC001413368  
 Contact: ACTION CLEANING  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1668 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 8.3400  
 Facility County: San Diego

37

**FRASERS BOILER  
 1735 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748493  
 N/A**

San Diego Co. HMMD:

Facility ID: 115778  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 13186  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAL000020343  
 Gas Station: Not reported  
 Inspection Date: 01/31/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: LARRY KELLY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASERS BOILER (Continued)**

**S104748493**

Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: P O BOX 676007  
 Property City,St,Zip: 92067  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-0195

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37 LUBE EQUIPMENT & PUMP SERVICE CO  
 1795 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103636834  
 N/A**

HAZNET:  
 Gepaid: CAC001153336  
 Contact: JAMES KELLY  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1795 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: .4000  
 Facility County: San Diego

**37 LUBE EQUIP. PUMP SERV. CO.  
 178K LOGAN AVE.  
 SAN DIEGO, CA 92113**

**HIST UST 1000196601  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000019501  
 Facility Type: Other  
 Other Type: SERVICE STATION MAIN  
 Total Tanks: 0003  
 Contact Name: Not reported  
 Telephone: 6192343561  
 Owner Name: MECHTRONIC PUMP SERC. INC.  
 Owner Address: 1785 LOGAN AVE.  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1966  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: 3/16" inches  
 Leak Detection: Stock Inventor, None

Tank Num: 002  
 Container Num: 2  
 Year Installed: 1966  
 Tank Capacity: 00000550  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 3/16" inches  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 3  
 Year Installed: 1966  
 Tank Capacity: 00000280  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

**LUBE EQUIP. PUMP SERV. CO. (Continued)**

**1000196601**

Tank Construction: 3/16" inches  
 Leak Detection: Visual, None

**37**

**NORTHWEST PUMP & EQUIPMENT SER  
 1785 LOGAN AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106070450  
 N/A**

San Diego Co. HMMD:

Facility ID:	200308
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1785 LOGAN AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	51
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	04/30/04
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	MARTA PARKER
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	KELLY JAMES F FAMILY TRUST 03-
Property Address:	P O BOX 124663
Property City,St,Zip:	92112
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	10/30/05
Facility Phone:	619-239-2282

HMMD DISCLOSURE INVENTORY:

Item Number:	HE78
Chemical Name:	HELIUM
Case Number:	7440-59-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	PRESSURE RELEASE
2nd Hazard Category:	ACUTE
Item Number:	NI66
Chemical Name:	NITROGEN

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTHWEST PUMP & EQUIPMENT SER (Continued)**

**S106070450**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 6995  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 04/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 6996  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 01/31/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6708  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/31/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 6709  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 01/31/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 6710  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/30/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1011  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTHWEST PUMP & EQUIPMENT SER (Continued)**

**S106070450**

Item Number: 1186  
 Violation Desc: TRAINING RECORDS NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**LUBE EQUIPMENT & PUMP SERVICE  
 1785 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET S106928889  
 SWEEPS UST N/A**

**HAZNET:**

Gepaid: CAC002561512  
 Contact: MARTA PARKER  
 Telephone: 9192392282  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1785 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.1  
 Facility County: San Diego

Gepaid: CAC002561512  
 Contact: MARTA PARKER  
 Telephone: 9192392282  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1785 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: San Diego  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 0.17  
 Facility County: San Diego

Gepaid: CAC002561512  
 Contact: MARTA PARKER

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**LUBE EQUIPMENT & PUMP SERVICE (Continued)**

**S106928889**

Telephone: 9192392282  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1785 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Disposal, Land Fill  
 Tons: Not reported  
 Facility County: San Diego

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 3634  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003634-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 3634  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003634-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3634  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LUBE EQUIPMENT & PUMP SERVICE (Continued)**

**S106928889**

Swrcb Tank Id: 37-000-003634-000003  
 Actv Date: Not reported  
 Capacity: 280  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3634  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

37

**LUBE EQUIPMENT & PUMP SERVICE  
 1785 LOGAN AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104745745  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 103634  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1785 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD981399082  
 Gas Station: Not reported  
 Inspection Date: 01/05/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JEFF JANDURA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KELLY JAMES F FAMILY TRUST 03-  
 Property Address: P O BOX 124663  
 Property City,St,Zip: 92112

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

**LUBE EQUIPMENT & PUMP SERVICE (Continued)**

**S104745745**

Tank Owner: MECHTRONIC PUMP SERVICE INC  
Tank Address: 1785 LOGAN AV  
Tank City,St,Zip: San Diego, CA 92113  
Business Plan Acceptance Date: Not reported  
Reinspection Date Y2K Compatible: Not reported  
Facility Phone: 619-234-3561

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
Chemical Name: Not reported  
Case Number: Not reported  
Quantity Stored At One Time: Not reported  
Quantity Stored at One Time: Not reported  
Annual Quantity String: Not reported  
Annual Quantity String: Not reported  
Measurement Units: Not reported  
Carcinogen: No  
1st Hazard Category: Not reported  
2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
Tank ID Number: 1  
Waste or Product: Not reported  
Tank Contents: REGULAR UNLEADED

Tank Number: T002  
Tank ID Number: 2 HYDRAULI  
Waste or Product: Not reported  
Tank Contents: Not reported

Tank Number: T003  
Tank ID Number: 3  
Waste or Product: Not reported  
Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
Waste Code: Not reported  
Type of Violation: Not reported  
Occurrences: Not reported  
Item Number: Not reported  
Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
Waste Item #: Not reported  
Waste Code: Not reported  
Waste Name: Not reported  
Qnty at Inspection: Not reported  
Quantity String: Not reported  
Annual Qty: Not reported  
Annual Qty String: Not reported  
Measurement Unit: Not reported  
Treatment Method: Not reported  
Storage Method: Not reported



MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

**LUBE EQUIPMENT & PUMP SERVICE (Continued)**

**S104745745**

Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**37**

**1025 SIGSBEE ST.  
 SAN DIEGO, CA 92113**

**Notify 65 S100178402  
 N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92113-1017

**37**

**GEORGES TRANSMISSION  
 1025 SIGSBEE ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104747722  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 113237  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1025 SIGSBEE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000040901  
 Gas Station: Not reported  
 Inspection Date: 08/27/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: GEORGE GUZMAN JR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GUZMAN MARIA D L A  
 Property Address: 5711 ALBEMARLE ST  
 Property City,St,Zip: 92139  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-5688

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GEORGES TRANSMISSION (Continued)**

**S104747722**

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/16/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0046  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/02/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 8554  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 09/02/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8555  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 5480  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5481  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/13/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GEORGES TRANSMISSION (Continued)**

**S104747722**

Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	5482
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	5483
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	5484
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0215
Occurrences:	Not reported
Item Number:	5485
Violation Desc:	OIL FILTERS IMPROPERLY MANAGED
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	5486
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	08/27/03
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	3588
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	08/27/03
Waste Code:	Not reported
Type of Violation:	6HV0210
Occurrences:	Not reported
Item Number:	3589
Violation Desc:	DID NOT CLEAN SPILL TO FLOOR
Inspection Date:	08/27/03
Waste Code:	Not reported
Type of Violation:	6HV0215
Occurrences:	Not reported
Item Number:	3590
Violation Desc:	OIL FILTERS IMPROPERLY MANAGED
Inspection Date:	08/27/03
Waste Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GEORGES TRANSMISSION (Continued)**

**S104747722**

Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3591  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 08/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 3592  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 08/27/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3593  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203137  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1025 SIGSBEE ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/10/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GEORGES TRANSMISSION (Continued)**

**S104747722**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GUZMAN MARIA D L A  
 Property Address: 5711 ALBEMARLE ST  
 Property City,St,Zip: 92139  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/10/05  
 Facility Phone: 619-234-5685

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 03/10/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 15  
 Annual Qty String: 15  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESS EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GEORGES TRANSMISSION (Continued)**

**S104747722**

Inspection Date: 03/10/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: USED OIL  
 Carcinogen: No

37

**ACME AUTO BODY  
 1025 SIGSBEE ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S106061466  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 119290  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1025A SIGSBEE ST #A  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000045724  
 Gas Station: Not reported  
 Inspection Date: 02/06/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ANGEL VILLEGAS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GUZMAN MARIA D L A  
 Property Address: 5711 ALBEMARLE ST  
 Property City,St,Zip: 92139  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-0455

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACME AUTO BODY (Continued)**

**S106061466**

Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**1023 SIGSBEE  
 SAN DIEGO, CA 92123**

**CHMIRS S105669721  
 N/A**

**CHMIRS:**

OES Incident Number: 01-7482  
 OES notification: 12/27/200104:11:05 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105669721

Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: Storm Drain  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2001  
 Agency: City of San Diego  
 Incident Date: 12/27/2001 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Merchant/Business  
 E Date: Not reported  
 Substance: Sewage;;;  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 1  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0



MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**(Continued)**

**S105669721**

Quarts:	0	
Sheen:	0	
Tons:	0	
Unknown:	0.000000	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	Substance was released due to main blockage. Note: 1,000 Gallons was Recovered.	

**37**

**1640 NEWTON AVE  
SAN DIEGO, CA 92113**

**Notify 65 S100178098  
N/A**

Notify 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Incident Description:	92113-1013

**37**

**NATIONAL TRANSMISSION  
1709 NATIONAL AV  
SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106879580  
N/A**

San Diego Co. HMMD:

Facility ID:	204076
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1709 NATIONAL AVE
Mailing City, St, Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	51
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	09/15/04
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	TONY ZARCO
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	KROOSKOS FAMILY TRUST 09-12-01
Property Address:	425 LA CRESTA HEIGHT
Property City, St, Zip:	92021
Tank Owner:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL TRANSMISSION (Continued)**

**S106879580**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/15/06  
 Facility Phone: 619-238-6068

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 4907  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4908  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4909  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 4910  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0207

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL TRANSMISSION (Continued)**

**S106879580**

Occurrences: Not reported  
 Item Number: 4911  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 4912  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 4913  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 4914  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 4915  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1601  
 Occurrences: Not reported  
 Item Number: 4916  
 Violation Desc: HAZWASTE TANKS W/O P.E. ASSESSMENT

Inspection Date: 09/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4917  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 09/15/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 400  
 Quantity String: 400  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL TRANSMISSION (Continued)**

**S106879580**

Storage Method: ABVG TNK  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 09/15/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 600  
 Quantity String: 600  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: OILY ABSORBENT/CONTAMINAT  
 Carcinogen: No

Inspection Date: 09/15/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 12  
 Quantity String: 12  
 Annual Qty: 30  
 Annual Qty String: 30  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 09/15/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EPA ID Number

37 **FBI GARAGE** **HAZNET** **S102812931**  
**1637 NEWTON AVE** **N/A**  
**SAN DIEGO, CA 92113**

HAZNET:  
 Gepaid: CAL000047042  
 Contact: FBI  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 880 FRONT STREET RM6531  
 Mailing City,St,Zip: SAN DIEGO, CA 921880000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

37 **1702 NATIONAL AVE** **Notify 65** **S100178362**  
**SAN DIEGO, CA 92113** **N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92113-1011

37 **SUPER WELDING OF SO. CA., INC.** **SAN DIEGO CO. SAM** **S108407264**  
**1702 NATIONAL AV** **N/A**  
**SAN DIEGO, CA 92123**

SAN DIEGO CO. SAM:  
 Case Number: H16472-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/28/2006  
 Begandt: Not reported

37 **SIGSBEE ROW HOMES LLC** **HAZNET** **S108755191**  
**1702 NATIONAL AVE** **N/A**  
**SAN DIEGO, CA 92113**

HAZNET:  
 Gepaid: CAC002598982  
 Contact: GREG PAQUETTE  
 Telephone: 6196960470  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 813 13TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921016602

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SIGSBEE ROW HOMES LLC (Continued)**

**S108755191**

Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.5  
 Facility County: San Diego

37

**SUPER WELDING OF SO. CA., INC.  
 1702 NATIONAL AV  
 SAN DIEGO, CA 92123**

**LUST S107619928  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019741983  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-03-28 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Guenn Wilbor  
 RP Address: 961 S. 16th Street  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUPER WELDING OF SO. CA., INC. (Continued)**

**S107619928**

Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16472-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

37

**SUPER WELDING OF SO. CA INC.  
 1702 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104748599  
 N/A**

San Diego Co. HMMD:

Facility ID: 116472  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1702 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000241863  
 Gas Station: Not reported  
 Inspection Date: 06/23/03  
 Reinspection Date: Not reported  
 Inspector Name: MNYAGA  
 Violation Notice Issued: Not reported  
 Facility Contact: J. ALCALA & BILL SANTIAGO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SIGSBEE ROW L L C  
 Property Address: 811 13TH ST  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-8003

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUPER WELDING OF SO. CA INC. (Continued)**

**S104748599**

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8447  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8448  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/21/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8449  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 4766  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 4767  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/27/02



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SUPER WELDING OF SO. CA INC. (Continued)**

**S104748599**

Waste Code:	Not reported
Type of Violation:	6HV0209
Occurrences:	Not reported
Item Number:	4768
Violation Desc:	WASTE ONSITE >90/180/270 DAYS
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	4769
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	4770
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV0405
Occurrences:	Not reported
Item Number:	4771
Violation Desc:	AISLE SPACE IS OBSTRUCTED
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV1003
Occurrences:	Not reported
Item Number:	4772
Violation Desc:	HMBP NOT AMENDED W/IN 30 DAYS
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV1009
Occurrences:	Not reported
Item Number:	4773
Violation Desc:	HMBP: INADEQUATE SITE MAP
Inspection Date:	06/23/03
Waste Code:	Not reported
Type of Violation:	6HV0210
Occurrences:	Not reported
Item Number:	1584
Violation Desc:	DID NOT CLEAN SPILL TO FLOOR
Inspection Date:	06/23/03
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	1585
Violation Desc:	TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUPER WELDING OF SO. CA INC. (Continued)**

**S104748599**

Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**SAN DIEGO SAW AND KNIFE WORKS  
 1765 LOGAN AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000110782  
 FINDS CAD982498693  
 HAZNET  
 LUST  
 Cortese  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

RCRA-SQG:

Date form received by agency: 02/07/1990  
 Facility name: SAN DIEGO SAW AND KNIFE WORKS  
 Facility address: 1765 LOGAN AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982498693  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1765 LOGAN AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 234-5710  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: ROBERT BUQUET  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD982498693  
 Contact: --  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1765 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131006  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 0.27  
 Facility County: Not reported

Gepaid: CAD982498693  
 Contact: Not reported  
 Telephone: 0000000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1765 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131006  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Metal dust - machining waste and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)  
 Disposal Method: Transfer Station  
 Tons: .4500  
 Facility County: San Diego

Gepaid: CAD982498693  
 Contact: --  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1765 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131006  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: 0.40  
 Facility County: Not reported

Gepaid: CAD982498693  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1765 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131006  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Metal dust - machining waste and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)  
 Disposal Method: Disposal, Other  
 Tons: .4000  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019767802  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2005-06-15 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Susan Han  
 RP Address: 320 Golden Shore, Ste. 200  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00515-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302583  
 Stop Date: 1999-01-12 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-04-14 00:00:00  
 Discover Date: 1999-01-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-02-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: ATTN: MR. TOM KLOCK  
 RP Address: 1785 LOGAN AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00515-001  
 Case Number: 9UT3820  
 Qty Leaked: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT3820  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 01/12/1999  
 How Found: Tank Closure  
 Date Stopped: 01/12/1999  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 02/10/1999  
 Submit Workplan: 2/8/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 4/14/00  
 Pilot Program: LOP  
 Local Case: H00515-001  
 Basin Number: 908.22  
 Gwater Depth: 35  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 02/01/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 1765 LOGAN AVE

**San Diego Co. HMMD:**

Facility ID: 100515  
 Inactive Indicator: Active  
 Business Code: 6HK18

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1765 LOGAN AVE.  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD982498693  
 Gas Station: Not reported  
 Inspection Date: 01/30/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: BOB BUQUET  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: LOGAN INVESTMENT L L C  
 Property Address: P O BOX 124663  
 Property City, St, Zip: 92112  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/30/05  
 Facility Phone: 619-234-5710

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: at4283  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: 02/22/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3683



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/22/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3684  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 10/02/97  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 9012  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 10/02/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9013  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/21/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 4506  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/21/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4507  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 01/30/04  
 Waste Item #: 171  
 Waste Code: 171  
 Waste Name: METAL SLUDGE  
 Qnty at Inspection: 700  
 Quantity String: 700  
 Annual Qty: 700  
 Annual Qty String: 700  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0791 RHO-CHEM CORP/A. PHI  
 Waste Desc: SLUDGE FROM BLADE SHRPNG  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO SAW AND KNIFE WORKS (Continued)**

**1000110782**

Qty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 15  
 Annual Qty String: 15  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: COOLANT FROM MACHINE  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H00515-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 4/14/2000  
 Begandt: 1/12/1999

Case Number: H00515-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 6/15/2005  
 Begandt: Not reported

37

**LOGAN INVESTMENT LLC**  
**1765 LOGAN AVE**  
**SAN DIEGO, CA 92113**

**HAZNET S104565604**  
**N/A**

**HAZNET:**

Gepaid: CAC001175552  
 Contact: LOGAN INVESTMENT LLC  
 Telephone: 6192392282  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1785 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 0.1668  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37 CARLOS CLEANERS  
 1694 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S108540629  
 DRYCLEANERS N/A**

HAZNET:

Gepaid: CAC002603645  
 Contact: KAMAL SHAMOO  
 Telephone: 6199209861  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 10755 VIA DEL SOL  
 Mailing City,St,Zip: SPRING VALLEY, CA 91978  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.07  
 Facility County: San Diego

CLEANERS:

EPA Id: CAC002603645  
 NAICS Code: Not reported  
 NAICS Description: Not reported  
 Create Date: 5/10/2006  
 Facility Active: No  
 Inactive Date: 11/7/2006  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 10755 VIA DEL SOL  
 Mailing Address 2: Not reported  
 Mailing State: CA  
 Mailing Zip: 91978  
 Region Code: 4  
 Owner Name: KAMAL SHAMOO  
 Owner Address: 10755 VIA DEL SOL  
 Owner Address 2: Not reported  
 Owner Telephone: Not reported  
 Owner Fax Number: Not reported  
 Contact Name: KAMAL SHAMOO  
 Contact Address: 10755 VIA DEL SOL  
 Contact Address 2: Not reported  
 Contact Telephone: 6199209861  
 Contact Fax Number: Not reported  
 SIC Description: Not reported

**37 BARRETT ENGINEERED PUMPS  
 1695 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104751005  
 N/A**

San Diego Co. HMMD:

Facility ID: 126193  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ERIC EYRES  
 Mailing Address: P O BOX 13130

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRETT ENGINEERED PUMPS (Continued)**

**S104751005**

Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000051644  
 Gas Station: Not reported  
 Inspection Date: 03/09/05  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ERIC EYRES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BARRETT WALTER&MARION TRS  
 Property Address: 948 CYPRESS WAY  
 Property City,St,Zip: 92103  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/09/06  
 Facility Phone: 619-232-7867

**HMMD DISCLOSURE INVENTORY:**

Item Number: 7529  
 Chemical Name: 75% ARGON; 25% CARBON DIOXIDE-MIG MIX  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/17/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7706  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 05/02/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0401

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRETT ENGINEERED PUMPS (Continued)**

**S104751005**

Occurrences: Not reported  
 Item Number: 4831  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 05/02/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4832  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1244  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 1245  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 1246  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1247  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 1248  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 08/26/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3548  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 03/09/05  
 Waste Item #: 171  
 Waste Code: 171

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRETT ENGINEERED PUMPS (Continued)**

**S104751005**

Waste Name: METAL SLUDGE  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: 30% MURIATIC ACD/H2O-70%  
 Carcinogen: No

Inspection Date: 03/09/05  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 86  
 Annual Qty String: 86  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: SAFETY KLEEN- 1 UNIT  
 Carcinogen: No

Inspection Date: 03/09/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: 50 GAL 6/96 ER  
 Carcinogen: No

37

**SUNBELT DISTRIBUTING CHEMICAL  
 1625 NEWTON ST  
 SAN DIEGO, CA 92113**

**FINDS 1000162437  
 HIST UST CAD981433402  
 SWEEPS UST  
 RCRA-NonGen**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNBELT DISTRIBUTING CHEMICAL (Continued)**

**1000162437**

**HIST UST:**

Region: STATE  
 Facility ID: 00000065389  
 Facility Type: Other  
 Other Type: DISTRIBUTING AUTOMOT  
 Total Tanks: 0001  
 Contact Name: LEONARD LOFTHUS  
 Telephone: 6192361555  
 Owner Name: ROBERT JEAN GAIL F. LICHTER  
 Owner Address: 1555 SIXTH AVENUE  
 Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: None

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21207  
 Number: Not reported  
 Board Of Equalization: 44-023482  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021207-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: WASTE  
 Content: LEADED  
 Number Of Tanks: 1

**RCRA-NonGen:**

Date form received by agency: 08/01/1986  
 Facility name: SUNBELT DISTRIBUTING CHEMICAL  
 Facility address: 1625 NEWTON ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981433402  
 Mailing address: PO BOX 9000  
 LEMON GROVE, CA 92045  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1625 NEWTON ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 231-0841  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNBELT DISTRIBUTING CHEMICAL (Continued)**

**1000162437**

Owner/Operator Summary:

Owner/operator name: CARDIS CORP  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

37

**SUNBELT CHEMICAL  
 1625 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106060537  
 N/A**

San Diego Co. HMMD:

Facility ID: 105899  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City, St, Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SUNBELT CHEMICAL (Continued)**

**S106060537**

Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO HOUSING COMMISSION  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNBELT CHEMICAL (Continued)**

**S106060537**

Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**ROBERT & GAIL LICHTER  
 1625 NEWTON AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104749749  
 N/A**

San Diego Co. HMMD:

Facility ID: 121207  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 2910  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO HOUSING COMMISSION  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: C/O JOHN BURNHAM & CO  
 Tank Address: PO BOX 2910  
 Tank City,St,Zip: San Diego, CA 92112  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ROBERT & GAIL LICHTER (Continued)**

**S104749749**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 001  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**US COAST GUARD  
 1620 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103993647  
 N/A**

**HAZNET:**

Gepaid: CAC001040680  
 Contact: US COAST GUARD  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2716 N HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: .5000  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

37

**1620 NEWTON AVE.  
 SAN DIEGO, CA 92113**

**RCRA-LQG 1007199085  
 CAD980812978**

RCRA-LQG:

Date form received by agency: 02/21/1996  
 Facility name: Not reported  
 Facility address: 1620 NEWTON AVE.  
 SAN DIEGO, CA 92113  
 EPA ID: CAD980812978  
 Contact: DANIEL MILLS  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 233-1881  
 Contact email: Not reported  
 EPA Region: Not reported  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: Unknown  
 Transporter of hazardous waste: Unknown  
 Treater, storer or disposer of HW: No  
 Underground injection activity: Unknown  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: Unknown  
 Used oil processor: Unknown  
 User oil refiner: Unknown  
 Used oil fuel marketer to burner: Unknown  
 Used oil Specification marketer: Unknown  
 Used oil transfer facility: Unknown  
 Used oil transporter: Unknown  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

37

**ACTION CLEANING CORP  
 1620 NEWTON AV  
 SAN DIEGO, CA 92113**

**HAZNET 1001613756  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAD980812978  
 Contact: ROBERTO VICTORIA  
 Telephone: 6192331881  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1668 NEWTON AVE  
 Mailing City, St, Zip: SAN DIEGO, CA 921131013  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ACTION CLEANING CORP (Continued)**

**1001613756**

Disposal Method: Disposal, Other  
 Tons: .9000  
 Facility County: San Diego

Gepaid: CAD980812978  
 Contact: ROBERTO VICTORIA  
 Telephone: 6192331881  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1668 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131013  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .4500  
 Facility County: San Diego

Gepaid: CAD980812978  
 Contact: ROBERTO VICTORIA  
 Telephone: 6192331881  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1668 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131013  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .8500  
 Facility County: San Diego

Gepaid: CAD980812978  
 Contact: ROBERTO VICTORIA  
 Telephone: 6192331881  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1668 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131013  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: .5500  
 Facility County: San Diego

Gepaid: CAD980812978  
 Contact: ROBERTO VICTORIA  
 Telephone: 6192331881  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1668 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131013  
 Gen County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING CORP (Continued)**

**1001613756**

TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 9.1740  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 82 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 119269  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1620 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD980812978  
 Gas Station: Not reported  
 Inspection Date: 12/15/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVE RICHARDSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: VICTORIA ROBERTO  
 Property Address: 1668 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/15/05  
 Facility Phone: 619-233-1881

HMMD DISCLOSURE INVENTORY:

Item Number: AC28  
 Chemical Name: ACETYLENE OXYGEN/ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING CORP (Continued)**

**1001613756**

2nd Hazard Category: PRESSURE R

Item Number: AL50  
 Chemical Name: ALKYL PHENYLETHOXALATE, VANWET 9N9, DURFACTANT  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AR40  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: AR54  
 Chemical Name: ARGON/CO2  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CA53  
 Chemical Name: CAUSTIC SODA, 55 GAL + 200LBS  
 Case Number: 1310-13-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: CO51  
 Chemical Name: COAGULANT, WMC-400  
 Case Number: 128-04-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ACTION CLEANING CORP (Continued)**

**1001613756**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: DI34  
 Chemical Name: DIESEL  
 Case Number: 684-76-346  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: EH38  
 Chemical Name: EHTYLENE GLYCOL 50%, COOLANT  
 Case Number: 107-21-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: GA36  
 Chemical Name: GAMEZYME/ LIQUIZYME  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HY29  
 Chemical Name: HYDROCHLORIC ACID (MURIATIC)  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: LI42  
 Chemical Name: LIME, HYDRATED  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING CORP (Continued)**

**1001613756**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: NA48  
 Chemical Name: NAPTHA, PD680 TYPE 11  
 Case Number: 64742-47-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: NI45  
 Chemical Name: NITROGEN  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OI32  
 Chemical Name: OIL, LUBRICATING, MOTOR & HYDRAULIC OIL, GREASE  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX46  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PA47

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING CORP (Continued)**

**1001613756**

Chemical Name: PAINT, OIL BASED  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PE39  
 Chemical Name: PETROLEUM DISTILLATES, AMERIOD CLEAN BREAK DEGREASER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PO44  
 Chemical Name: POLYDIMETHYL SILOXANE EMULSION, SAG 10 ANTIFOAM  
 Case Number: 9016-00-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PR43  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: SO33  
 Chemical Name: SODIUM HYDROXIDE SOLUTION  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ACTION CLEANING CORP (Continued)**

**1001613756**

2nd Hazard Category: Not reported

Item Number: SO31  
 Chemical Name: SODIUM HYPOCHLORITE  
 Case Number: 7681-52-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO35  
 Chemical Name: SODIUM NITRITE  
 Case Number: 7632-00-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: SO49  
 Chemical Name: SODIUM PHOSPHATE, TRI BASIC  
 Case Number: 7601-54-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: ST37  
 Chemical Name: STOPS RUST PRESERVATIVE, OILS  
 Case Number: 68603-26-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: T356  
 Chemical Name: T35 EPOXY REDUCER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING CORP (Continued)**

**1001613756**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: TR30  
 Chemical Name: TRIETHANOLAMINE  
 Case Number: 2732-34-17  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: XY55  
 Chemical Name: XYLENE  
 Case Number: 1330-20-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: ZE52  
 Chemical Name: ZEP BLAST AWAY  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5498  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/13/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ACTION CLEANING CORP (Continued)**

**1001613756**

Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 5499  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5500  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 12/15/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6831  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/15/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 6832  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

**HMMD WASTE STREAMS:**

Inspection Date: 12/15/03  
 Waste Item #: 132  
 Waste Code: 132  
 Waste Name: AQUEOUS SOL'N WITH M  
 Qnty at Inspection: 1000  
 Quantity String: 1000  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: GAL  
 Treatment Method: 014 TRANSFER STATION  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 1127 ACTION CLEANING CORP  
 Waste Desc: LIQUIDS (40 PPM CHROME)  
 Carcinogen: No

Inspection Date: 12/15/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PARTS CLEANER  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING CORP (Continued)**

**1001613756**

Inspection Date: 12/15/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 275  
 Quantity String: 275  
 Annual Qty: 2500  
 Annual Qty String: 2500  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WSTE OIL FR TRUCKS/SHIPS  
 Carcinogen: No

Inspection Date: 12/15/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2804 ENVIROSERV  
 Waste Desc: OIL/WATER  
 Carcinogen: No

Inspection Date: 12/15/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 860  
 Annual Qty String: 860  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2804 ENVIROSERV  
 Waste Desc: OIL RAGS/ABSORBANT/SOIL  
 Carcinogen: No

Inspection Date: 12/15/03  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING CORP (Continued)**

**1001613756**

Waste Desc: ANTIFREEZE  
 Carcinogen: No  
  
 Inspection Date: 12/15/03  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2804 ENVIROSERV  
 Waste Desc: WASTE PAINT/CHIPS  
 Carcinogen: No

Inspection Date: 12/15/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 1200  
 Annual Qty String: 1200  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: OIL FILTERS FR CO VEH M.  
 Carcinogen: No

37

**CARLOS CLEANERS  
 1686 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET 1000290911  
 DRYCLEANERS N/A**

HAZNET:

Gepaid: CAD981962012  
 Contact: JUAN C MEZA  
 Telephone: 0002393793  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1686 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .0975  
 Facility County: San Diego

Gepaid: CAD981962012  
 Contact: JUAN C MEZA  
 Telephone: 0002393793  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLOS CLEANERS (Continued)**

**1000290911**

Mailing Name: Not reported  
 Mailing Address: 1686 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .0975  
 Facility County: San Diego

Gepaid: CAD981962012  
 Contact: JUAN C MEZA/OWNER  
 Telephone: 2393793  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1686 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.09  
 Facility County: Not reported

Gepaid: CAD981962012  
 Contact: JUAN C MEZA  
 Telephone: 0002393793  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1686 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .0975  
 Facility County: San Diego

Gepaid: CAD981962012  
 Contact: JUAN C MEZA/OWNER  
 Telephone: 2393793  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1686 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.09  
 Facility County: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLOS CLEANERS (Continued)**

**1000290911**

[Click this hyperlink](#) while viewing on your computer to access 6 additional CA\_HAZNET: record(s) in the EDR Site Report.

**CLEANERS:**

EPA Id: CAD981962012  
 NAICS Code: 81232  
 NAICS Description: Drycleaning and Laundry Services (except Coin-Operated)  
 Create Date: 7/3/1987  
 Facility Active: No  
 Inactive Date: 6/30/2004  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1686 NATIONAL AVE  
 Mailing Address 2: Not reported  
 Mailing State: CA  
 Mailing Zip: 921130000  
 Region Code: 4  
 Owner Name: JUAN C MEZA  
 Owner Address: 1686 NATIONAL AVE  
 Owner Address 2: Not reported  
 Owner Telephone: 2393793  
 Owner Fax Number: Not reported  
 Contact Name: JUAN C MEZA/OWNER  
 Contact Address: 1686 NATIONAL AVE  
 Contact Address 2: Not reported  
 Contact Telephone: 2393793  
 Contact Fax Number: Not reported  
 SIC Description: 7216 Drycleaning Plants Except Rug Cleaning  
 SIC Description: 7219 Laundry and Garment Services NEC (alteration and repair)  
 SIC Description: 7211 Power Laundries Family and Commercial  
 SIC Description: 7212 Garment Pressing and Agents for Laundries and Drycleaners

37

**CARLOS CLEANERS  
 1686 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104745521  
 N/A**

San Diego Co. HMMD:

Facility ID: 102642  
 Inactive Indicator: Active  
 Business Code: 6HK53  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1686 NATIONAL AV  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD981962012  
 Gas Station: Not reported  
 Inspection Date: 06/17/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS MEZA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLOS CLEANERS (Continued)**

**S104745521**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GARCIA RAQUEL C TRUST 02-04-95  
 Property Address: 1686 1/2 NATIONAL AV  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 12/17/05  
 Facility Phone: 619-239-3793

**HMMD DISCLOSURE INVENTORY:**

Item Number: PE52  
 Chemical Name: PERCHLORETHYLENE -0100 GALS IN PROCESS EQUIPMENT AND 55 GALS IN DRUM.  
 Case Number: 127-18-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/05/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6260  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/28/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 3132  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

Inspection Date: 02/28/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3133  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/28/00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CARLOS CLEANERS (Continued)**

**S104745521**

Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3134  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/06/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9514  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/06/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9515  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 01/13/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5821  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 01/13/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 5822  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 06/17/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 2315  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

**HMMD WASTE STREAMS:**

Inspection Date: 06/17/04  
 Waste Item #: 251  
 Waste Code: 251  
 Waste Name: STILL BOTTOMS W/HALO  
 Qnty at Inspection: 60  
 Quantity String: 60  
 Annual Qty: 195  
 Annual Qty String: 195  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: FILTER POWDER W/PERC  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**37 MARINE & RESTURANT FABRICATORS INC HAZNET S100733510**  
**1616 NEWTON AVE N/A**  
**SAN DIEGO, CA 92113**

HAZNET:

Gepaid: CAL000127370  
 Contact: CURT WRIGHT  
 Telephone: 6192327267  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1616 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Bernardino  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .3500  
 Facility County: San Bernardino

Gepaid: CAL000127370  
 Contact: CURT WRIGHT  
 Telephone: 6192327267  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1616 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Bernardino  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .0750  
 Facility County: San Bernardino

Gepaid: CAL000127370  
 Contact: CURT WRIGHT  
 Telephone: 6192327267  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1616 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Bernardino  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .1000  
 Facility County: San Bernardino

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37 MARINE & RESTAURANT FABRICATOR  
 1616 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104750963  
 N/A**

San Diego Co. HMMD:

Facility ID:	126131
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1616 NEWTON AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	51
EPA ID:	CAL000127370
Gas Station:	Not reported
Inspection Date:	06/20/95
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	CURT WRIGHT
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	ZELEDON KIM M
Property Address:	1616 NEWTON AVE
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-232-7267

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE & RESTAURANT FABRICATOR (Continued)**

**S104750963**

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203135  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1616 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000244807  
 Gas Station: Not reported  
 Inspection Date: 02/26/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ROBERT SPANN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ZELEDON KIM M  
 Property Address: 1616 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE & RESTAURANT FABRICATOR (Continued)**

**S104750963**

Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/26/05  
 Facility Phone: 619-234-2676

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC73  
 Chemical Name: ACETYLENE GAS  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: AR72  
 Chemical Name: ARGON / CARBON DIOXIDE MIG MIX/STEEL MIX  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: AR74  
 Chemical Name: ARGON GAS  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OX75  
 Chemical Name: OXYGEN GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE & RESTAURANT FABRICATOR (Continued)**

**S104750963**

Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 02/26/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 96  
 Annual Qty String: 96  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 02/26/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED OIL  
 Carcinogen: No

37

**ACTION CLEANING PRODUCTS  
 1616 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S104568840  
 N/A**

**HAZNET:**

Gepaid: CAC001479000  
 Contact: LORENA VICTORIA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1616 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING PRODUCTS (Continued)**

**S104568840**

Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Recycler  
 Tons: 1.6054  
 Facility County: San Diego

37

**ACTION CLEANING  
 1604 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103547286  
 LUST N/A  
 Cortese**

HAZNET:

Gepaid: CAC001380984  
 Contact: ROBERTO VICTORIA  
 Telephone: 6192331882  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 99 F ST  
 Mailing City,St,Zip: CHULA VISTA, CA 919100000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Not reported  
 Tons: 4.1700  
 Facility County: San Diego

Gepaid: CAC001380984  
 Contact: ROBERTO VICTORIA  
 Telephone: 6192331882  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 99 F ST  
 Mailing City,St,Zip: CHULA VISTA, CA 919100000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 27.9390  
 Facility County: San Diego

LUST:

Region: 9  
 Case Number: 9UT3877  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 12/30/1998  
 How Found: Tank Closure  
 Date Stopped: 12/30/1998  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: 02/01/1999

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING (Continued)**

**S103547286**

Submit Workplan: 4/8/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H16506-001  
 Basin Number: 908.22  
 Gwater Depth: 10'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: Not reported  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 01/29/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 1604 NEWTON AVE

37

**ACTION CLEANING**  
**1604 NEWTON AV**  
**SAN DIEGO, CA 92113**

**LUST S104748610**  
**San Diego Co. HMMD N/A**  
**SAN DIEGO CO. SAM**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302637  
 Stop Date: 1998-12-30 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-10-31 00:00:00  
 Discover Date: 1998-12-30 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-01-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING (Continued)**

**S104748610**

Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: IRENE SHAHAN  
 RP Address: 99 F STREET  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: EP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16506-001  
 Case Number: 9UT3877  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 116506  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1604 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/19/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING (Continued)**

**S104748610**

Violation Notice Issued: Not reported  
 Facility Contact: ALEXANDER FERNANDEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SHAHAN IRENE LIVING TRUST 10-1  
 Property Address: 5740 LAKE MURRAY BLV  
 Property City,St,Zip: 91942  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-6115

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: at4222  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: at4222  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING (Continued)**

**S104748610**

Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203602  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1668 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD980812978  
 Gas Station: Not reported  
 Inspection Date: 06/10/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVE RICHARDSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SHAHAN IRENE LIVING TRUST 10-1  
 Property Address: 5740 LAKE MURRAY BLV  
 Property City,St,Zip: 91942  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/10/06  
 Facility Phone: 619-233-1882

**HMMD DISCLOSURE INVENTORY:**

Item Number: PO62  
 Chemical Name: POTASSIUM CARBONATE (30%) CATALYST WASH SOLUTION  
 Case Number: 584-08-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACTION CLEANING (Continued)**

**S104748610**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 06/10/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 2222  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

Inspection Date: 06/10/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 2223  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H16506-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/31/2000  
 Begandt: 12/30/1998

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37      MARTINEZ GARAGE & TOWING  
 1604 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD      S106061971  
 N/A**

San Diego Co. HMMD:

Facility ID:	123082
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1604-B NEWTON
Mailing City, St, Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	51
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	02/26/90
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	MIGUEL MARTINEZ
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	SHAHAN IRENE LIVING TRUST 10-1
Property Address:	5740 LAKE MURRAY BLV
Property City, St, Zip:	91942
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City, St, Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-231-7767

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARTINEZ GARAGE & TOWING (Continued)**

**S106061971**

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**37 16TH & NEWTON  
 16TH & NEWTON  
 SAN DIEGO, CA 32101**

**ERNS 94367350  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**37 METRO TRANSIT  
 1601 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S107143267  
 N/A**

HAZNET:

Gepaid: CAC002570170  
 Contact: SCOTT SNYDER  
 Telephone: 8585761000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1255 IMPERIAL AVE STE 1000  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: AZC951206114  
 TSD County: San Diego  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Land Fill  
 Tons: 30.34  
 Facility County: San Diego  
  
 Gepaid: CAC002570170



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**METRO TRANSIT (Continued)**

**S107143267**

Contact: SCOTT SNYDER  
 Telephone: 8585761000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1255 IMPERIAL AVE STE 1000  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: AZC951206114  
 TSD County: San Diego  
 Waste Category: Not reported  
 Disposal Method: Disposal, Land Fill  
 Tons: 15.17  
 Facility County: San Diego

37

**SANDAG  
 1601 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S108754560  
 N/A**

HAZNET:  
 Gepaid: CAC002606568  
 Contact: BILL PREY  
 Telephone: 6196991900  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 401 B ST STE 900  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Gen County: San Diego  
 TSD EPA ID: AZR000002428  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: H13  
 Tons: 21  
 Facility County: San Diego

37

**SAN DIEGO TROLLEY  
 1601 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104752909  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 131989  
 Inactive Indicator: Active  
 Business Code: 6HK52  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1255 IMPERIAL AV #9  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 06/10/99  
 Reinspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY (Continued)**

**S104752909**

Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MITCHELL CAMPBELL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO METROPOLITAN TRANSIT  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-595-4904

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY (Continued)**

**S104752909**

Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**TRIAD MARINE & INDUSTRIAL CLEANING CORP.  
 1668 NATIONAL AVE.  
 SAN DIEGO, CA 92113**

**ENVIROSTOR**

**S100182132  
 N/A**

ENVIROSTOR:

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37280047  
 Site Code: 400238  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: RCRA  
 Status Date: 1995-05-10 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 32.7030555555556  
 Longitude: -117.148611111111  
 Alias Name: PACIFIC TREATMENT CORP #2  
 400238  
 CAD098240062  
 37280047  
 PACIFIC TREATMENT CORP  
 Alias Type: Alternate Name  
 Project Code (Site Code)  
 Envirostor ID Number  
 Alternate Name  
 EPA Identification Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: "NFA FOR SITE MITIGATION OPERATIONS, THIS IS A RCRA  
 FACILITY."FACILITY IDENTIFIED ID VIA CALIF. WASTE MGMT. BD.  
 PRINTOUTSITE SCREENING DONE STAINS OF UNKNOWN SUBSTANCE NEXT TO  
 CEMENT WASH PAD

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 02/09/95  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIAD MARINE & INDUSTRIAL CLEANING CORP. (Continued)**

**S100182132**

Completed Date: 06/05/87

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 02/22/83

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 20017  
 Potential Description: \* UNSPECIFIED ORGANIC LIQUID MIXTURE  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

37

**PACIFIC TREATMENT  
 1668 NATIONAL AVENUE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000249989  
 FINDS CAD098240062  
 RCRA-TSDF  
 CORRACTS  
 CERC-NFRAP  
 HIST UST**

RCRA-SQG:  
 Date form received by agency: 09/01/1996  
 Facility name: PACIFIC TREATMENT  
 Facility address: 1668 NATIONAL AVENUE  
 SAN DIEGO, CA 92113

EPA ID: CAD098240062  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: TSDF  
 Description: Handler is engaged in the treatment, storage or disposal of hazardous waste  
 TSD commencement date: Not reported

Owner/Operator Summary:  
 Owner/operator name: PACIFIC TREATMENT CORPORATION  
 Owner/operator address: PO BOX 13626  
 SAN DIEGO, CA 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT (Continued)**

**1000249989**

Owner/operator country: Not reported  
 Owner/operator telephone: (619) 233-0424  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: PACIFIC TREATMENT  
 Owner/operator address: 1668 NATIONAL AVE  
 SAN DIEGO, CA 92113

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 12/05/1980  
 Facility name: PACIFIC TREATMENT  
 Classification: Large Quantity Generator

**Corrective Action Summary:**

Event date: 09/09/1991  
 Event: CA029ST

Event date: 09/09/1991  
 Event: CA049PA

Event date: 09/09/1991  
 Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 02/11/1992  
 Event: Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1- it appears to be technically infeasible or inappropriate (NF) or 2- there is a lack of technical information (IN). Reasons for this

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT (Continued)**

**1000249989**

conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.

Event date: 02/11/1992  
 Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Facility Has Received Notices of Violations:

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/08/1994  
 Date achieved compliance: 09/08/1999  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 11/30/1993  
 Date achieved compliance: 09/08/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 06/08/1993  
 Date achieved compliance: 11/30/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 11/06/1992  
 Date achieved compliance: 06/08/1993  
 Violation lead agency: State  
 Enforcement action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT (Continued)**

**1000249989**

Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 04/07/1992  
 Date achieved compliance: 11/06/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 10/28/1991  
 Date achieved compliance: 04/07/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:  
 Evaluation date: 09/08/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 09/08/1999  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 11/30/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 09/08/1994  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/08/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 11/30/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 11/06/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT (Continued)**

**1000249989**

Area of violation: Generators - General  
 Date achieved compliance: 06/08/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 04/07/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 11/06/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 10/28/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 04/07/1992  
 Evaluation lead agency: State Contractor/Grantee

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**CORRACTS:**

EPA ID: CAD098240062  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 02/11/1992  
 Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority  
 NAICS Code(s): Not reported  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CAD098240062  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 09/09/1991  
 Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority  
 NAICS Code(s): Not reported  
 Original schedule date: Not reported  
 Schedule end date: Not reported

**CERC-NFRAP:**

Site ID: 0903904  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: Deferred to RCRA



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT (Continued)**

**1000249989**

CERCLIS-NFRAP Site Contact Name(s):

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 05/21/1991  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 09/12/1991  
 Priority Level: Deferred to RCRA (Subtitle C)

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 01/23/1996  
 Priority Level: Not reported

HIST UST:

Region: STATE  
 Facility ID: 00000004259  
 Facility Type: Other  
 Other Type: TSD F FACILITY  
 Total Tanks: 0004  
 Contact Name: GREG H. WIDDERS  
 Telephone: 6192392024  
 Owner Name: PACIFIC TREATMENT CORPORATION  
 Owner Address: P.O. BOX 13626\_\_\_\_  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1982  
 Tank Capacity: 00002100  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: 1/4 inches  
 Leak Detection: Visual

Tank Num: 002  
 Container Num: 2  
 Year Installed: 1982  
 Tank Capacity: 00000050  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: 4 inches  
 Leak Detection: Visual

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT (Continued)**

**1000249989**

Tank Num: 003  
 Container Num: 3  
 Year Installed: 1983  
 Tank Capacity: 00000800  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: 1/4 inches  
 Leak Detection: Visual

Tank Num: 004  
 Container Num: 4  
 Year Installed: 1981  
 Tank Capacity: 00000025  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: 1/16 inches  
 Leak Detection: Visual

37

**CENTER CITY TOWING  
 1668 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S106059798  
 N/A**

LUST:

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: SLT19739268  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2007-12-11 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTER CITY TOWING (Continued)**

**S106059798**

Responsible Party: Project Accountant  
 RP Address: 30141 Agoura Rd., Ste. 100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: TS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01553-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 101553  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1668 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/23/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RAUL JAQUEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTER CITY TOWING (Continued)**

**S106059798**

Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-2489

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/23/95  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 2692  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 08/23/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2693  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/23/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2694  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/23/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2695  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 08/23/95

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CENTER CITY TOWING (Continued)**

**S106059798**

Waste Code: Not reported  
 Type of Violation: 6HV0295  
 Occurrences: Not reported  
 Item Number: 2696  
 Violation Desc: DAMAGED BATTERIES: IMPROP MGMT

Inspection Date: 08/23/95  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 2697  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 08/23/95  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 2698  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H01553-001  
 Agency: CA Department of Toxic Substance Control  
**Funding: Non Billable**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/17/1991  
 Begandt: 5/17/1991

Case Number: H01553-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 4/24/2007  
 Begandt: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37 YALE COMBS  
 1668 NATIONAL AV  
 EL CAJON, CA 92020**

**San Diego Co. HMMD S106880126  
 N/A**

San Diego Co. HMMD:

Facility ID: 205259  
 Inactive Indicator: Active  
 Business Code: 6HT23  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City, St, Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: 939 ASSOCIATES INC  
 Property Address: 3245 BRANT ST  
 Property City, St, Zip: 92103  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-441-1818

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: T001  
 Tank ID Number: AT5169  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YALE COMBS (Continued)**

**S106880126**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**RADFORD OVERHEAD DOORS INC**  
**1659 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**HIST UST U001572991**  
**SWEEPS UST N/A**

**HIST UST:**

Region: STATE  
 Facility ID: 00000008678  
 Facility Type: Other  
 Other Type: DOOR MFGR  
 Total Tanks: 0001  
 Contact Name: RALPH R. RADFORD  
 Telephone: 6192398558  
 Owner Name: RADFORD OVERHEAD DOORS, INC.  
 Owner Address: 1659 NATIONAL AVE.  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1190-1346  
 Year Installed: Not reported  
 Tank Capacity: 00000950  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: None

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 636  
 Number: Not reported  
 Board Of Equalization: 44-021573  
 Ref Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RADFORD OVERHEAD DOORS INC (Continued)**

**U001572991**

Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000636-000001  
 Actv Date: Not reported  
 Capacity: 950  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

37

**RADFORD OVERHEAD DOORS INC  
 1659 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S105033118  
 N/A**

San Diego Co. HMMD:

Facility ID: 100636  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1659 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/15/91  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JOE BROOKMAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BROOKMAN JOSEPH E TRUST 02-09-  
 Property Address: 20872 DEERHORN VALLE  
 Property City,St,Zip: 91935  
 Tank Owner: RALPH R RADFORD  
 Tank Address: 1659 NATIONAL AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-8558

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RADFORD OVERHEAD DOORS INC (Continued)**

**S105033118**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1190-1346  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**REFRIGERATION SUPPLIES DIST  
 1721 LOGAN AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104754427  
 N/A**

San Diego Co. HMMD:

Facility ID: 134438  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1721 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**REFRIGERATION SUPPLIES DIST (Continued)**

**S104754427**

EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/16/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JOSE RAMOS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: REFRIGERATION SUPPLIES DISTRIB  
 Property Address: 26021 ATLANTIC OCEAN  
 Property City,St,Zip: 92630  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/16/05  
 Facility Phone: 619-239-4127

**HMMD DISCLOSURE INVENTORY:**

Item Number: CH13  
 Chemical Name: CHLORODIFLOUROMETHANE, CHLOROTETRAFLAUROETHANE (R-409, 404A)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CHRONIC

Item Number: CH09  
 Chemical Name: CHLORODIFLUOROMETHANE (FREON 22) MP36, AP-80, MP-66, HOTSHOT  
 Case Number: 75-45-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: DI08  
 Chemical Name: DICHLORODIFLUOROMETHANE (FREON 12)  
 Case Number: 75-71-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**REFRIGERATION SUPPLIES DIST (Continued)**

**S104754427**

Item Number: HY11  
 Chemical Name: HYDROCHLORIC ACID - LIQUID SCALE DISSOLVER  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: MO10  
 Chemical Name: MONOCHLORO/DIFLUOROMETHANE (AZ-20) AND CHLOROTETRAFLUROETHANE (GENETON M)  
 Case Number: 2837-89-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: TR12  
 Chemical Name: TRIFLUOROETHANE/CHLORODIFLUOROMETHANE (134A) PENTAFLUROETHANE (R408)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/23/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 8792  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**REFRIGERATION SUPPLIES DIST (Continued)**

**S104754427**

Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**SUNBELT DISTRIBUTING  
 1712 LOGAN AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104747027  
 N/A**

San Diego Co. HMMD:

Facility ID: 110874  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FILIPPI JOSEPH TRUST 07-01-91  
 Property Address: 2626 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNBELT DISTRIBUTING (Continued)**

**S104747027**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**SUNBELT PAINT & BODY  
 1712 LOGAN AVE  
 SAN DIEGO, CA 92113**

**FINDS 1000162438  
 RCRA-NonGen CAD981433469**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-NonGen:**

Date form received by agency: 08/01/1986  
 Facility name: SUNBELT PAINT & BODY

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SUNBELT PAINT & BODY (Continued)**

**1000162438**

Facility address: 1712 LOGAN AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981433469  
 Mailing address: PO BOX 9000  
 LEMON GROVE, CA 92045  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1712 LOGAN AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 231-0841  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: CARDIS CORP  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

<b>37</b>	<b>SAN DIEGO TROLLEY INC</b> <b>1535 NEWTON AVE</b> <b>SAN DIEGO, CA 92101</b>	<b>RCRA-SQG</b> <b>FINDS</b> <b>HAZNET</b> <b>CA WDS</b>	<b>1001023243</b> <b>CAR000006015</b>
-----------	--	---	--

RCRA-SQG:

Date form received by agency: 09/01/1996

Facility name: SAN DIEGO TROLLEY INC

Facility address: 1535 NEWTON AVE  
SAN DIEGO, CA 921017492

EPA ID: CAR000006015

Mailing address: 1255 IMPERIAL AVE STE 900  
SAN DIEGO, CA 921017492

Contact: Not reported

Contact address: Not reported

Contact country: Not reported

Contact telephone: Not reported

Contact email: Not reported

EPA Region: 09

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: METROPOLITAN TRANSIT DEVELOPMENT BOARD

Owner/operator address: 1255 IMPERIAL AVE STE 1000  
SAN DIEGO, CA 92101

Owner/operator country: Not reported

Owner/operator telephone: (619) 231-1466

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown

Mixed waste (haz. and radioactive): Unknown

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: Unknown

Furnace exemption: Unknown

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 09/27/1995

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY INC (Continued)**

**1001023243**

Facility name: SAN DIEGO TROLLEY INC  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000006015  
 Contact: MITCHELL CAMPBELL  
 Telephone: 6195954904  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1255 IMPERIAL AVE STE 900  
 Mailing City,St,Zip: SAN DIEGO, CA 921017440  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Not reported  
 Tons: 0.16  
 Facility County: Not reported

Gepaid: CAR000006015  
 Contact: METROPOLITAN TRANSIT DEV'T  
 Telephone: 6192311466  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1255 IMPERIAL AVE STE 900  
 Mailing City,St,Zip: SAN DIEGO, CA 921017440  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 5.9043  
 Facility County: San Diego

Gepaid: CAR000006015  
 Contact: METROPOLITAN TRANSIT DEV'T  
 Telephone: 6192311466  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1255 IMPERIAL AVE STE 900  
 Mailing City,St,Zip: SAN DIEGO, CA 921017440  
 Gen County: San Diego



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY INC (Continued)**

**1001023243**

TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Not reported  
 Tons: .2960  
 Facility County: San Diego

Gepaid: CAR000006015  
 Contact: MITCHELL CAMPBELL  
 Telephone: 6195954904  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1255 IMPERIAL AVE STE 900  
 Mailing City,St,Zip: SAN DIEGO, CA 921017440  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.45  
 Facility County: San Diego

Gepaid: CAR000006015  
 Contact: METROPOLITAN TRANSIT DEV'T  
 Telephone: 6192311466  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1255 IMPERIAL AVE STE 900  
 Mailing City,St,Zip: SAN DIEGO, CA 921017440  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 1.7263  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 12 additional CA\_HAZNET: record(s) in the EDR Site Report.

CA WDS:

Facility ID: San Diego 371014950  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: SAN DIEGO TROLLEY INC  
 Agency Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY INC (Continued)**

**1001023243**

Agency City,St,Zip: 0  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.  
 Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

37

**SAN DIEGO TROLLEY, INC  
 1535 NEWTON AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104748609  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608120514  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-02-03 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: JIM CLARK  
 RP Address: P O BOX 461866  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16505-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608192456  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-02-03 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: CHRISTINE RYCHEL  
 RP Address: 1255 IMPERIAL AVENUE  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16505-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608195831  
 Stop Date: Not reported  
 Confirm Leak: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: 1997-02-03 00:00:00  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Post remedial action monitoring  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16505-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 116505  
 Inactive Indicator: Active  
 Business Code: 6HK52  
 SIC: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1255 IMPERIAL AV #9  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD981696065  
 Gas Station: Not reported  
 Inspection Date: 12/08/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MITCH CAMPBELL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO METROPOLITAN TRANSIT  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/08/05  
 Facility Phone: 619-595-4904

**HMMD DISCLOSURE INVENTORY:**

Item Number: R-02  
 Chemical Name: R-12 BLDG B&C  
 Case Number: 75-71-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: R-04  
 Chemical Name: R-134A BLDG B  
 Case Number: 811-97-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: R-03  
 Chemical Name: R-22 BLDG B

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Case Number: 75-45-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: SU93  
 Chemical Name: SULFURIC ACID (BATTERY ELECTROLYTE) (1601 NEWTON) SHED  
 Case Number: 7664-93-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: EXTREMELY

Item Number: AC94  
 Chemical Name: ACETYLENE WELD SHOP  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR97  
 Chemical Name: ARGON WELD SHOP  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: CO00  
 Chemical Name: CO2/ARGON WELD SHOP  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Item Number: NI99  
 Chemical Name: NICAD BATTERIES STORAGE AREA/SHED  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: NI96  
 Chemical Name: NITROGEN BLDG C  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OI98  
 Chemical Name: OIL, LUBRICATING, GREASE BLDG B & C  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OX95  
 Chemical Name: OXYGEN WELD SHOP  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR01  
 Chemical Name: PROPANE BLDG B  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5165  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5166  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 5167  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5168  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 5169  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 5170  
 Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

Inspection Date: 12/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Item Number: 6613  
 Violation Desc: WASTE CONTAINER W/O LABELS  
  
 Inspection Date: 12/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1601  
 Occurrences: Not reported  
 Item Number: 6614  
 Violation Desc: HAZWASTE TANKS W/O P.E. ASSESSMENT

**HMMD WASTE STREAMS:**

Inspection Date: 12/08/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 350  
 Quantity String: 350  
 Annual Qty: 1050  
 Annual Qty String: 1050  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: 4 PARTS WASHERS (BLDG C)  
 Carcinogen: No

Inspection Date: 12/08/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: BLDG C  
 Carcinogen: No

Inspection Date: 12/08/03  
 Waste Item #: 222  
 Waste Code: 222  
 Waste Name: OIL/WATER SEPARATION  
 Qty at Inspection: 600  
 Quantity String: 600  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: BLDG C  
 Carcinogen: No

Inspection Date: 12/08/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TROLLEY, INC (Continued)**

**S104748609**

Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: CONTAMINATED GAS  
 Carcinogen: No

Inspection Date: 12/08/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 1500  
 Quantity String: 1500  
 Annual Qty: 1500  
 Annual Qty String: 1500  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: LEAD ACID/NICAD (SHED & B  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H16505-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/3/1997  
 Begandt: 6/22/1992

Case Number: H16505-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/3/1997  
 Begandt: Not reported

Case Number: H16505-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Post Remedial Monitoring  
 Date: 2/3/1997  
 Begandt: 2/3/1997

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37**      **QUALITY REFRIGERATION CO**  
**1680 LOGAN AVE**  
**SAN DIEGO, CA 92113**

**HAZNET**    **S100725527**  
**N/A**

HAZNET:

Gepaid:            CAD020206124  
 Contact:           Not reported  
 Telephone:        0000000000  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 1680 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County:       San Diego  
 TSD EPA ID:       CAD008252405  
 TSD County:       Los Angeles  
 Waste Category:   Adhesives  
 Disposal Method: Recycler  
 Tons:               .2500  
 Facility County:   San Diego

Gepaid:            CAD020206124  
 Contact:           Not reported  
 Telephone:        0000000000  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 1680 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County:       San Diego  
 TSD EPA ID:       CAT080033681  
 TSD County:       Los Angeles  
 Waste Category:   Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons:               .6875  
 Facility County:   San Diego

Gepaid:            CAL000270671  
 Contact:           MICHAEL BRAM/FAC MGR  
 Telephone:        6192301534  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 1680 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County:       San Diego  
 TSD EPA ID:       CAT080033681  
 TSD County:       Los Angeles  
 Waste Category:   Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons:               0.22  
 Facility County:   Not reported

Gepaid:            CAD020206124  
 Contact:           Not reported  
 Telephone:        0000000000  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 1680 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County:       San Diego  
 TSD EPA ID:       CAD009007626

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**QUALITY REFRIGERATION CO (Continued)**

**S100725527**

TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .1375  
 Facility County: San Diego

Gepaid: CAL000270671  
 Contact: MICHAEL BRAM/FAC MGR  
 Telephone: 6192301534  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1680 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.41  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

37

**HILL BROTHERS CHEMICAL CO  
 1680 LOGAN AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104745205  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 101090  
 Inactive Indicator: Active  
 Business Code: 6HK68  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1675 N MAIN ST  
 Mailing City,St,Zip: ORANGE, CA 92867  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD020206124  
 Gas Station: Not reported  
 Inspection Date: 05/17/00  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ALEC MCHENRY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PESUSICH CHARLOTTE R INTERVIVO  
 Property Address: 86 YACHT HARBOR DR  
 Property City,St,Zip: 90275  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HILL BROTHERS CHEMICAL CO (Continued)**

**S104745205**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 233-7171

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/08/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 7675  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 08/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 6985  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 08/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 6986  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 08/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 6987  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 05/17/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0203

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HILL BROTHERS CHEMICAL CO (Continued)**

**S104745205**

Occurrences: Not reported  
 Item Number: 5253  
 Violation Desc: DAMAGED CONTAINER NOT REPACKAGED

Inspection Date: 05/17/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5254  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**37 1680 LOGAN AVE  
 1680 LOGAN AVE  
 SAN DIEGO, CA 92113**

**ERNS 91236769  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**37 HILL BROTHERS CHEMICAL CO  
 1680 LOGAN AVENUE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000273779  
 FINDS CAD020206124**

RCRA-SQG:  
 Date form received by agency: 09/01/1996  
 Facility name: HILL BROS CHEM CO  
 Facility address: 1680 LOGAN AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD020206124  
 Mailing address: ONE CITY BLVD WEST STE 1521  
 ORANGE, CA 92668  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**HILL BROTHERS CHEMICAL CO (Continued)**

**1000273779**

EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 04/23/1982  
 Facility name: HILL BROS CHEM CO  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HILL BROTHERS CHEMICAL CO (Continued)**

**1000273779**

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

37

CHMIRS S100278312  
 N/A

**1680 LOGAN AVENUE  
 SAN DIEGO, CA 92113**

CHMIRS:

OES Incident Number: 9119713  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 09-OCT-91  
**Date Completed: 09-OCT-91**  
 Property Use: 500  
 Agency Id Number: 37140  
 Agency Incident Number: 28723  
 Time Notified: 2056  
 Time Completed: 2300  
 Surrounding Area: 500  
 Estimated Temperature: 68  
 Property Management: P  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agency Personel # Of Decontaminated: 0  
 Responding Agency Personel # Of Injuries: 0  
 Responding Agency Personel # Of Fatalities:0  
 Others Number Of Decontaminated: 0  
 Others Number Of Injuries: 0  
 Others Number Of Fatalities: 0  
 Vehicle Make/year: INTERNATIONAL 1987  
 Vehicle License Number: 3K12912  
 Vehicle State: CA  
 Vehicle Id Number: IHTLCZVMXHH493819  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: HILL CHEMICAL CO.  
 Reporting Officer Name/ID: ENG DON ROCK SDFD/HAZMAT  
 Report Date: 09-OCT-91  
 Comments: Y  
 Facility Telephone: 619 533-4300  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100278312

Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	06-AUG-92
Substance:	Not reported
Quantity Released:	Not reported
BBLs:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

37

**QUALITY REFRIGERATION CO, INC**  
**1680 LOGAN AV**  
**SAN DIEGO, CA 92113**

San Diego Co. HMMD S106072063  
 N/A

San Diego Co. HMMD:

Facility ID:	202115
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1680 LOGAN AVE
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	51
EPA ID:	CAL000270671
Gas Station:	Not reported
Inspection Date:	02/22/05
Reinspection Date:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**QUALITY REFRIGERATION CO, INC (Continued)**

**S106072063**

Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MICHAEL BRAM  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PESUSICH CHARLOTTE R INTERVIVO  
 Property Address: 86 YACHT HARBOR DR  
 Property City,St,Zip: 90275  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/22/06  
 Facility Phone: 619-230-1534

**HMMD DISCLOSURE INVENTORY:**

Item Number: 1,32  
 Chemical Name: 1,1,1,2-TETRA FLUOROETHANE REFRIGERANTS  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: NI34  
 Chemical Name: NITROGEN  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PE33  
 Chemical Name: PETROLEUM NAPHTHA HYDROCARBON SOLVENT  
 Case Number: 64741-65-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**QUALITY REFRIGERATION CO, INC (Continued)**

**S106072063**

Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 02/22/05  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 27  
 Quantity String: 27  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 02/22/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3076 CAL WEST ENVIRONMENT  
 Waste Desc: USED OIL  
 Carcinogen: No

37

**CLEANING DYNAMICS COMPANY  
 1606 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104749148  
 N/A**

San Diego Co. HMMD:

Facility ID: 119719  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CLEANING DYNAMICS COMPANY (Continued)**

**S104749148**

Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/14/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DOUG SLOAN - X41  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BEF INVESTMENTS L L C  
 Property Address: C/O TRILOGY REAL EST  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CLEANING DYNAMICS COMPANY (Continued)**

**S104749148**

Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**CENTRAL MEAT & PROVIDION COMPANY  
 1603 NATIONAL AVENUE  
 SAN DIEGO, CA 92113**

**HAZNET S105086270  
 N/A**

HAZNET:

Gepaid: CAC002275873  
 Contact: ROBERT KUHLKEN  
 Telephone: 6192391391  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1603 NATIONAL AVENUE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .7547  
 Facility County: San Diego

37

**CENTRAL MEAT AND PROVISION COM  
 1603 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HIST UST U001572974  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000011480  
 Facility Type: Other  
 Other Type: FOOD DISTRIBUTOR  
 Total Tanks: 0001  
 Contact Name: ALBERT D. RISLEY  
 Telephone: 6192391391  
 Owner Name: CENTRAL MEAT AND PROVISION COM  
 Owner Address: 1603 NATIONAL AVENUE  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTRAL MEAT AND PROVISION COM (Continued)**

**U001572974**

Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: None

37

**CENTRAL MEAT & PROVISION CO  
 1603 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S105033339  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Piping  
 Global Id: T0607399070  
 Stop Date: 2000-04-27 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-09-24 00:00:00  
 Discover Date: 2000-04-27 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2000-04-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: ROBERT W KUHLKEN  
 RP Address: 1603 NATIONAL AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTRAL MEAT & PROVISION CO (Continued)**

**S105033339**

Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21206-001  
 Case Number: 9UT4059  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 121206  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1603 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/01/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ROGER DUNCUN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KUHLEN ROBERT W TR  
 Property Address: 1603 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: CENTRAL MEAT AND PROVISION CO  
 Tank Address: 1603 NATIONAL AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/01/05  
 Facility Phone: 619-239-1391

**HMMD DISCLOSURE INVENTORY:**

Item Number: CA49  
 Chemical Name: CARBOCHLOR (HOTSY)CLEANER  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTRAL MEAT & PROVISION CO (Continued)**

**S105033339**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CA50  
 Chemical Name: CARBON DIOXIDE COMPRESSED GAS  
 Case Number: 1310-78-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CHRONIC

Item Number: DI47  
 Chemical Name: DICHLORODIFLUOROMETHANE (FREON 12)  
 Case Number: 75-71-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: MI48  
 Chemical Name: MINERAL OIL  
 Case Number: 8042-47-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT4562  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 07/11/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7788

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTRAL MEAT & PROVISION CO (Continued)**

**S105033339**

Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/11/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 7789  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 09/23/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 1742  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 5507  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5508  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 21206  
 Number: 9  
 Board Of Equalization: 44-023481  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTRAL MEAT & PROVISION CO (Continued)**

**S105033339**

Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021206-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H21206-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/24/2003  
 Begandt: 4/27/2000

37

**1531 NATIONAL AVENUE  
 SAN DIEGO, CA**

**RCRA-LQG 1007199660  
 CAD981976269**

**RCRA-LQG:**

Date form received by agency: 02/29/1992  
 Facility name: Not reported  
 Facility address: 1531 NATIONAL AVENUE  
 SAN DIEGO, CA  
 EPA ID: CAD981976269  
 Mailing address: 2913 CANON STREET  
 POST OFFICE BOX 6306  
 SAN DIEGO, CA 92106  
 Contact: MARY D BOEHM  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 224-6927  
 Contact email: Not reported  
 EPA Region: Not reported  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: Unknown  
 Transporter of hazardous waste: Unknown  
 Treater, storer or disposer of HW: No  
 Underground injection activity: Unknown  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: Unknown  
 Used oil processor: Unknown  
 User oil refiner: Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EPA ID Number  
 EDR ID Number

(Continued)

1007199660

Used oil fuel marketer to burner: Unknown  
 Used oil Specification marketer: Unknown  
 Used oil transfer facility: Unknown  
 Used oil transporter: Unknown  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 04/16/1990  
 Facility name: Not reported  
 Classification: Large Quantity Generator

Violation Status: No violations found

37 GRAYBILL TERMINALS  
 1531 NATIONAL AVENUE  
 SAN DIEGO, CA 92113

SLIC S106484242  
 N/A

SLIC:

Region: STATE  
 Global Id: SL372914239  
 Assigned Name: SLICSITE  
 Lead Agency Contact: DONALD F. HOIRUP  
 Lead Agency: SAN DIEGO RWQCB (REGION 9)  
 Lead Agency Case Number: 2090100  
 Responsible Party: UNOCAL CORP  
 Recent Dtw: Not reported  
 Substance Released: PET, VOC  
 Facility Status: Not reported

37 GRAYBILL TERMINALS CO  
 1531 NATIONAL AV  
 SAN DIEGO, CA 92113

LUST S104746152  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM  
 N/A

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: SLT19759516  
 Stop Date: 2004-03-16 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-06-11 00:00:00  
 Discover Date: 2004-03-16 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2004-03-16 00:00:00  
 Review Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAYBILL TERMINALS CO (Continued)**

**S104746152**

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Michael Singer  
 RP Address: P.O. Box 7600  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05324-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300795  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAYBILL TERMINALS CO (Continued)**

**S104746152**

Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-08-19 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05324-001  
 Case Number: 9UT202  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 105324  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: C/O J. SKULLERUD,CPA  
 Mailing Address: 3104 05TH AV

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAYBILL TERMINALS CO (Continued)**

**S104746152**

Mailing City,St,Zip: SAN DIEGO, CA 92103  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAX000046631  
 Gas Station: Not reported  
 Inspection Date: 01/09/91  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: WILLIM BOEHM JR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: UNION OIL COMPANY OF CALIFORNI  
 Property Address: ATTN: TAX ADMINISTRA  
 Property City,St,Zip: 77487  
 Tank Owner: GRAYBILL TERMINALS CO  
 Tank Address: 2913 CANON ST  
 Tank City,St,Zip: San Diego, CA 92106  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-295-5153

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/02/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0027  
 Occurrences: Not reported  
 Item Number: 5779

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAYBILL TERMINALS CO (Continued)**

**S104746152**

Violation Desc:	MANIFESTS NOT KEPT FOR 3 YEARS
Inspection Date:	07/02/85
Waste Code:	Not reported
Type of Violation:	6HX0031
Occurrences:	Not reported
Item Number:	5780
Violation Desc:	NO HAZWASTE DISPOSAL RECEIPTS
Inspection Date:	07/02/85
Waste Code:	Not reported
Type of Violation:	6HX0023
Occurrences:	Not reported
Item Number:	5781
Violation Desc:	HAZWASTE DISPOSAL TO GROUND
Inspection Date:	03/19/87
Waste Code:	Not reported
Type of Violation:	6HV0132
Occurrences:	Not reported
Item Number:	6351
Violation Desc:	EPA ID NUMBER NOT OBTAINED
Inspection Date:	03/19/87
Waste Code:	Not reported
Type of Violation:	6HV0499
Occurrences:	Not reported
Item Number:	6352
Violation Desc:	NO EMPLOYEE TRAINING FOR ER RESPONSE
Inspection Date:	03/19/87
Waste Code:	Not reported
Type of Violation:	6HX0069
Occurrences:	Not reported
Item Number:	6353
Violation Desc:	STORAGE OF WASTE FOR LONGER THAN 90 DAYS
Inspection Date:	03/19/87
Waste Code:	Not reported
Type of Violation:	6HV0205
Occurrences:	Not reported
Item Number:	6354
Violation Desc:	WASTE CONTAINER: POOR CONDITION
Inspection Date:	03/19/87
Waste Code:	Not reported
Type of Violation:	6HX0001
Occurrences:	Not reported
Item Number:	6355
Violation Desc:	CONTINGENCY PLAN NOT PROVIDED
<b>HMMD WASTE STREAMS:</b>	
Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAYBILL TERMINALS CO (Continued)**

**S104746152**

Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H05324-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/19/1987  
 Begandt: 8/22/1986

Case Number: H05324-002  
 Agency: CA Regional Water Quality Control Board  
**Funding: Non Billable**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/19/1999  
 Begandt: 1/1/1993

Case Number: H05324-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/11/2007  
 Begandt: 3/16/2004

37

**GRAYBILL TERMINALS CO  
 1531 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100936356  
 SWEEPS UST N/A**

**HAZNET:**

Gepaid: CAD981976269  
 Contact: GRAYBILL TERMINALS CO  
 Telephone: 6192251289  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6306  
 Mailing City,St,Zip: SAN DIEGO, CA 921660306  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 11.2590  
 Facility County: San Diego

Gepaid: CAD981976269

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GRAYBILL TERMINALS CO (Continued)**

**S100936356**

Contact: GRAYBILL TERMINALS CO  
 Telephone: 6192251289  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6306  
 Mailing City,St,Zip: SAN DIEGO, CA 921660306  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Recycler  
 Tons: 2.0850  
 Facility County: San Diego

Gepaid: CAD981976269  
 Contact: GRAYBILL TERMINALS CO  
 Telephone: 6192251289  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6306  
 Mailing City,St,Zip: SAN DIEGO, CA 921660306  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 15.8460  
 Facility County: San Diego

Gepaid: CAD981976269  
 Contact: GRAYBILL TERMINALS CO  
 Telephone: 6192251289  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6306  
 Mailing City,St,Zip: SAN DIEGO, CA 921660306  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 27.1050  
 Facility County: San Diego

Gepaid: CAD981976269  
 Contact: GRAYBILL TERMINALS CO  
 Telephone: 6192251289  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6306  
 Mailing City,St,Zip: SAN DIEGO, CA 921660306  
 Gen County: San Diego  
 TSD EPA ID: KSD981506025  
 TSD County: 99  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Treatment, Incineration  
 Tons: 14.2240

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAYBILL TERMINALS CO (Continued)**

**S100936356**

Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 15 additional CA\_HAZNET: record(s) in the EDR Site Report.

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 5324  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005324-000001  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 5324  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005324-000002  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 5324  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EPA ID Number  
 EDR ID Number

37 GRAYBILL TERMINALS LUST S105035569  
 1531 NATIONAL AVE Cortese N/A  
 SAN DIEGO, CA 92113

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1531 NATIONAL AVE  
 Region: CORTESE  
 Facility Addr2: 1531 NATIONAL AVE

37 GRAYBILL TERMINALS HIST UST U001572960  
 1531 NATIONAL AVE N/A  
 SAN DIEGO, CA 92112

HIST UST:  
 Region: STATE  
 Facility ID: 00000051513  
 Facility Type: Other  
 Other Type: BULK TERMINAL  
 Total Tanks: 0000  
 Contact Name: GIL PICO  
 Telephone: 6192251289  
 Owner Name: GRAYBILL TERMINALS CO.  
 Owner Address: 2913 CANON ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92106  
 Tank Num: 001  
 Container Num: 1  
 Year Installed: 1984  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual  
 Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: 06  
 Tank Construction: Not reported  
 Leak Detection: None

37 GRAYBILL TERMINAL(FORMER) ENVIROSTOR S106797717  
 1551 NATIONAL AVENUE N/A  
 SAN DIEGO, CA 92113

ENVIROSTOR:  
 Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAYBILL TERMINAL(FORMER) (Continued)**

**S106797717**

Division Branch: So Cal - Cypress  
 Facility ID: 37510139  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2004-03-18 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37510139  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

37

**TEEN HEALTH CENTER  
 1643 LOGAN AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104749745  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 154219  
 Inactive Indicator: Active  
 Business Code: 6HK10  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: LOGAN HEIGHTS FAMILY HEALTH CR  
 Mailing Address: 1643 LOGAN AVE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEEN HEALTH CENTER (Continued)**

**S104749745**

Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/06/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: NANCY BRYANT WALLIS OR CLARA C  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FAMILY HEALTH CENTERS OF SAN D  
 Property Address: 823 GATEWAY CENTER W  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/06/07  
 Facility Phone: 619-515-2333

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/09/98  
 Waste Code: Not reported  
 Type of Violation: 6HV4301  
 Occurrences: Not reported  
 Item Number: 1127  
 Violation Desc: MWMP NOT SUBMITTED TO HMD  
  
 Inspection Date: 02/09/98  
 Waste Code: Not reported  
 Type of Violation: 6HV4303

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEEN HEALTH CENTER (Continued)**

**S104749745**

Occurrences: Not reported  
 Item Number: 1128  
 Violation Desc: NO MED WASTE DISPOSAL RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: 08/06/04  
 Waste Item #: 901  
 Waste Code: 901  
 Waste Name: INFECTIOUS WASTE, GE  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BAG  
 Haz Waste Hauler: 3400 STERICYCLE, INC  
 Waste Desc: RED BAG WASTE  
 Carcinogen: No

Inspection Date: 08/06/04  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: CARBOY  
 Haz Waste Hauler: 3400 STERICYCLE, INC  
 Waste Desc: SHARPS  
 Carcinogen: No

37

**HUGHES ATTORNEY SERVICE INC**  
**1643 LOGAN AV**  
**V, CA 92113**

**San Diego Co. HMMD S106061834**  
**N/A**

San Diego Co. HMMD:

Facility ID: 121201  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City, St, Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HUGHES ATTORNEY SERVICE INC (Continued)**

**S106061834**

Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FAMILY HEALTH CENTERS OF SAN D  
 Property Address: 823 GATEWAY CENTER W  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT3771  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: AT3771  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HUGHES ATTORNEY SERVICE INC (Continued)**

**S106061834**

Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

37

**HUGHES ATTORNEY SERVICE INC  
 1643 LOGAN AV  
 SAN DIEGO, CA 92113**

**LUST S105690250  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302174  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-06-20 00:00:00  
 Discover Date: 1997-02-25 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1997-02-25 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 1  
 Contact Person: Not reported  
 Responsible Party: JAMES M HUGHES  
 RP Address: P O BOX 82125  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HUGHES ATTORNEY SERVICE INC (Continued)**

**S105690250**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21201-001  
 Case Number: 9UT3411  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H21201-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/20/1997  
 Begandt: 2/25/1997

37

**JAMES M HUGHES  
 1643 LOGAN AVE  
 SAN DIEGO, CA 92101**

**HAZNET S103634616  
 N/A**

**HAZNET:**

Gepaid: CAC000768264  
 Contact: JAMES M HUGHES  
 Telephone: 6196832000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 82125  
 Mailing City,St,Zip: SAN DIEGO, CA 921380000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 3.0232  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**37 HUGHES ATTORNEY SERVICES  
 1643 LOGAN AVE  
 SAN DIEGO, CA 92101**

**LUST S102532384  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT3411  
 Local Agency: San Diego  
 Substance: Premium Gasoline  
 Qty Leaked: 0  
 Date Found: 02/25/1997  
 How Found: Tank Closure  
 Date Stopped: 02/25/1997  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 03/05/1997  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 3/7/97  
 Closed Date: 6/20/97  
 Pilot Program: LOP  
 Local Case: H21201-001  
 Basin Number: 908.21  
 Gwater Depth: 29'  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/LOW - LOW POTENTIAL HEALTH/SAFTY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 03/07/1997  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 1643 LOGAN AVE

**37 GATEWAY HOUSING INVESTMENT LP  
 1637 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET S108747737  
 N/A**

HAZNET:

Gepaid: CAC002600443  
 Contact: PETE HARISPURU  
 Telephone: 5622562091  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 320 GOLDENSHORE STE 200  
 Mailing City,St,Zip: LONG BEACH, CA 90802

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GATEWAY HOUSING INVESTMENT LP (Continued)**

**S108747737**

Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.92  
 Facility County: San Diego

37

**QUALITY CABINET & FIXTURE CO. INC  
 939 S 16TH ST  
 SAN DIEGO, CA 92113**

**FINDS 1000287361  
 RCRA-NonGen CAD043315589**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-NonGen:**

Date form received by agency: 07/09/1980  
 Facility name: QUALITY CABINET & FIXTURE CO. INC  
 Facility address: 939 S 16TH ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD043315589  
 Mailing address: S 16TH ST  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 939 S 16TH ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (714) 233-6531  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**QUALITY CABINET & FIXTURE CO. INC (Continued)**

**1000287361**

Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

37

**QUALITY CABINET & FIXTURES CO  
 939 S 16TH ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S100725589  
 N/A**

San Diego Co. HMMD:

Facility ID: 101266  
 Inactive Indicator: Active  
 Business Code: 6HK07  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FLORES HERLINDA TR  
 Property Address: 1728 NATIONAL AVE  
 Property City,St,Zip: 92113

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

**QUALITY CABINET & FIXTURES CO (Continued)**

**S100725589**

Tank Owner: Not reported  
Tank Address: Not reported  
Tank City,St,Zip: Not reported  
Business Plan Acceptance Date: Not reported  
Reinspection Date Y2K Compatible: Not reported  
Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
Chemical Name: Not reported  
Case Number: Not reported  
Quantity Stored At One Time: Not reported  
Quantity Stored at One Time: Not reported  
Annual Quantity String: Not reported  
Annual Quantity String: Not reported  
Measurement Units: Not reported  
Carcinogen: No  
1st Hazard Category: Not reported  
2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
Tank ID Number: Not reported  
Waste or Product: Not reported  
Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
Waste Code: Not reported  
Type of Violation: Not reported  
Occurrences: Not reported  
Item Number: Not reported  
Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
Waste Item #: Not reported  
Waste Code: Not reported  
Waste Name: Not reported  
Qty at Inspection: Not reported  
Quantity String: Not reported  
Annual Qty: Not reported  
Annual Qty String: Not reported  
Measurement Unit: Not reported  
Treatment Method: Not reported  
Storage Method: Not reported  
Haz Waste Hauler: Not reported  
Waste Desc: Not reported  
Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37 PEPPER INDUSTRIES INC  
 1501 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**FINDS 1000346321  
 LUST CAD054783220  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM  
 RCRA-NonGen**

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608104175  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1994-10-25 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: DAVID ALLSBROOK  
 RP Address: 225 BROADWAY SUITE 1100  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PEPPER INDUSTRIES INC (Continued)**

**1000346321**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14546-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 114546  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 110 W C ST #110  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAD054783220  
 Gas Station: Not reported  
 Inspection Date: 05/11/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: PAUL PEPPER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO METROPOLITAN TRANSIT  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PEPPER INDUSTRIES INC (Continued)**

**1000346321**

Facility Phone: 619-234-3361

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H14546-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 10/25/1994  
 Begandt: 9/20/1994

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PEPPER INDUSTRIES INC (Continued)**

**1000346321**

RCRA-NonGen:

Date form received by agency: 07/08/1986  
 Facility name: PEPPER INDUSTRIES INC  
 Facility address: 1501 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD054783220  
 Mailing address: NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1501 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 234-3361  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: PAUL W PEPPER  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**PEPPER INDUSTRIES INC (Continued)**

**1000346321**

Violation Status: No violations found

**37**

**HENRY'S TRANSMISSION SHOP  
1603 LOGAN AV  
SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104747940  
N/A**

San Diego Co. HMMD:

Facility ID:	113709
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1603 LOGAN AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	51
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	03/27/90
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	HENRY ALLEN
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	FLORES HERLINDA TR
Property Address:	1728 NATIONAL AVE
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-234-0962

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HENRYS TRANSMISSION SHOP (Continued)**

**S104747940**

Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 113758  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FLORES HERLINDA TR  
 Property Address: 1728 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HENRYS TRANSMISSION SHOP (Continued)**

**S104747940**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID Direction Distance Distance (ft.)Site Database(s) EPA ID Number EDR ID Number

37 AMERICAN & FOREIGN AUTO W. CA WDS S106101093  
 1615 LOGAN AVE N/A  
 SAN DIEGO, CA 92113

CA WDS:  
 Facility ID: San Diego 371010093  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: JESSE M. VASQUEZ  
 Agency Address: 1615 LOGAN AVE  
 Agency City,St,Zip: SAN DIEGO 92113  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.  
 Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

37 AMERICAN & FOREIGN AUTO WRECKI HAZNET S103634054  
 1615 LOGAN AVE N/A  
 SAN DIEGO, CA 92113

HAZNET:  
 Gepaid: CAL000003877  
 Contact: VASQUEZ JESSE M  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1615 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN & FOREIGN AUTO WRECKI (Continued)**

**S103634054**

Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: .1500  
 Facility County: San Diego

Gepaid: CAL000003877  
 Contact: VASQUEZ JESSE M  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1615 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Recycler  
 Tons: .1251  
 Facility County: San Diego

Gepaid: CAL000003877  
 Contact: VASQUEZ JESSE M  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1615 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Recycler  
 Tons: .1668  
 Facility County: San Diego

Gepaid: CAL000003877  
 Contact: VASQUEZ JESSE M  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1615 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Recycler  
 Tons: .2085  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37 LUIS AUTO SERVICES  
 1603 LOGAN AV  
 SAN DIEGO, CA 92113**

**LUST S106874830  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T06019701706  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-09-06 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Lubricating Oil  
 Contact Person: Not reported  
 Responsible Party: Susan Han  
 RP Address: 531 Encinitas Blvd., Ste. 206  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13758-001  
 Case Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LUIS AUTO SERVICES (Continued)**

**S106874830**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H13758-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 11/15/2004  
 Begandt: Not reported

37

**AMERICAN & FOREIGN AUTO RECYCL  
 1615 LOGAN AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104748441  
 N/A**

**San Diego Co. HMMD:**

Facility ID: 115397  
 Inactive Indicator: Active  
 Business Code: 6HK32  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1615 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000003877  
 Gas Station: Not reported  
 Inspection Date: 03/13/02  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JESSE VASQUEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FLORES HERLINDA TR  
 Property Address: 1728 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN & FOREIGN AUTO RECYCL (Continued)**

**S104748441**

Facility Phone: 619-234-1905

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/12/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1969  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 06/14/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5225  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5491  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**AMERICAN & FOREIGN AUTO RECYCL (Continued)**

**S104748441**

Waste Desc: Not reported  
 Carcinogen: No

**37 GATEWAY ONE HOUSING INVESTORS LP  
 1603 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET S108747739  
 N/A**

HAZNET:  
 Gepaid: CAC002607737  
 Contact: MERIDETH MADOLE/PROJ MGR  
 Telephone: 5622562062  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 320 GOLDEN SHORE STE 200  
 Mailing City,St,Zip: LONG BEACH, CA 90802  
 Gen County: San Diego  
 TSD EPA ID: AZR000002428  
 TSD County: 99  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Land Fill  
 Tons: 14.32  
 Facility County: San Diego

**37 RELIABLE PIPE SUPPLY  
 1430 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST S104746213  
 San Diego Co. HMMD N/A  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608152064  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-02-01 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RELIABLE PIPE SUPPLY (Continued)**

**S104746213**

Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MV  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05613-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 105613  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1430 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/02/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RELIABLE PIPE SUPPLY (Continued)**

**S104746213**

Facility Contact: ARNOLD HAMM  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RELIABLE PIPE SUPPLY CO INC  
 Property Address: P O BOX 120522  
 Property City,St,Zip: 92112  
 Tank Owner: RELIABLE PIPE SUPPLY  
 Tank Address: 1430 NATIONAL AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-0618

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RELIABLE PIPE SUPPLY (Continued)**

**S104746213**

Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 116468  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1526 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/06/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: BOB LUNA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RELIABLE PIPE SUPPLY CO INC  
 Property Address: P O BOX 120522  
 Property City,St,Zip: 92112  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/06/05  
 Facility Phone: 619-233-0118

**HMMD DISCLOSURE INVENTORY:**

Item Number: OX80  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR79  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RELIABLE PIPE SUPPLY (Continued)**

**S104746213**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 06/26/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 4353  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 06/26/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4354  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 06/26/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4355  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 06/26/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4356  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 11/09/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9287  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 08/14/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8334  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/14/97

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RELIABLE PIPE SUPPLY (Continued)**

**S104746213**

Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8335  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/14/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 8336  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 08/14/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8337  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/02/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9374  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H05613-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 2/1/1988  
 Begandt: 2/17/1987



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37 RELIABLE PIPE SUPPLY  
 1430 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100727082  
 SWEEPS UST N/A**

HAZNET:

Gepaid: CAL913433317  
 Contact: PAULA C MENDELL  
 Telephone: 6192330118  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 120522  
 Mailing City,St,Zip: SAN DIEGO, CA 921120522  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Not reported  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL913433317  
 Contact: PAULA C MENDELL  
 Telephone: 6192330118  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 120522  
 Mailing City,St,Zip: SAN DIEGO, CA 921120522  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL913433317  
 Contact: PAULA C MENDELL  
 Telephone: 6192330118  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 120522  
 Mailing City,St,Zip: SAN DIEGO, CA 921120522  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: .5000  
 Facility County: San Diego

Gepaid: CAL913433317  
 Contact: PAULA C MENDELL  
 Telephone: 6192330118  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 120522  
 Mailing City,St,Zip: SAN DIEGO, CA 921120522  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RELIABLE PIPE SUPPLY (Continued)**

**S100727082**

TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: 0.75  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 5613  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005613-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: WASTE  
 Content: LEADED  
 Number Of Tanks: 1

37

**PENSKE TRUCK LEASING INC  
 1402 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**LUST U003789319  
 UST N/A  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607301054  
 Stop Date: 1992-10-01 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2004-04-22 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1992-10-01 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-10-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: Richard Saut  
 RP Address: Route 10, Green Hills, P.O. Box 7635  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: KK  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H12141-001  
 Case Number: 9UT2288  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H12141

San Diego Co. HMMD:

Facility ID: 112141  
 Inactive Indicator: Active  
 Business Code: 6HK17  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ROUTE 10, GREEN HILLS  
 Mailing Address: P O BOX 7635  
 Mailing City, St, Zip: READING, PA 19603  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAL000012800  
 Gas Station: Not reported  
 Inspection Date: 12/09/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JEFF SHULTZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PENSKE TRUCK LEASING CO L P  
 Property Address: ATTN REAL ESTATE DEP  
 Property City,St,Zip: 19603  
 Tank Owner: HERTZ PENSKE TRUCK LEASING INC  
 Tank Address: 1402 COMMERCIAL ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 11/15/05  
 Facility Phone: 619-233-1145

**HMMD DISCLOSURE INVENTORY:**

Item Number: DI53  
 Chemical Name: DIESEL UNDERGROUND TANK 112141 T004  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: EH12  
 Chemical Name: EHTYLENE GLYCOL  
 Case Number: 107-21-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: FR46  
 Chemical Name: FREON 3X 30LB R134A  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: RE52  
 Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 112141 T005  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: TR45  
 Chemical Name: TRANSMISSION FLUID  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 6831 REGUL  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 6832  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: 6833  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: NT1654 REG  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T005  
 Tank ID Number: NT1654 DIE  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 11/04/98  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	9161
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	03/08/02
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	5277
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	03/08/02
Waste Code:	Not reported
Type of Violation:	6HV0216
Occurrences:	Not reported
Item Number:	5278
Violation Desc:	HAZMATS WITHOUT PROPER LABELS
Inspection Date:	03/08/02
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	5279
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	03/08/02
Waste Code:	Not reported
Type of Violation:	6HX3011
Occurrences:	Not reported
Item Number:	5280
Violation Desc:	FAIL TO COMPLY WITH OP PERMIT CONDITIO
Inspection Date:	03/08/02
Waste Code:	Not reported
Type of Violation:	6HX3013
Occurrences:	Not reported
Item Number:	5281
Violation Desc:	NO FINANCIAL RESPOSIBILITY DOC
Inspection Date:	03/08/02
Waste Code:	Not reported
Type of Violation:	6HX3029
Occurrences:	Not reported
Item Number:	5282
Violation Desc:	SPILL/OVERFILL PREVENTION NOT INSTALLED
Inspection Date:	03/08/02
Waste Code:	Not reported
Type of Violation:	6HX3030
Occurrences:	Not reported
Item Number:	5283
Violation Desc:	NO RELEASE RECORD LOG
Inspection Date:	02/11/03
Waste Code:	Not reported
Type of Violation:	6HV3104

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

Occurrences: Not reported  
 Item Number: 7100  
 Violation Desc: FACILITY AND DETAIL FORMS NOT SUBMITTED

Inspection Date: 02/11/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3109  
 Occurrences: Not reported  
 Item Number: 7101  
 Violation Desc: MONITORING PLOT PLAN NOT SUBMITTED

Inspection Date: 02/11/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3151  
 Occurrences: Not reported  
 Item Number: 7102  
 Violation Desc: RELEASES NOT REPORTED/RECORDED

Inspection Date: 02/11/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3152  
 Occurrences: Not reported  
 Item Number: 7103  
 Violation Desc: MAINT. & MONITORING RECORDS AVAILABLE

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6446  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 6447  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 6448  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1601  
 Occurrences: Not reported  
 Item Number: 6449  
 Violation Desc: HAZWASTE TANKS W/O P.E. ASSESSMENT

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3109  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

Item Number: 6450  
 Violation Desc: MONITORING PLOT PLAN NOT SUBMITTED

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3255  
 Occurrences: Not reported  
 Item Number: 6451  
 Violation Desc: SPILL CONT NOT DRY & IN GOOD CONDITI

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3255  
 Occurrences: Not reported  
 Item Number: 6452  
 Violation Desc: SPILL CONT NOT DRY & IN GOOD CONDITI

Inspection Date: 11/15/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 6453  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3105  
 Occurrences: Not reported  
 Item Number: 5971  
 Violation Desc: FINANCIAL RESPONSIBILITY EXPIRED

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3109  
 Occurrences: Not reported  
 Item Number: 5972  
 Violation Desc: MONITORING PLOT PLAN NOT SUBMITTED

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3256  
 Occurrences: Not reported  
 Item Number: 5973  
 Violation Desc: FILL BOX DRAIN DOESN'T WORK

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3265  
 Occurrences: Not reported  
 Item Number: 5974  
 Violation Desc: SYS NOT RUN TO PREVENT SPILL/OVERFILL

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 5975



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 5976  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3402  
 Occurrences: Not reported  
 Item Number: 5977  
 Violation Desc: PUMP DOESN'T SHUT OFF IF MONITOR DISCONN

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3402  
 Occurrences: Not reported  
 Item Number: 5978  
 Violation Desc: PUMP DOESN'T SHUT OFF IF MONITOR DISCONN

**HMMD WASTE STREAMS:**

Inspection Date: 12/09/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 194  
 Annual Qty String: 194  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: SAFETY KLEEN - 1 UNIT  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 3645  
 Annual Qty String: 3645  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0242 EVERGREEN ENVIRONMEN  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 343  
 Waste Code: 343

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 400  
 Quantity String: 400  
 Annual Qty: 870  
 Annual Qty String: 870  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0242 EVERGREEN ENVIRONMEN  
 Waste Desc: WASTE ANTIFREEZE X 2 AST  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 231  
 Quantity String: 231  
 Annual Qty: 462  
 Annual Qty String: 462  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: GAS/FUEL FILTERS  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0242 EVERGREEN ENVIRONMEN  
 Waste Desc: CONTAMINATED ABSORBENT  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: INTER STATE  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PENSKE TRUCK LEASING INC (Continued)**

**U003789319**

Inspection Date: 12/09/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 800  
 Quantity String: 800  
 Annual Qty: 3600  
 Annual Qty String: 3600  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0242 EVERGREEN ENVIRONMEN  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H12141-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: POP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 4/22/2004  
 Begandt: 10/1/1992

37

**HERTZ - PENSKE TRUCK LEASING  
 1402 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**LUST S101301949  
 Cortese N/A  
 SWEEPS UST**

**LUST:**

Region: 9  
 Case Number: 9UT2288  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 10/01/1992  
 How Found: Tank Closure  
 Date Stopped: 10/01/1992  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 10/01/1992  
 Submit Workplan: 10/1/92  
 Prelim Assess: 10/01/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H12141-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HERTZ - PENSKE TRUCK LEASING (Continued)**

**S101301949**

Basin Number: 908.22  
 Gwater Depth: 7.5'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 10/01/1992  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

SWEEPS UST:

Status: A  
 Comp Number: 12141  
 Number: 9  
 Board Of Equalization: 44-015979  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012141-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 3

Status: A  
 Comp Number: 12141  
 Number: 9  
 Board Of Equalization: 44-015979  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012141-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 12141  
 Number: 9  
 Board Of Equalization: 44-015979  
 Ref Date: Not reported  
 Act Date: 06-26-92

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HERTZ - PENSKE TRUCK LEASING (Continued)**

**S101301949**

Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012141-000003  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

37

**G E O AUTO DISMANTLING  
 1610 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**HAZNET 1000249794  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAD982025595  
 Contact: DAN C HUMASON  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1610 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: .2210  
 Facility County: San Diego

Gepaid: CAD982025595  
 Contact: DAN C HUMASON  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1610 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD982025595  
 Contact: DAN C HUMASON  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1610 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**G E O AUTO DISMANTLING (Continued)**

**1000249794**

Tons: .0000  
 Facility County: San Diego  
  
 Gepaid: CAD982025595  
 Contact: DAN C HUMASON  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1610 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMMD:

Facility ID: 102627  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1610 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAD982025595  
 Gas Station: Not reported  
 Inspection Date: 10/16/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: GILBERT E ORTEGA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SVDP MANAGEMENT INC  
 Property Address: 3350 E ST  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-2333

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**G E O AUTO DISMANTLING (Continued)**

**1000249794**

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/09/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4674  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 08/09/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4670  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/09/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 4671  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

Inspection Date: 08/09/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 4672  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 08/09/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4673  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 10/13/97

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**G E O AUTO DISMANTLING (Continued)**

**1000249794**

Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 9195  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 10/13/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9196  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/13/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9197  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 10/13/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9198  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 10/16/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9304  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 10/16/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 9305  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No



MAP FINDINGS

Map ID Direction Distance Distance (ft.)Site Database(s) EPA ID Number EDR ID Number

37 B&L MASONRY, INC.  
#9 17TH ST.  
SAN DIEGO, CA 92101

HIST UST U001572536  
N/A

HIST UST:  
Region: STATE  
Facility ID: 00000033173  
Facility Type: Other  
Other Type: MASONRY CONTRACTOR  
Total Tanks: 0002  
Contact Name: Not reported  
Telephone: 6192360293  
Owner Name: B&L MASONRY, INC.  
Owner Address: #9 17TH ST.  
Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
Container Num: 1  
Year Installed: Not reported  
Tank Capacity: 00000550  
Tank Used for: PRODUCT  
Type of Fuel: REGULAR  
Tank Construction: Not reported  
Leak Detection: None

Tank Num: 002  
Container Num: 2  
Year Installed: Not reported  
Tank Capacity: 00000550  
Tank Used for: PRODUCT  
Type of Fuel: REGULAR  
Tank Construction: Not reported  
Leak Detection: None

37 MR PARTS OPS DIVISION  
16 15TH ST  
SAN DIEGO, CA 92101

RCRA-SQG 1000345289  
FINDS CAD981666084

RCRA-SQG:  
Date form received by agency: 09/01/1996  
Facility name: MR PARTS OPS DIVISION  
Facility address: 16 15TH ST  
SAN DIEGO, CA 92101  
EPA ID: CAD981666084  
Mailing address: PO BOX 9000  
LEMON GROVE, CA 92045  
Contact: Not reported  
Contact address: Not reported  
Not reported  
Contact country: Not reported  
Contact telephone: Not reported  
Contact email: Not reported  
EPA Region: 09  
Classification: Small Small Quantity Generator  
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MR PARTS OPS DIVISION (Continued)**

**1000345289**

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: CARDIS CORPORATION  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 10/14/1986  
 Facility name: MR PARTS OPS DIVISION  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

37 ST.VINCENT DE PAUL  
 16 15TH ST  
 SAN DIEGO, CA 92101

SAN DIEGO CO. SAM

S108407258  
 N/A

SAN DIEGO CO. SAM:

Case Number: H03652-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 7/20/1986  
 Begandt: 10/22/1986

Case Number: H03652-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/25/1993  
 Begandt: 4/29/1992

Case Number: H03652-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/17/2004  
 Begandt: 2/24/1993

37 DEWITT TRANSFER AND STORAGE  
 16 15TH ST  
 SAN DIEGO, CA 92101

HIST UST

U001572554  
 N/A

HIST UST:

Region: STATE  
 Facility ID: 00000004426  
 Facility Type: Other  
 Other Type: MOVING & STORAGE  
 Total Tanks: 0001  
 Contact Name: SAM GRIZZLE  
 Telephone: 6192346523  
 Owner Name: DEWITT TRANSFER AND STORAGE CO  
 Owner Address: 16 15TH STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Visual, None

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**37 ST. VINCENT DEPAUL  
 16 15TH ST  
 SAN DIEGO, CA 92101**

**LUST S102438027  
 Cortese N/A  
 San Diego Co. HMMD  
 SWEEPS UST**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301032  
 Stop Date: 1992-04-29 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-03-25 00:00:00  
 Discover Date: 1992-04-29 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-04-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: ATTN: PAT MACK  
 RP Address: 9089 CLAIREMONT MESA BLVD  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03652-002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ST. VINCENT DEPAUL (Continued)**

**S102438027**

Case Number: 9UT2265  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608154919  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1986-07-20 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MV  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ST. VINCENT DEPAUL (Continued)**

**S102438027**

Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03652-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0608195870  
 Stop Date: 1993-02-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-05-17 00:00:00  
 Discover Date: 1993-02-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1993-02-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: St. Vincent de Paul Center  
 RP Address: 3350 E Street  
 Interim: Not reported  
 Oversight Prgm: LOCNL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ST. VINCENT DEPAUL (Continued)**

**S102438027**

MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: TS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03652-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT2265  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 04/29/1992  
 How Found: Other Means  
 Date Stopped: 04/29/1992  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: 06/08/1992  
 Submit Workplan: 6/17/92  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 3/19/93  
 Pilot Program: LOP  
 Local Case: H03652-002  
 Basin Number: 908.22  
 Gwater Depth: 7.0'  
 Beneficial Use: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ST. VINCENT DEPAUL (Continued)**

**S102438027**

NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 04/29/1992  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 16 15TH ST

San Diego Co. HMMD:

Facility ID: 103652  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ST. VINCENT DE PAUL  
 Mailing Address: 16 15TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 02/19/92  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: KEITH MCKAY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MIRABILE HOUSING L P  
 Property Address: 3350 E ST  
 Property City,St,Zip: 92102  
 Tank Owner: DEWITT TRANSFER AND STORAGE CO  
 Tank Address: 16 P O BOX 82109  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-8797

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ST. VINCENT DEPAUL (Continued)**

**S102438027**

Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 11/14/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 7590  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 11/14/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3004  
 Occurrences: Not reported  
 Item Number: 7591  
 Violation Desc: NO SIR DATA TO LOCAL AGENCY

Inspection Date: 11/14/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3006  
 Occurrences: Not reported  
 Item Number: 7592  
 Violation Desc: DID NOT MEET REQS FOR TEMP CLOSURE

Inspection Date: 12/23/88  
 Waste Code: Not reported  
 Type of Violation: 6HX3002  
 Occurrences: Not reported  
 Item Number: 6923  
 Violation Desc: UST OWNR-OPR W/O HEALTH PERMIT

Inspection Date: 12/23/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0074  
 Occurrences: Not reported  
 Item Number: 6924  
 Violation Desc: UST MONITOR IN POOR CONDITION

Inspection Date: 12/23/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0084  
 Occurrences: Not reported  
 Item Number: 6925  
 Violation Desc: UST PRECISION TEST DATA NOT SENT TO HMMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ST. VINCENT DEPAUL (Continued)**

**S102438027**

Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 3652  
 Number: Not reported  
 Board Of Equalization: 44-021923  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003652-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 3652  
 Number: 9  
 Board Of Equalization: 44-021923  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

MAP FINDINGS

Map ID Direction Distance Distance (ft.)Site Database(s) EPA ID Number EDR ID Number

**37 SAINT VINCENT DE PAUL VILLAGE SLIC S106519121**  
**15TH / 16TH STREETS**  
**SAN DIEGO, CA 92102 N/A**

SLIC:  
 Region: 9  
 Facility Type: Not reported  
 Status: Dead  
 Code: 20-0339.02  
 Waste Discharger Id: 9 000339N99  
 Local Case Num: Not reported  
 Responsible Party: JOAN KROC CENTER  
 Category: GENERAL  
 Class: SLIC  
 Order Number: Not reported  
 File Number: 1  
 Date Entered: Not reported  
 End Date: Not reported  
 Archive Box #: 928  
 Archive Box Storage: 3-1-15F  
 Archive Box Storage Location: Not reported  
 Remarks: Not reported

Region: 9  
 Facility Type: Not reported  
 Status: Dead  
 Code: 20-0339.051  
 Waste Discharger Id: 9 000339N99  
 Local Case Num: Not reported  
 Responsible Party: JOAN KROC CENTER  
 Category: REPORT  
 Class: SLIC  
 Order Number: Not reported  
 File Number: 1  
 Date Entered: Not reported  
 End Date: Not reported  
 Archive Box #: 928  
 Archive Box Storage: 3-1-15F  
 Archive Box Storage Location: Not reported  
 Remarks: Not reported

**37 SAINT VINCENT DE PAUL HAZNET S103631875**  
**1501 IMPERIAL AVE SWEEPS UST N/A**  
**SAN DIEGO, CA 92101**

HAZNET:  
 Gepaid: CAL000144401  
 Contact: NON-PROFIT MEDICAL CLINIC  
 Telephone: 6192338500  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1501 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921017638  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .0025  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAINT VINCENT DE PAUL (Continued)**

**S103631875**

Gepaid: CAL000144401  
 Contact: NON-PROFIT MEDICAL CLINIC  
 Telephone: 6192338500  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1501 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921017638  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: .0050  
 Facility County: San Diego

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 24762  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-024762-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

37

**SAINT VINCENT DE PAUL  
 1501 IMPERIAL AV  
 SAN DIEGO, CA 92101**

**San Diego Co. HMMD S104750598  
 SAN DIEGO CO. SAM N/A**

San Diego Co. HMMD:  
 Facility ID: 124762  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1222 01ST AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAINT VINCENT DE PAUL (Continued)**

**S104750598**

Facility Contact: PAUL GALLARDO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: S V D P MANAGEMENT INC  
 Property Address: 3350 E ST  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-236-7051

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAINT VINCENT DE PAUL (Continued)**

**S104750598**

Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 150921  
 Inactive Indicator: Active  
 Business Code: 6HK10  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: VILLAGE FAMILY HEALTH CTR.  
 Mailing Address: 1501 IMPERIAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: CAL000144401  
 Gas Station: Not reported  
 Inspection Date: 09/08/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: TERESA SIMMS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: S V D P MANAGEMENT INC  
 Property Address: 3350 E ST  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/08/07  
 Facility Phone: 619-233-8500

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAINT VINCENT DE PAUL (Continued)**

**S104750598**

**HMMD VIOLATIONS:**

Inspection Date: 08/17/95  
 Waste Code: Not reported  
 Type of Violation: 6HX4008  
 Occurrences: Not reported  
 Item Number: 2680  
 Violation Desc: MEDWASTE CONTAINER IMPROP LABELED

Inspection Date: 08/17/95  
 Waste Code: Not reported  
 Type of Violation: 6HX4011  
 Occurrences: Not reported  
 Item Number: 2681  
 Violation Desc: MED SOLID WASTE NOT SECURED

Inspection Date: 08/27/98  
 Waste Code: Not reported  
 Type of Violation: 6HX4053  
 Occurrences: Not reported  
 Item Number: 6965  
 Violation Desc: NO DISPOSAL MANIFEST/RECEIPTS ONSITE

Inspection Date: 08/21/01  
 Waste Code: Not reported  
 Type of Violation: 6HX4113  
 Occurrences: Not reported  
 Item Number: 8839  
 Violation Desc: NO GENERATOR'S LABEL IN SHARPS & RED BAG

Inspection Date: 09/08/04  
 Waste Code: Not reported  
 Type of Violation: 6HV4204  
 Occurrences: Not reported  
 Item Number: 4670  
 Violation Desc: WARNING SIGN NOT POSTED

**HMMD WASTE STREAMS:**

Inspection Date: 09/08/04  
 Waste Item #: 541  
 Waste Code: 541  
 Waste Name: PHOTOCHEM/PHOTOPROC  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: CARBOY  
 Haz Waste Hauler: 3041 FREEDOM IMAGING INC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 09/08/04  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAINT VINCENT DE PAUL (Continued)**

**S104750598**

Qty at Inspection: 25  
 Quantity String: 25  
 Annual Qty: 180  
 Annual Qty String: 180  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: BOX  
 Haz Waste Hauler: 3400 STERICYCLE INC.  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 09/08/04  
 Waste Item #: 905  
 Waste Code: 905  
 Waste Name: INFECTIOUS WASTE, LA  
 Qty at Inspection: 40  
 Quantity String: 40  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: BAG  
 Haz Waste Hauler: 3400 STERICYCLE INC.  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H24762-001  
 Agency: CA Regional Water Quality Control Board  
**Funding: Non Billable**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/9/1999  
 Begandt: Not reported

37

**STUDIO 15  
 70 15TH ST  
 SAN DIEGO, CA 92113**

**SAN DIEGO CO. SAM S108407259  
 N/A**

SAN DIEGO CO. SAM:

Case Number: H39697-001  
 Agency: CA Department of Toxic Substance Control  
**Funding: Non Billable**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 10/12/2006  
 Begandt: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**37 STUDIO 15  
 70 15TH STREET  
 SAN DIEGO, CA 92101**

**VCP S108195978  
 ENVIROSTOR N/A**

VCP:

Facility ID: 60000490  
 Site Type: Voluntary Cleanup  
 Site Type Detail: Voluntary Cleanup  
 Acres: .64  
 National Priorities List: NO  
 Cleanup Oversight Agencies: SMBRP  
 Lead Agency: SMBRP  
 Lead Agency Description: DTSC - Site Mitigation And Brownfield Reuse Program  
 Project Manager: MARYAM TASNIF-ABBASI  
 Supervisor: Greg Holmes  
 Division Branch: So Cal - Cypress  
 Site Code: 401329  
 Assembly: 79  
 Senate: 39  
 Special Programs Code: CLRRRA Liability Immunity (AB 389)  
 Status: Active  
 Status Date: 2006-11-20 00:00:00  
 Restricted Use: NO  
 Funding: Responsible Party  
 Lat/Long: 32.70596 / -117.15036  
 Alias Name: 535-621-01  
 60000490  
 401329  
 Alias Type: APN  
 Project Code (Site Code)  
 Envirostor ID Number

APN: 535-621-01  
 APN Description: Not reported  
 Comments: The workplan was approved by DTSC.DTSC has completed its review and no written comments are needed at this time.This letter projects the number of hours DTSC may expend on the project during the 2008 calender year. This is just an estimate and could change based on project needs.Fact sheet was approved and mailed out on 4/30/07"There were no comments or concerns expressed by the public regarding this Addendum. The task is completed, no additional tasks are needed.""RsP for Soil was approved, with outstanding items needed in order to fill criteria of ""appropriate care"" for the site under the AB 389/CLRRRA Agreement."

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Investigation/Characterization Report  
 Completed Date: 12/13/06  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Remedial Action Plan  
 Completed Date: 06/28/07  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Fact Sheets  
 Completed Date: 05/01/07

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**STUDIO 15 (Continued)**

**S108195978**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Other Report  
 Completed Date: 06/04/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Other Report  
 Completed Date: 05/04/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Remedial Action Completion Report  
 Completed Date: 12/31/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: California Land Reuse and Revitalization Agreement  
 Completed Date: 11/20/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Correspondence - Sent  
 Completed Date: 01/03/08

Confirmed: 30013,, ,30022,30027,30136,30156,30195,30013,3002502-NO  
 Confirmed Description: Lead  
 Confirmed Description: Not reported  
 Confirmed Description: Tetrachloroethylene (PCE)  
 Confirmed Description: Tetrachloroethylene (PCE)  
 Confirmed Description: Trichloroethylene (TCE)  
 Confirmed Description: Chloroform  
 Confirmed Description: Copper and compounds  
 Confirmed Description: 1,2-Dichloroethylene (cis)  
 Confirmed Description: Lead  
 Confirmed Description: Not reported  
 Future Area Name: PROJECT WIDE  
 Future Sub Area Name: Not reported  
 Future Document Type: Operations and Maintenance Plan  
 Future Due Date: 2008  
 Future Area Name: PROJECT WIDE  
 Future Sub Area Name: Not reported  
 Future Document Type: Certification  
 Future Due Date: 2008  
 Future Area Name: PROJECT WIDE  
 Future Sub Area Name: Not reported  
 Future Document Type: Deed Restriction / Land Use Covenant  
 Future Due Date: 2008  
 Media Affected: SOIL  
 Media Affected Desc: Soil

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30013, 30022, 3002502, 30027, 30136, 30156, 30195  
 Potential Description: Lead  
 Potential Description: Tetrachloroethylene (PCE)  
 Potential Description: TPH-MOTOR OIL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**STUDIO 15 (Continued)**

**S108195978**

Potenital Description: Trichloroethylene (TCE)  
 Potenital Description: Chloroform  
 Potenital Description: Copper and compounds  
 Potenital Description: 1,2-Dichloroethylene (cis)  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: FUEL - VEHICLE STORAGE/ REFUELING, MANUFACTURING - CHEMICALS,  
 MANUFACTURING - METAL, RETAIL - VEHICLES, TRANSPORTATION - WAREHOUSING

**ENVIROSTOR:**

Site Type: Voluntary Cleanup  
 Site Type Detailed: Voluntary Cleanup  
 Acres: .64  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP  
 Program Manager: MARYAM TASNIF-ABBASI  
 Supervisor: Greg Holmes  
 Division Branch: So Cal - Cypress  
 Facility ID: 60000490  
 Site Code: 401329  
 Assembly: 79  
 Senate: 39  
 Special Program: CLRRRA Liability Immunity (AB 389)  
 Status: Active  
 Status Date: 2006-11-20 00:00:00  
 Restricted Use: NO  
 Funding: Responsible Party  
 Latitude: 32.70596  
 Longitude: -117.15036  
 Alias Name: 535-621-01  
 60000490  
 401329  
 Alias Type: APN  
 Project Code (Site Code)  
 Envirostor ID Number

APN: 535-621-01  
 APN Description: Not reported  
 Comments: The workplan was approved by DTSC.DTSC has completed its review and no written comments are needed at this time.This letter projects the number of hours DTSC may expend on the project during the 2008 calender year. This is just an estimate and could change based on project needs.Fact sheet was approved and mailed out on 4/30/07"There were no comments or concerns expressed by the public regarding this Addendum. The task is completed, no additional tasks are needed.""RsP for Soil was approved, with outstanding items needed in order to fill criteria of ""appropriate care"" for the site under the AB 389/CLRRRA Agreement."

**Completed Info:**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Investigation/Characterization Report

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**STUDIO 15 (Continued)**

**S108195978**

Completed Date: 12/13/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Remedial Action Plan  
 Completed Date: 06/28/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Fact Sheets  
 Completed Date: 05/01/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Other Report  
 Completed Date: 06/04/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Other Report  
 Completed Date: 05/04/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Remedial Action Completion Report  
 Completed Date: 12/31/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: California Land Reuse and Revitalization Agreement  
 Completed Date: 11/20/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Correspondence - Sent  
 Completed Date: 01/03/08

Confirmed: 30013,, ,30022,30027,30136,30156,30195,30013,3002502-NO  
 Confirmed Description: Lead  
 Confirmed Description: Not reported  
 Confirmed Description: Tetrachloroethylene (PCE)  
 Confirmed Description: Tetrachloroethylene (PCE)  
 Confirmed Description: Trichloroethylene (TCE)  
 Confirmed Description: Chloroform  
 Confirmed Description: Copper and compounds  
 Confirmed Description: 1,2-Dichloroethylene (cis)  
 Confirmed Description: Lead  
 Confirmed Description: Not reported  
 Future Area Name: PROJECT WIDE  
 Future Sub Area Name: Not reported  
 Future Document Type: Operations and Maintenance Plan  
 Future Due Date: 2008  
 Future Area Name: PROJECT WIDE  
 Future Sub Area Name: Not reported  
 Future Document Type: Certification  
 Future Due Date: 2008  
 Future Area Name: PROJECT WIDE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**STUDIO 15 (Continued)**

**S108195978**

Future Sub Area Name: Not reported  
 Future Document Type: Deed Restriction / Land Use Covenant  
 Future Due Date: 2008  
 Media Affected: SOIL  
 Media Affected Desc: Soil  
  
 Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30013, 30022, 3002502, 30027, 30136, 30156, 30195  
 Potential Description: Lead  
 Potential Description: Tetrachloroethylene (PCE)  
 Potential Description: TPH-MOTOR OIL  
 Potential Description: Trichloroethylene (TCE)  
 Potential Description: Chloroform  
 Potential Description: Copper and compounds  
 Potential Description: 1,2-Dichloroethylene (cis)  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: FUEL - VEHICLE STORAGE/ REFUELING, MANUFACTURING - CHEMICALS,  
 MANUFACTURING - METAL, RETAIL - VEHICLES, TRANSPORTATION - WAREHOUSING

37

**SAN DIEGO TRANSIT CORPORATION  
 100-16TH STREET  
 SAN DIEGO, CA 92112**

**HIST UST U001572963  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000024873  
 Facility Type: Other  
 Other Type: PUBLIC TRANSPORTATIO  
 Total Tanks: 0016  
 Contact Name: NICK BURRIE  
 Telephone: 6192380100  
 Owner Name: SAN DIEGO TRANSIT CORPORATION  
 Owner Address: 100-16TH STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92112

Tank Num: 001  
 Container Num: A  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: B  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORPORATION (Continued)**

**U001572963**

Tank Num: 003  
 Container Num: C  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 004  
 Container Num: D  
 Year Installed: 1981  
 Tank Capacity: 00020000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 005  
 Container Num: E  
 Year Installed: 1981  
 Tank Capacity: 00020000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 006  
 Container Num: F  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 007  
 Container Num: G  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 008  
 Container Num: H  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 009  
 Container Num: I  
 Year Installed: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO TRANSIT CORPORATION (Continued)**

**U001572963**

Tank Capacity: 00006000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 010  
 Container Num: J  
 Year Installed: 1971  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 011  
 Container Num: K  
 Year Installed: Not reported  
 Tank Capacity: 00007500  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 012  
 Container Num: L  
 Year Installed: 1971  
 Tank Capacity: 00007500  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 013  
 Container Num: M  
 Year Installed: 1971  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 014  
 Container Num: N  
 Year Installed: 1971  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 015  
 Container Num: O  
 Year Installed: 1971  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSIT CORPORATION (Continued)**

**U001572963**

Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 016  
 Container Num: P  
 Year Installed: 1981  
 Tank Capacity: 00001200  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

38

**3758 GILLETT ST.  
 SAN DIEGO, CA**

**Notify 65 S100178058  
 N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: Not reported

39

**CATELLUS DEVELOPMENT PROPERTY  
 702 HARBOR DR  
 SAN DIEGO, CA 92101**

**LUST S104753420  
 San Diego Co. HMMD N/A  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608120641  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1994-01-19 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: 1992-09-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CATELLUS DEVELOPMENT PROPERTY (Continued)**

**S104753420**

Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: KIMBERLY BRANDT  
 RP Address: 201 MISSION ST 30TH FLR  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: RR  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H32809-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMMD:

Facility ID: 132809  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 702 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CATELLUS DEVELOPMENT PROPERTY (Continued)**

**S104753420**

Facility Contact:	Not reported
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	Not reported
Property Address:	Not reported
Property City,St,Zip:	Not reported
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	T001
Tank ID Number:	at4336
Waste or Product:	Not reported
Tank Contents:	REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CATELLUS DEVELOPMENT PROPERTY (Continued)**

**S104753420**

Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H32809-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 1/19/1994  
 Begandt: Not reported

40

**2699 COMMERCIAL ST.  
 SAN DIEGO, CA 92101**

**SLIC S106519079  
 N/A**

**SLIC:**

Region: 9  
 Facility Type: Not reported  
 Status: Open  
 Code: 20-0015.05  
 Waste Discharger Id: Not reported  
 Local Case Num: Not reported  
 Responsible Party: ELMER LOTT  
 Category: ENFORCEMENT  
 Class: SLIC  
 Order Number: Not reported  
 File Number: 1  
 Date Entered: 12/1989  
 End Date: Not reported  
 Archive Box #: 0  
 Archive Box Storage: Not reported  
 Archive Box Storage Location: Not reported  
 Remarks: Not reported

Region: 9  
 Facility Type: Not reported  
 Status: Open  
 Code: 20-0015.051  
 Waste Discharger Id: Not reported  
 Local Case Num: Not reported  
 Responsible Party: ELMER LOTT  
 Category: ENF. REPORT  
 Class: SLIC  
 Order Number: Not reported  
 File Number: 1  
 Date Entered: 09/1989  
 End Date: Not reported  
 Archive Box #: 0  
 Archive Box Storage: Not reported  
 Archive Box Storage Location: Not reported  
 Remarks: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**40 EL DORADO SANDBLASTING  
 2694 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**LUST S100729623  
 Cortese N/A  
 AIRS**

LUST:

Region: 9  
 Case Number: 9UT3204  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 12/01/1995  
 How Found: Not reported  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: 12/01/1995  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 4/18/96  
 Pilot Program: LOP  
 Local Case: H14039-002  
 Basin Number: 908.22  
 Gwater Depth: 60'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: Not reported  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 12/01/1995  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2694 COMMERCIAL ST

EMI:

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6060  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EL DORADO SANDBLASTING (Continued)**

**S100729623**

Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	6060
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	6060
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	6060
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL DORADO SANDBLASTING (Continued)**

**S100729623**

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6060  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1  
 Reactive Organic Gases Tons/Yr: 1  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6060  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1.36715615  
 Reactive Organic Gases Tons/Yr: 1.361645  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0.05  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0.05

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6060  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1.36  
 Reactive Organic Gases Tons/Yr: 1.35  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: .0581395348837209302  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: .05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**40 EL DORADO SANDBLASTING CO  
 2694 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**HAZNET S103648159  
 LUST N/A  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

HAZNET:

Gepaid: CAD982005746  
 Contact: KEVIN B REESE  
 Telephone: 6194459150  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2694 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921131205  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: .1668  
 Facility County: San Diego

Gepaid: CAD982005746  
 Contact: KEVIN B REESE  
 Telephone: 6194459150  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2694 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921131205  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD982005746  
 Contact: KEVIN B REESE  
 Telephone: 6194459150  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2694 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921131205  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .1000  
 Facility County: San Diego

Gepaid: CAD982005746  
 Contact: KEVIN REESE - PRESIDENT  
 Telephone: 6196960700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2694 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921131205  
 Gen County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAD982005746  
 Contact: KEVIN REESE - PRESIDENT  
 Telephone: 6196960700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2694 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921131205  
 Gen County: San Diego  
 TSD EPA ID: ARD981057870  
 TSD County: 99  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: H06  
 Tons: 0.22  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 7 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301960  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-04-18 00:00:00  
 Discover Date: 1995-12-01 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1995-12-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: MARK BITTERLIN  
 RP Address: 525 B ST 1650  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14039-002  
 Case Number: 9UT3204  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608120491  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1995-09-10 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14039-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 114039  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2694 COMMERCIAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 48  
 EPA ID: CAD982005746  
 Gas Station: Not reported  
 Inspection Date: 01/28/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: KEVIN REESE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: REESE KEVIN B&YVONNE A  
 Property Address: 2694 COMMERCIAL ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/28/06  
 Facility Phone: 619-696-0700

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC08  
 Chemical Name: ACETYLENE  
 Case Number: 44-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: DI06  
 Chemical Name: DIESEL  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OX07  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PA05  
 Chemical Name: PAINT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PO04  
 Chemical Name: POWDER COATINGS  
 Case Number: 7440-47-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PR02  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: TH03  
 Chemical Name: THINNER-PROLINE 8-E LACQUER - THINNER  
 Case Number: 64742-95-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 9999999999  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 01/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

Occurrences:	Not reported
Item Number:	0267
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	01/06/98
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	0268
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	07/13/99
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	6250
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	07/13/99
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	6251
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	07/13/99
Waste Code:	Not reported
Type of Violation:	6HV0207
Occurrences:	Not reported
Item Number:	6252
Violation Desc:	FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Inspection Date:	07/13/99
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	6253
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	4741
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV0207
Occurrences:	Not reported
Item Number:	4742
Violation Desc:	FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Inspection Date:	02/27/02
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

Item Number: 4743  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4744  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 4745  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4746  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 04/21/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9452  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 01/28/05  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: PAINT BOOTH FILTERS  
 Carcinogen: No

Inspection Date: 01/28/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EL DORADO SANDBLASTING CO (Continued)**

**S103648159**

Storage Method: METAL DRUM  
 Haz Waste Hauler: 2948 GOLDEN STATE ENVIRON  
 Waste Desc: OIL/WATER  
 Carcinogen: No  
  
 Inspection Date: 01/28/05  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 4373 ENVIRONMENTAL RESOUR  
 Waste Desc: WASTE PAINTS AND THINNERS  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H14039-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/10/1995  
 Begandt: 10/4/1994

Case Number: H14039-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 4/18/1996  
 Begandt: 12/1/1995

40

**ELDORADO SAND BLASTING  
 2675 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**LUST S102429166  
 Cortese N/A  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301858  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELDORADO SAND BLASTING (Continued)**

**S102429166**

Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1995-09-10 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: MARK BITTERLIN  
 RP Address: 525 B ST 1650  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H11763-002  
 Case Number: 9UT3093  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELDORADO SAND BLASTING (Continued)**

**S102429166**

How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608164505  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1995-09-10 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: MARK BITTERLIN  
 RP Address: 525 B ST 1650  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H11763-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELDORADO SAND BLASTING (Continued)**

**S102429166**

LUST:

Region: 9  
 Case Number: 9UT3093  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 05/24/1995  
 How Found: Tank Closure  
 Date Stopped: 05/24/1995  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Other Cause  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 06/06/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 7/31/95  
 Closed Date: 8/25/95  
 Pilot Program: LOP  
 Local Case: H11763-002  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 07/26/1995  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2675 COMMERCIAL ST

San Diego Co. HMMD:

Facility ID: 111763  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 2388  
 Mailing City,St,Zip: NATIONAL CITY, CA 91951  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELDORADO SAND BLASTING (Continued)**

**S102429166**

Fire Dept District: Not reported  
 Census Tract Number: 49  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/31/94  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: CHESTER JACKSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: REESE KEVIN B&YVONNE A  
 Property Address: 2694 COMMERCIAL ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-0677

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT3417  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: AT3417  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: AT3417  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 01/31/94  
 Waste Code: Not reported  
 Type of Violation: 6HV1002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ELDORADO SAND BLASTING (Continued)**

**S102429166**

Occurrences: Not reported  
 Item Number: 0407  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H11763-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/10/1995  
 Begandt: 10/4/1994

Case Number: H11763-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/10/1995  
 Begandt: 5/24/1995

41

**GIFFORD'S BARRELS  
 2606 COMMERCIAL STREET  
 SAN DIEGO, CA 92113**

**ENVIROSTOR S100186129  
 N/A**

**ENVIROSTOR:**

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37500033  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: \* CERC2

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GIFFORD'S BARRELS (Continued)**

**S100186129**

Status: Refer: Other Agency  
 Status Date: 1995-04-25 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 32.7052777777778  
 Longitude: -117.1375  
 Alias Name: CAD982359531  
                   37500033  
 Alias Type: Envirostor ID Number  
                   EPA Identification Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: NFA for DTSC.Database verification program confirmed the status.FACILITY IDENTIFIED VIA ROUTINE SURVEILLANCE"Preliminary Assessment (PA) Done: Further investigation will be done by County Health. PA submitted to EPA: EPA recommendation is Screening Site Inspection based on Gifford's history of violations, observ- ed staining, and elevated heavy metal coSITE SCREENING DONEcentrations in the soil. Potential for direct contact hazards and migration of contaminants."

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 04/25/95

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 10/27/94

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 05/31/88

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 11/26/86

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 01/13/83

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GIFFORD'S BARRELS (Continued)**

**S100186129**

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 10009, 10093, 10097, 10119, 10195, 10199, 20012  
 Potential Description: \* HYDROCARBON SOLVENTS  
 Potential Description: \* AQUEOUS SOLUTION WITH METALS  
 Potential Description: \* CONTAMINATED SOIL  
 Potential Description: \* ACID SOLUTION 2>PH WITH METALS  
 Potential Description: \* UNSPECIFIED AQUEOUS SOLUTION  
 Potential Description: \* WASTE OIL & MIXED OIL  
 Potential Description: \* OTHER PESTICIDE CONTAINERS, 30 GALLONS OR MORE  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

42

**SDUSD MAINTENANCE  
 1826 IRVING AVE  
 SAN DIEGO, CA 92113**

**LUST S100944188  
 Cortese N/A  
 SWEEPS UST**

LUST:

Region: 9  
 Case Number: 9UT3532  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 08/15/1997  
 How Found: Tank Closure  
 Date Stopped: 08/15/1997  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 08/27/1997  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01530-003  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/LOW - MINOR OR NO POTENTIAL WATER RESOURCE IMPACT  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 08/26/1997  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDUSD MAINTENANCE (Continued)**

**S100944188**

Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 1826 IRVING AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 1530  
 Number: Not reported  
 Board Of Equalization: 44-021537  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001530-000001  
 Actv Date: Not reported  
 Capacity: 8500  
 Tank Use: M.V. FUEL  
 Stg: WASTE  
 Content: REG UNLEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 1530  
 Number: 9  
 Board Of Equalization: 44-021537  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001530-000002  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: A  
 Comp Number: 1530  
 Number: 9  
 Board Of Equalization: 44-021537  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001530-000003  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDUSD MAINTENANCE (Continued)**

**S100944188**

Number Of Tanks: Not reported

42

**BRIDGE HOUSING  
 1826 IRVING AVENUE  
 SAN DIEGO, CA 92113**

**ENVIROSTOR**

**S107735963  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: 3.45  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP  
 Program Manager: SAFOUH SAYED  
 Supervisor: Emad Yemut  
 Division Branch: So Cal - Cypress  
 Facility ID: 60000197  
 Site Code: 401264  
 Assembly: 79  
 Senate: 40  
 Special Program: EPA - Target Site Investigation  
 Status: Refer: RWQCB  
 Status Date: 2005-12-04 00:00:00  
 Restricted Use: NO  
 Funding: EPA Grant  
 Latitude: 32.70488  
 Longitude: -117.1434  
 Alias Name: 60000197  
                   401264  
 Alias Type: Project Code (Site Code)  
                   Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: 30550,30025,30003,30593,, ,30550,30003,30593,, ,40001  
 Confirmed Description: Toluene  
 Confirmed Description: TPH-gas  
 Confirmed Description: Benzene  
 Confirmed Description: Xylenes  
 Confirmed Description: Not reported  
 Confirmed Description: Toluene  
 Confirmed Description: Toluene  
 Confirmed Description: Benzene  
 Confirmed Description: Xylenes  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BRIDGE HOUSING (Continued)**

**S107735963**

Media Affected: OTH, OTH, SOIL, SV  
 Media Affected Desc: Other Groundwater affected (uses other than drinking water)  
 Media Affected Desc: Other Groundwater affected (uses other than drinking water)  
 Media Affected Desc: Soil  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30003, 30025, 30550, 30593, 30003, 30550, 30593, 40001  
 Potential Description: Benzene  
 Potential Description: TPH-gas  
 Potential Description: Toluene  
 Potential Description: Xylenes  
 Potential Description: Benzene  
 Potential Description: Toluene  
 Potential Description: Xylenes  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: FUEL - VEHICLE STORAGE/ REFUELING, TRANSPORTATION - WAREHOUSING

42

**SCHOOL**  
**1826 IRVING AVE**  
**SAN DIEGO, CA 92113**

**HIST UST U001572994**  
**N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000058704  
 Facility Type: Not reported  
 Other Type: Not reported  
 Total Tanks: 0004  
 Contact Name: Not reported  
 Telephone: 6192938116  
 Owner Name: SAN DIEGO UNIFIED SCHOOL DIST.  
 Owner Address: 4100 NORMAL ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92103

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SCHOOL (Continued)**

**U001572994**

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00008500  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

Tank Num: 004  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00000050  
 Tank Used for: WASTE  
 Type of Fuel: 06  
 Tank Construction: 4 inches  
 Leak Detection: None

42

**SDUSD - MAINTENANCE  
 1826 IRVING AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S106059787  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOV  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0607302301  
 Stop Date: 1997-08-15 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1997-08-28 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1997-08-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1997-08-26 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SDUSD - MAINTENANCE (Continued)**

**S106059787**

Responsible Party: TONY RASO  
 RP Address: 4860 RUFFNER ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: TS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01530-003  
 Case Number: 9UT3532  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Other Cause  
 Leak Source: Piping  
 Global Id: T0607302739  
 Stop Date: 1989-08-11 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1989-10-23 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1989-03-28 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-03-28 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDUSD - MAINTENANCE (Continued)**

**S106059787**

Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: TONY RASO  
 RP Address: 4860 RUFFNER ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: SJP  
 Staff Initials: TS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01530-002  
 Case Number: 9UT432  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608149012  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-04-05 00:00:00  
 Discover Date: 1986-08-14 00:00:00  
 Enforcement Dt: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDUSD - MAINTENANCE (Continued)**

**S106059787**

Release Date: 1986-08-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: SIGMUND HARABURDA  
 RP Address: 4100 NORMAL ST  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: MV  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01530-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMMD:

Facility ID: 101530  
 Inactive Indicator: Active  
 Business Code: 6HK29  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 4100 NORMAL ST / D  
 Mailing City,St,Zip: SAN DIEGO, CA 92103  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 49

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDUSD - MAINTENANCE (Continued)**

**S106059787**

EPA ID: CAD981453236  
 Gas Station: Not reported  
 Inspection Date: 05/16/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ANTHONY RASO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO UNIFIED SCHOOL DISTR  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: SAN DIEGO UNIFIED SCHOOL DIST  
 Tank Address: 4100 NORMAL STREET  
 Tank City,St,Zip: San Diego, CA 92103  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-293-8117

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: 0004  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDUSD - MAINTENANCE (Continued)**

**S106059787**

**HMMD VIOLATIONS:**

Inspection Date: 03/02/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 0547  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 03/02/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 0548  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 03/02/94  
 Waste Code: Not reported  
 Type of Violation: 6HX3028  
 Occurrences: Not reported  
 Item Number: 0549  
 Violation Desc: UST RESPONSE PLAN NOT AVAILABLE

Inspection Date: 05/16/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3010  
 Occurrences: Not reported  
 Item Number: 7037  
 Violation Desc: PERMIT TO OPERATE APPLIC. NOT COMPLETED

Inspection Date: 05/16/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3033  
 Occurrences: Not reported  
 Item Number: 7038  
 Violation Desc: DID NOT MEET UST CLOSURE REQ

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H01530-001  
 Agency: DEH Site Assessment & Mitigation

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDUSD - MAINTENANCE (Continued)**

**S106059787**

**Funding:** Non Billable  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 4/5/1988  
 Begandt: 8/14/1986

Case Number: H01530-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** LOP - State Fund  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 10/23/1989  
 Begandt: 3/28/1989

Case Number: H01530-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** LOP - State Fund  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 8/27/1997  
 Begandt: 8/15/1997

42

**SAN DIEGO USD SAN DIEGO CITY SCH MAINT  
 1826 IRVING ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000110706  
 FINDS CAD981453236**

RCRA-SQG:  
 Date form received by agency: 03/01/1992  
 Facility name: SAN DIEGO USD SAN DIEGO CITY SCH MAINT  
 Site name: SDUSD-MAINTENANCE  
 Facility address: 1826 IRVING ST.  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981453236  
 Contact: JOHN D BAKER  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 293-8117  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: District  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO USD SAN DIEGO CITY SCH MAINT (Continued)**

**1000110706**

Owner/operator name: SAN DIEGO USD  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: District  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: Unknown  
 Transporter of hazardous waste: Unknown  
 Treater, storer or disposer of HW: No  
 Underground injection activity: Unknown  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: Unknown  
 Used oil processor: Unknown  
 User oil refiner: Unknown  
 Used oil fuel marketer to burner: Unknown  
 Used oil Specification marketer: Unknown  
 Used oil transfer facility: Unknown  
 Used oil transporter: Unknown  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 03/12/1986  
 Facility name: SAN DIEGO USD SAN DIEGO CITY SCH MAINT  
 Classification: Small Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

42

**SAN DIEGO CITY SCHOOLS**  
**1826 IRVINE AVE**  
**SAN DIEGO, CA 92113**

**LUST S100232877**  
**Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT432  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 08/18/1986

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO CITY SCHOOLS (Continued)**

**S100232877**

How Found: Other Means  
 Date Stopped: 08/11/1989  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 08/11/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 08/11/1989  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01530-002  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 08/19/1986  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1826 IRVINE AVE

42

**KRASNE'S INC  
 2222 COMMERCIAL ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1008194520  
 CAL000114020**

RCRA-SQG:  
 Date form received by agency: 02/28/2004  
 Facility name: KRASNE'S INC  
 Facility address: 2222 COMMERCIAL ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAL000114020  
 Mailing address: 222 COMMERCIAL ST  
 SAN DIEGO, CA 92113  
 Contact: KURT KRASNE  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 232-2066  
 Telephone ext.: 120  
 Contact email: KURTK@TRIPLEK.COM  
 EPA Region: 09  
 Classification: Small Small Quantity Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KRASNE'S INC (Continued)**

**1008194520**

Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: KRASNE'S INC  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 02/24/1946  
 Owner/Op end date: Not reported

Owner/operator name: KRASNES INC  
 Owner/operator address: 2222 COMMERCIAL ST  
 SAN DIEGO, CA 92113

Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 02/24/1946  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**KRASNE'S INC (Continued)**

**1008194520**

Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Hazardous Waste Summary:  
 Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007  
 Waste name: CHROMIUM

Violation Status: No violations found

43

**CONTROLS ENGINEERING MAINTENANCE CORP.  
 105 SOUTH 31ST STREET  
 SAN DIEGO, CA 92113**

**ENVIROSTOR S106797741  
 N/A**

ENVIROSTOR:  
 Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37760083  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2004-01-27 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37760083  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTROLS ENGINEERING MAINTENANCE CORP. (Continued)**

**S106797741**

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

**44 TIME RECYCLING CENTER  
 412 CESAR E CHAVEZ PKWY  
 SAN DIEGO, CA 92113**

**SWRCY S107137884  
 N/A**

SWRCY:  
 Certification Status: O  
 Facility Phone Number: (619) 235-8182  
 Date facility became certified: 01/16/98  
 Date facility began operating: 02/04/98  
 Date facility ceased operating: Still operating  
 Whether The Facility Is Grandfathered: Not reported  
 Convenience Zone Where Facility Located: 2040  
 Convenience Zone Where Facility Located 2: 4592  
 Convenience Zone Where Facility Located 3: 4989  
 Convenience Zone Where Facility Located 4: 4990  
 Convenience Zone Where Facility Located 5: 0  
 Convenience Zone Where Facility Located 6: 0  
 Convenience Zone Where Facility Located 7: 0  
 Aluminum Beverage Containers Redeemed: AL  
 Glass Beverage Containers Redeemed: GL  
 Plastic Beverage Containers Redeemed: PL  
 Other mat beverage containers redeemed: Not reported  
 Refillable Beverage Containers Redeemed: Not reported

**45 8TH AVENUE TIDELAND DUMP  
 50 8TH AVENUE  
 SAN DIEGO, CA**

**SWF/LF S102362169  
 N/A**

SWF/LF:  
 Region: STATE  
 Facility ID: 37-AA-0430  
 Lat/Long: 32.716670 / -117.150000  
 Owner Name: Not reported  
 Owner Telephone: Not reported  
 Owner Address: Not reported  
 Owner Address2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**8TH AVENUE TIDELAND DUMP (Continued)**

**S102362169**

Owner City,St,Zip: Not reported  
 Operator: Not reported  
 Operator Phone: Not reported  
 Operator Address: Not reported  
 Operator Address2: Not reported  
 Operator City,St,Zip: Not reported  
 Operator's Status: Closed  
 Permit Date: Not reported  
 Permit Status: Not reported  
 Permitted Acreage: 0.00  
 Activity: Solid Waste Disposal Site  
 Regulation Status: Unpermitted  
 Landuse Name: Not reported  
 GIS Source: Place  
 Category: Disposal  
 Unit Number: 01  
 Inspection Frequency: Annual  
 Accepted Waste: Not reported  
 Closure Date: / /  
 Closure Type: Not reported  
 Disposal Acreage: \$0.00  
 Swisnumber: 37-AA-0430  
 Issue & Observations: Not reported  
 Program Type: Not reported  
 Permitted Throughput with Units: 0  
 Actual Throughput with Units: Not reported  
 Permitted Capacity with Units: 0  
 Remaining Capacity: 0  
 Remaining Capacity with Units: Not reported

45

**SD PORT DISTRICT MAINT DEPT  
 825 E HARBOR DR  
 SAN DIEGO, CA 92101**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S103982277  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301868  
 Stop Date: 1995-06-21 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-02-20 00:00:00  
 Discover Date: 1995-06-21 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1995-06-21 00:00:00  
 Review Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD PORT DISTRICT MAINT DEPT (Continued)**

**S103982277**

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: PAUL BROWN  
 RP Address: P.O. BOX 488  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H11530-002  
 Case Number: 9UT3102  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 111530  
 Inactive Indicator: Active  
 Business Code: 6HK52  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: LARRY HOFSTETTER  
 Mailing Address: P.O. BOX 120488  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 54  
 EPA ID: CAD980882153  
 Gas Station: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD PORT DISTRICT MAINT DEPT (Continued)**

**S103982277**

Inspection Date: 04/24/03  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: LARRY HOFSTETTER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: SAN DIEGO UNIFIED PORT DIST  
 Tank Address: 3165 PACIFIC HY  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 12/24/04  
 Facility Phone: 619-686-6321

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T005  
 Tank ID Number: 5  
 Waste or Product: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD PORT DISTRICT MAINT DEPT (Continued)**

**S103982277**

Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 06/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 7305  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 06/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7306  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/26/98  
 Waste Code: Not reported  
 Type of Violation: 6HV4303  
 Occurrences: Not reported  
 Item Number: 8808  
 Violation Desc: NO MED WASTE DISPOSAL RECORDS

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4288  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 4289  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 04/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9593  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0203  
 Occurrences: Not reported  
 Item Number: 9594  
 Violation Desc: DAMAGED CONTAINER NOT REPACKAGED

Inspection Date: 04/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 9595

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SD PORT DISTRICT MAINT DEPT (Continued)**

**S103982277**

Violation Desc: WASTE CONTAINER: POOR CONDITION

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H11530-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/20/1997  
 Begandt: 6/21/1995

45

**PORT OF SAN DIEGO DIST MAINT FACILITY  
 825 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000818169  
 FINDS CAD980882153  
 HAZNET  
 LUST**

**RCRA-SQG:**

Date form received by agency: 11/06/1992  
 Facility name: PORT OF SAN DIEGO DIST MAINT FACIL  
 Facility address: 825 E HARBOR DR  
 SAN DIEGO, CA 92101  
 EPA ID: CAD980882153  
 Mailing address: P O BOX 488  
 SAN DIEGO, CA 92112  
 Contact: RALPH HICKS  
 Contact address: P O BOX 488  
 SAN DIEGO, CA 92112  
 Contact country: US  
 Contact telephone: (619) 291-3900  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT OF SAN DIEGO DIST MAINT FACILITY (Continued)**

**1000818169**

Owner/operator name: SAN DIEGO UNIFIED PORT DIST  
 Owner/operator address: 3165 PACIFIC HWY  
 SAN DIEGO, CA 92101  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 291-3900  
 Legal status: District  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD980882153  
 Contact: SAN DIEGO UNIFIED PORT  
 Telephone: 6196866584  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 488  
 Mailing City,St,Zip: SAN DIEGO, CA 921120488  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .0225  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT OF SAN DIEGO DIST MAINT FACILITY (Continued)**

**1000818169**

Gepaid: CAD980882153  
 Contact: SAN DIEGO UNIFIED PORT  
 Telephone: 6196866584  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 488  
 Mailing City,St,Zip: SAN DIEGO, CA 921120488  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Unspecified alkaline solution  
 Disposal Method: Treatment, Tank  
 Tons: .0150  
 Facility County: San Diego

Gepaid: CAD980882153  
 Contact: SAN DIEGO UNIFIED PORT  
 Telephone: 6196866584  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 488  
 Mailing City,St,Zip: SAN DIEGO, CA 921120488  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: .5202  
 Facility County: San Diego

Gepaid: CAD980882153  
 Contact: SAN DIEGO UNIFIED PORT  
 Telephone: 6196866584  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 488  
 Mailing City,St,Zip: SAN DIEGO, CA 921120488  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2  
 Disposal Method: Treatment, Tank  
 Tons: .0125  
 Facility County: San Diego

Gepaid: CAD980882153  
 Contact: SAN DIEGO UNIFIED PORT  
 Telephone: 6196866584  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 488  
 Mailing City,St,Zip: SAN DIEGO, CA 921120488  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus inorganics  
 Disposal Method: Treatment, Incineration

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT OF SAN DIEGO DIST MAINT FACILITY (Continued)**

**1000818169**

Tons: .1575  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 239 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: 9  
 Case Number: 9UT3102  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: 0  
 Date Found: 06/21/1995  
 How Found: Subsurface Monitoring  
 Date Stopped: 06/21/1995  
 How Stopped: Not reported  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Taken - no action has as yet been taken at the site  
 Confirm Date: / /  
 Submit Workplan: 6/21/95  
 Prelim Assess: 08/03/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 8/3/95  
 Closed Date: 2/20/97  
 Pilot Program: LOP  
 Local Case: H11530-002  
 Basin Number: 908.21  
 Gwater Depth: 6'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/LOW - MINOR OR NO POTENTIAL WATER RESOURCE IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 06/21/1995  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

45

**PORT DISTRICT MAINTENANCE  
 825 HARBOR  
 SAN DEIGO, CA 92101**

**Cortese S105026103  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**45 MTDB LEASEHOLD  
 93 8TH AVENUE  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106797686  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000034  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-04-12 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37000034  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**46 TOSCO IDLE PIPELINE  
 8TH STREET/HARBOR AVE.  
 SAN DIEGO, CA 92101**

**ENVIROSTOR S106797705  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37130001  
 Site Code: Not reported  
 Assembly: 76  
 Senate: 39  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-05-31 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37130001  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>47</b>	<b>28TH AND WEBSTER AVENUE</b>	<b>Notify 65</b>	<b>S100178070</b> <b>N/A</b>
-----------	--------------------------------	------------------	---------------------------------

**SAN DIEGO, CA**

Notify 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Incident Description:	Not reported

---

<b>48</b>	<b>3020 WEBSTER.</b> <b>SAN DIEGO, CA 92113</b>	<b>Notify 65</b>	<b>S100178294</b> <b>N/A</b>
-----------	--	------------------	---------------------------------

Notify 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Incident Description:	92113-1436

---

<b>49</b>	<b>RALSTON PURINA/VAN CAMP</b> <b>1025 E HARBOR DR</b> <b>SAN DIEGO, CA 92101</b>	<b>LUST</b> <b>San Diego Co. HMMD</b> <b>SAN DIEGO CO. SAM</b>	<b>S100726703</b> <b>N/A</b>
-----------	---	--	---------------------------------

LUST:

Region:	STATE
Case Type:	Other ground water affected
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global Id:	T0607302723
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	1987-08-10 00:00:00
Discover Date:	Not reported
Enforcement Dt:	Not reported
Release Date:	Not reported
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RALSTON PURINA/VAN CAMP (Continued)**

**S100726703**

County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04622-001  
 Case Number: 9UT408  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 104622  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RALSTON PURINA/VAN CAMP (Continued)**

**S100726703**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RALSTON PURINA/VAN CAMP (Continued)**

**S100726703**

SAN DIEGO CO. SAM:

Case Number: H04622-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 8/10/1987  
 Begandt: 12/22/1986

49

**RALSTON PURINA COMPANY  
 1025 HARBOR DR E  
 SAN DIEGO, CA 92105**

**LUST S102435669  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT408  
 Local Agency: San Diego  
 Substance: 0  
 Qty Leaked: 0  
 Date Found: 12/18/1986  
 How Found: Tank Closure  
 Date Stopped: / /  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 03/26/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 8/11/87  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 8/10/87  
 Pilot Program: LOP  
 Local Case: H04622-001  
 Basin Number: 908.21  
 Gwater Depth: 2 FT  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 10/22/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Database(s) EPA ID Number  
 Distance (ft.)Site

**49 SUN ROAD MARINA Notify 65 S100179360**  
**955 HARBOR DR N/A**  
**SAN DIEGO, CA**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: Not reported

**50 DANNYS PAINT & BODY SHOP RCRA-SQG 1000323818**  
**1866 KEARNEY AVENUE FINDS CAD981463599**  
**SAN DIEGO, CA 92113 HAZNET**  
**San Diego Co. HMMD**  
**AIRS**

RCRA-SQG:  
 Date form received by agency:09/01/1996  
 Facility name: DANNYS PAINT AND BODY SHOP  
 Facility address: 1866 KEARNY AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981463599  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: DANIEL VILLALVA  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Historical Generators:

Date form received by agency: 04/01/1986  
 Facility name: DANNYS PAINT AND BODY SHOP  
 Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	12/22/2003
Date achieved compliance:	12/31/2003
Violation lead agency:	State
Enforcement action:	Not reported
Enforcement action date:	Not reported
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	Not reported
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Evaluation Action Summary:

Evaluation date:	12/22/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	12/31/2003
Evaluation lead agency:	State Contractor/Grantee

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD981463599  
 Contact: DANNYS PAINT AND BODY SHOP  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1866 KEARNEY AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD981463599  
 Contact: DANNYS PAINT AND BODY SHOP  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1866 KEARNEY AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Recycler  
 Tons: .3753  
 Facility County: San Diego

Gepaid: CAD981463599  
 Contact: DANIEL VILLALVA  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1866 KEARNEY AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.26  
 Facility County: Not reported

Gepaid: CAD981463599  
 Contact: DANIEL VILLALVA  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

Mailing Address: 1866 KEARNEY AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.29  
 Facility County: Not reported

Gepaid: CAD981463599  
 Contact: DANNYS PAINT AND BODY SHOP  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1866 KEARNEY AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: .1959  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 10 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 112528  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1866 KEARNEY AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 49  
 EPA ID: CAD981463599  
 Gas Station: Not reported  
 Inspection Date: 07/15/02  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: DANIEL E VILLALVA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: VILLALVA DANIEL&VERA  
 Property Address: 551 RIVERA ST  
 Property City,St,Zip: 91911

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-1585

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9671  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 202878  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1866 KEARNEY AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 49  
 EPA ID: CAD981463599  
 Gas Station: Not reported  
 Inspection Date: 01/11/05  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: DANIEL E VILLALVA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: VILLALVA DANIEL&VERA  
 Property Address: 551 RIVERA ST  
 Property City,St,Zip: 91911  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/11/07  
 Facility Phone: 619-239-1585

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/22/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 7078  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

**HMMD WASTE STREAMS:**

Inspection Date: 01/11/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 10  
 Annual Qty String: 10  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: TO AUTO ZONE RECYCLING  
 Carcinogen: No

Inspection Date: 01/11/05  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 63  
 Annual Qty String: 63  
 Measurement Unit: GAL  
 Treatment Method: Not reported  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: PAINT/THINNER  
 Carcinogen: No

**EMI:**

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 761  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 761  
 Air District Name: SD  
 SIC Code: 7532

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 761  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 761  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 761  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DANNYS PAINT & BODY SHOP (Continued)**

**1000323818**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	761
Air District Name:	SD
SIC Code:	7532
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.264672594
Reactive Organic Gases Tons/Yr:	0.24411
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	761
Air District Name:	SD
SIC Code:	7532
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.264672594
Reactive Organic Gases Tons/Yr:	.24411
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

51

**JANKOVICH & SONS INC**  
**920 GULL STREET**  
**SAN DIEGO, CA 92107**

**SLIC S106484243**  
**N/A**

SLIC:

Region:	STATE
Global Id:	SL0607371414
Assigned Name:	SLICSITE
Lead Agency Contact:	KELLY K. DORSEY
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	2090010
Responsible Party:	Not reported
Recent Dtw:	Not reported
Substance Released:	12031, TPHG
<b>Facility Status:</b>	<b>Not reported</b>

Region:	STATE
Global Id:	SL372934241
Assigned Name:	SLICSITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JANKOVICH & SONS INC (Continued)**

**S106484243**

Lead Agency Contact: KELLY K. DORSEY  
 Lead Agency: SAN DIEGO RWQCB (REGION 9)  
 Lead Agency Case Number: SL372934241  
 Responsible Party: JANKOVICH & SONS INC  
 Recent Dtw: Not reported  
 Substance Released: PAH, PET  
 Facility Status: **Not reported**

52

**INTERSTATE BRANDS CORPORATION  
 1955 JULIAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET  
 LUST  
 Cortese  
 San Diego Co. HMD  
 AIRS  
 WIP  
 CA WDS  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S105032866  
 N/A**

HAZNET:

Gepaid: CAD981667314  
 Contact: D GRAVES WEST DIV ENVIRON  
 Telephone: 3236604455  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2330 RIPPLE ST  
 Mailing City,St,Zip: LOS ANGELES, CA 900390000  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 5.05  
 Facility County: Not reported

Gepaid: CAD981667314  
 Contact: D GRAVES WEST DIV ENVIRON  
 Telephone: 3236604455  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2330 RIPPLE ST  
 Mailing City,St,Zip: LOS ANGELES, CA 900390000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.12  
 Facility County: San Diego

Gepaid: CAD981667314  
 Contact: D GRAVES WEST DIV ENVIRON  
 Telephone: 3236604455  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2330 RIPPLE ST  
 Mailing City,St,Zip: LOS ANGELES, CA 900390000  
 Gen County: San Diego  
 TSD EPA ID: AZ0000337360

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

TSD County: San Diego  
 Waste Category: Polychlorinated biphenyls and material containing PCB's  
 Disposal Method: Recycler  
 Tons: 0.04  
 Facility County: San Diego

Gepaid: CAD981667314  
 Contact: D GRAVES WEST DIV ENVIRON  
 Telephone: 3236604455  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2330 RIPPLE ST  
 Mailing City,St,Zip: LOS ANGELES, CA 900390000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: San Diego  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.16  
 Facility County: San Diego

Gepaid: CAD981667314  
 Contact: D GRAVES WEST DIV ENVIRON  
 Telephone: 3236604455  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2330 RIPPLE ST  
 Mailing City,St,Zip: LOS ANGELES, CA 900390000  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 5.05  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607300968  
 Stop Date: 1987-01-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Monitoring: Not reported  
 Close Date: 2006-06-23 00:00:00  
 Discover Date: 1987-01-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-01-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: DAVID GRAVES  
 RP Address: 2330 RIPPLE ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21210-001  
 Case Number: 9UT220  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:  
 Facility ID: 121210  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1955 JULIAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 49  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: INTERSTATE BRANDS CORP  
 Property Address: PROP TAX DEPT 22S024  
 Property City,St,Zip: 64141  
 Tank Owner: INTERSTATE BRANDS CORPORATION  
 Tank Address: 12 E ARMOUR BL  
 Tank City,St,Zip: Kansas City, MO 64111  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-8155

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 602401  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 602402  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 003



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: 004  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T005  
 Tank ID Number: 005  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T006  
 Tank ID Number: 006  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 202987  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 6841 SAN FERNANDO RD  
 Mailing City,St,Zip: GLENDALE, CA 91201  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 49

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 02/24/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JOE ARRIAGA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: INTERSTATE BRANDS CORP  
 Property Address: PROP TAX DEPT 22S024  
 Property City,St,Zip: 64141  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/24/05  
 Facility Phone: 619-525-7035

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC63  
 Chemical Name: ACETYLENE, ETHYNE ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: AR64  
 Chemical Name: ARGON ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ME78  
 Chemical Name: METHANOL METHANOL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Item Number:	OI66
Chemical Name:	OILS, LUBRICATING OILS, LUBRICATING
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	CHRONIC
Item Number:	OX02
Chemical Name:	OXYGEN OXYGEN
Case Number:	7782-44-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	Not reported
Item Number:	PO77
Chemical Name:	POTASSIUM HYDROXIDE ZEP FS FORMULA 4089
Case Number:	1310-58-3
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	ACUTE
2nd Hazard Category:	Not reported
Item Number:	PO79
Chemical Name:	POTASSIUM HYDROXIDE ZEP FS PRO-CHLOR
Case Number:	1310-58-3
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	ACUTE
2nd Hazard Category:	Not reported
Item Number:	SO70
Chemical Name:	SODIUM HYDROXIDE ZEP FS FORMULA 4665
Case Number:	7681-52-9
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 02/24/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 02/24/04  
 Waste Item #: 513  
 Waste Code: 513  
 Waste Name: EMPTY CONTNR(LESS TH  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: AEROSOL CANS  
 Carcinogen: No

Inspection Date: 02/24/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 500  
 Annual Qty String: 500

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203139  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 49  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: INTERSTATE BRANDS CORP  
 Property Address: C/O PROPERTY TAX DEP  
 Property City,St,Zip: 64141  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**EMI:**

Year:	1990
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	554
Air District Name:	SD
SIC Code:	2051
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	36
Reactive Organic Gases Tons/Yr:	36
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	1995
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	554
Air District Name:	SD
SIC Code:	2051
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 36  
 Reactive Organic Gases Tons/Yr: 36  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1996  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 554  
 Air District Name: SD  
 SIC Code: 2051  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 36  
 Reactive Organic Gases Tons/Yr: 36  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1997  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 554  
 Air District Name: SD  
 SIC Code: 2051  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 32  
 Reactive Organic Gases Tons/Yr: 31  
 Carbon Monoxide Emissions Tons/Yr: 1  
 NOX - Oxides of Nitrogen Tons/Yr: 2  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 554  
 Air District Name: SD  
 SIC Code: 2051  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 20  
 Reactive Organic Gases Tons/Yr: 20  
 Carbon Monoxide Emissions Tons/Yr: 2  
 NOX - Oxides of Nitrogen Tons/Yr: 3  
 SOX - Oxides of Sulphur Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	554
Air District Name:	SD
SIC Code:	2051
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	14
Reactive Organic Gases Tons/Yr:	14
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	554
Air District Name:	SD
SIC Code:	2051
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	14
Reactive Organic Gases Tons/Yr:	14
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	554
Air District Name:	SD
SIC Code:	2051
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	19
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Facility ID: 554  
 Air District Name: SD  
 SIC Code: 2051  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 19  
 Reactive Organic Gases Tons/Yr: 19  
 Carbon Monoxide Emissions Tons/Yr: 1  
 NOX - Oxides of Nitrogen Tons/Yr: 1  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 554  
 Air District Name: SD  
 SIC Code: 2051  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 19  
 Reactive Organic Gases Tons/Yr: 19  
 Carbon Monoxide Emissions Tons/Yr: 1  
 NOX - Oxides of Nitrogen Tons/Yr: 1  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 554  
 Air District Name: SD  
 SIC Code: 2051  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 19.0032777  
 Reactive Organic Gases Tons/Yr: 18.8749976  
 Carbon Monoxide Emissions Tons/Yr: 0.71736  
 NOX - Oxides of Nitrogen Tons/Yr: 0.854  
 SOX - Oxides of Sulphur Tons/Yr: 0.005124  
 Particulate Matter Tons/Yr: 0.064904  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0.064904

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 554  
 Air District Name: SD  
 SIC Code: 2051  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Total Organic Hydrocarbon Gases Tons/Yr: 21.26107  
 Reactive Organic Gases Tons/Yr: 21.150536  
 Carbon Monoxide Emissions Tons/Yr: .22819  
 NOX - Oxides of Nitrogen Tons/Yr: .53975  
 SOX - Oxides of Sulphur Tons/Yr: .0034885  
 Particulate Matter Tons/Yr: .040741  
 Part. Matter 10 Micrometers & Smllr Tons/Yr: .040741

WIP:

Region: 4  
 File Number: 115.0103  
**File Status: Historical**  
 Staff: CCHARMLE  
 Facility Suite: Not reported

CA WDS:

Facility ID: San Diego 371017258  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: 6195257035  
 Facility Contact: JOE ARRIAGA  
 Agency Name: INTER STATE BRANDS  
 Agency Address: 1955 Julian Ave  
 Agency City,St,Zip: San Diego 921131125  
 Agency Contact: JOE ARRIAGA  
 Agency Telephone: 6195257035  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.  
 Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

dischargers having waste storage systems with land disposal such as dairy waste ponds.

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21210  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021210-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 6

Status: Not reported  
 Comp Number: 21210  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021210-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: UNKNOWN  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 21210  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021210-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 21210

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021210-000004  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 21210  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021210-000005  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 21210  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021210-000006  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 21210  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERSTATE BRANDS CORPORATION (Continued)**

**S105032866**

Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H21210-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/23/2006  
 Begandt: 1/15/1987

52

**WEBER MILBROOK PLANT  
 1955 JULIAN AVE  
 SAN DIEGO, CA 92113**

**HIST UST U001573001  
 N/A**

**HIST UST:**

Region: STATE  
 Facility ID: 00000006075  
 Facility Type: Other  
 Other Type: Not reported  
 Total Tanks: 0001  
 Contact Name: G. CORWIN  
 Telephone: 6192398155  
 Owner Name: INTERSTATE BRANDS CORP  
 Owner Address: 1955 JULIAN  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00004000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

52

**INTERSTATE BRANDS CORPORATION  
 1955 JULIAN AVE  
 SAN DIEGO, CA 92113**

**HIST UST U001572985  
 N/A**

**HIST UST:**

Region: STATE  
 Facility ID: 00000005912  
 Facility Type: Other  
 Other Type: GARAGE FACILITY  
 Total Tanks: 0006  
 Contact Name: ESKEW MABRY  
 Telephone: 6192398155  
 Owner Name: INTERSTATE BRANDS CORPORATION

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**INTERSTATE BRANDS CORPORATION (Continued)**

**U001572985**

Owner Address: 12 EAST ARMOUR BOULEVARD  
 Owner City,St,Zip: KANSAS CITY, MO 64111

Tank Num: 001  
 Container Num: 602401  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

Tank Num: 002  
 Container Num: 602402  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: Not reported  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

Tank Num: 003  
 Container Num: 60-2404  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: WASTE  
 Type of Fuel: 5  
 Tank Construction: Unkown inches  
 Leak Detection: None

Tank Num: 004  
 Container Num: 60-2405  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 005  
 Container Num: 60-2406  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 006  
 Container Num: 24 B F  
 Year Installed: Not reported  
 Tank Capacity: 00004000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

53 YOUNGS MARKET CO  
 1709 MAIN ST  
 SAN DIEGO, CA 92113

LUST S104748498  
 San Diego Co. HMMD N/A  
 SWEEPS UST  
 SAN DIEGO CO. SAM

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301065  
 Stop Date: 1992-09-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-12-07 00:00:00  
 Discover Date: 1992-09-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-09-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15795-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YOUNGS MARKET CO (Continued)**

**S104748498**

Case Number: 9UT2298  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 115795  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1709 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/22/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: COLLEEN MOORE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: YOUNGS MARKET CO  
 Tank Address: 1709 S MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-5126

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YOUNGS MARKET CO (Continued)**

**S104748498**

1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 15795  
 Number: 9  
 Board Of Equalization: 44-022926  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015795-000001  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H15795-001  
 Agency: DEH Site Assessment & Mitigation

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YOUNGS MARKET CO (Continued)**

**S104748498**

**Funding:** LOP - Federal Fund  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/7/1992  
 Begandt: 9/8/1992

**53 YOUNG'S MARKET CO.  
 1709 MAIN ST  
 SAN DIEGO, CA 92112**

**HIST UST U001572966  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000044733  
 Facility Type: Gas Station  
 Other Type: Not reported  
 Total Tanks: 0001  
 Contact Name: RALPH HEILMAN  
 Telephone: 6192345126  
 Owner Name: YOUNG'S MARKET CO.  
 Owner Address: 500 SO. CENTRAL  
 Owner City,St,Zip: LOS ANGELES, CA 90013

Tank Num: 001  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

**53 YOUNG'S MARKET COMPANY  
 1709 MAIN ST S  
 SAN DIEGO, CA 92113**

**LUST S102441452  
 Cortese N/A**

LUST:  
 Region: 9  
 Case Number: 9UT2298  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 09/08/1992  
 How Found: Tank Closure  
 Date Stopped: 09/08/1992  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 09/23/1992  
 Submit Workplan: 9/23/92  
 Prelim Assess: / /  
 Desc Pollution: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YOUNG'S MARKET COMPANY (Continued)**

**S102441452**

Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/7/92  
 Pilot Program: LOP  
 Local Case: H15795-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 09/23/1992  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1709 MAIN ST S

**53 SEA MANAGEMENT  
 1202 SIGSBEE ST  
 SAN DIEGO, CA 92113**

**HAZNET S103625451  
 N/A**

HAZNET:  
 Gepaid: CAC001138616  
 Contact: SEA MANAGEMENT  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 7917 IVANHOE AVE  
 Mailing City,St,Zip: LA JOLLA, CA 920370000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Recycler  
 Tons: .2710  
 Facility County: San Diego

**53 NASSCO WAREHOUSE  
 1699 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1008194825  
 HAZNET CAR000161455**

RCRA-SQG:  
 Date form received by agency:03/24/2005  
 Facility name: NASSCO WAREHOUSE  
 Facility address: 1699 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000161455  
 Mailing address: PO BOX 85278  
 MS 22A  
 SAN DIEGO, CA 921865278

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NASSCO WAREHOUSE (Continued)**

**1008194825**

Contact: MIKE T CHEE  
 Contact address: PO BOX 85278 MS 22A  
 SAN DIEGO, CA 921865278  
 Contact country: US  
 Contact telephone: 619-544-7778  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: NATIONAL STEEL AND SHIPBUILDING  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 03/15/1987  
 Owner/Op end date: Not reported

Owner/operator name: HELF INVESTMENT CO  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 03/15/1983  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Universal Waste Summary:**

Waste type: Batteries  
 Accumulated waste on-site: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NASSCO WAREHOUSE (Continued)**

**1008194825**

Generated waste on-site: Yes

Waste type: Lamps

Accumulated waste on-site: No

Generated waste on-site: Yes

**Hazardous Waste Summary:**

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

**HAZNET:**

Gepaid: CAR000161455  
 Contact: MIKE T CHEE  
 Telephone: 6195447778  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85278 MS 22A  
 Mailing City,St,Zip: SAN DIEGO, CA 921865278  
 Gen County: San Diego  
 TSD EPA ID: IND000646943  
 TSD County: 99  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.91  
 Facility County: Not reported

53

**NASSCO WAREHOUSE  
 1699 MAIN ST  
 SAN DIEGO, CA 92113**

**FINDS 1008229214  
 110021004232**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

<b>53</b>	<b>PACIFIC RIGGING LOFT</b> <b>1694 MAIN ST</b> <b>SAN DIEGO, CA 92113</b>	<b>RCRA-SQG</b> <b>FINDS</b>	<b>1000250265</b> <b>CAD982498685</b>
-----------	--	---------------------------------	--

RCRA-SQG:

Date form received by agency: 02/07/1990  
 Facility name: PACIFIC RIGGING LOFT  
 Facility address: 1694 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982498685  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1694 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 239-3070  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: MILTON MACCREE  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC RIGGING LOFT (Continued)**

**1000250265**

Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

54

**JR GAS AND MINI MART  
 505 S 30TH ST  
 SAN DIEGO, CA 92113**

**LUST U003789710  
 UST N/A**

**San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608116823  
 Stop Date: 2001-07-25 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2002-10-24 00:00:00  
 Discover Date: 2001-07-25 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-07-25 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JR GAS AND MINI MART (Continued)**

**U003789710**

Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: NABEEL RAHIB  
 RP Address: P O BOX 2293  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21212-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H21212

San Diego Co. HMMD:

Facility ID: 121212  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 505 S 30TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/24/04  
 Reinspection Date: Not reported  
 Inspector Name: TTORRES  
 Violation Notice Issued: Not reported  
 Facility Contact: JERRY ELRAHEB



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JR GAS AND MINI MART (Continued)**

**U003789710**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RAFFO MUKHLIS  
 Property Address: 505 S 30TH ST  
 Property City,St,Zip: 92113  
 Tank Owner: JERRY ELRAHEB  
 Tank Address: 12397 S PICRUS ST  
 Tank City,St,Zip: San Diego, CA 92129  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 11/03/04  
 Facility Phone: 619-239-4550

**HMMD DISCLOSURE INVENTORY:**

Item Number: PR42  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: RE18  
 Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 121212 T004  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: SU19  
 Chemical Name: SUPER UNLEADED UNDERGROUND TANK 121212 T005  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: NT2276  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**JR GAS AND MINI MART (Continued)**

**U003789710**

Tank Number: T002  
 Tank ID Number: NT2276  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T003  
 Tank ID Number: NT21212  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: NT2276, RT  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T005  
 Tank ID Number: NT2276, RT  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 04/28/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 6757  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/28/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 6758  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 04/28/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3013  
 Occurrences: Not reported  
 Item Number: 6759  
 Violation Desc: NO FINANCIAL RESPOSIBILITY DOC

Inspection Date: 04/28/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 6760  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 04/28/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3025  
 Occurrences: Not reported  
 Item Number: 6761  
 Violation Desc: PRESURIZED LLD NOT TESTED ANNUALLY

Inspection Date: 04/28/97

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**JR GAS AND MINI MART (Continued)**

**U003789710**

Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 6762  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 04/28/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 6763  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 06/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4932  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 06/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4933  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 06/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3013  
 Occurrences: Not reported  
 Item Number: 4934  
 Violation Desc: NO FINANCIAL RESPOSIBILITY DOC

Inspection Date: 06/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 4935  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 06/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV3018  
 Occurrences: Not reported  
 Item Number: 4936  
 Violation Desc: IMPROPER INVENTORY RECONCILIATION

Inspection Date: 04/26/00  
 Waste Code: Not reported  
 Type of Violation: 6HX3007  
 Occurrences: Not reported  
 Item Number: 4746  
 Violation Desc: NO PERMIT FOR UST REPAIR/UPGRADE/REMOVAL

Inspection Date: 09/16/02  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**JR GAS AND MINI MART (Continued)**

**U003789710**

Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 2070  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 2071  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2072  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 2073  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3102  
 Occurrences: Not reported  
 Item Number: 2074  
 Violation Desc: OPERATING PERMIT CURRENT & AT FACILITY?

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3104  
 Occurrences: Not reported  
 Item Number: 2075  
 Violation Desc: FACILITY AND DETAIL FORMS NOT SUBMITTED

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3105  
 Occurrences: Not reported  
 Item Number: 2076  
 Violation Desc: FINANCIAL RESPONSIBILITY EXPIRED

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3107  
 Occurrences: Not reported  
 Item Number: 2077  
 Violation Desc: UST MONITORING PLAN NOT COMPLETE

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3109

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JR GAS AND MINI MART (Continued)**

**U003789710**

Occurrences:	Not reported
Item Number:	2078
Violation Desc:	MONITORING PLOT PLAN NOT SUBMITTED
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3112
Occurrences:	Not reported
Item Number:	2079
Violation Desc:	2NDRY CONT TEST NOT DONE (6/36 MOS.)
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3151
Occurrences:	Not reported
Item Number:	2080
Violation Desc:	RELEASES NOT REPORTED/RECORDED
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3152
Occurrences:	Not reported
Item Number:	2081
Violation Desc:	MAINT. & MONITORING RECORDS AVAILABLE
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3158
Occurrences:	Not reported
Item Number:	2082
Violation Desc:	OPERATING CONDITIONS VIOLATED
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3504
Occurrences:	Not reported
Item Number:	2083
Violation Desc:	DISPENSER METERS NOT CALIBRATED
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3504
Occurrences:	Not reported
Item Number:	2084
Violation Desc:	DISPENSER METERS NOT CALIBRATED
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3504
Occurrences:	Not reported
Item Number:	2085
Violation Desc:	DISPENSER METERS NOT CALIBRATED
Inspection Date:	09/16/02
Waste Code:	Not reported
Type of Violation:	6HV3506
Occurrences:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JR GAS AND MINI MART (Continued)**

**U003789710**

Item Number: 2086  
 Violation Desc: NO BIENNIAL 0.1 GPH TANK INT. TEST

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3506  
 Occurrences: Not reported

Item Number: 2087  
 Violation Desc: NO BIENNIAL 0.1 GPH TANK INT. TEST

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3506  
 Occurrences: Not reported

Item Number: 2088  
 Violation Desc: NO BIENNIAL 0.1 GPH TANK INT. TEST

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3507  
 Occurrences: Not reported

Item Number: 2089  
 Violation Desc: ANNUAL SIR REPORT NOT SUBMITTED

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3507  
 Occurrences: Not reported

Item Number: 2090  
 Violation Desc: ANNUAL SIR REPORT NOT SUBMITTED

Inspection Date: 09/16/02  
 Waste Code: Not reported  
 Type of Violation: 6HV3507  
 Occurrences: Not reported

Item Number: 2091  
 Violation Desc: ANNUAL SIR REPORT NOT SUBMITTED

Inspection Date: 09/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3505  
 Occurrences: Not reported

Item Number: 5130  
 Violation Desc: SIR NOT CAPABLE OF DETECTING 0.2 GPH

Inspection Date: 09/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3507  
 Occurrences: Not reported

Item Number: 5131  
 Violation Desc: ANNUAL SIR REPORT NOT SUBMITTED

Inspection Date: 09/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3102  
 Occurrences: Not reported

Item Number: 5132

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**JR GAS AND MINI MART (Continued)**

**U003789710**

Violation Desc: OPERATING PERMIT CURRENT & AT FACILITY?

Inspection Date: 09/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5133  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3102  
 Occurrences: Not reported  
 Item Number: 5769  
 Violation Desc: OPERATING PERMIT CURRENT & AT FACILITY?

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3105  
 Occurrences: Not reported  
 Item Number: 5770  
 Violation Desc: FINANCIAL RESPONSIBILITY EXPIRED

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3107  
 Occurrences: Not reported  
 Item Number: 5771  
 Violation Desc: UST MONITORING PLAN NOT COMPLETE

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3108  
 Occurrences: Not reported  
 Item Number: 5772  
 Violation Desc: UST EM RESPONSE PLAN NOT COMPLETE

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3109  
 Occurrences: Not reported  
 Item Number: 5773  
 Violation Desc: MONITORING PLOT PLAN NOT SUBMITTED

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3152  
 Occurrences: Not reported  
 Item Number: 5774  
 Violation Desc: MAINT. & MONITORING RECORDS AVAILABLE

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3253  
 Occurrences: Not reported  
 Item Number: 5775  
 Violation Desc: STICKER/TAG NOT AFFIXED TO MONIT. EQUIP.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JR GAS AND MINI MART (Continued)**

**U003789710**

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3253  
 Occurrences: Not reported  
 Item Number: 5776  
 Violation Desc: STICKER/TAG NOT AFFIXED TO MONIT. EQUIP.

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3263  
 Occurrences: Not reported  
 Item Number: 5777  
 Violation Desc: MONITORING SYSTEM NOT FUNCTIONAL

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3263  
 Occurrences: Not reported  
 Item Number: 5778  
 Violation Desc: MONITORING SYSTEM NOT FUNCTIONAL

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3401  
 Occurrences: Not reported  
 Item Number: 5779  
 Violation Desc: NO CONTIN. AUDIO&VISUAL ALARM W/+SHUT

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3401  
 Occurrences: Not reported  
 Item Number: 5780  
 Violation Desc: NO CONTIN. AUDIO&VISUAL ALARM W/+SHUT

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5781  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 11/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5782  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 09/24/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 10



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**JR GAS AND MINI MART (Continued)**

**U003789710**

Annual Qty String: 10  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED FUEL FILTERS/ABSORBA  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 21212  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021212-000001  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 3

Status: A  
 Comp Number: 21212  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021212-000002  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 21212  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021212-000003  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JR GAS AND MINI MART (Continued)**

**U003789710**

Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H21212-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 10/24/2002  
 Begandt: 7/25/2001

55

**ADVANCE DIESEL INJECTION INC  
 2049 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104748499  
 N/A**

**San Diego Co. HMMD:**

Facility ID: 115806  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2049 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000018717  
 Gas Station: Not reported  
 Inspection Date: 10/19/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: STUART TEUSCHER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GLASSON FAMILY SURVIVORS TRUST  
 Property Address: P O BOX 6456  
 Property City,St,Zip: 92166  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-6452

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCE DIESEL INJECTION INC (Continued)**

**S104748499**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**PERFORMANCE CONTRACTING GROUP  
 2015 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103980403  
 San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAC001497376  
 Contact: P A S  
 Telephone: 6192361533  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2015 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PERFORMANCE CONTRACTING GROUP (Continued)**

**S103980403**

Tons: .4500  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 115416  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2015 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/03/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ERNIE MARTINEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GLASSON FAMILY SURVIVORS TRUST  
 Property Address: P O BOX 6456  
 Property City,St,Zip: 92166  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/03/06  
 Facility Phone: 619-236-1531

HMMD DISCLOSURE INVENTORY:

Item Number: CH79  
 Chemical Name: CHLORINATED PARAFFIN, FOSTER 30-36/30-80/81-27; VIMASSCO  
 Case Number: 108-17126-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PR80  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PERFORMANCE CONTRACTING GROUP (Continued)**

**S103980403**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: TI81  
 Chemical Name: TITANIUM DIOXIDE- CP50  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: TO78  
 Chemical Name: TOLUENE, HEXANE, ACETONE, ADHESIVE, ARMSTRONG 520  
 Case Number: 108-88-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/09/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 8666  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 09/09/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1006  
 Occurrences: Not reported  
 Item Number: 8667  
 Violation Desc: HMBP: INVENTORY INADEQUATE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PERFORMANCE CONTRACTING GROUP (Continued)**

**S103980403**

Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**PERFORMANCE CONTRACTING, INC**  
**2015 MAIN ST**  
**SAN DIEGO, CA 92113**

**FINDS 1000230374**  
**RCRA-CESQG CAD981379217**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-CESQG:**

Date form received by agency: 02/04/1986  
 Facility name: PERFORMANCE CONTRACTING, INC  
 Facility address: 2015 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981379217  
 Mailing address: P O BOX 13189  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2015 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 236-1531  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Conditionally Exempt Small Quantity Generator  
 Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PERFORMANCE CONTRACTING, INC (Continued)**

**1000230374**

hazardous waste

Owner/Operator Summary:

Owner/operator name: OWENS/CORNING FIBERGL  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

55

**LOOMIS MAINTENANCE GARAGE  
 2007 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104749251  
 N/A**

San Diego Co. HMMD:

Facility ID: 119891  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2719 MARKET ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92102  
 Map Code/Business Plan on File: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LOOMIS MAINTENANCE GARAGE (Continued)**

**S104749251**

Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000006757  
 Gas Station: Not reported  
 Inspection Date: 03/20/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MARVIN ROBBINS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RAGTIME L L C  
 Property Address: C/O ROBERT SHAPIRO  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-8026

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LOOMIS MAINTENANCE GARAGE (Continued)**

**S104749251**

Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**NATIONAL PETROLEUM,INC  
 2005 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104749252  
 N/A**

San Diego Co. HMMD:

Facility ID: 119892  
 Inactive Indicator: Active  
 Business Code: 6HK78  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2005 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000142503  
 Gas Station: Not reported  
 Inspection Date: 12/22/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: HANK WURTZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RAGTIME L L C  
 Property Address: C/O ROBERT SHAPIRO  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/22/05  
 Facility Phone: 619-239-0256

HMMD DISCLOSURE INVENTORY:

Item Number: 2-51  
 Chemical Name: 2-BUTOXYETHANOL 10%, SUPER CLEAN  
 Case Number: 111-76-2  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PETROLEUM,INC (Continued)**

**S104749252**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: BR47  
 Chemical Name: BRAKE FLUID  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ET50  
 Chemical Name: ETHYLENE GLYCOL, ANTIFREEZE  
 Case Number: 107211  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: KE49  
 Chemical Name: KEROSENE  
 Case Number: 91-20-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: MI48  
 Chemical Name: MINERAL SPIRITS  
 Case Number: 8052-41-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OI46

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL PETROLEUM,INC (Continued)**

**S104749252**

Chemical Name: OIL: LUBRICATING  
 Case Number: 50-00-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PR19  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/03/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3871  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/03/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3872  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 09/18/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 7781  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/18/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7782

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PETROLEUM,INC (Continued)**

**S104749252**

Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9849  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 07/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9850  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9851  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 07/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 9852  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 12/22/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 7066  
 Violation Desc: WASTE CONTAINER NOT CLOSED

**HMMD WASTE STREAMS:**

Inspection Date: 12/22/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 440  
 Annual Qty String: 440  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2790 EVERGREEN ENVIRONMEN  
 Waste Desc: MIXED OILS  
 Carcinogen: No

Inspection Date: 12/22/03  
 Waste Item #: 512  
 Waste Code: 512  
 Waste Name: EMPTY CONTNR(30 GAL+

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PETROLEUM,INC (Continued)**

**S104749252**

Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 1275  
 Annual Qty String: 1275  
 Measurement Unit: LBS  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: DRUMS-EMPTY  
 Carcinogen: No

Facility ID: 150145  
 Inactive Indicator: Active  
 Business Code: 6HK10  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2005 MAIN ST  
 Mailing City,St,Zip: RAMONA, CA 92065  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Ramona  
 Census Tract Number: 208  
 EPA ID: CAL000143103  
 Gas Station: Not reported  
 Inspection Date: 05/09/03  
 Reinspection Date: Not reported  
 Inspector Name: EPAREDES  
 Violation Notice Issued: Not reported  
 Facility Contact: JAMES HILL DDS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: HILL JAMES L&KATHLEEN M TRS  
 Property Address: 12900 CAMINO DEL VAL  
 Property City,St,Zip: 92064  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/09/06  
 Facility Phone: 619-789-2330

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PETROLEUM,INC (Continued)**

**S104749252**

2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/02/93  
 Waste Code: Not reported  
 Type of Violation: 6HX4008  
 Occurrences: Not reported  
 Item Number: 9692  
 Violation Desc: MEDWASTE CONTAINER IMPROP LABELED

Inspection Date: 08/02/93  
 Waste Code: Not reported  
 Type of Violation: 6HX4012  
 Occurrences: Not reported  
 Item Number: 9693  
 Violation Desc: INADEQUATE TRAINING FOR MEDWASTE

Inspection Date: 08/23/96  
 Waste Code: Not reported  
 Type of Violation: 6HX4008  
 Occurrences: Not reported  
 Item Number: 4796  
 Violation Desc: MEDWASTE CONTAINER IMPROP LABELED

**HMMD WASTE STREAMS:**

Inspection Date: 05/09/03  
 Waste Item #: 541  
 Waste Code: 541  
 Waste Name: PHOTOCHEM/PHOTOPROC  
 Qnty at Inspection: 16  
 Quantity String: 16  
 Annual Qty: 16  
 Annual Qty String: 16  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: SPENT PHOTOFIXER  
 Carcinogen: No

Inspection Date: 05/09/03  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH  
 Qnty at Inspection: 12  
 Quantity String: 12  
 Annual Qty: 24  
 Annual Qty String: 24  
 Measurement Unit: LBS  
 Treatment Method: 105 DISENFECTION/ENC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PETROLEUM,INC (Continued)**

**S104749252**

Storage Method: PLASTIC BOTTLE  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: ISOLYZER  
 Carcinogen: No

55

**NATIONAL PETROLEUM, INC.  
 2005 MAIN ST.  
 SAN DIEGO, CA 92113**

**HAZNET**

**S103639915  
 N/A**

HAZNET:

Gepaid: CAL000142503  
 Contact: DAVID GOLOKOW  
 Telephone: 6192390256  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2005 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 2.62  
 Facility County: Not reported

Gepaid: CAL000142503  
 Contact: DAVID GOLOKOW, PRESIDENT  
 Telephone: 6192390256  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2005 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD981696420  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: 1.7514  
 Facility County: San Diego

Gepaid: CAL000142503  
 Contact: DAVID GOLOKOW  
 Telephone: 6192390256  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2005 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.2  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

55 P&L KNEPP TRUCKING  
 2001 MAIN ST  
 SAN DIEGO, CA 92113

LUST S102434817  
 Cortese N/A  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303107  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1994-06-16 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: ROBERT SHAPIRO  
 RP Address: 445 G STREET  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**P&L KNEPP TRUCKING (Continued)**

**S102434817**

Local Case #: H21282-001  
 Case Number: 9UT862  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT862  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 12/17/1987  
 How Found: Tank Closure  
 Date Stopped: 12/17/1987  
 How Stopped: Remove Contents  
 Source: Piping  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 12/17/1987  
 Submit Workplan: Not reported  
 Prelim Assess: 12/23/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 6/16/94  
 Pilot Program: LOP  
 Local Case: H21282-001  
 Basin Number: 908.22  
 Gwater Depth: 26'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 12/21/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2001 MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**P&L KNEPP TRUCKING (Continued)**

**S102434817**

San Diego Co. HMMD:

Facility ID:	121282
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	Not reported
Reinspection Date:	Not reported
Inspector Name:	Not reported
Violation Notice Issued:	Not reported
Facility Contact:	Not reported
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	MERCADO APARTMENTS L P
Property Address:	C/O BARONE,GALASSO A
Property City,St,Zip:	92101
Tank Owner:	BIG BEAR SUPER MARKET NO. 3
Tank Address:	5075 FEDERAL BLVD
Tank City,St,Zip:	San Diego, CA 92102
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	T001
Tank ID Number:	#2
Waste or Product:	Not reported
Tank Contents:	REGULAR UNLEADED
Tank Number:	T002
Tank ID Number:	#1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**P&L KNEPP TRUCKING (Continued)**

**S102434817**

Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 123030  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 04/04/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MARVIN ROBBINS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RAGTIME L L C  
 Property Address: C/O ROBERT SHAPIRO  
 Property City,St,Zip: 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**P&L KNEPP TRUCKING (Continued)**

**S102434817**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 123031  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**P&L KNEPP TRUCKING (Continued)**

**S102434817**

Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: PHIL KNEPP  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RAGTIME L L C  
 Property Address: C/O ROBERT SHAPIRO  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**P&L KNEPP TRUCKING (Continued)**

**S102434817**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21282  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021282-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 21282  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021282-000002  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 21282  
 Number: 9  
 Board Of Equalization: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**P&L KNEPP TRUCKING (Continued)**

**S102434817**

Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

SAN DIEGO CO. SAM:

Case Number: H21282-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/16/1994  
 Begandt: 12/17/1987

55

**PRODUCE WAREHOUSE  
 2001 MAIN ST  
 SAN DIEGO, CA 92123**

**HIST UST U001573229  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000008364  
 Facility Type: Other  
 Other Type: WAREHOUSE  
 Total Tanks: 0002  
 Contact Name: ED DITMAN  
 Telephone: 6192633161  
 Owner Name: BIG BEAR SUPER MARKET NO. 3  
 Owner Address: 5075 FEDERAL BLVD.  
 Owner City,St,Zip: SAN DIEGO, CA 92102

Tank Num: 001  
 Container Num: #2  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 002  
 Container Num: #1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**55      ATKINSON CONSTRUCTION  
 1997 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET    S104582480  
 N/A**

HAZNET:

Gepaid:            CAL000197053  
 Contact:           CLARK CONSTRUCTION  
 Telephone:        3012728100  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address:  1997 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County:       San Diego  
 TSD EPA ID:       CAD981696420  
 TSD County:       Los Angeles  
 Waste Category:   Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons:               2.085  
 Facility County:   San Diego

Gepaid:            CAL000197053  
 Contact:           CLARK CONSTRUCTION  
 Telephone:        3012728100  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address:  1997 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County:       San Diego  
 TSD EPA ID:       CAD982444481  
 TSD County:       San Bernardino  
 Waste Category:   Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons:               9.591  
 Facility County:   San Diego

Gepaid:            CAL000197053  
 Contact:           CLARK CONSTRUCTION  
 Telephone:        3012728100  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address:  1997 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County:       San Diego  
 TSD EPA ID:       CAD028409019  
 TSD County:       Los Angeles  
 Waste Category:   Other organic solids  
 Disposal Method: Transfer Station  
 Tons:               .2250  
 Facility County:   San Diego



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

55 CP KELCO RCRA-SQG 1010314209  
 1343 CEASAR CHAVEZ PKWY CAR000183475  
 SAN DIEGO, CA 92113

RCRA-SQG:

Date form received by agency: 04/16/2007  
 Facility name: CP KELCO  
 Facility address: 1343 CEASAR CHAVEZ PKWY  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000183475  
 Mailing address: 1330 PARK CENTER DR  
 GOOD AND ROBERTS INC  
 VISTA, CA 92081  
 Contact: RUSSELL GREEN  
 Contact address: 1330 PARK CENTER DR GOOD AND ROBERTS INC  
 VISTA, CA 92081  
 Contact country: US  
 Contact telephone: 619-520-4929  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: RUSSELL GREEN  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: Not reported  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1983  
 Owner/Op end date: Not reported  
 Owner/operator name: CP KELCO  
 Owner/operator address: 1343 CEASAR CHAVEZ PKWY  
 SAN DIEGO, CA 92113  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1999  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**1010314209**

Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

55

**BURLINGTON NORHTERN AND SANTA FE RR CO  
 1342 CESAR E CHAVEZ PKWY  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000242130  
 FINDS CAD981460124  
 HAZNET**

**RCRA-SQG:**

Date form received by agency: 04/20/2004  
 Facility name: BURLINGTON NORHTERN AND SANTA FE RR CO  
 Facility address: 1342 CESAR E CHAVEZ PKWY  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981460124  
 Mailing address: 740 E CARNEGIE DR  
 SAN BERNARDINO, CA 92408-3571  
 Contact: DANIEL SILVA  
 Contact address: 740 E CARNEGIE DR  
 SAN BERNARDINO, CA 92408-3571  
 Contact country: US  
 Contact telephone: 909-386-4320  
 Contact email: DANIEL.SILVA@BNSF.COM  
 EPA Region: 09  
 Land type: Private  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BURLINGTON NORHTERN AND SANTA FE RR CO (Continued)**

**1000242130**

Owner/Operator Summary:

Owner/operator name: BURLINGTON NORTHERN AND SANTA FE RR CO  
 Owner/operator address: 740 E CARNEGIE DR  
 SAN BERNARDINO, CA 92408  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1900  
 Owner/Op end date: Not reported

Owner/operator name: BURLINGTON NORTHERN AND SANTA FE RR CO  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1900  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 10/12/2000  
 Facility name: BURLINGTON NORHTERN AND SANTA FE RR CO  
 Site name: BNSF - SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 01/17/1997  
 Facility name: BURLINGTON NORHTERN AND SANTA FE RR CO  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: BURLINGTON NORHTERN AND SANTA FE RR CO  
 Classification: Large Quantity Generator

Date form received by agency: 04/02/1990  
 Facility name: BURLINGTON NORHTERN AND SANTA FE RR CO  
 Site name: ATCHISON TOPEKA SANTA FE RR CO

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BURLINGTON NORHTERN AND SANTA FE RR CO (Continued)**

**1000242130**

Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 01/12/2004  
 Date achieved compliance: 01/16/2004  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/06/1991  
 Date achieved compliance: 07/13/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 01/18/1990  
 Date achieved compliance: 09/06/1991  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BURLINGTON NORHTERN AND SANTA FE RR CO (Continued)**

**1000242130**

Evaluation Action Summary:

Evaluation date: 01/12/2004  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 01/16/2004  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 07/13/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 01/16/2004  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 09/06/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 07/13/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 01/18/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 09/06/1991  
 Evaluation lead agency: State Contractor/Grantee

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD981460124  
 Contact: MATT GRAHAM, MGR. ENV. OPTNS  
 Telephone: 9093864082  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: 0.1  
 Facility County: Not reported

Gepaid: CAD981460124  
 Contact: MATT GRAHAM, MGR. ENV. OPTNS  
 Telephone: 9093864082

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BURLINGTON NORHTERN AND SANTA FE RR CO (Continued)**

**1000242130**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: 0.1  
 Facility County: Not reported

Gepaid: CAD981460124  
 Contact: E PHILLIPS, MGR. ENV. OPTNS  
 Telephone: 9093864082  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons: 0.07  
 Facility County: San Diego

55

**TUM YETO, INC**  
**1995 MAIN ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106060270**  
**N/A**

San Diego Co. HMMD:  
 Facility ID: 102914  
 Inactive Indicator: Active  
 Business Code: 6HK37  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1995 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000205130  
 Gas Station: Not reported  
 Inspection Date: 07/03/03  
 Reinspection Date: Not reported  
 Inspector Name: MNYAGA  
 Violation Notice Issued: Not reported  
 Facility Contact: DION THURMAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STOCKHOLM JON&DONNA FAMILY TRU

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUM YETO, INC (Continued)**

**S106060270**

Property Address: 314 SANTA HELENA  
 Property City,St,Zip: 92075  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-6291

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 4643  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4644  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 4645  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4646  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUM YETO, INC (Continued)**

**S106060270**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**RANKIN INDUSTRIES INC  
 1991 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000270599  
 FINDS CAD982481210  
 HAZNET  
 San Diego Co. HMMD**

**RCRA-SQG:**

Date form received by agency: 09/01/1996  
 Facility name: RANKIN INDUSTRIES INC  
 Facility address: 1991 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982481210  
 Mailing address: 2285 MAIN ST  
 SAN DIEGO, CA 92154  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: County  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
  
 Owner/operator name: A.I. ENGINEERING COP LIMITED  
 Owner/operator address: NOT REQUIRED



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**RANKIN INDUSTRIES INC (Continued)**

**1000270599**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: County  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 07/29/1988  
 Facility name: RANKIN INDUSTRIES INC  
 Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD982481210  
 Contact: RANKIN INDUSTRIES INC  
 Telephone: 6195756000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RANKIN INDUSTRIES INC (Continued)**

**1000270599**

(antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)

Disposal Method: Disposal, Land Fill  
 Tons: 1.2000  
 Facility County: San Diego

Gepaid: CAD982481210  
 Contact: RANKIN INDUSTRIES INC  
 Telephone: 6195756000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Metal sludge - Alkaline solution (pH <UN> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)

Disposal Method: Not reported  
 Tons: 5.9000  
 Facility County: San Diego

Gepaid: CAD982481210  
 Contact: RANKIN INDUSTRIES INC  
 Telephone: 6195756000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Metal sludge - Alkaline solution (pH <UN> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)

Disposal Method: Transfer Station  
 Tons: 2.2500  
 Facility County: San Diego

San Diego Co. HMMMD:

Facility ID: 119601  
 Inactive Indicator: Active  
 Business Code: 6HK34  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2285 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 92154  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RANKIN INDUSTRIES INC (Continued)**

**1000270599**

EPA ID: CAD982481210  
 Gas Station: Not reported  
 Inspection Date: 12/15/92  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RON MILHAUSEN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STOCKHOLM JON&DONNA FAMILY TRU  
 Property Address: 314 SANTA HELENA  
 Property City,St,Zip: 92075  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-575-6000

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RANKIN INDUSTRIES INC (Continued)**

**1000270599**

Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**A.O. REED  
 1990 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST S102423626  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT1106  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: Not reported  
 Date Found: 12/16/1988  
 How Found: Tank Closure  
 Date Stopped: 12/16/1988  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Structure Failure  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 12/15/1988  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/1/89  
 Pilot Program: LOP  
 Local Case: H00841-001  
 Basin Number: 908.22  
 Gwater Depth: 15'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 12/16/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 1990 MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

55      **A O REED**  
**1990 MAIN ST**  
**SAN DIEGO, CA 92113**

**HAZNET**      **S103639397**  
**LUST**            **N/A**  
**San Diego Co. HMMD**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

HAZNET:

Gepaid:            CAC001246328  
 Contact:          CITY OF SAN DIEGO  
 Telephone:        0000000000  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 1200 3RD AVE #1620  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County:       San Diego  
 TSD EPA ID:       CAD050806850  
 TSD County:       Los Angeles  
 Waste Category:   Off-specification, aged, or surplus organics  
 Disposal Method: Not reported  
 Tons:               .5500  
 Facility County:   San Diego

LUST:

Region:            STATE  
 Case Type:        Soil only  
 Cross Street:      Not reported  
 Enf Type:          Not reported  
 Funding:           Not reported  
 How Discovered:   Not reported  
 How Stopped:      Not reported  
 Leak Cause:        Not reported  
 Leak Source:       Not reported  
 Global Id:          T0607300114  
 Stop Date:         1988-12-15 00:00:00  
 Confirm Leak:      Not reported  
 Workplan:          Not reported  
 Prelim Assess:     Not reported  
 Pollution Char:    Not reported  
 Remed Plan:        Not reported  
 Remed Action:     Not reported  
 Monitoring:        Not reported  
 Close Date:        1989-03-21 00:00:00  
 Discover Date:      1988-12-15 00:00:00  
 Enforcement Dt:    Not reported  
 Release Date:      1988-12-15 00:00:00  
 Review Date:       Not reported  
 Enter Date:        Not reported  
 MTBE Date:        Not reported  
 GW Qualifier:      Not reported  
 Soil Qualifier:     Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County:            37  
 Org Name:          Not reported  
 Reg Board:         San Diego Region  
 Status:             Case Closed  
 Chemical:          Waste Oil  
 Contact Person:    Not reported  
 Responsible Party: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A O REED (Continued)**

**S103639397**

RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: SP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00841-001  
 Case Number: 9UT1106  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 100841  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 6720 SAN MIGUEL  
 Mailing City,St,Zip: LEMON GROVE, CA 91945  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: KENNETH RUSSEL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A O REED (Continued)**

**S103639397**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-583-3250

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 841  
 Number: Not reported  
 Board Of Equalization: 44-021583

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A O REED (Continued)**

**S103639397**

Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000841-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 1

SAN DIEGO CO. SAM:

Case Number: H00841-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/21/1989  
 Begandt: 12/15/1988

55

**TUMYETO INC**  
**1991 MAIN STREET**  
**SAN DIEGO, CA 92154**

**HAZNET S105092124**  
**N/A**

HAZNET:

Gepaid: CAL000205131  
 Contact: DION THURMAN/MGR  
 Telephone: 6192346291  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1991 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: 0.19  
 Facility County: Not reported

Gepaid: CAL000205131  
 Contact: DION THURMAN/MGR  
 Telephone: 6192346291  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1991 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.21  
 Facility County: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUMYETO INC (Continued)**

**S105092124**

Gepaid: CAL000205131  
 Contact: TUMYETI INC  
 Telephone: 6192349291  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1991 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .1000  
 Facility County: San Diego

55

**OIL FILTER SERVICE INC  
 1987 MAIN ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104749269  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 119920  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1987 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/08/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MATT MONISE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STOCKHOLM JON&DONNA FAMILY TRU  
 Property Address: 314 SANTA HELENA  
 Property City,St,Zip: 92075  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-6792

HMMD DISCLOSURE INVENTORY:  
 Item Number: Not reported  
 Chemical Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OIL FILTER SERVICE INC (Continued)**

**S104749269**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**UNION ELECTRIC MOTOR SERVICE  
 2046 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104747425  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 112640  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2046 NEWTON AV  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNION ELECTRIC MOTOR SERVICE (Continued)**

**S104747425**

Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAD981991342  
 Gas Station: Not reported  
 Inspection Date: 03/11/94  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: WM PETERS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ARCINIEGA MERCEDES L  
 Property Address: 1922 RUTHIE WAY  
 Property City,St,Zip: 92139  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-4881

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNION ELECTRIC MOTOR SERVICE (Continued)**

**S104747425**

Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**55 UNION ELECTRIC MOTOR SVC  
 2046 NEWTON AVE  
 SAN DIEGO, CA 92077**

**HAZNET 1000336712  
 N/A**

HAZNET:  
 Gepaid: CAD981991342  
 Contact: UNION ELECTRIC MOTOR SVS  
 Telephone: 6192324881  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2046 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 920770000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .1167  
 Facility County: San Diego

**55 MAAC PRO ECT, SDG&E  
 2043 NEWTON AVE  
 SAN DIEGO, CA 92113**

**LUST S101302112  
 Cortese N/A**

LUST:  
 Region: 9  
 Case Number: 9UT2363  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 01/27/1993  
 How Found: Other Means  
 Date Stopped: 01/27/1993  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 02/18/1993

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAAC PRO ECT, SDG&E (Continued)**

**S101302112**

Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H32282-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/LOW - LOW POTENTIAL HEALTH/SAFTY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 02/18/1993  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 2043 NEWTON AVE

55

**SDG & E**  
**2043 NEWTON AV**  
**SAN DIEGO, CA 92113**

**LUST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**S104753100**  
**N/A**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301132  
 Stop Date: 1993-02-18 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2001-04-26 00:00:00  
 Discover Date: 1993-01-27 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1993-02-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG & E (Continued)**

**S104753100**

Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: ATTN: MS. SARA ISGUR  
 RP Address: P.O. BOX 1831  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: SW  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H32282-001  
 Case Number: 9UT2363  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 132282  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 1831  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: W G BRULL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG & E (Continued)**

**S104753100**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MERCADO APARTMENTS L P  
 Property Address: C/O BARONE,GALASSO|A  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-2417

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT2815  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG & E (Continued)**

**S104753100**

Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H32282-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 4/26/2001  
 Begandt: 1/27/1993

55

**MARINE PUMP SERVICE  
 1977 MAIN ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S10475531  
 N/A**

San Diego Co. HMMD:

Facility ID: 136355  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 382  
 Mailing City,St,Zip: LA MESA, CA 91944  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/18/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: CHARLES CHENELLE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STOCKHOLM JON&DONNA FAMILY TRU  
 Property Address: 314 SANTA HELENA  
 Property City,St,Zip: 92075  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-7345

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE PUMP SERVICE (Continued)**

**S104755531**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/24/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4026  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**CORROSION ENGINEERING SVCS  
 1444 CROSBY ST  
 SAN DIEGO, CA 92113**

**FINDS 1004675875  
 RCRA-NonGen CAR000078212**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-NonGen:**

Date form received by agency: 02/08/2001  
 Facility name: CORROSION ENGINEERING SVCS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CORROSION ENGINEERING SVCS (Continued)**

**1004675875**

Facility address: 1444 CROSBY ST  
 POWDER COATING FACILITY  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000078212  
 Mailing address: 1065 BAY BLVD STE A  
 CHULA VISTA, CA 91911  
 Contact: CHRIS BRADY  
 Contact address: 1065 BAY BLVD STE A  
 CHULA VISTA, CA 91911  
 Contact country: US  
 Contact telephone: (619) 422-0313  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: CORROSION ENG SVCS INC  
 Owner/operator address: 3635 RUFFIN RD STE 100  
 SAN DIEGO, CA 92123  
 Owner/operator country: Not reported  
 Owner/operator telephone: (858) 514-1280  
 Legal status: Other  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D000  
 Waste name: Not Defined  
 Waste code: D006  
 Waste name: CADMIUM  
 Waste code: D007  
 Waste name: CHROMIUM  
 Waste code: D008

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**CORROSION ENGINEERING SVCS (Continued)**

1004675875

Waste name: LEAD  
 Violation Status: No violations found

55 **TUNA CLIPPER  
 1444 CROSBY ST  
 SAN DIEGO, CA 92101**

**LUST S105036552  
 Cortese N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1444 CROSBY ST

55 **TUNA CLIPPER MARINE  
 1444 CROSBY ST  
 SAN DIEGO, CA 92113**

**HAZNET U001572999  
 LUST N/A  
 HIST UST  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

HAZNET:  
 Gepaid: CAL000016863  
 Contact: PORT OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2040 HARBOR ISLAND DR # SUIT208  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Not reported  
 Tons: 1.2510  
 Facility County: San Diego

Gepaid: CAL000016863  
 Contact: PORT OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2040 HARBOR ISLAND DR # SUIT208  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: 7.0890  
 Facility County: San Diego

Gepaid: CAL000016863  
 Contact: PORT OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUNA CLIPPER MARINE (Continued)**

**U001572999**

Mailing Address: 2040 HARBOR ISLAND DR # SUIT208  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: .8340  
 Facility County: San Diego

Gepaid: CAL000016863  
 Contact: PORT OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2040 HARBOR ISLAND DR # SUIT208  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .6046  
 Facility County: San Diego

Gepaid: CAL000016863  
 Contact: PORT OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2040 HARBOR ISLAND DR # SUIT208  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .8339  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 3 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301052  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUNA CLIPPER MARINE (Continued)**

**U001572999**

Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-03-03 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: JOHN REARDON, PROP DEPT  
 RP Address: P O BOX 488  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05633-002  
 Case Number: 9UT2286  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUNA CLIPPER MARINE (Continued)**

**U001572999**

How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608178516  
 Stop Date: 1992-04-06 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-03-03 00:00:00  
 Discover Date: 1992-04-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-04-06 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: DAVID HEINE  
 RP Address: 2040-#203 HARBOR ISLAND DRIVE  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05633-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUNA CLIPPER MARINE (Continued)**

**U001572999**

**LUST:**

Region: 9  
 Case Number: 9UT2286  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 08/11/1992  
 How Found: Tank Closure  
 Date Stopped: 08/11/1992  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Remove Free Product - remove floating product from water table  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 11/18/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 3/3/97  
 Pilot Program: LOP  
 Local Case: H05633-002  
 Basin Number: 908.22  
 Gwater Depth: 6'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - ADMINISTRATIVE (CLOSURE/SB2004/ENFORCEMENT)  
 File Dispn: File discarded, case closed  
 Release Date: 08/11/1992  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**HIST UST:**

Region: STATE  
 Facility ID: 00000068665  
 Facility Type: Other  
 Other Type: MARINE FUEL STATION  
 Total Tanks: 0001  
 Contact Name: G. KENNETH ALAMEDA  
 Telephone: 6192321838  
 Owner Name: TUNA CLIPPER MARINE  
 Owner Address: 1444 CROSBY STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92113  
 Tank Num: 001  
 Container Num: 1  
 Year Installed: 1965

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TUNA CLIPPER MARINE (Continued)**

**U001572999**

Tank Capacity: 00010000  
 Tank Used for: WASTE  
 Type of Fuel: 2  
 Tank Construction: Unkown centimeters  
 Leak Detection: Pressure Test

**SWEEPS UST:**

Status: A  
 Comp Number: 5633  
 Number: 9  
 Board Of Equalization: 44-022254  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005633-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H05633-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/3/1997  
 Begandt: 4/6/1992

Case Number: H05633-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 3/3/1997  
 Begandt: 4/6/1992

55

**CORROSION ENGRG,POWDER COATING  
 1444 CROSBY ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S105112827  
 N/A**

San Diego Co. HMMD:

Facility ID: 105633  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3635 RUFFIN RD #100  
 Mailing City,St,Zip: SAN DIEGO, CA 92123  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CORROSION ENGRG,POWDER COATING (Continued)**

**S105112827**

Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAR000078212  
 Gas Station: Not reported  
 Inspection Date: 01/03/01  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DAVID EVANS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: TUNA CLIPPER MARINE  
 Tank Address: 2040 HARBOR ISLAND  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-422-0313

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CORROSION ENGRG,POWDER COATING (Continued)**

**S105112827**

Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**1444 CROSBY ST.  
 SAN DIEGO, CA**

**CHMIRS S100216746  
 N/A**

CHMIRS:

OES Incident Number: 8904500  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 20-JAN-89  
**Date Completed: 20-JAN-89**  
 Property Use: 600  
 Agency Id Number: 37140  
 Agency Incident Number: 39494  
 Time Notified: 1259  
 Time Completed: 1332  
 Surrounding Area: 099  
 Estimated Temperature: 72  
 Property Management: C  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agncy Personel # Of Decontaminated: 0  
 Responding Agency Personel # Of Injuries: 0  
 Responding Agency Personel # Of Fatalities:0  
 Others Number Of Decontaminated: 0  
 Others Number Of Injuries: 0  
 Others Number Of Fatalities: 0  
 Vehicle Make/year: TRACTOR TRAILER TANKER  
 Vehicle License Number: BP84423 DT21784  
 Vehicle State: CA  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: PETROLEUM DELIVERY INC.  
 Reporting Officer Name/ID: RICHARD LEAP  
 Report Date: 20-JAN-89  
 Comments: Not reported  
 Facility Telephone: 619 236-7773  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**(Continued)**

**S100216746**

Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	14-MAY-90
Substance:	Not reported
Quantity Released:	Not reported
BBLs:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

---

55      **1444 CROSBY ST. (FUELING DOCK)**  
**1444 CROSBY ST. (FUELING DOCK)**  
**SAN DIEGO, CA 92113**

**ERNS 91236836**  
**N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

55      **1342 CROSBY STREET**  
**SAN DIEGO, CA**

**HMIRS 2002033981**  
**N/A**

[Click this hyperlink](#) while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

55      **1342 CROSBY**  
**1342 CROSBY**  
**SAN DIEGO, CA 0**

**ERNS**    **2002624487**  
**N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

55      **SANTA FE INTERMODAL**  
**1342 CROSBY ST**  
**SAN DIEGO, CA 92113**

**HAZNET**    **S101301969**  
**LUST**      **N/A**  
**CHMIRS**  
**Cortese**  
**San Diego Co. HMMD**  
**CA WDS**

HAZNET:

Gepaid:            CAD981460124  
 Contact:          JOHN D CHAVEZ MGR ENV  
 Telephone:        9093864082  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County:       San Diego  
 TSD EPA ID:      CAD028409019  
 TSD County:       San Diego  
 Waste Category:   Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons:              0.03  
 Facility County:   San Diego

Gepaid:            CAD981460124  
 Contact:          JOHN D CHAVEZ MGR ENV  
 Telephone:        9093864082  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County:       San Diego  
 TSD EPA ID:      CAT080013352  
 TSD County:       San Diego  
 Waste Category:   Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons:              10.42  
 Facility County:   San Diego

Gepaid:            CAD981460124  
 Contact:          JOHN D CHAVEZ MGR ENV  
 Telephone:        9093864082  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County:       San Diego  
 TSD EPA ID:      CAD099452708  
 TSD County:       San Diego  
 Waste Category:   Waste oil and mixed oil  
 Disposal Method: Recycler

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Tons: 0.08  
 Facility County: San Diego

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Not reported  
 Leak Source: Tank  
 Global Id: T0607300700  
 Stop Date: 1991-02-15 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1993-02-02 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1991-02-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-02-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Matthew Graham  
 RP Address: 740 East Carnegie Drive  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: CF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00076-002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Case Number: 9UT1920  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Tank  
 Global Id: T0607301247  
 Stop Date: 1993-03-15 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1993-03-15 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1993-03-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1993-03-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Matthew Graham  
 RP Address: 740 East Carnegie Drive  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: CF  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00076-003  
 Case Number: 9UT2495  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608114213  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1991-01-24 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: MICK HARDIN  
 RP Address: 740 E CARNEGIE AV  
 Interim: Not reported  
 Oversight Prgm: LOCNL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00076-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT1920  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 02/15/1991  
 How Found: Other Means  
 Date Stopped: 02/15/1991  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Remedial action (cleanup) Underway  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Remove Free Product - remove floating product from water table  
 Confirm Date: 02/25/1991  
 Submit Workplan: 2/25/91  
 Prelim Assess: 02/25/1991  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 2/25/91  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H00076-002  
 Basin Number: 908.22  
 Gwater Depth: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 02/15/1991  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**CHMIRS:**

OES Incident Number: 02-5318  
 OES notification: 10/1/200210:51:09 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: No  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: San Diego Co Coroner  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Year: 2002  
 Agency: BNSF RR  
 Incident Date: 10/1/200212:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Rail Road  
 E Date: Not reported  
 Substance: N/A  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 1  
 Description: A truck driver was found deceased on rail Rd property. no Foul play Evident.  
 Incident under investigation by San Diego PD.

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1342 CROSBY ST

San Diego Co. HMMD:  
 Facility ID: 100076  
 Inactive Indicator: Active  
 Business Code: 6HK52  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: JOHN CHAVEZ  
 Mailing Address: 740 E CARNEGIE DR  
 Mailing City, St, Zip: SAN BERNARDINO, CA 92408  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD981460124  
 Gas Station: Not reported  
 Inspection Date: 01/12/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ATCHISON TOPEKA&SANTA FE RAILW  
 Property Address: CALIFORNIA STATE ASS  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/12/05  
 Facility Phone: 909-386-4082

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC89  
 Chemical Name: ACETYLENE GAS  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: FU93  
 Chemical Name: FUSEES (FLARES)  
 Case Number: 10042-76-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: OX90  
 Chemical Name: OXYGEN GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: REACTIVE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT2154  
 Waste or Product: Not reported  
 Tank Contents: LEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Tank Number: T002  
 Tank ID Number: AT2154  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: AT2154  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T004  
 Tank ID Number: AT2883  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T005  
 Tank ID Number: AT2883  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T006  
 Tank ID Number: AT2883  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T007  
 Tank ID Number: AT2992  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 04/08/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3927  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/08/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3928  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 07/08/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 7674  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 07/05/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9418

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 07/05/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9419  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/05/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9420  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 01/12/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 7414  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 01/12/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 330  
 Annual Qty String: 330  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0147 CONSOLIDATED WASTE I  
 Waste Desc: MAINTENANCE SECTION  
 Carcinogen: No

Inspection Date: 01/12/04  
 Waste Item #: 222  
 Waste Code: 222  
 Waste Name: OIL/WATER SEPARATION  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: UNGD TNK  
 Haz Waste Hauler: 0147 CONSOLIDATED WASTE I  
 Waste Desc: ONE OIL & WATER SEPARATOR  
 Carcinogen: No

Inspection Date: 01/12/04  
 Waste Item #: 444  
 Waste Code: 444

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Waste Name: USED BATTERIES/ALKAL  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0147 CONSOLIDATED WASTE I  
 Waste Desc: LANTERN BATTERIES  
 Carcinogen: No

Inspection Date: 01/12/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 250  
 Quantity String: 250  
 Annual Qty: 250  
 Annual Qty String: 250  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3238 HAZPAK, INC.  
 Waste Desc: Not reported  
 Carcinogen: No

**CA WDS:**

Facility ID: San Diego 371012999  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: BURLINGTON NORTHERN & SANTA FE  
 Agency Address: 740 E. CARNEGIE DR.  
 Agency City,St,Zip: SAN BERNARDINO 92408  
 Agency Contact: MICK HARDEN  
 Agency Telephone: 9043864081  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE INTERMODAL (Continued)**

**S101301969**

Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.  
 Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

55

**BURLINGTON NORTHERN AND SANTA FE RAILWAY  
 1342 CROSBY ST  
 SAN DIEGO, CA 92113**

**HAZNET S103628780  
 N/A**

HAZNET:

Gepaid: CAD981460124  
 Contact: BURLINGTON NORTHERN AND SANTA  
 Telephone: 9093864082  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Treatment, Tank  
 Tons: 11.3506  
 Facility County: San Diego

Gepaid: CAD981460124  
 Contact: BURLINGTON NORTHERN AND SANTA  
 Telephone: 9093864082  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Latex waste  
 Disposal Method: Transfer Station  
 Tons: .4170  
 Facility County: San Diego

Gepaid: CAD981460124  
 Contact: BURLINGTON NORTHERN AND SANTA  
 Telephone: 9093864082  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BURLINGTON NORTHERN AND SANTA FE RAILWAY (Continued)**

**S103628780**

TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons: .0275  
 Facility County: San Diego

Gepaid: CAD981460124  
 Contact: BURLINGTON NORTHERN AND SANTA  
 Telephone: 9093864082  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .1042  
 Facility County: San Diego

Gepaid: CAD981460124  
 Contact: BURLINGTON NORTHERN AND SANTA  
 Telephone: 9093864082  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 740 CARNEGIE DR  
 Mailing City,St,Zip: SAN BERNARDINO, CA 924083571  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus inorganics  
 Disposal Method: Transfer Station  
 Tons: .3000  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 62 additional CA\_HAZNET: record(s) in the EDR Site Report.

55

**SANTA FE RAILWAY  
 1342 CROSBY ST  
 SAN DIEGO, CA 92113**

**LUST S100725175  
 Cortese N/A  
 SWEEPS UST**

LUST:  
 Region: 9  
 Case Number: 9UT2495  
 Local Agency: San Diego  
 Substance: Regular Gasoline  
 Qty Leaked: 0  
 Date Found: 06/03/1993  
 How Found: Tank Closure  
 Date Stopped: 03/15/1993  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE RAILWAY (Continued)**

**S100725175**

Status: Remedial action (cleanup) Underway  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Enhanced Biodegradation - use of any available technology to promote bacterial decomposition of contaminants  
 Confirm Date: 03/15/1993  
 Submit Workplan: 6/28/93  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 3/15/93  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H00076-003  
 Basin Number: 908.22  
 Gwater Depth: 12'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 06/28/1993  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1342 CROSBY ST

**SWEEPS UST:**  
 Status: Not reported  
 Comp Number: 76  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000076-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 76  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANTA FE RAILWAY (Continued)**

**S100725175**

Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000076-000002  
 Actv Date: Not reported  
 Capacity: 1200  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 76  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000076-000003  
 Actv Date: Not reported  
 Capacity: 1200  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 76  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**55 VEHICLE PROCESSING & DISTRIBUTION  
 1300 CROSBY  
 SAN DIEGO, CA 92113**

**HAZNET S103627684  
 N/A**

HAZNET:  
 Gepaid: CAL000143405  
 Contact: CORPORATION  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1300 CROSBY ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**VEHICLE PROCESSING & DISTRIBUTION (Continued)**

**S103627684**

TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: .1000  
 Facility County: San Diego

Gepaid: CAL000143405  
 Contact: CORPORATION  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1300 CROSBY ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: .4500  
 Facility County: San Diego

Gepaid: CAL000143405  
 Contact: CORPORATION  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1300 CROSBY ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: 0.1  
 Facility County: San Diego

Gepaid: CAL000143405  
 Contact: CORPORATION  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1300 CROSBY ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 0.2293  
 Facility County: San Diego

Gepaid: CAL000143405  
 Contact: CORPORATION  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1300 CROSBY ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VEHICLE PROCESSING & DISTRIBUTION (Continued)**

**S103627684**

Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 6.4301  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

55

**ALLIED TANK CLEANING CORP  
 1883 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92101**

**ENVIROSTOR 1000249041  
 N/A**

ENVIROSTOR:

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37420015  
 Site Code: Not reported  
 Assembly: Not reported  
 Senate: Not reported  
 Special Program: \* CERC2  
 Status: Refer: Other Agency  
 Status Date: 1995-08-21 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37420015  
 SPRR  
 Alias Type: Alternate Name  
 Envirostor ID Number

APN: NONE SPECIFIED

APN Description: Not reported

Comments: Site is an active generator. Staff recommends NFA for DTSC.FACILITY IDENTIFIED VIA DRIVEBY FACILITY DRIVE-BY DARKLY STAINED SOIL W/ PUDDLING. ABOUT 40 DRUMS ON LOADING DOCK.SITE SCREENING DONE PA RECOM BASED ON SEVERELY STAINED SOIL OVER A LARGE AREASUBMIT TO EPA NO FURTHER ACTION FOR EPA. SITE WILL NOT SCORE ABOVE 28 IN MITRE MODEL PRELIM ASSESS DONE UNCLER HAZ WST HANDLING & DISPOSAL PRACTICES AT SITE. SAMPLING SHOULD BE DONE IN STAINED AREAS.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 10/27/94

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALLIED TANK CLEANING CORP (Continued)**

**1000249041**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 01/11/88

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 03/02/87

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 06/01/83

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

**Management:**

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 10060, 10097, 10098, 10120, 10193, 10196, 10199  
 Potential Description: \* OIL/WATER SEPARATION SLUDGE  
 Potential Description: \* CONTAMINATED SOIL  
 Potential Description: \* DETERGENT & SOAP  
 Potential Description: \* ACID SOLUTION WITHOUT METALS  
 Potential Description: \* UNSPECIFIED ACID SOLUTION  
 Potential Description: \* UNSPECIFIED OIL CONTAINING WASTE  
 Potential Description: \* WASTE OIL & MIXED OIL  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

55

**ACME AWING & CANVUS COMPANY**  
**1961 MAIN ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106070754**  
**N/A**

San Diego Co. HMMD:

Facility ID: 200641  
 Inactive Indicator: Active  
 Business Code: 6HK50  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1961 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACME AWING & CANVUS COMPANY (Continued)**

**S106070754**

Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/26/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DAN LITTLE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STOCKHOLM JON&DONNA FAMILY TRU  
 Property Address: 314 SANTA HELENA  
 Property City,St,Zip: 92075  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/26/05  
 Facility Phone: 619-557-9322

**HMMD DISCLOSURE INVENTORY:**

Item Number: CA01  
 Chemical Name: CARBON DIOXIDE  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: PR00  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/21/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACME AWING & CANVUS COMPANY (Continued)**

**S106070754**

Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 0951  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 08/21/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 0952  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**ABREST WELDING AND FABRICATION  
 1212 CROSBY ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD S104749214  
 N/A

San Diego Co. HMMD:  
 Facility ID: 119833  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1212 CROSBY ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 02/23/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: TED TURNER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABREST WELDING AND FABRICATION (Continued)**

**S104749214**

Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	FELIPE-ARONZO CORP
Property Address:	1827 MAIN ST
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-696-0677

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qnty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**55 CROSBY ST CORRIDOR  
 1200 CROSBY ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106064118  
 N/A**

San Diego Co. HMMD:

Facility ID:	134128
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1200 3RD AV 1620
Mailing City, St, Zip:	SAN DIEGO, CA 92104
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	Not reported
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	Not reported
Reinspection Date:	Not reported
Inspector Name:	Not reported
Violation Notice Issued:	Not reported
Facility Contact:	BYRON ESTES-CITY OF SAN DIEGO
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	Not reported
Property Address:	Not reported
Property City, St, Zip:	Not reported
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City, St, Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CROSBY ST CORRIDOR (Continued)**

**S106064118**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**KIB MOTORS  
 1950 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104748442  
 N/A**

San Diego Co. HMMD:

Facility ID: 115414  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1841 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAD981972169  
 Gas Station: Not reported  
 Inspection Date: 07/17/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ALLEN WISELEY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**KIB MOTORS (Continued)**

**S104748442**

Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-6114

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

<b>55</b>	<b>1880 HARBOR DRIVE</b> <b>1880 HARBOR DRIVE</b> <b>SAN DIEGO, CA</b>	<b>ERNS</b>	<b>2007320188</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

<b>55</b>	<b>CALTRANS CORONADO BRIDGE MT ST</b> <b>1120 DEWEY STREET</b> <b>SAN DIEGO, CA 92113</b>	<b>RCRA-SQG</b> <b>FINDS</b>	<b>1000419441</b> <b>CAD982519969</b>
-----------	---	---------------------------------	--

RCRA-SQG:

Date form received by agency: 04/26/1989  
 Facility name: CALTRANS CORONADO BRIDGE MT ST  
 Facility address: 1120 DEWEY STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982519969  
 Mailing address: DEWEY STREET  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1120 DEWEY STREET  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 237-7802  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CALTRANS  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALTRANS CORONADO BRIDGE MT ST (Continued)**

**1000419441**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 11/19/2003  
 Date achieved compliance: 02/19/2004  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 11/19/2003  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 02/19/2004  
 Evaluation lead agency: State Contractor/Grantee

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**55**      **MERCADO COMMERCIAL CENTER**  
**1920 MAIN ST**  
**SAN DIEGO, CA 92113**

**LUST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**S104755426**  
**N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608182788  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2007-03-12 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Rudy Gonzalez  
 RP Address: 600 B Street, MS 904  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: COMPLAINT  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H36157-001  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MERCADO COMMERCIAL CENTER (Continued)**

**S104755426**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 136157  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1200 3RD AV CC REDE  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: BYRON ESTES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MERCADO COMMERCIAL CENTER (Continued)**

**S104755426**

2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H36157-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/12/2007  
 Begandt: 3/28/1996

55

**CORONADO TOLL BRIDGE MAINT FAC  
 1995 NEWTON AVE  
 SAN DIEGO, CA 92113**

**CA WDS S105558044  
 N/A**

**CA WDS:**

Facility ID: San Diego 000000999  
 Facility Type: Other - Does not fall into the category of Municipal/Domestic, Industrial, Agricultural or Solid Waste (Class I, II or III)  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000003 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CORONADO TOLL BRIDGE MAINT FAC (Continued)**

**S105558044**

Facility Contact: DAVE ANNIS  
 Agency Name: CALTRANS DISTRICT 11  
 Agency Address: 2829 JUAN STREET PO BOX 85406  
 Agency City,St,Zip: SAN DIEGO 922865406  
 Agency Contact: CORY BINNS  
 Agency Telephone: 6196883626  
 Agency Type: State  
 SIC Code: 1611  
 SIC Code 2: Not reported  
 Primary Waste: Stormwater Runoff  
 Primary Waste Type: Nonhazardous Solid Wastes/Influent or Solid Wastes that contain nonhazardous putrescible and non putrescible solid, semisolid, and liquid wastes (E.G., garbage, trash, refuse, paper, demolition and construction wastes, manure, vegetable or animal solid and semisolid waste).  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: No reclamation requirements associated with this facility.  
 POTW: The facility is not a POTW.  
 Treat To Water: Major Threat to Water Quality. A violation could render unusable a ground water or surface water resource used as a significant drink water supply, require closure of an area used for contact recreation, result in long-term deleterious effects on shell fish spawning or growth areas of aquatic resources, or directly expose the public to toxic substances.  
 Complexity: Category A - Any major NPDES facility, any non-NPDES facility (particularly those with toxic wastes) that would be a major if discharge was made to surface or ground waters, or any Class I disposal site. Includes any small-volume complex facility (particularly those with toxicwastes) with numerous discharge points, leak detection systems or ground water monitoring wells.

55

**CALTRANS/CORONADO BRIDGE  
 1995 NEWTON ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104750346  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 123408  
 Inactive Indicator: Active  
 Business Code: 6HK52  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ATTN: LANNY CHRONERT  
 Mailing Address: P.O. BOX 85406  
 Mailing City,St,Zip: SAN DIEGO, CA 92186  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD982519969  
 Gas Station: Not reported  
 Inspection Date: 11/19/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CALTRANS/CORONADO BRIDGE (Continued)**

**S104750346**

Facility Contact: LANNY CHRONERT  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MERCADO APARTMENTS L P  
 Property Address: C/O BARONE,GALASSO|A  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/19/05  
 Facility Phone: 619-645-2865

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC14  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: MI42  
 Chemical Name: MINERAL SPIRITS  
 Case Number: 8052-41-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX41  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: PA40  
 Chemical Name: PAINT (ALSO DP1)  
 Case Number: 111-77-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CALTRANS/CORONADO BRIDGE (Continued)**

**S104750346**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/23/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0196  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/23/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3715  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5857  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5858  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 11/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 6216  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 11/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 6217  
 Violation Desc: HMBP: INADEQUATE SITE MAP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALTRANS/CORONADO BRIDGE (Continued)**

**S104750346**

Inspection Date: 11/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6218  
 Violation Desc: WASTE CONTAINER NOT CLOSED

**HMMD WASTE STREAMS:**

Inspection Date: 11/19/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 385  
 Quantity String: 385  
 Annual Qty: 385  
 Annual Qty String: 385  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0919 DISPOSAL CONTROL SER  
 Waste Desc: SPENT COPPER BLAST/SLAG  
 Carcinogen: No

Inspection Date: 11/19/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: PARTS CLNR(PTROLEUM NAPTH  
 Carcinogen: No

Inspection Date: 11/19/03  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 550  
 Quantity String: 550  
 Annual Qty: 550  
 Annual Qty String: 550  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0115 HAZ MAT TRANS, INC.  
 Waste Desc: \*  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**55 CALTRANS DISTRICT 11-CORONADO BRIDGE  
 1995 NEWTON AVE  
 SAN DIEGO, CA 92113**

**FINDS 1007738682  
 HAZNET 110018987621**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

**HAZNET:**

Gepaid: CAD982519969  
 Contact: CALTRANS, LANNY CHRONERT, MS57  
 Telephone: 8586166556  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85406  
 Mailing City,St,Zip: SAN DIEGO, CA 921865406  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: Recycler  
 Tons: 0.12  
 Facility County: Not reported

Gepaid: CAD982519969  
 Contact: CALTRANS, F SANTIBANEZ, MS-220  
 Telephone: 6196883657  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 4050 TAYLOR STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921100000  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: 16  
 Facility County: San Diego

Gepaid: CAD982519969  
 Contact: CALTRANS, LANNY CHRONERT, MS57  
 Telephone: 8586166556  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85406  
 Mailing City,St,Zip: SAN DIEGO, CA 921865406  
 Gen County: San Diego  
 TSD EPA ID: CAD059494310  
 TSD County: San Diego  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 2  
 Facility County: San Diego

Gepaid: CAD982519969  
 Contact: CALTRANS, LANNY CHRONERT, MS57  
 Telephone: 8586166556

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALTRANS DISTRICT 11-CORONADO BRIDGE (Continued)**

**1007738682**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85406  
 Mailing City,St,Zip: SAN DIEGO, CA 921865406  
 Gen County: San Diego  
 TSD EPA ID: CAD059494310  
 TSD County: San Diego  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Disposal, Other  
 Tons: 0.25  
 Facility County: San Diego

Gepaid: CAD982519969  
 Contact: CALTRANS, LANNY CHRONERT, MS57  
 Telephone: 8586166556  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85406  
 Mailing City,St,Zip: SAN DIEGO, CA 921865406  
 Gen County: San Diego  
 TSD EPA ID: CAD059494310  
 TSD County: San Diego  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: 2.29  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

55

**CALTRANS DISTRICT 11-CORONADO BRIDGE  
 1995 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S104574879  
 N/A**

HAZNET:

Gepaid: CAD982519969  
 Contact: CALTRANS DISTRICT 11  
 Telephone: 8584673247  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 7183 OPPORTUNITY RD  
 Mailing City,St,Zip: SAN DIEGO, CA 921110000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Latex waste  
 Disposal Method: Disposal, Other  
 Tons: .1876  
 Facility County: San Diego

Gepaid: CAD982519969  
 Contact: CALTRANS DISTRICT 11  
 Telephone: 8584673247  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 7183 OPPORTUNITY RD  
 Mailing City,St,Zip: SAN DIEGO, CA 921110000  
 Gen County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CALTRANS DISTRICT 11-CORONADO BRIDGE (Continued)**

**S104574879**

TSD EPA ID: CAD089446710  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .1876  
 Facility County: San Diego

Gepaid: CAD982519969  
 Contact: LANNY CHRONERT/HAZ MAT MGR  
 Telephone: 6196883334  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 4120 TAYLOR ST MS 68  
 Mailing City,St,Zip: SAN DIEGO, CA 921112739  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: 1.25  
 Facility County: Not reported

Gepaid: CAD982519969  
 Contact: LANNY CHRONERT/HAZ MAT MGR  
 Telephone: 6196883334  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 4120 TAYLOR ST MS 68  
 Mailing City,St,Zip: SAN DIEGO, CA 921112739  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: 0.33  
 Facility County: Not reported

Gepaid: CAD982519969  
 Contact: LANNY CHRONERT/HAZ MAT MGR  
 Telephone: 6196883334  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 4120 TAYLOR ST MS 68  
 Mailing City,St,Zip: SAN DIEGO, CA 921112739  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.6  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access 13 additional CA\_HAZNET: record(s) in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**55 NATIONAL PUMP & INJECTOR CORP HAZNET S100940606**  
**1901 MAIN ST N/A**  
**SAN DIEGO, CA 92113**

HAZNET:

Gepaid: CAD981162266  
 Contact: NON-DELIVERABLE 4/94 FEE FORM  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1901 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.75  
 Facility County: Not reported

Gepaid: CAD981162266  
 Contact: NON-DELIVERABLE 4/94 FEE FORM  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1901 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Not reported  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons: 0.2  
 Facility County: Not reported

Gepaid: CAD981162266  
 Contact: NON-DELIVERABLE 4/94 FEE FORM  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1901 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Not reported  
 Tons: 0.2  
 Facility County: Not reported

Gepaid: CAD981162266  
 Contact: NON-DELIVERABLE 4/94 FEE FORM  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1901 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PUMP & INJECTOR CORP (Continued)**

**S100940606**

TSD County: Not reported  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.75  
 Facility County: Not reported

Gepaid: CAD981162266  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1901 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .0667  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

55

**NATIONAL PUMP & INJECTOR  
 1901 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103957304  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAC001238248  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1200 3RD AVENUE #1620  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Off-specification, aged, or surplus inorganics  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAC001238248  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1200 3RD AVENUE #1620  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PUMP & INJECTOR (Continued)**

**S103957304**

Gepaid: CAC001238248  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1200 3RD AVENUE #1620  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Latex waste  
 Disposal Method: Transfer Station  
 Tons: .0425  
 Facility County: San Diego

Gepaid: CAC001238248  
 Contact: CITY OF SAN DIEGO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1200 3RD AVENUE #1620  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: .3336  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMMD:

Facility ID: 111046  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1901 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAD981162266  
 Gas Station: Not reported  
 Inspection Date: 03/16/89  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ROSS CLYBORNE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL PUMP & INJECTOR (Continued)**

**S103957304**

Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	Not reported
Property Address:	Not reported
Property City,St,Zip:	Not reported
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-232-0831

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**55 NATIONAL PUMP INJECTOR(FORMER)  
 1901 MAIN STREET  
 SAN DIEGO, CA 92113**

**ENVIROSTOR S106797751  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37990010  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-09-12 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37990010  
 110002678996  
 Alias Type: EPA (FRS #)  
 Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

55 A.E.P. CORP.  
 1901 MAIN ST  
 SAN DIEGO, CA 92113

LUST  
 San Diego Co. HMMD  
 HIST UST  
 SWEEPS UST

U001572967  
 N/A

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608189862  
 Stop Date: 2001-08-17 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2002-01-14 00:00:00  
 Discover Date: 2001-08-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-08-17 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: CRAIG FERGUSON  
 RP Address: 9601 RIDGEHAVEN CT #310  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H11046-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A.E.P. CORP. (Continued)**

**U001572967**

Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 101089  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1901 MAI MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CHUEYS NUMERO UNO INC  
 Property Address: P O BOX 13810  
 Property City,St,Zip: 92170  
 Tank Owner: A.E.P. CORPORATION  
 Tank Address: 1901 T MAIN STREET  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-295-3131

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A.E.P. CORP. (Continued)**

**U001572967**

1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: UG-100  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**HIST UST:**

Region: STATE  
 Facility ID: 00000010743  
 Facility Type: Other  
 Other Type: METAL ROOFING  
 Total Tanks: 0001  
 Contact Name: J.W. GASKINS  
 Telephone: 6192953131  
 Owner Name: A.E.P. CORPORATION  
 Owner Address: 1901 MAIN STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: UG-100  
 Year Installed: 1970  
 Tank Capacity: 00000550  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Visual

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A.E.P. CORP. (Continued)**

**U001572967**

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 1089  
 Number: Not reported  
 Board Of Equalization: 44-021596  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-001089-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 1089  
 Number: 9  
 Board Of Equalization: 44-021596  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

55

**SAN DIEGO CITY REDEVELOPMENT AGENCY  
 1901 MAIN STREET  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000840789  
 FINDS CAD981162266**

**RCRA-SQG:**

Date form received by agency: 11/06/2001  
 Facility name: S D CITY REDEVELOPMENT AGENCY  
 Facility address: 1901 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981162266  
 Mailing address: 600 B ST STE 400  
 SAN DIEGO, CA 92101  
 Contact: BENJAMIN HUESO  
 Contact address: 600 B ST STE 400  
 SAN DIEGO, CA 92101  
 Contact country: US  
 Contact telephone: (619) 535-5214  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO CITY REDEVELOPMENT AGENCY (Continued)**

**1000840789**

hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: S D CITY ENV SRVCS DEPT  
 Owner/operator address: 9601 RIDGEHAVEN CRT STE 320  
 SAN DIEGO, CA 92123  
 Owner/operator country: Not reported  
 Owner/operator telephone: (858) 492-5005  
 Legal status: Municipal  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:

Waste code: D000  
 Waste name: Not Defined

Waste code: D008  
 Waste name: LEAD

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO CITY REDEVELOPMENT AGENCY (Continued)**

**1000840789**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**55 FORMER NATIONAL PUMP AND  
 1901 MAIN ST  
 SAN DIEGO, CA 92113**

**SAN DIEGO CO. SAM**

**S108407049  
 N/A**

SAN DIEGO CO. SAM:

Case Number: H11046-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/14/2002  
 Begandt: 8/17/2001

**55 CHAMPION CONSTRUCTION CO.  
 1969 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104748614  
 N/A**

San Diego Co. HMMD:

Facility ID: 116515  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1969 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/23/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: FRANK YOUNG  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHAMPION CONSTRUCTION CO. (Continued)**

**S104748614**

Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-0108

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

55      **CABINERY DESIGN INC**      **HAZNET**      **S108200074**  
**1878 MAIN ST**  
**SAN DIEGO, CA 92113**      **N/A**

HAZNET:  
 Gepaid: CAL000289311  
 Contact: JOHN LEIMBACH  
 Telephone: 6192339326  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1878 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.79  
 Facility County: Not reported

Gepaid: CAL000289311  
 Contact: JOHN LEIMBACH  
 Telephone: 6192339326  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1878 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.18  
 Facility County: San Diego

55      **NO NAME-FOUND ON TOP OF FILES**      **San Diego Co. HMMD**      **S105112720**  
**1960 NEWTON AV**  
**SAN DIEGO, CA 92113**      **N/A**

San Diego Co. HMMD:  
 Facility ID: 102370  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NO NAME-FOUND ON TOP OF FILES (Continued)**

**S105112720**

Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	Not reported
Property Address:	Not reported
Property City,St,Zip:	Not reported
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**NO NAME-FOUND ON TOP OF FILES (Continued)**

**S105112720**

Carcinogen: No

**55 REAL'S AUTO BODY  
1957 NEWTON AVE  
SAN DIEGO, CA 92113**

**HAZNET S100871938  
N/A**

HAZNET:  
 Gepaid: CAL000090059  
 Contact: JUAN REAL  
 Telephone: 6195638654  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1957 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921132119  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

**55 LUNA TRANSMISSIONS  
1957 NEWTON AV  
SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104746275  
N/A**

San Diego Co. HMMD:  
 Facility ID: 105889  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1957 1/2 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 06/09/92  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JUAN LUNA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LUNA TRANSMISSIONS (Continued)**

**S104746275**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-231-0730

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 116514  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LUNA TRANSMISSIONS (Continued)**

**S104746275**

Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1957 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAL000090059  
 Gas Station: Not reported  
 Inspection Date: 04/09/96  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JUAN REAL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-7906

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LUNA TRANSMISSIONS (Continued)**

**S104746275**

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**NEPTUNE OIL COMPANY  
 1950 NEWTON AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104748612  
 N/A**

San Diego Co. HMMD:

Facility ID: 116513  
 Inactive Indicator: Active  
 Business Code: 6HK78  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: PAUL OLIVER  
 Mailing Address: 1950 PO BOX 944  
 Mailing City,St,Zip: EL CAJON, CA 92022  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAD043314764  
 Gas Station: Not reported  
 Inspection Date: 10/22/92  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JOHN KROESCHE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: ACE HIGH/G & H TRUCKING  
 Tank Address: 1950 NEWTON AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-6992

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NEPTUNE OIL COMPANY (Continued)**

**S104748612**

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT1044-1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**NEPTUNE OIL COMPANY  
 1950 NEWTON AVE  
 SAN DIEGO, CA 92113**

**SWEEPS UST S106929853  
 N/A**

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 16513  
 Number: Not reported  
 Board Of Equalization: 44-022956  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NEPTUNE OIL COMPANY (Continued)**

**S106929853**

Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-016513-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 1

Status: A  
 Comp Number: 16513  
 Number: 9  
 Board Of Equalization: 44-022956  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

55

**ROMANS TRUCKING PAINTING  
 1941 NEWTON AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000153065  
 FINDS CAD982374787  
 HAZNET  
 San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: ROMANS TRUCKING PAINTING  
 Facility address: 1941 NEWTON AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982374787  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ROMANS TRUCKING PAINTING (Continued)**

**1000153065**

Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: ROMAN EFREN  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 05/04/1988  
 Facility name: ROMANS TRUCKING PAINTING  
 Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD982374787  
 Contact: Not reported  
 Telephone: 0000000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ROMANS TRUCKING PAINTING (Continued)**

**1000153065**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1941 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921132119  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 1.1758  
 Facility County: San Diego

San Diego Co. HMMMD:

Facility ID: 119921  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1941 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: CAD982374787  
 Gas Station: Not reported  
 Inspection Date: 03/14/96  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: EFREN ROMAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-1588

HMMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ROMANS TRUCKING PAINTING (Continued)**

**1000153065**

Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 126437  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1941 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ROMANS TRUCKING PAINTING (Continued)**

**1000153065**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**55 COUNTY OF DIEGO-ENVIRO SERVICE HAZNET S103638768**  
**1931 NEWTON AVE N/A**  
**SAN DIEGO, CA 92102**

HAZNET:  
 Gepaid: CAC001157520  
 Contact: COUNTY OF SAN DIEGO  
 Telephone: 6195731264  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 4950 MURPHY CANYON RD MS-89  
 Mailing City,St,Zip: SAN DIEGO, CA 921230000  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 3.2868  
 Facility County: San Diego

**55 JOHNSON TRUCK REPAIR & PAINT LUST S104745875**  
**1931 NEWTON AV San Diego Co. HMMD N/A**  
**SAN DIEGO, CA 92113 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608164552  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1994-01-13 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JOHNSON TRUCK REPAIR & PAINT (Continued)**

**S104745875**

Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04173-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 104173  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3611 PRINCE ST  
 Mailing City, St, Zip: ESCONDIDO, CA 92025  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JOHNSON TRUCK REPAIR & PAINT (Continued)**

**S104745875**

Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H04173-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JOHNSON TRUCK REPAIR & PAINT (Continued)**

**S104745875**

FType: Complaint  
 FStatus: Preliminary Assessment  
 Date: 1/13/1994  
 Begandt: 12/14/1987

55

**CENTER CITY TOWING  
 1911 NEWTON AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104751682  
 N/A**

San Diego Co. HMMD:

Facility ID: 128708  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1911 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/05/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RAUL JOSE JAQUEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-2489

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CENTER CITY TOWING (Continued)**

**S104751682**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**EMM, ELECTRICAL MOTOR MACHINE  
 1837 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S104572665  
 San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAC002222169  
 Contact: E M M LLC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1837 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 1.1467  
 Facility County: San Diego

**San Diego Co. HMMD:**

Facility ID: 138703  
 Inactive Indicator: Active  
 Business Code: 6HK77  
 SIC: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EMM, ELECTRICAL MOTOR MACHINE (Continued)**

**S104572665**

Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1837 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAL000214766  
 Gas Station: Not reported  
 Inspection Date: 12/03/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: KEVIN MCMILLAN, GEN MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TEACHER LUCY TR&TEACHER THEODO  
 Property Address: 32162 SEA ISLAND DR  
 Property City,St,Zip: 92629  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-744-3777

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EMM, ELECTRICAL MOTOR MACHINE (Continued)**

**S104572665**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**AVION DYNAMICS CORP  
 1827 MAIN STREET  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000336612  
 FINDS CAD982371809  
 San Diego Co. HMMD  
 SWEEPS UST**

**RCRA-SQG:**

Date form received by agency: 04/22/1988  
 Facility name: AVION DYNAMICS CORP  
 Facility address: 1827 MAIN STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982371809  
 Mailing address: MAIN STREET  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1827 MAIN STREET  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 544-9449  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: DAVID HADJES  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AVION DYNAMICS CORP (Continued)**

**1000336612**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

San Diego Co. HMMD:

Facility ID: 115797  
 Inactive Indicator: Active  
 Business Code: 6HK33  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1827 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAD982371809  
 Gas Station: Not reported  
 Inspection Date: 02/08/94  
 Reinspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AVION DYNAMICS CORP (Continued)**

**1000336612**

Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RICHARD PALMER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MITCHELL INVESTMENTS  
 Property Address: 1827 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: SAN DIEGO GLASS & PAINT COMPAN  
 Tank Address: 1827 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-544-9449

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AVION DYNAMICS CORP (Continued)**

**1000336612**

Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 15797  
 Number: Not reported  
 Board Of Equalization: 44-021644  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015797-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 15797  
 Number: Not reported  
 Board Of Equalization: 44-021644  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015797-000002  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 15797  
 Number: 9  
 Board Of Equalization: 44-021644  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

---

**AVION DYNAMICS CORP (Continued)**

**1000336612**

Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

---

**55 SAN DIEGO GLASS & PAINT COMPAN  
1827 MAIN ST  
SAN DIEGO, CA 92113**

**HIST UST U001572992  
N/A**

HIST UST:

Region:	STATE
Facility ID:	00000014918
Facility Type:	Other
Other Type:	CORPORATE OFFICES &
Total Tanks:	0002
Contact Name:	HOWARD PENDERGRASS
Telephone:	6192399251
Owner Name:	SAN DIEGO GLASS & PAINT COMPAN
Owner Address:	1827 MAIN STREET
Owner City,St,Zip:	SAN DIEGO, CA 92113

Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

---

**55 CALIFORNIA WATER CONDITIONING  
1884 NEWTON AV  
SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748611  
N/A**

San Diego Co. HMMD:

Facility ID:	116509
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1884 E NEWTON AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA WATER CONDITIONING (Continued)**

**S104748611**

Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/04/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JACK KNIGHT  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: VILLELA JAVIER M  
 Property Address: 3347 BONITA MESA RD  
 Property City,St,Zip: 91902  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-531-0096

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA WATER CONDITIONING (Continued)**

**S104748611**

Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

55

**QUALITY REFRIGERATION CO.  
 1815 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMD**

**S104755550  
 N/A**

HAZNET:

Gepaid: CAL000213937  
 Contact: MICHEAL BRAM/ MGR  
 Telephone: 6192301534  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1815 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAL000213937  
 Contact: JEFF HAWKE  
 Telephone: 3105491532  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1815 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL000213937  
 Contact: JEFF HAWKE  
 Telephone: 3105491532  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1815 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene,

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**QUALITY REFRIGERATION CO. (Continued)**

**S104755550**

etc.)  
 Disposal Method: Transfer Station  
 Tons: .0625  
 Facility County: San Diego

**San Diego Co. HMMD:**

Facility ID: 136380  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1815 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000213937  
 Gas Station: Not reported  
 Inspection Date: 03/27/02  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE BRAM, MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: COZAD W LEE TR&BRADLEY STORMY  
 Property Address: 3675 LOHE RD  
 Property City,St,Zip: 96741  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-230-1534

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**QUALITY REFRIGERATION CO. (Continued)**

**S104755550**

Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/31/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 7057  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 08/31/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 7058  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

Inspection Date: 08/31/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 7059  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 08/31/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7060  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/29/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 8104  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 07/29/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8105  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6098  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**QUALITY REFRIGERATION CO. (Continued)**

**S104755550**

Item Number: 6099  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**55 ORIENT ENGINES & PARTS INC  
 1805 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S100869658  
 N/A**

**HAZNET:**

Gepaid: CAL000064270  
 Contact: RAMON SERNA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1805 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Recycler  
 Tons: .0834  
 Facility County: San Diego

**55 FRYER KNOWLES INC  
 1858 NEWTON AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000210744  
 FINDS CAD982031320  
 HAZNET  
 San Diego Co. HMMD**

**RCRA-SQG:**

Date form received by agency: 08/24/1987  
 Facility name: FRYER KNOWLES INC  
 Facility address: 1858 NEWTON AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982031320  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 1858 NEWTON AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 236-0091

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRYER KNOWLES INC (Continued)**

**1000210744**

Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: BITTNER KEITH  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRYER KNOWLES INC (Continued)**

**1000210744**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid:	CAD982031320
Contact:	KEITH H BITTNER
Telephone:	6192360091
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1858 NEWTON AVE
Mailing City,St,Zip:	SAN DIEGO, CA 921132118
Gen County:	San Diego
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	5.2125
Facility County:	San Diego
Gepaid:	CAD982031320
Contact:	KEITH H BITTNER
Telephone:	6192360091
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1858 NEWTON AVE
Mailing City,St,Zip:	SAN DIEGO, CA 921132118
Gen County:	San Diego
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.834
Facility County:	San Diego

**San Diego Co. HMMMD:**

Facility ID:	100647
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1858 NEWTON AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	CAD982031320
Gas Station:	Not reported
Inspection Date:	11/05/03
Reinspection Date:	Not reported
Inspector Name:	AQUECAN

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRYER KNOWLES INC (Continued)**

**1000210744**

Violation Notice Issued: Not reported  
 Facility Contact: KEN RASMUSSEN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BITTNER BARBARA J TR  
 Property Address: 2060 S TULARE DR  
 Property City,St,Zip: 92264  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/05/05  
 Facility Phone: 619-236-0091

**HMMD DISCLOSURE INVENTORY:**

Item Number: AS20  
 Chemical Name: ASSORTED PAINTS, GROUTS, SEALERS  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: CO19  
 Chemical Name: COLORFLAKE BASECOAT PART A  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: EP18  
 Chemical Name: EPOXY RESIN (COMPONENT A)-TERRAZO  
 Case Number: 25085-99-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1 WASTE OI

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FRYER KNOWLES INC (Continued)**

**1000210744**

Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 8056  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 09/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8057  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8058  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 8059  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

Inspection Date: 04/13/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 4515  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

Inspection Date: 04/13/01  
 Waste Code: Not reported  
 Type of Violation: 6HX0081  
 Occurrences: Not reported  
 Item Number: 4516  
 Violation Desc: TREATING HAZWASTE WITHOUT AUTHORIZATION

Inspection Date: 04/13/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1006  
 Occurrences: Not reported  
 Item Number: 4517  
 Violation Desc: HMBP: INVENTORY INADEQUATE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRYER KNOWLES INC (Continued)**

**1000210744**

Inspection Date: 11/05/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5833  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/05/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5834  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

**HMMD WASTE STREAMS:**

Inspection Date: 11/05/03  
 Waste Item #: 272  
 Waste Code: 272  
 Waste Name: POLYMERIC RESIN WAST  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: GAL  
 Treatment Method: 003 LANDFILL  
 Storage Method: CAN  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: CURED, HARDENED  
 Carcinogen: No

Inspection Date: 11/05/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 25  
 Quantity String: 25  
 Annual Qty: 25  
 Annual Qty String: 25  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: BATTERIES-FORKLIFT, ETC.  
 Carcinogen: No

55

**SUPERIOR CRANE AND RIGGING, INC.**  
**1779 MAIN STREET**  
**SAN DIEGO, CA 92113**

**CERC-NFRAP 1003879836**  
**CAD983658477**

CERC-NFRAP:  
 Site ID: 0904777  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUPERIOR CRANE AND RIGGING, INC. (Continued)**

**1003879836**

CERCLIS-NFRAP Site Contact Name(s):

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: STANDARD IRON WORKS  
 Alias Address: FOOT OF BEARDSLEY  
 CA

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/08/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 09/17/1993  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 09/17/1993  
 Priority Level: NFRAP (No Further Remedial Action Planned)

55

**SUPERIOR CRANE AND RIGGING  
 1779 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD  
 SWEEPS UST**

**1000710151  
 N/A**

San Diego Co. HMMD:

Facility ID: 106167  
 Inactive Indicator: Active  
 Business Code: 6HK07  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1779 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/16/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DAVID MCMAHON/OWNER & GEN MGR  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUPERIOR CRANE AND RIGGING (Continued)**

**1000710151**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: YOUNGS MARKET CO  
 Property Address: 2164 N BATAVIA ST  
 Property City,St,Zip: 92865  
 Tank Owner: YOUNGS MARKET  
 Tank Address: 1779 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-5291

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUPERIOR CRANE AND RIGGING (Continued)**

**1000710151**

Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 6167  
 Number: Not reported  
 Board Of Equalization: 44-022344  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-006167-000001  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 6167  
 Number: Not reported  
 Board Of Equalization: 44-022344  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-006167-000002  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

55

**PERKINS ELEMENTARY  
 1770 MAIN STREET  
 SAN DIEGO, CA 92113**

**FINDS 1008304709  
 110021986430**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

Not reported

NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**55 WEST MARINE DIESEL  
 1835 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100948269  
 N/A**

HAZNET:

Gepaid: CAL000038931  
 Contact: WEST MARINE DIESEL  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .5000  
 Facility County: San Diego

Gepaid: CAL000038931  
 Contact: WEST MARINE DIESEL  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: .0290  
 Facility County: San Diego

Gepaid: CAL000038931  
 Contact: WEST MARINE DIESEL  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Recycler  
 Tons: .6672  
 Facility County: San Diego

Gepaid: CAL000038931  
 Contact: RICK PALACIOS  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WEST MARINE DIESEL (Continued)**

**S100948269**

TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: 0.05  
 Facility County: Not reported

Gepaid: CAL000038931  
 Contact: WEST MARINE DIESEL  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1835 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Alkaline solution without metals (pH > 12.5)  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 9 additional CA\_HAZNET: record(s) in the EDR Site Report.

55

**WEST MARINE DIESEL  
 1835 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104746568  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 108302  
 Inactive Indicator: Active  
 Business Code: 6HK33  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1835 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000038931  
 Gas Station: Not reported  
 Inspection Date: 10/03/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: RICK PALACIOS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PALACIOS-DELLY INC <DBA WEST M  
 Property Address: 1835 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WEST MARINE DIESEL (Continued)**

**S104746568**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/03/05  
 Facility Phone: 619-232-2883

**HMMD DISCLOSURE INVENTORY:**

Item Number: PR83  
 Chemical Name: PROPANE GAS-CYLINDER  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/13/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1216  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

**HMMD WASTE STREAMS:**

Inspection Date: 10/03/03  
 Waste Item #: 134  
 Waste Code: 134  
 Waste Name: AQUEOUS SOL'N W/LESS  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/03/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 20

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WEST MARINE DIESEL (Continued)**

**S104746568**

Annual Qty String: 20  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: CARBOY  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: SPENT SANDBLAST  
 Carcinogen: No

Inspection Date: 10/03/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: SAFETY KLEEN PARTS WASHER  
 Carcinogen: No

55

**SAN DIEGO EXPRESS PRINTING  
 1805 NEWTON AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104751011  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 126210  
 Inactive Indicator: Active  
 Business Code: 6HK37  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1805 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000030642  
 Gas Station: Not reported  
 Inspection Date: 12/05/01  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JEAN PIERRE EDERY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BASILE PAUL  
 Property Address: 640 10TH AVE  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS PRINTING (Continued)**

**S104751011**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-702-5141

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 05/19/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 7058  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 05/19/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7059  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 06/02/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4825  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 06/02/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4826  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0401

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS PRINTING (Continued)**

**S104751011**

Occurrences: Not reported  
 Item Number: 1858  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 1859  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 1860  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 135494  
 Inactive Indicator: Active  
 Business Code: 6HK55  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1805 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO EXPRESS PRINTING (Continued)**

**S104751011**

Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	BASILE PAUL
Property Address:	640 10TH AVE
Property City,St,Zip:	92101
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**55**      **SAN DIEGO EXPRESS PRINTING**      **HAZNET**      **S105093301**  
**1805 NEWTON AVENUE**  
**SAN DIEGO, CA 92113**      **N/A**

HAZNET:  
 Gepaid: CAL000218685  
 Contact: JEAN-PIERRE EDERY/OWNER  
 Telephone: 6197025141  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1805 NEWTON AVENUE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.13  
 Facility County: Not reported

Gepaid: CAL000218685  
 Contact: JEAN-PIERRE EDERY  
 Telephone: 6197025141  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1805 NEWTON AVENUE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .0625  
 Facility County: San Diego

**55**      **1110 BEARDSLEY STREET, SAN DIEGO, CA 92112**      **FINDS**      **1009410967**  
**SAN DIEGO, CA 92113**      **110024929906**

FINDS:  
 Other Pertinent Environmental Activity Identified at Site  
 Aerometric Information Retrieval System/Air Quality System

**56**      **BURBANK ELEMENTARY EXPANSION**      **SCH**      **S105628916**  
**2146 JULIAN AVENUE**      **ENVIROSTOR**      **N/A**  
**SAN DIEGO, CA 92113**

SCH:  
 Facility ID: 37880002  
 Site Type: School Cleanup  
 Site Type Detail: School  
 Acres: .76  
 National Priorities List: NO  
 Cleanup Oversight Agencies: SMBRP  
 Lead Agency: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BURBANK ELEMENTARY EXPANSION (Continued)**

**S105628916**

Lead Agency Description: Not reported  
 Project Manager: Not reported  
 Supervisor: Tawfiq Deek  
 Division Branch: School Evaluation - Cypress  
 Site Code: 404262-11  
 Assembly: 79  
 Senate: 40  
 Special Program Status: Not reported  
 Status: Certified  
 Status Date: 2005-10-27 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.7008  
 Longitude: -117.1374  
 Alias Name: SAN DIEGO CITY UNIFIED SCHOOL DISTRICT  
 BURBANK ELEMENTARY EXPANSION  
 37880002  
 404262-11  
 SAN DIEGO CITY USD-BURBANK ELEM EXP  
 Alias Type: Alternate Name  
 Alternate Name  
 Project Code (Site Code)  
 Alternate Name  
 Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: RAW approved for implementation  
 Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Endangerment Assessment Report  
 Completed Date: 05/03/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Workplan  
 Completed Date: 06/28/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Completion Report  
 Completed Date: 10/12/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 06/12/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 06/12/01  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Certification



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BURBANK ELEMENTARY EXPANSION (Continued)**

**S105628916**

Completed Date: 10/27/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 01/04/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 09/14/01

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1 Addendum  
 Completed Date: 06/16/04

Confirmed: 30013,, ,30013  
 Confirmed Description: Lead  
 Confirmed Description: Not reported  
 Confirmed Description: Lead  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: SOIL  
 Media Affected Desc: Soil

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30013, 30013  
 Potential Description: Lead  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA

ENVIROSTOR:  
 Site Type: School Cleanup  
 Site Type Detailed: School  
 Acres: .76  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Tawfiq Deek  
 Division Branch: School Evaluation - Cypress  
 Facility ID: 37880002  
 Site Code: 404262-11  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Certified  
 Status Date: 2005-10-27 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BURBANK ELEMENTARY EXPANSION (Continued)**

**S105628916**

Restricted Use: NO  
 Funding: School District  
 Latitude: 32.7008  
 Longitude: -117.1374  
 Alias Name: SAN DIEGO CITY UNIFIED SCHOOL DISTRICT  
 BURBANK ELEMENTARY EXPANSION  
 37880002  
 404262-11  
 SAN DIEGO CITY USD-BURBANK ELEM EXP  
 Alias Type: Alternate Name  
 Alternate Name  
 Project Code (Site Code)  
 Alternate Name  
 Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: RAW approved for implementation  
 Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Endangerment Assessment Report  
 Completed Date: 05/03/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Workplan  
 Completed Date: 06/28/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Completion Report  
 Completed Date: 10/12/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 06/12/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 06/12/01  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Certification  
 Completed Date: 10/27/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 01/04/06  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BURBANK ELEMENTARY EXPANSION (Continued)**

**S105628916**

Completed Date: 09/14/01

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1 Addendum  
 Completed Date: 06/16/04

Confirmed: 30013,, ,30013  
 Confirmed Description: Lead  
 Confirmed Description: Not reported  
 Confirmed Description: Lead  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: SOIL  
 Media Affected Desc: Soil

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30013, 30013  
 Potential Description: Lead  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA

57

**NORTH AMERICAN TERMINAL INC  
 1090 WATER ST  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000818152  
 FINDS CAD049904295  
 HAZNET  
 San Diego Co. HMMD  
 SWEEPS UST**

RCRA-SQG:  
 Date form received by agency:09/01/1996  
 Facility name: NORTH AMERICAN TERMINAL INC  
 Facility address: 1090 WATER ST  
 SAN DIEGO, CA 92101

EPA ID: CAD049904295  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Private  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Owner/Operator Summary:

Owner/operator name: NORTH AMERICAN CHEMICAL CO  
 Owner/operator address: PO BOX 367  
 TRONA, CA 93592  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 372-2462  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 09/01/1996  
 Facility name: NORTH AMERICAN TERMINAL INC  
 Classification: Small Quantity Generator

Date form received by agency: 04/22/1993  
 Facility name: NORTH AMERICAN TERMINAL INC  
 Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 10/17/2003  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD049904295  
 Contact: IMC CHEMICAL CO  
 Telephone: 7603722462  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1090 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017820  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: .0500  
 Facility County: San Diego

Gepaid: CAD049904295  
 Contact: IMC CHEMICAL CO  
 Telephone: 7603722462  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1090 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017820  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: .2000  
 Facility County: San Diego

Gepaid: CAD049904295  
 Contact: IMC CHEMICAL CO  
 Telephone: 7603722462  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1090 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017820  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD049904295  
 Contact: SEAN BATHRICK MGR PORT OPTN  
 Telephone: 6195441090  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1090 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017820

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 2.91  
 Facility County: Not reported

Gepaid: CAD049904295  
 Contact: IMC CHEMICAL CO  
 Telephone: 7603722462  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1090 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921017820  
 Gen County: San Diego  
 TSD EPA ID: CAD000633164  
 TSD County: Imperial  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 29.4980  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 23 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 102462  
 Inactive Indicator: Active  
 Business Code: 6HK68  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: NORTH AMERICAN TERMINALS, INC  
 Mailing Address: 1090 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: CAD049904295  
 Gas Station: Not reported  
 Inspection Date: 10/17/03  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: FRANCES SAWYER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: GARNAC GRAIN CO INC  
 Tank Address: 1090 WATER ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/17/05  
 Facility Phone: 619-544-1090

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC55  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: LP50  
 Chemical Name: LPS PRECISION CLEAN-DIPROPYLENE GLYCOL METHYL ETHER  
 Case Number: 34590-94-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: MI53  
 Chemical Name: MINERAL OIL WITH DIPHENYL AMINE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OI51  
 Chemical Name: OIL: ENGINE, LUBE OIL, GREASE  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OX57  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: SO52  
 Chemical Name: SODIU, TETRABORATE(ANHYDROUS) 99%,PYROBOR(DEHYDRATED BO RAX)  
 Case Number: 1330-43-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO56  
 Chemical Name: SODIUM CARBONATE, SODA ASH  
 Case Number: 497-19-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO54  
 Chemical Name: SODIUM SULFATE; ANHYDROUS (99%)  
 Case Number: 7757-82-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 02/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 6087



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/12/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 5358  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 03/12/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0203  
 Occurrences: Not reported  
 Item Number: 5359  
 Violation Desc: DAMAGED CONTAINER NOT REPACKAGED

Inspection Date: 03/12/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 5360  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

**HMMD WASTE STREAMS:**

Inspection Date: 10/17/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 10/17/03  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 240  
 Annual Qty String: 240  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2677 ADVANCED ENVIRONMENT  
 Waste Desc: NAPTHA & HEPTANE-SLIP PLT  
 Carcinogen: No

Inspection Date: 10/17/03  
 Waste Item #: 352  
 Waste Code: 352

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Waste Name: ORGANIC SOLIDS (OTHE)  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 105  
 Annual Qty String: 105  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2677 ADVANCED ENVIRONMENT  
 Waste Desc: OILY RAGS, GREASE  
 Carcinogen: No

Inspection Date: 10/17/03  
 Waste Item #: 860  
 Waste Code: 860  
 Waste Name: UNIVERSAL WASTE CRTS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: EMPTY AEROSOL CANS  
 Carcinogen: No

Inspection Date: 10/17/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

Facility ID: 204600  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1090 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 51  
 EPA ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Gas Station: Not reported  
 Inspection Date: 12/17/04  
 Reinspection Date: Not reported  
 Inspector Name: CFUENTEC  
 Violation Notice Issued: Not reported  
 Facility Contact: ILIAS KATSANIS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/17/06  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC66  
 Chemical Name: ACETYLENE GAS  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: DI60  
 Chemical Name: DIESEL FUEL IN TANK TRUCK  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OI67  
 Chemical Name: OILS, LUBRICATING  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Item Number: TR59  
 Chemical Name: TRACTOR HYDRAULIC OIL CHEVRON TORQUE FLUID  
 Case Number: 85-68-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/17/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 7132  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

**HMMD WASTE STREAMS:**

Inspection Date: 12/17/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 12/17/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: OILY ABSORBENT  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Inspection Date: 12/17/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 2000  
 Annual Qty String: 2000  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 12/17/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 2462  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002462-000001  
 Actv Date: Not reported  
 Capacity: 7500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 1

Status: A  
 Comp Number: 2462  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**NORTH AMERICAN TERMINAL INC (Continued)**

**1000818152**

Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

58

**NANDO'S GARAGE  
2078 LOGAN AV  
SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748935  
N/A**

San Diego Co. HMMD:

Facility ID:	119335
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2078 LOGAN AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	CAL000004072
Gas Station:	Not reported
Inspection Date:	01/08/04
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	CARMEN TOKARZ
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	NANDOS GARAGE
Property Address:	2078 LOGAN AVE
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	07/08/05
Facility Phone:	619-234-3200

HMMD DISCLOSURE INVENTORY:

Item Number:	MO05
Chemical Name:	MOTOR OILS
Case Number:	8002-05-9
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NANDO'S GARAGE (Continued)**

**S104748935**

Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/11/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0475  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 3613  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

**HMMD WASTE STREAMS:**

Inspection Date: 01/08/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: DIESEL  
 Carcinogen: No

Inspection Date: 01/08/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENVIR.  
 Waste Desc: WASTE OIL  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NANDO'S GARAGE (Continued)**

**S104748935**

Inspection Date: 01/08/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 40  
 Quantity String: 40  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: POWER STRIDE  
 Carcinogen: No

Inspection Date: 01/08/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: VORTEX  
 Carcinogen: No

58

**SANDEZ ORNAMENTAL IRON WORKS  
 2060 LOGAN AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S106065667  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 138623  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2060 LOGAN AV #C  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/31/02  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: AGRIPIN SANDEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SANDEZ ORNAMENTAL IRON WORKS (Continued)**

**S106065667**

Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: B&S L L C  
 Property Address: C/O MITCHELL INVS  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-235-6588

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/31/02  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 3786  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 01/31/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 3787  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANDEZ ORNAMENTAL IRON WORKS (Continued)**

**S106065667**

Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**59 COASTAL TRANSPORT CO INC  
 2351 E HARBOR BLVD DR  
 SAN DIEGO, CA 92113**

**FINDS 1000110657  
 RCRA-NonGen CAD981370521**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

**RCRA-NonGen:**

Date form received by agency: 02/11/1994  
 Facility name: COASTAL TRANSPORT CO INC  
 Facility address: 2351 E HARBOR BLVD DR  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981370521  
 Contact: DENNY DAY  
 Contact address: 1603 ACKERMAN RD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COASTAL TRANSPORT CO INC (Continued)**

**1000110657**

SAN ANTONIO, TX 78219  
 Contact country: US  
 Contact telephone: (210) 661-4287  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: COASTAL TRANSPORT CO INC  
 Owner/operator address: 1603 ACKERMAN RD  
 SAN ANTONIO, TX 78219  
 Owner/operator country: Not reported  
 Owner/operator telephone: (210) 661-4287  
 Legal status: Other  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**59 OIL FILTER SERVICE, INC.  
 2636 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103647729  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAC001214224  
 Contact: MJ MONISE  
 Telephone: 6192396792  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2636 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 115425  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2636 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/30/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: M.J. MONISE, SALES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MONISE ANTOINETTE J TR  
 Property Address: 1515 PLUM ST  
 Property City,St,Zip: 92106  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/30/05  
 Facility Phone: 619-239-6792

HMMD DISCLOSURE INVENTORY:

Item Number: NA82  
 Chemical Name: NALCOOL 2000 (NAOH, NAN03, NA B203)2, H2O, MERCAPTAN

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OIL FILTER SERVICE, INC. (Continued)**

**S103647729**

Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/28/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 8090  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 07/19/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 6466  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 07/19/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 6467  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/30/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1011  
 Occurrences: Not reported  
 Item Number: 4650  
 Violation Desc: TRAINING RECORDS NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**OIL FILTER SERVICE, INC. (Continued)**

**S103647729**

Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No

59

**PROLINE PAINTS AT0098  
2647 MAIN ST  
SAN DIEGO, CA 92113**

**San Diego Co. HMMD  
SWEEPS UST**

**S104749747  
N/A**

San Diego Co. HMMD:

Facility ID:	121203
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2647 MAIN ST
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	01/12/90
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	Not reported
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	4003 PARK CENTRE PARTNERS L L
Property Address:	8080 LA MESA BLVD #1
Property City,St,Zip:	91941
Tank Owner:	PROLINE PAINTS
Tank Address:	2647 MAIN ST
Tank City,St,Zip:	San Diego, CA 92113
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PROLINE PAINTS AT0098 (Continued)**

**S104749747**

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT0098-1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21203  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021203-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**59 SAN DIEGO COATINGS  
 2646 MAIN ST  
 SAN DIEGO, CA 92113**

**HIST UST U001573004  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000001245  
 Facility Type: Other  
 Other Type: PAINT MANUFACTURER  
 Total Tanks: 0005  
 Contact Name: ERNIE SOETERIK  
 Telephone: 6192328968  
 Owner Name: SAN DIEGO COATINGS  
 Owner Address: 2646 MAIN STREET  
 Owner City,St,Zip: SAN DIEGO, CA 921133697

Tank Num: 001  
 Container Num: 2  
 Year Installed: 1967  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 3  
 Year Installed: 1967  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 4  
 Year Installed: 1967  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 004  
 Container Num: 5  
 Year Installed: 1967  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 005  
 Container Num: 6  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported



MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**SAN DIEGO COATINGS (Continued)**

**U001573004**

Leak Detection: Stock Inventor

**59 THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
2646 MAIN ST  
SAN DIEGO, CA 92113**

**FINDS 1000139073  
HAZNET CAD044331130  
LUST  
Cortese  
RCRA-LQG  
San Diego Co. HMMD  
AIRS  
SWEEPS UST  
SAN DIEGO CO. SAM**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD044331130  
 Contact: SHERWIN WILLIAMS CO  
 Telephone: 2165662000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 PROSPECT AVE  
 Mailing City,St,Zip: CLEVELAND, OH 441150000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Transfer Station  
 Tons: 1.4700  
 Facility County: San Diego

Gepaid: CAD044331130

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Contact: SHERWIN WILLIAMS CO  
 Telephone: 2165662000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 PROSPECT AVE  
 Mailing City,St,Zip: CLEVELAND, OH 441150000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Recycler  
 Tons: 1.5150  
 Facility County: San Diego

Gepaid: CAD044331130  
 Contact: SHERWIN WILLIAMS CO  
 Telephone: 2165662000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 PROSPECT AVE  
 Mailing City,St,Zip: CLEVELAND, OH 441150000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Not reported  
 Tons: .1650  
 Facility County: San Diego

Gepaid: CAD044331130  
 Contact: SHERWIN WILLIAMS CO  
 Telephone: 2165662000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 PROSPECT AVE  
 Mailing City,St,Zip: CLEVELAND, OH 441150000  
 Gen County: San Diego  
 TSD EPA ID: KSD980633259  
 TSD County: 99  
 Waste Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)  
 Disposal Method: Not reported  
 Tons: 20.6869  
 Facility County: San Diego

Gepaid: CAD044331130  
 Contact: ERNIE SOTERIK  
 Telephone: 6192328968  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 PROSPECT AVE  
 Mailing City,St,Zip: CLEVELAND, OH 441150000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Transfer Station

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Tons: 3.5  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access 24 additional CA\_HAZNET: record(s) in the EDR Site Report.

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302716  
 Stop Date: 1986-08-29 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-06-03 00:00:00  
 Discover Date: 1986-09-03 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-08-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Stoddard Solvent  
 Contact Person: Not reported  
 Responsible Party: R. & P. MADRUGA/BELLE AIR ENT.  
 RP Address: 3456 VALEMONT ST.  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 3

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00536-001  
 Case Number: 9UT401  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT401  
 Local Agency: San Diego  
 Substance: Stoddard Solvent  
 Qty Leaked: 0  
 Date Found: 08/29/1986  
 How Found: Tank Closure  
 Date Stopped: 08/29/1986  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 08/29/1986  
 Submit Workplan: Not reported  
 Prelim Assess: 09/03/1986  
 Desc Pollution: Not reported  
 Remed Plan: 08/20/1987  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 9/3/86  
 Closed Date: 5/28/97  
 Pilot Program: LOP  
 Local Case: H00536-001  
 Basin Number: 908.22  
 Gwater Depth: 10FT  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - ADMINISTRATIVE (CLOSURE/SB2004/ENFORCEMENT)  
 File Dispn: File discarded, case closed  
 Release Date: 09/03/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2646 MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

RCRA-LQG:

Date form received by agency: 02/20/2006  
 Facility name: THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
 Facility address: 2646 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD044331130  
 Contact: RAUL ALONSO  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 232-8968  
 Telephone ext.: 4  
 Contact email: RAUL.ALONSO@SHERWIN.COM  
 EPA Region: 09  
 Land type: Private  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: KEN WINSLOW  
 Owner/operator address: 2646 MAIN ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 08/26/1996  
 Owner/Op end date: Not reported  
 Owner/operator name: THE SHERWIN-WILLIAMS CO.  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 08/26/1996  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Historical Generators:

Date form received by agency: 02/24/2004  
 Facility name: THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
 Site name: SHERWIN WILLIAMS  
 Classification: Large Quantity Generator

Date form received by agency: 02/21/2002  
 Facility name: THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
 Site name: SHERWIN WILLIAMS / PRO-LINE PAINT  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
 Site name: SHERWIN-WILLIAMS CO DBA PRO-LINE PAI  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
 Site name: PRO-LINE PAINT/SHERWIN-WILLIAMS CO  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
 Site name: PRO-LINE PAINT CO  
 Classification: Small Quantity Generator

Date form received by agency: 10/21/1980

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Facility name: THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT  
 Site name: PRO-LINE PAINT CO  
 Classification: Large Quantity Generator

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D035  
 Waste name: METHYL ETHYL KETONE

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

**Biennial Reports:**

Last Biennial Reporting Year: 2005

**Annual Waste Handled:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 64312

Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Amount (Lbs): 64312

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 64312

Facility Has Received Notices of Violations:

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 07/26/1993  
 Date achieved compliance: 07/26/1998  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 12/04/1991  
 Date achieved compliance: 07/26/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/17/1991  
 Date achieved compliance: 12/04/1991  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 07/26/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 07/26/1998  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 12/04/1991



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 07/26/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 09/17/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 12/04/1991  
 Evaluation lead agency: State Contractor/Grantee

San Diego Co. HMMD:

Facility ID: 100536  
 Inactive Indicator: Active  
 Business Code: 6HK76  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2646 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD044331130  
 Gas Station: Not reported  
 Inspection Date: 12/10/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: RAUL ALONSO/PLANT MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: 4003 PARK CENTRE PARTNERS L L  
 Property Address: 8080 LA MESA BLVD #1  
 Property City,St,Zip: 91941  
 Tank Owner: SAN DIEGO COATINGS  
 Tank Address: 2646 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/10/06  
 Facility Phone: 619-231-2313

HMMD DISCLOSURE INVENTORY:

Item Number: 1,67  
 Chemical Name: 1,1,1 TRICHLOROETHANE  
 Case Number: 71-55-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

2nd Hazard Category: Not reported

Item Number: 1,23  
 Chemical Name: 1,6 HEXAMETHYLEN DIISOCYANATE  
 Case Number: 123-86-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: 1,55  
 Chemical Name: 1,6 HEXAMETHYLENE DIISOCYANATE  
 Case Number: 26447-40-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: 1.02  
 Chemical Name: 1.6 JEXAMETHYLENE DIISOCYANATE  
 Case Number: 123-86-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: AC14  
 Chemical Name: ACETONE DIMETHYL KETONE  
 Case Number: 67-64-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: AC97  
 Chemical Name: ACRYLIC EMULSION EMULSION BT-175  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: AC05  
 Chemical Name: ACRYLIC POLYMER EMULSION  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AL20  
 Chemical Name: ALKYD RESIN 5060 IN BULK STORAGE PROPRIETARY POLYMER SOLVENTNAPHTHA HEAVY A  
 Case Number: 64741-65-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: AL21  
 Chemical Name: ALKYD RESIN 5150 IN BULK STORAGE SOLVENT NAPHTHA HEAVY ALKYLITE, NAPHTHA LI  
 Case Number: 64741-65-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: AL46  
 Chemical Name: ALKYD RESIN SOLUTION 60% MINERAL SPIRITS 40%  
 Case Number: 647-88-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: AM38  
 Chemical Name: AMMONIA 26 AMMONIUM HYDROXIDE 58%

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Case Number: 1336-21-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: AN29  
 Chemical Name: ANCAMIDE 507 AMIDOAMINE  
 Case Number: 68953-36-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: AN50  
 Chemical Name: ANCAMMIDE 700-B-75 AMINE POLYAMIDE EPOXY ADDUCT  
 Case Number: 68953-09-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: AN76  
 Chemical Name: ANHYDROUS ALUMINUM CLAY  
 Case Number: 66402-68-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AN53  
 Chemical Name: ANTITERR U SALTS OF UNSATURATED POLYIMIDES AND ACIDIC ESTERS  
 Case Number: 57-55-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Item Number: AR39  
 Chemical Name: AREOSIL 200 SILICON DIOXIDE  
 Case Number: 112945-52-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AR56  
 Chemical Name: AROMATIC ISOCYANATE DESMODUR XP7038 OR E-28  
 Case Number: 26447-40-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: BA87  
 Chemical Name: BASIC SINC MOLYBDATE ZINC OXIDE  
 Case Number: 22914-58-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: BL40  
 Chemical Name: BLACK IRON OXIDE BK5599 IRON OXIDE BLACK  
 Case Number: 1317-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: BY17  
 Chemical Name: BYK 300 POLYETHER MODIFIED DIMETHYL POLYSILOXANE  
 Case Number: 1330-20-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: BY24  
 Chemical Name: BYKETOL OK NAPHTHA LIGHT AROMATIC 65%  
 Case Number: 64742-95-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: CA32  
 Chemical Name: CALCIUM 6% PAINT DRIER CALCIUM PROPIONATE 31%  
 Case Number: 4075-81-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: CA79  
 Chemical Name: CALCIUM CARBONATE  
 Case Number: 1317-65-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CA82  
 Chemical Name: CALCIUM CARBONATE  
 Case Number: 1317-65-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CA07  
 Chemical Name: CARBON BLACK  
 Case Number: 1333-86-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CH22  
 Chemical Name: CHLORONATED ALKYD IN BULK STORAGE 5818 PROPRIETARY POLYMER  
 Case Number: 64742-95-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: CH14  
 Chemical Name: CHLORONATEED PARAFFIN RESIN  
 Case Number: 63449-39-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CM54  
 Chemical Name: CMD B60-820 POLYETHYLENE POLYAMIDE ADDUCT  
 Case Number: 1330-20-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: CO34  
 Chemical Name: COBOLT 12% PAINT DRIER COBALT 2-ETHYLHEXONATE 12%  
 Case Number: 136-52-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: CO75  
 Chemical Name: COPPER PHTHALOCYANINE BLUE  
 Case Number: 1328-53-6

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: CR41  
 Chemical Name: CRYSTALLINE SILICA  
 Case Number: 14808--60-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CU89  
 Chemical Name: CUPROUS OXIDE  
 Case Number: 1317-39-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CU90  
 Chemical Name: CUPROUS OXIDE CUPRIC OXIDE  
 Case Number: 1317-39-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: DI37  
 Chemical Name: DIBUTYL PHITHALATE  
 Case Number: 84-74-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Item Number: EB25  
 Chemical Name: EB GLYCOL ETHER EB SOLVENT 2-BUTOXYETHANOL  
 Case Number: 111-76-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: EK22  
 Chemical Name: EKTOSOL EEH-ETHYLENE GLYCOL MONO-2 ETHYLHEXYL ETHER 84%  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: EP49  
 Chemical Name: EPS 2597-100 ALKYD RESIN  
 Case Number: 67700-53-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: ET71  
 Chemical Name: ETHANOL  
 Case Number: 64-17-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ET13  
 Chemical Name: ETHYL ACETATE ACETIC ETHER  
 Case Number: 141-78-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: FU17  
 Chemical Name: FUMED SILICON DIOXIDE  
 Case Number: 7631-86-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: FU18  
 Chemical Name: FUMED SILICON DIOXIDE, TREATED  
 Case Number: 7631-86-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: GR80  
 Chemical Name: GROUND SILICA  
 Case Number: 00-1332-58-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: HA15  
 Chemical Name: HALOX 391 ZINC PHOSPHATE 45% ZINC OXIDE 15% STRONTIUM PHOSPHATE  
 Case Number: 13847-22-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: HA47  
 Chemical Name: HARDENER 815-T70 ALIPHATIC POLYAMINOAMIDE  
 Case Number: 68410-23-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: HY51  
 Chemical Name: HY 283 POLYMERIC FATTY ACIDE AMIDE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: HY03  
 Chemical Name: HYDROGENATED CASTOR OIL  
 Case Number: 123-26-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: IR42  
 Chemical Name: IRON OXIDE RED  
 Case Number: 1332-37-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: IS68  
 Chemical Name: ISBOUTYL ALCOHOL  
 Case Number: 78-8-31  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: IS72  
 Chemical Name: ISODECYL DIPHENYL PHOSPHATE  
 Case Number: 29761-21-5

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: IS00  
 Chemical Name: ISODECYL DIPHENYL PHOSPHATE  
 Case Number: 29761-21-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: IS66  
 Chemical Name: ISOPROPANOL  
 Case Number: 567-63-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: LA59  
 Chemical Name: LACQUER WASH 201X VM & P NAPHTHA  
 Case Number: 64742-89-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: MA93  
 Chemical Name: MAGNESIUM SILICATE  
 Case Number: 14807-96-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Item Number: MA95  
 Chemical Name: MAGNESIUM SILICATE  
 Case Number: 14807-91-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: MA33  
 Chemical Name: MANGANESE 6% PAINT DRIER MANGANESE NEODECANOATE 50%  
 Case Number: 27253-32-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: MA18  
 Chemical Name: MANGANESE 9% IN MINERAL SPIRIT  
 Case Number: 27253-32-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: ME08  
 Chemical Name: METHYL ACETATE  
 Case Number: 7902909  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: ME15  
 Chemical Name: METHYL AMYL KETONE (MAK)  
 Case Number: 110-43-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC  
  
 Item Number: ME28  
 Chemical Name: METHYL CARBITOL DM, DM GLYCOL ETHER  
 Case Number: 111-777-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ME12  
 Chemical Name: METHYL ETHYL KETONE  
 Case Number: 78-93-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: ME62  
 Chemical Name: METHYL ISOBUTYL KETONE  
 Case Number: 108-10-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ME27  
 Chemical Name: METHYLENE CHLORIDE  
 Case Number: 75-09-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: MI10  
 Chemical Name: MINERAL SPIRITS  
 Case Number: 64742-88-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: MU57  
 Chemical Name: MULTRON R221-75 PMA POLYESTER POLYOL  
 Case Number: 108-65-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: N 61  
 Chemical Name: N PORPYL ALCOHOL  
 Case Number: 72-23-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: N-65  
 Chemical Name: N-BUTYL ACETATE  
 Case Number: 123-86-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: N-69  
 Chemical Name: N-BUTYL ALCOHOL  
 Case Number: 71-36-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: N-19  
 Chemical Name: N-METYL PYROLIDONE  
 Case Number: 872-50-4

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OR83  
 Chemical Name: ORGANIC ACID-GUM ROSIN  
 Case Number: 8050-09-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: OR86  
 Chemical Name: ORGANOPHILIC CLAY  
 Case Number: 121888-68-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PA19  
 Chemical Name: PAINT LIQUID UN1263  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PA06  
 Chemical Name: PAINT: WITH BUTYL ACETATE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Item Number: PE98  
 Chemical Name: PETROLEUM HYDROCARBON DEFOAMER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PH44  
 Chemical Name: PHENOL 4, 1,1,DIMETHYLETHYL CHLOROMETHYL OXIRANE  
 Case Number: 67924-34-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PH23  
 Chemical Name: PHENOL 4.4.1-METHY;ETHY;IDENE BIS BISPHENOL A DIGLYCODYL ETHER  
 Case Number: 25068  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PO52  
 Chemical Name: POLY ALKYL-METHACRYLATE POLYMER CONTAINING TRIBUTYLTIN METHACRYLATE  
 Case Number: 1983-10-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PO73  
 Chemical Name: POLYAMIDE  
 Case Number: 68410-23-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PO01  
 Chemical Name: POLYAMIDE RESIN  
 Case Number: 68410-23-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PO04  
 Chemical Name: POLYGALLOYLESTER OF GLUCOSE  
 Case Number: 1401-55-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PO99  
 Chemical Name: POLYVINYLIDENE CHLORIDE ACRYLIC COPOLYMER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PO48  
 Chemical Name: POTASSIUM SOLICATE SOLUTION  
 Case Number: 1312-76-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PR11  
 Chemical Name: PRO LINE BLEND #2 CLEANING COMPOUND BUTYL ACETATE 30%  
 Case Number: 1238-65-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PR64  
 Chemical Name: PROPANOL  
 Case Number: 71-23-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PR30  
 Chemical Name: PROPYLENE GLYCOL 1.2-PORPANEDIOL  
 Case Number: 57-55-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PS58  
 Chemical Name: PS1066X XYLENE SUB COMPOUND THINNING LIQUID SHELL SOL M-75 COMPOSITION  
 Case Number: 108-88-83  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PU10  
 Chemical Name: PURE IRON OXIDE BLACK  
 Case Number: 1317-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PU11  
 Chemical Name: PURE IRON OXIDE BROWN  
 Case Number: 1309-37-1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PU12  
 Chemical Name: PURE IRON OXIDE YELLOW  
 Case Number: 51274-00-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PU84  
 Chemical Name: PURE ZINC OXIDE  
 Case Number: 8050-09-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: RA13  
 Chemical Name: RAVEN BLACK 1020 CARBON BLACK  
 Case Number: 1333-86-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: RH16  
 Chemical Name: RHEOLOGY MODIFIER QR 708 POLYURETHANE RESIN  
 Case Number: 57-55-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Item Number: SA07  
 Chemical Name: SATURATED POLYESTER POLYOL, 65%, DESMOPHENE 650-A 65  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: SH45  
 Chemical Name: SHELL 3292FX60 POLYETHYLENE POLYAMIDE ADDUCT XYLENE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: SI88  
 Chemical Name: SILICA FLUX CALCINED SIATOMACEOUS EARTH  
 Case Number: 68855-54-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: SI08  
 Chemical Name: SILICA SAND  
 Case Number: 1408-60-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: SI77  
 Chemical Name: SILICEOUS MUSCOVITE MICA  
 Case Number: 1318-94-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

1st Hazard Category:	CHRONIC
2nd Hazard Category:	Not reported
Item Number:	SI92
Chemical Name:	SILICON DIOXIDE (CRYSTELLINE SILICA)
Case Number:	1317-95-9
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	CHRONIC
2nd Hazard Category:	Not reported
Item Number:	SI91
Chemical Name:	SILICON DIOXIDE (CRYSTELLINE SILICA)
Case Number:	14808-60-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	CHRONIC
2nd Hazard Category:	Not reported
Item Number:	SI23
Chemical Name:	SILICON RESIN MP42E
Case Number:	MIXTURE
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	CHRONIC
2nd Hazard Category:	Not reported
Item Number:	SO16
Chemical Name:	SODIUM ANTIMONATE, LEAD
Case Number:	MIXTURE
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	CHRONIC
2nd Hazard Category:	Not reported
Item Number:	SO06
Chemical Name:	SOLICON DIOXIDE
Case Number:	67762-90-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: SO09  
 Chemical Name: SOLVENT NAPTHA (PETROLEUM)  
 Case Number: 64742-95-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: SP78  
 Chemical Name: SPARMITE  
 Case Number: 7727-43-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: TE20  
 Chemical Name: TEXANOL 2,2,4 TRIMETHYL 2,2,4 TRIMETHYL 1,1,1,3-PENTANEDIOL MONO 2-METHYLPR  
 Case Number: 25265-77-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: TH43  
 Chemical Name: THIXATROL GST DEHYDRATED CASTOR OIL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: TI21  
 Chemical Name: TINUVIN 1130

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Case Number: 104810-48-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: TI35  
 Chemical Name: TINUVIN 1130 U.V.ABSORBER  
 Case Number: 104810-47-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: TI36  
 Chemical Name: TINUVIN 292 LIGHT STABILIZER  
 Case Number: 41556-26-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: TI81  
 Chemical Name: TITANIUM DIOXIDE  
 Case Number: 13463-67-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: TO63  
 Chemical Name: TOLUENE  
 Case Number: 108-88-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Item Number: TR31  
 Chemical Name: TRPYSIN 192 2 (HYDROXYMETHYL) AMINO 2-METHYL PROPANOL  
 Case Number: 52299-20-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: UM96  
 Chemical Name: UMBER IRON OXIDE  
 Case Number: 12713-03-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: V 70  
 Chemical Name: V M & P NAPHTHA  
 Case Number: 64743-89-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: VI94  
 Chemical Name: VINYL CHLORDIE VINYL ACETATE COPOLYMER  
 Case Number: 25086-48-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: XY60  
 Chemical Name: XYLENE  
 Case Number: 1330-20-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: YE85  
 Chemical Name: YELLOW TITANIUM DIOXIDE  
 Case Number: 1317-80-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: ZI09  
 Chemical Name: ZINC PHOSPHO MOLYBDATE  
 Case Number: 13767-32-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: ZI26  
 Chemical Name: ZIRCONIUM 2-ETHYLHEXANOATE 44%  
 Case Number: 22464-99-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: 5

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T005  
 Tank ID Number: 6  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 08/19/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 8375  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

Inspection Date: 08/19/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1006  
 Occurrences: Not reported  
 Item Number: 8376  
 Violation Desc: HMBP: INVENTORY INADEQUATE

Inspection Date: 10/10/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 8780  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/10/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 8781  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0139  
 Occurrences: Not reported  
 Item Number: 0318  
 Violation Desc: NO BIENNIAL REPORT TO DTSC

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0144  
 Occurrences: Not reported  
 Item Number: 0319  
 Violation Desc: SB14 COMPLIANCE DOCS UNAVAILABLE

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0320  
 Violation Desc: WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

**HMMD WASTE STREAMS:**

Inspection Date: 12/10/04  
 Waste Item #: 133  
 Waste Code: 133  
 Waste Name: AQUEOUS SOL'N W/ 10%  
 Qnty at Inspection: 1500  
 Quantity String: 1500  
 Annual Qty: 3970  
 Annual Qty String: 3970  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: BOX  
 Haz Waste Hauler: 0699 VAN WATERS & ROGERS  
 Waste Desc: PAINT SOLIDS & RAGS  
 Carcinogen: No

Inspection Date: 12/10/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 4000  
 Quantity String: 4000  
 Annual Qty: 25001  
 Annual Qty String: 25001  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0699 VAN WATERS & ROGERS  
 Waste Desc: WASTE PAINT/THINNER  
 Carcinogen: No

**EMI:**

Year: 1990  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 12  
 Reactive Organic Gases Tons/Yr: 12  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 4  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 4

Year: 1995  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 1721

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 17  
 Reactive Organic Gases Tons/Yr: 16  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 6  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 5

Year: 1996  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 17  
 Reactive Organic Gases Tons/Yr: 16  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 6  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 5

Year: 1997  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 17  
 Reactive Organic Gases Tons/Yr: 16  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 6  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 5

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 2851  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 8  
 Reactive Organic Gases Tons/Yr: 8  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	4387
Air District Name:	SD
SIC Code:	2851
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	4387
Air District Name:	SD
SIC Code:	2851
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	4387
Air District Name:	SD
SIC Code:	2851
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 2851  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 8  
 Reactive Organic Gases Tons/Yr: 8  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 2851  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 8  
 Reactive Organic Gases Tons/Yr: 8  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 4387  
 Air District Name: SD  
 SIC Code: 2851  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 7.731  
 Reactive Organic Gases Tons/Yr: 7.731  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0.236078  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0.236078

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 536  
 Number: Not reported  
 Board Of Equalization: 44-021568  
 Ref Date: Not reported  
 Act Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000536-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 5

Status: Not reported  
 Comp Number: 536  
 Number: Not reported  
 Board Of Equalization: 44-021568  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000536-000002  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 536  
 Number: Not reported  
 Board Of Equalization: 44-021568  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000536-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 536  
 Number: Not reported  
 Board Of Equalization: 44-021568  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000536-000004  
 Actv Date: Not reported  
 Capacity: 2000



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SHERWIN-WILLIAMS CO., PRO-LINE PAINT (Continued)**

**1000139073**

Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 536  
 Number: Not reported  
 Board Of Equalization: 44-021568  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000536-000005  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 536  
 Number: 9  
 Board Of Equalization: 44-021568  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H00536-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 6/3/1997  
 Begandt: 9/3/1986

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

---

<b>59</b>	<b>SHERWIN-WILLIAMS COMPANY THE</b> <b>2646 MAIN ST</b> <b>SAN DIEGO, CA 92113</b>	<b>AIRS</b>	<b>S108433247</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

EMI:

Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	4387
Air District Name:	SD
SIC Code:	2851
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8.66
Reactive Organic Gases Tons/Yr:	8.6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.04444444444444444444
Part. Matter 10 Micrometers & Smlr Tons/Yr:	.04

<b>59</b>	<b>PROLINE PAINT PROFESSIONAL FINISHES</b> <b>2646 MAIN ST</b> <b>SAN DIEGO, CA 92113</b>	<b>FTTS</b>	<b>1009521257</b>
		<b>HIST FTTS</b>	<b>N/A</b>

FTTS INSP:

Inspection Number:	Not reported
Region:	09
Inspection Date:	Not reported
Inspector:	OALCANTARLEAL
Violation occurred:	No
Investigation Type:	Specific Product Review
Investigation Reason:	For Cause, Government
Legislation Code:	FIFRA
Facility Function:	Producer

HIST FTTS INSP:

Inspection Number:	19940503F2718 1
Region:	09
Inspection Date:	Not reported
Inspector:	OALCANTARLEAL
Violation occurred:	No
Investigation Type:	Specific Product Review
Investigation Reason:	For Cause, Government
Legislation Code:	FIFRA
Facility Function:	Producer

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 PROLINE PAINT STORE  
 2646 MAIN ST.  
 SAN DIEGO, CA 92113**

**CERC-NFRAP 1003879833  
 CAD983658444**

CERC-NFRAP:  
 Site ID: 0904772  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):  
 Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/08/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 06/28/1993  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 06/28/1993  
 Priority Level: NFRAP (No Further Remedial Action Planned)

**59 SHERWIN WILLIAMS (PRO-LINE PAINT STORE)  
 2646 MAIN STREET  
 SAN DIEGO, CA 92113**

**FTTS 1009401805  
 HIST FTTS N/A**

FTTS INSP:  
 Inspection Number: Not reported  
 Region: 09  
 Inspection Date: Not reported  
 Inspector: AMEHRABAN  
 Violation occurred: No  
 Investigation Type: General Product Review  
 Investigation Reason: For Cause, Follow-Up  
 Legislation Code: FIFRA  
 Facility Function: Producer

HIST FTTS INSP:  
 Inspection Number: 200512061422 2  
 Region: 09  
 Inspection Date: Not reported  
 Inspector: AMEHRABAN  
 Violation occurred: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN WILLIAMS (PRO-LINE PAINT STORE) (Continued)**

**1009401805**

Investigation Type: General Product Review  
 Investigation Reason: For Cause, Follow-Up  
 Legislation Code: FIFRA  
 Facility Function: Producer

59

**2646 MAIN ST.  
 SAN DIEGO, CA 92113**

**CHMIRS S100275094  
 N/A**

CHMIRS:

OES Incident Number: 8907779  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 05-SEP-89  
**Date Completed: 05-SEP-89**  
 Property Use: 962  
 Agency Id Number: 37140  
 Agency Incident Number: 12271  
 Time Notified: 1208  
 Time Completed: 1307  
 Surrounding Area: 500  
 Estimated Temperature: 75  
 Property Management: C  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agncy Personel # Of Decontaminated: 0  
 Responding Agency Personel # Of Injuries: 0  
 Responding Agency Personel # Of Fatalities:0  
 Others Number Of Decontaminated: 0  
 Others Number Of Injuries: 0  
 Others Number Of Fatalities: 0  
 Vehicle Make/year: 73 MERCURY  
 Vehicle License Number: 2PEL161  
 Vehicle State: CA  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: ROBERTO GALLERO  
 Reporting Officer Name/ID: TIMOTHY E. THORPE  
 Report Date: 05-SEP-89  
 Comments: Not reported  
 Facility Telephone: 619 236-7773  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S100275094

Year: 88-92  
 Agency: Not reported  
 Incident Date: Not reported  
 Admin Agency: Not reported  
 Amount: Not reported  
 Contained: Not reported  
 Site Type: Not reported  
 E Date: 18-MAY-90  
 Substance: Not reported  
 Quantity Released: Not reported  
 BBLS: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: Not reported  
 Evacuations: Not reported  
 Number of Injuries: Not reported  
 Number of Fatalities: Not reported  
 Description: Not reported

59

**PRO-LINE PAINT COMPANY  
 2646 MAIN STREET  
 SAN DIEGO, CA 92113**

**SSTS 1005435293  
 N/A**

SSTS:

Product: PRO-LINE 1077-33 COLORS  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1990  
 Permit: Registered  
 Product Number: 0402380009  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE 1080 COLORS  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1990  
 Permit: Registered  
 Product Number: 0402380003  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PRO-LINE PAINT COMPANY (Continued)**

**1005435293**

Region: Not reported

Product: PRO-LINE 1088C BLACK AND DOD-P-15931C F-129  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1990  
 Permit: Registered  
 Product Number: 04023800008  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE 1088C COLORS DOD-P-15931C F-121  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1990  
 Permit: Registered  
 Product Number: 04023800007  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE 888 COLORS WATER BASE ANTI-FOULING  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1990  
 Permit: Registered  
 Product Number: 04023800011  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: WATER BASE ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1991  
 Permit: Registered  
 Product Number: 04023800011  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: VINYL ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 040238CA 001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PRO-LINE PAINT COMPANY (Continued)**

**1005435293**

Report Year: 1991  
 Permit: Registered  
 Product Number: 04023800007  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: SPEED POLISHING POLYMER  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1991  
 Permit: Registered  
 Product Number: 04023800009  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: HARD VINYL ANTIFOULING  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1991  
 Permit: Registered  
 Product Number: 04023800003  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1991  
 Permit: Registered  
 Product Number: 04023800008  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1992  
 Permit: Registered  
 Product Number: 04023800008  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PRO-LINE PAINT COMPANY (Continued)**

**1005435293**

Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: HARD VINYL ANTIFOULING  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1992  
 Permit: Registered  
 Product Number: 04023800003  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: SPEED POLISHING POLYMER  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1992  
 Permit: Registered  
 Product Number: 04023800009  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: VINYL ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1992  
 Permit: Registered  
 Product Number: 04023800007  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: WATER BASE ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 040238CA 001  
 Report Year: 1992  
 Permit: Registered  
 Product Number: 04023800011  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRO-LINE PAINT COMPANY (Continued)**

**1005435293**

Product: VINYL ANTIFOULING PAINT FORMULA 121  
 Status: Inactive  
 Registration Number: 040238CA 001  
 Report Year: 1996  
 Permit: Registered  
 Product Number: 04023800007  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PROLINE WATERBASE ANTIFOULING PAINT 888  
 Status: Inactive  
 Registration Number: 040238CA 001  
 Report Year: 1996  
 Permit: Registered  
 Product Number: 04023800011  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States  
 Region: Not reported

Product: PRO-LINE YACHT FINISHES PRO-LINE CHALLENGER 1043 ANTI. PAINT  
 Status: Inactive  
 Registration Number: 040238CA 001  
 Report Year: 1996  
 Permit: Unregistered  
 Product Number: 040238CF00003  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Exported out of the United States  
 Region: Not reported

Product: PRO-LINE YACHT FINISHES CARIBE 444 ANTIFOULING BOTTOM PAINT  
 Status: Inactive  
 Registration Number: 040238CA 001  
 Report Year: 1996  
 Permit: Unregistered  
 Product Number: 040238CF00001  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Exported out of the United States  
 Region: Not reported

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT  
 Status: Inactive  
 Registration Number: 040238CA 001  
 Report Year: 1996  
 Permit: Registered

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRO-LINE PAINT COMPANY (Continued)**

**1005435293**

Product Number: 04023800003  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING PAINT FORMULA 129 MILITARY SPECIFIC.  
 Status: Inactive  
 Registration Number: 040238CA 001  
 Report Year: 1996  
 Permit: Registered  
 Product Number: 04023800008  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States  
 Region: Not reported

Product: PRO-LINE YACHT FINISHES TINTOX Y-1045 ANTIFOULING BOTTOM PNT  
 Status: Inactive  
 Registration Number: 040238CA 001  
 Report Year: 1996  
 Permit: Unregistered  
 Product Number: 040238CF00002  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Exported out of the United States  
 Region: Not reported

59

**SHERWIN-WILLIAMS CO  
 2646 MAIN ST  
 SAN DIEGO, CA 92113**

**SSTS 1005436744  
 N/A**

SSTS:

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: Not reported  
 Permit: Registered  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: Not reported  
 Permit: Registered  
 Product Number: 00057700551

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: PROLINE CHALLENGER 1043 ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: Not reported  
 Permit: Unregistered  
 Product Number: 000577CF00001  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Exported out of the United States  
 Region: Not reported

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: Not reported  
 Permit: Registered  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: 1997  
 Permit: Registered  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING PAINT FORMULA 129 MIL-P-15931C  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: 1997  
 Permit: Registered  
 Product Number: 00057700551  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Animal Repellent  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Region: Not reported

Product: PRO-LINE WATERBASE ANTIFOULING PAINT 888  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: 1997  
 Permit: Registered  
 Product Number: 00057700552  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States  
 Region: Not reported

Product: RED VINYL ANITFOULING PAINT FORMULA 121 MIL-P15931E  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: 1997  
 Permit: Registered  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE YACHT FINISHES PRO-LINE CHALLENGER 1045 ANTIFOULING  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: 1997  
 Permit: Unregistered  
 Product Number: 000577CF00002  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Exported out of the United States  
 Region: Not reported

Product: PRO-LINE YACHT FINISHES PRO-LINE CHALLENGER 1043 ANTIFOULING  
 Status: Active  
 Registration Number: 000577CA 004  
 Report Year: 1997  
 Permit: Unregistered  
 Product Number: 000577CF00001  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Insecticide-Fungicide  
 Product Use: Not reported  
 UOM: G  
 Market: Exported out of the United States  
 Region: Not reported

Product: PRO-LINE YACHT FINISHES CHALLENGER 1043 ANTIFOULING PAINT  
 Status: Not reported  
 Registration Number: 000577CA 004

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Report Year: 1999  
 Permit: Unregistered  
 Product Number: 000577CF00001  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Exported out of the United States  
 Region: Not reported

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 1999  
 Permit: Registered  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING PAINT 1088/ MIL-P-15931C FORMULA 129  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 1999  
 Permit: Registered  
 Product Number: 00057700551  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 1999  
 Permit: Registered  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING PAINT 1088/ MIL-P-15931C FORMULA 129  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Registered  
 Product Number: 00057700551  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT COPPER  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Registered  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: SEAGUARD VINYL ANTIFOULANT  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Registered  
 Product Number: 00057700558  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: SEAGUARD RED VINYL ANTIFOULING FORMULA 121A MIL P15931F  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Registered  
 Product Number: 00057700561  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: SEAGUARD HARD VINYL ANTIFOULANT  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Registered  
 Product Number: 00057700560  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product: SEAGUARD BLACK VINYL ANTIFOULING FORMULA 129A MIL P15931F  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Registered  
 Product Number: 00057700562  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Registered  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PROLINE 1083 ABLATIVE ANTIFOULING PAINT  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Unregistered  
 Product Number: 000577CF00001  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Exported out of the United States  
 Region: Not reported

Product: PROLINE 1043 ABTIFOULING PAINT  
 Status: Not reported  
 Registration Number: 000577CA 004  
 Report Year: 2000  
 Permit: Unregistered  
 Product Number: 000277CF00001  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Exported out of the United States  
 Region: Not reported

Product: BLACK VINYL ANTIFOULING PAINT 1088C, PROLINE  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product Number: 00057700551  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: SEAGUARD VINYL ANTI-FOULING BLACK  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 00057700559  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD RED VINYL ANTIFOULING FORMULA 121A MIL P15931F  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 00057700561  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD HARD VINYL ANTIFOULANT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 00057700560  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD VINYL ANTIFOULANT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 00057700558  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD ABLATIVE ANTI-FOULING COATING  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 01025000054  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088C  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT COPPER  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: SEAGUARD BLACK VINYL ANTIFOULING FORMULA 129A MIL P15931F  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2001  
 Permit: Registered  
 Product Number: 00057700562  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: BLACK VINYL ANTIFOULING PAINT FORUMLA 129  
 Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 00057700551  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT COPPER  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088C  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: SEAGUARD ABLATIVE ANTI-FOULING COATING (SUPP -577)  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 01025000054  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: SEAGUARD BLACK VINYL ANTIFOULING FORMULA 129A MIL  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 00057700562  
 Product Type: End-use blend, formulation, or concentrate

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD HARD VINYL ANTIFOULANT PAINT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 00057700560  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD RED VINYL ANTIFOULING FORMULA 121A MIL  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 00057700561  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD VINYL ANTIFOULANT PAINT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2002  
 Permit: Registered  
 Product Number: 00057700558  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD BLACK VINYL ANTI-FOULANT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700559  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product: SEAGUARD ABLATIVE ANTI-FOULING COATING (SUPP -577)  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 01025000054  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088C  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT COPPER  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: 09

Product: BLACK VINYL ANTIFOULING PAINT 1088  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700551  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SW SEAGUARD COPPER BOTTOM ANTI-FOULING PAINT #45  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product Number: 00057700569  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD HARD VINYL ANTIFOULANT PAINT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700560  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD RED VINYL ANTIFOULING FORMULA 121A MIL  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700561  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD VINYL ANTIFOULANT PAINT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700558  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SW SEAGUARD COPPER BOTTOM ANIT-FOULING PAINT # 60  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700568  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD BLACK VINYL ANTIFOULING FORMULA 129A MIL  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2003  
 Permit: Registered  
 Product Number: 00057700562  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: 09

Product: SEAGUARD RED VINYL ANTIFOULING FORMULA 121A MIL SPEC  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2004  
 Permit: Not reported  
 Product Number: 100057700561  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: SEAGUARD BLACK VINYL ANTIFOULING FORMULA 129A MIL  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2004  
 Permit: Not reported  
 Product Number: 100057700562  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088C & ALT BN  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2004  
 Permit: Not reported  
 Product Number: 100057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE BLACK VINYL ANTIFOULING PAINT 1088 & ALT BN  
 Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Registration Number: 000577CA004  
 Report Year: 2004  
 Permit: Not reported  
 Product Number: 100057700551  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: PRO-LINE 1080-H HARD VINYL ANTIFOULING PAINT COPPER  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2004  
 Permit: Not reported  
 Product Number: 100057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: SEAGUARD VINYL ANTIFOULANT PAINT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2004  
 Permit: Not reported  
 Product Number: 100057700558  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: PRO-LINE 1080 HARD VINYL ANTIFOULING PAINT COPPER  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700549  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE BLACK VINYL ANTIFOULING PAINT 1088 & ALT BN  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700551  
 Product Type: End-use blend, formulation, or concentrate

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: SEAGUARD VINYL ANTIFOULING BLACK  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700559  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: SEAGUARD HARD VINYL ANTI-FOULANT  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700560  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: SEAGUARD COPPER BOTTOM A.F. PAINT #60  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700568  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: SEAGUARD COPPER BOTTOM A.F. PAINT #45  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700569  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product: SEAGUARD BLACK VINYL A.F. FORMULA 129A MIL SPEC  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700562  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States  
 Region: Not reported

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088 & ALT BN  
 Status: Not reported  
 Registration Number: 000577CA004  
 Report Year: 2005  
 Permit: Not reported  
 Product Number: 00057700550  
 Product Type: End-use blend, formulation, or concentrate  
 Product Class: Antifouling Paint  
 Product Use: All other products  
 UOM: Not reported  
 Market: Marketed in the United States and exported out of the United States  
 Region: Not reported

Product: PRO-LINE 1080 HARD VINYL ANTIFOULING PAINT  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported  
 Product Number: 000577-00549  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported  
 Market: Not reported  
 Region: Not reported

Product: SEAGUARD COPPER BOTTOM A.F. PAINT #60  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported  
 Product Number: 000577-00568  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported  
 Market: Not reported  
 Region: Not reported

Product: SEAGUARD COPPER BOTTOM A.F. PAINT #45  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Product Number: 000577-00569  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported  
 Market: Not reported  
 Region: Not reported

Product: SEAGUARD BLACK VINYL A.F. FORMULA 129A MIL SP  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported  
 Product Number: 000577-00562  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported  
 Market: Not reported  
 Region: Not reported

Product: PROLINE VINYL COPPER ANTI-FOULING PAINT, 1088  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported  
 Product Number: 000577-00550  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported  
 Market: Not reported  
 Region: Not reported

Product: PROLINE 1083 ABLATIVE A-F PAINT FOR EXPORT  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported  
 Product Number: 000577-CF-00001  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported  
 Market: Not reported  
 Region: Not reported

Product: PRO-LINE BLACK VINYL ANTIFOULING PAINT 1088 &  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported  
 Product Number: 000577-00551  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS CO (Continued)**

**1005436744**

Market: Not reported  
 Region: Not reported  
  
 Product: SEAGUARD HARD VINYL ANTI-FOULANT  
 Status: Not reported  
 Registration Number: 000577-CA-004  
 Report Year: 2006  
 Permit: Not reported  
 Product Number: 000577-00560  
 Product Type: Not reported  
 Product Class: Not reported  
 Product Use: Not reported  
 UOM: Not reported  
 Market: Not reported  
 Region: Not reported

59

**SHERWIN-WILLIAMS - STORE# 8227  
 2640 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106071240  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 201189  
 Inactive Indicator: Active  
 Business Code: 6HK68  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ATTN: PHIL BARBUSCIA  
 Mailing Address: 2640 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000264479  
 Gas Station: Not reported  
 Inspection Date: 07/28/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DENNIS MCCARTHY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MONISE ANTOINETTE J TR  
 Property Address: 1515 PLUM ST  
 Property City,St,Zip: 92106  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/28/06  
 Facility Phone: 619-231-2313

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC50

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS - STORE# 8227 (Continued)**

**S106071240**

Chemical Name: ACETONE ACETONE  
 Case Number: 67-64-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: ME49  
 Chemical Name: MEK SOLVENTS METHYL ETHYL KETONE  
 Case Number: 78-93-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: MI51  
 Chemical Name: MINERAL SPIRITS: THINNER MINERAL SPIRITS/THINNER  
 Case Number: 647-42-88-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: MI45  
 Chemical Name: MIXTURE AEROSOL PAINT PRODUCTS  
 Case Number: 108-88-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: MI48  
 Chemical Name: MIXTURE EPOXY POLYURITHANES  
 Case Number: 1330-20-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHERWIN-WILLIAMS - STORE# 8227 (Continued)**

**S106071240**

2nd Hazard Category:	CHRONIC
Item Number:	MI47
Chemical Name:	MIXTURE INDUSTRIAL ENAMELS
Case Number:	64742-47-8
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	CHRONIC
Item Number:	MI54
Chemical Name:	MIXTURE XYLENES
Case Number:	1330-20-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	CHRONIC
Item Number:	MI43
Chemical Name:	MIXTURE: LATEX (WATER-BASED) PRODUCTS
Case Number:	107-21-1
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	CHRONIC
Item Number:	TO52
Chemical Name:	TOLUENE TOLUENE
Case Number:	108-88-3
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	CHRONIC
Item Number:	VM53
Chemical Name:	VM & P NAPTHA NAPTHA
Case Number:	64742-89-8
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHERWIN-WILLIAMS - STORE# 8227 (Continued)**

**S106071240**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 07/28/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: PAINT WASTE  
 Carcinogen: No

59

**EPSILON AIR CONDITIONING & REF  
 2640 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S100940899  
 San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAL000079287  
 Contact: TURNER MICHAEL S  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2640 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: .2085  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EPSILON AIR CONDITIONING & REF (Continued)**

**S100940899**

Gepaid: CAL000079287  
 Contact: TURNER MICHAEL S  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2640 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: FLD980711071  
 TSD County: 99  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: .4000  
 Facility County: San Diego

Gepaid: CAL000079287  
 Contact: TURNER MICHAEL S  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2640 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: FLD980711071  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: Recycler  
 Tons: .2000  
 Facility County: San Diego

**San Diego Co. HMMD:**

Facility ID: 133245  
 Inactive Indicator: Active  
 Business Code: 6HK33  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2640 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000122880  
 Gas Station: Not reported  
 Inspection Date: 12/03/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: SARAH SUAREZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MONISE ANTOINETTE J TR

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EPSILON AIR CONDITIONING & REF (Continued)**

**S100940899**

Property Address: 1515 PLUM ST  
 Property City,St,Zip: 92106  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-0074

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/01/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7614  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/16/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 7661  
 Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EPSILON AIR CONDITIONING & REF (Continued)**

**S100940899**

Waste Desc: Not reported  
 Carcinogen: No

**59 EPSILON A/C & R A UNIT OF DIGITAL  
 2640 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103962929  
 N/A**

HAZNET:

Gepaid: CAL000122880  
 Contact: JERROLD L MILLER  
 Telephone: 7573971039  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .4170  
 Facility County: San Diego

**59 SHERWIN WILLIAMS #8227  
 2640 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S108755016  
 N/A**

HAZNET:

Gepaid: CAL000301220  
 Contact: SHAY ROSEMAN  
 Telephone: 2165661710  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 101 PROSPECT AVE STE 333R  
 Mailing City,St,Zip: CLEVELAND, OH 44115  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: H14  
 Tons: 0.3  
 Facility County: San Diego

**59 JONES STUDIO  
 2602 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106466782  
 N/A**

San Diego Co. HMMD:

Facility ID: 202937  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JONES STUDIO (Continued)**

**S106466782**

2nd Name: JONES STUDIO  
 Mailing Address: 5808 LA JOLLA HERMOS  
 Mailing City,St,Zip: LA JOLLA, CA 92037  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/06/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MALCOLM JONES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: JONES MALCOLM W&PAULA M  
 Property Address: 5808 LA JOLLA HERMOS  
 Property City,St,Zip: 92037  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/06/06  
 Facility Phone: 619-227-6577

**HMMD DISCLOSURE INVENTORY:**

Item Number: 4-92  
 Chemical Name: 4-METH OXYPHENOL (10 PPM) METHYL METHACRYLATE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JONES STUDIO (Continued)**

**S106466782**

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**WESTERN BAY SHEET METAL/MARINE  
 1221 S 26TH ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S100727635  
 N/A**

San Diego Co. HMMD:

Facility ID: 108478  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1221 S 26TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000230474  
 Gas Station: Not reported  
 Inspection Date: 12/01/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ANDY LOZANO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GREEN FAMILY TRUST (SURVIVOR'S  
 Property Address: 955 CHANTILLY RD  
 Property City,St,Zip: 90077  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/01/05  
 Facility Phone: 619-233-1753

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTERN BAY SHEET METAL/MARINE (Continued)**

**S100727635**

**HMMD DISCLOSURE INVENTORY:**

Item Number: AR13  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CHRONIC

Item Number: CA14  
 Chemical Name: CARBON DIOXIDE  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CHRONIC

Item Number: HE15  
 Chemical Name: HELIUM  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/22/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 0903  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 01/22/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0904

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTERN BAY SHEET METAL/MARINE (Continued)**

**S100727635**

Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 10/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9334  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 10/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 9335  
 Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 5470  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5471  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5472  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/01/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6420  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/01/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 6421  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 12/01/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 10

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTERN BAY SHEET METAL/MARINE (Continued)**

**S100727635**

Quantity String: 10  
 Annual Qty: 10  
 Annual Qty String: 10  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: CAN  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: FROM COMPRESSOR  
 Carcinogen: No

59

**SAN DIEGO HOUSING COMMISSION  
 2650 BOSTON AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S106063110  
 N/A**

San Diego Co. HMMD:

Facility ID: 129927  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1625 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CHASE CHRISTOPHER C  
 Property Address: 19491 DEERHORN VALLE  
 Property City,St,Zip: 91935  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO HOUSING COMMISSION (Continued)**

**S106063110**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**BELAIR CORP  
 2645 BOSTON ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104754150  
 N/A**

San Diego Co. HMMD:

Facility ID: 134023  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City, St, Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BELAIR CORP (Continued)**

**S104754150**

Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: ERNIE SOETERIK  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: 4003 PARK CENTRE PARTNERS L L  
 Property Address: 8080 LA MESA BLVD #1  
 Property City,St,Zip: 91941  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BELAIR CORP (Continued)**

**S104754150**

Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**2635 BOSTON AV  
 SAN DIEGO, CA 92113**

**CHMIRS S100215850  
 N/A**

CHMIRS:

OES Incident Number: 8800970  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 28-MAR-88  
**Date Completed: 28-MAR-88**  
 Property Use: 400  
 Agency Id Number: 37140  
 Agency Incident Number: 49409  
 Time Notified: 1624  
 Time Completed: 1728  
 Surrounding Area: 600  
 Estimated Temperature: 80  
 Property Management: P  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: CAPT. JOHN LIBATORE  
 Report Date: 07-DEC-41  
 Comments: Not reported  
 Facility Telephone: 619 236-7773  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100215850

Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	16-MAR-89
Substance:	Not reported
Quantity Released:	Not reported
BBLs:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

59

**SAN DIEGO HOUSING COMMISSION**  
**2627 BOSTON AV**  
**SAN DIEGO, CA 92113**

San Diego Co. HMMD

S106063109  
 N/A

San Diego Co. HMMD:

Facility ID:	129926
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1625 NEWTON AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	Not reported
Reinspection Date:	Not reported
Inspector Name:	Not reported
Violation Notice Issued:	Not reported
Facility Contact:	Not reported
Delinquent Flag:	Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO HOUSING COMMISSION (Continued)**

**S106063109**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CHASE CHRISTOPHER C  
 Property Address: 19491 DEERHORN VALLE  
 Property City,St,Zip: 91935  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 ANDYS A&R  
 2627 BOSTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S105539588  
 N/A**

San Diego Co. HMMD:

Facility ID:	115104
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2863 COMMERCIAL ST
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	03/16/87
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	ANDY STANNARD
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	CHASE CHRISTOPHER C
Property Address:	19491 DEERHORN VALLE
Property City,St,Zip:	91935
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-239-9624

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ANDYS A&R (Continued)**

**S105539588**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**BAY DECKING COMPANY INCORPORATED**  
**2685 BOSTON ST.**  
**SAN DIEGO, CA 92113**

**FINDS 1000110771**  
**RCRA-NonGen CAD982401093**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-NonGen:**

Date form received by agency: 04/12/1996  
 Facility name: BAY DECKING CO INC  
 Facility address: 2685 BOSTON AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982401093  
 Mailing address: COMMERCIAL BLVD UNIT 16  
 NOVATO, CA 94949  
 Contact: MATTHEW TRUJILLO  
 Contact address: 21 COMMERCIAL BLVD UNIT 16  
 NOVATO, CA 94949  
 Contact country: US  
 Contact telephone: (415) 883-3391  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAY DECKING COMPANY INCORPORATED (Continued)**

**1000110771**

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MAURICE CLARK  
 Owner/operator address: 6864 PASEO LAREDO  
 LA JOLLA, CA 92037  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 525-2916  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 02/29/1996  
 Facility name: BAY DECKING CO INC  
 Site name: BAY DECKING COMPANY, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 03/30/1994  
 Facility name: BAY DECKING CO INC  
 Site name: BAY DECKING COMPANY, INC.  
 Classification: Large Quantity Generator

Violation Status: No violations found

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**59 BAY DECKING CO., INC.  
 2685 BOSTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100944163  
 N/A**

HAZNET:

Gepaid: CAD982401093  
 Contact: MIGUEL NARRO  
 Telephone: 4158833391  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 21 COMMERCIAL BLVD STE 16  
 Mailing City,St,Zip: NOVATO, CA 949496109  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: 99  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: .4500  
 Facility County: San Diego

Gepaid: CAD982401093  
 Contact: MIGUEL NARRO  
 Telephone: 4158833391  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 21 COMMERCIAL BLVD STE 16  
 Mailing City,St,Zip: NOVATO, CA 949496109  
 Gen County: San Diego  
 TSD EPA ID: CAD000088352  
 TSD County: 0  
 Waste Category: Not reported  
 Disposal Method: Transfer Station  
 Tons: .4169  
 Facility County: San Diego

Gepaid: CAD982401093  
 Contact: MIGUEL NARRO  
 Telephone: 4158833391  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 21 COMMERCIAL BLVD STE 16  
 Mailing City,St,Zip: NOVATO, CA 949496109  
 Gen County: San Diego  
 TSD EPA ID: CAD000088352  
 TSD County: 0  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: 4.7500  
 Facility County: San Diego

Gepaid: CAD982401093  
 Contact: MIGUEL NARRO  
 Telephone: 4158833391  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 21 COMMERCIAL BLVD STE 16  
 Mailing City,St,Zip: NOVATO, CA 949496109  
 Gen County: San Diego  
 TSD EPA ID: CAD000088352

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAY DECKING CO., INC. (Continued)**

**S100944163**

TSD County: 0  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: .1876  
 Facility County: San Diego

Gepaid: CAD982401093  
 Contact: MIGUEL NARRO  
 Telephone: 4158833391  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 21 COMMERCIAL BLVD STE 16  
 Mailing City,St,Zip: NOVATO, CA 949496109  
 Gen County: San Diego  
 TSD EPA ID: CAD000088352  
 TSD County: 0  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: 9.6500  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 18 additional CA\_HAZNET: record(s) in the EDR Site Report.

59

**BAY DECKING COMPANY INC  
 2685 BOSTON ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104750412  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 123513  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 21 COMMERCIAL BL #  
 Mailing City,St,Zip: NOVATO, CA 94949  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD982401093  
 Gas Station: Not reported  
 Inspection Date: 06/05/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MATT TRUJILLO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: EVERINGHAM ARLENE A  
 Property Address: P O BOX 1315  
 Property City,St,Zip: 92007  
 Tank Owner: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAY DECKING COMPANY INC (Continued)**

**S104750412**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-235-0679

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

59

**WESTECH**  
**2675 BOSTON AV**  
**SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104756649**  
**N/A**

San Diego Co. HMMD:

Facility ID:	138174
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2675 BOSTON AV
Mailing City, St, Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	10/09/03
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	MIKE BJELLAND
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	EVERINGHAM ARLENE A
Property Address:	P O BOX 1315
Property City, St, Zip:	92007
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City, St, Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	04/09/05
Facility Phone:	619-702-9353

HMMD DISCLOSURE INVENTORY:

Item Number:	AR93
Chemical Name:	ARGON
Case Number:	7440-37-1
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	PRESSURE RELEASE
2nd Hazard Category:	CHRONIC
Item Number:	AR94
Chemical Name:	ARGON: CO2
Case Number:	mixture
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTECH (Continued)**

**S104756649**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: OX92  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 0893  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 01/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 0894  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 01/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0895  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 5553  
 Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTECH (Continued)**

**S104756649**

Item Number: 5550  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 5551  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5552  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**TARANTINO WHOLESALE FOODS**  
**2707 BOSTON AV**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104754485**  
**N/A**

San Diego Co. HMMD:

Facility ID: 134543  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2707 BOSTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/29/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TARANTINO WHOLESALE FOODS (Continued)**

**S104754485**

Violation Notice Issued: Not reported  
 Facility Contact: PETER TARANTINO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TARANTINO PETER P&ROSE M  
 Property Address: 2707 BOSTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-7585

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TARANTINO WHOLESALE FOODS (Continued)**

**S104754485**

Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**ASTON AUTO CENTRE  
 2727 BOSTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104749254  
 N/A**

San Diego Co. HMMD:

Facility ID: 119895  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2727 BOSTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/07/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: BILL MANNING  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PACIFIC FURLOUGH PROPERTIES LL  
 Property Address: 2727 BOSTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-231-2456

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ASTON AUTO CENTRE (Continued)**

**S104749254**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**IMS RECYCLING SERVICES  
 2740 BOSTON AVE  
 SAN DIEGO, CA 92113**

**CA WDS S106101175  
 N/A**

**CA WDS:**

Facility ID: San Diego 371013268  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: IMS RECYCLING SERVICES INC  
 Agency Address: 2740 BOSTON AVE  
 Agency City,St,Zip: SAN DIEGO 92113  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES (Continued)**

**S106101175**

SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.  
 Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

59

**IMS RECYCLING INC  
 2740 BOSTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103969802  
 N/A**

HAZNET:

Gepaid: CAL000058671  
 Contact: IMS RECYCLING INC  
 Telephone: 6192319219  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703715  
 Gen County: San Diego  
 TSD EPA ID: CAT080025711  
 TSD County: San Bernardino  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .8340  
 Facility County: San Diego

Gepaid: CAL000058671  
 Contact: IMS RECYCLING INC  
 Telephone: 6192319219  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703715  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 3.7530  
 Facility County: San Diego



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

59 I M S RECYCLING SVC IRON DEPT  
 2740 BOSTON AV  
 SAN DIEGO, CA 92113

LUST  
 San Diego Co. HMMMD  
 SAN DIEGO CO. SAM

S104746988  
 N/A

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302440  
 Stop Date: 1998-06-04 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2002-03-28 00:00:00  
 Discover Date: 1998-06-04 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-06-12 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: MIKE HOWARD  
 RP Address: 2740 BOSTON AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10715-001  
 Case Number: 9UT3674

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**I M S RECYCLING SVC IRON DEPT (Continued)**

**S104746988**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 110715  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAD029136058  
 Gas Station: Not reported  
 Inspection Date: 06/01/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE HOWARD  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SCRAP METALS INC  
 Property Address: 1345 S 27TH ST  
 Property City,St,Zip: 92113  
 Tank Owner: INDUSTRIAL METALS & SALVAGE CO  
 Tank Address: 1345 S 27TH ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**I M S RECYCLING SVC IRON DEPT (Continued)**

**S104746988**

2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 4594  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 4595  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HX3007  
 Occurrences: Not reported  
 Item Number: 4596  
 Violation Desc: NO PERMIT FOR UST REPAIR/UPGRADE/REMOVAL

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HX3011  
 Occurrences: Not reported  
 Item Number: 4597  
 Violation Desc: FAIL TO COMPLY WITH OP PERMIT CONDITIO

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HX3012  
 Occurrences: Not reported  
 Item Number: 4598  
 Violation Desc: DIDN'T NOTIFY HMD OF UST CHANGES

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HX3016  
 Occurrences: Not reported  
 Item Number: 4599  
 Violation Desc: DID NOT SUBMIT INTEGRITY TEST RESULTS TO

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**I M S RECYCLING SVC IRON DEPT (Continued)**

**S104746988**

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HV3018  
 Occurrences: Not reported  
 Item Number: 4600  
 Violation Desc: IMPROPER INVENTORY RECONCILIATION

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HX3006  
 Occurrences: Not reported  
 Item Number: 4601  
 Violation Desc: DID NOT MEET REQS FOR TEMP CLOSURE

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 4602  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

Inspection Date: 08/05/96  
 Waste Code: Not reported  
 Type of Violation: 6HX3033  
 Occurrences: Not reported  
 Item Number: 4603  
 Violation Desc: DID NOT MEET UST CLOSURE REQS

Inspection Date: 10/22/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 9368  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 10/22/97  
 Waste Code: Not reported  
 Type of Violation: 6HV3018  
 Occurrences: Not reported  
 Item Number: 9369  
 Violation Desc: IMPROPER INVENTORY RECONCILIATION

Inspection Date: 10/22/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 9370  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SVC IRON DEPT (Continued)**

**S104746988**

Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H10715-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 3/28/2002  
 Begandt: 6/4/1998

59

**IMS RECYCLING  
 2740 BOSTON AVE  
 SAN DIEGO, CA 92113**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 SWEEPS UST**

**S105036292  
 N/A**

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2740 BOSTON AVE

**San Diego Co. HMMD:**

Facility ID: 135564  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAD029136058  
 Gas Station: Not reported  
 Inspection Date: 09/22/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RANDY PIZARRO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING (Continued)**

**S105036292**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-702-0247

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 10715  
 Number: 9  
 Board Of Equalization: 44-022486  
 Ref Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING (Continued)**

**S105036292**

Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010715-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: A  
 Comp Number: 10715  
 Number: 9  
 Board Of Equalization: 44-022486  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010715-000002  
 Actv Date: Not reported  
 Capacity: 3000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

59

**SAN DIEGO TRANSMISSION  
 1127 S 27TH ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000110646  
 FINDS CAD041323114  
 San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: SAN DIEGO TRANSMISSION  
 Facility address: 1127 S 27TH ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD041323114  
 Mailing address: S 27TH ST  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: FERNANDO ROBLES

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSMISSION (Continued)**

**1000110646**

Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

San Diego Co. HMMD:

Facility ID: 113058  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSMISSION (Continued)**

**1000110646**

2nd Name: Not reported  
 Mailing Address: 1127 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/07/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: FERNANDO ROBLES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GINGLARDY FAMILY TRUST 12-14-8  
 Property Address: 8108 DORCHESTER ST  
 Property City,St,Zip: 91977  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-2500

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSMISSION (Continued)**

**1000110646**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203850  
 Inactive Indicator: Active  
 Business Code: 6HK72  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1127 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/05/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: OSCAR (EDDIE) BIELMA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GINGLARDY FAMILY TRUST 12-14-8  
 Property Address: 8108 DORCHESTER ST  
 Property City,St,Zip: 91977  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/05/06  
 Facility Phone: 619-696-1136

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSMISSION (Continued)**

**1000110646**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 3653  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

Inspection Date: 08/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 3654  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3655  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 08/05/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 27  
 Quantity String: 27  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: PAINT BOOTH FILTERS & RAG  
 Carcinogen: No

Inspection Date: 08/05/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO TRANSMISSION (Continued)**

**1000110646**

Qty at Inspection: 27  
 Quantity String: 27  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

59

**ADVANCED WOOD FINISHING  
 1127 S 27TH ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMD**

**S106071415  
 N/A**

HAZNET:

Gepaid: CAL000266782  
 Contact: CATHY & DOUG SWANDA  
 Telephone: 6196961136  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1127 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAL000266782  
 Contact: CATHY & DOUG SWANDA  
 Telephone: 6196961136  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1127 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD980892731  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Recycler  
 Tons: 0.1  
 Facility County: San Diego

Gepaid: CAL000266782  
 Contact: CATHY & DOUG SWANDA  
 Telephone: 6196961136  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1127 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD980892731  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCED WOOD FINISHING (Continued)**

**S106071415**

Disposal Method: Transfer Station  
 Tons: 0  
 Facility County: San Diego  
  
 Gepaid: CAL000266782  
 Contact: CATHY & DOUG SWANDA  
 Telephone: 6196961136  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1127 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Click this hyperlink while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 201379  
 Inactive Indicator: Active  
 Business Code: 6HK72  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1127 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 02/14/03  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: DOUG SWANDA, MANAGER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GINGLARDY FAMILY TRUST 12-14-8  
 Property Address: 8108 DORCHESTER ST  
 Property City,St,Zip: 91977  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-1136

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCED WOOD FINISHING (Continued)**

**S106071415**

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/14/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 7203  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**MEDLAND CONTROLS INC  
 2393 NEWTON AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S106064557  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MEDLAND CONTROLS INC (Continued)**

**S106064557**

Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608131964  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-01-06 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: 1996-10-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: C/O WEXFORD MGMT CORP/C.INSLIS  
 RP Address: 411 W PUTNAM AV  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H35400-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MEDLAND CONTROLS INC (Continued)**

**S106064557**

San Diego Co. HMMD:  
 Facility ID: 135400  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2393 NEWTON AV #B  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000163147  
 Gas Station: Not reported  
 Inspection Date: 03/20/02  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ROBERT SPANN, QA DIR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: J A L LEASE L L C  
 Property Address: 15 G ST  
 Property City,St,Zip: 91910  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 235-4440

HMMD DISCLOSURE INVENTORY:  
 Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:  
 Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

HMMD VIOLATIONS:



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MEDLAND CONTROLS INC (Continued)**

**S106064557**

Inspection Date: 03/30/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0137  
 Occurrences: Not reported  
 Item Number: 2460  
 Violation Desc: MANIFEST NOT COMPLETED PROPERLY

Inspection Date: 03/30/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2461  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/30/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 2462  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 05/26/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4708  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/26/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4709  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 05/26/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4710  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5897  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5898  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/20/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MEDLAND CONTROLS INC (Continued)**

**S106064557**

Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5899  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H35400-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/6/1997  
 Begandt: Not reported

59

**ALLIED REFRIGERATION INC  
 2393 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106064422  
 N/A**

San Diego Co. HMMD:

Facility ID: 134982  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2393 NEWTON AV #B  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/12/94  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ROBERT SPANN, QA DIR

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALLIED REFRIGERATION INC (Continued)**

**S106064422**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: J A L LEASE L L C  
 Property Address: 15 G ST  
 Property City,St,Zip: 91910  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-235-4440

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALLIED REFRIGERATION INC (Continued)**

**S106064422**

Carcinogen: No

59

**FMC CORP  
 2393 NEWTON AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000857078  
 FINDS CA0000036475**

RCRA-SQG:

Date form received by agency: 10/26/1993  
 Facility name: FMC CORP  
 Facility address: 2393 NEWTON AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CA0000036475  
 Mailing address: W 35TH STE E  
 NATIONAL CITY, CA 91950  
 Contact: TERRY HAMILTON  
 Contact address: 155 W 35TH STE E  
 NATIONAL CITY, CA 91950  
 Contact country: US  
 Contact telephone: (619) 427-9300  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: FMC CORP  
 Owner/operator address: 4800 E RIVER RD PO BOX 59043  
 MINNEAPOLIS, MN 55459  
 Owner/operator country: Not reported  
 Owner/operator telephone: (612) 571-9201  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FMC CORP (Continued)**

**1000857078**

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

59

**RESURGENCE PROP INC  
 2363-2393 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103984172  
 N/A**

**HAZNET:**

Gepaid: CAC001225904  
 Contact: RESURGENCE PROP INC  
 Telephone: 6196315163  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 411 W PUTAM AVE  
 Mailing City,St,Zip: GRANDWICH, CT 068300000  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: .3000  
 Facility County: San Diego

Gepaid: CAC001225904  
 Contact: RESURGENCE PROP INC  
 Telephone: 6196315163  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 411 W PUTAM AVE  
 Mailing City,St,Zip: GRANDWICH, CT 068300000  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Alkaline solution without metals (pH > 12.5)  
 Disposal Method: Disposal, Other  
 Tons: .0208  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**59 UNION ELECTRIC MOTOR SERVICE  
 2777 NEWTON AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMMD  
 SAN DIEGO CO. SAM**

**S104750594  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303076  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-03-21 00:00:00  
 Discover Date: 1987-11-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-11-12 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H24752-001  
 Case Number: 9UT827

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNION ELECTRIC MOTOR SERVICE (Continued)**

**S104750594**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 124752  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2777 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000125430  
 Gas Station: Not reported  
 Inspection Date: 07/03/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MICHAEL DOWDELL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: LUCIO CHARLES  
 Property Address: 2777 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: TOM LIEBERMAN  
 Tank Address: 9496 MIRAMAR RD  
 Tank City,St,Zip: San Diego, CA 92126  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/03/05  
 Facility Phone: 619-232-4881

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC52  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNION ELECTRIC MOTOR SERVICE (Continued)**

**S104750594**

2nd Hazard Category: PRESSURE R  
 Item Number: OX51  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PO50  
 Chemical Name: POLYESTER RESIN  
 Case Number: 13-117-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT1105-1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: 07/18/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5671  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 07/18/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5672  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/18/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5673  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 07/18/98  
 Waste Code: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**UNION ELECTRIC MOTOR SERVICE (Continued)**

**S104750594**

Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5674  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 12/07/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 0928  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 12/07/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 0929  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 01/02/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2394  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/02/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2395  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 01/02/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2396  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 01/02/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 2397  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 07/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1952  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0301

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNION ELECTRIC MOTOR SERVICE (Continued)**

**S104750594**

Occurrences: Not reported  
 Item Number: 1953  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 07/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 1954  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 07/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1955  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 07/03/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: 15 GAL  
 Carcinogen: No

Inspection Date: 07/03/03  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 80  
 Annual Qty String: 80  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PAINT WASTE TO PARTS WASH  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H24752-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**UNION ELECTRIC MOTOR SERVICE (Continued)**

**S104750594**

Date: 3/21/1988  
 Begandt: 11/12/1987

59

**JVM SPA COVERS  
 2777 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET  
 LUST  
 Cortese  
 SWEEPS UST**

**S102432035  
 N/A**

HAZNET:

Gepaid: CAL000022785  
 Contact: ARTS AUTO BODY INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2777 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .1500  
 Facility County: San Diego

Gepaid: CAL000022785  
 Contact: ARTS AUTO BODY INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2777 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .0041  
 Facility County: San Diego

LUST:

Region: 9  
 Case Number: 9UT827  
 Local Agency: San Diego  
 Substance: Regular Gasoline  
 Qty Leaked: 0  
 Date Found: 11/13/1987  
 How Found: Tank Closure  
 Date Stopped: 11/13/1987  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JVM SPA COVERS (Continued)**

**S102432035**

Prelim Assess: 11/25/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 3/9/88  
 Pilot Program: LOP  
 Local Case: H24752-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 11/17/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2777 NEWTON AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 24752  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-024752-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 24752  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JVM SPA COVERS (Continued)**

**S102432035**

Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

59

**IMS RECYCLING SERVICES  
 2740 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S101579697  
 N/A**

HAZNET:

Gepaid: CAL000162852  
 Contact: MIKE HOWARD  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703666  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.6  
 Facility County: Not reported

Gepaid: CAL000162852  
 Contact: IMS RECYCLING SERVICES  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703666  
 Gen County: San Diego  
 TSD EPA ID: CAT080025711  
 TSD County: San Bernardino  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .6255  
 Facility County: San Diego

Gepaid: CAL000162852  
 Contact: IMS RECYCLING SERVICES  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703666  
 Gen County: San Diego  
 TSD EPA ID: CAT080025711  
 TSD County: San Bernardino  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 13.2397  
 Facility County: San Diego

Gepaid: CAL000162852  
 Contact: IMS RECYCLING SERVICES  
 Telephone: 6192312521  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES (Continued)**

**S101579697**

Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703666  
 Gen County: San Diego  
 TSD EPA ID: CAT080025711  
 TSD County: San Bernardino  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 6.8805  
 Facility County: San Diego

Gepaid: CAL000162852  
 Contact: IMS RECYCLING SERVICES  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703666  
 Gen County: San Diego  
 TSD EPA ID: CAT080025711  
 TSD County: San Bernardino  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .2085  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

59

**IMS RECYCLING SERVICES, INC.  
 2740 BOSTON AVE. SCALE HOUSE  
 SAN DIEGO, CA 92113**

**HIST UST U001572984  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000065553  
 Facility Type: Other  
 Other Type: RECYCLING YARD  
 Total Tanks: 0003  
 Contact Name: GEORGE W. STEINHAUER  
 Telephone: 6192312521  
 Owner Name: IMS RECYCLING SERVICES, INC.  
 Owner Address: 1345 S. 27TH ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00003000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**IMS RECYCLING SERVICES, INC. (Continued)**

**U001572984**

Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

59

**IMS RECYCLING SERVICES  
 2731 NEWTON AV  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMMD  
 CA WDS**

**S104752487**

**N/A**

HAZNET:

Gepaid: CAL922973861  
 Contact: STEVE ADLER/GENERAL MANAGER  
 Telephone: 6192320546  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703715  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Recycler  
 Tons: 5.83  
 Facility County: Not reported

Gepaid: CAL922973861  
 Contact: MIKE HOWARD/OPS MGR  
 Telephone: 6192320546  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703715  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.31  
 Facility County: Not reported

Gepaid: CAL922973861  
 Contact: IMS RECYCLING SERVICES, INC.  
 Telephone: 6192320546  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703715  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES (Continued)**

**S104752487**

TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .2126  
 Facility County: San Diego

Gepaid: CAL922973861  
 Contact: IMS RECYCLING SERVICES, INC.  
 Telephone: 6192320546  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921703715  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 3.3777  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 130575  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2731 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD029136058  
 Gas Station: Not reported  
 Inspection Date: 08/06/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE HOWARD  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SCRAP METALS INC  
 Property Address: 1327 S 27TH ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**IMS RECYCLING SERVICES (Continued)**

**S104752487**

Reinspection Date Y2K Compatible: 02/06/05  
 Facility Phone: 619-231-2521

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC61  
 Chemical Name: ACETYLENE  
 Case Number: 94-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: CA64  
 Chemical Name: CARBON DIOXIDE  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: LU63  
 Chemical Name: LUBRICATING OILS  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX62  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR60  
 Chemical Name: PROPANE  
 Case Number: 78-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES (Continued)**

**S104752487**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/21/00  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 3780  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 03/21/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3781  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/21/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 3782  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/21/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3783  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/21/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 3784  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: 08/06/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 88

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES (Continued)**

**S104752487**

Annual Qty String: 88  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: SOLVENT 105  
 Carcinogen: No

Inspection Date: 08/06/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 3960  
 Annual Qty String: 3960  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 08/06/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 6000  
 Annual Qty String: 6000  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: ABSRBNT CONTAM WITH OIL  
 Carcinogen: No

Inspection Date: 08/06/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 570  
 Quantity String: 570  
 Annual Qty: 1140  
 Annual Qty String: 1140  
 Measurement Unit: GAL  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: INTERSTATE  
 Carcinogen: No

Inspection Date: 08/06/03  
 Waste Item #: 451  
 Waste Code: 451  
 Waste Name: DEGREASING SLUDGE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**IMS RECYCLING SERVICES (Continued)**

**S104752487**

Qty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 3534 EFR ENVIRONMENTAL SV  
 Waste Desc: SUMP SLUDGE  
 Carcinogen: No

Inspection Date: 08/06/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3534 EFR ENVIRONMENTAL SV  
 Waste Desc: OIL FILTERS CRUSHED  
 Carcinogen: No

**CA WDS:**

Facility ID: San Diego 371013270  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: IMS RECYCLING SERVICES INC  
 Agency Address: 2731 NEWTON AVE  
 Agency City,St,Zip: SAN DIEGO 92113  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES (Continued)**

**S104752487**

POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.  
 Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

59

**PACIFIC PEBBLES  
 2709 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104754693  
 N/A**

San Diego Co. HMMD:

Facility ID: 134896  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2709 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000178841  
 Gas Station: Not reported  
 Inspection Date: 11/05/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: PAUL KOURY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BANK OF COMMERCE <LF> PACIFIC  
 Property Address: C/O PACIFIC PEBBLES  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-7600

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC PEBBLES (Continued)**

**S104754693**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/26/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3760  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/26/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3761  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5891  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 5892  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5893  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5894

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC PEBBLES (Continued)**

**S104754693**

Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	03/20/02
Waste Code:	Not reported
Type of Violation:	6HV1003
Occurrences:	Not reported
Item Number:	5895
Violation Desc:	HMBP NOT AMENDED W/IN 30 DAYS
Inspection Date:	03/20/02
Waste Code:	Not reported
Type of Violation:	6HV1009
Occurrences:	Not reported
Item Number:	5896
Violation Desc:	HMBP: INADEQUATE SITE MAP
Inspection Date:	11/05/03
Waste Code:	Not reported
Type of Violation:	6HV0133
Occurrences:	Not reported
Item Number:	5838
Violation Desc:	MANIFEST COPY NOT SENT TO DTSC
Inspection Date:	11/05/03
Waste Code:	Not reported
Type of Violation:	6HV1011
Occurrences:	Not reported
Item Number:	5839
Violation Desc:	TRAINING RECORDS NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qnty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No

Facility ID:	203261
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2709 NEWTON AVE
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC PEBBLES (Continued)**

**S104754693**

Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/30/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ISABEL CAMPOS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BANK OF COMMERCE <LF> PACIFIC  
 Property Address: C/O PACIFIC PEBBLES  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-8111

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC PEBBLES (Continued)**

**S104754693**

Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**LIFE DECK-PACIFIC PEBBLES  
 2709 NEWTON  
 SAN DIEGO, CA 92113**

**HAZNET S103648377  
 N/A**

HAZNET:

Gepaid: CAL000178841  
 Contact: PAUL KOURY  
 Telephone: 6196967600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2709 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 1.8348  
 Facility County: San Diego

Gepaid: CAL000178841  
 Contact: PAUL KOURY  
 Telephone: 6196967600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2709 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: .8000  
 Facility County: San Diego

Gepaid: CAL000178841  
 Contact: PAUL KOURY  
 Telephone: 6196967600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2709 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LIFE DECK-PACIFIC PEBBLES (Continued)**

**S103648377**

Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.2293  
 Facility County: San Diego

Gepaid: CAL000178841  
 Contact: PAUL KOURY  
 Telephone: 6196967600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2709 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Recycler  
 Tons: 0.1251  
 Facility County: San Diego

Gepaid: CAL000178841  
 Contact: JEFF MARSHALL  
 Telephone: 6196967600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2709 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.34  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

59

**FARRELL COURIER SERVICE INC**  
**2691 NEWTON AV**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106880164**  
**N/A**

San Diego Co. HMMD:  
 Facility ID: 103117  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FARRELL COURIER SERVICE INC (Continued)**

**S106880164**

Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GONZALEZ FRANCISCO  
 Property Address: 2691 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FARRELL COURIER SERVICE INC (Continued)**

**S106880164**

Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**CANDY'S AUTO BODY SHOP  
 2691 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S108200738  
 N/A**

HAZNET:

Gepaid: CAL000286361  
 Contact: FRANCISCO GONZALEZ/OWNER  
 Telephone: 6195466237  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2691 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAL000286361  
 Contact: FRANCISCO GONZALEZ/OWNER  
 Telephone: 6195466237  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2691 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Not reported  
 Disposal Method: Not reported  
 Tons: 0  
 Facility County: San Diego

59

**J&J AUTO BODY  
 2691 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S105112980  
 N/A**

San Diego Co. HMMD:

Facility ID: 128607  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2691 NEWTON AV

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**J&J AUTO BODY (Continued)**

**S105112980**

Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000146834  
 Gas Station: Not reported  
 Inspection Date: 09/07/01  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JAIME LOPEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GONZALEZ FRANCISCO  
 Property Address: 2691 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: DIEGO RODRIGUEZ  
 Tank Address: 4513 PATRIA DR  
 Tank City,St,Zip: San Diego, CA 92115  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-235-4303

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 04/13/98  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 2825  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE  
  
 Inspection Date: 04/13/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**J&J AUTO BODY (Continued)**

**S105112980**

Occurrences: Not reported  
 Item Number: 2826  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/13/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2827  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 04/13/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 2828  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 04/13/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0295  
 Occurrences: Not reported  
 Item Number: 2829  
 Violation Desc: DAMAGED BATTERIES: IMPROP MGMT

Inspection Date: 04/13/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 2830  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 09/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 9573  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 09/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9574  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 9575  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**J&J AUTO BODY (Continued)**

**S105112980**

Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 200338  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: JAIME LOPEZ  
 Mailing Address: 2691 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000146834  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GONZALEZ FRANCISCO  
 Property Address: 2691 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**J&J AUTO BODY (Continued)**

**S105112980**

1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**JESUS TRANSPORTATION**  
**2691 NEWTON AVE**  
**SAN DIEGO, CA 92113**

**SWEEPS UST S106927778**  
**N/A**

**SWEEPS UST:**

Status: A  
 Comp Number: 28607  
 Number: 9  
 Board Of Equalization: 44-023755  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-028607-000001  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 1



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 CANDY'S AUTO BODY LLC  
 2691 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMMD**

**S104745608  
 N/A**

San Diego Co. HMMMD:

Facility ID: 204367  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2691 NEWTON AV  
 Mailing City,St,Zip: San Diego, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/08/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: CHICO GONZALEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GONZALEZ FRANCISCO  
 Property Address: 2691 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 11/08/06  
 Facility Phone: 619-546-6237

HMMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CANDY'S AUTO BODY LLC (Continued)**

**S104745608**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 11/08/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0971 PACIFIC COAST LACQUE  
 Waste Desc: Not reported  
 Carcinogen: No

59

**HOWELL SERVICE  
 2681 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748617  
 N/A**

San Diego Co. HMMD:

Facility ID: 116523  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 4785 SOLOLA CT  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/19/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: CURTIS HOWELL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KOTCHER ANTHONY&DESIREE E  
 Property Address: 2679 NEWTON AVE

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

**HOWELL SERVICE (Continued)**

**S104748617**

Property City,St,Zip: 92113  
Tank Owner: Not reported  
Tank Address: Not reported  
Tank City,St,Zip: Not reported  
Business Plan Acceptance Date: Not reported  
Reinspection Date Y2K Compatible: Not reported  
Facility Phone: 619-232-9419

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
Chemical Name: Not reported  
Case Number: Not reported  
Quantity Stored At One Time: Not reported  
Quantity Stored at One Time: Not reported  
Annual Quantity String: Not reported  
Annual Quantity String: Not reported  
Measurement Units: Not reported  
Carcinogen: No  
1st Hazard Category: Not reported  
2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
Tank ID Number: Not reported  
Waste or Product: Not reported  
Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
Waste Code: Not reported  
Type of Violation: Not reported  
Occurrences: Not reported  
Item Number: Not reported  
Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
Waste Item #: Not reported  
Waste Code: Not reported  
Waste Name: Not reported  
Qty at Inspection: Not reported  
Quantity String: Not reported  
Annual Qty: Not reported  
Annual Qty String: Not reported  
Measurement Unit: Not reported  
Treatment Method: Not reported  
Storage Method: Not reported  
Haz Waste Hauler: Not reported  
Waste Desc: Not reported  
Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 HYTECH METAL FORMING  
 2676 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104748616  
 N/A**

San Diego Co. HMMD:

Facility ID:	116522
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2676 NEWTON AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	10/16/03
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	MIKE MERCADO
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	GARCIA/MERCADO FAMILY TRUST 02
Property Address:	359 PLAZA TOLUCA
Property City,St,Zip:	91914
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	04/16/05
Facility Phone:	619-239-6360

HMMD DISCLOSURE INVENTORY:

Item Number:	AC15
Chemical Name:	ACETYLENE AND OXYGEN (7782-44-7)
Case Number:	7782-44-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	PRESSURE R

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**HYTECH METAL FORMING (Continued)**

**S104748616**

**HMMD VIOLATIONS:**

Inspection Date:	04/07/98
Waste Code:	Not reported
Type of Violation:	6HV0135
Occurrences:	Not reported
Item Number:	2695
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	06/22/99
Waste Code:	Not reported
Type of Violation:	6HV0135
Occurrences:	Not reported
Item Number:	5488
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	06/22/99
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	5489
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	06/22/99
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	5490
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	5493
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	5494
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	5495
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	5496
Violation Desc:	TRAINING RECORDS UNAVAILABLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HYTECH METAL FORMING (Continued)**

**S104748616**

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5497  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 10/16/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 5308  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

Inspection Date: 10/16/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5309  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/16/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 5310  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 10/16/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5311  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 10/16/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 5312  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 10/16/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 GARCIA AUTO REPAIR  
 2340 NEWTON AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104747454  
 N/A**

San Diego Co. HMMD:

Facility ID: 112693  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2340 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000070786  
 Gas Station: Not reported  
 Inspection Date: 10/31/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: GONZALO GARCIA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MELERO HECTOR  
 Property Address: 1028 HELEN CIR  
 Property City,St,Zip: 91950  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/30/05  
 Facility Phone: 619-232-5864

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GARCIA AUTO REPAIR (Continued)**

**S104747454**

HMMD VIOLATIONS:

Inspection Date: 11/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9671  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 9672  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 11/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9673  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5152  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5153  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5154  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 5155  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5156  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GARCIA AUTO REPAIR (Continued)**

**S104747454**

Inspection Date: 10/31/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 5741  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 10/31/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 2986 INDUSTRIAL SOLVENT &  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/31/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/31/03  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: ORGANIC LIQUIDS WITH META  
 Carcinogen: No

Inspection Date: 10/31/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GARCIA AUTO REPAIR (Continued)**

**S104747454**

Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: EFR  
 Carcinogen: No

59

**GARCIA AUTO REPAIR  
 2340 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S102861728  
 N/A**

HAZNET:

Gepaid: CAL000070786  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2340 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133621  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .2500  
 Facility County: San Diego

Gepaid: CAL000070786  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2340 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133621  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .3000  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**59 FORDS & FOREIGN AUTO PARTS  
 2335 NEWTON AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMMD  
 SAN DIEGO CO. SAM**

**S104748615  
 N/A**

LUST:

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOV  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608185080  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1999-03-19 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: MR. MICHAEL MIHOS/MNGR.  
 RP Address: P.O.BOX 126506  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16521-001  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FORDS & FOREIGN AUTO PARTS (Continued)**

**S104748615**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 116521  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2335 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/01/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JOEL MCNEIL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: J A L LEASE L L C  
 Property Address: 15 G ST  
 Property City,St,Zip: 91910  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-8134

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FORDS & FOREIGN AUTO PARTS (Continued)**

**S104748615**

2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H16521-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Closed Case  
 Date: 3/19/1999  
 Begandt: 7/14/1988

59

**BARRIO SENIOR VILLAS  
 2330 NEWTON AVE  
 SAN DIEGO, CA 92102**

**FINDS 1000857234  
 HAZNET CAD982360786  
 CERC-NFRAP  
 RCRA-NonGen**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRIO SENIOR VILLAS (Continued)**

**1000857234**

HAZNET:

Gepaid: CAD982360786  
 Contact: BARRIO SENIOR VILLAS INC  
 Telephone: 6192361228  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 610 22ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: CAD000633164  
 TSD County: Imperial  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Land Fill  
 Tons: 15.1704  
 Facility County: San Diego

Gepaid: CAD982360786  
 Contact: BARRIO SENIOR VILLAS INC  
 Telephone: 6192361228  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 610 22ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: CAD000633164  
 TSD County: Imperial  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Treatment, Tank  
 Tons: 14.3276  
 Facility County: San Diego

CERC-NFRAP:

Site ID: 0903105  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 12/01/1987  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRIO SENIOR VILLAS (Continued)**

**1000857234**

Date Completed: 11/29/1988  
 Priority Level: Not reported  
 Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 11/29/1988  
 Priority Level: NFRAP (No Futher Remedial Action Planned)

**RCRA-NonGen:**

Date form received by agency: 06/12/1995  
 Facility name: BARRIO SENIOR VILLAS  
 Facility address: 2330 NEWTON AVE  
 SAN DIEGO, CA 92102  
 EPA ID: CAD982360786  
 Mailing address: 22ND ST  
 SAN DIEGO, CA 92102  
 Contact: PAMELA JOHANNSEN  
 Contact address: 610 22ND ST  
 SAN DIEGO, CA 92102  
 Contact country: US  
 Contact telephone: (619) 236-1228  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: BARRIO SENIOR VILLAS INC  
 Owner/operator address: 610 22ND ST  
 SAN DIEGO, CA 92102  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 236-1228  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**59 AUGUST'S FOUNDRY  
 2320 NEWTON AVENUE  
 SAN DIEGO, CA 92113**

**ENVIROSTOR 1000428569  
 N/A**

ENVIROSTOR:

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37330006  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: \* CERC2  
 Status: Refer: Other Agency  
 Status Date: 1995-08-21 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 32.695  
 Longitude: -117.138611111111  
 Alias Name: 37330006  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: CALSITES VALIDATION PROGRAM CONFIRMS NFA FOR DTSC.FACILITY IDENTIFIED ID VIA 50 PHONE BOOKSITE SCREENING DONE PA RECOM BASED ON POSSIBILITY OF ILLEGAL DUMPING OF CLASS 2 OR 3 MATERIALS HEREPRELIM ASSESS DONE PDS: REFERRED TO COUNTY HEALTH FOR UNDER GROUND TANK; NO HISTORY OF HAZARDOUS WASTE ACTIVITY

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 11/07/94

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 06/28/88

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 02/24/87

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 10/18/82

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AUGUST'S FOUNDRY (Continued)**

**1000428569**

Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

59

**BARRIO STATION INC  
 2320 NEWTON AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104752316  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608116918  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1990-02-06 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRIO STATION INC (Continued)**

**S104752316**

Responsible Party: RACHEL ORTIZ  
 RP Address: 2175 NEWTON AVE.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H29840-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608135393  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1994-01-21 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: 1992-02-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BARRIO STATION INC (Continued)**

**S104752316**

Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: PAM JOHANNSEN  
 RP Address: 610 22ND  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H29840-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 129840  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2320 NEWTON AV  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: JUDY ATKINS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRIO STATION INC (Continued)**

**S104752316**

Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	BARRIO SENIOR VILLAS
Property Address:	C/O CHICANO FEDERATI
Property City,St,Zip:	92104
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BARRIO STATION INC (Continued)**

**S104752316**

Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H29840-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/6/1990  
 Begandt: Not reported

Case Number: H29840-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/21/1994  
 Begandt: Not reported

59

**NORTH STAR PROPELLERS, INC  
 2317 NEWTON AV  
 SAN DIEGO, CA 92113**

**HAZNET S103644132  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAL000178958  
 Contact: BERNIE MARTIN  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2380 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921133643  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)  
 Disposal Method: Transfer Station  
 Tons: .3127  
 Facility County: San Diego

Gepaid: CAL000178958  
 Contact: BERNIE MARTIN  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2380 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921133643  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2  
 Disposal Method: Transfer Station  
 Tons: .8340  
 Facility County: San Diego

Gepaid: CAL000178958

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NORTH STAR PROPELLERS, INC (Continued)**

**S103644132**

Contact:	BERNIE MARTIN
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2380 MAIN STREET
Mailing City,St,Zip:	SAN DIEGO, CA 921133643
Gen County:	San Diego
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.3544
Facility County:	San Diego
Gepaid:	CAL000178958
Contact:	BERNIE MARTIN
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2380 MAIN STREET
Mailing City,St,Zip:	SAN DIEGO, CA 921133643
Gen County:	San Diego
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Not reported
Tons:	.2293
Facility County:	San Diego
Gepaid:	CAL000178958
Contact:	BERNIE MARTIN
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2380 MAIN STREET
Mailing City,St,Zip:	SAN DIEGO, CA 921133643
Gen County:	San Diego
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)
Disposal Method:	Not reported
Tons:	.9173
Facility County:	San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 3 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:	
Facility ID:	202739
Inactive Indicator:	Active
Business Code:	6HK35
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2317 NEWTON AVE
Mailing City,St,Zip:	SAN DIEGO, CA 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS, INC (Continued)**

**S103644132**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/01/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: OSCAR LUNA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: S B S PARTNERSHIP  
 Property Address: 2285 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/01/05  
 Facility Phone: 619-239-8309

**HMMD DISCLOSURE INVENTORY:**

Item Number: AR56  
 Chemical Name: ARGON GAS  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: AR48  
 Chemical Name: ARGON/CARBON DIOXIDE MIG MIX/ STEEL MIX  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NORTH STAR PROPELLERS, INC (Continued)**

**S103644132**

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: 12/01/03  
 Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 180  
 Annual Qty String: 180  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 12/01/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 25  
 Quantity String: 25  
 Annual Qty: 550  
 Annual Qty String: 550  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: PAINT BOOTH FILTERS  
 Carcinogen: No

Inspection Date: 12/01/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 60  
 Quantity String: 60  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: SYSTEM 1 - PETROLEUM NAPT  
 Carcinogen: No

Inspection Date: 12/01/03  
 Waste Item #: 221



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NORTH STAR PROPELLERS, INC (Continued)**

**S103644132**

Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: HYDRAULIC  
 Carcinogen: No

Inspection Date: 12/01/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 1200  
 Annual Qty String: 1200  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: UESD OIL  
 Carcinogen: No

Inspection Date: 12/01/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 25  
 Quantity String: 25  
 Annual Qty: 550  
 Annual Qty String: 550  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: OILY ASBORBENT  
 Carcinogen: No

Inspection Date: 12/01/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 1100  
 Annual Qty String: 1100  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

<b>59</b>	<b>NORTH STAR PROPELLERS INC</b> <b>2285 NEWTON AVENUE</b> <b>SAN DIEGO, CA 92110</b>	<b>FINDS</b>	<b>1006306458</b> <b>110012426543</b>
-----------	---	--------------	--

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

<b>59</b>	<b>NORTH STAR PROPELLERS INC.</b> <b>2285 NEWTON AV</b> <b>SAN DIEGO, CA 92113</b>	<b>San Diego Co. HMMD</b> <b>AIRS</b>	<b>S104752513</b> <b>N/A</b>
-----------	--	--	---------------------------------

San Diego Co. HMMD:

Facility ID:	130775
Inactive Indicator:	Active
Business Code:	6HK35
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2285 NEWTON AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	CAL000070921
Gas Station:	Not reported
Inspection Date:	11/19/03
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	OSCAR LUNA
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	STODDART BERNICE E EST
Property Address:	C/O THOMAS J HALL ES
Property City,St,Zip:	89501
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	05/19/05
Facility Phone:	619-239-8309

**HMMD DISCLOSURE INVENTORY:**

Item Number:	AC87
Chemical Name:	ACETYLENE (375 CFT)
Case Number:	74-86-2
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC. (Continued)**

**S104752513**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR86  
 Chemical Name: ARGON (336 CFT)  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: AR96  
 Chemical Name: ARGON/02 (335 CFT)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: AR95  
 Chemical Name: ARGON/C02 (381 CFT)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: AR94  
 Chemical Name: ARGON/HELIUM/C02 (211 CFT)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CA91  
 Chemical Name: CARBON DIOXIDE(50LBS/437 CFT)  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NORTH STAR PROPELLERS INC. (Continued)**

**S104752513**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: DI92  
 Chemical Name: DIESEL  
 Case Number: 68476-30-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: HE93  
 Chemical Name: HELIUM (291 CFT)  
 Case Number: 7740-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: LI98  
 Chemical Name: LIQUID NITROGEN (360 LBS)  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NI97  
 Chemical Name: NITROGEN (228 CFT)  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: OI89

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC. (Continued)**

**S104752513**

Chemical Name: OIL: CUTTING/HYDRAULIC OIL  
 Case Number: 64742-44-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: OX88  
 Chemical Name: OXYGEN (249 CFT)  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR90  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 2618  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2619  
 Violation Desc: WASTE CONTAINER NOT CLOSED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC. (Continued)**

**S104752513**

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5869  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 5870  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 5871  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5872  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0295  
 Occurrences: Not reported  
 Item Number: 5873  
 Violation Desc: DAMAGED BATTERIES: IMPROP MGMT

**HMMD WASTE STREAMS:**

Inspection Date: 11/19/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 36  
 Quantity String: 36  
 Annual Qty: 144  
 Annual Qty String: 144  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PARTS CLEANER (1 UNIT)  
 Carcinogen: No

Inspection Date: 11/19/03  
 Waste Item #: 252  
 Waste Code: 252  
 Waste Name: STILL BOTTOM WASTE (  
 Qnty at Inspection: 5  
 Quantity String: 5

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC. (Continued)**

**S104752513**

Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: STILL BOTTOMS  
 Carcinogen: No

EMI:

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6797  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 1  
 NOX - Oxides of Nitrogen Tons/Yr: 3  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6797  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 1  
 NOX - Oxides of Nitrogen Tons/Yr: 3  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6797  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC. (Continued)**

**S104752513**

NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	6797
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	6797
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	6797
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC. (Continued)**

**S104752513**

Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6797  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2.90055784  
 Reactive Organic Gases Tons/Yr: 2.66625748  
 Carbon Monoxide Emissions Tons/Yr: 0.58607036  
 NOX - Oxides of Nitrogen Tons/Yr: 2.7205586  
 SOX - Oxides of Sulphur Tons/Yr: 0.0319642  
 Particulate Matter Tons/Yr: 0.23099496  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0.23099496

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6797  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2.71  
 Reactive Organic Gases Tons/Yr: 2.5  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: .0465116279069767441  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: .04

59

**NORTH STAR PROPELLERS INC  
 2285 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S102863447  
 N/A**

HAZNET:

Gepaid: CAL000070921  
 Contact: HERMAN A SLEGE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133619  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: .1500  
 Facility County: San Diego

Gepaid: CAL000070921  
 Contact: DEREK M BATEMAN/VP-GEN MGR  
 Telephone: 6192398309  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC (Continued)**

**S102863447**

Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133619  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: 0.12  
 Facility County: Not reported

Gepaid: CAL000070921  
 Contact: HERMAN A SLEGE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133619  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 11.6760  
 Facility County: San Diego

Gepaid: CAL000070921  
 Contact: DEREK M BATEMAN/VP-GEN MGR  
 Telephone: 6192398309  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133619  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.01  
 Facility County: Not reported

Gepaid: CAL000070921  
 Contact: DEREK M BATEMAN/VP-GEN MGR  
 Telephone: 6192398309  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133619  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: 0.41  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NORTH STAR PROPELLERS INC (Continued)**

**S102863447**

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

59

**NORTH STAR PROPELLER  
 2285 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100735466  
 N/A**

HAZNET:

Gepaid: CAL000005597  
 Contact: NORTH STAR PROPELLERS  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: .0667  
 Facility County: San Diego

Gepaid: CAL000005597  
 Contact: INACTIVE PER SURVEY 2/95 AD  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.2  
 Facility County: Not reported

Gepaid: CAL000005597  
 Contact: NORTH STAR PROPELLERS  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2285 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 SICARD AUTO REPAIR  
 1025 SICARD ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106879866  
 N/A**

San Diego Co. HMMD:

Facility ID:	204729
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1025 SICARD
Mailing City,St,Zip:	San Diego, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	CAL000280022
Gas Station:	Not reported
Inspection Date:	01/25/05
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	JOSE ESTRADA
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	JOHNSON FAMILY TRUST 06-25-91
Property Address:	1237 E 24TH ST
Property City,St,Zip:	91950
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	07/25/06
Facility Phone:	Not reported

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SICARD AUTO REPAIR (Continued)**

**S106879866**

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: 01/25/05  
 Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 70  
 Annual Qty String: 70  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESS EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 01/25/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 01/25/05  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 550  
 Quantity String: 550  
 Annual Qty: 550  
 Annual Qty String: 550  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Distance (ft.)Site Database(s) EPA ID Number

59 ADVANCED METAL FORMING, INC. HAZNET S104745059  
 2618 NATIONAL AV San Diego Co. HMMD N/A  
 SAN DIEGO, CA 92113 CA WDS

HAZNET:

Gepaid: CAD982326738  
 Contact: CHARLES TEAHAN  
 Telephone: 6192399437  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13530  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: TXD077603371  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: H06  
 Tons: 0.12  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 100630  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 13530  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD982326738  
 Gas Station: Not reported  
 Inspection Date: 11/19/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: CHUCK TEAHAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PARTMAN FAMILY TRUST 11-10-88  
 Property Address: C/O JACQUELINE W BEA  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/19/05  
 Facility Phone: 619-239-9437

HMMD DISCLOSURE INVENTORY:

Item Number: AC97  
 Chemical Name: ACETYLENE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ADVANCED METAL FORMING, INC. (Continued)**

**S104745059**

Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR95  
 Chemical Name: ARGON 75%; C02 25%; ARGON, C02, HEL MIX  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: AR99  
 Chemical Name: ARGON X 250 CFT  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: CA01  
 Chemical Name: CARBON DIOXIDE X 50 LBS = 437 CFT  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: NI00  
 Chemical Name: NITROGEN X 304 CFT  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCED METAL FORMING, INC. (Continued)**

**S104745059**

Item Number: OX96  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR98  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/15/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 7819  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5142  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 11/19/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 30  
 Annual Qty String: 30  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCED METAL FORMING, INC. (Continued)**

**S104745059**

Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: ABSRBNT RAGS W/OIL/KTTY L  
 Carcinogen: No

Inspection Date: 11/19/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: Not reported  
 Carcinogen: No

**CA WDS:**

Facility ID: San Diego 371013986  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: J M BEAVAN  
 Agency Address: 2618 NATIONAL AVE  
 Agency City,St,Zip: SAN DIEGO 92113  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCED METAL FORMING, INC. (Continued)**

**S104745059**

Complexity: represent no threat to water quality.  
 Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

59

**L & M SAW WORKS INC  
 2670 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104745062  
 N/A**

San Diego Co. HMMD:

Facility ID: 100641  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GUEVAL INVESTMENTS L P  
 Property Address: C/O JESUS GUERRERO  
 Property City,St,Zip: 91910  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**L & M SAW WORKS INC (Continued)**

**S104745062**

1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**HANSSON INDUSTRIAL & TRUCK  
 2619 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748606  
 N/A**

San Diego Co. HMMD:

Facility ID: 116494  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2619 NATIONAL AV  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/30/03  
 Reinspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HANSSON INDUSTRIAL & TRUCK (Continued)**

**S104748606**

Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ALAN HAMADA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: HANSSON JOHN A TRUST 12-06-90  
 Property Address: C/O MARVIN L GILBERT  
 Property City,St,Zip: 92025  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-2101

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HANSSON INDUSTRIAL & TRUCK (Continued)**

**S104748606**

Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**ABC CONSTRUCTION CO  
 2665 NATIONAL AVENUE  
 SAN DIEGO, CA 92113**

**Notify 65 1000108586  
 RCRA-SQG CAD981405418  
 FINDS  
 LUST  
 Cortese  
 San Diego Co. HMMD  
 HIST UST  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

Notify 65:

Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92113-3617

RCRA-SQG:

Date form received by agency: 05/06/1986  
 Facility name: ABC CONSTRUCTION CO  
 Facility address: 2665 NATIONAL AVENUE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981405418  
 Mailing address: 3120 NATIONAL AVENUE  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2665 NATIONAL AVENUE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 239-3428  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: ABC CONSTRUCTION CO  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Not reported  
 Leak Source: Tank  
 Global Id: T0607300927  
 Stop Date: 1989-05-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2007-01-09 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1989-05-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-05-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: KEN CZUBERNAT  
 RP Address: 3120 NATIONAL AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: GM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05600-002  
 Case Number: 9UT2158  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608106750  
 Stop Date: 1988-11-11 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-12-22 00:00:00  
 Discover Date: 1988-10-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-10-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: KEN CZUBERNAT  
 RP Address: 3120 NATIONAL AV  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: MV  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05600-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

LUST:

Region: 9  
 Case Number: 9UT2158  
 Local Agency: San Diego  
 Substance: Regular Gasoline  
 Qty Leaked: 0  
 Date Found: 01/13/1992  
 How Found: Other Means  
 Date Stopped: 01/13/1992  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 05/24/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 06/02/1989  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H05600-002  
 Basin Number: 908.22  
 Gwater Depth: ~11  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 01/13/1992  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2665 NATIONAL AVE

San Diego Co. HMMD:

Facility ID: 105600  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3120 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

Census Tract Number: 50  
 EPA ID: CAD981405418  
 Gas Station: Not reported  
 Inspection Date: 11/18/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: WAYNE CZUBERNAT OR PATTY MAXWE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: ABC CONSTRUCTION CO INC  
 Tank Address: 3120 NATIONAL AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/18/05  
 Facility Phone: 619-239-3428

**HMMD DISCLOSURE INVENTORY:**

Item Number: HY79  
 Chemical Name: HYDRAULIC OIL/MOTOR OIL  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: RS78  
 Chemical Name: RS-1/RS-2/SS-1H EMULSIFIED ASPHALT 150 GALLON TANKS  
 Case Number: 8030-31-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 001  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 002  
 Waste or Product: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: 02/26/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1490  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/26/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1491  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 02/26/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1492  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/26/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 1493  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/26/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 1494  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 02/26/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 1495  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 05/11/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 4244  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5145

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 6168  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 11/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 6169  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 11/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6170  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 11/18/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: ENGINE OIL  
 Carcinogen: No

Inspection Date: 11/18/03  
 Waste Item #: 351  
 Waste Code: 351  
 Waste Name: ORGANIC SOLIDS WITH  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 30  
 Annual Qty String: 30  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: COOLANT  
 Carcinogen: No

Inspection Date: 11/18/03  
 Waste Item #: 888  
 Waste Code: 888

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 550  
 Quantity String: 550  
 Annual Qty: 550  
 Annual Qty String: 550  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2591 ENVIROPUR WEST CORPO  
 Waste Desc: FILTERS  
 Carcinogen: No

**HIST UST:**

Region: STATE  
 Facility ID: 00000014955  
 Facility Type: Other  
 Other Type: CONSTRUCTION  
 Total Tanks: 0002  
 Contact Name: ROBERT CZUBERNAT  
 Telephone: 6192393428  
 Owner Name: ABC CONSTRUCTION CO., INC.  
 Owner Address: 3120 NATIONAL AVENUE  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 001  
 Year Installed: Not reported  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

Tank Num: 002  
 Container Num: 002  
 Year Installed: Not reported  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 5600  
 Number: Not reported  
 Board Of Equalization: 44-022249  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005600-000001  
 Actv Date: Not reported  
 Capacity: 500

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABC CONSTRUCTION CO (Continued)**

**1000108586**

Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 5600  
 Number: 9  
 Board Of Equalization: 44-022249  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005600-000002  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H05600-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 12/22/1988  
 Begandt: 10/17/1988

Case Number: H05600-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 6/2/1989  
 Begandt: 5/18/1989

59

**LUIS COMANJA AUTO SERVICE  
 2295 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748496  
 N/A**

San Diego Co. HMMD:

Facility ID: 115784  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2295 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LUIS COMANJA AUTO SERVICE (Continued)**

**S104748496**

EPA ID: CAL000018388  
 Gas Station: Not reported  
 Inspection Date: 11/05/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: LUIS MALACARA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ROMO RICHARD REVOCABLE TRUST 1  
 Property Address: 2295 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-474-7486

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LUIS COMANJA AUTO SERVICE (Continued)**

**S104748496**

Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**CARLOS TRANSMISSION  
 2295 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET**

**S108200855  
 N/A**

HAZNET:

Gepaid: CAL000020320  
 Contact: UNDELIVERABLE SURVEY 1-25-95LH  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2295 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: NVD980895338  
 TSD County: 99  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

59

**WESTERN STEEL  
 2292 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104748605  
 N/A**

San Diego Co. HMMD:

Facility ID: 116491  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 13337  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/09/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JIM GALLEY  
 Delinquent Flag: Not Delinquent



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTERN STEEL (Continued)**

**S104748605**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PACIFIC PROPERTY TRUST  
 Property Address: P O BOX 1641  
 Property City,St,Zip: 92038  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/09/05  
 Facility Phone: 619-235-0171

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC86  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR73  
 Chemical Name: ARGON/CO2, COMPRESSED GAS  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: HE90  
 Chemical Name: HELIUM  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: HE70  
 Chemical Name: HELIUM/ARGON COMPRESSED GAS  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTERN STEEL (Continued)**

**S104748605**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OX87  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/13/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5616  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/13/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5617  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 08/24/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1699  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 08/24/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 1700  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTERN STEEL (Continued)**

**S104748605**

Item Number: 5164  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 10/09/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 5067  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 10/09/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 5068  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**WESTERN STEEL & METALS**  
**2292 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**HAZNET S104572827**  
**N/A**

**HAZNET:**

Gepaid: CAC002224113  
 Contact: SUE WINTHROPE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2292 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: 0.2085  
 Facility County: San Diego

Gepaid: CAC002224113  
 Contact: SUE WINTHROPE  
 Telephone: 0000000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WESTERN STEEL & METALS (Continued)**

**S104572827**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2292 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.2085  
 Facility County: San Diego

59

**ANGELS AUTO REPAIR  
 2276 NATIONAL AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104748604  
 N/A**

San Diego Co. HMMD:

Facility ID: 116490  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2276 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/01/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ANGEL SANCHEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PACIFIC PROPERTY TRUST  
 Property Address: P O BOX 1641  
 Property City,St,Zip: 92038  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-531-1675

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ANGELS AUTO REPAIR (Continued)**

**S104748604**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**TERESA'S TIRE SHOP  
 2276 NATIONAL AVENUE  
 SAN DIEGO, CA 92113**

**HAZNET S107141435  
 N/A**

**HAZNET:**

Gepaid: CAC002565660  
 Contact: RAYMOUND LUNA  
 Telephone: 6195449129  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2276 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133615  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Treatment, Tank  
 Tons: 0.22

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**TERESA'S TIRE SHOP (Continued)**

**S107141435**

Facility County: San Diego

59

**ALL WRENCH AUTO  
 925 S 26TH ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S105539678  
 N/A**

San Diego Co. HMMD:

Facility ID: 131332  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 925 1/2 S 26 ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/10/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: FRED FULCHER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: HARDIE GILBERT S&ISABEL B TRUS  
 Property Address: C/O ANTHONY L BEDFOR  
 Property City,St,Zip: 92115  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619- -

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALL WRENCH AUTO (Continued)**

**S105539678**

Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**ACE MUFFLER SHOP  
 2260 NATIONAL AV  
 SAN DIEGO, CA 92113**

**HAZNET S104749163  
 San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAL000212517  
 Contact: CARLOS TUCKER  
 Telephone: 6192301370  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2260 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAL000212517  
 Contact: CARLOS TUCKER  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2260 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD059494310

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ACE MUFFLER SHOP (Continued)**

**S104749163**

TSD County: Santa Clara  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: .3000  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 119743  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2260 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000212517  
 Gas Station: Not reported  
 Inspection Date: 12/23/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS TUCKER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DUTY DUSTY&NORMA FAMILY TRUST  
 Property Address: 4655 50TH ST  
 Property City,St,Zip: 92115  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/23/05  
 Facility Phone: 619-230-1393

HMMD DISCLOSURE INVENTORY:

Item Number: AC47  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: OX46  
 Chemical Name: OXYGEN



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE MUFFLER SHOP (Continued)**

**S104749163**

Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/15/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 0009  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 04/18/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4469  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/18/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4470  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/02/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 9329  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 07/02/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9330  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/23/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ACE MUFFLER SHOP (Continued)**

**S104749163**

Item Number: 7114  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**ODACO INC  
 2255 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100725578  
 N/A**

**HAZNET:**

Gepaid: CAC000878552  
 Contact: ODACO INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: P O BOX 881628  
 Mailing City,St,Zip: SAN FRANCISCO, CA 941881628  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Transfer Station  
 Tons: .0417  
 Facility County: San Diego

Gepaid: CAC000878552  
 Contact: ODACO INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: P O BOX 881628  
 Mailing City,St,Zip: SAN FRANCISCO, CA 941881628  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .0625  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**59 FRASER INC DBA OLYMPIC BOILER & DIESEL  
 2255 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103965018  
 N/A**

HAZNET:

Gepaid: CAL000047197  
 Contact: FRASER INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: .1275  
 Facility County: San Diego

Gepaid: CAL000047197  
 Contact: FRASER INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL000047197  
 Contact: FRASER INC  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: .1500  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 PROPULSION CONTROLS ENGRG  
 2255 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104745243  
 N/A**

San Diego Co. HMMD:

Facility ID: 101205  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2255 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD981387202  
 Gas Station: Not reported  
 Inspection Date: 03/07/05  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE TABOR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/03/06  
 Facility Phone: 619-687-0035

HMMD DISCLOSURE INVENTORY:

Item Number: DI95  
 Chemical Name: DISTILLATES, HYDROTREATED HEAVY PARAFFINIC CHEVRON DELO 100 MOTOR OIL  
 Case Number: 647422525  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: OI93  
 Chemical Name: OILS, LUBRICATING CALIBRATION FLUID  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PROPULSION CONTROLS ENGRG (Continued)**

**S104745243**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OX94  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR92  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/01/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1145  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/01/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 1146  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4821  
 Violation Desc: WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PROPULSION CONTROLS ENGRG (Continued)**

**S104745243**

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4822  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 06/23/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1555  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 06/23/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 1556  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 03/07/05  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 8295  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 03/07/05  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 8296  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 03/07/05  
 Waste Item #: 121  
 Waste Code: 121  
 Waste Name: ALKALINE SOL'N WITH  
 Qnty at Inspection: 80  
 Quantity String: 80  
 Annual Qty: 160  
 Annual Qty String: 160  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: HOT TANK  
 Carcinogen: No

Inspection Date: 03/07/05  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 10  
 Quantity String: 10

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PROPULSION CONTROLS ENGRG (Continued)**

**S104745243**

Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 03/07/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 330  
 Annual Qty String: 330  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 03/07/05  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 134943  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 881628  
 Mailing City, St, Zip: SAN FRANCISCO, CA 94188  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/27/94  
 Reinspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PROPULSION CONTROLS ENGRG (Continued)**

**S104745243**

Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MARK ODA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-8050

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PROPULSION CONTROLS ENGRG (Continued)**

**S104745243**

Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**INLAND WEST SYSTEMS, INC  
 2255 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S103969955  
 N/A**

HAZNET:

Gepaid: CAD981387202  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Not reported  
 Tons: .3502  
 Facility County: San Diego

Gepaid: CAD981387202  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: 1.6301  
 Facility County: San Diego

Gepaid: CAD981387202  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: .6588  
 Facility County: San Diego

Gepaid: CAD981387202  
 Contact: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INLAND WEST SYSTEMS, INC (Continued)**

**S103969955**

Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: 2.8476  
 Facility County: San Diego

Gepaid: CAD981387202  
 Contact: DAVID P CLAPP  
 Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2255 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: San Diego  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 0.72  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

59

**B&C MARINE ENTERPRISES INC**  
**2255 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**FINDS 1000123686**  
**RCRA-NonGen CAD981980097**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-NonGen:**

Date form received by agency: 09/22/1998  
 Facility name: B&C MARINE ENTERPRISES INC  
 Facility address: 2255 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981980097  
 Contact: DAVID CLAPP  
 Contact address: 1304 SAMPSON ST P O BOX 13606  
 SAN DIEGO, CA 921700606  
 Contact country: US  
 Contact telephone: (619) 235-0961

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**B&C MARINE ENTERPRISES INC (Continued)**

**1000123686**

Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: WILLIE CORETHER  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

59

**B & C MARINE ENTERPRISE  
 2255 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106060723  
 N/A**

San Diego Co. HMMD:

Facility ID: 109287  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**B & C MARINE ENTERPRISE (Continued)**

**S106060723**

Mailing Address: 2255 W NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/23/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: AL PETTI/QA MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-276-2628

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**B & C MARINE ENTERPRISE (Continued)**

**S106060723**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**PROPULSION CONTROLS ENGINEERING  
 2255 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000151903  
 FINDS CAD981387202  
 HAZNET**

RCRA-SQG:

Date form received by agency: 09/11/1998  
 Facility name: PROPULSION CONTROLS ENGINEERING  
 Facility address: 2255 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981387202  
 Mailing address: P O BOX 13606  
 SAN DIEGO, CA 921700606  
 Contact: LINDA HERNANDEZ  
 Contact address: P O BOX 13606  
 SAN DIEGO, CA 921700606  
 Contact country: US  
 Contact telephone: (619) 235-0961  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: PROPULSION CONTROLS ENG  
 Owner/operator address: P O BOX 13606  
 SAN DIEGO, CA 92170  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 235-0961  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PROPULSION CONTROLS ENGINEERING (Continued)**

**1000151903**

Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 09/01/1996  
 Facility name: PROPULSION CONTROLS ENGINEERING  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D006  
 Waste name: CADMIUM

Waste code: D008  
 Waste name: LEAD

Waste code: D018  
 Waste name: BENZENE

Waste code: D027  
 Waste name: 1,4-DICHLOROBENZENE

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE

Waste code: D040  
 Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PROPULSION CONTROLS ENGINEERING (Continued)**

**1000151903**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAL000188745  
 Contact: MATT REILLY MANAGER  
 Telephone: 6196870035  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921700606  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.83  
 Facility County: San Diego

Gepaid: CAL000188745  
 Contact: PROPULSION CONTROLS ENGINEERIN  
 Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921700606  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: .1084  
 Facility County: San Diego

59

**R & R AUTO TECH  
 2243 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106072148  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 202208  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2243 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/04/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**R & R AUTO TECH (Continued)**

**S106072148**

Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ISABEL CAMPOS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STONECRAIG  
 Property Address: 8720 GLENWICK LN  
 Property City,St,Zip: 92037  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-8111

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**R & R AUTO TECH (Continued)**

**S106072148**

Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**DBA BALLPARK COLLISION  
 2243 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET**

**S104582829  
 N/A**

HAZNET:

Gepaid: CAL000206775  
 Contact: ROBERT VALLE/PRESIDENT  
 Telephone: 6197025887  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13135  
 Mailing City,St,Zip: SAN DIEGO, CA 921703135  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: 0.1  
 Facility County: Not reported

Gepaid: CAL000206775  
 Contact: ROBERT VALLE/PRESIDENT  
 Telephone: 6197025887  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13135  
 Mailing City,St,Zip: SAN DIEGO, CA 921703135  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.1  
 Facility County: Not reported

Gepaid: CAL000206775  
 Contact: ROBERT VALLE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13135  
 Mailing City,St,Zip: SAN DIEGO, CA 921703135  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: 0.1542  
 Facility County: San Diego

Gepaid: CAL000206775

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DBA BALLPARK COLLISION (Continued)**

**S104582829**

Contact: ROBERT VALLE/PRESIDENT  
 Telephone: 6197025887  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13135  
 Mailing City,St,Zip: SAN DIEGO, CA 921703135  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: San Diego  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.1  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

59

**RESTORE AUTO BODY  
 2243 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104756796  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 138399  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 13135  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/20/01  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ROBERT VALLE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: STONECRAIG  
 Property Address: 8720 GLENWICK LN  
 Property City,St,Zip: 92037  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-702-5887

HMMD DISCLOSURE INVENTORY:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RESTORE AUTO BODY (Continued)**

**S104756796**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 0581  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 01/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 0582  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 01/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0583  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 11/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1494  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 11/20/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 1495  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 11/20/01  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RESTORE AUTO BODY (Continued)**

**S104756796**

Type of Violation:	6HV0205
Occurrences:	Not reported
Item Number:	1496
Violation Desc:	WASTE CONTAINER: POOR CONDITION
Inspection Date:	11/20/01
Waste Code:	Not reported
Type of Violation:	6HV0207
Occurrences:	Not reported
Item Number:	1497
Violation Desc:	FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Inspection Date:	11/20/01
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	1498
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	11/20/01
Waste Code:	Not reported
Type of Violation:	6HV0402
Occurrences:	Not reported
Item Number:	1499
Violation Desc:	TRAINING PROGRAM NOT ADEQUATE
Inspection Date:	11/20/01
Waste Code:	Not reported
Type of Violation:	6HV0405
Occurrences:	Not reported
Item Number:	1500
Violation Desc:	AISLE SPACE IS OBSTRUCTED
Inspection Date:	11/20/01
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	1501
Violation Desc:	HMBP NOT ESTABLISHED/IMPLEMENTED.
Inspection Date:	11/20/01
Waste Code:	Not reported
Type of Violation:	6HV1097
Occurrences:	Not reported
Item Number:	1502
Violation Desc:	HMBP: NO EMPLOYEE TRAINING PROGRAM

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RESTORE AUTO BODY (Continued)**

**S104756796**

Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**KARVON ELECTRIC  
 2635 LOGAN AVE  
 SAN DIEGO, CA 92113**

**LUST  
 Cortese  
 SWEEPS UST**

**S102432117  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT941  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 02/26/1988  
 How Found: Tank Closure  
 Date Stopped: 02/26/1988  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Vent Soil - bore holes in soil to allow volatilization of contaminants  
 Confirm Date: 02/24/1988  
 Submit Workplan: Not reported  
 Prelim Assess: 03/22/1988  
 Desc Pollution: Not reported  
 Remed Plan: 07/26/1988  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/21/89  
 Pilot Program: LOP  
 Local Case: H05002-001  
 Basin Number: Not reported  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 03/22/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2635 LOGAN AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 5002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KARVON ELECTRIC (Continued)**

**S102432117**

Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005002-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 5002  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

59

**SAN DIEGO EXPRESS  
 2635 LOGON ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000110780  
 FINDS CAD982497216  
 LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

RCRA-SQG:

Date form received by agency: 05/14/1990  
 Facility name: SAN DIEGO EXPRESS  
 Facility address: 2635 LOGON ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982497216  
 Mailing address: P O BOX 13159  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2635 LOGON ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 231-9609  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS (Continued)**

**1000110780**

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: SAN DIEGO EXPRESS INC  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LUST:

Region: STATE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS (Continued)**

**1000110780**

Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303177  
 Stop Date: 1988-02-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1990-01-23 00:00:00  
 Discover Date: 1988-02-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-02-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: RUSS HOFFMAN  
 RP Address: 2635 LOGAN AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05002-001  
 Case Number: 9UT941  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS (Continued)**

**1000110780**

Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 105002  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 13159  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAD982497216  
 Gas Station: Not reported  
 Inspection Date: 02/03/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: TOM HAMILTON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: KARVON ELECTRIC  
 Tank Address: 2635 LOGAN AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-1292

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO EXPRESS (Continued)**

**1000110780**

Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H05002-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/23/1990  
 Begandt: 2/24/1988

59

**SAN DIEGO AUTO EXPERT  
 2602 LOGAN AV  
 SAN DIEGO, CA 92113**

**HAZNET S103982424  
 San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAL000010652  
 Contact: MORALES CARLOS  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2602 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD981402522  
 TSD County: Kern  
 Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium,

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO AUTO EXPERT (Continued)**

**S103982424**

Disposal Method: vanadium, and zinc  
 Recycler  
 Tons: .0065  
 Facility County: San Diego

**San Diego Co. HMMD:**

Facility ID: 119229  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2602 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAT000613976  
 Gas Station: Not reported  
 Inspection Date: 07/23/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS MORALES GUITRON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO SCHOOL OF ARCHITECTU  
 Property Address: 1515 9TH AVE  
 Property City,St,Zip: 92101  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-998-4714

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO AUTO EXPERT (Continued)**

**S103982424**

Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**TANAKA MEDICAL CLINIC INC  
 2204 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104757649  
 N/A**

San Diego Co. HMMD:

Facility ID: 150310  
 Inactive Indicator: Active  
 Business Code: 6HK10  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2204 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/26/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: F TANAKA MD  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TANAKA MEDICAL CLINIC INC (Continued)**

**S104757649**

Last Letter Type: Not reported  
 Property Owner: FAMILY HEALTH CENTERS OF SAN D  
 Property Address: 823 GATEWAY CENTER W  
 Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-7673

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

59 CALIFORNIA METAL FORMING  
 2183 NATIONAL AV  
 SAN DIEGO, CA 92113

LUST S104745058  
 San Diego Co. HMMD N/A  
 SAN DIEGO CO. SAM

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300247  
 Stop Date: 1989-04-21 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-12-31 00:00:00  
 Discover Date: 1989-04-21 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-04-21 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: UST PROGRAM  
 RP Address: 4950 MURPHY CANYON RD  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: CL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00629-001  
 Case Number: 9UT1408

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA METAL FORMING (Continued)**

**S104745058**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 100629  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2183 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/21/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ROGELIO MERCADO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-6360

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CALIFORNIA METAL FORMING (Continued)**

**S104745058**

2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 00001  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 00002  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 00003  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: 000004  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H00629-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/31/1996



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA METAL FORMING (Continued)**

**S104745058**

Begandt: 4/21/1989

59

**CITY OF S.D. PARKING LOT  
 2183 NATIONAL AVE  
 SAN DIEGO, CA 92191**

**LUST  
 Cortese  
 SWEEPS UST**

**S101302105  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT1408  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 04/18/1989  
 How Found: Tank Closure  
 Date Stopped: 04/18/1989  
 How Stopped: Close Tank  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 04/21/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 06/07/1989  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/31/96  
 Pilot Program: LOP  
 Local Case: H00629-001  
 Basin Number: 908.22  
 Gwater Depth: 35.5  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 06/07/1989  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2183 NATIONAL AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 629  
 Number: Not reported  
 Board Of Equalization: 44-021572  
 Ref Date: Not reported  
 Act Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CITY OF S.D. PARKING LOT (Continued)**

**S101302105**

Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000629-000001  
 Actv Date: Not reported  
 Capacity: 750  
 Tank Use: PETROLEUM  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 4

Status: Not reported  
 Comp Number: 629  
 Number: Not reported  
 Board Of Equalization: 44-021572  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000629-000002  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 629  
 Number: Not reported  
 Board Of Equalization: 44-021572  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000629-000003  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 629  
 Number: Not reported  
 Board Of Equalization: 44-021572  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000629-000004  
 Actv Date: Not reported  
 Capacity: 500

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF S.D. PARKING LOT (Continued)**

**S101302105**

Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 629  
 Number: 9  
 Board Of Equalization: 44-021572  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

59

**MIMS PLATING  
 2169-B NATIONAL AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000375448  
 FINDS CAD981987928**

RCRA-SQG:

Date form received by agency: 03/24/1987  
 Facility name: MIMS PLATING  
 Facility address: 2169-B NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981987928  
 Mailing address: 150 E RIENSTRA ST  
 CHULA VISTA, CA 92011  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2169-B NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 422-0294  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: MIMS MITCHELL  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIMS PLATING (Continued)**

**1000375448**

Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

59

**PORT MEDICAL SERVICE,S.D.  
 2169 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748601  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 116482  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2169 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT MEDICAL SERVICE,S.D. (Continued)**

**S104748601**

Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/05/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: IRWIN FISHMAN,M.D.  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: EVERS DANIEL E  
 Property Address: 2169 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-9148

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT MEDICAL SERVICE,S.D. (Continued)**

**S104748601**

Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**2156 NATIONAL AV  
 SAN DIEGO, CA**

**CHMIRS S105887679  
 N/A**

**CHMIRS:**

OES Incident Number: 02-7020  
 OES notification: 12/25/200207:35:50 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities:Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: No  
 Waterway: Not reported  
 Spill Site: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105887679

Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	City of San Diego
Incident Date:	12/25/2002 12:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Yes
Site Type:	Residence
E Date:	Not reported
Substance:	sewage
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	1290
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Per caller, a sewer main break caused the release. No water way involved.

59 **TREJO TOWING**  
**2250 LOGAN AV**  
**SAN DIEGO, CA 92113**

San Diego Co. HMMD S106064235  
 N/A

San Diego Co. HMMD:

Facility ID:	134456
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2250 1/2 LOGAN AV
Mailing City, St, Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	08/09/95
Reinspection Date:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TREJO TOWING (Continued)**

**S106064235**

Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RAFAEL TREJO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TREJO ALICIA R TRUST 04-01-98  
 Property Address: P O BOX 2854  
 Property City,St,Zip: 91912  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-4906

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TREJO TOWING (Continued)**

**S106064235**

Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**RC AUTO ELECTRIC  
 2250 LOGAN AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S106061123  
 N/A**

San Diego Co. HMMD:

Facility ID: 113765  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2250 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000038845  
 Gas Station: Not reported  
 Inspection Date: 07/05/02  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: RIGOBERTO CAMPOS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TREJO ALICIA R TRUST 04-01-98  
 Property Address: P O BOX 2854  
 Property City,St,Zip: 91912  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-8111

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**RC AUTO ELECTRIC (Continued)**

**S106061123**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/18/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 0715  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 01/18/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0716  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/18/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 0717  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 10/17/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 9313  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 10/17/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9314  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 3605  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3606  
 Violation Desc: WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RC AUTO ELECTRIC (Continued)**

**S106061123**

Inspection Date: 03/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 3607  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 03/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3608  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/05/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 9416  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 07/05/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9417  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 204116  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2250 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92106  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RC AUTO ELECTRIC (Continued)**

**S106061123**

Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/23/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MAX CORONA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TREJO ALICIA R TRUST 04-01-98  
 Property Address: P O BOX 2854  
 Property City,St,Zip: 91912  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/23/06  
 Facility Phone: 619-233-4341

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/23/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 3732  
 Violation Desc: UPFP NOT OBTAINED for HAZWASTE

Inspection Date: 09/23/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 3733  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**RC AUTO ELECTRIC (Continued)**

**S106061123**

Inspection Date: 09/23/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 3734  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/23/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5091  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

**HMMD WASTE STREAMS:**

Inspection Date: 09/23/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 550  
 Quantity String: 550  
 Annual Qty: 300  
 Annual Qty String: 300  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 09/23/04  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: ANTIFREEZE  
 Carcinogen: No

Inspection Date: 09/23/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**RC AUTO ELECTRIC (Continued)**

**S106061123**

Waste Desc: Not reported  
 Carcinogen: No

**59 R & C AUTO ELECTRIC  
 2250 LOGAN AVE  
 SAN DIEGO, CA 92113**

**HAZNET S104575361  
 N/A**

HAZNET:  
 Gepaid: CAL000005874  
 Contact: RODRIGUEZ OLEGARIO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2250 LOGAN AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD009466392  
 TSD County: 7  
 Waste Category: Other empty containers 30 gallons or more  
 Disposal Method: Recycler  
 Tons: 3  
 Facility County: San Diego

**59 PORKYLAND  
 2196 LOGAN AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104750420  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 123524  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2196 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/16/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ENRIQUE ZAGURSKY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BRODYS PARTNERSHIP  
 Property Address: 2196 LOGAN AVE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORKYLAND (Continued)**

**S104750420**

Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-5139

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 AZTEC STEEL FABRICATORS  
 2183 LOGAN AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104754297  
 N/A**

San Diego Co. HMMD:

Facility ID: 134247  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2183 LOGAN AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/17/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JUAN RANGEL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CARRILLO MIRNA  
 Property Address: 2183 LOGAN AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-702-8083

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AZTEC STEEL FABRICATORS (Continued)**

**S104754297**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**MAGANA AUTOMATIC TRANSMISSIONS  
 2134 NATIONAL AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104755801  
 N/A**

San Diego Co. HMMD:

Facility ID: 136831  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2134 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000257054  
 Gas Station: Not reported  
 Inspection Date: 10/24/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: ERNESTO MAGANA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SEDLACK DEVELOPMENT CO LP  
 Property Address: 4760 FEDERAL BLVD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAGANA AUTOMATIC TRANSMISSIONS (Continued)**

**S104755801**

Property City,St,Zip: 92102  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/24/05  
 Facility Phone: 619-238-4117

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 05/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 3866  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 05/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3867  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 05/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3868  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3869  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 07/19/99

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAGANA AUTOMATIC TRANSMISSIONS (Continued)**

**S104755801**

Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 6464  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/29/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 6215  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 03/29/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 6216  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/29/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6217  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 10/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5658  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

**HMMD WASTE STREAMS:**

Inspection Date: 10/24/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 8  
 Quantity String: 8  
 Annual Qty: 16  
 Annual Qty String: 16  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 2986 INDUSTRIAL SOLVENT &  
 Waste Desc: TO OIL 5/98 ER  
 Carcinogen: No

Inspection Date: 10/24/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 180  
 Quantity String: 180  
 Annual Qty: 110

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAGANA AUTOMATIC TRANSMISSIONS (Continued)**

**S104755801**

Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: TO IMS  
 Carcinogen: No

Inspection Date: 10/24/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 40  
 Quantity String: 40  
 Annual Qty: 80  
 Annual Qty String: 80  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: Not reported  
 Carcinogen: No

59

**DIEGO AND SONS PRINTING INC  
 2104 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S100860403  
 N/A**

HAZNET:

Gepaid: CAR000079376  
 Contact: ISABEL AGUILERA  
 Telephone: 6192335373  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2104 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.52  
 Facility County: Not reported

Gepaid: CAR000079376  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2104 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: 0  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: .2877  
 Facility County: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**59 DIEGO AND SON PRINTING  
 2104 NATIONAL AV  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104754923  
 N/A**

San Diego Co. HMMD:

Facility ID: 135275  
 Inactive Indicator: Active  
 Business Code: 6HK37  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 13100  
 Mailing City, St, Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAR000079376  
 Gas Station: Not reported  
 Inspection Date: 02/28/05  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: ISABEL AGUILERA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DIA PROPERTIES L L C  
 Property Address: C/O DIEGO | SONS PRI  
 Property City, St, Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/28/06  
 Facility Phone: 619-233-5373

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIEGO AND SON PRINTING (Continued)**

**S104754923**

**HMMD VIOLATIONS:**

Inspection Date: 08/21/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 0970  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

Inspection Date: 08/21/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 0971  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 02/28/05  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 8190  
 Violation Desc: HMBP: INADEQUATE SITE MAP

**HMMD WASTE STREAMS:**

Inspection Date: 02/28/05  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 330  
 Annual Qty String: 330  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: WASTE INKS/SOLVENT  
 Carcinogen: No

Inspection Date: 02/28/05  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 34  
 Quantity String: 34  
 Annual Qty: 136  
 Annual Qty String: 136  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: SAFETY KLEEN UNIT  
 Carcinogen: No

Facility ID: 201884  
 Inactive Indicator: Active

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIEGO AND SON PRINTING (Continued)**

**S104754923**

Business Code: 6HK37  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P.O.BOX 13100  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DIA PROPERTIES L L C  
 Property Address: C/O DIEGO | SONS PRI  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-5373

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIEGO AND SON PRINTING (Continued)**

**S104754923**

Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

59

**DIEGO AND SON PRINTING INC  
 2104 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1004675972  
 FINDS CAR000079376  
 HAZNET**

**RCRA-SQG:**

Date form received by agency: 07/31/2000  
 Facility name: DIEGO AND SON PRINTING INC  
 Facility address: 2104 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000079376  
 Contact: ISABEL AGUILERA  
 Contact address: 2104 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 233-5373  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: DIEGO AGUILERA  
 Owner/operator address: 2104 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 233-5373  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIEGO AND SON PRINTING INC (Continued)**

**1004675972**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000079376  
 Contact: ISABEL AGUILERA  
 Telephone: 6192335373  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13100  
 Mailing City,St,Zip: SAN DIEGO, CA 921703100  
 Gen County: San Diego  
 TSD EPA ID: KYD053348108  
 TSD County: 99  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: 0.23  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DIEGO AND SON PRINTING INC (Continued)**

**1004675972**

Gepaid: CAR000079376  
 Contact: ISABEL AGUILERA  
 Telephone: 6192335373  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13100  
 Mailing City,St,Zip: SAN DIEGO, CA 921703100  
 Gen County: San Diego  
 TSD EPA ID: TXD077603371  
 TSD County: 99  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: H06  
 Tons: 0.22  
 Facility County: San Diego

Gepaid: CAL000063922  
 Contact: ISABEL NICHOLAS &  
 Telephone: 6192335373  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13100  
 Mailing City,St,Zip: SAN DIEGO, CA 921703100  
 Gen County: San Diego  
 TSD EPA ID: TND991279480  
 TSD County: 99  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Not reported  
 Tons: .9172  
 Facility County: San Diego

Gepaid: CAL000063922  
 Contact: ISABEL NICHOLAS &  
 Telephone: 6192335373  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13100  
 Mailing City,St,Zip: SAN DIEGO, CA 921703100  
 Gen County: San Diego  
 TSD EPA ID: TND991279480  
 TSD County: 99  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Not reported  
 Tons: .0000  
 Facility County: San Diego

Gepaid: CAL000063922  
 Contact: ISABEL NICHOLAS &  
 Telephone: 6192335373  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13100  
 Mailing City,St,Zip: SAN DIEGO, CA 921703100  
 Gen County: San Diego  
 TSD EPA ID: TND991279480  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIEGO AND SON PRINTING INC (Continued)**

**1004675972**

Tons: .1500  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 2 additional CA\_HAZNET: record(s) in the EDR Site Report.

59

**CHMIRS S108401235  
 N/A**

**2171 LOGAN AV  
 SAN DIEGO, CA**

CHMIRS:

OES Incident Number: 05-0468  
 OES notification: 1/18/200502:01:05 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S108401235

Year: 2005  
 Agency: City of San Diego  
 Incident Date: 1/18/2005 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Residence  
 E Date: Not reported  
 Substance: Sewage  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 208  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: Per caller, a blockage on a private lateral caused the release.

59

2159 LOGAN AVE.  
 SAN DIEGO, CA 91415

CHMIRS S105671725  
 N/A

CHMIRS:  
 OES Incident Number: 01-5525  
 OES notification: 9/29/2001 07:11:30 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personnel # Of Decontaminated: Not reported  
 Responding Agency Personnel # Of Injuries: Not reported  
 Responding Agency Personnel # Of Fatalities: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105671725

Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2001
Agency:	San Diego
Incident Date:	9/29/2001 12:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Yes
Site Type:	Residence
E Date:	Not reported
Substance:	Sewage
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	100
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0.000000
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A blockage in sewer line caused spill. The total amount of the spill was recovered.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

59

CHMIRS S108404787  
 N/A

**2154 LOGAN AVENUE  
 SAN DIEGO, CA**

CHMIRS:

OES Incident Number: 05-4941  
 OES notification: 8/23/200508:45:59 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2005  
 Agency: City of San Diego  
 Incident Date: 8/23/200512:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Merchant/Business

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**(Continued)**

**S108404787**

E Date:	Not reported
Substance:	Sewage
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	30
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Private lateral was plugged causing sewage to spill.

**60**

**LAURA G. RODRIGUEZ ELEMENTARY SCHOOL  
 32ND STREET/GREELY AVENUE  
 SAN DIEGO, CA 92113**

**SCH S105954576  
 ENVIROSTOR N/A**

SCH:

Facility ID:	37880011
Site Type:	School Cleanup
Site Type Detail:	School
Acres:	6.5
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Mitigation And Brownfield Reuse Program
Project Manager:	STEPHANIE LEWIS
Supervisor:	Javier Hinojosa
Division Branch:	School Evaluation - Glendale / Sacramento
Site Code:	404376-11
Assembly:	79
Senate:	40
Special Program Status:	Not reported
Status:	Active
Status Date:	2002-08-06 00:00:00
Restricted Use:	NO
Funding:	School District
Latitude:	32.69809
Longitude:	-117.12728
Alias Name:	KING/LOGAN/PERKINS PREFERRED SCHOOL 37880011 LAURA G. RODRIGUEZ ELEMENTARY SCHOOL 545-662-58 545-661-34 545-661-35 545-661-36 545-661-37 545-661-38

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)

S105954576

545-661-39  
545-662-50  
545-662-52  
545-662-54  
545-662-56  
SAN DIEGO USD-LAURA G RODRIGUEZ ELEM SCL  
404376-11  
545-661-31  
545-661-32  
545-661-33  
545-661-40  
545-661-41  
545-661-42  
545-661-43  
545-661-44  
545-661-45  
SAN DIEGO UNIFIED SCHOOL DISTRICT  
Alternate Name  
Alternate Name  
Alternate Name  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
Project Code (Site Code)  
APN  
Alternate Name  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
Envirostor ID Number

Alias Type:

APN: 545-662-58, 545-661-34, 545-661-35, 545-661-36, 545-661-37,  
545-661-38, 545-661-39, 545-662-50, 545-662-52, 545-662-54,  
545-662-56, 545-661-31 , 545-661-32, 545-661-33, 545-661-40,  
545-661-41, 545-661-42, 545-661-43, 545-661-44, 545-661-45  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)**

**S105954576**

APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 APN Description: Not reported  
 Comments: The comments on the additional investigation were addressed as part of the Removal Action Completion Report.SSI WP for residual area approved.Approved.Conditional approval with minor comments.Tech Memo Approved as SSI Work Plan for Additional Sampling Required to Delineate Residual Contamination Area.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Report  
 Completed Date: 01/12/07

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Endangerment Assessment Report  
 Completed Date: 02/26/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Workplan  
 Completed Date: 10/27/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Workplan  
 Completed Date: 03/14/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Report  
 Completed Date: 07/09/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Report  
 Completed Date: 07/13/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Completion Report  
 Completed Date: 07/13/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Technical Memorandums  
 Completed Date: 05/07/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)**

**S105954576**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Workplan  
 Completed Date: 08/31/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Workplan  
 Completed Date: 02/23/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Completion Report  
 Completed Date: 11/29/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: 4.15 Request  
 Completed Date: 07/27/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: CEQA - Notice of Exemption  
 Completed Date: 10/27/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 09/17/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 10/01/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 04/29/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 12/29/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 03/12/04

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 06/05/04

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)**

**S105954576**

Completed Document Type: Site Inspections/ Visit  
 Completed Date: 11/10/04

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 03/11/05

Confirmed: 30001,30013  
 Confirmed Description: Arsenic  
 Confirmed Description: Lead  
 Future Area Name: PROJECT WIDE  
 Future Sub Area Name: Not reported  
 Future Document Type: Certification  
 Future Due Date: 2007  
 Media Affected: SOIL  
 Media Affected Desc: Soil

**Management:**

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30001, 30013  
 Potential Description: Arsenic  
 Potential Description: Lead  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA, SCHOOL - ELEMENTARY

**ENVIROSTOR:**

Site Type: School Cleanup  
 Site Type Detailed: School  
 Acres: 6.5  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP  
 Program Manager: STEPHANIE LEWIS  
 Supervisor: Javier Hinojosa  
 Division Branch: School Evaluation - Glendale / Sacramento  
 Facility ID: 37880011  
 Site Code: 404376-11  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Active  
 Status Date: 2002-08-06 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.69809  
 Longitude: -117.12728  
 Alias Name: KING/LOGAN/PERKINS PREFERRED SCHOOL  
 37880011  
 LAURA G. RODRIGUEZ ELEMENTARY SCHOOL  
 545-662-58  
 545-661-34

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)

S105954576

545-661-35  
545-661-36  
545-661-37  
545-661-38  
545-661-39  
545-662-50  
545-662-52  
545-662-54  
545-662-56  
SAN DIEGO USD-LAURA G RODRIGUEZ ELEM SCL  
404376-11  
545-661-31  
545-661-32  
545-661-33  
545-661-40  
545-661-41  
545-661-42  
545-661-43  
545-661-44  
545-661-45

Alias Type:

SAN DIEGO UNIFIED SCHOOL DISTRICT  
Alternate Name  
Alternate Name  
Alternate Name  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
Project Code (Site Code)  
APN  
Alternate Name  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
APN  
Envirostor ID Number

APN: 545-662-58, 545-661-34, 545-661-35, 545-661-36, 545-661-37, 545-661-38, 545-661-39, 545-662-50, 545-662-52, 545-662-54, 545-662-56, 545-661-31, 545-661-32, 545-661-33, 545-661-40, 545-661-41, 545-661-42, 545-661-43, 545-661-44, 545-661-45

APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)

S105954576

APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported  
APN Description: Not reported

Comments: The comments on the additional investigation were addressed as part of the Removal Action Completion Report.SSI WP for residual area approved.Approved.Conditional approval with minor comments.Tech Memo Approved as SSI Work Plan for Additional Sampling Required to Delineate Residual Contamination Area.

Completed Info:

Completed Area Name: PROJECT WIDE  
Completed Sub Area Name: Not reported  
Completed Document Type: Supplemental Site Investigation Report  
Completed Date: 01/12/07

Completed Area Name: PROJECT WIDE  
Completed Sub Area Name: Not reported  
Completed Document Type: Preliminary Endangerment Assessment Report  
Completed Date: 02/26/03

Completed Area Name: PROJECT WIDE  
Completed Sub Area Name: Not reported  
Completed Document Type: Removal Action Workplan  
Completed Date: 10/27/03

Completed Area Name: PROJECT WIDE  
Completed Sub Area Name: Not reported  
Completed Document Type: Supplemental Site Investigation Workplan  
Completed Date: 03/14/03

Completed Area Name: PROJECT WIDE  
Completed Sub Area Name: Not reported  
Completed Document Type: Supplemental Site Investigation Report  
Completed Date: 07/09/03

Completed Area Name: PROJECT WIDE  
Completed Sub Area Name: Not reported  
Completed Document Type: Supplemental Site Investigation Report  
Completed Date: 07/13/05

Completed Area Name: PROJECT WIDE  
Completed Sub Area Name: Not reported  
Completed Document Type: Removal Action Completion Report  
Completed Date: 07/13/05

Completed Area Name: PROJECT WIDE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)**

**S105954576**

Completed Sub Area Name: Not reported  
 Completed Document Type: Technical Memorandums  
 Completed Date: 05/07/04

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Workplan  
 Completed Date: 08/31/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Supplemental Site Investigation Workplan  
 Completed Date: 02/23/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Removal Action Completion Report  
 Completed Date: 11/29/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: 4.15 Request  
 Completed Date: 07/27/06

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: CEQA - Notice of Exemption  
 Completed Date: 10/27/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 09/17/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 10/01/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: \* Public Participation  
 Completed Date: 04/29/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 12/29/03

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 03/12/04

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LAURA G. RODRIGUEZ ELEMENTARY SCHOOL (Continued)**

**S105954576**

Completed Date: 06/05/04

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 11/10/04

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Inspections/ Visit  
 Completed Date: 03/11/05

Confirmed: 30001,30013  
 Confirmed Description: Arsenic  
 Confirmed Description: Lead  
 Future Area Name: PROJECT WIDE  
 Future Sub Area Name: Not reported  
 Future Document Type: Certification  
 Future Due Date: 2007  
 Media Affected: SOIL  
 Media Affected Desc: Soil

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30001, 30013  
 Potential Description: Arsenic  
 Potential Description: Lead  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA, SCHOOL - ELEMENTARY

61

**CROWLEY MARINE SERVICE INC**  
**1843 WATER ST**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1004676697**  
**FINDS CAR000088344**  
**HAZNET**

RCRA-SQG:  
 Date form received by agency: 12/13/2000  
 Facility name: CROWLEY MARINE SERVICE INC  
 Facility address: 1843 WATER ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000088344  
 Contact: DAMON MOTE  
 Contact address: BERTH 86  
 SAN PEDRO, CA 90731  
 Contact country: US  
 Contact telephone: (310) 732-6523  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CROWLEY MARINE SERVICE INC (Continued)**

**1004676697**

Owner/Operator Summary:

Owner/operator name: PORT OF SAN DIEGO  
 Owner/operator address: 3165 PACIFIC HWY  
 SAN DIEGO, CA 92101  
 Owner/operator country: Not reported  
 Owner/operator telephone: (800) 854-2757  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAR000088344  
 Contact: --  
 Telephone: 3107326523



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CROWLEY MARINE SERVICE INC (Continued)**

**1004676697**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1843 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: H06  
 Tons: 0.1  
 Facility County: San Diego

Gepaid: CAR000088344  
 Contact: --  
 Telephone: 3107326523  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1843 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 10.50  
 Facility County: Not reported

Gepaid: CAR000088344  
 Contact: Not reported  
 Telephone: 3107326523  
 Facility Addr2: Not reported  
 Mailing Name: DAMON MOTE  
 Mailing Address: 1843 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: San Diego  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 8.34  
 Facility County: San Diego

Gepaid: CAR000088344  
 Contact: Not reported  
 Telephone: 3107326523  
 Facility Addr2: Not reported  
 Mailing Name: DAMON MOTE  
 Mailing Address: 1843 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Treatment, Tank  
 Tons: 15.42  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CROWLEY MARINE SERVICE INC (Continued)**

**1004676697**

Gepaid: CAR000088344  
 Contact: --  
 Telephone: 3107326523  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1843 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: 7.5  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

61

**NRC ENVIRONMENTAL SVCS INC  
 1839 WATER ST  
 SAN DIEGO, CA 92113**

**HAZNET 1007370134  
 RCRA-NonGen CAR000153064**

HAZNET:

Gepaid: CAR000153064  
 Contact: ART COWBURN  
 Telephone: 6192353324  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3500 ESTUDILLO STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921100000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: 0.08  
 Facility County: Not reported

Gepaid: CAR000153064  
 Contact: ART COWBURN  
 Telephone: 6192353324  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3500 ESTUDILLO STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921100000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: 0.08  
 Facility County: Not reported

RCRA-NonGen:

Date form received by agency: 04/30/2003  
 Facility name: NRC ENVIRONMENTAL SVCS INC  
 Facility address: 1839 WATER ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NRC ENVIRONMENTAL SVCS INC (Continued)**

**1007370134**

EPA ID: SAN DIEGO, CA 92113  
 CAR000153064  
 Mailing address: 3500 ESTUDILLO STREET  
 SAN DIEGO, CA 92110  
 Contact: SHELLEY SCALZO  
 Contact address: 3500 ESTUDILLO STREET  
 SAN DIEGO, CA 92110  
 Contact country: US  
 Contact telephone: 619-235-3324  
 Contact email: SRSCALZO@NRCES.COM  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: NRC ENV SVCS INC  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/2003  
 Owner/Op end date: Not reported

Owner/operator name: PORT OF SAN DIEGO  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1950  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NRC ENVIRONMENTAL SVCS INC (Continued)**

**1007370134**

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

61

**FREIGHT HANDLERS INC  
 1790 WATER ST  
 SAN DIEGO, CA 92101**

**LUST S104750828  
 San Diego Co. HMMD N/A  
 SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608125302  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-12-01 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: RALPH HICKS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FREIGHT HANDLERS INC (Continued)**

**S104750828**

RP Address: P O BOX 488  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H25935-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608195545  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1995-02-07 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FREIGHT HANDLERS INC (Continued)**

**S104750828**

County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: RALGH HICKS  
 RP Address: PORT OF S.D P.O. BOX 488  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H25935-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 125935  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1790 WATER ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FREIGHT HANDLERS INC (Continued)**

**S104750828**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FREIGHT HANDLERS INC (Continued)**

**S104750828**

SAN DIEGO CO. SAM:

Case Number: H25935-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/7/1995  
 Begandt: 7/17/1995

Case Number: H25935-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Complaint  
 FStatus: Closed Case  
 Date: 12/1/1996  
 Begandt: Not reported

61

**FORMER PACIFIC MOLASSES SITE  
 1750 WATER ST  
 SAN DIEGO, CA 92101**

**San Diego Co. HMMD  
 SWEEPS UST**

**S104748486  
 N/A**

San Diego Co. HMMD:

Facility ID: 115697  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3165 N PACIFIC H  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 02/09/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE TILLEY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-291-3900



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FORMER PACIFIC MOLASSES SITE (Continued)**

**S104748486**

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	T001
Tank ID Number:	001
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qnty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No

**SWEEPS UST:**

Status:	Not reported
Comp Number:	15697
Number:	Not reported
Board Of Equalization:	44-022924
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-015697-000001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FORMER PACIFIC MOLASSES SITE (Continued)**

**S104748486**

Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: UNKNOWN  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 1

**61 PACIFIC MOLASSES COMPANY  
 1750 WATER ST  
 SAN DIEGO, CA 92101**

**HIST UST U001572592  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000011537  
 Facility Type: Other  
 Other Type: Not reported  
 Total Tanks: 0001  
 Contact Name: LEROY MOOS  
 Telephone: 6192322991  
 Owner Name: PACIFIC MOLASSES COMPANY  
 Owner Address: 333 MARKET STREET  
 Owner City,St,Zip: SAN FRANCISCO, CA 94105

Tank Num: 001  
 Container Num: FG-1  
 Year Installed: 1962  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: 1/4 inches  
 Leak Detection: Stock Inventor

**62 S D UNIFIED SCHOOL DISTRICT  
 3550 LOGAN AV  
 SAN DIEGO, CA 92113**

**LUST S104753042  
 Cortese N/A  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300946  
 Stop Date: 1992-01-03 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S D UNIFIED SCHOOL DISTRICT (Continued)**

**S104753042**

Close Date: 1992-05-26 00:00:00  
 Discover Date: 1992-01-03 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-01-03 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 9  
 Contact Person: Not reported  
 Responsible Party: TONY RASSO  
 RP Address: 4100 NORMAL ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H32216-001  
 Case Number: 9UT2176  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: Not reported

**San Diego Co. HMMD:**

Facility ID: 132216  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S D UNIFIED SCHOOL DISTRICT (Continued)**

**S104753042**

Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 4100 NORMAL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92103  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 35  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: RALPH WARREN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO UNIFIED SCHOOL DISTR  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-6592

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT2394  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: AT2502  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S D UNIFIED SCHOOL DISTRICT (Continued)**

**S104753042**

Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H32216-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - For Non-LOP Tank**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/26/1992  
 Begandt: 1/3/1992

62

**BANDINI UNIOR HIGH SCHOOL  
 3550 LOGAN AVE  
 SAN DIEGO, CA 92113**

**LUST S102424912  
 SWEEPS UST N/A**

**LUST:**

Region: 9  
 Case Number: 9UT2176  
 Local Agency: San Diego  
 Substance: Boiler Fuel  
 Qty Leaked: 250  
 Date Found: 01/03/1992  
 How Found: Other Means  
 Date Stopped: 01/03/1992  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Cap Site - install horizontal impermeable layer to reduce rainfall infiltration  
 Confirm Date: 01/03/1992  
 Submit Workplan: 2/3/92  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BANDINI UNIOR HIGH SCHOOL (Continued)**

**S102424912**

Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/20/92  
 Pilot Program: LOP  
 Local Case: H32216-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 01/03/1992  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 32216  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-032216-000001  
 Actv Date: Not reported  
 Capacity: 280  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 32216  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-032216-000002  
 Actv Date: Not reported  
 Capacity: 1500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 32216  
 Number: 9  
 Board Of Equalization: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BANDINI UNIOR HIGH SCHOOL (Continued)**

**S102424912**

Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**63 LIQUID CARBONIC INDUSTRIES CORP  
 2205 NEWTON AVE  
 SAN DIEGO, CA 92113**

**TSCA 1005930069  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional TSCA detail in the EDR Site Report.

**63 AMERIGAS  
 2205 NEWTON AVE  
 SAN DIEGO, CA 92113**

**TSCA 1005925847  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional TSCA detail in the EDR Site Report.

**63 PRAXAIR DISTRIBUTION INC.  
 2205 NEWTON AV  
 SAN DIEGO, CA 92113**

**LUST S104745534  
 San Diego Co. HMMD N/A**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Other Cause  
 Leak Source: Tank  
 Global Id: T0619734913  
 Stop Date: 2007-03-03 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: 2007-12-14 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRAXAIR DISTRIBUTION INC. (Continued)**

**S104745534**

Close Date: Not reported  
 Discover Date: 2007-03-03 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2007-03-28 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Post remedial action monitoring  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: O'Neal Summers  
 RP Address: 2205 Newton Ave  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: 102702-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 102702  
 Inactive Indicator: Active  
 Business Code: 6HK79  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2205 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRAXAIR DISTRIBUTION INC. (Continued)**

**S104745534**

Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD000517777  
 Gas Station: Not reported  
 Inspection Date: 10/13/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: BRIAN HUTCHERS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PRAXAIR DISTRIBUTION INC  
 Property Address: C/O TAX DEPT  
 Property City,St,Zip: 50302  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/13/05  
 Facility Phone: 619-232-7341

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC48  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR56  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AR64  
 Chemical Name: ARGON/CO2  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PRAXAIR DISTRIBUTION INC. (Continued)**

**S104745534**

Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CA55  
 Chemical Name: CARBON DIOXIDE  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: DE57  
 Chemical Name: DEUTERIUM  
 Case Number: 7782-39-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: ET58  
 Chemical Name: ETHYLENE OXIDE 8.5% CO2 91.5%  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: HE49  
 Chemical Name: HELIUM  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: HE65  
 Chemical Name: HELIUM/ARGON  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRAXAIR DISTRIBUTION INC. (Continued)**

**S104745534**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: HY52  
 Chemical Name: HYDROGEN  
 Case Number: 133-74-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: HY63  
 Chemical Name: HYDROGEN/ARGON  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: HY62  
 Chemical Name: HYDROGEN/HELIUM  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: HY61  
 Chemical Name: HYDROGEN/NITROGEN  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: ME60  
 Chemical Name: METHANE (300/250 CFT)

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PRAXAIR DISTRIBUTION INC. (Continued)**

**S104745534**

Case Number:	74-82-8
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	PRESSURE R
Item Number:	NI54
Chemical Name:	NITRIGEN, LIQUID
Case Number:	7727-37-9
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	PRESSURE RELEASE
2nd Hazard Category:	Not reported
Item Number:	NI51
Chemical Name:	NITROUS OXIDE
Case Number:	10024-97-2
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	PRESSURE R
Item Number:	OX50
Chemical Name:	OXYGEN, LIQUID
Case Number:	7782-44-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	PRESSURE R
Item Number:	PR53
Chemical Name:	PROPANE
Case Number:	74-98-6
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	PRESSURE R

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRAXAIR DISTRIBUTION INC. (Continued)**

**S104745534**

Item Number: SU59  
 Chemical Name: SULFUR HEXAFLUORIDE  
 Case Number: 2551-62-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/20/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 9663  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 5144  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

**HMMD WASTE STREAMS:**

Inspection Date: 10/13/03  
 Waste Item #: 113  
 Waste Code: 113  
 Waste Name: UNSPECIFIED ACID SOL  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 1  
 Annual Qty String: 1  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: BATTERY ACID  
 Carcinogen: No

Inspection Date: 10/13/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 30

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRAXAIR DISTRIBUTION INC. (Continued)**

**S104745534**

Annual Qty String: 30  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: CMPRSR OIL BRGHT TO PEPBY  
 Carcinogen: No

63

**PRAXAIR  
 2205 NEWTON AVE  
 SAN DIEGO, CA 92113**

**HAZNET S108217178  
 N/A**

HAZNET:

Gepaid: CAC002594532  
 Contact: BRIAN HUTCHENS  
 Telephone: 6192327342  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2205 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

63

**PRAXAIR  
 2205 NEWTON AV  
 SAN DIEGO, CA 92113**

**SAN DIEGO CO. SAM S108540442  
 N/A**

SAN DIEGO CO. SAM:

Case Number: 102702-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: OX  
 FStatus: Preliminary Assessment  
 Date: 4/2/2007  
 Begandt: 3/3/2007

63

**PRAXAIR, INC.  
 2205 NEWTON AVENU  
 SAN DIEGO, CA 92113**

**TSCA 1005931665  
 N/A**

Click this hyperlink while viewing on your computer to access additional TSCA detail in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

63

CHMIRS S100223114  
 N/A

2186 NEWTON ST  
 SAN DIEGO, CA 92113

CHMIRS:

OES Incident Number: 9992021  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 04-FEB-88  
**Date Completed: 04-FEB-88**  
 Property Use: 099  
 Agency Id Number: 37140  
 Agency Incident Number: 039401  
 Time Notified: 1502  
 Time Completed: 1730  
 Surrounding Area: 936  
 Estimated Temperature: 70  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: C R BLACK  
 Report Date: 04-FEB-88  
 Comments: Y  
 Facility Telephone: 619 236-7773  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 88-92  
 Agency: Not reported  
 Incident Date: Not reported  
 Admin Agency: Not reported  
 Amount: Not reported  
 Contained: Not reported  
 Site Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100223114

E Date:	Not reported
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

63

**CITY OF SAN DIEGO  
 2184 NEWTON AV  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

S104750597  
 N/A

San Diego Co. HMMD:

Facility ID:	124761
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1222 01ST AV
Mailing City,St,Zip:	SAN DIEGO, CA 92101
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	Not reported
Reinspection Date:	Not reported
Inspector Name:	Not reported
Violation Notice Issued:	Not reported
Facility Contact:	PAUL GALLARDO
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	CITY OF SAN DIEGO
Property Address:	PUBLIC AGENCY
Property City,St,Zip:	00000
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CITY OF SAN DIEGO (Continued)**

**S104750597**

Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT1066-1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**63 CITY OF SAN DIEGO  
 2184 NEWTON AVE  
 SAN DIEGO, CA 92113**

**SWEEPS UST S106924642  
 N/A**

SWEEPS UST:

Status: Not reported  
 Comp Number: 24761  
 Number: Not reported  
 Board Of Equalization: 44-021803  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-024761-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 1

Status: A  
 Comp Number: 24761  
 Number: 9  
 Board Of Equalization: 44-021803  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**63 CARLSON AND BEAULOYE  
 2141 NEWTON AVE  
 SAN DIEGO, CA 92113**

**LUST S102426355  
 Cortese N/A  
 SWEEPS UST**

LUST:

Region: 9  
 Case Number: 9UT1576  
 Local Agency: San Diego  
 Substance: Chromic Acid  
 Qty Leaked: Not reported  
 Date Found: 11/01/1989  
 How Found: Tank Closure  
 Date Stopped: 11/01/1989  
 How Stopped: Close Tank  
 Source: Other Source  
 Cause: Overfill  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CARLSON AND BEAULOYE (Continued)**

**S102426355**

Confirm Date: 11/20/1989  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/9/92  
 Pilot Program: LOP  
 Local Case: H08980-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Disp: File discarded, case closed  
 Release Date: 11/20/1989  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2141 NEWTON AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 8980  
 Number: Not reported  
 Board Of Equalization: 44-022424  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-008980-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 8980  
 Number: Not reported  
 Board Of Equalization: 44-022424  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-008980-000002  
 Actv Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON AND BEAULOYE (Continued)**

**S102426355**

Capacity: 1000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 8980  
 Number: 9  
 Board Of Equalization: 44-022424  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-008980-000003  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: 2

Status: A  
 Comp Number: 8980  
 Number: 9  
 Board Of Equalization: 44-022424  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-008980-000004  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

63

**CARLSON & BEAULOYE MACHINE SHOP**  
**2141 NEWTON AVE**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000292448**  
**FINDS CAD008232860**  
**HAZNET**  
**LUST**  
**San Diego Co. HMMD**  
**AIRS**  
**SAN DIEGO CO. SAM**

RCRA-SQG:  
 Date form received by agency: 09/01/1996  
 Facility name: CARLSON & BEAULOYE MACHINE SHOP  
 Facility address: 2141 NEWTON AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD008232860  
 Contact: Not reported  
 Contact address: Not reported  
 Contact country: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: RONALD A BEAULOYE SR  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 01/16/1981  
 Facility name: CARLSON & BEAULOYE MACHINE SHOP  
 Classification: Large Quantity Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Facility Has Received Notices of Violations:

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 03/18/1994  
 Date achieved compliance: 03/18/1999  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 01/25/1993  
 Date achieved compliance: 03/18/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/16/1991  
 Date achieved compliance: 01/25/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 03/18/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 03/18/1999  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 01/25/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 03/18/1994  
 Evaluation lead agency: State Contractor/Grantee

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Evaluation date: 09/16/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 01/25/1993  
 Evaluation lead agency: State Contractor/Grantee

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD008232860  
 Contact: HJ BEAULOYE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2141 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .6750  
 Facility County: San Diego

Gepaid: CAD008232860  
 Contact: HJ BEAULOYE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2141 NEWTON AVE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: .7000  
 Facility County: San Diego

Gepaid: CAD008232860  
 Contact: AL BEAULOYE VP  
 Telephone: 6192325719  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2141 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: 0.87  
 Facility County: Not reported

Gepaid: CAD008232860  
 Contact: AL BEAULOYE VP  
 Telephone: 6192325719  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2141 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: 0.8  
 Facility County: San Diego

Gepaid: CAD008232860  
 Contact: HJ BEAULOYE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2141 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 33.7120  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 19 additional CA\_HAZNET: record(s) in the EDR Site Report.



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300396  
 Stop Date: 1989-11-01 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-12-09 00:00:00  
 Discover Date: 1989-11-01 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-11-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chromic Acid  
 Contact Person: Not reported  
 Responsible Party: MR. AL BEAULOYE  
 RP Address: 2143 NEWTON AVE  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H08980-001  
 Case Number: 9UT1576  
 Qty Leaked: Not reported  
 Abate Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 108980  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2141 NEWTON AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD008232860  
 Gas Station: Not reported  
 Inspection Date: 05/26/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: ALLEN BEAULOYE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BEAULOYE HENRY J SR TR&BEAULOY  
 Property Address: 2143 NEWTON AVE  
 Property City,St,Zip: 92113  
 Tank Owner: H BEAULOYE R BEAULOYE COLEMAN  
 Tank Address: 2141 NEWTON AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/26/05  
 Facility Phone: 232-5719

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC67  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Item Number: AR65  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: CH62  
 Chemical Name: CHROMIC ACID FLAKE  
 Case Number: 7440-47-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: EXTREMELY

Item Number: CH63  
 Chemical Name: CHROMIC ACID SOLN; PLATING TANKS VAULTED  
 Case Number: 7738-94-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: KE69  
 Chemical Name: KEROSENE  
 Case Number: 8008-20-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: NI64  
 Chemical Name: NITROGEN  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OI68  
 Chemical Name: OIL: LUBRICATING, COMPRESSED CUTTING  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: OX66  
 Chemical Name: OXYGEN  
 Case Number: 7782-42-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1 CHROMIC  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 2 CHROMIC  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 00003 CHRO  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: 00004 CHRO  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9245  
 Violation Desc: WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Inspection Date: 11/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9246  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 9247  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 11/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9248  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 08/01/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8162  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/01/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 8163  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 02/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 4406  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 4407  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 02/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4408  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 05/26/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1858  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/26/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1859  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 05/26/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 1860  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: 05/26/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 2000  
 Quantity String: 2000  
 Annual Qty: 3000  
 Annual Qty String: 3000  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 2950 FILTER RECYCLING SER  
 Waste Desc: SLUDGE/DRY WASTE  
 Carcinogen: No

Inspection Date: 05/26/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 30  
 Annual Qty String: 30  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: 1 PARTS CLEANING UNIT/TO  
 Carcinogen: No

Inspection Date: 05/26/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 385  
 Quantity String: 385

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Annual Qty: 800  
 Annual Qty String: 800  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: OILS  
 Carcinogen: No

Inspection Date: 05/26/04  
 Waste Item #: 111  
 Waste Code: 111  
 Waste Name: ACID SOL'N WITH META  
 Qty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 1  
 Annual Qty String: 1  
 Measurement Unit: GAL  
 Treatment Method: 099 OTHER  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: SULFURIC ACID ETCHANT  
 Carcinogen: No

Inspection Date: 05/26/04  
 Waste Item #: 171  
 Waste Code: 171  
 Waste Name: METAL SLUDGE  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2950 FILTER RECYCLING SER  
 Waste Desc: CHROME FILTERS - TANK LNR  
 Carcinogen: No

EMI:

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0.0495  
 Reactive Organic Gases Tons/Yr: 0.0495  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0.000393412  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0.000393412

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92177  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: .04  
 Reactive Organic Gases Tons/Yr: .04  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**CARLSON & BEAULOYE MACHINE SHOP (Continued)**

**1000292448**

NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: .000409375  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: .000393

**SAN DIEGO CO. SAM:**

Case Number: H08980-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - For Non-LOP Tank**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/9/1992  
 Begandt: 11/1/1989

63

**TRIMM WOODWORKING, INC**  
**2130 NEWTON AV**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104749080**  
**N/A**

**San Diego Co. HMMD:**

Facility ID: 119600  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2130 NEWTON AV  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD981664097  
 Gas Station: Not reported  
 Inspection Date: 05/17/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JENNIFER CRONAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BATTIKHA WADE&ELHAM  
 Property Address: 1897 NATIONAL AVE  
 Property City, St, Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-236-0686

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIMM WOODWORKING, INC (Continued)**

**S104749080**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/07/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7669  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/29/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 8125  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

Inspection Date: 09/29/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 8126  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5202  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

**TRIMM WOODWORKING, INC (Continued)**

**S104749080**

Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**63 CALIFORNIA WOOD DESI  
 2130 NEWTON AV  
 SAN DIEGO, CA 92113**

**AIRS S106827800  
 N/A**

EMI:

Year: 1993  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6272  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1995  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6272  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1996  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6272  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA WOOD DESI (Continued)**

**S106827800**

Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0  
  
 Year: 1997  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 6272  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

63

**TRIMM WOODWORKING INC**  
**2130 NEWTON AVE**  
**SAN DIEGO, CA 92113**

**HAZNET S108223227**  
**N/A**

HAZNET:  
 Gepaid: CAL000279743  
 Contact: JENNIFER METZ  
 Telephone: 6192360686  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.06  
 Facility County: Not reported

63

**2116 NEWTON AVENUE**  
**SAN DIEGO, CA 92113**

**DOT OPS 1009648326**  
**N/A**

DOT OPS:  
 Report ID: 1820580  
 Facility name: Not reported  
 Address: 2116 NEWTON AVENUE  
 SAN DIEGO, CA 92113  
  
 Latitude: Not reported  
 Longitude: Not reported  
  
 EDR type: NATURAL GAS DISTRIBUTION  
 Cause of incident: CORROSION  
 Operator code: 18112  
 Operator name: SAN DIEGO GAS AND ELECTRIC COM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

1009648326

Incident address: 2116 NEWTON AVENUE  
 SAN DIEGO, CA 92113  
 Incident county: SAN DIEGO  
 Incident congressional district: Not reported  
 Incident date: 19820406  
 Detection time: 1345  
 Stoppage hours: 1  
 Stoppage minutes: 45  
 Estimated pressure at incident time: 60.00  
 Max. allowable operating pressure: 60.00  
 Part of operation that failed: SERVICE  
 Part of operation other comment: Not reported  
 Part of system that failed: PIPE  
 Part of system other comment: Not reported  
 Year oart installed: 1965  
 Where leak originated: OTHER  
 Leak other comment: CHEMICAL  
 Real nominal pipe diameter: 1.000  
 Pipe wall thickness (inches): 0.040  
 Pipe specifications: Not reported  
 Pipe grade: L  
 Type of repair done: REPLACE PIPE  
 Type other comment: Not reported  
 Length of replaced pipe: 0.00  
 Component replaced/reconditioned: NO DATA  
 Component other comment: Not reported  
 Employee fatalities: 0  
 Employees injured: 0  
 Non-empl. fatalities: 0  
 Non-empl. inured: 0  
 Did a rupture occur: NO  
 Did gas ignite: YES  
 Did an explosion occur: NO  
 Secondary fires/explosions: NO  
 Operator property damage: 0  
 Structure adjacent to leak: RESIDENTIAL SINGLE-STORY  
 Structure other comment: Not reported  
 Dist. to nearest structure: 40  
 Underground facility involved: NO  
 Underground facility other comment: Not reported  
 Any utilities affected: Not reported  
 Dist. of other gas fac. contributing: 0  
 Dist. of other gas fac. impaired: 0  
 Dist. of telephone fac. contributing: 0  
 Dist. of telephone fac. impaired: 0  
 Dist. of electric fac. contributing: 0  
 Dist. of electric fac. impaired: 0  
 Dist. of storm sewer fac. contributing: 0  
 Dist. of storm sewer fac. impaired: 0  
 Dist. of other sewer fac. contributing: 0  
 Dist. of other sewer fac. impaired: 0  
 Dist. of water fac. contributing: 0  
 Dist. of water fac. impaired: 0  
 Dist. of other fac. contributing: 0  
 Other fac. contributing: Not reported  
 Dist. of other fac. impaired: 0  
 Other facility impaired: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

1009648326

Location of leak or failure: NO DATA  
 Location other comment: Not reported  
 Cover depth: 24  
 Soil at pipe depth: SOIL  
 Soil temperature at soil leak: 060  
 Report by: CUSTOMER  
 Report other comment: Not reported

63 **PAKAN INC (MASTER PLATING)**  
**2109 NEWTON AVE**  
**SAN DIEGO, CA 92113**

**FTTS 1009520130**  
**HIST FTTS N/A**

FTTS INSP:

Inspection Number: Not reported  
 Region: 09  
 Inspection Date: Not reported  
 Inspector: GREENWALT  
 Violation occurred: No  
 Investigation Type: EPCRA, Enforcement, SEE Conducted  
 Investigation Reason: Neutral Scheme, Region  
 Legislation Code: EPCRA  
 Facility Function: User

HIST FTTS INSP:

Inspection Number: 19900619R9001 3  
 Region: 09  
 Inspection Date: Not reported  
 Inspector: GREENWALT  
 Violation occurred: No  
 Investigation Type: EPCRA, Enforcement, SEE Conducted  
 Investigation Reason: Neutral Scheme, Region  
 Legislation Code: EPCRA  
 Facility Function: User

63 **MASTER PLATING**  
**2109 NEWTON AVE**  
**SAN DIEGO, CA 92113**

**CERCLIS 1006426280**  
**HAZNET CAN000905947**

CERCLIS:

Site ID: 0905947  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

CERCLIS Site Contact Name(s):

Contact Name: Harry Allen  
 Contact Tel: (415) 972-3063  
 Contact Title: On-Scene Coordinator (OSC)

Contact Name: Dawn Richmond  
 Contact Tel: (415) 972-3097  
 Contact Title: Site Assessment Manager (SAM)

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER PLATING (Continued)**

**1006426280**

Contact Name: Karen Jurist  
 Contact Tel: (415) 972-3219  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Jeff Inglis  
 Contact Tel: (415) 972-3095  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS Assessment History:

Action: ADMINISTRATIVE ORDER ON CONSENT  
 Date Started: Not reported  
 Date Completed: 02/25/2003  
 Priority Level: Not reported

Action: POTENTIALLY RESPONSIBLE PARTY REMOVAL  
 Date Started: 02/27/2003  
 Date Completed: 05/20/2003  
 Priority Level: Cleaned up

Action: ADMINISTRATIVE RECORDS  
 Date Started: 07/14/2003  
 Date Completed: 07/14/2003  
 Priority Level: Admin Record Compiled for a Removal Event

HAZNET:

Gepaid: CAD067629311  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2109 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD088504881  
 TSD County: Orange  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .4000  
 Facility County: San Diego

Gepaid: CAD067629311  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2109 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .8000  
 Facility County: San Diego



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MASTER PLATING (Continued)**

**1006426280**

Gepaid: CAD067629311  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2109 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD980892731  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: .2000  
 Facility County: San Diego

Gepaid: CAD067629311  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2109 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD089446710  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .5000  
 Facility County: San Diego

Gepaid: CAD067629311  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2109 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD089446710  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .7500  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 24 additional CA\_HAZNET: record(s) in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**63 MASTER PLATING  
 2109 NEWTON AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000401457  
 FINDS CAD067629311  
 San Diego Co. HMMD  
 AIRS**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: MASTER PLATING  
 Facility address: 2109 NEWTON AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD067629311  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CASTRO ROBERT  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MASTER PLATING (Continued)**

**1000401457**

User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 12/18/1985  
 Facility name: MASTER PLATING  
 Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 10/23/1991  
 Date achieved compliance: 10/23/1996  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/23/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 10/23/1996  
 Evaluation lead agency: State Contractor/Grantee

FINDS:

Other Pertinent Environmental Activity Identified at Site

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

The NEI (National Emissions Inventory) database contains information

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER PLATING (Continued)**

**1000401457**

on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

San Diego Co. HMMD:

Facility ID:	108549
Inactive Indicator:	Active
Business Code:	6HK34
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2109 NEWTON AV
Mailing City, St, Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	CAD067629311
Gas Station:	Not reported
Inspection Date:	02/26/02
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	MOHAMED AFCARI
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER PLATING (Continued)**

**1000401457**

Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PARTY HATS INC  
 Property Address: 3200 ADAMS AVE #207  
 Property City,St,Zip: 92116  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 232-3092

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/05/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 1598  
 Violation Desc: NO TSDF SIGNED MANIFEST ONSITE

Inspection Date: 01/05/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1599  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 01/05/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1600  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/05/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MASTER PLATING (Continued)**

**1000401457**

Item Number: 1601  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 01/05/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported

Item Number: 1602  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 01/05/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0212  
 Occurrences: Not reported

Item Number: 1603  
 Violation Desc: INCOMPATIBLE WASTE NOT SEPARATED

Inspection Date: 01/05/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported

Item Number: 1604  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 09/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0137  
 Occurrences: Not reported

Item Number: 8260  
 Violation Desc: MANIFEST NOT COMPLETED PROPERLY

Inspection Date: 09/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported

Item Number: 8261  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 09/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported

Item Number: 8262  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported

Item Number: 8263  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/14/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported

Item Number: 8264

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER PLATING (Continued)**

**1000401457**

Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 4656  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 4657  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 4658  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 4659  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4660  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4661  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER PLATING (Continued)**

**1000401457**

Waste Desc: Not reported  
 Carcinogen: No

EMI:

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 8621  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 8621  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 8621  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**63 MASTER PLATING  
 2109 NEWTON AVE  
 SAN DIEGO, CA 92113**

**ICIS 1010628157  
 N/A**

ICIS:

Enforcement Action ID: 09-2003-0026  
 FRS ID: 110002655234  
 Program ID: FRS 110002655234  
 Action Name: MASTER PLATING  
 Facility Name: MASTER PLATING  
 Facility Address: 2109 NEWTON AVE  
 SAN DIEGO, California 92113  
 Enforcement Action Type: CERCLA 104E5A AO For Access And/Or Info  
 Facility County: SAN DIEGO  
 EPA Region #: 9

Program ID: AIRS/AFS 06073R9813  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: CERCLIS CAN000905947  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: FRS 110002655234  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: No  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NCDB I09#19900619R9001 3  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NEI 060733712278621  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NEI NEICA0732934  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MASTER PLATING (Continued)**

**1010628157**

Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	NEI NTICA0732934
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	NTI NTI23072
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	RCRAINFO CAD067629311
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Enforcement Action ID:	09-2003-0026
FRS ID:	110002655234
Program ID:	FRS 110002655234
Action Name:	MASTER PLATING
Facility Name:	MASTER PLATING
Facility Address:	2109 NEWTON AVE SAN DIEGO, California 92113
Enforcement Action Type:	CERCLA 122A/104A Agrmt For RI/FS
Facility County:	SAN DIEGO
EPA Region #:	9
Program ID:	AIRS/AFS 06073R9813
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	CERCLIS CAN000905947
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	FRS 110002655234

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MASTER PLATING (Continued)**

**1010628157**

Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: No  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NCDB I09#19900619R9001 3  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NEI 060733712278621  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NEI NEICA0732934  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NEI NTICA0732934  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NTI NTI23072  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: RCRAINFO CAD067629311  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Enforcement Action ID: 09-2003-0026  
 FRS ID: 110002655234

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MASTER PLATING (Continued)**

**1010628157**

Program ID:	FRS 110002655234
Action Name:	MASTER PLATING
Facility Name:	MASTER PLATING
Facility Address:	2109 NEWTON AVE SAN DIEGO, California 92113
Enforcement Action Type:	CERCLA 106 AO For Resp Action/Imm Haz
Facility County:	SAN DIEGO
EPA Region #:	9
Program ID:	AIRS/AFS 06073R9813
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	CERCLIS CAN000905947
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	FRS 110002655234
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	No
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	NCDB I09#19900619R9001 3
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	NEI 060733712278621
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported
Program ID:	NEI NEICA0732934
Facility Name:	MASTER PLATING
Address:	2109 NEWTON AVE SAN DIEGO CA 92113
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER PLATING (Continued)**

**1010628157**

Program ID: NEI NTICA0732934  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: NTI NTI23072  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

Program ID: RCRAINFO CAD067629311  
 Facility Name: MASTER PLATING  
 Address: 2109 NEWTON AVE SAN DIEGO CA 92113  
 Tribal Indicator: Not reported  
 Fed Facility: Not reported  
 NAIC Code: Not reported  
 SIC Code: Not reported

63

**PARTY HATS INC  
 2109 NEWTON AV  
 SAN DIEGO, CA 92113**

**AIRS S108432837  
 N/A**

EMI:

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 92180  
 Air District Name: SD  
 SIC Code: 2672  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: .21  
 Reactive Organic Gases Tons/Yr: .21  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Distance (ft.) Site Database(s) EPA ID Number

64 SAN DIEGO USA MEMORIAL JUNIOR HIGH SCHOOL RCRA-SQG 1000110715  
 2850 LOGAN AVENUE FINDS CAD981453541  
 SAN DIEGO, CA 92113 MANIFEST

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: SAN DIEGO USA MEMORIAL JR HS  
 Facility address: 2850 LOGAN AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981453541  
 Mailing address: 4100 NORMAL STREET A1, 112  
 SAN DIEGO, CA 92103  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: SANDIEGO CITY SCHOOL  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO USA MEMORIAL JUNIOR HIGH SCHOOL (Continued)**

**1000110715**

User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 03/12/1986  
 Facility name: SAN DIEGO USA MEMORIAL JR HS  
 Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

Document ID: NYA5525847  
 Manifest Status: Completed copy  
 Trans1 State ID: 808185  
 Trans2 State ID: 75318B-NY  
 Generator Ship Date: 871021  
 Trans1 Recv Date: 871021  
 Trans2 Recv Date: 871021  
 TSD Site Recv Date: 871102  
 Part A Recv Date: 871028  
 Part B Recv Date: 871106  
 Generator EPA ID: CAD981453541  
 Trans1 EPA ID: NYD980769947  
 Trans2 EPA ID: NYD980769947  
 TSDF ID: NYD000632372  
 Waste Code: D001 - NON-LISTED IGNITABLE WASTES  
 Quantity: 00150  
 Units: P - Pounds  
 Number of Containers: 001  
 Container Type: DM - Metal drums, barrels  
 Handling Method: T Chemical, physical, or biological treatment.  
 Specific Gravity: 100  
 Year: 87  
 Manifest Tracking Num: Not reported  
 Import Ind: Not reported  
 Export Ind: Not reported  
 Discr Quantity Ind: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO USA MEMORIAL JUNIOR HIGH SCHOOL (Continued)**

**1000110715**

Discr Type Ind: Not reported  
 Discr Residue Ind: Not reported  
 Discr Partial Reject Ind: Not reported  
 Discr Full Reject Ind: Not reported  
 Manifest Ref Num: Not reported  
 Alt Fac RCRA Id: Not reported  
 Alt Fac Sign Date: Not reported  
 Mgmt Method Type Code: Not reported  
 EPA ID: CAD981453541  
 Facility Name: SAN DIEGO CITY SCHOOLS  
 Facility Address: 2850 LOGAN AVENUE  
 Facility City: SAN DIEGO  
 Facility Address 2: Not reported  
 Country: USA  
 Mailing Name: SAN DIEGO CITY SCHOOLS  
 Mailing Contact: SAN DIEGO CITY SCHOOLS  
 Mailing Address: MEMORIAL HIGH SCHOOL - 2850  
 Mailing Address 2: Not reported  
 Mailing City: LOGAN AVENUE - SAN DIEGO  
 Mailing State: CA  
 Mailing Zip: 92103  
 Mailing Zip4: Not reported  
 Mailing Country: USA  
 Mailing Phone: 619-293-8116

65

**MEMORIAL AREA MIDDLE SCHOOL ALT SITE B  
 43RD STREET/LOGAN AVENUE  
 SAN DIEGO, CA 92113**

**SCH S107736717  
 ENVIROSTOR N/A**

SCH:

Facility ID: 60000073  
 Site Type: School Investigation  
 Site Type Detail: School  
 Acres: 14.7  
 National Priorities List: NO  
 Cleanup Oversight Agencies: SMBRP  
 Lead Agency: SMBRP  
 Lead Agency Description: DTSC - Site Mitigation And Brownfield Reuse Program  
 Project Manager: TAWFIQ DEEK  
 Supervisor: Shahir Haddad  
 Division Branch: School Evaluation - Cypress  
 Site Code: 404597-11  
 Assembly: 79  
 Senate: 40  
 Special Program Status: Not reported  
 Status: Inactive - Action Required  
 Status Date: 2005-01-28 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.695659  
 Longitude: -117.101437  
 Alias Name: 404597-11  
 SAN DIEGO SD-MEMRL AREA MID SCL ALT B  
 60000073  
 Alias Type: Project Code (Site Code)  
 Envirostor ID Number  
 Alternate Name



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MEMORIAL AREA MIDDLE SCHOOL ALT SITE B (Continued)**

**S107736717**

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 12/05/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 01/28/05

Confirmed: 31000-NO  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NMA  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED,31000  
 Potential Description: Not reported  
 Potential Description: No Contaminants found  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA

ENVIROSTOR:  
 Site Type: School Investigation  
 Site Type Detailed: School  
 Acres: 14.7  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP  
 Program Manager: TAWFIQ DEEK  
 Supervisor: Shahir Haddad  
 Division Branch: School Evaluation - Cypress  
 Facility ID: 60000073  
 Site Code: 404597-11  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Inactive - Action Required  
 Status Date: 2005-01-28 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.695659  
 Longitude: -117.101437

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MEMORIAL AREA MIDDLE SCHOOL ALT SITE B (Continued)**

**S107736717**

Alias Name: 404597-11  
 SAN DIEGO SD-MEMRL AREA MID SCL ALT B  
 60000073

Alias Type: Project Code (Site Code)  
 Envirostor ID Number  
 Alternate Name

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 12/05/05

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 01/28/05

Confirmed: 31000-NO  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NMA  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED,31000  
 Potential Description: Not reported  
 Potential Description: No Contaminants found  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA

66

**KENNEDY/KNOX SCHOOL SITE NO. 1  
 DOMINION STREET/LOGAN AVENUE  
 SAN DIEGO, CA 92113**

**SCH S107736535  
 ENVIROSTOR N/A**

SCH:

Facility ID: 37880004  
 Site Type: School Investigation  
 Site Type Detail: School  
 Acres: 7.9  
 National Priorities List: NO  
 Cleanup Oversight Agencies: SMBRP  
 Lead Agency: SMBRP  
 Lead Agency Description: DTSC - Site Mitigation And Brownfield Reuse Program  
 Project Manager: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KENNEDY/KNOX SCHOOL SITE NO. 1 (Continued)**

**S107736535**

Supervisor: Mark Malinowski  
 Division Branch: School Evaluation - Cypress  
 Site Code: 404276-11  
 Assembly: 79  
 Senate: 40  
 Special Program Status: Not reported  
 Status: Inactive - Needs Evaluation  
 Status Date: 2002-04-04 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.695675  
 Longitude: -117.100163  
 Alias Name: KENNEDY/KNOX SCHOOL SITE #1  
 37880004  
 404276-11  
 SAN DIEGO CITY USD-KNEDY/KNOX EL SITE 1  
 Alias Type: Alternate Name  
 Project Code (Site Code)  
 Alternate Name  
 Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 04/04/02

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 10/09/01

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KENNEDY/KNOX SCHOOL SITE NO. 1 (Continued)**

**S107736535**

**ENVIROSTOR:**

Site Type: School Investigation  
 Site Type Detailed: School  
 Acres: 7.9  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP  
 Program Manager: Not reported  
 Supervisor: Mark Malinowski  
 Division Branch: School Evaluation - Cypress  
 Facility ID: 37880004  
 Site Code: 404276-11  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Inactive - Needs Evaluation  
 Status Date: 2002-04-04 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.695675  
 Longitude: -117.100163  
 Alias Name: KENNEDY/KNOX SCHOOL SITE #1  
 37880004  
 404276-11  
 SAN DIEGO CITY USD-KNEDY/KNOX EL SITE 1  
 Alias Type: Alternate Name  
 Project Code (Site Code)  
 Alternate Name  
 Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

**Completed Info:**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 04/04/02  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 10/09/01  
 Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

**Management:**

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KENNEDY/KNOX SCHOOL SITE NO. 1 (Continued)**

**S107736535**

Potenital Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA

67

**920 SO. 33RD ST.  
 SAN DIEGO, CA 92113**

**Notify 65 S100178351  
 N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92113-2628

67

**CALIFORNIA MARINE CLEANING INC  
 905 S 33RD ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000596364  
 FINDS CAD983603341  
 HAZNET  
 San Diego Co. HMMD**

RCRA-SQG:  
 Date form received by agency: 09/21/1991  
 Facility name: CALIFORNIA MARINE CLEANING INC  
 Facility address: 905 S 33RD ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD983603341  
 Mailing address: PO BOX 13653  
 SAN DIEGO, CA 92170  
 Contact: MATTHEW CARR  
 Contact address: 905 S 33RD ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 231-8788  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Private  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: HAZEL CARR  
 Owner/operator address: 905 S 33RD ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 231-8788  
 Legal status: Private  
 Owner/Operator Type: Owner

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA MARINE CLEANING INC (Continued)**

**1000596364**

Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 02/01/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: Local

Evaluation date: 01/24/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD983603341  
 Contact: MATT & HAZEL CARR  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13653

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CALIFORNIA MARINE CLEANING INC (Continued)**

**1000596364**

Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .3000  
 Facility County: San Diego

Gepaid: CAD983603341  
 Contact: MATT & HAZEL CARR  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13653  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000

Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with metals (restricted levels and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc )

Disposal Method: Recycler  
 Tons: .8757  
 Facility County: San Diego

Gepaid: CAD983603341  
 Contact: MATT & HAZEL CARR  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13653  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000

Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with metals (restricted levels and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc )

Disposal Method: Not reported  
 Tons: .8757  
 Facility County: San Diego

Gepaid: CAD983603341  
 Contact: MATT & HAZEL CARR  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13653  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000

Gen County: San Diego  
 TSD EPA ID: CAD981458466  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA MARINE CLEANING INC (Continued)**

**1000596364**

Tons: 16.6800  
 Facility County: San Diego  
  
 Gepaid: CAD983603341  
 Contact: MATT & HAZEL CARR  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13653  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 9.1740  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 52 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMMD:

Facility ID: 123187  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 905 S 33RD ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAD983603341  
 Gas Station: Not reported  
 Inspection Date: 02/18/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DAVE BECHTEL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KRUEGEL HOWARD J TRUST 04-23-0  
 Property Address: 299 HILLTOP DR  
 Property City,St,Zip: 91910  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/18/05  
 Facility Phone: 619-231-8788



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CALIFORNIA MARINE CLEANING INC (Continued)**

**1000596364**

**HMMD DISCLOSURE INVENTORY:**

Item Number: CA40  
 Chemical Name: CARBON DIOXIDE GAS  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: LU57  
 Chemical Name: LUBRICATING OILS  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: SU41  
 Chemical Name: SULFAMIC ACID 2%  
 Case Number: 5329-14-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/17/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 5654  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 05/03/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 3978

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA MARINE CLEANING INC (Continued)**

**1000596364**

Violation Desc: HAZMATS WITHOUT PROPER LABELS  
 Inspection Date: 05/03/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0081  
 Occurrences: Not reported  
 Item Number: 3979  
 Violation Desc: TREATING HAZWASTE WITHOUT AUTHORIZATION

Inspection Date: 08/08/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 0584  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 02/18/04  
 Waste Item #: 131  
 Waste Code: 131  
 Waste Name: AQUEOUS SOL'N W/REAC  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 475  
 Annual Qty String: 475  
 Measurement Unit: LBS  
 Treatment Method: 014 TRANSFER STATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: METHELYENE CHLORIDE; AMIN  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 141  
 Waste Code: 141  
 Waste Name: OFF-SPEC,AGED,SURPL  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 225  
 Annual Qty String: 225  
 Measurement Unit: LBS  
 Treatment Method: 014 TRANSFER STATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: CORROSIVE WASTE  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 175  
 Annual Qty String: 175  
 Measurement Unit: LBS  
 Treatment Method: 014 TRANSFER STATION

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA MARINE CLEANING INC (Continued)**

**1000596364**

Storage Method: METAL DRUM  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: OXIDIZING SOLID  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: SODIUM HYDROXIDE  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: OIL  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: GAL  
 Treatment Method: 103 TREATED, THEN SEW  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 2174 CALIFORNIA MARINE CL  
 Waste Desc: SUMP WASTE/STEAM CLNG  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 55

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA MARINE CLEANING INC (Continued)**

**1000596364**

Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: NAPHTHA SOLVENT  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 003 LANDFILL  
 Storage Method: UNKNOWN  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: TANK BOTTOMS  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 26700  
 Annual Qty String: 26700  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: OILY RAGS, DEBRIS, CHT SL  
 Carcinogen: No

Inspection Date: 02/18/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: FILTER RECYCLING  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**68 BAY DECKING COMPANY INC  
 1995 BAY FRONT ST  
 SAN DIEGO, CA 92113**

**FINDS 1000110204  
 RCRA-NonGen CAD982019077**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-NonGen:**

Date form received by agency: 04/22/1992  
 Facility name: BAY DECKING COMPANY INC  
 Facility address: 1995 BAY FRONT ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982019077  
 Mailing address: 21 COMMERCIAL BLVD SUITE 16  
 IGNACIO, CA 94947  
 Contact: MATTHEW TRUJILLO  
 Contact address: 1995 BAY FRONT ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (510) 769-6033  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: CONTINENTAL MARITIME  
 Owner/operator address: 1995 BAYFRONT ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 234-8851  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: MIGUEL M NARRO  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAY DECKING COMPANY INC (Continued)**

**1000110204**

Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

68

**1995 BAYFRONT STREET  
 SAN DIEGO, CA 92113**

**RCRA-LQG 1008194718  
 CAP000147272**

RCRA-LQG:

Date form received by agency: 02/16/2004  
 Facility name: Not reported  
 Facility address: 1995 BAYFRONT STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CAP000147272  
 Mailing address: P.O. BOX 85278 MS-22A  
 SAN DIEGO, CA 921865278  
 Contact: MICHAEL T CHEE  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 544-7778  
 Contact email: MCHEE@NASSCO.COM  
 EPA Region: Not reported  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: SAN DIEGO PORT DISTRICT  
 Owner/operator address: P.O BOX 120488  
 SAN DIEGO, CA 92112  
 Owner/operator country: US  
 Owner/operator telephone: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**(Continued)**

**1008194718**

Legal status:	District
Owner/Operator Type:	Owner
Owner/Op start date:	02/14/1963
Owner/Op end date:	Not reported
Owner/operator name:	SOUTHWEST MARINE
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/14/1976
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Universal Waste Summary:

Waste type:	Batteries
Accumulated waste on-site:	No
Generated waste on-site:	No

Waste type:	Lamps
Accumulated waste on-site:	No
Generated waste on-site:	No

Waste type:	Pesticides
Accumulated waste on-site:	No
Generated waste on-site:	No

Waste type:	Thermostats
Accumulated waste on-site:	No
Generated waste on-site:	No

Hazardous Waste Summary:

Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET,

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

1008194718

WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D008  
 Waste name: LEAD  
 Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Violation Status: No violations found

68

**CORROSION ENGN SVC, INC.**  
**1995 BAY FRONT ST**  
**SAN DIEGO, CA 92113**

**CHMIRS S104746413**  
**Cortese N/A**  
**San Diego Co. HMMD**

CHMIRS:  
 OES Incident Number: 98-1243  
 OES notification: 3/12/199812:35:07 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: No  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CORROSION ENGN G SVC, INC. (Continued)**

**S104746413**

What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1998  
 Agency: USCG-MSO San Diego  
 Incident Date: 3/12/1998 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: No  
 Site Type: Road  
 E Date: Not reported  
 Substance: Hydraulic Fluid  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 10-20  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: CalTrans vehicle spewed fluid from overpass onto approximately 70 vehicles parked below belonging to employees of Continental Maritime. CalTrans apparently not doing clean-up to vehicles; Russel McCarthy from Continental Maritime (619)234-8851 X-531 called USCG to report the following after calling both Caltrans & RWQCB-9 and getting either no response or incorrect response. Someone RWQ??? told him to take the vehicles to a carwash.

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported  
 Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:  
 Facility ID: 106677  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3635 RUFFIN RD  
 Mailing City, St, Zip: SAN DIEGO, CA 92123

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CORROSION ENGN SVC, INC. (Continued)**

**S104746413**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAL000196534  
 Gas Station: Not reported  
 Inspection Date: 12/17/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DAVID EVANS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SERVICE ENGINEERING INDUSTRIES  
 Property Address: C/O LEE E WILSON  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 858-514-1280

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CORROSION ENGNNG SVC, INC. (Continued)**

**S104746413**

Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

68

**BUMBLE BEE SEAFOODS  
 1995 BAYFRONT  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000163719  
 FINDS CAD020511010  
 HIST UST**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: BUMBLE BEE SEAFOODS  
 Facility address: 1995 BAYFRONT  
 SAN DIEGO, CA 92113  
 EPA ID: CAD020511010  
 Mailing address: PO BOX X-1017  
 SAN DIEGO, CA 92112  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: BUMBLE BEE SEAFOODS  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BUMBLE BEE SEAFOODS (Continued)**

**1000163719**

Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 06/16/1983  
 Facility name: BUMBLE BEE SEAFOODS  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HIST UST:**

Region: STATE  
 Facility ID: 00000011727  
 Facility Type: Other  
 Other Type: FOOD PROCESSING  
 Total Tanks: 0004  
 Contact Name: GENE PENN  
 Telephone: 6192350160  
 Owner Name: BUMBLE BEE SEAFOODS  
 Owner Address: 1995 BAYFRONT  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: CD-1  
 Year Installed: Not reported  
 Tank Capacity: 00000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BUMBLE BEE SEAFOODS (Continued)**

**1000163719**

Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002  
 Container Num: CG-1  
 Year Installed: Not reported  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: PREMIUM  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

Tank Num: 003  
 Container Num: FD-1  
 Year Installed: 1979  
 Tank Capacity: 00000000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

Tank Num: 004  
 Container Num: FD-2  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

68

**CONTINENTAL MARITIME  
 1995 BAY FRONT ST  
 SAN DIEGO, CA 92113**

**Cortese 1006893987  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1995 BAY FRONT ST

68

**CONTINENTAL MARITIME OF S D  
 1995 BAYFRONT ST  
 SAN DIEGO, CA 92113**

**HAZNET S103978937  
 LUST N/A  
 San Diego Co. HMMD  
 SWEEPS UST**

HAZNET:  
 Gepaid: CAC001308808  
 Contact: NATIONAL STEEL & SHIPBLDG CO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85278 MS 22A  
 Mailing City,St,Zip: SAN DIEGO, CA 921865278

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: 5.2125  
 Facility County: San Diego

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300219  
 Stop Date: 1986-12-12 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-05-25 00:00:00  
 Discover Date: 1986-12-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-12-12 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: SHAUN GILLS  
 RP Address: 1995 BAYFRONT ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00120-001  
 Case Number: 9UT138  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301225  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1997-02-24 00:00:00  
 Discover Date: 1992-07-10 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-07-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: SANDOR HALVAX  
 RP Address: 1995 BAY FRONT ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: ML  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00120-003  
 Case Number: 9UT2467  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0607301763  
 Stop Date: 1990-08-30 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2005-04-15 00:00:00  
 Discover Date: 1990-08-30 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-08-30 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Contact Person: Not reported  
 Responsible Party: SEAN HALVAX  
 RP Address: 1995 Bay Front Street  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 2  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00120-002  
 Case Number: 9UT2996  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 100120  
 Inactive Indicator: Active  
 Business Code: 6HK71  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1995 BAYFRONT ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD981418395  
 Gas Station: Not reported  
 Inspection Date: 11/13/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: RUSSELL MCCARTHY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO UNIFIED PORT DISTRIC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: CONTINENTAL MARITIME OF SD INC  
 Tank Address: 1445 P O BOX X-1007  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/13/05  
 Facility Phone: 619-234-885

**HMMD DISCLOSURE INVENTORY:**

Item Number: AB72  
 Chemical Name: ABRASIVE STEEL SHOT  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AB13  
 Chemical Name: ABRASIVE: COPPER SLAG  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: AB14  
 Chemical Name: ABRASIVE: GARNET, SILICA, STEEL SHOT  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: AC04  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Item Number: AD73  
 Chemical Name: ADHESIVES, VARIOUS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: AE77  
 Chemical Name: AEROSOLS, LUBRICANTS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AE78  
 Chemical Name: AEROSOLS, PAINTS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AE79  
 Chemical Name: AEROSOLS, SOLVENT  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AQ09  
 Chemical Name: AQUEOUS FILM FORMING FOAM (AFFF)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported  
  
 Item Number: AR02  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: AR82  
 Chemical Name: ARGON, LIQUID  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CRYOGENIC

Item Number: BA15  
 Chemical Name: BACTICIDE: MICROBIOCIDE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: CA17  
 Chemical Name: CARBON DIOXIDE  
 Case Number: 12-438-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CA83  
 Chemical Name: CARBON DIOXIDE, LIQUID  
 Case Number: 12-438-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CRYOGENIC

Item Number: CI07  
 Chemical Name: CITRIC ACID  
 Case Number: 77-92-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: CO84  
 Chemical Name: COMPRESSED GAS 75% ARGON 25% HELIUM  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CO97  
 Chemical Name: COMPRESSED GAS 84% ARGON 16% CARBON DIOXIDE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CO98  
 Chemical Name: COMPRESSED GAS 90% HELIUM 7.5% ARGON 2.5% CARBON DIOXIDE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CO99  
 Chemical Name: COMPRESSED GAS 95% ARGON 5% CARBON DIOXIDE  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CO00  
 Chemical Name: COMPRESSED GAS 98% ARGON 2% CARBON DIOXIDE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CO11  
 Chemical Name: CONCENTRATED GOTAR (PHOSPHORIC ACID 75%, IPA 15%)  
 Case Number: 7664-38-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: CO07  
 Chemical Name: CORROSION INHIBITOR  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: CO08  
 Chemical Name: CORROSION INHIBITOR  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Item Number:	DI09
Chemical Name:	DIESEL FUEL2
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	ACUTE
Item Number:	EP91
Chemical Name:	EPOXY & ENAMEL REDUCER; HARDENER
Case Number:	25068-38-6
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	ACUTE
Item Number:	ET96
Chemical Name:	ETHYLENE GLYCOL
Case Number:	107-21-1
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	ACUTE
2nd Hazard Category:	Not reported
Item Number:	FO11
Chemical Name:	FORMULA 1 POTASSIUM HYDROXIDE 5%
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	ACUTE
2nd Hazard Category:	Not reported
Item Number:	GO13
Chemical Name:	GOTAR DC (CONCENTRATE)
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: GR14  
 Chemical Name: GREASE, VARIOUS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: HE03  
 Chemical Name: HELIUM  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: HY98  
 Chemical Name: HYDROCHLORIC ACID  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HY94  
 Chemical Name: HYPOCHLORIC ACID (MURIATIC ACID)  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: KE89  
 Chemical Name: KEROSENE  
 Case Number: 8008-20-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: LI17  
 Chemical Name: LIQUID PETROLEUM GAS  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: MI95  
 Chemical Name: MINERAL SPIRITS  
 Case Number: 8052-41-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: NA97  
 Chemical Name: NAPHTHA PETROLEUM DISTILLATE  
 Case Number: 8030-30-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: NI01  
 Chemical Name: NITROGEN, LIQUID  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: OI90  
 Chemical Name: OILS: LUBE, MOTOR, CUTTING, HYDRAULIC  
 Case Number: 647-42-445

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX93  
 Chemical Name: OXYGEN (LIQUID & GASEOUS)  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PA20  
 Chemical Name: PAINT PAINT, ALKYD  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: PA87  
 Chemical Name: PAINT THINNERS,VARIOUS  
 Case Number: 8032-32-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PA18  
 Chemical Name: PAINT, ACRYLIC  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Item Number: PA21  
 Chemical Name: PAINT, ENAMEL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PA36  
 Chemical Name: PAINT, EPOXY  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PA37  
 Chemical Name: PAINT, SILOXANE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PA86  
 Chemical Name: PAINT, VARIOUS  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: PO18  
 Chemical Name: POLYPROPYLENE: HPG  
 Case Number: 115-07-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR88  
 Chemical Name: PROPANE GAS - PETROLANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: RY10  
 Chemical Name: RYDLYME, HYDROGEN CHLORIDE, AQUEOUS 10%  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SE38  
 Chemical Name: SEALANTS, VARIOUS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: SO12  
 Chemical Name: SODIUM CARBONATE; SODA ASH  
 Case Number: 497-19-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO99  
 Chemical Name: SODIUM HYDROXIDE  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO00  
 Chemical Name: SODIUM HYPOCHLORITE  
 Case Number: 7681-52-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO92  
 Chemical Name: SODIUM NITRATE & NITRITE  
 Case Number: 7632-00-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SU16  
 Chemical Name: SULFAMIC ACID  
 Case Number: 5329-14-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SU08  
 Chemical Name: SULFAMIC ACID  
 Case Number: 5329-14-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SU39  
 Chemical Name: SURFACTANTS  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: TH40  
 Chemical Name: THINNERS, VAROIOUS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: TR05  
 Chemical Name: TRIETHANOLAMINE COMMERCIAL GRADE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: TR06  
 Chemical Name: TRISODIUM PHOSPHATE  
 Case Number: 10101-89-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: CD-1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: CG-1  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T003

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Tank ID Number: FD-1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T004  
 Tank ID Number: FD-2  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T005  
 Tank ID Number: AT1978  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T006  
 Tank ID Number: AT2018  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T007  
 Tank ID Number: 007  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T008  
 Tank ID Number: 008  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 07/09/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 7702  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 07/09/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 7703  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 07/09/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 7704  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 02/03/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1216  
 Violation Desc: WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Inspection Date: 02/03/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1006  
 Occurrences: Not reported  
 Item Number: 1217  
 Violation Desc: HMBP: INVENTORY INADEQUATE

Inspection Date: 01/22/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3313  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/22/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 3314  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 11/13/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 6425  
 Violation Desc: HMBP: INADEQUATE SITE MAP

**HMMD WASTE STREAMS:**

Inspection Date: 11/13/04  
 Waste Item #: 134  
 Waste Code: 134  
 Waste Name: AQUEOUS SOL'N W/LESS  
 Qty at Inspection: 80000  
 Quantity String: 80000  
 Annual Qty: 250000  
 Annual Qty String: 250000  
 Measurement Unit: GAL  
 Treatment Method: 201 SEWER  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: TRTD THEN SWRD BILGE WATR  
 Carcinogen: No

Inspection Date: 11/13/04  
 Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 6000  
 Annual Qty String: 6000  
 Measurement Unit: GAL  
 Treatment Method: 008 NEUTRALIZATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: SULFAMIC ACID



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Carcinogen:	No
Inspection Date:	11/13/04
Waste Item #:	151
Waste Code:	151
Waste Name:	ASBESTOS CONTAINING
Qnty at Inspection:	891
Quantity String:	891
Annual Qty:	1890
Annual Qty String:	1890
Measurement Unit:	CFT
Treatment Method:	003 LANDFILL
Storage Method:	METAL DRUM
Haz Waste Hauler:	2091 PACIFIC TREATMENT CO
Waste Desc:	QUANTITY VARIES
Carcinogen:	No
Inspection Date:	11/13/04
Waste Item #:	172
Waste Code:	172
Waste Name:	METAL DUST & MACHINI
Qnty at Inspection:	20000
Quantity String:	20000
Annual Qty:	40000
Annual Qty String:	40000
Measurement Unit:	LBS
Treatment Method:	001 RECYCLE
Storage Method:	METAL DRUM
Haz Waste Hauler:	2091 PACIFIC TREATMENT CO
Waste Desc:	SANDBLAST/BAGHOUSE
Carcinogen:	No
Inspection Date:	11/13/04
Waste Item #:	172
Waste Code:	172
Waste Name:	METAL DUST & MACHINI
Qnty at Inspection:	40000
Quantity String:	40000
Annual Qty:	60000
Annual Qty String:	60000
Measurement Unit:	LBS
Treatment Method:	001 RECYCLE
Storage Method:	WASTE PILE
Haz Waste Hauler:	9997 UNREGISTERED HAZ WST
Waste Desc:	SNDBLAST WSTE,ERM,NONRCRA
Carcinogen:	No
Inspection Date:	11/13/04
Waste Item #:	213
Waste Code:	213
Waste Name:	HYDROCARBON SOLVENTS
Qnty at Inspection:	65
Quantity String:	65
Annual Qty:	55
Annual Qty String:	55
Measurement Unit:	GAL
Treatment Method:	001 RECYCLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 2804 ENVIROSERV  
 Waste Desc: 4 SOLVENT TANKS  
 Carcinogen: No

Inspection Date: 11/13/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 1850  
 Quantity String: 1850  
 Annual Qty: 21000  
 Annual Qty String: 21000  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: AUTO/VEHICLES/TTU/SHIPS  
 Carcinogen: No

Inspection Date: 11/13/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 4000  
 Quantity String: 4000  
 Annual Qty: 8000  
 Annual Qty String: 8000  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2091 PACIFIC TREATMENT CO  
 Waste Desc: SHIP-TANK BOTTOM SLUDGE  
 Carcinogen: No

Inspection Date: 11/13/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 3000  
 Quantity String: 3000  
 Annual Qty: 25000  
 Annual Qty String: 25000  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: PAINT CHIPS/DEBRIS  
 Carcinogen: No

Inspection Date: 11/13/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 1400

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Annual Qty String: 1400  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 120  
 Number: Not reported  
 Board Of Equalization: 44-021534  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000120-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 6

Status: Not reported  
 Comp Number: 120  
 Number: Not reported  
 Board Of Equalization: 44-021534  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000120-000002  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 120  
 Number: Not reported  
 Board Of Equalization: 44-021534  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000120-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	120
Number:	Not reported
Board Of Equalization:	44-021534
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-000120-000004
Actv Date:	Not reported
Capacity:	6000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	120
Number:	Not reported
Board Of Equalization:	44-021534
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-000120-000005
Actv Date:	Not reported
Capacity:	10000
Tank Use:	OIL
Stg:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	120
Number:	Not reported
Board Of Equalization:	44-021534
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-000120-000006
Actv Date:	Not reported
Capacity:	12000
Tank Use:	OIL
Stg:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported
Status:	A
Comp Number:	120

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF S D (Continued)**

**S103978937**

Number: 9  
 Board Of Equalization: 44-021534  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

68

**SOUTHBAY SANDBLASTING AND TANK CLEAN  
 1995 BAYFRONT ST PIER 1 2 3 AN  
 SAN DIEGO, CA 92173**

**RCRA-SQG 1001217436  
 FINDS CAR000034363**

RCRA-SQG:

Date form received by agency: 12/04/1997  
 Facility name: SOUTHBAY SANDBLASTING AND TANK CLEAN  
 Facility address: 1995 BAYFRONT ST PIER 1 2 3 AN  
 SAN DIEGO, CA 92173  
 EPA ID: CAR000034363  
 Mailing address: 3763 DELBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact: CARLOS BERNAL  
 Contact address: 3763 DELBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 238-8338  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CANUTO LOPEZ  
 Owner/operator address: 3763 DELBERGIA ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 238-8338  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHBAY SANDBLASTING AND TANK CLEAN (Continued)**

**1001217436**

Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 12/04/1997  
 Facility name: SOUTHBAY SANDBLASTING AND TANK CLEAN  
 Classification: Large Quantity Generator

Date form received by agency: 12/04/1997  
 Facility name: SOUTHBAY SANDBLASTING AND TANK CLEAN  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

68

**CP KELCO  
 2025 HARBOR DR  
 SAN DIEGO, CA 92113**

**LUST S105113177  
 San Diego Co. HMMD N/A  
 SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: SLT19724600  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Close Date: 2008-03-06 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H38979-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Remove Contents  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608116327  
 Stop Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2001-10-16 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2001-10-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-10-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Ron Halik  
 RP Address: 2025 Harbor Drive  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H38979-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**S105113177**

Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608121886  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2001-12-31 00:00:00  
 Discover Date: 2001-03-19 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-03-19 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: RON HALIK  
 RP Address: 2025 E HARBOR DR  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H38979-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**S105113177**

Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 138979  
 Inactive Indicator: Active  
 Business Code: 6HK76  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2025 E HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAR000084533  
 Gas Station: Not reported  
 Inspection Date: 10/02/03  
 Reinspection Date: Not reported  
 Inspector Name: JGOHRES  
 Violation Notice Issued: Not reported  
 Facility Contact: RON HALIK  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KELCO CO  
 Property Address: 123 N WACKER DR #20  
 Property City,St,Zip: 60606  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/02/05  
 Facility Phone: 858-292-4900

HMMD DISCLOSURE INVENTORY:

Item Number: 1,71  
 Chemical Name: 1,4 - BUTANEDIOL  
 Case Number: 110-63-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: AR38  
 Chemical Name: ARGON GAS  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: CA67  
 Chemical Name: CALCIUM CARBONATE  
 Case Number: 471-34-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: CA72  
 Chemical Name: CALCIUM HYDROXIDE  
 Case Number: 1305-62-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: CA65  
 Chemical Name: CALCIUM NITRATE  
 Case Number: 10124-37-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: DI10  
 Chemical Name: DIESEL FUEL NO 2  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: DR96  
 Chemical Name: DREW PLUS ANTIFOAM ANTIFOAM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: GL66  
 Chemical Name: GLYOXIAL, 80% (ALIPHAATIC ALDEHYDE)  
 Case Number: 107-22-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: GU33  
 Chemical Name: GUAR GUM  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HO32  
 Chemical Name: HODAG K60K ANTIFOAM  
 Case Number: PROPRIET-AR-  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: LI31  
 Chemical Name: LITHIUM BROMIDE 18 SOLUTION  
 Case Number: 7550-35-8  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**S105113177**

Item Number: MA29  
 Chemical Name: MAZU 4141  
 Case Number: PROPRIET-AR-  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: MA30  
 Chemical Name: MAZU DF 204  
 Case Number: PROPRIET-AR-  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: MO26  
 Chemical Name: MONODODIUM GLATAMATE MSG  
 Case Number: 142-47-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NA74  
 Chemical Name: NALCO 2563 ANTIFOAM  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NA50  
 Chemical Name: NALCO 2833 CORROSION/ SCALE INHIBITOR  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NA88  
 Chemical Name: NALCO 8735 PH STABILIZER  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NA87  
 Chemical Name: NALCO TRI-ACT 1820 WATER TREATMENT CHEMICALS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NE28  
 Chemical Name: NEXGUARD 22310 WATER TREATMENT CHEMICALS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NE86  
 Chemical Name: NEXGUARD 22350 WATER TREATMENT CHEMICAL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NI61  
 Chemical Name: NITROGEN GAS  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**S105113177**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: ON85  
 Chemical Name: ONDEO CL-50 WATER TREATMENT CHEMICALS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: OP27  
 Chemical Name: OPTIMASE APL 440F6  
 Case Number: 9014-01-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: OR26  
 Chemical Name: ORBITAL ACID CLEANER #6  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: OX29  
 Chemical Name: OXYGEN LIQUID  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PE31  
 Chemical Name: PERLITE  
 Case Number: n/a

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**S105113177**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: PE62  
 Chemical Name: PETROLEUM OILS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: PO25  
 Chemical Name: POTASSIUM CHLORIDE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: PO34  
 Chemical Name: POTASSIUM HYDROXIDE CAUSTIC SODA  
 Case Number: 1310-58-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: PR70  
 Chemical Name: PROTEASE SUBTILISIN  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Item Number: SO24  
 Chemical Name: SODIUM ACETATE ANHYDROUS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO45  
 Chemical Name: SODIUM HYDROXIDE CAUSTIC SODA  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO46  
 Chemical Name: SODIUM HYPOCHLORITE LEACH  
 Case Number: 310-37-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO77  
 Chemical Name: SODIUM LAURLY SULFATE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO67  
 Chemical Name: SODIUM PHOSPHATE MONOBASIC  
 Case Number: 7558-80-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO75  
 Chemical Name: SODIUM SULFITE  
 Case Number: 7757-83-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SU50  
 Chemical Name: SULFURIC ACID, 98%  
 Case Number: 7664-93-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: EXTREMELY

Item Number: TE23  
 Chemical Name: TENASE L1200 BACTERIAL ALPHA-AMYLASE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: ZE76  
 Chemical Name: ZEP-DZ-7  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

**HMMD VIOLATIONS:**

Inspection Date: 06/08/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6493  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/02/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4763  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/02/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4764  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 10/02/03  
 Waste Code: Not reported  
 Type of Violation: 6HV4209  
 Occurrences: Not reported  
 Item Number: 4765  
 Violation Desc: NO GENERATOR'S INFO ON RED BAGS/SHARPS

Inspection Date: 10/02/03  
 Waste Code: Not reported  
 Type of Violation: 6HV4204  
 Occurrences: Not reported  
 Item Number: 4766  
 Violation Desc: WARNING SIGN NOT POSTED

**HMMD WASTE STREAMS:**

Inspection Date: 10/02/03  
 Waste Item #: 112  
 Waste Code: 112  
 Waste Name: ACID SOL'N W/OUT MET  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 3947 POLLUTION CONTROL IN  
 Waste Desc: NITRIC, HCL  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 122  
 Waste Code: 122  
 Waste Name: ALKALINE SOL'N W/OUT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**S105113177**

Qty at Inspection: 115  
 Quantity String: 115  
 Annual Qty: 115  
 Annual Qty String: 115  
 Measurement Unit: GAL  
 Treatment Method: Not reported  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: WASTE POTASSIUM HYDROXIDE  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 132  
 Waste Code: 132  
 Waste Name: AQUEOUS SOL'N WITH M  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: Not reported  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: WATER WITH COPPER  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: BOX  
 Haz Waste Hauler: 3947 POLLUTION CONTROL IN  
 Waste Desc: AEROSOL CANS  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qty at Inspection: 545  
 Quantity String: 545  
 Annual Qty: 545  
 Annual Qty String: 545  
 Measurement Unit: LBS  
 Treatment Method: Not reported  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: SAND WITH COPPER  
 Carcinogen: No

Inspection Date: 10/02/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Waste Item #: 212  
 Waste Code: 212  
 Waste Name: OXYGENATED SOLVENTS  
 Qnty at Inspection: 120  
 Quantity String: 120  
 Annual Qty: 285  
 Annual Qty String: 285  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3947 POLLUTION CONTROL IN  
 Waste Desc: METHANOL  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 214  
 Waste Code: 214  
 Waste Name: UNSPEC SOLVENT MIXTU  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 550  
 Quantity String: 550  
 Annual Qty: 2200  
 Annual Qty String: 2200  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3947 POLLUTION CONTROL IN  
 Waste Desc: MOTOR OIL  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 331  
 Waste Code: 331  
 Waste Name: OFF-SPEC,AGED,SURPLU  
 Qnty at Inspection: 1245  
 Quantity String: 1245  
 Annual Qty: 1245  
 Annual Qty String: 1245  
 Measurement Unit: LBS  
 Treatment Method: Not reported  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: SURPLUS POLYETHYLENE GLYC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**S105113177**

Carcinogen: No  
 Inspection Date: 10/02/03  
 Waste Item #: 331  
 Waste Code: 331  
 Waste Name: OFF-SPEC,AGED,SURPLU  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 3947 POLLUTION CONTROL IN  
 Waste Desc: POLYETHYLENE GLYCOL  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 85  
 Quantity String: 85  
 Annual Qty: 85  
 Annual Qty String: 85  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 3947 POLLUTION CONTROL IN  
 Waste Desc: ANTIFOAM  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: GAL  
 Treatment Method: Not reported  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: IPA AND WATER  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 800  
 Quantity String: 800  
 Annual Qty: 2574  
 Annual Qty String: 2574  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: OILY SOLIDS  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 727  
 Waste Code: 727  
 Waste Name: LIQUIDS W SELENIUM -  
 Qnty at Inspection: 458  
 Quantity String: 458  
 Annual Qty: 458  
 Annual Qty String: 458  
 Measurement Unit: LBS  
 Treatment Method: Not reported  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: WASTE SELENITE CYSTINE BR  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 791  
 Waste Code: 791  
 Waste Name: LIQUIDS WITH PH <OR=  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 3947 POLLUTION CONTROL IN  
 Waste Desc: ACIDS  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 791  
 Waste Code: 791  
 Waste Name: LIQUIDS WITH PH <OR=  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: GAL  
 Treatment Method: Not reported  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: WASTE LACTIC ACID  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 10

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**S105113177**

Annual Qty String: 10  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BOX  
 Haz Waste Hauler: 3400 STERICYCLE INC.  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/02/03  
 Waste Item #: 905  
 Waste Code: 905  
 Waste Name: INFECTIOUS WASTE, LA  
 Qty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BAG  
 Haz Waste Hauler: 3400 STERICYCLE INC.  
 Waste Desc: RED BAGS  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H38979-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/31/2001  
 Begandt: 3/19/2001

Case Number: H38979-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 10/16/2001  
 Begandt: 10/15/2001

Case Number: H38979-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 5/31/2007  
 Begandt: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**68 CP KELCO  
 2025 E. HARBOR DRIVE  
 SAN DIEGO, CA 92113**

**ENVIROSTOR S106797687  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000035  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-04-12 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37000035  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**68 CP KELCO  
 2025 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1004676382  
 FINDS CAR000084533  
 HAZNET  
 AST**

RCRA-SQG:

Date form received by agency: 02/28/2006  
 Facility name: CP KELCO  
 Facility address: 2025 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000084533  
 Contact: TONY W BRENTNALL  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 595-5957  
 Contact email: TONY.BRENTNALL@CPKELCO.COM  
 EPA Region: 09  
 Land type: Private  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CP KELCO  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 09/29/2000  
 Owner/Op end date: Not reported

Owner/operator name: C P KELCO  
 Owner/operator address: 2025 E HARBOR DR  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 595-5065  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: HUBER EQUITY CORPORATION  
 Owner/operator address: 2025 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92113  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 09/30/2004  
 Owner/Op end date: Not reported

Handler Activities Summary:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**1004676382**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: Yes  
 Generated waste on-site: Yes

Waste type: Lamps  
 Accumulated waste on-site: Yes  
 Generated waste on-site: Yes

Waste type: Pesticides  
 Accumulated waste on-site: Unknown  
 Generated waste on-site: Unknown

Waste type: Thermostats  
 Accumulated waste on-site: Yes  
 Generated waste on-site: Yes

Historical Generators:

Date form received by agency: 02/28/2006  
 Facility name: CP KELCO  
 Classification: Large Quantity Generator

Date form received by agency: 10/27/2004  
 Facility name: CP KELCO  
 Classification: Small Quantity Generator

Date form received by agency: 02/28/2002  
 Facility name: CP KELCO  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: CP KELCO  
 Site name: C P KELCO  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**1004676382**

CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D009  
 Waste name: MERCURY

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: 122  
 Waste name: 122

Waste code: 141  
 Waste name: 141

Waste code: 181  
 Waste name: 181

Waste code: 221  
 Waste name: 221

Waste code: 223  
 Waste name: 223

Waste code: 331  
 Waste name: 331

Waste code: 343  
 Waste name: 343

Waste code: 352  
 Waste name: 352

Waste code: 513  
 Waste name: 513

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**1004676382**

Waste code: 551  
 Waste name: 551

Waste code: 611  
 Waste name: 611

Waste code: 727  
 Waste name: 727

Waste code: 791  
 Waste name: 791

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003  
 Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D008  
 Waste name: LEAD

Waste code: D009  
 Waste name: MERCURY

Waste code: D010  
 Waste name: SELENIUM

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**1004676382**

Amount (Lbs): 3536 WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 15318

Waste code: D004  
 Waste name: ARSENIC  
 Amount (Lbs): 6800

Waste code: D006  
 Waste name: CADMIUM  
 Amount (Lbs): 6800

Waste code: D007  
 Waste name: CHROMIUM  
 Amount (Lbs): 6800

Waste code: D008  
 Waste name: LEAD  
 Amount (Lbs): 6950

Waste code: D010  
 Waste name: SELENIUM  
 Amount (Lbs): 334

Waste code: D038  
 Waste name: PYRIDINE  
 Amount (Lbs): 1535

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 10/02/2003  
 Date achieved compliance: 10/15/2003  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 279  
 Area of violation: Used Oil - Generators  
 Date violation determined: 06/08/2001  
 Date achieved compliance: 06/22/2001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CP KELCO (Continued)**

**1004676382**

Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: 07/26/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 264.50-56.D  
 Area of violation: TSD - General  
 Date violation determined: 06/08/2001  
 Date achieved compliance: 06/22/2001  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 08/27/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 279  
 Area of violation: Used Oil - Generators  
 Date violation determined: 06/08/2001  
 Date achieved compliance: 06/22/2001  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 08/27/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 264.50-56.D  
 Area of violation: TSD - General  
 Date violation determined: 06/08/2001  
 Date achieved compliance: 06/22/2001  
 Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: 07/26/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:  
 Evaluation date: 10/02/2003  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 10/15/2003

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**1004676382**

Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/08/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Used Oil - Generators  
 Date achieved compliance: 06/22/2001  
 Evaluation lead agency: EPA

Evaluation date: 06/08/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 06/22/2001  
 Evaluation lead agency: EPA

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AFS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**1004676382**

HAZNET:

Gepaid: CAR000084533  
 Contact: RON HALIK ENV MANAGER  
 Telephone: 6195955065  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2025 E HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Alkaline solution without metals (pH > 12.5)  
 Disposal Method: Recycler  
 Tons: 10.42  
 Facility County: Not reported

Gepaid: CAR000084533  
 Contact: RON HALIK ENV MANAGER  
 Telephone: 6195955065  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2025 E HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Alkaline solution without metals (pH > 12.5)  
 Disposal Method: Recycler  
 Tons: 10.42  
 Facility County: Not reported

Gepaid: CAR000084533  
 Contact: RON HALIK ENV MANAGER  
 Telephone: 6195955065  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2025 E HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: IND093219012  
 TSD County: Not reported  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Not reported  
 Tons: 0  
 Facility County: San Diego

Gepaid: CAR000084533  
 Contact: RON HALIK ENV MANAGER  
 Telephone: 6195955065  
 Facility Addr2: Not reported  
 Mailing Name: RON HALIK  
 Mailing Address: 2025 E HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: IND000646943  
 TSD County: San Diego  
 Waste Category: Laboratory waste chemicals

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CP KELCO (Continued)**

**1004676382**

Disposal Method: Disposal, Other  
 Tons: 0.22  
 Facility County: San Diego  
  
 Gepaid: CAR000084533  
 Contact: RON HALIK ENV MANAGER  
 Telephone: 6195955065  
 Facility Addr2: Not reported  
 Mailing Name: RON HALIK  
 Mailing Address: 2025 E HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: IND000646943  
 TSD County: San Diego  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.99  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 28 additional CA\_HAZNET: record(s) in the EDR Site Report.

AST:  
 Owner: HUBER EQUITY CORPORATION  
 Total Gallons: 150000

68

**2040 E. HARBOR DR.  
 SAN DIEGO, CA**

**CHMIRS S107449131  
 N/A**

CHMIRS:  
 OES Incident Number: 04-2809  
 OES notification: 5/28/200407:11:52 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S107449131

Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Pacific Ocean
Spill Site:	Not reported
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2004
Agency:	NRC
Incident Date:	5/28/200412:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Unknown
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Unknown Oil
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Via NRC report, caller is reporting an unknown sheen.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**69      SUNSHINE TRUCK WORKS  
 2191 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD      S105539592  
 N/A**

San Diego Co. HMMD:

Facility ID:	115810
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	3367 NATIONAL AV
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	CAD981404296
Gas Station:	Not reported
Inspection Date:	11/12/91
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	ROBERT STANG
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	SAMPSON CADILLAC L L C
Property Address:	C/O BOB SHAPIRO
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-233-3996

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNSHINE TRUCK WORKS (Continued)**

**S105539592**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

69

**COMMERCIAL FLEET SERVICES  
 2191 MAIN ST  
 SAN DIEGO, CA 92101**

San Diego Co. HMMD

**S106064597  
 N/A**

San Diego Co. HMMD:

Facility ID: 135523  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 05/27/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**COMMERCIAL FLEET SERVICES (Continued)**

**S106064597**

Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**69 CAR CONNECTION 2  
 2191 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106063624  
 N/A**

San Diego Co. HMMD:

Facility ID:	132673
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2191 MAIN ST #3
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	12/19/91
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	RON FOSTER
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	SAMPSON CADILLAC L L C
Property Address:	C/O BOB SHAPIRO
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-232-8738

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAR CONNECTION 2 (Continued)**

**S106063624**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

69

**PACIFIC TREATMENT CORP  
 2190 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000249933  
 FINDS CAD095894556  
 RCRA-TSDF  
 CORRACTS  
 CERC-NFRAP**

**RCRA-SQG:**

Date form received by agency: 09/01/1996  
 Facility name: PACIFIC TREATMENT CORP  
 Facility address: 2190 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD095894556  
 Mailing address: PO BOX 13626  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: TSDF  
 Description: Handler is engaged in the treatment, storage or disposal of hazardous waste  
 TSD commencement date: Not reported

**Owner/Operator Summary:**

Owner/operator name: PACIFIC TREATMENT CORP  
 Owner/operator address: PO BOX 13626  
 SAN DIEGO, CA 92113



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Owner/operator country: Not reported  
 Owner/operator telephone: (619) 233-0424  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: PACIFIC TREATMENT CORP  
 Owner/operator address: PO BOX 13626  
 SAN DIEGO, CA 92113

Owner/operator country: Not reported  
 Owner/operator telephone: (619) 233-0424  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Accepts waste from (any) off-site source(s)

**Historical Generators:**

Date form received by agency: 03/31/1992  
 Facility name: PACIFIC TREATMENT CORP  
 Site name: PACIFIC TREATMENT CORP. #1  
 Classification: Small Quantity Generator

Date form received by agency: 07/03/1990  
 Facility name: PACIFIC TREATMENT CORP  
 Classification: Large Quantity Generator

Date form received by agency: 02/24/1982  
 Facility name: PACIFIC TREATMENT CORP  
 Classification: Large Quantity Generator

**Corrective Action Summary:**

Event date: 07/01/1988  
 Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 07/01/1988  
 Event: CA029ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Event date:	07/01/1988
Event:	CA049PA
Event date:	07/28/1988
Event:	RFA Completed, Assessment was an RFA.
Event date:	08/01/1988
Event:	CA049SI
Event date:	01/01/1990
Event:	CA029ST
Event date:	08/17/1992
Event:	CA Prioritization, Facility or area was assigned a low corrective action priority.
Event date:	08/17/1992
Event:	Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1- it appears to be technically infeasible or inappropriate (NF) or 2- there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.
Event date:	Not reported
Event:	CA03193

Facility Has Received Notices of Violations:

Regulation violated:	FR - 264.140-150.H
Area of violation:	TSD - Financial Requirements
Date violation determined:	11/23/1994
Date achieved compliance:	11/23/1994
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/23/1994
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	FR - 270
Area of violation:	TSD - General
Date violation determined:	10/24/1990
Date achieved compliance:	02/07/1991
Violation lead agency:	State
Enforcement action:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date:	12/06/1990
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	41500
Paid penalty amount:	41500

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 10/24/1990  
 Date achieved compliance: 02/07/1991  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/06/1990  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 04/11/1990  
 Date achieved compliance: 07/23/1990  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/23/1990  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 03/12/1990  
 Date achieved compliance: 04/11/1990  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 10/31/1989  
 Date achieved compliance: 07/23/1990  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 11/30/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.140-150.H

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Area of violation: TSD - Financial Requirements  
 Date violation determined: 03/29/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 03/22/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268 ALL  
 Area of violation: LDR - General  
 Date violation determined: 03/22/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 08/01/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268 ALL  
 Area of violation: LDR - General  
 Date violation determined: 03/22/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/08/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.140-150.H  
 Area of violation: TSD - Financial Requirements  
 Date violation determined: 03/22/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 03/22/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Date violation determined: 03/22/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/08/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 03/22/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 08/01/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: 55150  
 Final penalty amount: 55150  
 Paid penalty amount: 55150

Regulation violated: FR - 268.7  
 Area of violation: LDR - General  
 Date violation determined: 03/22/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 08/01/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268.7  
 Area of violation: LDR - General  
 Date violation determined: 03/22/1989  
 Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/08/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 03/22/1989

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Date achieved compliance: 03/31/1989  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 08/01/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 270  
 Area of violation: TSD - General  
 Date violation determined: 04/08/1988  
 Date achieved compliance: 11/29/1988  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 06/08/1988  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 270  
 Area of violation: TSD - General  
 Date violation determined: 08/06/1987  
 Date achieved compliance: 10/11/1987  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 09/02/1987  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 270  
 Area of violation: TSD - General  
 Date violation determined: 01/14/1987  
 Date achieved compliance: 03/19/1987  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 01/14/1987  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 01/14/1987  
 Date achieved compliance: 08/06/1987

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/12/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - Financial Requirements  
 Date achieved compliance: 11/23/1994  
 Evaluation lead agency: State

Evaluation date: 11/25/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 10/24/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 02/07/1991  
 Evaluation lead agency: State

Evaluation date: 10/02/1990  
 Evaluation: FINANCIAL RECORD REVIEW  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 04/11/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 07/23/1990  
 Evaluation lead agency: State

Evaluation date: 03/13/1990  
 Evaluation: FINANCIAL RECORD REVIEW  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 03/12/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 04/11/1990  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 10/31/1989  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 07/23/1990

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Evaluation lead agency:	State
Evaluation date:	06/18/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/29/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/22/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	TSD - Financial Requirements
Date achieved compliance:	03/31/1989
Evaluation lead agency:	State
Evaluation date:	03/22/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	LDR - General
Date achieved compliance:	03/31/1989
Evaluation lead agency:	State
Evaluation date:	03/22/1989
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/22/1989
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	TSD - General
Date achieved compliance:	03/31/1989
Evaluation lead agency:	State
Evaluation date:	12/20/1988
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	04/13/1988
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	04/08/1988
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	11/29/1988
Evaluation lead agency:	State
Evaluation date:	04/08/1988



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 09/21/1987  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: EPA

Evaluation date: 08/06/1987  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 08/06/1987  
 Evaluation: NON-FINANCIAL RECORD REVIEW  
 Area of violation: TSD - General  
 Date achieved compliance: 10/11/1987  
 Evaluation lead agency: State

Evaluation date: 01/14/1987  
 Evaluation: NON-FINANCIAL RECORD REVIEW  
 Area of violation: TSD - General  
 Date achieved compliance: 08/06/1987  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 01/14/1987  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 03/19/1987  
 Evaluation lead agency: State

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**CORRACTS:**

EPA ID: CAD095894556  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 07/01/1988  
 Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority  
 NAICS Code(s): Not reported  
 Original schedule date: Not reported  
 Schedule end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

EPA ID: CAD095894556  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 08/17/1992  
 Action: CA225NR - Stabilization Measures Evaluation, This facility is, not amenable to stabilization activity at the, present time for reasons other than (1) it appears to be technically, infeasible or inappropriate (NF) or (2) there is a lack of technical, information (IN). Reasons for this conclusion may be the status of, closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other, administrative considerations  
 NAICS Code(s): Not reported  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CAD095894556  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 08/17/1992  
 Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority  
 NAICS Code(s): Not reported  
 Original schedule date: Not reported  
 Schedule end date: Not reported

**CERC-NFRAP:**

Site ID: 0900179  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: Deferred to RCRA

**CERCLIS-NFRAP Site Contact Name(s):**

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

**CERCLIS-NFRAP Assessment History:**

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 03/01/1988  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 07/01/1988  
 Priority Level: Deferred to RCRA (Subtitle C)

Action: SITE INSPECTION  
 Date Started: Not reported  
 Date Completed: 08/01/1988

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT CORP (Continued)**

**1000249933**

Priority Level: Deferred to RCRA (Subtitle C)

Action: RESOURCE CONSERVATION AND RECOVERY ACT FACILITY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 08/01/1988  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 01/23/1996  
 Priority Level: Not reported

69

**GJS WAREHOUSE  
 2191 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S105539510  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAC002553142  
 Contact: JEREMY WHITE  
 Telephone: 2815793700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 16211 PARK TEN PLACE  
 Mailing City,St,Zip: HOUSTON, TX 77084  
 Gen County: San Diego  
 TSD EPA ID: CAD982444481  
 TSD County: San Bernardino  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 0.3  
 Facility County: San Diego

Gepaid: CAC002553142  
 Contact: JEREMY WHITE  
 Telephone: 2815793700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 16211 PARK TEN PLACE  
 Mailing City,St,Zip: HOUSTON, TX 77084  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Recycler  
 Tons: 0.20  
 Facility County: Not reported

San Diego Co. HMMD:

Facility ID: 101937  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2191 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GJS WAREHOUSE (Continued)**

**S105539510**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/11/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ARMANDO VILLALVAZO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BURKHARD INVESTMENT CO  
 Property Address: C/O DON METELON  
 Property City,St,Zip: 92111  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 10/11/06  
 Facility Phone: 619-232-2408

**HMMD DISCLOSURE INVENTORY:**

Item Number: PR29  
 Chemical Name: PROPANE 6X10 GAL CYLINDERS  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/31/01  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 1454  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 10/11/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GJS WAREHOUSE (Continued)**

**S105539510**

Item Number: 5656  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

69

**CLEANING DYNAMICS  
 2190 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S100232926  
 LUST N/A  
 Cortese**

**HAZNET:**

Gepaid: CAC002284201  
 Contact: BURKHARD INVESTMENT CO INC  
 Telephone: 8587455769  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2630 CHATSWORTH BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921060000  
 Gen County: San Diego  
 TSD EPA ID: AZR000035915  
 TSD County: 99  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .9174  
 Facility County: San Diego

**LUST:**

Region: 9  
 Case Number: 9UT132  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 55  
 Date Found: 05/30/1986  
 How Found: Tank Closure  
 Date Stopped: 05/30/1986  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Remedial action (cleanup) Underway  
 Abate Method: Not reported  
 Confirm Date: 05/30/1986

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CLEANING DYNAMICS (Continued)**

**S100232926**

Submit Workplan: Not reported  
 Prelim Assess: 08/31/1993  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 1/23/87  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 9/1/93  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01225-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 05/30/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2190 MAIN ST

69

**PACIFIC TREATMENT  
 2190 MAIN ST  
 SAN DIEGO, CA 92113**

**Ind. Haz Waste S102746289  
 N/A**

**Ind. Haz Waste:**

Transporters Registration Number: 40957  
 Registration Initial Notification Date: 19860912  
 Registration Last Amendment Date: 20031023  
 EPA Identification: CAD095894556  
 Primary NAICS Code: 484121  
 Status Change Date: 20031023  
 Land Type: Not reported  
 Description of Facility Site Location: 2190 Main St, San Diego, CA  
 Site Primary Standard Industrial Code: 42130  
 Site Primary SIC Description: Trucking, Except Local  
 Registration is Generator of Waste: No  
 Registration is Receivers of Waste: No  
 Registration is Transporter of Waste: Yes  
 Registration is Transfer Facility: No  
 Facility is STEERS Reporter: No  
 Required to Submit Annual Waste Summary: No  
 Facility Involved In Recycling: No  
 Revcr Has Monthly Reporting Requirement: 0  
 Mexican Facility: Does not represent a Maquiladora (Mexican Facility)  
 Facility Status: Inactive  
 Type of Generator: Not reported  
 TNRCC Region Number: Not reported  
 TNRCC Region: Not reported  
 Company Name: Pacific Treatment Corp  
 Contact Name: Michael H Donley  
 Contact Telephone Number: 619-233-0424

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT (Continued)**

**S102746289**

Mailing Address: 2190 Main St  
 Mailing Address2: Not reported  
 Mailing City,St,Zip: San Diego, CA 92113 2299  
 Mailing County: USA  
 Facility County Code: Not reported  
 Facility County: Not reported  
 Facility Country: USA  
 TNRCC Facility ID: 017358  
 Site Owner Tax ID: Not reported  
 Site Location Latitude: Not reported  
 Site Location Longitude: Not reported  
 Last Update to NOR Data: 20040519  
 Ind. waste permit Number: Not reported  
 Mun waste permit Number: Not reported  
 Non Notifier: No  
 Year: 2006

**OWNER:**

Owner Mailing Address: Not reported  
 Owner Mailing Address2: PO Box 13626  
 Owner City,St,Zip: San Diego, CA 92113  
 Owner Country: USA  
 Owner Phone Number: 619-233-0424  
 Owner Fax Number: Not reported  
 Owner Email Address: Not reported  
 Owner Business Type: Unknown  
 Owner Tax Id: Not reported  
 Owner Bankruptcy Code: 0

**OPERATOR:**

Operator Last Name: Pacific Treatment Corp  
 Operator First Name: Not reported  
 Operator Name: Pacific Treatment Corp  
 Operator Mailing Address: Not reported  
 Operator Mailing Address 2: Not reported  
 Operator Mailing City,St,Zip: San Diego, CA 92113  
 Operator Country: USA  
 Operator Phone: 619-233-0424  
 Operator Fax: Not reported  
 Operator Email: Not reported  
 Operator Business Type: Unknown  
 Operator Tax Id: Not reported  
 Operator Bankruptcy Code: 0

**CONTACT:**

Contact Name: Michael H Donley  
 Contact Title: Env Mgr  
 Contact Role: Primary Contact  
 Contact Address: 2190 Main St  
 Contact Address2: Not reported  
 Contact City,St,Zip: San Diego, CA 92113 2299  
 Contact Phone: 619-233-0424  
 Contact Fax: Not reported  
 Contact Email: Not reported  
 Business Desc: 10/23/2003-inactivated due to return mail. cw

**UNIT:**

Unit No: Not reported  
 Unit Type Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT (Continued)**

**S102746289**

Unit Type: Not reported  
 Unit Status: Not reported  
 Unit Regulatory Status: Not reported  
 UIC Permit Number: Not reported  
 Capacity: Not reported  
 Capacity Measurement: Not reported  
 Off Site Hazardous Waste: No  
 Off Site Class 1 Waste: Not reported  
 Off Site Class 2 Waste: Not reported  
 Off Site Class 3 Waste: Not reported  
 Off Site Non Indstrl Sld Wst: Not reported  
 System Type Code: Not reported  
 System Type: Not reported  
 System Type Code 1: Not reported  
 System Type 1: Not reported  
 System Type Code 2: Not reported  
 System Type 2: Not reported  
 System Type Code 3: Not reported  
 System Type 3: Not reported  
 System Type Code 4: Not reported  
 System Type 4: Not reported  
 Permit Seq #: Not reported  
 Waste Desc: Not reported  
 Dt Last Changed: Not reported  
 WasteID: ,

**ACTIVITY:**

Activity Type Involves: Not reported  
 Activity Desc: Not reported

**OTS:**

Site Name: Not reported  
 One-time Shipper ID: Not reported  
 Location Desc: Not reported  
 Location Address: Not reported  
 Location Address 2: Not reported  
 Location City: Not reported  
 Location Zip: Not reported  
 Broker Name: Not reported  
 EPA Waste Source Code: Not reported  
 EPA System Type Code: Not reported  
 EPA Form: Not reported  
 EPA Waste No: Not reported  
 Broker Phone: Not reported  
 Date Processing Complete: Not reported  
 Date Request Sent: Not reported  
 Company Name: Not reported  
 Waste ID: Not reported  
 Waste Form: Not reported  
 Waste Class: Not reported  
 Waste Origin Code: Not reported  
 Shipment Request ID: Not reported  
 Waste Code Audited: Not reported

**RCV:**

Waste Receipts Summary Form Code: Not reported  
 State Manifest Documentaion Number: Not reported  
 Generators TX Registration Number: Not reported  
 Generators EPA ID: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TREATMENT (Continued)**

**S102746289**

Generators Waste Code:	Not reported
Generators Waste Classification:	Not reported
Generators Waste Form Code:	Not reported
Generators Waste Form:	Not reported
Quantity Shipped:	Not reported
Units:	Not reported
How Waste Handled by Receivers:	Not reported
Receivers Date:	Not reported
Transporters Registration Number:	Not reported
Shipment Comment:	Not reported
EPA Haz Waste:	Not reported
EPA Haz Waste:	Not reported
EPA Haz Waste:	Not reported
EPA Haz Waste:	Not reported
Receiver Name:	Not reported
Reporting method:	Not reported
No Shipmnts Recvd In Rept Period:	Not reported
Record Creation Date:	Not reported
Record Contains Error:	Not reported
Record ID:	Not reported
Co. Submitting Report:	Not reported
Authorized Agent Submitting Report:	Not reported
Authorized Agent Title:	Not reported
<b>ANNUAL:</b>	
Waste Code:	Not reported
Waste Class:	Not reported
Generators Waste Form Code:	Not reported
Generators Waste Form:	Not reported
Texas Waste Code:	Not reported
Quantity Shipped:	Not reported
Unit Quantity Handled:	Not reported
More than 1.1 Tons Waste Gen:	Not reported
More than 2.2 lbs Acute Waste Gen:	Not reported
How Waste Handled By Recievers:	Not reported
Facility Id:	Not reported
EPA Identification:	Not reported
Comments:	Not reported
EPA Waste Code:	Not reported
EPA Haz Waste:	Not reported
DEF Code1:	Not reported
EPA Haz Waste:	Not reported
DEF Code2:	Not reported
EPA Haz Waste:	Not reported
DEF Code3:	Not reported
EPA Haz Waste:	Not reported
Unit Quantity Handled:	Not reported
Fee Exemption Request:	Not reported
Resolution of Exemption Request:	Not reported
Report Required:	Not reported
Record Creation Date:	Not reported
Record Contains Error:	Not reported
Reporting method:	Not reported
Record ID:	Not reported
Co. Submitting Report:	Not reported
Authorized Agent Submitting Report:	Not reported
Authorized Agent Title:	Not reported
Total Qty Generated:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TREATMENT (Continued)**

**S102746289**

WASTE:

Waste ID: Not reported  
 Waste Desc Yr: Not reported  
 Waste Descriptn: Not reported  
 Desc of Waste: Not reported  
 Texas Waste Code: Not reported  
 Texas Waste Code 2: Not reported  
 Waste Code Status: Not reported  
 Waste Form Code: Not reported  
 Waste Form: Not reported  
 Waste Classification: Not reported  
 Waste is Radioactive: Not reported  
 Waste Treated Off Site: Not reported  
 Primary Standard Industrial Code: Not reported  
 Standard Industrial Classification: Not reported  
 Primary Source: Not reported  
 Primary Source: Not reported  
 Primary Measurement Point Code: Not reported  
 Primary Measurement Point: Not reported  
 Primary Origin Code: Not reported  
 Primary Origin: Not reported  
 Primary System Type Code: Not reported  
 Primary System Type: Not reported  
 New Chemical Substance: Not reported  
 Audit Performed: Not reported  
 Company Waste ID: Not reported  
 Primary NAICS Code: Not reported  
 EPA Waste Form Code: Not reported  
 Reason Waste Form No Longer Gen.: Not reported  
 EPA Haz Waste: Not reported

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW: detail in the EDR Site Report.

69

**CLEANING DYNAMICS/PACIFIC TREATMENT CORP  
 2190 MAIN STREET  
 SAN DIEGO, CA 92113**

**ENVIROSTOR S101481980  
 N/A**

ENVIROSTOR:

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37420008  
 Site Code: 600268  
 Assembly: 79  
 Senate: 40  
 Special Program: \* CERC2  
 Status: Refer: RCRA  
 Status Date: 1995-08-21 00:00:00  
 Restricted Use: NO  
 Funding: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CLEANING DYNAMICS/PACIFIC TREATMENT CORP (Continued)**

**S101481980**

Latitude: 32.6955555555556  
 Longitude: -117.141944444444  
 Alias Name: 37420008  
 CAD095894556  
 600268  
 Alias Type: Envirostor ID Number  
 Project Code (Site Code)  
 EPA Identification Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: "Site Closure Plan approved on 09/17/1991, undergoing closure oversight. Facility will submit workplan for arsenic contamination removal and HRA in 94/95. According to AWP, closure to be completed in 94/95 FY. Staff recommends NFA for Site MitigaSITE SCREENING DONE  
 DHS RECOMMENDATION: PENDING STATUS THE FACILITY IS CURRENTLY REGULATED BY STATE DHS AS A HAZ WASTE TSD FACILITY AND SHOULD CONTINUE ROUTINE TSD INSPECT. CONTINUED ENFORCEMENT BY THE SURVEILL - AND ENFORCEMENT UNIT IS RECOMMENDED.E&E REVIEW OF DHS PA RECOMMENDS NFA FOR EPA DUE TO NO GROUNDWATER TARGETS. DTSC STATUS NEEDS TO BE DETERMINED.FACILITY IDENTIFIED VIA S.D. METRO. INDUSTRIAL WASTE DIV.PRELIM ASSESS DONE SI MED RECOMMENDED TO CHECK FOR THE EVIDENCE OF CONTAMINATIONSITE SCREENING DONE RATIONALE FOR PA: OBVIOUS SIGNS OF HAZ WASTE SPILLAGE; EXTENT OF CONTAM REQ.tion Branch."

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 10/27/94

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 09/19/88

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 05/23/88

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 03/01/88

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 09/26/86

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 04/20/83

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CLEANING DYNAMICS/PACIFIC TREATMENT CORP (Continued)**

**S101481980**

Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 10002, 10003, 10009, 10037, 10060, 10097, 10180, 10185, 10193, 10196, 10198, 10199, 20002, 30013, 30108, 30153, 30407

Potenital Description: \* HALOGENATED ORGANIC COMPOUNDS  
 Potenital Description: \* HALOGENATED SOLVENTS  
 Potenital Description: \* HYDROCARBON SOLVENTS  
 Potenital Description: \* Metals - Sludge  
 Potenital Description: \* OIL/WATER SEPARATION SLUDGE  
 Potenital Description: \* CONTAMINATED SOIL  
 Potenital Description: \* Sludge - Sewage  
 Potenital Description: \* TANK BOTTOM WASTES  
 Potenital Description: \* UNSPECIFIED ACID SOLUTION  
 Potenital Description: \* UNSPECIFIED OIL CONTAINING WASTE  
 Potenital Description: \* UNSPECIFIED SOLVENT MIXTURES  
 Potenital Description: \* WASTE OIL & MIXED OIL  
 Potenital Description: \* AQUEOUS SOLUTION 2<PH<12.5, WITH REACTIVE ANIONS  
 Potenital Description: Lead  
 Potenital Description: Cadmium and compounds  
 Potenital Description: Chromium VI  
 Potenital Description: Nickel

Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

69

**AMERICAN KELP  
 2190 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**LUST S106059746  
 N/A**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Tank  
 Global Id: T0607300187  
 Stop Date: 1986-05-30 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1995-09-27 00:00:00  
 Remed Action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN KELP (Continued)**

**S106059746**

Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1986-05-30 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-05-30 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: YALE COMBS  
 RP Address: P O BOX 307  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: KK  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01225-001  
 Case Number: 9UT132  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 101225  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: TERRELL KAUCHER  
 Mailing Address: P O BOX 370178  
 Mailing City,St,Zip: SAN DIEGO, CA 92137

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN KELP (Continued)**

**S106059746**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/11/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: PATRICK OSIO, MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BURKHARD INVESTMENT CO  
 Property Address: C/O DON METELON  
 Property City,St,Zip: 92111  
 Tank Owner: CLEANING DYNAMICS  
 Tank Address: 2190 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-7231

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT0255-1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: AT0255-2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: AT0255-3  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: AT0255-4

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN KELP (Continued)**

**S106059746**

Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T005  
 Tank ID Number: AT2473  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H01225-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: POP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Post Remedial Monitoring  
 Date: 8/3/2003  
 Begandt: 5/30/1986

Case Number: H01225-002  
 Agency: CA Department of Toxic Substance Control  
**Funding: Non Billable**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/20/1991  
 Begandt: 5/30/1986

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**69      COMMERCIAL FLEET SERVICE  
 2191 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106063623  
 N/A**

San Diego Co. HMMD:

Facility ID:	132672
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2191 MAIN ST #5
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	50
EPA ID:	CAL000012758
Gas Station:	Not reported
Inspection Date:	07/29/97
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	MICHAEL LYONS
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	SAMPSON CADILLAC L L C
Property Address:	C/O BOB SHAPIRO
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-238-8170

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COMMERCIAL FLEET SERVICE (Continued)**

**S106063623**

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

69

**SHREVE & HAYS  
 2191 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S105539616  
 SWEEPS UST N/A**

San Diego Co. HMMD:

Facility ID: 121488  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2191 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAMPSON CADILLAC L L C  
 Property Address: C/O BOB SHAPIRO

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHREVE & HAYS (Continued)**

**S105539616**

Property City,St,Zip: 92113  
 Tank Owner: SHREVE & HAYS  
 Tank Address: 2191 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 858-569-7777

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21488  
 Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHREVE & HAYS (Continued)**

**S105539616**

Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021488-000001  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 1

**69 SUNSHINE TRUCK & AUTO BODY  
 2191 MAIN ST #4  
 SAN DIEGO, CA 92117**

**HAZNET S103642433  
 N/A**

HAZNET:

Gepaid: CAD981404296  
 Contact: YVONNE STANG  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2191 MAIN ST #4  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .1365  
 Facility County: San Diego

**69 MARINE BARGE SERVICES INC  
 2146 MAIN ST  
 SAN DIEGO, CA 92113**

**FINDS 1000256323  
 RCRA-NonGen CAD121705354**

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RCRA-NonGen:

Date form received by agency: 08/26/1986  
 Facility name: MARINE BARGE SERVICES INC  
 Facility address: 2146 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD121705354  
 Mailing address: MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE BARGE SERVICES INC (Continued)**

**1000256323**

Contact: SAN DIEGO, CA 92113  
 ENVIRONMENTAL MANAGER  
 Contact address: 2146 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 233-0863  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: MARINE BARGE SER INC  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**69 CLEANING DYNAMICS CORP  
 2146 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000152621  
 FINDS CAD980886360  
 CERC-NFRAP**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: CLEANING DYNAMICS CORP  
 Facility address: 2146 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD980886360  
 Mailing address: PO BOX 13567  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CLEANING DYNAMICS CORP (Continued)**

**1000152621**

Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 08/06/1985  
 Facility name: CLEANING DYNAMICS CORP  
 Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 06/06/1986  
 Date achieved compliance: 06/06/1991  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 06/06/1986  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/06/1986  
 Evaluation: NON-FINANCIAL RECORD REVIEW  
 Area of violation: Generators - General  
 Date achieved compliance: 06/06/1991  
 Evaluation lead agency: State Contractor/Grantee

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CERC-NFRAP:

Site ID: 0900048  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CLEANING DYNAMICS CORP (Continued)**

**1000152621**

Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 12/01/1987  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 11/10/1988  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 11/10/1988  
 Priority Level: NFRAP (No Futher Remedial Action Planned)

69

**E.J. FERGUSON'S  
 2146 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S100941780  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAD095894556  
 Contact: PETER J MCCOY, ASST SECRETARY  
 Telephone: 6192229613  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: AC LIQUADATING CORP  
 Mailing City,St,Zip: SANTEE, CA 920710000  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: .0208  
 Facility County: San Diego

Gepaid: CAD095894556  
 Contact: PETER J MCCOY, ASST SECRETARY  
 Telephone: 6192229613  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: AC LIQUADATING CORP  
 Mailing City,St,Zip: SANTEE, CA 920710000  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**E.J. FERGUSON'S (Continued)**

**S100941780**

TSD County: San Diego  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Transfer Station  
 Tons: .0416  
 Facility County: San Diego

Gepaid: CAD095894556  
 Contact: PETER J MCCOY, ASST SECRETARY  
 Telephone: 6192229613  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: AC LIQUADATING CORP  
 Mailing City,St,Zip: SANTEE, CA 920710000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: .1500  
 Facility County: San Diego

Gepaid: CAD095894556  
 Contact: PETER J MCCOY, ASST SECRETARY  
 Telephone: 6192229613  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: AC LIQUADATING CORP  
 Mailing City,St,Zip: SANTEE, CA 920710000  
 Gen County: San Diego  
 TSD EPA ID: IRC957100891  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 38.0000  
 Facility County: San Diego

Gepaid: CAD095894556  
 Contact: PETER J MCCOY, ASST SECRETARY  
 Telephone: 6192229613  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: AC LIQUADATING CORP  
 Mailing City,St,Zip: SANTEE, CA 920710000  
 Gen County: San Diego  
 TSD EPA ID: UTD991301748  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .6000  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:  
 Facility ID: 102608  
 Inactive Indicator: Active



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**E.J. FERGUSON'S (Continued)**

**S100941780**

Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2146 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD980886360  
 Gas Station: Not reported  
 Inspection Date: 11/10/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: EMERY FERGUSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DUEA DAVID J&MARY J REVOCABLE  
 Property Address: 7786 SIERRA MAR DR  
 Property City,St,Zip: 92037  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/10/05  
 Facility Phone: 619-233-1243

**HMMD DISCLOSURE INVENTORY:**

Item Number: EP67  
 Chemical Name: EPOXY COATINGS, RESIN, ADHESIVES  
 Case Number: 25068-38-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: ET62  
 Chemical Name: ETHANOL  
 Case Number: 64-17-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**E.J. FERGUSON'S (Continued)**

**S100941780**

Item Number: NA68  
 Chemical Name: NAPHTHA, ALKYD PAINT THINNER  
 Case Number: 6472-95-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PA70  
 Chemical Name: PAINT, MARINE, TRAFFIC, ANTIFOULANT  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PA66  
 Chemical Name: PAINTS, LATEX  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PO65  
 Chemical Name: POLYAMIDE RESIN, ADHESIVE, VERSAMID  
 Case Number: 6841-02-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: RU63  
 Chemical Name: RUSTLICK (HEXYLENE GLYCOL 107-41-5\_  
 Case Number: 107-41-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**E.J. FERGUSON'S (Continued)**

**S100941780**

1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: ZI64  
 Chemical Name: ZINC, DUST 100%, DIMETCOTE  
 Case Number: 1314-13-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/10/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1131  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/10/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 1132  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**69 MARINE BARGE SERVICES INC  
 2146 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-NonGen 1000256329  
 CAD981396260**

RCRA-NonGen:

Date form received by agency: 04/21/1986  
 Facility name: MARINE BARGE SERVICES INC  
 Facility address: 2146 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981396260  
 Mailing address: MAIN ST  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2146 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 233-0863  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
  
 Owner/operator name: MARINE BARGE SERVICES  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**MARINE BARGE SERVICES INC (Continued)**

**1000256329**

Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**69 MAIN STREET YARD  
 2141 MAIN ST  
 SAN DIEGO, CA 92101**

**HIST UST U001572579  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000063881  
 Facility Type: Other  
 Other Type: UTILITY  
 Total Tanks: 0000  
 Contact Name: FLEET MAINTENANCE  
 Telephone: 6196962000  
 Owner Name: SAN DIEGO GAS & ELECTRIC COMPA  
 Owner Address: 101 ASH STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
 Container Num: 801  
 Year Installed: 1965  
 Tank Capacity: 00006000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002  
 Container Num: 802  
 Year Installed: 1970  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: None

**69 TANK #801 & #802 \*  
 2141 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST S102438395  
 Cortese N/A  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302745  
 Stop Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TANK #801 & #802 \* (Continued)**

**S102438395**

Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1994-10-13 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: JOHN DAWSEY  
 RP Address: PO BOX 1831  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15419-001  
 Case Number: 9UT439  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:TIAJUANA VALLEY COMMUNITY WATER DISTRICT  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: W0607310043  
 Waste Disch Assigned Name: 3710043-001  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT439  
 Local Agency: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TANK #801 & #802 \* (Continued)**

**S102438395**

Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 07/02/1986  
 How Found: Tank Closure  
 Date Stopped: 07/02/1986  
 How Stopped: Remove Contents  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Regional Board  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Enhanced Biodegradation - use of any available technology to promote bacterial decomposition of contaminants  
 Confirm Date: 07/02/1986  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: 07/31/1987  
 Remed Action: 4/1/87  
 Began Monitor: 10/1/90  
 Enforce Type: Cleanup and Abatement Orders  
 Enforce Date: 8/1/89  
 Closed Date: 4/29/93  
 Pilot Program: UST  
 Local Case: H15419-001  
 Basin Number: 908.22  
 Gwater Depth: 32'  
 Beneficial Use: NBNB/EISW  
 NPDES Number: Not reported  
 priority: LOP/LOW - LOW POTENTIAL HEALTH/SAFTY/ENVIRONMENTAL IMPACT  
 File Disp: Not reported  
 Release Date: 06/24/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: 89-063  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2141 MAIN ST

**San Diego Co. HMMD:**

Facility ID: 105871  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TANK #801 & #802 \* (Continued)**

**S102438395**

Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO GAS&ELECTRIC CO  
 Property Address: CALIFORNIA STATE ASS  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TANK #801 & #802 \* (Continued)**

**S102438395**

Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 115419  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 1831  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO GAS&ELECTRIC CO  
 Property Address: CALIFORNIA STATE ASS  
 Property City,St,Zip: 00000  
 Tank Owner: SAN DIEGO GAS & ELECTRIC COMPA  
 Tank Address: 101 ASH ST  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-2414

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TANK #801 & #802 \* (Continued)**

**S102438395**

HMMD UNDERGROUND TANKS:

Tank Number: T001  
 Tank ID Number: 801  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 802  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SWEEPS UST:

Status: Not reported  
 Comp Number: 15419  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015419-000001  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TANK #801 & #802 \* (Continued)**

**S102438395**

Comp Number: 15419  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015419-000002  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 15419  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H15419-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/13/1994  
 Begandt: 7/2/1986

69

**SDG&E TANKS 801 & 802**  
**2141 MAIN ST**  
**SAN DIEGO, CA 92102**

**RCRA-SQG 1000137441**  
**FINDS CAD982518250**

**RCRA-SQG:**

Date form received by agency: 09/01/1996  
 Facility name: SDG&E TANKS 801 & 802  
 Facility address: 2141 MAIN ST  
 SAN DIEGO, CA 92102  
 EPA ID: CAD982518250  
 Mailing address: P O BOX 1831 /ENVIRONMENTAL  
 SAN DIEGO, CA 92112  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SDG&E TANKS 801 & 802 (Continued)**

**1000137441**

Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: SAN DIEGO GAS & ELECTRIC  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 01/12/1990  
 Facility name: SDG&E TANKS 801 & 802  
 Classification: Large Quantity Generator

Violation Status: No violations found

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**SDG&E TANKS 801 & 802 (Continued)**

**1000137441**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

69

**EARL INDUSTRIES, LLC  
2102 MAIN ST  
SAN DIEGO, CA 92113**

**HAZNET S103547774  
San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAL000140871  
 Contact: GARY LORENTZEN/SAFTY MGR  
 Telephone: 6192380074  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Polychlorinated biphenyls and material containing PCB's  
 Disposal Method: Treatment, Incineration  
 Tons: 0  
 Facility County: Not reported

Gepaid: CAL000140871  
 Contact: GARY LORENTZEN/SAFTY MGR  
 Telephone: 6192380074  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: 0.29  
 Facility County: Not reported

Gepaid: CAL000140871  
 Contact: GARY LORENTZEN/SAFTY MGR  
 Telephone: 6192380074  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EARL INDUSTRIES, LLC (Continued)**

**S103547774**

Disposal Method: Recycler  
 Tons: 0.45  
 Facility County: Not reported

Gepaid: CAL000140871  
 Contact: GARY LORENTZEN/SAFTY MGR  
 Telephone: 6192380074  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Treatment, Tank  
 Tons: 0.45  
 Facility County: Not reported

Gepaid: CAL000140871  
 Contact: GARY LORENTZEN/SAFTY MGR  
 Telephone: 6192380074  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Treatment, Tank  
 Tons: 0.22  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 22 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 138321  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000140871  
 Gas Station: Not reported  
 Inspection Date: 03/27/02  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EARL INDUSTRIES, LLC (Continued)**

**S103547774**

Facility Contact: GARY LORENTZEN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DUEA DAVID J&MARY J REVOCABLE  
 Property Address: 7786 SIERRA MAR DR  
 Property City,St,Zip: 92037  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-0074

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/03/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9150  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 03/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 6105  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 03/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 6106  
 Violation Desc: HMBP: INADEQUATE SITE MAP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EARL INDUSTRIES, LLC (Continued)**

**S103547774**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203502  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2227 FELTON ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92104  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD981664097  
 Gas Station: Not reported  
 Inspection Date: 05/17/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JENNIFER METZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DUEA DAVID J&MARY J REVOCABLE  
 Property Address: 7786 SIERRA MAR DR  
 Property City,St,Zip: 92037  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 11/17/05  
 Facility Phone: 619-236-0686

**HMMD DISCLOSURE INVENTORY:**

Item Number: PA90  
 Chemical Name: PAINT: FRAZEE OIL BASE, LACQUER THINNER MIXTURE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EARL INDUSTRIES, LLC (Continued)**

**S103547774**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 05/17/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 50  
 Annual Qty String: 50  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0971 PACIFIC COAST LACQUE  
 Waste Desc: PAINT BOOTH FILTERS  
 Carcinogen: No

Inspection Date: 05/17/04  
 Waste Item #: 30  
 Waste Code: 30  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 7  
 Quantity String: 7  
 Annual Qty: 15  
 Annual Qty String: 15  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0971 PACIFIC COAST LACQUE  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**69 TRIMM WOODWORKING INC  
 2102 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S108223226  
 N/A**

HAZNET:  
 Gepaid: CAL000280248  
 Contact: CHRISTINA SEVILLA OFFICE MGR  
 Telephone: 6192360686  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2102 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.06  
 Facility County: Not reported

**70 PORT OF SAN DIEGO  
 1875 WATER ST  
 SAN DIEGO, CA 92101**

**LUST S101302186  
 Cortese N/A  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303164  
 Stop Date: 1974-01-01 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-12-05 00:00:00  
 Discover Date: 1974-01-01 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-02-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT OF SAN DIEGO (Continued)**

**S101302186**

Contact Person: Not reported  
 Responsible Party: ATTN: MR. RALPH HICKS  
 RP Address: PO BOX 488  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H24706-001  
 Case Number: 9UT921  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608133034  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1996-12-04 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1996-12-04 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT OF SAN DIEGO (Continued)**

**S101302186**

Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Not reported  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H24706-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT921  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 02/23/1988  
 How Found: Other Means  
 Date Stopped: 01/01/1974  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 11/02/1987  
 Submit Workplan: Not reported  
 Prelim Assess: 03/10/1988  
 Desc Pollution: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT OF SAN DIEGO (Continued)**

**S101302186**

Remed Plan: 05/26/1992  
 Remed Action: 11/5/92  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/5/96  
 Pilot Program: LOP  
 Local Case: H24706-001  
 Basin Number: 908.22  
 Gwater Depth: 7.0'  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 03/01/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 1875 WATER ST

San Diego Co. HMMD:

Facility ID: 124706  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 488  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 51  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE TILLEY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: SAN DIEGO UNIFIED PORT DIST  
 Tank Address: P O BOX 488  
 Tank City,St,Zip: San Diego, CA 92112  
 Business Plan Acceptance Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PORT OF SAN DIEGO (Continued)**

**S101302186**

Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT2659  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: AT2659  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: AT2659  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: AT2659  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PORT OF SAN DIEGO (Continued)**

**S101302186**

Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H24706-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Drinking Water Aquifer Impacted  
 FStatus: Closed Case  
 Date: 12/5/1996  
 Begandt: 1/1/1974

Case Number: H24706-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Preliminary Assessment  
 Date: 12/4/1996  
 Begandt: 12/4/1996

71 **CALIFORNIA CARPET CLEANERS INTERIOR SERVICES**  
**3356 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**DRYCLEANERS S108540613**  
**N/A**

**CLEANERS:**

EPA Id: CAL000320905  
 NAICS Code: 99999  
 NAICS Description: Not Otherwise Specified  
 Create Date: 6/18/2007  
 Facility Active: Yes  
 Inactive Date: Not reported  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3356 NATIONAL AVE  
 Mailing Address 2: Not reported  
 Mailing State: CA  
 Mailing Zip: 92113  
 Region Code: 4  
 Owner Name: LEONARD SMITH  
 Owner Address: 4820 ZION AVE  
 Owner Address 2: Not reported  
 Owner Telephone: Not reported  
 Owner Fax Number: Not reported  
 Contact Name: LEONARD SMITH  
 Contact Address: 3356 NATIONAL AVE  
 Contact Address 2: Not reported  
 Contact Telephone: 6192327519  
 Contact Fax Number: Not reported  
 SIC Description: 9999 Not Otherwise Specified

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

71 **COOL RADIATOR SHOP**  
**3362 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000274849**  
**FINDS CAD982007189**  
**HAZNET**  
**San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: COOL RADIATOR SHOP  
 Facility address: 3362 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982007189  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CONRADO C GARCIA  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**COOL RADIATOR SHOP (Continued)**

**1000274849**

Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 06/02/1987  
 Facility name: COOL RADIATOR SHOP  
 Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD982007189  
 Contact: CONRADO GARCIA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3362 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .0625  
 Facility County: San Diego

Gepaid: CAD982007189  
 Contact: CONRADO GARCIA  
 Telephone: 6192369565  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3362 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: WAD991281767  
 TSD County: 99  
 Waste Category: Household waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.04  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COOL RADIATOR SHOP (Continued)**

**1000274849**

Gepaid: CAD982007189  
 Contact: CONRADO GARCIA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3362 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .0350  
 Facility County: San Diego

Gepaid: CAD982007189  
 Contact: CONRADO GARCIA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3362 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .0385  
 Facility County: San Diego

Gepaid: CAD982007189  
 Contact: CONRADO GARCIA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3362 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: .0150  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 112498  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3362 NATIONAL AV

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COOL RADIATOR SHOP (Continued)**

**1000274849**

Mailing City,St,Zip: SAN DIEGO, CA 92020  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAD000082496  
 Gas Station: Not reported  
 Inspection Date: 12/16/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: CONRADO GARCIA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ALAMO DRIVE LIMITED PARTNERSHI  
 Property Address: 4644 ALAMO DR  
 Property City,St,Zip: 92115  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/16/06  
 Facility Phone: 619-236-9565

**HMMD DISCLOSURE INVENTORY:**

Item Number: OX74  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/25/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 4389  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

**HMMD WASTE STREAMS:**

Inspection Date: 12/16/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COOL RADIATOR SHOP (Continued)**

**1000274849**

Waste Item #: 121  
 Waste Code: 121  
 Waste Name: ALKALINE SOL'N WITH  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 4148 ANTIFREEZE DELIVERY  
 Waste Desc: COOLANT RECYCLED  
 Carcinogen: No

Inspection Date: 12/16/04  
 Waste Item #: 171  
 Waste Code: 171  
 Waste Name: METAL SLUDGE  
 Qnty at Inspection: 50  
 Quantity String: 50  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: CAN  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: WORK TANK SLUDGE  
 Carcinogen: No

71

**SUNSHINE TRUCK WORKS  
 3361 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000597880  
 FINDS CAD983619156  
 San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 02/17/1992  
 Facility name: SUNSHINE TRUCK WORKS  
 Facility address: 3361 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD983619156  
 Mailing address: NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact: BOB STANG  
 Contact address: 3361 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 233-3996  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SUNSHINE TRUCK WORKS (Continued)**

**1000597880**

Owner/operator name: ROBERT STANG  
 Owner/operator address: 3361 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 233-3996  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**San Diego Co. HMMD:**

Facility ID: 100632  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3361 NATIONAL AVE  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNSHINE TRUCK WORKS (Continued)**

**1000597880**

Inspection Date: 08/07/92  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: ROBERT STANG  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BARTOLINI SERGIO TR&BARTOLINI  
 Property Address: 1625 COOLIDGE AVE  
 Property City,St,Zip: 91950  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-3996

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNSHINE TRUCK WORKS (Continued)**

**1000597880**

Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

71

**MARTINEZ AUTO REPAIR  
 3369 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104754413  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301511  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-01-25 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARTINEZ AUTO REPAIR (Continued)**

**S104754413**

Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H34416-001  
 Case Number: 9UT2755  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 134416  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3369 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 05/02/00  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MIGUEL MARTINEZ HERNANDEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-531-7003

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARTINEZ AUTO REPAIR (Continued)**

**S104754413**

Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 001  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H34416-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 1/25/1996  
 Begandt: 5/12/1994

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**71 ADAMS COMMERCIAL PROPERTY  
 3369 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S102423692  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT2755  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 05/12/1994  
 How Found: Tank Closure  
 Date Stopped: 05/12/1994  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 05/18/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/25/96  
 Pilot Program: LOP  
 Local Case: H34416-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 05/12/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 3369 NATIONAL AVE

**71 J & R RECYCING  
 3374 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**SWRCY S107137154  
 N/A**

SWRCY:

Certification Status: O  
 Facility Phone Number: (619) 235-8010  
 Date facility became certified: 09/14/07  
 Date facility began operating: 12/01/07  
 Date facility ceased operating: Still operating  
 Whether The Facility Is Grandfathered: Not reported  
 Convenience Zone Where Facility Located: 2069

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**J & R RECYCLING (Continued)**

**S107137154**

Convenience Zone Where Facility Located 2: 4204  
 Convenience Zone Where Facility Located 3: 0  
 Convenience Zone Where Facility Located 4: 0  
 Convenience Zone Where Facility Located 5: 0  
 Convenience Zone Where Facility Located 6: 0  
 Convenience Zone Where Facility Located 7: 0  
 Aluminum Beverage Containers Redeemed: AL  
 Glass Beverage Containers Redeemed: GL  
 Plastic Beverage Containers Redeemed: PL  
 Other mat beverage containers redeemed: Not reported  
 Refillable Beverage Containers Redeemed: Not reported

Certification Status: D  
 Facility Phone Number: (619) 235-8010  
 Date facility became certified: 12/24/92  
 Date facility began operating: 01/15/93  
 Date facility ceased operating: 11/30/07  
 Whether The Facility Is Grandfathered: Not reported  
 Convenience Zone Where Facility Located: 2069  
 Convenience Zone Where Facility Located 2: 4204  
 Convenience Zone Where Facility Located 3: 0  
 Convenience Zone Where Facility Located 4: 0  
 Convenience Zone Where Facility Located 5: 0  
 Convenience Zone Where Facility Located 6: 0  
 Convenience Zone Where Facility Located 7: 0  
 Aluminum Beverage Containers Redeemed: AL  
 Glass Beverage Containers Redeemed: GL  
 Plastic Beverage Containers Redeemed: PL  
 Other mat beverage containers redeemed: Not reported  
 Refillable Beverage Containers Redeemed: Not reported

72

**U.S.A. PETROLEUM  
 3502 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S101302108  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT1918  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 02/20/1991  
 How Found: Other Means  
 Date Stopped: 02/20/1991  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 02/20/1991  
 Submit Workplan: Not reported  
 Prelim Assess: 02/20/1991  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S.A. PETROLEUM (Continued)**

**S101302108**

Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H03879-002  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 02/20/1991  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3502 NATIONAL AVE

72

**USA GASOLINE CORP #50**  
**3502 NATIONAL AV**  
**SAN DIEGO, CA 92113**

**LUST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**S104745811**  
**N/A**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Tank  
 Global Id: T0607300248  
 Stop Date: 1989-03-31 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-09-28 00:00:00  
 Discover Date: 1989-03-31 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-03-31 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Chuck Miller  
 RP Address: 905 Rancho Conejo Blvd.  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 2  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03879-001  
 Case Number: 9UT1409  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Spill  
 Leak Source: D  
 Global Id: T0607300697  
 Stop Date: 1991-02-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-09-28 00:00:00  
 Discover Date: 1991-02-20 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-02-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Ms. Joyce Salamy  
 RP Address: 905 Rancho Conejo Blvd.  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 2  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03879-002  
 Case Number: 9UT1918  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608122950  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Close Date: 1994-05-25 00:00:00  
 Discover Date: 1993-01-27 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1993-01-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03879-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 103879  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: C I DIAZ  
 Mailing Address: 30101 AGOURA CT #20  
 Mailing City,St,Zip: AGOURA HILLS, CA 91301  
 Map Code/Business Plan on File: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 35  
 EPA ID: CAL922104902  
 Gas Station: Not reported  
 Inspection Date: 11/20/03  
 Reinspection Date: Not reported  
 Inspector Name: 6HR204  
 Violation Notice Issued: Not reported  
 Facility Contact: DANIEL CABALLERO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: AJALAT-SALAMY  
 Property Address: 4315 CLYBOURN AVE  
 Property City,St,Zip: 91602  
 Tank Owner: USA PETROLEUM #50  
 Tank Address: PO BOX 1839  
 Tank City,St,Zip: Santa Monica, CA 90401  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-237-9381

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

Tank Number: T003  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T004  
 Tank ID Number: 4 WASTE OI  
 Waste or Product: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Tank Contents: Not reported  
 Tank Number: T005  
 Tank ID Number: nt2239  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T006  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T007  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 12/03/87  
 Waste Code: Not reported  
 Type of Violation: 6HX3002  
 Occurrences: Not reported  
 Item Number: 6514  
 Violation Desc: UST OWNR-OPR W/O HEALTH PERMIT

Inspection Date: 12/03/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0084  
 Occurrences: Not reported  
 Item Number: 6515  
 Violation Desc: UST PRECISION TEST DATA NOT SENT TO HMMD

Inspection Date: 07/02/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5970  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/02/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 5971  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 07/02/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 5972  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 09/21/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Item Number: 8393  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 12/14/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2118  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/14/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 2119  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 12/14/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 2120  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 12/14/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 2121  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 12/14/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3028  
 Occurrences: Not reported  
 Item Number: 2122  
 Violation Desc: UST RESPONSE PLAN NOT AVAILABLE

Inspection Date: 12/14/01  
 Waste Code: Not reported  
 Type of Violation: 6HX3029  
 Occurrences: Not reported  
 Item Number: 2123  
 Violation Desc: SPILL/OVERFILL PREVENTION NOT INSTALLED

Inspection Date: 06/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3112  
 Occurrences: Not reported  
 Item Number: 1476  
 Violation Desc: 2NDRY CONT TEST NOT DONE (6/36 MOS.)

Inspection Date: 06/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3251  
 Occurrences: Not reported  
 Item Number: 1477

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Violation Desc: MONITOR IN ALARM AT START OF INSPECTION

Inspection Date: 06/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 1478  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 06/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 1479  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 06/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 1480  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 06/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1481  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 06/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 1482  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 202741  
 Inactive Indicator: Active  
 Business Code: 6HK28

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ATTN: JENNIFER TALBERT  
 Mailing Address: 16868 A ST  
 Mailing City, St, Zip: Huntington Beac, CA 92647  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 35  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/22/04  
 Reinspection Date: Not reported  
 Inspector Name: WMARTINE  
 Violation Notice Issued: Not reported  
 Facility Contact: AMERICA MUNIZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: AJALAT-SALAMY  
 Property Address: 4315 CLYBOURN AVE  
 Property City, St, Zip: 91602  
 Tank Owner: G & M OIL, INC  
 Tank Address: 16868 A STREET  
 Tank City, St, Zip: Huntington Beac, CA 92647  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/22/05  
 Facility Phone: 619-237-9381

**HMMD DISCLOSURE INVENTORY:**

Item Number: DI97  
 Chemical Name: DIESEL UNDERGROUND TANK 103879 T007  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PR96  
 Chemical Name: PREMIUM UNLEADED UNDERGROUND TANK 103879 T006  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: RE95

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 103879 T005  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T005  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T006  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T007  
 Tank ID Number: NT2239  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 3225  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3226  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3102  
 Occurrences: Not reported  
 Item Number: 3227  
 Violation Desc: OPERATING PERMIT CURRENT & AT FACILITY?

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3152  
 Occurrences: Not reported  
 Item Number: 3228  
 Violation Desc: MAINT. & MONITORING RECORDS AVAILABLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3252  
 Occurrences: Not reported  
 Item Number: 3229  
 Violation Desc: AUDIO AND VISUAL ALARM NOT WORKING PROPE

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3252  
 Occurrences: Not reported  
 Item Number: 3230  
 Violation Desc: AUDIO AND VISUAL ALARM NOT WORKING PROPE

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3252  
 Occurrences: Not reported  
 Item Number: 3231  
 Violation Desc: AUDIO AND VISUAL ALARM NOT WORKING PROPE

Inspection Date: 07/22/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3265  
 Occurrences: Not reported  
 Item Number: 3232  
 Violation Desc: SYS NOT RUN TO PREVENT SPILL/OVERFILL

**HMMD WASTE STREAMS:**

Inspection Date: 07/22/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: GAS FILTERS  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H03879-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: POP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/28/2006  
 Begandt: 3/31/1989

Case Number: H03879-002  
 Agency: DEH Site Assessment & Mitigation

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA GASOLINE CORP #50 (Continued)**

**S104745811**

**Funding:** LOP - Federal Fund  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/28/2006  
 Begandt: 2/20/1991

Case Number: H03879-003  
 Agency: DEH Site Assessment & Mitigation

**Funding:** Non Billable  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 5/25/1994  
 Begandt: 1/27/1993

72

**USA PETROLEUM STA. #50  
 3502 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S104160564  
 Cortese N/A  
 SWEEPS UST**

LUST:

Region: 9  
 Case Number: 9UT1409  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 03/31/1989  
 How Found: Other Means  
 Date Stopped: 03/31/1989  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Drinking Water Aquifer affected  
 Status: Preliminary site assessment underway  
 Abate Method: Vapor Extraction  
 Confirm Date: 03/31/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 06/07/1989  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 4/3/89  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H03879-001  
 Basin Number: 908.31  
 Gwater Depth: Not reported  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - KNOWN HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 03/31/1989  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA PETROLEUM STA. #50 (Continued)**

**S104160564**

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3502 NATIONAL AVE

**SWEEPS UST:**

Status: A  
 Comp Number: 3879  
 Number: 9  
 Board Of Equalization: 44-021975  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003879-000001  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 4

Status: A  
 Comp Number: 3879  
 Number: 9  
 Board Of Equalization: 44-021975  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003879-000002  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3879  
 Number: 9  
 Board Of Equalization: 44-021975  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003879-000003  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USA PETROLEUM STA. #50 (Continued)**

**S104160564**

Status: A  
 Comp Number: 3879  
 Number: 9  
 Board Of Equalization: 44-021975  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003879-000004  
 Actv Date: Not reported  
 Capacity: 3000  
 Tank Use: PETROLEUM  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

72

**AMERICAN FORKLIFT/J MAGRE  
 3485 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMMD  
 SAN DIEGO CO. SAM**

**S104748603  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T06019724887  
 Stop Date: 2005-05-09 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-07-12 00:00:00  
 Discover Date: 2005-05-09 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2005-05-09 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Jamilah Haygood

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN FORKLIFT/J MAGRE (Continued)**

**S104748603**

RP Address: 905 Rancho Conejo Blvd.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KH  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16486-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300893  
 Stop Date: 1991-12-13 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-10-17 00:00:00  
 Discover Date: 1991-12-13 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-12-13 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN FORKLIFT/J MAGRE (Continued)**

**S104748603**

County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: J. ROGERS MAGEE  
 RP Address: P.O. BOX 9118  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: CS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16486-001  
 Case Number: 9UT2125  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0619723912  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2007-03-26 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2007-03-05 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2007-03-16 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN FORKLIFT/J MAGRE (Continued)**

**S104748603**

Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Charles Miller  
 RP Address: 905 Rancho Conejo  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: SM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16486-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMMD:**

Facility ID: 116486  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 1 18  
 Mailing City,St,Zip: LA JOLLA, CA 92038  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN FORKLIFT/J MAGRE (Continued)**

**S104748603**

Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: J RODGERS MAGRE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PALISADES GAS&WASH INC  
 Property Address: 905 RANCHO CONEJO BL  
 Property City,St,Zip: 91320  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 858-272-7024

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT2460  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: AT2460  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: AT2460  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN FORKLIFT/J MAGRE (Continued)**

**S104748603**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H16486-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/17/2000  
 Begandt: 12/13/1991

Case Number: H16486-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 7/12/2006  
 Begandt: 5/9/2005

Case Number: H16486-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 3/26/2007  
 Begandt: 3/5/2007

72

**AMERICAN FORKLIFT  
 3485 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S100470933  
 Cortese N/A  
 SWEEPS UST**

**LUST:**

Region: 9  
 Case Number: 9UT2125  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 12/13/1991  
 How Found: Tank Closure  
 Date Stopped: 12/13/1991  
 How Stopped: Close Tank  
 Source: Tank

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN FORKLIFT (Continued)**

**S100470933**

Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 01/09/1992  
 Submit Workplan: Not reported  
 Prelim Assess: 12/13/1991  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H16486-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 01/09/1992  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 3485 NATIONAL AVE

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 16486  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-016486-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 16486  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN FORKLIFT (Continued)**

**S100470933**

Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-016486-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 16486  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-016486-000003  
 Actv Date: Not reported  
 Capacity: 2100  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 16486  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

72

**GENERAL AUTO REPAIR  
 3451 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104748602  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GENERAL AUTO REPAIR (Continued)**

**S104748602**

Leak Source: Not reported  
 Global Id: T0608158862  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-08-10 00:00:00  
 Discover Date: 1990-06-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-06-12 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: MR. HANBY  
 RP Address: 909 S. 41ST ST.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H16484-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GENERAL AUTO REPAIR (Continued)**

**S104748602**

San Diego Co. HMMD:  
 Facility ID: 116484  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3451 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/29/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: SAID HASHEMI  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CASTILLO MARIA D  
 Property Address: 3451 NATIONAL AVE #4  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-236-9056

HMMD DISCLOSURE INVENTORY:  
 Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:  
 Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

HMMD VIOLATIONS:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GENERAL AUTO REPAIR (Continued)**

**S104748602**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H16484-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/10/1991  
 Begandt: 6/12/1990

73

**SOUTHERN CALIFORNIA PLATING**  
**3261 NATIONAL AVE.**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000409126**  
**FINDS CAD981694011**  
**HAZNET**

**RCRA-SQG:**

Date form received by agency: 02/29/1996  
 Facility name: SOUTHERN CA PLATING  
 Site name: SOUTHERN CALIFORNIA PLATING  
 Facility address: 3261 NATIONAL AVE.  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981694011  
 Contact: PAUL HUMMELL JR.  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 231-1481  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING (Continued)**

**1000409126**

Owner/Operator Summary:

Owner/operator name: HUMMELL PAUL  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: Unknown  
 Transporter of hazardous waste: Unknown  
 Treater, storer or disposer of HW: No  
 Underground injection activity: Unknown  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: Unknown  
 Used oil processor: Unknown  
 User oil refiner: Unknown  
 Used oil fuel marketer to burner: Unknown  
 Used oil Specification marketer: Unknown  
 Used oil transfer facility: Unknown  
 Used oil transporter: Unknown  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/02/1987  
 Facility name: SOUTHERN CA PLATING  
 Classification: Small Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHERN CALIFORNIA PLATING (Continued)**

**1000409126**

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

HAZNET:

Gepaid: CAD981694011  
 Contact: SOUTHERN CALIFORNIA PLATING  
 Telephone: 6192311481  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13338  
 Mailing City,St,Zip: SAN DIEGO, CA 921703338  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: .5500  
 Facility County: San Diego

Gepaid: CAD981694011  
 Contact: SOUTHERN CALIFORNIA PLATING  
 Telephone: 6192311481  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13338  
 Mailing City,St,Zip: SAN DIEGO, CA 921703338  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHERN CALIFORNIA PLATING (Continued)**

**1000409126**

TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .5000  
 Facility County: San Diego

Gepaid: CAD981694011  
 Contact: PAUL HUMMELL/PRESIDENT  
 Telephone: 6192311481  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13338  
 Mailing City,St,Zip: SAN DIEGO, CA 921703338  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 3.25  
 Facility County: Not reported

Gepaid: CAD981694011  
 Contact: SOUTHERN CALIFORNIA PLATING  
 Telephone: 6192311481  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13338  
 Mailing City,St,Zip: SAN DIEGO, CA 921703338  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Treatment, Incineration  
 Tons: .1350  
 Facility County: San Diego

Gepaid: CAD981694011  
 Contact: SOUTHERN CALIFORNIA PLATING  
 Telephone: 6192311481  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13338  
 Mailing City,St,Zip: SAN DIEGO, CA 921703338  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Liquids with chromium (VI) > 500 mg/l  
 Disposal Method: Recycler  
 Tons: 6.6720  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 16 additional CA\_HAZNET: record(s) in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

73 SOUTHERN CALIFORNIA PLATING CO  
 3261 NATIONAL AV  
 SAN DIEGO, CA 92113

Cortese S104745063  
 San Diego Co. HMMD N/A  
 AIRS

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:  
 Facility ID: 100644  
 Inactive Indicator: Active  
 Business Code: 6HK34  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3261 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAD981694011  
 Gas Station: Not reported  
 Inspection Date: 04/06/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: PAUL HUMMELL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: HUMMELL PAUL C JR&BRENDA  
 Property Address: 720 NIANTIC CT #B  
 Property City,St,Zip: 92109  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/13/05  
 Facility Phone: 231-1481

HMMD DISCLOSURE INVENTORY:

Item Number: AL11  
 Chemical Name: ALUMINUM DYES FROMIC ACID .5-1% CHROMIUM 5-6% (TANKS #7-900 GAL & #11-1800  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported  
 Item Number: CH06

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Chemical Name: CHROMIC ANHYDRIDE-CHEMICAL FILM (CHROMATE CONVERSION COATING-TANK #12&12A-1)  
 Case Number: 1333-82-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: DE12  
 Chemical Name: DETERGENT CLEANER (TANK #16-950 GALS) BORATE MIXTURE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HY09  
 Chemical Name: HYDROCHLORIC ACID 30% (TANK #13-950 GAL)  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: IR13  
 Chemical Name: IRON PHOSPHATE - KOTE #60 MIXTURE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: ME14  
 Chemical Name: METHYLETHYL KETONE  
 Case Number: 78-93-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE  
  
 Item Number: NI10  
 Chemical Name: NICKEL ACETATE (TANK #8-900 GAL)  
 Case Number: 6018-89-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: NI16  
 Chemical Name: NITRIC ACID 40%  
 Case Number: 07697-37-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: EXTREMELY

Item Number: PA15  
 Chemical Name: PAINTS  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: PH17  
 Chemical Name: PHOSPHORIC ACID 20%  
 Case Number: 7664-38-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO07  
 Chemical Name: SODIUM BISULFATE & POTASSIUM BICHROMATE-CAS#7778-50-9  
 DEOXIDER/DESMUT(TANK#  
 Case Number: 7681-38-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO08  
 Chemical Name: SODIUM DICHROMATE (TANK #10-900-1,000 GAL/5 OZ/GAL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO05  
 Chemical Name: SODIUM HYDROXIDE (TANK #1-1800 GALS, 4 OZ/GAL)  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SU04  
 Chemical Name: SULFURIC ACID 20% TANKS 5&6-2000GALS EA/12% TANK 19-1000 G/7% TANK  
 18-500G  
 Case Number: 7664-93-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/27/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3822

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/27/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 3823  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 03/27/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 3824  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/27/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 3825  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 06/24/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7515  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 06/24/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 7516  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/21/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 6773  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 08/21/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6774  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/21/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6775  
 Violation Desc: WASTE CONTAINER NOT CLOSED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0141  
 Occurrences: Not reported  
 Item Number: 5570  
 Violation Desc: OPERATING TSDf W/O AUTHORIZATION

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0142  
 Occurrences: Not reported  
 Item Number: 5571  
 Violation Desc: DID NOT NOTIFY OF TIERED PERMITTING

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0143  
 Occurrences: Not reported  
 Item Number: 5572  
 Violation Desc: TP NOTIFICATION INCOMPLETE/INCORRECT

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5573  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5574  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 5575  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 5576  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 5577  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 03/13/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 5578  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 5579  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 5580  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0213  
 Occurrences: Not reported  
 Item Number: 5581  
 Violation Desc: CONTAINER INCOMPATIBLE W/ WASTE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 5582  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 5583  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5584  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 5585  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 03/13/02  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 5586  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1006  
 Occurrences: Not reported  
 Item Number: 5587  
 Violation Desc: HMBP: INVENTORY INADEQUATE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 5588  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1011  
 Occurrences: Not reported  
 Item Number: 5589  
 Violation Desc: TRAINING RECORDS NOT AVAILABLE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1701  
 Occurrences: Not reported  
 Item Number: 5590  
 Violation Desc: UNAUTH. TREATMENT OF HAZARDOUS WASTE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1702  
 Occurrences: Not reported  
 Item Number: 5591  
 Violation Desc: TREATMENT NOTIFICATION NO DONE/INADEQ.

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1601  
 Occurrences: Not reported  
 Item Number: 5592  
 Violation Desc: HAZWASTE TANKS W/O P.E. ASSESSMENT

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1604  
 Occurrences: Not reported  
 Item Number: 5593  
 Violation Desc: 2ND. CONTAINMENT NOT KEPT EMPTY

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1605

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Occurrences:	Not reported
Item Number:	5594
Violation Desc:	NO DAILY TANK INSPECTION/LOG
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0141
Occurrences:	Not reported
Item Number:	0374
Violation Desc:	OPERATING TSDF W/O AUTHORIZATION
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0142
Occurrences:	Not reported
Item Number:	0375
Violation Desc:	DID NOT NOTIFY OF TIERED PERMITTING
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0145
Occurrences:	Not reported
Item Number:	0376
Violation Desc:	ERM REPORT NOT SUBMITTED TO HMD
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	0377
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	0378
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0203
Occurrences:	Not reported
Item Number:	0379
Violation Desc:	DAMAGED CONTAINER NOT REPACKAGED
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0207
Occurrences:	Not reported
Item Number:	0380
Violation Desc:	FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Inspection Date:	04/06/04
Waste Code:	Not reported
Type of Violation:	6HV0209
Occurrences:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Item Number: 0381  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported

Item Number: 0382  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported

Item Number: 0383  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1601  
 Occurrences: Not reported

Item Number: 0384  
 Violation Desc: HAZWASTE TANKS W/O P.E. ASSESSMENT

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1604  
 Occurrences: Not reported

Item Number: 0385  
 Violation Desc: 2ND. CONTAINMENT NOT KEPT EMPTY

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1605  
 Occurrences: Not reported

Item Number: 0386  
 Violation Desc: NO DAILY TANK INSPECTION/LOG

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1611  
 Occurrences: Not reported

Item Number: 0387  
 Violation Desc: IMPROPER CLOSURE OF HW TANK UNIT

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1006  
 Occurrences: Not reported

Item Number: 0388  
 Violation Desc: HMBP: INVENTORY INADEQUATE

Inspection Date: 04/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported

Item Number: 0389



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Violation Desc: HMBP: INADEQUATE SITE MAP

**HMMD WASTE STREAMS:**

Inspection Date: 04/06/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: POWDER COAT WASTE  
 Carcinogen: No

Inspection Date: 04/06/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 150  
 Quantity String: 150  
 Annual Qty: 150  
 Annual Qty String: 150  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 2831 PACIFIC TREATMENT EN  
 Waste Desc: PAINT FILTERS  
 Carcinogen: No

Inspection Date: 04/06/04  
 Waste Item #: 214  
 Waste Code: 214  
 Waste Name: UNSPEC SOLVENT MIXTU  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 102 ON SITE RECYCLIN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: MEK-THINNER WASTE  
 Carcinogen: No

Inspection Date: 04/06/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 1  
 Quantity String: 1  
 Annual Qty: 10  
 Annual Qty String: 10  
 Measurement Unit: GAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Treatment Method:	999 UNKNOWN
Storage Method:	CARBOY
Haz Waste Hauler:	0001 NO HAULER
Waste Desc:	USED OIL
Carcinogen:	No
Inspection Date:	04/06/04
Waste Item #:	252
Waste Code:	252
Waste Name:	STILL BOTTOM WASTE (
Qnty at Inspection:	200
Quantity String:	200
Annual Qty:	400
Annual Qty String:	400
Measurement Unit:	LBS
Treatment Method:	001 RECYCLE
Storage Method:	METAL DRUM
Haz Waste Hauler:	2831 PACIFIC TREATMENT EN
Waste Desc:	MEK STILL BOTTOMS
Carcinogen:	No
Inspection Date:	04/06/04
Waste Item #:	461
Waste Code:	461
Waste Name:	PAINT SLUDGE
Qnty at Inspection:	500
Quantity String:	500
Annual Qty:	500
Annual Qty String:	500
Measurement Unit:	LBS
Treatment Method:	999 UNKNOWN
Storage Method:	METAL DRUM
Haz Waste Hauler:	0001 NO HAULER
Waste Desc:	SOLVENT/PAINT SATRTD RAGS
Carcinogen:	No
Inspection Date:	04/06/04
Waste Item #:	491
Waste Code:	491
Waste Name:	UNSPECIFIED SLUDGE W
Qnty at Inspection:	110
Quantity String:	110
Annual Qty:	110
Annual Qty String:	110
Measurement Unit:	GAL
Treatment Method:	003 LANDFILL
Storage Method:	METAL DRUM
Haz Waste Hauler:	2831 PACIFIC TREATMENT EN
Waste Desc:	TANK SLUDGE CLEAN-UP
Carcinogen:	No
Inspection Date:	04/06/04
Waste Item #:	792
Waste Code:	792
Waste Name:	LIQUIDS W/PH <OR= 2
Qnty at Inspection:	4300
Quantity String:	4300

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Annual Qty: 1400  
 Annual Qty String: 1400  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0335 MARTIN INDUSTRIES PU  
 Waste Desc: TANK EMPTIED ONCE/3 YR  
 Carcinogen: No

**EMI:**

Year: 1990  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2669  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 18  
 Reactive Organic Gases Tons/Yr: 9  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1995  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2669  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 19  
 Reactive Organic Gases Tons/Yr: 7  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1996  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2669  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 19  
 Reactive Organic Gases Tons/Yr: 7  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	1997
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2669
Air District Name:	SD
SIC Code:	3471
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	7
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	1998
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2669
Air District Name:	SD
SIC Code:	3471
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2669
Air District Name:	SD
SIC Code:	3471
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2669  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 5  
 Reactive Organic Gases Tons/Yr: 5  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2669  
 Air District Name: SD  
 SIC Code: 3479  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 5  
 Reactive Organic Gases Tons/Yr: 5  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2669  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2669  
 Air District Name: SD  
 SIC Code: 3471  
 Air District Name: SAN DIEGO COUNTY APCD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHERN CALIFORNIA PLATING CO (Continued)**

**S104745063**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2669
Air District Name:	SD
SIC Code:	3471
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.46168
Reactive Organic Gases Tons/Yr:	3.46168
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2669
Air District Name:	SD
SIC Code:	3471
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.45
Reactive Organic Gases Tons/Yr:	3.45
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

74

**CAL SOFT WATER SERVICE INC**  
**3094 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000131990**  
**FINDS CAD044329803**  
**LUST**  
**San Diego Co. HMMD**  
**HIST UST**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

RCRA-SQG:  
 Date form received by agency:09/09/1986  
 Facility name: CAL SOFT WATER SERVICE INC  
 Facility address: 3094 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD044329803

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAL SOFT WATER SERVICE INC (Continued)**

**1000131990**

Mailing address: PO BOX 13398  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 3094 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 232-6588  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: C C MACEVICZ  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAL SOFT WATER SERVICE INC (Continued)**

**1000131990**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**LUST:**

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608162909  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-08-06 00:00:00  
 Discover Date: 1989-07-14 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-07-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**CAL SOFT WATER SERVICE INC (Continued)**

**1000131990**

Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00643-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 100643  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 13398  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/03/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DANTO STEVE&BROSTEDT-DANTO EVA  
 Property Address: 10016 PANDORA DR  
 Property City,St,Zip: 91941  
 Tank Owner: CC MACEVICZ  
 Tank Address: 3094 A NATIONAL AVE  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-6588

HMMD DISCLOSURE INVENTORY:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAL SOFT WATER SERVICE INC (Continued)**

**1000131990**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: #3  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: #2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: #1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 12/03/87  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 6513  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**HIST UST:**

Region: STATE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAL SOFT WATER SERVICE INC (Continued)**

**1000131990**

Facility ID: 00000000883  
 Facility Type: Other  
 Other Type: WATER CO.  
 Total Tanks: 0003  
 Contact Name: JOHN LORENZEN  
 Telephone: 6192326588  
 Owner Name: CAL SOFT WATER SERVICE, INC  
 Owner Address: 3094 NATIONAL AVE  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: #3  
 Year Installed: Not reported  
 Tank Capacity: 00004000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Visual, Pressure Test

Tank Num: 002  
 Container Num: #2  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Visual, Pressure Test

Tank Num: 003  
 Container Num: #1  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Visual, Pressure Test

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 643  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000643-000001  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 643

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAL SOFT WATER SERVICE INC (Continued)**

**1000131990**

Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000643-000002  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 643  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-000643-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 643  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H00643-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 8/6/1991  
 Begandt: 7/14/1989

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**75 NATIONAL RECYCLING CENTER SWRCY S107137346**  
**3008 NATIONAL AVE N/A**  
**SAN DIEGO, CA 92113**

SWRCY:  
 Certification Status: R  
 Facility Phone Number: (619) 696-9727  
 Date facility became certified: 01/24/00  
 Date facility began operating: 02/01/00  
 Date facility ceased operating: 08/02/00  
 Whether The Facility Is Grandfathered: Not reported  
 Convenience Zone Where Facility Located: 2070  
 Convenience Zone Where Facility Located 2: 4204  
 Convenience Zone Where Facility Located 3: 0  
 Convenience Zone Where Facility Located 4: 0  
 Convenience Zone Where Facility Located 5: 0  
 Convenience Zone Where Facility Located 6: 0  
 Convenience Zone Where Facility Located 7: 0  
 Aluminum Beverage Containers Redeemed: AL  
 Glass Beverage Containers Redeemed: GL  
 Plastic Beverage Containers Redeemed: PL  
 Other mat beverage containers redeemed: Not reported  
 Refillable Beverage Containers Redeemed: Not reported

**75 A&A AUTO & TRUCK ELEC RCRA-SQG 1000103234**  
**3005 NATIONAL AVE FINDS CAD982011694**  
**SAN DIEGO, CA 92113 HAZNET**

RCRA-SQG:  
 Date form received by agency: 09/01/1996  
 Facility name: A&A AUTO & TRUCK ELEC  
 Facility address: 3005 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982011694  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: A&A TRUCK & AUTO INC  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**A&A AUTO & TRUCK ELEC (Continued)**

**1000103234**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 07/06/1987  
 Facility name: A&A AUTO & TRUCK ELEC  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD982011694  
 Contact: JOHNNY RIOS  
 Telephone: 6192336178  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3005 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**A&A AUTO & TRUCK ELEC (Continued)**

**1000103234**

Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: .0208  
 Facility County: San Diego

Gepaid: CAD982011694  
 Contact: JOHNNY RIOS  
 Telephone: 6192336178  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3005 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .6000  
 Facility County: San Diego

Gepaid: CAD982011694  
 Contact: PETROS Y HANAEE  
 Telephone: 6192336178  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3005 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.06  
 Facility County: Not reported

Gepaid: CAD982011694  
 Contact: PETROS Y HANAEE  
 Telephone: 6192336178  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3005 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: San Diego  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 0.06  
 Facility County: San Diego

Gepaid: CAD982011694  
 Contact: JOHNNY RIOS  
 Telephone: 6192336178  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A&A AUTO & TRUCK ELEC (Continued)**

**1000103234**

Mailing Name: Not reported  
 Mailing Address: 3005 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: .2293  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

76

**FORMER FORNACA BAKERY  
 2828 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**LUST S104539578  
 SWEEPS UST N/A**

LUST:

Region: 9  
 Case Number: 9UT2119  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 12/18/1991  
 How Found: Tank Closure  
 Date Stopped: 12/18/1991  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 12/18/1991  
 Submit Workplan: Not reported  
 Prelim Assess: 01/08/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 1/9/92  
 Closed Date: 10/5/99  
 Pilot Program: LOP  
 Local Case: H04887-001  
 Basin Number: 908.22  
 Gwater Depth: 57.4  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 12/18/1991  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FORMER FORNACA BAKERY (Continued)**

**S104539578**

SWEEPS UST:

Status: Not reported  
 Comp Number: 4887  
 Number: Not reported  
 Board Of Equalization: 44-022125  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-004887-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 4887  
 Number: Not reported  
 Board Of Equalization: 44-022125  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-004887-000002  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 4887  
 Number: 9  
 Board Of Equalization: 44-022125  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

76 **HOLSUM BAKING CO**  
**2828 NATIONAL AVE**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000390245**  
**FINDS CAD008230013**  
**LUST**  
**Cortese**  
**San Diego Co. HMMMD**  
**SAN DIEGO CO. SAM**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: HOLSUM BAKING CO  
 Facility address: 2828 NATIONAL AVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD008230013  
 Mailing address: NATIONAL AVE  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HOLSUM BAKING CO (Continued)**

**1000390245**

Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**LUST:**

Region:	STATE
Case Type:	Soil only
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	NOR
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global Id:	T0607300886
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	1999-10-05 00:00:00
Discover Date:	Not reported
Enforcement Dt:	Not reported
Release Date:	Not reported
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	37
Org Name:	Not reported
Reg Board:	San Diego Region
Status:	Case Closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HOLSUM BAKING CO (Continued)**

**1000390245**

Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: RONALD FORNCA  
 RP Address: 2069 ALDERGROVE AVENUE  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04887-001  
 Case Number: 9UT2119  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: Not reported

**San Diego Co. HMMD:**

Facility ID: 104887  
 Inactive Indicator: Active  
 Business Code: 6HK29  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2828 NATIONAL AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: CAD008230013  
 Gas Station: Not reported  
 Inspection Date: 05/15/91  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JIM SLOAN

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HOLSUM BAKING CO (Continued)**

**1000390245**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: NATIONAL L L C  
 Property Address: C/O ELKINS-ZIRPOLO  
 Property City,St,Zip: 92101  
 Tank Owner: FORNACA INC.  
 Tank Address: 2828 NATIONAL AV  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 233-7364

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: AT4101  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HOLSUM BAKING CO (Continued)**

**1000390245**

Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H04887-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/5/1999  
 Begandt: 12/18/1991

77

**GAS QUIK  
 2865 NATIONAL AVE  
 SAN DIEGO, CA 92113**

**HAZNET S105723273  
 SWEEPS UST N/A**

HAZNET:

Gepaid: CAL000148021  
 Contact: JIM DAVIS  
 Telephone: 9014957240  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 123 S FRONT ST DEPT 8190  
 Mailing City,St,Zip: MEMPHIS, TN 381030000  
 Gen County: San Diego  
 TSD EPA ID: TXD077603371  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: H14  
 Tons: 0.03  
 Facility County: San Diego

Gepaid: CAL000148021  
 Contact: FARLON WILLIAMS  
 Telephone: 9014957217  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 123 S FRONT ST  
 Mailing City,St,Zip: MEMPHIS, TN 381030000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Marin  
 Waste Category: Photochemicals/photoprocessing waste  
 Disposal Method: Recycler  
 Tons: 0.18  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GAS QUIK (Continued)**

**S105723273**

SWEEPS UST:

Status: Not reported  
 Comp Number: 3347  
 Number: Not reported  
 Board Of Equalization: 44-021843  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003347-000001  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 4

Status: Not reported  
 Comp Number: 3347  
 Number: Not reported  
 Board Of Equalization: 44-021843  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003347-000002  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3347  
 Number: Not reported  
 Board Of Equalization: 44-021843  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003347-000003  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3347  
 Number: Not reported  
 Board Of Equalization: 44-021843  
 Ref Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GAS QUIK (Continued)**

**S105723273**

Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003347-000004  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3347  
 Number: 9  
 Board Of Equalization: 44-021843  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

77

**AUTOZONE #5674  
 2865 NATIONAL AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104745667  
 N/A**

LUST:

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608176608  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-12-04 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AUTOZONE #5674 (Continued)**

**S104745667**

MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MV  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03347-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 103347  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: AUTOZONE, DEPT 8190  
 Mailing Address: 123 S FRONT ST  
 Mailing City,St,Zip: MEMPHIS, TN 38103  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000148021  
 Gas Station: Not reported  
 Inspection Date: 04/22/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AUTOZONE #5674 (Continued)**

**S104745667**

Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ARMANDO ACHONDO, MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SKOP ALEXANDER&SOPHIE FAMILY T  
 Property Address: C/O AUTO ZONE INC  
 Property City,St,Zip: 38101  
 Tank Owner: GAS QUIK  
 Tank Address: P O BOX 13127  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/22/06  
 Facility Phone: 619-232-2393

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT1053-1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: AT1053-2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: AT1053-3  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: AT1053-4  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T005  
 Tank ID Number: AT2666  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AUTOZONE #5674 (Continued)**

**S104745667**

**HMMD VIOLATIONS:**

Inspection Date: 04/06/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3205  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 04/06/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3206  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6978  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 04/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 6979  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 04/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6980  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 04/22/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 5720  
 Annual Qty String: 5720  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE OIL  
 Carcinogen: No

Inspection Date: 04/22/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AUTOZONE #5674 (Continued)**

**S104745667**

Qty at Inspection: 440  
 Quantity String: 440  
 Annual Qty: 1320  
 Annual Qty String: 1320  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: WASTE ABSORBENT  
 Carcinogen: No

Inspection Date: 04/22/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 2600  
 Annual Qty String: 2600  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: OLD AUTOMOTIVE BATTERIES  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H03347-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 12/4/1987  
 Begandt: 3/23/1987

78

**DORMANS TIRE CO**  
**2385 MAIN ST**  
**SAN DIEGO, CA 92113**

**LUST**  
**San Diego Co. HMMD**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

**S104748446**  
**N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608177867  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DORMANS TIRE CO (Continued)**

**S104748446**

Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-02-26 00:00:00  
 Discover Date: 1988-01-05 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-01-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: MR. SCOTT BENJAMIN  
 RP Address: P.O. BOX 9410  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: LB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15421-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMMD:

Facility ID: 115421  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DORMANS TIRE CO (Continued)**

**S104748446**

Mailing Address: 820 HIGHLAND AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92073  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CALIFORNIA PROPERTIES  
 Property Address: 1311 1ST ST  
 Property City,St,Zip: 92118  
 Tank Owner: NORMAN TIRE CO  
 Tank Address: 2385 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92102  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT0046-1  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DORMANS TIRE CO (Continued)**

**S104748446**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 15421  
 Number: Not reported  
 Board Of Equalization: 44-022919  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015421-000001  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H15421-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/26/1988  
 Begandt: 1/5/1988

78

**AMERICAN RIGGING & SUPPLY CO**  
**2380 MAIN ST**  
**SAN DIEGO, CA 92113**

**HAZNET S104756924**  
**San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAL000234152  
 Contact: KEVIN D. COLLINS SAFETY  
 Telephone: 6192470319  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2380 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN RIGGING & SUPPLY CO (Continued)**

**S104756924**

TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: San Diego

Gepaid: CAL000234152  
 Contact: JOHN BROOKS-SHOP FOREMAN  
 Telephone: 6192335625  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2380 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAL000234152  
 Contact: JOHN BROOKS-SHOP FOREMAN  
 Telephone: 6192335625  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2380 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Recycler  
 Tons: 0.84  
 Facility County: Not reported

Gepaid: CAL000234152  
 Contact: KEVIN COLLINS  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2380 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: San Diego  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.08  
 Facility County: San Diego

Gepaid: CAL000234152  
 Contact: KEVIN COLLINS  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2380 MAIN ST



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN RIGGING & SUPPLY CO (Continued)**

**S104756924**

Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: San Diego  
 Waste Category: Liquids with pH <UN-> 2  
 Disposal Method: Recycler  
 Tons: 0.14  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 138635  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ATT'N: KEVIN COLLINS  
 Mailing Address: 2380 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000234152  
 Gas Station: Not reported  
 Inspection Date: 08/20/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: KEVIN COLLINS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DEWITT TRANSFER&STORAGE CO  
 Property Address: 9089 CLAIREMONT MESA  
 Property City,St,Zip: 92123  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/20/05  
 Facility Phone: 619-233-5625

HMMD DISCLOSURE INVENTORY:

Item Number: AC27  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN RIGGING & SUPPLY CO (Continued)**

**S104756924**

Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: HE26  
 Chemical Name: HEXANE  
 Case Number: 110-54-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: LU28  
 Chemical Name: LUBRICATING GREASE JET LUBE  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: OX24  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR25  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: ZO29  
 Chemical Name: ZONE DEFENSE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN RIGGING & SUPPLY CO (Continued)**

**S104756924**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 1256  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1257  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 1258  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1259  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 1260  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 1261  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN RIGGING & SUPPLY CO (Continued)**

**S104756924**

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 1262  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 11/07/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 1263  
 Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

Inspection Date: 08/20/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 3396  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 08/20/03  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: HEXANE  
 Carcinogen: No

Inspection Date: 08/20/03  
 Waste Item #: 791  
 Waste Code: 791  
 Waste Name: LIQUIDS WITH PH <OR=  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 35  
 Annual Qty String: 35  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 2804 ENVIROSERV  
 Waste Desc: HC1/H2O MIXTURE  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

78      **TRICK TRUX INC**      **RCRA-SQG**      **1000173020**  
**2380 MAIN ST**      **FINDS**      **CAD981693831**  
**SAN DIEGO, CA 92113**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: TRICK TRUX INC  
 Facility address: 2380 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981693831  
 Mailing address: MAIN ST  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: FRED HAYNES  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRICK TRUX INC (Continued)**

**1000173020**

User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

78

**LEASEWAY TRANSPORTATION  
 2304 MAIN ST  
 SAN DIEGO, CA 92113**

**HIST UST U001572987  
 N/A**

**HIST UST:**

Region: STATE  
 Facility ID: 00000010271  
 Facility Type: Other  
 Other Type: TRUCK LEASR & RENTAL  
 Total Tanks: 0003  
 Contact Name: BOB WRAAMANN  
 Telephone: 6192341875  
 Owner Name: LEASEWAY TRANSPORTATION  
 Owner Address: 4285 CAMINO DEL RIO SO  
 Owner City,St,Zip: SAN DIEGO, CA 92108

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00012000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**LEASEWAY TRANSPORTATION (Continued)**

**U001572987**

Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

78

**PHD CORP  
 2304 MAIN ST  
 SAN DIEGO, CA 92113**

**FINDS 1000109311  
 HIST UST CAD981162399  
 RCRA-NonGen**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HIST UST:**

Region: STATE  
 Facility ID: 00000067631  
 Facility Type: Other  
 Other Type: TRANSPORTATION & LEA  
 Total Tanks: 0003  
 Contact Name: Not reported  
 Telephone: 6192837161  
 Owner Name: DEWITT VAN STORAGE  
 Owner Address: 6060 FIQUEROA  
 Owner City,St,Zip: LOS ANGELES, CA 90042

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1956  
 Tank Capacity: 00012000  
 Tank Used for: WASTE  
 Type of Fuel: 4  
 Tank Construction: Unkown centimeters  
 Leak Detection: None

Tank Num: 002  
 Container Num: 2  
 Year Installed: 1956  
 Tank Capacity: 00012000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 003  
 Container Num: 3  
 Year Installed: 1956  
 Tank Capacity: 00000500  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**PHD CORP (Continued)**

**1000109311**

Leak Detection: None

RCRA-NonGen:

Date form received by agency: 11/06/1985  
 Facility name: PHD CORP  
 Facility address: 2304 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981162399  
 Mailing address: P O BOX 20008  
 SAN DIEGO, CA 92120  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2304 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 283-7161  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: LEASEWAY TRANSPORTATION CORP  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No



MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

**PHD CORP (Continued)**

**1000109311**

Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**78**

**SAN DIEGO EXPRESS INC.,  
 2304 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST S101302066  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT2130  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 03/06/1992  
 How Found: Other Means  
 Date Stopped: 03/06/1992  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: 03/06/1992  
 Submit Workplan: Not reported  
 Prelim Assess: 03/09/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 6/20/96  
 Pilot Program: LOP  
 Local Case: H15812-001  
 Basin Number: 908.22  
 Gwater Depth: >15  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 03/06/1992  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2304 MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

78 **SAN DIEGO EXPRESS INC**  
**2304 MAIN ST**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000110768**  
**LUST CAD982342610**  
**San Diego Co. HMMD**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

RCRA-SQG:

Date form received by agency: 01/04/1988  
 Facility name: SAN DIEGO EXPRESS INC  
 Facility address: 2304 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982342610  
 Mailing address: PO BOX 13159  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2304 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 268-4855  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: DEWITT TRANSFER STORAGE  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO EXPRESS INC (Continued)**

**1000110768**

Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300899  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-06-20 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: ATTN: MR. TOM HAMILTON  
 RP Address: 9089 CLAIREMONT MESA #204  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: PV  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO EXPRESS INC (Continued)**

**1000110768**

Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15812-001  
 Case Number: 9UT2130  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 115812  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 13159  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/19/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DON NOWASKEY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DEWITT TRANSFER&STORAGE CO  
 Property Address: 9089 CLAIREMONT MESA  
 Property City,St,Zip: 92123  
 Tank Owner: DEWITT TRANSFER & ST  
 Tank Address: 2304 PO BOX 13159  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-5454

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS INC (Continued)**

**1000110768**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/18/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0031  
 Occurrences: Not reported  
 Item Number: 6506  
 Violation Desc: NO HAZWASTE DISPOSAL RECEIPTS

Inspection Date: 11/18/87  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 6507  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 11/18/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 6508  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 11/18/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0042  
 Occurrences: Not reported  
 Item Number: 6509  
 Violation Desc: HAZWASTE CONT. NOT LABELED OR MARKED

Inspection Date: 12/03/87

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO EXPRESS INC (Continued)**

**1000110768**

Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 6518  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 03/19/90  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 7287  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 03/19/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 7288  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 03/19/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0084  
 Occurrences: Not reported  
 Item Number: 7289  
 Violation Desc: UST PRECISION TEST DATA NOT SENT TO HMMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 15812  
 Number: Not reported  
 Board Of Equalization: 44-022927  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015812-000001  
 Actv Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO EXPRESS INC (Continued)**

**1000110768**

Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 15812  
 Number: Not reported  
 Board Of Equalization: 44-022927  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015812-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 15812  
 Number: 9  
 Board Of Equalization: 44-022927  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015812-000003  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H15812-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/20/1996  
 Begandt: 3/6/1992

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

78 **DORMAN/DAPPER TIRE**  
**2301 MAIN ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD**  
**SWEEPS UST**

**S104750562**  
**N/A**

San Diego Co. HMMD:

Facility ID: 124687  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2301 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO CALIFORNIA PROPERTIE  
 Property Address: 1311 1ST ST  
 Property City, St, Zip: 92118  
 Tank Owner: DORMAN/DAPPER TIRE  
 Tank Address: 2301 MAIN ST  
 Tank City, St, Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: T001  
 Tank ID Number: 001  
 Waste or Product: Not reported  
 Tank Contents: DIESEL



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DORMAN/DAPPER TIRE (Continued)**

**S104750562**

Tank Number: T002  
 Tank ID Number: 002  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 24687  
 Number: Not reported  
 Board Of Equalization: 44-023620  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-024687-000001  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 24687  
 Number: Not reported  
 Board Of Equalization: 44-023620  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DORMAN/DAPPER TIRE (Continued)**

**S104750562**

Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-024687-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

78

**SOUTHWEST MARINE  
 2286 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S105694683  
 N/A**

LUST:

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOV  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608125152  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-07-25 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: 1991-03-26 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: DANA AUSTIN  
 RP Address: 2286 A MAIN ST.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE (Continued)**

**S105694683**

Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H23569-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 123569  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/26/91  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DANA AUSTIN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KS&S PARTNERSHIP  
 Property Address: C/O SANGER|MOLEVER  
 Property City,St,Zip: 92262  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-1000

HMMD DISCLOSURE INVENTORY:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE (Continued)**

**S105694683**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/18/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 7550  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 10/18/90  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 7551  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/18/90  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 7552  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 10/18/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0010  
 Occurrences: Not reported  
 Item Number: 7553  
 Violation Desc: BUS. PLAN NOT COMPLETE/CURRENT/ON SITE

Inspection Date: 10/18/90  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 7554  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 03/26/91  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE (Continued)**

**S105694683**

Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 7759  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/26/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 7760  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/26/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7761  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/26/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 7762  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 03/26/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0404  
 Occurrences: Not reported  
 Item Number: 7763  
 Violation Desc: SPILL CONTROL EQUIPMT NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H23569-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Complaint  
 FStatus: Closed Case

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE (Continued)**

**S105694683**

Date: 7/25/1991  
 Begandt: Not reported

78

**SAN DIEGO MUSEUM OF ART  
 2286 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S102436321  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303125  
 Stop Date: 1987-12-23 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-05-27 00:00:00  
 Discover Date: 1987-12-23 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-12-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: MARK ALEXANDER  
 RP Address: 2286 MAIN ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO MUSEUM OF ART (Continued)**

**S102436321**

Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15420-001  
 Case Number: 9UT880  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608195257  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-07-25 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: HOWARD SANGER  
 RP Address: 400 S FARRELL, SUITE B-112  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO MUSEUM OF ART (Continued)**

**S102436321**

MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: RG  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H15420-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT880  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 12/23/1987  
 How Found: Tank Closure  
 Date Stopped: 12/23/1987  
 How Stopped: Close Tank  
 Source: Piping  
 Cause: Overfill  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 12/23/1987  
 Submit Workplan: Not reported  
 Prelim Assess: 01/05/1988  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/27/88  
 Pilot Program: LOP  
 Local Case: H15420-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO MUSEUM OF ART (Continued)**

**S102436321**

Release Date: 01/05/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2286 MAIN ST

**San Diego Co. HMMD:**

Facility ID: 115420  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 400 S FARRELL DR  
 Mailing City,St,Zip: PALM SPRINGS, CA 92262  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/16/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KS&S PARTNERSHIP  
 Property Address: C/O SANGER|MOLEVER  
 Property City,St,Zip: 92262  
 Tank Owner: KS & S PARTNERSHIP  
 Tank Address: 400 S FARRELL DR  
 Tank City,St,Zip: Palm Springs, CA 92262  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-5473

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO MUSEUM OF ART (Continued)**

**S102436321**

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 11/16/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 7593  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 11/16/90  
 Waste Code: Not reported  
 Type of Violation: 6HX3004  
 Occurrences: Not reported  
 Item Number: 7594  
 Violation Desc: NO SIR DATA TO LOCAL AGENCY

Inspection Date: 12/14/88  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 6910  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 12/14/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0084  
 Occurrences: Not reported  
 Item Number: 6911  
 Violation Desc: UST PRECISION TEST DATA NOT SENT TO HMMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO MUSEUM OF ART (Continued)**

**S102436321**

Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 119285  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2286 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/16/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JERRY HUSTON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KS&S PARTNERSHIP  
 Property Address: C/O SANGER|MOLEVER  
 Property City,St,Zip: 92262  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-5365

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO MUSEUM OF ART (Continued)**

**S102436321**

Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 15420  
 Number: Not reported  
 Board Of Equalization: 44-002269  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015420-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 15420  
 Number: Not reported  
 Board Of Equalization: 44-002269  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015420-000002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO MUSEUM OF ART (Continued)**

**S102436321**

Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 15420  
 Number: Not reported  
 Board Of Equalization: 44-002269  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015420-000003  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 15420  
 Number: 9  
 Board Of Equalization: 44-002269  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H15420-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/27/1988  
 Begandt: 12/23/1987

Case Number: H15420-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 7/25/1991  
 Begandt: 3/1/1991

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

78 **WILLIG FREIGHT LINES**  
**2286 MAIN ST**  
**SAN DIEGO, CA 92113**

**HIST UST** **U001573002**  
**N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000013430  
 Facility Type: Other  
 Other Type: TRUCKING  
 Total Tanks: 0001  
 Contact Name: J. FLETCHER  
 Telephone: 6192345473  
 Owner Name: MRS. MARION A. PHILLIPS  
 Owner Address: 4749 LA RUEDA DRIVE  
 Owner City,St,Zip: LA MESA, CA 92041

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

78 **1100 SICARD (IN ALLEY) ST.**  
**SAN DIEGO, CA**

**CHMIRS** **S100223102**  
**N/A**

CHMIRS:  
 OES Incident Number: 9992009  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 21-JAN-88  
**Date Completed: 21-JAN-88**  
 Property Use: 600  
 Agency Id Number: 37140  
 Agency Incident Number: 37385  
 Time Notified: 1421  
 Time Completed: Not reported  
 Surrounding Area: 962  
 Estimated Temperature: 68  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100223102

Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: C L NEAL  
 Report Date: 21-JAN-88  
 Comments: N  
 Facility Telephone: 619 236-7773  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 88-92  
 Agency: Not reported  
 Incident Date: Not reported  
 Admin Agency: Not reported  
 Amount: Not reported  
 Contained: Not reported  
 Site Type: Not reported  
 E Date: Not reported  
 Substance: Not reported  
 Quantity Released: Not reported  
 BBLS: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: Not reported  
 Evacuations: Not reported  
 Number of Injuries: Not reported  
 Number of Fatalities: Not reported  
 Description: Not reported

79

2295 BELT STREET  
 SAN DIEGO, CA 92113

CHMIRS S100219208  
 ENVIROSTOR N/A

CHMIRS:  
 OES Incident Number: 9000121  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 11-FEB-90  
**Date Completed: 11-FEB-90**  
 Property Use: 767

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100219208

Agency Id Number: 37140  
 Agency Incident Number: 040828  
 Time Notified: 850  
 Time Completed: 1320  
 Surrounding Area: 800  
 Estimated Temperature: 75  
 Property Management: P  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agency Personel # Of Decontaminated: 0  
 Responding Agency Personel # Of Injuries: 0  
 Responding Agency Personel # Of Fatalities: 0  
 Others Number Of Decontaminated: 0  
 Others Number Of Injuries: 0  
 Others Number Of Fatalities: 0  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: CHEVRON  
 Reporting Officer Name/ID: SAMUEL E. CAMPBELL  
 Report Date: 11-FEB-90  
 Comments: Not reported  
 Facility Telephone: 619 236-7773  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 88-92  
 Agency: Not reported  
 Incident Date: Not reported  
 Admin Agency: Not reported  
 Amount: Not reported  
 Contained: Not reported  
 Site Type: Not reported  
 E Date: 29-MAY-90  
 Substance: Not reported  
 Quantity Released: Not reported  
 BBLs: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100219208

Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: Not reported  
 Evacuations: Not reported  
 Number of Injuries: Not reported  
 Number of Fatalities: Not reported  
 Description: Not reported

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37290007  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-09-13 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37290007  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100219208

Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

79

**SOUTHWEST REGIONAL MAINTENANCE CENTER  
 2205 EAST BELT ST.  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000820614  
 FINDS CA1170090616  
 HAZNET**

RCRA-SQG:

Date form received by agency: 02/15/2006  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Facility address: 2205 EAST BELT ST.  
 SAN DIEGO, CA 92113  
 EPA ID: CA1170090616  
 Mailing address: 3755 BRINSER ST. BLDG 91  
 SAN DIEGO, CA 92136  
 Contact: LAMBERTO R TORRES  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 556-1055  
 Telephone ext.: NA  
 Contact email: LAMBERTO.TORRES@NAVY.MIL  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: UNIFIED PORT OF SAN DIEGO  
 Owner/operator address: 3165 PACIFIC HIGHWAY  
 SAN DIEGO, CA 92101  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: County  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1958  
 Owner/Op end date: Not reported  
 Owner/operator name: BAE SYSTEMS OF SAN DIEGO  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 10/01/1985  
 Owner/Op end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST REGIONAL MAINTENANCE CENTER (Continued)**

**1000820614**

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 02/15/2006  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Classification: Large Quantity Generator

Date form received by agency: 02/16/2005  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Classification: Large Quantity Generator

Date form received by agency: 01/30/2004  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: NAVSEA SAN DIEGO, USN AT SOUTHWEST MARINE  
 Classification: Large Quantity Generator

Date form received by agency: 01/30/2002  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: SUPERVISOR OF SHIPBUILDING, CONVERSIONA  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: SOUTHWEST MARINE INC.  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: SOUTHWEST MARINE INC.  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: USNAVY SUPERVISOR OF SHIPBUILDING  
 Classification: Large Quantity Generator

Date form received by agency: 02/26/1996  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: SOUTHWEST MARINE INC.  
 Classification: Large Quantity Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST REGIONAL MAINTENANCE CENTER (Continued)**

**1000820614**

Date form received by agency: 03/18/1994  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: SOUTHWEST MARINE, INC OF SAN DIEGO  
 Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 9793

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 472

Waste code: D005  
 Waste name: BARIUM  
 Amount (Lbs): 10084

Waste code: D006  
 Waste name: CADMIUM  
 Amount (Lbs): 1794

Waste code: D007  
 Waste name: CHROMIUM  
 Amount (Lbs): 180

Waste code: D008  
 Waste name: LEAD  
 Amount (Lbs): 635

Waste code: D011  
 Waste name: SILVER  
 Amount (Lbs): 91

Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Amount (Lbs): 338

Violation Status: No violations found

FINDS:

MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST REGIONAL MAINTENANCE CENTER (Continued)**

**1000820614**

Other Pertinent Environmental Activity Identified at Site

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

HAZNET:

Gepaid: CA1170090616  
Contact: US DEPT OF THE NAVY SUPSHIP  
Telephone: 6195561053  
Facility Addr2: Not reported  
Mailing Name: Not reported  
Mailing Address: 3600 SURFACE NAVY BLVD  
Mailing City,St,Zip: SAN DIEGO, CA 921365066  
Gen County: San Diego  
TSD EPA ID: CA6170024289  
TSD County: San Diego  
Waste Category: Detergent and soap  
Disposal Method: Transfer Station  
Tons: .0510  
Facility County: San Diego

Gepaid: CA1170090616  
Contact: US DEPT OF THE NAVY SUPSHIP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST REGIONAL MAINTENANCE CENTER (Continued)**

**1000820614**

Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .6805  
 Facility County: San Diego

Gepaid: CA1170090616  
 Contact: US DEPT OF THE NAVY SUPSHIP  
 Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: .2535  
 Facility County: San Diego

Gepaid: CA1170090616  
 Contact: US DEPT OF THE NAVY SUPSHIP  
 Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: .0685  
 Facility County: San Diego

Gepaid: CA1170090616  
 Contact: US DEPT OF THE NAVY SUPSHIP  
 Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: 2.3750  
 Facility County: San Diego

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

**SOUTHWEST REGIONAL MAINTENANCE CENTER (Continued)** **1000820614**

[Click this hyperlink](#) while viewing on your computer to access  
168 additional CA\_HAZNET: record(s) in the EDR Site Report.

<b>79</b>	<b>SOUTHWEST MARINE, INC.</b>	<b>HIST UST</b>	<b>U001572997</b>
	<b>2205 E BELT ST</b>		<b>N/A</b>
	<b>SAN DIEGO, CA 92113</b>		

HIST UST:

Region: STATE  
 Facility ID: 00000036362  
 Facility Type: Other  
 Other Type: BOAT REPAIR  
 Total Tanks: 0003  
 Contact Name: DAVE BECHTEL  
 Telephone: 6192381000  
 Owner Name: SOUTHWEST MARINE, INC.  
 Owner Address: 2205 BELT STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1983  
 Tank Capacity: 00009995  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 003  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00009900  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: None

<b>79</b>	<b>PACIFIC SHIP (BAE SYSTEMS)</b>	<b>FINDS</b>	<b>1000434381</b>
	<b>2205 E BELT ST</b>	<b>RCRA-LQG</b>	<b>CAT000614933</b>
	<b>SAN DIEGO, CA 92113</b>		

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource  
Conservation and Recovery Act (RCRA) program through the tracking of  
events and activities related to facilities that generate, transport,

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP (BAE SYSTEMS) (Continued)**

**1000434381**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

**RCRA-LQG:**

Date form received by agency: 01/04/2007  
 Facility name: BAE SYSTEMS  
 Facility address: 2205 E BELT ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAT000614933  
 Mailing address: PO BOX 85278  
 MS 22A  
 SAN DIEGO, CA 92186 5278  
 Contact: MICHAEL CHEE  
 Contact address: PO BOX 85278 MS 22A  
 SAN DIEGO, CA 92186 5278  
 Contact country: US  
 Contact telephone: 619-544-7778  
 Contact email: MCHEE@NASSCO.COM  
 EPA Region: 09  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

**Owner/Operator Summary:**

Owner/operator name: BAE SYSTEMS  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: Not reported  
 Owner/operator telephone: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP (BAE SYSTEMS) (Continued)**

**1000434381**

Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/29/2001  
 Owner/Op end date: Not reported

Owner/operator name: PORT OF SAN DIEGO  
 Owner/operator address: 3165 PACIFIC HWY  
 SAN DIEGO, CA 92101

Owner/operator country: US  
 Owner/operator telephone: Not reported

Legal status: State  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1963  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 09/01/1996  
 Facility name: BAE SYSTEMS  
 Site name: CHEVRON USA INC BUMBLE BEE SEAFOODS BP  
 Classification: Small Quantity Generator

Date form received by agency: 08/15/1980  
 Facility name: BAE SYSTEMS  
 Site name: CHEVRON USA INC BUMBLE BEE SEAFOODS BP  
 Classification: Large Quantity Generator

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP (BAE SYSTEMS) (Continued)**

**1000434381**

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D006  
 Waste name: CADMIUM

Waste code: D008  
 Waste name: LEAD

Violation Status: No violations found

79

**PACIFIC SHIP REPAIR AND FABRICATION BAE  
 2205 E BELT ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1008402385  
 CAR000164632**

RCRA-SQG:

Date form received by agency: 07/15/2005  
 Facility name: PACIFIC SHIP REPAIR AND FABRICATION BAE  
 Facility address: 2205 E BELT ST  
 PIER 1  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000164632  
 Mailing address: 1625 RIGEL ST  
 SAN DIEGO, CA 92113  
 Contact: LISA L SIPES  
 Contact address: 1625 RIGEL ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: 619-232-3200  
 Telephone ext.: 155  
 Contact email: LSIPES@PACSHIP.COM  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: PACIFIC SHIP REPAIR AND FABRICATION  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 07/13/2005  
 Owner/Op end date: Not reported

Owner/operator name: PORT OF SAN DIEGO  
 Owner/operator address: PO BOX 488  
 SAN DIEGO, CA 92112  
 Owner/operator country: US

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR AND FABRICATION BAE (Continued)**

**1008402385**

Owner/operator telephone: Not reported  
 Legal status: District  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1965  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D005  
 Waste name: BARIUM

Waste code: D007  
 Waste name: CHROMIUM

Waste code: D008  
 Waste name: LEAD

Waste code: D009  
 Waste name: MERCURY

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EPA ID Number  
 EDR ID Number

**PACIFIC SHIP REPAIR AND FABRICATION BAE (Continued)**

1008402385

MIXTURES.

Violation Status: No violations found

79 **SOUTHWEST MARINE INC**  
**1427 W SAMPSON ST**  
**SAN DIEGO, CA 92113**

**SAN DIEGO CO. SAM** **S108407254**  
**N/A**

SAN DIEGO CO. SAM:

Case Number: H09689-003  
 Agency: CA Regional Water Quality Control Board  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Preliminary Assessment  
 Date: 10/18/2002  
 Begandt: 9/11/2002

79 **BAE SYSTEMS SAN DIEGO SHIP REPAIR MSD**  
**1401 SAMPSON ST**  
**SAN DIEGO, CA 92113**

**HAZNET** **1008402424**  
**RCRA-LQG** **CAR000165183**

HAZNET:

Gepaid: CAR000165183  
 Contact: SANDOR HALVAX  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 921703308  
 Gen County: San Diego  
 TSD EPA ID: CAD008488025  
 TSD County: Los Angeles  
 Waste Category: Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)  
 Disposal Method: Recycler  
 Tons: 2.05  
 Facility County: Not reported

Gepaid: CAR000165183  
 Contact: SANDOR HALVAX  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 921703308  
 Gen County: San Diego  
 TSD EPA ID: CAD008488025  
 TSD County: Los Angeles  
 Waste Category: Alkaline solution without metals (pH > 12.5)  
 Disposal Method: Recycler  
 Tons: 0.1  
 Facility County: San Diego

RCRA-LQG:

Date form received by agency: 08/29/2005  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR MSD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR MSD (Continued)**

**1008402424**

Facility address: 1401 SAMPSON ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000165183  
 Mailing address: PO BOX 13308  
 SAN DIEGO, CA 921703308  
 Contact: SANDOR HALVAX  
 Contact address: PO BOX 13308  
 SAN DIEGO, CA 921703308  
 Contact country: US  
 Contact telephone: 619-238-1000  
 Telephone ext.: 2060  
 Contact email: SANDOR.HALVAX@BAESYSTEMS.COM  
 EPA Region: 09  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

**Owner/Operator Summary:**

Owner/operator name: BAE SYSTEMS SAN DIEGO SHIP REPAIR  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1985  
 Owner/Op end date: Not reported

Owner/operator name: BAE SYSTEMS SAN DIEGO SHIP REPAIR  
 Owner/operator address: PO BOX 13308  
 SAN DIEGO, CA 92170  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1985  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR MSD (Continued)**

**1008402424**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D004  
 Waste name: ARSENIC

Waste code: D005  
 Waste name: BARIUM

Waste code: D006  
 Waste name: CADMIUM

Waste code: D008  
 Waste name: LEAD

Waste code: D009  
 Waste name: MERCURY

Waste code: D035  
 Waste name: METHYL ETHYL KETONE

Waste code: F001  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR MSD (Continued)**

**1008402424**

Waste code: F002  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

79

**SOUTHWEST MARINE  
 1401 SAMPSON ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104750101  
 SWEEPS UST N/A**

San Diego Co. HMMD:  
 Facility ID: 123049  
 Inactive Indicator: Active  
 Business Code: 6HK71  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P O BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD981172554  
 Gas Station: Not reported  
 Inspection Date: 05/28/04  
 Reinspection Date: Not reported  
 Inspector Name: MCHAIRS  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE (Continued)**

**S104750101**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: S W M HOLDINGS INC  
 Property Address: C/O SOUTHWEST MARINE  
 Property City,St,Zip: 92170  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 11/28/05  
 Facility Phone: 619-238-1000

**HMMD DISCLOSURE INVENTORY:**

Item Number: 2150  
 Chemical Name: 2190 TEP LUBE OIL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: AC58  
 Chemical Name: ACETONE  
 Case Number: 67-64-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: AC70  
 Chemical Name: ACETONE ACETONE  
 Case Number: 67-64-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: AR98  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST MARINE (Continued)**

**S104750101**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: CE51  
 Chemical Name: CE-27 RUST STRIPPER  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: DI49  
 Chemical Name: DIESEL FUEL #2  
 Case Number: 64873-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: GR59  
 Chemical Name: GREASE, VARIOUS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: MI72  
 Chemical Name: MIL-P-2441/20 F-150 EPOXY COATING  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: Not reported

Item Number: NI99  
 Chemical Name: NITROGEN (LIQUID AND GAS)  
 Case Number: 7727-37-9

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST MARINE (Continued)**

**S104750101**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: NM54  
 Chemical Name: NM-50 CHEMICAL CLEANER AND DEGREASER  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: OI01  
 Chemical Name: OILS; LUBRICATING  
 Case Number: 8002-09-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: OX96  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PA60  
 Chemical Name: PAINT, EPOXY  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE (Continued)**

**S104750101**

Item Number: PR97  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: SO71  
 Chemical Name: SODIUM HYDROXIDE SODIUM HYDROXIDE  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

Item Number: SO56  
 Chemical Name: SODIUM HYDROXIDE SOLUTION  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/02/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4382  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/02/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 4383  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHWEST MARINE (Continued)**

**S104750101**

Inspection Date: 08/02/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 6838  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 05/28/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1920  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 05/28/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 22  
 Annual Qty String: 22  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 05/28/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 400  
 Quantity String: 400  
 Annual Qty: 1200  
 Annual Qty String: 1200  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: OILY RAGS  
 Carcinogen: No

Inspection Date: 05/28/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHWEST MARINE (Continued)**

**S104750101**

Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 23049  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-023049-000001  
 Actv Date: Not reported  
 Capacity: 675  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: 1

79

**ISP ALGINATES  
 2145 E BELT ST  
 SAN DIEGO, CA 92113**

**LUST U003789073  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301155  
 Stop Date: 1985-11-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-05-16 00:00:00  
 Discover Date: 1985-11-20 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1985-11-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

ISP ALGINATES (Continued)

U003789073

Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Alcohol  
 Contact Person: Not reported  
 Responsible Party: RON J. HALIK  
 RP Address: P.O. BOX 23576  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-001  
 Case Number: 9UT239  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301188  
 Stop Date: 1987-07-21 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-09-28 00:00:00  
 Discover Date: 1987-07-21 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-07-21 00:00:00  
 Review Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

ISP ALGINATES (Continued)

U003789073

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Kerosene  
 Contact Person: Not reported  
 Responsible Party: RON J. HALIK  
 RP Address: P.O. BOX 23576  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-002  
 Case Number: 9UT2423  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608117074  
 Stop Date: 1994-12-06 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

ISP ALGINATES (Continued)

U003789073

Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1995-08-15 00:00:00  
 Discover Date: 1993-12-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-09-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-007  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

ISP ALGINATES (Continued)

U003789073

Global Id: T0608119278  
 Stop Date: 1992-08-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-08-21 00:00:00  
 Discover Date: 1992-08-20 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-09-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-004  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ISP ALGINATES (Continued)**

**U003789073**

Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608126802  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-03-15 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: MS EVELYN PETERSON  
 RP Address: 2025 E HARBOR DR  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-009  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES (Continued)**

**U003789073**

Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608138779  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1995-03-27 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1995-03-27 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1995-03-27 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

ISP ALGINATES (Continued)

U003789073

Local Case #: H02377-005  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608151729  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-08-20 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: CHET VASEY  
 RP Address: 2145 E BELT ST  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES (Continued)**

**U003789073**

Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-008  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608151998  
 Stop Date: 1994-01-13 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-03-15 00:00:00  
 Discover Date: 1994-01-13 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-03-17 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ISP ALGINATES (Continued)

U003789073

Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-006  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608163856  
 Stop Date: 2001-03-12 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2001-03-29 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2001-03-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-03-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES (Continued)**

**U003789073**

Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: ATT.: JON J. HALIK  
 RP Address: P.O. BOX 23576  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-010  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608179993  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1992-03-26 00:00:00  
 Discover Date: 1990-01-02 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-01-02 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES (Continued)**

**U003789073**

MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: RON HALIK  
 RP Address: 2145 E BELT ST  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02377-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

79

**KELCO DIVISION OF MERCK & CO., INC.**  
**2145 EAST BELT**  
**SAN DIEGO, CA 92113**

**CERC-NFRAP 1003879832**  
**CAD983658436**

CERC-NFRAP:  
 Site ID: 0904769  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):  
 Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)  
  
 Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KELCO DIVISION OF MERCK & CO., INC. (Continued)**

**1003879832**

Contact Title: Site Assessment Manager (SAM)

CERCLIS-NFRAP Site Alias Name(s):  
 Alias Name: MERCK AND CO.  
 Alias Address: Not reported  
 CA  
 Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/08/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 08/31/1993  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 08/31/1993  
 Priority Level: NFRAP (No Futher Remedial Action Planned)

79

**MERCK & COMPANY  
 2145 E BELT ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 HIST UST  
 SWEEPS UST**

**1000175734  
 N/A**

HAZNET:

Gepaid: CAD981379415  
 Contact: DAVID MCKINLEY, ENV HEALTH & SAFTEY  
 Telephone: 6195573100  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2145 E BELT ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921132213  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: 1.4  
 Facility County: Not reported

Gepaid: CAD981379415  
 Contact: DAVID MCKINLEY, ENV HEALTH & SAFTEY  
 Telephone: 6195573100  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1361 ALPS ROAD  
 Mailing City,St,Zip: WAYNE, NJ 74700000  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.84  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MERCK & COMPANY (Continued)**

**1000175734**

Gepaid: CAD981379415  
 Contact: DAVID MCKINLEY, ENV HEALTH & SAFTEY  
 Telephone: 6195573100  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2145 E BELT ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921132213  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.1  
 Facility County: San Diego

Gepaid: CAD981379415  
 Contact: DAVID MCKINLEY, ENV HEALTH & SAFTEY  
 Telephone: 6195573100  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2145 E BELT ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921132213  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Not reported  
 Tons: 0.11  
 Facility County: San Diego

Gepaid: CAD981379415  
 Contact: DAVID MCKINLEY, ENV HEALTH & SAFTEY  
 Telephone: 6195573100  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2145 E BELT ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921132213  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Treatment, Incineration  
 Tons: 1.8  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 6 additional CA\_HAZNET: record(s) in the EDR Site Report.

HIST UST:  
 Region: STATE  
 Facility ID: 00000001334  
 Facility Type: Other  
 Other Type: KELP PROCESSING AND  
 Total Tanks: 0010  
 Contact Name: R. M. KULAKOW, PLANT MANAGER  
 Telephone: 6192924900  
 Owner Name: KELCO, DIV. MERCK & CO., INC.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MERCK & COMPANY (Continued)**

**1000175734**

Owner Address: 8355 AERO DRIVE  
 Owner City,St,Zip: SAN DIEGO, CA 92123

Tank Num: 001  
 Container Num: B 1  
 Year Installed: 1943  
 Tank Capacity: 00000000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002  
 Container Num: G 1  
 Year Installed: 1982  
 Tank Capacity: 00000550  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: 5/16 inches  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: IPA 1  
 Year Installed: 1947  
 Tank Capacity: 00015000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: Visual, Stock Inventor

Tank Num: 004  
 Container Num: IPA 2  
 Year Installed: 1947  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: Visual, Stock Inventor

Tank Num: 005  
 Container Num: IPA 3  
 Year Installed: 1947  
 Tank Capacity: 00003000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: None

Tank Num: 006  
 Container Num: PO 1  
 Year Installed: 1970  
 Tank Capacity: 00011000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: Stock Inventor

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MERCK & COMPANY (Continued)**

**1000175734**

Tank Num: 007  
 Container Num: PO 2  
 Year Installed: 1969  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: Stock Inventor

Tank Num: 008  
 Container Num: PO 3  
 Year Installed: 1960  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: Stock Inventor

Tank Num: 009  
 Container Num: PO 4  
 Year Installed: 1960  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: Stock Inventor

Tank Num: 010  
 Container Num: PO 5  
 Year Installed: 1974  
 Tank Capacity: 00011000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 5/16 inches  
 Leak Detection: Stock Inventor

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 2377  
 Number: Not reported  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000001  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: 5

Status: Not reported  
 Comp Number: 2377  
 Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MERCK & COMPANY (Continued)**

**1000175734**

Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2377  
 Number: Not reported  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000003  
 Actv Date: Not reported  
 Capacity: 15000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2377  
 Number: Not reported  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000004  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 2377  
 Number: Not reported  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MERCK & COMPANY (Continued)**

**1000175734**

Swrcb Tank Id: 37-000-002377-000005  
 Actv Date: Not reported  
 Capacity: 3000  
 Tank Use: CHEMICAL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2377  
 Number: 9  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000006  
 Actv Date: Not reported  
 Capacity: 11000  
 Tank Use: CHEMICAL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: 5

Status: A  
 Comp Number: 2377  
 Number: 9  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000007  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: CHEMICAL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2377  
 Number: 9  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000008  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: CHEMICAL  
 Stg: P  
 Content: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MERCK & COMPANY (Continued)**

1000175734

Number Of Tanks: Not reported

Status: A  
 Comp Number: 2377  
 Number: 9  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000009  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: CHEMICAL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2377  
 Number: 9  
 Board Of Equalization: 44-021680  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002377-000010  
 Actv Date: Not reported  
 Capacity: 11000  
 Tank Use: CHEMICAL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

79

**2145 EAST BELT STREET  
 SAN DIEGO, CA**

CHMIRS S105654627  
 ENVIROSTOR N/A

CHMIRS:  
 OES Incident Number: 98-3972  
 OES notification: 8/31/199802:36:44 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105654627

Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1998  
 Agency: USCG San Diego  
 Incident Date: 8/31/1998 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Unknown  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Unk  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuatiions: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105654627

Description: Sheen reported at dock in front of 2145 East Belt Street, in San Diego Bay, sheen size 40' by 500' long, lat 32.40.5 North/lon 117.8.5 West. Per NRC: The material released from a flare due to normal operation.

OES Incident Number: 03-0404  
 OES notification: 1/21/2003 11:57:29 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personnel # Of Decontaminated: Not reported  
 Responding Agency Personnel # Of Injuries: Not reported  
 Responding Agency Personnel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: No  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2003  
 Agency: NRC  
 Incident Date: 1/21/2003 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105654627

Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Choline Chloride solution
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Sheen reported at dock in front of 2145 East Belt Street, in San Diego Bay, sheen size 40' by 500' long, lat 32.40.5 North/lon 117.8.5 West. Per NRC: The material released from a flare due to normal operation.

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	So Cal - Cypress
Facility ID:	37000031
Site Code:	Not reported
Assembly:	79
Senate:	40
Special Program:	Not reported
Status:	Refer: 1248 Local Agency
Status Date:	2001-01-23 00:00:00
Restricted Use:	NO
Funding:	Not Applicable
Latitude:	0
Longitude:	0
Alias Name:	37000031
Alias Type:	Envirostor ID Number
APN:	NONE SPECIFIED
APN Description:	Not reported
Comments:	Not reported

Completed Info:

Completed Area Name:	Not reported
Completed Sub Area Name:	Not reported
Completed Document Type:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105654627

Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

79

**ISP ALGINATES INCORPORATED**  
**2145 EAST BELT STREET**  
**SAN DIEGO, CA 92113**

**LUST 1000984877**  
**Cortese 92113KLCDV21**  
**TRIS**  
**AIRS**

LUST:

Region: 9  
 Case Number: 9UT239  
 Local Agency: San Diego  
 Substance: Alcohol  
 Qty Leaked: 0  
 Date Found: 07/21/1987  
 How Found: Other Means  
 Date Stopped: 07/21/1987  
 How Stopped: Repair Piping  
 Source: Piping  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 11/20/1985  
 Submit Workplan: Not reported  
 Prelim Assess: 06/17/1986  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 9/28/88  
 Pilot Program: LOP  
 Local Case: H02377-001  
 Basin Number: 908.22  
 Gwater Depth: >25'

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES INCORPORATED (Continued)**

**1000984877**

Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 11/18/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT2423  
 Local Agency: San Diego  
 Substance: Kerosene  
 Qty Leaked: 0  
 Date Found: 07/21/1987  
 How Found: Other Means  
 Date Stopped: 07/21/1987  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site

Confirm Date: 07/21/1987  
 Submit Workplan: 7/21/87  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 9/28/88  
 Pilot Program: LOP  
 Local Case: H02377-002  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 07/24/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 2145 BELT ST E

Region: CORTESE  
 Facility Addr2: 2145 BELT ST E

EMI:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ISP ALGINATES INCORPORATED (Continued)**

**1000984877**

Year: 1997  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 118  
 Air District Name: SD  
 SIC Code: 2833  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1219  
 Reactive Organic Gases Tons/Yr: 1165  
 Carbon Monoxide Emissions Tons/Yr: 122  
 NOX - Oxides of Nitrogen Tons/Yr: 175  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 12  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 12

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 118  
 Air District Name: SD  
 SIC Code: 2833  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 981  
 Reactive Organic Gases Tons/Yr: 926  
 Carbon Monoxide Emissions Tons/Yr: 99  
 NOX - Oxides of Nitrogen Tons/Yr: 179  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 12  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 12

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 118  
 Air District Name: SD  
 SIC Code: 2833  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 981  
 Reactive Organic Gases Tons/Yr: 926  
 Carbon Monoxide Emissions Tons/Yr: 99  
 NOX - Oxides of Nitrogen Tons/Yr: 179  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 12  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 12

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7006  
 Air District Name: SD  
 SIC Code: 2833

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES INCORPORATED (Continued)**

**1000984877**

Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 41  
 Reactive Organic Gases Tons/Yr: 41  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 118  
 Air District Name: SD  
 SIC Code: 2099  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: N  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 103  
 Reactive Organic Gases Tons/Yr: 58  
 Carbon Monoxide Emissions Tons/Yr: 44  
 NOX - Oxides of Nitrogen Tons/Yr: 94  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 10  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 10

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7006  
 Air District Name: SD  
 SIC Code: 2833  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 41  
 Reactive Organic Gases Tons/Yr: 41  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 118  
 Air District Name: SD  
 SIC Code: 2099  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 72  
 Reactive Organic Gases Tons/Yr: 59  
 Carbon Monoxide Emissions Tons/Yr: 15

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ISP ALGINATES INCORPORATED (Continued)**

**1000984877**

NOX - Oxides of Nitrogen Tons/Yr:	76
SOX - Oxides of Sulphur Tons/Yr:	2
Particulate Matter Tons/Yr:	10
Part. Matter 10 Micrometers & Smlr Tons/Yr:	10
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7006
Air District Name:	SD
SIC Code:	2833
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	28
Reactive Organic Gases Tons/Yr:	28
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	118
Air District Name:	SD
SIC Code:	2099
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	N
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	96
Reactive Organic Gases Tons/Yr:	47
Carbon Monoxide Emissions Tons/Yr:	14
NOX - Oxides of Nitrogen Tons/Yr:	72
SOX - Oxides of Sulphur Tons/Yr:	1
Particulate Matter Tons/Yr:	11
Part. Matter 10 Micrometers & Smlr Tons/Yr:	11
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7006
Air District Name:	SD
SIC Code:	2833
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	N
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	34
Reactive Organic Gases Tons/Yr:	34
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ISP ALGINATES INCORPORATED (Continued)**

**1000984877**

Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 118  
 Air District Name: SD  
 SIC Code: 2099  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 95.6526  
 Reactive Organic Gases Tons/Yr: 47.407455  
 Carbon Monoxide Emissions Tons/Yr: 14.3596697  
 NOX - Oxides of Nitrogen Tons/Yr: 71.9631818  
 SOX - Oxides of Sulphur Tons/Yr: 0.81207  
 Particulate Matter Tons/Yr: 10.74165  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 10.74165

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7006  
 Air District Name: SD  
 SIC Code: 2833  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 33.5049992  
 Reactive Organic Gases Tons/Yr: 33.5049992  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7006  
 Air District Name: SD  
 SIC Code: 2833  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 43.54  
 Reactive Organic Gases Tons/Yr: 43.54  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

79 **ISP ALGINATES INCORPORATED**  
**2145 E. BELT STREET**  
**SAN DIEGO, CA 92113**

**UST** 1007199198  
**SAN DIEGO CO. SAM** CAD981379415  
**RCRA-NonGen**  
**MANIFEST**

UST:

Local Agency: 37000  
 Facility ID: H02377

SAN DIEGO CO. SAM:

Case Number: H02377-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/16/1989  
 Begandt: 11/20/1985

Case Number: H02377-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/28/1988  
 Begandt: 7/21/1987

Case Number: H02377-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/26/1992  
 Begandt: 1/2/1990

Case Number: H02377-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/21/1993  
 Begandt: 8/20/1992

Case Number: H02377-005  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 3/27/1995  
 Begandt: 3/27/1995

Case Number: H02377-006  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/15/2004  
 Begandt: 1/13/1994

Case Number: H02377-007

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ISP ALGINATES INCORPORATED (Continued)**

**1007199198**

Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/15/1995  
 Begandt: 12/6/1993

Case Number: H02377-008  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/20/1996  
 Begandt: 9/18/1995

Case Number: H02377-009  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/15/2004  
 Begandt: 1/22/2001

Case Number: H02377-010  
 Agency: DEH Site Assessment & Mitigation  
**Funding:** **Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 3/29/2001  
 Begandt: 3/12/2001

RCRA-NonGen:

Date form received by agency: 01/23/2007  
 Facility name: ISP ALGINATES INCORPORATED  
 Facility address: 2145 E BELT ST  
 SAN DIEGO, CA 92113-2213  
 EPA ID: CAD981379415  
 Mailing address: HWY 95  
 CALVERT CITY, KY 42029  
 Contact: JAMES LEONARD  
 Contact address: HWY 95  
 CALVERT CITY, KY 42029  
 Contact country: US  
 Contact telephone: 270-395-1370  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Private  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: INTERNATIONAL SPECIALTY PRODUCTS INC  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: Not reported  
 Owner/operator telephone: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES INCORPORATED (Continued)**

**1007199198**

Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	10/18/1999
Owner/Op end date:	Not reported
Owner/operator name:	INTERNATIONAL SPECIALTY PRODUCTS INC
Owner/operator address:	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/18/1999
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Historical Generators:

Date form received by agency:	11/21/2006
Facility name:	ISP ALGINATES INCORPORATED
Classification:	Not a generator, verified
Date form received by agency:	08/21/2003
Facility name:	ISP ALGINATES INCORPORATED
Classification:	Small Quantity Generator
Date form received by agency:	10/01/2001
Facility name:	ISP ALGINATES INCORPORATED
Site name:	KELCO A UNIT OF MONSANTO CO
Classification:	Not a generator, verified
Date form received by agency:	09/01/1996
Facility name:	ISP ALGINATES INCORPORATED
Site name:	KELCO A UNIT OF MONSANTO CO
Classification:	Small Quantity Generator
Date form received by agency:	02/29/1996
Facility name:	ISP ALGINATES INCORPORATED
Site name:	THE NUTRASWEET KELCO COMPANY
Classification:	Large Quantity Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ISP ALGINATES INCORPORATED (Continued)**

**1007199198**

Date form received by agency: 04/12/1990  
 Facility name: ISP ALGINATES INCORPORATED  
 Site name: KELCO DIV OF MERCK & CO, INC  
 Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 01/25/1996  
 Evaluation: FOCUSED COMPLIANCE INSPECTION  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

NY MANIFEST:

Document ID: NYA6107922  
 Manifest Status: Completed copy  
 Trans1 State ID: 703759  
 Trans2 State ID: X17593  
 Generator Ship Date: 870421  
 Trans1 Recv Date: 870421  
 Trans2 Recv Date: Not reported  
 TSD Site Recv Date: 870429  
 Part A Recv Date: 870430  
 Part B Recv Date: 870506  
 Generator EPA ID: CAD981379415  
 Trans1 EPA ID: NYD980769947  
 Trans2 EPA ID: Not reported  
 TSD ID: NYD000632372  
 Waste Code: D003 - NON-LISTED REACTIVE WASTES  
 Quantity: 00003  
 Units: P - Pounds  
 Number of Containers: 001  
 Container Type: DM - Metal drums, barrels  
 Handling Method: T Chemical, physical, or biological treatment.  
 Specific Gravity: 100  
 Year: 87  
 Manifest Tracking Num: Not reported  
 Import Ind: Not reported  
 Export Ind: Not reported  
 Discr Quantity Ind: Not reported  
 Discr Type Ind: Not reported  
 Discr Residue Ind: Not reported  
 Discr Partial Reject Ind: Not reported  
 Discr Full Reject Ind: Not reported  
 Manifest Ref Num: Not reported  
 Alt Fac RCRA Id: Not reported  
 Alt Fac Sign Date: Not reported  
 Mgmt Method Type Code: Not reported  
 EPA ID: CAD981379415  
 Facility Name: KELCO  
 Facility Address: P. O. BOX 13216  
 Facility City: SAN DIEGO  
 Facility Address 2: Not reported  
 Country: USA  
 Mailing Name: KELCO  
 Mailing Contact: KELCO

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ISP ALGINATES INCORPORATED (Continued)**

**1007199198**

Mailing Address: P. O. BOX 13216  
 Mailing Address 2: Not reported  
 Mailing City: SAN DIEGO  
 Mailing State: CA  
 Mailing Zip: 92112  
 Mailing Zip4: Not reported  
 Mailing Country: USA  
 Mailing Phone: 619-292-4900

79

**SAN DIEGO GAS AND ELECTRIC  
 1348 SAMPSON STREET  
 SAN DIEGO, CA**

**SLIC S107869637  
 N/A**

**SLIC:**

Region: STATE  
 Global Id: SL0607312697  
 Assigned Name: SLICSITE  
 Lead Agency Contact: BEATRICE GRIFFEY  
 Lead Agency: SAN DIEGO RWQCB (REGION 9)  
 Lead Agency Case Number: 9 000552N05  
 Responsible Party: Not reported  
 Recent Dtw: Not reported  
 Substance Released: 76  
**Facility Status: Case Open**

79

**SILVER GATE POWER PLANT  
 1348 SAMPSON ST  
 SAN DIEGO, CA 92113**

**HIST UST U001572995  
 N/A**

**HIST UST:**

Region: STATE  
 Facility ID: 00000063684  
 Facility Type: Other  
 Other Type: UTILITY  
 Total Tanks: 0005  
 Contact Name: ERTL F. OXENDINE  
 Telephone: 6196962000  
 Owner Name: SAN DIEGO GAS & ELECTRIC  
 Owner Address: 101 ASH STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92101

Tank Num: 001  
 Container Num: 1501  
 Year Installed: 1941  
 Tank Capacity: 00224000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: 12 inches  
 Leak Detection: Groundwater Monitoring Well

Tank Num: 002  
 Container Num: 1502  
 Year Installed: 1941  
 Tank Capacity: 00224000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SILVER GATE POWER PLANT (Continued)**

**U001572995**

Tank Construction: 12 inches  
 Leak Detection: Groundwater Monitoring Well

Tank Num: 003  
 Container Num: 1503  
 Year Installed: 1941  
 Tank Capacity: 00224000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: 12 inches  
 Leak Detection: Groundwater Monitoring Well

Tank Num: 004  
 Container Num: 1504  
 Year Installed: 1947  
 Tank Capacity: 00114000  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: 10 inches  
 Leak Detection: None

Tank Num: 005  
 Container Num: 1505  
 Year Installed: 1945  
 Tank Capacity: 00038000  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: 10 inches  
 Leak Detection: None

79

**SAN DIEGO GAS & ELECTRIC - SILVERGATE  
 1348 SAMPSON STREET  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000110791  
 FINDS CAT000618934  
 HAZNET**

RCRA-SQG:

Date form received by agency: 03/22/2006  
 Facility name: SAN DIEGO GAS & ELECTRIC - SILVERGATE  
 Facility address: 1348 SAMPSON STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CAT000618934  
 Mailing address: 8315 CENTURY PARK COURT  
 CP21E  
 SAN DIEGO, CA 92123  
 Contact: PATRICK J CANNEY  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (858) 637-3740  
 Contact email: PCANNEY@SEMPRAUTILITIES.COM  
 EPA Region: 09  
 Land type: Private  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO GAS & ELECTRIC - SILVERGATE (Continued)**

**1000110791**

Owner/Operator Summary:

Owner/operator name: SAN DIEGO GAS & ELECTRIC  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1943  
 Owner/Op end date: Not reported

Owner/operator name: SAN DIEGO GAS & ELECTRIC  
 Owner/operator address: 8316 CENTURY PARK COURT  
 SAN DIEGO, CA 92123  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1943  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO GAS & ELECTRIC - SILVERGATE (Continued)**

**1000110791**

Historical Generators:

Date form received by agency: 03/22/2006  
 Facility name: SAN DIEGO GAS & ELECTRIC - SILVERGATE  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: SAN DIEGO GAS & ELECTRIC - SILVERGATE  
 Site name: SAN DIEGO GAS & ELEC SILVERGATE POW PLT  
 Classification: Small Quantity Generator

Date form received by agency: 04/09/1990  
 Facility name: SAN DIEGO GAS & ELECTRIC - SILVERGATE  
 Site name: SAN DIEGO GAS & ELECTRIC CO. SILVER GATE  
 Classification: Large Quantity Generator

Date form received by agency: 08/18/1980  
 Facility name: SAN DIEGO GAS & ELECTRIC - SILVERGATE  
 Site name: SAN DIEGO GAS & ELEC SILVERGATE POW PLT  
 Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D008  
 Waste name: LEAD

Waste code: D009  
 Waste name: MERCURY

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D008  
 Waste name: LEAD  
 Amount (Lbs): 650

Waste code: D009  
 Waste name: MERCURY  
 Amount (Lbs): 4788

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 01/31/1996  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 04/21/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GAS & ELECTRIC - SILVERGATE (Continued)**

**1000110791**

Evaluation date: 10/15/1984  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

CAMDBS (Clean Air Markets Division Business System) is a national information system that supports the implementation of market-based air pollution control programs administered by the Clean Air Markets Division, within the Office of Air and Radiation. These programs include the Acid Rain Program, established by Title IV of the Clean Air Act Amendments of 1990, and regional programs designed reduce the transport of ozone. These emissions trading programs allows regulated facilities (primarily electric utilities) to adopt the most cost-effective strategies to reduce emissions at their units. Units that reduce their emissions below the number of allowances they hold -- each allowance is equivalent to one ton of sulfur dioxide or nitrogen oxides -- may trade allowances with other units in their system, sell them to other utilities on the open market or through EPA auctions, or bank them to cover emissions in future years. CAMDBS functions include registering responsible officials, establishing allowance accounts, reporting hourly emissions data, and transferring allowances between accounts.

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAT000618934  
 Contact: PATRICK CANNEY/ENV. SPEC.  
 Telephone: 8586373740  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 8315 CENTURY PARK CT CP21E  
 Mailing City,St,Zip: SAN DIEGO, CA 921231548  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Other  
 Tons: 0.05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GAS & ELECTRIC - SILVERGATE (Continued)**

**1000110791**

Facility County: Not reported  
 Gepaid: CAT000618934  
 Contact: PATRICK CANNEY/ENV. SPEC.  
 Telephone: 8586373740  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 8315 CENTURY PARK CT CP21E  
 Mailing City,St,Zip: SAN DIEGO, CA 921231548  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Other  
 Tons: 0.05  
 Facility County: Not reported

Gepaid: CAT000618934  
 Contact: PATRICK CANNEY/ENV. SPEC.  
 Telephone: 8586533104  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 6875 CONSOLIDATED WAY SD1373  
 Mailing City,St,Zip: SAN DIEGO, CA 921212602  
 Gen County: San Diego  
 TSD EPA ID: AZ0000337360  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Recycler  
 Tons: 0.01  
 Facility County: San Diego

79

**SILVERGATE POWER PLANT  
 1348 SAMPSON ST  
 SAN DIEGO, CA 92112**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S102437552  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: SLT19730585  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2006-11-30 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Ken Rowland  
 RP Address: 555 W. 5th St., GT16G2  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13942-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019761425  
 Stop Date: Not reported  
 Confirm Leak: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

Workplan: Not reported  
 Prelim Assess: 2006-07-24 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Ken Rowland  
 RP Address: 8315 Century Park Court, CP2E  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13942-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302743  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1988-02-04 00:00:00  
 Discover Date: 1986-09-29 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-09-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13942-001  
 Case Number: 9UT437  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

Summary: Not reported

LUST:

Region: 9  
 Case Number: 9UT437  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 09/29/1986  
 How Found: Other Means  
 Date Stopped: / /  
 How Stopped: Remove Contents  
 Source: Piping  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 04/01/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 7/31/87  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 2/12/88  
 Pilot Program: LOP  
 Local Case: H13942-001  
 Basin Number: 908.22  
 Gwater Depth: 19FT  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 10/03/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 1348 SAMPSON ST

San Diego Co. HMMD:

Facility ID: 113942  
 Inactive Indicator: Active  
 Business Code: 6HK52  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ENVIRONMENTAL - HQ05D  
 Mailing Address: 101 ASH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: CAT000618934  
 Gas Station: Not reported  
 Inspection Date: 06/03/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: LYNN JAHN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO GAS&ELECTRIC CO  
 Property Address: CALIFORNIA STATE ASS  
 Property City,St,Zip: 00000  
 Tank Owner: SAN DIEGO GAS & ELECTRIC  
 Tank Address: 101 ASH ST  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-4925

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1501  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 1502  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 1503  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: 1504  
 Waste or Product: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

Tank Contents: Not reported  
 Tank Number: T005  
 Tank ID Number: 1505  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 13942  
 Number: Not reported  
 Board Of Equalization: 44-016357  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013942-000001  
 Actv Date: Not reported  
 Capacity: 224000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 5  
 Status: Not reported  
 Comp Number: 13942  
 Number: Not reported  
 Board Of Equalization: 44-016357  
 Ref Date: Not reported  
 Act Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013942-000002  
 Actv Date: Not reported  
 Capacity: 224000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 13942  
 Number: Not reported  
 Board Of Equalization: 44-016357  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013942-000003  
 Actv Date: Not reported  
 Capacity: 224000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 13942  
 Number: Not reported  
 Board Of Equalization: 44-016357  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013942-000004  
 Actv Date: Not reported  
 Capacity: 114000  
 Tank Use: CHEMICAL  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 13942  
 Number: Not reported  
 Board Of Equalization: 44-016357  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013942-000005  
 Actv Date: Not reported  
 Capacity: 38000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SILVERGATE POWER PLANT (Continued)**

**S102437552**

Tank Use: CHEMICAL  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 13942  
 Number: 9  
 Board Of Equalization: 44-016357  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H13942-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/4/1988  
 Begandt: 9/29/1986

Case Number: H13942-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 7/24/2006  
 Begandt: Not reported

Case Number: H13942-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Preliminary Assessment  
 Date: 11/20/2006  
 Begandt: Not reported

79 **CONTINENTAL MARITIME OF SAN DIEGO, INC.**  
**1995 BAY FRONT STREET**  
**SAN DIEGO, CA 92113**

**LUST 1000412848**  
**CHMIRS CAD981418395**  
**RCRA-LQG**  
**CERC-NFRAP**  
**SAN DIEGO CO. SAM**  
**MANIFEST**

LUST:  
 Region: STATE  
 Case Type: Soil only

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608190985  
 Stop Date: 2002-05-21 00:00:00  
 Confirm Leak: 2002-05-21 00:00:00  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2002-05-21 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2002-05-21 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Leak being confirmed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Craig Fergusson  
 RP Address: 9601 Ridgehaven Court  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: KK  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02857-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT138  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 6000  
 Date Found: 12/12/1986  
 How Found: Tank Closure  
 Date Stopped: 12/12/1986  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 12/12/1986  
 Submit Workplan: Not reported  
 Prelim Assess: 01/09/1987  
 Desc Pollution: Not reported  
 Remed Plan: 08/27/1987  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/25/89  
 Pilot Program: LOP  
 Local Case: H00120-001  
 Basin Number: 908.21  
 Gwater Depth: ~10'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 12/12/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT2467  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 07/10/1992  
 How Found: Subsurface Monitoring  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Case Type: Drinking Water Aquifer affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 07/10/1992  
 Submit Workplan: 7/10/92  
 Prelim Assess: 07/10/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 2/24/97  
 Pilot Program: LOP  
 Local Case: H00120-003  
 Basin Number: 908.22  
 Gwater Depth: 9.03  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 05/06/1993  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT2996  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 08/30/1990  
 How Found: Other Means  
 Date Stopped: 08/30/1990  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 08/30/1990  
 Submit Workplan: Not reported  
 Prelim Assess: 11/22/1991  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 8/31/90  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H00120-002  
 Basin Number: 908.21  
 Gwater Depth: 5'  
 Beneficial Use: No Beneficial groundwater use

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

NPDES Number: Not reported  
 priority: LOP/HIGH - KNOWN HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 08/30/1990  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**CHMIRS:**

OES Incident Number: 006449  
 OES notification: Not reported  
 OES Date: 1/26/1995  
 OES Time: 12:58:25 PM  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: NO  
 Waterway: san diego bay outfall of storm drain  
 Spill Site: Not reported  
 Cleanup By: contennental  
 Containment: Not reported  
 What Happened: Not reported  
 Type: PETROLEUM  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1995

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Agency: contental  
 Incident Date: 0345 26 jan 95  
 Admin Agency: Not reported  
 Amount: residual on ground  
 Contained: YES  
 Site Type: IND PLT  
 E Date: Not reported  
 Substance: transmission fluid  
 Quantity Released: Not reported  
 BBLS: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: transmission failed on truck, some material on the ground carried into storm drain by heavey rains  
 Evacuatuons: NO  
 Number of Injuries: NO  
 Number of Fatalities: NO  
 Description: Not reported

**RCRA-LQG:**

Date form received by agency: 02/25/2006  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Facility address: 1995 BAY FRONT STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981418395  
 Contact: RUSSELL MCCARTHY  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 234-8851  
 Telephone ext.: 351  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: District  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Owner/Operator Summary:

Owner/operator name: CONTINENTIAL MARITIME INC  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 06/01/1986  
 Owner/Op end date: Not reported

Owner/operator name: SAN DIEGO UNIFIED PORT DISTRICT  
 Owner/operator address: 1212 PACIFIC HWY  
 SAN DIEGO, CA 92110  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: District  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1900  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: Yes  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: Yes  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Historical Generators:

Date form received by agency: 02/20/2004  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME SAN DIEGO (SITE)  
 Classification: Large Quantity Generator

Date form received by agency: 02/28/2002  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME INC.  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME INC.  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME INC.  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME OF S D INC  
 Classification: Large Quantity Generator

Date form received by agency: 01/29/1996  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 06/05/1995  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME OF S D INC  
 Classification: Large Quantity Generator

Date form received by agency: 03/31/1994  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 04/30/1992  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME OF SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 04/11/1990  
 Facility name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Site name: CONTINENTAL MARITIME OF S. D.  
 Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: 122  
 Waste name: 122

Waste code: 135  
 Waste name: 135

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Waste code: 212  
 Waste name: 212

Waste code: 214  
 Waste name: 214

Waste code: 331  
 Waste name: 331

Waste code: 352  
 Waste name: 352

Waste code: 791  
 Waste name: 791

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D008  
 Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 27910

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.  
 Amount (Lbs): 16880  
 Waste code: D008  
 Waste name: LEAD  
 Amount (Lbs): 8000

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 10/21/2005  
 Date achieved compliance: 06/26/2006  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 10/21/2005  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/19/1994  
 Date achieved compliance: 08/19/1999  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 01/14/1993  
 Date achieved compliance: 08/19/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 07/23/2007  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Evaluation lead agency: State

Evaluation date: 10/21/2005  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/26/2006  
 Evaluation lead agency: Local

Evaluation date: 08/19/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/19/1999  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 01/14/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/19/1994  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/21/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/26/2006  
 Evaluation lead agency: State Contractor/Grantee

**CERC-NFRAP:**

Site ID: 0904767  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

**CERCLIS-NFRAP Site Contact Name(s):**

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

**CERCLIS-NFRAP Assessment History:**

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/08/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 01/10/1994  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 01/10/1994  
 Priority Level: NFRAP (No Further Remedial Action Planned)

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

SAN DIEGO CO. SAM:

Case Number: H02857-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Leak Being Confirmed  
 Date: 5/21/2002  
 Begandt: 5/21/2002

Case Number: H00120-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/25/1989  
 Begandt: 12/12/1986

Case Number: H00120-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: POP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 4/15/2005  
 Begandt: 8/30/1990

Case Number: H00120-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 2/24/1997  
 Begandt: 7/10/1992

NY MANIFEST:

Document ID: NYB5660415  
 Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC  
 Trans1 State ID: 409234  
 Trans2 State ID: Not reported  
 Generator Ship Date: 930430  
 Trans1 Recv Date: 930430  
 Trans2 Recv Date: Not reported  
 TSD Site Recv Date: 930526  
 Part A Recv Date: 930517  
 Part B Recv Date: 930609  
 Generator EPA ID: CAD981418395  
 Trans1 EPA ID: NYD980769947  
 Trans2 EPA ID: Not reported  
 TSDF ID: NYD048148175  
 Waste Code: D009 - MERCURY 0.2 MG/L TCLP  
 Quantity: 00010  
 Units: P - Pounds  
 Number of Containers: 001  
 Container Type: DM - Metal drums, barrels  
 Handling Method: R Material recovery of more than 75 percent of the total material.  
 Specific Gravity: 100  
 Year: 93

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO, INC. (Continued)**

**1000412848**

Manifest Tracking Num: Not reported  
 Import Ind: Not reported  
 Export Ind: Not reported  
 Discr Quantity Ind: Not reported  
 Discr Type Ind: Not reported  
 Discr Residue Ind: Not reported  
 Discr Partial Reject Ind: Not reported  
 Discr Full Reject Ind: Not reported  
 Manifest Ref Num: Not reported  
 Alt Fac RCRA Id: Not reported  
 Alt Fac Sign Date: Not reported  
 Mgmt Method Type Code: Not reported  
 EPA ID: CAD981418395  
 Facility Name: CONTINENTAL MARITIME OF SAN DIEGO INC  
 Facility Address: 1995 GAY FRONT  
 Facility City: SAN DIEGO  
 Facility Address 2: Not reported  
 Country: USA  
 Mailing Name: CONTINENTAL MARITIME OF SAN DIEGO INC  
 Mailing Contact: CONTINENTAL MARITIME OF SAN DIEGO INC  
 Mailing Address: 1995 GAY FRONT  
 Mailing Address 2: Not reported  
 Mailing City: SAN DIEGO  
 Mailing State: CA  
 Mailing Zip: 92113  
 Mailing Zip4: Not reported  
 Mailing Country: USA  
 Mailing Phone: 819-234-8851

79

**CONTINENTAL MARTIME NASSCO  
 1995 BAY FRONT ST  
 SAN DIEGO, CA 92113**

**RCRA-LQG 1010313741  
 CAR000177378**

RCRA-LQG:

Date form received by agency: 09/19/2006  
 Facility name: CONTINENTAL MARTIME NASSCO  
 Facility address: 1995 BAY FRONT ST  
 PIER 5  
 SAN DIEGO, CA 92113 2122  
 EPA ID: CAR000177378  
 Mailing address: 85278 MS 22 A  
 SAN DIEGO, CA 92186 5278  
 Contact: MICHAEL CHEE  
 Contact address: 85278 MS 22 A  
 SAN DIEGO, CA 92186 5278  
 Contact country: US  
 Contact telephone: 619-544-7778  
 Contact email: MCHEE@NASSCO.COM  
 EPA Region: 09  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARTIME NASSCO (Continued)**

**1010313741**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

**Owner/Operator Summary:**

Owner/operator name: SAN DIEGO UNIFIED PORT DISTRICT  
 Owner/operator address: 3165 PACIFIC HWY  
 SAN DIEGO, CA 92101  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: District  
 Owner/Operator Type: Owner  
 Owner/Op start date: 02/14/1963  
 Owner/Op end date: Not reported

Owner/operator name: CONTINENTAL MARTIME  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 06/08/1985  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Distance (ft.)Site Database(s) EPA ID Number

79 CONTINENTAL MARITIME OF SAN DIEGO RCRA-SQG 1000820618  
 1995 BAYFRONT STREET FINDS CA4170090613  
 SAN DIEGO, CA 92113 HAZNET

RCRA-SQG:

Date form received by agency: 02/15/2006  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Facility address: 1995 BAY FRONT STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CA4170090613  
 Mailing address: 3755 BRINSER ST. BLDG 91  
 SAN DIEGO, CA 92136  
 Contact: LAMBERTO R TORRES  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 556-1055  
 Telephone ext.: NA  
 Contact email: LAMBERTO.TORRES@NAVY.MIL  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: UNIFIED PORT OF SAN DIEGO  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: County  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1958  
 Owner/Op end date: Not reported  
 Owner/operator name: CONTINENTAL MARITIME OF SAN DIEGO  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 10/01/1985  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO (Continued)**

**1000820618**

Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 02/15/2006  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Classification: Large Quantity Generator

Date form received by agency: 02/16/2005  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: SOUTH WEST REGIONAL MAINTENANCE CENTER  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: CONTINENTAL MARITIME OF SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: CONTINENTAL MARITIME OF SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: USNAVY SUPERVISOR OF SHIPBUILDING  
 Classification: Large Quantity Generator

Date form received by agency: 02/26/1996  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: CONTINENTAL MARITIME SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 03/18/1994  
 Facility name: SOUTHWEST REGIONAL MAINTENANCE CENTER  
 Site name: CONTINENTAL MARITIME OF SAN DIEGO, INC.  
 Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 7797

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CONTINENTAL MARITIME OF SAN DIEGO (Continued)**

**1000820618**

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 132

Waste code: D005  
 Waste name: BARIUM  
 Amount (Lbs): 7743

Waste code: D006  
 Waste name: CADMIUM  
 Amount (Lbs): 947

Waste code: D008  
 Waste name: LEAD  
 Amount (Lbs): 635

Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Amount (Lbs): 338

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO (Continued)**

**1000820618**

HAZNET:

Gepaid: CA4170090613  
 Contact: LAMBERTO R. TORRES  
 Telephone: 6195561055  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365299  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Not reported  
 Disposal Method: \*\*\*  
 Tons: Not reported  
 Facility County: Not reported

Gepaid: CA4170090613  
 Contact: US DEPT OF THE NAVY SUPSHIP  
 Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA7170090016  
 TSD County: San Diego  
 Waste Category: Paint sludge  
 Disposal Method: Transfer Station  
 Tons: .1540  
 Facility County: San Diego

Gepaid: CA4170090613  
 Contact: US DEPT OF THE NAVY SUPSHIP  
 Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Adhesives  
 Disposal Method: Transfer Station  
 Tons: .2380  
 Facility County: San Diego

Gepaid: CA4170090613  
 Contact: US DEPT OF THE NAVY SUPSHIP  
 Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Paint sludge

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CONTINENTAL MARITIME OF SAN DIEGO (Continued)**

**1000820618**

Disposal Method: Transfer Station  
 Tons: 5.1875  
 Facility County: San Diego

Gepaid: CA4170090613  
 Contact: US DEPT OF THE NAVY SUPSHIP  
 Telephone: 6195561053  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3600 SURFACE NAVY BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921365066  
 Gen County: San Diego  
 TSD EPA ID: CA6170024289  
 TSD County: San Diego  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Transfer Station  
 Tons: 2.5740  
 Facility County: San Diego

Click this hyperlink while viewing on your computer to access  
 172 additional CA\_HAZNET: record(s) in the EDR Site Report.

79

**PROPULSION CONTROLS ENGINEERING  
 1304 S SAMPSON ST  
 SAN DIEGO, CA 92113**

**FINDS 1000350137  
 HAZNET CAD073349607  
 RCRA-NonGen**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD073349607  
 Contact: JOHN P REILLY  
 Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921703606  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 1.6856  
 Facility County: San Diego

Gepaid: CAD073349607  
 Contact: JOHN P REILLY

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PROPULSION CONTROLS ENGINEERING (Continued)**

**1000350137**

Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921703606  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 6.2000  
 Facility County: San Diego

Gepaid: CAD073349607  
 Contact: JOHN P REILLY  
 Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921703606  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 2.0850  
 Facility County: San Diego

Gepaid: CAD073349607  
 Contact: JOHN P REILLY  
 Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921703606  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Recycler  
 Tons: .3127  
 Facility County: San Diego

Gepaid: CAD073349607  
 Contact: JOHN P REILLY  
 Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921703606  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**PROPULSION CONTROLS ENGINEERING (Continued)**

**1000350137**

[Click this hyperlink](#) while viewing on your computer to access  
 30 additional CA\_HAZNET: record(s) in the EDR Site Report.

RCRA-NonGen:

Date form received by agency: 06/26/2007  
 Facility name: PROPULSION CONTROLS ENGINEERING \*D  
 Facility address: 1304 SAMPSON ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD073349607  
 Mailing address: PO BOX 13606  
 SAN DIEGO, CA 92170 3606  
 Contact: KATY SANFORD  
 Contact address: PO BOX 13606  
 SAN DIEGO, CA 92170 3606  
 Contact country: US  
 Contact telephone: 619-235-0961  
 Telephone ext.: 304  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 09/01/1996  
 Facility name: PROPULSION CONTROLS ENGINEERING \*D

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PROPULSION CONTROLS ENGINEERING (Continued)**

**1000350137**

Site name: PROPULSION CONTROLS ENGINEERING  
 Classification: Small Quantity Generator

Date form received by agency: 06/24/1986  
 Facility name: PROPULSION CONTROLS ENGINEERING \*D  
 Site name: PROPULSION CONTROLS ENGINEERING  
 Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 06/17/1993  
 Date achieved compliance: 06/17/1998  
 Violation lead agency: State  
     Enforcement action: Not reported  
     Enforcement action date: Not reported  
     Enf. disposition status: Not reported  
     Enf. disp. status date: Not reported  
     Enforcement lead agency: Not reported  
     Proposed penalty amount: Not reported  
     Final penalty amount: Not reported  
     Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 04/17/1991  
 Date achieved compliance: 06/17/1993  
 Violation lead agency: State  
     Enforcement action: Not reported  
     Enforcement action date: Not reported  
     Enf. disposition status: Not reported  
     Enf. disp. status date: Not reported  
     Enforcement lead agency: Not reported  
     Proposed penalty amount: Not reported  
     Final penalty amount: Not reported  
     Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 06/17/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/17/1998  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 04/17/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/17/1993  
 Evaluation lead agency: State Contractor/Grantee

MAP FINDINGS

Map ID Direction Distance Distance (ft.)Site Database(s) EPA ID Number EDR ID Number

79 SOLAR TURBINES 2201 HARBOR DR SAN DIEGO, CA 92101 SLIC S106484213 N/A

SLIC:  
 Region: STATE  
 Global Id: SL209174192  
 Assigned Name: SLICSITE  
 Lead Agency Contact: TOM ALO  
 Lead Agency: SAN DIEGO RWQCB (REGION 9)  
 Lead Agency Case Number: 2091700  
 Responsible Party: NAVISTAR INTERNATIONAL TRANSPORTATI  
 Recent Dtw: Not reported  
 Substance Released: CHROME 6, CR, MET, NOT\_SELECTED, NOT\_SELECTED, PAH, PCB, PCE, PET, SVO, TCE, VOC  
 Facility Status: Feasibility Study for Remedial Action Plan

79 BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD FOOT OF SAMSON STREET SAN DIEGO, CA 92113 PADS 1000411002 Notify 65 CAD981172554 HAZNET LUST Cortese RCRA-LQG UST San Diego Co. HMMD CERC-NFRAP AIRS

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: Not reported

HAZNET:  
 Gepaid: CAD981172554  
 Contact: SOUTHWEST MARINE INC  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 921703308  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 1.0000  
 Facility County: San Diego

Gepaid: CAD981172554  
 Contact: SOUTHWEST MARINE INC  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 921703308



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: .5421  
 Facility County: San Diego

Gepaid: CAD981172554  
 Contact: SOUTHWEST MARINE INC  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 921703308  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .0500  
 Facility County: San Diego

Gepaid: CAD981172554  
 Contact: SOUTHWEST MARINE INC  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 921703308  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 8.2000  
 Facility County: San Diego

Gepaid: CAD981172554  
 Contact: SOUTHWEST MARINE INC  
 Telephone: 6192381000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13308  
 Mailing City,St,Zip: SAN DIEGO, CA 921703308  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: .6500  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 538 additional CA\_HAZNET: record(s) in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

LUST:

Region: 9  
 Case Number: 9UT3470  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 12/30/1996  
 How Found: Tank Closure  
 Date Stopped: 12/30/1996  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 05/19/1997  
 Submit Workplan: 5/27/97  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 7/13/98  
 Pilot Program: LOP  
 Local Case: H09689-002  
 Basin Number: 908.22  
 Gwater Depth: 8'  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 12/30/1996  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

RCRA-LQG:

Date form received by agency: 02/24/2006  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Facility address: FOOT OF SAMSON STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981172554  
 Mailing address: PO BOX 13308  
 SAN DIEGO, CA 921703308  
 Contact: SANDOR HALVAX  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 238-1000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Telephone ext.: 2060  
 Contact email: SANDOR.HALVAX@BAESYSTEMS.COM  
 EPA Region: 09  
 Land type: Private  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

**Owner/Operator Summary:**

Owner/operator name: BAE SYSTEMS SAN DIEGO SHIP  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 09/17/1979  
 Owner/Op end date: Not reported

Owner/operator name: SAN DIEGO UNIFIED PORT DISTRICT  
 Owner/operator address: 3165 PACIFIC HIGHWAY  
 SAN DIEGO, CA 92101

Owner/operator country: UG  
 Owner/operator telephone: Not reported  
 Legal status: District  
 Owner/Operator Type: Owner  
 Owner/Op start date: 03/14/1963  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Historical Generators:

Date form received by agency: 09/06/2005  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: BAE SYSTEMS SAN DIEGO SHIP REPAIR  
 Classification: Large Quantity Generator

Date form received by agency: 07/22/2005  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: BAE SYSTEMS SAN DIEGO SHIP REPAIR  
 Classification: Large Quantity Generator

Date form received by agency: 03/01/2004  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: SOUTHWEST MARINE, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 03/29/2002  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: SOUTHWEST MARINE, INC. (SAMPSON STREET)  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: SOUTHWEST MARINE  
 Classification: Large Quantity Generator

Date form received by agency: 04/15/1999  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: SOUTHWEST MARINE  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: SOUTHWEST MARINE INC  
 Classification: Large Quantity Generator

Date form received by agency: 03/29/1996  
 Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD  
 Site name: SOUTHWEST MARINE, INC.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Classification: Large Quantity Generator

Date form received by agency: 03/30/1994

Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD

Site name: SOUTHWEST MARINE, INC.

Classification: Large Quantity Generator

Date form received by agency: 03/17/1992

Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD

Site name: SOUTHWEST MARINE INC

Classification: Large Quantity Generator

Date form received by agency: 05/03/1990

Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD

Site name: SOUTHWEST MARINE INC SAN DIEGO DIVISION

Classification: Large Quantity Generator

Date form received by agency: 01/22/1986

Facility name: BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD

Site name: SOUTHWEST MARINE INC

Classification: Large Quantity Generator

**Hazardous Waste Summary:**

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D004

Waste name: ARSENIC

Waste code: D005

Waste name: BARIUM

Waste code: D006

Waste name: CADMIUM

Waste code: D007

Waste name: CHROMIUM

Waste code: D008

Waste name: LEAD

Waste code: D009

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Waste name: MERCURY

Waste code: D018  
 Waste name: BENZENE

Waste code: D035  
 Waste name: METHYL ETHYL KETONE

Waste code: F001  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F002  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:  
 Last Biennial Reporting Year: 2005

Annual Waste Handled:  
 Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 62497

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 15056.5

Waste code: D005  
 Waste name: BARIUM  
 Amount (Lbs): 52877

Waste code: D008  
 Waste name: LEAD  
 Amount (Lbs): 390

Waste code: D009  
 Waste name: MERCURY  
 Amount (Lbs): 40

Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Amount (Lbs): 9620

Waste code: F005  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 9620

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 05/28/2004  
 Date achieved compliance: 08/28/2004  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 05/05/1994  
 Date achieved compliance: 06/12/1996  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 02/17/1994  
 Date achieved compliance: 05/05/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 11/05/1992  
 Date achieved compliance: 02/17/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:  
 Evaluation date: 05/28/2004  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/28/2004  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/12/1996  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: EPA

Evaluation date: 05/05/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/12/1996  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 02/17/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/05/1994  
 Evaluation lead agency: State Contractor/Grantee



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Evaluation date: 11/05/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 02/17/1994  
 Evaluation lead agency: State Contractor/Grantee

UST:

Local Agency: 37000  
 Facility ID: H09689

San Diego Co. HMMD:

Facility ID: 132800  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 488  
 Mailing City,St,Zip: SAN DIEGO, CA 92112  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**CERC-NFRAP:**

Site ID: 0904776  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

**CERCLIS-NFRAP Site Contact Name(s):**

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

**CERCLIS-NFRAP Assessment History:**

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/08/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Date Started:	Not reported
Date Completed:	01/10/1994
Priority Level:	Not reported
Action:	PRELIMINARY ASSESSMENT
Date Started:	Not reported
Date Completed:	01/10/1994
Priority Level:	NFRAP (No Futher Remedial Action Planned)

**EMI:**

Year:	1987
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	50
Reactive Organic Gases Tons/Yr:	38
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	5
Particulate Matter Tons/Yr:	8
Part. Matter 10 Micrometers & Smlr Tons/Yr:	7

Year:	1990
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	47
Reactive Organic Gases Tons/Yr:	41
Carbon Monoxide Emissions Tons/Yr:	8
NOX - Oxides of Nitrogen Tons/Yr:	6
SOX - Oxides of Sulphur Tons/Yr:	1
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smlr Tons/Yr:	1

Year:	1995
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	61
Reactive Organic Gases Tons/Yr:	58
Carbon Monoxide Emissions Tons/Yr:	3
NOX - Oxides of Nitrogen Tons/Yr:	14

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

SOX - Oxides of Sulphur Tons/Yr:	2
Particulate Matter Tons/Yr:	8
Part. Matter 10 Micrometers & Smlr Tons/Yr:	7
Year:	1996
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	61
Reactive Organic Gases Tons/Yr:	58
Carbon Monoxide Emissions Tons/Yr:	3
NOX - Oxides of Nitrogen Tons/Yr:	14
SOX - Oxides of Sulphur Tons/Yr:	2
Particulate Matter Tons/Yr:	8
Part. Matter 10 Micrometers & Smlr Tons/Yr:	7
Year:	1998
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	32
Reactive Organic Gases Tons/Yr:	31
Carbon Monoxide Emissions Tons/Yr:	17
NOX - Oxides of Nitrogen Tons/Yr:	42
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	5
Part. Matter 10 Micrometers & Smlr Tons/Yr:	5
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	43
Reactive Organic Gases Tons/Yr:	42
Carbon Monoxide Emissions Tons/Yr:	8
NOX - Oxides of Nitrogen Tons/Yr:	35
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	6
Part. Matter 10 Micrometers & Smlr Tons/Yr:	6
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Air Basin: SD  
 Facility ID: 478  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 63  
 Reactive Organic Gases Tons/Yr: 62  
 Carbon Monoxide Emissions Tons/Yr: 9  
 NOX - Oxides of Nitrogen Tons/Yr: 41  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 6  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 6

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 478  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 34  
 Reactive Organic Gases Tons/Yr: 33  
 Carbon Monoxide Emissions Tons/Yr: 6  
 NOX - Oxides of Nitrogen Tons/Yr: 26  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 6  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 6

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 478  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 47  
 Reactive Organic Gases Tons/Yr: 47  
 Carbon Monoxide Emissions Tons/Yr: 5  
 NOX - Oxides of Nitrogen Tons/Yr: 19  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 5  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 5

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 478  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS SAN DIEGO SHIP REPAIR / YARD (Continued)**

**1000411002**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	47
Reactive Organic Gases Tons/Yr:	47
Carbon Monoxide Emissions Tons/Yr:	5
NOX - Oxides of Nitrogen Tons/Yr:	19
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	5
Part. Matter 10 Micrometers & Smlr Tons/Yr:	5
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	47.10779044
Reactive Organic Gases Tons/Yr:	46.70312968
Carbon Monoxide Emissions Tons/Yr:	4.89075181
NOX - Oxides of Nitrogen Tons/Yr:	18.7063867
SOX - Oxides of Sulphur Tons/Yr:	0.257661755
Particulate Matter Tons/Yr:	5.064479915
Part. Matter 10 Micrometers & Smlr Tons/Yr:	5.047541285
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	478
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	38.573483
Reactive Organic Gases Tons/Yr:	38.212401
Carbon Monoxide Emissions Tons/Yr:	5.03316
NOX - Oxides of Nitrogen Tons/Yr:	22.07
SOX - Oxides of Sulphur Tons/Yr:	.247892
Particulate Matter Tons/Yr:	10.77888751568088157
Part. Matter 10 Micrometers & Smlr Tons/Yr:	8.255461835

79

**S D UNIFIED PORT DIST AT0192  
 2025 BELT ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104749741  
 SWEEPS UST N/A**

San Diego Co. HMMD:  
 Facility ID: 121194  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2025 BELT ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S D UNIFIED PORT DIST AT0192 (Continued)**

**S104749741**

Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO UNIFIED PORT DISTRIC  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: S D UNIFIED PORT DIST  
 Tank Address: 2025 BELT ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT0192-1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S D UNIFIED PORT DIST AT0192 (Continued)**

**S104749741**

Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21194  
 Number: Not reported  
 Board Of Equalization: 44-023475  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021194-000001  
 Actv Date: Not reported  
 Capacity: 400  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 1

**80**

**TEXACO SERVICE STATION  
 1145 SOUTH 28TH STREET  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000374742  
 FINDS CAD982337974  
 HAZNET**

**RCRA-SQG:**

Date form received by agency: 06/19/2001  
 Facility name: TEXACO SERVICE STATION  
 Facility address: 1145 S 28TH ST  
 S A P 120520  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982337974  
 Mailing address: P O BOX 2099  
 HOUSTON, TX 772522099  
 Contact: SONDRA BIENVENU  
 Contact address: P O BOX 2099  
 HOUSTON, TX 772522099  
 Contact country: US  
 Contact telephone: (713) 241-5036  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO SERVICE STATION (Continued)**

**1000374742**

Owner/Operator Summary:

Owner/operator name: SHELL OIL COMPANY  
 Owner/operator address: P O BOX 2099  
 HOUSTON, TX 77252  
 Owner/operator country: Not reported  
 Owner/operator telephone: (713) 241-5036  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018  
 Waste name: BENZENE

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO SERVICE STATION (Continued)**

**1000374742**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD982337974  
 Contact: RCHEL WILLIAMSON/RM 300-G03  
 Telephone: 212742224  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 12700 NORTHBOROUGH DR RM 300-F07  
 Mailing City,St,Zip: HOUSTON, TX 77067  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.01  
 Facility County: Not reported

Gepaid: CAD982337974  
 Contact: RCHEL WILLIAMSON/RM 300-G03  
 Telephone: 212742224  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 12700 NORTHBOROUGH DR RM 300-F07  
 Mailing City,St,Zip: HOUSTON, TX 77067  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.01  
 Facility County: Not reported

Gepaid: CAD982337974  
 Contact: R HULL/ENV. REPORTING ANALYST  
 Telephone: 2818742224  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 12700 NORTHBOROUGH DR 300G03  
 Mailing City,St,Zip: HOUSTON, TX 770670000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Alkaline solution without metals (pH > 12.5)  
 Disposal Method: Recycler  
 Tons: 0.31  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**80 TEXACO MARKETING  
 1145 S 28TH ST  
 SAN DIEGO, CA 92113**

**LUST U003789143  
 UST N/A  
 San Diego Co. HMMMD  
 SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300460  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1990-07-20 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: ROGER JOHNSON  
 RP Address: 10 UNIVERSAL CITY PLAZA  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03719-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO MARKETING (Continued)**

**U003789143**

Case Number: 9UT1644  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0619722482  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2000-06-13 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2007-03-28 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2007-05-23 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Marvin Katz  
 RP Address: 20945 S. Wilmington Ave.  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE. Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO MARKETING (Continued)**

**U003789143**

Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03719-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H03719

San Diego Co. HMMD:

Facility ID: 103719  
 Inactive Indicator: Active  
 Business Code: 6HK29  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ATTN: MICHELLE PONCE  
 Mailing Address: 20945 S WILMINGTON A  
 Mailing City,St,Zip: CARSON, CA 90810  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAD982018509  
 Gas Station: Not reported  
 Inspection Date: 02/24/04  
 Reinspection Date: Not reported  
 Inspector Name: TTORRES  
 Violation Notice Issued: Not reported  
 Facility Contact: TAMI FAHEY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: EQUILON ENTERPRISES L L C  
 Property Address: TAX DEPARTMENT - PRO  
 Property City,St,Zip: 77210  
 Tank Owner: EQUILON ENTERPRISES LLC  
 Tank Address: P.O. BOX 4453  
 Tank City,St,Zip: Houston, TX 77210  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/24/05

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO MARKETING (Continued)**

**U003789143**

Facility Phone: 619-239-8313

**HMMD DISCLOSURE INVENTORY:**

Item Number: DI87  
 Chemical Name: DIESEL UNDERGROUND TANK 103719 T008  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PR83  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: RE84  
 Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 103719 T005  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: RE85  
 Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 103719 T006  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: SU86  
 Chemical Name: SUPER UNLEADED UNDERGROUND TANK 103719 T007  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**TEXACO MARKETING (Continued)**

**U003789143**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T004  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T005  
 Tank ID Number: NT1367 / R  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T006  
 Tank ID Number: NT1367/ RT  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T007  
 Tank ID Number: NT1367 / R  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T008  
 Tank ID Number: NT1367/ RT  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T009  
 Tank ID Number: NT1367/ RT  
 Waste or Product: Not reported  
 Tank Contents: OTHER

**HMMD VIOLATIONS:**

Inspection Date: 03/24/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 2286  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/24/98  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**TEXACO MARKETING (Continued)**

**U003789143**

Type of Violation:	6HX3001
Occurrences:	Not reported
Item Number:	2287
Violation Desc:	UST RECORDS NOT MAINTAINED ONSITE
Inspection Date:	03/24/98
Waste Code:	Not reported
Type of Violation:	6HX3027
Occurrences:	Not reported
Item Number:	2288
Violation Desc:	UST MONITORING PROCEDURE NOT IMPLEMENTED
Inspection Date:	07/08/99
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	6126
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	07/08/99
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	6127
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HV0135
Occurrences:	Not reported
Item Number:	1586
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HV0138
Occurrences:	Not reported
Item Number:	1587
Violation Desc:	NO TSDF SIGNED MANIFEST ONSITE
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	1588
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HV0406
Occurrences:	Not reported
Item Number:	1589
Violation Desc:	CONT PLAN NOT PREPARED/ONSITE
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HV1096



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO MARKETING (Continued)**

**U003789143**

Occurrences:	Not reported
Item Number:	1590
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HX0062
Occurrences:	Not reported
Item Number:	1591
Violation Desc:	NO UST OWNER OPERATOR AGREEMENT
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HX3013
Occurrences:	Not reported
Item Number:	1592
Violation Desc:	NO FINANCIAL RESPOSIBILITY DOC
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HX3001
Occurrences:	Not reported
Item Number:	1593
Violation Desc:	UST RECORDS NOT MAINTAINED ONSITE
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HX3027
Occurrences:	Not reported
Item Number:	1594
Violation Desc:	UST MONITORING PROCEDURE NOT IMPLEMENTED
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HX3028
Occurrences:	Not reported
Item Number:	1595
Violation Desc:	UST RESPONSE PLAN NOT AVAILABLE
Inspection Date:	11/27/01
Waste Code:	Not reported
Type of Violation:	6HX3029
Occurrences:	Not reported
Item Number:	1596
Violation Desc:	SPILL/OVERFILL PREVENTION NOT INSTALLED
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3108
Occurrences:	Not reported
Item Number:	8942
Violation Desc:	UST EM RESPONSE PLAN NOT COMPLETE
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3109
Occurrences:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**TEXACO MARKETING (Continued)**

**U003789143**

Item Number:	8943
Violation Desc:	MONITORING PLOT PLAN NOT SUBMITTED
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3157
Occurrences:	Not reported
Item Number:	8944
Violation Desc:	FALSIFICATION OF RECORDS/TAMPER W/EQUIP
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3159
Occurrences:	Not reported
Item Number:	8945
Violation Desc:	MONITOR EQUIP NOT USED PER MANUFACTURER
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3160
Occurrences:	Not reported
Item Number:	8946
Violation Desc:	UST SYS REPAIRS NOT DONE PROPERLY
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3255
Occurrences:	Not reported
Item Number:	8947
Violation Desc:	SPILL CONT NOT DRY & IN GOOD CONDITI
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3257
Occurrences:	Not reported
Item Number:	8948
Violation Desc:	2NDRY CONTAINMENT NOT LIQUID FREE
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3257
Occurrences:	Not reported
Item Number:	8949
Violation Desc:	2NDRY CONTAINMENT NOT LIQUID FREE
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3257
Occurrences:	Not reported
Item Number:	8950
Violation Desc:	2NDRY CONTAINMENT NOT LIQUID FREE
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3257
Occurrences:	Not reported
Item Number:	8951

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO MARKETING (Continued)**

**U003789143**

Violation Desc:	2NDRY CONTAINMENT NOT LIQUID FREE
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3258
Occurrences:	Not reported
Item Number:	8952
Violation Desc:	SENSORS NOT PLACED AT LOW POINT/ADEQU
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3258
Occurrences:	Not reported
Item Number:	8953
Violation Desc:	SENSORS NOT PLACED AT LOW POINT/ADEQU
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3261
Occurrences:	Not reported
Item Number:	8954
Violation Desc:	DISPENSER CONTAINMENT NOT DRY
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3261
Occurrences:	Not reported
Item Number:	8955
Violation Desc:	DISPENSER CONTAINMENT NOT DRY
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV3261
Occurrences:	Not reported
Item Number:	8956
Violation Desc:	DISPENSER CONTAINMENT NOT DRY
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV0132
Occurrences:	Not reported
Item Number:	8957
Violation Desc:	EPA ID NUMBER NOT OBTAINED
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV0135
Occurrences:	Not reported
Item Number:	8958
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	02/24/04
Waste Code:	Not reported
Type of Violation:	6HV0138
Occurrences:	Not reported
Item Number:	8959
Violation Desc:	NO TSDF SIGNED MANIFEST ONSITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**TEXACO MARKETING (Continued)**

**U003789143**

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8960  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 8961  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 8962  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 8963  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 8964  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3262  
 Occurrences: Not reported  
 Item Number: 8965  
 Violation Desc: SEC CONT PIPING DRAINAGE OBSTRUCTED

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3262  
 Occurrences: Not reported  
 Item Number: 8966  
 Violation Desc: SEC CONT PIPING DRAINAGE OBSTRUCTED

Inspection Date: 02/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3262  
 Occurrences: Not reported  
 Item Number: 8967  
 Violation Desc: SEC CONT PIPING DRAINAGE OBSTRUCTED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO MARKETING (Continued)**

**U003789143**

**HMMD WASTE STREAMS:**

Inspection Date: 02/24/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: UNGD TNK  
 Haz Waste Hauler: 2948 GOLDEN STATE ENVIRON  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 02/24/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 15  
 Annual Qty String: 15  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED GAS FILTERS  
 Carcinogen: No

Inspection Date: 02/24/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: INTERSTATE  
 Carcinogen: No

Inspection Date: 02/24/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO MARKETING (Continued)**

**U003789143**

Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H03719-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 7/20/1990  
 Begandt: 3/1/1990

Case Number: H03719-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 6/13/2000  
 Begandt: 3/28/2007

80

**TEXACO REFINING & MARKETING**  
**1145 S 28TH ST**  
**SAN DIEGO, CA 92113**

**HAZNET**  
**HIST UST**  
**SWEEPS UST**

**U001572977**  
**N/A**

HAZNET:

Gepaid: CAD982018509  
 Contact: LARS SORENSEN, PE  
 Telephone: 7142506609  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 19649  
 Mailing City,St,Zip: IRVINE, CA 927130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 0.62  
 Facility County: Not reported

Gepaid: CAD982337974  
 Contact: --  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1145 S 28TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133703  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.04  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO REFINING & MARKETING (Continued)**

**U001572977**

Gepaid: CAD982018509  
 Contact: LARS SORENSEN, PE  
 Telephone: 7142506609  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 19649  
 Mailing City,St,Zip: IRVINE, CA 927130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 0.64  
 Facility County: Not reported

Gepaid: CAD982337974  
 Contact: --  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1145 S 28TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133703  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Not reported  
 Disposal Method: Treatment, Tank  
 Tons: 0.20  
 Facility County: Not reported

Gepaid: CAD982337974  
 Contact: --  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1145 S 28TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133703  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Treatment, Tank  
 Tons: 0.72  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access 4 additional CA\_HAZNET: record(s) in the EDR Site Report.

HIST UST:  
 Region: STATE  
 Facility ID: 00000023900  
 Facility Type: Gas Station  
 Other Type: Not reported  
 Total Tanks: 0004  
 Contact Name: FARID HANAII  
 Telephone: 6192398318  
 Owner Name: EXXON COMPANY U.S.A.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO REFINING & MARKETING (Continued)**

**U001572977**

Owner Address: 16945 NORTHCHASE BLVD  
 Owner City,St,Zip: HOUSTON, TX 77210

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1966  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: PREMIUM  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 2  
 Year Installed: 1966  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 3  
 Year Installed: 1966  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 004  
 Container Num: 4  
 Year Installed: 1966  
 Tank Capacity: 00000500  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

**SWEEPS UST:**

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000001  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 9



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO REFINING & MARKETING (Continued)**

**U001572977**

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000002  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000003  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000004  
 Actv Date: Not reported  
 Capacity: 500  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO REFINING & MARKETING (Continued)**

**U001572977**

Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000005  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000006  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000007  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000008  
 Actv Date: Not reported  
 Capacity: 10000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO REFINING & MARKETING (Continued)**

**U001572977**

Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 3719  
 Number: 9  
 Board Of Equalization: 44-000217  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003719-000009  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

80

**TEXACO REFINING AND MARKETING INC  
 1145 S 28TH ST  
 SAN DIEGO, CA 92113**

**HAZNET S103624025  
 N/A**

HAZNET:

Gepaid: CAL000032902  
 Contact: TEXACO REFINING AND MARKETING  
 Telephone: 8185052802  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 10 UNIVERSAL CITY PLAZA 7TH FLOOR  
 Mailing City,St,Zip: UNIVERSAL CITY, CA 916081009  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Treatment, Tank  
 Tons: .1459  
 Facility County: San Diego

Gepaid: CAL000032902  
 Contact: TEXACO REFINING AND MARKETING  
 Telephone: 8185052802  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 10 UNIVERSAL CITY PLAZA 7TH FLOOR  
 Mailing City,St,Zip: UNIVERSAL CITY, CA 916081009  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Treatment, Tank  
 Tons: 1.0924  
 Facility County: San Diego

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

<b>80</b>	<b>TEXACO #120520</b> <b>1145 28TH ST S</b> <b>SAN DIEGO, CA 92113</b>	<b>FINDS</b>	<b>1008239679</b> <b>110021281263</b>
-----------	--	--------------	--

FINDS:  
 Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

<b>80</b>	<b>TEXACO SERVICE STATION</b> <b>1145 28TH ST S</b> <b>SAN DIEGO, CA 92113</b>	<b>LUST</b>	<b>S102438737</b>
		<b>Cortese</b>	<b>N/A</b>
		<b>AIRS</b>	

LUST:

Region:	9
Case Number:	9UT1644
Local Agency:	San Diego
Substance:	Gasoline
Qty Leaked:	0
Date Found:	03/01/1990
How Found:	Tank Closure
Date Stopped:	03/01/1990
How Stopped:	Close Tank
Source:	Tank
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Soil only
Status:	Case Closed
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Confirm Date:	03/01/1990
Submit Workplan:	Not reported
Prelim Assess:	06/12/1990
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Enforce Type:	Not reported
Enforce Date:	Not reported
Closed Date:	6/29/90
Pilot Program:	LOP
Local Case:	H03719-001
Basin Number:	Not reported
Gwater Depth:	Not reported
Beneficial Use:	Not reported
NPDES Number:	Not reported
priority:	3
File Dispn:	File discarded, case closed
Release Date:	03/01/1990
Interim Remedial Actions:	Yes
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

Cortese:

Region:	CORTESE
Facility Addr2:	1145 28TH ST S

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO SERVICE STATION (Continued)**

**S102438737**

EMI:

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1883  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1883  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1883  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1883  
 Air District Name: SD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TEXACO SERVICE STATION (Continued)**

**S102438737**

SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1883
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.937908
Reactive Organic Gases Tons/Yr:	1.937908
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1883
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.937908
Reactive Organic Gases Tons/Yr:	1.937908
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

81

**KENNEDY/KNOX SCHOOL SITE NO. 2  
 43RD STREET/KEELER AVENUE  
 SAN DIEGO, CA 92113**

**SCH S107736536  
 ENVIROSTOR N/A**

SCH:

Facility ID:	37880003
Site Type:	School Investigation
Site Type Detail:	School
Acres:	9.6
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KENNEDY/KNOX SCHOOL SITE NO. 2 (Continued)**

**S107736536**

Lead Agency: SMBRP  
 Lead Agency Description: DTSC - Site Mitigation And Brownfield Reuse Program  
 Project Manager: Not reported  
 Supervisor: Mark Malinowski  
 Division Branch: School Evaluation - Cypress  
 Site Code: 404277-11  
 Assembly: 79  
 Senate: 40  
 Special Program Status: Not reported  
 Status: Inactive - Needs Evaluation  
 Status Date: 2002-04-04 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.695675  
 Longitude: -117.100163  
 Alias Name: KENNEDY/KNOX SCHOOL SITE #2  
 37880003  
 404277-11  
 SAN DIEGO CITY USD-KENEDY/KNOX EL SITE 2  
 Alias Type: Alternate Name  
 Project Code (Site Code)  
 Alternate Name  
 Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported  
 Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 04/04/02  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 10/09/01  
 Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported  
 Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**KENNEDY/KNOX SCHOOL SITE NO. 2 (Continued)**

**S107736536**

PastUse: RESIDENTIAL AREA

ENVIROSTOR:

Site Type: School Investigation  
 Site Type Detailed: School  
 Acres: 9.6  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP  
 Program Manager: Not reported  
 Supervisor: Mark Malinowski  
 Division Branch: School Evaluation - Cypress  
 Facility ID: 37880003  
 Site Code: 404277-11  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Inactive - Needs Evaluation  
 Status Date: 2002-04-04 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.695675  
 Longitude: -117.100163  
 Alias Name: KENNEDY/KNOX SCHOOL SITE #2  
 37880003  
 404277-11  
 SAN DIEGO CITY USD-KENEDY/KNOX EL SITE 2

Alias Type: Alternate Name  
 Project Code (Site Code)  
 Alternate Name  
 Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 04/04/02

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 10/09/01

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KENNEDY/KNOX SCHOOL SITE NO. 2 (Continued)**

**S107736536**

Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA

82

**2851 BOSTON AVE  
 SAN DIEGO, CA**

**CHMIRS S105883226  
 N/A**

CHMIRS:

OES Incident Number: 02-1143  
 OES notification: 2/28/200202:32:17 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**(Continued)**

**S105883226**

Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	City of San Diego
Incident Date:	2/28/200212:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Unknown
Site Type:	Merchant/Business
E Date:	Not reported
Substance:	Sewage
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	66
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A back up at clean out at building and spilled into parking lot.

82

**SAN DIEGO HOUSING COMMISSION  
 2883 BOSTON AV  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104752185  
 N/A**

LUST:

Region:	STATE
Case Type:	Undefined
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Other Means
Leak Cause:	Other Cause
Leak Source:	Unknown
Global Id:	T0608115094
Stop Date:	1989-08-24 00:00:00
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	1989-08-24 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO HOUSING COMMISSION (Continued)**

**S104752185**

Enforcement Dt: Not reported  
 Release Date: 1989-08-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Not reported  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: UU  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H29629-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 129629  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO HOUSING COMMISSION (Continued)**

**S104752185**

Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SAN DIEGO HOUSING COMMISSION  
 Property Address: PUBLIC AGENCY  
 Property City,St,Zip: 00000  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO HOUSING COMMISSION (Continued)**

**S104752185**

Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H29629-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Complaint  
 FStatus: Preliminary Assessment  
 Date: 8/24/1989  
 Begandt: 8/24/1989

83

**A TO Z AUTO DISMANTLING  
 1249 SO. 32ND STREET  
 SAN DIEGO, CA 92113**

**CA WDS S106105466  
 N/A**

CA WDS:

Facility ID: San Diego 371004969  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: A TO Z AUTO DISMANTLING  
 Agency Address: 3202 MAIN ST  
 Agency City,St,Zip: SAN DIEGO 92113  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A TO Z AUTO DISMANTLING (Continued)**

**S106105466**

to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

83

**MIGUEL'S AUTO SERVICE  
 1249 32ND ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104890697  
 N/A**

San Diego Co. HMMD:

Facility ID:	130056
Inactive Indicator:	Active
Business Code:	6HK18
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1249 32ND ST
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	39
EPA ID:	CAL000001295
Gas Station:	Not reported
Inspection Date:	08/18/03
Reinspection Date:	Not reported
Inspector Name:	MNYAGA
Violation Notice Issued:	Not reported
Facility Contact:	MIGUEL PEREZ
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	RUSSELL KENNETH L&MILDRED B TR
Property Address:	6720 SAN MIGUEL AVE
Property City,St,Zip:	91945
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-234-7476

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIGUEL'S AUTO SERVICE (Continued)**

**S104890697**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 202581  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1249 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000001295  
 Gas Station: Not reported  
 Inspection Date: 08/18/03  
 Reinspection Date: Not reported  
 Inspector Name: MNYAGA  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MIGUEL'S AUTO SERVICE (Continued)**

**S104890697**

Facility Contact: MIGUEL PEREZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RUSSELL KENNETH L&MILDRED B TR  
 Property Address: 6720 SAN MIGUEL AVE  
 Property City,St,Zip: 91945  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/18/05  
 Facility Phone: 619-234-7476

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3335  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 08/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 3336  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 08/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 3337  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MIGUEL'S AUTO SERVICE (Continued)**

**S104890697**

Inspection Date: 08/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3338  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 08/18/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3339  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 08/18/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 660  
 Annual Qty String: 660  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 08/18/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

83

**ATALS FENCE COMPANY  
 1211 32ND ST S  
 SAN DIEGO, CA 92113**

**LUST S102424745  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT2786  
 Local Agency: San Diego  
 Substance: Regular Gasoline  
 Qty Leaked: 0  
 Date Found: 04/05/1994

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ATALS FENCE COMPANY (Continued)**

**S102424745**

How Found: Other Means  
 Date Stopped: 04/05/1994  
 How Stopped: Other Means  
 Source: Piping  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 04/05/1994  
 Submit Workplan: Not reported  
 Prelim Assess: 04/05/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 6/30/94  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H04283-001  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: NBNOC  
 NPDES Number: Not reported  
 priority: LOP/LOW - LOW POTENTIAL HEALTH/SAFTY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 04/05/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1211 32ND ST S

83

**ATLAS FENCE COMPANY  
 1211 32ND ST S  
 SAN DIEGO, CA 92113**

**HAZNET S102424754  
 LUST N/A  
 Cortese**

HAZNET:  
 Gepaid: CAC000879888  
 Contact: ATLAS FENCE CO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1211 S 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Treatment, Tank  
 Tons: 1.8765  
 Facility County: San Diego  
 Gepaid: CAL000018718

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ATLAS FENCE COMPANY (Continued)**

**S102424754**

Contact: VICTOR THIBEAULT  
 Telephone: 3238751342  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1211 S 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 925090000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: 0.2  
 Facility County: Not reported

Gepaid: CAL000018718  
 Contact: VICTOR THIBEAULT  
 Telephone: 3238751342  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1211 S 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 925090000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.08  
 Facility County: Not reported

Gepaid: CAL000018718  
 Contact: VICTOR THIBEAULT  
 Telephone: 3238751342  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1211 S 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 925090000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons: 0.00  
 Facility County: Not reported

Gepaid: CAL000018718  
 Contact: VICTOR THIBEAULT  
 Telephone: 3238751342  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1211 S 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 925090000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Recycler  
 Tons: 0.52

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ATLAS FENCE COMPANY (Continued)**

**S102424754**

Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 12 additional CA\_HAZNET: record(s) in the EDR Site Report.

LUST:

Region: 9  
 Case Number: 9UT2979  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 12/06/1994  
 How Found: Tank Closure  
 Date Stopped: 12/06/1994  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 01/10/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H04283-002  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: NBNO  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 12/06/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 1211 32ND ST S

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**83 ALCORN FENCE COMPANY DBA ATLAS  
 1211 S 32ND ST  
 SAN DIEGO, CA 92113**

**LUST U001573318  
 San Diego Co. HMMD N/A  
 HIST UST  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0607301544  
 Stop Date: 1994-04-05 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-09-24 00:00:00  
 Discover Date: 1994-04-05 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-04-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: KENNETH RUSSELL  
 RP Address: P O BOX 4337  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.32  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 8  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Local Case #: H04283-001  
 Case Number: 9UT2786  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607301746  
 Stop Date: 1994-12-06 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2003-09-24 00:00:00  
 Discover Date: 1994-12-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-12-06 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: KENNITH & MILDRED RUSSELL  
 RP Address: 6720 SAN MIQUEL AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: NS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04283-002  
 Case Number: 9UT2979  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 104283  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 9901 S GLENNOAKS BL  
 Mailing City,St,Zip: SUN VALLEY, CA 91352  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000018718  
 Gas Station: Not reported  
 Inspection Date: 09/08/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DAVID DEL PEGO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RUSSELL KENNETH L&MILDRED B TR  
 Property Address: 6720 SAN MIGUEL AVE  
 Property City,St,Zip: 91945  
 Tank Owner: JAMES WILLIAMS & KENNETH RUSSE  
 Tank Address: 6720 SAN MIGUEL AV  
 Tank City,St,Zip: 92045  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/08/05  
 Facility Phone: 619-232-1151

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC15

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Chemical Name: ACETYLENE WELDING CYLINDERS  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: GA17  
 Chemical Name: GASOLINE UNLEADED FUEL  
 Case Number: 12031  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: LU14  
 Chemical Name: LUBRICATING OILS (ALSO DM5)  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX16  
 Chemical Name: OXYGEN (7782-44-7)  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PE93  
 Chemical Name: PENTACHLOROPHENOL TREATED WOOD TREATED WOOD  
 Case Number: 87-86-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 11/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0137  
 Occurrences: Not reported  
 Item Number: 9525  
 Violation Desc: MANIFEST NOT COMPLETED PROPERLY

Inspection Date: 11/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9526  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9527  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 11/06/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9528  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 1976  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1977  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 02/25/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1978

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	02/25/99
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	1979
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	02/25/99
Waste Code:	Not reported
Type of Violation:	6HV0205
Occurrences:	Not reported
Item Number:	1980
Violation Desc:	WASTE CONTAINER: POOR CONDITION
Inspection Date:	02/25/99
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	1981
Violation Desc:	HMBP NOT ESTABISHED/IMPLEMENTED.
Inspection Date:	02/25/99
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	1982
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0216
Occurrences:	Not reported
Item Number:	5461
Violation Desc:	HAZMATS WITHOUT PROPER LABELS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	5462
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV1003
Occurrences:	Not reported
Item Number:	5463
Violation Desc:	HMBP NOT AMENDED W/IN 30 DAYS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV1097
Occurrences:	Not reported
Item Number:	5464
Violation Desc:	HMBP: NO EMPLOYEE TRAINING PROGRAM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3832  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3833  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 3834  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3835  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3836  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 09/08/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 90  
 Annual Qty String: 90  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: \*  
 Carcinogen: No

Inspection Date: 09/08/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 55  
 Quantity String: 55

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Annual Qty: 240  
 Annual Qty String: 240  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 09/08/03  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 330  
 Annual Qty String: 330  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: USED ANTIFREEZE  
 Carcinogen: No

Inspection Date: 09/08/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: USED CAR BATTERIES  
 Carcinogen: No

Inspection Date: 09/08/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 330  
 Annual Qty String: 330  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

HIST UST:  
 Region: STATE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Facility ID: 00000000971  
 Facility Type: Other  
 Other Type: CONTRACTOR  
 Total Tanks: 0011  
 Contact Name: DON BAILEY  
 Telephone: 6192322115  
 Owner Name: K.L. RUSSELL  
 Owner Address: 6720 SAN MIGUEL AVENUE  
 Owner City,St,Zip: LEMON GROVE, CA 92045

Tank Num: 001  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 004  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 005  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 006  
 Container Num: 5

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Year Installed: Not reported  
 Tank Capacity: 00012000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 007  
 Container Num: 6  
 Year Installed: Not reported  
 Tank Capacity: 00012000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 008  
 Container Num: 7  
 Year Installed: Not reported  
 Tank Capacity: 00012000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 009  
 Container Num: 8  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 010  
 Container Num: 9  
 Year Installed: Not reported  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 011  
 Container Num: 10  
 Year Installed: Not reported  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

**SWEEPS UST:**

Status: A  
 Comp Number: 4283  
 Number: 9  
 Board Of Equalization: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANY DBA ATLAS (Continued)**

**U001573318**

Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-004283-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: 1

SAN DIEGO CO. SAM:

Case Number: H04283-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/24/2003  
 Begandt: 4/5/1994

Case Number: H04283-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/24/2003  
 Begandt: 12/6/1994

83

**ALCORN FENCE COMPANY DBA ATLAS FENCE CO  
 1211 S 32ND\_ST  
 SAN DIEGO, CA 92113**

**HAZNET S108197121  
 N/A**

HAZNET:

Gepaid: CAL000018718  
 Contact: VICTOR THIBEAULT  
 Telephone: 3238751342  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1211 S 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 925090000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAL000018718  
 Contact: CORY WHITFIELD SAFETY DIRECTOR  
 Telephone: 3238751342  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1211 S 32ND ST  
 Mailing City,St,Zip: SAN DIEGO, CA 925090000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALCORN FENCE COMPANYDBA ATLAS FENCE CO (Continued)**

**S108197121**

Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.1  
 Facility County: San Diego

**84**

**CHEVRON SERVICE STATION  
 2351 HARBOR DR E  
 SAN DIEGO, CA 92113**

**LUST S101302018  
 Cortese N/A  
 AIRS**

**LUST:**

Region: 9  
 Case Number: 9UT0015  
 Local Agency: San Diego  
 Substance: Hydrocarbons  
 Qty Leaked: 0  
 Date Found: 01/28/1984  
 How Found: Other Means  
 Date Stopped: 03/30/1987  
 How Stopped: New Tank  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Remediation Plan  
 Abate Method: Remove Free Product - remove floating product from water table  
 Confirm Date: 03/30/1987  
 Submit Workplan: Not reported  
 Prelim Assess: 08/29/1986  
 Desc Pollution: Not reported  
 Remed Plan: 08/27/1987  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H03791-001  
 Basin Number: 908.22  
 Gwater Depth: 20  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 08/04/1986  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2351 HARBOR DR E

**EMI:**

Year: 1997



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON SERVICE STATION (Continued)**

**S101302018**

Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 44  
 Reactive Organic Gases Tons/Yr: 43  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 41  
 Reactive Organic Gases Tons/Yr: 40  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 36  
 Reactive Organic Gases Tons/Yr: 36  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON SERVICE STATION (Continued)**

**S101302018**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	36
Reactive Organic Gases Tons/Yr:	36
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1968
Air District Name:	SD
SIC Code:	5171
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	17
Reactive Organic Gases Tons/Yr:	17
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1968
Air District Name:	SD
SIC Code:	5171
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	17
Reactive Organic Gases Tons/Yr:	17
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1968
Air District Name:	SD
SIC Code:	5171
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON SERVICE STATION (Continued)**

**S101302018**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1968
Air District Name:	SD
SIC Code:	5171
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.41324868
Reactive Organic Gases Tons/Yr:	1.41324868
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1968
Air District Name:	SD
SIC Code:	5171
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8.71
Reactive Organic Gases Tons/Yr:	7.62
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

84

**SAN DIEGO TERMINAL  
 2351 E. HARBOR DR.  
 SAN DIEGO, CA 92113**

**AST A100226540  
 N/A**

AST:  
 Owner: CHEVRON U.S.A. PRODUCTS CO.  
 Total Gallons: 7421664

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

84 CHEVRON USA INC.  
 2351 HARBOR DR  
 SAN DIEGO, CA 92113

LUST U003789146  
 UST N/A  
 SAN DIEGO CO. SAM

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608145563  
 Stop Date: 2001-10-01 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2001-12-05 00:00:00  
 Discover Date: 2001-10-01 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-10-01 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: SW  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03791-004  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**U003789146**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H03791

SAN DIEGO CO. SAM:

Case Number: H03791-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/5/2001  
 Begandt: 10/1/2001

84 **CHEVRON SAN DIEGO TERMINAL**  
**2351 E HARBOR DR**  
**SAN DIEGO, CA 92113**

TRIS **1005454842**  
**92113CHVRN23**

84 **CHEVRON USA INC.**  
**2351 E HARBOR DR**  
**SAN DIEGO, CA 92113**

LUST **S104234412**  
 San Diego Co. HMMD **N/A**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0607300019  
 Stop Date: 1987-03-30 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1988-10-11 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1987-03-30 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**S104234412**

Enforcement Dt: Not reported  
 Release Date: 1987-03-30 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Ralph Hicks  
 RP Address: P.O. Box 4888  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: SM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03791-001  
 Case Number: 9UT0015  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608117151  
 Stop Date: 1993-06-15 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**S104234412**

Prelim Assess: 1993-06-16 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1993-06-15 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1993-06-15 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Eric Roehl  
 RP Address: P.O. Box 2292  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: SM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H03791-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 103791  
 Inactive Indicator: Active  
 Business Code: 6HK78  
 SIC: Not reported  
 Permit Expiration: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHEVRON USA INC. (Continued)**

**S104234412**

Owner: Not reported  
 2nd Name: ATTN: PAUL COON  
 Mailing Address: 2351 E. HARBOR DRIVE  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAT000614958  
 Gas Station: Not reported  
 Inspection Date: 08/24/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: PAUL COON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CHEVRON U S A INC  
 Property Address: P O BOX 285  
 Property City,St,Zip: 77001  
 Tank Owner: CHEVRON USA, INC  
 Tank Address: PO BOX 6004  
 Tank City,St,Zip: San Ramon, CA 94583  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/24/05  
 Facility Phone: 619-232-3334

**HMMD DISCLOSURE INVENTORY:**

Item Number: AD71  
 Chemical Name: ADDITIVE O6A 600  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: AQ76  
 Chemical Name: AQUEOUS FILM FORMING FOAM AFFF  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: DI67  
 Chemical Name: DIESEL FUEL DIESEL FUEL LS 2  
 Case Number: 68476-34-6



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHEVRON USA INC. (Continued)**

**S104234412**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: ET68  
 Chemical Name: ETHANOL T021  
 Case Number: 64-17-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: ET73  
 Chemical Name: ETHYLENE GLYCOL ANTIFREEZE  
 Case Number: 107-21-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: GA66  
 Chemical Name: GASOLINE  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: GE72  
 Chemical Name: GENERIC ADDITIVE O6A 600  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**S104234412**

Item Number: LU70  
 Chemical Name: LUBE OIL CHEVRON DELO 400 MULTIGRADE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: TR69  
 Chemical Name: TRANSMIX  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 00001 WAST  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: 00002  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: 00003  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: 00004  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T005  
 Tank ID Number: 00005  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T007  
 Tank ID Number: 002  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T008  
 Tank ID Number: 11 RAINWAT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**S104234412**

Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T009  
 Tank ID Number: 11 RAINWAT  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T010  
 Tank ID Number: NT2364  
 Waste or Product: Not reported  
 Tank Contents: OTHER

**HMMD VIOLATIONS:**

Inspection Date: 09/16/97  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 8760  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 06/12/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3109  
 Occurrences: Not reported  
 Item Number: 1256  
 Violation Desc: MONITORING PLOT PLAN NOT SUBMITTED

Inspection Date: 06/12/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 1257  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

Inspection Date: 06/12/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3262  
 Occurrences: Not reported  
 Item Number: 1258  
 Violation Desc: SEC CONT PIPING DRAINAGE OBSTRUCTED

Inspection Date: 08/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3107  
 Occurrences: Not reported  
 Item Number: 4282  
 Violation Desc: UST MONITORING PLAN NOT COMPLETE

Inspection Date: 08/24/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 4283  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**S104234412**

**HMMD WASTE STREAMS:**

Inspection Date: 08/24/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 16000  
 Quantity String: 16000  
 Annual Qty: 40000  
 Annual Qty String: 40000  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: TO REFINERY (25143)  
 Carcinogen: No

Inspection Date: 08/24/04  
 Waste Item #: 241  
 Waste Code: 241  
 Waste Name: TANK BOTTOM WASTE  
 Qnty at Inspection: 10000  
 Quantity String: 10000  
 Annual Qty: 11440  
 Annual Qty String: 11440  
 Measurement Unit: GAL  
 Treatment Method: 009 FILTRATION  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 1533 ECOLOGY CONTROL INDU  
 Waste Desc: TANK BOTTOMS SLUDGE/WATER  
 Carcinogen: No

Inspection Date: 08/24/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 1100  
 Quantity String: 1100  
 Annual Qty: 2200  
 Annual Qty String: 2200  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: BOX  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: GASOLINE FUEL FILTERS  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 3791  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**S104234412**

Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003791-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 4

Status: Not reported  
 Comp Number: 3791  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003791-000003  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3791  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003791-000004  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 3791  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003791-000005  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHEVRON USA INC. (Continued)**

**S104234412**

Content:	Not reported
Number Of Tanks:	Not reported
Status:	A
Comp Number:	3791
Number:	9
Board Of Equalization:	Not reported
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-003791-000001
Actv Date:	Not reported
Capacity:	12000
Tank Use:	OIL
Stg:	W
Content:	Not reported
Number Of Tanks:	4
Status:	A
Comp Number:	3791
Number:	9
Board Of Equalization:	Not reported
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-003791-000007
Actv Date:	Not reported
Capacity:	1000
Tank Use:	OIL
Stg:	P
Content:	Not reported
Number Of Tanks:	Not reported
Status:	A
Comp Number:	3791
Number:	9
Board Of Equalization:	Not reported
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-003791-000008
Actv Date:	Not reported
Capacity:	5000
Tank Use:	OIL
Stg:	P
Content:	Not reported
Number Of Tanks:	Not reported
Status:	A
Comp Number:	3791
Number:	9

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC. (Continued)**

**S104234412**

Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-003791-000009  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

SAN DIEGO CO. SAM:

Case Number: H03791-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 10/11/1988  
 Begandt: 3/30/1987

Case Number: H03791-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 6/16/1993  
 Begandt: 6/15/1993

Case Number: H03791-003  
 Agency: CA Regional Water Quality Control Board  
**Funding: Non Billable**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Leak Being Confirmed  
 Date: 2/6/2001  
 Begandt: 2/6/2001

84

**CHEVRON SAN DIEGO TERMINAL 1001252**  
**2351 E HARBOR DR**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000434382**  
**HAZNET CAT000614958**  
**HIST UST**

RCRA-SQG:

Date form received by agency: 03/28/2002  
 Facility name: CHEVRON SAN DIEGO TERMINAL 1001252  
 Facility address: 2351 E HARBOR DR  
 SAN DIEGO, CA 92113  
 EPA ID: CAT000614958  
 Mailing address: PO BOX 6004  
 ROOM L2173  
 SAN RAMON, CA 94583  
 Contact: KATHY L NORRIS  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (925) 842-5931

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON SAN DIEGO TERMINAL 1001252 (Continued)**

**1000434382**

Contact email: KNORRIS@CHEVRONTEXACO.COM  
 EPA Region: 09  
 Land type: Private  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: Unknown  
 Transporter of hazardous waste: Unknown  
 Treater, storer or disposer of HW: No  
 Underground injection activity: Unknown  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: Unknown  
 Used oil processor: Unknown  
 User oil refiner: Unknown  
 Used oil fuel marketer to burner: Unknown  
 Used oil Specification marketer: Unknown  
 Used oil transfer facility: Unknown  
 Used oil transporter: Unknown  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 03/28/2002  
 Facility name: CHEVRON SAN DIEGO TERMINAL 1001252  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: CHEVRON SAN DIEGO TERMINAL 1001252  
 Site name: CHEVRON USA INC SAN DIEGO SUPPLY SITE  
 Classification: Large Quantity Generator

Date form received by agency: 02/14/1996  
 Facility name: CHEVRON SAN DIEGO TERMINAL 1001252  
 Site name: SAN DIEGO TERMINAL-CHEVRON RETAIL MARKTG  
 Classification: Large Quantity Generator

Date form received by agency: 02/23/1994  
 Facility name: CHEVRON SAN DIEGO TERMINAL 1001252  
 Site name: CHEVRON USA PRODUCTS SAN DIEGO TERMINAL  
 Classification: Large Quantity Generator

Date form received by agency: 02/27/1992  
 Facility name: CHEVRON SAN DIEGO TERMINAL 1001252  
 Site name: CHEVRON TERMINAL-SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 08/15/1980  
 Facility name: CHEVRON SAN DIEGO TERMINAL 1001252  
 Site name: CHEVRON USA INC SAN DIEGO SUPPLY SITE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON SAN DIEGO TERMINAL 1001252 (Continued)**

**1000434382**

Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 09/09/2005  
 Date achieved compliance: Not reported  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 09/09/2005  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/02/1993  
 Date achieved compliance: 08/02/1998  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 01/25/1991  
 Date achieved compliance: 08/02/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 09/09/2005  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: Not reported  
 Evaluation lead agency: Local

Evaluation date: 08/02/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/02/1998

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHEVRON SAN DIEGO TERMINAL 1001252 (Continued)**

**1000434382**

Evaluation lead agency: State Contractor/Grantee

Evaluation date: 01/25/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/02/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 12/06/1989  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

HAZNET:

Gepaid: CAT000614958  
 Contact: CHERVON PRODUCTS CO  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Transfer Station  
 Tons: .1876  
 Facility County: San Diego

Gepaid: CAT000614958  
 Contact: CHERVON PRODUCTS CO  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: CAP980883177  
 TSD County: 0  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 26.6880  
 Facility County: San Diego

Gepaid: CAT000614958  
 Contact: CHERVON PRODUCTS CO  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: CAD980883177  
 TSD County: Kern  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: 25.8498

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON SAN DIEGO TERMINAL 1001252 (Continued)**

**1000434382**

Facility County: San Diego  
 Gepaid: CAT000614958  
 Contact: CHERVON PRODUCTS CO  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: CAD980883177  
 TSD County: Kern  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 128.8362  
 Facility County: San Diego

Gepaid: CAT000614958  
 Contact: CHERVON PRODUCTS CO  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: AZD982441263  
 TSD County: 99  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Treatment, Incineration  
 Tons: .1000  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 27 additional CA\_HAZNET: record(s) in the EDR Site Report.

**HIST UST:**

Region: STATE  
 Facility ID: 00000021494  
 Facility Type: Other  
 Other Type: TERMINAL  
 Total Tanks: 0006  
 Contact Name: R. W. CLEWORTH  
 Telephone: 6192328573  
 Owner Name: CHEVRON USA INC.  
 Owner Address: 1201 S. BEACH BLVD.  
 Owner City,St,Zip: LA HABRA, CA 90631

Tank Num: 001  
 Container Num: U  
 Year Installed: Not reported  
 Tank Capacity: 00012000  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHEVRON SAN DIEGO TERMINAL 1001252 (Continued)**

**1000434382**

Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00000550  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 004  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 005  
 Container Num: 5  
 Year Installed: Not reported  
 Tank Capacity: 00000550  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 006  
 Container Num: 6  
 Year Installed: Not reported  
 Tank Capacity: 00000750  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

84

**2351 HARBOR DRIVE  
 2351 HARBOR DRIVE  
 SAN DIEGO, CA 92113**

**ERNS 2007324709  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

<b>84</b>	<b>CHEVRON SAN DIEGO TERMINAL 2351 EAST HARBOR DR. SAN DIEGO, CA 92113</b>	<b>CA WDS</b>	<b>S106105461 N/A</b>
-----------	--	---------------	---------------------------

CA WDS:

Facility ID: San Diego 371002749

Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.

Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.

NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board

Subregion: 9

Facility Telephone: Not reported

Facility Contact: Not reported

Agency Name: CHEVRON PRODUCTS CO

Agency Address: Not reported

Agency City,St,Zip: 0

Agency Contact: Not reported

Agency Telephone: Not reported

Agency Type: Private

SIC Code: 0

SIC Code 2: Not reported

Primary Waste: Not reported

Primary Waste Type: Not reported

Secondary Waste: Not reported

Secondary Waste Type: Not reported

Design Flow: 0

Baseline Flow: 0

Reclamation: Not reported

POTW: Not reported

Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

<b>84</b>	<b>CHEVRON USA INC 2351 E HARBOR DR SAN DIEGO, CA 92113</b>	<b>AIRS</b>	<b>S106828547 N/A</b>
-----------	---	-------------	---------------------------

EMI:

Year: 1990

Carbon Monoxide Emissions Tons/Yr: 37

Air Basin: SD

Facility ID: 1968

Air District Name: SD

SIC Code: 5171

Air District Name: SAN DIEGO COUNTY APCD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHEVRON USA INC (Continued)**

**S106828547**

Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 43  
 Reactive Organic Gases Tons/Yr: 42  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1993  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 35  
 Reactive Organic Gases Tons/Yr: 35  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1995  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 35  
 Reactive Organic Gases Tons/Yr: 35  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1996  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 35  
 Reactive Organic Gases Tons/Yr: 35  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON USA INC (Continued)**

**S106828547**

SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

84

**CHEVRON 1001252 SAN DIEGO  
 2351 EAST HARBOR DR  
 SAN DIEGO, CA 92113**

**HAZNET S107150124  
 N/A**

HAZNET:

Gepaid: CAT000614958  
 Contact: KATHY NORRIS  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 3.33  
 Facility County: San Diego

Gepaid: CAT000614958  
 Contact: KATHY NORRIS  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: AZD009015389  
 TSD County: 99  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Recycler  
 Tons: 0.27  
 Facility County: Not reported

Gepaid: CAT000614958  
 Contact: KATHY NORRIS  
 Telephone: 9258425931  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 6004  
 Mailing City,St,Zip: SAN RAMON, CA 945830000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: San Diego  
 Waste Category: Paint sludge  
 Disposal Method: Transfer Station  
 Tons: 0.2  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**84 CHEVRON USA INC AIRS S106828546**  
**2351 E HARBOR DR N/A**  
**, CA 92113**

EMI:  
 Year: 1987  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1968  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 31  
 Reactive Organic Gases Tons/Yr: 31  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

**84 SAN DIEGO PETROLEUM CORP HAZNET S104574079**  
**2351 E HARBOR BLVD N/A**  
**SAN DIEGO, CA 92113**

HAZNET:  
 Gepaid: CAD981370521  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2351 E HARBOR BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: .0450  
 Facility County: San Diego

Gepaid: CAD981370521  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2351 E HARBOR BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAL931024038  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: .1900  
 Facility County: San Diego

Gepaid: CAD981370521  
 Contact: Not reported  
 Telephone: 0000000000



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO PETROLEUM CORP (Continued)**

**S104574079**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2351 E HARBOR BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: .3750  
 Facility County: San Diego

Gepaid: CAD981370521  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2351 E HARBOR BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .1925  
 Facility County: San Diego

Gepaid: CAD981370521  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2351 E HARBOR BLVD  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD000633164  
 TSD County: Imperial  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Land Fill  
 Tons: .5000  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 29 additional CA\_HAZNET: record(s) in the EDR Site Report.

84

**ARCO SAN DIEGO TERMINAL  
 2295 HARBOR DR  
 SAN DIEGO, CA 92113**

**TRIS 1005454843  
 UST 92113RCSND22**

UST:  
 Local Agency: 37000  
 Facility ID: H02375

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

84 ARCO SAN DIEGO TERMINAL  
 2295 HARBOR DR E  
 SAN DIEGO, CA 92101

LUST S100725892  
 Cortese N/A  
 San Diego Co. HMMD  
 AIRS  
 SWEEPS UST  
 SAN DIEGO CO. SAM

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607301045  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: 1997-11-14 00:00:00  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1992-09-10 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-09-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remedial action (cleanup) Underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: W.C. STAHLER  
 RP Address: P O BOX 13661  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Work Suspended: Not reported  
 Local Case #: H02375-002  
 Case Number: 9UT2279  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607301799  
 Stop Date: 1994-11-22 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: 1998-05-01 00:00:00  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1994-11-22 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1995-01-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remedial action (cleanup) Underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Jack Oman  
 RP Address: 6667 Indiana Av, Suite F #248  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02375-003  
 Case Number: 9UT3030  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607301975  
 Stop Date: 1996-04-12 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1996-06-27 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1996-04-12 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1996-04-12 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Jack Oman  
 RP Address: 6667 Indiana Av, Suite F #248

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02375-004  
 Case Number: 9UT3218  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Structure Failure  
 Leak Source: Unknown  
 Global Id: T0607399202  
 Stop Date: 1998-08-07 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1998-05-01 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1998-08-07 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1998-08-17 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Jack Oman  
 RP Address: 6667 Indiana Av, Suite F #248  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02375-005  
 Case Number: 9UT3986  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608130078  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 1992-06-20 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Jack Oman  
 RP Address: 6 Centerpointe Dr.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02375-001  
 Case Number: 9UT19  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT19  
 Local Agency: San Diego  
 Substance: Misc. Motor Vehicle Fuels  
 Qty Leaked: Not reported  
 Date Found: / /  
 How Found: Not reported  
 Date Stopped: / /  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 09/30/1986  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 4/20/87  
 Pilot Program: LOP  
 Local Case: T00299  
 Basin Number: 908.21  
 Gwater Depth: Not reported  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: Not reported  
 File Dispn: File discarded, case closed  
 Release Date: 09/10/1986  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT2279  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 09/10/1992  
 How Found: Tank Closure  
 Date Stopped: 09/10/1992  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 10/19/1992  
 Submit Workplan: 10/20/92  
 Prelim Assess: 03/31/1993  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H02375-002  
 Basin Number: 908.21  
 Gwater Depth: 19'  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 09/10/1992



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT3218  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 04/12/1996  
 How Found: Not reported  
 Date Stopped: 04/12/1996  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 06/13/1996  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 6/28/96  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H02375-004  
 Basin Number: 908.22  
 Gwater Depth: 11'+  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 04/12/1996

Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 2295 HARBOR DR E

Region: CORTESE  
 Facility Addr2: 2295 HARBOR DR E

Region: CORTESE  
 Facility Addr2: 2295 HARBOR DR E

San Diego Co. HMMID:  
 Facility ID: 102375  
 Inactive Indicator: Active  
 Business Code: 6HK78

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ARCO PRODUCT CO MICHAEL BURKE  
 Mailing Address: 2295 E HARBOR DR  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD000633271  
 Gas Station: Not reported  
 Inspection Date: 05/05/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE BURKE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ATLANTIC RICHFIELD CO  
 Property Address: P O BOX 5015  
 Property City, St, Zip: 90622  
 Tank Owner: ARCO PETROLEUM PRODUCTS  
 Tank Address: 2295 HARBOR DR  
 Tank City, St, Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/05/05  
 Facility Phone: 619-233-4400

**HMMD DISCLOSURE INVENTORY:**

Item Number: AF45  
 Chemical Name: AFFF, FIRE FIGHTING FOAM  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: DE43  
 Chemical Name: DENATURED ALCOHOL  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: DI49

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Chemical Name: DIESEL  
 Case Number: 68476-30-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: ET24  
 Chemical Name: ETHYL ALCOHOL - DENATURED ETHANOL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ET76  
 Chemical Name: ETHYL ALCOHOL- DENATURED ETHANOL  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: ET47  
 Chemical Name: ETHYLENE GLYCOL  
 Case Number: 107-21-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: FR48  
 Chemical Name: FREON 502,503  
 Case Number: 75-69-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

2nd Hazard Category: ACUTE

Item Number: FU46  
 Chemical Name: FUEL ADDITIVE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: GA34  
 Chemical Name: GASOLINE(TYPE UNKNOWN) UNDERGROUND TANK 102375 T009 VAPOR RECOVERY  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: MA42  
 Chemical Name: MAX-179,215 BBLs GASOLINE 152,000 BBLs 1/96  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OT33  
 Chemical Name: OTHER - SPECIFY UNDERGROUND TANK 102375 T007 PUMPBACK(MISC.FUEL PRODUCTS)  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Tank Number: T002  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: GASOLINE  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T004  
 Tank ID Number: WATER DRA  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T005  
 Tank ID Number: WASTER WA  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T006  
 Tank ID Number: 56  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T007  
 Tank ID Number: NT1806 PUM  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T008  
 Tank ID Number: NT1861  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T009  
 Tank ID Number: NT1861 VAP  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/05/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 9198  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 11/05/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 9199  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 04/04/02  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Type of Violation: 6HX3011  
 Occurrences: Not reported  
 Item Number: 6393  
 Violation Desc: FAIL TO COMPLY WITH OP PERMIT CONDITIO

Inspection Date: 04/04/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 6394  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 01/22/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 3286  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 01/22/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3029  
 Occurrences: Not reported  
 Item Number: 3287  
 Violation Desc: SPILL/OVERFILL PREVENTION NOT INSTALLED

Inspection Date: 04/09/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3110  
 Occurrences: Not reported  
 Item Number: 9142  
 Violation Desc: NO ANNUAL CERT OF ATG AND SENSORS

**HMMD WASTE STREAMS:**

Inspection Date: 05/05/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 40  
 Annual Qty String: 40  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3058 ADVANCED CLEANUP TEC  
 Waste Desc: ABSORBENT /SOIL  
 Carcinogen: No

Inspection Date: 05/05/04  
 Waste Item #: 222  
 Waste Code: 222  
 Waste Name: OIL/WATER SEPARATION  
 Qnty at Inspection: 10000  
 Quantity String: 10000  
 Annual Qty: 10000  
 Annual Qty String: 10000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: EXCLUDED(TO REFIERY)  
 Carcinogen: No

Inspection Date: 05/05/04  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 2500  
 Quantity String: 2500  
 Annual Qty: 5000  
 Annual Qty String: 5000  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 3058 ADVANCED CLEANUP TEC  
 Waste Desc: GAS/WATER FROM WELLS  
 Carcinogen: No

**EMI:**

Year: 1997  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 25  
 Reactive Organic Gases Tons/Yr: 25  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 21  
 Reactive Organic Gases Tons/Yr: 21  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 22  
 Reactive Organic Gases Tons/Yr: 22  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 22  
 Reactive Organic Gases Tons/Yr: 22  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 22  
 Reactive Organic Gases Tons/Yr: 22  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 22  
 Reactive Organic Gases Tons/Yr: 22  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 21  
 Reactive Organic Gases Tons/Yr: 21  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 21.20002278  
 Reactive Organic Gases Tons/Yr: 21.20002278  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 201  
 Air District Name: SD  
 SIC Code: 5171  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 21.9  
 Reactive Organic Gases Tons/Yr: 21.9  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

**SWEEPS UST:**

Status: A  
 Comp Number: 2375  
 Number: 9  
 Board Of Equalization: 44-000506  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002375-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 5

Status: A  
 Comp Number: 2375  
 Number: 9  
 Board Of Equalization: 44-000506  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002375-000002  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2375  
 Number: 9  
 Board Of Equalization: 44-000506  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002375-000003  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

ARCO SAN DIEGO TERMINAL (Continued)

S100725892

Status: A  
 Comp Number: 2375  
 Number: 9  
 Board Of Equalization: 44-000506  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002375-000004  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2375  
 Number: 9  
 Board Of Equalization: 44-000506  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002375-000005  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

SAN DIEGO CO. SAM:

Case Number: H02375-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 6/10/1992  
 Begandt: 2/12/1992

Case Number: H02375-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Action (Clean-Up)  
 Date: 5/1/1998  
 Begandt: 9/10/1992

Case Number: H02375-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Action (Clean-Up)  
 Date: 5/1/1998

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO SAN DIEGO TERMINAL (Continued)**

**S100725892**

Begandt: 11/22/1994  
 Case Number: H02375-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 6/13/1996  
 Begandt: 4/12/1996

Case Number: H02375-005  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 5/1/1998  
 Begandt: 8/7/1998

84

**ATLANTIC RICHFIELD CO SAN DIEGO TERM  
 2295 E. HARBOR DRIVE  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000153711  
 FINDS CAD000633271**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: ATLANTIC RICHFIELD CO SAN DIEGO TERM  
 Facility address: 2295 E HARBOR DR  
 SAN DIEGO, CA 92113  
 EPA ID: CAD000633271  
 Mailing address: PO BOX 13013  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Facility is not located on Indian land. Additional information is not known.  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: ATLANTIC RICHFIELD COMPANY  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ATLANTIC RICHFIELD CO SAN DIEGO TERM (Continued)**

**1000153711**

Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 09/01/1996  
 Facility name: ATLANTIC RICHFIELD CO SAN DIEGO TERM  
 Classification: Small Quantity Generator

Date form received by agency: 02/29/1996  
 Facility name: ATLANTIC RICHFIELD CO SAN DIEGO TERM  
 Site name: ARCO PRODUCTS COMPANY-SAN DIEGO TERMINAL  
 Classification: Large Quantity Generator

Date form received by agency: 03/25/1994  
 Facility name: ATLANTIC RICHFIELD CO SAN DIEGO TERM  
 Site name: ARCO PRODUCTS CO SAN DIEGO TERM  
 Classification: Large Quantity Generator

Date form received by agency: 02/28/1992  
 Facility name: ATLANTIC RICHFIELD CO SAN DIEGO TERM  
 Site name: ARCO PETROLEUM PRODUCTS CO SAN DIEGO TER  
 Classification: Large Quantity Generator

Date form received by agency: 08/18/1980  
 Facility name: ATLANTIC RICHFIELD CO SAN DIEGO TERM  
 Classification: Large Quantity Generator

Violation Status: No violations found

**Evaluation Action Summary:**

Evaluation date: 05/05/2004  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ATLANTIC RICHFIELD CO SAN DIEGO TERM (Continued)**

**1000153711**

Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

Not reported

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

84

**ARCO GAS TERMINAL  
 2295 HARBOR DR E  
 SAN DIEGO, CA 92113**

**LUST S104494692  
 N/A**

**LUST:**

Region: 9  
 Case Number: 9UT3986  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 08/07/1998  
 How Found: Other Means  
 Date Stopped: 08/07/1998  
 How Stopped: Other Means  
 Source: Piping  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO GAS TERMINAL (Continued)**

**S104494692**

Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: 08/17/1998  
 Submit Workplan: 10/5/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 10/8/99  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H02375-005  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Disp: Not reported  
 Release Date: 08/17/1998  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

84

**SAN DIEGO PIPELINE COMPANY HAR  
 2295 HARBOR DR  
 SAN DIEGO, CA 90014**

**HIST UST U001560576  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000004638  
 Facility Type: Other  
 Other Type: PIPELINE CO.  
 Total Tanks: 0001  
 Contact Name: E. W. HALE  
 Telephone: 6192836511  
 Owner Name: SAN DIEGO PIPELINE COMPANY  
 Owner Address: 610 SOUTH MAIN STREET  
 Owner City,St,Zip: LOS ANGELES, CA 90014

Tank Num: 001  
 Container Num: RELIEF TAN  
 Year Installed: 1973  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Visual

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>84</b>	<b>SAN DIEGO TERMINAL</b> <b>2295 E. HARBOR DR.</b> <b>SAN DIEGO, CA 92113</b>	<b>AST</b>	<b>A100226539</b> <b>N/A</b>
-----------	--	------------	---------------------------------

AST:  
 Owner: BP WEST COAST PRODUCTS  
 Total Gallons: 9316620

<b>84</b>	<b>ARCO TERMINAL</b> <b>2295 HARBOR DR E</b> <b>SAN DIEGO, CA 92113</b>	<b>LUST</b> <b>Cortese</b>	<b>S102424490</b> <b>N/A</b>
-----------	---	-------------------------------	---------------------------------

LUST:  
 Region: 9  
 Case Number: 9UT3030  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 11/22/1994  
 How Found: Not reported  
 Date Stopped: 11/22/1994  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 01/06/1995  
 Submit Workplan: Not reported  
 Prelim Assess: 01/09/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 1/5/95  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H02375-003  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: BUOC  
 NPDES Number: Not reported  
 priority: 2  
 File Dispn: File discarded, case closed  
 Release Date: 01/05/1995  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 2295 HARBOR DR E



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

85

CHMIRS S100216608  
 N/A

**N/B I-5 AT I-15  
 SAN DIEGO, CA**

CHMIRS:

OES Incident Number: 8804094  
 OES notification: Not reported  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: 13-DEC-88  
**Date Completed: 13-DEC-88**  
 Property Use: 961  
 Agency Id Number: 37140  
 Agency Incident Number: 32064  
 Time Notified: 1039  
 Time Completed: 1201  
 Surrounding Area: 600  
 Estimated Temperature: 65  
 Property Management: S  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agncy Personel # Of Decontaminated: 2  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: VERN SCOTT TRUCKING  
 Reporting Officer Name/ID: JERRY GRAY, #1250  
 Report Date: 13-DEC-88  
 Comments: N  
 Facility Telephone: 619 236-7773  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 88-92  
 Agency: Not reported  
 Incident Date: Not reported  
 Admin Agency: Not reported  
 Amount: Not reported  
 Contained: Not reported  
 Site Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100216608

E Date: Not reported  
 Substance: Not reported  
 Quantity Released: Not reported  
 BBLS: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: Not reported  
 Evacuations: Not reported  
 Number of Injuries: Not reported  
 Number of Fatalities: Not reported  
 Description: Not reported

85 I 5 @ I 15  
 I 5 @ I 15  
 SAN DIEGO, CA

ERNS 8875088  
 N/A

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

86 VALVOLINE INSTANT OIL CHANGE  
 32ND & MAIN #3456  
 SAN DIEGO, CA 92136

FINDS 1007679163  
 110017970294

FINDS:  
 Other Pertinent Environmental Activity Identified at Site

UORS (California - Used Oil Recycling System). California Integrated Waste Management Board (CIWMB) helps communities establish and promote convenient collection opportunities for used oil and used oil filters.

86 CITY OF SAN DIEGO, TRANSPORTATION DEPT  
 3200 MAIN ST  
 SAN DIEGO, CA 92113

HAZNET S107139906  
 N/A

HAZNET:  
 Gepaid: CAC002561627  
 Contact: MARK HOFFORD  
 Telephone: 6195277506  
 Facility Addr2: CREEK CLEAN UP  
 Mailing Name: Not reported  
 Mailing Address: 2781 CAMITO CHOLLAS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CITY OF SAN DIEGO, TRANSPORTATION DEPT (Continued)**

**S107139906**

Mailing City,St,Zip: SAN DIEGO, CA 92105  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Treatment, Incineration  
 Tons: 0.07  
 Facility County: San Diego

86

**A TO Z AUTO INC  
 3202 MAIN ST  
 SAN DIEGO, CA 92113**

**SWRCY S108086783  
 N/A**

SWRCY:

Certification Status: O  
 Facility Phone Number: (619) 234-6691  
 Date facility became certified: 08/18/06  
 Date facility began operating: 10/02/06  
 Date facility ceased operating: Still operating  
 Whether The Facility Is Grandfathered: Not reported  
 Convenience Zone Where Facility Located: 4204  
 Convenience Zone Where Facility Located 2: 0  
 Convenience Zone Where Facility Located 3: 0  
 Convenience Zone Where Facility Located 4: 0  
 Convenience Zone Where Facility Located 5: 0  
 Convenience Zone Where Facility Located 6: 0  
 Convenience Zone Where Facility Located 7: 0  
 Aluminum Beverage Containers Redeemed: AL  
 Glass Beverage Containers Redeemed: GL  
 Plastic Beverage Containers Redeemed: PL  
 Other mat beverage containers redeemed: Not reported  
 Refillable Beverage Containers Redeemed: Not reported

86

**A TO Z  
 3202 MAIN ST  
 SAN DIEGO, CA 92113**

**PADS 1009401979  
 CAW000000628**

86

**A TO Z AUTO DISMANTLING  
 3202 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S102861585  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAL000001295  
 Contact: A TO Z AUTO INC.  
 Telephone: 6192346691  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3202 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**A TO Z AUTO DISMANTLING (Continued)**

**S102861585**

Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 1.2510  
 Facility County: San Diego

Gepaid: CAL000027947  
 Contact: QUIGGLE RICHARD  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3202 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL000001295  
 Contact: A TO Z AUTO INC.  
 Telephone: 6192346691  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3202 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 0.2293  
 Facility County: San Diego

Gepaid: CAL000001295  
 Contact: A TO Z AUTO INC.  
 Telephone: 6192346691  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3202 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 3.7530  
 Facility County: San Diego

Gepaid: CAL000001295  
 Contact: A TO Z AUTO INC.  
 Telephone: 6192346691  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3202 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A TO Z AUTO DISMANTLING (Continued)**

**S102861585**

Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Recycler  
 Tons: .1876  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 110663  
 Inactive Indicator: Active  
 Business Code: 6HK32  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3202 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000001295  
 Gas Station: Not reported  
 Inspection Date: 07/03/03  
 Reinspection Date: Not reported  
 Inspector Name: MNYAGA  
 Violation Notice Issued: Not reported  
 Facility Contact: RICHARD QUIGGLE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WINETEER DWIGHT D REVOCABLE TR  
 Property Address: 6541 CARTWRIGHT ST  
 Property City,St,Zip: 92120  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/03/05  
 Facility Phone: 619-234-6691

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**A TO Z AUTO DISMANTLING (Continued)**

**S102861585**

1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 06/18/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7472  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 08/19/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 6657  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 07/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1966  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 07/03/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 240  
 Annual Qty String: 240  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 07/03/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 1040  
 Annual Qty String: 1040  
 Measurement Unit: GAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**A TO Z AUTO DISMANTLING (Continued)**

**S102861585**

Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 07/03/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 50  
 Quantity String: 50  
 Annual Qty: 130  
 Annual Qty String: 130  
 Measurement Unit: LBS  
 Treatment Method: 006 SURFACE IMPOUNDM  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2091 PACIFIC TREATMENT CO  
 Waste Desc: OIL ABSORBANT  
 Carcinogen: No

Inspection Date: 07/03/03  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 07/03/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 1500  
 Annual Qty String: 1500  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: SUNCOAST  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

86

CHMIRS S108402215  
 N/A

**3150 MAIN ST.  
 SAN DIEGO, CA**

CHMIRS:

OES Incident Number: 05-1692  
 OES notification: 3/16/200512:47:03 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2005  
 Agency: San Diego Waste Water  
 Incident Date: 3/16/200512:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Residence



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S108402215

E Date: Not reported  
 Substance: Sewage  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 100  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: A private lateral blockage caused the release.

86

**ADVANCED SURFACE TECHNOLOGY INC**  
**3134 MAIN ST**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000151409**  
**FINDS CAD981401094**

RCRA-SQG:

Date form received by agency: 04/25/1986  
 Facility name: ADVANCED SURFACE TECHNOLOGY INC  
 Facility address: 3134 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981401094  
 Mailing address: MAIN ST  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 3134 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 231-1471  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: LARRY ONSTOTT  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCED SURFACE TECHNOLOGY INC (Continued)**

**1000151409**

Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

86

**ADVANCED SURFACE TECHNOLOGY  
 3134 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000151422  
 HIST UST CAD981978836  
 SWEEPS UST**

**RCRA-SQG:**

Date form received by agency: 04/17/1987  
 Facility name: ADVANCED SURFACE TECHNOLOGY  
 Facility address: 3134 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981978836  
 Mailing address: MAIN ST  
 SAN DIEGO, CA 92113  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 3134 MAIN ST  
 SAN DIEGO, CA 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**ADVANCED SURFACE TECHNOLOGY (Continued)**

**1000151422**

Contact country: US  
 Contact telephone: (619) 231-1471  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: LARRY ONSTOTT  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**HIST UST:**

Region: STATE  
 Facility ID: 00000068915  
 Facility Type: Other  
 Other Type: ADVANCED SURFACE TEC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCED SURFACE TECHNOLOGY (Continued)**

**1000151422**

Total Tanks: 0002  
 Contact Name: Not reported  
 Telephone: 6192311471  
 Owner Name: ADVANCED SURFACE TECHNOLOGY IN  
 Owner Address: 3134 MAIN STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1983  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: 1  
 Tank Construction: Unkown inches  
 Leak Detection: Visual

Tank Num: 002  
 Container Num: 2  
 Year Installed: 1983  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: PREMIUM  
 Tank Construction: Not reported  
 Leak Detection: Visual

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 14719  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014719-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 14719  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014719-000002  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)	Site	Database(s) EPA ID Number

**ADVANCED SURFACE TECHNOLOGY (Continued)**

1000151422

Content: REG UNLEADED  
 Number Of Tanks: Not reported

86

**ADVANCE DIESEL INJECTION  
 3134 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748319  
 N/A**

San Diego Co. HMMD:

Facility ID:	114719
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	3134 MAIN ST
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	39
EPA ID:	CAL000018717
Gas Station:	Not reported
Inspection Date:	06/27/03
Reinspection Date:	Not reported
Inspector Name:	MNYAGA
Violation Notice Issued:	Not reported
Facility Contact:	WAYNE HANGEN
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	ADVANCED DIESEL INJECTION INC
Property Address:	3134 MAIN ST
Property City,St,Zip:	92113
Tank Owner:	LARRY L ONSTOTT
Tank Address:	3134 MAIN ST
Tank City,St,Zip:	San Diego, CA 92113
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	12/27/04
Facility Phone:	619-232-6452

**HMMD DISCLOSURE INVENTORY:**

Item Number:	NA09
Chemical Name:	NAPTHA: VISCOR 148 AW2 CALIBRATION FLUID
Case Number:	8030-31-7
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	CHRONIC
Item Number:	VI10
Chemical Name:	VISCOSITY, CST A 84.2F

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCE DIESEL INJECTION (Continued)**

**S104748319**

Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 06/27/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 7591  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4747  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4748  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4749  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: 06/27/03  
 Waste Item #: 121  
 Waste Code: 121  
 Waste Name: ALKALINE SOL'N WITH  
 Qty at Inspection: 100

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ADVANCE DIESEL INJECTION (Continued)**

**S104748319**

Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: TO ALLEY 6/97 ER HOT TANK  
 Carcinogen: No

Inspection Date: 06/27/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 360  
 Annual Qty String: 360  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: 2 PARTS WASHERS  
 Carcinogen: No

Inspection Date: 06/27/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 10  
 Annual Qty String: 10  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: CARBOY  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: CUTTING/COMPRESSOR OILS  
 Carcinogen: No

86

**S.A. HYDRAULIC SERVICE  
 3120 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748448  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 115431  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3120 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S.A. HYDRAULIC SERVICE (Continued)**

**S104748448**

Census Tract Number: 39  
 EPA ID: CAL000145871  
 Gas Station: Not reported  
 Inspection Date: 03/15/01  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVE ARIAS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SHIELDS GEORGE H TR  
 Property Address: 5200 IRVINE BLVD #48  
 Property City,St,Zip: 92620  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-544-1211

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 8286  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 08/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8287  
 Violation Desc: WASTE CONTAINER W/O LABELS



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S.A. HYDRAULIC SERVICE (Continued)**

**S104748448**

Inspection Date: 05/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 4350  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 05/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4351  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 05/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4352  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/15/01  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 3157  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 03/15/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3158  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/15/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3159  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S.A. HYDRAULIC SERVICE (Continued)**

**S104748448**

Facility ID: 203210  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3120 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/10/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SHIELDS GEORGE H TR  
 Property Address: 5200 IRVINE BLVD #48  
 Property City,St,Zip: 92620  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-0093

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S.A. HYDRAULIC SERVICE (Continued)**

**S104748448**

Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 204274  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3120 MAIN ST  
 Mailing City,St,Zip: San Diego, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 10/25/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: FRANK GARCIA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SHIELDS GEORGE H TR  
 Property Address: 5200 IRVINE BLVD #48  
 Property City,St,Zip: 92620  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/25/06  
 Facility Phone: 619-546-5718

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S.A. HYDRAULIC SERVICE (Continued)**

**S104748448**

**HMMD DISCLOSURE INVENTORY:**

Item Number: AR50  
 Chemical Name: ARGON GAS ARGON/CO2 MIX  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OX49  
 Chemical Name: OXYGEN GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 10/25/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED OIL  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S.A. HYDRAULIC SERVICE (Continued)**

**S104748448**

Inspection Date: 10/25/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 60  
 Quantity String: 60  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: SUNBELT BATTERIES  
 Carcinogen: No

86

**ABAMEX INC  
 3106 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S108196614  
 N/A**

HAZNET:

Gepaid: CAC002576929  
 Contact: OLGA LEMENI/PRINCIPLES  
 Telephone: 8582792846  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 6218 CAMINITO LUISITO  
 Mailing City,St,Zip: SAN DIEGO, CA 92111  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

86

**ARC CASTLE ELECTRONICS  
 3106 MAIN ST  
 SAN DIEGO, CA 92123**

**LUST S106874099  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T06019741969  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARC CASTLE ELECTRONICS (Continued)**

**S106874099**

Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2004-07-20 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: Marilyn Kriebel, Administrator  
 RP Address: 772 Jamacha Rd., PMB 355  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00215-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H00215-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 7/20/2004  
 Begandt: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**86      ARC CASTLE ELECTRIC  
 3106 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104744933  
 N/A**

San Diego Co. HMMD:

Facility ID: 100215  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3106 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000157634  
 Gas Station: Not reported  
 Inspection Date: 08/26/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: BUDDY MCLANE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TOMA SABAH Y&PATRICE Y  
 Property Address: 4208 LOMA PASEO  
 Property City, St, Zip: 91902  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-0158

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARC CASTLE ELECTRIC (Continued)**

**S104744933**

**HMMD VIOLATIONS:**

Inspection Date: 12/16/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 0036  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 12/16/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0037  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5449  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5450  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5451  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5452  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 08/26/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 3562  
 Violation Desc: UFPF NOT OBTAINED for HAZWASTE

Inspection Date: 08/26/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3563  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARC CASTLE ELECTRIC (Continued)**

**S104744933**

Inspection Date: 08/26/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3564  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

86

**CASINO ELECTRIC COMPANY INC  
 3106 MAIN STREET  
 SAN DIEGO, CA 92113**

**HAZNET S103651746  
 ENVIROSTOR N/A**

**HAZNET:**

Gepaid: CAL000157634  
 Contact: OB MCLANE JR  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13266  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .2500  
 Facility County: San Diego

**ENVIROSTOR:**

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37990007  
 Site Code: Not reported  
 Assembly: 79

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CASINO ELECTRIC COMPANY INC (Continued)**

**S103651746**

Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2004-04-22 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37990007  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:  
 Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed:  
 Confirmed Description: NONE SPECIFIED  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

87

**DIESEL ELECTRIC EXCHANGE  
 2874 MAIN ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

S104747923  
 N/A

San Diego Co. HMMD:  
 Facility ID: 113658  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIESEL ELECTRIC EXCHANGE (Continued)**

**S104747923**

Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SALVAREZZA FAMILY TRUST 12-30-  
 Property Address: 110 BRAEMAR DR  
 Property City,St,Zip: 94010  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIESEL ELECTRIC EXCHANGE (Continued)**

**S104747923**

Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

87

**COAST INDUSTRIAL SYSTEMS  
 3004 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S106065653  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAL000256741  
 Contact: LARRY ONSTOTT JR  
 Telephone: 6192323549  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3004 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133731  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Transfer Station  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAL000256741  
 Contact: LARRY ONSTOTT JR  
 Telephone: 6192323549  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3004 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133731  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: San Diego

Gepaid: CAL000256741  
 Contact: JUSTIN ISBELL  
 Telephone: 6192323549  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3004 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COAST INDUSTRIAL SYSTEMS (Continued)**

**S106065653**

Tons: 0.20  
 Facility County: Not reported

**San Diego Co. HMMD:**

Facility ID: 138581  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3004 MAIN ST # A  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000256741  
 Gas Station: Not reported  
 Inspection Date: 08/12/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: LARRY ONSTOTT JR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GOODWIN MICHAEL R&EDITH A  
 Property Address: P O BOX 820  
 Property City,St,Zip: 91962  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/12/06  
 Facility Phone: 619-232-3549

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COAST INDUSTRIAL SYSTEMS (Continued)**

**S106065653**

**HMMD VIOLATIONS:**

Inspection Date: 05/10/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 4232  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 05/10/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 4233  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 09/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2039  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 09/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 2040  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 09/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 2041  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

**HMMD WASTE STREAMS:**

Inspection Date: 08/12/04  
 Waste Item #: 081  
 Waste Code: 81  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: STODDORD/PAINT  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**87 B & C DIVING & CONST SOUTH INC  
 3004 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104755948  
 N/A**

San Diego Co. HMMD:

Facility ID: 137088  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P.O. BOX 13187  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/21/00  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RUSS VAN CLEVE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: GOODWIN MICHAEL R&EDITH A  
 Property Address: P O BOX 820  
 Property City,St,Zip: 91962  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-237-0409

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**B & C DIVING & CONST SOUTH INC (Continued)**

**S104755948**

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

87

**B & C DIVING  
 3004 MAIN STREET  
 SAN DIEGO, CA 92112**

**HAZNET S102626260  
 N/A**

HAZNET:

Gepaid: CAC002290121  
 Contact: B & C DIVING  
 Telephone: 6192370409  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13187  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Recycler  
 Tons: 0.2293  
 Facility County: San Diego

Gepaid: CAC001144864  
 Contact: B & C DIVING  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13187  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**B & C DIVING (Continued)**

**S102626260**

Tons: .2293  
 Facility County: San Diego  
  
 Gepaid: CAC001144864  
 Contact: B & C DIVING  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13187  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

87

**FABRICATION ARTS  
 2926 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104745019  
 AIRS N/A**

San Diego Co. HMMD:  
 Facility ID: 100537  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ACCTS PAYABLE  
 Mailing Address: 2952 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000049059  
 Gas Station: Not reported  
 Inspection Date: 09/29/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: BOBBI BAUR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ANDREWS RUBEN  
 Property Address: 2952 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/29/05  
 Facility Phone: 619-232-5087

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FABRICATION ARTS (Continued)**

**S104745019**

HMMD DISCLOSURE INVENTORY:

Item Number: AR25  
 Chemical Name: ARGON, COMPRESSED GAS  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: OX26  
 Chemical Name: OXYGEN, COMPRESSED GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PA24  
 Chemical Name: PAINTS AND DYE (5)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

HMMD VIOLATIONS:

Inspection Date: 03/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2585  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 2586

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FABRICATION ARTS (Continued)**

**S104745019**

Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 4468  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 09/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4469  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 09/29/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: BAG  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PAINT BOOTH FILTERS  
 Carcinogen: No

Inspection Date: 09/29/03  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: GAL  
 Treatment Method: 014 TRANSFER STATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: THINNER USED IN SPRAY-GUN  
 Carcinogen: No

**EMI:**

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 90230  
 Air District Name: SD  
 SIC Code: 2750  
 Air District Name: SAN DIEGO COUNTY APCD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FABRICATION ARTS (Continued)**

**S104745019**

Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 90230  
 Air District Name: SD  
 SIC Code: 2750  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 90230  
 Air District Name: SD  
 SIC Code: 2752  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: N  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 90230  
 Air District Name: SD  
 SIC Code: 2752  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FABRICATION ARTS (Continued)**

**S104745019**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	90230
Air District Name:	SD
SIC Code:	2752
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.2895125
Reactive Organic Gases Tons/Yr:	0.2094
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	90230
Air District Name:	SD
SIC Code:	2752
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.2895125
Reactive Organic Gases Tons/Yr:	.2094
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

87

**GRAPHIC SOLUTIONS**  
**2926 MAIN ST**  
**SAN DIEGO, CA 92113**

**FINDS 1008207100**  
**110021116745**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**87 GRAPHIC SOLUTIONS DBA FABRICATION ARTS  
 2926 MAIN STREET  
 SAN DIEGO, CA 92113**

**HAZNET S100863354  
 N/A**

HAZNET:

Gepaid: CAL000049059  
 Contact: GRAPHIC SOLUTIONS LTD  
 Telephone: 6192325087  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2926 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133730  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .8890  
 Facility County: San Diego

Gepaid: CAL000049059  
 Contact: JOHN OCONNELL  
 Telephone: 6192325087  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2926 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133730  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 1.9  
 Facility County: Not reported

Gepaid: CAL000049059  
 Contact: GRAPHIC SOLUTIONS LTD  
 Telephone: 6192325087  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2926 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133730  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .5880  
 Facility County: San Diego

Gepaid: CAL000049059  
 Contact: GRAPHIC SOLUTIONS LTD  
 Telephone: 6192325087  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2926 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133730  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAPHIC SOLUTIONS DBA FABRICATION ARTS (Continued)**

**S100863354**

TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 1.4665  
 Facility County: San Diego

Gepaid: CAL000049059  
 Contact: JOHN OCONNELL  
 Telephone: 6192325087  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2926 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133730  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 0.18  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 8 additional CA\_HAZNET: record(s) in the EDR Site Report.

87

**GRAPHIC SOLUTIONS  
 2952 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748497  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 115786  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2952 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: CAD981644123  
 Gas Station: Not reported  
 Inspection Date: 03/19/90  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JOHN OCONNELL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ANDREWS RUBEN&DEIRDRE  
 Property Address: 2952 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAPHIC SOLUTIONS (Continued)**

**S104748497**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 232-5087

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 138216  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GRAPHIC SOLUTIONS (Continued)**

**S104748497**

2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 132  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/30/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GRAPHIC SOLUTIONS (Continued)**

**S104748497**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

87

**CALIFORNIA MARINE CLEANING  
 2970 MAIN ST  
 SAN DIEGO, CA 92113**

**FINDS 1000252226  
 RCRA-NonGen CAD981407430**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**RCRA-NonGen:**

Date form received by agency: 10/01/1991  
 Facility name: CALIFORNIA MARINE CLEANING  
 Facility address: 2970 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981407430  
 Mailing address: 3562 PERSHING AVE  
 SAN DIEGO, CA 92104  
 Contact: ENVIRONMENTAL MANAGER  
 Contact address: 2970 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 231-8788  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: MATTHEW CARR  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CALIFORNIA MARINE CLEANING (Continued)**

**1000252226**

Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212

Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

87

**RPM WELDING**  
**2970 MAIN ST**  
**SAN DIEGO, CA 92113**

**HAZNET S100869474**  
**San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAL000145143  
 Contact: TOM LUCIANO, PARTNER  
 Telephone: 6192348801  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1841 NATIONAL AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921133730  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: .1245  
 Facility County: San Diego

Gepaid: CAL923004836  
 Contact: LA VAN MC CREE  
 Telephone: 6192393010

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2970 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Not reported  
 Tons: .0135  
 Facility County: San Diego

Gepaid: CAL923004836  
 Contact: LA VAN MC CREE  
 Telephone: 6192393010  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2970 MAIN STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .1485  
 Facility County: San Diego

**San Diego Co. HMMD:**

Facility ID: 119163  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2970 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL000043619  
 Gas Station: Not reported  
 Inspection Date: 01/07/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DANIEL PEARCE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/04/05  
 Facility Phone: 619-239-0723

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC52  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR55  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: LU18  
 Chemical Name: LUBRICATING SOIL LUBRICATING SOIL  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: OX53  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR54  
 Chemical Name: PROPANE  
 Case Number: 74-98-6

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 7293  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 01/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7294  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 7295  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 01/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 7296  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 01/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 7297  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 01/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 7298

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 01/07/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: FROM VEHICLES  
 Carcinogen: No

Facility ID: 119238  
 Inactive Indicator: Active  
 Business Code: 6HK71  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2990 JAMACHA RD  
 Mailing City,St,Zip: EL CAJON, CA 92019  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 04/06/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: BILL KELLER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-6991

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 133816  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2970 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: CAL923004836  
 Gas Station: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Inspection Date: 12/10/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RICARDO GUERRA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-8801

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203723  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2970 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/02/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ALBERTO ALCANTAR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: R&H PROPERTIES L P  
 Property Address: 78273 BIRKDALE CT  
 Property City,St,Zip: 92253  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/02/06  
 Facility Phone: 619-239-5264

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**RPM WELDING (Continued)**

**S100869474**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 07/02/04  
 Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 45  
 Annual Qty String: 45  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESS EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 07/02/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 07/02/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RPM WELDING (Continued)**

**S100869474**

Waste Desc: Not reported  
 Carcinogen: No

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HMMD: record(s) in the EDR Site Report.

87

**ADVANCE ENG TECH SERV INC  
 3032 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104752757  
 N/A**

San Diego Co. HMMD:

Facility ID: 131511  
 Inactive Indicator: Active  
 Business Code: 6HK77  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3032 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: CAC000912784  
 Gas Station: Not reported  
 Inspection Date: 08/10/95  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: CESAR BUSTAMANTE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DIAZ JUAN R  
 Property Address: 3030 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-1468

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**ADVANCE ENG TECH SERV INC (Continued)**

**S104752757**

2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

87

**M D S ENGINEERING INC**  
**3030 MAIN ST**  
**SAN DIEGO, CA 92113**

San Diego Co. HMMD S104745910  
 N/A

San Diego Co. HMMD:

Facility ID: 104329  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: CAD981426125  
 Gas Station: Not reported  
 Inspection Date: 08/17/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**M D S ENGINEERING INC (Continued)**

**S104745910**

Violation Notice Issued: Not reported  
 Facility Contact: DALE HOLTHAUS V P  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DIAZ JUAN R  
 Property Address: 3030 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**M D S ENGINEERING INC (Continued)**

**S104745910**

Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

88

**1345 S. 27TH ST.  
 SAN DIEGO, CA**

**CHMIRS S108402936  
 N/A**

CHMIRS:

OES Incident Number: 05-2635  
 OES notification: 5/3/200509:22:37 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2005

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S108402936

Agency:	Dept of Navy
Incident Date:	4/25/2005 12:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Unknown
Site Type:	Military Base
E Date:	Not reported
Substance:	Granular Activated Carbon
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A filter went through a shredder at recycling facility. There was a rain event during this time. It is unknown the amount, if any reached the environment.

88

**NAVY REGION SOUTHWEST**  
**1345 S 27TH ST**  
**SAN DIEGO, CA 92113**

**HAZNET S108214736**  
**N/A**

HAZNET:

Gepaid:	CAC002589913
Contact:	ANDY YADVISH
Telephone:	6195456520
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 181470
Mailing City,St,Zip:	CORONADO, CA 92178
Gen County:	San Diego
TSD EPA ID:	CA7170090016
TSD County:	San Diego
Waste Category:	Other organic solids
Disposal Method:	Storage, Container
Tons:	16.85
Facility County:	Not reported



MAP FINDINGS

Map ID Direction Distance Distance (ft.) Site Database(s) EPA ID Number EDR ID Number

88 **IMS RECYCLING SERVICES INC** RCRA-SQG 1000129619  
**1345 SOUTH 27TH ST** FINDS CAD029136058  
**SAN DIEGO, CA 92113** HAZNET  
LUST  
Cortese  
San Diego Co. HMMD  
CERC-NFRAP  
SWRCY  
SWEEPS UST  
SAN DIEGO CO. SAM

RCRA-SQG:

Date form received by agency: 09/01/1996  
Facility name: IMS RECYCLING SERVICES INC  
Facility address: 1345 SOUTH 27TH ST  
SAN DIEGO, CA 92113  
EPA ID: CAD029136058  
Contact: Not reported  
Contact address: Not reported  
Not reported  
Contact country: Not reported  
Contact telephone: Not reported  
Contact email: Not reported  
EPA Region: 09  
Land type: Facility is not located on Indian land. Additional information is not known.  
Classification: Small Small Quantity Generator  
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
Owner/operator address: NOT REQUIRED  
NOT REQUIRED, ME 99999  
Owner/operator country: Not reported  
Owner/operator telephone: (415) 555-1212  
Legal status: Private  
Owner/Operator Type: Owner  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
Owner/operator address: NOT REQUIRED  
NOT REQUIRED, ME 99999  
Owner/operator country: Not reported  
Owner/operator telephone: (415) 555-1212  
Legal status: Private  
Owner/Operator Type: Operator  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
Mixed waste (haz. and radioactive): Unknown  
Recycler of hazardous waste: No  
Transporter of hazardous waste: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 02/16/1982  
 Facility name: IMS RECYCLING SERVICES INC  
 Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 12/18/2001  
 Date achieved compliance: 12/20/2001  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/19/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 12/18/2001  
 Evaluation: FOCUSED COMPLIANCE INSPECTION  
 Area of violation: Generators - General  
 Date achieved compliance: 12/20/2001  
 Evaluation lead agency: State

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD029136058  
 Contact: IMS RECYCLING SVS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 5.7140  
 Facility County: San Diego

Gepaid: CAD029136058  
 Contact: IMS RECYCLING SVS  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 5.8380  
 Facility County: San Diego

Gepaid: CAD029136058  
 Contact: IMS RECYCLING SVS  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 5.4210  
 Facility County: San Diego

Gepaid: CAD029136058  
 Contact: STEVE ADLER/GENERAL MANAGER  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Not reported  
 Tons: 4.12  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Gepaid: CAD029136058  
 Contact: JOSH WAGNER/OPERATIONS MANAGER  
 Telephone: 6192312521  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13666  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: AZR000030452  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: 3.44  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 15 additional CA\_HAZNET: record(s) in the EDR Site Report.

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300482  
 Stop Date: 1990-03-13 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-05-23 00:00:00  
 Discover Date: 1990-03-13 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-04-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: GEORGE STEINHAUER  
 RP Address: 1345 S 27TH ST  
 Interim: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: ML  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21211-001  
 Case Number: 9UT1667  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT1667  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: Not reported  
 Date Found: 03/13/1990  
 How Found: Tank Closure  
 Date Stopped: 03/13/1990  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 04/12/1990  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/20/91  
 Pilot Program: LOP  
 Local Case: H21211-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 04/11/1990  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 1345 27TH ST S

San Diego Co. HMMD:  
 Facility ID: 121211  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1345 S 27TH ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAD029136058  
 Gas Station: Not reported  
 Inspection Date: 11/06/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: MARCELLINO FERNANDEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SCRAP METALS INC  
 Property Address: 1345 S 27TH ST  
 Property City,St,Zip: 92113  
 Tank Owner: INDUSTRIAL METALS & SALVAGE CO  
 Tank Address: 1345 S 27TH ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/06/05  
 Facility Phone: 619-231-2521

HMMD DISCLOSURE INVENTORY:  
 Item Number: OX57  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR56  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: 00002  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 00003  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: 00004  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T005  
 Tank ID Number: 00005  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/17/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2075  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/17/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2076

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 06/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5377

Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 06/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 5378

Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 06/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 5379

Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 06/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5380

Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 11/06/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0213  
 Occurrences: Not reported  
 Item Number: 4511

Violation Desc: CONTAINER INCOMPATIBLE W/ WASTE

**HMMD WASTE STREAMS:**

Inspection Date: 11/06/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 7500  
 Quantity String: 7500  
 Annual Qty: 7500  
 Annual Qty String: 7500  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: DROSS FROM MEXICO VARIOUS  
 Carcinogen: No

Inspection Date: 11/06/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Qty at Inspection: 450  
 Quantity String: 450  
 Annual Qty: 800  
 Annual Qty String: 800  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: H2O SOLUBLE OIL  
 Carcinogen: No

Inspection Date: 11/06/03  
 Waste Item #: 860  
 Waste Code: 860  
 Waste Name: UNIVERSAL WASTE CRTS  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 506576  
 Annual Qty String: 506576  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: UNKNOWN  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: CRTS  
 Carcinogen: No

**CERC-NFRAP:**

Site ID: 0904768  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

**CERCLIS-NFRAP Site Contact Name(s):**

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

**CERCLIS-NFRAP Assessment History:**

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/08/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 08/31/1993  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Date Completed: 08/31/1993  
 Priority Level: NFRAP (No Further Remedial Action Planned)

SWRCY:

Certification Status: O  
 Facility Phone Number: (619) 231-2521  
 Date facility became certified: 09/09/87  
 Date facility began operating: 01/01/61  
 Date facility ceased operating: Still operating  
 Whether The Facility Is Grandfathered: Not reported  
 Convenience Zone Where Facility Located: 0  
 Convenience Zone Where Facility Located 2: 0  
 Convenience Zone Where Facility Located 3: 0  
 Convenience Zone Where Facility Located 4: 0  
 Convenience Zone Where Facility Located 5: 0  
 Convenience Zone Where Facility Located 6: 0  
 Convenience Zone Where Facility Located 7: 0  
 Aluminum Beverage Containers Redeemed: AL  
 Glass Beverage Containers Redeemed: GL  
 Plastic Beverage Containers Redeemed: PL  
 Other mat beverage containers redeemed: OB  
 Refillable Beverage Containers Redeemed: Not reported

SWEEPS UST:

Status: Not reported  
 Comp Number: 21211  
 Number: Not reported  
 Board Of Equalization: 44-022486  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021211-000001  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 5

Status: Not reported  
 Comp Number: 21211  
 Number: Not reported  
 Board Of Equalization: 44-022486  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021211-000002  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 21211  
 Number: Not reported  
 Board Of Equalization: 44-022486  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021211-000003  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 21211  
 Number: Not reported  
 Board Of Equalization: 44-022486  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021211-000004  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: OIL  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 21211  
 Number: Not reported  
 Board Of Equalization: 44-022486  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021211-000005  
 Actv Date: Not reported  
 Capacity: 1500  
 Tank Use: PETROLEUM  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H21211-001  
 Agency: DEH Site Assessment & Mitigation  
 Funding: **LOP - State Fund**

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

**IMS RECYCLING SERVICES INC (Continued)**

**1000129619**

FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/23/1991  
 Begandt: 3/13/1990

**88**

**IMS RECYCLING SERVICES  
 1345 SO. 27TH ST.  
 SAN DIEGO, CA 92113**

**CA WDS S106105483  
 N/A**

CA WDS:

Facility ID: San Diego 371007237  
 Facility Type: Not reported  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: IMS RECYCLING SERVICES INC  
 Agency Address: 1345 S. 27TH ST.  
 Agency City,St,Zip: SAN DIEGO 92113  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.  
 Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

88

CHMIRS S105658846  
 N/A

**1300 SOUTH 28TH STREET  
 SAN DIEGO, CA 92123**

CHMIRS:

OES Incident Number: 99-5056  
 OES notification: 11/29/199903:12:21 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1999  
 Agency: City of San Diego  
 Incident Date: 11/29/199912:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Road

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**(Continued)**

**S105658846**

E Date: Not reported  
 Substance: Raw Sewage  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 7700  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: Stop on a 12" main. Recovered 3500 gals.

**88**

**THE SICKLES GROUP  
 2795 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S100733029  
 N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303166  
 Stop Date: 1988-03-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-05-28 00:00:00  
 Discover Date: 1988-03-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-03-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SICKLES GROUP (Continued)**

**S100733029**

County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: MARK MCLAREN  
 RP Address: 6305 LUSK BLVD.  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H24682-001  
 Case Number: 9UT924  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT924  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 03/24/1988  
 How Found: Tank Closure  
 Date Stopped: 03/24/1988  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: 03/24/1988  
 Submit Workplan: Not reported  
 Prelim Assess: 03/24/1988  
 Desc Pollution: Not reported  
 Remed Plan: / /

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SICKLES GROUP (Continued)**

**S100733029**

Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 3/25/88  
 Closed Date: 5/28/93  
 Pilot Program: LOP  
 Local Case: H24682-001  
 Basin Number: 908.22  
 Gwater Depth: 24'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 2  
 File Dispn: File discarded, case closed  
 Release Date: 03/24/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2795 MAIN ST

San Diego Co. HMMMD:

Facility ID: 124682  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 4275 EXECUTIVE SQ #  
 Mailing City,St,Zip: LA JOLLA, CA 92037  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: AHADIAN FAMILY TRUST 04-05-04  
 Property Address: 13993 CRYSTAL GROVE  
 Property City,St,Zip: 92130  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported



MAP FINDINGS

Map ID  
Direction  
Distance  
Distance (ft.)Site

EDR ID Number  
EPA ID Number

Database(s)

**THE SICKLES GROUP (Continued)**

**S100733029**

Facility Phone: 858-458-1179

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
Chemical Name: Not reported  
Case Number: Not reported  
Quantity Stored At One Time: Not reported  
Quantity Stored at One Time: Not reported  
Annual Quantity String: Not reported  
Annual Quantity String: Not reported  
Measurement Units: Not reported  
Carcinogen: No  
1st Hazard Category: Not reported  
2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
Tank ID Number: 1  
Waste or Product: Not reported  
Tank Contents: REGULAR UNLEADED

Tank Number: T002  
Tank ID Number: 2  
Waste or Product: Not reported  
Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
Waste Code: Not reported  
Type of Violation: Not reported  
Occurrences: Not reported  
Item Number: Not reported  
Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
Waste Item #: Not reported  
Waste Code: Not reported  
Waste Name: Not reported  
Qty at Inspection: Not reported  
Quantity String: Not reported  
Annual Qty: Not reported  
Annual Qty String: Not reported  
Measurement Unit: Not reported  
Treatment Method: Not reported  
Storage Method: Not reported  
Haz Waste Hauler: Not reported  
Waste Desc: Not reported  
Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
Comp Number: 24682  
Number: Not reported  
Board Of Equalization: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THE SICKLES GROUP (Continued)**

**S100733029**

Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-024682-000001  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 24682  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-024682-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 24682  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H24682-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/28/1993  
 Begandt: 3/24/1988

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**88 VCA MAIN ST ANIMAL HOSPITAL  
 2773 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104757645  
 N/A**

San Diego Co. HMMD:

Facility ID: 150305  
 Inactive Indicator: Active  
 Business Code: 6HK12  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2773 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000076078  
 Gas Station: Not reported  
 Inspection Date: 07/07/03  
 Reinspection Date: Not reported  
 Inspector Name: MNYAGA  
 Violation Notice Issued: Not reported  
 Facility Contact: MICHAEL J. KELLEY, DVM  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MULLIGAN THOMAS W FAMILY TRUST  
 Property Address: 2773 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/07/05  
 Facility Phone: 619-232-7401

HMMD DISCLOSURE INVENTORY:

Item Number: OX00  
 Chemical Name: OXYGEN GAS OXYGEN GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

VCA MAIN ST ANIMAL HOSPITAL (Continued)

S104757645

HMMD VIOLATIONS:

Inspection Date: 03/14/95  
 Waste Code: Not reported  
 Type of Violation: 6HX0064  
 Occurrences: Not reported  
 Item Number: 2014  
 Violation Desc: QC DOC NOT MAINTAINED FOR ONSITE TREATME

Inspection Date: 03/14/95  
 Waste Code: Not reported  
 Type of Violation: 6HX4008  
 Occurrences: Not reported  
 Item Number: 2015  
 Violation Desc: MEDWASTE CONTAINER IMPROP LABELED

Inspection Date: 03/15/01  
 Waste Code: Not reported  
 Type of Violation: 6HV4251  
 Occurrences: Not reported  
 Item Number: 3186  
 Violation Desc: IMPROPER TREATMENT OF MEDWASTE

Inspection Date: 03/15/01  
 Waste Code: Not reported  
 Type of Violation: 6HV4252  
 Occurrences: Not reported  
 Item Number: 3187  
 Violation Desc: NO AUTOCLAVE WRITTEN PROCEDURE

Inspection Date: 03/15/01  
 Waste Code: Not reported  
 Type of Violation: 6HV4253  
 Occurrences: Not reported  
 Item Number: 3188  
 Violation Desc: THERMOM: NO ANNUAL CALIBRATION

Inspection Date: 03/15/01  
 Waste Code: Not reported  
 Type of Violation: 6HV4258  
 Occurrences: Not reported  
 Item Number: 3189  
 Violation Desc: TREATMENT: NO RECORDS ONSITE

HMMD WASTE STREAMS:

Inspection Date: 07/07/03  
 Waste Item #: 541  
 Waste Code: 541  
 Waste Name: PHOTOCHEM/PHOTOPROC  
 Qty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 3141 FREEDOM IMAGING INC.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VCA MAIN ST ANIMAL HOSPITAL (Continued)**

**S104757645**

Waste Desc: Not reported  
 Carcinogen: No  
  
 Inspection Date: 07/07/03  
 Waste Item #: 901  
 Waste Code: 901  
 Waste Name: INFECTIOUS WASTE, GE  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 50  
 Annual Qty String: 50  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BAG  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 07/07/03  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BOX  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: Not reported  
 Carcinogen: No

88

**EVERINGHAM BROS BAIT CO**  
**2750 MAIN ST**  
**SAN DIEGO, CA 92113**

**HAZNET S108206371**  
**N/A**

HAZNET:

Gepaid: CAL000153790  
 Contact: ROY EVERINGHAM/PRESIDENT  
 Telephone: 6196966673  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 2449  
 Mailing City,St,Zip: LA MESA, CA 919432449  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Transfer Station  
 Tons: 0.2  
 Facility County: Not reported

Gepaid: CAL000153790  
 Contact: ROY EVERINGHAM/PRESIDENT  
 Telephone: 6196966673  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**EVERINGHAM BROS BAIT CO (Continued)**

**S108206371**

Mailing Name: Not reported  
Mailing Address: PO BOX 2449  
Mailing City,St,Zip: LA MESA, CA 919432449  
Gen County: San Diego  
TSD EPA ID: CAD028409019  
TSD County: Los Angeles  
Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
Disposal Method: Transfer Station  
Tons: 0.04  
Facility County: San Diego

**88**

**PACIFIC TANK CLEANING SVCS INC  
2734 MAIN ST  
SAN DIEGO, CA 92113**

**FINDS 1001115531  
HAZNET CAR000014670  
San Diego Co. HMMD  
RCRA-CESQG**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000014670  
Contact: DAVE BECHTEL/ ENVIRO MGR  
Telephone: 6192350970  
Facility Addr2: Not reported  
Mailing Name: Not reported  
Mailing Address: PO BOX 13528  
Mailing City,St,Zip: SAN DIEGO, CA 921700000  
Gen County: San Diego  
TSD EPA ID: CAT080013352  
TSD County: Los Angeles  
Waste Category: Unspecified oil-containing waste  
Disposal Method: Recycler  
Tons: 1.25  
Facility County: Not reported

Gepaid: CAR000014670  
Contact: RICARDO BEAS  
Telephone: 6192350970  
Facility Addr2: Not reported  
Mailing Name: Not reported  
Mailing Address: PO BOX 1267  
Mailing City,St,Zip: NATIONAL CITY, CA 919511267  
Gen County: San Diego  
TSD EPA ID: CAD097030993  
TSD County: Los Angeles  
Waste Category: Other organic solids  
Disposal Method: Disposal, Other  
Tons: .3000  
Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TANK CLEANING SVCS INC (Continued)**

**1001115531**

Gepaid: CAR000014670  
 Contact: RICARDO BEAS  
 Telephone: 6192350970  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 1267  
 Mailing City,St,Zip: NATIONAL CITY, CA 919511267  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: 0.2  
 Facility County: San Diego

Gepaid: CAR000014670  
 Contact: RICARDO BEAS  
 Telephone: 6192350970  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 1267  
 Mailing City,St,Zip: NATIONAL CITY, CA 919511267  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 115.509  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMMD:

Facility ID: 137021  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: JORGE LUQUIN  
 Mailing Address: PO BOX 13528  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000017529  
 Gas Station: Not reported  
 Inspection Date: 11/17/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ELMER MORENO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TANK CLEANING SVCS INC (Continued)**

**1001115531**

Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: C C C H  
 Property Address: 5216 NARANJA ST  
 Property City,St,Zip: 92114  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/17/05  
 Facility Phone: 619-235-0970

**HMMD DISCLOSURE INVENTORY:**

Item Number: OX81  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 6100  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6101  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 6102  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: 11/17/03  
 Waste Item #: 221



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC TANK CLEANING SVCS INC (Continued)**

**1001115531**

Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 11/17/03  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 400  
 Quantity String: 400  
 Annual Qty: 800  
 Annual Qty String: 800  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2804 ENVIROSERV  
 Waste Desc: OILY DEBRIS/RAGS  
 Carcinogen: No

Inspection Date: 11/17/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 120  
 Quantity String: 120  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: BATTERIES  
 Carcinogen: No

Inspection Date: 11/17/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TANK CLEANING SVCS INC (Continued)**

**1001115531**

RCRA-CESQG:

Date form received by agency: 01/17/1997  
 Facility name: PACIFIC TANK CLEANING SVCS INC  
 Facility address: 2734 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000014670  
 Mailing address: PO BOX 13528  
 SAN DIEGO, CA 92170  
 Contact: RICARDO BEAS  
 Contact address: PO BOX 13528  
 SAN DIEGO, CA 92170  
 Contact country: US  
 Contact telephone: (619) 235-0970  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Private  
 Classification: Conditionally Exempt Small Quantity Generator  
 Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: RICARDO BEAS  
 Owner/operator address: 816 LA HUERTA WY  
 SAN DIEGO, CA 92154  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 662-2960  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC TANK CLEANING SVCS INC (Continued)**

**1001115531**

Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Transporters - General  
 Date violation determined: 09/18/2001  
 Date achieved compliance: 09/18/2001  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 09/18/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 09/18/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Transporters - General  
 Date achieved compliance: 09/18/2001  
 Evaluation lead agency: State

88

**BRITISH MOTORS  
 2720 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S104573620  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAC002244377  
 Contact: ALFONSO MAGALLANES  
 Telephone: 6195440999  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2720 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: 0.2293  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 123081  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2720 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BRITISH MOTORS (Continued)**

**S104573620**

Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000032768  
 Gas Station: Not reported  
 Inspection Date: 10/24/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: ALFONSO MAGALLANES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: HARDIE GILBERT S&ISABEL B TRUS  
 Property Address: C/O ANTHONY L BEDFOR  
 Property City,St,Zip: 92115  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/24/05  
 Facility Phone: 619-544-0999

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/20/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 5703  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 07/20/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BRITISH MOTORS (Continued)**

**S104573620**

Item Number:	5704
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	07/20/98
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	5705
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	07/20/98
Waste Code:	Not reported
Type of Violation:	6HV0405
Occurrences:	Not reported
Item Number:	5706
Violation Desc:	AISLE SPACE IS OBSTRUCTED
Inspection Date:	07/20/98
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	5707
Violation Desc:	HMBP NOT ESTABLISHED/IMPLEMENTED.
Inspection Date:	07/20/98
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	5708
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	12/06/99
Waste Code:	Not reported
Type of Violation:	6HX0108
Occurrences:	Not reported
Item Number:	0859
Violation Desc:	NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE
Inspection Date:	12/06/99
Waste Code:	Not reported
Type of Violation:	6HV0209
Occurrences:	Not reported
Item Number:	0860
Violation Desc:	WASTE ONSITE >90/180/270 DAYS
Inspection Date:	12/06/99
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	0861
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	12/06/99
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	0862

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BRITISH MOTORS (Continued)**

**S104573620**

Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/06/99  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 0863  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5515  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 5516  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 10/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5665  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 5666  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 10/24/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5667  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

**HMMD WASTE STREAMS:**

Inspection Date: 10/24/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 16  
 Quantity String: 16  
 Annual Qty: 86  
 Annual Qty String: 86  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 1406 SAFETY-KLEEN

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BRITISH MOTORS (Continued)**

**S104573620**

Waste Desc:	Not reported
Carcinogen:	No
Inspection Date:	10/24/03
Waste Item #:	221
Waste Code:	221
Waste Name:	WASTE OIL & MIXED OI
Qty at Inspection:	165
Quantity String:	165
Annual Qty:	260
Annual Qty String:	260
Measurement Unit:	GAL
Treatment Method:	001 RECYCLE
Storage Method:	METAL DRUM
Haz Waste Hauler:	0015 ASBURY ENVIR. SERVIC
Waste Desc:	130 GAL 7/98 ER (ONSITE)
Carcinogen:	No
Inspection Date:	10/24/03
Waste Item #:	444
Waste Code:	444
Waste Name:	USED BATTERIES
Qty at Inspection:	100
Quantity String:	100
Annual Qty:	100
Annual Qty String:	100
Measurement Unit:	LBS
Treatment Method:	444 BATTERIES RECYCL
Storage Method:	BOX
Haz Waste Hauler:	9997 UNREGISTERED HAZ WST
Waste Desc:	INTERSTATE
Carcinogen:	No
Inspection Date:	10/24/03
Waste Item #:	888
Waste Code:	888
Waste Name:	USED OIL FILTERS
Qty at Inspection:	100
Quantity String:	100
Annual Qty:	100
Annual Qty String:	100
Measurement Unit:	LBS
Treatment Method:	888 FILTERS/METAL RE
Storage Method:	METAL DRUM
Haz Waste Hauler:	0015 ASBURY ENVIR. SERVIC
Waste Desc:	Not reported
Carcinogen:	No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**88**      **MARKEL-JOHNSON POULTRY CO., IN**  
**2697 MAIN ST**  
**SAN DIEGO, CA 92113**

**HIST UST**      **U001572989**  
**N/A**

HIST UST:  
 Region:                    STATE  
 Facility ID:                00000067747  
 Facility Type:             Other  
 Other Type:                WHSLE. MEAT DIST.  
 Total Tanks:              0001  
 Contact Name:             ROBERT L. VANDENBERG  
 Telephone:                6192337303  
 Owner Name:                MARKEL-JOHNSON POULTRY CO., IN  
 Owner Address:            2697 MAIN STREET  
 Owner City,St,Zip:      SAN DIEGO, CA 92113

Tank Num:                 001  
 Container Num:            1  
 Year Installed:            Not reported  
 Tank Capacity:            00000000  
 Tank Used for:            WASTE  
 Type of Fuel:             2  
 Tank Construction:        Unkown centimeters  
 Leak Detection:            None

**88**      **MARKEL OHNSON**  
**2697 MAIN ST**  
**SAN DIEGO, CA 92113**

**HAZNET**      **S100726063**  
**LUST**            **N/A**  
**Cortese**  
**San Diego Co. HMMD**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

HAZNET:  
 Gepaid:                    CAC001036040  
 Contact:                    MARKEL-JOHNSON POULTRY INC  
 Telephone:                6192962948  
 Facility Addr2:            Not reported  
 Mailing Name:             Not reported  
 Mailing Address:         4641 MASSACHUSETTS ST  
 Mailing City,St,Zip:    SAN DIEGO, CA 931160000  
 Gen County:                San Diego  
 TSD EPA ID:                CAT080013352  
 TSD County:                Los Angeles  
 Waste Category:          Unspecified oil-containing waste  
 Disposal Method:         Recycler  
 Tons:                        1.2510  
 Facility County:            San Diego

LUST:  
 Region:                    STATE  
 Case Type:                 Soil only  
 Cross Street:             Not reported  
 Enf Type:                  Not reported  
 Funding:                   Not reported  
 How Discovered:         Not reported  
 How Stopped:             Not reported  
 Leak Cause:                Not reported  
 Leak Source:              Not reported  
 Global Id:                  T0607301872



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARKEL OHNSON (Continued)**

**S100726063**

Stop Date: 1995-06-20 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1995-10-05 00:00:00  
 Discover Date: 1995-06-20 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1995-06-20 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: PAUL MARKEL, JR  
 RP Address: 5092 PRINCETON AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02891-001  
 Case Number: 9UT3106  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

LUST:

Region: 9  
 Case Number: 9UT3106

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARKEL OHNSON (Continued)**

**S100726063**

Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 06/20/1995  
 How Found: Not reported  
 Date Stopped: 06/20/1995  
 How Stopped: Remove Contents  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 06/20/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 9/8/95  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 10/5/95  
 Pilot Program: LOP  
 Local Case: H02891-001  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 06/20/1995  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 2697 MAIN ST

**San Diego Co. HMMD:**

Facility ID: 102891  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2697 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARKEL OHNSON (Continued)**

**S100726063**

Inspection Date: 08/16/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS MILAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: I M S RECYCLING SERVICES INC  
 Property Address: P O BOX 13666  
 Property City,St,Zip: 92170  
 Tank Owner: PAUL C MARKEL  
 Tank Address: 4641 MASSACHUSETTS  
 Tank City,St,Zip: San Diego, CA 92116  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-7303

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: AT3459  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 01/10/91  
 Waste Code: Not reported  
 Type of Violation: 6HX0010  
 Occurrences: Not reported  
 Item Number: 7647  
 Violation Desc: BUS. PLAN NOT COMPLETE/CURRENT/ON SITE

Inspection Date: 01/10/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 7648

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARKEL OHNSON (Continued)**

**S100726063**

Violation Desc:	TRAINING PROGRAM NOT ADEQUATE
Inspection Date:	01/10/91
Waste Code:	Not reported
Type of Violation:	6HX3003
Occurrences:	Not reported
Item Number:	7649
Violation Desc:	MONITORING SYTEM NOT TESTED ANNUALLY
Inspection Date:	02/26/92
Waste Code:	Not reported
Type of Violation:	6HX3003
Occurrences:	Not reported
Item Number:	8320
Violation Desc:	MONITORING SYTEM NOT TESTED ANNUALLY
Inspection Date:	08/16/93
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	9751
Violation Desc:	HMBP NOT ESTABISHED/IMPLEMENTED.
Inspection Date:	08/16/93
Waste Code:	Not reported
Type of Violation:	6HV1004
Occurrences:	Not reported
Item Number:	9752
Violation Desc:	HMBP NOT SUBMITTED TO HMD
Inspection Date:	08/16/93
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	9753
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	08/16/93
Waste Code:	Not reported
Type of Violation:	6HX3013
Occurrences:	Not reported
Item Number:	9754
Violation Desc:	NO FINANCIAL RESPOSIBILITY DOC
Inspection Date:	08/16/93
Waste Code:	Not reported
Type of Violation:	6HX3001
Occurrences:	Not reported
Item Number:	9755
Violation Desc:	UST RECORDS NOT MAINTAINED ONSITE
Inspection Date:	08/16/93
Waste Code:	Not reported
Type of Violation:	6HX3017
Occurrences:	Not reported
Item Number:	9756
Violation Desc:	TANK GAUGING NOT PROPERLY DONE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARKEL OHNSON (Continued)**

**S100726063**

Inspection Date: 08/16/93  
 Waste Code: Not reported  
 Type of Violation: 6HV3018  
 Occurrences: Not reported  
 Item Number: 9757  
 Violation Desc: IMPROPER INVENTORY RECONCILIATION

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 2891  
 Number: 9  
 Board Of Equalization: 44-021751  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002891-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H02891-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 10/5/1995  
 Begandt: 6/20/1995

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**88 VINCENT DESIGN  
 2694 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S105112865  
 N/A**

San Diego Co. HMMD:

Facility ID:	112608
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	2694 MAIN ST
Mailing City, St, Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	50
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	02/26/04
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	BRIAN LINN
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	LINN BRIAN V
Property Address:	2694 MAIN ST
Property City, St, Zip:	92113
Tank Owner:	ALDA M. LULUE & GLORIA GIOLZET
Tank Address:	2306 N HOPKINS ST
Tank City, St, Zip:	San Diego, CA 92139
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	08/26/05
Facility Phone:	619-233-7224

HMMD DISCLOSURE INVENTORY:

Item Number:	AR32
Chemical Name:	ARGON 75%, C02 25%: COMPRESSED GASES
Case Number:	7440-37-1
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	PRESSURE RELEASE
2nd Hazard Category:	Not reported
Item Number:	CA33
Chemical Name:	CARBON DIOXIDE COMPRESSED GAS
Case Number:	124-38-9
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**VINCENT DESIGN (Continued)**

**S105112865**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: I  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: II  
 Waste or Product: Not reported  
 Tank Contents: AVIATION FUEL

Tank Number: T003  
 Tank ID Number: III  
 Waste or Product: Not reported  
 Tank Contents: AVIATION FUEL

Tank Number: T004  
 Tank ID Number: 004  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T005  
 Tank ID Number: 005  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 03/10/97  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 6304  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 03/10/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 6305  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/10/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6306  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/23/98  
 Waste Code: Not reported  
 Type of Violation: 6HX0108

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**VINCENT DESIGN (Continued)**

**S105112865**

Occurrences: Not reported  
 Item Number: 3232  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 04/23/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 3233  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 04/23/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 3234  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 04/23/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3235  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/23/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3236  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 06/04/01  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 6278  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 09/24/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2454  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/26/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1011  
 Occurrences: Not reported  
 Item Number: 9066  
 Violation Desc: TRAINING RECORDS NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VINCENT DESIGN (Continued)**

**S105112865**

Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

88

**EDDIE'S VOLKSWAGEN & FOREIGN R  
 2694 MAIN ST  
 SAN DIEGO, CA 92113**

**HIST UST 1000249635  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000059527  
 Facility Type: Other  
 Other Type: AUTO REPAIR  
 Total Tanks: 0003  
 Contact Name: EDDIE BLEA  
 Telephone: 6192321604  
 Owner Name: ALDA M. LULUE & GLORIA GIOLZET  
 Owner Address: 2306 HOPPKINS ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92139

Tank Num: 001  
 Container Num: I  
 Year Installed: Not reported  
 Tank Capacity: 00000300  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 002  
 Container Num: II  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: 06  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 003  
 Container Num: III  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: 06  
 Tank Construction: Not reported  
 Leak Detection: None

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EPA ID Number  
 EDR ID Number

88      **J J AUTO BODY**      **SAN DIEGO CO. SAM**      **S108407092**  
**2694 MAIN ST**      **N/A**  
**SAN DIEGO, CA 92113**

SAN DIEGO CO. SAM:  
 Case Number: H12608-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/26/1989  
 Begandt: 3/3/1986

88      **GIOLZETTI AND LULUE**      **LUST**      **S102430792**  
**2694 MAIN ST**      **Cortese**      **N/A**  
**SAN DIEGO, CA 92113**      **SWEEPS UST**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302367  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-05-26 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: GLORIA GIOLZETTI  
 RP Address: 6383 MURRAY PARK CT  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GIOLZETTI AND LULUE (Continued)**

**S102430792**

MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: FA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H12608-001  
 Case Number: 9UT360  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT360  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 02/28/1986  
 How Found: Tank Closure  
 Date Stopped: 02/28/1986  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 03/03/1986  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: 03/19/1987  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/26/89  
 Pilot Program: LOP  
 Local Case: H12608-001  
 Basin Number: 908.22  
 Gwater Depth: 24'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 03/03/1986

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GIOLZETTI AND LULUE (Continued)**

**S102430792**

Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 2694 MAIN ST

SWEEPS UST:

Status: Not reported  
 Comp Number: 12608  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012608-000001  
 Actv Date: Not reported  
 Capacity: 300  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 5

Status: Not reported  
 Comp Number: 12608  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012608-000002  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: AVIA. GAS  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 12608  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012608-000003  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GIOLZETTI AND LULUE (Continued)**

**S102430792**

Stg:	PRODUCT
Content:	AVIA. GAS
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	12608
Number:	Not reported
Board Of Equalization:	Not reported
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-012608-000004
Actv Date:	Not reported
Capacity:	550
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	12608
Number:	Not reported
Board Of Equalization:	Not reported
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-012608-000005
Actv Date:	Not reported
Capacity:	550
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	A
Comp Number:	12608
Number:	9
Board Of Equalization:	Not reported
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-012608-000008
Actv Date:	Not reported
Capacity:	8000
Tank Use:	M.V. FUEL
Stg:	P
Content:	LEADED
Number Of Tanks:	3
Status:	A
Comp Number:	12608

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GIOLZETTI AND LULUE (Continued)**

**S102430792**

Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012608-000009  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 12608  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-012608-000010  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

88

**ABLE AUTO WRECKING  
 2704 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S104747593  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAL000102564  
 Contact: KAMRAN DIBA  
 Telephone: 6192337276  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2704 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 0.37  
 Facility County: Not reported

San Diego Co. HMMD:

Facility ID: 112968  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABLE AUTO WRECKING (Continued)**

**S104747593**

Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2704 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: CAL000102564  
 Gas Station: Not reported  
 Inspection Date: 08/04/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: KAMRAN DIBA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MARANTZ SPERANZA T TRUST 04-27  
 Property Address: 1054 BANBURY DR  
 Property City,St,Zip: 92544  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-7276

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 06/09/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 4434  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ABLE AUTO WRECKING (Continued)**

**S104747593**

Inspection Date: 11/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 0298  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 0299  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 11/21/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1532  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 11/21/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 1533  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/21/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1534  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 11/21/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 1535  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 08/04/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2926  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABLE AUTO WRECKING (Continued)**

**S104747593**

Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203720  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2704 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/02/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MEHDI (MIKE) PATTARI  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MARANTZ SPERANZA T TRUST 04-27  
 Property Address: 1054 BANBURY DR  
 Property City,St,Zip: 92544  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/02/06  
 Facility Phone: 619-233-7276

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABLE AUTO WRECKING (Continued)**

**S104747593**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 07/02/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 660  
 Annual Qty String: 660  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 07/02/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 30  
 Annual Qty String: 30  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: OILY ABSORBENT  
 Carcinogen: No

Inspection Date: 07/02/04  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABLE AUTO WRECKING (Continued)**

**S104747593**

Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: ANTIFREEZE  
 Carcinogen: No

Inspection Date: 07/02/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 2400  
 Annual Qty String: 2400  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: SUNCOAST BATTERY  
 Carcinogen: No

Facility ID: 204635  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 2704 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 50  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MARANTZ SPERANZA T TRUST 04-27  
 Property Address: 1054 BANBURY DR  
 Property City,St,Zip: 92544  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-7276

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ABLE AUTO WRECKING (Continued)**

**S104747593**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

89

**CHEVRON PIPELINE RUPTURE  
 BELT STREET / SICARD STREET (NO PHYSIC  
 SAN DIEGO, CA**

**SLIC S106485387  
 N/A**

**SLIC:**

Region: STATE  
 Global Id: SL607392791  
 Assigned Name: SLICSITE  
 Lead Agency Contact: Not reported  
 Lead Agency: Not reported  
 Lead Agency Case Number: Not reported  
 Responsible Party: Not reported  
 Recent Dtw: Not reported  
 Substance Released: Not reported  
**Facility Status: Not reported**

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Distance (ft.)Site Database(s) EPA ID Number

90 AMERICAN MARINE DECKING SYSTEMS INC HAZNET S100726740  
 1531 RIGEL STREET N/A  
 SAN DIEGO, CA 92113

HAZNET:

Gepaid: CAL000121618  
 Contact: AMERICAN MARINE DECKING INC  
 Telephone: 6196969950  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1531 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133807  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Transfer Station  
 Tons: .4587  
 Facility County: San Diego

Gepaid: CAL000121618  
 Contact: AMERICAN MARINE DECKING INC  
 Telephone: 6196969950  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1531 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133807  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Not reported  
 Tons: .4587  
 Facility County: San Diego

Gepaid: CAL000121618  
 Contact: AMERICAN MARINE DECKING INC  
 Telephone: 6196969950  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1531 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133807  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Transfer Station  
 Tons: 0.2293  
 Facility County: San Diego

Gepaid: CAL000121618  
 Contact: AMERICAN MARINE DECKING INC  
 Telephone: 6196969950  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1531 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133807  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN MARINE DECKING SYSTEMS INC (Continued)**

**S100726740**

TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL000121618  
 Contact: AMERICAN MARINE DECKING INC  
 Telephone: 6196969950  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1531 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133807  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Not reported  
 Tons: .2293  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

90

**AMERICAN MARINE DECKING & COAT  
 1531 RIGEL ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106060435  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 104727  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 8734  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 03/05/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVEN RICHARDSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BILL LEONGS IMPORT-EXPORT LTD  
 Property Address: 5328 OAK PARK DR  
 Property City,St,Zip: 92105  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN MARINE DECKING & COAT (Continued)**

**S106060435**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-9950

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/04/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9818  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/04/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 9819  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

Inspection Date: 03/05/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1001  
 Occurrences: Not reported  
 Item Number: 7969  
 Violation Desc: NO UPF PERMIT FOR HAZMATS

Inspection Date: 03/05/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 7970  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN MARINE DECKING & COAT (Continued)**

**S106060435**

Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

90

**BILL LEONG'S IMPORT/EXPORT  
 1531 RIGEL ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 LUST  
 Cortese**

**S102363368  
 N/A**

**San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**HAZNET:**

Gepaid: CAC000976512  
 Contact: CHARLES LEONG  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: BILL LEONG,S IMPORT EXPORT  
 Mailing City,St,Zip: SAN DIEGO, CA 921050000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Treatment, Tank  
 Tons: .4170  
 Facility County: San Diego

**LUST:**

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607399250  
 Stop Date: 1994-05-24 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-07-06 00:00:00



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BILL LEONG'S IMPORT/EXPORT (Continued)**

**S102363368**

Discover Date: 1994-05-24 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1994-05-24 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: CHARLES LEONG  
 RP Address: 5328 OAK PARK DR  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04727-001  
 Case Number: 9UT4070  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT2825  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 05/24/1994  
 How Found: Tank Closure  
 Date Stopped: 05/24/1994  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BILL LEONG'S IMPORT/EXPORT (Continued)**

**S102363368**

Lead Agency: Local Agency  
 Case Type: Drinking Water Aquifer affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 07/26/1994  
 Submit Workplan: 8/10/94  
 Prelim Assess: 04/18/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 7/29/94  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H34376-001  
 Basin Number: 908.31  
 Gwater Depth: Not reported  
 Beneficial Use: MUNBU  
 NPDES Number: Not reported  
 priority: 1  
 File Dispn: Not reported  
 Release Date: 05/24/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT4070  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 05/24/1994  
 How Found: Tank Closure  
 Date Stopped: 05/24/1994  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 07/26/1994  
 Submit Workplan: Not reported  
 Prelim Assess: 07/26/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 7/29/94  
 Closed Date: 7/6/00  
 Pilot Program: LOP  
 Local Case: H04727-001  
 Basin Number: 908.22  
 Gwater Depth: 14  
 Beneficial Use: No Beneficial groundwater use

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BILL LEONG'S IMPORT/EXPORT (Continued)**

**S102363368**

NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 05/24/1994  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:

Facility ID: 134376  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1531 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: BILL LEONG  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BILL LEONGS IMPORT-EXPORT LTD  
 Property Address: 5328 OAK PARK DR  
 Property City,St,Zip: 92105  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-264-7978

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BILL LEONG'S IMPORT/EXPORT (Continued)**

**S102363368**

Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H04727-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 7/6/2000  
 Begandt: 5/24/1994

90

**NAVAL COATING INC  
 1505 RIGEL ST  
 SAN DIEGO, CA 92113**

**FINDS 1000455584  
 RCRA-NonGen CAD982431496**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL COATING INC (Continued)**

**1000455584**

corrective action activities required under RCRA.

RCRA-NonGen:

Date form received by agency: 02/24/1993  
 Facility name: NAVAL COATING INC  
 Facility address: 1505 RIGEL ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982431496  
 Contact: JULIA RAUKKO  
 Contact address: 1505 RIGEL ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 234-8366  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: State  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: CALTRANS  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: State  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

---

**NAVAL COATING INC (Continued)**

**1000455584**

Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

---

**91**      **TELEDYNE RYAN AERONAUTICAL**  
**2701 HARBOR DR**  
**SAN DIEGO, CA 92138**

**SLIC 1008190634**  
**HIST FTTS N/A**

**SLIC:**

Region: STATE  
Global Id: SL209054180  
Assigned Name: SLICSITE  
Lead Agency Contact: TOM ALO  
Lead Agency: SAN DIEGO RWQCB (REGION 9)  
Lead Agency Case Number: 2090500  
Responsible Party: EDGARD BERTAUT  
Recent Dtw: Not reported  
Substance Released: 376, MET, 39500, 39504, 39508, PCE, PCB, PAH, TCE, TPHD, TPHG, SUB024  
**Facility Status: Pollution Characterization**

**HIST FTTS:**

Case Number: Not reported  
Docket Number: 09-87-0010  
Complaint Issue Date: 12/22/1986  
Abatement Amount: 0.0000  
Proposed Penalty: 63000.0000  
Final Assessment: 48000.0000  
Final Order Date: 08/27/1987  
Close Date: / /  
Violations(s): PCB, Use  
PCB, Label or Marking  
PCB, Dispose  
PCB, Storage  
PCB, Failure to Maintain Records

**HIST FTTS INSP:**

Inspection Number: 1986092903379 1  
Region: 09  
Inspection Date: Not reported  
Inspector: SCHMIDT  
Violation occurred: Yes  
Investigation Type: Section 6 PCB Federal Conducted  
Investigation Reason: For Cause, Government  
Legislation Code: TSCA  
Facility Function: User

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**91 US COAST GUARD SECTOR  
 2710 HARBOR DR  
 SAN DIEGO, CA 92113**

**HAZNET S108223889  
 N/A**

HAZNET:

Gepaid: CAL000017096  
 Contact: GEORGE HATHAWAY FAC ENGINEER  
 Telephone: 6196836389  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Not reported  
 Tons: 0.16  
 Facility County: Not reported

Gepaid: CAL000017096  
 Contact: GEORGE HATHAWAY FAC ENGINEER  
 Telephone: 6196836389  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Not reported  
 Tons: 0.16  
 Facility County: Not reported

Gepaid: CAL000017096  
 Contact: GEORGE HATHAWAY FAC ENGINEER  
 Telephone: 6196836389  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921010000  
 Gen County: San Diego  
 TSD EPA ID: ARD981057870  
 TSD County: 99  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Not reported  
 Tons: 0.35  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

91 US COAST GUARD AIR STATION  
 2710 HARBOR DR  
 SAN DIEGO, CA 92101

HAZNET S100615726  
 LUST N/A  
 SWEEPS UST  
 SAN DIEGO CO. SAM

HAZNET:

Gepaid: CAL000017096  
 Contact: US COAST GUARD AIR STATION  
 Telephone: 6196836390  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: .2502  
 Facility County: San Diego

Gepaid: CAL000017096  
 Contact: US COAST GUARD AIR STATION  
 Telephone: 6196836390  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .0200  
 Facility County: San Diego

Gepaid: CAL000017096  
 Contact: US COAST GUARD AIR STATION  
 Telephone: 6196836390  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: .1500  
 Facility County: San Diego

Gepaid: CAL000017096  
 Contact: US COAST GUARD AIR STATION  
 Telephone: 6196836390  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**US COAST GUARD AIR STATION (Continued)**

**S100615726**

TSD EPA ID: AZC950823111  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 11.2091  
 Facility County: San Diego

Gepaid: CAL000017096  
 Contact: US COAST GUARD AIR STATION  
 Telephone: 6196836390  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2710 HARBOR DR  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: .1167  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 148 additional CA\_HAZNET: record(s) in the EDR Site Report.

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302982  
 Stop Date: 1988-08-22 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2001-04-19 00:00:00  
 Discover Date: 1988-08-22 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-08-22 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**US COAST GUARD AIR STATION (Continued)**

**S100615726**

Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Jet Fuel  
 Contact Person: Not reported  
 Responsible Party: J.H. DONAHUE  
 RP Address: 915 SECOND AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05335-002  
 Case Number: 9UT716  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608103383  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-07-10 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**US COAST GUARD AIR STATION (Continued)**

**S100615726**

MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MV  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05335-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608130862  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**US COAST GUARD AIR STATION (Continued)**

**S100615726**

Monitoring: Not reported  
 Close Date: 2001-04-19 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: R.S.CLARK; CIVENGUNIT, OAKLAND  
 RP Address: 2000 EMBARCADERO #200  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: EP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H05335-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 5335  
 Number: Not reported  
 Board Of Equalization: 44-012973  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**US COAST GUARD AIR STATION (Continued)**

**S100615726**

Swrcb Tank Id: 37-000-005335-000001  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 3

Status: Not reported  
 Comp Number: 5335  
 Number: Not reported  
 Board Of Equalization: 44-012973  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005335-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: AVIA. GAS  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 5335  
 Number: Not reported  
 Board Of Equalization: 44-012973  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005335-000003  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: AVIA. GAS  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 5335  
 Number: 9  
 Board Of Equalization: 44-012973  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005335-000008  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: JET FUEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**US COAST GUARD AIR STATION (Continued)**

**S100615726**

Number Of Tanks: 2  
 Status: A  
 Comp Number: 5335  
 Number: 9  
 Board Of Equalization: 44-012973  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-005335-000009  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: JET FUEL  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H05335-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 7/10/1987  
 Begandt: 1/23/1987

Case Number: H05335-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 4/19/2001  
 Begandt: 8/22/1988

Case Number: H05335-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 4/19/2001  
 Begandt: 1/1/1960

91

**U.S. COAST GUARD ACTIVITIES SA  
 2710 HARBOR DR  
 SAN DIEGO, CA 92101**

**San Diego Co. HMMD S106060490  
 N/A**

**San Diego Co. HMMD:**

Facility ID: 105335  
 Inactive Indicator: Active  
 Business Code: 6HK57  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: C/O FACILITIES ENGINEER  
 Mailing Address: 2710 N HARBOR DR

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Mailing City,St,Zip: SAN DIEGO, CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 38  
 EPA ID: CAL000017096  
 Gas Station: Not reported  
 Inspection Date: 12/09/04  
 Reinspection Date: Not reported  
 Inspector Name: LWIRSCHE  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVE HATHAWAY  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: NATIONAL STEEL&SHIPBUILDING CO  
 Property Address: P O BOX 85278  
 Property City,St,Zip: 92186  
 Tank Owner: UNITED STATES COAST GUARD ACTI  
 Tank Address: 2710 N HARBOR DRIVE  
 Tank City,St,Zip: San Diego, CA 92101  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 06/30/05  
 Facility Phone: 619-683-6389

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC91  
 Chemical Name: ACETYLENE ) TANKS CAS#7782447  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AI17  
 Chemical Name: AIRCRAFT CLEANING COMPOUND  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: AR96  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: DI92  
 Chemical Name: DIESEL (TWO TANKS)  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: GA94  
 Chemical Name: GASOLINE  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: HY90  
 Chemical Name: HYDRAULIC OILS  
 Case Number: 64742-54-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: JP78  
 Chemical Name: JP5 JET FUEL UNDERGROUND TANK 105335 T008  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: JP79  
 Chemical Name: JP5 JET FUEL UNDERGROUND TANK 105335 T009  
 Case Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: JP80  
 Chemical Name: JP5 JET FUEL UNDERGROUND TANK 105335 T010 JP 5 FUEL TANK  
 Case Number: 8008-20-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: JP81  
 Chemical Name: JP5 JET FUEL UNDERGROUND TANK 105335 T011 JP 5 FUEL TANK  
 Case Number: 8008-20-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: NI97  
 Chemical Name: NITROGEN  
 Case Number: 7727-37-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OX95  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Item Number: SA20  
 Chemical Name: SAFE D'ORANG, CLEANER/ DEGREASER/ DEODORIZER  
 Case Number: 9016-45-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: #1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: #2  
 Waste or Product: Not reported  
 Tank Contents: AVIATION FUEL

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: AVIATION FUEL

Tank Number: T008  
 Tank ID Number: 008 - J-3  
 Waste or Product: Not reported  
 Tank Contents: JET FUEL

Tank Number: T009  
 Tank ID Number: J-4 DISPEN  
 Waste or Product: Not reported  
 Tank Contents: JET FUEL

Tank Number: T010  
 Tank ID Number: J.1 STORAG  
 Waste or Product: Not reported  
 Tank Contents: JET FUEL

Tank Number: T011  
 Tank ID Number: J-2 STORAG  
 Waste or Product: Not reported  
 Tank Contents: JET FUEL

Tank Number: T012  
 Tank ID Number: 12 DIESEL  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T013  
 Tank ID Number: AT3601  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Tank Number: T014  
 Tank ID Number: AT3601  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T015  
 Tank ID Number: AT3601  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T016  
 Tank ID Number: AT3601  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T017  
 Tank ID Number: AT3601  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 03/07/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 6302  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/07/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6303  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 05/05/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3565  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/05/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3566  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 05/05/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 3567  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 05/20/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Waste Code: Not reported  
 Type of Violation: 6HV3112  
 Occurrences: Not reported  
 Item Number: 0378  
 Violation Desc: 2NDRY CONT TEST NOT DONE (6/36 MOS.)

Inspection Date: 05/20/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3113  
 Occurrences: Not reported  
 Item Number: 0379  
 Violation Desc: 2NDRY CONT TEST NOT SENT TO CUPA

Inspection Date: 05/20/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3601  
 Occurrences: Not reported  
 Item Number: 0380  
 Violation Desc: SWCSP: PIPING INT. TEST NOT DONE-3YRS

Inspection Date: 05/20/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3601  
 Occurrences: Not reported  
 Item Number: 0381  
 Violation Desc: SWCSP: PIPING INT. TEST NOT DONE-3YRS

Inspection Date: 05/20/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0382  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 06/30/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3113  
 Occurrences: Not reported  
 Item Number: 2687  
 Violation Desc: 2NDRY CONT TEST NOT SENT TO CUPA

Inspection Date: 06/30/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3405  
 Occurrences: Not reported  
 Item Number: 2688  
 Violation Desc: LLD DOESN'T DETECT 3.0 GPH OR EQUIVA

Inspection Date: 06/30/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3406  
 Occurrences: Not reported  
 Item Number: 2689  
 Violation Desc: AUTOMATIC LLD NOT CERTIFIED ANNUALLY?

Inspection Date: 06/30/04  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Type of Violation: 6HV4204  
 Occurrences: Not reported  
 Item Number: 2690  
 Violation Desc: WARNING SIGN NOT POSTED

Inspection Date: 06/30/04  
 Waste Code: Not reported  
 Type of Violation: 6HV4209  
 Occurrences: Not reported  
 Item Number: 2691  
 Violation Desc: NO GENERATOR'S INFO ON RED BAGS/SHARPS

Inspection Date: 12/09/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3114  
 Occurrences: Not reported  
 Item Number: 6993  
 Violation Desc: 2NDRY CONT TEST NOT DONE/SENT TO CUPA

**HMMD WASTE STREAMS:**

Inspection Date: 12/09/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 1  
 Annual Qty String: 1  
 Measurement Unit: TON  
 Treatment Method: 001 RECYCLE  
 Storage Method: UNKNOWN  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: PIER PITING, BATTERIES,BA  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 245  
 Annual Qty String: 245  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: ALKALINE BATTTS/NICAD  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 16  
 Quantity String: 16  
 Annual Qty: 48

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Annual Qty String: 48  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 750  
 Quantity String: 750  
 Annual Qty: 1620  
 Annual Qty String: 1620  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 222  
 Waste Code: 222  
 Waste Name: OIL/WATER SEPARATION  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 925  
 Annual Qty String: 925  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: BILGE WATER  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: JET FUEL FILTERS  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 331  
 Waste Code: 331  
 Waste Name: OFF-SPEC,AGED,SURPLU

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Qty at Inspection: 450  
 Quantity String: 450  
 Annual Qty: 450  
 Annual Qty String: 450  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: FUEL  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qty at Inspection: 90  
 Quantity String: 90  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE ANTIFREEZE  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qty at Inspection: 600  
 Quantity String: 600  
 Annual Qty: 2720  
 Annual Qty String: 2720  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: ABSORBENT, OIL/RAGS  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qty at Inspection: 50  
 Quantity String: 50  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: EXCHANGED & LOGGED  
 Carcinogen: No

Inspection Date: 12/09/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 170  
 Annual Qty String: 170  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: PAINTS, THINNERS  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: OIL FILTERS  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 901  
 Waste Code: 901  
 Waste Name: INFECTIOUS WASTE, GE  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: BAG  
 Haz Waste Hauler: 3773 PWN ENVIROMENTAL  
 Waste Desc: RED BAGS  
 Carcinogen: No

Inspection Date: 12/09/04  
 Waste Item #: 902  
 Waste Code: 902  
 Waste Name: INFECTIOUS WASTE, SH  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: LBS  
 Treatment Method: 101 AUTOCLAVE  
 Storage Method: CARBOY  
 Haz Waste Hauler: 3773 PWN ENVIROMENTAL  
 Waste Desc: SHARPS



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**U.S. COAST GUARD ACTIVITIES SA (Continued)**

**S106060490**

Carcinogen: No

92

**HARBOR DRIVE AND 28TH STREET  
 SAN DIEGO, CA 92186**

**CHMIRS S105882637  
 SLIC N/A**

CHMIRS:

OES Incident Number: 02-4956  
 OES notification: 9/12/200210:22:33 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Harbor  
 Spill Site: Not reported  
 Cleanup By: Responsible Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2002  
 Agency: NRC  
 Incident Date: 9/12/200212:00:00 AM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105882637

Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Yes
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	lubricating oil
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	1
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Per the NRC report, a construction ship, the USS Soderman, has a bow thruster which leaks oil when the thruster runs. A sheen was found after running the system. The vessel is always boomed and dry dock the boat for repair. Release is coming from a docking arm to a floating dry dock. Absorbent pads are in place.
OES Incident Number:	02-0839
OES notification:	2/13/200211:56:52 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
<b>Date Completed:</b>	<b>Not reported</b>
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105882637

Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2002  
 Agency: National Steel and Shipbuilding  
 Incident Date: 2/13/200212:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: hydraulic oil  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 1  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: Per the NRC report, a construction ship, the USS Soderman, has a bow thruster which leaks oil when the thruster runs. A sheen was found after running the system. The vessel is always boomed and dry dock the boat for repair. Release is coming from a docking arm to a floating dry dock. Absorbent pads are in place.

SLIC:

Region: STATE  
 Global Id: SL607392737  
 Assigned Name: SLICSITE  
 Lead Agency Contact: TOM ALO  
 Lead Agency: SAN DIEGO RWQCB (REGION 9)

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105882637

Lead Agency Case Number: 2090004  
 Responsible Party: Not reported  
 Recent Dtw: Not reported  
 Substance Released: ARSENIC, 01027, 01042, 01051, 71900, 39516, TPHU, 01092  
**Facility Status: Not reported**

92

28TH ST / HARBOR DR, BERTH 5  
 SAN DIEGO, CA 92186

CHMIRS S105648302  
 N/A

CHMIRS:

OES Incident Number: 97-4721  
 OES notification: 11/26/199711:56:53 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: SAN DIEGO BAY  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**(Continued)**

**S105648302**

Year: 1997  
 Agency: NATIONAL STEEL AND SHIP BUILDING CO  
 Incident Date: 11/26/1997 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: HYDRAULIC FLUID  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 1  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: EQUIPMENT FAILURE CAUSED SPILL.

**92 HARBOR DR & 28TH ST BERTH 2  
 HARBOR DR & 28TH ST BERTH 2  
 SAN DIEGO, CA**

**ERNS 96495563  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**92 SS ALMERIA LYKES EX PRES MCKINLEY  
 HARBOR DR / 28TH ST  
 SAN DIEGO, CA 92186**

**HAZNET S102815696  
 N/A**

HAZNET:  
 Gepaid: CAL000079898  
 Contact: AMERICAN PRESIDENT LINES LTD  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2001 JOHN GIBSON BLVD  
 Mailing City,St,Zip: SAN PEDRO, CA 907310000  
 Gen County: San Diego  
 TSD EPA ID: CAD083166728  
 TSD County: Stanislaus  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .6255

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SS ALMERIA LYKES EX PRES MCKINLEY (Continued)**

**S102815696**

Facility County: San Diego

92 **28 & HARBOR DRIVE  
 28 & HARBOR DRIVE  
 SAN DIEGO, CA**

**ERNS 98428628  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92 **HARBOR DRIVE / 28TH STREET BERTH #6 AT NASSO FAC  
 SAN DIEGO, CA**

**CHMIRS S106391707  
 N/A**

CHMIRS:

OES Incident Number: 015342  
 OES notification: Not reported  
 OES Date: 8/29/1996  
 OES Time: 10:23:11 AM  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: YES  
 Waterway: san diego bay  
 Spill Site: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S106391707

Cleanup By: nasso fire dept  
 Containment: Not reported  
 What Happened: Not reported  
 Type: PETROLEUM  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1996  
 Agency: national steel & ship building comp  
 Incident Date: 0900 29Aug96  
 Admin Agency: Not reported  
 Amount: less than 1 pint  
 Contained: YES  
 Site Type: OTHER  
 E Date: Not reported  
 Substance: hydraulic oil  
 Quantity Released: Not reported  
 BBLs: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: the hydraulic fitting on board "usns yano" that was to an acuator failed under pressure.  
 Evacuations: NO  
 Number of Injuries: NO  
 Number of Fatalities: NO  
 Description: Not reported

92 NATIONAL STEEL AND SHIPBUILDING COMPANY  
 2798 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92113

CHMIRS 1000260467  
 RCRA-LQG 92138NTNLSHA  
 TRIS  
 CERC-NFRAP  
 HIST UST

CHMIRS:  
 OES Incident Number: 016220  
 OES notification: Not reported  
 OES Date: 10/27/1996  
 OES Time: 06:39:43 PM  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: YES  
 Waterway: san diego bay  
 Spill Site: Not reported  
 Cleanup By: action cleaning  
 Containment: Not reported  
 What Happened: Not reported  
 Type: PETROLEUM  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1996  
 Agency: nat'l steel and shipbuilding co.  
 Incident Date: 1652/27 Oct 96  
 Admin Agency: Not reported  
 Amount: unknown  
 Contained: YES  
 Site Type: OTHER  
 E Date: Not reported  
 Substance: sheen  
 Quantity Released: Not reported  
 BBLS: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: sheen was spotted by internal fire dept. people who spotted in the



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

harbor. upon investigation, it is suspected that the sheen is originating from pier pilings or residual oil which is then carried out by the tide.

Evacuations: NO  
 Number of Injuries: NO  
 Number of Fatalities: NO  
 Description: Not reported

**RCRA-LQG:**

Date form received by agency: 02/22/2006  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Facility address: 2798 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92113  
 EPA ID: CAD009158932  
 Mailing address: P.O. BOX 85278, MS-22A  
 SAN DIEGO, CA 921865278  
 Contact: MICHAEL CHEE  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 544-7778  
 Contact email: MCHEE@NASSCO.COM  
 EPA Region: 09  
 Land type: District  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

**Owner/Operator Summary:**

Owner/operator name: SAN DIEGO UNIFIED PORT DISTRICT  
 Owner/operator address: P.O. BOX 120488  
 SAN DIEGO, CA 92112  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: District  
 Owner/Operator Type: Owner  
 Owner/Op start date: 02/14/1963  
 Owner/Op end date: Not reported

Owner/operator name: OPERATOR  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Owner/Op start date: 01/04/1960  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: Yes  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: Yes

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: Yes

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Historical Generators:

Date form received by agency: 02/16/2004  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Classification: Large Quantity Generator

Date form received by agency: 02/15/2002  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Site name: NATIONAL STL SHIPBUILDING CO#  
 Classification: Large Quantity Generator

Date form received by agency: 04/01/1996  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Classification: Large Quantity Generator

Date form received by agency: 03/30/1994  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Site name: NATIONAL STEEL & SHIPBUILDING  
 Classification: Large Quantity Generator

Date form received by agency: 04/01/1992  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Site name: NATIONAL STEEL & SHIPBUILDING COMPANY  
 Classification: Large Quantity Generator

Date form received by agency: 04/13/1990  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Site name: NATIONAL STL SHIPBUILDING CO  
 Classification: Large Quantity Generator

Date form received by agency: 08/13/1980  
 Facility name: NATIONAL STEEL AND SHIPBUILDING COMPANY  
 Site name: NATIONAL STL SHIPBUILDING CO#  
 Classification: Large Quantity Generator

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007  
 Waste name: CHROMIUM

Waste code: D009  
 Waste name: MERCURY

Waste code: D011  
 Waste name: SILVER

Waste code: D035

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Waste name: METHYL ETHYL KETONE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: F003

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 787338

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 314580

Waste code: D007

Waste name: CHROMIUM

Amount (Lbs): 440

Waste code: D009

Waste name: MERCURY

Amount (Lbs): 1300

Waste code: D011

Waste name: SILVER

Amount (Lbs): 3101

Waste code: D035

Waste name: METHYL ETHYL KETONE

Amount (Lbs): 516937

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE  
 Amount (Lbs): 91361

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 91361

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 04/26/2006  
 Date achieved compliance: 06/12/2006  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 04/26/2006  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - Pre-transport  
 Date violation determined: 11/16/2005  
 Date achieved compliance: 04/17/2006  
 Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: 12/19/2005  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - Pre-transport  
 Date violation determined: 11/16/2005  
 Date achieved compliance: 04/17/2006  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 04/17/2006  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 04/22/2004  
 Date achieved compliance: 07/06/2004  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 05/23/1994  
 Date achieved compliance: 05/23/1999  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 03/09/1993  
 Date achieved compliance: 05/23/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 03/25/1986  
 Date achieved compliance: 12/05/1991  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 04/26/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/12/2006  
 Evaluation lead agency: Local

Evaluation date: 11/16/2005  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - Pre-transport  
 Date achieved compliance: 04/17/2006  
 Evaluation lead agency: EPA

Evaluation date: 04/22/2004  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 07/06/2004  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/23/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/23/1999  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 03/09/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/23/1994  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 12/05/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/12/2006  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 03/25/1986  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 12/05/1991  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 03/25/1986  
 Evaluation: NON-FINANCIAL RECORD REVIEW  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

CERC-NFRAP:

Site ID: 0904770  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

CERCLIS-NFRAP Site Contact Name(s):

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: NATIONAL STEEL & SHIPBUILDING CO.  
 Alias Address: Not reported  
 CA

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/08/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 03/16/1994  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 03/16/1994  
 Priority Level: NFRAP (No Further Remedial Action Planned)

HIST UST:

Region: STATE  
 Facility ID: 00000030066  
 Facility Type: Other  
 Other Type: SHIPBUILDING  
 Total Tanks: 0005  
 Contact Name: JOHN CARPENTER  
 Telephone: 6196967938  
 Owner Name: NATIONAL STEEL & SHIPBUILDING  
 Owner Address: 28TH STREET AND HARBOR DRIVE  
 Owner City,St,Zip: SAN DIEGO, CA 92138

Tank Num: 001  
 Container Num: #200  
 Year Installed: 1978  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: #400  
 Year Installed: Not reported  
 Tank Capacity: 00000000



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL STEEL AND SHIPBUILDING COMPANY (Continued)**

**1000260467**

Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 003  
 Container Num: 500  
 Year Installed: Not reported  
 Tank Capacity: 00000000  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: None

Tank Num: 004  
 Container Num: #300  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 005  
 Container Num: #100  
 Year Installed: 1978  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

92

**28TH ST / HARBOR DR  
 SAN DIEGO, CA 92186**

**CHMIRS S105661006  
 N/A**

CHMIRS:

OES Incident Number: 99-0088  
 OES notification: 1/8/199904:32:21 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105661006

Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1999  
 Agency: Natl Steel and Shipbuilding Comp.  
 Incident Date: 1/8/1999 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: oil  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 20  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: A manlift broke a hydraulic line. Most fluid confined to dock but some spray got into bay. Area is boomed and dock is bermed. Absorbant pads used spill cleaned upwater pump developeped a oil leak. Boom deployed and pads on the oil.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105661006

OES Incident Number: 99-2758  
 OES notification: 6/30/199909:19:45 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1999  
 Agency: National Steel and Ship Building Co  
 Incident Date: 6/30/199912:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Hydraulic Fluid  
 Quantity Released: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105661006

BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 1  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: A manlift broke a hydraulic line. Most fluid confined to dock but some spray got into bay. Area is boomed and dock is bermed. Absorbant pads used spill cleaned upwater pump developeped a oil leak. Boom deployed and pads on the oil.

92

2800 HARBOR DRIVE  
 SAN DIEGO, CA 92101

CHMIRS S100277701  
 N/A

CHMIRS:  
 OES Incident Number: 99-5106  
 OES notification: 12/2/199911:37:28 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100277701

Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	San Diego Bay
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1999
Agency:	National Steel and Ship Building
Incident Date:	12/2/199912:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Yes
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Hydraulic Fluid
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	2
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Incident under investigation. Believed to be a propeller seal. Coming from the USNS Red Cloud. Ship was not under boom but one is deployed now.
OES Incident Number:	9117287
OES notification:	Not reported
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	01-JUN-91
<b>Date Completed:</b>	<b>01-JUN-91</b>
Property Use:	600
Agency Id Number:	37140
Agency Incident Number:	58807
Time Notified:	531
Time Completed:	737
Surrounding Area:	600

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100277701

Estimated Temperature: 65  
 Property Management: F  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: N  
 Resp Agency Personel # Of Decontaminated: 0  
 Responding Agency Personel # Of Injuries: 0  
 Responding Agency Personel # Of Fatalities:0  
 Others Number Of Decontaminated: 0  
 Others Number Of Injuries: 0  
 Others Number Of Fatalities: 0  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: TIM ADKINS  
 Report Date: 02-JUN-91  
 Comments: Y  
 Facility Telephone: 619 533-4300  
 Waterway Involved: Not reported  
 Waterway: Not reported  
 Spill Site: Not reported  
 Cleanup By: Not reported  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 88-92  
 Agency: Not reported  
 Incident Date: Not reported  
 Admin Agency: Not reported  
 Amount: Not reported  
 Contained: Not reported  
 Site Type: Not reported  
 E Date: 08-JUL-92  
 Substance: Not reported  
 Quantity Released: Not reported  
 BBLS: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100277701

Unknown: Not reported  
 Description: Not reported  
 Evacuations: Not reported  
 Number of Injuries: Not reported  
 Number of Fatalities: Not reported  
 Description: Incident under investigation. Believed to be a propeller seal. Coming from the USNS Red Cloud. Ship was not under boom but one is deployed now.

92

**NATIONAL STEEL AND SHIPBUILDING CO  
 2798 EAST HARBOR DRIVE  
 SAN DIEGO, CA 92113**

**HAZNET S103978936  
 N/A**

HAZNET:

Gepaid: CAD009158932  
 Contact: NASSCO HOLDINGS INC NHI  
 Telephone: 6195448600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85278  
 Mailing City,St,Zip: SAN DIEGO, CA 921865278  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Not reported  
 Tons: 16.6800  
 Facility County: San Diego

Gepaid: CAD009158932  
 Contact: NASSCO HOLDINGS INC NHI  
 Telephone: 6195448600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85278  
 Mailing City,St,Zip: SAN DIEGO, CA 921865278  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 152.2050  
 Facility County: San Diego

Gepaid: CAD009158932  
 Contact: NASSCO HOLDINGS INC NHI  
 Telephone: 6195448600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85278  
 Mailing City,St,Zip: SAN DIEGO, CA 921865278  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Paint sludge  
 Disposal Method: Treatment, Incineration  
 Tons: 8.4280  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL STEEL AND SHIPBUILDING CO (Continued)**

**S103978936**

Gepaid: CAD009158932  
 Contact: NASSCO HOLDINGS INC NHI  
 Telephone: 6195448600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85278  
 Mailing City,St,Zip: SAN DIEGO, CA 921865278  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Treatment, Incineration  
 Tons: 25.5500  
 Facility County: San Diego

Gepaid: CAD009158932  
 Contact: NASSCO HOLDINGS INC NHI  
 Telephone: 6195448600  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 85278  
 Mailing City,St,Zip: SAN DIEGO, CA 921865278  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Polychlorinated biphenyls and material containing PCB's  
 Disposal Method: Not reported  
 Tons: .3581  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 389 additional CA\_HAZNET: record(s) in the EDR Site Report.

**92 2798 HARBOR DRIVE  
 2798 HARBOR DRIVE  
 SAN DIEGO, CA 92186**

**ERNS 2006793474  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**92 2798 HARBOR DRIVE  
 2798 HARBOR DRIVE  
 SAN DIEGO, CA**

**ERNS 2006791426  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

92

CHMIRS S106396865  
 N/A

**2798 HARBOR DR.  
 SAN DIEGO, CA 92113**

CHMIRS:

OES Incident Number: 03-4504  
 OES notification: 9/2/200301:04:57 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2003  
 Agency: NASSCO  
 Incident Date: 9/2/200312:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S106396865

E Date: Not reported  
 Substance: Diesel Fuel  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 2  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description:

A tipped over 5 gallon can of diesel tipped over and spilling in the San Diego BayPer fax from the NRC: An operator accidentally dropped an oily hose causing residue from the hose to spill into San Diego Bay. Material dissipated naturally. Caller reports release of material into the San Diego Bay from a fuel caddy due to operator error. Absorbents applied, clean up underway.

OES Incident Number: 05-4218  
 OES notification: 7/16/200509:52:34 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S106396865

CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Dissipate Naturally  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2005  
 Agency: NRC  
 Incident Date: 7/16/200512:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Hydraulic Oil  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: A tipped over 5 gallon can of diesel tipped over and spilling in the San Diego BayPer fax from the NRC: An operator accidentally dropped an oily hose causing residue from the hose to spill into San Diego Bay. Material dissipated naturally. Caller reports release of material into the San Diego Bay from a fuel caddy due to operator error. Absorbents applied, clean up underway.

OES Incident Number: 05-6558  
 OES notification: 11/12/200501:56:00 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S106396865

Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2005  
 Agency: National Steel Ship Building  
 Incident Date: 11/12/2005 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Diesel  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S106396865

Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0

Description: A tipped over 5 gallon can of diesel tipped over and spilling in the San Diego Bay. Per fax from the NRC: An operator accidentally dropped an oily hose causing residue from the hose to spill into San Diego Bay. Material dissipated naturally. Caller reports release of material into the San Diego Bay from a fuel caddy due to operator error. Absorbents applied, clean up underway.

92 2800 HARBOR DR.  
 2800 HARBOR DR.  
 SAN DIEGO, CA 92113

ERNS 2007314743  
 N/A

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92 2798 HARBOR DRIVE  
 SAN DIEGO, CA 92186

CHMIRS S105885188  
 N/A

CHMIRS:  
 OES Incident Number: 03-5509  
 OES notification: 10/24/2003 10:50:21 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personnel # Of Decontaminated: Not reported  
 Responding Agency Personnel # Of Injuries: Not reported  
 Responding Agency Personnel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105885188

Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	San Diego Bay
Spill Site:	Not reported
Cleanup By:	N/A
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2003
Agency:	national Steel and Shipbuilding Co,
Incident Date:	10/24/200312:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Yes
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	oil
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	2
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Sheen caused by oil that was sprayed into the water while washing down a floating dry dock. Sheen disapated almost immediately.During testing on a side door, an equipment failure occurred causing the spill. Booms in place with absorbants.
OES Incident Number:	02-3604
OES notification:	7/2/200208:30:47 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105885188

**Date Completed:** Not reported  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2002  
 Agency: Natl Steel and Shipbuilding Co  
 Incident Date: 7/2/2002 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Hydraulic oil  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**(Continued)**

**S105885188**

Pounds:	0
Liters:	0
Ounces:	0
Pints:	1
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Sheen caused by oil that was sprayed into the water while washing down a floating dry dock. Sheen disapated almost immediately.During testing on a side door, an equipment failure occurred causing the spill. Booms in place with absorbants.

92

**NATIONAL STEEL & SHIPBUILDING  
 28TH ST / HARBOR DR  
 SAN DIEGO, CA 92113**

**AIRS S105938782  
 N/A**

EMI:

Year:	1997
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	19
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	202
Reactive Organic Gases Tons/Yr:	202
Carbon Monoxide Emissions Tons/Yr:	17
NOX - Oxides of Nitrogen Tons/Yr:	24
SOX - Oxides of Sulphur Tons/Yr:	1
Particulate Matter Tons/Yr:	15
Part. Matter 10 Micrometers & Smlr Tons/Yr:	15
Year:	1998
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	19
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	202
Reactive Organic Gases Tons/Yr:	202
Carbon Monoxide Emissions Tons/Yr:	17
NOX - Oxides of Nitrogen Tons/Yr:	24
SOX - Oxides of Sulphur Tons/Yr:	1
Particulate Matter Tons/Yr:	15
Part. Matter 10 Micrometers & Smlr Tons/Yr:	14
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	37



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL STEEL & SHIPBUILDING (Continued)**

**S105938782**

Air Basin: SD  
 Facility ID: 19  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 202  
 Reactive Organic Gases Tons/Yr: 202  
 Carbon Monoxide Emissions Tons/Yr: 17  
 NOX - Oxides of Nitrogen Tons/Yr: 24  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 15  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 14

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 19  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 166  
 Reactive Organic Gases Tons/Yr: 165  
 Carbon Monoxide Emissions Tons/Yr: 7  
 NOX - Oxides of Nitrogen Tons/Yr: 19  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 10  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 10

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 19  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y  
 Consolidated Emission Reporting Rule: B  
 Total Organic Hydrocarbon Gases Tons/Yr: 166  
 Reactive Organic Gases Tons/Yr: 165  
 Carbon Monoxide Emissions Tons/Yr: 7  
 NOX - Oxides of Nitrogen Tons/Yr: 19  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 10  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 10

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 19  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Y

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL STEEL & SHIPBUILDING (Continued)**

**S105938782**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	162
Reactive Organic Gases Tons/Yr:	161
Carbon Monoxide Emissions Tons/Yr:	8
NOX - Oxides of Nitrogen Tons/Yr:	24
SOX - Oxides of Sulphur Tons/Yr:	1
Particulate Matter Tons/Yr:	9
Part. Matter 10 Micrometers & Smlr Tons/Yr:	9
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	19
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	198
Reactive Organic Gases Tons/Yr:	196
Carbon Monoxide Emissions Tons/Yr:	13
NOX - Oxides of Nitrogen Tons/Yr:	36
SOX - Oxides of Sulphur Tons/Yr:	2
Particulate Matter Tons/Yr:	12
Part. Matter 10 Micrometers & Smlr Tons/Yr:	12

92

**NATL STEEL & SHIPBUILDING A GENERAL DYNAMICS CO**  
**28TH ST / HARBOR DR**  
**SAN DIEGO, CA 92113**

**AIRS S108432587**  
**N/A**

EMI:

Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	19
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	226.10944
Reactive Organic Gases Tons/Yr:	224.53147
Carbon Monoxide Emissions Tons/Yr:	13.858992
NOX - Oxides of Nitrogen Tons/Yr:	53.65
SOX - Oxides of Sulphur Tons/Yr:	1.624259
Particulate Matter Tons/Yr:	39.20859957624543390
Part. Matter 10 Micrometers & Smlr Tons/Yr:	24.925022

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

92	<b>PACIFIC SHIP REPAIR AND FABRICATION NASSCO</b> <b>2798 HARBOR DR</b> <b>SAN DIEGO, CA 92113</b>	FINDS	<b>1010735990</b> <b>110033623620</b>
----	--	-------	--

FINDS:  
Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

92	<b>2800 HARBOR DR.</b> <b>2800 HARBOR DR.</b> <b>SAN DIEGO, CA 92113</b>	ERNS	<b>2007312073</b> <b>N/A</b>
----	--	------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	<b>2800 HARBOR DR.</b> <b>2800 HARBOR DR.</b> <b>SAN DIEGO, CA 92113</b>	ERNS	<b>2006821705</b> <b>N/A</b>
----	--	------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	<b>2798 HARBOR DRIVE</b> <b>2798 HARBOR DRIVE</b> <b>SAN DIEGO, CA 92113</b>	ERNS	<b>2007327078</b> <b>N/A</b>
----	--	------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	<b>2798 HARBOR DRIVE</b> <b>2798 HARBOR DRIVE</b> <b>SAN DIEGO, CA</b>	ERNS	<b>2004719114</b> <b>N/A</b>
----	--	------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

MAP FINDINGS

Map ID	Direction	Distance	Distance (ft.)	Site	Database(s)	EPA ID Number	EDR ID Number
--------	-----------	----------	----------------	------	-------------	---------------	---------------

92				2800 HARBOR DR. 2800 HARBOR DR. SAN DIEGO, CA	ERNS	2003637721 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2800 HARBOR DR. 2800 HARBOR DR. SAN DIEGO, CA 92113	ERNS	2007301089 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2800 HARBOR DR. 2800 HARBOR DR. SAN DIEGO, CA 92113	ERNS	2006815981 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2798 HARBOR DRIVE 2798 HARBOR DRIVE SAN DIEGO, CA 92113	ERNS	2006819362 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2798 HARBOR DR. 2798 HARBOR DR. SAN DIEGO, CA	ERNS	2006819833 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>92</b>	<b>2798 HARBOR DRIVE</b> <b>2798 HARBOR DRIVE</b> <b>SAN DIEGO, CA</b>	<b>ERNS</b>	<b>2003703525</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

<b>92</b>	<b>2798 HARBOR DR.</b> <b>2798 HARBOR DR.</b> <b>SAN DIEGO, CA</b>	<b>ERNS</b>	<b>2006820462</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

<b>92</b>	<b>28TH / HARBOR DRIVE</b> <b>28TH / HARBOR DRIVE</b> <b>SAN DIEGO, CA 92113</b>	<b>ERNS</b>	<b>96477382</b> <b>N/A</b>
-----------	--	-------------	-------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

<b>92</b>	<b>2798 HARBOR DRIVE</b> <b>2798 HARBOR DRIVE</b> <b>SAN DIEGO, CA 92118</b>	<b>ERNS</b>	<b>2005629410</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

<b>92</b>	<b>NATIONAL STEEL &amp; SHI</b> <b>28TH ST / HARBOR DR</b> <b>, CA 92113</b>	<b>AIRS</b>	<b>S106836142</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

EMI:

Year:	1987
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	19
Air District Name:	SD
SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	98
Reactive Organic Gases Tons/Yr:	90
Carbon Monoxide Emissions Tons/Yr:	0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL STEEL & SHI (Continued)**

**S106836142**

NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 2  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 2

**92 2800 HARBOR DR.  
 2800 HARBOR DR.  
 SAN DIEGO, CA 92113**

**ERNS 2000524228  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**92 28TH / HARBOR  
 SAN DIEGO, CA**

**CHMIRS S105677855  
 N/A**

CHMIRS:

OES Incident Number: 01-0139  
 OES notification: 1/8/200103:24:36 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105677855

Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Fire Dept.  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2001  
 Agency: Nat'l Steel & Ship Building  
 Incident Date: 1/8/2001 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Hydraulic Fluid  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 1  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0.000000  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: O Ring failed causing hydraulic fluid leak.

92

**NASSCO SHIPYARD**  
**2798 HARBOR DR**  
**SAN DIEGO, CA 92113**

CHMIRS S105298935  
 San Diego Co. HMMD N/A

CHMIRS:  
 OES Incident Number: 03-4160  
 OES notification: 8/15/2003 03:44:24 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NASSCO SHIPYARD (Continued)**

**S105298935**

Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2003  
 Agency: National Steel and Ship Building  
 Incident Date: 8/15/2003 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Rustoleum Pain  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NASSCO SHIPYARD (Continued)**

**S105298935**

Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: Substance was released when an employee was broom sweeping the deck and substance went over the side.Substance was released when spray can was ruptured. Can was recovered but product dissipated in water.

OES Incident Number: 05-5067  
 OES notification: 8/30/200510:30:34 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities:Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2005  
 Agency: National Steel & Shipbuilding  
 Incident Date: 8/30/200512:00:00 AM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NASSCO SHIPYARD (Continued)**

**S105298935**

Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Oily Water  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: Substance was released when an employee was broom sweeping the deck and substance went over the side. Substance was released when spray can was ruptured. Can was recovered but product dissipated in water.

**San Diego Co. HMMID:**

Facility ID: 139530  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City, St, Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: Not reported  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE CHEE (619) 544-7778  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City, St, Zip: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NASSCO SHIPYARD (Continued)**

**S105298935**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID	Direction	Distance	Distance (ft.)	Site	Database(s)	EPA ID Number	EDR ID Number
--------	-----------	----------	----------------	------	-------------	---------------	---------------

92				2798 HARBOR DRIVE 2798 HARBOR DRIVE SAN DIEGO, CA	ERNS	2005618320 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2798 HARBOR DRIVE 2798 HARBOR DRIVE SAN DIEGO, CA	ERNS	2005606081 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2798 HARBOR DR 2798 HARBOR DR SAN DIEGO, CA	ERNS	2006784878 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2798 HARBOR DRIVE 2798 HARBOR DRIVE SAN DIEGO, CA 92118	ERNS	2006813194 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92				2798 HARBOR DRIVE 2798 HARBOR DRIVE SAN DIEGO, CA 92118	ERNS	2007317151 N/A	
----	--	--	--	---	------	-------------------	--

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

92	2798 HARBOR DR. 2798 HARBOR DR. SAN DIEGO, CA 92113	ERNS	2006815982 N/A
----	---	------	-------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	NATIONAL STEEL AND SHIPBUILDING (NASSCO) 2798 EAST HARBOR DRIVE SAN DIEGO, CA 92113	FINDS	1006870562 110014337413
----	---	-------	----------------------------

FINDS:

Other Pertinent Environmental Activity Identified at Site

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Database(s) EPA ID Number  
 Distance (ft.)Site

92 2798 HARBOR DR ERNS 2004742667  
 2798 HARBOR DR N/A  
 SAN DIEGO, CA

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92 2798 HARBOR DR. CHMIRS S107449530  
 SAN DIEGO, CA 92186 N/A

CHMIRS:  
 OES Incident Number: 04-5126  
 OES notification: 10/4/200410:44:12 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S107449530

Other:	Not reported
Date/Time:	Not reported
Year:	2004
Agency:	NRC
Incident Date:	10/4/200412:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Unknown
Site Type:	Waterways
E Date:	Not reported
Substance:	Lubrication Oil
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	1.5
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	The material released from a ship due to loose equipment. The caller stated that a line on a compressor was not properly fastened which caused material to leak into the bay. The caller also stated that an hour later, an employee was carrying a container with paint solvent. The employee tripped and spilled the paint solvent.
OES Incident Number:	04-6201
OES notification:	11/29/200410:16:40 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
<b>Date Completed:</b>	<b>Not reported</b>
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agency Personel # Of Decontaminated:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S107449530

Responding Agency Personnel # Of Injuries: Not reported  
 Responding Agency Personnel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: San Diego Harbor  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2004  
 Agency: NRC  
 Incident Date: 11/29/2004 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Unknown  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Hydraulic Oil  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 1  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: The material released from a ship due to loose equipment. The caller stated that a line on a compressor was not properly fastened which caused material to leak into the bay. The caller also stated that an hour later, an employee was carrying a container with paint solvent. The employee tripped and spilled the paint solvent.



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**92 NATIONAL STEEL & SHIP  
 28TH ST / HARBOR DR  
 SAN DIEGO, CA 92113**

**AIRS S106836143  
 N/A**

EMI:

Year: 1990  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 19  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 113  
 Reactive Organic Gases Tons/Yr: 103  
 Carbon Monoxide Emissions Tons/Yr: 7  
 NOX - Oxides of Nitrogen Tons/Yr: 30  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 3  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 3

Year: 1995  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 19  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 92  
 Reactive Organic Gases Tons/Yr: 83  
 Carbon Monoxide Emissions Tons/Yr: 8  
 NOX - Oxides of Nitrogen Tons/Yr: 38  
 SOX - Oxides of Sulphur Tons/Yr: 1  
 Particulate Matter Tons/Yr: 10  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 9

Year: 1996  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 19  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 158  
 Reactive Organic Gases Tons/Yr: 157  
 Carbon Monoxide Emissions Tons/Yr: 10  
 NOX - Oxides of Nitrogen Tons/Yr: 22  
 SOX - Oxides of Sulphur Tons/Yr: 4  
 Particulate Matter Tons/Yr: 7  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 6

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

92	2798 E. HARBOR DRIVE 2798 E. HARBOR DRIVE SAN DIEGO, CA 92113	ERNS	2006820195 N/A
----	---	------	-------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	2800 HARBOUR DR 2800 HARBOUR DR SAN DIEGO, CA 92113	ERNS	91222031 N/A
----	---	------	-----------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	28TH STREEET AND HARBOR DR. 28TH STREEET AND HARBOR DR. SAN DIEGO, CA 92113	ERNS	2000532289 N/A
----	---	------	-------------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	28TH ST AND HARBOR DR 28TH ST AND HARBOR DR SAN DIEGO, CA 92113	ERNS	99622326 N/A
----	---	------	-----------------

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92	NASSCO SHIP YARD 2798 HARBOR DRIVE SAN DIEGO, CA	CHMIRS	S105885489 N/A
----	---	--------	-------------------

CHMIRS:

OES Incident Number:	02-4232
OES notification:	8/5/200211:50:57 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
<b>Date Completed:</b>	<b>Not reported</b>
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S105885489

Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agency Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	San Diego Bay
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	USS Antetam
Incident Date:	8/5/200212:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Yes
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	oily water
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105885489

Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: 3 gallons of oily water with 3 oil in the water. During a transfer a valve was improperly seated. Caused a 10X30 foot sheen.

92

**S S HOWELL LYKES EXPRESS VAN BUREN  
 HARBOR DR AND 28 ST CSS HOWELL  
 SAN DIEGO, CA 92186**

**RCRA-SQG 1000819375  
 FINDS CAD983653569  
 HAZNET**

RCRA-SQG:

Date form received by agency: 11/23/1992  
 Facility name: S S HOWELL LYKES EXPRESS VAN BUREN  
 Facility address: HARBOR DR AND 28 ST CSS HOWELL  
 LYKES EXPRESS VAN BUREN  
 SAN DIEGO, CA 92186  
 EPA ID: CAD983653569  
 Mailing address: JOHN GIBSON BLVD  
 SAN PEDRO, CA 90731  
 Contact: ROBERT A CLARK  
 Contact address: 2001 JOHN GIBSON BLVD  
 SAN PEDRO, CA 90731  
 Contact country: US  
 Contact telephone: (310) 548-8822  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: AMERICAN PRESIDENT LINES LTD  
 Owner/operator address: 1111 BROADWAY  
 OAKLAND, CA 94607  
 Owner/operator country: Not reported  
 Owner/operator telephone: (510) 272-8000  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**S S HOWELL LYKES EXPRESS VAN BUREN (Continued)**

**1000819375**

User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD983653569  
 Contact: AMERICAN PRESIDENT LINES LTD  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2001 JOHN GIBSON BLVD  
 Mailing City,St,Zip: SAN PEDRO, CA 907310000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 15.5207  
 Facility County: San Diego

Gepaid: CAD983653569  
 Contact: AMERICAN PRESIDENT LINES LTD  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2001 JOHN GIBSON BLVD  
 Mailing City,St,Zip: SAN PEDRO, CA 907310000  
 Gen County: San Diego  
 TSD EPA ID: CAD067786749  
 TSD County: Los Angeles  
 Waste Category: Not reported  
 Disposal Method: Not reported  
 Tons: .4214  
 Facility County: San Diego

Gepaid: CAD983653569  
 Contact: AMERICAN PRESIDENT LINES LTD  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2001 JOHN GIBSON BLVD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**S S HOWELL LYKES EXPRESS VAN BUREN (Continued)**

**1000819375**

Mailing City,St,Zip: SAN PEDRO, CA 907310000  
 Gen County: San Diego  
 TSD EPA ID: CAD067786749  
 TSD County: Los Angeles  
 Waste Category: Not reported  
 Disposal Method: Disposal, Land Fill  
 Tons: .0000  
 Facility County: San Diego

92 **NASSCO HARBOR DRIVE  
 NASSCO HARBOR DRIVE  
 SAN DIEGO, CA**

**ERNS 93300605  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92 **NASSCO SHIP YARD BERTH NO. 6  
 NASSCO SHIP YARD BERTH NO. 6  
 SAN DIEGO, CA**

**ERNS 90173044  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92 **NASSCO SHIP YARD BERTH 4  
 NASSCO SHIP YARD BERTH 4  
 SAN DIEGO, CA**

**ERNS 96500446  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

92 **NASSCO PIER DIRECTLY ACROSS FROM NAVAL STATION PIER NR UNK  
 NASSCO PIER DIRECTLY ACROSS FROM NAVAL STATION PIER NR UNK  
 SAN DIEGO, CA**

**ERNS 98433376  
 N/A**

[Click this hyperlink](#) while viewing on your computer to access additional ERNS detail in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**93 L C EMBROIDERY & CLEANERS  
 3280 MAIN ST STE 6  
 SAN DIEGO, CA 92113**

**HAZNET S105807979  
 DRYCLEANERS N/A**

HAZNET:

Gepaid: CAL000286068  
 Contact: FREDDY PATZI/OWNER  
 Telephone: 6192392477  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3280 MAIN ST STE 6  
 Mailing City,St,Zip: SAN DIEGO, CA 921133736  
 Gen County: San Diego  
 TSD EPA ID: OHD980587364  
 TSD County: 99  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Not reported  
 Tons: Not reported  
 Facility County: Not reported

Gepaid: CAL000286068  
 Contact: FREDDY PATZI/OWNER  
 Telephone: 6192392477  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3280 MAIN ST STE 6  
 Mailing City,St,Zip: SAN DIEGO, CA 921133736  
 Gen County: San Diego  
 TSD EPA ID: OHD980587364  
 TSD County: 99  
 Waste Category: Solids or sludges with halogenated organic compounds > 1000mg/kg  
 Disposal Method: Transfer Station  
 Tons: 0.04  
 Facility County: San Diego

Gepaid: CAL000259406  
 Contact: FROILAN PATZI/OWNER  
 Telephone: 6193250830  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3280 MAIN ST STE 6  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: \*\*\*  
 Tons: 0.04  
 Facility County: Not reported

Gepaid: CAL000259406  
 Contact: FROILAN PATZI/OWNER  
 Telephone: 6193250830  
 Facility Addr2: Not reported  
 Mailing Name: FROILAN PATZI/OWNER  
 Mailing Address: 3158 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: OHD980587364

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**L C EMBROIDERY & CLEANERS (Continued)**

**S105807979**

TSD County: San Diego  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Not reported  
 Tons: 0.09  
 Facility County: San Diego

Gepaid: CAL000259406  
 Contact: FROILAN PATZI/OWNER  
 Telephone: 6193250830  
 Facility Addr2: Not reported  
 Mailing Name: FROILAN PATZI/OWNER  
 Mailing Address: 3158 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113

Gen County: San Diego  
 TSD EPA ID: OHD980587364  
 TSD County: San Diego  
 Waste Category: Liquids with halogenated organic compounds > 1000 mg/l  
 Disposal Method: Not reported  
 Tons: 0.1  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 2 additional CA\_HAZNET: record(s) in the EDR Site Report.

**CLEANERS:**

EPA Id: CAL000286068  
 NAICS Code: 81232  
 NAICS Description: Drycleaning and Laundry Services (except Coin-Operated)  
 Create Date: 8/27/2004  
 Facility Active: Yes  
 Inactive Date: Not reported  
 Facility Addr2: Not reported  
 Mailing Name: FREDDY PATZI/OWNER  
 Mailing Address: 3280 MAIN ST STE 6  
 Mailing Address 2: Not reported  
 Mailing State: CA  
 Mailing Zip: 921133736  
 Region Code: 4  
 Owner Name: FREDDY AGUSTIN PATZI  
 Owner Address: 3280 MAIN ST STE 6  
 Owner Address 2: Not reported  
 Owner Telephone: Not reported  
 Owner Fax Number: Not reported  
 Contact Name: FREDDY PATZI/OWNER  
 Contact Address: 3280 MAIN ST STE 6  
 Contact Address 2: Not reported  
 Contact Telephone: 6192392477  
 Contact Fax Number: 6193250830  
 SIC Description: 7211 Power Laundries Family and Commercial  
 SIC Description: 7212 Garment Pressing and Agents for Laundries and Drycleaners  
 SIC Description: 7216 Drycleaning Plants Except Rug Cleaning  
 SIC Description: 7219 Laundry and Garment Services NEC (alteration and repair)

EPA Id: CAL000259406  
 NAICS Code: 81232  
 NAICS Description: Drycleaning and Laundry Services (except Coin-Operated)  
 Create Date: 9/18/2002



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**L C EMBROIDERY & CLEANERS (Continued)**

**S105807979**

Facility Active: No  
 Inactive Date: 6/30/2004  
 Facility Addr2: Not reported  
 Mailing Name: FROILAN PATZI/OWNER  
 Mailing Address: 3158 MAIN ST  
 Mailing Address 2: Not reported  
 Mailing State: CA  
 Mailing Zip: 92113  
 Region Code: 4  
 Owner Name: FROILAN PATZI  
 Owner Address: 3280 MAIN ST STE 6  
 Owner Address 2: Not reported  
 Owner Telephone: Not reported  
 Owner Fax Number: Not reported  
 Contact Name: FROILAN PATZI/OWNER  
 Contact Address: 3280 MAIN ST STE 6  
 Contact Address 2: Not reported  
 Contact Telephone: 6193250830  
 Contact Fax Number: Not reported  
 SIC Description: 7211 Power Laundries Family and Commercial  
 SIC Description: 7216 Drycleaning Plants Except Rug Cleaning  
 SIC Description: 7212 Garment Pressing and Agents for Laundries and Drycleaners  
 SIC Description: 7219 Laundry and Garment Services NEC (alteration and repair)

93

**BUTLER BROTHERS CLEANERS  
 3280 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104755119  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 135649  
 Inactive Indicator: Active  
 Business Code: 6HK53  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3280 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/23/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE BUTLER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BUTLER LIVING TRUST 11-20-87  
 Property Address: 127 WHITE OAK DR  
 Property City,St,Zip: 91006  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BUTLER BROTHERS CLEANERS (Continued)**

**S104755119**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-8492

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 204275  
 Inactive Indicator: Active  
 Business Code: 6HK53  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BUTLER BROTHERS CLEANERS (Continued)**

**S104755119**

2nd Name: Not reported  
 Mailing Address: 3280 MAIN ST #6  
 Mailing City,St,Zip: San Diego, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 39  
 EPA ID: CAL000286068  
 Gas Station: Not reported  
 Inspection Date: 10/26/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: FROILAN PATZI/MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BUTLER LIVING TRUST 11-20-87  
 Property Address: 127 WHITE OAK DR  
 Property City,St,Zip: 91006  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/26/06  
 Facility Phone: 619-239-2477

**HMMD DISCLOSURE INVENTORY:**

Item Number: SY59  
 Chemical Name: SYNTHETIC ALIPHATIC HYDROCARBON DF-2000 SYNTHETIC ALIPHATIC HYDROCARBON DF-  
 Case Number: 64742-48-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BUTLER BROTHERS CLEANERS (Continued)**

**S104755119**

HMMD WASTE STREAMS:

Inspection Date: 10/26/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 1400  
 Annual Qty String: 1400  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: HYDROCARBON FILTERS  
 Carcinogen: No

94

**TRIPLE A SOUTH  
 3350 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST S102439255  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT754  
 Local Agency: San Diego  
 Substance: 0  
 Qty Leaked: 0  
 Date Found: 06/11/1987  
 How Found: Tank Closure  
 Date Stopped: 06/11/1987  
 How Stopped: Remove Contents  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 9/15/87  
 Pilot Program: LOP  
 Local Case: H20594-001  
 Basin Number: 908.21  
 Gwater Depth: 9-12  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 06/19/1987  
 Interim Remedial Actions: Yes

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIPLE A SOUTH (Continued)**

**S102439255**

Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3350 MAIN ST

94

**BABYLAND DIAPER SERVICE**  
**3348 MAIN ST**  
**SAN DIEGO, CA 92113**

**LUST**  
**Cortese**  
**San Diego Co. HMMD**  
**SWEEPS UST**  
**SAN DIEGO CO. SAM**

**S101302068**  
**N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300131  
 Stop Date: 1988-12-14 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-05-04 00:00:00  
 Discover Date: 1988-12-14 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-12-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: MR. RICHMAN  
 RP Address: 45 KNIGHTS BRIDGE RD  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

Staff: UNA  
 Staff Initials: MF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02238-001  
 Case Number: 9UT1127  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301239  
 Stop Date: 1993-04-26 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-07-05 00:00:00  
 Discover Date: 1993-04-26 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1993-04-26 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: ANNIE DAVIES

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

RP Address: 10340 BONNIE LN  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02238-002  
 Case Number: 9UT2485  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT1127  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 12/14/1988  
 How Found: Not reported  
 Date Stopped: 12/14/1988  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 12/14/1988  
 Submit Workplan: Not reported  
 Prelim Assess: 02/10/1989  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 5/4/89  
 Pilot Program: LOP  
 Local Case: H02238-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

Basin Number: 908.22  
 Gwater Depth: 15'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 12/14/1988  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT2485  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 04/26/1993  
 How Found: Tank Closure  
 Date Stopped: 04/26/1993  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 04/27/1993  
 Submit Workplan: 4/26/93  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 7/5/00  
 Pilot Program: LOP  
 Local Case: H02238-002  
 Basin Number: 908.22  
 Gwater Depth: 15'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 04/27/1993  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3348 MAIN ST

Region: CORTESE  
 Facility Addr2: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

San Diego Co. HMMD:

Facility ID: 102238  
 Inactive Indicator: Active  
 Business Code: 6HK54  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 7685 SIEMPRE VIVA RD  
 Mailing City,St,Zip: SAN DIEGO, CA 92154  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 07/03/03  
 Reinspection Date: Not reported  
 Inspector Name: MNYAGA  
 Violation Notice Issued: Not reported  
 Facility Contact: JOHN DRAKE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DAVIES ANNA S TR  
 Property Address: 2399 CAMINO DEL RIO  
 Property City,St,Zip: 92108  
 Tank Owner: ANNA DAVIES  
 Tank Address: 10340 BONNIE LANE  
 Tank City,St,Zip: 92041  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/03/05  
 Facility Phone: 619-232-3511

HMMD DISCLOSURE INVENTORY:

Item Number: BL40  
 Chemical Name: BLEACH-SODIUM HYPOCHLORITE  
 Case Number: 7681-52-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: DI42  
 Chemical Name: DIRECT FAST SCARLET (RED DYE DP5+DF)  
 Case Number: mixture  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: DY39  
 Chemical Name: DYNA SOFT  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: RA38  
 Chemical Name: RAGGER DETERGENT NAOH  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: SO41  
 Chemical Name: SODIUM THIOSULFATE; ANTI-CHLOR  
 Case Number: 7772-98-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT2898  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 11/19/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9639  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/08/99  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 2256  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 03/08/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 2257  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 01/29/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3551  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/03/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 1951  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 07/03/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 10  
 Annual Qty String: 10  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9999 SELF:SMALL QTY EXEMP  
 Waste Desc: GEAR OIL  
 Carcinogen: No

Facility ID: 133671  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 10340 BONNIE LN  
 Mailing City,St,Zip: LA MESA, CA 92041  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

Gas Station: Not reported  
 Inspection Date: 02/25/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DAVIES ANNA S TR  
 Property Address: 2399 CAMINO DEL RIO  
 Property City,St,Zip: 92108  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: 02/25/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3002  
 Occurrences: Not reported  
 Item Number: 9217  
 Violation Desc: UST OWNR-OPR W/O HEALTH PERMIT

Inspection Date: 02/25/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3007  
 Occurrences: Not reported  
 Item Number: 9218  
 Violation Desc: NO PERMIT FOR UST REPAIR/UPGRADE/REMOVAL

Inspection Date: 02/25/93  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

Type of Violation: 6HX3010  
 Occurrences: Not reported  
 Item Number: 9219  
 Violation Desc: PERMIT TO OPERATE APPLIC. NOT COMPLETED

Inspection Date: 02/25/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 9220  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 02/25/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 9221  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 02/25/93  
 Waste Code: Not reported  
 Type of Violation: 6HV3018  
 Occurrences: Not reported  
 Item Number: 9222  
 Violation Desc: IMPROPER INVENTORY RECONCILIATION

Inspection Date: 02/25/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3030  
 Occurrences: Not reported  
 Item Number: 9223  
 Violation Desc: NO RELEASE RECORD LOG

Inspection Date: 02/25/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 9224  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

SWEEPS UST:

Status: Not reported  
 Comp Number: 2238  
 Number: Not reported  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002238-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 1

Status: A  
 Comp Number: 2238  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002238-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 2

Status: A  
 Comp Number: 2238  
 Number: 9  
 Board Of Equalization: Not reported  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002238-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

SAN DIEGO CO. SAM:

Case Number: H02238-001  
 Agency: DEH Site Assessment & Mitigation  
 Funding: LOP - State Fund

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EDR ID Number  
 EPA ID Number

**BABYLAND DIAPER SERVICE (Continued)**

**S101302068**

FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/4/1989  
 Begandt: 12/14/1988  
  
 Case Number: H02238-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 7/5/2000  
 Begandt: 4/26/1993

**94 PCE & BAYSIDE HARBOR PROPERTY  
 3348 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S108752853  
 N/A**

HAZNET:  
 Gepaid: CAC002604311  
 Contact: DAVID CLAPP  
 Telephone: 6192350961  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13606  
 Mailing City,St,Zip: SAN DIEGO, CA 921703606  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 10.36  
 Facility County: San Diego

**94 RIGEL STREET DRUM  
 SAN DIEGO, CA**

**NPL LIENS S100700141  
 N/A**

**94 PACIFIC SHIP REPAIR& FABRICATION  
 1625 RIGEL STREET  
 SAN DIEGO, CA 92113**

**FINDS 1000249968  
 HAZNET CAD053854451  
 RCRA-LQG  
 San Diego Co. HMMD  
 AIRS  
 SWEEPS UST**

FINDS:  
 Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

**HAZNET:**

Gepaid: CAD053854451  
 Contact: PACIFIC SHIP RPR & FABRI INC  
 Telephone: 6192323200  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1625 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133808  
 Gen County: Los Angeles  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 1.2218  
 Facility County: Los Angeles

Gepaid: CAD053854451  
 Contact: PACIFIC SHIP RPR & FABRI INC  
 Telephone: 6192323200  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1625 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133808  
 Gen County: Los Angeles  
 TSD EPA ID: AZD980892731  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: .1500  
 Facility County: Los Angeles

Gepaid: CAD053854451  
 Contact: PACIFIC SHIP RPR & FABRI INC  
 Telephone: 6192323200



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1625 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133808  
 Gen County: Los Angeles  
 TSD EPA ID: AZD980892731  
 TSD County: 99  
 Waste Category: Aqueous solution with metals (restricted levels and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc )  
 Disposal Method: Not reported  
 Tons: .2085  
 Facility County: Los Angeles

Gepaid: CAD053854451  
 Contact: PACIFIC SHIP RPR & FABRI INC  
 Telephone: 6192323200  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1625 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133808  
 Gen County: Los Angeles  
 TSD EPA ID: AZD980892731  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .8250  
 Facility County: Los Angeles

Gepaid: CAD053854451  
 Contact: PACIFIC SHIP RPR & FABRI INC  
 Telephone: 6192323200  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1625 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133808  
 Gen County: Los Angeles  
 TSD EPA ID: AZD980892731  
 TSD County: 99  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Not reported  
 Tons: .0200  
 Facility County: Los Angeles

[Click this hyperlink](#) while viewing on your computer to access 105 additional CA\_HAZNET: record(s) in the EDR Site Report.

**RCRA-LQG:**

Date form received by agency: 02/07/2006  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Facility address: 1625 RIGEL STREET  
 SAN DIEGO, CA 92113  
 EPA ID: CAD053854451  
 Contact: LISA L SIPES  
 Contact address: Not reported  
 Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Contact country: Not reported  
 Contact telephone: (619) 232-3200  
 Telephone ext.: 155  
 Contact email: LSIPES@PACSHIP.COM  
 EPA Region: 09  
 Land type: Private  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

**Owner/Operator Summary:**

Owner/operator name: NORTH RICHMOND PROPERTIES  
 Owner/operator address: 1625 RIGEL STREET  
 SAN DIEGO, CA 92113  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 12/31/1997  
 Owner/Op end date: Not reported

Owner/operator name: PACIFIC SHIP REPAIR & FABRICATION  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 12/01/1987  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Historical Generators:

Date form received by agency: 02/18/2004  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR & FABRICATION, INC  
 Classification: Large Quantity Generator

Date form received by agency: 02/25/2002  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR RIGEL ST  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR RIGEL ST  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR & FAB  
 Classification: Large Quantity Generator

Date form received by agency: 02/27/1996  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR & FAB.  
 Classification: Large Quantity Generator

Date form received by agency: 03/24/1994  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR AND FAB  
 Classification: Large Quantity Generator

Date form received by agency: 03/30/1992  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR & FABRICATION  
 Classification: Large Quantity Generator

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Date form received by agency: 05/04/1990  
 Facility name: PACIFIC SHIP REPAIR & FABRICATION  
 Site name: PACIFIC SHIP REPAIR & FABRICATION  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003  
 Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D005  
 Waste name: BARIUM

Waste code: D006  
 Waste name: CADMIUM

Waste code: D007  
 Waste name: CHROMIUM

Waste code: D008  
 Waste name: LEAD

Waste code: D011  
 Waste name: SILVER

Waste code: D018  
 Waste name: BENZENE

Waste code: D035  
 Waste name: METHYL ETHYL KETONE

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE

Waste code: D040  
 Waste name: TRICHLOROETHYLENE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 14930.1

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 5

Waste code: D005  
 Waste name: BARIUM  
 Amount (Lbs): 8050

Waste code: D006  
 Waste name: CADMIUM  
 Amount (Lbs): 10600

Waste code: D007  
 Waste name: CHROMIUM  
 Amount (Lbs): 10600

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Waste code: D008  
 Waste name: LEAD  
 Amount (Lbs): 10600

Waste code: D011  
 Waste name: SILVER  
 Amount (Lbs): 8050

Waste code: D018  
 Waste name: BENZENE  
 Amount (Lbs): 6130.1

Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Amount (Lbs): 8050

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE  
 Amount (Lbs): 6130.1

Waste code: D040  
 Waste name: TRICHLOROETHYLENE  
 Amount (Lbs): 6130.1

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 8050

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 01/24/2006  
 Date achieved compliance: 02/28/2006  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 01/24/2006  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 01/24/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Area of violation: Generators - General  
 Date achieved compliance: 02/28/2006  
 Evaluation lead agency: Local

Evaluation date: 02/23/2004  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/25/2002  
 Evaluation: FOCUSED COMPLIANCE INSPECTION  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

**San Diego Co. HMMD:**

Facility ID: 115789  
 Inactive Indicator: Active  
 Business Code: 6HK71  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1625 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAD053854451  
 Gas Station: Not reported  
 Inspection Date: 02/23/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DENNIS STONE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: NORTH RICHMOND PROPERTIES INC  
 Property Address: 32 WASHINGTON AVE  
 Property City,St,Zip: 94801  
 Tank Owner: TRIPLE  
 Tank Address: A  
 Tank City,St,Zip: HUNTRS POINT, 94 San  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/23/05  
 Facility Phone: 619-232-3200

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC56  
 Chemical Name: ACETYLENE GAS  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR58  
 Chemical Name: ARGON GAS HELLIUM MIX  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: CA64  
 Chemical Name: CARBON DIOXIDE-LIQUID  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: DI59  
 Chemical Name: DIESEL NO.2  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: HE62  
 Chemical Name: HELIUM COMPRESSED GAS  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: LI55  
 Chemical Name: LIQUID PROPANE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: OI60  
 Chemical Name: OILS; HYDRAULIC, MOTOR, & LUBE  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX57  
 Chemical Name: OXY GEN GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PA63  
 Chemical Name: PAINT(S)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: SO65  
 Chemical Name: SOLVENT (1200-EL CLEANER)  
 Case Number: 8052-41-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Item Number: VA61  
 Chemical Name: VARNISH  
 Case Number: 8030-30-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: #1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: #2  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: #3  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T004  
 Tank ID Number: #4  
 Waste or Product: Not reported  
 Tank Contents: LEADED

**HMMD VIOLATIONS:**

Inspection Date: 06/16/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 4750  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 06/16/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 4751  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 5492  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

**HMMD WASTE STREAMS:**

Inspection Date: 02/23/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 6000  
 Annual Qty String: 6000  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: STOCK PILE  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: PRESSURE TREATED WOOD (AR  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 3100  
 Annual Qty String: 3100  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: AUTOSHOP  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 222  
 Waste Code: 222  
 Waste Name: OIL/WATER SEPARATION  
 Qnty at Inspection: 225  
 Quantity String: 225  
 Annual Qty: 420  
 Annual Qty String: 420  
 Measurement Unit: GAL  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: OIL/SEPARATOR SLUDGE  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: MACHINE COOLANT/ STEEL SH  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 330  
 Annual Qty String: 330  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: EPOXY/ FORMALDAHYDE  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 16160  
 Annual Qty String: 16160  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2951 A & S ENVIRONMENTAL  
 Waste Desc: PAINT CHIPS, OIL DEBRIS,  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: PCB BALLASTS & NON PCB BA  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 300  
 Annual Qty String: 300

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Measurement Unit: GAL  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 2100  
 Annual Qty String: 2100  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: INCLDS PWDR WST RSD/OVRSP  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 513  
 Waste Code: 513  
 Waste Name: EMPTY CONTNR(LESS TH  
 Qnty at Inspection: 60  
 Quantity String: 60  
 Annual Qty: 580  
 Annual Qty String: 580  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: AEROSOL CANS  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 551  
 Waste Code: 551  
 Waste Name: LABORATORY WASTE CHE  
 Qnty at Inspection: 25  
 Quantity String: 25  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 008 NEUTRALIZATION  
 Storage Method: CARBOY  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: WASTE CORROSIVE LAB-PACK  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 551  
 Waste Code: 551  
 Waste Name: LABORATORY WASTE CHE  
 Qnty at Inspection: 40

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Quantity String: 40  
 Annual Qty: 1630  
 Annual Qty String: 1630  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: WST FLMMBLE LQDS LAB-PACK  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 551  
 Waste Code: 551  
 Waste Name: LABORATORY WASTE CHE  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 70  
 Annual Qty String: 70  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: PENTANE, NITROGEN, CO, CH  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 551  
 Waste Code: 551  
 Waste Name: LABORATORY WASTE CHE  
 Qnty at Inspection: 25  
 Quantity String: 25  
 Annual Qty: 25  
 Annual Qty String: 25  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: CARBOY  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: WST HYDRGN PEROXIDE LB-PK  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 551  
 Waste Code: 551  
 Waste Name: LABORATORY WASTE CHE  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: CARBOY  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: WASTE CYANIDE LAB-PACK  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 591

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Waste Code: 591  
 Waste Name: BAGHOUSE WASTE  
 Qnty at Inspection: 440  
 Quantity String: 440  
 Annual Qty: 13300  
 Annual Qty String: 13300  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0816 INDUSTRIAL WASTE UTI  
 Waste Desc: SANDBLAST WASTE  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 741  
 Waste Code: 741  
 Waste Name: LIQ W HALOG ORG >OR=  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 740  
 Annual Qty String: 740  
 Measurement Unit: Not reported  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PETROLEUM NAPHTHA (PARTS W  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 860  
 Waste Code: 860  
 Waste Name: UNIVERSAL WASTE CRTS  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 1050  
 Annual Qty String: 1050  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: GEN. ENV. MGMT.  
 Carcinogen: No

Inspection Date: 02/23/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

EMI:

Year: 1990  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7067  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 8  
 Reactive Organic Gases Tons/Yr: 7  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1995  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7067  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 6  
 Reactive Organic Gases Tons/Yr: 5  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1996  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7067  
 Air District Name: SD  
 SIC Code: 3731  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 6  
 Reactive Organic Gases Tons/Yr: 5  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1997  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7067  
 Air District Name: SD



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

SIC Code:	3731
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7067
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7067
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7067
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7067
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7067
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	7067
Air District Name:	SD
SIC Code:	1721
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.8643631
Reactive Organic Gases Tons/Yr:	0.8263175
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.028414496
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0.028414496

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 7067  
 Air District Name: SD  
 SIC Code: 1721  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: .84  
 Reactive Organic Gases Tons/Yr: .8  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: .0457487440239850903  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: .027881

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 15789  
 Number: Not reported  
 Board Of Equalization: 44-022925  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015789-000001  
 Actv Date: Not reported  
 Capacity: 4000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: 4

Status: Not reported  
 Comp Number: 15789  
 Number: Not reported  
 Board Of Equalization: 44-022925  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015789-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 15789  
 Number: Not reported  
 Board Of Equalization: 44-022925  
 Ref Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR & FABRICATION (Continued)**

**1000249968**

Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015789-000003  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 15789  
 Number: Not reported  
 Board Of Equalization: 44-022925  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-015789-000004  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 15789  
 Number: 9  
 Board Of Equalization: 44-022925  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

94

**PACIFIC SHIP REPAIR AND FABRICATION  
 1625 RIGEL AVENUE  
 SAN DIEGO, CA 92113**

**FTTS 1009520096  
 HIST FTTS N/A**

FTTS INSP:  
 Inspection Number: Not reported  
 Region: 09  
 Inspection Date: Not reported  
 Inspector: FRAZER/LOPEZ/WOLF  
 Violation occurred: No  
 Investigation Type: EPCRA, Enforcement, Federal Conducted  
 Investigation Reason: Neutral Scheme, Region

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC SHIP REPAIR AND FABRICATION (Continued)**

**1009520096**

Legislation Code: EPCRA  
 Facility Function: Manufacturer

**HIST FTTS INSP:**

Inspection Number: 20060823RF01 1  
 Region: 09  
 Inspection Date: Not reported  
 Inspector: FRAZER/LOPEZ/WOLF  
 Violation occurred: No  
 Investigation Type: EPCRA, Enforcement, Federal Conducted  
 Investigation Reason: Neutral Scheme, Region  
 Legislation Code: EPCRA  
 Facility Function: Manufacturer

**94 PROPULSION CONTROLS ENGINEERING  
 1620 RIGEL ST  
 SAN DIEGO, CA 92113**

**FINDS 1010497709  
 110032641924**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**94 PROPULSION CONTROLS ENGINEERING  
 1620 RIGEL ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1010561983  
 CAR000185405**

**RCRA-SQG:**

Date form received by agency: 06/26/2007  
 Facility name: PROPULSION CONTROLS ENGINEERING  
 Facility address: 1620 RIGEL ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000185405  
 Mailing address: PO BOX 13606  
 SAN DIEGO, CA 92170 3606  
 Contact: KATY SANFORD  
 Contact address: PO BOX 13606  
 SAN DIEGO, CA 92170 3606  
 Contact country: US  
 Contact telephone: 619-235-0961  
 Telephone ext.: 304  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PROPULSION CONTROLS ENGINEERING (Continued)**

**1010561983**

hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: PROPULSION CONTROLS ENGINEERING  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: Not reported  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 04/09/2007  
 Owner/Op end date: Not reported

Owner/operator name: JOHN P REILLY III  
 Owner/operator address: 1620 RIGEL ST  
 SAN DIEGO, CA 92113

Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1996  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D040  
 Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**94 PLENUMS PLUS\_INC  
 1620 RIGEL STREET  
 SAN DIEGO, CA 92113**

**HAZNET S102793458  
 N/A**

HAZNET:

Gepaid: CAC000732352  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1620 RIGEL STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD004771168  
 TSD County: San Francisco  
 Waste Category: Other empty containers 30 gallons or more  
 Disposal Method: Not reported  
 Tons: .1400  
 Facility County: San Diego

Gepaid: CAC000732352  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1620 RIGEL STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD044429835  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .1250  
 Facility County: San Diego

Gepaid: CAC000732352  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1620 RIGEL STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD083166728  
 TSD County: Stanislaus  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 1.6680  
 Facility County: San Diego

Gepaid: CAC000732352  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1620 RIGEL STREET  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD083166728

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PLENUMS PLUS\_INC (Continued)**

**S102793458**

TSD County: Stanislaus  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: 1.6680  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

94

**A & B COPP INC  
 1620 RIGEL ST  
 SAN DIEGO, CA 92113**

**HAZNET S103948134  
 N/A**

HAZNET:

Gepaid: CAC001361808  
 Contact: A & B COPP INC  
 Telephone: 6192347587  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1620 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Adhesives  
 Disposal Method: Disposal, Other  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAC001361808  
 Contact: A & B COPP INC  
 Telephone: 6192347587  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1620 RIGEL ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

94

**RIGEL STREET DRUM SITE  
 1620 RIGEL ST  
 SAN DIEGO, CA 92113**

**CERC-NFRAP 1003879036  
 LIENS 2 CAD982029423**

CERC-NFRAP:

Site ID: 0902535  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

CERCLIS-NFRAP Site Contact Name(s):

Contact Name: Matt Mitguard



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RIGEL STREET DRUM SITE (Continued)**

**1003879036**

Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: INDUSTRIAL MARINE INC  
 Alias Address: Not reported  
 CA

Alias Name: NATIONAL ANODIZING INC  
 Alias Address: Not reported  
 CA

Site Description: 500 CONTAINERS OF CAUSTICS, FLAMMABLES, OXIDIZERS, CYANIDES, STORED IN LEAKING CONTAINERS ALONGSIDE A CREEK POSED THE THREAT OF CYANIDE GAS RELEASES, FIRES, EXPLOSIONS, AND RUN OFF TO SAN DIEGO BAY.

CERCLIS-NFRAP Assessment History:

Action: UNILATERAL ADMIN ORDER  
 Date Started: Not reported  
 Date Completed: 02/09/1987  
 Priority Level: Not reported

Action: REMOVAL  
 Date Started: 02/05/1987  
 Date Completed: 05/29/1987  
 Priority Level: Cleaned up

Action: ADMINISTRATIVE RECORDS  
 Date Started: 06/24/1988  
 Date Completed: 06/24/1988  
 Priority Level: Admin Record Compiled for a Removal Event

Action: NON-NATIONAL PRIORITIES LIST POTENTIALLY RESPONSIBLE PARTY SEARCH  
 Date Started: 02/04/1988  
 Date Completed: 06/30/1988  
 Priority Level: Search Complete, Viable PRPs

Action: ADMINISTRATIVE/VOLUNTARY COST RECOVERY  
 Date Started: Not reported  
 Date Completed: 09/09/1988  
 Priority Level: Not reported

Action: ADMINISTRATIVE ORDER ON CONSENT  
 Date Started: Not reported  
 Date Completed: 09/09/1988  
 Priority Level: Not reported

Action: COST RECOVERY NEGOTIATIONS  
 Date Started: 03/08/1988  
 Date Completed: 09/09/1988  
 Priority Level: Not reported

Action: ADMINISTRATIVE/VOLUNTARY COST RECOVERY  
 Date Started: Not reported  
 Date Completed: 02/06/1989

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**RIGEL STREET DRUM SITE (Continued)**

**1003879036**

Priority Level: Not reported  
 Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 01/23/1996  
 Priority Level: Not reported

**LIENS 2:**

Facility name: RIGEL STREET DRUM SITE  
 Facility address: 1620 RIGEL ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD982029423  
 Action: LP001 - Lien on PRP property  
 Start date: 09/25/1987  
 Complete date: Not reported  
 Notice date: Not reported  
 Enforcemant date: Not reported  
 Reardon date: Not reported  
 Statutes: Not reported

94

**TRIPLE "A" SOUTH  
 PO BOX 13097  
 SAN DIEGO, CA 92113**

**HIST UST U001572998  
 N/A**

**HIST UST:**

Region: STATE  
 Facility ID: 00000010257  
 Facility Type: Other  
 Other Type: SHIP REPAIR  
 Total Tanks: 0009  
 Contact Name: Not reported  
 Telephone: 6192361391  
 Owner Name: TRIPLE A MACHINE SHOP INC.  
 Owner Address: BUILDING 214 HUNTERS POINTSHIP  
 Owner City,St,Zip: SAN FRANCISCO, CA 94124

Tank Num: 001  
 Container Num: #1  
 Year Installed: 1979  
 Tank Capacity: 00004000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Pressure Test

Tank Num: 002  
 Container Num: #2  
 Year Installed: 1977  
 Tank Capacity: 00000550  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 003  
 Container Num: #3  
 Year Installed: 1977

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**TRIPLE "A" SOUTH (Continued)**

**U001572998**

Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 004  
 Container Num: #4  
 Year Installed: 72-7  
 Tank Capacity: 00002000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Not reported

Tank Num: 005  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

Tank Num: 006  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00012000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

Tank Num: 007  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

Tank Num: 008  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

Tank Num: 009  
 Container Num: 5  
 Year Installed: 1977  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRIPLE "A" SOUTH (Continued)**

**U001572998**

Tank Construction: Not reported  
 Leak Detection: Visual

94

**AEROSPACE COATINGS & TECH  
 1610 RIGEL ST  
 SAN DIEGO, CA 92113**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S106059766  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608173970  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-01-30 00:00:00  
 Discover Date: 1987-01-30 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-01-30 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: 0  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AEROSPACE COATINGS & TECH (Continued)**

**S106059766**

Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01472-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 101472  
 Inactive Indicator: Active  
 Business Code: 6HK07  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 6980 CONVOY COURT  
 Mailing City,St,Zip: SAN DIEGO, CA 92111  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: CAD981985732  
 Gas Station: Not reported  
 Inspection Date: 05/17/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: DEL FULLER/MGR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SEGAWA JERRY&PAMELA  
 Property Address: 1864 NATIONAL AVE  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-696-0185

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AEROSPACE COATINGS & TECH (Continued)**

**S106059766**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 6102  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HV0499  
 Occurrences: Not reported  
 Item Number: 6103  
 Violation Desc: NO EMPLOYEE TRAINING FOR ER RESPONSE

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0001  
 Occurrences: Not reported  
 Item Number: 6104  
 Violation Desc: CONTINGENCY PLAN NOT PROVIDED

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HV0212  
 Occurrences: Not reported  
 Item Number: 6105  
 Violation Desc: INCOMPATIBLE WASTE NOT SEPARATED

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 6106  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0023  
 Occurrences: Not reported  
 Item Number: 6107  
 Violation Desc: HAZWASTE DISPOSAL TO GROUND

Inspection Date: 05/08/86

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AEROSPACE COATINGS & TECH (Continued)**

**S106059766**

Waste Code: Not reported  
 Type of Violation: 6HX0069  
 Occurrences: Not reported  
 Item Number: 6108  
 Violation Desc: STORAGE OF WASTE FOR LONGER THAN 90 DAYS

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0042  
 Occurrences: Not reported  
 Item Number: 6109  
 Violation Desc: HAZWASTE CONT. NOT LABELED OR MARKED

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0043  
 Occurrences: Not reported  
 Item Number: 6110  
 Violation Desc: HAZWASTE CONT. NOT DATED WITH START DATE

Inspection Date: 05/08/86  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 6101  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 01/29/87  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 6319  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 01/29/87  
 Waste Code: Not reported  
 Type of Violation: 6HV0198  
 Occurrences: Not reported  
 Item Number: 6320  
 Violation Desc: SEWER PERMIT NOT AVAILABLE

Inspection Date: 01/29/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 6321  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 01/29/87  
 Waste Code: Not reported  
 Type of Violation: 6HV0499  
 Occurrences: Not reported  
 Item Number: 6322  
 Violation Desc: NO EMPLOYEE TRAINING FOR ER RESPONSE

Inspection Date: 01/29/87  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AEROSPACE COATINGS & TECH (Continued)**

**S106059766**

Type of Violation: 6HX0001  
 Occurrences: Not reported  
 Item Number: 6323  
 Violation Desc: CONTINGENCY PLAN NOT PROVIDED

Inspection Date: 05/17/88  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6687  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 05/17/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0042  
 Occurrences: Not reported  
 Item Number: 6688  
 Violation Desc: HAZWASTE CONT. NOT LABELED OR MARKED

Inspection Date: 05/17/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0043  
 Occurrences: Not reported  
 Item Number: 6689  
 Violation Desc: HAZWASTE CONT. NOT DATED WITH START DATE

Inspection Date: 05/17/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0044  
 Occurrences: Not reported  
 Item Number: 6690  
 Violation Desc: HAZWASTE CONT-NO STATE,COMP,PROP,OR GEN

Inspection Date: 05/17/88  
 Waste Code: Not reported  
 Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 6691  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

Inspection Date: 05/17/88  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6692  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AEROSPACE COATINGS & TECH (Continued)**

**S106059766**

Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H01472-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/30/1987  
 Begandt: 1/30/1987

**94 RIGEL STREET DRUM (AMMENDED - SEE #17)**  
**SAN DIEGO, CA**

**NPL LIENS S100700148**  
**N/A**

**95 ON GROUND**  
**3654 BETA ST**  
**SAN DIEGO, CA 92113**

**Notify 65 S100178570**  
**N/A**

Notify 65:  
 Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92113-3929

**96 MEMORIAL AREA MIDDLE SCHOOL ALT SITE C**  
**4103 BETA STREET**  
**SAN DIEGO, CA 92113**

**SCH S107736718**  
**ENVIROSTOR N/A**

**SCH:**

Facility ID: 60000118  
 Site Type: School Investigation  
 Site Type Detail: School  
 Acres: 16.4  
 National Priorities List: NO  
 Cleanup Oversight Agencies: SMBRP  
 Lead Agency: SMBRP  
 Lead Agency Description: DTSC - Site Mitigation And Brownfield Reuse Program  
 Project Manager: TAWFIQ DEEK  
 Supervisor: Shahir Haddad  
 Division Branch: School Evaluation - Cypress  
 Site Code: 404598-11  
 Assembly: 79  
 Senate: 40

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MEMORIAL AREA MIDDLE SCHOOL ALT SITE C (Continued)**

**S107736718**

Special Program Status: Not reported  
 Status: Inactive - Action Required  
 Status Date: 2005-01-28 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.689843  
 Longitude: -117.104419  
 Alias Name: 404598-11  
 SAN DIEGO SD-MEMRL AREA MID SCL ALT C  
 60000118  
 Alias Type: Project Code (Site Code)  
 Envirostor ID Number  
 Alternate Name  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported  
 Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 12/05/05  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Phase 1  
 Completed Date: 01/28/05  
 Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NMA  
 Media Affected Desc: Not reported  
 Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED,31000  
 Potental Description: Not reported  
 Potenital Description: No Contaminants found  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: RESIDENTIAL AREA  
 ENVIROSTOR:  
 Site Type: School Investigation  
 Site Type Detailed: School  
 Acres: 16.4  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MEMORIAL AREA MIDDLE SCHOOL ALT SITE C (Continued)**

**S107736718**

Program Manager: TAWFIQ DEEK  
 Supervisor: Shahir Haddad  
 Division Branch: School Evaluation - Cypress  
 Facility ID: 60000118  
 Site Code: 404598-11  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Inactive - Action Required  
 Status Date: 2005-01-28 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.689843  
 Longitude: -117.104419  
 Alias Name: 404598-11  
                   SAN DIEGO SD-MEMRL AREA MID SCL ALT C  
                   60000118  
 Alias Type: Project Code (Site Code)  
                   Envirostor ID Number  
                   Alternate Name  
  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported  
  
 Completed Info:  
   Completed Area Name: PROJECT WIDE  
   Completed Sub Area Name: Not reported  
   Completed Document Type: Cost Recovery Closeout Memo  
   Completed Date: 12/05/05  
  
   Completed Area Name: PROJECT WIDE  
   Completed Sub Area Name: Not reported  
   Completed Document Type: Phase 1  
   Completed Date: 01/28/05  
  
 Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NMA  
 Media Affected Desc: Not reported  
  
 Management:  
   Management Required: NONE SPECIFIED  
   Management Required Desc: Not reported  
   Potential: NONE SPECIFIED,31000  
   Potential Description: Not reported  
   Potential Description: No Contaminants found  
   Schedule Area Name: Not reported  
   Schedule Sub Area Name: Not reported  
   Schedule Document Type: Not reported  
   Schedule Due Date: Not reported  
   Schedule Revised Date: Not reported  
   PastUse: RESIDENTIAL AREA

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>97</b>	<b>PUBLIC WORKS CENTER</b> <b>BLDG 132 32ND ST</b> <b>NS SAN DIEGO, CA 92136</b>	<b>LUST</b>	<b>S101301896</b> <b>N/A</b>
-----------	--	-------------	---------------------------------

LUST:

Region:	9
Case Number:	9UT2646
Local Agency:	San Diego
Substance:	Diesel
Qty Leaked:	Not reported
Date Found:	06/11/1993
How Found:	Tank Closure
Date Stopped:	06/11/1993
How Stopped:	Close Tank
Source:	Unknown
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Other ground water affected
Status:	Case Closed
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Confirm Date:	06/11/1993
Submit Workplan:	Not reported
Prelim Assess:	06/11/1993
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	12/1/93
Began Monitor:	Not reported
Enforce Type:	Not reported
Enforce Date:	Not reported
Closed Date:	8/17/94
Pilot Program:	LOP
Local Case:	H01447-028
Basin Number:	908.32
Gwater Depth:	8'
Beneficial Use:	NBNABB/E
NPDES Number:	Not reported
priority:	3
File Dispn:	Not reported
Release Date:	08/05/1993
Interim Remedial Actions:	Yes
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

<b>98</b>	<b>FRASER'S BOILER SERV INC @ NAVAL STATION</b> <b>32ND ST NAVAL STATION</b> <b>SAN DIEGO, CA 92133</b>	<b>Notify 65</b> <b>HAZNET</b> <b>CHMIRS</b>	<b>S100178493</b> <b>N/A</b>
-----------	---	--	---------------------------------

Notify 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Incident Description:	92102

HAZNET:

Gepaid:	CAL000160296
Contact:	ANDY MACIAS QA. MANG.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

FRASER'S BOILER SERV INC @ NAVAL STATION (Continued)

S100178493

Telephone: 6192330195  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1746 NEWTON AVE  
 Mailing City,St,Zip: SAN DIEGO, CA 921131014  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 0.66  
 Facility County: Not reported

CHMIRS:

OES Incident Number: 02-4536  
 OES notification: 8/21/200207:39:53 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities:Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

FRASER'S BOILER SERV INC @ NAVAL STATION (Continued)

S100178493

Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	NRC
Incident Date:	8/21/200212:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Unknown
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Sheen
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Per the NRC report, caller is reporting an unknown sheen sighting.SUBSTANCE NOTICED NEAR SHIP COMING FROM UNDERNEATH. SUBSTANCE APPEARS TO BE BREAKING UP. seal leaked oil out onto the engine
OES Incident Number:	97-1437
OES notification:	4/10/199712:38:29 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
<b>Date Completed:</b>	<b>Not reported</b>
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agency Personel # Of Decontaminated:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FRASER'S BOILER SERV INC @ NAVAL STATION (Continued)**

**S100178493**

Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Reporting Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1997  
 Agency: Navy Public Works Center  
 Incident Date: 4/10/1997 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: Oil  
 Quantity Released: Not reported  
 BBLS: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0.000000  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 1  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: Per the NRC report, caller is reporting an unknown sheen sighting. SUBSTANCE NOTICED NEAR SHIP COMING FROM UNDERNEATH. SUBSTANCE APPEARS TO BE BREAKING UP. seal leaked oil out onto the engine  
 OES Incident Number: 97-4699

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

FRASER'S BOILER SERV INC @ NAVAL STATION (Continued)

S100178493

OES notification: 11/25/199709:17:38 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: SAN DIEGO BAY  
 Spill Site: Not reported  
 Cleanup By: NO  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1997  
 Agency: USN  
 Incident Date: 11/25/199712:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: No  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: OIL  
 Quantity Released: Not reported  
 BBLs: 0



MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

---

**FRASER'S BOILER SERV INC @ NAVAL STATION (Continued)**

**S100178493**

Cups:	0	
CUFT:	0	
Gallons:	3-5	
Grams:	0	
Pounds:	0	
Liters:	0	
Ounces:	0	
Pints:	0	
Quarts:	0	
Sheen:	0	
Tons:	0	
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	Per the NRC report, caller is reporting an unknown sheen sighting.SUBSTANCE NOTICED NEAR SHIP COMING FROM UNDERNEATH. SUBSTANCE APPEARS TO BE BREAKING UP. seal leaked oil out onto the engine	

**98 24TH ST MARINE TERMINAL  
FOOT OF 24TH ST  
SAN DIEGO, CA**

**Notify 65 S100179334  
N/A**

Notify 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Incident Description:	Not reported

**99 CO FLEET TRAINING CENTER  
32ND ST  
NS SAN DIEGO, CA 92136**

**LUST S101308212  
N/A**

LUST:

Region:	9
Case Number:	9UT1754
Local Agency:	San Diego
Substance:	Waste Oil
Qty Leaked:	Not reported
Date Found:	04/14/1989
How Found:	Not reported
Date Stopped:	04/14/1989
How Stopped:	Not reported
Source:	Not reported
Cause:	Not reported
Lead Agency:	Local Agency
Case Type:	Other ground water affected
Status:	Case Closed
Abate Method:	No Action Required - incident is minor, requiring no remedial action
Confirm Date:	05/22/1989
Submit Workplan:	Not reported
Prelim Assess:	08/02/1993
Desc Pollution:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CO FLEET TRAINING CENTER (Continued)**

**S101308212**

Remed Plan: 04/14/1989  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 1/4/95  
 Pilot Program: LOP  
 Local Case: H01447-004  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Not reported  
 Release Date: 04/14/1989  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

100

**NEX GAS 28TH ST  
 28ND ST  
 NS SAN DIEGO, CA 92136**

**Cortese S105025278  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

101

**SLOAN ELECTRIC COMPANY  
 3520 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103654863  
 N/A**

HAZNET:  
 Gepaid: CAL000126367  
 Contact: SLOAN ELECTRIC COMPANY  
 Telephone: 6192395174  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 1.8348  
 Facility County: San Diego  
  
 Gepaid: CAL000126367  
 Contact: SLOAN ELECTRIC COMPANY  
 Telephone: 6192395174  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC COMPANY (Continued)**

**S103654863**

Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAL099452708  
 TSD County: 0  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 1.3761  
 Facility County: San Diego

Gepaid: CAL000126367  
 Contact: SLOAN ELECTRIC COMPANY  
 Telephone: 6192395174  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAL099452708  
 TSD County: 0  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Recycler  
 Tons: .4586  
 Facility County: San Diego

Gepaid: CAL000126367  
 Contact: SLOAN ELECTRIC COMPANY  
 Telephone: 6192395174  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: .1500  
 Facility County: San Diego

Gepaid: CAL000126367  
 Contact: SLOAN ELECTRIC COMPANY  
 Telephone: 6192395174  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: .4125  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 55 additional CA\_HAZNET: record(s) in the EDR Site Report.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**101 ARNHART ELECTRIC CERC-NFRAP 1003878048**  
**3520 MAIN ST CAD982360729**  
**SAN DIEGO, CA 92113**

CERC-NFRAP:  
 Site ID: 0900464  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):  
 Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 12/01/1987  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported  
 Date Completed: 08/01/1988  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 08/01/1988  
 Priority Level: NFRAP (No Futher Remedial Action Planned)

**101 SLOAN ELECTRIC CO HAZNET S101481994**  
**3520 MAIN ST San Diego Co. HMMD N/A**  
**SAN DIEGO, CA 92113 ENVIROSTOR**

HAZNET:  
 Gepaid: CAD982018129  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAL000113451  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: .2085  
 Facility County: San Diego

Gepaid: CAD982018129  
 Contact: Not reported  
 Telephone: 0000000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAD000633164  
 TSD County: Imperial  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 5.0568  
 Facility County: San Diego

Gepaid: CAD982018129  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133804  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: \*\*\*  
 Tons: 2.5020  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 100545  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: SLOAN ELECTRIC CO  
 Mailing Address: 3520 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000126367  
 Gas Station: Not reported  
 Inspection Date: 11/08/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVE WATSON OR AL MEDEL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: 3520 MAIN STREET L L C  
 Property Address: 3520 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/08/06  
 Facility Phone: 619-239-5174

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC31  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR33  
 Chemical Name: ARGON AND ARGON/CO2  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: B929  
 Chemical Name: B9-116 HIGH PERFORMANCE EPOXY RESIN  
 Case Number: 25068386  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: DI35  
 Chemical Name: DIATA MOTOR OIL  
 Case Number: 647-42-445  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: DI34  
 Chemical Name: DIESEL  
 Case Number: 68476-30-2

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: HE83  
 Chemical Name: HELIUM  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OX32  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PE30  
 Chemical Name: PETROLEUM BASED SOLVENT  
 Case Number: 8030-30-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/31/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Item Number: 2471  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/19/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4499  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/19/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4500  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4706  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4707  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4708  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 04/29/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9701  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/08/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3738  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 11/08/04  
 Waste Item #: 123  
 Waste Code: 123  
 Waste Name: UNSPECIFIED ALKALINE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION  
 Storage Method: CAN  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: LAB PACK - CHEMICAL CLEAN  
 Carcinogen: No

Inspection Date: 11/08/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: SPNT ABSRBNT/SANDBLAST  
 Carcinogen: No

Inspection Date: 11/08/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 1320  
 Annual Qty String: 1320  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: FROM ENGINES,MACHINES  
 Carcinogen: No

Inspection Date: 11/08/04  
 Waste Item #: 331  
 Waste Code: 331  
 Waste Name: OFF-SPEC,AGED,SURPLU  
 Qty at Inspection: 150  
 Quantity String: 150  
 Annual Qty: 150  
 Annual Qty String: 150  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: LAB PACK - CHEMICAL CLEAN  
 Carcinogen: No

Inspection Date: 11/08/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: THINNER/PAINT/SOLV. TANK  
 Carcinogen: No

Inspection Date: 11/08/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: STM.CLN.SLDGE.  
 Carcinogen: No

Inspection Date: 11/08/04  
 Waste Item #: 791  
 Waste Code: 791  
 Waste Name: LIQUIDS WITH PH <OR=  
 Qnty at Inspection: 60  
 Quantity String: 60  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 015 TANK TREATMENT  
 Storage Method: CAN  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: LAB PACK - CHEMICAL CLEAN  
 Carcinogen: No

Inspection Date: 11/08/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Carcinogen: No

**ENVIROSTOR:**

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37590001  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: \* CERC2  
 Status: Refer: Other Agency  
 Status Date: 1995-06-01 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 32.6875  
 Longitude: -117.118055555556  
 Alias Name: SOL'S SURPLUS  
 37590001  
 Alias Type: Envirostor ID Number  
 Alternate Name

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments:

File review indicates that the SD County Dept. of Health Services is the lead agency. NFA for DTSC>File review indicates that the SD County Dept of Health is the lead agency. NFA for DTSC.FACILITY IDENTIFIED VIA PHONE BOOK '45SITE SCREENING DONE PA RECOM DUE TO HEAVILY STAINED SOILS & POTENTIAL FOR HALOGENATED HYDROCARBONS AND PCB'S. SOL'S HANDLED USED DRUMSPRELIM ASSESS DONE NO ADDITIONAL DATA ABOUT SURPLUS. DHS RECOMMEND MEDIUM PRIORITY SITE INVESTIGATION SINCE LITTLE INFORMATION EXISTS REGARDING PREVIOUS OPERATOR PRACTICES AND SOME SOIL STAINING. PRESENT OPERATOR HAS POOR HAZ WASTE PRACTICES.

**Completed Info:**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 06/01/95  
  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 05/02/95  
  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Assessment Report  
 Completed Date: 04/22/88

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SLOAN ELECTRIC CO (Continued)**

**S101481994**

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 03/17/87

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 10/04/82

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 10002, 10009, 10060, 10097, 10098, 10176, 10180, 10193, 10196, 10198, 10199, 20012, 20017, 30018

Potenital Description: \* HALOGENATED ORGANIC COMPOUNDS  
 Potentital Description: \* HYDROCARBON SOLVENTS  
 Potentital Description: \* OIL/WATER SEPARATION SLUDGE  
 Potentital Description: \* CONTAMINATED SOIL  
 Potentital Description: \* DETERGENT & SOAP  
 Potentital Description: \* Sludge - Degreasing  
 Potentital Description: \* Sludge - Sewage  
 Potentital Description: \* UNSPECIFIED ACID SOLUTION  
 Potentital Description: \* UNSPECIFIED OIL CONTAINING WASTE  
 Potentital Description: \* UNSPECIFIED SOLVENT MIXTURES  
 Potentital Description: \* WASTE OIL & MIXED OIL  
 Potentital Description: \* OTHER PESTICIDE CONTAINERS, 30 GALLONS OR MORE  
 Potentital Description: \* UNSPECIFIED ORGANIC LIQUID MIXTURE  
 Potentital Description: Polychlorinated biphenyls (PCBs)

Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

101

**FISCHBACH PROPERTIES**  
**3520 MAIN ST**  
**SAN DIEGO, CA 92113**

**HAZNET S103964474**  
**N/A**

HAZNET:  
 Gepaid: CAP601252198  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: 000000000  
 Gen County: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**FISCHBACH PROPERTIES (Continued)**

**S103964474**

TSD EPA ID: CAT080022148  
 TSD County: San Bernardino  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: 1.2000  
 Facility County: 0

Gepaid: CAP601252198  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: 000000000  
 Gen County: 0

TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .1251  
 Facility County: 0

Gepaid: CAP601252198  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: 000000000  
 Gen County: 0  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Transfer Station  
 Tons: .4500  
 Facility County: 0

Gepaid: CAP601252198  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: 000000000  
 Gen County: 0  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: 0

Gepaid: CAP601252198  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FISCHBACH PROPERTIES (Continued)**

**S103964474**

Mailing Address: Not reported  
 Mailing City,St,Zip: 000000000  
 Gen County: 0  
 TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .0208  
 Facility County: 0

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

101

**ARATEX SERVICES  
 3504 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S100232935  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T06019781184  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-08-03 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: Bob Robbins  
 RP Address: N779 State Road 113  
 Interim: Not reported  
 Oversight Prgm: LOCNL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARATEX SERVICES (Continued)**

**S100232935**

MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04015-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Not reported  
 Leak Source: Tank  
 Global Id: T0607303089  
 Stop Date: 1987-12-07 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-05-23 00:00:00  
 Discover Date: 1987-12-07 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-12-07 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARATEX SERVICES (Continued)**

**S100232935**

Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: REBECCA ARMBRUSTER  
 RP Address: 1834 WALDEN OFFICE SQ#450  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H04015-001  
 Case Number: 9UT843  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT843  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 12/07/1987  
 How Found: Tank Closure  
 Date Stopped: 12/07/1987  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Drinking Water Aquifer affected  
 Status: Remediation Plan  
 Abate Method: Not reported  
 Confirm Date: 02/17/1987  
 Submit Workplan: Not reported  
 Prelim Assess: 12/07/1987  
 Desc Pollution: Not reported  
 Remed Plan: 03/29/1988  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 12/7/87



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARATEX SERVICES (Continued)**

**S100232935**

Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H04015-001  
 Basin Number: 908.31  
 Gwater Depth: 12'  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Not reported  
 Release Date: 12/07/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 3504 MAIN ST

**San Diego Co. HMMD:**

Facility ID: 104015  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: P PO BOX 7891  
 Mailing City,St,Zip: BURBANK, CA 91510  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: CAD087579892  
 Gas Station: Not reported  
 Inspection Date: 04/22/98  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: TROY WOODARD  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ARATEX SERVICES INC  
 Property Address: C/O TERI S MALTESE  
 Property City,St,Zip: 91510  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-9381

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARATEX SERVICES (Continued)**

**S100232935**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H04015-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 5/23/2006  
 Begandt: 12/7/1987

Case Number: H04015-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARATEX SERVICES (Continued)**

**S100232935**

Date: 8/3/2006  
 Begandt: Not reported

101

**MASTER PLATING  
 2109 NEWTON AVENUE  
 SAN DEIGO, CA**

**US BROWNFIELDS 1006883419  
 N/A**

US BROWNFIELDS:

Recipient name: City of San Diego Redevelopment Agency  
 Project name: San Diego, CA  
 Property name: Master Plating  
 Parcel #: Not reported  
 Parcel size: Not reported  
 Latitude: 32.697223  
 Longitude: -117.142435  
 Region: 9  
 HCM label: Address Matching-House Number  
 Map scale: Not reported  
 Point of reference: Entrance Point of a Facility or Station  
 Datum: North American Datum of 1983  
 ACRES property ID: 12142  
 Start date: 12/31/1998  
 Completed date: 12/31/1998  
 Accomplishment type: Phase I Environmental Assessment  
 Accomplishment (acres): Not reported  
 Ownership entity: Not reported  
 Current use: Not reported  
 Current owner: Not reported  
 Future use: Not reported  
 Past use flag: Not reported  
 Future use flag: Not reported  
 Cleanup required: Not reported  
 Proprietary controls: Not reported  
 Gov. control: Not reported  
 Enforcement permit tools: Not reported  
 Info. devices: Not reported  
 Video available: Not reported  
 Photo available: Not reported  
 Usage type: Not reported  
 Not in state/tribal program: Not reported  
 IC data address: Not reported  
 IC in place date: Not reported  
 IC in place flag: Unknown  
 IC required flag: Not reported  
 NFA issue date: Not reported  
 State and tribal program: Not reported  
 State and tribal program: Not reported  
 Air contaminated: Not reported  
 Air cleaned: Not reported  
 Asbestos found: Not reported  
 Asbestos cleaned: Not reported  
 Controlled substance found: Not reported  
 Controlled substance cleaned: Not reported  
 Drinking water affected: Not reported  
 Drinking water cleaned: Not reported  
 Groundwater affected: Not reported  
 Groundwater cleaned: Not reported  
 Lead contaminant found: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER PLATING (Continued)**

**1006883419**

Lead cleaned up: Not reported  
 None found: Not reported  
 None cleaned up: Not reported  
 No media found: Not reported  
 No media cleaned up: Not reported  
 Other found: Not reported  
 Other cleaned up: Not reported  
 Other metals found: Not reported  
 Other metals cleaned: Not reported  
 PAHs found: Not reported  
 PAHs cleaned up: Not reported  
 PCBs found: Not reported  
 PCBs cleaned up: Not reported  
 Petro products found: Not reported  
 Petro products cleaned: Not reported  
 Sediments found: Not reported  
 Sediments cleaned: Not reported  
 Soil affected: Not reported  
 Soil cleaned up: Not reported  
 Surface water affected: Not reported  
 Surface water cleaned: Not reported  
 Unknown found: Not reported  
 Unknwon cleaned: Not reported  
 Unknown media: Not reported  
 Unknown media cleaned: Not reported  
 VOCs found: Not reported  
 VOCs cleaned: Not reported

101

**BALBOA PARK NURSERY  
 500' E OF NAVAL HOSPITAL / 400' S OF UPAS  
 SAN DIEGO, CA**

**SWF/LF S106198564  
 N/A**

SWF/LF:  
 Region: STATE  
 Facility ID: 37-CR-0006  
 Lat/Long: 32.728610 / -117.145550  
 Owner Name: City Of San Diego  
 Owner Telephone: 6195278037  
 Owner Address: Not reported  
 Owner Address2: 9601 Ridgehaven Court, Suite 301  
 Owner City,St,Zip: San Diego, CA 92123-1636  
 Operator: Not reported  
 Operator Phone: Not reported  
 Operator Address: Not reported  
 Operator Address2: Not reported  
 Operator City,St,Zip: Not reported  
 Operator's Status: Closed  
 Permit Date: Not reported  
 Permit Status: Not reported  
 Permitted Acreage: 0.00  
 Activity: Solid Waste Disposal Site  
 Regulation Status: Pre-regulations  
 Landuse Name: Other  
 GIS Source: Map  
 Category: Disposal  
 Unit Number: 01  
 Inspection Frequency: None  
 Accepted Waste: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BALBOA PARK NURSERY (Continued)**

**S106198564**

Closure Date: / /  
 Closure Type: Not reported  
 Disposal Acreage: Not reported  
 Swisnumber: 37-CR-0006  
 Issue & Observations: Not reported  
 Program Type: Not reported  
 Permitted Throughput with Units: Not reported  
 Actual Throughput with Units: Not reported  
 Permitted Capacity with Units: Not reported  
 Remaining Capacity: Not reported  
 Remaining Capacity with Units: Not reported

101

**PIER 13  
 NAVAL STN 32ND ST  
 SAN DIEGO, CA 92136**

**RCRA-SQG 1007264003  
 CAR000151522**

RCRA-SQG:

Date form received by agency: 07/01/2004  
 Facility name: PIER 13  
 Facility address: NAVAL STN 32ND ST  
 PIER 13  
 SAN DIEGO, CA 92136  
 EPA ID: CAR000151522  
 Contact: MATTHEW GROCHOWSKI  
 Contact address: NAVAL STN 32ND ST PIER 13  
 SAN DIEGO, CA 92136  
 Contact country: US  
 Contact telephone: 757-615-4901  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: USNAVY  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Federal  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1942  
 Owner/Op end date: Not reported  
 Owner/operator name: US DEPT OF DEFENSE  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Federal  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1942  
 Owner/Op end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PIER 13 (Continued)**

**1007264003**

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 03/08/2004  
 Facility name: PIER 13  
 Site name: USS BONHOMME RICHARD LHD-6 PIER 13  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D007  
 Waste name: CHROMIUM

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

101

**SAN DIEGO NAVAL STATION  
 P. O. BOX 113 NAVAL BASE, CODE 610  
 SAN DIEGO, CA 92136**

**CA BOND EXP. PLAN S105960475  
 N/A**

CA BOND EXP. PLAN:

Responsible Party: BACKLOG SITE CLEANUP PLANNING REPORT  
 Project Revenue Source Company: Not reported  
 Project Revenue Source Addr: Not reported  
 Project Revenue Source City,St,Zip: Not reported  
 Project Revenue Source Desc: This site is projected for cleanup funded by responsible parties with reimbursement to DHS for staff and related costs. However, if the responsible parties fail to provide funding for the cleanup another source of funds will need to be established.

Site Description: San Diego Naval Station consists of six potentially contaminated sites. The base is located in the tidelands of San Diego Bay.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO NAVAL STATION (Continued)**

**S105960475**

Hazardous Waste Desc: A total of six sites that received hazardous wastes of unknown composition were identified at the base. However, an initial assessment study (IAS) concluded that only three of the six sites warrant further investigation. The history of waste disposal at the site indicates that oil wastes, paint sludges, petroleum, diesel fuel, contaminated gasoline, solvents and thinners are present. Exact quantities are unknown.

Threat To Public Health & Env: The IAS concluded that only three of the sites may pose a potential threat to human health or to the environment. However, the Department has not yet made a determination as to the hazards posed by this base. There is no known exposure at this time.

Site Activity Status: The installation restoration program has been initiated at this base. Currently the program is in the confirmation (RI/FS) phase of the mitigation process.

101

**POINT LOMA NAVAL COMPLEX  
 SITE # 4 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320856  
 N/A**

WMUDS/SWAT:

Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**POINT LOMA NAVAL COMPLEX (Continued)**

**S103320856**

Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370061NUR  
 Solid Waste Information ID: Not reported

101

**USN-NAVSTA/NEX ANNEX  
 BLD G 3156-28TH ST  
 SAN DIEGO, CA 92136**

**UST U003790061  
 N/A**

UST:

Local Agency: 37000  
 Facility ID: H80652

101

**NAVAL COATING INC  
 32ND ST NAVAL STATION  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1006805569  
 FINDS CAR000129353  
 HAZNET**

RCRA-SQG:

Date form received by agency: 10/16/2002  
 Facility name: NAVAL COATING INC  
 Facility address: 32ND ST NAVAL STATION  
 PIER 5000  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000129353  
 Mailing address: 3475 E ST  
 SAN DIEGO, CA 92102  
 Contact: STACI HOYLE  
 Contact address: 3475 E ST  
 SAN DIEGO, CA 92102  
 Contact country: US  
 Contact telephone: (619) 234-8366  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: JAMES D KUVELAS  
 Owner/operator address: 3475 E ST  
 SAN DIEGO, CA 92102  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 234-8366



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NAVAL COATING INC (Continued)**

**1006805569**

Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 10/16/2002  
 Facility name: NAVAL COATING INC  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D005  
 Waste name: BARIUM

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL COATING INC (Continued)**

**1006805569**

HAZNET:

Gepaid: CAR000129353  
 Contact: DON VARGO - ESH MANAGER  
 Telephone: 6192348366  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3475 E ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 3.35  
 Facility County: Not reported

Gepaid: CAR000129353  
 Contact: DON VARGO - ESH MANAGER  
 Telephone: 6192348366  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3475 E ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: ARD981057870  
 TSD County: 99  
 Waste Category: Degreasing sludge  
 Disposal Method: Not reported  
 Tons: 0.45  
 Facility County: San Diego

Gepaid: CAR000129353  
 Contact: DON VARGO - ESH MANAGER  
 Telephone: 6192348366  
 Facility Addr2: PIER 5000  
 Mailing Name: Not reported  
 Mailing Address: 3475 E ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: 0.45  
 Facility County: San Diego

Gepaid: CAR000129353  
 Contact: DON VARGO - ESH MANAGER  
 Telephone: 6192348366  
 Facility Addr2: PIER 5000  
 Mailing Name: Not reported  
 Mailing Address: 3475 E ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: San Diego  
 Waste Category: Other organic solids

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL COATING INC (Continued)**

**1006805569**

Disposal Method: Not reported  
 Tons: 0.2  
 Facility County: San Diego  
  
 Gepaid: CAR000129353  
 Contact: DON VARGO - ESH MANAGER  
 Telephone: 6192348366  
 Facility Addr2: PIER 5000  
 Mailing Name: Not reported  
 Mailing Address: 3475 E ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921020000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 5.16  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

101

**BAE SYSTEMS MES  
 32ND ST NAVAL STATION  
 SAN DIEGO, CA 92123**

**RCRA-SQG 1001815606  
 FINDS CAR000057752  
 HAZNET**

RCRA-SQG:  
 Date form received by agency: 05/25/2006  
 Facility name: BAE SYSTEMS MES  
 Facility address: 32ND ST NAVAL STATION  
 VARIOUS PIERS  
 SAN DIEGO, CA 92123  
  
 EPA ID: CAR000057752  
 Mailing address: 7330 ENGINEER RD  
 STE A  
 SAN DIEGO, CA 92111  
  
 Contact: ROBERT H ROHBOCK  
 Contact address: 7330 ENGINEER RD STE A  
 SAN DIEGO, CA 92111  
  
 Contact country: US  
 Contact telephone: 858-514-1280  
 Contact email: ROBERT.H.ROHBOCK@BAESYSTEMS.COM  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time  
  
 Owner/Operator Summary:  
 Owner/operator name: BAE SYSTEMS MES  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAE SYSTEMS MES (Continued)**

**1001815606**

Owner/Operator Type: Operator  
 Owner/Op start date: 06/28/2005  
 Owner/Op end date: Not reported

Owner/operator name: US NAVY  
 Owner/operator address: 7330 ENGINEER RD STE A  
 SAN DIEGO, CA 92111

Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Federal  
 Owner/Operator Type: Owner  
 Owner/Op start date: 06/28/2005  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 07/01/2005  
 Facility name: BAE SYSTEMS MES  
 Site name: BAE SYSTEMS MARITIME ENGINEERING AND SVC  
 Classification: Small Quantity Generator

Date form received by agency: 10/08/1999  
 Facility name: BAE SYSTEMS MES  
 Site name: CORROSION ENGINEERING SERVICES  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D006  
 Waste name: CADMIUM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS MES (Continued)**

**1001815606**

Waste code: D007  
 Waste name: CHROMIUM

Waste code: D008  
 Waste name: LEAD

Waste code: F002  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000057752  
 Contact: R ROHBOCK ENV/SFTY MANAGER  
 Telephone: 8585141280

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS MES (Continued)**

**1001815606**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 7330 ENGINEER RD SUITE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921110000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.12  
 Facility County: Not reported

Gepaid: CAR000057752  
 Contact: R ROHBOCK ENV/SFTY MANAGER  
 Telephone: 8585141280  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 7330 ENGINEER RD SUITE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921110000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 8.75  
 Facility County: San Diego

Gepaid: CAR000057752  
 Contact: R ROHBOCK ENV/SFTY TEAM LEADER  
 Telephone: 6194220313  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3635 RUFFIN RD SUITE 100  
 Mailing City,St,Zip: SAN DIEGO, CA 921230000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 0.25  
 Facility County: Not reported

Gepaid: CAR000057752  
 Contact: C E S CAL CORP  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3635 RUFFIN RD SUITE 100  
 Mailing City,St,Zip: SAN DIEGO, CA 921230000  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 0.8  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAE SYSTEMS MES (Continued)**

**1001815606**

Gepaid: CAR000057752  
 Contact: C E S CAL CORP  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3635 RUFFIN RD SUITE 100  
 Mailing City,St,Zip: SAN DIEGO, CA 921230000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: 0.4  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

**101 USN-NAVSTA/PWC GAS STATION  
 BLD G 305  
 SAN DIEGO, CA 92136**

**UST U003790018  
 N/A**

UST:  
 Local Agency: 37000  
 Facility ID: H80007

**101 NAVAL STATION SAN DIEGO  
 BLDG 3300 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735616  
 Cortese N/A**

LUST:  
 Region: 9  
 Case Number: 9UT3278  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 10/13/1995  
 How Found: Tank Closure  
 Date Stopped: 10/13/1995  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 10/13/1995  
 Submit Workplan: 10/13/95  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104735616**

Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 2/5/99  
 Pilot Program: LOP  
 Local Case: H01447-040  
 Basin Number: 908.32  
 Gwater Depth: 12  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 10/13/1995  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 322/65 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735609  
 N/A**

LUST:  
 Region: 9  
 Case Number: 9UT3028  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 11/01/1994  
 How Found: Not reported  
 Date Stopped: 11/01/1994  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 01/04/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 8/1/96  
 Pilot Program: LOP  
 Local Case: H01447-033  
 Basin Number: 908.32  
 Gwater Depth: 7.5'  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104735609**

priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Not reported  
 Release Date: 11/01/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 223 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735613  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT3087  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 06/27/1995  
 How Found: Tank Closure  
 Date Stopped: 06/27/1995  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Remove Free Product - remove floating product from water table  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 07/11/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 7/11/95  
 Closed Date: 11/21/97  
 Pilot Program: LOP  
 Local Case: H01447-036  
 Basin Number: 908.32  
 Gwater Depth: 9'  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Dispn: Not reported  
 Release Date: 07/11/1995  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Distance (ft.)Site Database(s) EPA ID Number

101 32ND STREET NAVAL STATION RCRA-LQG 1004676791  
 3600 SURFACE NAVY BOULEVARD CAR000089508  
 SAN DIEGO, CA 92136

RCRA-LQG:

Date form received by agency: 02/22/2006  
 Facility name: 32ND STREET NAVAL STATION  
 Facility address: 3600 SURFACE NAVY BOULEVARD  
 SAN DIEGO, CA 92136  
 EPA ID: CAR000089508  
 Mailing address: P.O. BOX 85278 MS-22A  
 SAN DIEGO, CA 92186  
 Contact: MICHAEL T CHEE  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 544-7788  
 Contact email: MCHEE@NASSCO.COM  
 EPA Region: 09  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: SOUTHWEST REGION U.S. NAVY  
 Owner/operator address: 3600 SURFACE NAVY BLVD  
 SAN DIEGO, CA 92136  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Federal  
 Owner/Operator Type: Owner  
 Owner/Op start date: 02/12/1930  
 Owner/Op end date: Not reported

Owner/operator name: U.S. NAVY  
 Owner/operator address: Not reported  
 Not reported

Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Federal  
 Owner/Operator Type: Operator  
 Owner/Op start date: 02/12/1930  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**32ND STREET NAVAL STATION (Continued)**

**1004676791**

Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Historical Generators:

Date form received by agency: 02/16/2004  
 Facility name: 32ND STREET NAVAL STATION  
 Classification: Large Quantity Generator

Date form received by agency: 02/15/2002  
 Facility name: 32ND STREET NAVAL STATION  
 Classification: Large Quantity Generator

Date form received by agency: 01/04/2001  
 Facility name: 32ND STREET NAVAL STATION  
 Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D035  
 Waste name: METHYL ETHYL KETONE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**32ND STREET NAVAL STATION (Continued)**

**1004676791**

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.  
 Amount (Lbs): 22790

Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Amount (Lbs): 11495

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 1350

Violation Status: No violations found

101

**APPLIED ENERGY AT NAVSTA  
 3970 SURFACE NAVY B-3427  
 SAN DIEGO, CA 92136**

**LUST S105691804  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**APPLIED ENERGY AT NAVSTA (Continued)**

**S105691804**

Leak Cause: Other Cause  
 Leak Source: Other Source  
 Global Id: T0608124276  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-12-04 00:00:00  
 Discover Date: 1999-10-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-10-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Bruce Furbush  
 RP Address: 4600 Carlsbad Blvd.  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: NS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 911.12  
 Beneficial: MUN,AGR,IND,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H29576-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**APPLIED ENERGY AT NAVSTA (Continued)**

**S105691804**

SAN DIEGO CO. SAM:

Case Number: H29576-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/4/2006  
 Begandt: 10/18/1999

101

**APPLIED ENERGY LLC 32ND ST NAVAL STN  
 BLDG 3427 SURFACE NAVY BLVD  
 SAN DIEGO, CA 92101**

**RCRA-SQG 1000357992  
 CAD981575558**

RCRA-SQG:

Date form received by agency: 03/03/2004  
 Facility name: APPLIED ENERGY LLC 32ND ST NAVAL STN  
 Facility address: BLDG 3427 SURFACE NAVY BLVD  
 32ND ST NAVAL STN  
 SAN DIEGO, CA 92101  
 EPA ID: CAD981575558  
 Mailing address: 707 BROADWAY  
 STE 1600  
 SAN DIEGO, CA 92101-5378  
 Contact: DAVID J HERMANSON  
 Contact address: 707 BROADWAY STE 1600  
 SAN DIEGO, CA 92101-5378  
 Contact country: US  
 Contact telephone: 619-515-3003  
 Contact email: DHERMANSON@SITHE.COM  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: APPLIED ENERGY LLC  
 Owner/operator address: 707 BROADWAY STE 1600  
 SAN DIEGO, CA 92101  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 11/25/2003  
 Owner/Op end date: Not reported  
 Owner/operator name: SITHE ENERGIES POWER SERVICES  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1986  
 Owner/Op end date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**APPLIED ENERGY LLC 32ND ST NAVAL STN (Continued)**

**1000357992**

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 11/10/1986  
 Facility name: APPLIED ENERGY LLC 32ND ST NAVAL STN  
 Site name: ENERGY FACTORS INC  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

101

**MCAS MIRAMAR  
 OFF OF MIRAMAR BOULEVARD  
 SAN DIEGO, CA 92136**

**RESPONSE S101272845  
 ENVIROSTOR N/A**

RESPONSE:

Facility ID: 37970010  
 Site Type: State Response  
 Site Type Detail: Open Base  
 Acres: 24,000  
 National Priorities List: NO  
 Cleanup Oversight Agencies: SMBRP, RWQCB 9 - San Diego  
 Lead Agency: RWQCB 9 - San Diego, SMBRP  
 Lead Agency Description: RWQCB 9 - San Diego  
 Lead Agency Description: DTSC - Site Mitigation And Brownfield Reuse Program  
 Project Manager: ALICE GIMENO-O'BRIEN  
 Supervisor: Shelia Lowe  
 Division Branch: OMF - So (Cypress)  
 Site Code: 400097  
 Assembly: 76  
 Senate: 39  
 Special Program Status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MCAS MIRAMAR (Continued)**

**S101272845**

Status: Active  
 Status Date: 1997-07-23 00:00:00  
 Restricted Use: NO  
 Funding: DERA  
 Latitude: 32.8791666666667  
 Longitude: -117.125277777778  
 Alias Name: P43039  
 37970010  
 400097  
 CA9170024740  
 Alias Type: PCode  
 EPA Identification Number  
 Project Code (Site Code)  
 Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: PPP 03/21/95 Production of final Public Participation Plan for for site 4 and 11 - 14 was completed.FACILITY IDENTIFIED VIA EPA PRINTOUTAn RI/FS workplan was submitted for review and a tour of the base was don by RPM Ghazi. The RI will be reviewed as PEA until such time as an FFSA is negotiated with the Navy for this site.

Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Public Participation Plan / Community Relations Plan  
 Completed Date: 03/21/95

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 10/18/91

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 03/22/83

Confirmed: 30011-NO,3002501-NO,, ,32000  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Future Area Name: WATER BOARD  
 Future Sub Area Name: Not reported  
 Future Document Type: Removal Action Workplan  
 Future Due Date: 2009  
 Future Area Name: MilCon  
 Future Sub Area Name: Not reported  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2008  
 Future Area Name: Site 8  
 Future Sub Area Name: Not reported  
 Future Document Type: Removal Action Completion Report  
 Future Due Date: 2010  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 1



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MCAS MIRAMAR (Continued)**

**S101272845**

Future Document Type: Preliminary Assessment Report  
 Future Due Date: 2008  
 Future Area Name: Site 8  
 Future Sub Area Name: Not reported  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 3  
 Future Document Type: Preliminary Assessment Report  
 Future Due Date: 2008  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 10  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 6  
 Future Document Type: Preliminary Assessment Report  
 Future Due Date: 2008  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 12  
 Future Document Type: Preliminary Assessment Report  
 Future Due Date: 2008  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 5  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 12  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 6  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 6  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 13  
 Future Document Type: Preliminary Assessment Report  
 Future Due Date: 2008  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 13  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 7  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 1  
 Future Document Type: Site Inspection Report  
 Future Due Date: 2009  
 Future Area Name: Site 8  
 Future Sub Area Name: Not reported  
 Future Document Type: Removal Action Workplan  
 Future Due Date: 2010  
 Future Area Name: MMRP Sites  
 Future Sub Area Name: Site 8  
 Future Document Type: Site Inspection Report

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MCAS MIRAMAR (Continued)**

**S101272845**

Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 7
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 8
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 10
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 5
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 9
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	Site 8
Future Sub Area Name:	Not reported
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 2
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Media Affected:	OTH, SOIL
Media Affected Desc:	Other Groundwater affected (uses other than drinking water)
Media Affected Desc:	Soil
<b>Management:</b>	
Management Required:	NONE SPECIFIED
Management Required Desc:	Not reported
Potential:	30011, 3002501, 32000
Potential Description:	Explosives (UXO, MEC)
Potential Description:	TPH-JET FUEL
Potential Description:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported
PastUse:	AIRCRAFT MAINTENANCE, AIRFIELD OPERATIONS, EQUIPMENT/INSTRUMENT REPAIR, FIRING RANGE - ARTILLERY, FIRING RANGE - SMALL ARMS ETC..., FUEL - AIRCRAFT STORAGE/ REFUELING, FUEL - VEHICLE STORAGE/ REFUELING, JET FUEL STORAGE/REFUELING, VEHICLE MAINTENANCE
<b>ENVIROSTOR:</b>	
Site Type:	State Response
Site Type Detailed:	Open Base
Acres:	24,000
NPL:	NO
Regulatory Agencies:	SMBRP, RWQCB 9 - San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MCAS MIRAMAR (Continued)**

**S101272845**

Lead Agency: RWQCB 9 - San Diego,SMBRP  
 Program Manager: ALICE GIMENO-O'BRIEN  
 Supervisor: Shelia Lowe  
 Division Branch: OMF - So (Cypress)  
 Facility ID: 37970010  
 Site Code: 400097  
 Assembly: 76  
 Senate: 39  
 Special Program: Not reported  
 Status: Active  
 Status Date: 1997-07-23 00:00:00  
 Restricted Use: NO  
 Funding: DERA  
 Latitude: 32.8791666666667  
 Longitude: -117.125277777778  
 Alias Name: P43039  
 37970010  
 400097  
 CA9170024740  
 Alias Type: PCode  
 EPA Identification Number  
 Project Code (Site Code)  
 Envirostor ID Number  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: PPP 03/21/95 Production of final Public Participation Plan for for site 4 and 11 - 14 was completed.FACILITY IDENTIFIED VIA EPA PRINTOUTAn RI/FS workplan was submitted for review and a tour of the base was don by RPM Ghazi. The RI will be reviewed as PEA until such time as an FFSRA is negotiated with the Navy for this site.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Public Participation Plan / Community Relations Plan  
 Completed Date: 03/21/95

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 10/18/91

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 03/22/83

Confirmed: 30011-NO,3002501-NO,, ,32000  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Future Area Name: WATER BOARD  
 Future Sub Area Name: Not reported  
 Future Document Type: Removal Action Workplan  
 Future Due Date: 2009  
 Future Area Name: MilCon

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MCAS MIRAMAR (Continued)**

**S101272845**

Future Sub Area Name:	Not reported
Future Document Type:	Site Inspection Report
Future Due Date:	2008
Future Area Name:	Site 8
Future Sub Area Name:	Not reported
Future Document Type:	Removal Action Completion Report
Future Due Date:	2010
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 1
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	Site 8
Future Sub Area Name:	Not reported
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 3
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 10
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 6
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 12
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 5
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 12
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 6
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 13
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 13
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 7
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MCAS MIRAMAR (Continued)**

**S101272845**

Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	Site 8
Future Sub Area Name:	Not reported
Future Document Type:	Removal Action Workplan
Future Due Date:	2010
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 8
Future Document Type:	Site Inspection Report
Future Due Date:	2009
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 7
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 8
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 10
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 5
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 9
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	Site 8
Future Sub Area Name:	Not reported
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Future Area Name:	MMRP Sites
Future Sub Area Name:	Site 2
Future Document Type:	Preliminary Assessment Report
Future Due Date:	2008
Media Affected:	OTH, SOIL
Media Affected Desc:	Other Groundwater affected (uses other than drinking water)
Media Affected Desc:	Soil
<b>Management:</b>	
Management Required:	NONE SPECIFIED
Management Required Desc:	Not reported
Potential:	30011, 3002501, 32000
Potenital Description:	Explosives (UXO, MEC)
Potenital Description:	TPH-JET FUEL
Potenital Description:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported
PastUse:	AIRCRAFT MAINTENANCE, AIRFIELD OPERATIONS, EQUIPMENT/INSTRUMENT REPAIR, FIRING RANGE - ARTILLERY, FIRING RANGE - SMALL ARMS ETC..., FUEL - AIRCRAFT STORAGE/ REFUELING, FUEL - VEHICLE STORAGE/ REFUELING, JET FUEL STORAGE/REFUELING, VEHICLE MAINTENANC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site  
 Database(s)  
 EPA ID Number  
 EDR ID Number  
 EPA ID Number

MCAS MIRAMAR (Continued)

S101272845

E

101 SOUTHBAY SANDBLAST AND TANK CLEANING  
 32ND ST NAS PIERS  
 SAN DIEGO, CA 92113

RCRA-SQG 1001217333  
 FINDS CAR000032375  
 HAZNET

RCRA-SQG:

Date form received by agency: 11/24/1999  
 Facility name: SOUTHBAY SANDBLAST AND TANK CLEANING  
 Facility address: 32ND ST NAS PIERS  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000032375  
 Mailing address: 3763 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact: CARLOS BERNAL  
 Contact address: 3763 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 238-8338  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: LOPEZ CANUTO  
 Owner/operator address: 3763 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 238-8338  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHBAY SANDBLAST AND TANK CLEANING (Continued)**

**1001217333**

Historical Generators:

Date form received by agency: 11/24/1999  
 Facility name: SOUTHBAY SANDBLAST AND TANK CLEANING  
 Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D000  
 Waste name: Not Defined

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D004  
 Waste name: ARSENIC

Waste code: D008  
 Waste name: LEAD

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000032375  
 Contact: CANUTO LOPEZ  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHBAY SANDBLAST AND TANK CLEANING (Continued)**

**1001217333**

Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: 1.5000  
 Facility County: San Diego

Gepaid: CAR000032375  
 Contact: CANUTO LOPEZ  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 1.6928  
 Facility County: San Diego

Gepaid: CAR000032375  
 Contact: CANUTO LOPEZ  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Not reported  
 Tons: 1.5000  
 Facility County: San Diego

Gepaid: CAR000032375  
 Contact: CANUTO LOPEZ  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CA0097030993  
 TSD County: 0  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Other  
 Tons: 2.1500  
 Facility County: San Diego

Gepaid: CAR000032375  
 Contact: CARLO BERNAL/ENVTL MGR.  
 Telephone: 6192388338  
 Facility Addr2: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHBAY SANDBLAST AND TANK CLEANING (Continued)**

**1001217333**

Mailing Name: Not reported  
 Mailing Address: 1343 CESAR CHAVEZ PARKWAY SUITE A  
 Mailing City, St, Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 2.71  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 2 additional CA\_HAZNET: record(s) in the EDR Site Report.

101

**NAVAL STATION SAN DIEGO 32 ST  
 PIER 14  
 SAN DIEGO, CA 92136**

**RCRA-SQG 1004676553  
 AST CAR000086702**

RCRA-SQG:

Date form received by agency: 11/02/2000  
 Facility name: NAVAL STATION SAN DIEGO 32 ST  
 Facility address: PIER 14  
 NAVAL STATION SAN DIEGO 32 ST  
 SAN DIEGO, CA 921365588  
 EPA ID: CAR000086702  
 Mailing address: 3975 NORMAN SCOTT RD  
 SAN DIEGO, CA 921365588  
 Contact: DAVID SHARP  
 Contact address: 3975 NORMAN SCOTT RD  
 SAN DIEGO, CA 921365588  
 Contact country: US  
 Contact telephone: (619) 556-7760  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: DON FLEET TRAINING CTR S D  
 Owner/operator address: 3975 NORMAN SCOTT RD  
 SAN DIEGO, CA 92136  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 556-7760  
 Legal status: Federal  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO 32 ST (Continued)**

**1004676553**

Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:

Waste code: D000  
 Waste name: Not Defined

Waste code: D007  
 Waste name: CHROMIUM

Waste code: D008  
 Waste name: LEAD

Waste code: D009  
 Waste name: MERCURY

Violation Status: No violations found

AST:

Owner: NAVY, DEPARTMENT OF THE  
 Total Gallons: 4900

101

**PUMP STATION 2  
 PUMP STATION 2  
 SAN DIEGO, CA**

**Notify 65 S100178514  
 N/A**

Notify 65:

Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 332 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735628  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT3385  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 12/30/1994  
 How Found: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104735628**

Date Stopped: 12/30/1994  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 01/09/1994  
 Submit Workplan: Not reported  
 Prelim Assess: 01/09/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 1/11/95  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-034  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 12/30/1994  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

101 **NAVAL STATION SAN DIEGO**  
**BLDG 209 32ND ST**  
**NS SAN DIEGO, CA 92136**

**LUST S104735640**  
**Cortese N/A**

LUST:  
 Region: 9  
 Case Number: 9UT3899  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 01/13/1999  
 How Found: Tank Closure  
 Date Stopped: 01/13/1999  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: 02/19/1999  
 Submit Workplan: 5/14/99

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104735640**

Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-044  
 Basin Number: 908.32  
 Gwater Depth: 10.5  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/HIGH - KNOWN HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Not reported  
 Release Date: 01/13/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 3403 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735643  
 N/A**

LUST:  
 Region: 9  
 Case Number: 9UT3968  
 Local Agency: San Diego  
 Substance: Boiler Fuel  
 Qty Leaked: 0  
 Date Found: 08/09/1999  
 How Found: Tank Closure  
 Date Stopped: 08/09/1999  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: 08/19/1999  
 Submit Workplan: 8/26/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-045

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104735643**

Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - KNOWN HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Not reported  
 Release Date: 08/09/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 3356 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735617  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT3279  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 02/02/1994  
 How Found: Tank Closure  
 Date Stopped: 02/02/1994  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: No Action Taken - no action has as yet been taken at the site  
 Confirm Date: 12/14/1995  
 Submit Workplan: 12/14/95  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 4/20/98  
 Pilot Program: LOP  
 Local Case: H01447-039  
 Basin Number: 908.32  
 Gwater Depth: 8'  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 02/02/1994  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>101</b>	<b>NAVAL STATION FTC, FFS-12</b> <b>BLDG 171 32ND ST</b> <b>SAN DEIGO, CA 92136</b>	<b>Cortese</b>	<b>S105026088</b> <b>N/A</b>
------------	---	----------------	---------------------------------

Cortese:  
 Region:           CORTESE  
 Facility Addr2:   Not reported

<b>101</b>	<b>NAVAL STATION SAN DIEGO</b> <b>BLDG 3162 32ND ST</b> <b>NS SAN DIEGO, CA 92136</b>	<b>LUST</b> <b>Cortese</b>	<b>S104735618</b> <b>N/A</b>
------------	---	-------------------------------	---------------------------------

LUST:  
 Region:           9  
 Case Number:     9UT3280  
 Local Agency:    San Diego  
 Substance:       Diesel  
 Qty Leaked:      0  
 Date Found:      02/02/1994  
 How Found:       Not reported  
 Date Stopped:    / /  
 How Stopped:    Not reported  
 Source:          Tank  
 Cause:           Unknown  
 Lead Agency:     Local Agency  
 Case Type:       Other ground water affected  
 Status:          Case Closed  
 Abate Method:    Not reported  
 Confirm Date:    02/02/1994  
 Submit Workplan: 2/2/94  
 Prelim Assess:   / /  
 Desc Pollution:   Not reported  
 Remed Plan:      / /  
 Remed Action:    Not reported  
 Began Monitor:   Not reported  
 Enforce Type:    Not reported  
 Enforce Date:    Not reported  
 Closed Date:     7/23/99  
 Pilot Program:   LOP  
 Local Case:      H01447-038  
 Basin Number:    908.31  
 Gwater Depth:   8  
 Beneficial Use:   NBNABB/E  
 NPDES Number:   Not reported  
 priority:         LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn:      Administratively opened on database, however no file physically exists  
 Release Date:    02/02/1994  
 Interim Remedial Actions:           Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region:           CORTESE  
 Facility Addr2:   Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**101      NAVAL STATION SAN DIEGO  
 BLDG 265 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST    S104735626  
 Cortese    N/A**

LUST:

Region: 9  
 Case Number: 9UT3338  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 06/08/1995  
 How Found: Not reported  
 Date Stopped: 06/08/1995  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 06/08/1995  
 Submit Workplan: Not reported  
 Prelim Assess: 06/08/1995  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 7/20/95  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-037  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 06/08/1995  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

**101      NAVAL STATION SAN DIEGO  
 TANK 270 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST    S104793881  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT4085  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 06/16/2000  
 How Found: Tank Closure

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104793881**

Date Stopped: 06/16/2000  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: 8/28/00  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-047  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: Not reported  
 File Dispn: Not reported  
 Release Date: 08/28/2000  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 132 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104406443  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT2152  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 01/06/1992  
 How Found: Other Means  
 Date Stopped: 01/06/1992  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 01/09/1992  
 Submit Workplan: 3/4/92  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104406443**

Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 9/16/94  
 Pilot Program: LOP  
 Local Case: H01447-014  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported  
 priority: LOP/LOW - LOW POTENTIAL HEALTH/SAFTY/ENVIRONMENTAL IMPACT  
 File Dispn: Not reported  
 Release Date: 01/06/1992  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

Region: CORTESE  
 Facility Addr2: BLDG 132 32ND ST

101

**NAVAL STATION SAN DIEGO  
 BLDG 129 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735614  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT3147  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: 0  
 Date Found: 01/03/1996  
 How Found: Tank Closure  
 Date Stopped: 01/03/1996

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104735614**

How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site, Pump and Treat Ground Water - generally employed to remove dissolved contaminants  
 Confirm Date: 01/03/1996  
 Submit Workplan: 2/29/96  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 8/30/00  
 Pilot Program: LOP  
 Local Case: H01447-041  
 Basin Number: 908.31  
 Gwater Depth: 10.58  
 Beneficial Use: NBNB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 01/03/1996  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

101

**NAVAL STATION SAN DIEGO  
 TANK 259 / 268 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735656  
 N/A**

LUST:  
 Region: 9  
 Case Number: 9UT4079  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 06/16/2000  
 How Found: Tank Closure  
 Date Stopped: / /  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Overfill  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: / /

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104735656**

Submit Workplan: 8/28/00  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: DOD  
 Local Case: H01447-046  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 08/28/2000  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 271 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104406463  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT2824  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 12/02/1992  
 How Found: Not reported  
 Date Stopped: 12/02/1992  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 12/02/1992  
 Submit Workplan: Not reported  
 Prelim Assess: 12/02/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 12/2/92  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-019  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S104406463**

priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Not reported  
 Release Date: 12/02/1992  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

101

**NAVAL STATION SAN DIEGO  
 BLDG 254 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104539603  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT3569  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 05/14/1997  
 How Found: Tank Closure  
 Date Stopped: 05/14/1997  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 08/14/1997  
 Submit Workplan: 11/13/97  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/30/99  
 Pilot Program: LOP  
 Local Case: H01447-043  
 Basin Number: 908.22  
 Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: Not reported  
 Release Date: 05/14/1997  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

101 **NAVAL STATION SAN DIEGO  
 BLDG 273 32ND ST  
 NS SAN DIEGO, CA 92136**

**LUST S104735605  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT2992  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: 0  
 Date Found: 02/22/1993  
 How Found: Tank Closure  
 Date Stopped: 02/22/1993  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 03/30/1993  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-025  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Not reported  
 Release Date: 03/29/1993  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

101 **NAVAL STATION CENTRAL STEAM PL  
 213 WARD RD.  
 SAN DIEGO, CA 92136**

**AST A100109265  
 N/A**

AST:

Owner: APPLIED ENERGY, INC.  
 Total Gallons: 806400

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 **NAVAL STATION  
 SITE # 3 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320847  
 N/A**

WMUDS/SWAT:

Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: NAVAL STATION  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: NAVAL STATION  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370048NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**101 POINT LOMA NAVAL COMPLEX  
 SITE # 6 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320866  
 N/A**

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370079NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 7 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320865  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370078NUR  
 Solid Waste Information ID: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 13 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320875  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370089NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101

**NAVAL STATION  
 SITE # 1 IAS  
 SAN DIEGO, CA**

WMUDS/SWAT

**S103320840  
 N/A**

WMUDS/SWAT:

Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: SW DIVISION-NAVAL FACILITIES  
 Agency Address: 1220 PACIFIC HIGHWAY  
 Agency City,St,Zip: SAN DIEGO 92132  
 Agency Contact: ANDY P.  
 Agency Telephone: 6195321239  
 Land Owner Name: U.S. NAVAL STATION 32ND ST  
 Land Owner Address: CODE ODEP, P.O. BOX 16  
 Land Owner City,St,Zip: SAN DIEGO, CA 92136  
 Land Owner Contact: MICHAEL SHEPHERD  
 Land Owner Phone: 6195566438  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: NAVAL STATION  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: DFH  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370028NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 **NAVAL TRAINING CENTER  
 SITE # 1 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320839  
 N/A**

WMUDS/SWAT:

Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: COMMAND, ENVIRONMENTAL DIVISIO  
 Agency Department: SOUTHWEST NAVAL FACILITIES ENG  
 Agency Address: 12200 COAST HWY  
 Agency City,St,Zip: SAN DIEGO  
 Agency Contact: MS. MARTHA GANDY (CODE 17.4)  
 Agency Telephone: 6195241022  
 Land Owner Name: DEPARTMENT OF THE NAVY  
 Land Owner Address: NAVAL TRAINING CENTER (CODE 17  
 Land Owner City,St,Zip: SAN DIEGO, CA 92133  
 Land Owner Contact: MR. JEFF KIDWELL  
 Land Owner Phone: 6195323152  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: NAVAL TRAINING CENTER  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: COMMAND, ENVIRONMENTAL DIVISION  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: True  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370027NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

101 **NAVAL STATION  
 SITE # 4 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320845  
 N/A**

WMUDS/SWAT:

Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: NAVAL STATION  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: NAVAL STATION  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370045NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 5 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320853  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370058NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

101 POINT LOMA NAVAL COMPLEX  
 SITE # 2 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320855  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370060NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 8 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320864  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370077NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

101 POINT LOMA NAVAL COMPLEX  
 SITE # 3 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320854  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370059NUR  
 Solid Waste Information ID: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**101 POINT LOMA NAVAL COMPLEX  
 SITE # 12 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320867  
 N/A**

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370080NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 16 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320871  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370085NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 9 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320868  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370081NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 10 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320873  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370087NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 17 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320872  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370086NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 POINT LOMA NAVAL COMPLEX  
 SITE # 14 IAS  
 SAN DIEGO, CA

WMUDS/SWAT S103320881  
 N/A

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370095NUR  
 Solid Waste Information ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

101 **SAN DIEGO NAVAL STATION - SITE 12**  
**SAN DIEGO BAY, 113 NAVAL BASE 610**  
**SAN DIEGO, CA 92136**

**RESPONSE** S103454984  
**ENVIROSTOR** N/A  
**HIST Cal-Sites**

RESPONSE:

Facility ID: 37970026  
 Site Type: State Response  
 Site Type Detail: Open Base  
 Acres: Not reported  
 National Priorities List: NO  
 Cleanup Oversight Agencies: DTSC  
 Lead Agency: NONE SPECIFIED  
 Lead Agency Description: Not reported  
 Project Manager: Not reported  
 Supervisor: Shelia Lowe  
 Division Branch: OMF - So (Cypress)  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program Status: Not reported  
 Status: Certified  
 Status Date: 1998-10-14 00:00:00  
 Restricted Use: NO  
 Funding: DERA  
 Latitude: 32.6827777777778  
 Longitude: -117.1263888888889  
 Alias Name: 37970026  
 Alias Type: SAN DIEGO NAVAL STATION - SITE 12  
 Envirostor ID Number  
 Alternate Name

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: Removal Action Completion Report  
 Completed Date: 01/29/97

Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: Action Memorandum (if <\$1M)  
 Completed Date: 06/14/96

Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: Certification  
 Completed Date: 10/14/98

Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: \* CEQA  
 Completed Date: 06/14/96

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO NAVAL STATION - SITE 12 (Continued)**

**S103454984**

Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

ENVIROSTOR:

Site Type: State Response  
 Site Type Detailed: Open Base  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: DTSC  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Shelia Lowe  
 Division Branch: OMF - So (Cypress)  
 Facility ID: 37970026  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Certified  
 Status Date: 1998-10-14 00:00:00  
 Restricted Use: NO  
 Funding: DERA  
 Latitude: 32.6827777777778  
 Longitude: -117.126388888889  
 Alias Name: 37970026  
                   SAN DIEGO NAVAL STATION - SITE 12  
 Alias Type: Envirostor ID Number  
                   Alternate Name  
  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: Removal Action Completion Report  
 Completed Date: 01/29/97  
  
 Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: Action Memorandum (if <\$1M)  
 Completed Date: 06/14/96



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO NAVAL STATION - SITE 12 (Continued)**

**S103454984**

Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: Certification  
 Completed Date: 10/14/98

Completed Area Name: Sites With No Operable Unit  
 Completed Sub Area Name: SITE12  
 Completed Document Type: \* CEQA  
 Completed Date: 06/14/96

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

**Management:**

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

**HISTORICAL CAL-SITES:**

Facility ID: 37970026  
 Region: 3  
 Region Name: GLENDALE  
 Branch: SO  
 Branch Name: OMF-SOUTHERN CALIF  
 File Name: SAN DIEGO NAVAL STATION - SITE 12  
 State Senate District: 10141998  
 Status: CERT - CERTIFIED AS HAVING BEEN REMEDIED SATISFACTORILY UNDER DTSC  
 OVERSIGHT  
 Status Name: CERTIFIED  
 Lead Agency: DTSC  
 Lead Agency: DEPT OF TOXIC SUBSTANCES CONTROL  
 Facility Type: OPEN  
 Type Name: OPEN MILITARY BASE  
 NPL: Not Listed  
 SIC Code: 97  
 SIC Name: NATIONAL SECURITY/INTERNATIONAL AFFAIRS  
 Access: Controlled  
 Cortese: Not reported  
 Hazardous Ranking Score: Not reported  
 Date Site Hazard Ranked: Not reported  
 Groundwater Contamination: Suspected  
 Staff Member Responsible for Site: Not reported  
 Supervisor Responsible for Site: Not reported  
 Region Water Control Board: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO NAVAL STATION - SITE 12 (Continued)**

**S103454984**

Region Water Control Board Name: Not reported  
 Lat/Long Direction: Not reported  
 Lat/Long (dms): 0 0 0 / 0 0 0  
 Lat/long Method: Not reported  
 Lat/Long Description: Not reported  
 State Assembly District Code: 79  
 State Senate District Code: 40

[Click this hyperlink](#) while viewing on your computer to access additional CA\_CALSITE: detail in the EDR Site Report.

101

**SAN DIEGO NAVAL STATION  
 SAN DIEGO BAY 113 NAVAL B  
 SAN DIEGO, CA 92136**

**Cortese S105026127  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

101

**SAN DIEGO NAVAL STATION -  
 SAN DIEGO BAY 113 NAVAL B  
 SAN DIEGO, CA 92136**

**Cortese S105026126  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

101

**POINT LOMA NAVAL COMPLEX  
 SITE # 15 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320882  
 N/A**

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**POINT LOMA NAVAL COMPLEX (Continued)**

**S103320882**

Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Land Owner Name: POINT LOMA NAVAL COMPLEX  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: POINT LOMA NAVAL COMPLEX  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370096NUR  
 Solid Waste Information ID: Not reported

101

**NAVAL TRAINING CENTER  
 SITE # 2 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320879  
 N/A**

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: NAVAL TRAINING CENTER  
 Agency Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL TRAINING CENTER (Continued)**

**S103320879**

Agency City,St,Zip: SAN DIEGO 92133-1000  
 Agency Contact: MS. MARTHA GANDY  
 Agency Telephone: 6195241022  
 Land Owner Name: NAVAL TRAINING CENTER  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: SAN DIEGO 92133-1000  
 Land Owner Contact: COMMANDING OFFICER  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: NAVAL TRAINING CENTER  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370093NUR  
 Solid Waste Information ID: Not reported

101

**NAVAL TRAINING CENTER  
 SITE # 3 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320886  
 N/A**

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: NAVAL TRAINING CENTER  
 Agency Address: Not reported  
 Agency City,St,Zip: SAN DIEGO 92133

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL TRAINING CENTER (Continued)**

**S103320886**

Agency Contact: MS. MARTHA GANDY  
 Agency Telephone: 6195241022  
 Land Owner Name: NAVAL TRAINING CENTER  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: SAN DIEGO 92133-1000, CA 92133  
 Land Owner Contact: COMMANDING OFFICER  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: NAVAL TRAINING CENTER  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370103NUR  
 Solid Waste Information ID: Not reported

101

**NAVAL STATION SAN DIEGO  
 SITE # 6 IAS  
 SAN DIEGO, CA**

**WMUDS/SWAT S103320852  
 N/A**

WMUDS/SWAT:  
 Edit Date: Not reported  
 Complexity: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Base Meridian: Not reported  
 NPID: Not reported  
 Tonnage: 0  
 Regional Board ID: Not reported  
 Municipal Solid Waste: False  
 Superorder: False  
 Open To Public: False  
 Waste List: False  
 Agency Type: Not reported  
 Agency Name: NAVY  
 Agency Department: Not reported  
 Agency Address: Not reported  
 Agency City,St,Zip: Not reported  
 Agency Contact: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVAL STATION SAN DIEGO (Continued)**

**S103320852**

Agency Telephone: Not reported  
 Land Owner Name: NAVAL STATION  
 Land Owner Address: Not reported  
 Land Owner City,St,Zip: Not reported  
 Land Owner Contact: Not reported  
 Land Owner Phone: Not reported  
 Region: 9  
 Facility Type: Not reported  
 Facility Description: Not reported  
 Facility Telephone: Not reported  
 SWAT Facility Name: NAVAL STATION SAN DIEGO  
 Primary SIC: Not reported  
 Secondary SIC: Not reported  
 Comments: Not reported  
 Last Facility Editors: Not reported  
 Waste Discharge System: False  
 Solid Waste Assessment Test Program: True  
 Toxic Pits Cleanup Act Program: False  
 Resource Conservation Recovery Act: False  
 Department of Defence: False  
 Solid Waste Assessment Test Program: NAVY  
 Threat to Water Quality: Not reported  
 Sub Chapter 15: False  
 Regional Board Project Officer: MA  
 Number of WMUDS at Facility: 1  
 Section Range: Not reported  
 RCRA Facility: Not reported  
 Waste Discharge Requirements: Not reported  
 Self-Monitoring Rept. Frequency: Not reported  
 Waste Discharge System ID: 9 370057NUR  
 Solid Waste Information ID: Not reported

101

**YYK ENTERPRISES INC  
 3460 W MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106061638  
 N/A**

San Diego Co. HMMD:

Facility ID: 119978  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3460 W MAIN ST #H  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAD981578685  
 Gas Station: Not reported  
 Inspection Date: 06/26/00  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: STEVE WOO  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YYK ENTERPRISES INC (Continued)**

**S106061638**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WATSON CHARLES K&ROBERTA L FAM  
 Property Address: 1110 ALAMEDA BLVD  
 Property City,St,Zip: 92118  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-645-7757

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

101 AMERICAN LINEN  
 3460 MAIN ST  
 SAN DIEGO, CA 92113

LUST S105035128  
 Cortese N/A  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300108  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1987-04-21 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H00543-001



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN LINEN (Continued)**

**S105035128**

Case Number: 9UT11  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 3460 MAIN ST

**San Diego Co. HMMD:**

Facility ID: 100543  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WATSON CHARLES K&ROBERTA L FAM  
 Property Address: 1110 ALAMEDA BLVD  
 Property City,St,Zip: 92118  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN LINEN (Continued)**

**S105035128**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 203994  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3460 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/31/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN LINEN (Continued)**

**S105035128**

Violation Notice Issued: Not reported  
 Facility Contact: KEN PETERSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WATSON CHARLES K&ROBERTA L FAM  
 Property Address: 1110 ALAMEDA BLVD  
 Property City,St,Zip: 92118  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/28/06  
 Facility Phone: 619-235-1718

**HMMD DISCLOSURE INVENTORY:**

Item Number: PA59  
 Chemical Name: PAINTS & VARIOUS FLAMMABLE LIQUIDS THINNERS, SPRAY ADHESIVES  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN LINEN (Continued)**

**S105035128**

Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

SAN DIEGO CO. SAM:

Case Number: H00543-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 4/21/1987  
 Begandt: 11/5/1986

101

**AMERICAN LINEN SERV.  
 3460 MAIN ST  
 SAN DIEGO, CA 92113**

**HIST UST U001572969  
 N/A**

HIST UST:

Region: STATE  
 Facility ID: 00000044016  
 Facility Type: Other  
 Other Type: LAUNDRY  
 Total Tanks: 0000  
 Contact Name: ROSS SMITH  
 Telephone: 6192346428  
 Owner Name: AMERICAN LINEN SERVICE  
 Owner Address: 3460 MAIN ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1970  
 Tank Capacity: 00003000  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 1/4 inches  
 Leak Detection: Stock Inventor

101

**YYK ENTERPRISES INC  
 3460 MAIN STREET  
 SAN DIEGO, CA 92113**

**HAZNET S100731213  
 N/A**

HAZNET:

Gepaid: CAD981578685  
 Contact: YONG C KIM, PRES  
 Telephone: 5105322330  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3460 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133803  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus inorganics  
 Disposal Method: Recycler

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YYK ENTERPRISES INC (Continued)**

**S100731213**

Tons: 1.8556  
 Facility County: San Diego  
  
 Gepaid: CAD981578685  
 Contact: YONG C KIM, PRES  
 Telephone: 5105322330  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3460 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133803  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Disposal, Other  
 Tons: .2500  
 Facility County: San Diego

Gepaid: CAD981578685  
 Contact: YONG C KIM, PRES  
 Telephone: 5105322330  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3460 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133803  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Not reported  
 Tons: 2.0850  
 Facility County: San Diego

Gepaid: CAD981578685  
 Contact: YONG C KIM, PRES  
 Telephone: 5105322330  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3460 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133803  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: .8750  
 Facility County: San Diego

Gepaid: CAD981578685  
 Contact: YONG C KIM, PRES  
 Telephone: 5105322330  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3460 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133803  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YYK ENTERPRISES INC (Continued)**

**S100731213**

TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Recycler  
 Tons: 72.5580  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 21 additional CA\_HAZNET: record(s) in the EDR Site Report.

101

**AMERICAN UNIFORM  
 3440 MAIN STREET  
 SAN DIEGO, CA 92113**

**HIST UST U001572971  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000063390  
 Facility Type: Other  
 Other Type: UNIFORM SUPPLIES  
 Total Tanks: 0002  
 Contact Name: K. MILES  
 Telephone: 6192326178  
 Owner Name: AMERICAN COVERALL SUPPLY  
 Owner Address: 3440 MAIN ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92113

Tank Num: 001  
 Container Num: 2  
 Year Installed: 1973  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: 06  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

Tank Num: 002  
 Container Num: 3  
 Year Installed: 1973  
 Tank Capacity: 00002500  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: Not reported  
 Leak Detection: Visual, Stock Inventor

101

**AMRICAN UNIFORM & TOWEL SUPPLY  
 3440 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST S101302069  
 Cortese N/A  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

LUST:  
 Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMRICAN UNIFORM & TOWEL SUPPLY (Continued)**

**S101302069**

How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300578  
 Stop Date: 1990-08-17 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1994-11-29 00:00:00  
 Discover Date: 1989-08-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-08-17 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: KENNETH MILES  
 RP Address: P.O. BOX 54029  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: SD  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H11422-001  
 Case Number: 9UT1787  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMRICAN UNIFORM & TOWEL SUPPLY (Continued)**

**S101302069**

LUST:

Region: 9  
 Case Number: 9UT1787  
 Local Agency: San Diego  
 Substance: Unleaded Gasoline  
 Qty Leaked: 0  
 Date Found: 08/17/1989  
 How Found: Other Means  
 Date Stopped: 08/17/1990  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Drinking Water Aquifer affected  
 Status: Case Closed  
 Abate Method: Vapor Extraction, Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)  
 Confirm Date: 08/17/1989  
 Submit Workplan: 10/15/90  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: 9/17/90  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 11/29/94  
 Pilot Program: LOP  
 Local Case: H11422-001  
 Basin Number: 908.31  
 Gwater Depth: 6.3'  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 10/15/1990  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:

Facility ID: 111422  
 Inactive Indicator: Active  
 Business Code: 6HK54  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3410 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMRICAN UNIFORM & TOWEL SUPPLY (Continued)**

**S101302069**

Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/26/02  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JOANNE CORSO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WATSON CHARLES K&ROBERTA L FAM  
 Property Address: 1110 ALAMEDA BLVD  
 Property City,St,Zip: 92118  
 Tank Owner: AMERICAN COVERALL SUPPLY  
 Tank Address: 3440 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-0395

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/22/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMRICAN UNIFORM & TOWEL SUPPLY (Continued)**

**S101302069**

Occurrences: Not reported  
 Item Number: 3676  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 09/13/01  
 Waste Code: Not reported  
 Type of Violation: 6HX4113  
 Occurrences: Not reported  
 Item Number: 9709  
 Violation Desc: NO GENERATOR'S LABEL IN SHARPS & RED BAG

Inspection Date: 09/13/01  
 Waste Code: Not reported  
 Type of Violation: 6HV4301  
 Occurrences: Not reported  
 Item Number: 9710  
 Violation Desc: MWMP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 11422  
 Number: Not reported  
 Board Of Equalization: 44-022503  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-011422-000001  
 Actv Date: Not reported  
 Capacity: 3000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 11422  
 Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMRICAN UNIFORM & TOWEL SUPPLY (Continued)**

**S101302069**

Board Of Equalization: 44-022503  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-011422-000003  
 Actv Date: Not reported  
 Capacity: 2500  
 Tank Use: CHEMICAL  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 11422  
 Number: 9  
 Board Of Equalization: 44-022503  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-011422-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: OIL  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: 1

**SAN DIEGO CO. SAM:**

Case Number: H11422-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 11/29/1994  
 Begandt: 8/17/1989

101

**AMERICAN COVERALL SUPPLY  
 3440 MAIN ST  
 SAN DIEGO, CA 92113**

**HIST UST U001572968  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000053548  
 Facility Type: Other  
 Other Type: Not reported  
 Total Tanks: 0001  
 Contact Name: Not reported  
 Telephone: 6192326178  
 Owner Name: AMERICAN COVERALL SUPPLY  
 Owner Address: 3440 MAIN ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92113  
  
 Tank Num: 001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN COVERALL SUPPLY (Continued)**

**U001572968**

Container Num: 1  
 Year Installed: 1973  
 Tank Capacity: 00003000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

101

**AMERICAN LINEN SUPPLY  
 3410 MAIN ST  
 SAN DIEGO, CA 92113**

**LUST  
 Cortese  
 San Diego Co. HMMD  
 DRYCLEANERS  
 SAN DIEGO CO. SAM**

**S105035105  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300061  
 Stop Date: 1988-09-19 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-04-18 00:00:00  
 Discover Date: 1988-09-19 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-09-19 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: AL SIBEL  
 RP Address: 3410 MAIN ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN LINEN SUPPLY (Continued)**

**S105035105**

Staff: UNA  
 Staff Initials: CL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H02656-001  
 Case Number: 9UT1046  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 3410 MAIN ST

**San Diego Co. HMMMD:**

Facility ID: 102656  
 Inactive Indicator: Active  
 Business Code: 6HK54  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3410 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/26/02  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: MIKE MERCEREAN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WATSON CHARLES K&ROBERTA L FAM  
 Property Address: 1110 ALAMEDA BLVD  
 Property City, St, Zip: 92118  
 Tank Owner: AMERICAN LINEN SUPPLY CORP.  
 Tank Address: 3410 T MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AMERICAN LINEN SUPPLY (Continued)**

**S105035105**

Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-234-0395

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: #1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 12/05/88  
 Waste Code: Not reported  
 Type of Violation: 6HV1098  
 Occurrences: Not reported  
 Item Number: 6882  
 Violation Desc: HMBP W/O EMERG RESPONSE PLAN

Inspection Date: 12/05/88  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 6883  
 Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

Inspection Date: 10/16/90  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 7531  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/16/90  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7532  
 Violation Desc: WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN LINEN SUPPLY (Continued)**

**S105035105**

Inspection Date: 10/16/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0010  
 Occurrences: Not reported  
 Item Number: 7533  
 Violation Desc: BUS. PLAN NOT COMPLETE/CURRENT/ON SITE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**CLEANERS:**

EPA Id: CAL000123018  
 NAICS Code: 812331  
 NAICS Description: Linen Supply  
 Create Date: 12/6/1994  
 Facility Active: No  
 Inactive Date: 6/30/2002  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3410 MAIN ST  
 Mailing Address 2: Not reported  
 Mailing State: CA  
 Mailing Zip: 921133803  
 Region Code: 4  
 Owner Name: NATIONAL LINEN SERVICE  
 Owner Address: 3410 MAIN ST  
 Owner Address 2: Not reported  
 Owner Telephone: 0  
 Owner Fax Number: Not reported  
 Contact Name: ANGEL DE LA TORRE/MAINT MNGR  
 Contact Address: 3410 MAIN ST  
 Contact Address 2: Not reported  
 Contact Telephone: 6192340395  
 Contact Fax Number: Not reported  
 SIC Description: 7219 Laundry and Garment Services NEC (alteration and repair)  
 SIC Description: 7213 Linen Supply

**SAN DIEGO CO. SAM:**

Case Number: H02656-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**AMERICAN LINEN SUPPLY (Continued)**

**S105035105**

FStatus: Closed Case  
 Date: 4/18/1991  
 Begandt: 9/19/1988

**101      ALSCO AMERICAN LINEN SUPPLY CO  
 3410 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD    S106071194  
 N/A**

San Diego Co. HMMD:

Facility ID:	201138
Inactive Indicator:	Active
Business Code:	6HK54
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	AMERICAN LINEN DIVISION
Mailing Address:	PO BOX 122671
Mailing City,St,Zip:	SAN DIEGO, CA 92112
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	36
EPA ID:	CAL000123018
Gas Station:	Not reported
Inspection Date:	12/26/02
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	CARLOS DE CASAS/ PLANT MGR.
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	WATSON CHARLES K&ROBERTA L FAM
Property Address:	1110 ALAMEDA BLVD
Property City,St,Zip:	92118
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-234-0395

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ALSCO AMERICAN LINEN SUPPLY CO (Continued)**

**S106071194**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5417  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 5418  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 12/26/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 5419  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

101

**NATIONAL LINEN SERVICE  
 3410 MAIN STREET  
 SAN DIEGO, CA 92113**

**Notify 65 U000031089  
 HAZNET N/A**

**Notify 65:**

Date Reported: Not reported  
 Staff Initials: Not reported  
 Board File Number: Not reported  
 Facility Type: Not reported  
 Discharge Date: Not reported  
 Incident Description: 92113-3803

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL LINEN SERVICE (Continued)**

**U000031089**

HAZNET:  
 Gepaid: CAL000123018  
 Contact: NATIONAL LINEN SERVICE  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3410 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133803  
 Gen County: San Diego  
 TSD EPA ID: CAD009452657  
 TSD County: San Mateo  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Not reported  
 Tons: .3336  
 Facility County: San Diego

**101 AMERICAN LINEN SUPPLY  
 3410 MAIN ST  
 SAN DIEGO, CA 92113**

**HIST UST U001572970  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000043430  
 Facility Type: Other  
 Other Type: LAUNDRY  
 Total Tanks: 0001  
 Contact Name: A.J. SIBEL  
 Telephone: 6192340395  
 Owner Name: AMERICAN LINEN SUPPLY CORP.  
 Owner Address: 3410 MAIN ST.  
 Owner City,St,Zip: SAN DIEGO, CA 92113  
  
 Tank Num: 001  
 Container Num: #1  
 Year Installed: 1978  
 Tank Capacity: 00005000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

**101 AMERICAN LINEN SUPPLY  
 3410 S MAIN ST  
 SAN DIEGO, CA 92113**

**SWEEPS UST S106922634  
 N/A**

SWEEPS UST:  
 Status: Not reported  
 Comp Number: 2656  
 Number: Not reported  
 Board Of Equalization: 44-021719  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002656-000001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**AMERICAN LINEN SUPPLY (Continued)**

**S106922634**

Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 2656  
 Number: Not reported  
 Board Of Equalization: 44-021719  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-002656-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 2656  
 Number: 9  
 Board Of Equalization: 44-021719  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

101

**WATSON LAMINATES INC**  
**3388 MAIN ST**  
**SAN DIEGO, CA 92113**

**FINDS 1006826468**  
**HAZNET 110013855480**  
**AIRS**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

**HAZNET:**

Gepaid: CAL000298541  
 Contact: CHARLES WATSON  
 Telephone: 6193394643

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WATSON LAMINATES INC (Continued)**

**1006826468**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13250  
 Mailing City,St,Zip: SAN DIEGO, CA 92118  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 0.62  
 Facility County: Not reported

**EMI:**

Year: 1998  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**WATSON LAMINATES INC (Continued)**

**1006826468**

Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WATSON LAMINATES INC (Continued)**

**1006826468**

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 1.994962  
 Reactive Organic Gases Tons/Yr: 1.929796  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 88032  
 Air District Name: SD  
 SIC Code: 2511  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 6.19  
 Reactive Organic Gases Tons/Yr: 2.71  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

101

**WATSON LAMINATES, INC.**  
**3388 MAIN ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104751674**  
**N/A**

San Diego Co. HMMD:  
 Facility ID: 128693  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3388 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/24/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WATSON LAMINATES, INC. (Continued)**

**S104751674**

Facility Contact: DON WICK  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: NORTH RICHMOND PROPERTIES INC  
 Property Address: 32 WASHINGTON AVE  
 Property City,St,Zip: 94801  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-233-8177

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/24/97  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 9728  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 11/24/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 9729  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 11/24/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9730  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WATSON LAMINATES, INC. (Continued)**

**S104751674**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 200318  
 Inactive Indicator: Active  
 Business Code: 6HK37  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3388 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/26/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JIM JOHNSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: NORTH RICHMOND PROPERTIES INC  
 Property Address: 32 WASHINGTON AVE  
 Property City,St,Zip: 94801  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/26/05  
 Facility Phone: 619-233-8177

**HMMD DISCLOSURE INVENTORY:**

Item Number: CH38  
 Chemical Name: CHROMIUM NITRITE: NATIONAL CASEIN K10 CATYST  
 Case Number: 13548-38-4  
 Quantity Stored At One Time: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**WATSON LAMINATES, INC. (Continued)**

**S104751674**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: IN39  
 Chemical Name: INKS (VARIOUS COLORS)  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: LA40  
 Chemical Name: LACQUER  
 Case Number: 67-64-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: MI58  
 Chemical Name: MINERAL OIL; (MACHINERY HYDROLIC PRESSES)  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PR41  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WATSON LAMINATES, INC. (Continued)**

**S104751674**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 7045  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 04/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 7046  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 04/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 7047  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 04/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1097  
 Occurrences: Not reported  
 Item Number: 7048  
 Violation Desc: HMBP: NO EMPLOYEE TRAINING PROGRAM

Inspection Date: 08/23/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 1063  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 08/23/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1064  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 08/23/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1065  
 Violation Desc: WASTE CONTAINER W/O LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**WATSON LAMINATES, INC. (Continued)**

**S104751674**

Inspection Date: 08/23/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 1066  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 08/23/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 1067  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 08/23/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 1068  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 01/26/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 7794  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 01/26/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: PAINT BOOTH FILTERS  
 Carcinogen: No

Inspection Date: 01/26/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: WASTE OIL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WATSON LAMINATES, INC. (Continued)**

**S104751674**

Carcinogen: No  
 Inspection Date: 01/26/04  
 Waste Item #: 331  
 Waste Code: 331  
 Waste Name: OFF-SPEC,AGED,SURPLU  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 200  
 Annual Qty String: 200  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: WASTE INK/ LAQUER THINNER  
 Carcinogen: No

102

**ANFEL'S AUTO BODY  
 3814 ACACIA ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000203815  
 FINDS CAD095897880**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: ANFEL'S AUTO BODY  
 Facility address: 3814 ACACIA ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD095897880  
 Mailing address: ACACIA ST  
 SAN DIEGO, CA 92113  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: ANGEL GOMEZ  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ANFEL'S AUTO BODY (Continued)**

**1000203815**

NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

103

**YARA NORTH AMERICA, INC**  
**1770 THOR ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104750227**  
**N/A**

San Diego Co. HMMD:

Facility ID: 123233  
 Inactive Indicator: Active  
 Business Code: 6HK39  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1770 THOR ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000096072

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**YARA NORTH AMERICA, INC (Continued)**

**S104750227**

Gas Station: Not reported  
 Inspection Date: 10/20/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: FRED HICKS  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: ARATEX SERVICES INC  
 Property Address: C/O TERI S MALTESE  
 Property City,St,Zip: 91510  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/20/05  
 Facility Phone: 619-236-8241

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC98  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AM97  
 Chemical Name: AMMONIUM PHOSPHATE SULFATE; (P205 20%)  
 Case Number: 7722-76-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: AM92  
 Chemical Name: AMMONIUM SULFATE  
 Case Number: 13814-01-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**YARA NORTH AMERICA, INC (Continued)**

**S104750227**

Item Number: CA90  
 Chemical Name: CALCIUM NITRATE (AMMONIUM CALCIUM NITRATE DECAHYDRATE)  
 Case Number: 39368-85-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: CHRONIC

Item Number: DI94  
 Chemical Name: DIESEL  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: FE95  
 Chemical Name: FERROUS SULFATE  
 Case Number: 7782-63-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HY93  
 Chemical Name: HYDROPRILL (21-7-14; 15-15-15;16-16-15) (NITROGEN-21%)  
 Case Number: 57605-40-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HY05  
 Chemical Name: HYDROTEX (DIESEL ADDITIVE)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YARA NORTH AMERICA, INC (Continued)**

**S104750227**

1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: MA96  
 Chemical Name: MAGNESIUM SULFATE  
 Case Number: 7487-88-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: OI00  
 Chemical Name: OILS: LUBRICATING  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX99  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: UR02  
 Chemical Name: UREA (HYDRO AGRI, UNOCAL, AND HYDROFORM  
 Case Number: 57-13-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**YARA NORTH AMERICA, INC (Continued)**

**S104750227**

**HMMD VIOLATIONS:**

Inspection Date:	10/27/98
Waste Code:	Not reported
Type of Violation:	6HV0209
Occurrences:	Not reported
Item Number:	8834
Violation Desc:	WASTE ONSITE >90/180/270 DAYS
Inspection Date:	10/27/98
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	8835
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	10/27/98
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	8836
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	08/13/97
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	8319
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	10/20/03
Waste Code:	Not reported
Type of Violation:	6HV0204
Occurrences:	Not reported
Item Number:	5384
Violation Desc:	WASTE CONTAINER:IMPROPER MGMT
Inspection Date:	10/20/03
Waste Code:	Not reported
Type of Violation:	6HV0215
Occurrences:	Not reported
Item Number:	5385
Violation Desc:	OIL FILTERS IMPROPERLY MANAGED
Inspection Date:	10/20/03
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	5386
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	10/20/03
Waste Code:	Not reported
Type of Violation:	6HV1011
Occurrences:	Not reported
Item Number:	5387
Violation Desc:	TRAINING RECORDS NOT AVAILABLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**YARA NORTH AMERICA, INC (Continued)**

**S104750227**

**HMMD WASTE STREAMS:**

Inspection Date: 10/20/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: 165 GAL 10/98 ER  
 Carcinogen: No

Inspection Date: 10/20/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 450  
 Quantity String: 450  
 Annual Qty: 450  
 Annual Qty String: 450  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

104

**G&M OIL / MAIN STREET  
 3774 MAIN ST  
 SAN DIEGO, CA 92113**

**FINDS 1006823980  
 AIRS 110013825584**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

**EMI:**

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 3295  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4  
 Reactive Organic Gases Tons/Yr: 4  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**G&M OIL / MAIN STREET (Continued)**

**1006823980**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	3295
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	3295
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	3295
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2003

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**G&M OIL / MAIN STREET (Continued)**

**1006823980**

Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 3295  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 5  
 Reactive Organic Gases Tons/Yr: 5  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 3295  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4.6616052  
 Reactive Organic Gases Tons/Yr: 4.6616052  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 3295  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 4.6616052  
 Reactive Organic Gases Tons/Yr: 4.6616052  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

<b>104</b>	<b>SUNDANCE STAGE LINES</b>	<b>CA WDS</b>	<b>S106100944</b>
	<b>3762 MAIN ST</b>		<b>N/A</b>
	<b>SAN DIEGO, CA 92113</b>		

CA WDS:

Facility ID: San Diego 371001021

Facility Type: Agricultural - Facility that treats and/or disposes of the wastes associated with confined and concentrated animal feeding, confined animal feeding, confined animal holding, confined and concentrated aquatic animal production facilities, and aquaculture. the treatment and/or disposal of agricultural return water is included in this category.

Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.

NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board

Subregion: 9

Facility Telephone: Not reported

Facility Contact: Not reported

Agency Name: SUNDANCE STAGE LINES

Agency Address: Not reported

Agency City,St,Zip: 0

Agency Contact: Not reported

Agency Telephone: Not reported

Agency Type: Private

SIC Code: 0

SIC Code 2: Not reported

Primary Waste: Not reported

Primary Waste Type: Not reported

Secondary Waste: Not reported

Secondary Waste Type: Not reported

Design Flow: 0

Baseline Flow: 0

Reclamation: Not reported

POTW: Not reported

Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

<b>104</b>	<b>SUNDANCE STAGE LINES INC</b>	<b>LUST</b>	<b>U003789308</b>
	<b>3762 MAIN ST</b>	<b>UST</b>	<b>N/A</b>
	<b>SAN DIEGO, CA 92113</b>	<b>San Diego Co. HMMMD</b>	
		<b>SWEEPS UST</b>	
		<b>SAN DIEGO CO. SAM</b>	

LUST:

Region: STATE

Case Type: Other ground water affected

Cross Street: Not reported

Enf Type: Not reported

Funding: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300691  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1995-12-11 00:00:00  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: DAVID CALLENDER  
 RP Address: 3762 MAIN ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10508-001  
 Case Number: 9UT1911  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302293  
 Stop Date: 1997-08-19 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1999-02-05 00:00:00  
 Discover Date: 1997-08-19 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1997-08-19 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: JIM SEATON  
 RP Address: 3762 MAIN ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10508-002  
 Case Number: 9UT3525  
 Qty Leaked: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608157074  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1999-06-02 00:00:00  
 Discover Date: 1999-04-02 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-04-02 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: JOHN REAVES/BILL DAVIS  
 RP Address: 3762 MAIN ST  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10508-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H10508

San Diego Co. HMMD:

Facility ID: 110508  
 Inactive Indicator: Active  
 Business Code: 6HK24  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3762 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000016372  
 Gas Station: Not reported  
 Inspection Date: 04/28/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JIM SEATON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CALLENDER DAVID V  
 Property Address: 3762 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: DAVID V CALLENDER  
 Tank Address: 8221 BEAVER LAKE DR  
 Tank City,St,Zip: San Diego, CA 92109  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/28/05  
 Facility Phone: 619-525-1570

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

HMMD DISCLOSURE INVENTORY:

Item Number:	BR36
Chemical Name:	BRUSHLESS TRUCK & TRAILER WASH
Case Number:	mixture
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	ACUTE
2nd Hazard Category:	Not reported
Item Number:	DI21
Chemical Name:	DIESEL UNDERGROUND TANK 110508 T002
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	Not reported
Item Number:	ET35
Chemical Name:	ETHYLENE GLYCOL
Case Number:	107-21-1
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	CHRONIC
2nd Hazard Category:	Not reported
Item Number:	NA34
Chemical Name:	NAL COOL 300
Case Number:	MIXTURE
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	ACUTE
2nd Hazard Category:	CHRONIC
Item Number:	OI37
Chemical Name:	OIL: LUBRICATING
Case Number:	8002-05-9
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: NT 1973  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: rt1599  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 01/07/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0362  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 01/07/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 0363  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 01/30/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 3659  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 01/30/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 3660  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 01/30/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 3661  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 04/28/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3105  
 Occurrences: Not reported  
 Item Number: 1114

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

Violation Desc: FINANCIAL RESPONSIBILITY EXPIRED  
 Inspection Date: 04/28/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3255  
 Occurrences: Not reported  
 Item Number: 1115  
 Violation Desc: SPILL CONT NOT DRY & IN GOOD CONDITI

Inspection Date: 04/28/04  
 Waste Code: Not reported  
 Type of Violation: 6HV3257  
 Occurrences: Not reported  
 Item Number: 1116  
 Violation Desc: 2NDRY CONTAINMENT NOT LIQUID FREE

**HMMD WASTE STREAMS:**

Inspection Date: 04/28/04  
 Waste Item #: 132  
 Waste Code: 132  
 Waste Name: AQUEOUS SOL'N WITH M  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: SPENT ANTIFREEZE  
 Carcinogen: No

Inspection Date: 04/28/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: SAFETY KLEEN  
 Carcinogen: No

Inspection Date: 04/28/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 1200  
 Annual Qty String: 1200  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

Storage Method: ABVG TNK  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 04/28/04  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 1900  
 Annual Qty String: 1900  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: EXIDE  
 Carcinogen: No

Inspection Date: 04/28/04  
 Waste Item #: 451  
 Waste Code: 451  
 Waste Name: DEGREASING SLUDGE  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: SUMP SLUDGE  
 Carcinogen: No

Inspection Date: 04/28/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

SWEEPS UST:  
 Status: A  
 Comp Number: 10508  
 Number: 9  
 Board Of Equalization: 44-022465  
 Ref Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**U003789308**

Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010508-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: 1

SAN DIEGO CO. SAM:

Case Number: H10508-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - For Non-LOP Tank**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 12/11/1995  
 Begandt: 1/28/1991

Case Number: H10508-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 2/5/1999  
 Begandt: 8/19/1997

Case Number: H10508-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/2/1999  
 Begandt: 4/2/1999

104

**SUNDANCE STAGE LINES INC**  
**3762 MAIN STREET**  
**SAN DIEGO, CA 92113**

**HAZNET S100728067**  
**N/A**

HAZNET:

Gepaid: CAL000016372  
 Contact: SUNDANCE STAGE LINES  
 Telephone: 6195251570  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3762 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Recycler  
 Tons: .7923  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SUNDANCE STAGE LINES INC (Continued)**

**S100728067**

Gepaid: CAL000016372  
 Contact: JIM SEATON  
 Telephone: 6195251570  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3762 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133875  
 Gen County: San Diego  
 TSD EPA ID: UTD981552177  
 TSD County: 99  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: 0.3  
 Facility County: Not reported

Gepaid: CAL000016372  
 Contact: SUNDANCE STAGE LINES  
 Telephone: 6195251570  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3762 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAL000016372  
 Contact: JIM SEATON  
 Telephone: 6195251570  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3762 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133875  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: H14  
 Tons: 0.05  
 Facility County: San Diego

Gepaid: CAL000016372  
 Contact: SUNDANCE STAGE LINES  
 Telephone: 6195251570  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3762 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Recycler

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES INC (Continued)**

**S100728067**

Tons: .6880  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 9 additional CA\_HAZNET: record(s) in the EDR Site Report.

104

**SUNDANCE STAGE LINES  
 3762 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 LUST  
 Cortese**

**S101302070  
 N/A**

HAZNET:

Gepaid: CAC001334496  
 Contact: SUNDANCE STAGE LINES  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3762 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133875  
 Gen County: San Diego  
 TSD EPA ID: CAT080025711  
 TSD County: San Bernardino  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 1.0425  
 Facility County: San Diego

LUST:

Region: 9  
 Case Number: 9UT1911  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 01/28/1991  
 How Found: Other Means  
 Date Stopped: 01/28/1991  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 01/28/1991  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 12/11/95  
 Pilot Program: LOP  
 Local Case: H10508-001  
 Basin Number: 908.31  
 Gwater Depth: 10'  
 Beneficial Use: No Beneficial groundwater use



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SUNDANCE STAGE LINES (Continued)**

**S101302070**

NPDES Number: Not reported  
 priority: 2  
 File Dispn: File discarded, case closed  
 Release Date: 01/28/1991  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Region: 9  
 Case Number: 9UT3525  
 Local Agency: San Diego  
 Substance: Diesel  
 Qty Leaked: Not reported  
 Date Found: 08/19/1997  
 How Found: Tank Closure  
 Date Stopped: 08/19/1997  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)

Confirm Date: 08/19/1997  
 Submit Workplan: 8/28/97  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 2/5/99  
 Pilot Program: LOP  
 Local Case: H10508-002  
 Basin Number: 908.31  
 Gwater Depth: 12.2  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 08/19/1997  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3762 MAIN ST  
  
 Region: CORTESE  
 Facility Addr2: 3762 MAIN ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104 K&R GRAPHIX  
 3754 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103656108  
 N/A**

HAZNET:

Gepaid: CAD024715252  
 Contact: RICHARD PICKENPAUGH  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST STE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAD008488025  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Treatment, Tank  
 Tons: 2.7522  
 Facility County: San Diego

Gepaid: CAD024715252  
 Contact: RICHARD PICKPENPAUGH  
 Telephone: 6192321463  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST STE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAD008488025  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Recycler  
 Tons: 1.37  
 Facility County: Not reported

Gepaid: CAD024715252  
 Contact: RICHARD PICKPENPAUGH  
 Telephone: 6192321463  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST STE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAD008488025  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Recycler  
 Tons: 0.45  
 Facility County: San Diego

Gepaid: CAD024715252  
 Contact: RICHARD PICKENPAUGH  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST STE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAD008488025

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**K&R GRAPHIX (Continued)**

**S103656108**

TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Recycler  
 Tons: .9174  
 Facility County: San Diego

Gepaid: CAD024715252  
 Contact: RICHARD PICKPENPAUGH  
 Telephone: 6192321463  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST STE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Recycler  
 Tons: 0.91  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

104

**MARBLE WORKS OF SAN DIEGO  
 3754 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106062145  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 123578  
 Inactive Indicator: Active  
 Business Code: 6HK77  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3754 MAIN ST #B  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000093181  
 Gas Station: Not reported  
 Inspection Date: 11/07/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: CHARLENE BUTLER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BUTLER-PICKENPAUGH PARTNERSHIP  
 Property Address: 3754 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MARBLE WORKS OF SAN DIEGO (Continued)**

**S106062145**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/07/05  
 Facility Phone: 619-595-1800

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC47  
 Chemical Name: ACETONE  
 Case Number: 67-64-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: AL48  
 Chemical Name: ALUMINUIM TRIHYDRATE  
 Case Number: 21645-51-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: CA52  
 Chemical Name: CALCIUM CARBONATE  
 Case Number: 1317-65-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: PO50  
 Chemical Name: POLYESTER RESIN-GEL COAT  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: RE46  
 Chemical Name: RESIN SOLUTION; POLYSTRENE  
 Case Number: 100-42-5

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARBLE WORKS OF SAN DIEGO (Continued)**

**S106062145**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: ST51  
 Chemical Name: STYRENE MONOMER  
 Case Number: 100-42-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: TI49  
 Chemical Name: TITANIUM DIOXIDE  
 Case Number: 3463-67-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0562  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/13/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 0563  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 01/13/99  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARBLE WORKS OF SAN DIEGO (Continued)**

**S106062145**

Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0564  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 10/08/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9113  
 Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 11/07/03  
 Waste Item #: 252  
 Waste Code: 252  
 Waste Name: STILL BOTTOM WASTE (  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: CARBOY  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: STILL BOTTOM ACETONE SLDG  
 Carcinogen: No

104

**CENTRAL MARBLE SUPPLY  
 3754 MAIN ST  
 SAN DIEGO, CA 92113**

**FINDS 1006824059  
 AIRS 110013826388**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

**EMI:**

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1062  
 Air District Name: SD  
 SIC Code: 3299  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 1  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CENTRAL MARBLE SUPPLY (Continued)**

**1006824059**

Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1062
Air District Name:	SD
SIC Code:	3299
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1062
Air District Name:	SD
SIC Code:	3299
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1062
Air District Name:	SD
SIC Code:	3299
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1062

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CENTRAL MARBLE SUPPLY (Continued)**

**1006824059**

Air District Name: SD  
 SIC Code: 3299  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1062  
 Air District Name: SD  
 SIC Code: 3299  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2.8483924  
 Reactive Organic Gases Tons/Yr: 1.7790924  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1062  
 Air District Name: SD  
 SIC Code: 3299  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2.83  
 Reactive Organic Gases Tons/Yr: 1.768  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

104

**K & R GRAPHICS**  
**3754 MAIN ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106061624**  
**N/A**

San Diego Co. HMMD:  
 Facility ID: 119937  
 Inactive Indicator: Active  
 Business Code: 6HK37  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**K & R GRAPHICS (Continued)**

**S106061624**

2nd Name: Not reported  
 Mailing Address: 3754 MAIN ST #A  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAD024715252  
 Gas Station: Not reported  
 Inspection Date: 11/10/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: R PICKENPAUGH  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BUTLER-PICKENPAUGH PARTNERSHIP  
 Property Address: 3754 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/10/05  
 Facility Phone: 619-232-1463

**HMMD DISCLOSURE INVENTORY:**

Item Number: FE46  
 Chemical Name: FERRIC CHLORIDE 42 GRADES  
 Case Number: 7705-08-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8914  
 Violation Desc: WASTE CONTAINER W/O LABELS  
  
 Inspection Date: 10/28/98

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**K & R GRAPHICS (Continued)**

**S106061624**

Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8915  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 10/28/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8916  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 08/11/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8260  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/11/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8261  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/10/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 5970  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

**HMMD WASTE STREAMS:**

Inspection Date: 11/10/03  
 Waste Item #: 111  
 Waste Code: 111  
 Waste Name: ACID SOL'N WITH META  
 Qty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 1882 ATLAS CHEMICAL & MFG  
 Waste Desc: FECL3 + HCL  
 Carcinogen: No

Inspection Date: 11/10/03  
 Waste Item #: 541  
 Waste Code: 541  
 Waste Name: PHOTOCHEM/PHOTOPROC  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 10

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**K & R GRAPHICS (Continued)**

**S106061624**

Annual Qty String: 10  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 3213 POWERS AND HUNT CO.  
 Waste Desc: SILVER POW/HUNT UNIT  
 Carcinogen: No

104

**MARBLE WORKS  
 3754 MAIN ST, #B  
 SAN DIEGO, CA 92113**

**HAZNET S100732895  
 N/A**

HAZNET:

Gepaid: CAL000093181  
 Contact: MIKE BUTLER/PRES  
 Telephone: 6195951800  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST # B  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD049318009  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .0050  
 Facility County: San Diego

Gepaid: CAL000093181  
 Contact: MIKE BUTLER/PRES  
 Telephone: 6195951800  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST # B  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: .8428  
 Facility County: San Diego

Gepaid: CAL000093181  
 Contact: MIKE BUTLER/PRES  
 Telephone: 6195951800  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST # B  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000646117  
 TSD County: Kings  
 Waste Category: Not reported  
 Disposal Method: Not reported  
 Tons: .0000  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARBLE WORKS (Continued)**

**S100732895**

Gepaid: CAL000093181  
 Contact: MIKE BUTLER/PRES  
 Telephone: 6195951800  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST # B  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .2950  
 Facility County: San Diego

Gepaid: CAL000093181  
 Contact: CHARLENE BUTLER, PRES  
 Telephone: 6195951800  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3754 MAIN ST # B  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: KYD053348108  
 TSD County: 99  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 0.2  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

104

**CENTRAL MARBLE SUPPLY MARBLE WORKS  
 3754 MAIN STREET UNIT B  
 SAN DIEGO, CA 92113**

**FINDS 1005650799  
 110002144046**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**104 SERGIO AUTO ELECTRIC, INC.  
 3746 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106062581  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 127746  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3746 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000194868  
 Gas Station: Not reported  
 Inspection Date: 03/28/05  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: CARMEN MARTINEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DANNA AGNES C TR  
 Property Address: 3354 COPLEY AVE  
 Property City,St,Zip: 92116  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/28/06  
 Facility Phone: 619-531-1144

HMMD DISCLOSURE INVENTORY:  
 Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:  
 Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SERGIO AUTO ELECTRIC, INC. (Continued)**

**S106062581**

**HMMD VIOLATIONS:**

Inspection Date: 01/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 0898  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 10/07/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9074  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/28/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3728  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/28/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3729  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 08/12/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 3204  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 08/12/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3205  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/28/05  
 Waste Code: Not reported  
 Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 8469  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

**HMMD WASTE STREAMS:**

Inspection Date: 03/28/05  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 50

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SERGIO AUTO ELECTRIC, INC. (Continued)**

**S106062581**

Quantity String: 50  
 Annual Qty: 50  
 Annual Qty String: 50  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: SANDBLAST WASTE  
 Carcinogen: No

Inspection Date: 03/28/05  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: 2-CONTAINERS; 1-BASIN  
 Carcinogen: No

Inspection Date: 03/28/05  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 330  
 Annual Qty String: 330  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE OIL  
 Carcinogen: No

Inspection Date: 03/28/05  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: COOLANT  
 Carcinogen: No

Inspection Date: 03/28/05  
 Waste Item #: 444

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SERGIO AUTO ELECTRIC, INC. (Continued)**

**S106062581**

Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 50  
 Quantity String: 50  
 Annual Qty: 2400  
 Annual Qty String: 2400  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: INTERSTATE  
 Carcinogen: No

Inspection Date: 03/28/05  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 2110  
 Annual Qty String: 2110  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

104

**SERGIO'S AUTO ELECTRIC  
 3746 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103987417  
 N/A**

HAZNET:

Gepaid: CAL000194868  
 Contact: ROSARIO/SERGIO/CARMEN MARTINEZ  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3746 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Recycler  
 Tons: .4586  
 Facility County: San Diego

Gepaid: CAL000194868  
 Contact: ROSARIO/SERGIO/CARMEN MARTINEZ  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3746 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SERGIO'S AUTO ELECTRIC (Continued)**

**S103987417**

TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: .4586  
 Facility County: San Diego

104

**SANCHEZ AUTO BODY  
 3746 MAIN STREET #B  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000170709  
 FINDS CAD981390859  
 HAZNET  
 AIRS**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: SANCHEZ AUTO BODY SHOP  
 Facility address: 3746 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981390859  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: MC JAF PARTNERSHIP  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANCHEZ AUTO BODY (Continued)**

**1000170709**

Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 03/14/1986  
 Facility name: SANCHEZ AUTO BODY SHOP  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD981390859  
 Contact: GILBERTO/GLORIA SANCHEZ  
 Telephone: 6192324652  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3746 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Not reported  
 Tons: 0.11  
 Facility County: Not reported

Gepaid: CAD981390859  
 Contact: GILBERTO/GLORIA SANCHEZ  
 Telephone: 6192324652  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANCHEZ AUTO BODY (Continued)**

**1000170709**

Mailing Name: Not reported  
 Mailing Address: 6231 ROANOKE ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921390000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.09  
 Facility County: San Diego

Gepaid: CAD981390859  
 Contact: GILBERTO SANCHEZ R  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3746 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD981390859  
 Contact: GILBERTO SANCHEZ R  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3746 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Paint sludge  
 Disposal Method: Recycler  
 Tons: .1751  
 Facility County: San Diego

Gepaid: CAD981390859  
 Contact: GILBERTO SANCHEZ R  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3746 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Recycler  
 Tons: 0.0834  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SANCHEZ AUTO BODY (Continued)**

**1000170709**

[Click this hyperlink](#) while viewing on your computer to access additional CA\_HAZNET: detail in the EDR Site Report.

EMI:

Year:	1999
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2351
Air District Name:	SD
SIC Code:	7532
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

Year:	2000
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2351
Air District Name:	SD
SIC Code:	7532
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

Year:	2001
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	2351
Air District Name:	SD
SIC Code:	7532
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

Year:	2002
Carbon Monoxide Emissions Tons/Yr:	37

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANCHEZ AUTO BODY (Continued)**

**1000170709**

Air Basin: SD  
 Facility ID: 2351  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2351  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0  
 Reactive Organic Gases Tons/Yr: 0  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2004  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2351  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 0.247921164  
 Reactive Organic Gases Tons/Yr: 0.22866  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2005  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 2351  
 Air District Name: SD  
 SIC Code: 7532  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANCHEZ AUTO BODY (Continued)**

**1000170709**

Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: .247921164  
 Reactive Organic Gases Tons/Yr: .22866  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

104

**SANCHEZ AUTO BODY  
 3746 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106060398  
 N/A**

San Diego Co. HMMD:

Facility ID: 104082  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3746 MAIN ST #B  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAD981390859  
 Gas Station: Not reported  
 Inspection Date: 02/04/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: GILBERTO SANCHEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DANNA AGNES C TR  
 Property Address: 3354 COPLEY AVE  
 Property City,St,Zip: 92116  
 Tank Owner: SANCHEZ AUTO BODY  
 Tank Address: 3746 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/04/05  
 Facility Phone: 619-232-4652

HMMD DISCLOSURE INVENTORY:

Item Number: LA30  
 Chemical Name: LACQUER THINNER  
 Case Number: 8030-31-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANCHEZ AUTO BODY (Continued)**

**S106060398**

Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: AT0156-1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: AT0156-2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: AT0156-3  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 02/04/04  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 20  
 Quantity String: 20  
 Annual Qty: 40  
 Annual Qty String: 40  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PAINT BOOTH FILTERS  
 Carcinogen: No

Inspection Date: 02/04/04  
 Waste Item #: 451  
 Waste Code: 451  
 Waste Name: DEGREASING SLUDGE  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 10  
 Annual Qty String: 10  
 Measurement Unit: LBS  
 Treatment Method: 003 LANDFILL  
 Storage Method: CARBOY  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANCHEZ AUTO BODY (Continued)**

**S106060398**

Waste Desc: SUMP SLUDGE  
 Carcinogen: No  
  
 Inspection Date: 02/04/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: LACQUER THIN./PAINT  
 Carcinogen: No

**104 THE BUMPER GUY INC  
 3746 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S108756327  
 N/A**

HAZNET:  
 Gepaid: CAL000312328  
 Contact: PEDRO CARDENAS  
 Telephone: 6192371353  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2127 OLYMPIC PKWY STE 1006 # 108  
 Mailing City,St,Zip: CHULA VISTA, CA 919151361  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: H06  
 Tons: 0.02  
 Facility County: San Diego

**104 PRO TRANSMISSION & AUTOMOTIVE  
 3738 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104745440  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 102240  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3738 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRO TRANSMISSION & AUTOMOTIVE (Continued)**

**S104745440**

Census Tract Number: 36  
 EPA ID: CAD063116065  
 Gas Station: Not reported  
 Inspection Date: 10/01/96  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: RODNEY MORALES  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DANNA AGNES C TR  
 Property Address: 3354 COPLEY AVE  
 Property City,St,Zip: 92116  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-531-8726

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/24/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7795  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/24/91  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 7796  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PRO TRANSMISSION & AUTOMOTIVE (Continued)**

**S104745440**

Inspection Date: 10/06/93  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9925  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/06/93  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9926  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/06/93  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9927  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 10/06/93  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9928  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 10/06/93  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 9929  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 10/01/96  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 5097  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 10/01/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5098  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/01/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5099  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 10/01/96

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PRO TRANSMISSION & AUTOMOTIVE (Continued)**

**S104745440**

Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 5100  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

Inspection Date: 10/01/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 5101  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**DOOR-MAN  
 3738 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000352156  
 FINDS CAD063116065**

**RCRA-SQG:**

Date form received by agency: 09/01/1996  
 Facility name: DOOR-MAN  
 Facility address: 3738 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD063116065  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DOOR-MAN (Continued)**

**1000352156**

NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Historical Generators:**

Date form received by agency: 09/19/1985  
 Facility name: DOOR-MAN  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

104 WELCHS TIRES, INC.  
 3724 MAIN STREET  
 SAN DIEGO, CA 92113

HAULERS S108487955  
 N/A

HAULERS:  
 Facility ID: 1002197  
 Facility Phone: (619) 234-1271  
 Other: Other: JORGE CUEVA  
 Registration Expires: 12/31/2008  
 Hauls for Public: Yes  
 Number of Vehicles: 4

Facility ID: 1002197  
 Facility Phone: (619) 234-1271  
 Other: Other: JORGE CUEVA  
 Registration Expires: 12/31/2008  
 Hauls for Public: Yes  
 Number of Vehicles: 4

104 WELCHS TIRE CO  
 3724 MAIN ST  
 SAN DIEGO, CA 92113

HAZNET S104581032  
 San Diego Co. HMMD N/A

HAZNET:  
 Gepaid: CAL000180568  
 Contact: JORGE CUEVA  
 Telephone: 6192341271  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3724 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: 0.0003  
 Facility County: San Diego

San Diego Co. HMMD:  
 Facility ID: 137968  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3724 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000180568  
 Gas Station: Not reported  
 Inspection Date: 10/17/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WELCHS TIRE CO (Continued)**

**S104581032**

Facility Contact: JORGE CUEVA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DECUEVA BERTHA S <AKA CUEVA B  
 Property Address: 3724 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/17/05  
 Facility Phone: 619-234-1271

**HMMD DISCLOSURE INVENTORY:**

Item Number: IN58  
 Chemical Name: INDUSTRIAL PURPLE CLEANER AND DEGREASEZ - ZEP INDUSTRIAL PURPLE  
 CLEANER AND  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OI14  
 Chemical Name: OILS, LUBRICATING  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/31/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 2283  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS  
 Inspection Date: 01/31/00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**WELCHS TIRE CO (Continued)**

**S104581032**

Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	2284
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	01/31/00
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	2285
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	01/31/00
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	2286
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	01/31/00
Waste Code:	Not reported
Type of Violation:	6HV1004
Occurrences:	Not reported
Item Number:	2287
Violation Desc:	HMBP NOT SUBMITTED TO HMD
Inspection Date:	08/22/01
Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	8904
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	08/22/01
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	8905
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	08/22/01
Waste Code:	Not reported
Type of Violation:	6HV0208
Occurrences:	Not reported
Item Number:	8906
Violation Desc:	STORAGE AREA: NO WEEKLY INSPECTION
Inspection Date:	08/22/01
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	8907
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	08/22/01
Waste Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WELCHS TIRE CO (Continued)**

**S104581032**

Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8908  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 10/17/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5360  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/17/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 5361  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 10/17/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0213  
 Occurrences: Not reported  
 Item Number: 5362  
 Violation Desc: CONTAINER INCOMPATIBLE W/ WASTE

Inspection Date: 10/17/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 5363  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 10/17/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 5364  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

**HMMD WASTE STREAMS:**

Inspection Date: 10/17/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 40  
 Annual Qty String: 40  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: MINERAL SPIRITS, IPA  
 Carcinogen: No

Inspection Date: 10/17/03



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WELCHS TIRE CO (Continued)**

**S104581032**

Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 400  
 Quantity String: 400  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2790 EVERGREEN ENVIRONMEN  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/17/03  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: OILY ABSORBENT/ RAGS  
 Carcinogen: No

Inspection Date: 10/17/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2790 EVERGREEN ENVIRONMEN  
 Waste Desc: Not reported  
 Carcinogen: No

104

**SALSCO INC**  
**3722 MAIN ST**  
**SAN DIEGO, CA 92113**

San Diego Co. HMMD S106059835  
 N/A

San Diego Co. HMMD:  
 Facility ID: 101626  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 110 C ST 1100

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SALSCO INC (Continued)**

**S106059835**

Mailing City,St,Zip: CA 92101  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: CAD981162043  
 Gas Station: Not reported  
 Inspection Date: 03/26/87  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: AL HEFLIN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: EGLEY MARCELLE L  
 Property Address: P O BOX 371368  
 Property City,St,Zip: 92137  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-231-1436

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 5797  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0108

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SALSCO INC (Continued)**

**S106059835**

Occurrences: Not reported  
 Item Number: 5798  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0042  
 Occurrences: Not reported  
 Item Number: 5799  
 Violation Desc: HAZWASTE CONT. NOT LABELED OR MARKED

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0043  
 Occurrences: Not reported  
 Item Number: 5800  
 Violation Desc: HAZWASTE CONT. NOT DATED WITH START DATE

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0035  
 Occurrences: Not reported  
 Item Number: 5801  
 Violation Desc: HAZWASTE TO AN UNREGISTERED HAULER

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0035  
 Occurrences: Not reported  
 Item Number: 5802  
 Violation Desc: HAZWASTE TO AN UNREGISTERED HAULER

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0034  
 Occurrences: Not reported  
 Item Number: 5803  
 Violation Desc: MANIFEST NOT DONE PRIOR TO TRANSPORT

Inspection Date: 08/15/85  
 Waste Code: Not reported  
 Type of Violation: 6HX0034  
 Occurrences: Not reported  
 Item Number: 5804  
 Violation Desc: MANIFEST NOT DONE PRIOR TO TRANSPORT

Inspection Date: 03/26/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0027  
 Occurrences: Not reported  
 Item Number: 6366  
 Violation Desc: MANIFESTS NOT KEPT FOR 3 YEARS

Inspection Date: 03/26/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0031  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SALSCO INC (Continued)**

**S106059835**

Item Number: 6367  
 Violation Desc: NO HAZWASTE DISPOSAL RECEIPTS

Inspection Date: 03/26/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0034  
 Occurrences: Not reported

Item Number: 6368  
 Violation Desc: MANIFEST NOT DONE PRIOR TO TRANSPORT

Inspection Date: 03/26/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0029  
 Occurrences: Not reported

Item Number: 6369  
 Violation Desc: NO HAZARDOUS WASTE DETERMINATION

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**SALSCO, INC**  
**3722 MAIN ST**  
**SAN DIEGO, CA 92113**

**RCRA-SQG 1000378355**  
**FINDS CAD981162043**

**RCRA-SQG:**

Date form received by agency: 09/01/1996  
 Facility name: SALSCO, INC  
 Facility address: 3722 MAIN ST  
 SAN DIEGO, CA 92113

EPA ID: CAD981162043  
 Mailing address: MAIN ST  
 SAN DIEGO, CA 92113

Contact: Not reported  
 Contact address: Not reported  
 Not reported

Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported

EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SALSCO, INC (Continued)**

**1000378355**

waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: R E HUFFMAN  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**104 MAIN AUTO REPAIR  
 3714 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104747085  
 N/A**

San Diego Co. HMMD:

Facility ID: 111051  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3714 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000098266  
 Gas Station: Not reported  
 Inspection Date: 06/18/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: FRANCISCO BEZERRA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MORALES MIGUEL J&MARIA D J  
 Property Address: 3858 DELTA ST  
 Property City, St, Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-4385

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MAIN AUTO REPAIR (Continued)**

**S104747085**

HMMD VIOLATIONS:

Inspection Date: 03/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 6318  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 03/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6319  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 6320  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 3511  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 04/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3512  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 04/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 3513  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 04/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3514  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/16/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3515  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAIN AUTO REPAIR (Continued)**

**S104747085**

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 1848  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 1849  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 1850  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0207  
 Occurrences: Not reported  
 Item Number: 1851  
 Violation Desc: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

Inspection Date: 12/05/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 1852  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 202004  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAIN AUTO REPAIR (Continued)**

**S104747085**

Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3714 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 06/18/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JOSE RODRIGUEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MORALES MIGUEL J&MARIA D J  
 Property Address: 3858 DELTA ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 12/18/04  
 Facility Phone: 619-238-4385

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAIN AUTO REPAIR (Continued)**

**S104747085**

**HMMD WASTE STREAMS:**

Inspection Date: 06/18/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 2600  
 Annual Qty String: 2600  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: WASTE OIL  
 Carcinogen: No

Inspection Date: 06/18/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: USED BATTERIES: BRODING  
 Carcinogen: No

Inspection Date: 06/18/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 3432 GOLDEN STATE ENV. SE  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

104

**CUCAMANGOS  
 3712 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S103655865  
 San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAL000144654  
 Contact: ARTURO H. TELLO  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CUCAMANGOS (Continued)**

**S103655865**

Mailing Address: 3712 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133830  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: .2668  
 Facility County: San Diego

San Diego Co. HMMMD:

Facility ID: 114043  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3984 HILLTOP AV  
 Mailing City,St,Zip: SAN DIEGO, CA 92102  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000142187  
 Gas Station: Not reported  
 Inspection Date: 06/15/99  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: NORBERTO HUEZO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CLARK WILLIAM&LAUREEN TRUST 10  
 Property Address: 3704 CAMEO CT  
 Property City,St,Zip: 92111  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-499-5116

HMMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CUCAMANGOS (Continued)**

**S103655865**

2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/16/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3449  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 01/16/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 3450  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 01/16/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 3451  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 01/16/96  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3452  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 01/16/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3453  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 01/16/96  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 3454  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 12/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 9979

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CUCAMANGOS (Continued)**

**S103655865**

Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 12/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0206  
 Occurrences: Not reported  
 Item Number: 9980  
 Violation Desc: IGNITABLE WSTE NOT<50FT PROPERTY LINE

Inspection Date: 12/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9981  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 12/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9982  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 06/15/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 5340  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 06/15/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 5341  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 06/15/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5342  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 06/15/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 5343  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CUCAMANGOS (Continued)**

**S103655865**

Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**BENNY AUTO BODY & PAINT  
 3712 MAIN ST.  
 SAN DIEGO, CA 92113**

**HAZNET S101854467  
 N/A**

HAZNET:

Gepaid: CAL000142187  
 Contact: BON SAN ROQUE  
 Telephone: 6192390846  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3712 MAIN ST.  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .0525  
 Facility County: San Diego

Gepaid: CAL000142187  
 Contact: UNDELIVERABLE 1996 FEES FORM  
 Telephone: 6192390846  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3712 MAIN ST.  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Not reported  
 Tons: 0.52  
 Facility County: Not reported

Gepaid: CAL000142187  
 Contact: BON SAN ROQUE  
 Telephone: 6192390846  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3712 MAIN ST.  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BENNY AUTO BODY & PAINT (Continued)**

**S101854467**

Tons: .0175  
 Facility County: San Diego

104

**G & A AUTO AIR  
 3708 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S105112839  
 N/A**

San Diego Co. HMMD:

Facility ID: 108522  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3708 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000224362  
 Gas Station: Not reported  
 Inspection Date: 02/25/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS CARRILLO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CARRILLO CARLOS A&CARRILLO GUA  
 Property Address: C/O GJA AUTO  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/25/05  
 Facility Phone: 619-232-6761

HMMD DISCLOSURE INVENTORY:

Item Number: R148  
 Chemical Name: R12 FREON, 4134 REFRIGERANT  
 Case Number: 75-43-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

HMMD UNDERGROUND TANKS:

Tank Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**G & A AUTO AIR (Continued)**

**S105112839**

Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 05/22/01  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 5866  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 05/22/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5867  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 08/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 0797  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 02/25/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 76  
 Annual Qty String: 76  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESS EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 02/25/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: Not reported  
 Carcinogen: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**G & A AUTO AIR (Continued)**

**S105112839**

Inspection Date: 02/25/04  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: ANTIFREEZE  
 Carcinogen: No

Inspection Date: 02/25/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: Not reported  
 Carcinogen: No

104

**CUSTOM CNTR AUTO BODY & PAINT  
 3708 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMD**

**S105112645  
 N/A**

HAZNET:

Gepaid: CAL000224360  
 Contact: cancel per letter request 5/31  
 Telephone: 6192825738  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3708 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.06  
 Facility County: Not reported

Gepaid: CAL000224360  
 Contact: cancel per letter request 5/31  
 Telephone: 6192825738  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3708 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CUSTOM CNTR AUTO BODY & PAINT (Continued)**

**S105112645**

Gen County:	San Diego
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Recycler
Tons:	0.06
Facility County:	Not reported
San Diego Co. HMMD:	
Facility ID:	102195
Inactive Indicator:	Active
Business Code:	6HK18
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	3708 MAIN ST
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	36
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	05/22/01
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	ANITA CARRILLO
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	CARRILLO CARLOS A&CARRILLO GUA
Property Address:	C/O GJA AUTO
Property City,St,Zip:	92113
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-232-6761
HMMD DISCLOSURE INVENTORY:	
Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CUSTOM CNTR AUTO BODY & PAINT (Continued)**

**S105112645**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**GOLDEN WHEELS  
 3698 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106061473  
 N/A**

San Diego Co. HMMD:

Facility ID: 119324  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3698 1/2 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAD981395221  
 Gas Station: Not reported  
 Inspection Date: 11/19/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: EBRAHIM DAVODI FAR

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GOLDEN WHEELS (Continued)**

**S106061473**

Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KARANA AWATIF LIVING TRUST 11-  
 Property Address: 4430 WOODRIDGE CT  
 Property City,St,Zip: 48328  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/19/05  
 Facility Phone: 619-234-3434

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC07  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: OX89  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/07/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 6308  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 12/07/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GOLDEN WHEELS (Continued)**

**S106061473**

Occurrences: Not reported  
 Item Number: 0912  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/06/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5171  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 11/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6214  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 11/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1011  
 Occurrences: Not reported  
 Item Number: 6215  
 Violation Desc: TRAINING RECORDS NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 11/19/03  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: PAINT, WASTE, THINNER, &  
 Carcinogen: No

104

**GOLDEN WHEELS  
 3698 1/2 MAIN ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000277736  
 FINDS CAD981395221  
 HAZNET**

**RCRA-SQG:**

Date form received by agency: 06/26/1992  
 Facility name: GOLDEN WHEELS  
 Facility address: 3698 1/2 MAIN ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD981395221  
 Contact: EBRAHIM DAVODI FAR  
 Contact address: 3698 1/2 MAIN ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 234-3434

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GOLDEN WHEELS (Continued)**

**1000277736**

Contact email: Not reported  
 EPA Region: 09  
 Land type: Private  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: EBRAHIM DAVODI FAR  
 Owner/operator address: 3698 1/2 MAIN ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 234-3434  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 11/19/2003  
 Date achieved compliance: 02/19/2004  
 Violation lead agency: State  
 Enforcement action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GOLDEN WHEELS (Continued)**

**1000277736**

Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 11/19/2003  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 02/19/2004  
 Evaluation lead agency: State Contractor/Grantee

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD981395221  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1225 E 2ND ST  
 Mailing City,St,Zip: NATIONAL CITY, CA 920500000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD981395221  
 Contact: --  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3698 1/2 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.2  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GOLDEN WHEELS (Continued)**

**1000277736**

Gepaid: CAD981395221  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1225 E 2ND ST  
 Mailing City,St,Zip: NATIONAL CITY, CA 920500000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAD981395221  
 Contact: --  
 Telephone: --  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3698 1/2 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAD981395221  
 Contact: Not reported  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1225 E 2ND ST  
 Mailing City,St,Zip: NATIONAL CITY, CA 920500000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .1980  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 6 additional CA\_HAZNET: record(s) in the EDR Site Report.



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104**      **ESPARZA'S USED TIRES**  
**3698 MAIN ST**  
**SAN DIEGO, CA 92113**

**HAZNET**      **S102429276**  
**LUST**            **N/A**  
**Cortese**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

HAZNET:

Gepaid:            CAC002596843  
 Contact:          AWATIF KARANA  
 Telephone:        2486817580  
 Facility Addr2:    Not reported  
 Mailing Name:     Not reported  
 Mailing Address:  4430 WOODRIDGE CT  
 Mailing City,St,Zip: WATERFORD, MI 48328  
 Gen County:        San Diego  
 TSD EPA ID:        CAD982444481  
 TSD County:        San Bernardino  
 Waste Category:   Unspecified aqueous solution  
 Disposal Method:  Recycler  
 Tons:                0.2  
 Facility County:    San Diego

LUST:

Region:            STATE  
 Case Type:        Other ground water affected  
 Cross Street:      Not reported  
 Enf Type:          Not reported  
 Funding:           NOR  
 How Discovered:   Not reported  
 How Stopped:      Close Tank  
 Leak Cause:        Not reported  
 Leak Source:        Tank  
 Global Id:          T0607301702  
 Stop Date:          1994-09-08 00:00:00  
 Confirm Leak:      Not reported  
 Workplan:          Not reported  
 Prelim Assess:     Not reported  
 Pollution Char:    Not reported  
 Remed Plan:        2004-04-22 00:00:00  
 Remed Action:      Not reported  
 Monitoring:        Not reported  
 Close Date:        Not reported  
 Discover Date:      1994-09-08 00:00:00  
 Enforcement Dt:    Not reported  
 Release Date:      1994-10-10 00:00:00  
 Review Date:        Not reported  
 Enter Date:        Not reported  
 MTBE Date:        Not reported  
 GW Qualifier:      Not reported  
 Soil Qualifier:     Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County:             37  
 Org Name:          Not reported  
 Reg Board:         San Diego Region  
 Status:             Remediation Plan  
 Chemical:          Waste Oil  
 Contact Person:    Not reported  
 Responsible Party: AWATIF KARANA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ESPARZA'S USED TIRES (Continued)**

**S102429276**

RP Address: 4430 WOODRIDGE CT  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: JC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H33453-001  
 Case Number: 9UT2936  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT2936  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 09/08/1994  
 How Found: Tank Closure  
 Date Stopped: 09/08/1994  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 10/10/1994  
 Submit Workplan: Not reported  
 Prelim Assess: 10/25/1994  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H33453-001  
 Basin Number: 908.22

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ESPARZA'S USED TIRES (Continued)**

**S102429276**

Gwater Depth: Not reported  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: File discarded, case closed  
 Release Date: 10/10/1994  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 3698 MAIN ST

**San Diego Co. HMMD:**

Facility ID: 133453  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 6924 COTTONWOOD KNO  
 Mailing City,St,Zip: BLOOMFIELD, MI 48322  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 12/17/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: AWATIF KARANA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: KARANA AWATIF LIVING TRUST 11-  
 Property Address: 4430 WOODRIDGE CT  
 Property City,St,Zip: 48328  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ESPARZA'S USED TIRES (Continued)**

**S102429276**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: 003  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/09/92  
 Waste Code: Not reported  
 Type of Violation: 6HX3002  
 Occurrences: Not reported  
 Item Number: 8890  
 Violation Desc: UST OWNR-OPR W/O HEALTH PERMIT

Inspection Date: 10/09/92  
 Waste Code: Not reported  
 Type of Violation: 6HX3013  
 Occurrences: Not reported  
 Item Number: 8891  
 Violation Desc: NO FINANCIAL RESPOSIBILITY DOC

Inspection Date: 10/09/92  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 8892  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 10/09/92  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 8893  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3002  
 Occurrences: Not reported  
 Item Number: 0197

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ESPARZA'S USED TIRES (Continued)**

**S102429276**

Violation Desc: UST OWNR-OPR W/O HEALTH PERMIT

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3007  
 Occurrences: Not reported  
 Item Number: 0198  
 Violation Desc: NO PERMIT FOR UST REPAIR/UPGRADE/REMOVAL

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3010  
 Occurrences: Not reported  
 Item Number: 0199  
 Violation Desc: PERMIT TO OPERATE APPLIC. NOT COMPLETED

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3012  
 Occurrences: Not reported  
 Item Number: 0200  
 Violation Desc: DIDN'T NOTIFY HMD OF UST CHANGES

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3013  
 Occurrences: Not reported  
 Item Number: 0201  
 Violation Desc: NO FINANCIAL RESPOSIBILITY DOC

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 0202  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3014  
 Occurrences: Not reported  
 Item Number: 0203  
 Violation Desc: QUANT RELEASE DETECTION INADEQUATE

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 0204  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HV3018  
 Occurrences: Not reported  
 Item Number: 0205  
 Violation Desc: IMPROPER INVENTORY RECONCILIATION

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ESPARZA'S USED TIRES (Continued)**

**S102429276**

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3020  
 Occurrences: Not reported  
 Item Number: 0206  
 Violation Desc: PUMP DISPENSER METER NOT CALIBRATED

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3006  
 Occurrences: Not reported  
 Item Number: 0207  
 Violation Desc: DID NOT MEET REQS FOR TEMP CLOSURE

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3032  
 Occurrences: Not reported  
 Item Number: 0208  
 Violation Desc: UST ABANDONED, NO CLOSURE PERMIT

Inspection Date: 12/17/93  
 Waste Code: Not reported  
 Type of Violation: 6HX3033  
 Occurrences: Not reported  
 Item Number: 0209  
 Violation Desc: DID NOT MEET UST CLOSURE REQS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H33453-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: POP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Investigation  
 Date: 4/22/2004  
 Begandt: 9/8/1994

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**104 COMPLETE WELDING OF SD  
 3676 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106466922  
 N/A**

San Diego Co. HMMD:

Facility ID: 203445  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3676 MAIN ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 04/30/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JUVENTINO LUCIO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: MACCECA VICTOR TRUST OF 1991  
 Property Address: 4844 70TH ST  
 Property City, St, Zip: 92115  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 10/30/05  
 Facility Phone: 619-546-9353

HMMD DISCLOSURE INVENTORY:

Item Number: AC77  
 Chemical Name: ACETYLENE GAS  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR78  
 Chemical Name: ARGON GAS/CARBON DIOXIDE MIX MIG MIX/STEEL MIX  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**COMPLETE WELDING OF SD (Continued)**

**S106466922**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: CA79  
 Chemical Name: CARBON DIOXIDE GAS  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: HE80  
 Chemical Name: HELIUM GAS  
 Case Number: 7440-59-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: OX81  
 Chemical Name: OXYGEN GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COMPLETE WELDING OF SD (Continued)**

**S106466922**

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**COMPLETE WELDING OF SAN DIEGO  
 3676 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET S108202967  
 N/A**

**HAZNET:**

Gepaid: CAC002576245  
 Contact: JUVENTINO LUCIO  
 Telephone: 6195206078  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3676 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Treatment, Tank  
 Tons: 0.22  
 Facility County: Not reported

104

**PACIFIC MARINE PROPELLERS INC  
 3781 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104744948  
 N/A**

**San Diego Co. HMMD:**

Facility ID: 100251  
 Inactive Indicator: Active  
 Business Code: 6HK35  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3781 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**PACIFIC MARINE PROPELLERS INC (Continued)**

**S104744948**

Gas Station: Not reported  
 Inspection Date: 09/09/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: BRUCE BRAWN  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: S B S PARTNERSHIP  
 Property Address: C/O NORTHSTAR PROPEL  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/09/05  
 Facility Phone: 619-239-0129

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC64  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR65  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: CA66  
 Chemical Name: CARBON DIOXIDE  
 Case Number: 124-38-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC MARINE PROPELLERS INC (Continued)**

**S104744948**

Item Number: OX62  
 Chemical Name: OXYGEN (8 CYL. @ 400 CU FT EA)7782-44-7  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR63  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 8293  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 10/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8294  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 08/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 8273  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PACIFIC MARINE PROPELLERS INC (Continued)**

**S104744948**

Item Number: 5834  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5835  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/09/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1011  
 Occurrences: Not reported  
 Item Number: 3894  
 Violation Desc: TRAINING RECORDS NOT AVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**MARINE & RESTAURANT FABRICATOR**  
**3768 DALBERGIA ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104749216**  
**N/A**

San Diego Co. HMMD:

Facility ID: 119840  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3768 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000128726  
 Gas Station: Not reported  
 Inspection Date: 01/09/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE & RESTAURANT FABRICATOR (Continued)**

**S104749216**

Violation Notice Issued: Not reported  
 Facility Contact: CARLOS VELAZQUEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WRIGHT CURTISS W REVOCABLE TRU  
 Property Address: 2637 PINE GLEN CT  
 Property City,St,Zip: 92019  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/09/05  
 Facility Phone: 619-232-7267

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC95  
 Chemical Name: ACETYLENE 7782-44-7)  
 Case Number: 74-86=2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AR56  
 Chemical Name: ARGON  
 Case Number: 7440-37-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

Item Number: OX34  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PR33  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE & RESTAURANT FABRICATOR (Continued)**

**S104749216**

Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 06/16/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 7415  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/18/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9848  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 01/09/04  
 Waste Item #: 212  
 Waste Code: 212  
 Waste Name: OXYGENATED SOLVENTS  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 4385 AMERI CHEM  
 Waste Desc: PAINT RELATED WASTE/THINN  
 Carcinogen: No

Inspection Date: 01/09/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 3260  
 Annual Qty String: 3260  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PROCESSING EQUIPMENT

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE & RESTAURANT FABRICATOR (Continued)**

**S104749216**

Haz Waste Hauler: 4385 AMERI CHEM  
 Waste Desc: RAGS/FILTERS  
 Carcinogen: No

104

**MARINE & RESTAURANT FABRICATORS  
 3768 DALBERGIA STREET  
 SAN DIEGO, CA 92113**

**HAZNET**

**S103656173  
 N/A**

HAZNET:

Gepaid: CAL000128726  
 Contact: CURT WRIGHT  
 Telephone: 6192327267  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3768 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Transfer Station  
 Tons: 0.05  
 Facility County: Not reported

Gepaid: CAL000128726  
 Contact: MARINE & RESTAURANT FABRICATIO  
 Telephone: 6192327267  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3768 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Latex waste  
 Disposal Method: Transfer Station  
 Tons: .0625  
 Facility County: San Diego

Gepaid: CAL000128726  
 Contact: MARINE & RESTAURANT FABRICATIO  
 Telephone: 6192327267  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3768 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Recycler  
 Tons: .0667  
 Facility County: San Diego

Gepaid: CAL000128726  
 Contact: MARINE & RESTAURANT FABRICATIO  
 Telephone: 6192327267

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MARINE & RESTAURANT FABRICATORS (Continued)**

**S103656173**

Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3768 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .9922  
 Facility County: San Diego

Gepaid: CAL000128726  
 Contact: MARINE & RESTAURANT FABRICATIO  
 Telephone: 6192327267  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3768 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Latex waste  
 Disposal Method: Recycler  
 Tons: .0667  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 23 additional CA\_HAZNET: record(s) in the EDR Site Report.

104

**MASTER MACHINE CORP  
 3763 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104749217  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 119841  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 900 CIVIC CENTER DR  
 Mailing City,St,Zip: NATIONAL CITY, CA 91950  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/10/93  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: GARY FUNK  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MASTER MACHINE CORP (Continued)**

**S104749217**

Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	PEPPER DAVID M SR&NORA P TRUST
Property Address:	9500 EL GRANITO AVE
Property City,St,Zip:	91941
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-531-1170

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qnty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104**      **DIMENSIONAL SILKSCREEN INC**  
**3750 DALBERGIA ST**  
**SAN DIEGO, CA 92113**

**HAZNET**      **S103960763**  
**San Diego Co. HMMD**      **N/A**

HAZNET:

Gepaid:                    CAL000146591  
 Contact:                    MICHAEL J. TARDY  
 Telephone:                0000000000  
 Facility Addr2:            Not reported  
 Mailing Name:            Not reported  
 Mailing Address:        3750 DALBERGIA ST  
 Mailing City,St,Zip:    SAN DIEGO, CA 921130000  
 Gen County:              San Diego  
 TSD EPA ID:              CAD000088252  
 TSD County:              Los Angeles  
 Waste Category:        Other organic solids  
 Disposal Method:        Transfer Station  
 Tons:                        .0300  
 Facility County:         San Diego

Gepaid:                    CAL000146591  
 Contact:                    MICHAEL J. TARDY/OWNER  
 Telephone:                6192329100  
 Facility Addr2:            Not reported  
 Mailing Name:            Not reported  
 Mailing Address:        3750 DALBERGIA ST  
 Mailing City,St,Zip:    SAN DIEGO, CA 921130000  
 Gen County:              San Diego  
 TSD EPA ID:              CAD028409019  
 TSD County:              San Diego  
 Waste Category:        Other organic solids  
 Disposal Method:        Transfer Station  
 Tons:                        0.1  
 Facility County:         San Diego

San Diego Co. HMMD:

Facility ID:                    100250  
 Inactive Indicator:        Active  
 Business Code:            6HK55  
 SIC:                            Not reported  
 Permit Expiration:        Not reported  
 Owner:                        Not reported  
 2nd Name:                    Not reported  
 Mailing Address:        3750 DALBERGIA ST  
 Mailing City,St,Zip:    SAN DIEGO, CA 92113  
 Map Code/Business Plan on File:    Not reported  
 Corporate Code:            Not reported  
 Fire Dept District:        San Diego  
 Census Tract Number:     36  
 EPA ID:                        CAL000146591  
 Gas Station:                Not reported  
 Inspection Date:            09/08/03  
 Reinspection Date:        Not reported  
 Inspector Name:            MPRICE  
 Violation Notice Issued:    Not reported  
 Facility Contact:            MICHAEL TARDY  
 Delinquent Flag:            Not Delinquent  
 Last Update:                05/10/05  
 Last Delinquent Letter:    Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIMENSIONAL SILKSCREEN INC (Continued)**

**S103960763**

Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: TARDY BERNARD A&SIMETA L  
 Property Address: 502 ANITA ST #98  
 Property City,St,Zip: 91911  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/08/05  
 Facility Phone: 619-232-9100

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3822  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3823  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 09/08/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 60  
 Quantity String: 60  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIMENSIONAL SILKSCREEN INC (Continued)**

**S103960763**

Treatment Method: 007 INCINERATION  
 Storage Method: BOX  
 Haz Waste Hauler: 3233 FOSS ENVIRONMENTA, B  
 Waste Desc: MEK/RAGS  
 Carcinogen: No

Inspection Date: 09/08/03  
 Waste Item #: 541  
 Waste Code: 541  
 Waste Name: PHOTOCHEM/PHOTOPROC  
 Qnty at Inspection: 10  
 Quantity String: 10  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: LBS  
 Treatment Method: 103 TREATED, THEN SEW  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 3213 POWERS AND HUNT CO.  
 Waste Desc: SILVER SLUDGE  
 Carcinogen: No

104

**TRANS TECH TRANSMISSIONS**  
**3644 MAIN ST**  
**SAN DIEGO, CA 92113**

**LUST S105691268**  
**SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608130825  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-06-13 00:00:00  
 Discover Date: 1995-09-26 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1995-09-26 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRANS TECH TRANSMISSIONS (Continued)**

**S105691268**

Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Chlorinated Hydrocarbons  
 Contact Person: Not reported  
 Responsible Party: LANCE AMANO  
 RP Address: 3644 MAIN ST  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H09693-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H09693-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 6/13/1996  
 Begandt: 9/26/1995

104

**BC AUTOMOTIVE**  
**3644 MAIN ST**  
**SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106071306**  
**N/A**

San Diego Co. HMMD:  
 Facility ID: 201259  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 292 COOLWATER DR  
 Mailing City, St, Zip: SAN DIEGO, CA 92114  
 Map Code/Business Plan on File: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BC AUTOMOTIVE (Continued)**

**S106071306**

Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000268265  
 Gas Station: Not reported  
 Inspection Date: 08/06/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: FRANCISCO BECERRA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FUENTES ANTONIO  
 Property Address: 3644 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/06/06  
 Facility Phone: 619-231-9395

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 08/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0131  
 Occurrences: Not reported  
 Item Number: 3671  
 Violation Desc: UPFP NOT OBTAINED for HAZWASTE

Inspection Date: 08/06/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3672

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BC AUTOMOTIVE (Continued)**

**S106071306**

Violation Desc: WASTE CONTAINER W/O LABELS

**HMMD WASTE STREAMS:**

Inspection Date: 08/06/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: WASTE OIL  
 Carcinogen: No

Inspection Date: 08/06/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: USED OIL FILTERS  
 Carcinogen: No

104

**TRANSTECH TRANSMISSIONS**  
**3644 MAIN ST**  
**SAN DIEGO, CA 92113**

San Diego Co. HMMD U001573003  
 HIST UST N/A

San Diego Co. HMMD:  
 Facility ID: 109693  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3644 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/23/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRANSTECH TRANSMISSIONS (Continued)**

**U001573003**

Violation Notice Issued: Not reported  
 Facility Contact: KARLA GARCIA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FUENTES ANTONIO  
 Property Address: 3644 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: ZARCON CORP  
 Tank Address: 3644 MAIN ST  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-232-7430

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 2022  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 2023  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 2024  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRANSTECH TRANSMISSIONS (Continued)**

**U001573003**

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 2025  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2026  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2027  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2028  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 2029  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 03/20/95  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 2030  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 05/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 4572  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 05/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4573  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 05/21/99

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**TRANSTECH TRANSMISSIONS (Continued)**

**U001573003**

Waste Code:	Not reported
Type of Violation:	6HV0403
Occurrences:	Not reported
Item Number:	4574
Violation Desc:	FACILITY DOESN'T MINIMIZE RELEASE
Inspection Date:	05/21/99
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	4575
Violation Desc:	HMBP NOT ESTABISHED/IMPLEMENTED.
Inspection Date:	05/21/99
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	4576
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	01/29/02
Waste Code:	Not reported
Type of Violation:	6HX0108
Occurrences:	Not reported
Item Number:	3553
Violation Desc:	NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE
Inspection Date:	01/29/02
Waste Code:	Not reported
Type of Violation:	6HV0135
Occurrences:	Not reported
Item Number:	3554
Violation Desc:	MANIFESTS/RECEIPTS NO ONSITE
Inspection Date:	01/29/02
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	3555
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	01/29/02
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	3556
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	01/29/02
Waste Code:	Not reported
Type of Violation:	6HV0401
Occurrences:	Not reported
Item Number:	3557
Violation Desc:	TRAINING RECORDS UNAVAILABLE
Inspection Date:	01/29/02
Waste Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRANSTECH TRANSMISSIONS (Continued)**

**U001573003**

Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 3558  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 01/29/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3559  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 201367  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3644 MAIN ST #A  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000253373  
 Gas Station: Not reported  
 Inspection Date: 07/07/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: FUENTES ANTONIO  
 Property Address: 3644 MAIN ST  
 Property City,St,Zip: 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**TRANSTECH TRANSMISSIONS (Continued)**

**U001573003**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/07/06  
 Facility Phone: 619-232-7430

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/22/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6202  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 01/22/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 6203  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 01/22/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 6204  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 07/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 2785  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 07/07/04  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRANSTECH TRANSMISSIONS (Continued)**

**U001573003**

Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 2786  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 07/07/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 2787  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

**HMMD WASTE STREAMS:**

Inspection Date: 07/07/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 95  
 Annual Qty String: 95  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 2986 INDUSTRIAL SOLVENT &  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 07/07/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 220  
 Quantity String: 220  
 Annual Qty: 610  
 Annual Qty String: 610  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

**HIST UST:**

Region: STATE  
 Facility ID: 00000046814  
 Facility Type: Other  
 Other Type: SANDBLASTING & COATI  
 Total Tanks: 0002  
 Contact Name: Not reported  
 Telephone: 6192348366  
 Owner Name: ZARCON CORPORATION  
 Owner Address: 3644 MAIN STREET  
 Owner City,St,Zip: SAN DIEGO, CA 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TRANSTECH TRANSMISSIONS (Continued)**

**U001573003**

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1974  
 Tank Capacity: 00009000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: 1/4 inches  
 Leak Detection: None

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: 1/4 inches  
 Leak Detection: None

104

**DBA ALL TRANSMISSION PRODUCTS  
 3636 MAIN ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106466802  
 N/A**

San Diego Co. HMMD:

Facility ID: 203041  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ATTN: DALE WILDES  
 Mailing Address: 3636 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL920833105  
 Gas Station: Not reported  
 Inspection Date: 01/30/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WILDES DALE T&FRANCES L  
 Property Address: 3636 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/30/05  
 Facility Phone: 619-234-8387

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DBA ALL TRANSMISSION PRODUCTS (Continued)**

**S106466802**

**HMMD DISCLOSURE INVENTORY:**

Item Number: OI16  
 Chemical Name: OILS, LUBRICATING ATF  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: 01/30/04  
 Waste Item #: 135  
 Waste Code: 135  
 Waste Name: UNSPECIFIED AQUEOUS  
 Qty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 15  
 Annual Qty String: 15  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: PARTS WASHER/STEAM  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 60  
 Annual Qty String: 60  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DBA ALL TRANSMISSION PRODUCTS (Continued)**

**S106466802**

Waste Desc: PARTS WASHER/SYSTEM ONE  
 Carcinogen: No  
  
 Inspection Date: 01/30/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 200  
 Quantity String: 200  
 Annual Qty: 400  
 Annual Qty String: 400  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY-KLEEN SYSTEMS  
 Waste Desc: USED OIL  
 Carcinogen: No

104

**INTERNATIONAL COMPOSITES  
 3715 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMD**

**S100725263  
 N/A**

HAZNET:  
 Gepaid: CAL000115008  
 Contact: ERIC SPEYER  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3715 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD070148432  
 TSD County: 1  
 Waste Category: Photochemicals/photoprocessing waste  
 Disposal Method: Not reported  
 Tons: .0417  
 Facility County: San Diego

San Diego Co. HMMD:  
 Facility ID: 100248  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3715 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 09/08/03  
 Reinspection Date: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERNATIONAL COMPOSITES (Continued)**

**S100725263**

Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JORGE M FERNANDEZ  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: DALBERGIA PROPERTIES LLC  
 Property Address: 3035 CAMINITO NIQUEL  
 Property City,St,Zip: 92117  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/08/05  
 Facility Phone: 619-231-4797

**HMMD DISCLOSURE INVENTORY:**

Item Number: AR57  
 Chemical Name: ARGON/CARBON DIOXIDE MIG MIX/STEEL MIX  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: ACUTE

Item Number: OX60  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PO61  
 Chemical Name: POLYESTER RESIN THIXOTROPIC EPOXY RESIN  
 Case Number: 64386-66-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**INTERNATIONAL COMPOSITES (Continued)**

**S100725263**

Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 04/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 3167  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 04/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 3168  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 04/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3169  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 04/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3170  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 04/22/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3171  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 06/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5479  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 06/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5480  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 06/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0403

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**INTERNATIONAL COMPOSITES (Continued)**

**S100725263**

Occurrences: Not reported  
 Item Number: 5481  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 06/21/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 5482  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 05/23/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 5948  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 05/23/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 5949  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 05/23/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 5950  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 05/23/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 5951  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 05/23/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5952  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 3819  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**INTERNATIONAL COMPOSITES (Continued)**

**S100725263**

Item Number: 3820  
 Violation Desc: TRAINING RECORDS UNAVAILABLE  
  
 Inspection Date: 09/08/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3821  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

**HMMD WASTE STREAMS:**

Inspection Date: 09/08/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 120  
 Annual Qty String: 120  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: CAN  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: ACETONE EVAPORATES  
 Carcinogen: No

104

**3713 DALVERGIA ST.  
 SAN DIEGO, CA**

**CHMIRS S105668395  
 N/A**

**CHMIRS:**

OES Incident Number: 00-1322  
 OES notification: 3/20/200010:50:36 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S105668395

Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Unknown
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2000
Agency:	San Diego Collision Specialists
Incident Date:	3/20/200012:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	No
Site Type:	Road
E Date:	Not reported
Substance:	Antifreeze
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	unk
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	antifreeze running down the gutter.

MAP FINDINGS

Map ID Direction EDR ID Number  
 Distance Distance (ft.)Site Database(s) EPA ID Number

104 SAN DIEGO COLLISION SPECIALIST HAZNET S103986259  
 3713 DILBERTIA ST N/A  
 SAN DIEGO, CA 92113

HAZNET:

Gepaid: CAL000139397  
 Contact: MONICA VALENCIA  
 Telephone: 6192380803  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3713 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.45  
 Facility County: Not reported

Gepaid: CAL000139397  
 Contact: MONICA VALENCIA  
 Telephone: 6192380803  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3713 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.29  
 Facility County: Not reported

Gepaid: CAL000139397  
 Contact: MONICA VALENCIA  
 Telephone: 6192380803  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3713 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: San Diego

Gepaid: CAL000139397  
 Contact: MONICA VALENCIA  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3713 DILBERTIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO COLLISION SPECIALIST (Continued)**

**S103986259**

TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: .3335  
 Facility County: San Diego

Gepaid: CAL000139397  
 Contact: MONICA VALENCIA  
 Telephone: 000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3713 DILBERTIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified solvent mixture Waste  
 Disposal Method: Recycler  
 Tons: 0.0667  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 3 additional CA\_HAZNET: record(s) in the EDR Site Report.

104

**SAN DIEGO COLLISION SPECIALIST  
 3713 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S104748453  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 115466  
 Inactive Indicator: Active  
 Business Code: 6HK27  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3713 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000139397  
 Gas Station: Not reported  
 Inspection Date: 07/07/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JACIE MANDIOLA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RICHARDS ROBERT J&EFFIE E REVO  
 Property Address: 280 CALLE LA MIRADA  
 Property City,St,Zip: 91902  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO COLLISION SPECIALIST (Continued)**

**S104748453**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/07/06  
 Facility Phone: 619-238-0803

**HMMD DISCLOSURE INVENTORY:**

Item Number: CA89  
 Chemical Name: CARBON DIOXIDE  
 Case Number: 7440-27-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 5573  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

Inspection Date: 07/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0403  
 Occurrences: Not reported  
 Item Number: 5574  
 Violation Desc: FACILITY DOESN'T MINIMIZE RELEASE

Inspection Date: 07/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5575  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 12/10/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 1072  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 12/10/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0401



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO COLLISION SPECIALIST (Continued)**

**S104748453**

Occurrences: Not reported  
 Item Number: 1073  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 12/10/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 1074  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 02/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 4415  
 Violation Desc: NO TSDf SIGNED MANIFEST ONSITE

Inspection Date: 02/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4416  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 4417  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 11/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4323  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 11/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4324  
 Violation Desc: WASTE CONTAINER NOT CLOSED

**HMMD WASTE STREAMS:**

Inspection Date: 07/07/04  
 Waste Item #: 214  
 Waste Code: 214  
 Waste Name: UNSPEC SOLVENT MIXTU  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 007 INCINERATION

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO COLLISION SPECIALIST (Continued)**

**S104748453**

Storage Method: METAL DRUM  
 Haz Waste Hauler: 0971 PACIFIC COAST LACQUE  
 Waste Desc: PAINT RELATED MATERIAL  
 Carcinogen: No

104

**ELITE AUTO BODY AND PAINT  
 3626 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET**

**S108746831  
 N/A**

HAZNET:

Gepaid: CAL000306302  
 Contact: ENRIQUE MILLAN  
 Telephone: 6197371332  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3626 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133805  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: Los Angeles  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 0.01  
 Facility County: San Diego

104

**VIC'S GO BATTERY  
 3616 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMD**

**S103655398  
 N/A**

HAZNET:

Gepaid: CAL912674828  
 Contact: VICTOR AGUIRRE  
 Telephone: 6192345204  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3616 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133805  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: .0200  
 Facility County: San Diego

Gepaid: CAL912674828  
 Contact: VICTOR AGUIRRE  
 Telephone: 6192345204  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3616 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133805  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VIC'S GO BATTERY (Continued)**

**S103655398**

Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .0500  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 134798  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3616 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL912674828  
 Gas Station: Not reported  
 Inspection Date: 10/31/03  
 Reinspection Date: Not reported  
 Inspector Name: AQUECAN  
 Violation Notice Issued: Not reported  
 Facility Contact: VICTOR AGUIRRE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: AGUIRRE VICTOR  
 Property Address: 3616 MAIN ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 04/30/05  
 Facility Phone: 619-239-5631

HMMD DISCLOSURE INVENTORY:

Item Number: OX05  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: SU06  
 Chemical Name: SULFURIC ACID; BATTERY ELECTROLYTE  
 Case Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**VIC'S GO BATTERY (Continued)**

**S103655398**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: EXTREMELY

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 5888  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5889  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/20/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 5890  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 09/09/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0208  
 Occurrences: Not reported  
 Item Number: 3913  
 Violation Desc: STORAGE AREA: NO WEEKLY INSPECTION

Inspection Date: 09/09/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 3914  
 Violation Desc: HMBP: INADEQUATE SITE MAP

**HMMD WASTE STREAMS:**

Inspection Date: 10/31/03  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**VIC'S GO BATTERY (Continued)**

**S103655398**

Qty at Inspection: 16  
 Quantity String: 16  
 Annual Qty: 64  
 Annual Qty String: 64  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/31/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 230  
 Quantity String: 230  
 Annual Qty: 230  
 Annual Qty String: 230  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: 3-55 GAL AND DM5(S)  
 Carcinogen: No

Inspection Date: 10/31/03  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qty at Inspection: 10000  
 Quantity String: 10000  
 Annual Qty: 240000  
 Annual Qty String: 240000  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: BOX  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: SUN BELT  
 Carcinogen: No

Inspection Date: 10/31/03  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: EFR  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104 ATC VANCOM  
 3683 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1000818857  
 FINDS CAD983647850**

RCRA-SQG:

Date form received by agency: 09/08/1992  
 Facility name: ATC VANCOM  
 Facility address: 3683 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD983647850  
 Mailing address: DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact: JOHN RICARD  
 Contact address: 3683 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 232-7579  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: ATC VANCOM INC  
 Owner/operator address: ONE RIVER PL  
 S HOLLAND, IL 60473  
 Owner/operator country: Not reported  
 Owner/operator telephone: (800) 882-6266  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ATC VANCOM (Continued)**

**1000818857**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

104

**STEVE CAVADAIS  
 3683 DALBERGIA  
 SAN DIEGO, CA 92113**

**HAZNET S103655684  
 N/A**

HAZNET:

Gepaid: CAC001066192  
 Contact: STEVE CAVADAIS  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13707  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: 1.3344  
 Facility County: San Diego

104

**HIGH GEAR TRANSMISSION & AUTOM  
 3683 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106059839  
 N/A**

San Diego Co. HMMD:

Facility ID: 101634  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3683 1/2 DALBERGIA  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/29/01  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: HELIO DELGADILLO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HIGH GEAR TRANSMISSION & AUTOM (Continued)**

**S106059839**

Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	CAVADIAS FAMILY 2003 TRUST 06-
Property Address:	P O BOX 13707
Property City,St,Zip:	92170
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-239-2624

**HMMD DISCLOSURE INVENTORY:**

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

**HMMD VIOLATIONS:**

Inspection Date:	Not reported
Waste Code:	Not reported
Type of Violation:	Not reported
Occurrences:	Not reported
Item Number:	Not reported
Violation Desc:	Not reported

**HMMD WASTE STREAMS:**

Inspection Date:	Not reported
Waste Item #:	Not reported
Waste Code:	Not reported
Waste Name:	Not reported
Qnty at Inspection:	Not reported
Quantity String:	Not reported
Annual Qty:	Not reported
Annual Qty String:	Not reported
Measurement Unit:	Not reported
Treatment Method:	Not reported
Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104 C AND B AUTO REPAIR  
 3683 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**LUST S105691244  
 SAN DIEGO CO. SAM N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: M  
 Leak Source: Tank  
 Global Id: T0607302236  
 Stop Date: 1997-05-19 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: 2004-09-17 00:00:00  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1997-05-19 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1997-05-19 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remedial action (cleanup) Underway  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: STEPHEN CAVADIAS  
 RP Address: P O BOX 13707  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31 Note 2: Ocean  
 Beneficial: IND,REC-1,REC-2,BIOL,WILD,RARE,SPWN  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10655-006  
 Case Number: 9UT3472

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**C AND B AUTO REPAIR (Continued)**

**S105691244**

Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608105479  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-12-23 00:00:00  
 Discover Date: 1991-10-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-12-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**C AND B AUTO REPAIR (Continued)**

**S105691244**

Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10655-005  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608107264  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-12-29 00:00:00  
 Discover Date: 1991-10-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-12-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**C AND B AUTO REPAIR (Continued)**

**S105691244**

MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10655-002  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608119598  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-12-29 00:00:00  
 Discover Date: 1991-10-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-12-02 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**C AND B AUTO REPAIR (Continued)**

**S105691244**

Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10655-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608136292  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-12-29 00:00:00  
 Discover Date: 1991-10-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-12-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**C AND B AUTO REPAIR (Continued)**

**S105691244**

Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10655-004  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Undefined  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608169490  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1993-12-29 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**C AND B AUTO REPAIR (Continued)**

**S105691244**

Discover Date: 1991-10-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1991-12-05 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Not reported  
 RP Address: Not reported  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: MP  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: FAILED PRECISION TEST  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H10655-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H10655-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 12/29/1993  
 Begandt: 10/18/1991

Case Number: H10655-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**C AND B AUTO REPAIR (Continued)**

**S105691244**

FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 12/29/1993  
 Begandt: 10/18/1991

Case Number: H10655-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 12/29/1993  
 Begandt: 10/18/1991

Case Number: H10655-004  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 12/29/1993  
 Begandt: 10/18/1991

Case Number: H10655-005  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Non Billable**  
 FType: Failed Integrity Test  
 FStatus: Closed Case  
 Date: 12/29/1993  
 Begandt: 10/18/1991

Case Number: H10655-006  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Remedial Action (Clean-Up)  
 Date: 5/27/1997  
 Begandt: 5/19/1997

104

**HIGH GEAR TRANSMISSION & AUTO  
 3683 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD  
 SWEEPS UST**

**S106059838  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 101633  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3683 1/2 DALBERGIA  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 05/01/03



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HIGH GEAR TRANSMISSION & AUTO (Continued)**

**S106059838**

Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: TORIBIO NAVARRO  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CAVADIAS FAMILY 2003 TRUST 06-  
 Property Address: P O BOX 13707  
 Property City,St,Zip: 92170  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-239-2624

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/30/00  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 9216  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATs/HAZWASTE

Inspection Date: 10/30/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9217  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/30/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HIGH GEAR TRANSMISSION & AUTO (Continued)**

**S106059838**

Item Number: 9218  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 10/30/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9219  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 10/30/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9220  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 10655  
 Number: 9  
 Board Of Equalization: 44-022481  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010655-000001  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: OIL  
 Stg: P  
 Content: Not reported  
 Number Of Tanks: 7

Status: A  
 Comp Number: 10655  
 Number: 9  
 Board Of Equalization: 44-022481

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HIGH GEAR TRANSMISSION & AUTO (Continued)**

**S106059838**

Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010655-000002  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 10655  
 Number: 9  
 Board Of Equalization: 44-022481  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010655-000003  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 10655  
 Number: 9  
 Board Of Equalization: 44-022481  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010655-000004  
 Actv Date: Not reported  
 Capacity: 1000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 10655  
 Number: 9  
 Board Of Equalization: 44-022481  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010655-000005

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HIGH GEAR TRANSMISSION & AUTO (Continued)**

**S106059838**

Actv Date: Not reported  
 Capacity: 7500  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 10655  
 Number: 9  
 Board Of Equalization: 44-022481  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010655-000006  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 10655  
 Number: 9  
 Board Of Equalization: 44-022481  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-010655-000007  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

104

**SAFIRO PORTABLE TOILETS  
 3683 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD S100728111  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 110655  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 3071  
 Mailing City,St,Zip: NATIONAL CITY, CA 91951  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAFIRO PORTABLE TOILETS (Continued)**

**S100728111**

Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 02/02/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: JAMIE GARCIA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CAVADIAS FAMILY 2003 TRUST 06-  
 Property Address: P O BOX 13707  
 Property City,St,Zip: 92170  
 Tank Owner: STEPHEN AND TULA CAVADIAS  
 Tank Address: P O BOX 13707  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/02/06  
 Facility Phone: 619-232-8606

**HMMD DISCLOSURE INVENTORY:**

Item Number: AL34  
 Chemical Name: ALIPHATIC NAPHTHA, TOILET DEODERIZER  
 Case Number: 64741-65-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: LO 2  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T002  
 Tank ID Number: WO 1  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T003  
 Tank ID Number: G 1  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: G 2  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAFIRO PORTABLE TOILETS (Continued)**

**S100728111**

Tank Number: T005  
 Tank ID Number: D 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T006  
 Tank ID Number: D 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

**HMMD VIOLATIONS:**

Inspection Date: 12/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 1258  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 12/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1259  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 12/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 1260  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 12/17/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 1261  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

Inspection Date: 04/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 3865  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 04/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 3866  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 04/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0137  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAFIRO PORTABLE TOILETS (Continued)**

**S100728111**

Item Number: 3867  
 Violation Desc: MANIFEST NOT COMPLETED PROPERLY

Inspection Date: 04/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 3868  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 04/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 3869  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 4309  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4310  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)	Site	Database(s) EPA ID Number

<b>104</b>	<b>MC AUTO ELECTRIC 3683 DALBERGIA ST SAN DIEGO, CA 92113</b>	<b>San Diego Co. HMMD</b>	<b>S106071742 N/A</b>
------------	---	---------------------------	---------------------------

San Diego Co. HMMD:

Facility ID:	201753
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	3683 1/2 DALBERGIA S
Mailing City, St, Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	36
EPA ID:	CAL000261883
Gas Station:	Not reported
Inspection Date:	10/27/04
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	EFRAIN RODRIGUEZ
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	CAVADIAS FAMILY 2003 TRUST 06-
Property Address:	P O BOX 13707
Property City, St, Zip:	92170
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City, St, Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	04/27/06
Facility Phone:	619-234-5707

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MC AUTO ELECTRIC (Continued)**

**S106071742**

**HMMD VIOLATIONS:**

Inspection Date: 10/27/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 6049  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 10/27/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 30  
 Quantity String: 30  
 Annual Qty: 180  
 Annual Qty String: 180  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 2986 INDUSTRIAL SOLVENT &  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/27/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 165  
 Annual Qty String: 165  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 10/27/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 6000  
 Annual Qty String: 6000  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104 BAY CITIES SERVICES  
 3683 DALBERGIA  
 SAN DIEGO, CA 92113**

**LUST S105032438  
 Cortese N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3683 DALBERGIA

**104 BAY CITIES SERVICES, INC  
 3683 DALBERGIA ST # 3675  
 SAN DIEGO, CA 92113**

**HIST UST U001572972  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000001333  
 Facility Type: Other  
 Other Type: COMPANY TRUCK SERVIC  
 Total Tanks: 0006  
 Contact Name: EDWARD DUTRA  
 Telephone: 6192347774  
 Owner Name: STEPHEN AND TULA CAVADIAS  
 Owner Address: 419 MURRAY DRIVE  
 Owner City,St,Zip: EL CAJON, CA 92020

Tank Num: 001  
 Container Num: LO 2  
 Year Installed: 1984  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: Not reported  
 Tank Construction: 1/4 inches  
 Leak Detection: Vapor Sniff Well

Tank Num: 002  
 Container Num: WO 1  
 Year Installed: 1984  
 Tank Capacity: 00000500  
 Tank Used for: WASTE  
 Type of Fuel: Not reported  
 Tank Construction: 1/4 inches  
 Leak Detection: Vapor Sniff Well

Tank Num: 003  
 Container Num: G 1  
 Year Installed: Not reported  
 Tank Capacity: 00000800  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Vapor Sniff Well

Tank Num: 004  
 Container Num: G 2  
 Year Installed: 1984  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**BAY CITIES SERVICES, INC (Continued)**

**U001572972**

Tank Construction: 1/4 inches  
 Leak Detection: Vapor Sniff Well

Tank Num: 005  
 Container Num: D 1  
 Year Installed: Not reported  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Vapor Sniff Well

Tank Num: 006  
 Container Num: D 2  
 Year Installed: 1984  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: 1/4 inches  
 Leak Detection: Vapor Sniff Well

104

**CHICKS ELECTRIC  
 3592 MAIN ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104745204  
 N/A**

HAZNET:

Gepaid: CAL000018767  
 Contact: JOEL VAN PROYEN, MGR  
 Telephone: 6192322162  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3592 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAC002276177  
 Contact: CHICKS ELECTRIC MOTOR SERVICE  
 Telephone: 6192322162  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3592 MAIN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: IND000646943  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: \*\*\*  
 Tons: 1.1467  
 Facility County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHICKS ELECTRIC (Continued)**

**S104745204**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608124121  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1999-05-03 00:00:00  
 Discover Date: 1999-02-28 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-02-28 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: RICHARD KAHLE OR DAVID KLEIN  
 RP Address: 10954 SANTA MONICA BL  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: Not reported  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H01088-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHICKS ELECTRIC (Continued)**

**S104745204**

Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 101088  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: M D PROPERTIES  
 Property Address: C/O CHICKS ELECTRIC  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHICKS ELECTRIC (Continued)**

**S104745204**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H01088-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - For Non-LOP Tank**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 5/3/1999  
 Begandt: 2/28/1999

104

**EDCO TRANSFER STATION  
 3660 DALBERGIA STREET  
 SAN DIEGO, CA**

**SWF/LF S102362159  
 N/A**

**SWF/LF:**

Region: STATE  
 Facility ID: 37-AA-0105  
 Lat/Long: 32.683330 / -117.113330  
 Owner Name: Edco Disposal Corporation  
 Owner Telephone: 6192873532  
 Owner Address: Not reported  
 Owner Address2: 6670 Federal Blvd  
 Owner City,St,Zip: Lemon Grove, CA 91945  
 Operator: Edco Disposal Corporation  
 Operator Phone: 6192873532  
 Operator Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EDCO TRANSFER STATION (Continued)**

**S102362159**

Operator Address2: 6670 Federal Blvd  
 Operator City,St,Zip: Lemon Grove, CA 91945  
 Operator's Status: Active  
 Permit Date: 12/16/2003  
 Permit Status: Permitted  
 Permitted Acreage: 1.60  
 Activity: Large Volume Transfer/Proc Facility  
 Regulation Status: Permitted  
 Landuse Name: Residential,Industrial,Commercial  
 GIS Source: Map  
 Category: Transfer/Processing  
 Unit Number: 01  
 Inspection Frequency: Monthly  
 Accepted Waste: Construction/demolition,Industrial,Mixed municipal  
 Closure Date: / /  
 Closure Type: Not reported  
 Disposal Acreage: Not reported  
 Swisnumber: 37-AA-0105  
 Issue & Observations: Lemon Grove, CA 91945  
 Program Type: Not reported  
 Permitted Throughput with Units: 1500  
 Actual Throughput with Units: Tons/day  
 Permitted Capacity with Units: 1716  
 Remaining Capacity: Not reported  
 Remaining Capacity with Units: Tons/day

104

**BAY CITIES SERVICES CO INC  
 3660 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET S100727071  
 N/A**

HAZNET:

Gepaid: CAD003233616  
 Contact: STEPHEN CAVADIAS, PRES  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13707  
 Mailing City,St,Zip: SAN DIEGO, CA 921703707  
 Gen County: San Diego  
 TSD EPA ID: CAD093459485  
 TSD County: Fresno  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Transfer Station  
 Tons: .4461  
 Facility County: San Diego

Gepaid: CAD003233616  
 Contact: STEPHEN CAVADIAS, PRES  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13707  
 Mailing City,St,Zip: SAN DIEGO, CA 921703707  
 Gen County: San Diego  
 TSD EPA ID: CAL000113451  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**BAY CITIES SERVICES CO INC (Continued)**

**S100727071**

Tons: .7297  
 Facility County: San Diego  
  
 Gepaid: CAD003233616  
 Contact: STEPHEN CAVADIAS, PRES  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13707  
 Mailing City,St,Zip: SAN DIEGO, CA 921703707  
 Gen County: San Diego  
 TSD EPA ID: CAL000113451  
 TSD County: Los Angeles  
 Waste Category: Unspecified organic liquid mixture  
 Disposal Method: Transfer Station  
 Tons: 1.3552  
 Facility County: San Diego

Gepaid: CAD003233616  
 Contact: STEPHEN CAVADIAS, PRES  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13707  
 Mailing City,St,Zip: SAN DIEGO, CA 921703707  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Transfer Station  
 Tons: .4170  
 Facility County: San Diego

Gepaid: CAD003233616  
 Contact: STEPHEN CAVADIAS, PRES  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13707  
 Mailing City,St,Zip: SAN DIEGO, CA 921703707  
 Gen County: San Diego  
 TSD EPA ID: CAT093459485  
 TSD County: 0  
 Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)  
 Disposal Method: Not reported  
 Tons: .0000  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 10 additional CA\_HAZNET: record(s) in the EDR Site Report.



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104 SANI-TAINER INC  
 3660 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMMD  
 CA WDS**

**S103962337  
 N/A**

HAZNET:

Gepaid: CAL000160382  
 Contact: BILL DEAN - SAFETY DIR  
 Telephone: 6192877555  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 6700 FEDERAL BLVD  
 Mailing City,St,Zip: LEMON GROVE, CA 919451313  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Household waste  
 Disposal Method: Transfer Station  
 Tons: 0.3  
 Facility County: San Diego

Gepaid: CAC000880824  
 Contact: EDCO DISPOSAL CORP  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 6770 FEDERAL BLVD  
 Mailing City,St,Zip: LEMON GROVE, CA 919450000  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 1.6856  
 Facility County: San Diego

Gepaid: CAL000160382  
 Contact: BILL DEAN - SAFETY DIR  
 Telephone: 6192877555  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 6700 FEDERAL BLVD  
 Mailing City,St,Zip: LEMON GROVE, CA 919451313  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Household waste  
 Disposal Method: Not reported  
 Tons: 0.1  
 Facility County: Not reported

San Diego Co. HMMMD:

Facility ID: 105594  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANI-TAINER INC (Continued)**

**S103962337**

Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CAVADIAS FAMILY 2003 TRUST 06-  
 Property Address: P O BOX 13707  
 Property City,St,Zip: 92170  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANI-TAINER INC (Continued)**

**S103962337**

Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

Facility ID: 139233  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 6670 FEDERAL BL  
 Mailing City,St,Zip: LEMON GROVE, CA 91945  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000160582  
 Gas Station: Not reported  
 Inspection Date: 05/17/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DALE HIXSON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CAVADIAS FAMILY 2003 TRUST 06-  
 Property Address: P O BOX 13707  
 Property City,St,Zip: 92170  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 11/17/05  
 Facility Phone: 619-234-7774

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SANI-TAINER INC (Continued)**

**S103962337**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/02/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 8627  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 09/24/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 2457  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 09/24/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 2458  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

**HMMD WASTE STREAMS:**

Inspection Date: 05/17/04  
 Waste Item #: 111  
 Waste Code: 111  
 Waste Name: ACID SOL'N WITH META  
 Qty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: FIBER DRUM  
 Haz Waste Hauler: 0791 RHO-CHEM CORP/A. PHI  
 Waste Desc: HCL & H2S04  
 Carcinogen: No

Inspection Date: 05/17/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 110

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANI-TAINER INC (Continued)**

**S103962337**

Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0791 RHO-CHEM CORP/A. PHI  
 Waste Desc: OIL  
 Carcinogen: No

Inspection Date: 05/17/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 1000  
 Annual Qty String: 1000  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: FIBER DRUM  
 Haz Waste Hauler: 0791 RHO-CHEM CORP/A. PHI  
 Waste Desc: VARIOUS PAINT  
 Carcinogen: No

**CA WDS:**

Facility ID: San Diego 371013840  
 Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.  
 Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.  
 NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board  
 Subregion: 9  
 Facility Telephone: Not reported  
 Facility Contact: Not reported  
 Agency Name: EDCO DISPOSAL CORP  
 Agency Address: Not reported  
 Agency City,St,Zip: 0  
 Agency Contact: Not reported  
 Agency Telephone: Not reported  
 Agency Type: Private  
 SIC Code: 0  
 SIC Code 2: Not reported  
 Primary Waste: Not reported  
 Primary Waste Type: Not reported  
 Secondary Waste: Not reported  
 Secondary Waste Type: Not reported  
 Design Flow: 0  
 Baseline Flow: 0  
 Reclamation: Not reported  
 POTW: Not reported  
 Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SANI-TAINER INC (Continued)**

**S103962337**

to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or those who must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

104

**FIBRE RESOURCES ULTD INC  
 3652 N DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S104398472  
 N/A**

San Diego Co. HMMD:

Facility ID:	126163
Inactive Indicator:	Active
Business Code:	Not reported
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	Not reported
Census Tract Number:	36
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	02/22/91
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	J CASTILLO
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	CAVADIAS FAMILY 2003 TRUST 06-
Property Address:	P O BOX 13707
Property City,St,Zip:	92170
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	Not reported

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**FIBRE RESOURCES ULTD INC (Continued)**

**S104398472**

Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**NATIONAL ORDINANCE COMPANY INC  
 3647 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET S108214684  
 N/A**

**HAZNET:**

Gepaid: CAL000293862  
 Contact: DON SLACK  
 Telephone: 6192381280  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3647 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133812  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Treatment, Tank  
 Tons: 0.22  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL ORDINANCE COMPANY INC (Continued)**

**S108214684**

Gepaid: CAL000293862  
 Contact: DON SLACK  
 Telephone: 6192381280  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3647 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133812  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Treatment, Tank  
 Tons: 1.04  
 Facility County: San Diego

104

**PAUL BROWN  
 3641 DALBERGIA ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S104749743  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 121199  
 Inactive Indicator: Active  
 Business Code: 6HK03  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3641 DALBERGIA  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: HAM JIMMY L  
 Property Address: 3645 DALBERGIA ST  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-561-3186

HMMD DISCLOSURE INVENTORY:  
 Item Number: Not reported  
 Chemical Name: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**PAUL BROWN (Continued)**

**S104749743**

Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**SOUTH BAY SANDBLASTING AND TANK CLEAN  
 1920 UNA ST  
 SAN DIEGO, CA 92113**

**FINDS 1000921667  
 RCRA-NonGen CA0000039461**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING AND TANK CLEAN (Continued)**

**1000921667**

RCRA-NonGen:

Date form received by agency: 04/19/1999  
 Facility name: SOUTH BAY SANDBLASTING AND TANK CLEAN  
 Facility address: 1920 UNA ST  
 SAN DIEGO, CA 92113  
 EPA ID: CA0000039461  
 Contact: CARLOS E BERNAL  
 Contact address: 1920 UNA ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 238-8338  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Private  
 Classification: Non-Generator  
 Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: SOUTH BAY SANDBLASTING AND TANK CLEAN  
 Owner/operator address: 1920 UNA ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 238-8338  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: TSD - Closure/Post-Closure  
 Date violation determined: 03/25/1999  
 Date achieved compliance: 06/08/1999  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 03/25/1999  
 Enf. disposition status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTH BAY SANDBLASTING AND TANK CLEAN (Continued)**

**1000921667**

Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: TSD - General Facility Standards  
 Date violation determined: 03/25/1999  
 Date achieved compliance: 06/08/1999  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: TSD - Contingency Plan and Emergency Procedures  
 Date violation determined: 03/25/1999  
 Date achieved compliance: 06/08/1999  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: TSD - General Facility Standards  
 Date violation determined: 03/25/1999  
 Date achieved compliance: 06/08/1999  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 03/25/1999  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:  
 Evaluation date: 03/25/1999  
 Evaluation: FOCUSED COMPLIANCE INSPECTION  
 Area of violation: TSD - Closure/Post-Closure  
 Date achieved compliance: 06/08/1999  
 Evaluation lead agency: State

Evaluation date: 03/25/1999  
 Evaluation: FOCUSED COMPLIANCE INSPECTION

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING AND TANK CLEAN (Continued)**

**1000921667**

Area of violation: TSD - Contingency Plan and Emergency Procedures  
 Date achieved compliance: 06/08/1999  
 Evaluation lead agency: State

Evaluation date: 03/25/1999  
 Evaluation: FOCUSED COMPLIANCE INSPECTION  
 Area of violation: TSD - General Facility Standards  
 Date achieved compliance: 06/08/1999  
 Evaluation lead agency: State

Evaluation date: 03/25/1999  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

104

**DECA FORKLIFT, INC  
 1920 UNA ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 San Diego Co. HMMD**

**S100727923  
 N/A**

HAZNET:

Gepaid: CAL000000114  
 Contact: AQUARIUS MARINE  
 Telephone: 6192392628  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1920 UNA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133819  
 Gen County: San Diego  
 TSD EPA ID: CAD089446710  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Not reported  
 Tons: .2293  
 Facility County: San Diego

San Diego Co. HMMD:

Facility ID: 109695  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3596 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000008683  
 Gas Station: Not reported  
 Inspection Date: 11/01/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DOUG CESAR  
 Delinquent Flag: Not Delinquent

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DECA FORKLIFT, INC (Continued)**

**S100727923**

Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CESAR DOUGLAS E&JUNE  
 Property Address: 3153 KEMBERLY LN  
 Property City,St,Zip: 91935  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 05/01/06  
 Facility Phone: 619-235-6461

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC15  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: OI14  
 Chemical Name: OILS, MOTOR, ATF (55 GAL)  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OX16  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DECA FORKLIFT, INC (Continued)**

**S100727923**

**HMMD VIOLATIONS:**

Inspection Date: 06/27/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 6141  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 06/27/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0069  
 Occurrences: Not reported  
 Item Number: 6142  
 Violation Desc: STORAGE OF WASTE FOR LONGER THAN 90 DAYS

Inspection Date: 06/27/86  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6143  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 06/27/86  
 Waste Code: Not reported  
 Type of Violation: 6HX0042  
 Occurrences: Not reported  
 Item Number: 6144  
 Violation Desc: HAZWASTE CONT. NOT LABELED OR MARKED

Inspection Date: 11/04/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0027  
 Occurrences: Not reported  
 Item Number: 6484  
 Violation Desc: MANIFESTS NOT KEPT FOR 3 YEARS

Inspection Date: 11/04/87  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 6485  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 11/04/87  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 6486  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 11/04/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0042  
 Occurrences: Not reported  
 Item Number: 6487  
 Violation Desc: HAZWASTE CONT. NOT LABELED OR MARKED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DECA FORKLIFT, INC (Continued)**

**S100727923**

Inspection Date: 11/04/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0034  
 Occurrences: Not reported  
 Item Number: 6488  
 Violation Desc: MANIFEST NOT DONE PRIOR TO TRANSPORT

Inspection Date: 11/04/87  
 Waste Code: Not reported  
 Type of Violation: 6HX0072  
 Occurrences: Not reported  
 Item Number: 6489  
 Violation Desc: TRANSPORT OF HAZWASTE TO UNAUTH POING

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 4723  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4724  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4725  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 4726  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4727  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 05/05/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9837  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/05/03

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DECA FORKLIFT, INC (Continued)**

**S100727923**

Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9838  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 11/01/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0204  
 Occurrences: Not reported  
 Item Number: 6120  
 Violation Desc: WASTE CONTAINER:IMPROPER MGMT

Inspection Date: 11/01/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 6121  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

**HMMD WASTE STREAMS:**

Inspection Date: 11/01/04  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 14  
 Quantity String: 14  
 Annual Qty: 84  
 Annual Qty String: 84  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 1406 SAFETY KLEEN  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: 11/01/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 165  
 Quantity String: 165  
 Annual Qty: 1530  
 Annual Qty String: 1530  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 11/01/04  
 Waste Item #: 342  
 Waste Code: 342  
 Waste Name: ORGANIC LIQUIDS W/ME  
 Qnty at Inspection: 55  
 Quantity String: 55



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DECA FORKLIFT, INC (Continued)**

**S100727923**

Annual Qty:	55
Annual Qty String:	55
Measurement Unit:	GAL
Treatment Method:	001 RECYCLE
Storage Method:	METAL DRUM
Haz Waste Hauler:	3635 KEM
Waste Desc:	ANTIFREEZE
Carcinogen:	No
Inspection Date:	11/01/04
Waste Item #:	444
Waste Code:	444
Waste Name:	USED BATTERIES
Qnty at Inspection:	1840
Quantity String:	1840
Annual Qty:	8000
Annual Qty String:	8000
Measurement Unit:	LBS
Treatment Method:	444 BATTERIES RECYCL
Storage Method:	NONE
Haz Waste Hauler:	9997 UNREGISTERED HAZ WST
Waste Desc:	POWER STRIDE BATTERY
Carcinogen:	No
Inspection Date:	11/01/04
Waste Item #:	888
Waste Code:	888
Waste Name:	USED OIL FILTERS
Qnty at Inspection:	200
Quantity String:	200
Annual Qty:	500
Annual Qty String:	500
Measurement Unit:	LBS
Treatment Method:	888 FILTERS/METAL RE
Storage Method:	METAL DRUM
Haz Waste Hauler:	3635 KEM
Waste Desc:	Not reported
Carcinogen:	No
Facility ID:	123321
Inactive Indicator:	Active
Business Code:	6HK70
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	1920 UNA ST
Mailing City,St,Zip:	SAN DIEGO, CA 92113
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	36
EPA ID:	CA0000039461
Gas Station:	Not reported
Inspection Date:	10/14/96
Reinspection Date:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DECA FORKLIFT, INC (Continued)**

**S100727923**

Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: JUAN LOZA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CESAR DOUGLAS E&JUNE  
 Property Address: 3153 KEMBERLY LN  
 Property City,St,Zip: 91935  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-8338

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site	Database(s)	EPA ID Number

**DECA FORKLIFT, INC (Continued)**

**S100727923**

Storage Method:	Not reported
Haz Waste Hauler:	Not reported
Waste Desc:	Not reported
Carcinogen:	No

104

**AGUINAGA'S MOBIL SHOP  
3625 DALBERGIA ST  
SAN DIEGO, CA 92113**

**San Diego Co. HMMD S106066056  
N/A**

San Diego Co. HMMD:

Facility ID:	139600
Inactive Indicator:	Active
Business Code:	6HK26
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	Not reported
Mailing Address:	PO BOX 131377
Mailing City,St,Zip:	SAN DIEGO, CA 92170
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	36
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	06/12/03
Reinspection Date:	Not reported
Inspector Name:	MPRICE
Violation Notice Issued:	Not reported
Facility Contact:	Not reported
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	DAVILA WILLIAM A&NORMA E
Property Address:	4690 TIVOLI ST
Property City,St,Zip:	92107
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City,St,Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-696-9646

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**AGUINAGA'S MOBIL SHOP (Continued)**

**S106066056**

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 4811  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4812  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4813  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4814  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**104 CRANK IT AUTO ELECTRIC  
 3625 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**San Diego Co. HMMD**

**S106060261  
 N/A**

San Diego Co. HMMD:

Facility ID:	102899
Inactive Indicator:	Active
Business Code:	6HK18
SIC:	Not reported
Permit Expiration:	Not reported
Owner:	Not reported
2nd Name:	JOSE EVILLEGAS
Mailing Address:	4027 ESTRELLA AV #B
Mailing City, St, Zip:	SAN DIEGO, CA 92105
Map Code/Business Plan on File:	Not reported
Corporate Code:	Not reported
Fire Dept District:	San Diego
Census Tract Number:	36
EPA ID:	Not reported
Gas Station:	Not reported
Inspection Date:	02/15/02
Reinspection Date:	Not reported
Inspector Name:	LEGACY
Violation Notice Issued:	Not reported
Facility Contact:	DANIEL QUIROZ
Delinquent Flag:	Not Delinquent
Last Update:	05/10/05
Last Delinquent Letter:	Not reported
Delinquent Comment:	Not reported
Last Letter Type:	Not reported
Property Owner:	Not reported
Property Address:	Not reported
Property City, St, Zip:	Not reported
Tank Owner:	Not reported
Tank Address:	Not reported
Tank City, St, Zip:	Not reported
Business Plan Acceptance Date:	Not reported
Reinspection Date Y2K Compatible:	Not reported
Facility Phone:	619-235-9080

HMMD DISCLOSURE INVENTORY:

Item Number:	Not reported
Chemical Name:	Not reported
Case Number:	Not reported
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	Not reported
2nd Hazard Category:	Not reported

HMMD UNDERGROUND TANKS:

Tank Number:	Not reported
Tank ID Number:	Not reported
Waste or Product:	Not reported
Tank Contents:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CRANK IT AUTO ELECTRIC (Continued)**

**S106060261**

**HMMD VIOLATIONS:**

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 4303  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4304  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 4305  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4306  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**JIM SALLEE  
 1915 UNA ST  
 SAN DIEGO, CA 92113**

**HAZNET S105083087  
 N/A**

**HAZNET:**

Gepaid: CAC001327312  
 Contact: JIM SALLEE  
 Telephone: 6194296365  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2276 POIPU WAY

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**JIM SALLEE (Continued)**

**S105083087**

Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Recycler  
 Tons: .2293  
 Facility County: San Diego

Gepaid: CAC001327312  
 Contact: JIM SALLEE  
 Telephone: 6194296365  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2276 POIPU WAY  
 Mailing City,St,Zip: SAN DIEGO, CA 921540000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Contaminated soil from site clean-ups  
 Disposal Method: Disposal, Land Fill  
 Tons: .1500  
 Facility County: San Diego

104

**TINO'S IRON WORKS  
 1915 UNA ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD

**S106060263  
 N/A**

San Diego Co. HMMD:  
 Facility ID: 102901  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 1915 UNA ST #A  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 02/15/02  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: TINO BARRERA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**TINO'S IRON WORKS (Continued)**

**S106060263**

Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-993-8524

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 4307  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

Inspection Date: 02/15/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 4308  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

104      **DECA FORKLIFT, INC.**      **HAZNET**      **S100730101**  
**3596 DALBERGIA ST**      **San Diego Co. HMMD**      **N/A**  
**SAN DIEGO, CA 92113**

HAZNET:

Gepaid: CAL000008683  
 Contact: CESAR DOUG  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3596 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133811  
 Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Recycler  
 Tons: .4587  
 Facility County: San Diego

Gepaid: CAL000008683  
 Contact: CESAR DOUG  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3596 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133811  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Unspecified sludge waste  
 Disposal Method: Recycler  
 Tons: .4587  
 Facility County: San Diego

Gepaid: CAL000008683  
 Contact: CESAR DOUG  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3596 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133811  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Treatment, Tank  
 Tons: .2085  
 Facility County: San Diego

Gepaid: CAL000008683  
 Contact: CESAR DOUG  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3596 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133811  
 Gen County: San Diego  
 TSD EPA ID: CAD088504881

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DECA FORKLIFT, INC. (Continued)**

**S100730101**

TSD County: Orange  
 Waste Category: Degreasing sludge  
 Disposal Method: Transfer Station  
 Tons: 1.1500  
 Facility County: San Diego

Gepaid: CAL000008683  
 Contact: DOUGLAS CESAR  
 Telephone: 6192356461  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3596 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133811  
 Gen County: San Diego  
 TSD EPA ID: CAD088504881  
 TSD County: Orange  
 Waste Category: Degreasing sludge  
 Disposal Method: Not reported  
 Tons: 0.6  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 8 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 115461  
 Inactive Indicator: Active  
 Business Code: 6HK26  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3596 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000008683  
 Gas Station: Not reported  
 Inspection Date: 11/01/04  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: DOUG CESAR  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CESAR DOUGLAS&JUNE 2002 TRUST  
 Property Address: 3153 KEMBERLY LN  
 Property City,St,Zip: 91935  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DECA FORKLIFT, INC. (Continued)**

**S100730101**

Reinspection Date Y2K Compatible: 05/01/06  
 Facility Phone: 619-235-6461

**HMMD DISCLOSURE INVENTORY:**

Item Number: DI88  
 Chemical Name: DIESEL  
 Case Number: 68476-30-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PR87  
 Chemical Name: PROPANE(LPG), 250 GAL CYLINDER  
 Case Number: 74-98-4  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 07/03/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 5240  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 07/03/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5241  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 12/08/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0976  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/08/99

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DECA FORKLIFT, INC. (Continued)**

**S100730101**

Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 0977  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 4761  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 4762  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 4763  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 05/02/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9811  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 05/02/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 9812  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 11/01/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 6119  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

**HMMD WASTE STREAMS:**

Inspection Date: 11/01/04  
 Waste Item #: 491  
 Waste Code: 491  
 Waste Name: UNSPECIFIED SLUDGE W  
 Qnty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DECA FORKLIFT, INC. (Continued)**

**S100730101**

Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 3635 KEM  
 Waste Desc: SUMP SLUDGE FRM STM CLEAN  
 Carcinogen: No

104

**SOUTHBAY SANDBLAST & TANK CLEANING  
 3589 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1001481070  
 FINDS CAR000051185  
 HAZNET**

RCRA-SQG:

Date form received by agency: 02/08/2000  
 Facility name: SOUTHBAY SANDBLAST & TANK CLEANING  
 Facility address: 3589 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000051185  
 Mailing address: 3763 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact: CARLOS BERNAL  
 Contact address: 3763 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 238-8338  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: LOPEZ CANUTO  
 Owner/operator address: 3763 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 238-8338  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHBAY SANDBLAST & TANK CLEANING (Continued)**

**1001481070**

Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D000  
 Waste name: Not Defined

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D004  
 Waste name: ARSENIC

Waste code: D008  
 Waste name: LEAD

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000051185  
 Contact: CARLOS E BERNAL/ENVMTL MGR  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1343 CESAR CHAVEZ PARKWAY SUITE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTHBAY SANDBLAST & TANK CLEANING (Continued)**

**1001481070**

Gen County: San Diego  
 TSD EPA ID: CAD008252405  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Transfer Station  
 Tons: 5.65  
 Facility County: Not reported

Gepaid: CAR000051185  
 Contact: CARLOS E BERNAL/ENVMTL MGR  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1343 CESAR CHAVEZ PARKWAY SUITE A  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZR000030452  
 TSD County: 99  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Not reported  
 Tons: 2.98  
 Facility County: San Diego

Gepaid: CAR000051185  
 Contact: CARLOS E BERNAL/ENVMTL MGR  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Tank bottom waste  
 Disposal Method: Recycler  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAR000051185  
 Contact: CARLOS E BERNAL/ENVMTL MGR  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: 0.35  
 Facility County: Not reported

Gepaid: CAR000051185  
 Contact: CARLOS E BERNAL/ENVMTL MGR  
 Telephone: 6192388338  
 Facility Addr2: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTHBAY SANDBLAST & TANK CLEANING (Continued)**

**1001481070**

Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Recycler  
 Tons: 3.85  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 3 additional CA\_HAZNET: record(s) in the EDR Site Report.

104

**SOUTH BAY SANDBLASTING  
 3589 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET S103988625  
 San Diego Co. HMMD N/A**

HAZNET:

Gepaid: CAL000157082  
 Contact: SOUTH BAY SANDBLASTING INC  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080011059  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Disposal, Other  
 Tons: .3500  
 Facility County: San Diego

Gepaid: CAL000157082  
 Contact: SOUTH BAY SANDBLASTING INC  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: .4750  
 Facility County: San Diego

Gepaid: CAL000157082  
 Contact: SOUTH BAY SANDBLASTING INC  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Recycler  
 Tons: .5750  
 Facility County: San Diego

Gepaid: CAL000157082  
 Contact: SOUTH BAY SANDBLASTING INC  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Not reported  
 Tons: .4000  
 Facility County: San Diego

Gepaid: CAL000157082  
 Contact: SOUTH BAY SANDBLASTING INC  
 Telephone: 6192388338  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Other  
 Tons: .2125  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 12 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMMD:

Facility ID: 123511  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/30/04  
 Reinspection Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS BERNAL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: CESAR DOUGLAS E&JUNE  
 Property Address: 3153 KEMBERLY LN  
 Property City,St,Zip: 91935  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 07/30/05  
 Facility Phone: 619-238-8338

**HMMD DISCLOSURE INVENTORY:**

Item Number:	AC29
Chemical Name:	ACID, MURIATIC
Case Number:	7647-01-0
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	ACUTE
2nd Hazard Category:	CHRONIC
Item Number:	CO33
Chemical Name:	COATINGS: EPOXY, POLYURETHANE
Case Number:	MIXTURE
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	CHRONIC
2nd Hazard Category:	Not reported
Item Number:	DI35
Chemical Name:	DIESEL
Case Number:	68476-34-6
Quantity Stored At One Time:	Not reported
Quantity Stored at One Time:	Not reported
Annual Quantity String:	Not reported
Annual Quantity String:	Not reported
Measurement Units:	Not reported
Carcinogen:	No
1st Hazard Category:	FIRE
2nd Hazard Category:	CHRONIC
Item Number:	ET34
Chemical Name:	ETHYLENE GLYCOL (COOLANT)
Case Number:	107-21-1

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: CHRONIC

Item Number: GA36  
 Chemical Name: GASOLINE, UNLEADED  
 Case Number: 8690-81-5  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: LA31  
 Chemical Name: LACQUER WASH 201X  
 Case Number: 71-43-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: LU30  
 Chemical Name: LUBRICATING, GEAR, HYDRAULIC  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: OX28  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: PRESSURE RELEASE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Item Number: PR32  
 Chemical Name: PROLINE EPOXY REDUCER  
 Case Number: 64742-95-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PR18  
 Chemical Name: PROPANE PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: RE37  
 Chemical Name: RESIN: EPOXY BASE, MS375, MS440G  
 Case Number: 1330-20-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: RE38  
 Chemical Name: RESIN: EPOXY HARDENER  
 Case Number: 071-36-3  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/24/92

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Waste Code: Not reported  
 Type of Violation: 6HX0010  
 Occurrences: Not reported  
 Item Number: 8283  
 Violation Desc: BUS. PLAN NOT COMPLETE/CURRENT/ON SITE

Inspection Date: 09/25/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0108  
 Occurrences: Not reported  
 Item Number: 7507  
 Violation Desc: NO PERMIT OBTAINED FOR HAZMATS/HAZWASTE

Inspection Date: 09/25/90  
 Waste Code: Not reported  
 Type of Violation: 6HX0010  
 Occurrences: Not reported  
 Item Number: 7508  
 Violation Desc: BUS. PLAN NOT COMPLETE/CURRENT/ON SITE

Inspection Date: 09/25/90  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 7509  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 12/30/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0193  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/30/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0205  
 Occurrences: Not reported  
 Item Number: 0194  
 Violation Desc: WASTE CONTAINER: POOR CONDITION

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9880  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 9881  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 07/19/02  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9882  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0210  
 Occurrences: Not reported  
 Item Number: 9883  
 Violation Desc: DID NOT CLEAN SPILL TO FLOOR

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0215  
 Occurrences: Not reported  
 Item Number: 9884  
 Violation Desc: OIL FILTERS IMPROPERLY MANAGED

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 9885  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0405  
 Occurrences: Not reported  
 Item Number: 9886  
 Violation Desc: AISLE SPACE IS OBSTRUCTED

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0406  
 Occurrences: Not reported  
 Item Number: 9887  
 Violation Desc: CONT PLAN NOT PREPARED/ONSITE

Inspection Date: 07/19/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9888  
 Violation Desc: HMBP NOT ESTABISHED/IMPLEMENTED.

Inspection Date: 01/30/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 8071  
 Violation Desc: NO TSDF SIGNED MANIFEST ONSITE

Inspection Date: 01/30/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1601

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Occurrences: Not reported  
 Item Number: 8072  
 Violation Desc: HAZWASTE TANKS W/O P.E. ASSESSMENT

**HMMD WASTE STREAMS:**

Inspection Date: 01/30/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: ABVG TNK  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 223  
 Waste Code: 223  
 Waste Name: UNSPEC OIL CONTAININ  
 Qty at Inspection: 50  
 Quantity String: 50  
 Annual Qty: 220  
 Annual Qty String: 220  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: RAS SATURATED WITH OIL  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 351  
 Waste Code: 351  
 Waste Name: ORGANIC SOLIDS WITH  
 Qty at Inspection: 110  
 Quantity String: 110  
 Annual Qty: 110  
 Annual Qty String: 110  
 Measurement Unit: GAL  
 Treatment Method: 205 RECLAIMED  
 Storage Method: Not reported  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: SANDBLASTER WASTE  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Annual Qty String: 55  
 Measurement Unit: LBS  
 Treatment Method: 007 INCINERATION  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: RAGS SATURATED WITH SOLVE  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 401  
 Waste Code: 401  
 Waste Name: OXY PRIMER & NON-SLI  
 Qty at Inspection: 85  
 Quantity String: 85  
 Annual Qty: 85  
 Annual Qty String: 85  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: PAINT, EXPOXY PRIMER & NO  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 461  
 Waste Code: 461  
 Waste Name: PAINT SLUDGE  
 Qty at Inspection: 8000  
 Quantity String: 8000  
 Annual Qty: 100000  
 Annual Qty String: 100000  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: PAINT DEBRIS  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 491  
 Waste Code: 491  
 Waste Name: UNSPECIFIED SLUDGE W  
 Qty at Inspection: 36  
 Quantity String: 36  
 Annual Qty: 36  
 Annual Qty String: 36  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIRONMENTAL  
 Waste Desc: UNSPECIFIED WASTE SLUDGE  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 512  
 Waste Code: 512  
 Waste Name: EMPTY CONTNR(30 GAL+



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING (Continued)**

**S103988625**

Qty at Inspection: 600  
 Quantity String: 600  
 Annual Qty: 840  
 Annual Qty String: 840  
 Measurement Unit: LBS  
 Treatment Method: 205 RECLAIMED  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 CODE BLANK  
 Waste Desc: CROWN OR POCO OIL  
 Carcinogen: No

Inspection Date: 01/30/04  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: Not reported  
 Carcinogen: No

104

**SOUTH BAY SANDBLASTING  
 3577 DALBERGIA ST  
 SAN DIEGO, CA 92113**

San Diego Co. HMMD S104756252  
 N/A

San Diego Co. HMMD:  
 Facility ID: 137560  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3763 DALBERGIA ST  
 Mailing City, St, Zip: SAN DIEGO, CA 92118  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 11/17/97  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: CARLOS BERNAL  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: LOZA JUAN H&BERTHA

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOUTH BAY SANDBLASTING (Continued)**

**S104756252**

Property Address: C/O CCI COASTAL COAT  
 Property City,St,Zip: 92113  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-238-8338

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**104 CHAPMANS DIESEL SALES AND SVC  
 3561 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1001201435  
 FINDS CAR000020883  
 HAZNET  
 San Diego Co. HMMD**

RCRA-SQG:

Date form received by agency: 07/15/1997  
 Facility name: CHAPMANS DIESEL SALES AND SVC  
 Facility address: 3561 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000020883  
 Mailing address: DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact: GORDON KING  
 Contact address: 3561 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 Contact country: US  
 Contact telephone: (619) 234-7247  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: ALDON LEASING  
 Owner/operator address: 4565 ESTRELLA AVE  
 SAN DIEGO, CA 92115  
 Owner/operator country: Not reported  
 Owner/operator telephone: (619) 583-5247  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHAPMANS DIESEL SALES AND SVC (Continued)**

**1001201435**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAR000020883  
 Contact: ALDON LEASING  
 Telephone: 6195835247  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3561 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Metal dust - machining waste and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)  
 Disposal Method: Disposal, Other  
 Tons: 1.1250  
 Facility County: San Diego

Gepaid: CAR000020883  
 Contact: ALDON LEASING  
 Telephone: 6195835247  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3561 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Metal dust - machining waste and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)  
 Disposal Method: Not reported  
 Tons: 1.2000  
 Facility County: San Diego

Gepaid: CAR000020883  
 Contact: ALDON LEASING  
 Telephone: 6195835247  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3561 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHAPMANS DIESEL SALES AND SVC (Continued)**

**1001201435**

TSD EPA ID: CAD000088252  
 TSD County: Los Angeles  
 Waste Category: Metal dust - machining waste and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)  
 Disposal Method: Transfer Station  
 Tons: 1.2000  
 Facility County: San Diego

Gepaid: CAR000020883  
 Contact: ALDON LEASING  
 Telephone: 6195835247  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3561 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: CAT080033681  
 TSD County: Los Angeles  
 Waste Category: Other organic solids  
 Disposal Method: Disposal, Land Fill  
 Tons: .9000  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMMD:

Facility ID: 136733  
 Inactive Indicator: Active  
 Business Code: 6HK70  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3561 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 08/20/03  
 Reinspection Date: Not reported  
 Inspector Name: MPRICE  
 Violation Notice Issued: Not reported  
 Facility Contact: ROY E. BENNINGTON  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: BENNINGTON ROY E  
 Property Address: 3561 DALBERGIA ST  
 Property City,St,Zip: 92113

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHAPMANS DIESEL SALES AND SVC (Continued)**

**1001201435**

Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City, St, Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 02/20/05  
 Facility Phone: 619-858-8500

**HMMD DISCLOSURE INVENTORY:**

Item Number: HY54  
 Chemical Name: HYDROCHLORIC ACID 30%  
 Case Number: 7645-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO53  
 Chemical Name: SODIUM HYDROXIDE  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 01/14/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 0495  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 04/07/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 3242  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 04/07/99  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHAPMANS DIESEL SALES AND SVC (Continued)**

**1001201435**

Item Number: 3243  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS  
  
 Inspection Date: 07/12/00  
 Waste Code: Not reported  
 Type of Violation: 6HX2001  
 Occurrences: Not reported  
 Item Number: 6648  
 Violation Desc: HAZMAT HANDLER W/O HEALTH PERMIT

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

104

**MAJOR SCIENTIFIC INDUSTRIES  
 3557 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**RCRA-CESQG 1008194437  
 CAL000004153**

**RCRA-CESQG:**

Date form received by agency: 02/27/2004  
 Facility name: MAJOR SCIENTIFIC INDUSTRIES  
 Facility address: 3557 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAL000004153  
 Contact: CHET A VEDDER  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 232-9774  
 Contact email: MAJSCI@AOL.COM  
 EPA Region: 09  
 Classification: Conditionally Exempt Small Quantity Generator  
 Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**1008194437**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: MAJOR SCIENTIFIC INDUSTRIES  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 11/01/1987  
 Owner/Op end date: Not reported

Owner/operator name: NANCYE VEDDER  
 Owner/operator address: 3705 ALCOTT ST  
 SAN DIEGO, CA 92107  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 11/01/1987  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: Yes  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**1008194437**

Accumulated waste on-site: No  
 Generated waste on-site: No

**Hazardous Waste Summary:**

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

104

**MAJOR SCIENTIFIC INDUSTRIES  
 3557 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**FINDS 1008229252  
 HAZNET 110021007202**

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAL000004153  
 Contact: CHET VEDDER/OWNER  
 Telephone: 6192329774  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3557 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: NJD062204864  
 TSD County: San Diego  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Not reported  
 Tons: 2.71  
 Facility County: San Diego

104

**MAJOR SCIENTIFIC INDUSTRIES  
 3557 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET S100734218  
 San Diego Co. HMMD N/A**

**HAZNET:**

Gepaid: CAL000004153  
 Contact: CHET VEDDER/OWNER  
 Telephone: 6192329774  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**S100734218**

Mailing Address: 3557 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: NVT330010000  
 TSD County: 99  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 0.79  
 Facility County: Not reported

Gepaid: CAL000004153  
 Contact: CHET VEDDER/OWNER  
 Telephone: 6192329774  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3557 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: TXD077603371  
 TSD County: 99  
 Waste Category: Unspecified sludge waste  
 Disposal Method: H06  
 Tons: 0.02  
 Facility County: San Diego

Gepaid: CAL000004153  
 Contact: DONALD & NANCYE VEDDER  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3557 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: AZD980735500  
 TSD County: 99  
 Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals  
 (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt,  
 copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium,  
 vanadium, and zinc)  
 Disposal Method: Recycler  
 Tons: .7955  
 Facility County: San Diego

Gepaid: CAL000004153  
 Contact: CHET VEDDER/GENERAL MGR  
 Telephone: 6192329774  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3557 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Santa Clara  
 Waste Category: Liquids with cyanides > 1000 mg/l  
 Disposal Method: Recycler  
 Tons: 0.12  
 Facility County: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**S100734218**

Gepaid: CAL000004153  
 Contact: DONALD & NANCYE VEDDER  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3557 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921130000  
 Gen County: San Diego  
 TSD EPA ID: NJD052204864  
 TSD County: 99  
 Waste Category: Not reported  
 Disposal Method: \*\*\*  
 Tons: 5.0040  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 128457  
 Inactive Indicator: Active  
 Business Code: 6HK36  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3557 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000004153  
 Gas Station: Not reported  
 Inspection Date: 07/27/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: CHET VEDDER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: VEDDER FAMILY TRUST B 06-22-99  
 Property Address: 3705 ALCOTT ST  
 Property City,St,Zip: 92106  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/07/06  
 Facility Phone: 619-232-9774

HMMD DISCLOSURE INVENTORY:

Item Number: BU03  
 Chemical Name: BUTOXYETHANOL 30% SCREEN CLEANER

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**S100734218**

Case Number: 111-76-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: MU01  
 Chemical Name: MURIATIC ACID  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: SO02  
 Chemical Name: SODIUM HYDROXIDE  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 11/19/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported  
 Item Number: 9641  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 11/19/97  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 9642  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 03/08/99

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**S100734218**

Waste Code:	Not reported
Type of Violation:	6HV0301
Occurrences:	Not reported
Item Number:	2286
Violation Desc:	HAZWASTE:UNAUTHORIZED DISPOSAL
Inspection Date:	03/08/99
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	2287
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0209
Occurrences:	Not reported
Item Number:	5535
Violation Desc:	WASTE ONSITE >90/180/270 DAYS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0202
Occurrences:	Not reported
Item Number:	5536
Violation Desc:	WASTE CONTAINER W/O LABELS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0216
Occurrences:	Not reported
Item Number:	5537
Violation Desc:	HAZMATS WITHOUT PROPER LABELS
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0201
Occurrences:	Not reported
Item Number:	5538
Violation Desc:	WASTE CONTAINER NOT CLOSED
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0208
Occurrences:	Not reported
Item Number:	5539
Violation Desc:	STORAGE AREA: NO WEEKLY INSPECTION
Inspection Date:	03/13/02
Waste Code:	Not reported
Type of Violation:	6HV0304
Occurrences:	Not reported
Item Number:	5540
Violation Desc:	WASTE DETERMINATION NOT MADE
Inspection Date:	03/13/02
Waste Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**S100734218**

Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 5541  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0402  
 Occurrences: Not reported  
 Item Number: 5542  
 Violation Desc: TRAINING PROGRAM NOT ADEQUATE

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0405  
 Occurrences: Not reported  
 Item Number: 5543  
 Violation Desc: AISLE SPACE IS OBSTRUCTED

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 5544  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 03/13/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1096  
 Occurrences: Not reported  
 Item Number: 5545  
 Violation Desc: NO EMPLOYEE TRAINING RECORDS

Inspection Date: 07/27/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3352  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/27/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 3353  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 07/27/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 3354  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 07/27/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0209

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**S100734218**

Occurrences: Not reported  
 Item Number: 3355  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 07/27/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0209  
 Occurrences: Not reported  
 Item Number: 3356  
 Violation Desc: WASTE ONSITE >90/180/270 DAYS

Inspection Date: 07/27/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0301  
 Occurrences: Not reported  
 Item Number: 3357  
 Violation Desc: HAZWASTE:UNAUTHORIZED DISPOSAL

**HMMD WASTE STREAMS:**

Inspection Date: 07/27/04  
 Waste Item #: 171  
 Waste Code: 171  
 Waste Name: METAL SLUDGE  
 Qnty at Inspection: 1000  
 Quantity String: 1000  
 Annual Qty: 2000  
 Annual Qty String: 2000  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: 0586 CHEMICAL DISPOSAL CO  
 Waste Desc: CUPRIC CHLORIDE&HCL/FLTRS  
 Carcinogen: No

Inspection Date: 07/27/04  
 Waste Item #: 171  
 Waste Code: 171  
 Waste Name: METAL SLUDGE  
 Qnty at Inspection: 2500  
 Quantity String: 2500  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: CAN  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: SLUDGES,DEBERING,COPPER  
 Carcinogen: No

Inspection Date: 07/27/04  
 Waste Item #: 172  
 Waste Code: 172  
 Waste Name: METAL DUST & MACHINI  
 Qnty at Inspection: 2000  
 Quantity String: 2000  
 Annual Qty: 2000  
 Annual Qty String: 2000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MAJOR SCIENTIFIC INDUSTRIES (Continued)**

**S100734218**

Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: BOX  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: ERM,CIR BORD SHDNG&DRLL C  
 Carcinogen: No

Inspection Date: 07/27/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: CARBOY  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: MEK WIPES/EXCSS PAINTS/IN  
 Carcinogen: No

Inspection Date: 07/27/04  
 Waste Item #: 711  
 Waste Code: 711  
 Waste Name: LIQUIDS W CYANIDES -  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 5  
 Annual Qty String: 5  
 Measurement Unit: GAL  
 Treatment Method: 999 UNKNOWN  
 Storage Method: CARBOY  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: CN GOLD RINSE WATERS&BATH  
 Carcinogen: No

104

**ARAMARK UNIFORM SERVICES  
 3554 DALBERGIA  
 SAN DIEGO, CA 92170**

**RCRA-SQG 1000404132  
 LUST CAD087579892  
 Cortese**

RCRA-SQG:

Date form received by agency: 02/17/2006  
 Facility name: ARAMARK UNIFORM SERVICES  
 Facility address: 3554 DALBERGIA ST  
 SAN DIEGO, CA 92113  
 EPA ID: CAD087579892  
 Mailing address: 3554 DALBERGIA STREET  
 SAN DIEGO, CA 92113  
 Contact: SAMUEL J NIEMANN  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (317) 581-0668  
 Contact email: SAM@TWCINDY.NET  
 EPA Region: 09  
 Classification: Small Small Quantity Generator



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICES (Continued)**

**1000404132**

Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: ARAMARK UNIFORM & CAREER APPAREL, INC.  
 Owner/operator address: 115 N. FIRST STREET  
 BURBANK, CA 91502  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 01/01/1980  
 Owner/Op end date: Not reported

Owner/operator name: ARAMARK UNIFORM & CAREER APPAREL, INC.  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 01/01/1980  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARAMARK UNIFORM SERVICES (Continued)**

**1000404132**

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Lamps  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Historical Generators:

Date form received by agency: 02/17/2006  
 Facility name: ARAMARK UNIFORM SERVICES  
 Classification: Small Quantity Generator

Date form received by agency: 12/17/1997  
 Facility name: ARAMARK UNIFORM SERVICES  
 Site name: ARAMARK UNIFORM SVCS  
 Classification: Small Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: ARAMARK UNIFORM SERVICES  
 Site name: ARAMARK UNIFORM SVCS  
 Classification: Small Quantity Generator

Date form received by agency: 02/28/1996  
 Facility name: ARAMARK UNIFORM SERVICES  
 Classification: Large Quantity Generator

Date form received by agency: 09/26/1980  
 Facility name: ARAMARK UNIFORM SERVICES  
 Site name: ARAMARK UNIFORM SVCS  
 Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE

Waste code: F002  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICES (Continued)**

**1000404132**

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE  
 Amount (Lbs): 3680.1

Waste code: F002  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 3680.1

Violation Status: No violations found

LUST:

Region: 9  
 Case Number: 9UT2546  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 01/28/1987  
 How Found: Tank Closure  
 Date Stopped: 01/28/1987  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: No Action Required - incident is minor, requiring no remedial action  
 Confirm Date: 02/10/1987  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 8/19/91  
 Pilot Program: LOP  
 Local Case: H21198-002  
 Basin Number: 908.22  
 Gwater Depth: 30'  
 Beneficial Use: Not reported  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICES (Continued)**

**1000404132**

Release Date: 02/10/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3554 DALBERGIA ST

104

**ARAMARK UNIFORM SERVICE INC  
 3554 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 LUST  
 San Diego Co. HMMD  
 DRYCLEANERS  
 SAN DIEGO CO. SAM**

**S103655092  
 N/A**

HAZNET:  
 Gepaid: CAD087579892  
 Contact: ARAMARK UNIFORM SERVICES INC  
 Telephone: 8189733700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1827 WALDEN OFFICE SQ STE 200  
 Mailing City,St,Zip: SCHAUMBURG, IL 601734275  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Treatment, Tank  
 Tons: 1.3552  
 Facility County: San Diego

Gepaid: CAD087579892  
 Contact: ARAMARK UNIFORM SERVICES INC  
 Telephone: 8189733700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1827 WALDEN OFFICE SQ STE 200  
 Mailing City,St,Zip: SCHAUMBURG, IL 601734275  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Treatment, Tank  
 Tons: 1.3343  
 Facility County: San Diego

Gepaid: CAD087579892  
 Contact: ARAMARK UNIFORM SERVICES INC  
 Telephone: 8189733700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1827 WALDEN OFFICE SQ STE 200  
 Mailing City,St,Zip: SCHAUMBURG, IL 601734275  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Disposal Method: Transfer Station  
 Tons: 5.7837  
 Facility County: San Diego

Gepaid: CAD087579892  
 Contact: ARAMARK UNIFORM SERVICES INC  
 Telephone: 8189733700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1827 WALDEN OFFICE SQ STE 200  
 Mailing City,St,Zip: SCHAUMBURG, IL 601734275  
 Gen County: San Diego  
 TSD EPA ID: CAD050806850  
 TSD County: Los Angeles  
 Waste Category: Other inorganic solid waste  
 Disposal Method: Transfer Station  
 Tons: .1750  
 Facility County: San Diego

Gepaid: CAD087579892  
 Contact: ARAMARK UNIFORM SERVICES INC  
 Telephone: 8189733700  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 1827 WALDEN OFFICE SQ STE 200  
 Mailing City,St,Zip: SCHAUMBURG, IL 601734275  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)  
 Disposal Method: Transfer Station  
 Tons: .6255  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 8 additional CA\_HAZNET: record(s) in the EDR Site Report.

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T06019721782  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2006-08-03 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Close Date: Not reported  
 Discover Date: Not reported  
 Enforcement Dt: Not reported  
 Release Date: Not reported  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Not reported  
 Contact Person: Not reported  
 Responsible Party: Stephanie Walter  
 RP Address: 2300 Warrentville Road  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21198-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Structure Failure  
 Leak Source: Tank  
 Global Id: T0607300419  
 Stop Date: 1987-01-06 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2006-09-08 00:00:00  
 Discover Date: 1987-01-06 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-01-06 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: Robert J. Robbins  
 RP Address: 3554 DALBERGIA ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: LA  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 5  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21198-001  
 Case Number: 9UT16  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
  
 Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607301291  
 Stop Date: 1987-02-10 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1991-08-19 00:00:00  
 Discover Date: 1987-02-10 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-02-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: BILL WITHROW  
 RP Address: 3554 DALBERGIA ST  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: AN  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.22  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H21198-002  
 Case Number: 9UT2546  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Waste Disch Assigned Name: Not reported  
 Summary: Not reported

San Diego Co. HMMD:

Facility ID: 121198  
 Inactive Indicator: Active  
 Business Code: 6HK54  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 3554 DALBERGIA ST  
 Mailing City,St,Zip: SAN DIEGO, CA 92113  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAD087579892  
 Gas Station: Not reported  
 Inspection Date: 03/05/04  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: RICHARD KENNARD  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RED STAR INDUSTRIAL SERVICE  
 Property Address: C/O ARATEX SERVICES  
 Property City,St,Zip: 91502  
 Tank Owner: ARATEX SERVICES INC  
 Tank Address: 3554 DALBERGIA  
 Tank City,St,Zip: San Diego, CA 92113  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 09/05/05  
 Facility Phone: 619-234-6562

HMMD DISCLOSURE INVENTORY:

Item Number: CA43  
 Chemical Name: CALCIUM HYDROXIDE LIME  
 Case Number: 1305-62-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: ACUTE

Item Number: CA31  
 Chemical Name: CATIONIC POLYMER POLYCLEAR CL III  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: CO29  
 Chemical Name: CONDITIONER TEXSTAT II  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: CO32  
 Chemical Name: CONDITIONER TURBO FLEXTRA VISCO CONDITIONER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: ET59  
 Chemical Name: ETHYLENE ACETYLENE  
 Case Number: 74-85-1  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: FE39  
 Chemical Name: FERRIC CHLORIDE FERRIC CHLORIDE  
 Case Number: 7705-08-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: CHRONIC

Item Number: HY35  
 Chemical Name: HYDRAULIC OIL HYDRAULIC LUBRICATING OIL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Case Number: 64742-54-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: HY17  
 Chemical Name: HYDROFLUOSILICIC ACID TURBOLIZER  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: ACUTE

Item Number: HY34  
 Chemical Name: HYPOCHLORITE AQUEOUS SOLUTION LIQUID CHLORINE BLEACH 12.5%  
 Case Number: 7681-52-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: CHRONIC

Item Number: OX37  
 Chemical Name: OXYGEN OXYGEN, COMPRESSED GAS  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PE58  
 Chemical Name: PERLITE (HARBOLITE) PERLITE VOLCANIC GLASS  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

ARAMARK UNIFORM SERVICE INC (Continued)

S103655092

Item Number: PE35  
 Chemical Name: PETROLEUM DISTILLATE FROC FLOCCULANT AE 8405H POLYCLEAR  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: PE33  
 Chemical Name: PETROLEUM DISTILLATES ILF-15  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: REACTIVE

Item Number: PR33  
 Chemical Name: PROPANE PROPANE (LP GAS)  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: SO18  
 Chemical Name: SOAP TURBO FRESH  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: SO11  
 Chemical Name: SOAP TURBO OVERDRIVE  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

Item Number: SO10  
 Chemical Name: SODIUM HYDROXIDE TURBO CHARGE II  
 Case Number: 1310-73-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: ACUTE

Item Number: SO28  
 Chemical Name: SODIUM THIOSULFATE TURBO TEX  
 Case Number: 7772-98-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: REACTIVE  
 2nd Hazard Category: CHRONIC

Item Number: ST19  
 Chemical Name: STARCIT TURBO CRISP LIQUID STARCH  
 Case Number: MIXTURE  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: CHRONIC  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T003  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

**HMMD VIOLATIONS:**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Inspection Date: 03/23/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 2783  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 12/12/97  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 9985  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0304  
 Occurrences: Not reported  
 Item Number: 4778  
 Violation Desc: WASTE DETERMINATION NOT MADE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 4779  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/27/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 4780  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

Inspection Date: 03/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0133  
 Occurrences: Not reported  
 Item Number: 9315  
 Violation Desc: MANIFEST COPY NOT SENT TO DTSC

Inspection Date: 03/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 9316  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/05/04  
 Waste Code: Not reported  
 Type of Violation: 6HV1604  
 Occurrences: Not reported  
 Item Number: 9317  
 Violation Desc: 2ND. CONTAINMENT NOT KEPT EMPTY

Inspection Date: 03/05/04

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Waste Code: Not reported  
 Type of Violation: 6HV1003  
 Occurrences: Not reported  
 Item Number: 9318  
 Violation Desc: HMBP NOT AMENDED W/IN 30 DAYS

**HMMD WASTE STREAMS:**

Inspection Date: 03/05/04  
 Waste Item #: 134  
 Waste Code: 134  
 Waste Name: AQUEOUS SOL'N W/LESS  
 Qnty at Inspection: 440  
 Quantity String: 440  
 Annual Qty: 825  
 Annual Qty String: 825  
 Measurement Unit: GAL  
 Treatment Method: Not reported  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: HAZARDOUS LIQUID WASTE N.  
 Carcinogen: No

Inspection Date: 03/05/04  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 300  
 Quantity String: 300  
 Annual Qty: 1500  
 Annual Qty String: 1500  
 Measurement Unit: GAL  
 Treatment Method: Not reported  
 Storage Method: PLASTIC DRUM  
 Haz Waste Hauler: Not reported  
 Waste Desc: MIXED WASTE OIL  
 Carcinogen: No

**CLEANERS:**

EPA Id: CAC002351231  
 NAICS Code: 812332  
 NAICS Description: Industrial Launderers  
 Create Date: 7/19/2001  
 Facility Active: No  
 Inactive Date: 9/10/2002  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3554 DALBERGIA ST  
 Mailing Address 2: Not reported  
 Mailing State: CA  
 Mailing Zip: 921130000  
 Region Code: 4  
 Owner Name: ARAMARK UNIFORM SERVICES INC  
 Owner Address: 3554 DALBERGIA ST  
 Owner Address 2: Not reported  
 Owner Telephone: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARAMARK UNIFORM SERVICE INC (Continued)**

**S103655092**

Owner Fax Number: Not reported  
 Contact Name: GLENNA SPADROW  
 Contact Address: 3554 DALBERGIA ST  
 Contact Address 2: Not reported  
 Contact Telephone: 8585501131  
 Contact Fax Number: Not reported  
 SIC Description: 7218 Industrial Launderers

**SAN DIEGO CO. SAM:**

Case Number: H21198-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Closed Case  
 Date: 9/8/2006  
 Begandt: 1/6/1987

Case Number: H21198-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/19/1991  
 Begandt: 2/10/1987

Case Number: H21198-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Preliminary Assessment  
 Date: 8/3/2006  
 Begandt: Not reported

104

**ARATEX SERVICES INC.  
 3554 DALBERGIA ST  
 SAN DIEGO, CA 92113**

**HAZNET S102424058  
 LUST N/A  
 Cortese  
 DRYCLEANERS  
 SWEEPS UST**

**HAZNET:**

Gepaid: CAD087579892  
 Contact: TOM DIKOS  
 Telephone: 7084799487  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2300 WARRENVILLE ROAD  
 Mailing City,St,Zip: DOWNERS GROVE, IL 605151765  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 2.98  
 Facility County: Not reported

Gepaid: CAD087579892  
 Contact: TOM DIKOS



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARATEX SERVICES INC. (Continued)**

**S102424058**

Telephone: 7084799487  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2300 WARRENVILLE RD  
 Mailing City,St,Zip: DOWNERS GROVE, IL 605151765  
 Gen County: San Diego  
 TSD EPA ID: AZR000030452  
 TSD County: 99  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Not reported  
 Tons: 20.85  
 Facility County: San Diego

Gepaid: CAD087579892  
 Contact: TOM DIKOS  
 Telephone: 6302712979  
 Facility Addr2: Not reported  
 Mailing Name: ARAMARK UNIFORM SVCS & CAREER APPAR  
 Mailing Address: 2300 WARRENVILLE ROAD  
 Mailing City,St,Zip: DOWNERS GROVE, IL 605151765  
 Gen County: San Diego  
 TSD EPA ID: AZC950823111  
 TSD County: San Diego  
 Waste Category: Not reported  
 Disposal Method: Not reported  
 Tons: 25.28  
 Facility County: San Diego

Gepaid: CAD087579892  
 Contact: TOM DIKOS  
 Telephone: 7084799487  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2300 WARRENVILLE ROAD  
 Mailing City,St,Zip: DOWNERS GROVE, IL 605151765  
 Gen County: San Diego  
 TSD EPA ID: CAD008302903  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 2.98  
 Facility County: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: 9  
 Case Number: 9UT16  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 01/06/1987  
 How Found: Tank Closure  
 Date Stopped: 01/06/1989  
 How Stopped: Close Tank  
 Source: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARATEX SERVICES INC. (Continued)**

**S102424058**

Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site  
 Confirm Date: 01/07/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 08/12/1987  
 Desc Pollution: Not reported  
 Remed Plan: 02/11/1987  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 1/7/89  
 Closed Date: 8/8/91  
 Pilot Program: LOP  
 Local Case: H21198-001  
 Basin Number: 908.22  
 Gwater Depth: 12  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 01/07/1987  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 3554 DALBERGIA ST

**CLEANERS:**

EPA Id: CAD087579892  
 NAICS Code: 812332  
 NAICS Description: Industrial Launderers  
 Create Date: 7/23/1982  
 Facility Active: Yes  
 Inactive Date: Not reported  
 Facility Addr2: Not reported  
 Mailing Name: ARAMARK UNIFORM SVCS & CAREER APPAR  
 Mailing Address: 2300 WARRENVILLE RD  
 Mailing Address 2: Not reported  
 Mailing State: IL  
 Mailing Zip: 605151765  
 Region Code: 4  
 Owner Name: ARAMARK UNIFORM & CAREER  
 Owner Address: 115 N FIRST ST  
 Owner Address 2: Not reported  
 Owner Telephone: Not reported  
 Owner Fax Number: Not reported  
 Contact Name: TOM DIKOS  
 Contact Address: 2300 WARRENVILLE RD  
 Contact Address 2: Not reported  
 Contact Telephone: 7084799487

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARATEX SERVICES INC. (Continued)**

**S102424058**

Contact Fax Number: Not reported  
 SIC Description: 7218 Industrial Launderers

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 21198  
 Number: Not reported  
 Board Of Equalization: 44-003362  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021198-000001  
 Actv Date: Not reported  
 Capacity: 5000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: 2

Status: Not reported  
 Comp Number: 21198  
 Number: Not reported  
 Board Of Equalization: 44-003362  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021198-000002  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 21198  
 Number: 9  
 Board Of Equalization: 44-003362  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-021198-000003  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 1

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

<b>104</b>	<b>ARATEX SERVICES, INC.</b> <b>3554 DALBERGIA STREET</b> <b>SAN DIEGO, CA 92113</b>	<b>FINDS</b>	<b>1007467035</b> <b>110017404487</b>
------------	--	--------------	--

FINDS:  
Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RACT/BACT/LAER Clearinghouse (RBLC) data base contains case-specific information on the 'Best Available' air pollution technologies that have been required to reduce the emission of air pollutants from stationary sources (e.g., power plants, steel mills, chemical plants, etc.). This information has been provided by State and local permitting agencies. The Clearinghouse also contains a regulation data base that summarizes EPA emission limits required in New Source Performance Standards (NSPS), National Emission Standards for Hazardous Air Pollutants (NESHAP), and Maximum Achievable Control Technology (MACT) standards.

<b>104</b>	<b>SAN DIEGO GALVANIZING INCORPORATED</b> <b>3586 DALBERGIA STREET</b> <b>SAN DIEGO, CA 92113</b>	<b>RCRA-SQG</b> <b>FINDS</b> <b>HAZNET</b> <b>TRIS</b> <b>San Diego Co. HMMD</b> <b>CERC-NFRAP</b>	<b>1000710129</b> <b>92113SNDGG35</b>
------------	---	---	--

RCRA-SQG:

Date form received by agency:	03/17/2006
Facility name:	SAN DIEGO GALVANIZING, INC.
Facility address:	3586 DALBERGIA ST. SAN DIEGO, CA 92113
EPA ID:	CAD008230849
Mailing address:	P.O. BOX 13157 SAN DIEGO, CA 92170
Contact:	LEWIS H WISE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(619) 233-4763
Contact email:	INFO@SDGALV.COM
EPA Region:	09
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Owner/operator name: CECILIA WISE  
 Owner/operator address: P.O. BOX 300892  
 ESCONDIDO, CA 92030  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: 07/01/1967  
 Owner/Op end date: Not reported

Owner/operator name: CECILIA WISE  
 Owner/operator address: Not reported  
 Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 07/01/1967  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 03/17/2006  
 Facility name: SAN DIEGO GALVANIZING, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 02/28/2002  
 Facility name: SAN DIEGO GALVANIZING, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: SAN DIEGO GALVANIZING, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: SAN DIEGO GALVANIZING, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Facility name: SAN DIEGO GALVANIZING, INC.  
 Site name: SAN DIEGO GALVANIZING INC  
 Classification: Large Quantity Generator

Date form received by agency: 03/11/1996  
 Facility name: SAN DIEGO GALVANIZING, INC.  
 Classification: Large Quantity Generator

Date form received by agency: 01/22/1996  
 Facility name: SAN DIEGO GALVANIZING, INC.  
 Site name: SAN DIEGO GALVANIZING INC  
 Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 56672.7

Waste code: D004  
 Waste name: ARSENIC  
 Amount (Lbs): 37241.3

Waste code: D006  
 Waste name: CADMIUM  
 Amount (Lbs): 37241.3

Waste code: D007  
 Waste name: CHROMIUM  
 Amount (Lbs): 46641.6

Waste code: D010  
 Waste name: SELENIUM  
 Amount (Lbs): 37241.3

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 08/19/2003  
 Date achieved compliance: 08/22/2003  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 08/19/2003  
 Date achieved compliance: 08/26/2003  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 279  
 Area of violation: Used Oil - Generators  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 01/10/2002  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 11/26/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 262.40-43.D  
 Area of violation: Generators - General  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 01/10/2002  
 Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: 11/15/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 262.40-43.D  
 Area of violation: Generators - General  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 01/10/2002  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 11/26/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Paid penalty amount: Not reported

Regulation violated: F - 279  
 Area of violation: Used Oil - Generators  
 Date violation determined: 10/30/2001  
 Date achieved compliance: 01/10/2002  
 Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: 11/15/2001  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

**Evaluation Action Summary:**

Evaluation date: 08/19/2003  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/26/2003  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/19/2003  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/22/2003  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 10/30/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 01/10/2002  
 Evaluation lead agency: EPA

Evaluation date: 10/30/2001  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Used Oil - Generators  
 Date achieved compliance: 01/10/2002  
 Evaluation lead agency: EPA

**FINDS:**

**Other Pertinent Environmental Activity Identified at Site**

California - Hazardous Waste Tracking System - Datamart

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD008230849  
 Contact: ALFRED WISE  
 Telephone: 6192334763  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13157  
 Mailing City,St,Zip: SAN DIEGO, CA 921703157  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with metals (restricted levels and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc )  
 Disposal Method: Recycler  
 Tons: 17.5140  
 Facility County: San Diego

Gepaid: CAD008230849  
 Contact: ALFRED WISE  
 Telephone: 6192334763  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13157  
 Mailing City,St,Zip: SAN DIEGO, CA 921703157  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Liquids with pH <UN-> 2 with metals  
 Disposal Method: Disposal, Other  
 Tons: 2.0641  
 Facility County: San Diego

Gepaid: CAD008230849  
 Contact: ALFRED WISE  
 Telephone: 6192334763  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13157  
 Mailing City,St,Zip: SAN DIEGO, CA 921703157  
 Gen County: San Diego  
 TSD EPA ID: CAD097030993  
 TSD County: Los Angeles  
 Waste Category: Liquids with cadmium > 100 mg/l  
 Disposal Method: Recycler  
 Tons: 1.9210  
 Facility County: San Diego

Gepaid: CAD008230849  
 Contact: LEWIS WISE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Telephone: 6192334763  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13157  
 Mailing City,St,Zip: SAN DIEGO, CA 921703157  
 Gen County: San Diego  
 TSD EPA ID: CAD008364432  
 TSD County: Los Angeles  
 Waste Category: Unspecified aqueous solution  
 Disposal Method: Treatment, Tank  
 Tons: 3.44  
 Facility County: Not reported

Gepaid: CAL000014709  
 Contact: AL WISE AL WISE JR LEWIS WISE  
 Telephone: 6192334763  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 13157  
 Mailing City,St,Zip: SAN DIEGO, CA 921700000  
 Gen County: San Diego  
 TSD EPA ID: CAD008488025  
 TSD County: Los Angeles  
 Waste Category: Liquids with chromium (VI) > 500 mg/l  
 Disposal Method: Not reported  
 Tons: 15.0120  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 52 additional CA\_HAZNET: record(s) in the EDR Site Report.

San Diego Co. HMMD:

Facility ID: 100247  
 Inactive Indicator: Active  
 Business Code: 6HK34  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: PO BOX 13157  
 Mailing City,St,Zip: SAN DIEGO, CA 92170  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAD008230849  
 Gas Station: Not reported  
 Inspection Date: 08/19/03  
 Reinspection Date: Not reported  
 Inspector Name: JHENDERS  
 Violation Notice Issued: Not reported  
 Facility Contact: LEWIS WISE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Property Owner: WISE ALFRED E&CECILIA A TRS  
 Property Address: P O BOX 300892  
 Property City,St,Zip: 92030  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 08/19/04  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: AC58  
 Chemical Name: ACETYLENE  
 Case Number: 74-86-2  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: AM54  
 Chemical Name: AMMONIUM CHLORIDE  
 Case Number: 12125-02-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: AM50  
 Chemical Name: AMMONIUM HYDROXIDE  
 Case Number: 1336-21-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: HY49  
 Chemical Name: HYDROCHLORIC ACID (15% BY WEIGHT) 1 PICKLING TANK-5000 GALS EA-4 TWO  
 7000 G  
 Case Number: 7647-01-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

2nd Hazard Category: Not reported

Item Number: OI59  
 Chemical Name: OILS-LUBRICATING, MOTOR OIL, TRANSMISSION, HYDRAULIC  
 Case Number: 8002-05-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: OX57  
 Chemical Name: OXYGEN  
 Case Number: 7782-44-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: PR56  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: SO51  
 Chemical Name: SODIUM HYDROXIDE & SODIUM METASILICATE MIXTURE  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: ZA53  
 Chemical Name: ZAFLON FLUXES - ZINC CHLORIDE & AMMONIUM CHLORIDE MIXTURES  
 Case Number: 12125-02-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: ZA52  
 Chemical Name: ZACLON K PREFLUX - ZINC CHLORIDE & AMMONIUM CHLORIDE MIXTURE  
 Case Number: 7646-85-7  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

Item Number: ZI55  
 Chemical Name: ZINC-MOLTEN- 820 TO 850 DEGREES FAHRENHEIT  
 Case Number: 7440-66-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: ACUTE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 10/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 8291  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

Inspection Date: 10/06/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0201  
 Occurrences: Not reported  
 Item Number: 8292  
 Violation Desc: WASTE CONTAINER NOT CLOSED

Inspection Date: 08/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0216  
 Occurrences: Not reported  
 Item Number: 3344  
 Violation Desc: HAZMATS WITHOUT PROPER LABELS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Inspection Date: 08/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV1604  
 Occurrences: Not reported  
 Item Number: 3345  
 Violation Desc: 2ND. CONTAINMENT NOT KEPT EMPTY

**HMMD WASTE STREAMS:**

Inspection Date: 08/19/03  
 Waste Item #: 171  
 Waste Code: 171  
 Waste Name: METAL SLUDGE  
 Qnty at Inspection: 2156  
 Quantity String: 2156  
 Annual Qty: 2156  
 Annual Qty String: 2156  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0335 MARTIN INDUSTRIES PU  
 Waste Desc: CAUSTIC TANK SLUDGE  
 Carcinogen: No

Inspection Date: 08/19/03  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 48000  
 Quantity String: 48000  
 Annual Qty: 200000  
 Annual Qty String: 200000  
 Measurement Unit: LBS  
 Treatment Method: 205 RECLAIMED  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: ZINC OXIDE/DROSS & FLUX  
 Carcinogen: No

Inspection Date: 08/19/03  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 0015 ASBURY ENVIR. SERVIC  
 Waste Desc: WASTE OIL  
 Carcinogen: No

Inspection Date: 08/19/03  
 Waste Item #: 723  
 Waste Code: 723  
 Waste Name: LIQUIDS W CHROMIUM -

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Qty at Inspection: 3600  
 Quantity String: 3600  
 Annual Qty: 3600  
 Annual Qty String: 3600  
 Measurement Unit: GAL  
 Treatment Method: 008 NEUTRALIZATION  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 0699 VAN WATERS & ROGERS  
 Waste Desc: ACID STRIP SLUDGE  
 Carcinogen: No

Inspection Date: 08/19/03  
 Waste Item #: 792  
 Waste Code: 792  
 Waste Name: LIQUIDS W/PH <OR= 2  
 Qty at Inspection: 3400  
 Quantity String: 3400  
 Annual Qty: 3400  
 Annual Qty String: 3400  
 Measurement Unit: GAL  
 Treatment Method: 008 NEUTRALIZATION  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 9997 UNREGISTERED HAZ WST  
 Waste Desc: PICKLE LIQUOR EXCLUDED RM  
 Carcinogen: No

**CERC-NFRAP:**

Site ID: 0904780  
 Federal Facility: Not a Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: NFRAP

**CERCLIS-NFRAP Site Contact Name(s):**

Contact Name: Matt Mitguard  
 Contact Tel: (415) 972-3096  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz  
 Contact Tel: (415) 972-3811  
 Contact Title: Site Assessment Manager (SAM)

**CERCLIS-NFRAP Site Alias Name(s):**

Alias Name: SOUTHWESTERN GALVANIZING, CO.  
 Alias Address: Not reported  
 CA

Site Description: Not reported

**CERCLIS-NFRAP Assessment History:**

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 02/10/1993  
 Priority Level: Not reported

Action: ARCHIVE SITE  
 Date Started: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s)  
 EPA ID Number

**SAN DIEGO GALVANIZING INCORPORATED (Continued)**

**1000710129**

Date Completed: 01/04/1994  
 Priority Level: Not reported  
 Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 01/04/1994  
 Priority Level: NFRAP (No Further Remedial Action Planned)

105

**SOVEREIGN CONST-GEN DYNAM/CONV  
 2980 HARBOR DR  
 SAN DIEGO, CA 92101**

**HAZNET S100730017  
 Cortese N/A  
 San Diego Co. HMMD**

HAZNET:

Gepaid: CAL000091052  
 Contact: GENERAL DYNAMICS SPACE SYSTEM  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: JIM O'BRIEN  
 Mailing City,St,Zip: SAN DIEGO, CA 921865990  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: .0800  
 Facility County: San Diego

Gepaid: CAL000091052  
 Contact: GENERAL DYNAMICS SPACE SYSTEM  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: JIM O'BRIEN  
 Mailing City,St,Zip: SAN DIEGO, CA 921865990  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Organic solids with halogens  
 Disposal Method: Not reported  
 Tons: .0050  
 Facility County: San Diego

Gepaid: CAL000091052  
 Contact: GENERAL DYNAMICS SPACE SYSTEM  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: JIM O'BRIEN  
 Mailing City,St,Zip: SAN DIEGO, CA 921865990  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Off-specification, aged, or surplus organics  
 Disposal Method: Not reported  
 Tons: .0740  
 Facility County: San Diego



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOVEREIGN CONST-GEN DYNAM/CONV (Continued)**

**S100730017**

Gepaid: CAL000091052  
 Contact: GENERAL DYNAMICS SPACE SYSTEM  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: JIM O'BRIEN  
 Mailing City,St,Zip: SAN DIEGO, CA 921865990  
 Gen County: San Diego  
 TSD EPA ID: CAT080010101  
 TSD County: San Diego  
 Waste Category: Organic liquids (nonsolvents) with halogens  
 Disposal Method: Transfer Station  
 Tons: .1605  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

San Diego Co. HMMD:  
 Facility ID: 136602  
 Inactive Indicator: Active  
 Business Code: 6HK20  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 99  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SOVEREIGN CONST-GEN DYNAM/CONV (Continued)**

**S100730017**

Facility Phone: Not reported

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

HMMD VIOLATIONS:

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

HMMD WASTE STREAMS:

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

105

**GENERAL DYNAMICS CONVAIR  
 2980 HARBOR DR  
 SAN DIEGO, CA 92113**

**LUST U003789500  
 UST N/A  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GENERAL DYNAMICS CONVAIR (Continued)**

**U003789500**

Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607300717  
 Stop Date: 1986-10-02 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1996-08-20 00:00:00  
 Discover Date: 1986-10-02 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1986-10-02 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Jet Fuel  
 Contact Person: Not reported  
 Responsible Party: ATTN: MR. RICK ADCOCK  
 RP Address: P.O. BOX 488  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.21  
 Beneficial: REC-1,REC-2,WARM,WILD  
 Priority: 2  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H14919-001  
 Case Number: 9UT194  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GENERAL DYNAMICS CONVAIR (Continued)**

**U003789500**

Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H14919

San Diego Co. HMMD:

Facility ID: 114919  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: C/O GF HARDACRE  
 Mailing Address: PO BOX M2 8825 252  
 Mailing City, St, Zip: SAN DIEGO, CA 92186  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 62  
 EPA ID: CAD981393192  
 Gas Station: Not reported  
 Inspection Date: 06/10/94  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: GERRY HARDACRE  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: WW SAN DIEGO HARBOR ISLAND INC  
 Property Address: C/O WESTMONT MGNT GR  
 Property City, St, Zip: 77057  
 Tank Owner: GENERAL DYNAMICS CORP  
 Tank Address: 7733 FORSYTH BL  
 Tank City, St, Zip: Saint Louis, MO 63105  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-542-8074

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GENERAL DYNAMICS CONVAIR (Continued)**

**U003789500**

**HMMD UNDERGROUND TANKS:**

Tank Number:	T001
Tank ID Number:	HD-3T
Waste or Product:	Not reported
Tank Contents:	AVIATION FUEL
Tank Number:	T002
Tank ID Number:	HD-4T
Waste or Product:	Not reported
Tank Contents:	DIESEL
Tank Number:	T003
Tank ID Number:	HD-1T
Waste or Product:	Not reported
Tank Contents:	AVIATION FUEL
Tank Number:	T004
Tank ID Number:	HD-2T
Waste or Product:	Not reported
Tank Contents:	AVIATION FUEL
Tank Number:	T005
Tank ID Number:	5
Waste or Product:	Not reported
Tank Contents:	Not reported
Tank Number:	T006
Tank ID Number:	6
Waste or Product:	Not reported
Tank Contents:	Not reported
Tank Number:	T007
Tank ID Number:	AT3421
Waste or Product:	Not reported
Tank Contents:	Not reported
Tank Number:	T008
Tank ID Number:	NT1826
Waste or Product:	Not reported
Tank Contents:	REGULAR UNLEADED
Tank Number:	T009
Tank ID Number:	NT1826
Waste or Product:	Not reported
Tank Contents:	REGULAR UNLEADED

**HMMD VIOLATIONS:**

Inspection Date:	01/24/92
Waste Code:	Not reported
Type of Violation:	6HX0010
Occurrences:	Not reported
Item Number:	8282
Violation Desc:	BUS. PLAN NOT COMPLETE/CURRENT/ON SITE
Inspection Date:	10/12/90
Waste Code:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**GENERAL DYNAMICS CONVAIR (Continued)**

**U003789500**

Type of Violation: 6HX0042  
 Occurrences: Not reported  
 Item Number: 7528  
 Violation Desc: HAZWASTE CONT. NOT LABELED OR MARKED

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SWEEPS UST:**

Status: Not reported  
 Comp Number: 14919  
 Number: Not reported  
 Board Of Equalization: 44-008699  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014919-000001  
 Actv Date: Not reported  
 Capacity: 2000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: AVIA. GAS  
 Number Of Tanks: 6

Status: Not reported  
 Comp Number: 14919  
 Number: Not reported  
 Board Of Equalization: 44-008699  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014919-000002  
 Actv Date: Not reported  
 Capacity: 8200  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: OTHER  
 Number Of Tanks: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GENERAL DYNAMICS CONVAIR (Continued)**

**U003789500**

Status: Not reported  
 Comp Number: 14919  
 Number: Not reported  
 Board Of Equalization: 44-008699  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014919-000003  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: AVIA. GAS  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 14919  
 Number: Not reported  
 Board Of Equalization: 44-008699  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014919-000004  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: AVIA. GAS  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 14919  
 Number: Not reported  
 Board Of Equalization: 44-008699  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014919-000005  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: UNKNOWN  
 Stg: PRODUCT  
 Content: Not reported  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 14919  
 Number: Not reported  
 Board Of Equalization: 44-008699  
 Ref Date: Not reported  
 Act Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**GENERAL DYNAMICS CONVAIR (Continued)**

**U003789500**

Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-014919-000006  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: JET FUEL  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 14919  
 Number: 9  
 Board Of Equalization: 44-008699  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: Not reported  
 Actv Date: Not reported  
 Capacity: Not reported  
 Tank Use: Not reported  
 Stg: Not reported  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H14919-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/20/1996  
 Begandt: 10/2/1986

106

**NAVY EXCHANGE SVC STA  
 32ND ST & HARBOR DR  
 SAN DIEGO, CA 92136**

**RCRA-SQG 1000440003  
 LUST CAD982015398  
 HIST UST**

**RCRA-SQG:**

Date form received by agency: 09/01/1996  
 Facility name: NAVY EXCHANGE SVC STA  
 Facility address: 32ND ST & HARBOR DR  
 SAN DIEGO, CA 92136  
 EPA ID: CAD982015398  
 Mailing address: PO BOX 150  
 SAN DIEGO, CA 92136  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVY EXCHANGE SVC STA (Continued)**

**1000440003**

Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NAVY RESALE SERVICE  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 07/21/1987  
 Facility name: NAVY EXCHANGE SVC STA  
 Classification: Large Quantity Generator

Violation Status: No violations found

LUST:

Region: 9  
 Case Number: 9UT1108  
 Local Agency: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NAVY EXCHANGE SVC STA (Continued)**

**1000440003**

Substance: Unleaded Gasoline  
 Qty Leaked: 100  
 Date Found: 11/17/1988  
 How Found: Other Means  
 Date Stopped: 11/17/1988  
 How Stopped: Not reported  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Remediation Plan  
 Abate Method: Remove Free Product - remove floating product from water table  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: 01/01/1993  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: SEL  
 Enforce Date: 2/24/93  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H01447-002  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: NBNABB/E  
 NPDES Number: Not reported  
 priority: 1  
 File Dispn: Not reported  
 Release Date: 11/28/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**HIST UST:**

Region: STATE  
 Facility ID: 00000000099  
 Facility Type: Other  
 Other Type: GAS SUPPLY  
 Total Tanks: 0003  
 Contact Name: JOHN M. DYE  
 Telephone: 6192351509  
 Owner Name: NAVAL STATION, SAN DIEGO  
 Owner Address: P.O. BOX 16, BLDG-72  
 Owner City,St,Zip: SAN DIEGO, CA 92136

Tank Num: 001  
 Container Num: #1  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 002

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NAVY EXCHANGE SVC STA (Continued)**

**1000440003**

Container Num: #2  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 003  
 Container Num: #3  
 Year Installed: Not reported  
 Tank Capacity: 00000500  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: Visual

106

**USNAVY EXCHANGE SERVICE STATION  
 32ND & HARBOR DR NAVAL STA  
 SAN DIEGO, CA 92136**

**RCRA-SQG 1000440006  
 CHMIRS CA6170090231  
 HIST UST**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: USNAVY EXCHANGE SERVICE STATION  
 Facility address: 32ND & HARBOR DR NAVAL STA  
 SAN DIEGO, CA 92136  
 EPA ID: CA6170090231  
 Mailing address: PO BOX 150  
 SAN DIEGO, CA 92136  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Federal  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NAVY RESALE OFFICE  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Federal  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 11/03/1986  
 Facility name: USNAVY EXCHANGE SERVICE STATION  
 Classification: Large Quantity Generator

Violation Status: No violations found

CHMIRS:

OES Incident Number: 98-0397  
 OES notification: 1/30/199801:58:41 PM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	San Diego Bay
Spill Site:	Not reported
Cleanup By:	Not Feasible
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1998
Agency:	USN
Incident Date:	1/30/199812:00:00 AM
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	No
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Oil
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	50 ft. by 30 ft. sheen discovered in the bay. Spill has been contained with absorbent pads.Per NRC; The material released from a vessel due to failure of a three valve manifold leaking into a fuel oil tank. Absorbents were used to soak up the spill.Per NRC; THE CALLER REPORTED A RELEASE OF 2190 LUBE OIL FROM CONTAINER ON THE VESSEL WHEN POUED INTO WRONG SINKVia NRC report, caller reporting an unknown sheen possibly coming from an oily waste tank.Light sheen 100 feet X 700 feet. Dry dock facility and the sheen was against the quay wall

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

and wind pushed the sheen into the dry dock when the doors were open. The sheen was to light to pick up as per the Naval Oil Response Team. When the Navy pumps the dock dry to get the ship on the blocks the material will be pumped into the bay. It is expected that the sheen will disipate quickly because it is so light.

OES Incident Number: 03-0134  
 OES notification: 1/8/200310:57:49 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities:Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Harbor  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2003  
 Agency: NRC  
 Incident Date: 1/8/200312:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Contained:	Unknown
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	lubricating oil
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	.5
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	50 ft. by 30 ft. sheen discovered in the bay. Spill has been contained with absorbent pads. Per NRC; The material released from a vessel due to failure of a three valve manifold leaking into a fuel oil tank. Absorbents were used to soak up the spill. Per NRC; THE CALLER REPORTED A RELEASE OF 2190 LUBE OIL FROM CONTAINER ON THE VESSEL WHEN Poured INTO WRONG SINK Via NRC report, caller reporting an unknown sheen possibly coming from an oily waste tank. Light sheen 100 feet X 700 feet. Dry dock facility and the sheen was against the quay wall and wind pushed the sheen into the dry dock when the doors were open. The sheen was too light to pick up as per the Naval Oil Response Team. When the Navy pumps the dock dry to get the ship on the blocks the material will be pumped into the bay. It is expected that the sheen will disipate quickly because it is so light.
OES Incident Number:	01-1837
OES notification:	3/28/200108:07:52 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
<b>Date Completed:</b>	<b>Not reported</b>
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agency Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Harbor  
 Spill Site: Not reported  
 Cleanup By: Port Operations  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2001  
 Agency: USN USS Antietam  
 Incident Date: 3/28/2001 12:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: oil sheen  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 0  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 1  
 Sheen: 0  
 Tons: 0  
 Unknown: 0.000000  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: 50 ft. by 30 ft. sheen discovered in the bay. Spill has been contained with absorbent pads. Per NRC; The material released from a vessel due to failure of a three valve manifold leaking into a fuel oil tank. Absorbents were used to soak up the spill. Per NRC; THE CALLER REPORTED A RELEASE OF 2190 LUBE OIL FROM CONTAINER ON THE VESSEL WHEN Poured INTO WRONG SINK via NRC report, caller reporting an unknown sheen possibly coming from an oily waste tank. Light sheen



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

100 feet X 700 feet. Dry dock facility and the sheen was against the quay wall and wind pushed the sheen into the dry dock when the doors were open. The sheen was to light to pick up as per the Naval Oil Response Team. When the Navy pumps the dock dry to get the ship on the blocks the material will be pumped into the bay. It is expected that the sheen will disipate quickly because it is so light.

OES Incident Number: 05-2885  
 OES notification: 5/15/200510:29:44 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities:Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Not reported  
 Waterway: San Diego Bay  
 Spill Site: Not reported  
 Cleanup By: Unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2005  
 Agency: NRC  
 Incident Date: 5/14/200512:00:00 AM  
 Admin Agency: San Diego County Health Services Dept.

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Amount:	Not reported
Contained:	Unknown
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Unknown Oil
Quantity Released:	Not reported
BBLs:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	80
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	50 ft. by 30 ft. sheen discovered in the bay. Spill has been contained with absorbent pads.Per NRC; The material released from a vessel due to failure of a three valve manifold leaking into a fuel oil tank. Absorbents were used to soak up the spill.Per NRC; THE CALLER REPORTED A RELEASE OF 2190 LUBE OIL FROM CONTAINER ON THE VESSEL WHEN POUED INTO WRONG SINKVia NRC report, caller reporting an unknown sheen possibly coming from an oily waste tank.Light sheen 100 feet X 700 feet. Dry dock facility and the sheen was against the quay wall and wind pushed the sheen into the dry dock when the doors were open. The sheen was to light to pick up as per the Naval Oil Response Team. When the Navy pumps the dock dry to get the ship on the blocks the material will be pumped into the bay. It is expected that the sheen will disipate quickly because it is so light.
OES Incident Number:	014924
OES notification:	Not reported
OES Date:	8/1/1996
OES Time:	02:57:32 PM
Incident Date:	Not reported
<b>Date Completed:</b>	<b>Not reported</b>
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agency Personel # Of Decontaminated:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities:Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: NO  
 Waterway: san diego harbor  
 Spill Site: Not reported  
 Cleanup By: unknown  
 Containment: Not reported  
 What Happened: Not reported  
 Type: PETROLEUM  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1996  
 Agency: uss fort fisatr  
 Incident Date: 1430 01Aug96  
 Admin Agency: Not reported  
 Amount: 20-25 gals  
 Contained: YES  
 Site Type: OTHER  
 E Date: Not reported  
 Substance: diesel fuel marine  
 Quantity Released: Not reported  
 BBLS: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: unk source, crew noticed a sheen. still under investigation.  
 Evacuations: NO  
 Number of Injuries: NO  
 Number of Fatalities: NO  
 Description: 50 ft. by 30 ft. sheen discovered in the bay. Spill has been contained with absorbent pads.Per NRC; The material released from a vessel due to failure of a three valve manifold leaking into a fuel oil tank. Absorbents were used to soak up the spill.Per NRC; THE CALLER REPORTED A RELEASE OF 2190 LUBE OIL FROM CONTAINER ON THE VESSEL WHEN Poured INTO WRONG SINKVia NRC report, caller

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

reporting an unknown sheen possibly coming from an oily waste tank. Light sheen 100 feet X 700 feet. Dry dock facility and the sheen was against the quay wall and wind pushed the sheen into the dry dock when the doors were open. The sheen was too light to pick up as per the Naval Oil Response Team. When the Navy pumps the dock dry to get the ship on the blocks the material will be pumped into the bay. It is expected that the sheen will dissipate quickly because it is so light.

OES Incident Number: 02-1865  
 OES notification: 4/4/200209:11:17 AM  
 OES Date: Not reported  
 OES Time: Not reported  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agency Personnel # Of Decontaminated: Not reported  
 Responding Agency Personnel # Of Injuries: Not reported  
 Responding Agency Personnel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported  
 Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: Yes  
 Waterway: San Diego Harbor  
 Spill Site: Not reported  
 Cleanup By: Responsible Party  
 Containment: Not reported  
 What Happened: Not reported  
 Type: Not reported  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 2002  
 Agency: NRC  
 Incident Date: 4/4/200212:00:00 AM

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Admin Agency: San Diego County Health Services Dept.  
 Amount: Not reported  
 Contained: Yes  
 Site Type: Ship/Harbor/Port  
 E Date: Not reported  
 Substance: diesel marine fuel  
 Quantity Released: Not reported  
 BBLs: 0  
 Cups: 0  
 CUFT: 0  
 Gallons: 10  
 Grams: 0  
 Pounds: 0  
 Liters: 0  
 Ounces: 0  
 Pints: 0  
 Quarts: 0  
 Sheen: 0  
 Tons: 0  
 Unknown: 0  
 Description: Not reported  
 Evacuations: 0  
 Number of Injuries: 0  
 Number of Fatalities: 0  
 Description: 50 ft. by 30 ft. sheen discovered in the bay. Spill has been contained with absorbent pads. Per NRC; The material released from a vessel due to failure of a three valve manifold leaking into a fuel oil tank. Absorbents were used to soak up the spill. Per NRC; THE CALLER REPORTED A RELEASE OF 2190 LUBE OIL FROM CONTAINER ON THE VESSEL WHEN POUED INTO WRONG SINK Via NRC report, caller reporting an unknown sheen possibly coming from an oily waste tank. Light sheen 100 feet X 700 feet. Dry dock facility and the sheen was against the quay wall and wind pushed the sheen into the dry dock when the doors were open. The sheen was to light to pick up as per the Naval Oil Response Team. When the Navy pumps the dock dry to get the ship on the blocks the material will be pumped into the bay. It is expected that the sheen will disipate quickly because it is so light.

**HIST UST:**

Region: STATE  
 Facility ID: 00000029890  
 Facility Type: Other  
 Other Type: NAVY  
 Total Tanks: 0000  
 Contact Name: JOHN M. DYE  
 Telephone: 6192351509  
 Owner Name: NAVAL STATION, SAN DIEGO  
 Owner Address: P.O. BOX 16, BLDG 72  
 Owner City,St,Zip: SAN DIEGO, CA 92136

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00001600  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: None, 10

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00001600  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00002700  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 004  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00001600  
 Tank Used for: PRODUCT  
 Type of Fuel: DIESEL  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 004  
 Container Num: 4  
 Year Installed: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 005  
 Container Num: 5  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 006  
 Container Num: 6  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 007  
 Container Num: 7  
 Year Installed: Not reported  
 Tank Capacity: 00006000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 008  
 Container Num: 8  
 Year Installed: Not reported  
 Tank Capacity: 00006000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 009  
 Container Num: 9  
 Year Installed: Not reported  
 Tank Capacity: 00006000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 010  
 Container Num: 10  
 Year Installed: Not reported  
 Tank Capacity: 00006000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY EXCHANGE SERVICE STATION (Continued)**

**1000440006**

Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 011  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: 10

Tank Num: 012  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 013  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00001000  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Visual

Tank Num: 014  
 Container Num: 4  
 Year Installed: Not reported  
 Tank Capacity: 00000600  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Visual

106

**CAMPBELL INDUSTRIES  
 32ND ST AND HARBOR DR  
 SAN DIEGO, CA 92136**

**RCRA-SQG 1000857474  
 FINDS CAD983669110  
 HAZNET**

RCRA-SQG:

Date form received by agency: 05/03/1993  
 Facility name: CAMPBELL INDUSTRIES  
 Facility address: 32ND ST AND HARBOR DR  
 USNAVAL STN  
 SAN DIEGO, CA 92136  
 EPA ID: CAD983669110  
 Mailing address: P O BOX 1870  
 SAN DIEGO, CA 92112  
 Contact: CLARENCE WRIGHT  
 Contact address: P O BOX 1870  
 SAN DIEGO, CA 92112  
 Contact country: US  
 Contact telephone: (619) 233-7115  
 Contact email: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAMPBELL INDUSTRIES (Continued)**

**1000857474**

EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

**Owner/Operator Summary:**

Owner/operator name: MARINE DESIGN AND CONSTRUCTION CO  
 Owner/operator address: 2300 W COMMODORE WY  
 SEATTLE, WA 98199  
 Owner/operator country: Not reported  
 Owner/operator telephone: (206) 285-3200  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**HAZNET:**

Gepaid: CAD983669110  
 Contact: MARINE DESIGN AND CONSTRUCTION  
 Telephone: 6192337115  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CAMPBELL INDUSTRIES (Continued)**

**1000857474**

Mailing Address: PO BOX 121870  
 Mailing City,St,Zip: SAN DIEGO, CA 921121870  
 Gen County: San Diego  
 TSD EPA ID: CAD009007626  
 TSD County: Los Angeles  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Disposal, Land Fill  
 Tons: 3.5819  
 Facility County: San Diego

107

**SAN DIEGO PUBLIC WORKS CENTER  
 SAN DIEGO NAVAL STATION  
 SAN DIEGO, CA 92145**

**CERCLIS 1000110801  
 CA2170090235**

CERCLIS:

Site ID: 0902735  
 Federal Facility: Federal Facility  
 NPL Status: Not on the NPL  
 Non NPL Status: Fed Fac Site Inspection Review Start Needed

CERCLIS Site Contact Name(s):

Contact Name: Philip Armstrong  
 Contact Tel: (415) 972-3098  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Dawn Richmond  
 Contact Tel: (415) 972-3097  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Karen Jurist  
 Contact Tel: (415) 972-3219  
 Contact Title: Site Assessment Manager (SAM)

Contact Name: Jeff Inglis  
 Contact Tel: (415) 972-3095  
 Contact Title: Site Assessment Manager (SAM)

CERCLIS Site Alias Name(s):

Alias Name: PUBLIC WORKS CENTER SAN DIEGO  
 Alias Address: Not reported  
 CA  
 Site Description: Not reported

CERCLIS Assessment History:

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 06/01/1987  
 Priority Level: Low

Action: DISCOVERY  
 Date Started: Not reported  
 Date Completed: 07/01/1988  
 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT  
 Date Started: Not reported  
 Date Completed: 08/07/1992

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

**SAN DIEGO PUBLIC WORKS CENTER (Continued)**

**1000110801**

Priority Level: High

**108 FIRE FIGHTER TRAINING FACILITY  
32ND ST  
NS SAN DIEGO, CA 92136**

**LUST S101308211  
N/A**

LUST:

Region: 9  
Case Number: 9UT1640  
Local Agency: San Diego  
Substance: Gasoline  
Qty Leaked: 0  
Date Found: 02/22/1990  
How Found: Subsurface Monitoring  
Date Stopped: 02/22/1990  
How Stopped: Not reported  
Source: Tank  
Cause: Unknown  
Lead Agency: Local Agency  
Case Type: Other ground water affected  
Status: Preliminary site assessment underway  
Abate Method: Not reported  
Confirm Date: 02/22/1990  
Submit Workplan: Not reported  
Prelim Assess: 05/16/1990  
Desc Pollution: Not reported  
Remed Plan: / /  
Remed Action: Not reported  
Began Monitor: Not reported  
Enforce Type: Not reported  
Enforce Date: Not reported  
Closed Date: Not reported  
Pilot Program: LOP  
Local Case: H01447-006  
Basin Number: 908.32  
Gwater Depth: 9  
Beneficial Use: NBNABB/E  
NPDES Number: Not reported  
priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
File Dispn: Not reported  
Release Date: 02/22/1990  
Interim Remedial Actions: No  
Cleanup and Abatement order Number: Not reported  
Waste Discharge Requirement Number: Not reported

**108 NEW BLDG #P-235  
P-235 FLEASWTRACENPAC  
FASWTC SAN DIEGO, CA 92147**

**LUST S101302132  
N/A**

LUST:

Region: 9  
Case Number: 9UT286  
Local Agency: San Diego  
Substance: Boiler Fuel  
Qty Leaked: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NEW BLDG #P-235 (Continued)**

**S101302132**

Date Found: 09/23/1986  
 How Found: Other Means  
 Date Stopped: 09/24/1986  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 09/24/1986  
 Submit Workplan: Not reported  
 Prelim Assess: 08/04/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H02451-002  
 Basin Number: 908.10  
 Gwater Depth: 8'  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Disp: Not reported  
 Release Date: 09/24/1986  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

108

**EAST OF BLDG #2  
 E BLDG #2 FLEASWTRACENPAC  
 FASWTC SAN DIEGO, CA 92147**

**LUST S101301976  
 N/A**

**LUST:**

Region: 9  
 Case Number: 9UT263  
 Local Agency: San Diego  
 Substance: Boiler Fuel  
 Qty Leaked: 0  
 Date Found: 09/23/1986  
 How Found: Other Means  
 Date Stopped: 09/23/1986  
 How Stopped: Not reported  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: 09/23/1986  
 Submit Workplan: Not reported  
 Prelim Assess: 08/04/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EAST OF BLDG #2 (Continued)**

**S101301976**

Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H02451-001  
 Basin Number: 908.10  
 Gwater Depth: 5 FT  
 Beneficial Use: No Beneficial groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: Not reported  
 Release Date: 09/24/1986  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

109

**EARL SCHEIB OF CALIF INC  
 111 NATIONAL CITY BLVD  
 NATIONAL CITY, CA 91950**

**RCRA-SQG 1000274958  
 FINDS CAD981371941  
 HAZNET**

RCRA-SQG:

Date form received by agency: 09/01/1996  
 Facility name: EARL SCHEIB OF CALIF INC  
 Facility address: 111 NATIONAL CITY BLVD  
 NATIONAL CITY, CA 91950  
 EPA ID: CAD981371941  
 Mailing address: 111 NATIONAL BLVD  
 NATIONAL CITY, CA 92050  
 Contact: Not reported  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: Not reported  
 Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: EARL SHCEIB OF CALIF INC  
 Owner/operator address: NOT REQUIRED  
 NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported  
 Owner/operator name: NOT REQUIRED  
 Owner/operator address: NOT REQUIRED

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EARL SCHEIB OF CALIF INC (Continued)**

**1000274958**

NOT REQUIRED, ME 99999  
 Owner/operator country: Not reported  
 Owner/operator telephone: (415) 555-1212  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Historical Generators:

Date form received by agency: 01/28/1986  
 Facility name: EARL SCHEIB OF CALIF INC  
 Classification: Large Quantity Generator

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid: CAD981371941  
 Contact: EARL SCHEIB OF CALIF INC  
 Telephone: 3106524880  
 Facility Addr2: Not reported  
 Mailing Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**EARL SCHEIB OF CALIF INC (Continued)**

**1000274958**

Mailing Address: 8737 WILSHIRE BLVD  
 Mailing City,St,Zip: BEVERLY HILLS, CA 902112701  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .2345  
 Facility County: San Diego

Gepaid: CAD981371941  
 Contact: R TISHERMAN DIR OF RISK MGMT  
 Telephone: 8189819992  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 15206 VENTURA BOULEVARD SUITE 200  
 Mailing City,St,Zip: SHERMAN OAKS, CA 914030000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 0.11  
 Facility County: Not reported

Gepaid: CAD981371941  
 Contact: EARL SCHEIB OF CALIF INC  
 Telephone: 3106524880  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 8737 WILSHIRE BLVD  
 Mailing City,St,Zip: BEVERLY HILLS, CA 902112701  
 Gen County: San Diego  
 TSD EPA ID: CAT000613976  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: .3640  
 Facility County: San Diego

Gepaid: CAD981371941  
 Contact: R TISHERMAN DIR OF RISK MGMT  
 Telephone: 8189819992  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 15206 VENTURA BOULEVARD SUITE 200  
 Mailing City,St,Zip: SHERMAN OAKS, CA 914030000  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Orange  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 0.22  
 Facility County: Not reported

Gepaid: CAD981371941  
 Contact: JOSHUA BERMAN/MGR OF CORPORATE RISK

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EARL SCHEIB OF CALIF INC (Continued)**

**1000274958**

Telephone: 8189819992  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 15206 VENTURA BLVD STE 200  
 Mailing City,St,Zip: SHERMAN OAKS, CA 914030000  
 Gen County: San Diego  
 TSD EPA ID: CAT000613893  
 TSD County: San Diego  
 Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)  
 Disposal Method: Transfer Station  
 Tons: 0.11  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 1 additional CA\_HAZNET: record(s) in the EDR Site Report.

109

**ONE TEN LIQUOR  
 110 NATIONAL CITY BLVD  
 NATIONAL CITY, CA 91950**

**LUST S101301801  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT2317  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 10/26/1992  
 How Found: Tank Closure  
 Date Stopped: 10/26/1992  
 How Stopped: Close Tank  
 Source: Tank  
 Cause: Corrosion  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Preliminary site assessment underway  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 10/26/1992  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H32253-001  
 Basin Number: 908.31  
 Gwater Depth: 30'  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: LOP/HIGH - KNOWN HEALTH/SAFETY/ENVIRONMENTAL IMPACT  
 File Dispn: File discarded, case closed  
 Release Date: 10/26/1992  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ONE TEN LIQUOR (Continued)**

**S101301801**

Cortese:  
 Region: CORTESE  
 Facility Addr2: 110 NATIONAL CITY BLVD

109

**ONE TEN LIQUOR STORE  
 110 NATIONAL CITY BL  
 NATIONAL CITY, CA 91950**

**LUST S105692289  
 SAN DIEGO CO. SAM N/A**

LUST:  
 Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607301086  
 Stop Date: 1992-10-26 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1994-05-03 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1992-10-26 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1992-10-26 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: LOUIS ATTIQ  
 RP Address: 110 NATIONAL CITY BL  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: SM  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ONE TEN LIQUOR STORE (Continued)**

**S105692289**

Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 2  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H32253-001  
 Case Number: 9UT2317  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H32253-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Drinking Water Aquifer Impacted  
 FStatus: Remedial Investigation  
 Date: 5/3/1994  
 Begandt: 10/26/1992

109

**NATIONAL MOBIL SERVICE STATION  
 10 OSBORN ST  
 NATIONAL CITY, CA 91950**

**HAZNET U003789450  
 LUST N/A  
 UST  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**HAZNET:**

Gepaid: CAL912195719  
 Contact: SID SHAHROKNI  
 Telephone: 6194820751  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 10 OSBORN ST  
 Mailing City,St,Zip: NATIONAL CITY, CA 919501115  
 Gen County: San Diego  
 TSD EPA ID: CAD099452708  
 TSD County: Los Angeles  
 Waste Category: Oil/water separation sludge  
 Disposal Method: Recycler  
 Tons: 0.3127  
 Facility County: San Diego

**LUST:**

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: NPP  
 Leak Cause: Other Cause  
 Leak Source: Unknown

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL MOBIL SERVICE STATION (Continued)**

**U003789450**

Global Id: T0607302611  
 Stop Date: Not reported  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 2002-01-31 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1999-02-17 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-02-17 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: Shahrokni Seyed Mahmoud  
 RP Address: 3700 W 190TH ST, TPT 2  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 1  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13372-002  
 Case Number: 9UT3852  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported  
 Region: STATE  
 Case Type: Soil only

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL MOBIL SERVICE STATION (Continued)**

**U003789450**

Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607303178  
 Stop Date: 1988-03-22 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1990-09-07 00:00:00  
 Discover Date: 1988-03-22 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1988-03-22 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: R.J. EDWARDS  
 RP Address: 3800 W ALAMEDA AV., STE 700  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DL  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13372-001  
 Case Number: 9UT942  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**NATIONAL MOBIL SERVICE STATION (Continued)**

**U003789450**

Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

UST:

Local Agency: 37000  
 Facility ID: H13372

SWEEPS UST:

Status: Not reported  
 Comp Number: 13372  
 Number: Not reported  
 Board Of Equalization: 44-000400  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013372-000004  
 Actv Date: Not reported  
 Capacity: 280  
 Tank Use: PETROLEUM  
 Stg: WASTE  
 Content: Not reported  
 Number Of Tanks: 1

Status: A  
 Comp Number: 13372  
 Number: 9  
 Board Of Equalization: 44-000400  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013372-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 4

Status: A  
 Comp Number: 13372  
 Number: 9  
 Board Of Equalization: 44-000400  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013372-000002  
 Actv Date: Not reported  
 Capacity: 8000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**NATIONAL MOBIL SERVICE STATION (Continued)**

**U003789450**

Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 13372  
 Number: 9  
 Board Of Equalization: 44-000400  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013372-000003  
 Actv Date: Not reported  
 Capacity: 6000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 13372  
 Number: 9  
 Board Of Equalization: 44-000400  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013372-000005  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H13372-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 9/7/1990  
 Begandt: 3/22/1988

Case Number: H13372-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Drinking Water Aquifer Impacted  
 FStatus: Remedial Investigation  
 Date: 1/31/2002  
 Begandt: 2/17/1999

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**109 MOBIL OIL STATION #18-FF9  
 10 OSBORN ST  
 NATIONAL CITY, CA 91950**

**HAZNET S103723448  
 LUST N/A  
 Cortese  
 San Diego Co. HMMD**

HAZNET:

Gepaid: CAL000055781  
 Contact: DALE VIATOR, ENVT'L ADVISOR  
 Telephone: 2816548470  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 16825 NORTHCHASE DRIVE RM 911  
 Mailing City,St,Zip: HOUSTON, TX 770600000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Transfer Station  
 Tons: 0.06  
 Facility County: Not reported

Gepaid: CAL000055781  
 Contact: DALE VIATOR, ENVT'L ADVISOR  
 Telephone: 2816548470  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 16945 NORTHCHASE DRIVE RM 538  
 Mailing City,St,Zip: HOUSTON, TX 770600000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Transfer Station  
 Tons: 0.04  
 Facility County: San Diego

Gepaid: CAL000055781  
 Contact: DALE VIATOR, ENVT'L ADVISOR  
 Telephone: 2816548470  
 Facility Addr2: Not reported  
 Mailing Name: TANKNOLOGY NDE  
 Mailing Address: 16825 NORTHCHASE DRIVE RM 911  
 Mailing City,St,Zip: HOUSTON, TX 770600000  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: San Diego  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Treatment, Tank  
 Tons: 1.83  
 Facility County: San Diego

Gepaid: CAL000055781  
 Contact: DALE VIATOR, ENVT'L ADVISOR  
 Telephone: 2816548470  
 Facility Addr2: Not reported  
 Mailing Name: TANKNOLOGY NDE  
 Mailing Address: 16825 NORTHCHASE DRIVE RM 911  
 Mailing City,St,Zip: HOUSTON, TX 770600000  
 Gen County: San Diego

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL OIL STATION #18-FF9 (Continued)**

**S103723448**

TSD EPA ID: CAD028409019  
 TSD County: San Diego  
 Waste Category: Aqueous solution with 10% or more total organic residues  
 Disposal Method: Treatment, Tank  
 Tons: 0.22  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access  
 -1 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: 9  
 Case Number: 9UT3852  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 02/17/1999  
 How Found: Subsurface Monitoring  
 Date Stopped: 02/17/1999  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Other ground water affected  
 Status: Preliminary site assessment workplan submitted  
 Abate Method: Not reported  
 Confirm Date: 02/17/1999  
 Submit Workplan: 3/8/99  
 Prelim Assess: / /  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H13372-002  
 Basin Number: 908.31  
 Gwater Depth: Not reported  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: Not reported  
 File Disp: Administratively opened on database, however no file physically exists  
 Release Date: 03/08/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: 10 OSBORN ST

**San Diego Co. HMMD:**

Facility ID: 205233  
 Inactive Indicator: Active



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL OIL STATION #18-FF9 (Continued)**

**S103723448**

Business Code: 6HK29  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: Not reported  
 Mailing City,St,Zip: Not reported  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: National City  
 Census Tract Number: 114  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: Not reported  
 Reinspection Date: Not reported  
 Inspector Name: Not reported  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: SHAHROKNI SEYED MAHMOUD  
 Property Address: 10 OSBORN ST  
 Property City,St,Zip: 91950  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: MI56  
 Chemical Name: MIDGRADE UNLEADED UNDERGROUND TANK 113372 T003  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

Item Number: PR55  
 Chemical Name: PREMIUM UNLEADED UNDERGROUND TANK 113372 T002  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MOBIL OIL STATION #18-FF9 (Continued)**

**S103723448**

Item Number: PR63  
 Chemical Name: PROPANE  
 Case Number: 74-98-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: PRESSURE R

Item Number: RE54  
 Chemical Name: REGULAR UNLEADED UNDERGROUND TANK 113372 T001  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: NT2321  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T002  
 Tank ID Number: NT2321  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T003  
 Tank ID Number: NT2321  
 Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

Tank Number: T004  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T005  
 Tank ID Number: RT0952  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T006  
 Tank ID Number: NT2321  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T007  
 Tank ID Number: NT2321

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL OIL STATION #18-FF9 (Continued)**

**S103723448**

Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

Tank Number: T008  
 Tank ID Number: NT2321  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: 181  
 Waste Code: 181  
 Waste Name: INORGANIC SOLID WAST  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 100  
 Annual Qty String: 100  
 Measurement Unit: LBS  
 Treatment Method: 001 RECYCLE  
 Storage Method: CARBOY  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: GAS FILTERS  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 213  
 Waste Code: 213  
 Waste Name: HYDROCARBON SOLVENTS  
 Qnty at Inspection: 15  
 Quantity String: 15  
 Annual Qty: 113  
 Annual Qty String: 113  
 Measurement Unit: GAL  
 Treatment Method: 001 RECYCLE  
 Storage Method: PROCESSING EQUIPMENT  
 Haz Waste Hauler: 1406 SAFETY-KLEEN  
 Waste Desc: PARTS WASHER  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 221  
 Waste Code: 221  
 Waste Name: WASTE OIL & MIXED OI  
 Qnty at Inspection: 500  
 Quantity String: 500  
 Annual Qty: 3600  
 Annual Qty String: 3600  
 Measurement Unit: GAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL OIL STATION #18-FF9 (Continued)**

**S103723448**

Treatment Method: 001 RECYCLE  
 Storage Method: UNGD TNK  
 Haz Waste Hauler: 3432 GOLDEN STATE ENVIR.  
 Waste Desc: USED OIL  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 343  
 Waste Code: 343  
 Waste Name: UNSPEC ORGANIC LIQUI  
 Qnty at Inspection: 55  
 Quantity String: 55  
 Annual Qty: 55  
 Annual Qty String: 55  
 Measurement Unit: GAL

Treatment Method: 001 RECYCLE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 4148 ANTIFREEZE DELIVERY  
 Waste Desc: USED COOLANT  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 444  
 Waste Code: 444  
 Waste Name: USED BATTERIES  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 600  
 Annual Qty String: 600  
 Measurement Unit: LBS  
 Treatment Method: 444 BATTERIES RECYCL  
 Storage Method: NONE  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: INTERSTATE  
 Carcinogen: No

Inspection Date: Not reported  
 Waste Item #: 888  
 Waste Code: 888  
 Waste Name: USED OIL FILTERS  
 Qnty at Inspection: 100  
 Quantity String: 100  
 Annual Qty: 500  
 Annual Qty String: 500  
 Measurement Unit: LBS  
 Treatment Method: 888 FILTERS/METAL RE  
 Storage Method: METAL DRUM  
 Haz Waste Hauler: 9998 UNKNOWN HAZ WST HAUL  
 Waste Desc: VORTEX  
 Carcinogen: No

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**109 MOBIL SERVICE STATION #18-FF9  
 10 OSBORN ST  
 NATIONAL CITY, CA 91950**

**HAZNET S102433805  
 LUST N/A  
 Cortese**

HAZNET:

Gepaid: CAL000055781  
 Contact: MOBIL  
 Telephone: 7038465734  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 142667  
 Mailing City,St,Zip: AUSTIN, TX 787142667  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Transfer Station  
 Tons: .1000  
 Facility County: San Diego

Gepaid: CAL000055781  
 Contact: MOBIL  
 Telephone: 7038465734  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 142667  
 Mailing City,St,Zip: AUSTIN, TX 787142667  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Treatment, Tank  
 Tons: .2085  
 Facility County: San Diego

Gepaid: CAL000055781  
 Contact: MOBIL  
 Telephone: 7038465734  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 142667  
 Mailing City,St,Zip: AUSTIN, TX 787142667  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019  
 TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Not reported  
 Tons: .0875  
 Facility County: San Diego

Gepaid: CAL000055781  
 Contact: MOBIL  
 Telephone: 7038465734  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 142667  
 Mailing City,St,Zip: AUSTIN, TX 787142667  
 Gen County: San Diego  
 TSD EPA ID: CAD028409019

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**MOBIL SERVICE STATION #18-FF9 (Continued)**

**S102433805**

TSD County: Los Angeles  
 Waste Category: Unspecified oil-containing waste  
 Disposal Method: Treatment, Tank  
 Tons: .4167  
 Facility County: San Diego

Gepaid: CAL000055781  
 Contact: MOBIL  
 Telephone: 7038465734  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: PO BOX 142667  
 Mailing City,St,Zip: AUSTIN, TX 787142667  
 Gen County: San Diego  
 TSD EPA ID: CAD981696420  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

[Click this hyperlink](#) while viewing on your computer to access 18 additional CA\_HAZNET: record(s) in the EDR Site Report.

**LUST:**

Region: 9  
 Case Number: 9UT942  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: Not reported  
 Date Found: 03/03/1988  
 How Found: Tank Closure  
 Date Stopped: 03/03/1988  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site

Confirm Date: 03/22/1988  
 Submit Workplan: Not reported  
 Prelim Assess: 03/22/1988  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 9/4/90  
 Pilot Program: LOP  
 Local Case: H13372-001  
 Basin Number: Not reported  
 Gwater Depth: Not reported  
 Beneficial Use: Not reported  
 NPDES Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**MOBIL SERVICE STATION #18-FF9 (Continued)**

**S102433805**

priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 03/22/1988  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

109

**WILLIAM TABER  
 10 OSBORN ST  
 NATIONAL CITY, CA 92050**

**HIST UST U001571939  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000039442  
 Facility Type: Gas Station  
 Other Type: Not reported  
 Total Tanks: 0004  
 Contact Name: Not reported  
 Telephone: 6194774344  
 Owner Name: MOBIL OIL CORPORATION  
 Owner Address: 612 S. FLOWER STREET  
 Owner City,St,Zip: LOS ANGELES, CA 90017

Tank Num: 001  
 Container Num: 1  
 Year Installed: Not reported  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 002  
 Container Num: 2  
 Year Installed: Not reported  
 Tank Capacity: 00008000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 003  
 Container Num: 3  
 Year Installed: Not reported  
 Tank Capacity: 00006000  
 Tank Used for: PRODUCT  
 Type of Fuel: PREMIUM  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

Tank Num: 004  
 Container Num: 4  
 Year Installed: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**WILLIAM TABER (Continued)**

**U001571939**

Tank Capacity: 00000280  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: Not reported  
 Leak Detection: Stock Inventor

109

**SHELL STATION  
 3890 DIVISION ST  
 SAN DIEGO, CA 92113**

**LUST S104539616  
 AIRS N/A**

LUST:

Region: STATE  
 Case Type: Other ground water affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Tank  
 Global Id: T0619793008  
 Stop Date: Not reported  
 Confirm Leak: 2007-04-09 00:00:00  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2007-04-09 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2007-04-10 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Leak being confirmed  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Williams Family Trust  
 RP Address: P.O. Box 97  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: JS  
 Lead Agency: Local Agency  
 Local Agency: 37000L



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**SHELL STATION (Continued)**

**S104539616**

Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13121-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**LUST:**

Region: 9  
 Case Number: 9UT3930  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: 0  
 Date Found: 06/18/1999  
 How Found: Tank Closure  
 Date Stopped: 06/18/1999  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Soil only  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: / /  
 Submit Workplan: Not reported  
 Prelim Assess: 06/25/1999  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 3/15/00  
 Pilot Program: LOP  
 Local Case: H13121-002  
 Basin Number: 908.31  
 Gwater Depth: Not reported  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: Administratively opened on database, however no file physically exists  
 Release Date: 06/18/1999  
 Interim Remedial Actions: Not reported  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL STATION (Continued)**

**S104539616**

EMI:

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1342  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1342  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2002  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1342  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2003  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1342  
 Air District Name: SD

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL STATION (Continued)**

**S104539616**

SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1342
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.52
Reactive Organic Gases Tons/Yr:	2.52
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	37
Air Basin:	SD
Facility ID:	1342
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.52
Reactive Organic Gases Tons/Yr:	2.52
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smlr Tons/Yr:	0

109

**KENNETH L RUSSEL  
 3890 DIVISION ST  
 SAN DIEGO, CA 92113**

**HIST UST U001572986  
 N/A**

HIST UST:  
 Region: STATE  
 Facility ID: 00000016495  
 Facility Type: Gas Station  
 Other Type: Not reported  
 Total Tanks: 0004  
 Contact Name: KENNETH L RUSSELL  
 Telephone: 0000000000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**KENNETH L RUSSEL (Continued)**

**U001572986**

Owner Name: SHELL OIL COMPANY  
 Owner Address: P.O. BOX 4848  
 Owner City,St,Zip: ANAHEIM, CA 92803

Tank Num: 001  
 Container Num: 1  
 Year Installed: 1965  
 Tank Capacity: 00000550  
 Tank Used for: WASTE  
 Type of Fuel: WASTE OIL  
 Tank Construction: 12 gauge  
 Leak Detection: Stock Inventor, Groundwater Monitoring Well, 10

Tank Num: 002  
 Container Num: 2  
 Year Installed: 1984  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: UNLEADED  
 Tank Construction: 1/4 inches  
 Leak Detection: Stock Inventor, Groundwater Monitoring Well, 10

Tank Num: 003  
 Container Num: 3  
 Year Installed: 1984  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: REGULAR  
 Tank Construction: 1/4 inches  
 Leak Detection: Stock Inventor, Groundwater Monitoring Well, 10

Tank Num: 004  
 Container Num: 4  
 Year Installed: 1984  
 Tank Capacity: 00010000  
 Tank Used for: PRODUCT  
 Type of Fuel: PREMIUM  
 Tank Construction: 1/4 inches  
 Leak Detection: Stock Inventor, Groundwater Monitoring Well, 10

109

**SHELL SVC STN  
 3890 DIVISION  
 SAN DIEGO, CA 92113**

**RCRA-SQG 1004675857  
 FINDS CAR000077867**

RCRA-SQG:

Date form received by agency: 07/13/2000  
 Facility name: SHELL SVC STN  
 Facility address: 3890 DIVISION  
 SAP 135911  
 SAN DIEGO, CA 92113  
 EPA ID: CAR000077867  
 Mailing address: P O BOX 2099  
 HOUSTON, TX 772522099  
 Contact: SONDRA BIENVENU  
 Contact address: P O BOX 2099  
 HOUSTON, TX 772522099  
 Contact country: US  
 Contact telephone: (713) 241-5036

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**SHELL SVC STN (Continued)**

**1004675857**

Contact email: Not reported  
 EPA Region: 09  
 Classification: Small Small Quantity Generator  
 Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:  
 Owner/operator name: EQUILON ENTERPRISES L L C  
 Owner/operator address: P O BOX 2099  
 HOUSTON, TX 77252  
 Owner/operator country: Not reported  
 Owner/operator telephone: (713) 241-5036  
 Legal status: Private  
 Owner/Operator Type: Owner  
 Owner/Op start date: Not reported  
 Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: Unknown  
 Mixed waste (haz. and radioactive): Unknown  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: No  
 Treater, storer or disposer of HW: No  
 Underground injection activity: No  
 On-site burner exemption: Unknown  
 Furnace exemption: Unknown  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: No  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018  
 Waste name: BENZENE

Violation Status: No violations found

**FINDS:**

Other Pertinent Environmental Activity Identified at Site

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**SHELL SVC STN (Continued)**

**1004675857**

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

109

**DIVISION SHELL SERVICE  
 3890 DIVISION ST  
 SAN DIEGO, CA 92113**

**HAZNET  
 LUST  
 Cortese  
 San Diego Co. HMMD  
 SWEEPS UST  
 SAN DIEGO CO. SAM**

**S103547246  
 N/A**

HAZNET:

Gepaid: CAL000067854  
 Contact: BAGDASAR ED  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3890 DIVISION ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133820  
 Gen County: San Diego  
 TSD EPA ID: CAD981696420  
 TSD County: Los Angeles  
 Waste Category: Waste oil and mixed oil  
 Disposal Method: Transfer Station  
 Tons: 0.1042  
 Facility County: San Diego

Gepaid: CAL000067854  
 Contact: BAGDASAR ED  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3890 DIVISION ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921133820  
 Gen County: San Diego  
 TSD EPA ID: CAT080013352  
 TSD County: Los Angeles  
 Waste Category: Aqueous solution with less than 10% total organic residues  
 Disposal Method: Recycler  
 Tons: 1.4553  
 Facility County: San Diego

Gepaid: CAL000067854  
 Contact: BAGDASAR ED  
 Telephone: 0000000000  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 3890 DIVISION ST

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Mailing City,St,Zip: SAN DIEGO, CA 921133820  
 Gen County: San Diego  
 TSD EPA ID: CAD981696420  
 TSD County: Los Angeles  
 Waste Category: Not reported  
 Disposal Method: Transfer Station  
 Tons: .2293  
 Facility County: San Diego

**LUST:**

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302691  
 Stop Date: 1999-06-18 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2000-03-15 00:00:00  
 Discover Date: 1999-06-18 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1999-06-18 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: MARVIN KATZ  
 RP Address: 209455 WILMINGTON AV  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: ML  
 Lead Agency: Local Agency  
 Local Agency: 37000L

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13121-002  
 Case Number: 9UT3930  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0607302775  
 Stop Date: 1985-09-03 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1989-08-28 00:00:00  
 Discover Date: 1985-09-03 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1985-09-03 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Waste Oil  
 Contact Person: Not reported  
 Responsible Party: FRANK FOSSATI  
 RP Address: PO BOX 4848  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: VC  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.32  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13121-001  
 Case Number: 9UT474  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**Cortese:**

Region: CORTESE  
 Facility Addr2: Not reported

**San Diego Co. HMMD:**

Facility ID: 113121  
 Inactive Indicator: Active  
 Business Code: 6HK29  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ATTN: MICHELLE PONCE, HSE PERM  
 Mailing Address: 20945 S. WILMINGTON  
 Mailing City, St, Zip: CARSON, CA 90810  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: San Diego  
 Census Tract Number: 36  
 EPA ID: CAL000067854  
 Gas Station: Not reported  
 Inspection Date: 03/23/04  
 Reinspection Date: Not reported  
 Inspector Name: RHANSEN  
 Violation Notice Issued: Not reported  
 Facility Contact: BILL MARTA  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: RUSSELL KENNETH L&MILDRED B TR  
 Property Address: 6720 SAN MIGUEL AVE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Property City,St,Zip: 91945  
 Tank Owner: EQUILON ENTERPRISES LLC  
 Tank Address: P.O. BOX 4453  
 Tank City,St,Zip: Houston, TX 77210  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 03/23/05  
 Facility Phone: 619-236-9822

**HMMD DISCLOSURE INVENTORY:**

Item Number: BL13  
 Chemical Name: BLENDED EMULSIFIER CAR WASH WAX-POLISHER  
 Case Number: 67-63-0  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

Item Number: PR16  
 Chemical Name: PREMIUM UNLEADED - T007 UNDERGROUND TANK 113121 T007  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: RE15  
 Chemical Name: REGULAR UNLEADED - T006 UNDERGROUND TANK 113121 T006  
 Case Number: 8006-61-9  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

Item Number: SO14  
 Chemical Name: SOLVENT HIGH PRESSURE SOAP  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: CHRONIC

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

**HMMD UNDERGROUND TANKS:**

Tank Number:	T001
Tank ID Number:	1
Waste or Product:	Not reported
Tank Contents:	Not reported
Tank Number:	T002
Tank ID Number:	RT0746/NT2
Waste or Product:	Not reported
Tank Contents:	REGULAR UNLEADED
Tank Number:	T003
Tank ID Number:	RT0746/NT2
Waste or Product:	Not reported
Tank Contents:	MIDGRADE UNLEADED
Tank Number:	T004
Tank ID Number:	RT0746/NT2
Waste or Product:	Not reported
Tank Contents:	PREMIUM UNLEADED
Tank Number:	T005
Tank ID Number:	RT1182
Waste or Product:	Not reported
Tank Contents:	Not reported
Tank Number:	T006
Tank ID Number:	NT2357
Waste or Product:	Not reported
Tank Contents:	REGULAR UNLEADED
Tank Number:	T007
Tank ID Number:	NT2357
Waste or Product:	Not reported
Tank Contents:	PREMIUM UNLEADED

**HMMD VIOLATIONS:**

Inspection Date:	04/20/98
Waste Code:	Not reported
Type of Violation:	6HV1002
Occurrences:	Not reported
Item Number:	3038
Violation Desc:	HMBP NOT ESTABLISHED/IMPLEMENTED.
Inspection Date:	04/20/98
Waste Code:	Not reported
Type of Violation:	6HV1096
Occurrences:	Not reported
Item Number:	3039
Violation Desc:	NO EMPLOYEE TRAINING RECORDS
Inspection Date:	04/20/98
Waste Code:	Not reported
Type of Violation:	6HX3001
Occurrences:	Not reported
Item Number:	3040

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 04/20/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 3041  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 04/20/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3028  
 Occurrences: Not reported  
 Item Number: 3042  
 Violation Desc: UST RESPONSE PLAN NOT AVAILABLE

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 3100  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HV0401  
 Occurrences: Not reported  
 Item Number: 3101  
 Violation Desc: TRAINING RECORDS UNAVAILABLE

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HV1004  
 Occurrences: Not reported  
 Item Number: 3102  
 Violation Desc: HMBP NOT SUBMITTED TO HMD

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HX3013  
 Occurrences: Not reported  
 Item Number: 3103  
 Violation Desc: NO FINANCIAL RESPOSIBILITY DOC

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 3104  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HX3015  
 Occurrences: Not reported  
 Item Number: 3105  
 Violation Desc: ANNUAL INTEGRITY TEST NOT DONE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HX3020  
 Occurrences: Not reported  
 Item Number: 3106  
 Violation Desc: PUMP DISPENSER METER NOT CALIBRATED

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 3107  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 02/25/00  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 3108  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 03/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 4935  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 03/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 4936  
 Violation Desc: NO TSDF SIGNED MANIFEST ONSITE

Inspection Date: 03/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 4937  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

Inspection Date: 03/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 4938  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 03/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 4939  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 03/01/02

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Waste Code: Not reported  
 Type of Violation: 6HX3029  
 Occurrences: Not reported  
 Item Number: 4940  
 Violation Desc: SPILL/OVERFILL PREVENTION NOT INSTALLED

Inspection Date: 03/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HX3030  
 Occurrences: Not reported  
 Item Number: 4941  
 Violation Desc: NO RELEASE RECORD LOG

Inspection Date: 03/01/02  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 4942  
 Violation Desc: HMBP: INADEQUATE SITE MAP

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3501  
 Occurrences: Not reported  
 Item Number: 0290  
 Violation Desc: MONTHLY 0.2 GPH TANK GAUGING NOT DONE

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3501  
 Occurrences: Not reported  
 Item Number: 0291  
 Violation Desc: MONTHLY 0.2 GPH TANK GAUGING NOT DONE

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3501  
 Occurrences: Not reported  
 Item Number: 0292  
 Violation Desc: MONTHLY 0.2 GPH TANK GAUGING NOT DONE

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV3101  
 Occurrences: Not reported  
 Item Number: 0293  
 Violation Desc: UPF PERMIT CURRENT AND AT FACILITY?

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 0294  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 05/19/03  
 Waste Code: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Type of Violation: 6HV0138  
 Occurrences: Not reported  
 Item Number: 0295  
 Violation Desc: NO TSDF SIGNED MANIFEST ONSITE

Inspection Date: 05/19/03  
 Waste Code: Not reported  
 Type of Violation: 6HV0202  
 Occurrences: Not reported  
 Item Number: 0296  
 Violation Desc: WASTE CONTAINER W/O LABELS

Inspection Date: 03/23/04  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9980  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: 03/23/04  
 Waste Item #: 352  
 Waste Code: 352  
 Waste Name: ORGANIC SOLIDS (OTHE  
 Qnty at Inspection: 5  
 Quantity String: 5  
 Annual Qty: 20  
 Annual Qty String: 20  
 Measurement Unit: LBS  
 Treatment Method: 999 UNKNOWN  
 Storage Method: BOX  
 Haz Waste Hauler: 0001 NO HAULER  
 Waste Desc: FILTER/ABSORBENT  
 Carcinogen: No

**SWEEPS UST:**

Status: A  
 Comp Number: 13121  
 Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013121-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: REG UNLEADED  
 Number Of Tanks: 4  
  
 Status: A  
 Comp Number: 13121

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013121-000003  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 13121  
 Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013121-000004  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: A  
 Comp Number: 13121  
 Number: 9  
 Board Of Equalization: 44-000074  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-013121-000005  
 Actv Date: Not reported  
 Capacity: 550  
 Tank Use: PETROLEUM  
 Stg: W  
 Content: Not reported  
 Number Of Tanks: Not reported

**SAN DIEGO CO. SAM:**

Case Number: H13121-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 8/28/1989  
 Begandt: 9/3/1985



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**DIVISION SHELL SERVICE (Continued)**

**S103547246**

Case Number: H13121-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 3/15/2000  
 Begandt: 6/18/1999

Case Number: H13121-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: GW With No Beneficial Use Designation  
 FStatus: Leak Being Confirmed  
 Date: 4/10/2007  
 Begandt: 4/9/2007

109

**SHELL SERVICE STATION  
 3890 DIVISION ST  
 SAN DIEGO, CA 92113**

**LUST S102437305  
 Cortese N/A**

LUST:

Region: 9  
 Case Number: 9UT474  
 Local Agency: San Diego  
 Substance: Waste Oil  
 Qty Leaked: Not reported  
 Date Found: 09/03/1985  
 How Found: Not reported  
 Date Stopped: 09/03/1985  
 How Stopped: Close Tank  
 Source: Not reported  
 Cause: Not reported  
 Lead Agency: Local Agency  
 Case Type: Drinking Water Aquifer affected  
 Status: Case Closed  
 Abate Method: Not reported  
 Confirm Date: 09/03/1985  
 Submit Workplan: Not reported  
 Prelim Assess: 06/10/1987  
 Desc Pollution: Not reported  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: 8/28/89  
 Pilot Program: LOP  
 Local Case: H13121-001  
 Basin Number: 908.32  
 Gwater Depth: Not reported  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: 3  
 File Dispn: File discarded, case closed  
 Release Date: 09/20/1985  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

---

**SHELL SERVICE STATION (Continued)**

**S102437305**

Cortese:  
 Region: CORTESE  
 Facility Addr2: 3890 DIVISION ST

---

**110 SDGE STN A, BLOCK 148 UST  
 114 10TH AVE/900 L  
 SAN DIEGO, CA 92101**

**Cortese S102270666  
 N/A**

Cortese:  
 Region: CORTESE  
 Facility Addr2: Not reported

---

**111 OLD SCHOOLHOUSE SQUARE  
 550 E. 8TH STREET, SUITE #12B  
 NATIONAL CITY, CA 91950**

**ENVIROSTOR S106893819  
 N/A**

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	So Cal - Cypress
Facility ID:	37000061
Site Code:	Not reported
Assembly:	79
Senate:	40
Special Program:	Not reported
Status:	Refer: 1248 Local Agency
Status Date:	2000-04-24 00:00:00
Restricted Use:	NO
Funding:	Not Applicable
Latitude:	0
Longitude:	0
Alias Name:	37000061
Alias Type:	Envirostor ID Number
APN:	NONE SPECIFIED
APN Description:	Not reported
Comments:	DTSC is not involved with this project.

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	SB 1248 Notification
Completed Date:	04/24/00

Confirmed:

Confirmed:	NONE SPECIFIED
Confirmed Description:	Not reported
Future Area Name:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OLD SCHOOLHOUSE SQUARE (Continued)**

**S106893819**

Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

112

**HOLIDAY INN SAN DIEGO SOUTH BA  
 700 NATIONAL CITY BL  
 NATIONAL CITY, CA 91950**

**LUST  
 San Diego Co. HMMD  
 SAN DIEGO CO. SAM**

**S104752339  
 N/A**

LUST:

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Not reported  
 Leak Cause: Not reported  
 Leak Source: Not reported  
 Global Id: T0608118547  
 Stop Date: 1987-09-30 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 1990-01-08 00:00:00  
 Discover Date: 1987-09-30 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1987-09-30 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HOLIDAY INN SAN DIEGO SOUTH BA (Continued)**

**S104752339**

Responsible Party: JEFFREY R LANDIE  
 RP Address: 1138 INDIA ST STE 101  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: DF  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: Not reported  
 Beneficial: Not reported  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H29886-001  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 204746  
 Inactive Indicator: Active  
 Business Code: 6HK18  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 700 NATIONAL CITY BL  
 Mailing City,St,Zip: NATIONAL CITY, CA 91950  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: National City  
 Census Tract Number: 114  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 01/27/05  
 Reinspection Date: Not reported  
 Inspector Name: BGARCHIT  
 Violation Notice Issued: Not reported  
 Facility Contact: BILL GUARINO/CHIEF ENGINEER  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: PACIFICA HARBOR VIEW ONE L P  
 Property Address: 1785 HANCOCK ST #100

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HOLIDAY INN SAN DIEGO SOUTH BA (Continued)**

**S104752339**

Property City,St,Zip: 92110  
 Tank Owner: Not reported  
 Tank Address: Not reported  
 Tank City,St,Zip: Not reported  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: 01/27/07  
 Facility Phone: Not reported

**HMMD DISCLOSURE INVENTORY:**

Item Number: DI37  
 Chemical Name: DIESEL DIESEL  
 Case Number: 68476-34-6  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: FIRE  
 2nd Hazard Category: ACUTE

**HMMD UNDERGROUND TANKS:**

Tank Number: Not reported  
 Tank ID Number: Not reported  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: Not reported  
 Waste Code: Not reported  
 Type of Violation: Not reported  
 Occurrences: Not reported  
 Item Number: Not reported  
 Violation Desc: Not reported

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H29886-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - VAP**

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**HOLIDAY INN SAN DIEGO SOUTH BA (Continued)**

**S104752339**

FType: Soils Only  
 FStatus: Closed Case  
 Date: 1/8/1990  
 Begandt: 9/30/1987

113

**OFFICE OF EDUCATION BUILDING  
 NATIONAL CITY BOULEVARD/8TH STREET  
 NATIONAL CITY, CA 91950**

**SCH S105628897  
 ENVIROSTOR N/A**

SCH:

Facility ID: 37590004  
 Site Type: School Investigation  
 Site Type Detail: School  
 Acres: .5  
 National Priorities List: NO  
 Cleanup Oversight Agencies: SMBRP  
 Lead Agency: SMBRP  
 Lead Agency Description: DTSC - Site Mitigation And Brownfield Reuse Program  
 Project Manager: Not reported  
 Supervisor: Rebecca Chou  
 Division Branch: School Evaluation - Cypress  
 Site Code: 404361-11  
 Assembly: 79  
 Senate: 40  
 Special Program Status: Not reported  
 Status: Inactive - Action Required  
 Status Date: 2002-11-12 00:00:00  
 Restricted Use: NO  
 Funding: School District  
 Latitude: 32.68216  
 Longitude: -117.1105  
 Alias Name: OFFICE OF EDUCATION BUILDING  
 404361-11  
 COMMUNITY DEVELOPMENT COMMISSION  
 37590004  
 COMM. DEVELOP. COMMISSION NATIONAL CITY  
 SAN DIEGO COE-CMUNITY DVELPMNT NATIONAL  
 Alias Type: Envirostor ID Number  
 Alternate Name  
 Alternate Name  
 Alternate Name  
 Project Code (Site Code)  
 Alternate Name  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: PEA-equivalent was reviewed and comments issued. Comments consisted of PEA format and inquiries on the field work done.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Preliminary Endangerment Assessment Report  
 Completed Date: 09/06/02

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OFFICE OF EDUCATION BUILDING (Continued)**

**S105628897**

Completed Document Type: Cost Recovery Closeout Memo  
 Completed Date: 11/12/02

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Environmental Oversight Agreement  
 Completed Date: 07/22/02

Confirmed: 30025-NO,30004-NO,30006-NO,30007-NO,30008-NO,30013-NO  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: SOIL, SV  
 Media Affected Desc: Soil  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 30004, 30006, 30007, 30008, 30013, 30025  
 Potential Description: Chlordane  
 Potential Description: DDD  
 Potential Description: DDE  
 Potential Description: DDT  
 Potential Description: Lead  
 Potential Description: TPH-gas  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: \* RETIAL - MISC.

ENVIROSTOR:  
 Site Type: School Investigation  
 Site Type Detailed: School  
 Acres: .5  
 NPL: NO  
 Regulatory Agencies: SMBRP  
 Lead Agency: SMBRP  
 Program Manager: Not reported  
 Supervisor: Rebecca Chou  
 Division Branch: School Evaluation - Cypress  
 Facility ID: 37590004  
 Site Code: 404361-11  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Inactive - Action Required  
 Status Date: 2002-11-12 00:00:00

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OFFICE OF EDUCATION BUILDING (Continued)**

**S105628897**

Restricted Use: NO  
 Funding: School District  
 Latitude: 32.68216  
 Longitude: -117.1105  
 Alias Name: OFFICE OF EDUCATION BUILDING  
                   404361-11  
                   COMMUNITY DEVELOPMENT COMMISSION  
                   37590004  
                   COMM. DEVELOP. COMMISSION NATIONAL CITY  
                   SAN DIEGO COE-CMUNITY DVELPMNT NATIONAL  
 Alias Type: Envirostor ID Number  
                   Alternate Name  
                   Alternate Name  
                   Alternate Name  
                   Project Code (Site Code)  
                   Alternate Name  
  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: PEA-equivalent was reviewed and comments issued. Comments consisted  
                   of PEA format and inquiries on the field work done.  
  
 Completed Info:  
   Completed Area Name: PROJECT WIDE  
   Completed Sub Area Name: Not reported  
   Completed Document Type: Preliminary Endangerment Assessment Report  
   Completed Date: 09/06/02  
  
   Completed Area Name: PROJECT WIDE  
   Completed Sub Area Name: Not reported  
   Completed Document Type: Cost Recovery Closeout Memo  
   Completed Date: 11/12/02  
  
   Completed Area Name: PROJECT WIDE  
   Completed Sub Area Name: Not reported  
   Completed Document Type: Environmental Oversight Agreement  
   Completed Date: 07/22/02  
  
 Confirmed: 30025-NO,30004-NO,30006-NO,30007-NO,30008-NO,30013-NO  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: SOIL, SV  
 Media Affected Desc: Soil  
 Media Affected Desc: Not reported  
  
 Management:  
   Management Required: NONE SPECIFIED  
   Management Required Desc: Not reported  
   Potential: 30004, 30006, 30007, 30008, 30013, 30025  
   Potential Description: Chlordane



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**OFFICE OF EDUCATION BUILDING (Continued)**

**S105628897**

Potenital Description: DDD  
 Potenital Description: DDE  
 Potenital Description: DDT  
 Potenital Description: Lead  
 Potenital Description: TPH-gas  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: \* RETIAL - MISC.

114

**CHEVRON STAT. #98225  
 105 8TH ST W  
 NATIONAL CITY, CA 92050**

**LUST S101301820  
 Cortese N/A**

**LUST:**

Region: 9  
 Case Number: 9UT1378  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: 0  
 Date Found: 03/14/1989  
 How Found: Tank Closure  
 Date Stopped: 03/14/1989  
 How Stopped: Close Tank  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Drinking Water Aquifer affected  
 Status: Remedial action (cleanup) Underway  
 Abate Method: Remove Free Product - remove floating product from water table, Vapor  
 Extraction  
 Confirm Date: 03/14/1989  
 Submit Workplan: Not reported  
 Prelim Assess: 06/05/1989  
 Desc Pollution: 11/23/92  
 Remed Plan: / /  
 Remed Action: 4/6/95  
 Began Monitor: Not reported  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H13517-001  
 Basin Number: 909.12  
 Gwater Depth: 21'  
 Beneficial Use: MUNISWB/E  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Dispn: Not reported  
 Release Date: 01/24/1990  
 Interim Remedial Actions: Yes  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 Database(s) EPA ID Number

**CHEVRON STAT. #98225 (Continued)**

**S101301820**

Region: CORTESE  
 Facility Addr2: 105 8TH ST W

114

**EDUCATION VILLAGE  
 801 ROOSEVELT AVE.  
 NATIONAL CITY, CA 91950**

**ENVIROSTOR S106797682  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37000028  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2001-01-31 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37000028  
 Alias Type: Envirostor ID Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: Not reported

Completed Info:

Completed Area Name: Not reported  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Not reported  
 Completed Date: Not reported

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:

Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**EDUCATION VILLAGE (Continued)**

**S106797682**

Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

114

**THRIFTY #103  
 801 ROOSEVELT AVE  
 NATIONAL CITY, CA 91950**

**LUST  
 Cortese  
 SWEEPS UST**

**S102438966  
 N/A**

LUST:

Region: 9  
 Case Number: 9UT1762  
 Local Agency: San Diego  
 Substance: Gasoline  
 Qty Leaked: Not reported  
 Date Found: 08/08/1990  
 How Found: Other Means  
 Date Stopped: 08/08/1990  
 How Stopped: Other Means  
 Source: Unknown  
 Cause: Unknown  
 Lead Agency: Local Agency  
 Case Type: Drinking Water Aquifer affected  
 Status: Post remedial action monitoring  
 Abate Method: Remove Free Product - remove floating product from water table  
 Confirm Date: / /  
 Submit Workplan: 8/13/90  
 Prelim Assess: / /  
 Desc Pollution: 3/8/93  
 Remed Plan: / /  
 Remed Action: Not reported  
 Began Monitor: 8/17/93  
 Enforce Type: Not reported  
 Enforce Date: Not reported  
 Closed Date: Not reported  
 Pilot Program: LOP  
 Local Case: H18486-002  
 Basin Number: 908.32  
 Gwater Depth: >21'  
 Beneficial Use: Municipal groundwater use  
 NPDES Number: Not reported  
 priority: LOP/MODERATE - POTENTIAL WATER IMPACT  
 File Disp: Not reported  
 Release Date: 08/08/1990  
 Interim Remedial Actions: No  
 Cleanup and Abatement order Number: Not reported  
 Waste Discharge Requirement Number: Not reported

Cortese:

Region: CORTESE  
 Facility Addr2: 801 ROOSEVELT AVE

SWEEPS UST:

Status: Not reported  
 Comp Number: 18486  
 Number: Not reported  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THRIFTY #103 (Continued)**

**S102438966**

Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-018486-000001  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: 4

Status: Not reported  
 Comp Number: 18486  
 Number: Not reported  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-018486-000002  
 Actv Date: Not reported  
 Capacity: 10000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: REG UNLEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 18486  
 Number: Not reported  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-018486-000003  
 Actv Date: Not reported  
 Capacity: 8000  
 Tank Use: M.V. FUEL  
 Stg: PRODUCT  
 Content: LEADED  
 Number Of Tanks: Not reported

Status: Not reported  
 Comp Number: 18486  
 Number: Not reported  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: Not reported  
 Created Date: Not reported  
 Tank Status: Not reported  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-018486-000004  
 Actv Date: Not reported  
 Capacity: 8000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**THRIFTY #103 (Continued)**

**S102438966**

Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	A
Comp Number:	18486
Number:	9
Board Of Equalization:	44-007386
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-018486-000005
Actv Date:	Not reported
Capacity:	15000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	4
Status:	A
Comp Number:	18486
Number:	9
Board Of Equalization:	44-007386
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-018486-000006
Actv Date:	Not reported
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	OTHER
Number Of Tanks:	Not reported
Status:	A
Comp Number:	18486
Number:	9
Board Of Equalization:	44-007386
Ref Date:	Not reported
Act Date:	06-26-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	37-000-018486-000007
Actv Date:	Not reported
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	LEADED
Number Of Tanks:	Not reported
Status:	A

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**THRIFTY #103 (Continued)**

**S102438966**

Comp Number: 18486  
 Number: 9  
 Board Of Equalization: 44-007386  
 Ref Date: Not reported  
 Act Date: 06-26-92  
 Created Date: 02-29-88  
 Tank Status: A  
 Owner Tank Id: Not reported  
 Swrcb Tank Id: 37-000-018486-000009  
 Actv Date: Not reported  
 Capacity: 12000  
 Tank Use: M.V. FUEL  
 Stg: P  
 Content: LEADED  
 Number Of Tanks: Not reported

114

**ARCO FACILITY NO. 9565  
 801 ROOSEVELT AV  
 NATIONAL CITY, CA 91950**

**LUST  
 San Diego Co. HMMD  
 AIRS  
 SAN DIEGO CO. SAM**

**S105691570  
 N/A**

**LUST:**

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Spill  
 Leak Source: Unknown  
 Global Id: T0607300551  
 Stop Date: 1990-08-08 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: 1993-08-17 00:00:00  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1990-08-08 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1990-08-08 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remediation Plan  
 Chemical: Gasoline  
 Contact Person: Not reported  
 Responsible Party: PETER D'AMICO

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

RP Address: 140 East 12th Street, Suite B  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.32  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H18486-002  
 Case Number: SLT90023  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Soil only  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Other Cause  
 Leak Source: Unknown  
 Global Id: T0608106980  
 Stop Date: 2001-06-29 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: 2001-12-24 00:00:00  
 Discover Date: 2001-06-29 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-06-29 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Case Closed  
 Chemical: Diesel  
 Contact Person: Not reported  
 Responsible Party: ERIC CROCKETT  
 RP Address: 140 E 12 ST SUITE B  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 0  
 MTBE Tested: Not Required to be Tested.  
 Staff: UNA  
 Staff Initials: SW  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.31  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 7  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H18486-003  
 Case Number: Not reported  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: Not reported  
 How Discovered: Not reported  
 How Stopped: Other Means  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0608136121  
 Stop Date: 2001-01-19 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: 2000-09-12 00:00:00  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: Not reported  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 2001-01-19 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 2001-01-19 00:00:00



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Preliminary site assessment underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: Patricia Beard  
 RP Address: 140 E 12TH ST #B  
 Interim: Not reported  
 Oversight Prgm: LOCNL  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 908.32  
 Beneficial: MUN,REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H18486-001  
 Case Number: SLT90024  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name:Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported  
 Summary: Not reported

**San Diego Co. HMMD:**

Facility ID: 118486  
 Inactive Indicator: Active  
 Business Code: 6HK28  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: ENVIRONMENTAL COMPLIANCE  
 Mailing Address: P O BOX 6038  
 Mailing City,St,Zip: ARTESIA, CA 90702  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: National City  
 Census Tract Number: 114  
 EPA ID: CAL000225550

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

Gas Station: Not reported  
 Inspection Date: 01/14/03  
 Reinspection Date: Not reported  
 Inspector Name: TTORRES  
 Violation Notice Issued: Not reported  
 Facility Contact: SAFAR DAVODI  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: BP WEST COAST PRODUCTS LLC  
 Tank Address: P.O. BOX 6038  
 Tank City,St,Zip: Artesia, CA 90702  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 213-477-1451

**HMMD DISCLOSURE INVENTORY:**

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

**HMMD UNDERGROUND TANKS:**

Tank Number: T001  
 Tank ID Number: 103-1/ AT4  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T002  
 Tank ID Number: 103-2/ AT4  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T003  
 Tank ID Number: 103-3/ AT4  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T004  
 Tank ID Number: AT4776  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T005  
 Tank ID Number: AT4776

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T006  
 Tank ID Number: AT4776  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED

Tank Number: T007  
 Tank ID Number: AT4776  
 Waste or Product: Not reported  
 Tank Contents: DIESEL

Tank Number: T009  
 Tank ID Number: AT4776  
 Waste or Product: Not reported  
 Tank Contents: MIDGRADE UNLEADED

Tank Number: T010  
 Tank ID Number: AT4857  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T001  
 Tank ID Number: AT4967  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T011  
 Tank ID Number: AT4967  
 Waste or Product: Not reported  
 Tank Contents: Not reported

Tank Number: T012  
 Tank ID Number: AT4967  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 09/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 7261  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 09/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 7262  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 09/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HV1002  
 Occurrences: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

Item Number: 7263  
 Violation Desc: HMBP NOT ESTABLISHED/IMPLEMENTED.

Inspection Date: 09/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3026  
 Occurrences: Not reported  
 Item Number: 7264  
 Violation Desc: MONITORING SYSTEM NOT FUNCTIONAL

Inspection Date: 09/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3027  
 Occurrences: Not reported  
 Item Number: 7265  
 Violation Desc: UST MONITORING PROCEDURE NOT IMPLEMENTED

Inspection Date: 09/04/98  
 Waste Code: Not reported  
 Type of Violation: 6HX3028  
 Occurrences: Not reported  
 Item Number: 7266  
 Violation Desc: UST RESPONSE PLAN NOT AVAILABLE

Inspection Date: 10/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 9811  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 10/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3003  
 Occurrences: Not reported  
 Item Number: 9812  
 Violation Desc: MONITORING SYTEM NOT TESTED ANNUALLY

Inspection Date: 10/28/99  
 Waste Code: Not reported  
 Type of Violation: 6HX3022  
 Occurrences: Not reported  
 Item Number: 9813  
 Violation Desc: GAUGING STICK IN POOR CONDITION

Inspection Date: 01/19/01  
 Waste Code: Not reported  
 Type of Violation: 6HV0135  
 Occurrences: Not reported  
 Item Number: 1078  
 Violation Desc: MANIFESTS/RECEIPTS NO ONSITE

Inspection Date: 01/19/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1005  
 Occurrences: Not reported  
 Item Number: 1079

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

Violation Desc: HMBP: NO ER CONTACTS LISTED

Inspection Date: 01/19/01  
 Waste Code: Not reported  
 Type of Violation: 6HV1009  
 Occurrences: Not reported  
 Item Number: 1080  
 Violation Desc: HMBP: INADEQUATE SITE MAP

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qnty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**EMI:**

Year: 1999  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1450  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 2  
 Reactive Organic Gases Tons/Yr: 2  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2000  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1450  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**ARCO FACILITY NO. 9565 (Continued)**

**S105691570**

NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

Year: 2001  
 Carbon Monoxide Emissions Tons/Yr: 37  
 Air Basin: SD  
 Facility ID: 1450  
 Air District Name: SD  
 SIC Code: 5541  
 Air District Name: SAN DIEGO COUNTY APCD  
 Community Health Air Pollution Info System: Not reported  
 Consolidated Emission Reporting Rule: Not reported  
 Total Organic Hydrocarbon Gases Tons/Yr: 3  
 Reactive Organic Gases Tons/Yr: 3  
 Carbon Monoxide Emissions Tons/Yr: 0  
 NOX - Oxides of Nitrogen Tons/Yr: 0  
 SOX - Oxides of Sulphur Tons/Yr: 0  
 Particulate Matter Tons/Yr: 0  
 Part. Matter 10 Micrometers & Smlr Tons/Yr: 0

**SAN DIEGO CO. SAM:**

Case Number: H18486-001  
 Agency: DEH Site Assessment & Mitigation  
**Funding: Private - Site Designation**  
 FType: Drinking Water Aquifer Impacted  
 FStatus: Preliminary Assessment  
 Date: 1/19/2001  
 Begandt: 1/19/2001

Case Number: H18486-002  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Drinking Water Aquifer Impacted  
 FStatus: Remedial Investigation  
 Date: 8/17/1993  
 Begandt: 8/8/1990

Case Number: H18486-003  
 Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - Federal Fund**  
 FType: Soils Only  
 FStatus: Closed Case  
 Date: 12/24/2001  
 Begandt: 6/29/2001

114

**CHEVRON #98225**  
**105 W 08TH ST**  
**NATIONAL CITY, CA 91950**

**LUST**  
**San Diego Co. HMMD**  
**SAN DIEGO CO. SAM**

**S104397836**  
**N/A**

**LUST:**

Region: STATE  
 Case Type: Drinking Water Aquifer affected  
 Cross Street: Not reported  
 Enf Type: Not reported  
 Funding: NOR

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON #98225 (Continued)**

**S104397836**

How Discovered: Not reported  
 How Stopped: Close Tank  
 Leak Cause: Unknown  
 Leak Source: Unknown  
 Global Id: T0607300217  
 Stop Date: 1989-03-14 00:00:00  
 Confirm Leak: Not reported  
 Workplan: Not reported  
 Prelim Assess: Not reported  
 Pollution Char: Not reported  
 Remed Plan: Not reported  
 Remed Action: 2004-09-07 00:00:00  
 Monitoring: Not reported  
 Close Date: Not reported  
 Discover Date: 1989-03-14 00:00:00  
 Enforcement Dt: Not reported  
 Release Date: 1989-03-14 00:00:00  
 Review Date: Not reported  
 Enter Date: Not reported  
 MTBE Date: Not reported  
 GW Qualifier: Not reported  
 Soil Qualifier: Not reported  
 Max MTBE GW ppb: Not reported  
 Max MTBE Soil ppb: Not reported  
 County: 37  
 Org Name: Not reported  
 Reg Board: San Diego Region  
 Status: Remedial action (cleanup) Underway  
 Chemical: Unleaded Gasoline  
 Contact Person: Not reported  
 Responsible Party: KILE & DONNA MORGAN  
 RP Address: P.O. Box 2292  
 Interim: Not reported  
 Oversight Prgm: LUST  
 MTBE Class: \*  
 MTBE Conc: 0  
 MTBE Fuel: 1  
 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected  
 Staff: UNA  
 Staff Initials: CB  
 Lead Agency: Local Agency  
 Local Agency: 37000L  
 Hydr Basin #: 909.12  
 Beneficial: MUN,AGR,IND,REC-1,REC-2,WARM,WILD  
 Priority: 4  
 Cleanup Fund Id: Not reported  
 Work Suspended: Not reported  
 Local Case #: H13517-001  
 Case Number: 9UT1378  
 Qty Leaked: Not reported  
 Abate Method: Not reported  
 Operator: Not reported  
 Water System Name: Not reported  
 Well Name: Not reported  
 Distance To Lust: 0  
 Waste Discharge Global ID: Not reported  
 Waste Disch Assigned Name: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON #98225 (Continued)**

**S104397836**

Summary: Not reported

San Diego Co. HMMD:

Facility ID: 113517  
 Inactive Indicator: Active  
 Business Code: Not reported  
 SIC: Not reported  
 Permit Expiration: Not reported  
 Owner: Not reported  
 2nd Name: Not reported  
 Mailing Address: 105 W 08TH ST  
 Mailing City,St,Zip: NATIONAL CITY, CA 91950  
 Map Code/Business Plan on File: Not reported  
 Corporate Code: Not reported  
 Fire Dept District: Not reported  
 Census Tract Number: 114  
 EPA ID: Not reported  
 Gas Station: Not reported  
 Inspection Date: 04/27/88  
 Reinspection Date: Not reported  
 Inspector Name: LEGACY  
 Violation Notice Issued: Not reported  
 Facility Contact: Not reported  
 Delinquent Flag: Not Delinquent  
 Last Update: 05/10/05  
 Last Delinquent Letter: Not reported  
 Delinquent Comment: Not reported  
 Last Letter Type: Not reported  
 Property Owner: Not reported  
 Property Address: Not reported  
 Property City,St,Zip: Not reported  
 Tank Owner: CHEVRON USA INC  
 Tank Address: S P O BOX 2833  
 Tank City,St,Zip: La Habra, CA 90632  
 Business Plan Acceptance Date: Not reported  
 Reinspection Date Y2K Compatible: Not reported  
 Facility Phone: 619-474-1664

HMMD DISCLOSURE INVENTORY:

Item Number: Not reported  
 Chemical Name: Not reported  
 Case Number: Not reported  
 Quantity Stored At One Time: Not reported  
 Quantity Stored at One Time: Not reported  
 Annual Quantity String: Not reported  
 Annual Quantity String: Not reported  
 Measurement Units: Not reported  
 Carcinogen: No  
 1st Hazard Category: Not reported  
 2nd Hazard Category: Not reported

HMMD UNDERGROUND TANKS:

Tank Number: T001  
 Tank ID Number: 1  
 Waste or Product: Not reported  
 Tank Contents: PREMIUM UNLEADED



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**CHEVRON #98225 (Continued)**

**S104397836**

Tank Number: T002  
 Tank ID Number: 2  
 Waste or Product: Not reported  
 Tank Contents: LEADED

Tank Number: T003  
 Tank ID Number: 3  
 Waste or Product: Not reported  
 Tank Contents: REGULAR UNLEADED

Tank Number: T004  
 Tank ID Number: 4  
 Waste or Product: Not reported  
 Tank Contents: Not reported

**HMMD VIOLATIONS:**

Inspection Date: 12/03/87  
 Waste Code: Not reported  
 Type of Violation: 6HV0132  
 Occurrences: Not reported  
 Item Number: 6517  
 Violation Desc: EPA ID NUMBER NOT OBTAINED

Inspection Date: 04/27/88  
 Waste Code: Not reported  
 Type of Violation: 6HX0031  
 Occurrences: Not reported  
 Item Number: 6676  
 Violation Desc: NO HAZWASTE DISPOSAL RECEIPTS

Inspection Date: 04/27/88  
 Waste Code: Not reported  
 Type of Violation: 6HX3001  
 Occurrences: Not reported  
 Item Number: 6677  
 Violation Desc: UST RECORDS NOT MAINTAINED ONSITE

**HMMD WASTE STREAMS:**

Inspection Date: Not reported  
 Waste Item #: Not reported  
 Waste Code: Not reported  
 Waste Name: Not reported  
 Qty at Inspection: Not reported  
 Quantity String: Not reported  
 Annual Qty: Not reported  
 Annual Qty String: Not reported  
 Measurement Unit: Not reported  
 Treatment Method: Not reported  
 Storage Method: Not reported  
 Haz Waste Hauler: Not reported  
 Waste Desc: Not reported  
 Carcinogen: No

**SAN DIEGO CO. SAM:**

Case Number: H13517-001

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**CHEVRON #98225 (Continued)**

**S104397836**

Agency: DEH Site Assessment & Mitigation  
**Funding: LOP - State Fund**  
 FType: Drinking Water Aquifer Impacted  
 FStatus: Remedial Action (Clean-Up)  
 Date: 4/6/1995  
 Begandt: 3/14/1989

115

**USNAVY SAN DIEGO NAVAL STN PWC HM HW  
 32ND ST AND HARBOR DR  
 SAN DIEGO, CA 92136**

**PADS 1000110797  
 HAZNET CA6170024289  
 RCRA-LQG  
 RCRA-TSDF  
 CORRACTS  
 MANIFEST**

HAZNET:

Gepaid: CA6170024289  
 Contact: DEELLEN M BRASHER REGIONAL  
 Telephone: 6195246351  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2730 MCKEAN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921365294  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Not reported  
 Waste Category: Aqueous solution with metals (restricted levels and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc )  
 Disposal Method: Not reported  
 Tons: 4.17  
 Facility County: Not reported

Gepaid: CA6170024289  
 Contact: DEELLEN M BRASHER REGIONAL  
 Telephone: 6195246351  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2730 MCKEAN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921365294  
 Gen County: San Diego  
 TSD EPA ID: Not reported  
 TSD County: Not reported  
 Waste Category: Aqueous solution with metals (restricted levels and Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc )  
 Disposal Method: Not reported  
 Tons: 4.17  
 Facility County: Not reported

Gepaid: CA6170024289  
 Contact: DEELLEN M BRASHER REGIONAL  
 Telephone: 6195246351  
 Facility Addr2: Not reported  
 Mailing Name: Not reported  
 Mailing Address: 2730 MCKEAN ST  
 Mailing City,St,Zip: SAN DIEGO, CA 921365294

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Gen County: San Diego  
 TSD EPA ID: AZD983481813  
 TSD County: 99  
 Waste Category: Asbestos-containing waste  
 Disposal Method: Storage, Container  
 Tons: 16.85  
 Facility County: San Diego

**RCRA-LQG:**

Date form received by agency: 02/21/2006  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Facility address: BLDG 3458, NAVAL STATION  
 SAN DIEGO, CA 92136  
 EPA ID: CA6170024289  
 Mailing address: COMMANDER, NAVY REG. SW  
 33000 NIXIE WY, BLDG 50 RM 326  
 SAN DIEGO, CA 92147  
 Contact: LINDA K MORGAN  
 Contact address: Not reported  
 Not reported  
 Contact country: Not reported  
 Contact telephone: (619) 524-6371  
 Contact email: Not reported  
 EPA Region: 09  
 Land type: Federal  
 Classification: TSDF  
 Description: Handler is engaged in the treatment, storage or disposal of hazardous waste  
 TSD commencement date: Not reported  
 Classification: Large Quantity Generator  
 Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

**Owner/Operator Summary:**

Owner/operator name: USNAVY,COMMANDER, NAVY REGION SW  
 Owner/operator address: 33000 NIXIE WAY, BLDG 50RM 326  
 SAN DIEGO, CA 92147  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Federal  
 Owner/Operator Type: Owner  
 Owner/Op start date: 07/23/1982  
 Owner/Op end date: Not reported  
 Owner/operator name: SHAW INFRASTRUCTURE, INC  
 Owner/operator address: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Not reported  
 Owner/operator country: US  
 Owner/operator telephone: Not reported  
 Legal status: Private  
 Owner/Operator Type: Operator  
 Owner/Op start date: 04/01/2005  
 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
 Mixed waste (haz. and radioactive): No  
 Recycler of hazardous waste: No  
 Transporter of hazardous waste: Yes  
 Treater, storer or disposer of HW: Yes  
 Underground injection activity: No  
 On-site burner exemption: No  
 Furnace exemption: No  
 Used oil fuel burner: No  
 Used oil processor: No  
 User oil refiner: No  
 Used oil fuel marketer to burner: No  
 Used oil Specification marketer: No  
 Used oil transfer facility: Yes  
 Used oil transporter: No  
 Off-site waste receiver: Commercial status unknown

Universal Waste Summary:

Waste type: Batteries  
 Accumulated waste on-site: Yes  
 Generated waste on-site: Yes

Waste type: Lamps  
 Accumulated waste on-site: Yes  
 Generated waste on-site: Yes

Waste type: Pesticides  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Waste type: Thermostats  
 Accumulated waste on-site: No  
 Generated waste on-site: No

Historical Generators:

Date form received by agency: 02/26/2004  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: NAVAL STATION SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 08/15/2002  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: U S NAVY BUILDING 3458 NAVAL STATION  
 Classification: Large Quantity Generator

Date form received by agency: 02/27/2002  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Site name: 32ND STREET NAVAL STATION  
 Classification: Large Quantity Generator

Date form received by agency: 10/12/2000  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: NAVAL STATION, SAN DIEGO (BLDG 3458)  
 Classification: Large Quantity Generator

Date form received by agency: 03/04/1999  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: NAVAL STATION SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 09/01/1996  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: U S NAVY BUILDING 3458 NAVAL STATION  
 Classification: Large Quantity Generator

Date form received by agency: 02/29/1996  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: USNAVY SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 03/31/1994  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: USNAVY NAVAL STN SAN DIEGO  
 Classification: Large Quantity Generator

Date form received by agency: 02/29/1992  
 Facility name: NAVAL ST (32ND ST) NAVAL BASE SAN DIEGO  
 Site name: NAVAL STATION  
 Classification: Large Quantity Generator

**Hazardous Waste Summary:**

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003  
 Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D005  
 Waste name: BARIUM

Waste code: D006  
 Waste name: CADMIUM

Waste code: D007  
 Waste name: CHROMIUM

Waste code: D008  
 Waste name: LEAD

Waste code: D009  
 Waste name: MERCURY

Waste code: D010  
 Waste name: SELENIUM

Waste code: D011  
 Waste name: SILVER

Waste code: D018  
 Waste name: BENZENE

Waste code: D019  
 Waste name: CARBON TETRACHLORIDE

Waste code: D022  
 Waste name: CHLOROFORM

Waste code: D023  
 Waste name: O-CRESOL

Waste code: D035  
 Waste name: METHYL ETHYL KETONE

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE

Waste code: D040  
 Waste name: TRICHLOROETHYLENE

Waste code: F001  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F002  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE,

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: U075  
 Waste name: DICHLORODIFLUOROMETHANE

Waste code: U080  
 Waste name: METHANE, DICHLORO-

Waste code: U226  
 Waste name: ETHANE, 1,1,1-TRICHLORO-

Waste code: U228  
 Waste name: ETHENE, TRICHLORO-

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:

Waste code: D001  
 Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 430061

Waste code: D002  
 Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)

1000110797

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Amount (Lbs): 38073

Waste code: D003

Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Amount (Lbs): 75536

Waste code: D005

Waste name: BARIUM

Amount (Lbs): 1027235

Waste code: D006

Waste name: CADMIUM

Amount (Lbs): 1113144

Waste code: D007

Waste name: CHROMIUM

Amount (Lbs): 1324098

Waste code: D008

Waste name: LEAD

Amount (Lbs): 1304956

Waste code: D009

Waste name: MERCURY

Amount (Lbs): 1799

Waste code: D010

Waste name: SELENIUM

Amount (Lbs): 2646

Waste code: D011

Waste name: SILVER

Amount (Lbs): 359125

Waste code: D018

Waste name: BENZENE

Amount (Lbs): 86921

Waste code: D019

Waste name: CARBON TETRACHLORIDE

Amount (Lbs): 20058

Waste code: D022

Waste name: CHLOROFORM

Amount (Lbs): 19715

Waste code: D023



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)

1000110797

Waste name: O-CRESOL  
 Amount (Lbs): 4

Waste code: D035  
 Waste name: METHYL ETHYL KETONE  
 Amount (Lbs): 35

Waste code: D039  
 Waste name: TETRACHLOROETHYLENE  
 Amount (Lbs): 5097

Waste code: D040  
 Waste name: TRICHLOROETHYLENE  
 Amount (Lbs): 1791

Waste code: F001  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 3781

Waste code: F002  
 Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 23567

Waste code: F003  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.  
 Amount (Lbs): 46

Waste code: F005  
 Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 100

Waste code: U075  
 Waste name: DICHLORODIFLUOROMETHANE  
 Amount (Lbs): 7

Waste code: U080  
 Waste name: METHANE, DICHLORO-  
 Amount (Lbs): 7

Waste code: U226  
 Waste name: ETHANE, 1,1,1-TRICHLORO-  
 Amount (Lbs): 7

Waste code: U228  
 Waste name: ETHENE, TRICHLORO-  
 Amount (Lbs): 7

**Corrective Action Summary:**

Event date: 04/21/1992  
 Event: RFA Completed, Assessment was an RFA.

Event date: 08/16/1993  
 Event: CMS Imposition

Event date: 08/16/1993  
 Event: RFI Imposition

Event date: 12/07/1993  
 Event: Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations.

Event date: 12/07/1993  
 Event: CA Prioritization, Facility or area was assigned a high corrective action priority.

Event date: 05/24/1994  
 Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.

Event date: 05/24/1994  
 Event: Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations.

Event date: 06/14/1996  
 Event: Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment).

Event date: 01/29/1997

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Event: Stabilization Construction Completed

Event date: 06/03/1998  
 Event: Current Human Exposures under Control, More information is needed to make a determination.

Event date: 06/03/1998  
 Event: Igration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected.

Event date: 06/03/1998  
 Event: CA210SM

Event date: 01/23/2001  
 Event: Current Human Exposures under Control, Current human exposures are NOT under control.

Event date: 01/23/2001  
 Event: Igration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected.

Event date: 09/08/2003  
 Event: Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

Event date: 06/02/2004  
 Event: Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the EI determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.

Facility Has Received Notices of Violations:

Regulation violated: Not reported  
 Area of violation: TSD - Preparedness and Prevention  
 Date violation determined: 05/24/2007  
 Date achieved compliance: 05/24/2007  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/24/2007  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Regulation violated: Not reported  
 Area of violation: TSD - General Facility Standards  
 Date violation determined: 05/24/2007  
 Date achieved compliance: 05/24/2007  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/24/2007  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Permits - Application  
 Date violation determined: 01/08/2007  
 Date achieved compliance: 01/08/2007  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 01/08/2007  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 05/17/2006  
 Date achieved compliance: 06/22/2006  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/17/2006  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: TSD - General Facility Standards  
 Date violation determined: 04/11/2006  
 Date achieved compliance: 08/22/2006  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 04/12/2006  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Area of violation: TSD - General Facility Standards  
 Date violation determined: 04/11/2006  
 Date achieved compliance: 04/25/2006  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 04/12/2006  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 04/05/2006  
 Date achieved compliance: 04/05/2006  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 04/05/2006  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: TSD - Contingency Plan and Emergency Procedures  
 Date violation determined: 05/27/2004  
 Date achieved compliance: 07/19/2004  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 05/27/2004  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 12/31/2003  
 Date achieved compliance: 01/07/2004  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Date violation determined: 12/31/2003  
 Date achieved compliance: 05/09/2004  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 09/29/2003  
 Date achieved compliance: 01/06/2004  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 09/29/2003  
 Date achieved compliance: 09/30/2003  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - General  
 Date violation determined: 07/23/2003  
 Date achieved compliance: 08/04/2003  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: Not reported  
 Area of violation: Generators - Records/Reporting  
 Date violation determined: 06/28/2000

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Date achieved compliance: 08/30/2000  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 08/29/2000  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60  
 Area of violation: Generators - General  
 Date violation determined: 10/26/1995  
 Date achieved compliance: 10/26/1995  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 10/26/1995  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.30-34.C  
 Area of violation: Generators - General  
 Date violation determined: 10/26/1995  
 Date achieved compliance: 10/26/1995  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 10/26/1995  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.190-201.J  
 Area of violation: TSD - General  
 Date violation determined: 03/27/1995  
 Date achieved compliance: 04/28/1995  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 03/27/1995  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/26/1994  
 Date achieved compliance: 03/27/1995

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/25/1994  
 Date achieved compliance: 08/26/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/22/1994  
 Date achieved compliance: 08/25/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/11/1994  
 Date achieved compliance: 08/22/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.50-56.D  
 Area of violation: TSD - General  
 Date violation determined: 03/30/1994  
 Date achieved compliance: 05/27/1994  
 Violation lead agency: State



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 03/30/1994  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 03/30/1994  
 Date achieved compliance: 05/27/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 05/13/1994  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 800  
 Final penalty amount: 800  
 Paid penalty amount: 800

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 03/30/1994  
 Date achieved compliance: 05/27/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 03/30/1994  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.50-56.D  
 Area of violation: TSD - General  
 Date violation determined: 03/30/1994  
 Date achieved compliance: 05/27/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 05/13/1994  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 800  
 Final penalty amount: 800  
 Paid penalty amount: 800

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 03/14/1994  
 Date achieved compliance: 08/11/1994  
 Violation lead agency: State  
 Enforcement action: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 11/08/1993  
 Date achieved compliance: 01/31/1994  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 10/15/1993  
 Date achieved compliance: 11/08/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 10/06/1993  
 Date achieved compliance: 10/15/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 10/05/1993  
 Date achieved compliance: 10/06/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/29/1993  
 Date achieved compliance: 10/05/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/24/1993  
 Date achieved compliance: 09/29/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/20/1993  
 Date achieved compliance: 09/24/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 09/17/1993  
 Date achieved compliance: 09/20/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/27/1993  
 Date achieved compliance: 09/17/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/23/1993  
 Date achieved compliance: 08/27/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/20/1993  
 Date achieved compliance: 08/23/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/13/1993  
 Date achieved compliance: 08/20/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/04/1993  
 Date achieved compliance: 08/13/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 08/03/1993  
 Date achieved compliance: 08/04/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 07/26/1993  
 Date achieved compliance: 08/03/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 05/03/1993  
 Date achieved compliance: 07/26/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 01/14/1993  
 Date achieved compliance: 05/03/1993  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 263  
 Area of violation: Transporters - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.30-34.C  
 Area of violation: Generators - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60  
 Area of violation: Generators - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 263  
 Area of violation: Transporters - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.190-201.J  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.170-177.I  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Paid penalty amount: Not reported

Regulation violated: FR - 264.170-177.I  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.40-43.D  
 Area of violation: Generators - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.30-34.C  
 Area of violation: Generators - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.190-201.J  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Regulation violated: FR - 264.50-56.D  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/28/1992  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60  
 Area of violation: Generators - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.50-56.D  
 Area of violation: TSD - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.40-43.D

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Area of violation: Generators - General  
 Date violation determined: 12/28/1992  
 Date achieved compliance: 04/15/1994  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 06/23/1992  
 Date achieved compliance: 11/17/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 06/16/1992  
 Date achieved compliance: 06/23/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 06/11/1992  
 Date achieved compliance: 06/16/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Date violation determined: 06/08/1992  
 Date achieved compliance: 06/11/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 05/27/1992  
 Date achieved compliance: 06/08/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 05/26/1992  
 Date achieved compliance: 05/27/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 05/20/1992  
 Date achieved compliance: 05/26/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 05/14/1992

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Date achieved compliance: 05/20/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 04/23/1992  
 Date achieved compliance: 05/12/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 04/22/1992  
 Date achieved compliance: 04/23/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A  
 Area of violation: Generators - General  
 Date violation determined: 04/16/1992  
 Date achieved compliance: 04/22/1992  
 Violation lead agency: State  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 270  
 Area of violation: TSD - General  
 Date violation determined: 12/03/1991  
 Date achieved compliance: 01/21/1992

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 264.50-56.D  
 Area of violation: TSD - General  
 Date violation determined: 11/26/1991  
 Date achieved compliance: 01/21/1992  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 264.170-177.I  
 Area of violation: TSD - General  
 Date violation determined: 11/26/1991  
 Date achieved compliance: 01/21/1992  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: F - 264.10-18.B  
 Area of violation: TSD - General  
 Date violation determined: 11/26/1991  
 Date achieved compliance: 01/21/1992  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 11/15/1990  
 Date achieved compliance: 01/25/1991  
 Violation lead agency: State

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 12/27/1990  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 11/15/1990  
 Date achieved compliance: 01/25/1991  
 Violation lead agency: State  
 Enforcement action: INITIAL 3008(A) COMPLIANCE  
 Enforcement action date: 04/26/1993  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: 260032  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268 ALL  
 Area of violation: LDR - General  
 Date violation determined: 05/08/1990  
 Date achieved compliance: 08/22/1990  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 07/05/1990  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.70-77.E  
 Area of violation: TSD - General  
 Date violation determined: 05/08/1990  
 Date achieved compliance: 08/22/1990  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 07/05/1990  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 05/08/1990  
 Date achieved compliance: 08/22/1990  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enforcement action date: 07/05/1990  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268.7  
 Area of violation: LDR - General  
 Date violation determined: 05/08/1990  
 Date achieved compliance: 08/22/1990  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 07/05/1990  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.70-77.E  
 Area of violation: TSD - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 07/18/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: EPA TO STATE ADMINISTRATIVE REFERRAL  
 Enforcement action date: 07/18/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 07/18/1989

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 264.70-77.E  
 Area of violation: TSD - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: EPA TO STATE ADMINISTRATIVE REFERRAL  
 Enforcement action date: 07/18/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268 ALL  
 Area of violation: LDR - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 07/18/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268.7  
 Area of violation: LDR - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: WRITTEN INFORMAL  
 Enforcement action date: 07/18/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268.7  
 Area of violation: LDR - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: EPA TO STATE ADMINISTRATIVE REFERRAL  
 Enforcement action date: 07/18/1989  
 Enf. disposition status: Not reported



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 268 ALL  
 Area of violation: LDR - General  
 Date violation determined: 06/06/1989  
 Date achieved compliance: 11/06/1989  
 Violation lead agency: EPA  
 Enforcement action: EPA TO STATE ADMINISTRATIVE REFERRAL  
 Enforcement action date: 07/18/1989  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: EPA  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 07/21/1988  
 Date achieved compliance: 06/06/1989  
 Violation lead agency: EPA  
 Enforcement action: Not reported  
 Enforcement action date: Not reported  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: Not reported  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Regulation violated: FR - 270  
 Area of violation: TSD - General  
 Date violation determined: 03/25/1987  
 Date achieved compliance: 07/21/1988  
 Violation lead agency: EPA  
 Enforcement action: EPA TO STATE ADMINISTRATIVE REFERRAL  
 Enforcement action date: 10/30/1987  
 Enf. disposition status: Not reported  
 Enf. disp. status date: Not reported  
 Enforcement lead agency: State  
 Proposed penalty amount: Not reported  
 Final penalty amount: Not reported  
 Paid penalty amount: Not reported

Evaluation Action Summary:  
 Evaluation date: 05/24/2007  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General Facility Standards  
 Date achieved compliance: 05/24/2007  
 Evaluation lead agency: State  
  
 Evaluation date: 05/24/2007  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Area of violation: TSD - Preparedness and Prevention  
 Date achieved compliance: 05/24/2007  
 Evaluation lead agency: State

Evaluation date: 01/08/2007  
 Evaluation: FACILITY SELF DISCLOSURE  
 Area of violation: Permits - Application  
 Date achieved compliance: 01/08/2007  
 Evaluation lead agency: State

Evaluation date: 05/17/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/22/2006  
 Evaluation lead agency: Local

Evaluation date: 04/11/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General Facility Standards  
 Date achieved compliance: 04/25/2006  
 Evaluation lead agency: State

Evaluation date: 04/11/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General Facility Standards  
 Date achieved compliance: 08/22/2006  
 Evaluation lead agency: State

Evaluation date: 04/05/2006  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 04/05/2006  
 Evaluation lead agency: Local

Evaluation date: 06/15/2005  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 05/27/2004  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - Contingency Plan and Emergency Procedures  
 Date achieved compliance: 07/19/2004  
 Evaluation lead agency: State

Evaluation date: 02/05/2004  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 12/31/2003  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 01/07/2004  
 Evaluation lead agency: State Contractor/Grantee

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Evaluation date:	12/31/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	05/09/2004
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	11/10/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	09/29/2003
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Generators - General
Date achieved compliance:	01/06/2004
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	09/29/2003
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Generators - General
Date achieved compliance:	09/30/2003
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	07/23/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	08/04/2003
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	07/21/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	01/22/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	05/16/2002
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	02/07/2001
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	06/28/2000
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - Records/Reporting

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Date achieved compliance: 08/30/2000  
 Evaluation lead agency: State

Evaluation date: 02/25/1999  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 08/13/1997  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 08/13/1996  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 10/26/1995  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 10/26/1995  
 Evaluation lead agency: State

Evaluation date: 03/27/1995  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 04/28/1995  
 Evaluation lead agency: State

Evaluation date: 08/26/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 03/27/1995  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/25/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/26/1994  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/22/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/25/1994  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/11/1994  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/22/1994  
 Evaluation lead agency: State Contractor/Grantee

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Evaluation date:	04/15/1994
Evaluation:	NOT A SIGNIFICANT NON-COMPLIER
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/14/1994
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	08/11/1994
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	01/31/1994
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD - General
Date achieved compliance:	05/27/1994
Evaluation lead agency:	State
Evaluation date:	11/08/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	01/31/1994
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	10/15/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	11/08/1993
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	10/06/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	10/15/1993
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	10/05/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	10/06/1993
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	09/29/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	10/05/1993
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	09/24/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	09/29/1993
Evaluation lead agency:	State Contractor/Grantee
Evaluation date:	09/20/1993
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Date achieved compliance: 09/24/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 09/17/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 09/20/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/27/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 09/17/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/23/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/27/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/20/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/23/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/13/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/20/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/04/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/13/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 08/03/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/04/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 07/26/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 08/03/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/03/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 07/26/1993  
 Evaluation lead agency: State Contractor/Grantee

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Evaluation date: 01/14/1993  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/03/1993  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 12/28/1992  
 Evaluation: SIGNIFICANT NON-COMPLIER  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State

Evaluation date: 11/17/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 04/15/1994  
 Evaluation lead agency: State

Evaluation date: 11/17/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 04/15/1994  
 Evaluation lead agency: State

Evaluation date: 11/17/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Transporters - General  
 Date achieved compliance: 04/15/1994  
 Evaluation lead agency: State

Evaluation date: 06/23/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 11/17/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/16/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/23/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/11/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/16/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/08/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 06/11/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/27/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Date achieved compliance: 06/08/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/26/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/27/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/20/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/26/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/14/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/20/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 05/12/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 04/23/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 05/12/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 04/22/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 04/23/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 04/16/1992  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Generators - General  
 Date achieved compliance: 04/22/1992  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 10/28/1991  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 01/21/1992  
 Evaluation lead agency: State

Evaluation date: 11/15/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 01/25/1991  
 Evaluation lead agency: State



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Evaluation date: 05/08/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 08/22/1990  
 Evaluation lead agency: EPA

Evaluation date: 05/08/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: LDR - General  
 Date achieved compliance: 08/22/1990  
 Evaluation lead agency: EPA

Evaluation date: 05/04/1990  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: Not reported  
 Date achieved compliance: Not reported  
 Evaluation lead agency: State Contractor/Grantee

Evaluation date: 06/06/1989  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: LDR - General  
 Date achieved compliance: 11/06/1989  
 Evaluation lead agency: EPA

Evaluation date: 06/06/1989  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 11/06/1989  
 Evaluation lead agency: EPA

Evaluation date: 07/21/1988  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 06/06/1989  
 Evaluation lead agency: EPA

Evaluation date: 03/25/1987  
 Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
 Area of violation: TSD - General  
 Date achieved compliance: 07/21/1988  
 Evaluation lead agency: EPA

**CORRACTS:**

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 01/23/2001  
 Action: CA725NO - Current Human Exposures Under Control, Current human exposures are NOT under control  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported  
 EPA ID: CA6170024289  
 EPA Region: 09

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Area Name: ENTIRE FACILITY  
 Actual Date: 01/23/2001  
 Action: CA750NO - Migration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: SITE 12  
 Actual Date: 01/29/1997  
 Action: CA650 - Stabilization Construction Completed  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 05/24/1994  
 Action: CA225YE - Stabilization Measures Evaluation, This facility ,is amenable to stabilization activity based on the, status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 05/24/1994  
 Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 06/02/2004  
 Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human Exposures Under Control has been verified  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Area Name: ENTIRE FACILITY  
 Actual Date: 06/03/1998  
 Action: CA750NO - Migration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 06/03/1998  
 Action: CA725IN - Current Human Exposures Under Control, More information is needed to make a determination  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: SITE 12  
 Actual Date: 06/14/1996  
 Action: CA600SR - Stabilization Measures Implemented, Primary measure is source removal and/or treatment  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: SWMUS 6,9,12,14,16,22,30  
 Actual Date: 08/16/1993  
 Action: CA100 - RFI Imposition  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 09/08/2003  
 Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 12/07/1993

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Action: CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: SWMUS 6,9,12,14,16,22,30  
 Actual Date: 12/07/1993  
 Action: CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: ENTIRE FACILITY  
 Actual Date: 12/07/1993  
 Action: CA225YE - Stabilization Measures Evaluation, This facility ,is amenable to stabilization activity based on the, status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

EPA ID: CA6170024289  
 EPA Region: 09  
 Area Name: SWMUS 6,9,12,14,16,22,30  
 Actual Date: 12/07/1993  
 Action: CA225YE - Stabilization Measures Evaluation, This facility ,is amenable to stabilization activity based on the, status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations  
 NAICS Code(s): 92811  
 National Security  
 Original schedule date: Not reported  
 Schedule end date: Not reported

**NY MANIFEST:**

Document ID: NYA8297631  
 Manifest Status: Completed after the designated time period for a TSDf to get a copy to the DEC  
 Trans1 State ID: 000000000  
 Trans2 State ID: 000000000  
 Generator Ship Date: 890713  
 Trans1 Recv Date: 890713  
 Trans2 Recv Date: 890718  
 TSD Site Recv Date: 890801  
 Part A Recv Date: 890719  
 Part B Recv Date: 890809  
 Generator EPA ID: CA6170024289  
 Trans1 EPA ID: TND987766292

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Trans2 EPA ID:	GAD981233000
TSDf ID:	NYD000632372
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported
EPA ID:	CA6170024289
Facility Name:	UNITED STATES MILITARY-DRMO SAN DIEGO
Facility Address:	PO BOX 337 32ND ST
Facility City:	IMPERIAL BEACH
Facility Address 2:	Not reported
Country:	USA
Mailing Name:	UNITED STATES MILITARY-DRMO SAN DIEGO
Mailing Contact:	UNITED STATES MILITARY-DRMO SAN DIEGO
Mailing Address:	DRMO SAN DIEGO(NAVY BASE)
Mailing Address 2:	Not reported
Mailing City:	PO BOX 337-IMPERIAL BEACH
Mailing State:	CA
Mailing Zip:	92032
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	619-437-9800
Document ID:	NYG0719703
Manifest Status:	Not reported
Trans1 State ID:	MOD095038998
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/1998
Trans1 Recv Date:	07/20/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/04/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CA6170024289
Trans1 EPA ID:	NYD067919340
Trans2 EPA ID:	Not reported
TSDf ID:	HQ32091OR
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00480
Units:	P - Pounds
Number of Containers:	005

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	98
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported
EPA ID:	CA6170024289
Facility Name:	UNITED STATES MILITARY-DRMO SAN DIEGO
Facility Address:	PO BOX 337 32ND ST
Facility City:	IMPERIAL BEACH
Facility Address 2:	Not reported
Country:	USA
Mailing Name:	UNITED STATES MILITARY-DRMO SAN DIEGO
Mailing Contact:	UNITED STATES MILITARY-DRMO SAN DIEGO
Mailing Address:	DRMO SAN DIEGO(NAVY BASE)
Mailing Address 2:	Not reported
Mailing City:	PO BOX 337-IMPERIAL BEACH
Mailing State:	CA
Mailing Zip:	92032
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	619-437-9800
Document ID:	CAA0605000
Manifest Status:	Not reported
Trans1 State ID:	SCR000074591
Trans2 State ID:	NYD982792814
Generator Ship Date:	06/05/2000
Trans1 Recv Date:	06/05/2000
Trans2 Recv Date:	06/12/2000
TSD Site Recv Date:	06/23/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CA6170024289
Trans1 EPA ID:	NYD000632372
Trans2 EPA ID:	Not reported
TSD ID:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00125
Units:	P - Pounds
Number of Containers:	001
Container Type:	CY - Cylinders
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	00
Manifest Tracking Num:	Not reported
Import Ind:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported
EPA ID:	CA6170024289
Facility Name:	UNITED STATES MILITARY-DRMO SAN DIEGO
Facility Address:	PO BOX 337 32ND ST
Facility City:	IMPERIAL BEACH
Facility Address 2:	Not reported
Country:	USA
Mailing Name:	UNITED STATES MILITARY-DRMO SAN DIEGO
Mailing Contact:	UNITED STATES MILITARY-DRMO SAN DIEGO
Mailing Address:	DRMO SAN DIEGO(NAVY BASE)
Mailing Address 2:	Not reported
Mailing City:	PO BOX 337-IMPERIAL BEACH
Mailing State:	CA
Mailing Zip:	92032
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	619-437-9800
Document ID:	NYG0272385
Manifest Status:	Completed copy
Trans1 State ID:	MO001
Trans2 State ID:	Not reported
Generator Ship Date:	970806
Trans1 Recv Date:	970806
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970813
Part A Recv Date:	Not reported
Part B Recv Date:	970828
Generator EPA ID:	CA6170024289
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSD ID:	NYD067919340
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00470
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	97
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**USNAVY SAN DIEGO NAVAL STN PWC HM HW (Continued)**

**1000110797**

Manifest Ref Num: Not reported  
 Alt Fac RCRA Id: Not reported  
 Alt Fac Sign Date: Not reported  
 Mgmt Method Type Code: Not reported  
 EPA ID: CA6170024289  
 Facility Name: UNITED STATES MILITARY-DRMO SAN DIEGO  
 Facility Address: PO BOX 337 32ND ST  
 Facility City: IMPERIAL BEACH  
 Facility Address 2: Not reported  
 Country: USA  
 Mailing Name: UNITED STATES MILITARY-DRMO SAN DIEGO  
 Mailing Contact: UNITED STATES MILITARY-DRMO SAN DIEGO  
 Mailing Address: DRMO SAN DIEGO(NAVY BASE)  
 Mailing Address 2: Not reported  
 Mailing City: PO BOX 337-IMPERIAL BEACH  
 Mailing State: CA  
 Mailing Zip: 92032  
 Mailing Zip4: Not reported  
 Mailing Country: USA  
 Mailing Phone: 619-437-9800

116

**COLONIAL FORD (FORMER)  
 1401 NATIONAL CITY BLVD.  
 NATIONAL CITY, CA 91950**

**ENVIROSTOR S105691293  
 N/A**

ENVIROSTOR:

Site Type: Evaluation  
 Site Type Detailed: Evaluation  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: Referred - Not Assigned  
 Division Branch: So Cal - Cypress  
 Facility ID: 37550011  
 Site Code: Not reported  
 Assembly: 79  
 Senate: 40  
 Special Program: Not reported  
 Status: Refer: 1248 Local Agency  
 Status Date: 2000-04-24 00:00:00  
 Restricted Use: NO  
 Funding: Not Applicable  
 Latitude: 0  
 Longitude: 0  
 Alias Name: 37550011  
 Alias Type: Envirostor ID Number  
  
 APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: DTSC is not involved with this project.

Completed Info:

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: SB 1248 Notification  
 Completed Date: 04/24/00



MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

**COLONIAL FORD (FORMER) (Continued)**

**S105691293**

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: NONE SPECIFIED  
 Potential Description: Not reported  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

117

**1211 MCKINLEY AVE  
 NATIONAL CITY, CA**

**CHMIRS S100538846  
 ENVIROSTOR N/A**

CHMIRS:  
 OES Incident Number: 27087  
 OES notification: Not reported  
 OES Date: 3/2/1993  
 OES Time: 08:00:00 AM  
 Incident Date: Not reported  
**Date Completed: Not reported**  
 Property Use: Not reported  
 Agency Id Number: Not reported  
 Agency Incident Number: Not reported  
 Time Notified: Not reported  
 Time Completed: Not reported  
 Surrounding Area: Not reported  
 Estimated Temperature: Not reported  
 Property Management: Not reported  
 Special Studies 1: Not reported  
 Special Studies 2: Not reported  
 Special Studies 3: Not reported  
 Special Studies 4: Not reported  
 Special Studies 5: Not reported  
 Special Studies 6: Not reported  
 More Than Two Substances Involved?: Not reported  
 Resp Agncy Personel # Of Decontaminated: Not reported  
 Responding Agency Personel # Of Injuries: Not reported  
 Responding Agency Personel # Of Fatalities: Not reported  
 Others Number Of Decontaminated: Not reported  
 Others Number Of Injuries: Not reported  
 Others Number Of Fatalities: Not reported  
 Vehicle Make/year: Not reported  
 Vehicle License Number: Not reported  
 Vehicle State: Not reported  
 Vehicle Id Number: Not reported  
 CA/DOT/PUC/ICC Number: Not reported

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

(Continued)

S100538846

Company Name: Not reported  
 Reporting Officer Name/ID: Not reported  
 Report Date: Not reported  
 Comments: Not reported  
 Facility Telephone: Not reported  
 Waterway Involved: YES  
 Waterway: unk  
 Spill Site: Not reported  
 Cleanup By: san diego co.  
 Containment: Not reported  
 What Happened: Not reported  
 Type: CHEMICAL  
 Measure: Not reported  
 Other: Not reported  
 Date/Time: Not reported  
 Year: 1993  
 Agency: ospr  
 Incident Date: unk  
 Admin Agency: Not reported  
 Amount: unk.  
 Contained: Not reported  
 Site Type: Not reported  
 E Date: Not reported  
 Substance: waste oil/solvents  
 Quantity Released: Not reported  
 BBLs: Not reported  
 Cups: Not reported  
 CUFT: Not reported  
 Gallons: Not reported  
 Grams: Not reported  
 Pounds: Not reported  
 Liters: Not reported  
 Ounces: Not reported  
 Pints: Not reported  
 Quarts: Not reported  
 Sheen: Not reported  
 Tons: Not reported  
 Unknown: Not reported  
 Description: substance in tank overflow had overflow due to rains.  
 Evacuations: UNKNOWN  
 Number of Injuries: UNKNOWN  
 Number of Fatalities: UNKNOWN  
 Description: Not reported

ENVIROSTOR:

Site Type: Historical  
 Site Type Detailed: \* Historical  
 Acres: Not reported  
 NPL: NO  
 Regulatory Agencies: NONE SPECIFIED  
 Lead Agency: NONE SPECIFIED  
 Program Manager: Not reported  
 Supervisor: \* MMONROY  
 Division Branch: So Cal - Cypress  
 Facility ID: 37290001  
 Site Code: Not reported  
 Assembly: 79

MAP FINDINGS

Map ID  
 Direction  
 Distance  
 Distance (ft.)Site

EDR ID Number  
 EPA ID Number

Database(s)

(Continued)

S100538846

Senate: 40  
 Special Program: Not reported  
 Status: Refer: Other Agency  
 Status Date: 1995-04-11 00:00:00  
 Restricted Use: NO  
 Funding: Not reported  
 Latitude: 32.67  
 Longitude: -117.113055555556  
 Alias Name: CAD008352890  
 37290001  
 Alias Type: Envirostor ID Number  
 EPA Identification Number

APN: NONE SPECIFIED  
 APN Description: Not reported  
 Comments: FACILITY IDENTIFIED ID VIA 50 PHONE BOOKNFA FOR DTSC

Completed Info:  
 Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Site Screening  
 Completed Date: 04/11/95

Completed Area Name: PROJECT WIDE  
 Completed Sub Area Name: Not reported  
 Completed Document Type: Discovery  
 Completed Date: 10/19/82

Confirmed: NONE SPECIFIED  
 Confirmed Description: Not reported  
 Future Area Name: Not reported  
 Future Sub Area Name: Not reported  
 Future Document Type: Not reported  
 Future Due Date: Not reported  
 Media Affected: NONE SPECIFIED  
 Media Affected Desc: Not reported

Management:  
 Management Required: NONE SPECIFIED  
 Management Required Desc: Not reported  
 Potential: 10097, 10193, 10198, 10199, 20005, 20012  
 Potental Description: \* CONTAMINATED SOIL  
 Potental Description: \* UNSPECIFIED ACID SOLUTION  
 Potental Description: \* UNSPECIFIED SOLVENT MIXTURES  
 Potental Description: \* WASTE OIL & MIXED OIL  
 Potental Description: \* EMPTY CONTAINERS, LESS THAN 30 GALLONS  
 Potental Description: \* OTHER PESTICIDE CONTAINERS, 30 GALLONS OR MORE  
 Schedule Area Name: Not reported  
 Schedule Sub Area Name: Not reported  
 Schedule Document Type: Not reported  
 Schedule Due Date: Not reported  
 Schedule Revised Date: Not reported  
 PastUse: NONE SPECIFIED

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
CORONADO	S106930941	PUBLIC SERVICE MAINTENANCE YAR	1300 E 1ST ST	92118	SWEEPS UST
CORONADO	1003878853	CORONADO CAYS BATTERY WASTE	NR CORONADO FIRE DEPT	92118	CERC-NFRAP
CORONADO	1006838188	GOLF COURSE GARBAGE DISP AREA	SHERMAN ROAD NAS NORTH ISLAND	92118	FINDS
CORONADO CA	S103866785	GRAND CARIBE	CORONADO CAYS	92118	CHMIRS, WMUDS/SWAT
NATIONAL CITY	U004061661	TEXACO	804 E 08TH ST	91950	UST
NATIONAL CITY	S104397417	AZTEC	1540 E 08TH ST	91950	LUST, San Diego Co. HMMD, SAN DIEGO CO. SAM
NATIONAL CITY	S104397444	MOBIL STATION #100802	3530 E 08TH ST	91950	LUST, San Diego Co. HMMD, SAN DIEGO CO. SAM
NATIONAL CITY	S106874929	SHELL OIL	1601 E 08TH ST	91950	LUST, SAN DIEGO CO. SAM
NATIONAL CITY	S106875383	TEXACO SERVICE STATION	804 E 08TH ST	91950	LUST, SAN DIEGO CO. SAM
NATIONAL CITY	S106905773	FORMER CUYAMACA MEATS	24TH STREET	91950	SLIC
NATIONAL CITY	S108407230	SANTA FE RAILROAD	2400 HARRISON AV	91950	SAN DIEGO CO. SAM
NATIONAL CITY	S108540791	EL DORADO CLEANERS	3003 HIGHLAND AVE STE A	91950	DRYCLEANERS
NATIONAL CITY	S104749504	TRIPLE A SOUTH	3350 MAIN ST	91950	LUST, San Diego Co. HMMD, SWEEP UST, SAN DIEGO CO. SAM
NATIONAL CITY	S106929793	NATIONAL CITY TRANSFER & STG CO	2150 S MC KINLEY AVE	91950	SWEEPS UST
NATIONAL CITY	S105754273	EDUCATION VILLAGE PROJECT	NATIONAL CITY BOULEVARD/EIGHTH STREET	91950	SCH, ENVIROSTOR
NATIONAL CITY	S106927071	HARBOR JEEP EAGLE	NATIONAL CITY BLVD	91950	SWEEPS UST
NATIONAL CITY	U003937978	ARCO FACILITY #9566	1606 E PLAZA BLVD # 105	91950	UST
NATIONAL CITY	U003938217	ARCO SMOGPROS #1758	1540 E PLAZA BLVD # 1758	91950	UST
NATIONAL CITY	S106893851	BNSF CAR TRANSFER LOT	SEC OF 24TH / TIDELANDS AVE.	91950	ENVIROSTOR
NS SAN DIEGO	S104735601	NEX GAS	28TH ST	92136	LUST
NS SAN DIEGO	S100727279	NAVAL STATION COMMISSARY	32ND ST	92136	LUST
NS SAN DIEGO	S104735570	NEAR DRYDOCK	32ND ST	92136	LUST
SAN DIEGO	S108407128	METROPOLITAN TRANSIT PROPERTY	0 1ST / HARBOR DR	92101	LUST, SAN DIEGO CO. SAM
SAN DIEGO	S108407188	PROPOSED CROWN BAY	04TH AV / K ST	92101	SAN DIEGO CO. SAM
SAN DIEGO	S108406975	CAMPBELL INDUSTRIES	08TH AV / HARBOR DR	92101	SAN DIEGO CO. SAM
SAN DIEGO	S108407139	MTS-PORT DISTRICT SITE CLOSED	08TH AV / HARBOR DR	92101	SAN DIEGO CO. SAM
SAN DIEGO	U001572539	BLK. 149 STA. A AREA	10TH / 11TH STREETS, N/O IMPER	92101	HIST UST
SAN DIEGO	S106931994	SDG&E ENVIRONMENTAL	114 W 10TH AVE	92101	SWEEPS UST
SAN DIEGO	U001572541	BLK. 155, STA. A AREA	11TH / 12TH STREETS, S/O IMP	92101	HIST UST
SAN DIEGO	U001572540	BLK. 150, STA. A AREA	11TH / 12TH STREETS, N/O IMP	92101	HIST UST
SAN DIEGO	S106519112	MTS TOWER PARKING GARAGE	12TH / IMPERIAL AVE.	92101	SLIC
SAN DIEGO	S108407303	USN-NAVSTA/UST PERMIT	28TH STREET GAS STATION	92136	SAN DIEGO CO. SAM
SAN DIEGO	1008372041	BAE SYSTEMS NASSCO	28TH AND HARBOR DR	92113	RCRA-LQG
SAN DIEGO	1007569243	32ND ST NAVAL STN	32ND ST	92136	RCRA-SQG, HAZNET
SAN DIEGO	S106922243	32 ST NAVY BASE COMMISSORY	32ND ST	92136	SWEEPS UST
SAN DIEGO	S106929829	NAVY PUBLIC WORKS 32ND ST	32ND ST NAVAL STA	92136	SWEEPS UST
SAN DIEGO	S106932027	SENIOR CHIEF LABIT - CODE 0DA2	32ND ST	92136	SWEEPS UST
SAN DIEGO	S106933885	USN-32ND ST NAVAL STN (PWC)	32ND ST NAVAL STA	92136	SWEEPS UST
SAN DIEGO	S106933887	USN-FLEET TRAINING CENTER	32ND ST	92136	SWEEPS UST
SAN DIEGO	S106797704	ICON	312 / 354 11TH AVENUE	92101	ENVIROSTOR

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SAN DIEGO	S106895177	MEMORIAL AREA MIDDLE SCHOOL ALT SITE A	36TH STREET/OCEAN BOULEVARD	92113	SCH, ENVIROSTOR
SAN DIEGO	S106893841	CITY WALK CONDOS	600-614 / 620 UNION STREET	92101	ENVIROSTOR
SAN DIEGO	2004742542	A-8 ANCHORAGE AREA	A-8 ANCHORAGE AREA		ERNS
SAN DIEGO	1004678317	CITY OF SAN DIEGO WATER DEPT	8TH AND S W CORNER	92101	RCRA-SQG, FINDS, HAZNET
SAN DIEGO	S106915949	SDGE BLOCK 150 FUELING FAC	175 11TH AV/1100LS	92101	LUST, SAN DIEGO CO. SAM
SAN DIEGO	S106916458	SDGE STA A BL 148 FUELING FAC	114 10TH AV/900 L ST	92101	LUST, SAN DIEGO CO. SAM
SAN DIEGO	1001815545	CONTINENTAL MARITIME OF S D	8TH AVE AT HARBOR DR	92101	RCRA-SQG, FINDS
SAN DIEGO	S103675413	PACIFIC TANK CLEANING SERVICES	8TH AVE AT HARBOR DR	92101	HAZNET, SLIC
SAN DIEGO	S106893825	THE RENAISSANCE MARINA CENTER	1ST AVE/FRONT ST/G ST/MARKET ST	92101	ENVIROSTOR
SAN DIEGO	S106797727	HARD ROCK HOTEL	208-228 6TH AVENUE / K STREET	92101	ENVIROSTOR
SAN DIEGO	S108226114	BAY FRONT STREET/CROSBY STREET RELEASE	BAY FRONT STREET	92101	SLIC
SAN DIEGO	1007200573		1995 BAY FRONT STREET	92113	RCRA-LQG
SAN DIEGO	U001572610	STATION A AREA	BETWEEN 11TH / 12TH ST,S/O IMP	92101	HIST UST
SAN DIEGO	U003790058	USN-NAVSTA/AUTO HOBBY SHOP	BLD G 3234	92136	UST
SAN DIEGO	U003790060	USN-NAVSTA (NSC ANNEX)	BLD G 65	92136	UST
SAN DIEGO	U003790077	USN-NAVSTA/BLDG 3362 UST	BLD G 3362	92136	UST
SAN DIEGO	U003790078	USN-NAVSTA/BLDG 74 UST	BLD G 74	92136	UST
SAN DIEGO	S106797694	LOTS 2 THRU 12 IN BLOCK 24 OF MIDDLETOWN	BLK BORDERED BY CEDAR,BEECH,STATE,UNION	92101	ENVIROSTOR
SAN DIEGO	S105539830	NAVAL MEDICAL CENTER PWC PERMT	2200 BOB WILSON DR	92101	San Diego Co. HMMD, SWEEPS UST
SAN DIEGO	S105539831	NAVAL MEDICAL CENTER SAN DIEGO	2200 BOB WILSON DR	92134	LUST, San Diego Co. HMMD, SAN DIEGO CO. SAM
SAN DIEGO	97408693	BOOMED AREA / ABSORBENT PADS	BOOMED AREA / ABSORBENT PADS	92101	ERNS
SAN DIEGO	S108407224	SAN DIEGO HOUSING COMMISSION	BOSTON AV	92113	RCRA-SQG, FINDS, HAZNET
SAN DIEGO	S106797701	UNION SQUARE	1400,1434 BROADWAY / 1441 C STREET	92101	ENVIROSTOR
SAN DIEGO	S106932471	SPRECKELS BLDG	121 BROADWAY 600	92101	SWEEPS UST
SAN DIEGO	S108540690	CONTINENTAL CLEANERS	1001 BROADWAY STE 100	92101	DRYCLEANERS
SAN DIEGO	A100109260	NAVAL HOSPITAL	CODE BGA/2200 BOB WILSON DR.	92134	AST
SAN DIEGO	2000548158	COMMERCIAL BASIN AREA	COMMERCIAL BASIN AREA		ERNS
SAN DIEGO	1003879071	GIFFORD'S BARRELS	NE CORNER OF 26TH & COMMERCIAL ST	92113	CERC-NFRAP
SAN DIEGO	S108407019	CROSBY STREET MERCADO	CROSBY ST	92101	SAN DIEGO CO. SAM
SAN DIEGO	S108406969	BURLINGTON NTHRN & SANTA FE RAIL	1342 CROSBY ST	92113	SAN DIEGO CO. SAM
SAN DIEGO	S108407018	CROSBY ST CORRIDOR	CROSBY ST	92113	SAN DIEGO CO. SAM
SAN DIEGO	S108407052	FORMER UNOCAL PIPELINE	CROSBY / BAY FRONT	92113	SAN DIEGO CO. SAM
SAN DIEGO	S101301972	CITY OF S.D. FIRE STATION #7	944 CROSBY ST	92101	LUST, Cortese
SAN DIEGO	U003941535	SDCTY-FIRE STATION #07	944 CROSBY ST	92113	LUST, UST, San Diego Co. HMMD, SWEEPS UST, SAN DIEGO CO. SAM
SAN DIEGO	S106797678	INTERNATIONAL GATEWAY	N E OF WILLOW RD / TIA JUANA ST.	92101	ENVIROSTOR
SAN DIEGO	U001572628	CONTRACT SYSTEMS ASSOCIATES, I	1352 FAIRCHILD T.	92102	HIST UST
SAN DIEGO	92268646	FLIGHT LINE AREA	FLIGHT LINE AREA	92101	ERNS
SAN DIEGO	S100270128	U.S. NAVAL HOSPITAL, SAN DIEGO	FLORIDA PL. / PERSHING DR.	92101	ENVIROSTOR
SAN DIEGO	1001231335	ELECTROSOLVE SVCS	FOOT OF SAMPSON ST	92113	RCRA-SQG
SAN DIEGO	S106396901		FOOT OF SAMPSON STREET		CHMIRS, SLIC
SAN DIEGO	S108407102	LAURA G. RODRIGUEZ SCHOOL	GREELY AVENUE	92113	SAN DIEGO CO. SAM
SAN DIEGO	1001231395	SHIP MV GALAXY 9106297	1140 N HARBOR DR B ST PIER	92101	RCRA-SQG, FINDS
SAN DIEGO	1001231397	MV RHAPSODY OF THE SEAS	1140 N HARBOR DR (B ST PIER)	92101	RCRA-SQG, FINDS, HAZNET
SAN DIEGO	1001231398	SHIP MS LEGEND OF THE SEAS 9070620	1140 NORTH HARBOR DRIVE	92101	RCRA-SQG, FINDS, HAZNET
SAN DIEGO	1001481008	SHIP M V ZENITH 8918136	1140 N HARBOR DR B ST 8918136	92101	RCRA-SQG, FINDS

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SAN DIEGO	1007569193	CONTINENTAL MARITIME OF SAN DIEGO INC	910 HARBOR DRIVE	92101	RCRA-SQG, HAZNET
SAN DIEGO	1009398325	ALLIANCE STAR ENERGY LLC	1380 CG HARBOR ISLAND DRIVE	92101	RCRA-SQG
SAN DIEGO	S106905767	LINDBERGH FIELD PLANT - BLDG 75	HARBOR DRIVE	92101	SLIC
SAN DIEGO	U003940840	NASSCO	2800 N HARBOR DR # 6	92101	UST
SAN DIEGO	S106929786	NASSCO	2800 H HARBOR DR 6	92113	SWEEPS UST
SAN DIEGO	S106931790	SAN DIEGO PIPELINE CO	2295 E HARBOR DR A	92113	SWEEPS UST
SAN DIEGO	S104575933	CARMEL MOUNTAIN RANCH COUNTRY	12200 HIGHLAND RANCH RD		HAZNET, SWEEPS UST
SAN DIEGO	S108406920	24TH & IMPERIAL AUTO REPAIR	IMPERIAL AV	92102	SAN DIEGO CO. SAM
SAN DIEGO	S106893822	9TH AND IMPERIAL	IMPERIAL AV BW WEST OF 8TH / EAST OF 9TH	92101	ENVIROSTOR
SAN DIEGO	S108407084	IMPERIAL AV 8TH> >9TH (VAP)	IMPERIAL/BTWN8TH / 9TH	92101	SAN DIEGO CO. SAM
SAN DIEGO	1008402438	GRANT HILL SUB	INTERSECTION OF 30TH	92102	HAZNET, RCRA-LQG
SAN DIEGO	S108992030	NAVAL STATION (NAVSTA) SAN DIEGO - IR SITE 1 FORME	KIDD STREET	92136	SLIC
SAN DIEGO	S106167356	BUTLER BROS CLEANERS	3280 MAIN ST STE 1	92113	DRYCLEANERS
SAN DIEGO	S106930431	PACIFIC TREATMENT DIVISION	2190 MAIN ST 1	92113	SWEEPS UST
SAN DIEGO	S106931855	SANCHEZ AUTO BODY	3746 MAIN ST B	92113	SWEEPS UST
SAN DIEGO	S108407253	SOUTHWEST MARINE	MAIN ST	92113	SAN DIEGO CO. SAM
SAN DIEGO	S108418346	NAVAL STATION (NAVSTA) SAN DIEGO - IR SITE 22 (AOP)	MAIN STREET	92136	LUST
SAN DIEGO	S103630679	MARINA REDEVELOPMENT AREA	144 WEST MARKET SEC. B	92101	HAZNET
SAN DIEGO	S106922612	AMALIA FLORES	4196 MARKET ST B	92102	SWEEPS UST
SAN DIEGO	S100731892	CENTER CITY DEV CORP T0172	MARKET ST	92101	San Diego Co. HMMD, SAN DIEGO CO. SAM
SAN DIEGO	S108407044	F.S.E.INC	MARKET ST	92101	SAN DIEGO CO. SAM
SAN DIEGO	1000243714	MT HOPE CEMETERY	3751 MARTIN L KING WAY	92102	FINDS, RCRA-NonGen
SAN DIEGO	1007199544		1002 E MARTIN LUTHER KING JR	92101	RCRA-LQG
SAN DIEGO	S103442758	MAY BE PARADISE OR JAMACHE LAN	I MILE W OF SWEETWATER I		WMUDS/SWAT
SAN DIEGO	S106922192		32 ST NAVY BASE COMMISSORY/32ND ST	92136	SWEEPS UST
SAN DIEGO	S106916142	CABRILLO POWER II LLC	NONE WARD RD / VESTA ST	92136	LUST
SAN DIEGO	S106874815	CROSBY STREET MERCADO	NONE CROSBY ST	92101	LUST
SAN DIEGO	S106915963	SETON	NONE B ST	92101	LUST
SAN DIEGO	S106916022	MTS-PORT DISTRICT SITE CLOSED	NONE 08TH AV / HARBOR DR	92101	LUST
SAN DIEGO	S106916355	PROPOSED CROWN BAY DEVELOPMENT	NONE 04TH AV / K ST	92101	LUST
SAN DIEGO	S106916418	CAMPBELL INDUSTRIES	NONE 08TH AV / HARBOR DR	92101	LUST
SAN DIEGO	S106916470	IMPERIAL AV 8TH> >9TH (VAP)	NONE IMPERIAL/BTWN8TH / 9TH	92101	LUST
SAN DIEGO	S106916569	F.S.E. INC	NONE MARKET ST	92101	LUST
SAN DIEGO	S106915861	SAN DIEGO HOUSING COMMISSION	NONE BOSTON AV	92113	LUST
SAN DIEGO	S106916250	SOUTHWEST MARINE	NONE MAIN ST	92113	LUST
SAN DIEGO	S106916255	FORMER UNOCAL PIPELINE	NONE CROSBY / BAY FRONT	92113	LUST
SAN DIEGO	S106916375	SOUTHWEST MARINE INC	NONE SAMPSON ST (FOOT OF)	92113	LUST
SAN DIEGO	S106916598	CROSBY ST CORRIDOR	NONE CROSBY ST	92113	LUST
SAN DIEGO	1004654691	AIR FORCE PLT 19	4297 PACIFIC COAST HWY	92101	CERC-NFRAP
SAN DIEGO	1004675676	SHELL SERVICE STATION - 135897	2008 PACIFIC HWY/GRAPE	92101	RCRA-SQG, FINDS, HAZNET
SAN DIEGO	A100282052	OGDEN AVIATION FUELING CO.,INC	3698 C PACIFIC HWY.	92101	AST
SAN DIEGO	S106519116	NAVISTAR INTERNATIONAL TRANS. CORP.	2200 PACIFIC COAST HWY	92101	SLIC
SAN DIEGO	U003940914	OGDEN AVIATION FUELING COINC	3698 PACIFIC HWY # C	92101	UST
SAN DIEGO	U001573326	NAVAL HOSPITAL	PARK BLVD	92134	HIST UST

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SAN DIEGO	S103679709	CITY OF SAN DIEGO/BARRIO LOGAN PROJECT	REAL ESTATE ASSET	92113	HAZNET
SAN DIEGO	S106932437	SOUTHWEST MARINE INC	W SAMPSON	92113	SWEEPS UST
SAN DIEGO	S108407255	SOUTHWEST MARINE INC	SAMPSON ST (FOOT OF)	92113	SAN DIEGO CO. SAM
SAN DIEGO	S106800180	NAVAL STATION SAN DIEGO	SAN DIEGO BAY, 113 NAVAL BASE 610	92136	RESPONSE, ENVIROSTOR, HIST Cal-Sites
SAN DIEGO	S107737243	SAN DIEGO NALF (AUXLNDFL)	SAN DIEGO	92101	ENVIROSTOR
SAN DIEGO	S103442740	NORTH MIRAMAR	SAN CLEMENTE CANYON		WMUDS/SWAT
SAN DIEGO	1002850098	SAN DIEGO NAVAL STATION	SAN DIEGO NAVAL STATION	92136	CERC-NFRAP
SAN DIEGO	S105790779	SAN DIEGO SIMA	SAN DIEGO		LUST, ENVIROSTOR
SAN DIEGO	S105790786	SAN DIEGO PWC	SAN DIEGO		LUST, ENVIROSTOR
SAN DIEGO	S106567722	SAN DIEGO NAVAL SPACE COMMAND	SAN DIEGO		LUST, ENVIROSTOR
SAN DIEGO	S106797698	PROPOSED 5TH & K DEVELOPMENT	NORTH SIDE OF K STREET B/W 5TH / 6TH AVE	92101	ENVIROSTOR
SAN DIEGO	S106933947	USN-SIMA 32ND ST NAVSTATION	SIMA 32ND ST NAVSTA	92136	SWEEPS UST
SAN DIEGO	S104574377	SATURN CLEANERS LLC	655 19TH ST STE E	92102	HAZNET, DRYCLEANERS
SAN DIEGO	S108407248	SETON	B ST	92101	SAN DIEGO CO. SAM
SAN DIEGO	S105690963	MERCURIO PROPERTY	702 K ST	92101	LUST, SAN DIEGO CO. SAM
SAN DIEGO	S107472908	DIAMOND VIEW TOWER	0 J ST	92101	LUST, SAN DIEGO CO. SAM
SAN DIEGO	S106797667	TRIANGLE PROPERTY	65 13TH ST. / 1344 NATIONAL AVENUE	92101	ENVIROSTOR
SAN DIEGO	S108407333	W-HOTEL SAN DIEGO	STATE ST	92101	SAN DIEGO CO. SAM
SAN DIEGO	S106922804	ARCO LINDBERGH FIELD	2400 STILLWATER RD C	92101	SWEEPS UST
SAN DIEGO	2000523156	G STREET MOLE AREA	G STREET MOLE AREA		ERNS
SAN DIEGO	S106893820	9TH AND IMPERIAL	9TH STREET SOUTH OF IMPERIAL	92101	ENVIROSTOR
SAN DIEGO	1007200584		C/O SUPSHIP SAN DIEGO, USN AT	92113	RCRA-LQG
SAN DIEGO	U003937222	550 CORPORATE CENTER	550-# 690 W C ST	92101	UST
SAN DIEGO	S107473118	WEBSTER AVENUE LOTS	0 WEBSTER	92113	LUST, SAN DIEGO CO. SAM
SAN DIEGO	1002850009	NAVAL FACILITIES ENGINEERING COMM	WESTERN DIV	92136	CERC-NFRAP
SAN DIEGO	CA S103442801	INDUSTRIAL/OIL WTP	NAS NORTH ISLAND, SITE 11	92136	WMUDS/SWAT
SAN DIEGO	CA S102006413	NASNI BIOREMEDIATION FACILITY	NAVAL AIR STATION NORTH ISLAND	92136	CHMIRS, WMUDS/SWAT

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Number of Days to Update:** Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

## **FEDERAL RECORDS**

### **NPL: National Priority List**

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/31/2008	Source: EPA
Date Data Arrived at EDR: 02/08/2008	Telephone: N/A
Date Made Active in Reports: 03/17/2008	Last EDR Contact: 04/28/2008
Number of Days to Update: 38	Next Scheduled EDR Contact: 07/28/2008
	Data Release Frequency: Quarterly

### **NPL Site Boundaries**

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)  
Telephone: 202-564-7333

EPA Region 1  
Telephone 617-918-1143

EPA Region 6  
Telephone: 214-655-6659

EPA Region 3  
Telephone 215-814-5418

EPA Region 7  
Telephone: 913-551-7247

EPA Region 4  
Telephone 404-562-8033

EPA Region 8  
Telephone: 303-312-6774

EPA Region 5  
Telephone 312-886-6686

EPA Region 9  
Telephone: 415-947-4246

EPA Region 10  
Telephone 206-553-8665

### **Proposed NPL: Proposed National Priority List Sites**

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 01/31/2008	Source: EPA
Date Data Arrived at EDR: 02/04/2008	Telephone: N/A
Date Made Active in Reports: 03/17/2008	Last EDR Contact: 04/28/2008
Number of Days to Update: 42	Next Scheduled EDR Contact: 07/28/2008
	Data Release Frequency: Quarterly

### **DELISTED NPL: National Priority List Deletions**

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/31/2008	Source: EPA
Date Data Arrived at EDR: 02/08/2008	Telephone: N/A
Date Made Active in Reports: 03/17/2008	Last EDR Contact: 04/28/2008
Number of Days to Update: 38	Next Scheduled EDR Contact: 07/28/2008
	Data Release Frequency: Quarterly



# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **NPL LIENS:** Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991	Source: EPA
Date Data Arrived at EDR: 02/02/1994	Telephone: 202-564-4267
Date Made Active in Reports: 03/30/1994	Last EDR Contact: 05/19/2008
Number of Days to Update: 56	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: No Update Planned

## **CERCLIS:** Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/08/2008	Source: EPA
Date Data Arrived at EDR: 04/25/2008	Telephone: 703-412-9810
Date Made Active in Reports: 05/21/2008	Last EDR Contact: 04/25/2008
Number of Days to Update: 26	Next Scheduled EDR Contact: 06/16/2008
	Data Release Frequency: Quarterly

## **CERCLIS-NFRAP:** CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 12/03/2007	Source: EPA
Date Data Arrived at EDR: 12/06/2007	Telephone: 703-412-9810
Date Made Active in Reports: 02/20/2008	Last EDR Contact: 05/20/2008
Number of Days to Update: 76	Next Scheduled EDR Contact: 06/16/2008
	Data Release Frequency: Quarterly

## **LIENS 2:** CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/08/2008	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/07/2008	Telephone: 202-564-6023
Date Made Active in Reports: 03/20/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 13	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Varies

## **CORRACTS:** Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/26/2008	Source: EPA
Date Data Arrived at EDR: 04/02/2008	Telephone: 800-424-9346
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 06/02/2008
Number of Days to Update: 34	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: Quarterly

## **RCRA-TSDF:** RCRA - Transporters, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 03/06/2008  
Date Data Arrived at EDR: 03/06/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 43

Source: Environmental Protection Agency  
Telephone: (415) 495-8895  
Last EDR Contact: 05/21/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Quarterly

## **RCRA-LQG:** RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/06/2008  
Date Data Arrived at EDR: 03/06/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 43

Source: Environmental Protection Agency  
Telephone: (415) 495-8895  
Last EDR Contact: 05/21/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Quarterly

## **RCRA-SQG:** RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/06/2008  
Date Data Arrived at EDR: 03/06/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 43

Source: Environmental Protection Agency  
Telephone: (415) 495-8895  
Last EDR Contact: 05/21/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Quarterly

## **RCRA-CESQG:** RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/06/2008  
Date Data Arrived at EDR: 03/06/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 43

Source: Environmental Protection Agency  
Telephone: (415) 495-8895  
Last EDR Contact: 05/21/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Varies

## **RCRA-NonGen:** RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/06/2008  
Date Data Arrived at EDR: 03/06/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 43

Source: Environmental Protection Agency  
Telephone: (415) 495-8895  
Last EDR Contact: 05/21/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **US ENG CONTROLS:** Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 04/04/2008	Source: Environmental Protection Agency
Date Data Arrived at EDR: 04/17/2008	Telephone: 703-603-0695
Date Made Active in Reports: 05/15/2008	Last EDR Contact: 03/31/2008
Number of Days to Update: 28	Next Scheduled EDR Contact: 06/30/2008
	Data Release Frequency: Varies

## **US INST CONTROL:** Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 04/04/2008	Source: Environmental Protection Agency
Date Data Arrived at EDR: 04/17/2008	Telephone: 703-603-0695
Date Made Active in Reports: 05/15/2008	Last EDR Contact: 03/31/2008
Number of Days to Update: 28	Next Scheduled EDR Contact: 06/30/2008
	Data Release Frequency: Varies

## **ERNS:** Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2007	Source: National Response Center, United States Coast Guard
Date Data Arrived at EDR: 01/23/2008	Telephone: 202-267-2180
Date Made Active in Reports: 03/17/2008	Last EDR Contact: 04/22/2008
Number of Days to Update: 54	Next Scheduled EDR Contact: 07/21/2008
	Data Release Frequency: Annually

## **HMIRS:** Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2007	Source: U.S. Department of Transportation
Date Data Arrived at EDR: 04/16/2008	Telephone: 202-366-4555
Date Made Active in Reports: 05/15/2008	Last EDR Contact: 04/16/2008
Number of Days to Update: 29	Next Scheduled EDR Contact: 07/14/2008
	Data Release Frequency: Annually

## **DOT OPS:** Incident and Accident Data

Department of Transportation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 02/14/2008	Source: Department of Transportation, Office of Pipeline Safety
Date Data Arrived at EDR: 02/27/2008	Telephone: 202-366-4595
Date Made Active in Reports: 03/20/2008	Last EDR Contact: 05/28/2008
Number of Days to Update: 22	Next Scheduled EDR Contact: 08/25/2008
	Data Release Frequency: Varies

## **CDL:** Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 09/01/2007  
Date Data Arrived at EDR: 12/03/2007  
Date Made Active in Reports: 12/28/2007  
Number of Days to Update: 25

Source: Drug Enforcement Administration  
Telephone: 202-307-1000  
Last EDR Contact: 03/28/2008  
Next Scheduled EDR Contact: 06/23/2008  
Data Release Frequency: Quarterly

## **US BROWNFIELDS:** A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 04/01/2008  
Date Data Arrived at EDR: 04/30/2008  
Date Made Active in Reports: 05/30/2008  
Number of Days to Update: 30

Source: Environmental Protection Agency  
Telephone: 202-566-2777  
Last EDR Contact: 04/30/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: Semi-Annually

## **DOD:** Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005  
Date Data Arrived at EDR: 11/10/2006  
Date Made Active in Reports: 01/11/2007  
Number of Days to Update: 62

Source: USGS  
Telephone: 703-692-8801  
Last EDR Contact: 05/09/2008  
Next Scheduled EDR Contact: 08/04/2008  
Data Release Frequency: Semi-Annually

## **FUDS:** Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2006  
Date Data Arrived at EDR: 08/31/2007  
Date Made Active in Reports: 10/11/2007  
Number of Days to Update: 41

Source: U.S. Army Corps of Engineers  
Telephone: 202-528-4285  
Last EDR Contact: 04/03/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Varies

## **LUCIS:** Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005  
Date Data Arrived at EDR: 12/11/2006  
Date Made Active in Reports: 01/11/2007  
Number of Days to Update: 31

Source: Department of the Navy  
Telephone: 843-820-7326  
Last EDR Contact: 03/10/2008  
Next Scheduled EDR Contact: 06/09/2008  
Data Release Frequency: Varies

## **CONSENT:** Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/08/2008  
Date Data Arrived at EDR: 04/25/2008  
Date Made Active in Reports: 05/30/2008  
Number of Days to Update: 35

Source: Department of Justice, Consent Decree Library  
Telephone: Varies  
Last EDR Contact: 04/22/2008  
Next Scheduled EDR Contact: 07/21/2008  
Data Release Frequency: Varies

## **ROD:** Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/14/2008  
Date Data Arrived at EDR: 01/22/2008  
Date Made Active in Reports: 01/30/2008  
Number of Days to Update: 8

Source: EPA  
Telephone: 703-416-0223  
Last EDR Contact: 03/31/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Annually

## **UMTRA:** Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 07/13/2007  
Date Data Arrived at EDR: 12/03/2007  
Date Made Active in Reports: 01/24/2008  
Number of Days to Update: 52

Source: Department of Energy  
Telephone: 505-845-0011  
Last EDR Contact: 03/17/2008  
Next Scheduled EDR Contact: 06/16/2008  
Data Release Frequency: Varies

## **ODI:** Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985  
Date Data Arrived at EDR: 08/09/2004  
Date Made Active in Reports: 09/17/2004  
Number of Days to Update: 39

Source: Environmental Protection Agency  
Telephone: 800-424-9346  
Last EDR Contact: 06/09/2004  
Next Scheduled EDR Contact: N/A  
Data Release Frequency: No Update Planned

## **DEBRIS REGION 9:** Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 03/25/2008  
Date Data Arrived at EDR: 04/17/2008  
Date Made Active in Reports: 05/15/2008  
Number of Days to Update: 28

Source: EPA, Region 9  
Telephone: 415-972-3336  
Last EDR Contact: 03/24/2008  
Next Scheduled EDR Contact: 06/23/2008  
Data Release Frequency: Varies

## **MINES:** Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/07/2008  
Date Data Arrived at EDR: 03/26/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 23

Source: Department of Labor, Mine Safety and Health Administration  
Telephone: 303-231-5959  
Last EDR Contact: 03/26/2008  
Next Scheduled EDR Contact: 06/23/2008  
Data Release Frequency: Semi-Annually

## **TRIS:** Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2006  
Date Data Arrived at EDR: 02/29/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 49

Source: EPA  
Telephone: 202-566-0250  
Last EDR Contact: 02/29/2008  
Next Scheduled EDR Contact: 06/16/2008  
Data Release Frequency: Annually

## **TSCA: Toxic Substances Control Act**

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2002  
Date Data Arrived at EDR: 04/14/2006  
Date Made Active in Reports: 05/30/2006  
Number of Days to Update: 46

Source: EPA  
Telephone: 202-260-5521  
Last EDR Contact: 04/28/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: Every 4 Years

**FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)**  
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/11/2008  
Date Data Arrived at EDR: 04/24/2008  
Date Made Active in Reports: 05/21/2008  
Number of Days to Update: 27

Source: EPA/Office of Prevention, Pesticides and Toxic Substances  
Telephone: 202-566-1667  
Last EDR Contact: 03/17/2008  
Next Scheduled EDR Contact: 06/16/2008  
Data Release Frequency: Quarterly

**FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)**  
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/11/2008  
Date Data Arrived at EDR: 04/24/2008  
Date Made Active in Reports: 05/21/2008  
Number of Days to Update: 27

Source: EPA  
Telephone: 202-566-1667  
Last EDR Contact: 03/17/2008  
Next Scheduled EDR Contact: 06/16/2008  
Data Release Frequency: Quarterly

## **HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing**

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006  
Date Data Arrived at EDR: 03/01/2007  
Date Made Active in Reports: 04/10/2007  
Number of Days to Update: 40

Source: Environmental Protection Agency  
Telephone: 202-564-2501  
Last EDR Contact: 12/17/2007  
Next Scheduled EDR Contact: 03/17/2008  
Data Release Frequency: No Update Planned

## **HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing**

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/19/2006  
Date Data Arrived at EDR: 03/01/2007  
Date Made Active in Reports: 04/10/2007  
Number of Days to Update: 40

Source: Environmental Protection Agency  
Telephone: 202-564-2501  
Last EDR Contact: 12/17/2008  
Next Scheduled EDR Contact: 03/17/2008  
Data Release Frequency: No Update Planned

## **SSTS:** Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2006  
Date Data Arrived at EDR: 03/14/2008  
Date Made Active in Reports: 04/18/2008  
Number of Days to Update: 35

Source: EPA  
Telephone: 202-564-4203  
Last EDR Contact: 04/14/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: Annually

## **ICIS:** Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 02/28/2008  
Date Data Arrived at EDR: 03/18/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 49

Source: Environmental Protection Agency  
Telephone: 202-564-5088  
Last EDR Contact: 04/14/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: Quarterly

## **PADS:** PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 12/04/2007  
Date Data Arrived at EDR: 02/07/2008  
Date Made Active in Reports: 03/17/2008  
Number of Days to Update: 39

Source: EPA  
Telephone: 202-566-0500  
Last EDR Contact: 05/30/2008  
Next Scheduled EDR Contact: 08/04/2008  
Data Release Frequency: Annually

## **MLTS:** Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/15/2008  
Date Data Arrived at EDR: 02/07/2008  
Date Made Active in Reports: 03/17/2008  
Number of Days to Update: 39

Source: Nuclear Regulatory Commission  
Telephone: 301-415-7169  
Last EDR Contact: 03/31/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Quarterly

## **RADINFO:** Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/29/2008  
Date Data Arrived at EDR: 05/01/2008  
Date Made Active in Reports: 05/21/2008  
Number of Days to Update: 20

Source: Environmental Protection Agency  
Telephone: 202-343-9775  
Last EDR Contact: 05/01/2008  
Next Scheduled EDR Contact: 07/28/2008  
Data Release Frequency: Quarterly

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **FINDS:** Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/03/2008	Source: EPA
Date Data Arrived at EDR: 04/08/2008	Telephone: (415) 947-8000
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 03/31/2008
Number of Days to Update: 28	Next Scheduled EDR Contact: 06/30/2008
	Data Release Frequency: Quarterly

## **RAATS:** RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995	Source: EPA
Date Data Arrived at EDR: 07/03/1995	Telephone: 202-564-4104
Date Made Active in Reports: 08/07/1995	Last EDR Contact: 06/02/2008
Number of Days to Update: 35	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: No Update Planned

## **BRS:** Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2005	Source: EPA/NTIS
Date Data Arrived at EDR: 03/06/2007	Telephone: 800-424-9346
Date Made Active in Reports: 04/13/2007	Last EDR Contact: 03/13/2008
Number of Days to Update: 38	Next Scheduled EDR Contact: 06/09/2008
	Data Release Frequency: Biennially

## **STATE AND LOCAL RECORDS**

### **HIST CAL-SITES:** Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005	Source: Department of Toxic Substance Control
Date Data Arrived at EDR: 08/03/2006	Telephone: 916-323-3400
Date Made Active in Reports: 08/24/2006	Last EDR Contact: 05/27/2008
Number of Days to Update: 21	Next Scheduled EDR Contact: 08/25/2008
	Data Release Frequency: No Update Planned

### **CA BOND EXP. PLAN:** Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989	Source: Department of Health Services
Date Data Arrived at EDR: 07/27/1994	Telephone: 916-255-2118
Date Made Active in Reports: 08/02/1994	Last EDR Contact: 05/31/1994
Number of Days to Update: 6	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned



# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **SCH:** School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 02/26/2008	Source: Department of Toxic Substances Control
Date Data Arrived at EDR: 02/27/2008	Telephone: 916-323-3400
Date Made Active in Reports: 03/27/2008	Last EDR Contact: 05/28/2008
Number of Days to Update: 29	Next Scheduled EDR Contact: 08/25/2008
	Data Release Frequency: Quarterly

## **TOXIC PITS:** Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995	Source: State Water Resources Control Board
Date Data Arrived at EDR: 08/30/1995	Telephone: 916-227-4364
Date Made Active in Reports: 09/26/1995	Last EDR Contact: 04/28/2008
Number of Days to Update: 27	Next Scheduled EDR Contact: 07/28/2008
	Data Release Frequency: No Update Planned

## **SWF/LF (SWIS):** Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inventory of solid waste disposal facilities or landfills. These may be active or inactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 03/10/2008	Source: Integrated Waste Management Board
Date Data Arrived at EDR: 03/12/2008	Telephone: 916-341-6320
Date Made Active in Reports: 04/14/2008	Last EDR Contact: 03/12/2008
Number of Days to Update: 33	Next Scheduled EDR Contact: 06/09/2008
	Data Release Frequency: Quarterly

## **WMUDS/SWAT:** Waste Management Unit Database

Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000	Source: State Water Resources Control Board
Date Data Arrived at EDR: 04/10/2000	Telephone: 916-227-4448
Date Made Active in Reports: 05/10/2000	Last EDR Contact: 06/02/2008
Number of Days to Update: 30	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: Quarterly

## **CA WDS:** Waste Discharge System

Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007	Source: State Water Resources Control Board
Date Data Arrived at EDR: 06/20/2007	Telephone: 916-341-5227
Date Made Active in Reports: 06/29/2007	Last EDR Contact: 03/17/2008
Number of Days to Update: 9	Next Scheduled EDR Contact: 06/16/2008
	Data Release Frequency: Quarterly

## **CORTESE:** "Cortese" Hazardous Waste & Substances Sites List

The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites). This listing is no longer updated by the state agency.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 04/01/2001  
Date Data Arrived at EDR: 05/29/2001  
Date Made Active in Reports: 07/26/2001  
Number of Days to Update: 58

Source: CAL EPA/Office of Emergency Information  
Telephone: 916-323-3400  
Last EDR Contact: 04/21/2008  
Next Scheduled EDR Contact: 07/21/2008  
Data Release Frequency: No Update Planned

## **SWRCY:** Recycler Database

A listing of recycling facilities in California.

Date of Government Version: 04/07/2008  
Date Data Arrived at EDR: 04/09/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 27

Source: Department of Conservation  
Telephone: 916-323-3836  
Last EDR Contact: 04/09/2008  
Next Scheduled EDR Contact: 07/07/2008  
Data Release Frequency: Quarterly

## **LUST REG 9:** Leaking Underground Storage Tank Report

Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001  
Date Data Arrived at EDR: 04/23/2001  
Date Made Active in Reports: 05/21/2001  
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)  
Telephone: 858-637-5595  
Last EDR Contact: 04/14/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: No Update Planned

## **LUST REG 8:** Leaking Underground Storage Tanks

California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005  
Date Data Arrived at EDR: 02/15/2005  
Date Made Active in Reports: 03/28/2005  
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)  
Telephone: 909-782-4496  
Last EDR Contact: 05/05/2008  
Next Scheduled EDR Contact: 08/04/2008  
Data Release Frequency: Varies

## **LUST REG 6V:** Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005  
Date Data Arrived at EDR: 06/07/2005  
Date Made Active in Reports: 06/29/2005  
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)  
Telephone: 760-241-7365  
Last EDR Contact: 03/31/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: No Update Planned

## **LUST REG 6L:** Leaking Underground Storage Tank Case Listing

For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003  
Date Data Arrived at EDR: 09/10/2003  
Date Made Active in Reports: 10/07/2003  
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)  
Telephone: 530-542-5572  
Last EDR Contact: 06/02/2008  
Next Scheduled EDR Contact: 09/01/2008  
Data Release Frequency: No Update Planned

## **LUST REG 5:** Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 04/01/2008  
Date Data Arrived at EDR: 04/23/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 13

Source: California Regional Water Quality Control Board Central Valley Region (5)  
Telephone: 916-464-4834  
Last EDR Contact: 04/23/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Quarterly

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **LUST REG 4:** Underground Storage Tank Leak List

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4)
Date Data Arrived at EDR: 09/07/2004	Telephone: 213-576-6710
Date Made Active in Reports: 10/12/2004	Last EDR Contact: 03/24/2008
Number of Days to Update: 35	Next Scheduled EDR Contact: 06/23/2008
	Data Release Frequency: No Update Planned

## **LUST REG 3:** Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003	Source: California Regional Water Quality Control Board Central Coast Region (3)
Date Data Arrived at EDR: 05/19/2003	Telephone: 805-542-4786
Date Made Active in Reports: 06/02/2003	Last EDR Contact: 05/12/2008
Number of Days to Update: 14	Next Scheduled EDR Contact: 08/11/2008
	Data Release Frequency: No Update Planned

## **LUST REG 2:** Fuel Leak List

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004	Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Date Data Arrived at EDR: 10/20/2004	Telephone: 510-622-2433
Date Made Active in Reports: 11/19/2004	Last EDR Contact: 04/07/2008
Number of Days to Update: 30	Next Scheduled EDR Contact: 07/07/2008
	Data Release Frequency: Quarterly

## **LUST REG 1:** Active Toxic Site Investigation

Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001	Source: California Regional Water Quality Control Board North Coast (1)
Date Data Arrived at EDR: 02/28/2001	Telephone: 707-570-3769
Date Made Active in Reports: 03/29/2001	Last EDR Contact: 05/19/2008
Number of Days to Update: 29	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: No Update Planned

## **LUST:** Geotracker's Leaking Underground Fuel Tank Report

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state. For more information on a particular leaking underground storage tank sites, please contact the appropriate regulatory agency.

Date of Government Version: 04/08/2008	Source: State Water Resources Control Board
Date Data Arrived at EDR: 04/09/2008	Telephone: see region list
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 04/09/2008
Number of Days to Update: 27	Next Scheduled EDR Contact: 07/07/2008
	Data Release Frequency: Quarterly

## **LUST REG 7:** Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004	Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Date Data Arrived at EDR: 02/26/2004	Telephone: 760-776-8943
Date Made Active in Reports: 03/24/2004	Last EDR Contact: 05/19/2008
Number of Days to Update: 27	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: No Update Planned

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994	Source: California Environmental Protection Agency
Date Data Arrived at EDR: 09/05/1995	Telephone: 916-341-5851
Date Made Active in Reports: 09/29/1995	Last EDR Contact: 12/28/1998
Number of Days to Update: 24	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

## SLIC: Statewide SLIC Cases

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/08/2008	Source: State Water Resources Control Board
Date Data Arrived at EDR: 04/09/2008	Telephone: 866-480-1028
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 01/09/2008
Number of Days to Update: 27	Next Scheduled EDR Contact: 07/07/2008
	Data Release Frequency: Varies

## SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003	Source: California Regional Water Quality Control Board, North Coast Region (1)
Date Data Arrived at EDR: 04/07/2003	Telephone: 707-576-2220
Date Made Active in Reports: 04/25/2003	Last EDR Contact: 05/19/2008
Number of Days to Update: 18	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: No Update Planned

## SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004	Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Date Data Arrived at EDR: 10/20/2004	Telephone: 510-286-0457
Date Made Active in Reports: 11/19/2004	Last EDR Contact: 04/07/2008
Number of Days to Update: 30	Next Scheduled EDR Contact: 04/07/2008
	Data Release Frequency: Quarterly

## SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006	Source: California Regional Water Quality Control Board Central Coast Region (3)
Date Data Arrived at EDR: 05/18/2006	Telephone: 805-549-3147
Date Made Active in Reports: 06/15/2006	Last EDR Contact: 05/12/2008
Number of Days to Update: 28	Next Scheduled EDR Contact: 08/11/2008
	Data Release Frequency: Semi-Annually

## SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004	Source: Region Water Quality Control Board Los Angeles Region (4)
Date Data Arrived at EDR: 11/18/2004	Telephone: 213-576-6600
Date Made Active in Reports: 01/04/2005	Last EDR Contact: 04/21/2008
Number of Days to Update: 47	Next Scheduled EDR Contact: 07/21/2008
	Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **SLIC REG 5:** Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005  
Date Data Arrived at EDR: 04/05/2005  
Date Made Active in Reports: 04/21/2005  
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)  
Telephone: 916-464-3291  
Last EDR Contact: 03/31/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Semi-Annually

## **SLIC REG 6V:** Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005  
Date Data Arrived at EDR: 05/25/2005  
Date Made Active in Reports: 06/16/2005  
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch  
Telephone: 619-241-6583  
Last EDR Contact: 03/31/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Semi-Annually

## **SLIC REG 6L:** SLIC Sites

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004  
Date Data Arrived at EDR: 09/07/2004  
Date Made Active in Reports: 10/12/2004  
Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region  
Telephone: 530-542-5574  
Last EDR Contact: 06/02/2008  
Next Scheduled EDR Contact: 09/01/2008  
Data Release Frequency: No Update Planned

## **SLIC REG 7:** SLIC List

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004  
Date Data Arrived at EDR: 11/29/2004  
Date Made Active in Reports: 01/04/2005  
Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region  
Telephone: 760-346-7491  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: No Update Planned

## **SLIC REG 8:** Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008  
Date Data Arrived at EDR: 04/03/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 11

Source: California Region Water Quality Control Board Santa Ana Region (8)  
Telephone: 951-782-3298  
Last EDR Contact: 03/31/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Semi-Annually

## **SLIC REG 9:** Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007  
Date Data Arrived at EDR: 09/11/2007  
Date Made Active in Reports: 09/28/2007  
Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)  
Telephone: 858-467-2980  
Last EDR Contact: 05/27/2008  
Next Scheduled EDR Contact: 08/25/2008  
Data Release Frequency: Annually

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## UST: Active UST Facilities

Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 04/08/2008	Source: SWRCB
Date Data Arrived at EDR: 04/09/2008	Telephone: 916-480-1028
Date Made Active in Reports: 05/01/2008	Last EDR Contact: 04/09/2008
Number of Days to Update: 22	Next Scheduled EDR Contact: 07/07/2008
	Data Release Frequency: Semi-Annually

## UST MENDOCINO: Mendocino County UST Database

A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 03/24/2008	Source: Department of Public Health
Date Data Arrived at EDR: 03/25/2008	Telephone: 707-463-4466
Date Made Active in Reports: 04/09/2008	Last EDR Contact: 03/24/2008
Number of Days to Update: 15	Next Scheduled EDR Contact: 06/23/2008
	Data Release Frequency: Varies

## HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990	Source: State Water Resources Control Board
Date Data Arrived at EDR: 01/25/1991	Telephone: 916-341-5851
Date Made Active in Reports: 02/12/1991	Last EDR Contact: 07/26/2001
Number of Days to Update: 18	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

## AST: Aboveground Petroleum Storage Tank Facilities

Registered Aboveground Storage Tanks.

Date of Government Version: 11/01/2007	Source: State Water Resources Control Board
Date Data Arrived at EDR: 11/27/2007	Telephone: 916-341-5712
Date Made Active in Reports: 02/14/2008	Last EDR Contact: 04/28/2008
Number of Days to Update: 79	Next Scheduled EDR Contact: 07/28/2008
	Data Release Frequency: Quarterly

## LIENS: Environmental Liens Listing

A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 02/05/2008	Source: Department of Toxic Substances Control
Date Data Arrived at EDR: 02/06/2008	Telephone: 916-323-3400
Date Made Active in Reports: 03/14/2008	Last EDR Contact: 05/05/2008
Number of Days to Update: 37	Next Scheduled EDR Contact: 08/04/2008
	Data Release Frequency: Varies

## SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994	Source: State Water Resources Control Board
Date Data Arrived at EDR: 07/07/2005	Telephone: N/A
Date Made Active in Reports: 08/11/2005	Last EDR Contact: 06/03/2005
Number of Days to Update: 35	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

## CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2005  
Date Data Arrived at EDR: 02/23/2007  
Date Made Active in Reports: 04/06/2007  
Number of Days to Update: 42

Source: Office of Emergency Services  
Telephone: 916-845-8400  
Last EDR Contact: 05/02/2008  
Next Scheduled EDR Contact: 05/19/2008  
Data Release Frequency: Varies

### **NOTIFY 65:** Proposition 65 Records

Proposition 65 Notification Records. NOTIFY 65 contains facility notifications about any release which could impact drinking water and thereby expose the public to a potential health risk.

Date of Government Version: 10/21/1993  
Date Data Arrived at EDR: 11/01/1993  
Date Made Active in Reports: 11/19/1993  
Number of Days to Update: 18

Source: State Water Resources Control Board  
Telephone: 916-445-3846  
Last EDR Contact: 04/14/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: No Update Planned

### **DEED:** Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 04/01/2008  
Date Data Arrived at EDR: 04/02/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 12

Source: Department of Toxic Substances Control  
Telephone: 916-323-3400  
Last EDR Contact: 04/02/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Semi-Annually

### **VCP:** Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 02/26/2008  
Date Data Arrived at EDR: 02/27/2008  
Date Made Active in Reports: 03/27/2008  
Number of Days to Update: 29

Source: Department of Toxic Substances Control  
Telephone: 916-323-3400  
Last EDR Contact: 05/28/2008  
Next Scheduled EDR Contact: 08/25/2008  
Data Release Frequency: Quarterly

### **DRYCLEANERS:** Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 07/31/2007  
Date Data Arrived at EDR: 07/31/2007  
Date Made Active in Reports: 08/09/2007  
Number of Days to Update: 9

Source: Department of Toxic Substance Control  
Telephone: 916-327-4498  
Last EDR Contact: 05/30/2008  
Next Scheduled EDR Contact: 08/11/2008  
Data Release Frequency: Annually

### **WIP:** Well Investigation Program Case List

Well Investigation Program case in the San Gabriel and San Fernando Valley area.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/26/2008  
Date Data Arrived at EDR: 04/23/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 13

Source: Los Angeles Water Quality Control Board  
Telephone: 213-576-6726  
Last EDR Contact: 04/23/2008  
Next Scheduled EDR Contact: 07/21/2008  
Data Release Frequency: Varies

## **CDL:** Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2007  
Date Data Arrived at EDR: 04/22/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 14

Source: Department of Toxic Substances Control  
Telephone: 916-255-6504  
Last EDR Contact: 04/21/2008  
Next Scheduled EDR Contact: 07/21/2008  
Data Release Frequency: Varies

## **RESPONSE:** State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 02/26/2008  
Date Data Arrived at EDR: 02/27/2008  
Date Made Active in Reports: 03/27/2008  
Number of Days to Update: 29

Source: Department of Toxic Substances Control  
Telephone: 916-323-3400  
Last EDR Contact: 05/28/2008  
Next Scheduled EDR Contact: 08/25/2008  
Data Release Frequency: Quarterly

## **HAZNET:** Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method.

Date of Government Version: 12/31/2006  
Date Data Arrived at EDR: 10/04/2007  
Date Made Active in Reports: 11/07/2007  
Number of Days to Update: 34

Source: California Environmental Protection Agency  
Telephone: 916-255-1136  
Last EDR Contact: 05/09/2008  
Next Scheduled EDR Contact: 08/04/2008  
Data Release Frequency: Annually

## **EMI:** Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2005  
Date Data Arrived at EDR: 04/17/2007  
Date Made Active in Reports: 05/10/2007  
Number of Days to Update: 23

Source: California Air Resources Board  
Telephone: 916-322-2990  
Last EDR Contact: 04/18/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: Varies

## **HAULERS:** Registered Waste Tire Haulers Listing

A listing of registered waste tire haulers.

Date of Government Version: 04/28/2008  
Date Data Arrived at EDR: 04/29/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 7

Source: Integrated Waste Management Board  
Telephone: 916-341-6422  
Last EDR Contact: 04/28/2008  
Next Scheduled EDR Contact: 06/09/2008  
Data Release Frequency: Varies

## **ENVIROSTOR:** EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifies sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.



# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/26/2008  
Date Data Arrived at EDR: 02/27/2008  
Date Made Active in Reports: 03/27/2008  
Number of Days to Update: 29

Source: Department of Toxic Substances Control  
Telephone: 916-323-3400  
Last EDR Contact: 05/28/2008  
Next Scheduled EDR Contact: 08/25/2008  
Data Release Frequency: Quarterly

## TRIBAL RECORDS

### **INDIAN RESERV:** Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005  
Date Data Arrived at EDR: 12/08/2006  
Date Made Active in Reports: 01/11/2007  
Number of Days to Update: 34

Source: USGS  
Telephone: 202-208-3710  
Last EDR Contact: 05/09/2008  
Next Scheduled EDR Contact: 08/04/2008  
Data Release Frequency: Semi-Annually

### **INDIAN ODI:** Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998  
Date Data Arrived at EDR: 12/03/2007  
Date Made Active in Reports: 01/24/2008  
Number of Days to Update: 52

Source: Environmental Protection Agency  
Telephone: 703-308-8245  
Last EDR Contact: 05/27/2008  
Next Scheduled EDR Contact: 08/25/2008  
Data Release Frequency: Varies

### **INDIAN LUST R10:** Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/21/2008  
Date Data Arrived at EDR: 02/26/2008  
Date Made Active in Reports: 03/20/2008  
Number of Days to Update: 23

Source: EPA Region 10  
Telephone: 206-553-2857  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Quarterly

### **INDIAN LUST R6:** Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 02/28/2008  
Date Data Arrived at EDR: 02/29/2008  
Date Made Active in Reports: 03/17/2008  
Number of Days to Update: 17

Source: EPA Region 6  
Telephone: 214-665-6597  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Varies

### **INDIAN LUST R9:** Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 02/25/2008  
Date Data Arrived at EDR: 02/26/2008  
Date Made Active in Reports: 03/17/2008  
Number of Days to Update: 20

Source: Environmental Protection Agency  
Telephone: 415-972-3372  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Quarterly

### **INDIAN LUST R8:** Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 02/20/2008  
Date Data Arrived at EDR: 03/04/2008  
Date Made Active in Reports: 03/17/2008  
Number of Days to Update: 13

Source: EPA Region 8  
Telephone: 303-312-6271  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Quarterly

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **INDIAN LUST R7:** Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/17/2008	Source: EPA Region 7
Date Data Arrived at EDR: 03/27/2008	Telephone: 913-551-7003
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 40	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Varies

## **INDIAN LUST R4:** Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 03/17/2008	Source: EPA Region 4
Date Data Arrived at EDR: 03/27/2008	Telephone: 404-562-8677
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 40	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Semi-Annually

## **INDIAN LUST R1:** Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 03/12/2008	Source: EPA Region 1
Date Data Arrived at EDR: 03/14/2008	Telephone: 617-918-1313
Date Made Active in Reports: 03/20/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 6	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Varies

## **INDIAN UST R1:** Underground Storage Tanks on Indian Land

A listing of underground storage tank locations on Indian Land.

Date of Government Version: 03/12/2008	Source: EPA, Region 1
Date Data Arrived at EDR: 03/14/2008	Telephone: 617-918-1313
Date Made Active in Reports: 03/20/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 6	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Varies

## **INDIAN UST R4:** Underground Storage Tanks on Indian Land

No description is available for this data

Date of Government Version: 03/17/2008	Source: EPA Region 4
Date Data Arrived at EDR: 03/27/2008	Telephone: 404-562-9424
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 40	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Semi-Annually

## **INDIAN UST R10:** Underground Storage Tanks on Indian Land

No description is available for this data

Date of Government Version: 02/21/2008	Source: EPA Region 10
Date Data Arrived at EDR: 02/26/2008	Telephone: 206-553-2857
Date Made Active in Reports: 03/20/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 23	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Quarterly

## **INDIAN UST R8:** Underground Storage Tanks on Indian Land

No description is available for this data

Date of Government Version: 02/20/2008	Source: EPA Region 8
Date Data Arrived at EDR: 03/04/2008	Telephone: 303-312-6137
Date Made Active in Reports: 03/17/2008	Last EDR Contact: 05/19/2008
Number of Days to Update: 13	Next Scheduled EDR Contact: 08/18/2008
	Data Release Frequency: Quarterly

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **INDIAN UST R6:** Underground Storage Tanks on Indian Land

No description is available for this data

Date of Government Version: 02/28/2008  
Date Data Arrived at EDR: 02/29/2008  
Date Made Active in Reports: 03/17/2008  
Number of Days to Update: 17

Source: EPA Region 6  
Telephone: 214-665-7591  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Semi-Annually

## **INDIAN UST R5:** Underground Storage Tanks on Indian Land

No description is available for this data

Date of Government Version: 12/21/2007  
Date Data Arrived at EDR: 12/21/2007  
Date Made Active in Reports: 01/24/2008  
Number of Days to Update: 34

Source: EPA Region 5  
Telephone: 312-886-6136  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Varies

## **INDIAN UST R9:** Underground Storage Tanks on Indian Land

No description is available for this data

Date of Government Version: 02/25/2008  
Date Data Arrived at EDR: 02/26/2008  
Date Made Active in Reports: 03/20/2008  
Number of Days to Update: 23

Source: EPA Region 9  
Telephone: 415-972-3368  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Quarterly

## **INDIAN UST R7:** Underground Storage Tanks on Indian Land

No description is available for this data

Date of Government Version: 06/01/2007  
Date Data Arrived at EDR: 06/14/2007  
Date Made Active in Reports: 07/05/2007  
Number of Days to Update: 21

Source: EPA Region 7  
Telephone: 913-551-7003  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Varies

## **EDR PROPRIETARY RECORDS**

### **Manufactured Gas Plants:** EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A  
Date Data Arrived at EDR: N/A  
Date Made Active in Reports: N/A  
Number of Days to Update: N/A

Source: EDR, Inc.  
Telephone: N/A  
Last EDR Contact: N/A  
Next Scheduled EDR Contact: N/A  
Data Release Frequency: No Update Planned

## **COUNTY RECORDS**

### **ALAMEDA COUNTY:**

#### **Contaminated Sites**

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 01/28/2008  
Date Data Arrived at EDR: 01/29/2008  
Date Made Active in Reports: 02/14/2008  
Number of Days to Update: 16

Source: Alameda County Environmental Health Services  
Telephone: 510-567-6700  
Last EDR Contact: 05/05/2008  
Next Scheduled EDR Contact: 07/21/2008  
Data Release Frequency: Semi-Annually

## Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 01/28/2008  
Date Data Arrived at EDR: 01/29/2008  
Date Made Active in Reports: 02/08/2008  
Number of Days to Update: 10

Source: Alameda County Environmental Health Services  
Telephone: 510-567-6700  
Last EDR Contact: 05/05/2008  
Next Scheduled EDR Contact: 07/21/2008  
Data Release Frequency: Semi-Annually

## CONTRA COSTA COUNTY:

### Site List

List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 03/07/2008  
Date Data Arrived at EDR: 03/11/2008  
Date Made Active in Reports: 03/27/2008  
Number of Days to Update: 16

Source: Contra Costa Health Services Department  
Telephone: 925-646-2286  
Last EDR Contact: 05/27/2008  
Next Scheduled EDR Contact: 08/25/2008  
Data Release Frequency: Semi-Annually

## FRESNO COUNTY:

### CUPA Resources List

Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 03/31/2008  
Date Data Arrived at EDR: 04/18/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 18

Source: Dept. of Community Health  
Telephone: 559-445-3271  
Last EDR Contact: 04/18/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: Semi-Annually

## KERN COUNTY:

### Underground Storage Tank Sites & Tank Listing

Kern County Sites and Tanks Listing.

Date of Government Version: 04/01/2008  
Date Data Arrived at EDR: 04/18/2008  
Date Made Active in Reports: 05/01/2008  
Number of Days to Update: 13

Source: Kern County Environment Health Services Department  
Telephone: 661-862-8700  
Last EDR Contact: 06/02/2008  
Next Scheduled EDR Contact: 09/01/2008  
Data Release Frequency: Quarterly

## LOS ANGELES COUNTY:

### San Gabriel Valley Areas of Concern

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/1998  
Date Data Arrived at EDR: 07/07/1999  
Date Made Active in Reports: N/A  
Number of Days to Update: 0

Source: EPA Region 9  
Telephone: 415-972-3178  
Last EDR Contact: 04/14/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: No Update Planned

## HMS: Street Number List

Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 02/28/2008  
Date Data Arrived at EDR: 04/16/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 20

Source: Department of Public Works  
Telephone: 626-458-3517  
Last EDR Contact: 05/12/2008  
Next Scheduled EDR Contact: 08/11/2008  
Data Release Frequency: Semi-Annually

## List of Solid Waste Facilities

Solid Waste Facilities in Los Angeles County.

Date of Government Version: 02/12/2008  
Date Data Arrived at EDR: 02/21/2008  
Date Made Active in Reports: 03/27/2008  
Number of Days to Update: 35

Source: La County Department of Public Works  
Telephone: 818-458-5185  
Last EDR Contact: 05/14/2008  
Next Scheduled EDR Contact: 08/11/2008  
Data Release Frequency: Varies

## City of Los Angeles Landfills

Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 03/01/2008  
Date Data Arrived at EDR: 03/20/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 25

Source: Engineering & Construction Division  
Telephone: 213-473-7869  
Last EDR Contact: 03/12/2008  
Next Scheduled EDR Contact: 06/09/2008  
Data Release Frequency: Varies

## Site Mitigation List

Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 02/14/2008  
Date Data Arrived at EDR: 04/10/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 26

Source: Community Health Services  
Telephone: 323-890-7806  
Last EDR Contact: 05/12/2008  
Next Scheduled EDR Contact: 08/11/2008  
Data Release Frequency: Annually

## City of El Segundo Underground Storage Tank

Underground storage tank sites located in El Segundo city.

Date of Government Version: 02/11/2008  
Date Data Arrived at EDR: 02/21/2008  
Date Made Active in Reports: 03/14/2008  
Number of Days to Update: 22

Source: City of El Segundo Fire Department  
Telephone: 310-524-2236  
Last EDR Contact: 05/27/2008  
Next Scheduled EDR Contact: 08/11/2008  
Data Release Frequency: Semi-Annually

## City of Long Beach Underground Storage Tank

Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 03/28/2003  
Date Data Arrived at EDR: 10/23/2003  
Date Made Active in Reports: 11/26/2003  
Number of Days to Update: 34

Source: City of Long Beach Fire Department  
Telephone: 562-570-2563  
Last EDR Contact: 05/21/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Annually

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## City of Torrance Underground Storage Tank

Underground storage tank sites located in the city of Torrance.

Date of Government Version: 02/26/2008  
Date Data Arrived at EDR: 02/27/2008  
Date Made Active in Reports: 03/14/2008  
Number of Days to Update: 16

Source: City of Torrance Fire Department  
Telephone: 310-618-2973  
Last EDR Contact: 05/27/2008  
Next Scheduled EDR Contact: 08/11/2008  
Data Release Frequency: Semi-Annually

## MARIN COUNTY:

### Underground Storage Tank Sites

Currently permitted USTs in Marin County.

Date of Government Version: 02/04/2008  
Date Data Arrived at EDR: 02/21/2008  
Date Made Active in Reports: 03/14/2008  
Number of Days to Update: 22

Source: Public Works Department Waste Management  
Telephone: 415-499-6647  
Last EDR Contact: 04/28/2008  
Next Scheduled EDR Contact: 07/28/2008  
Data Release Frequency: Semi-Annually

## NAPA COUNTY:

### Sites With Reported Contamination

A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 04/24/2008  
Date Data Arrived at EDR: 04/25/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 11

Source: Napa County Department of Environmental Management  
Telephone: 707-253-4269  
Last EDR Contact: 04/07/2008  
Next Scheduled EDR Contact: 06/23/2008  
Data Release Frequency: Semi-Annually

### Closed and Operating Underground Storage Tank Sites

Underground storage tank sites located in Napa county.

Date of Government Version: 01/15/2008  
Date Data Arrived at EDR: 01/16/2008  
Date Made Active in Reports: 02/08/2008  
Number of Days to Update: 23

Source: Napa County Department of Environmental Management  
Telephone: 707-253-4269  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 06/23/2008  
Data Release Frequency: Annually

## ORANGE COUNTY:

### List of Industrial Site Cleanups

Petroleum and non-petroleum spills.

Date of Government Version: 03/03/2008  
Date Data Arrived at EDR: 03/20/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 25

Source: Health Care Agency  
Telephone: 714-834-3446  
Last EDR Contact: 03/06/2008  
Next Scheduled EDR Contact: 06/02/2008  
Data Release Frequency: Annually

### List of Underground Storage Tank Cleanups

Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 03/03/2008  
Date Data Arrived at EDR: 03/25/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 20

Source: Health Care Agency  
Telephone: 714-834-3446  
Last EDR Contact: 03/06/2008  
Next Scheduled EDR Contact: 06/02/2008  
Data Release Frequency: Quarterly

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## List of Underground Storage Tank Facilities

Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 03/03/2008	Source: Health Care Agency
Date Data Arrived at EDR: 03/18/2008	Telephone: 714-834-3446
Date Made Active in Reports: 04/09/2008	Last EDR Contact: 03/06/2008
Number of Days to Update: 22	Next Scheduled EDR Contact: 06/02/2008
	Data Release Frequency: Quarterly

## PLACER COUNTY:

### Master List of Facilities

List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 07/23/2007	Source: Placer County Health and Human Services
Date Data Arrived at EDR: 07/23/2007	Telephone: 530-889-7312
Date Made Active in Reports: 08/09/2007	Last EDR Contact: 03/17/2008
Number of Days to Update: 17	Next Scheduled EDR Contact: 06/16/2008
	Data Release Frequency: Semi-Annually

## RIVERSIDE COUNTY:

### Listing of Underground Tank Cleanup Sites

Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 08/06/2007	Source: Department of Public Health
Date Data Arrived at EDR: 08/07/2007	Telephone: 951-358-5055
Date Made Active in Reports: 09/26/2007	Last EDR Contact: 04/14/2008
Number of Days to Update: 50	Next Scheduled EDR Contact: 07/14/2008
	Data Release Frequency: Quarterly

### Underground Storage Tank Tank List

Underground storage tank sites located in Riverside county.

Date of Government Version: 08/06/2007	Source: Health Services Agency
Date Data Arrived at EDR: 08/07/2007	Telephone: 951-358-5055
Date Made Active in Reports: 09/24/2007	Last EDR Contact: 04/14/2008
Number of Days to Update: 48	Next Scheduled EDR Contact: 07/14/2008
	Data Release Frequency: Quarterly

## SACRAMENTO COUNTY:

### Contaminated Sites

List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 02/11/2008	Source: Sacramento County Environmental Management
Date Data Arrived at EDR: 02/27/2008	Telephone: 916-875-8406
Date Made Active in Reports: 03/14/2008	Last EDR Contact: 05/02/2008
Number of Days to Update: 16	Next Scheduled EDR Contact: 07/28/2008
	Data Release Frequency: Quarterly

### ML - Regulatory Compliance Master List

Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 02/11/2008	Source: Sacramento County Environmental Management
Date Data Arrived at EDR: 02/27/2008	Telephone: 916-875-8406
Date Made Active in Reports: 03/14/2008	Last EDR Contact: 05/02/2008
Number of Days to Update: 16	Next Scheduled EDR Contact: 07/28/2008
	Data Release Frequency: Quarterly

## SAN BERNARDINO COUNTY:

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## Hazardous Material Permits

This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 03/18/2008  
Date Data Arrived at EDR: 03/19/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 26

Source: San Bernardino County Fire Department Hazardous Materials Division  
Telephone: 909-387-3041  
Last EDR Contact: 06/02/2008  
Next Scheduled EDR Contact: 09/01/2008  
Data Release Frequency: Quarterly

## SAN DIEGO COUNTY:

### Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 05/16/2005  
Date Data Arrived at EDR: 05/18/2005  
Date Made Active in Reports: 06/16/2005  
Number of Days to Update: 29

Source: Hazardous Materials Management Division  
Telephone: 619-338-2268  
Last EDR Contact: 04/02/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Quarterly

### Solid Waste Facilities

San Diego County Solid Waste Facilities.

Date of Government Version: 08/01/2007  
Date Data Arrived at EDR: 02/05/2008  
Date Made Active in Reports: 02/14/2008  
Number of Days to Update: 9

Source: Department of Health Services  
Telephone: 619-338-2209  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Varies

### Environmental Case Listing

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 11/28/2007  
Date Data Arrived at EDR: 03/13/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 32

Source: San Diego County Department of Environmental Health  
Telephone: 619-338-2371  
Last EDR Contact: 04/23/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Varies

## SAN FRANCISCO COUNTY:

### Local Oversight Facilities

A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 03/03/2008  
Date Data Arrived at EDR: 03/04/2008  
Date Made Active in Reports: 03/14/2008  
Number of Days to Update: 10

Source: Department Of Public Health San Francisco County  
Telephone: 415-252-3920  
Last EDR Contact: 06/02/2008  
Next Scheduled EDR Contact: 09/01/2008  
Data Release Frequency: Quarterly



# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## Underground Storage Tank Information

Underground storage tank sites located in San Francisco county.

Date of Government Version: 03/03/2008	Source: Department of Public Health
Date Data Arrived at EDR: 03/04/2008	Telephone: 415-252-3920
Date Made Active in Reports: 03/14/2008	Last EDR Contact: 06/02/2008
Number of Days to Update: 10	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: Quarterly

## SAN JOAQUIN COUNTY:

### San Joaquin Co. UST

A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 02/01/2008	Source: Environmental Health Department
Date Data Arrived at EDR: 02/26/2008	Telephone: N/A
Date Made Active in Reports: 03/14/2008	Last EDR Contact: 04/14/2008
Number of Days to Update: 17	Next Scheduled EDR Contact: 07/14/2008
	Data Release Frequency: Semi-Annually

## SAN MATEO COUNTY:

### Business Inventory

List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 01/31/2008	Source: San Mateo County Environmental Health Services Division
Date Data Arrived at EDR: 02/01/2008	Telephone: 650-363-1921
Date Made Active in Reports: 02/14/2008	Last EDR Contact: 04/07/2008
Number of Days to Update: 13	Next Scheduled EDR Contact: 07/07/2008
	Data Release Frequency: Annually

### Fuel Leak List

A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 04/10/2008	Source: San Mateo County Environmental Health Services Division
Date Data Arrived at EDR: 04/11/2008	Telephone: 650-363-1921
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 04/07/2008
Number of Days to Update: 25	Next Scheduled EDR Contact: 07/07/2008
	Data Release Frequency: Semi-Annually

## SANTA CLARA COUNTY:

### HIST LUST - Fuel Leak Site Activity Report

A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005	Source: Santa Clara Valley Water District
Date Data Arrived at EDR: 03/30/2005	Telephone: 408-265-2600
Date Made Active in Reports: 04/21/2005	Last EDR Contact: 03/24/2008
Number of Days to Update: 22	Next Scheduled EDR Contact: 06/23/2008
	Data Release Frequency: No Update Planned

### LOP Listing

A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 04/28/2008	Source: Department of Environmental Health
Date Data Arrived at EDR: 04/29/2008	Telephone: 408-918-3417
Date Made Active in Reports: 05/06/2008	Last EDR Contact: 04/28/2008
Number of Days to Update: 7	Next Scheduled EDR Contact: 06/23/2008
	Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## Hazardous Material Facilities

Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 03/04/2008  
Date Data Arrived at EDR: 03/04/2008  
Date Made Active in Reports: 03/14/2008  
Number of Days to Update: 10

Source: City of San Jose Fire Department  
Telephone: 408-277-4659  
Last EDR Contact: 06/02/2008  
Next Scheduled EDR Contact: 09/01/2008  
Data Release Frequency: Annually

## SOLANO COUNTY:

### Leaking Underground Storage Tanks

A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 04/04/2008  
Date Data Arrived at EDR: 04/22/2008  
Date Made Active in Reports: 05/06/2008  
Number of Days to Update: 14

Source: Solano County Department of Environmental Management  
Telephone: 707-784-6770  
Last EDR Contact: 03/24/2008  
Next Scheduled EDR Contact: 06/23/2008  
Data Release Frequency: Quarterly

### Underground Storage Tanks

Underground storage tank sites located in Solano county.

Date of Government Version: 04/04/2008  
Date Data Arrived at EDR: 04/22/2008  
Date Made Active in Reports: 05/01/2008  
Number of Days to Update: 9

Source: Solano County Department of Environmental Management  
Telephone: 707-784-6770  
Last EDR Contact: 03/24/2008  
Next Scheduled EDR Contact: 06/23/2008  
Data Release Frequency: Quarterly

## SONOMA COUNTY:

### Leaking Underground Storage Tank Sites

A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 01/22/2008  
Date Data Arrived at EDR: 01/22/2008  
Date Made Active in Reports: 02/14/2008  
Number of Days to Update: 23

Source: Department of Health Services  
Telephone: 707-565-6565  
Last EDR Contact: 04/21/2008  
Next Scheduled EDR Contact: 07/21/2008  
Data Release Frequency: Quarterly

## SUTTER COUNTY:

### Underground Storage Tanks

Underground storage tank sites located in Sutter county.

Date of Government Version: 05/04/2007  
Date Data Arrived at EDR: 05/04/2007  
Date Made Active in Reports: 05/24/2007  
Number of Days to Update: 20

Source: Sutter County Department of Agriculture  
Telephone: 530-822-7500  
Last EDR Contact: 03/31/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Semi-Annually

## VENTURA COUNTY:

### Business Plan, Hazardous Waste Producers, and Operating Underground Tanks

The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/27/2008  
Date Data Arrived at EDR: 03/25/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 20

Source: Ventura County Environmental Health Division  
Telephone: 805-654-2813  
Last EDR Contact: 03/12/2008  
Next Scheduled EDR Contact: 06/09/2008  
Data Release Frequency: Quarterly

## Inventory of Illegal Abandoned and Inactive Sites

Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 08/01/2007  
Date Data Arrived at EDR: 08/29/2007  
Date Made Active in Reports: 09/26/2007  
Number of Days to Update: 28

Source: Environmental Health Division  
Telephone: 805-654-2813  
Last EDR Contact: 05/19/2008  
Next Scheduled EDR Contact: 08/18/2008  
Data Release Frequency: Annually

## Listing of Underground Tank Cleanup Sites

Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 02/27/2008  
Date Data Arrived at EDR: 03/25/2008  
Date Made Active in Reports: 04/14/2008  
Number of Days to Update: 20

Source: Environmental Health Division  
Telephone: 805-654-2813  
Last EDR Contact: 03/12/2008  
Next Scheduled EDR Contact: 06/09/2008  
Data Release Frequency: Quarterly

## Underground Tank Closed Sites List

Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 03/26/2008  
Date Data Arrived at EDR: 04/09/2008  
Date Made Active in Reports: 05/01/2008  
Number of Days to Update: 22

Source: Environmental Health Division  
Telephone: 805-654-2813  
Last EDR Contact: 04/09/2008  
Next Scheduled EDR Contact: 07/07/2008  
Data Release Frequency: Quarterly

## YOLO COUNTY:

### Underground Storage Tank Comprehensive Facility Report

Underground storage tank sites located in Yolo county.

Date of Government Version: 01/29/2008  
Date Data Arrived at EDR: 02/20/2008  
Date Made Active in Reports: 03/14/2008  
Number of Days to Update: 23

Source: Yolo County Department of Health  
Telephone: 530-666-8646  
Last EDR Contact: 05/12/2008  
Next Scheduled EDR Contact: 07/14/2008  
Data Release Frequency: Annually

## OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

### CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2005  
Date Data Arrived at EDR: 06/15/2007  
Date Made Active in Reports: 08/20/2007  
Number of Days to Update: 66

Source: Department of Environmental Protection  
Telephone: 860-424-3375  
Last EDR Contact: 03/14/2008  
Next Scheduled EDR Contact: 06/09/2008  
Data Release Frequency: Annually

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **NJ MANIFEST:** Manifest Information

Hazardous waste manifest information.

Date of Government Version: 09/30/2007  
Date Data Arrived at EDR: 12/04/2007  
Date Made Active in Reports: 12/31/2007  
Number of Days to Update: 27

Source: Department of Environmental Protection  
Telephone: N/A  
Last EDR Contact: 04/03/2008  
Next Scheduled EDR Contact: 06/30/2008  
Data Release Frequency: Annually

## **NY MANIFEST:** Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 02/15/2008  
Date Data Arrived at EDR: 02/28/2008  
Date Made Active in Reports: 04/09/2008  
Number of Days to Update: 41

Source: Department of Environmental Conservation  
Telephone: 518-402-8651  
Last EDR Contact: 05/29/2008  
Next Scheduled EDR Contact: 08/25/2008  
Data Release Frequency: Annually

## **PA MANIFEST:** Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2006  
Date Data Arrived at EDR: 12/21/2007  
Date Made Active in Reports: 01/10/2008  
Number of Days to Update: 20

Source: Department of Environmental Protection  
Telephone: N/A  
Last EDR Contact: 03/10/2008  
Next Scheduled EDR Contact: 06/09/2008  
Data Release Frequency: Annually

## **RI MANIFEST:** Manifest information

Hazardous waste manifest information

Date of Government Version: 10/01/2007  
Date Data Arrived at EDR: 11/09/2007  
Date Made Active in Reports: 01/15/2008  
Number of Days to Update: 67

Source: Department of Environmental Management  
Telephone: 401-222-2797  
Last EDR Contact: 03/17/2008  
Next Scheduled EDR Contact: 06/16/2008  
Data Release Frequency: Annually

## **WI MANIFEST:** Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2006  
Date Data Arrived at EDR: 04/27/2007  
Date Made Active in Reports: 06/08/2007  
Number of Days to Update: 42

Source: Department of Natural Resources  
Telephone: N/A  
Last EDR Contact: 04/07/2008  
Next Scheduled EDR Contact: 07/07/2008  
Data Release Frequency: Annually

**Sensitive Receptors:** There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

### **AHA Hospitals:**

Source: American Hospital Association, Inc.  
Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

### **Medical Centers: Provider of Services Listing**

Source: Centers for Medicare & Medicaid Services  
Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

### **Nursing Homes**

Source: National Institutes of Health  
Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## **Public Schools**

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

## **Private Schools**

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

## **Daycare Centers: Licensed Facilities**

Source: Department of Social Services

Telephone: 916-657-4041

**Flood Zone Data:** This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

**NWI:** National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

## **STREET AND ADDRESS INFORMATION**

© 2008 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.