

Transportation & Storm Water Department
2014 Storm Water Division Habitat Impacts and Mitigation
ATTACHMENT 7

Habitat Type	Position	Tier	Acres Impacted in MHPA	Acres Impacted out of MHPA	Location/Project	Mitigation
Freshwater Marsh (on concrete channel)	Wetland	N/A		0.18	Soledad/Flintkote Channel Maintenance - Reach 7	1.91 acres of wetland creation at
Freshwater Marsh (on concrete channel)	Wetland	N/A		0.63	Soledad/Flintkote Channel Maintenance - Reach 3	El Cuervo Del Sur Mitigation Site;
Developed, Unvegetated Concrete Lined Channel		N/A		2.65	Soledad/Flintkote Channel Maintenance - Reach 3	5.53 acres of wetlands
Freshwater Marsh (on concrete channel)	Wetland	N/A	0.004		San Carlos Channel (Map 54) Emergency Maintenance	To Be Determined
Disturbed Freshwater Marsh (on concrete channel)	Wetland	N/A	0.071		Reservoir Drive Channel Emergency Maintenance	To Be Determined
Disturbed Wetland	Wetland	N/A	0.012		Reservoir Drive Channel Emergency Maintenance	To Be Determined
Developed, Unvegetated Concrete Lined Channel		N/A	0.065		Reservoir Drive Channel Emergency Maintenance	To Be Determined
Developed, Unvegetated Concrete Lined Channel		N/A	1.3		Smythe Channel (Map 129) Emergency Maintenance	N/A
Wetlands/Non-Wetland Waters subtotal			1.45			
Total			1.45			

Note: All impact acreages identified are projections based on pre-project biological assessment. All impacts are due to maintenance of existing flood control channels.