

## Table of Contents

Summary .....		1
Chapter 1:	Introduction .....	1-1
	1.1 Requirements of the Watershed Sanitary Survey .....	1-1
	1.2 Objectives of the Watershed Sanitary Survey .....	1-1
	1.3 Conduct of the Watershed Sanitary Survey .....	1-1
	1.4 Basic Water Rights.....	1-2
	1.5 Historical Background .....	1-7
	1.6 Water Operations Plan.....	1-11
Chapter 2:	Description of the Source Water System .....	2-1
	2.1 Water Sources .....	2-1
	Imported Water .....	2-3
	Local Runoff .....	2-4
	2.2 Source Water Reservoirs .....	2-7
	San Diego River System .....	2-11
	Otay-Cottonwood System .....	2-16
	Miramar System .....	2-19
	Hodges System.....	2-20
	2.3 Emergency Plans.....	2-22
Chapter 3:	Conditions within the Local Source Water System .....	3-1
	3.1 Erosion.....	3-1
	3.2 Geology.....	3-5
	Geology within the Local Source Water System .....	3-7
	Soils and Slope .....	3-8
	Geologic Hazards and Contaminants.....	3-9
	3.3 Biology .....	3-14
	Vegetation.....	3-14
	Wildlife .....	3-20
	Land Ownership and Population .....	3-20
	Aquatic Invasive Species .....	3-23
	Biologic Hazards and Contaminants .....	3-26
Chapter 4:	Potential Contaminant Sources within the Local Source Water System .....	4-1
	4.1 Point Source .....	4-4
	Hazardous Material and Waste Sites .....	4-7
	(Concentrated) Animal Feeding Operations.....	4-8

	Mines .....	4-12
	Wastewater Treatment Facilities .....	4-14
	Sanitary Sewer Overflows (SSO's) .....	4-20
4.2	Nonpoint Source .....	4-23
	Septic Systems .....	4-24
	Agriculture .....	4-29
	Grazing .....	4-32
	Recreation.....	4-34
	Fires .....	4-35
Chapter 5:	Water Quality Assessment.....	5-1
5.1	Summary of Local Source Water Monitoring Program .....	5-1
5.2	San Diego River System Water Quality Review .....	5-2
	Source Water Review .....	5-3
	Alvarado WTP Influent /Effluent Review .....	5-12
5.3	Otay-Cottonwood System Water Quality Review .....	5-20
	Source Water Review .....	5-20
	Otay WTP Influent /Effluent Review .....	5-27
5.4	Miramar System Water Quality Review.....	5-35
	Source Water Review .....	5-36
	Miramar WTP Influent /Effluent Review .....	5-40
5.5	Hodges System Water Quality Review .....	5-49
	Source Water Review .....	5-49
Chapter 6:	Conclusions and Recommendations .....	6-1
6.1	Conclusions .....	6-1
	Conditions within the Local Source Water System.....	6-1
	Potential Contaminant Sources within the Local Source Water System.....	6-2
	Assessment of Source Waters.....	6-2
	Assessment of Regulatory Compliance .....	6-4
6.2	Watershed Management and Control Practices.....	6-5
6.3	Recommendations .....	6-6
Appendix 1:	Soil Categories within Local Source Water System Boundaries .....	A1-1
Appendix 2:	Vegetation within Local Source Water System Boundaries .....	A2-1
Appendix 3:	Wildlife within Local Source Water System Boundaries.....	A3-1
Appendix 4:	City of San Diego Dreissena Mussel Annual 2009 Report.....	A4-1
Appendix 5:	Water Quality Data .....	A5-1
Appendix 6:	References .....	A6-1