JAMES NAUGHTON JR., MAI

REAL ESTATE APPRAISALS & CONSULTATION

September 29, 2022
Ref. No. 22-009

Jason Shepard
Director of Project Management
ColRich Communities
444 West Beech St. Suite 300
San Diego, CA, 92101

RE: **ROAD WIDENING OFFSITES – EPOCA PROJECT**
Britannia Innovation Center LLC Property – 5761 Airway Road, San Diego 92154
Joseph Paez, Jr. Property – Cactus Road, San Diego 92154
Crown Enterprises Inc. Property – San Diego, CA 92154

Dear Mr. Shepard:

Inspections, investigations and analyses have been conducted that have been of assistance in forming an opinion of value and to serve as a basis for acquisition of property rights that are required for the Epoca Project (previous Lumina Tentative Map Project) for street widenings. The proposed acquisitions for the street widening will be in the form of Public Street Easement. There are no separate easements required for drainage or slope areas but construction easements that go beyond the new right of way limits are needed, and these will be in an easement format as Temporary Construction Easements (TCEs).

The properties are all within the Otay Mesa Community Plan area of the City of San Diego. There are three ownerships, and the properties are currently raw, vacant land. An appraisal has been completed, the results of which are presented in the following report consistent with USPAP requirements.

The appraisal is based on land value and site improvements only. The areas proposed for acquisition are for street widenings that would be a required dedication for development in the discretionary approval process, so the values estimated rely on an alternate non-development, "non-triggering," highest and best uses that would not require dedication, generally open space use. These values are applied to the "Larger Parcel" as well as the portions to be acquired.

Subject to the attached assumptions and limiting conditions, the appraiser has formed an opinion of Fair Market Value for Compensation as of the specified date of value, August 21, 2022. The following report identifies, describes and analyzes the subject property and pertinent market data, from which a reasoned conclusion to value has been made possible. The appraisal contains three sections, including BRITANNIA INNOVATION CENTER LLC PROPERTY, JOSEPH PAEZ, JR. PROPERTY and CROWN ENTERPRISES INC. PROPERTY. The details of each property and the estimated values are included in the individual property owner section of the report.

Respectfully submitted,

James Naughton, Jr., MAI
State Certified General Real Estate Appraiser
Certificate #AG006748

14272 HALF MOON BAY DRIVE, DEL MAR, CA 92014
TELEPHONE: 858/481-2123 CELL: 619/980-3742
E-MAIL: *bznaughton@aol.com*

DRAFT

EXECUTIVE SUMMARY

IDENTIFICATION	A. Britannia Innovation Center LLC – Airway Road, San Diego 92154 B: Joseph Paez, Jr. – Cactus Road, San Diego 92154 C: Crown Enterprises Inc. – San Diego, CA 92154
CURRENT USE	A, B, C - Vacant land
ASSESSOR'S PARCEL NOS.	A. 646-100-74 B. 646-100-77 C. 646-110-19
OWNERS OF RECORD	A. Britannia Innovation Center LLC; B. Joseph Paez, Jr.; C. Crown Enterprises Inc.
DATE OF VALUE	August 21, 2022
USE/USER OF APPRAISAL	The appraisal is for use by the client ColRich Communities to obtain right of way for street widening from three property owners for their Epoca (Lumina) Project including portions along Airway Road, Britannia Boulevard and Cactus Road. The appraisal will estimate Fair Market of Public Street Easements and Temporary Construction Easements (TCE) for a 12-month term. There are no other Intended Users known.
SITE DATA	A. Britannia Innovation Center Property – Vacant land proposed for truck/trailer storage use and park; 37.9 acres; Zoned IBT-1-1. General Plan Land Use Designation is Business Park and Park within Central District of the Otay Mesa Community Plan. B. Joseph Paez, Jr. Property - Vacant land proposed for multi-family and mixed use; 39.62 acres; Zoned AR-1-1, CC-3-6, RM-2-5 and RM-3-7. General Plan Land Use Designation is MH Mixed Use and MH Multi-Family within Central District of the Otay Mesa Community Plan. C. Crown Enterprises Inc. Property - Vacant industrial land; 19.70 acres; Zoned IBT-1-1. General Plan Land Use Designation is Business and International Trade within South District of the Otay Mesa Community Plan. The Central District is generally bounded by Spring Canyon to the west, Siempre Viva Road, Britannia Boulevard, and Airway Road to the south, and the SR-905 to the east and north. The Spring Canyon system is home to many protected sensitive biological resources and habitat areas. The district includes Airway Road which is the spine of the community and is Otay Mesa's primary transit corridor. The District extends from Heritage Road to Harvest Road and is in between the Airport District and the industrial South District. The Central District includes the Central Village, the Grand Park, and employment opportunities that are further defined in the Urban Design Element. The Central District envisions a village center at the western end of the mesa with employment,

DRAFT

educational, and recreation opportunities sited along the transit corridor.

The South District is generally bounded by Wruck Canyon to the west, the International border to the south, the boundary with the County to the east, and Airway Road to the north. Open space canyon lands and wetlands with sensitive biological resources and habitat areas, large lot heavy commercial, open space and industrial uses characterize the land uses, with much of the developed land occupied by warehousing, distribution, truck depots, and customs brokerages to support the international logistics industry. The South District includes the international Port of Entry, and the uses are intended to support the international business and trade uses that are necessary for the movement of goods across the border. The west portion of the South District is designated for heavy industrial uses, such as automobile recycling, truck depots that rely upon outdoor storage, and other uses which can tolerate the truck traffic and noise generated in this area. The South District's proximity to the International border and adjacency to the Rodriguez International Airport provides an opportunity to create a cross border airport facility and associated uses south of Siempre Viva Road and in close proximity to the border

The subject properties are along both sides of Airway Road, east side of Cactus Road and the west side of Britannia Road. Airway Road and Britannia Boulevard are both shown on the circulation element in this location as a 6-lane Major Arterials and Cactus Road is shown as a 4-lane Major Arterial, however current conditions have Airway Road as 2 lanes transitioning to 3 lanes, Britannia as 3 lanes and Cactus Road as 2 lanes. All of the frontages are only partially improved (paving) and would require dedication and road improvements if the property is developed. The current acquisitions and improvements are a phased improvement, and the ultimate road width and improvements are not being finished at this time. Specific road requirements would be identified upon plan submission for future development.

The subject properties include three undeveloped parcels. Two of the parcels have development proposals in progress. Future development would require widening and street improvements of the adjoining street for development approvals.

The specific environmental condition of the properties is not known but will have development controls for discretionary approvals.

HIGHEST AND BEST USE

The valuation of the properties was guided by uses that would not trigger "required dedication." Since Airway Road, Britannia Road and Cactus Road are circulation element roads, development of the adjoining properties would require dedication of the right of way as well as construction of the road improvements.

The most reasonable non-triggering uses appear to be open space types of use including mitigation, which would include marketing recognized environmental sensitivity for potential off-site mitigation to private

DRAFT

developers and/or governmental agencies.

SIGNIFICANT ASSUMPTIONS

The appraisal assumes that sites have no hazardous waste conditions.

A non-development alternate highest and best use that would not trigger "Required Dedication" has been used.

VALUES

The appraisal contains three sections, including BRITANNIA INNOVATION CENTER LLC PROPERTY, JOSEPH PAEZ, JR. PROPERTY and CROWN ENTERPRISES INC. PROPERTY. The details of each property and the estimated values are included in the individual property owner section of the report.

DRAFT

VIEW OF SUBJECT SITES




1 5761 Airway Rd
San Diego, CA 92154
APN: 646-100-74-00 **Owner:** Britannia Innovation Center LLC

2 Cactus Rd
San Diego, CA 92154
APN: 646-100-77-00 **Owner:** Paez Joseph Jr

3 No Address Available
San Diego, CA 92154
APN: 646-110-19-00 **Owner:** Crown Enterprises Inc C/O Real Estate Dept

PROJECT LOCATION



DRAFT

APPRAISAL OVERVIEW

PROJECT and PROPERTY

The client, ColRich Communities, requested appraisals for the proposed offsite acquisitions necessary to accommodate road widening for portions of Airway Road, Britannia Road and Cactus Road in the Otay Mesa Community of the City of San Diego. Airway Road and Britannia Road are shown as a 6-lane Major Streets and Cactus Road is a 4-lane road. The acquisition of the road widening is an offsite requirement placed on the Epoca Project in a stage of development for future construction. The proposed acquisitions include public street easements and construction easements that go beyond the new ROW limits.

The need for the current appraisal results from the ongoing development Epoca (previously Lumina) project in the Otay Mesa Community of San Diego being developed by the client, ColRich Communities. One of the conditions of the discretionary approval process includes an offsite requirement to obtain right of way for street widening from three property owners including portions along Airway Road, Britannia Boulevard and Cactus Road for mitigation of development traffic impacts and is phased.

The project included the subdivision of a 93.4-acre site located west of Cactus Road, north of Siempre Viva Road and is bisected by Airway Road, for the development of up to 1,868 residential dwelling units, up to 62,525 square feet of commercial uses, 6.3 acres of school/recreation uses, 6.6 acres of parks, and 16.2 acres of public streets, and vacation of an unimproved 0.3-acre portion of an unnamed road, within the Central Village Specific Plan and the Otay Mesa Community Plan area.

Public road improvements include offsite improvements to Cactus Road. To the north of Airway Road, Cactus Road would be improved to its ultimate half-width section as a "Four-Lane Major (126-foot ROW)," which would provide for 64 feet of travel way along the southbound side of the road and 19 feet of travel way along the northbound side, a six-foot wide raised median nose, an asphalt concrete (AC) berm along the eastern edge of the road, and a six-foot wide non-contiguous sidewalk within a 12-foot parkway along the Project boundary.

To the south of Airway Road, Cactus Road would be improved to its ultimate half-width as a "Four-Lane Major Arterial (114-foot ROW)," including 19 feet of travel way along the northbound side of the road and 30 feet of travel way along the southbound side, a 16-foot-wide raised median, and eight-foot-wide non-contiguous sidewalk within a 26-foot-wide parkway.

The project also proposes offsite improvements to Airway Road. To the west of Cactus Road, Airway Road would be improved as a "Six-Lane Primary Arterial" along the Project's frontage with a total ROW width of 162 feet, with a 27-foot-wide parkway on the eastbound side of the roadway accommodating a 6-foot-wide non-contiguous sidewalk with a Class I bike path to be constructed by the Lumina Project and a 17-foot wide parkway on the westbound side of the roadway accommodating a 6-foot wide non-contiguous sidewalk.

Between Cactus Road and Britannia Boulevard, Airway Road would be improved for access purposes as a traffic mitigation measure to provide between 70 and 96 feet of travel way with AC berms along both sides of the roadway. The segment of Airway Road east of Cactus Road ultimately would additionally be improved by others as a "Six-Lane Urban Major (139-foot ROW)."

The subject properties include three vacant parcels with development proposals processing for two of the ownerships. There are no individual, site-specific studies on the environmental constraints that might be present on the individual properties, but this does not impact the scope of the appraisal, which has relied on public data information.

DRAFT

Unsigned right of way maps have been provided and are used as the basis of the current appraisal. Full constructions plans and project schedules are not available at this time.

The purpose of the appraisal is for use by the client and the intended user, ColRich Communities, for acquisition of the public street easements and temporary construction easements. The effective date of the appraisal is a current date, based on the site inspection date, and the definition of fair market value used is as found in the State of California Code of Civil Procedure 1263.320.

This appraisal includes three property ownerships with three assessor parcels:

Parcel Name	APN	Current Use	Larger Parcel Size (AC)	Street Easement	Temporary Construction Easement (TCE)
Britannia Innovation Center LLC	646-100-74	Vacant Land	37.9	1.93 acres	1.133 acres
Joseph Paez, Jr.	646-100-77	Vacant Land	39.62	0.893 acres	0.597 acres
Crown Enterprises Inc.	646-110-19	Vacant Land	19.7	2,700 square feet	None
The acquisitions needed for ROW are for street widening in the form of street easement and there are no separate acquisitions for drainage or slope. The acquisition values considered existing easement and encumbrance overlays as calculated by Project Design Consultants, the project engineer.					

LOCATION

The properties are located along both sides of Airway Road, between Cactus Road and Airway Road and La Media Road, within the Otay Mesa Community of the City of San Diego, all within Zip Code 92154.

There are three (3) ownership properties, two within the Central Village Specific Plan Area and the other within the South District of the Otay Mesa Community Plan.

The Central District envisions a village center at the western end of the mesa with employment, educational, and recreation opportunities sited along the transit corridor.

The South District's proximity to the international border and adjacency to the Rodriguez International Airport provides an opportunity to create a cross border airport facility and associated uses south of Siempre Viva Road and in close proximity to the border. The west portion of the South District is designated for heavy industrial uses, such as automobile recycling, truck depots that rely upon outdoor storage, and other uses which can tolerate the truck traffic and noise generated in this area.

APPRAISAL PROCESS / ALTERNATE HIGHEST and BEST USE

The Sales Comparison Approach is the primary approach to valuing the larger parcels to establish a unit value to be used in the property rights to be acquired, to include the permanent street easements. Temporary construction easements consider a land rental. In addition to the larger parcel the appraisal estimates a value of the part to be acquired as part of the whole, the value of the remainder before and after the construction, and any damages or benefits that accrue to the properties from the proposed project.

The Sales Comparison Approach is the best valuation method for land. The Income Capitalization Approach is not applicable since the land in the project area is raw land and does not typically generate income. The Cost Approach is not applicable for land and the improvements are not valued in this report.

DRAFT

For the easement acquisition area, per square foot land value is applied to the amount of land being encumbered and an easement factor is applied.

The subject market area of Otay Mesa has an assortment of industrial uses and is evolving to include residential and commercial uses, both free-standing and as mixed use. There is a strong border influence and much of the market activity is focused on international business and trade. There are also sensitive environmental areas that need to be protected and this has created a need and market for open space/mitigation property.

All of the parcels were considered for the uses that might be permitted by zoning and general plan and economically supported by the market. However, the valuation of the portions to be acquired is guided by uses that would not trigger "required dedication." Since Airway Road, Britannia Boulevard and Cactus Road are circulation element roads, development of the adjoining properties would require dedication of the right of way as well as development of the road improvements. Open space/mitigation uses would not require dedication or road improvement. SEE FOLLOWING REQUIRED DEDICATION PARAGRAPH.

COMPARABLE DATA

Comparable data was researched through an assortment of sources, including Costar COMPS, Sandicor Multiple Listing System (MLS) and research of public records. The subject properties alternate "non-triggering" uses required research for open space land, and the most relevant market influenced transfer were based on a mitigation use. To some degree the open space values are being influenced by the improving demand for other property types within the market area and the overall economy and outlook for the region is strong.

APPRAISAL REQUIREMENTS

This appraisal is intended to value the fair market value of the property rights to be acquired, including Public Street Easements for the street widening and Temporary Construction Easements (TCEs). As a partial acquisition the appraisal also considers potential damages to the remainder property.

The impact of the project as proposed is analyzed based on the best information available from all sources as well as consideration of other similar facilities in comparable neighborhoods.

- Contact for property owners for notification of inspection.
- Appraiser will use typical City easement document for street easement.
- The appraiser will use the right of way maps to identify existing easements in the ROW areas.
- Right-of-way maps showing location and areas with overlaps were provided.
- The appraiser has relied on the proposed road improvement details provided by the client which do not include improvement costs and also referred to City of San Diego Transportation & Storm Water Design Manuals - Street Design Manual. The proposed acquisitions and road improvements will be a phased development and the roads are not being improved to full width or final improvement configuration. The current project is generally providing road pavement and A.C. berms as required.

REQUIRED DEDICATION (FOR PORTIONS TO BE ACQUIRED)

The subject properties are all raw, vacant land parcels with frontages on circulation element roads. The easement areas proposed for acquisition would be an element of "Required Dedication" for any new development approval. Land Development Code (LDC) Section 142.061 identifies when public improvements are required, and Development Services Department confirmed that a discretionary development would trigger the need for public improvements, which would include right of way

DRAFT

dedication. Depending on the specific project, additional public improvements, such as the circulation element road improvements, could also be required but that exact determination would be made during the entitlement process.

Since eventual development would trigger required dedication of the proposed easement areas, those areas could be considered to have a nominal value. The alternate valuation methodology provides a reasonable compensation to the property owner. The appraisal has considered an Alternate Valuation based on uses that could be exempt from "Required Dedication," and the considered use involves an open space use, including mitigation use. The alternate valuation methodology sometimes refers to "non-triggering" uses and values.

Airway Road, Britannia Boulevard and Cactus Road are circulation element roads so development would require dedication of the right of way as well as development of the road improvements. Open space/mitigation uses would not require dedication or road improvement.

A current example of the road requirement was found with reference to a recent project from July 2020, identified as Airway Logistics Center, Process Three Decision, Project No. 665589, seeking a Site Development Permit to construct a new 247,780-square-foot multiple tenant industrial distribution building, located on parcel 646-110-28. The 12.83-acre site (net size from gross 13.13 acres) is in the IBT-1-1 Zone, within the Otay Mesa Community Plan area. A significant project issue stated that LDR-Transportation outlined the need for half-width improvements along the Airway Road frontage along with off-site transitions. This project is east of the subject properties near La Media Road. The requirements included staged dedications and road improvements including additional right-of-way along the project frontage on Airway Road and the improvement of additional right of way with improvements to be completed and operational prior to first occupancy.



This project also had offsite requirements, prior to the issuance of any construction permit, to assure by permit and bond the widening and improvement of La Media Road on the east side for construction of a second northbound through lane from Airway Road to approximately 600 feet north of Airway Road.

DRAFT

TABLE OF CONTENTS

APPRAISAL REPORT **1**
EXECUTIVE SUMMARY **1**
VIEW OF SUBJECT SITES **4**
PROJECT LOCATION **5**
APPRAISAL OVERVIEW **6**
PROJECT and PROPERTY 6
LOCATION 7
APPRAISAL PROCESS / ALTERNATE HIGHEST and BEST USE 7
COMPARABLE DATA 8
APPRAISAL REQUIREMENTS 8
REQUIRED DEDICATION (For Portions To Be Acquired) 8
TABLE OF CONTENTS **10**
CERTIFICATION **13**
LIMITING CONDITIONS AND ASSUMPTIONS **14**
EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS **15**
INTRODUCTION TO REPORT **16**
PURPOSE OF THE APPRAISAL 16
USE and USER OF THE APPRAISAL 16
PROPERTY RIGHTS APPRAISED 16
IDENTIFICATION OF THE PROPERTY 16
OWNERSHIP AND RECENT HISTORY 16
EFFECTIVE DATE OF APPRAISAL 16
EXPOSURE TIME 16
DATE OF REPORT 16
DEFINITIONS OF SIGNIFICANT TERMS **17**
MARKET VALUE 17
HIGHEST AND BEST USE 17
FEE SIMPLE ESTATE 17
EASEMENT 17
SCOPE OF WORK **18**
LOCATION DATA **19**
VALUATION METHODOLOGY AND MARKET DATA SECTION **21**
SALES COMPARISON APPROACH 21
COMPARABLE MARKET DATA MAP 23
COMPARABLE MARKET DATA 24
DISCUSSION OF MARKET DATA 25
ANALYSIS 27
SUMMARY 28
EXECUTIVE SUMMARY – BRITANNIA INNOVATION CENTER **30**
EXHIBITS – BRITANNIA **31**
SUBJECT PHOTOS – BRITANNIA (..... **32**
INTRODUCTION – BRITANNIA PROPERTY **33**
PURPOSE OF THE APPRAISAL 33
USE and USER OF THE APPRAISAL 33
PROPERTY RIGHTS APPRAISED 33
IDENTIFICATION OF THE PROPERTY 33
OWNERSHIP AND RECENT HISTORY 33
EFFECTIVE DATE OF APPRAISAL 34

DRAFT

DATE OF REPORT 34
SITE DESCRIPTION AND ANALYSIS – BRITANNIA PROPERTY 35
LOCATION 35
SIZE AND SHAPE 35
TOPOGRAPHY 35
SOIL 35
ENVIRONMENTAL STUDY 35
STREET IMPROVEMENTS 35
UTILITIES 36
ZONING AND LAND USE DESIGNATION 36
TAX ASSESSMENT 36
EASEMENTS AND RESTRICTIONS 36
FLOOD ZONE CLASSIFICATION 38
PRESENT USE 38
IMPROVEMENTS 38
HIGHEST AND BEST USE – BRITANNIA PROPERTY 39
ALTERNATE HIGHEST and BEST - REQUIRED DEDICATION 40
VALUATION METHODOLOGY – BRITANNIA PROPERTY 41
VALUE OF THE WHOLE BEFORE ACQUISITION 41
DESCRIPTION AND VALUATION OF THE PART TO BE ACQUIRED 41
DESCRIPTION OF THE PART TO BE ACQUIRED 42
VALUE OF THE PART ACQUIRED AS PART OF THE WHOLE 44
VALUE OF THE REMAINDER AS PART OF THE WHOLE 46
VALUE OF THE REMAINDER IN THE AFTER CONDITION, BEFORE BENEFITS 47
BENEFITS 47
TEMPORARY CONSTRUCTION AREA 47
EXECUTIVE SUMMARY – PAEZ PROPERTY 48
EXHIBITS –PAEZ 49
SUBJECT PHOTOS – PAEZ 50
INTRODUCTION - PAEZ 51
PURPOSE OF THE APPRAISAL 51
USE and USER OF THE APPRAISAL 51
PROPERTY RIGHTS APPRAISED 51
IDENTIFICATION OF THE PROPERTY 51
OWNERSHIP AND RECENT HISTORY 51
EFFECTIVE DATE OF THE APPRAISAL 52
DATE OF REPORT 52
SITE DESCRIPTION AND ANALYSIS – PAEZ PROPERTY 53
LOCATION 53
SIZE AND SHAPE 53
TOPOGRAPHY 53
SOIL 53
ENVIRONMENTAL STUDY 53
STREET IMPROVEMENTS 53
UTILITIES 53
ZONING AND LAND USE DESIGNATION 54
TAX ASSESSMENT 55
EASEMENTS AND RESTRICTIONS 55
FLOOD ZONE CLASSIFICATION 56
PRESENT USE 56
IMPROVEMENTS 56
HIGHEST AND BEST USE – PAEZ PROPERTY 57
ALTERNATE HIGHEST and BEST - REQUIRED DEDICATION 58

DRAFT

VALUATION METHODOLOGY – PAEZ PROPERTY 59
VALUE OF THE WHOLE BEFORE ACQUISITION 59
FEE SIMPLE VALUE – PAEZ 59
DESCRIPTION AND VALUATION OF THE PART TO BE ACQUIRED 59
DESCRIPTION OF THE PART TO BE ACQUIRED 60
VALUE OF THE PART ACQUIRED AS PART OF THE WHOLE 62
VALUE OF THE REMAINDER AS PART OF THE WHOLE 63
VALUE OF THE REMAINDER IN THE AFTER CONDITION, BEFORE BENEFITS 64
BENEFITS 64
TEMPORARY CONSTRUCTION AREA 64
EXECUTIVE SUMMARY – CROWN PROPERTY 65
EXHIBITS – CROWN 66
SUBJECT PHOTOS – CROWN 67
INTRODUCTION – CROWN PROPERTY 68
PURPOSE OF THE APPRAISAL 68
USE and USER OF THE APPRAISAL 68
PROPERTY RIGHTS APPRAISED 68
IDENTIFICATION OF THE PROPERTY 68
OWNERSHIP AND RECENT HISTORY 68
EFFECTIVE DATE OF THE APPRAISAL 68
DATE OF REPORT 68
SITE DESCRIPTION AND ANALYSIS – CROWN PROPERTY 69
LOCATION 69
SIZE AND SHAPE 69
TOPOGRAPHY 69
SOIL 69
ENVIRONMENTAL STUDY 69
STREET IMPROVEMENTS 69
UTILITIES 69
ZONING AND LAND USE DESIGNATION 69
TAX ASSESSMENT 70
EASEMENTS AND RESTRICTIONS 70
FLOOD ZONE CLASSIFICATION 70
PRESENT USE 71
IMPROVEMENTS 71
HIGHEST AND BEST USE – CROWN PROPERTY 72
ALTERNATE HIGHEST and BEST - REQUIRED DEDICATION 72
VALUATION METHODOLOGY – CROWN PROPERTY 74
VALUE OF THE WHOLE BEFORE ACQUISITION 74
FEE SIMPLE VALUE – MILLER 74
DESCRIPTION AND VALUATION OF THE PART TO BE ACQUIRED 74
DESCRIPTION OF THE PART TO BE ACQUIRED 75
VALUE OF THE PART ACQUIRED AS PART OF THE WHOLE 77
VALUE OF THE REMAINDER AS PART OF THE WHOLE 78
VALUE OF THE REMAINDER IN THE AFTER CONDITION, BEFORE BENEFITS 78
BENEFITS 78
TOTAL COMPENSATION 78
ADDENDUM 79
COMPARABLE MARKET DATA EXHIBITS 80
QUALIFICATIONS 85

DRAFT

CERTIFICATION

I certify that, to the best of my knowledge and belief:

1. The statements of fact contained in this report are true and correct.
2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions, and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions.
3. I have no present or prospective interest in the properties that are the subjects of this report, and no personal interest with respect to the parties involved.
4. I have no bias with respect to the properties that are the subjects of this report or to the parties involved with this assignment.
5. Neither my engagement nor my compensation is contingent upon the reporting of predetermined values or direction in value that favors the cause of the client, the amount of the value estimate, the attainment of a stipulated result, or the occurrence of a subsequent event. My compensation is not contingent on analyses, opinions nor value conclusion, nor have they been based on a requested a specific value directly related to the intended use of this appraisal.
6. My compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
7. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice and the requirements of the Code of Professional Ethics and Standards of Professional Appraisal Practice of the Appraisal Institute.
8. The use of this report is subject to the requirements of the Appraisal Institute relating to review by its duly authorized representatives.
9. I have made a personal inspection of the properties that are the subjects of this report.
10. No one provided significant professional assistance to the person signing this report. The undersigned has the necessary training and experience to complete this appraisal assignment in a competent manner.
11. I have not performed appraisal services regarding the properties that are the subjects in this report within the three-year period immediately preceding acceptance of this appraisal assignment.
12. As of the date of this report, I, James Naughton, Jr., MAI, have completed the requirements under the continuing education program of the Appraisal Institute.

James Naughton, Jr., MAI
State Certified Real Estate Appraiser
Certificate #AG006748

DRAFT

LIMITING CONDITIONS AND ASSUMPTIONS

Standards Rule ("S.R.") 2 of the Uniform Standards of Professional Appraisal Practice (USPAP) requires that the appraiser "clearly and accurately disclose any extraordinary assumptions or limiting conditions that directly affects the appraisal and indicates its impact on value." In compliance with this rule and for proper interpretation of the report, both general and extraordinary assumptions and limiting conditions are outlined in the following paragraphs.

1. This is an appraisal report as guided by USPAP. The format is short at the request of the client. It contains a summary of the data, reasoning and analyses that were used to develop the opinions of value.

2. The appraiser assumes no responsibility for economic or physical factors that may affect or alter the opinions in this report if said economic, physical or demographic factors were not present as of the date of the letter of transmittal accompanying this report. The appraiser is not obligated to predict future political or social trends.

3. In preparing this report, the appraiser was required to rely on information furnished by other individuals or found in previously existing records and/or documents. Unless otherwise indicated, such information is presumed to be reliable. However, no warranty, either expressed or implied, is given by the appraiser for the accuracy of such information and the appraiser assumes no responsibility for information relied upon that later is found to have been inaccurate. The appraiser reserves the right to make such adjustments to the analyses, opinions and conclusions set forth in this report as may be required by consideration of additional data or more reliable data that may become available.

4. No opinion is intended to be expressed on matters which require legal expertise or specialized investigation or knowledge beyond that ordinarily employed by real estate appraisers, although such matters may be discussed in the report. Also, no liability is assumed on account of matters of a legal nature affecting these properties, such as title defects, liens, encroachments, overlapping boundaries, etc.

5. Maps, photos, plats, sketches, floor plans and other exhibits are included for illustration only, to assist the reader in visualizing the properties. The appraiser has made no survey of the properties. Approximate dimensions may be shown, but exhibits should not be considered as surveys or relied upon for any other purpose.

6. No opinion is expressed as to the value of subsurface oil, gas or mineral rights and the properties are not subject to surface entry for the exploration or removal of such materials except as is expressly stated.

7. All mortgages, liens, encumbrances, leases and servitude have been disregarded unless so specified within this report. Title to the properties appraised is assumed to be marketable and free of encumbrances.

8. Possession of this report, or any copy thereof, does not carry with it the right of publication. This report may not be used for any purpose by anyone but the applicant, without the previous written consent of the appraisers, and in any event, only in its entirety.

DRAFT

9. The appraiser assumes that there are no hidden conditions of the properties, subsoil, terrain or structures, which would render them more or less valuable. The appraiser assumes no responsibility for such conditions, or for engineering that might be required to discover such factors. Furthermore, unless otherwise stated, the subject properties are assumed not to be rendered any more or less valuable by the existence or non-existence of endangered species or habitat.

10. The appraiser is not qualified to detect hazardous waste and/or toxic materials. Any comment by the appraiser that might suggest the possibility of the presence of such substances would not be taken as confirmation of the presence of hazardous waste and/or toxic materials. Such determination would require investigation by a qualified expert in the field of environmental assessment. The presence of substances such as asbestos, urea-formaldehyde foam insulation or other potentially hazardous materials may affect the value of the property. The appraiser's value estimates are predicated on the assumption that there is no such material on or in the properties that would cause a loss in value unless otherwise stated in this report. No responsibility would cause a loss in value unless otherwise stated in this report. No responsibility is assumed for any environmental conditions or for any expertise or engineering knowledge required to discover them. The appraiser's descriptions and resulting comments are the result of the routine observations made during the appraisal process. Unless otherwise stated, this report assumes the subject properties are in compliance with all federal, state and local environmental laws, regulations and rules.

11. Since earthquakes are common in the area, no opinion is offered regarding their possible effect on individual properties and no responsibility for possible effects is assumed, unless detailed geologic reports are made available.

12. The appraiser shall not be required by reason of this appraisal to give testimony or to be in attendance in court or any governmental or other hearing with reference to the properties without prior arrangements having first been made with the appraisers relative to such employment.

EXTRAORDINARY ASSUMPTIONS and HYPOTHETICAL CONDITIONS

The appraiser was not provided and has not conducted specific biological studies or assessments but has considered any information provided by the property owner and available as public data through the City and County of San Diego to determine the environmental characteristics of the subject properties.

HYPOTHETICAL CONDITIONS
A hypothetical condition is a condition, directly related to a specific assignment, which is contrary to what is known by the appraiser to exist on the effective date of the assignment results but is used for the purpose of analysis.

There are no hypothetical conditions.

DRAFT

INTRODUCTION TO REPORT

PURPOSE OF THE APPRAISAL

This appraisal is intended to estimate fair market value of the property rights to be acquired for the Epoca Project as part of their offsite road widening requirements.

USE AND USER OF THE APPRAISAL

This appraisal is prepared to assist ColRich Communities in acquiring property rights for the widening of Airway Road, Britannia Boulevard and Cactus Road.

PROPERTY RIGHTS APPRAISED

The proposed acquisitions include Public Street Easements and Temporary Construction Easements (TCEs). The methodology includes estimates of fee simple estate values and easement values for each ownership. The appraisal considers damage issues to the remainder parcel.

IDENTIFICATION OF THE PROPERTY

This appraisal includes four (3) ownership properties, which are included in the following report. The properties include:

Britannia Innovation Center LLC	646-100-74
Joseph Paez, Jr .	646-100-77
Crown Enterprises Inc.	646-110-19

OWNERSHIP AND RECENT HISTORY

Ownership and recent history of the subject properties are described in the following report in the appropriate sections.

EFFECTIVE DATE OF APPRAISAL

The Effective Date of the Appraisal is August 21, 2022, which is the date of the site inspection.

EXPOSURE TIME

Exposure time for the subject properties is estimated as an average of twelve (12) months from the date of value, based on the market activity of the comparable sales.

Exposure is defined in The Dictionary of Real Estate Appraisal, Seventh Edition, as:

1. The time a property remains on the market.

2. An opinion, based on supporting market data, of the length of time that the property interest being appraised would have been offered on the market prior to the hypothetical consummation of a sale at market value on the effective date of the appraisal. (USPAP, 2020-2021 ed.)

DATE OF REPORT

The date of this report is the date of the cover letter.

DRAFT

DEFINITIONS OF SIGNIFICANT TERMS

MARKET VALUE

Reference: Article 4, Paragraph 1263.320 of Civil Procedure Code, State of California

a. "The fair market value of the property taken is the highest price on the date of valuation that would be agreed to by a seller being willing to sell but under no particular or urgent necessity for so doing, nor obligated to sell, and a buyer, being ready, willing, and able to buy under no particular necessity for so doing, each dealing with the other with full knowledge of all uses and purposes for which the property is reasonably adaptable and available."

b. "The fair market value of the property taken for which there is no relevant market is its value on the date of valuation as determined by any method of valuation that is just and equitable."

HIGHEST AND BEST USE

1. The reasonably probable use of property that results in the highest value. The four criteria that the highest and best use must meet are legal permissibility, physical possibility, financial feasibility, and maximum productivity.

2. The use of an asset that maximizes its potential and that is possible, legally permissible, and financially feasible. The highest and best use may be for continuation of an asset's existing use or for some alternative use. This is determined by the use that a market participant would have in mind for the asset when formulating the price that it would be willing to bid. (IVS)

3. [The] highest and most profitable use for which the property is adaptable and needed or likely to be needed in the reasonably near future. (Uniform Appraisal Standards for Federal Land Acquisitions)

The Dictionary of Real Estate Appraisal, 7th Edition

FEE SIMPLE ESTATE

Absolute ownership unencumbered by any other interest or estate, subject only to the limitations imposed by the governmental powers of taxation, eminent domain, police power, and escheat.

The Dictionary of Real Estate Appraisal, 7th Edition

EASEMENT

The right to use another's land for a stated purpose.

The Dictionary of Real Estate Appraisal, 7th Edition

DRAFT

SCOPE OF WORK

According to the Uniform Standards of Professional Appraisal Practice, it is the appraiser's responsibility to develop and report a scope of work that results in credible results that are appropriate for the appraisal problem and intended user(s). Therefore, the appraiser must identify and consider:

- the client and intended users;
- the intended use of the report;
- the type and definition of value;
- typical appraisal work by peers for similar assignments.
- assignment conditions;
- typical client expectations; and
- the effective date of value;

This appraisal was prepared to assist ColRich Communities in acquiring property rights for the offsite street widening requirements for the Epoca Project on three ownership properties in the Otay Mesa Community of the City of San Diego. The project has been identified based on information from the client. Report Type: This is an Appraisal Report as defined by Uniform Standards of Professional Appraisal Practice under Standards Rule 2-2.

Property Identification: The subject properties were identified using assessor's parcel maps and right of way maps provided by the client. City and County of San Diego data and information and other statistical information were relied upon.

Inspection: An inspection of each site was made, and photographs were taken on August 21, 2022. Only one owner representative was able to be contacted. The properties were capable of being inspected from a public right of way.

All property information and site analysis were performed from the inspections and various records through the City and County of San Diego. It is assumed there are no unobserved conditions on the sites that would impact value.

Market Area and Analysis of Market Conditions: An analysis of market conditions was made. Principals and brokers were interviewed concerning recent market trends.

Market Data: Market data was developed from public information sources as well as subscription sources. The data were verified with one or both of the parties to the transaction to the extent possible.

Highest and Best Use Analysis: An analysis of highest and best use as vacant was conducted.

Valuation Analyses: The subject properties are valued as vacant land. The valuation process has considered the highest and best use based on the current zoning and community plan designations. The valuation analysis includes a value estimate for the fee simple value and storm drain easements.

Cost Approach: The Cost Approach was not developed since it is not relevant to vacant land.
Income Capitalization Approach: The income capitalization approach is not applicable since no income is generated by the land.
Sales Comparison Approach: A complete Sales Comparison Approach was applied.


Summary: The previous is a brief description of many of the sources and procedures used in the course of the appraisal process. The appraiser attempted to obtain the most recent reliable market data for analysis and comparison to the subject. The appraiser is satisfied that the investigation has been thorough and extensive, and that the data used in this report are well documented and reliable.

DRAFT

LOCATION DATA

The subject parcels are within the Otay Mesa Community planning area of the City of San Diego, with the most current plan adopted on March 11, 2014. Otay Mesa is envisioned as a major employment center with two new residential village areas and public trails that traverse the canyons and mesas. Current uses include residential, commercial, industrial, agricultural, and municipal uses, as well as areas of undeveloped, naturally vegetated land.

The community of Otay Mesa encompasses approximately 9,300 acres located at the southern limit of the City of San Diego. The community is bordered by the San Ysidro and Otay Mesa-Nestor communities to the west, the City of Chula Vista and the Otay Valley Regional Park to the north, the County of San Diego to the east and the U.S./Mexico border and the City of Tijuana to the south. Major natural and manmade features define the community and create its boundaries, including the Otay River Valley, the canyon and mesa systems in the western portion, Brown Field airport and the U.S./Mexico border. Otay Mesa's unique location along the Mexican border and its broad flat topography promotes a border economy. The historical development pattern followed the natural topography of the land, with development occurring on the flat mesa tops and bounded by the extensive canyon system. Known sensitive biological resources have been documented, and planning in the area included preservation of canyon lands and sensitive resources along with development opportunities.



DRAFT

One of the subject properties (Crown Enterprises, Inc.) is in the South District of the community plan, which is bounded by Otay Mesa Road to the north, the US-Mexico international border to the south, La Media Road to the east, and Wruck Canyon to the west. The western portion is predominantly developed with commercial/light-industrial properties and the eastern portion consists of agricultural land.

The South District includes open space canyon lands and wetlands with sensitive biological resources and habitat areas, large lot heavy commercial, open space and industrial uses characterize the land uses, with much of the developed land occupied by warehousing, distribution, truck depots, and customs brokerages to support the international logistics industry. The South District also includes the Otay Mesa International Port of Entry, and the uses are intended to support the international business and trade uses that are necessary for the movement of goods across the border. The west portion of the district is designated for heavy industrial uses, such as automobile recycling, truck depots that rely upon outdoor storage, and other uses which can tolerate the truck traffic and noise generated in this area. The district's proximity to the International border and adjacency to the Rodriguez International Airport in Tijuana provides an opportunity to create a cross border airport facility and associated uses.

Two of the properties are in the Central District of the community plan, which is generally bounded by Spring Canyon to the west, Siempre Viva Road, Britannia Boulevard, and Airway Road to the south, and the SR-905 to the east and north. The Spring Canyon system is home to many protected sensitive biological resources and habitat areas. The district includes Airway Road which is the spine of the community and is Otay Mesa's primary transit corridor. The District is between the Airport District and the industrial South District and is defined by two subareas; the Central Village with the Grand Park, and the Industrial/Education corridor.

The Central Village includes both neighborhood and community village areas and is envisioned as a medium to high density residential community centered along Airway Road, and focused on school and park uses, as well as village-scale retail. The Grand Park is adjacent to the Central Village and is located along Airway Boulevard transit corridor east of Cactus Road. The Industrial/Education Corridor includes business park and office uses along Britannia Boulevard, and business parks, a community college campus, and International Business and Trade industrial uses along the northern portion of Airway Road. The Central District Non-Village area is intended to include commercial, industrial, parking, and other non-residential uses, for development that will be adjacent to freeways and truck routes. And to create a visual and distance separation between the public right-of-way and industrial uses such as auto dismantling, truck transportation terminals, and other uses that create noise, visual, or air quality impacts.

DRAFT

VALUATION METHODOLOGY and MARKET DATA SECTION

The value sought in this appraisal is the Fair Market Value for the subject properties. The primary purpose of this appraisal is to determine the value of portions of the property for road widening. So, this is a partial acquisition appraisal, and the process includes estimating a value for the Larger Parcel and then determining a value estimate for the portions of the property required for the project (road widening) as well as estimating damages and benefits. Considering the aspect of Required Dedication, this appraisal utilizes as alternate "non-triggering" highest and best use.

The Sales Comparison, Cost, and Income Capitalization Approaches are typically used to value real property. The subject appraisal is intended to estimate a value of the land as if vacant, so the Cost Approach is not relevant. There is insufficient land lease data in the market area for properties in raw land condition similar to the subject, so the Income Approach is not relevant. Therefore, only the Sales Comparison Approach to value as applied to comparable land sales was deemed appropriate for valuing the subject property.

SALES COMPARISON APPROACH

The valuation methodology for the subject property has been guided by the analysis of the Highest and Best Use. The properties are currently vacant, raw land parcels available for future development or speculative investment and capital appreciation (land banking). Included within the speculative activities would be marketing the property to private and public users for mitigation uses.

Within the Otay Mesa market transactions have included speculative holding purchases, mitigation purchases and industrial development or yard use purchases and more recently for mixed uses. The basic unit of comparison used for development properties is price paid per square foot of land area, although the price per acre is often used for the open space/mitigation properties.

One of the most active brokers in the Otay Mesa market identified the following as Categories of Land in Otay Mesa. Source: Rob Hixson, Broker CBRE (2018 Seminar).

- Mitigation Land, unimproved and unentitled land, which may have species of interest –burrowing owls or vernal pools.
- Raw Land, unimproved and unentitled land.
- Raw Land with Clean Biological, above that has been farmed or has been accessed by a biologist and is clean.
- Tentative Map, received a tentative map with requirements to develop.
- Tentative Map with All Mitigation Land; Mitigation land is required in both the City and County for non-native grasses.
- Final Map, all entitlements complete.
- Improved Lot, all offsite improvements done and utilities to site. Some compaction of soil maybe required to construct buildings.
- Fully Improved Lot with Soil Mitigation, all improvements done, utilities to site, soil compacted and ready to build on.
- Fully Improved for Truck Parking, improved lot with fencing, screening, landscaping, lighting, drive aisles and entry.
-

The subject properties are not within MHPA or VPHCP overlay areas but as with all raw land there is the possibility of environmental constraints which would be unknown without biological studies and determined by the City environmental review process.

DRAFT

It is important to realize that road dedication and road improvements are required for any development or expansion of uses that require additional discretionary site approvals. So, in keeping with an alternate "non-triggering" highest and best use as open space the most appropriate land category from the previous list is the first one, as mitigation land.

The market data are summarized in the following Land Sales Grid and the discussion of the sales. A Qualitative Analysis Worksheet is included in the individual property sections to support the estimate of value for the subject property. The analysis process is applied on a qualitative basis since reliable support for quantitative adjustments is not available. An array is also presented, which is a bracketing technique.


The sales/offers have been selected for use by the appraiser, and all of the transactions are within the City of San Diego in Otay Mesa. All of the subject properties have similar legal and physical characteristics considering the alternate highest and best use.

The valuation methodology for the subject property has been guided by the need to provide a valuation that is based on the alternate "non-triggering" use, which focuses on uses that would be exempt from the required dedication previously discussed. This requirement was outlined in the Highest and Best Use section. The limited non-triggering uses focus on open space use, which includes marketing the property to private and public users for mitigation uses.

The market data are summarized in the following Land Sales Grid and the discussion of the sales. A Land Sales Analysis Worksheet is included to support the estimate of value for the subject property. The analysis process has been applied on a qualitative basis since reliable support for quantitative adjustments is not available. An array is presented, which is a bracketing technique.

DRAFT

COMPARABLE MARKET DATA MAP



SEE ADDENDUM FOR AERIAL EXHIBITS OF THE MARKET DATA

COMPARABLE MARKET DATA

#	Location APN	Buyer/ Seller	Date / Document	Zone	Area (Acre)	Price	Per/Acre (Per SF)	Comments
1	La Media Road 667-060-28	Daxton & Maxwell Corn / Metropolitan Airpark LLC	09/24/2015 0503198	IBT-1-1	15.39	$1,100,000	$71,475 ($1.64)	Vernal pools. Private developer. Mitigation Use
2	Siempre Viva Road 646-110-10	Siempre Viva Development LLP / Metropolitan Airpark LLC	07/15/2016 0354288	IBT-1-1	10.00	$800,000	$80,000 ($1.84)	Speculative purchase with no current plans. Private developer. Mitigation Use
3	6260 Siempre Viva Road 646-110-12	Robert E. Miller Trust / Metropolitan Airpark LLC	11/02/2015 0571276	IBT-1-1	10.00	$800,000	$80,000 ($1.84)	Speculative purchase with no current plans. Private developer. Mitigation Use
4	8901 Siempre Viva Road 667-060-15	M&A Equities LLC / Otay TJ North	04/07/2017 0157874	IBT-1-1	10.00	$850,000	$85,000 ($1.95)	Vernal pools. Private developer. Future uses
5	8381 Siempre Viva Rd 667-060-10	Otay TJ East / Robert H. Hagey, Trustee	11/21/2017 0543139	IBT-1-1	49.40	$4,800,000	$97,166 ($2.23)	Vernal pools. Private developer. Future uses
6	Harry Wetland Mitigation 646-110-05	Harry Trust & Bradstreet Trust / City of San Diego	8/4/2022 316545	IBT-1-1	1.81 (part)	$271,500 (part)	$150,000 ($3.44)	Mitigation use by City
7	Tirado Wetland Mitigation 646-110-06	Jose Tirado / City of San Diego	6/22/2022 258140	IBT-1-1	4.77	$750,000	$157,233 ($3.61)	Mitigation use by City
8	5761 Airway Road 646-100-74	Britannia Innovation LLC / Wen Shin M Chang, Trustee	6/2/2021	IBT-1-1	37.9	$7,250,000	$191,293 ($4.39)	Future development
9	Lonestar & Harvest 646-080-20&21	TBD / Marathon Land	Escrow August 2022	S88	39.72	$7,944,444	$200,000 ($4.59)	Mitigation use by developer

DRAFT

DISCUSSION OF MARKET DATA

In the sales comparison approach, the subject properties have been compared to sales of similarly zoned parcels with a focus on the South District of Otay Mesa Community. The transactions included in the grid are helpful in establishing a value to apply to the subject properties.

All of the properties are raw vacant land parcels and would require discretionary approvals for development and uses and generally fall into the first two categories of land described earlier as either raw land or mitigation land.

Market Data 1, 2, 3 – North and South of Siempre Viva Road – These three transactions are acquisitions by Metropolitan Airpark LLC for Brown Field redevelopment and range from $71,475 to $80,000 per acre. These properties are mitigation acquisitions that relate to endangered and threatened species, including Burrowing Owls and Vernal Pools. Acquisitions for similar species mitigation in the Otay Mesa area (City and County) in the past (2007-2009) were in the range of $65,000 per acre. Each of the properties shows signs of being previously disturbed, have drainage conditions and MHPA overlay in portions. Vegetation appears to be mostly non-native grasslands. The transactions recorded in July 2016 and September/October 2015. The parcel sizes range from 10.0 acres to 15.9 acres.

Market Data 4 – 8901 Siempre Viva Road, is located in Otay Mesa, west of La Media Road. This undeveloped parcel contains 10.0 gross acres and is shown as a project site in the newly approved VPHCP as 75% conserved. This property was purchased by the same buyer as Data 3, and the buyer also owns a private border crossing to the south of this property, the Cross-Border Xpress (CBX). They purchased this property to control the land and development between La Media Road and the CBX. They will hold this land for eventual development. Portions could be used for mitigation. According to their consultant, there is a drainage swale that bisects the northern portion, so only the rear has development potential. Access would need to cross the drainage or enter from an adjoining property. Vegetation includes grassland, but no vernal pools are shown on the mapping. There are utilities, including electric, water and sewer available in the area. This property sold in April 2017 for $850,000 and had been acquired in a Trustee's sale. On a gross land size of 10.0 acres, the sale is equal to $85,000 per acre ($1.95 per SF). Zoning is IBT-1-1 (International Business and Trade). The Siempre Viva Road frontage is not improved, and this portion of the road is not paved. Development would require road improvements and dedication for widening.

Market Data 5 – 8381 Siempre Viva Road, is located in Otay Mesa, at the southeast corner of La Media Road and Siempre Viva Road. This large site had some older industrial improvements that did not contribute to the price and the property is assessed as land only. The property has 49.40 gross acres and a broker estimate of 36 net acres, considering habitat protection areas and anticipated future road widening. VPHCP 100% Conserved areas are present onsite, with 5.17 acres at the northeast corner and 4.95 acres along the south property line. The buyer also owns a private border crossing to the south of this property, the Cross-Border Xpress (CBX), and purchased this property to control the land and development between La Media Road and the CBX. They will hold this land for eventual development and portions could be used for mitigation. The lot is crossed by drainage through the northwest corner and vegetation and habitat includes grassland and vernal pools. There are utilities, including electric, water and sewer available. This property sold in November 2017 for $4,800,000. On a gross land area of 49.40 acres, the unit indicator is $97,166 per acre ($2.23 per SF). Zoning is IBT-1-1 (International Business and Trade). The property has frontage on both Siempre Viva Road and La Media Road. Siempre Viva frontage is not improved, and this portion of the road is not paved, so development would require road improvements and dedication for road widening. La Media Road is designated as a truck route south of Siempre Viva Road.

DRAFT

Market Data #6– 8219 Airway Road, is currently in use as truck yard and open space with a total of 9.16± acres, zoned IBT-1-1 and within the IBT (International--Business and Trade) Zone and also includes Open Space as a land use. The subject property is located along the south side of Airway Road at a corner with La Media Road. The location is referred to as the La Media Swale, influenced by drainage and Multiple Habitat Property Area (MHPA) overlay. La Media Road in this location is circulation element road designated as a 5-Lane Major Road in the Otay Mesa Community Plan, and currently serves as a truck route with one way traffic in a southerly direction. Outside of the trailer yard the MHPA portions are considered to be 75% conserved. The subject parcel had been considered for acquisition by the City for open space preservation as part of the Vernal Pool Habitat Conservation Plan (VPHCP) due to their recognized environmental sensitivity, including drainage, wetlands and vernal pools. Additional environmental sensitivity results from the predominant non-native grassland (NNG) in the area and the general presence of burrowing owl (BUOW).

This property was appraised for the La Media Road widening project and the appraisal concluded a highest and best use as border oriented industrial activities, including truck storage and transport and the open space portion might be usable for on-site mitigation for redevelopment. The City acquired property rights for the street widening recording August 4, 2022 and the compensation included an amount of $271,500 for the 1.81-acre portion of this site as a Wetland Mitigation Parcel. This is equal to $157,233 per acre or $3.61 per square foot.

Market Data #7– La Media Road is a 4.77± acre vacant parcel. Zoning is IBT-1-1 with environmental constraints designating most of the property as Open Space and within a MHPA area shown as 75% conserved. The parcel is level with a drainage swale bisecting the property. The property was acquired by a previous owner as an investment with no specific plan for use or development with the sale recorded on August 25, 2014 for $220,000, equal to $46,121 per acre. The property was later designated to be within the City of San Diego Vernal Pool Habitat Conservation Plan (VPHCP), approved January 31, 2018 and the City of San Diego commenced efforts to acquire the property. The City had the property appraised in 2021 and the appraisal highest and best use was determined to be combination uses with some industrial use or development and/or holding the land for speculative investment and capital appreciation (land banking) while marketing the individual parcel for future uses and marketing the recognized environmental sensitivity for potential off-site mitigation to private developers and/or governmental agencies. The City continued acquisition efforts and acquired the property as a wetland mitigation parcel in a recorded transaction on 6/22/2022 for $750,000, equal to $150,000 per acre or $3.44 per square foot.

Market Data #8 – 5761 Airway Road has frontage on Airway Road, Britannia Boulevard and Cactus Road and contains 37.9 acres. The last transfer was recorded 6/4/2021 for $7,250,000 equal to $191,293 per acre or $4.39 per square foot. The property had been listed for $6,500,000, reported to be on market 1,451 days. Sale price exceeded listing price due to multiple offers. Zoning is IBT-1-1 and Community Plan Land Use shows as Business Park-Office Permitted and Park. The broker describes the condition as raw and there are known environmental limitations based on current information but no specific studies. Although there are no apparent environmental issues, the land use for park influences about one-half of the site. There are no known extraordinary development costs but road widening, and improvement would be needed. Utilities are available in the area and this location adjoins the recently approved Central Village Specific Plan, which includes mixed uses including residential uses.

The buyer has submitted for a site development permit to allow for the development of a temporary truck parking and trailer storage facility, dated 12/22/2021 and the notice identifies a filing for a process three site development permit to allow development of truck parking and trailer storage on site containing non-native grasslands. The 32.47-acre site is in the IBT-1-1 Base Zone of the Otay Mesa Community Plan area. About half of this property is designated as a park in the Otay Mesa Community Plan. (Pages 16, 21,25, 29, and 113 of the OMCPU). The current request is for Britannia Logistics Center, an industrial

DRAFT

logistics distribution building on 19 acres and will features 36' clear height, in a 322,200 SF building which will be delivered in Q2 2023.

Market Data #9 - Pending Sale North end Harvest Road at Lonestar Road. Rob Hixon of CBRE has been marketing 39.72 acres within the unincorporated San Diego County in the East Otay Mesa Specific Plan. The property is generally sloping and was listed for sale at $3,575,000. The property is being marketed as prime biological mitigation land with Burrowing Owl. There was one reported offer received in 2021 for $3,000,000 and countered at $3,200,000 but that was not accepted. The broker reports he is in escrow now at a price of $7,944,444, equal to $200,000 per acre or $4.59 per square foot.

ADDITIONAL MARKET INFORMATION

Lonestar Credits Sold for $162,866 per acre/credit with a total of 27.5 acres, confirmed by the seller John DeSantis, Kearny Real Estate 8/5/2022. Seefried was the sole buyer, representing Amazon for their purchase of the Rabago property on Otay Mesa Road.

ANALYSIS

This section of the report has identified and described the market data that was determined to be the most relevant to all of the subject properties. The following discussion outlines the general characteristics used for comparison of the market data to the subject properties.

Theoretically any adjustment should have a supportable basis. However, particularly with land sales, there are too many differing characteristics to identify specific adjustments for every feature. The appraiser is often faced with the need to apply "reasonable" adjustments in an effort to make sense of the raw data and to apply in an estimate of value. No quantitative adjustments are made due to the inability to support adjustments with paired sales. Rather, a qualitative analysis process is applied, including a relative comparison and ranking analysis as described in The Appraisal of Real Estate. The following discussion summarizes the treatment of the comparable sales in the analysis of the various subject properties.

PROPERTY RIGHTS

All items of market data involve the transfer of the fee simple estate subject to existing easements, which are the property rights appraised herein.

SALE OR FINANCING CONCESSIONS

Each of the sales analyzed were acquired for cash, or terms equivalent to cash.

CONDITIONS OF SALE

Conditions of a sale (motivations behind the sale) were investigated to ensure that neither party in the transaction was under any undue pressure, and that it was an arm's length transaction. All of the sales were confirmed to be negotiated without undue duress on the part of the buyer or seller. However, two of the transactions, Data #6 and #7, were City acquisitions for a road project and although negotiated this type of transaction has the threat of condemnation and may represent a premium price to avoid same, so the price could be trended downward.

The open escrow is given less weight since there may be some undisclosed or unknown contingencies.

MARKET CONDITIONS

The subject "non-triggering" use has been identified as open space/mitigation. Overall San Diego County industrial demand and values have been increasing and this could support upward trending of the mitigation transactions that enable industrial development, but a quantified measurement is not possible for land transactions.

DRAFT

In general, the market for mitigation land has been stable with regional upward influences. The subject area has a few unique environmental features and influences including grassland areas (NNG) that support burrowing owls (BUOW) and wetland including vernal pools. Recent discussions with Rob Hixson, one of the most active brokers in the Otay Mesa market suggests that the mitigation market for Otay Mesa properties had remained stable with recent increases.

LOCATION

Location comparisons are less significant for open space properties and are generally similar as part of the overall Otay Mesa Community.

SIZE

Larger properties tend to sell for less per acre or per square foot than smaller properties, when all else is equal. This is partly due to the smaller number of buyers for higher priced properties. This is not always the case when certain uses require larger sites for economies of scale and future expansion.

ZONING

The subject and the comparables have similar zoning and this is also less significant characteristic for open space uses but might be an element in their desirability for specific mitigation uses.

LAND CONDITION/TOPOGRAPHY

The subject properties and the market transactions are generally level but there are differences with respect to usability due to drainage and environmental issues.

SHAPE

The subject properties are generally regular in shape based on property lines, and shape has limited influence on open space use.

UTILITIES

Open space use is not directly influenced by utilities but might factor into specific mitigation desirability, since the threat of development and disturbance from surrounding development influence agency approvals.

ACCESS

Access has limited influence on open space use except as might influence the mitigation use based on threat of disturbance.

INTERIM USE/IMPROVEMENTS

None. All of the market transaction are considered to be vacant land.

SUMMARY

The valuation process in this appraisal is to determine a value basis for an alternate use that does not trigger required dedication. The use was determined to an open space use and includes use for mitigation, as found in the market area. These items can represent a value to an existing owner for use as on-site mitigation during approval processing or sale to a third party for their use.

The included market data represents an assortment of properties all within and relevant to the Otay Mesa market and include transactions with an assortment of acquisition motivations. None of the subject properties have specific environmental reports to establish specific types or condition of the habitats but this valuation process was necessary to establish a certain generic value for a type of property that can represent the alternate open space use.

DRAFT

The following grid presents the market data and an analysis that compares the characteristics of the properties and sale transactions. This is a qualitative process that allows a relative comparison and considers the market data as inferior, similar or superior. This then allows an array presentation.

LAND SALES ANALYSIS									
Land Sale Data No.	1	2	3	4	5	6	7	8	9 (Inf)
Location	La Media Road	Siempre Viva Road	6260 Siempre Viva Road	8901 Siempre Viva Road	8381 Siempre Viva Road	Harry Wetland (Partial)	La Media Rd. Tirado Wetland	5761 Airway Road	Harvest & Lonestar Road
Area	Otay Mesa	Otay Mesa	Otay Mesa	Otay Mesa	Otay Mesa	Otay Mesa	Otay Mesa	Otay Mesa	Otay Mesa
Assessor's Parcel No(s).	667-060-28	646-110-10	646-110-12	667-060-15	667-060-10	646-110-05	646-110-06	646-100-74	646-080-20&21
Land Area (ac)	15.39	10.00	10.00	10.00	49.40	1.81	4.77	37.90	39.72
Zoning	IBT-1-1	IBT-1-1	IBT-1-1	IBT-1-1	IBT-1-1	IBT-1-1	IBT-1-1	IBT-1-1	Specific Plan
General Plan	International Business and Trade	International Business and Trade	International Business and Trade	International Business and Trade	International Business and Trade	International Business and Trade	International Business and Trade	International Business / Park	Specific Plan
Condition/Habitat	Vernal Pools Mapped	MHPA	MHPA	Vernal Pools Project (75%)	Vernal Pools Mapped	MHPA	MHPA	Raw, level	Sloping, raw
SALE DATA									
Use at Sale	Open	Open	Open	Vacant	Vacant	Vacant	Vacant	Vacant	Vacant
Proposed Use	Conservation	Conservation	Conservation	Future uses	Future uses	Wetland	Wetland	Industrial	Miotigation
Recording Date	Sep-15	Jul-16	Oct-15	Apr-17	Nov-17	Aug-22	Jun-22	Jun-21	Pending 2022
Sale/Listing Price	$1,100,000	$800,000	$800,000	$850,000	$4,800,000	$271,500	$750,000	$7,250,000	$7,944,000
Price/Acre	$71,475	$80,000	$80,000	$85,000	$97,166	$150,000	$157,233	$191,293	$200,000
Price/Square Foot	$1.64	$1.84	$1.84	$1.95	$2.23	$3.44	$3.61	$4.39	$4.59
ANALYSIS									
	COMMENTS	COMMENTS	COMMENTS	COMMENTS	COMMENTS	COMMENTS	COMMENTS	COMMENTS	COMMENTS
Property Rights	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar
Financing	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar
Conditions of Sale	Similar	Similar	Similar	Similar	Similar	Superior	Superior	Similar	Superior
Market Conditions	Inferior	Inferior	Inferior	Inferior	Inferior	Similar	Similar	Similar	Similar
Location	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar
Size (acres)	Superior	Superior	Superior	Superior	Inferior	Superior	Superior	Similar	Similar
Zoning	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar
Land Condition/Topc	Similar	Similar	Similar	Similar	Similar	Superior	Superior	Superior	Similar
Shape	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar
Utilities	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar	Similar
Access	Inferior	Inferior	Inferior	Inferior	Similar	Similar	Similar	Similar	Similar
OVERALL	Inferior	Inferior	Inferior	Inferior	Inferior	Similar	Similar	Similar	Similar
Value (per SF)	**More Than $1.64/SF**	**More Than $1.84/SF**	**More Than $1.84/SF**	**More Than $1.95/SF**	**More Than $2.23/SF**	**Less Than $3.44/SF**	**Less Than $3.61/SF**	**Less Than 4.39/SF**	**Information Only**

Sale No.	Size (Acre)	Date	Price Per Gross Acre	Price Per Square Foot	Comparison To Subject
1	15.39	Sep-15	$71,475	$1.64	Inferior
2	10.00	Jul-16	$80,000	$1.84	Inferior
3	10.00	Oct-15	$80,000	$1.84	Inferior
4	10.00	Apr-17	$85,000	$1.95	Inferior
5	49.40	Nov-17	$97,166	$2.23	Inferior
6	1.81	Aug-22	$150,000	$3.44	Superior
7	4.77	Jun-22	$157,233	$3.61	Superior
8	37.90	Jun-21	$191,293	$4.39	Superior
9	39.72	Pending 2022	$200,000	$4.59	Information

Particular attention is paid to the more recent transactions. An estimate of value to apply to the subject should fall between the inferior and superior transactions. The lowest two superior transactions show $150,000 to $157,233 per acre but require a small downward trending for conditions of sale. The next higher superior sale # 8 was not acquired for mitigation and has development potential for at least one-half, while the balance has a park land use. Considering the data analyzed an estimate of $135,000 per acre, equal to $3.10 per square foot is selected.

DRAFT

EXECUTIVE SUMMARY – BRITANNIA INNOVATION CENTER

IDENTIFICATION	BRITANNIA INNOVATION CENTER PROPERTY
LOCATION	5761 Airway Road, San Diego, CA 92154
ASSESSOR PARCEL NUMBER	646-100-74
CURRENT USES	Vacant land
OWNERS OF RECORD	Britannia Innovation Center LLC
EFFECTIVE DATE OF APPRAISAL	August 21, 2022
SITE DATA	The subject is a 37.9± acre parcel of raw land with perimeter fencing. Zoning is IBT-1-1 and no MHPA exists on this property. Land use is Business Park-Office Permitted. The subject parcel is level, slightly below street grade, and has frontage on Airway Road, Britannia Boulevard and Cactus Road.
HIGHEST AND BEST USE	A Non-Development Alternate Highest and Best Use that would not trigger "Required Dedication" has been used. This use is open space including possible sale or use for mitigation.
SPECIAL LIMITIED CONDITIONS	A Non-Development Alternate Highest and Best Use that would not trigger "Required Dedication" has been used.


VALUES

Value of the Whole Before Acquisition	**$5,120,000**
Value of the Part Acquired as Part of the Whole	**$179,500**
Value of the Remainder	**$4,940,500**
Severance Damage	**None**
Benefits	**None**
Temporary Construction Area	**$15,300**
VALUE OF RIGHTS TO BE ACQUIRED	**$194,800**

DRAFT

EXHIBITS – BRITANNIA





SUBJECT PHOTOS – BRITANNIA (
August 21, 2022 by James Naughton, Jr. MAI




View northeast from southwest corner.



Interior view east. Poles mark SDGE easement along Airway Road frontage.



North along Cactus Road at southwest corner.



Southwest view at Airway and Britannia intersection.



Drainage easement area west of Britannia Boulevard.



West along Airway Road. Poles in SDGE easement.

INTRODUCTION – BRITANNIA PROPERTY

PURPOSE OF THE APPRAISAL

This appraisal is intended to estimate fair market value of the property rights to be acquired for the Epoca Project as part of their offsite road widening requirements.

USE AND USER OF THE APPRAISAL

This appraisal is prepared to assist ColRich Communities in acquiring property rights for the widening of Airway Road, Britannia Boulevard and Cactus Road.

PROPERTY RIGHTS APPRAISED

The proposed acquisitions include Public Street Easements and Temporary Construction Easements (TCEs). The methodology includes estimates of fee simple estate values and easement values for each ownership. The appraisal considers damage issues to the remainder parcel.

IDENTIFICATION OF THE PROPERTY

The subject property "Larger Parcel" has been identified based on the three unities of ownership, contiguity and use (highest and best use). This section of the appraisal includes:

The Larger Parcel is defined as Britannia Innovation Center Property – 5716 Airway Road, San Diego, CA 92154; APN: 646-100-74-00. The subject is one APN containing 37.9± acres.

Title is vested as: Britannia Innovation Center LLC.

LEGAL DESCRIPTION - The land referred to herein is situated in the city of San Diego, County of San Diego, State of California, and is described as follows:

The north quarter of the southeast quarter of section 33, township 18 south, range 1 west, San Bernardino base and meridian, in the County of San Diego, State of California, according to the plat in That certain decree establishing boundary lines in the southeast Quarter of said section 33, in superior court of San Diego county, case No. 212718, a certified copy of said decree being recorded March 3, 1958 In book 6975, page 305 of official records, said boundary line in said Decree being as follows:

Beginning at the east quarter corner of said section; thence south 1° 27' 1 0" west along the east line of said section, 662.92 feet to an old fence line position; thence along said old fence line position, north 89° 46' 40" west, 2642.60 feet to the west line of said southeast quarter; Thence along said west line, north 1° 24' east, 662.38 feet (measured 754.41 feet) to the center line of airway road known as road survey No. 121; thence along said center line, south 89° 40' 50" east, 2643.12 feet To the point of beginning.

Excepting therefrom that portion of said land, if any, lying within The southeast quarter of the northeast quarter of the southeast Quarter and the southwest quarter of the northeast quarter of the Southeast quarter of said section 33.

This legal description is made pursuant to that certain certificate Of compliance recorded january26, 1990as instrument no. 1990-47684 of Official records.

OWNERSHIP AND RECENT HISTORY

The last transfer was recorded 6/4/2021, document 2021-0417421. This was a market transaction for $7,250,000 in which Britannia Innovation Center LLC acquired from Chang Wen Shin M Chang, Trustee. The property had been listed for sale by Rob Hixson, SIOR, Senior Vice President, CBRE, Inc., for $6,500,000, reported to be on Market 1,451 Days, Escrow Length 90 Days. Sale price exceeded listing price due to multiple offers.

DRAFT

The selling broker indicated that future development plans were considering hotel/retail along Britannia and additional industrial uses. The buyer has submitted for a Site Development Permit (PRJ-1048583) dated 12/22/2021. A March 1, 2022 notice identifies a filing with the City of San Diego for a Process Three Site Development Permit to allow development of truck parking and trailer storage on a portion of the property containing non-native grasslands. The 32.47-acre site is in the IBT-1-1 base zone of the Otay Mesa Community Plan area. PROJECT NO: PRJ-1048583, PROJECT NAME: 2150 BRITANNIA BLVD.t Project Manager (619) 446-5333 / BHudson@sandiego.gov.

The owner's website identifies the future project to be BRITANNIA LOGISTICS CENTER, an industrial logistics distribution building on 19 acres. This project features 36' clear height, in a 322,200 SF building which will be delivered in Q2 2023.

The appraiser contacted Marlon I. Pangilinan, Senior Planner, City of San Diego Planning Department regarding required dedication along the road frontages and he confirmed with the staff in Development Services Department that dedication is required.

EFFECTIVE DATE OF APPRAISAL

The effective date of the appraisal is August 21, 2022, the date of the most recent inspection.

DATE OF REPORT

The date of this report is the date of the cover letter.

DRAFT

SITE DESCRIPTION AND ANALYSIS – BRITANNIA PROPERTY

LOCATION

The subject property is located at 5761 Airway Road in the public record (also identified as 2150 Britannia Boulevard), along the south side of Airway Road between Cactus Road and Britannia Boulevard. The location is within the Central District of the Otay Mesa Community in the City of San Diego, 92154.

SIZE AND SHAPE

The Assessor's records identify the property as 37.9± acres in one parcel, or approximately 1,650,924 square feet. The shape is rectangular.

TOPOGRAPHY

The subject parcel is predominately level, slightly below street grade and has evidence of a ponding area near the southeast corner.

The approximate elevation ranges from 518 feet above sea level at the northwest corner to about 499 feet at the southeast corner.

SOIL

A soils report was not provided for review. According to mapping and data from the County of San Diego as presented by Land Use Environmental Group (LUEG) the soils are Stockpen gravelly clay loam, 0 to 2 percent slopes and 2 to 5 percent slopes. The appraiser assumes there are no soil conditions that impact current or future legal uses of the land or land value.

ENVIRONMENTAL STUDY

The appraiser has not been provided a specific environmental study or report. The County's LUEG identifies the vegetation as 18300 Extensive Agriculture - Field/Pasture, Row Crops.

No Multiple Habitat Planning Area (MHPA) exists on this property.

STREET IMPROVEMENTS

The subject has frontage along the south side of Airway Road, east side of Cactus Road and west side of Britannia Boulevard. Airway Road and Britannia Boulevard are both shown on the circulation element in this location as a 6-lane Major Arterials and Cactus Road is shown as a 4-lane Major Arterial, however current conditions have Airway Road as 2 lanes transitioning to 3 lanes, Britannia as 3 lanes and Cactus Road as 2 lanes. All of the frontages are only partially improved (paving) and would require dedication and road improvements if the property is developed. Specific road requirements would be identified upon plan submission. The following is general road design from the published materials (Street Design Manual).

A Four Lane Major Street design has a 120 foot right of way width, to include bike lanes and raised center median. Intersection turn lanes are also required.

A Six Lane Major Street design has a 140 to 152 foot right of way width, to include bike lanes and raised center median. Intersection turn lanes are also required.

The current width along the subject's north frontage is 40 feet (29-foot street widening for portion in the east on the north side) and the distance from centerline is 20 feet. Cactus Road along frontage is also 40-foot width. Britannia Boulevard along frontage is 56 feet wide. Considering the most recent circulation plan, new development would require road widening.

DRAFT

Future road improvements would include pavement, concrete medians, sidewalk, curb and gutter, landscaping and street lighting, although interim street improvements would only include paving and AC berms.

UTILITIES

Public water and electric service are available in the area. Otay Water District provides potable water to the majority of the Specific Plan area (east of Heritage Road) via connections to the existing and planned water mains located in the rights-of-way of Cactus, Airway, Heritage, and Siempre Viva Roads.

The City of San Diego is the sewer collection system provider for the area. As of 2017, sewer flows generated within the Specific Plan area were conveyed to a pump station located near Cactus Road and Siempre Viva Road. From the pump station, sewer flows are conveyed to a gravity sewer in Otay Mesa Road that connects to the City's Otay Valley Trunk Sewer.

ZONING AND LAND USE DESIGNATION

The zoning designation for the subject is IBT-1-1 (International--Business and Trade). The purpose of the IBT zone is to provide for a wide variety of base sector industrial and office uses. It is intended to apply in portions of communities adjacent to the international border, other ports of entry, and areas in transition to higher intensity industries. The IBT designation allows a variety of uses including light industrial, manufacturing, distribution services, research and development, and business services. Single-and multi-tenant office uses, as well as limited commercial retail uses that serve the IBT workforce and businesses, are also permitted.

The subject is within the South District of the Otay Mesa Community Plan (OMCP), designated as partly as Business and International Trade and Park, and about half of this property is designated as a park in the Otay Mesa Community Plan. (Pages 16, 21,25, 29, and 113 of the OMCP).

The site is within the Otay Mesa Community Plan Implementation Overlay Zone (CPIOZ). The purpose of the CPIOZ is to provide site specific analysis to ensure protection of environmentally sensitive resources, construction of circulation infrastructure and conformance with applicable policies of the Urban Design Element.

TAX ASSESSMENT

Assessment Year:	2021-2022
Parcel No.	646-100-74
Land:	$6,620,376
Improvements:	$0
Total Assessed Value:	$6,620,376
Tax Bill:	$83,918.20

EASEMENTS AND RESTRICTIONS

First American Title Order Number: N HSC-5676024 (06) dated as of July 20, 2020 has been reviewed together with the easements as mapped and measured on the right of way plat maps and have been considered for the partial interests being appraised.

Items #5 and #6 are old road easements (1896 & 1914) and appear to be the existing adjoining roads.

7. An easement for either or both pole lines, underground conduits and incidental purposes, recorded October 26, 1948 in Book 2996, Page 23 of Official Records. In Favor of: San Diego Gas and Electric Company.

<u>The is one of the right of way plat overlay easements (A) considered in the valuation and has an estimate 50% impact on the fee value.</u>

DRAFT

8. An easement for either or both pole lines, underground conduits together with the right of ingress and egress and incidental purposes, recorded July 27, 1953 in Book 4934, Page 560 of Official Records. In Favor of: San Diego Gas and Electric Company.

The is one of the overlay easements considered in the valuation and has an estimate 50% impact on the fee value.

9. An easement for erect, construct, reconstruct, replace. repair, maintain together with the right of ingress and egress and incidental purposes, recorded December 27, 1989 as Instrument No. 89-699811 of Official Records. In Favor of: San Diego Gas and Electric Company, a corporation.

The is one of the overlay easements considered in the valuation and has an estimate 50% impact on the fee value.

11. An easement for public road, slope and incidental purposes, recorded June 09, 2009 as Instrument No. 2009-0310110 of Official Records. In Favor of: State of California. Affects: as described therein

The is one of the overlay easements considered in the valuation and has an estimate 50% impact on the fee value.

Fairly typical slope easement that reserves the right to remove slopes in the future by removing the necessity for the slope by providing other lateral support

12. An easement for transmission and distribution of electricity, communication facilities and incidental purposes, recorded June 09, 2009 as Instrument No. 2009-0310163 of Official Records. In Favor of: San Diego Gas & Electric Company, a corporation.

This easement is to erect, construct, change the size of, improve, reconstruct, relocate, repair, maintain and use facilities consisting of poles, wires, cables and appurtenances for the transmission and distribution of electricity as well as underground facilities and appurtenances for the transmission and distribution of electricity and communication facilities, overhead and/or underground and appurtenances. Grantee has the right to choose location within the easement and has the right of ingress and egress, to, from and along this easement in, upon, over and across the hereinafter described lands. Grantee further has the right, but not the duty to clear and keep this easement clear from explosives, buildings, structures and materials.

Grantor grants to Grantee the right to erect and maintain on Grantor's property adjacent to this easement such anchorage as may be necessary for Grantee's purposes. Grantor shall not erect, place or construct, nor permit to be erected, placed or constructed, any building or other structure, plant any tree, drill or dig any well, within this easement. Grantor shall not increase or decrease the ground surface elevations within this easement after installation of Grantee's facilities, without prior written consent of Grantee.

Grantee shall have the right but not the duty, to trim or remove trees and brush along or adjacent to this easement and remove roots from within this easement whenever Grantee deems it necessary. Said right shall not relieve Grantor of the duty as owner to trim or remove trees and brush to prevent danger or hazard to property or persons.

The is one of the overlay easements considered in the valuation and has an estimate 50% impact on the fee value.

13. The terms, provisions and easement(s) contained in the document entitled "Easement Agreement for Drainage Channel" recorded June 25, 2009 as Instrument No. 2009-0349303 of Official Records.

- Agreement identifies a perpetual, non-exclusive easement for an earthen drainage channel to drain surface water and for the construction, maintenance and repair of that channel.

DRAFT

- Grantor, Grantee, the City of San Diego and any other governmental agency with jurisdiction may mutually agree in the future that the Channel Easement is no longer necessary. Then Grantor and Grantee may terminate and quitclaim all rights and obligations hereunder.
- Grantee shall be allowed to access, enter onto and use the property, whether within or outside of the Channel Easement Area, as reasonably necessary or appropriate to install and maintain the Channel. Grantee shall install the Channel at its sole cost and expense and shall maintain the Channel.
- Grantor's rights to improve and use the Channel Easement Area shall be limited to: (a) landscaping; and (b) using the Channel for drainage with the proper approvals from all government agencies with jurisdiction.
- If at any time Grantor or any successor in interest to Grantor shall develop the property, then all obligation of Grantee for maintenance of the Channel shall cease and it shall be the obligation of Grantor and Grantor hereby covenants to either (i) maintain the Channel and continue to allow Grantee the right to use it for drainage, or (ii) provide alternative approved drainage.

The is one of the overlay easements considered in the valuation and has an estimate 50% impact on the fee value.

14. Lien for abatement in favor of City of San Diego. Against: Chang Jaw Min Tr. Amount: $7,500.00, and any other amounts due thereunder. Recorded: November 05, 2014 as Instrument No. 2014-0482761 of Official Records. This item is presumed cleared in the most recent sale transaction.

The appraiser has relied on the right of way plat maps provided and has considered the easements that have been platted by the engineer for the partial interests being appraised.

A. Indicates Centerline Of Existing SDG&E Electric Transmission Line Easement Rec. 10/26/1948 In Bk. 2996, Pg. 23, O.R., No Width Given,
B. Indicates Centerline Of Existing SDG&E Easement Rec. 07/27/1953 In Bk. 4934, Pg.560, O.R., No Width Given
C. Indicates Public Street Easement Per File No. 89-538670, Rec. 10/05/1989, O.R.

FLOOD ZONE CLASSIFICATION

Flood Zone Code: X. Refers to an area with minimal flooding risk
Flood Zone Panel: 06073C2200G
Panel Date: 05/16/2012
Zone Source: FEMA

PRESENT USE

The present use vacant, raw land with a perimeter fence.

IMPROVEMENTS

None.

DRAFT

HIGHEST AND BEST USE – BRITANNIA PROPERTY

Highest and Best Use considers the subject "as is." This analysis considers four basic elements: 1) legal permissibility; 2) physical possibility; 3) financial feasibility; and 4) maximum productivity.

PROBABLE LEGAL USES

The subject is zoned IBT-1-1 (International--Business and Trade) and the land use is designated as Business and International Trade and Park. The purpose of the IBT zone is to provide for a wide variety of base sector industrial and office uses. It is intended to apply in portions of communities adjacent to the international border, other ports of entry, and areas in transition to higher intensity industries. Based on this, the subject legal uses include an assortment of industrial and commercial uses, such as support business uses for the border activities, including trucking and cross border activities.

About half of this property is designated as a park in the community plan. The Otay Mesa Community Plan Update (March 11, 2014) designated a portion of Britannia Innovation property as park land for the "grand park". See the exhibits on pages 16, 21,25, 29, and 113 of the OMCPU that a portion of the Britannia Innovation property as park.

The broker describes the condition as raw and there are known environmental limitations based on current information but no specific studies. Although there are no apparent environmental issues, the land use for park influences about one-half of the site. There are no known extraordinary development costs but road widening and improvement would be needed. Utilities are available in the area and this location adjoins the recently approved Central Village Specific Plan, which includes mixed uses including residential uses.

The property is subject to general area environmental constraints as found locally in raw land, but no specific areas are identified, and the subject is not within the Multiple Habitat Planning Area (MHPA) or the Vernal Pool Habitat Conservation Plan (VPHCP) overlay. Development approval would require biological study to identify environmental conditions, which if found would require some form of mitigation and or avoidance. The area is known to have vernal pools and burrowing owls (BUOW) as well as other sensitive habitats.

PHYSICALLY POSSIBLE USES

The subject has a generally level topography at and slightly below street grade and has evidence of a ponding area near the southeast corner, which appears to be the direction of drainage across the site. Access and visibility are good along Airway Road, Britannia Boulevard and Cactus Road and utilities are available in the area. Future development of the property will require dedication for widening and road improvements.

The subject is physically capable of an assortment of industrial uses as well as park.

FINANCIALLY FEASIBLE USES

The test for financial feasibility results from measuring and finding a positive return to the land.

The industrial real estate market and opportunities have been improving in the Otay Mesa area over the past few years. The subject location overall is suitable for an assortment of industrial uses and the area is being promoted for border and international trade activities and is also influenced by the newly approved Central Village Specific Plan which includes an assortment of residential and mixed uses.

In addition to the development opportunities, the subject location has an opportunity for open space/ mitigation uses. The value range for mitigation properties is potentially in the range from $100,000 to $200,000 per acre, which is less than the value of even raw industrial lands but could be potentially available as saleable mitigation property for potential off-site mitigation to private developers and/or governmental agencies. This type of open space use would not trigger required dedication or road

DRAFT

improvements so potentially the total gross acreage might be available for this use and value.

MAXIMAL PRODUCTIVITY

Primarily considering the location along major circulation and truck routes, the subject is best suited to border oriented industrial activities.

However, this use is for the larger parcel uses that would have road widening requirements. An alternate "non-triggering" use has been adopted for the current partial acquisition appraisal.

ALTERNATE HIGHEST and BEST - REQUIRED DEDICATION

The subject property is raw, vacant land parcels with frontages on circulation element roads. The easement areas proposed for acquisition would be an element of "Required Dedication" for any new development approval. Land Development Code (LDC) Section 142.061 identifies when public improvements are required, and Development Services Department confirmed that a discretionary development would trigger the need for public improvements, which would include right of way dedication. Depending on the specific project, additional public improvements, such as the circulation element road improvements, could also be required but that exact determination would be made during the entitlement process.

Since eventual development would trigger required dedication of the proposed easement areas, those areas could be considered to have a nominal value. The alternate valuation methodology provides a reasonable compensation to the property owner. The appraisal has considered an Alternate Valuation based on uses that could be exempt from "Required Dedication," and the considered use involves an open space use, including mitigation use. The alternate valuation methodology sometimes refers to "non-triggering" uses and values. REFER TO EARLIER SECTION FOR ADDITIONAL REQUIRED DEDICATION DETAILS.

For the subject, the appraiser contacted Marlon I. Pangilinan, Senior Planner, City of San Diego Planning Department to confirm that discretionary approval for use or development will require that the road frontages be dedicated (Required Dedication) for street purpose and/or be required to be improved. He indicated that he referred to staff in DSD Transportation and their response was dedication would be required.

DRAFT

VALUATION METHODOLOGY – BRITANNIA PROPERTY

Reference is made to the earlier section which identified that the valuation methodology for the subject property has been guided by the need to provide a valuation that is based on the alternate "non-triggering" use, which focuses on uses that would be exempt from the required dedication previously discussed. This requirement was outlined in the Highest and Best Use section. The limited non-triggering uses focus on open space use, which includes marketing the property to private and public users for mitigation uses.

The details of the market data and valuation process are as previously described and a fair market value for use in the appraisal has been estimated to equal $135,000 per acre, equal to $3.10 per square foot for the partial acquisition.

VALUE OF THE WHOLE BEFORE ACQUISITION

FEE SIMPLE VALUE – BRITANNIA	
37.9 acres @ $135,000 per acre ($3.10 per square foot)	$5,116,500
Rounded to	$5,120,000

The property was acquired for $7,250,000. HOWEVER, The valuation was guided by uses that would not trigger "required dedication." Since Airway Road, Britannia Road and Cactus Road are circulation element roads, development of the adjoining properties would require dedication of the right of way as well as construction of the road improvements.

DESCRIPTION AND VALUATION OF THE PART TO BE ACQUIRED


The project requires a permanent easement within the subject larger parcel. The portion to be acquired is a strip of varying depth along the frontages of Airway Road, Britannia Boulevard and Cactus Road, currently raw, vacant land with a cyclone fence.

The valuation process for the subject easement involves the analysis of the easement and the rights to be acquired. The valuation of an easement is a unique part of the appraisal process because there are usually no open market sales on which to base an opinion of value. Easements are usually acquired by public agencies having power of condemnation and few transactions of this type meet the test of the open market or arm's length sales. Estimating the value of easements becomes a matter of appraisal judgment based on analysis of the easement being acquired and familiarity with other easement acquisitions. The value of an easement is generally expressed as a percentage of the underlying fee. The impact of an easement can be equivalent to a taking of the fee interest and represent 100 percent of the fee value or it may be so trivial as to represent only nominal impact, or 0% of the fee. Valuation of the easement is a two-step process involving analysis of the language of the document creating the easement to determine what rights are restricted and estimating a percentage of the total fee value as represented by the easement rights. There is no "standard" factor to be applied to easement valuation. However, the appraisers must determine a factor to apply to the fee value and consider any damages to the remainder property. Due to the nature of the project and scope of the appraisal, the appraisers have considered damage implications in the selection of an easement factor.

An easement for public right of way is typically considered as equivalent to a fee taking, equal to 100% of the fee simple value.

DRAFT


DESCRIPTION OF THE PART TO BE ACQUIRED



LEGEND

INDICATES STREET EASEMENT ACQUIRED
AREA = 1.930 AC. MORE OR LESS

AERIAL and ROAD SECTIONS



Property rights are needed for the widening of three circulation element roads, including Airway Road, Britannia Boulevard and Cactus Road as part of their traffic mitigation. The proposed acquisition for the street widening will be in the form of a Permanent Street Easement. A Temporary Construction Easement (TCE) is also required to enable the road improvement. NOTE: At this time the commencement date is unknown.

Airway Road and Britannia Boulevard are both shown on the circulation element in this location as a 6-lane Major Arterials and Cactus Road is shown as a 4-lane Major Arterial. The ultimate street design includes bike lanes and raised center median. Intersection turn lanes are also required, which could add additional width. However, the current acquisition and road improvements will be a phased development and the road is not being improved to full width or final improvement configuration. The current project is generally providing road pavement and A.C. berms as required.

STREET EASEMENT – 1.93 acres (84,070.8 square feet)

The widening contains 1.93 acres and includes areas with varying depths of 12 to 17 feet along the west side of Cactus Road, 26 to 40 feet along the south side of Airway Road and 12 to 20 feet along the west side of Britannia Boulevard. There are existing easements that are present in certain portions of the proposed easement locations.

The street easement widening is within raw land portions of the existing street frontages in areas that would be required for dedication and road improvements for discretionary development approval. There are sections of perimeter cyclone fencing that will be relocated or replaced with a fence of equal utility.

No separate areas for slope or drainage have been identified.

DRAFT

TEMPORARY CONSTRUCTION EASEMENT – 1.133 acres (49,365.68 square feet)

The project engineer identified a need for a construction easement (TCE) that goes beyond the new ROW limits as shown on an included exhibit. The TCE is generally based on 10-feet from the tow of slope/daylight line.

The Temporary Construction Area contains an area of 49,365.68 square feet and adjoins the interior lines of the proposed street widening along Airway Road, Britannia Boulevard and Cactus Road. The requested term will be 12 months. At this time the commencement date is unknown.

The area of the TCE also falls within the raw land portions of the existing street frontages in areas that would be required for dedication and road improvements for discretionary development approval. Also, there is a portion of the TCE that is within an existing Drainage Easement within the larger parcel west of Britannia Boulevard.

VALUE OF THE PART ACQUIRED AS PART OF THE WHOLE

The value of the part to be acquired considers that if developed, there would be an element of "required dedication" as part of the discretionary approval process. This requirement was outlined in the Highest and Best Use section.

The street easement value is based on a value for the subject that would not trigger "required dedication" and also considers existing easements in the acquisition areas.

The alternate non-triggering land use portions have been valued as open space with a possible opportunity for mitigation use. The portions of the property to be acquired have used $135,000 per acre as the fee simple land basis.


PUBLIC STREET EASEMENT – 1.93 acres (84,070.8 square feet)

A typical public street easement grants to The City of San Diego a permanent easement and right-of-way for public street, including all incidents and appurtenances thereto, together with the right of ingress and egress, over, under, upon, along and across all that real property described.

The acquisition of the street easement is valued as of the effective date of appraisal and the property rights are equal to 100% of the fee simple ownership but also considers the impact of existing easements.

DRAFT

PLATS WITH EXISTING EASEMENT OVERLAYS and CONSTRUCTION EASEMENT (TCE)



OVERLAP TOTALS FROM PLAT Page 5 (Revised 9/21/2022)

Overlap Document	Size	Location and Impact
Slope Easement (2009):	22,657.96 S.F.	Along south side of Airway Road. Impact 50% of fee value.
Utility Easement To SDGE (2009):	19,043.45 S.F.	Along south side of Airway Road. Impact 50% of fee value.
Drainage Easement (2009):	1,007.44 S.F.	In eastern area parallel to Britannia Boulevard. Impact 50% fee value.fo
46' Wide Aerial Easement To SDGE (1989):	9,626.78 S.F.	Along east side Cactus Road. Impact 50% fee value.
Centerline of SDGE Elec. Easement (1948, 1953):	1,470.80 L.F.	Unplotted but appear to be within other overlays. No further adjustment.
Temp. Slope Construction Easement:	49,365.68 S.F.	Rent loss calculation follows.

The public street easement is typically considered as equivalent to a fee taking, equal to 100% of the fee value.

Existing easement overlaps required an adjustment since the impacted area has a reduced fee simple value in the before condition. The new easement acquisition value is adjusted to reflect the impact of existing overlay easements below.

EASEMENT SEGMENTS	LOCATION/ CONSTRAINTS	SIZE (ACRE)	VALUE PER SF	EASEMENT FACTOR	VALUE
STREET EASEMENT	Surface & Subsurface	84,070.80 1.930	$3.10	100%	$260,619
Adjustment For Existing Easements					
Less: Existing Slope Easement	Surface & Subsurface	22,658 0.520	$3.10	50%	($35,120)
Less: Existing Drainage Easement	Surface & Subsurface	1,007 0.023	$3.10	50%	($1,562)
Less: Existing Utility Easement SDGE 2009	Surface & Subsurface	19,043.45 0.437	$3.10	50%	($29,517)
Less: Existing Aerial Easement SDGE 1989	Surface & Subsurface	9,626.78 0.221	$3.10	50%	($14,922)
Centerline SDG&E Elec. Easement (1948, 1953)					
TOTAL					$179,499
ROUNDED					$179,500

VALUE OF THE REMAINDER AS PART OF THE WHOLE

The value of the remainder as part of the whole in the before condition is equal to the difference between the total property value in the before condition and the value of the property to be acquired. The value of the remainder as part of the whole is calculated as follows.

Value of the Larger Parcel (Land Only) – Before Condition	**$5,120,000**
Value of the Property to be Acquired	**($179,500)**
Value of the Remainder as Part of the Whole	**$4,940,500**

DRAFT

VALUE OF THE REMAINDER IN THE AFTER CONDITION, BEFORE BENEFITS

In order to estimate severance damages, it is necessary to estimate the value of the remainder parcel in the after condition, as severance damages can result from the acquisition or construction of the proposed project. The permanent acquisitions total 1.93 acres. However, the acquisition area is a portion of the property that would be part of the required dedication area for development approvals. In addition, the acquisition areas have considerable existing easement overlays for drainage, slope and utilities in the before condition. The highest and best use of the subject is the same in the after condition as in the before condition. Severance Damage is estimated as $0.

BENEFITS

Since there are no damages, benefits were not measured. However, the project could be a benefit to the subject property on a general and specific basis due to the traffic mitigation improvements. In addition, the project eliminates some of the subject road improvement costs for future development.

TEMPORARY CONSTRUCTION AREA

The temporary construction area TCE) to be acquired is 1.133 acres (49,365.68 square feet). A typical method to estimate the value for a temporary construction easement is accomplished through use of a rate of return. The value is estimated based on a rent factor. Land rents in the region are typically calculated at 9% to 10% per year of the underlying land value. In order to estimate land rent factors, the appraiser relied on experience and review and analysis of other land rents. The appraiser estimates a rent factor at 10% per year of the underlying land value.

The land value is based on a value for the subject that would not trigger "required dedication," and this is determined to be a mitigation use as discussed earlier, with an estimated value of $3.10 per square foot. The temporary construction area has an estimated rental value as follows:

49,365.68 square feet times $3.10 per SF, times 10%/year, times one year (12 months) = $15,303, or $15,300 (R).

TOTAL COMPENSATION

Value of the Whole Before Acquisition	**$5,120,000**
Value of the Part Acquired As Part of The Whole	**($179,500)**
Value of the Remainder As Part of The Whole	**$4,940,500**
Value of the Remainder After Acquisition before Consideration of Benefits	**$4,940,500**
Severance Damage	**None**
Value of the Remainder After Acquisition and After Consideration of Benefits	**$4,940,500**
Benefits	**None measured**
Net Damage or Benefits	**None measured**
Temporary Construction Area	**$15,300**
TOTAL VALUE OF RIGHTS TO BE ACQUIRED	**$194,800**

DRAFT

EXECUTIVE SUMMARY – PAEZ PROPERTY

IDENTIFICATION	PAEZ PROPERTY
LOCATION	Cactus Road & Airway Road, San Diego, CA 92154 (Identified as 7020 Airway Road in planning documents)
ASSESSOR PARCEL NUMBER	646-100-77
CURRENT USES	Vacant Land
OWNERS OF RECORD	Joseph Paez, Jr.
DATE OF VALUE	August 21, 2022
SITE DATA	The subject is a 39.62± acre vacant parcel with perimeter fencing. Zoning is AR-1-1, CC-3-6, RM-2-5 and RM-3-7 and no MHPA exists on this property. Land use is MH Mixed Use and MH Multi-Family within Central District of the Otay Mesa Community Plan. The subject parcel is level generally at street grade and has frontage on Airway Road and Cactus Road.
HIGHEST AND BEST USE	A Non-Development Alternate Highest and Best Use that would not trigger "Required Dedication" has been used. This use is open space including possible sale or use for mitigation.
SPECIAL LIMITING CONDITION	A Non-Development Alternate Highest and Best Use that would not trigger "Required Dedication" has been used.


VALUES

Value of the Whole Before Acquisition (Land Only)	**$5,350,000**
Value of the Part Acquired as Part of the Whole	**$88,100**
Value of the Remainder	**$5,261,900**
Severance Damage	**None**
Benefits	**None**
Temporary Construction Area	**$8,100**
VALUE OF RIGHTS TO BE ACQUIRED	**$96,200**

DRAFT

EXHIBITS –PAEZ





SUBJECT PHOTOS – PAEZ
August 21, 2022 by James Naughton, Jr. MAI




Northeast view from Airway/Cactus corner.



View east along Airway Road. Shows existing slope easement overlay area.



North view along Cactus from Airway Road. Subject to right.



South view along Cactus. Subject on left.

DRAFT

INTRODUCTION - PAEZ

PURPOSE OF THE APPRAISAL

This appraisal is intended to estimate fair market value of the property rights to be acquired for the Epoca Project as part of their offsite road widening requirements.

USE AND USER OF THE APPRAISAL

This appraisal is prepared to assist ColRich Communities in acquiring property rights for the widening of Airway Road and Cactus Road.

PROPERTY RIGHTS APPRAISED

The proposed acquisitions include Public Street Easements and Temporary Construction Easements (TCEs). The methodology includes estimates of fee simple estate values and easement values for each ownership. The appraisal considers damage issues to the remainder parcel.

IDENTIFICATION OF THE PROPERTY

The subject property "Larger Parcel" has been identified based on the three unities of ownership, contiguity and use (highest and best use).

The Larger Parcel is defined as Paez Property, Airway Road and Cactus Road, San Diego, CA 92154; APN: 646-100-77. The subject is one APN with 39.62± acres.

Title is vested as: Joseph Paez, Jr.

LEGAL DESCRIPTION - Real property in the City of San Diego, County of San Diego, State of California, described as follows:

The southwest quarter of the northeast quarter of section 33, township 18 south, range 1 west, San Bernardino Base and Meridian, in the County of San Diego, State of California, according to United States Government Survey thereof.

Excepting therefrom that portion described in final order of condemnation recorded July 13, 2007 as instrument No. 2007-0469983 of Official Records.

Also excepting therefrom that portion described in final order of condemnation recorded October 12, 2010 as Instrument No. 2010-0547452 of Official Records.

APN: 646-100-77-00

OWNERSHIP AND RECENT HISTORY

The property was acquired by the current owner and recorded on 7/1/2002 from Curtis J Corn by Grant Deed 2002-0552600, with a price of $3,059,500, equal to $77,027 per acre.

The owner has submitted a TM (PTS# 620164) to the city and has been through a couple rounds of plan checks. The TM is identified as City of San Diego Tentative Map Planning Areas 10-13 & 17, Floreo – Otay.

Project 696032 – Scope OTAY MESA (Process 4) Tentative Parcel Map to subdivide one existing lot into 5 proposed lots, located at 7020 Airway Road. The 40.05-acre site is in the RM-2-5, AR-1-1, CC-3-6, RM-3-7 base zone within the Otay Mesa Central Village Specific Plan and Otay Mesa Community Plan area.

Note: The TM shows 37 and 49-foot future dedications on two sides of Cactus Road and 43 and 56-foot future dedications on Airway Road.

DRAFT

EFFECTIVE DATE OF THE APPRAISAL

The effective date of the appraisal is August 21, 2022, the date of the most recent inspection.

DATE OF REPORT

The date of this report is the date of the cover letter.

DRAFT

SITE DESCRIPTION AND ANALYSIS – PAEZ PROPERTY

LOCATION

The subject property is located at the corner of Airway Road and Cactus Road and adjoins State Route 905 along the northern border. The location is within the Central District of the Otay Mesa Community in the City of San Diego, 92154 and is within the Central Village Specific Plan.

SIZE AND SHAPE

The Assessor's record and the multiple listing identify the property as 39.62± acres in one parcel, proposed to be split into 5 parcels. The shape is a slightly irregular polygon.

TOPOGRAPHY

The subject parcel is predominately level and slightly below street grade. The approximate elevation ranges from 505 feet above sea level at the northwest corner to about 520 feet at the southeast corner. A natural drainage appears along the northern edge bordering State Route 905.

SOIL

A soils report was not provided for review. According to mapping and data from the County of San Diego as presented by Land Use Environmental Group (LUEG), the soils are Stockpen gravelly clay loam, 0 to 2 percent slopes and 2 to 5 percent slopes. The appraiser assumes there are no soil conditions that impact current or future legal uses of the land or land value.

ENVIRONMENTAL STUDY

The appraiser has not been provided a specific environmental study or report. The County's LUEG identifies the vegetation as 18300 Extensive Agriculture - Field/Pasture, Row Crops.

No Multiple Habitat Planning Area (MHPA) exists on this property.

STREET IMPROVEMENTS

The subject has frontage along the north side of Airway Road and the east side of Cactus Road. Airway Road is shown on the circulation element in this location as a 6-lane Major Arterial and Cactus Road is shown as a 4-lane Major Arterial, however current conditions have Airway Road as 2 lanes transitioning to 3 lanes and Cactus Road as 2 lanes. All of the frontages are only partially improved (paving) and would require dedication and road improvements if the property is developed. Specific road requirements would be identified upon plan submission. The following is general road design from the published materials (Street Design Manual).

A Four Lane Major Street design has a 120 foot right of way width, to include bike lanes and raised center median. Intersection turn lanes are also required.

A Six Lane Major Street design has a 140 to 152 foot right of way width, to include bike lanes and raised center median. Intersection turn lanes are also required.

The current width along the subject's south frontage is 40 feet and the distance from centerline is 20 feet. Cactus Road along frontage is also 40-foot width.

UTILITIES

Public water and electric service are available in the area. Otay Water District provides potable water to the majority of the Specific Plan area (east of Heritage Road) via connections to the existing and planned water mains located in the rights-of-way of Cactus, Airway, Heritage, and Siempre Viva Roads.

DRAFT

The City of San Diego is the sewer collection system provider for the area. As of 2017, sewer flows generated within the Specific Plan area were conveyed to a pump station located near Cactus Road and Siempre Viva Road. From the pump station, sewer flows are conveyed to a gravity sewer in Otay Mesa Road that connects to the City's Otay Valley Trunk Sewer.

ZONING AND LAND USE DESIGNATION

The zoning designation for the subject includes RM-2-5, AR-1-1, CC-3-6, RM-3-7 base zone within the Otay Mesa Central Village Specific Plan and Otay Mesa Community Plan area.

The subject is within the Central South District of the Otay Mesa Community Plan, within the 229.2-acre Central Village Specific Plan, a mixed-use village located in the central portion of the City of San Diego's Otay Mesa Community. The Otay Mesa Community Plan designates this plan area as "neighborhood village" and "community village" land uses, with land use categories for a range of housing choices located near community-serving commercial uses, civic uses, a mixed-use village that integrates residential, commercial, civic, and recreational uses.



The CENTRAL VILLAGE is a 229.2-acre village and provides for the development of up to 4,485 dwelling units and is divided for planning purposes into 22 planning areas, containing the following land uses:

Moderate to High Density (MH) Mixed Use: Provides for up to 139,700 square feet of commercial land uses and 2,046 homes on 54.5 acres, within an allowable density range of 15 to 44 dwelling units per acre (du/ac); Moderate to High Density (MH) Multi-Family: Provides for 495 homes on 12.4 acres, within an allowable density range of 15 to 44 du/ac; Medium Density (MD) Multi-Family: Provides for 1,444 homes on 50.3 acres, within an allowable density range of 15 to 29 du/ac; Low Density (LD) Multi-Family: Provides for 500 homes on 28.3 acres, within a density range of 10 to 29 du/ac; Parks: Provides for passive and active recreation on 16.1 acres, intended to meet a portion of the population-based parkland requirements within the village; Open Space: Provides for the preservation of 15.9 acres of

undeveloped open space; and School/Recreation: Provides a public school site with public recreation areas on 13.1 acres.

TAX ASSESSMENT

Assessment Year:	2021-2022
Parcel No.	646-100-77
Land:	$4,093,407
Improvements:	$0
Total Assessed Value:	$4,093,407
Tax Bill:	$52,722.68

EASEMENTS AND RESTRICTIONS

First American Title, Order Number: N HSC-5676014 (DG), dated as of February 26, 2021, updated March 8, 2021 has been reviewed together with the easements as mapped and measured on the right of way plat maps, and have been considered for the partial interests being appraised.

Items #3 and #4 are old road easements (1896 & 1901) and appear to be the existing adjoining roads.

5. An easement for public utilities, ingress and egress and incidental purposes, recorded October 19, 1948 as Book 2985, Page 317 of Official Records. In Favor of: San Diego Gas and Electric Company. Affects: As described therein. Affects 18 feet along west property line and appears to be within existing roadway. Nominal impact.

6. An easement for public utilities, ingress and egress and incidental purposes, recorded July 22, 1953 as Book 4930, Page 330 of Official Records. In Favor of: San Diego Gas and Electric Company. Affects 6 feet along the east property line. – Nominal impact.

7. The fact that the land lies within the boundaries of the Otay Mesa Reorganization Project Area, as disclosed by the document recorded March 14, 1985 as Instrument No. 85-086495 of Official records. No impact.

8. The effect of a map purporting to show the land and other property, filed Map No. 13227 of Record of Surveys. No impact.

10. A notice of assessment recorded August 25, 2004 as Instrument No. 2004-0808880 of Official Records, executed by City of San Diego. Standard FBA notice.


11. Abutter's rights of ingress and egress to or from the State Highway, adjacent thereto have been relinquished in the document recorded July 13, 2007 as Instrument No. 2007-0469983 of Official records. Nominal impact.

The is one of the right of way plat overlay easements (A) considered in the valuation and has an estimate 50% impact on the fee value.

FROM R/W Plat

A. INDICATES CENTERLINE OF EXISTING SDG&E ELECTRIC TRANSMISSION LINE EASEMENT REC. 10/19/1948 IN BK. 2985, PG. 317, O.R. NO WIDTH GIVEN; EASEMENT CENTERLINE LOCATED 18' EASTERLY & PARALLEL WITH CENTERLINE OF CACTUS ROAD.
B. INDICATES SLOPE EASEMENT (PARCEL 33278-4) PER FINAL ORDER OF CONDEMNATION DOC. NO.2010-0547452, 10/12/2010, O.R.

DRAFT



FLOOD ZONE CLASSIFICATION

Flood Zone Code: X. Refers to an area with minimal flooding risk
Flood Zone Panel: 06073C2200G
Panel Date: 05/16/2012
Zone Source: FEMA

PRESENT USE

The present use vacant, raw land with a perimeter fence.

IMPROVEMENTS

None.

DRAFT

HIGHEST AND BEST USE – PAEZ PROPERTY


Highest and Best Use considers the subject "as is" without improvements. This analysis considers four basic elements: 1) legal permissibility; 2) physical possibility; 3) financial feasibility; and 4) maximum productivity.

PROBABLE LEGAL USES

The subject is within the Central South District of the Otay Mesa Community Plan, within the 229.2-acre Central Village Specific Plan, a mixed-use village located in the central portion of the City of San Diego's Otay Mesa Community. The Otay Mesa Community Plan designates this plan area as "neighborhood village" and "community village" land uses, with land use categories for a range of housing choices located near community-serving commercial uses, civic uses, a mixed-use village that integrates residential, commercial, civic, and recreational uses.

The zoning designation for the subject includes RM-2-5, AR-1-1, CC-3-6, RM-3-7 base zone within the Otay Mesa Central Village Specific Plan and Otay Mesa Community Plan area.

The CENTRAL VILLAGE Specific Plan is a regulatory document that sets forth physical design standards and policies relative to land use designations; building intensity; landscaping; architectural character; vehicular and pedestrian circulation; and other infrastructure improvements such as water, wastewater, and drainage systems. When using this Specific Plan to review future development projects or determine appropriate uses for a site, the applicable zoning regulations of the City's Land Development Code that are not superseded by the design standards contained in this Specific Plan should also be reviewed to ensure full implementation of this plan. The Specific Plan provisions shall take precedence over the Land Development Code. Where the Specific Plan is silent on a topic, the Land Development Code requirements shall remain in force.



PLANNING AREAS	GENERAL PLAN LAND USE	SPECIFIC PLAN LAND USE	TARGET DENSITY	GROSS ACRES	NET ACRES*	DWELLING UNITS	MAX. COMMERCIAL SQUARE FOOTAGE
2, 4, 10	Neighborhood Village (15-44 du/ac)	MH Mixed Use	35-44	36.4	32.8	1,389	98,200
3, 9	Neighborhood Village (15-44 du/ac)	MH Mixed Use	25-40	23.3	21.7	657	41,500
1	Residential - Medium to Medium High (15-44 du/ac)	MH Multi Family	35-44	6.7	6.7	295	--
13	Residential - Medium to Medium High (15-44 du/ac)	MH Multi Family	25-40	6.5	5.7	200	--
5, 6, 11, 12	Residential - Medium (15-29 du/ac)	MD Multi Family	20-29	55.0	50.3	1,444	--
7, 8	Residential - Low Medium to Medium (10-29 du/ac)	LD Multi Family	15-29	29.7	28.3	500	--
14**	Institutional	School/Recreation	--	15.5	13.1	--	--
15, 16, 17, 18	Population-Based Park	Park	--	16.1	16.1	--	--
19, 20, 21, 22	Open Space	Open Space	--	15.9	15.9	--	--
--	Public Roadways	Public Roadways	--	24.1	18.6	--	--
		PROJECT TOTALS	--	229.2	229.2	4,485	139,700

The property is subject to general environmental constraints, but no specific areas are identified, and the subject is not within the Multiple Habitat Planning Area (MHPA) or the Vernal Pool Habitat Conservation Plan (VPHCP) overlay, Development approval would require biological study to identify environmental conditions, which if found would require some form of mitigation. The area is known to have vernal pools and burrowing owls (BUOW) as well as other sensitive habitats. The status of the subject environmental condition is unknown but there were no known conditions currently identified.

DRAFT

PHYSICALLY POSSIBLE USES

The subject has a generally level topography at and slightly below street grade. Access and visibility are good along Airway Road and Cactus Road as well as visibility from State Route 905. Utilities are available in the area. Future development of the property will require dedication for widening and road improvements.

The subject is physically capable of an assortment of mixed uses, including residential and commercial uses.

FINANCIALLY FEASIBLE USES

The test for financial feasibility results from measuring and finding a positive return to the land.

The real estate market and opportunities have been improving in the Otay Mesa area over the past few years. The subject location overall is suitable for an assortment mixed use development including residential and commercial uses in a village type atmosphere within the Central Village Specific Plan.

In addition to the development opportunities, the subject location has an opportunity for open space/ mitigation uses. The value range for mitigation properties is potentially in the range from $100,000 to $200,000 per acre, which is less than the value of even raw industrial lands but could be potentially available as saleable mitigation property for potential off-site mitigation to private developers and/or governmental agencies. This type of open space use would not trigger required dedication or road improvements so potentially the total gross acreage might be available for this use and value.

MAXIMAL PRODUCTIVITY

Primarily considering the uses identified in the Central Village Specific Plan, the subject is best suited for an assortment of mixed uses to include residential and commercial opportunities.

However, this use is for the larger parcel uses that would have road widening requirements. An alternate "non-triggering" use has been adopted for the current partial acquisition appraisal.

ALTERNATE HIGHEST and BEST - REQUIRED DEDICATION

The subject property is raw, vacant land parcels with frontages on circulation element roads. The easement areas proposed for acquisition would be an element of "Required Dedication" for any new development approval. Land Development Code (LDC) Section 142.061 identifies when public improvements are required, and Development Services Department confirmed that a discretionary development would trigger the need for public improvements, which would include right of way dedication. Depending on the specific project, additional public improvements, such as the circulation element road improvements, could also be required but that exact determination would be made during the entitlement process.

Since eventual development would trigger required dedication of the proposed easement areas, those areas could be considered to have a nominal value. The alternate valuation methodology provides a reasonable compensation to the property owner. The appraisal has considered an Alternate Valuation based on uses that could be exempt from "Required Dedication," and the considered use involves an open space use, including mitigation use. The alternate valuation methodology sometimes refers to "non-triggering" uses and values. REFER TO EARLIER SECTION FOR ADDITIONAL REQUIRED DEDICATION DETAILS.

DRAFT

VALUATION METHODOLOGY – PAEZ PROPERTY

Reference is made to the earlier section which identified that the valuation methodology for the subject property has been guided by the need to provide a valuation that is based on the alternate "non-triggering" use, which focuses on uses that would be exempt from the required dedication previously discussed. This requirement was outlined in the Highest and Best Use section. The limited non-triggering uses focus on open space use, which includes marketing the property to private and public users for mitigation uses.

The details of the market data and valuation process are as previously described and a fair market value for use in the appraisal has been estimated to equal $135,000 per acre, equal to $3.10 per square foot for the partial acquisition.

VALUE OF THE WHOLE BEFORE ACQUISITION

FEE SIMPLE VALUE – PAEZ	
39.62 acres @ $135,000 per acre	$5,348,700
ROUNDED	$5,350,000

The valuation was guided by uses that would not trigger "required dedication." Since Airway Road and Cactus Road are circulation element roads, development of the adjoining properties would require dedication of the right of way as well as construction of the road improvements.

DESCRIPTION AND VALUATION OF THE PART TO BE ACQUIRED


The project requires a permanent easement within the subject larger parcel. The portion to be acquired is a strip of varying depth along the frontages of Airway Road and Cactus Road, currently raw, vacant land with a cyclone fence.

The valuation process for the subject easement involves the analysis of the easement and the rights to be acquired. The valuation of an easement is a unique part of the appraisal process because there are usually no open market sales on which to base an opinion of value. Easements are usually acquired by public agencies having power of condemnation and few transactions of this type meet the test of the open market or arm's length sales. Estimating the value of easements becomes a matter of appraisal judgment based on analysis of the easement being acquired and familiarity with other easement acquisitions. The value of an easement is generally expressed as a percentage of the underlying fee. The impact of an easement can be equivalent to a taking of the fee interest and represent 100 percent of the fee value or it may be so trivial as to represent only nominal impact, or 0% of the fee. Valuation of the easement is a two-step process involving analysis of the language of the document creating the easement to determine what rights are restricted and estimating a percentage of the total fee value as represented by the easement rights. There is no "standard" factor to be applied to easement valuation. However, the appraisers must determine a factor to apply to the fee value and consider any damages to the remainder property. Due to the nature of the project and scope of the appraisal, the appraisers have considered damage implications in the selection of an easement factor.

An easement for public right of way is typically considered as equivalent to a fee taking, equal to 100% of the value.

DRAFT


DESCRIPTION OF THE PART TO BE ACQUIRED



LEGEND

INDICATES STREET EASEMENT ACQUIRED
AREA = 0.893 AC. MORE OR LESS

AERIAL and ROAD SECTIONS



The client seeks to acquire property rights that will be needed for the widening of Airway Road and Cactus Road as part of their traffic mitigation. The proposed acquisitions for the street widening will be in the form of a Public Street Easement. There are no separate slope or drainage easements, but a Temporary Construction Easement (TCE) is also required. NOTE: At this time, the commencement date is unknown.

Airway Road is both shown on the circulation element in this location as a 6-lane Major Arterial and Cactus Road is shown as a 4-lane Major Arterial. The ultimate street design includes bike lanes and raised center median. Intersection turn lanes are also required, which could add additional width. However, the current acquisition and road improvements will be a phased development and the road is not being improved to full width or final improvement configuration. The current project is generally providing road pavement and A.C. berms as required.

STREET EASEMENT – 0.893 acres (38,899.08 square feet)

The widening contains an area of 0.893 acres and includes an area with a varying width from 14 feet to 30 feet parallel to the existing Airway Road and Cactus Road right of way.

The street easement widening is within raw land portions of the existing street frontages in areas that would be required for dedication and road improvements for discretionary development approval. There are sections of perimeter cyclone fencing that will be relocated or replaced with a fence of equal utility.

There are existing easements that are present in certain portions of the proposed easement locations.

DRAFT

TEMPORARY CONSTRUCTION EASEMENT (TCE) – 0.597 acres (25,998 square feet)

The project engineer identified a need for a construction easement (TCE) that goes beyond the new ROW limits as shown on an included exhibit. The TCE is generally based on 10-feet from the tow of slope/daylight line.

The Temporary Construction Area contains an area of 25,998 square feet and adjoins the interior lines of the proposed street widening along both Airway Road and Cactus Road. The requested term will be 12 months. At this time the commencement date is unknown.

The area of the TCE also falls within the raw land portions of the existing street frontages in areas that would be required for dedication and road improvements for discretionary development approval.

VALUE OF THE PART ACQUIRED AS PART OF THE WHOLE

The value of the part to be acquired considers that if developed, there would be an element of "required dedication" as part of the discretionary approval process. This requirement was outlined in the Highest and Best Use section.

The street easement value is based on a value for the subject that would not trigger "required dedication" and also considers existing easements in the acquisition areas.

The alternate non-triggering land use portions have been valued as open space with a possible opportunity for mitigation use. The portions of the property to be acquired have used $135,000 per acre as the fee simple land basis. This is equal to $3.10 per square foot.

PUBLIC STREET EASEMENT – 0.893 acres (38,899.08 square feet)

A typical public street easement grants to The City of San Diego a permanent easement and right-of-way for public street, including all incidents and appurtenances thereto, together with the right of ingress and egress, over, under, upon, along and across all that real property described.


The acquisition of the street easement is valued as of the effective date of appraisal and the property rights are equal to 100% of the fee simple ownership but also considers the impact of existing easements.

EXISTING EASEMENT OVERLAYS – 20,954.35 square feet

The only significant easement overlay for the subject is shown on the right of way plat as Slope Easement (Parcel 33278-4) per final order of condemnation document number 20100054752, 10/12/2010. This is considered to be a typical slope easement that reserves the right to remove slopes in the future by removing the necessity for the slope by providing other lateral support. As the one overlay easement considered in the valuation this overlay is considered to have a 50% impact on the fee value and the easement acquisition value is reduced accordingly.

DRAFT

PLATS WITH OVERLAYS and CONSTRUCTION EASEMENT (TCE)



An easement for public right of way is typically considered as equivalent to a fee taking, equal to 100% of the fee value.

Existing easement overlaps required an adjustment since the impacted area has a reduced fee simple value in the before condition. The new easement acquisition value is adjusted to reflect the impact of existing overlay easements below.

EASEMENT SEGMENTS	LOCATION/ CONSTRAINTS	SIZE (SF)	VALUE PER SF	EASEMENT FACTOR	VALUE
STREET EASEMENT	Surface & Subsurface	38,899 (0.893 ac)	$3.10	100%	$120,587
Less: Existing Slope Easement	Surface	20,954.35	$3.10	50%	($32,479)
TOTAL					$88,108
ROUNDED					$88,100

VALUE OF THE REMAINDER AS PART OF THE WHOLE

The value of the remainder as part of the whole in the before condition is equal to the difference between the total property value in the before condition and the value of the property to be acquired. The value of the remainder as part of the whole is calculated as follows.

Value of the Larger Parcel (Land Only) – Before Condition	**$5,350,000**
Value of the Property to be Acquired	**($88,100)**
Value of the Remainder as Part of the Whole	**$5,261,900**

DRAFT

VALUE OF THE REMAINDER IN THE AFTER CONDITION, BEFORE BENEFITS

In order to estimate severance damages, it is necessary to estimate the value of the remainder parcel in the after condition, as severance damages can result from the acquisition or construction of the proposed project. The permanent acquisitions total 0.893 acres. However, the acquisition area is a portion of the property that would be part of the required dedication area for development approvals. In addition, the acquisition area has a considerable existing easement overlay for slope in the before condition.

The highest and best use of the subject is the same in the after condition as in the before condition. Severance Damage is estimated as $0.

BENEFITS

Since there are no damages, benefits were not measured. However, the project could be a benefit to the subject property on a general and specific basis due to the traffic mitigation improvements. In addition, the project eliminates some of the subject road improvement costs for future development.

TEMPORARY CONSTRUCTION AREA

The temporary construction area (TCE) to be acquired is 0.597 acres (25,998 square feet). A typical method to estimate the value for a temporary construction easement is accomplished through use of a rate of return. The value is estimated based on a rent factor. Land rents in the region are typically calculated at 9% to 10% per year of the underlying land value. In order to estimate land rent factors, the appraiser relied on experience and review and analysis of other land rents. The appraiser estimates a rent factor at 10% per year of the underlying land value.

The land value is based on a value for the subject that would not trigger "required dedication," and this is determined to be a mitigation use as discussed earlier, with an estimated value of $3.10 per square foot. The temporary construction area has an estimated rental value as follows:

25,998 square feet times $3.10 per SF, times 10%/year, times one year (12 months) = $8,059, or $8,100 (R).

TOTAL COMPENSATION

Value of the Whole Before Acquisition	**$5,350,000**
Value of the Part Acquired As Part of The Whole	**($88,100)**
Value of the Remainder As Part of The Whole	**$5,261,900**
Value of the Remainder After Acquisition before Consideration of Benefits	**$5,261,900**
Severance Damage	**None**
Value of the Remainder After Acquisition and After Consideration of Benefits	**$5,261,900**
Benefits	**None measured**
Net Damage or Benefits	**None measured**
Temporary Construction Area	**$8,100**
TOTAL VALUE OF RIGHTS TO BE ACQUIRED	**$96,200**

DRAFT

EXECUTIVE SUMMARY – CROWN PROPERTY

IDENTIFICATION	CROWN PROPERTY
LOCATION	Airway Road, San Diego, CA 92154
ASSESSOR PARCEL NUMBERS	646-110-19
CURRENT USES	Vacant Land
OWNERS OF RECORD	Crown Enterprises Inc.
DATE OF VALUE	August 21, 2022
SITE DATA	The subject is a 19.7± acre parcel of raw land. Zoning is IBT-1-1 and no MHPA exists on this property. Land use is Business and International Trade within the South District of the Otay Community Plan. The subject parcel is level, slightly below street grade, and has frontage on Airway Road.
HIGHEST AND BEST USE	A Non-Development Alternate Highest and Best Use that would not trigger "Required Dedication" has been used. This use is open space including possible sale or use for mitigation.
SPECIAL LIMITING CONDITION	A Non-Development Alternate Highest and Best Use that would not trigger "Required Dedication" has been used.


VALUES

Value of the Whole Before Acquisition	**$2,660,000**
Value of the Part Acquired as Part of the Whole	**$4,400**
Value of the Remainder	**$2,655,600**
Severance Damage	**None**
Benefits	**None**
Temporary Construction Area	**None**
VALUE OF RIGHTS TO BE ACQUIRED	**$4,400**

DRAFT

EXHIBITS – CROWN





SUBJECT PHOTOS – CROWN
August 21, 2022 by James Naughton, Jr. MAI



Frontage view north on Airway Road.



View east along Airway Road. Frontage has existing easement overlay.



East view along Airway Road.



West view along Airway Road within widening area.

DRAFT

INTRODUCTION – CROWN PROPERTY

PURPOSE OF THE APPRAISAL

This appraisal is intended to estimate fair market value of the property rights to be acquired for the Epoca Project as part of their offsite road widening requirements.

USE AND USER OF THE APPRAISAL

This appraisal is prepared to assist ColRich Communities in acquiring property rights for the widening of Airway Road.

PROPERTY RIGHTS APPRAISED

The proposed acquisitions include a Public Street Easement. The methodology includes estimates of fee simple estate values and easement values for each ownership. The appraisal considers damage issues to the remainder parcel.

IDENTIFICATION OF THE PROPERTY

The subject property "Larger Parcel" has been identified based on the three unities of ownership, contiguity and use (highest and best use).

The Larger Parcel is defined as Crown Enterprises Property, Airway Road, San Diego, CA 92154; APN: 646-110-19. The subject one APN containing 19.7± acres.

Title is vested as: Crown Enterprises, Inc.

LEGAL DESCRIPTION - Real property in the City of San Diego, County of San Diego, State of California, described as follows:

The east half of the northwest quarter of the southwest quarter, section 34, township 18 south, range 1 west, San Bernardino Meridian in the County of San Diego, State of California, according to official plat thereof.

APN: 646-110-19-00

OWNERSHIP AND RECENT HISTORY

The last recorded transfer was recorded 8/13/2004 to Crown Enterprises Inc from Theodore Thiemane by Grant Deed 2004-0772375.

The appraiser made attempts to contact the property owner to determine if there were any specific use or development plans, but the attempts were not successful.

EFFECTIVE DATE OF THE APPRAISAL

The Effective Date of the Appraisal is August 21, 2022.

DATE OF REPORT

The date of this report is the date of the cover letter.

.

DRAFT

SITE DESCRIPTION AND ANALYSIS – CROWN PROPERTY

LOCATION

The subject property is located along the south side of Airway Road with no specific address, east of Britannia Boulevard. The location is within the South District of the Otay Mesa Community in the City of San Diego, 92154.

SIZE AND SHAPE

The subject property contains 19.70± acres in one assessor parcel and has a regular, rectangular shape.

TOPOGRAPHY

The subject parcel is predominately level, slightly below street grade. The approximate elevation ranges from 510 feet above sea level at the northwest corner to about 497 feet at the southeast corner.

SOIL

A soils report was not provided for review. According to mapping and data from the County of San Diego as presented by Land Use Environmental Group (LUEG), the soils are Stockpen gravelly clay loam, 0 to 2 percent slopes. The appraiser assumes there are no soil conditions that impact current or future legal uses of the land or land value.

ENVIRONMENTAL STUDY

The appraiser has not been provided a specific environmental study or report. The County's LUEG identifies the vegetation as 18300 Extensive Agriculture - Field/Pasture, Row Crops.

No Multiple Habitat Planning Area (MHPA) exists on this property.

STREET IMPROVEMENTS

The subject has frontage along the south side of Airway Road, which is designated as a 4-Lane Major Road in this location on the circulation element of the Community Plan. At this time the road is only paved along the frontage and would require dedication and road improvements if the property is developed.

UTILITIES

Public water, electric service and sewer are currently available to the subject area. Water and sewer lines are in Airway Road at the front of the subject parcel, but connection to public sewer would be an additional expense depending on the intensity of any potential redevelopment plan.

ZONING AND LAND USE DESIGNATION

The zoning designation for the subject is IBT-1-1 (International--Business and Trade). The purpose of the IBT zone is to provide for a wide variety of base sector industrial and office uses. It is intended to apply in portions of communities adjacent to the international border, other ports of entry, and areas in transition to higher intensity industries.

The IBT designation allows a variety of uses including light industrial, manufacturing, distribution services, research and development, and business services. Single-and multi-tenant office uses, as well as limited commercial retail uses that serve the IBT workforce and businesses, are also permitted.

The subject is within the South District of the Otay Mesa Community Plan, designated as Business and International Trade.

DRAFT

The site is within the Otay Mesa Community Plan Implementation Overlay Zone (CPIOZ). The purpose of the CPIOZ is to provide site specific analysis to ensure protection of environmentally sensitive resources, construction of circulation infrastructure and conformance with applicable policies of the Urban Design Element.

TAX ASSESSMENT

Assessment Year:	2021-2022
Parcel No.	646-110-19
Land:	$3,347,916
Improvements:	$0
Total Assessed Value:	$3,347,916
Tax Bill:	$42,467.34

EASEMENTS AND RESTRICTIONS

First American Title, Order Number: N HSC-6315005 (DG) dated as of February 26, 2021 has been reviewed together with the easements as mapped and measured on the right of way plat maps and have been considered for the partial interests being appraised.

Item #3 is an easement for public road from July 09, 1897 appears to be the existing right of way for Airway Road although the title company states that the location of the easement cannot be determined from record information.

Item #4 is an easement for right of way to erect, construct, change the size of, improve, reconstruct, relocate, repair, maintain and use facilities consisting of: (1) underground electric facilities, and appurtenances for the transmission and distribution of electricity, (2) underground communication facilities, and appurtenances, together with the right of ingress thereto and egress therefrom and incidental purposes, recorded August 04, 2005 as instrument no. 2005-664962 of official records.

In favor of: San Diego Gas & Electric Company, a corporation. The interest of San Diego Gas & Electric Company, a corporation of said easement has been assigned to Pacific Bell by assignment of easement recorded August 25, 2005 as instrument no. 2005-732592 of official records

This easement impacts the westerly 260 feet of the northerly 49 feet of the subject property and allows subsurface use for electric and communication facilities as well as the right of ingress thereto and egress therefrom by practical routes. It also states that Grantor shall not erect, place or construct, nor permit to be erected, placed or constructed any building or other structure, park any vehicle, deposit any materials, plant any trees and/or shrubs within eight (8) feet of the front of the door or hinged opening of any above ground facility installed within this easement and allows Grantee the right to erect and maintain on Grantor's property immediately adjacent to this easement retaining walls and/or protective barricades as may be necessary for Grantee's purposes. The easement prevents erecting, placing, or storing on said easement any flammable or other hazards and any structures, objects, or earth fills/cuts or other obstructions.

The is one of the overlay easements considered in the valuation and has an estimate 50% impact on the fee value.

FLOOD ZONE CLASSIFICATION

Flood Zone Code: X. Refers to an area with minimal flooding risk
Flood Zone Panel: 060295-06073C2200G
Panel Date: 05/16/2012
Zone Source: FEMA

DRAFT

PRESENT USE

The present use is vacant land.

IMPROVEMENTS

None.

DRAFT

HIGHEST AND BEST USE – CROWN PROPERTY

Highest and Best Use considers the subject "as is." This analysis considers four basic elements: 1) legal permissibility; 2) physical possibility; 3) financial feasibility; and 4) maximum productivity.

PROBABLE LEGAL USES

The subject is zoned IBT-1-1 (International--Business and Trade) and the land use is designated as Business and International Trade and Park. The purpose of the IBT zone is to provide for a wide variety of base sector industrial and office uses. It is intended to apply in portions of communities adjacent to the international border, other ports of entry, and areas in transition to higher intensity industries. Based on this, the subject legal uses include an assortment of industrial and commercial uses, such as support business uses for the border activities, including trucking and cross border activities.

The property is subject to general area environmental constraints as found locally in raw land, but no specific areas are identified, and the subject is not within the Multiple Habitat Planning Area (MHPA) or the Vernal Pool Habitat Conservation Plan (VPHCP) overlay. Development approval would require biological study to identify environmental conditions, which if found would require some form of mitigation and or avoidance. The area is known to have vernal pools and burrowing owls (BUOW) as well as other sensitive habitats.

PHYSICALLY POSSIBLE USES

The subject has a generally level topography at and slightly below street grade. Access and visibility are good along Airway Road and utilities are available in the area. Future development of the property will require dedication for widening and road improvements.

The subject is physically capable of an assortment of industrial uses.

FINANCIALLY FEASIBLE USES

The test for financial feasibility results from measuring and finding a positive return to the land.

The industrial real estate market and opportunities have been improving in the Otay Mesa area over the past few years. The subject location overall is suitable for an assortment of industrial uses and the area is being promoted for border and international trade activities and is also influenced by the newly approved Central Village Specific Plan which includes an assortment of residential and mixed uses.

In addition to the development opportunities, the subject location has an opportunity for open space/ mitigation uses. The value range for mitigation properties is potentially in the range from $100,000 to $200,000 per acre, which is less than the value of even raw industrial lands but could be potentially available as saleable mitigation property for potential off-site mitigation to private developers and/or governmental agencies. This type of open space use would not trigger required dedication or road improvements so potentially the total gross acreage might be available for this use and value.

MAXIMAL PRODUCTIVITY

Primarily considering the location along major circulation and truck routes, the subject is best suited to border oriented industrial activities.

However, this use is for the larger parcel uses that would have road widening requirements. An alternate "non-triggering" use has been adopted for the current partial acquisition appraisal.

ALTERNATE HIGHEST and BEST - REQUIRED DEDICATION

The subject property is raw, vacant land parcels with frontages on circulation element roads. The easement areas proposed for acquisition would be an element of "Required Dedication" for any new development approval. Land Development Code (LDC) Section 142.061 identifies when public

DRAFT

improvements are required, and Development Services Department confirmed that a discretionary development would trigger the need for public improvements, which would include right of way dedication. Depending on the specific project, additional public improvements, such as the circulation element road improvements, could also be required but that exact determination would be made during the entitlement process.

Since eventual development would trigger required dedication of the proposed easement areas, those areas could be considered to have a nominal value. The alternate valuation methodology provides a reasonable compensation to the property owner. The appraisal has considered an Alternate Valuation based on uses that could be exempt from "Required Dedication," and the considered use involves an open space use, including mitigation use. The alternate valuation methodology sometimes refers to "non-triggering" uses and values. REFER TO EARLIER SECTION FOR ADDITIONAL REQUIRED DEDICATION DETAILS.

DRAFT

VALUATION METHODOLOGY – CROWN PROPERTY

Reference is made to the earlier section which identified that the valuation methodology for the subject property has been guided by the need to provide a valuation that is based on the alternate "non-triggering" use, which focuses on uses that would be exempt from the required dedication previously discussed. This requirement was outlined in the Highest and Best Use section. The limited non-triggering uses focus on open space use, which includes marketing the property to private and public users for mitigation uses.

The details of the market data and valuation process are as previously described and a fair market value for use in the appraisal has been estimated to equal $135,000 per acre, equal to $3.10 per square foot for the partial acquisition.

VALUE OF THE WHOLE BEFORE ACQUISITION

FEE SIMPLE VALUE – MILLER	
19.7 acres @ $135,000 per acre	**$2,659,500**
ROUNDED	**$2,660,000**

The valuation was guided by uses that would not trigger "required dedication." Since Airway Road and Cactus Road are circulation element roads, development of the adjoining properties would require dedication of the right of way as well as construction of the road improvements.

DESCRIPTION AND VALUATION OF THE PART TO BE ACQUIRED


The project requires a permanent easement within the subject larger parcel. The portion to be acquired is a 10-foot-wide strip along the frontage of Airway Road, currently raw, vacant land. This location also has an existing utility easement that overlays most of the area.

The valuation process for the subject easement involves the analysis of the easement and the rights to be acquired. The valuation of an easement is a unique part of the appraisal process because there are usually no open market sales on which to base an opinion of value. Easements are usually acquired by public agencies having power of condemnation and few transactions of this type meet the test of the open market or arm's length sales. Estimating the value of easements becomes a matter of appraisal judgment based on analysis of the easement being acquired and familiarity with other easement acquisitions. The value of an easement is generally expressed as a percentage of the underlying fee. The impact of an easement can be equivalent to a taking of the fee interest and represent 100 percent of the fee value or it may be so trivial as to represent only nominal impact, or 0% of the fee. Valuation of the easement is a two-step process involving analysis of the language of the document creating the easement to determine what rights are restricted and estimating a percentage of the total fee value as represented by the easement rights. There is no "standard" factor to be applied to easement valuation. However, the appraisers must determine a factor to apply to the fee value and consider any damages to the remainder property. Due to the nature of the project and scope of the appraisal, the appraisers have considered damage implications in the selection of an easement factor.

An easement for public right of way is typically considered as equivalent to a fee taking, equal to 100% of the value.

DRAFT

DESCRIPTION OF THE PART TO BE ACQUIRED





LEGEND

INDICATES STREET EASEMENT ACQUIRED
AREA = 2,700 SQ. FT. MORE OR LESS

The client seeks to acquire property rights that will be needed for the widening of Airway Road as part of their traffic mitigation. The proposed acquisitions for the street widening will be in the form of a Public Street Easement. There are no separate slope, drainage or temporary construction easements. The larger parcel includes one assessor parcel with a total size of 19.7± acres as vacant land. Zoning is IBT-1-1 with no identified environmental constraints. The subject parcel is level and has frontage on Airway Road.

AERIAL and ROAD SECTIONS





The project involves the widening of Airway Road, which is shown as a circulation element four-lane Major Road but is not currently improved to the ultimate design width. A Four Lane Major has a design width of 120 feet. The ultimate street would include bike lanes and raised center median, but the current phased improvements are not to full width and use an AC berm along the frontage.

However, the current acquisition and road improvements will be a phased development and the road is not being improved to full width or final improvement configuration.

STREET EASEMENT – 2,700 square feet

The widening contains an area of 2,700 square feet and includes an area with a depth of 10 feet parallel to the existing Airway Road right of way for a distance of 270 feet.

TEMPORARY CONSTRUCTION EASEMENT – None

VALUE OF THE PART ACQUIRED AS PART OF THE WHOLE

The value of the part to be acquired considers that if developed, there would be an element of "required dedication" as part of the discretionary approval process. This requirement was outlined in the Highest and Best Use section.

The street easement value is based on a value for the subject that would not trigger "required dedication" and also considers existing easements in the acquisition areas.

The alternate non-triggering land use portions have been valued as open space with a possible opportunity for mitigation use. The portions of the property to be acquired have used $135,000 per acre as the fee simple land basis.


STREET EASEMENT – 2,700 square feet

A typical public street easement grants to The City of San Diego a permanent easement and right-of-way for public street, including all incidents and appurtenances thereto, together with the right of ingress and egress, over, under, upon, along and across all that real property described.

The acquisition of the street easement is valued as of the effective date of appraisal and the property rights are equal to 100% of the fee simple ownership but also considers the impact of existing easements.

PLAT WITH EXISTING EASEMENT OVERLAY – 2,600 square feet

An easement for right of way to erect, construct, change the size of, improve, reconstruct, relocate, repair, maintain and use facilities consisting of: (1) underground electric facilities, and appurtenances for the transmission and distribution of electricity, (2) underground communication facilities, and appurtenances, together with the right of ingress thereto and egress therefrom and incidental purposes, recorded august 04, 2005 as instrument no. 2005-664962 of official records, in favor of: San Diego Gas & Electric Company, a corporation



The interest of San Diego Gas & Electric Company, a corporation of said easement has been assigned to Pacific Bell by assignment of easement recorded August 25, 2005 as instrument no. 2005-732592 of official records

The SDG&E easement is non-exclusive. This appraisal does not have the benefit of any road improvement plans or construction details and it is assumed that there will be activity that will preclude use of all or most of the mitigation value to the fee ownership.

An easement for public right of way is typically considered as equivalent to a fee taking, equal to 100% of the fee value.

Existing easement overlaps required an adjustment since the impacted area has a reduced fee simple value in the before condition. The new easement acquisition value is adjusted to reflect the impact of existing overlay easement described above, and the existing easement impact is estimated to be 50% of the fee value.

DRAFT

EASEMENT SEGMENTS	LOCATION/ CONSTRAINTS	SIZE (SF)	VALUE PER SF	EASEMENT FACTOR	VALUE
STREET EASEMENT	Surface & Subsurface	2,700	$3.10	100%	$8,370
Less: Existing Utility Easement	Surface & Subsurface	2,600	$3.10	50%	($4,030)
TOTAL					$4,340
ROUNDED					$4,400

VALUE OF THE REMAINDER AS PART OF THE WHOLE

The value of the remainder as part of the whole in the before condition is equal to the difference between the total property value in the before condition and the value of the property to be acquired. The value of the remainder as part of the whole is calculated as follows.

Value of the Larger Parcel (Land Only) – Before Condition	**$2,660,000**
Value of the Property to be Acquired	**($4,400)**
Value of the Remainder as Part of the Whole	**$2,655,600**

VALUE OF THE REMAINDER IN THE AFTER CONDITION, BEFORE BENEFITS

In order to estimate severance damages, it is necessary to estimate the value of the remainder parcel in the after condition, as severance damages can result from the acquisition or construction of the proposed project.

The acquisition is a minor area and is within the area impacted by existing easement overlays as well as being in the area that would be required for dedication for development purposes. The highest and best use of the subject is the same in the after condition as in the before condition.

Severance Damage is estimated as $0.

BENEFITS

Since there are no damages, benefits were not measured. However, the project could be a benefit to the subject property on a general and specific basis if the access and drainage is improved, including an abatement or control of the flooding that has been an issue in the immediate area. In addition, the project eliminates the owner road improvement cost in the event of development.

TOTAL COMPENSATION

Value of the Whole Before Acquisition	**$2,660,000**
Value of the Part Acquired As Part of The Whole	**($4,400)**
Value of the Remainder As Part of The Whole	**$2,655,600**
Value of the Remainder After Acquisition before Consideration of Benefits	**$2,655,600**
Severance Damage	**None**
Value of the Remainder After Acquisition and After Consideration of Benefits	**$2,655,600**
Benefits	**None measured**
Net Damage or Benefits	**None measured**
Temporary Construction Area	**$0**
TOTAL VALUE OF RIGHTS TO BE ACQUIRED	**$4,400**

DRAFT


ADDENDUM

DRAFT

COMPARABLE MARKET DATA EXHIBITS



Market Data #1



Market Data #2



Market Data #3




Market Data #4

DRAFT



Market Data #5




Market Data #6



Market Data #7



Market Data #8



Market Data #9 (Information)

DRAFT

QUALIFICATIONS

DRAFT

Rob

Transmittal

February 3, 2014

To: Joseph Paez, Jr.
7808 St. Andrews Avenue
San Diego, CA 92154

From: James Roberts, PE

Re: Continental Street Vacation
Project number 339219

Enclosed:

Murphy Development Street Vacation request
Street Vacation Exhibit
Aerial Exhibit
Acknowledgement Letter

Mr. Paez,

Murphy Development Company is processing a street vacation for the segment of Continental Street between Colchester Court and SR905. This segment is no longer needed with the construction of SR905. With the street segment removed the development area of your property will be increased and you will not be required to build the west half of the street on your property. The City has asked for written acknowledgement from adjoining owners. Please contact me if you have any questions about the transmittal.

If you are in agreement, please review the attached documents and sign the acknowledgement form. Return the acknowledgement in the enclosed stamped/ addressed envelope.

Thank you,

James M Roberts, PE


1422 Lomita Road
El Cajon, CA 92020
619-405-8737
jroberts.lomita@me.com

To: Tim Daly - Project Manager
City Of San Diego
Development Services Department

From: Joseph Paez, Jr.

Re: Continental Street Vacation
Project # 339219
Otay Mesa Community Plan

I am the owner of assessor parcel # 646-100-77. I have reviewed the proposed vacation of a segment of Continental Street right of way adjacent to my property. I support approval of the right of way vacation.




2/18/14

Joseph Paez, Jr. Date

STREET VACATION EXHIBIT
CONTINENTAL STREET

SHEET 1 OF 1 SHEETS



LINE TABLE		
LINE	LENGTH	BEARING
L1	35.05'	N83°59'16"W
L2	30.85'	N00°58'25"E
L3	193.77'	N00°58'25"E
L4	54.24'	N88°26'35"W

CURVE TABLE			
CURVE	LENGTH	RADIUS	DELTA
C1	121.32'	65.00'	106°56'12"
C2	17.32'	20.00'	49°36'17"
C3	30.65'	20.00'	87°49'02"

LINE TABLE		
LINE	LENGTH	BEARING
L5	42.00'	S89°01'35"E
L6	107.02'	N00°58'25"E
L7	19.97'	N00°58'25"E
L8	36.16'	N74°29'49"W

CURVE TABLE			
CURVE	LENGTH	RADIUS	DELTA
C3	31.42'	20.00'	90°00'00"
C4	17.34'	20.00'	49°40'47"
C5	121.59'	65.00'	107°06'03"

PROPERTY INFORMATION:

LOTS 1 THROUGH 21 OF PARCEL MAP 20706
A.P.NO. 646-101-79 - 98

BASIS OF BEARINGS

THE BASIS OF BEARING FOR THIS SURVEY IS A PORTION OF THE CENTERLINE OF BRITANNIA BOULEVARD PER OTAY MESA BUSINESS PARK, LTD, MAP NUMBER 13498 AND PARCEL MAP 20706. BEARING: NORTH 00°59'42" EAST

LEGEND

TPOB INDICATES TRUE POINT OF BEGINNING

INDICATES STREET RIGHT OF WAY TO BE VACATED

PROJECT LOCATION

VICINITY MAP

RONALD LAND SURVEYOR
SCOTT R. MORGAN
NO. 8484
STATE OF CALIFORNIA

PRIVATE CONTRACT J-095152006

PUBLIC RIGHT-OF-WAY VACATION:

BROWN FIELD TECH PARK

ENGINEERING DEPARTMENT
SHEET 1 OF 1 SHEETS

W.O. NO. 425575
P.T.N.O. 88422
DR. 91-0395

REVISIONS					
DESCRIPTION	BY	APPROVED	DATE	M.P.D.	
ORIGINAL	KARPI				

1786-6333

146-1773

CONTINENTAL STREET VACATION
AERIAL PHOTOGRAPH



CALIFORNIA ALL-PURPOSE CERTIFICATE OF ACKNOWLEDGMENT

State of California

County of San Diego

On Jan 21, 2009 before me, Beatriz Torres, Notary Public
(Here insert name and title of the officer),

personally appeared Joseph Paez, Jr,

who proved to me on the basis of satisfactory evidence to be the person(s) whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies), and that by his/her/their signature(s) on the instrument the person(s), or the entity upon behalf of which the person(s) acted, executed the instrument.

I certify under PENALTY OF PERJURY under the laws of the State of California that the foregoing paragraph is true and correct.

WITNESS my hand and official seal.

Signature of Notary Public

(Notary Seal)

BEATRIZ TORRES
COMM.# 1747290
NOTARY PUBLIC-CALIFORNIA
SAN DIEGO COUNTY
MY COMM. EXP. MAY 26 201

ADDITIONAL OPTIONAL INFORMATION

DESCRIPTION OF THE ATTACHED DOCUMENT

(Title or description of attached document)

(Title or description of attached document continued)

Number of Pages ____ Document Date ____

(Additional information)

CAPACITY CLAIMED BY THE SIGNER

- ☐ Individual (s)
- ☐ Corporate Officer

(Title)

- ☐ Partner(s)
- ☐ Attorney-in-Fact
- ☐ Trustee(s)
- ☐ Other ____

INSTRUCTIONS FOR COMPLETING THIS FORM

Any acknowledgment completed in California must contain verbiage exactly as appears above in the notary section or a separate acknowledgment form must be properly completed and attached to that document. The only exception is if a document is to be recorded outside of California. In such instances, any alternative acknowledgment verbiage as may be printed on such a document so long as the verbiage does not require the notary to do something that is illegal for a notary in California (i.e certifying the authorized capacity of the signer). Please check the document carefully for proper notarial wording and attach this form if required.

- State and County information must be the State and County where the document signer(s) personally appeared before the notary public for acknowledgment.
- Date of notarization must be the date that the signer(s) personally appeared which must also be the same date the acknowledgment is completed.
- The notary public must print his or her name as it appears within his or her commission followed by a comma and then your title (notary public).
- Print the name(s) of document signer(s) who personally appear at the time of notarization.
- Indicate the correct singular or plural forms by crossing off incorrect forms (i.e. ~~he~~/she/~~they~~ is /~~are~~) or circling the correct forms. Failure to correctly indicate this information may lead to rejection of document recording.
- The notary seal impression must be clear and photographically reproducible. Impression must not cover text or lines. If seal impression smudges, re-seal if a sufficient area permits, otherwise complete a different acknowledgment form.
- Signature of the notary public must match the signature on file with the office of the county clerk.
  - Additional information is not required but could help to ensure this acknowledgment is not misused or attached to a different document.
  - Indicate title or type of attached document, number of pages and date.
  - Indicate the capacity claimed by the signer. If the claimed capacity is a corporate officer, indicate the title (i.e. CEO, CFO, Secretary).
- Securely attach this document to the signed document

CALIFORNIA ALL-PURPOSE CERTIFICATE OF ACKNOWLEDGMENT

State of California

County of San Diego

On Jan 21, 2009 before me, Beatriz Torres Notary Public
(Here insert name and title of the officer),

personally appeared Joseph Paez, Jr.,

who proved to me on the basis of satisfactory evidence to be the person(s) whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies), and that by his/her/their signature(s) on the instrument the person(s), or the entity upon behalf of which the person(s) acted, executed the instrument.

I certify under PENALTY OF PERJURY under the laws of the State of California that the foregoing paragraph is true and correct.

WITNESS my hand and official seal.

Beatriz Torres
Signature of Notary Public

(Notary Seal)

BEATRIZ TORRES
COMM. # 1747290
NOTARY PUBLIC-CALIFORNIA
SAN DIEGO COUNTY
MY COMM. EXP. MAY 26, 2011

ADDITIONAL OPTIONAL INFORMATION

DESCRIPTION OF THE ATTACHED DOCUMENT

(Title or description of attached document)

(Title or description of attached document continued)

Number of Pages ____ Document Date____

(Additional information)

CAPACITY CLAIMED BY THE SIGNER

- ☐ Individual (s)
- ☐ Corporate Officer

(Title)

- ☐ Partner(s)
- ☐ Attorney-in-Fact
- ☐ Trustee(s)
- ☐ Other ____

INSTRUCTIONS FOR COMPLETING THIS FORM

Any acknowledgment completed in California must contain verbiage exactly as appears above in the notary section or a separate acknowledgment form must be properly completed and attached to that document. The only exception is if a document is to be recorded outside of California. In such instances, any alternative acknowledgment verbiage as may be printed on such a document so long as the verbiage does not require the notary to do something that is illegal for a notary in California (i.e. certifying the authorized capacity of the signer). Please check the document carefully for proper notarial wording and attach this form if required.

- State and County information must be the State and County where the document signer(s) personally appeared before the notary public for acknowledgment.
- Date of notarization must be the date that the signer(s) personally appeared which must also be the same date the acknowledgment is completed.
- The notary public must print his or her name as it appears within his or her commission followed by a comma and then your title (notary public).
- Print the name(s) of document signer(s) who personally appear at the time of notarization.
- Indicate the correct singular or plural forms by crossing off incorrect forms (i.e. ~~he/she/they,~~ is ~~/are~~) or circling the correct forms. Failure to correctly indicate this information may lead to rejection of document recording.
- The notary seal impression must be clear and photographically reproducible. Impression must not cover text or lines. If seal impression smudges, re-seal if a sufficient area permits, otherwise complete a different acknowledgment form.
- Signature of the notary public must match the signature on file with the office of the county clerk.
  - Additional information is not required but could help to ensure this acknowledgment is not misused or attached to a different document.
  - Indicate title or type of attached document, number of pages and date.
  - Indicate the capacity claimed by the signer. If the claimed capacity is a corporate officer, indicate the title (i.e. CEO, CFO, Secretary).
- Securely attach this document to the signed document

RECORDING REQUESTED BY:

THE CITY OF SAN DIEGO

AND WHEN RECORDED MAIL TO:

CITY CLERK
CITY OF SAN DIEGO
MAIL STATION 2A

Originating Dept – DSD/LDR – M.S. 501

(THIS SPACE FOR RECORDER'S USE ONLY)

GRANT DEED - SEWER EASEMENT

J.O. NO: 425575

ASSESSOR'S PARCEL NO: 646-101-72

PTS NO: 88422

DWG NO: _____

NO DOCUMENT TAX DUE
R & T CODE 11922

NO FEE FOR GOVT. AGENCY
GOVERNMENT CODE 27383

For valuable consideration, receipt of which is hereby acknowledged, JOSEPH PAEZ, JR., a single man

HEREBY GRANT(S) to the City of San Diego, a municipal corporation, in the County of San Diego, State of California, a permanent easement and a right-of-way for access to construct, reconstruct, maintain, operate and repair **sewer facilities,** including any or all appurtenances thereto, together with the right of ingress and egress, over, under, along and across all that real property situated in the City of San Diego, County of San Diego, State of California, described as follows:

See exhibit "A" attached hereto and exhibit "B" attached for illustration purposes

Reserving unto the Grantor herein, heirs and assigns the continued use of the above described parcel of land subject to the following conditions: The erecting of buildings, masonry walls, and other permanent structures; the planting of trees; the changing of the surface grade; and the installation of privately owned pipe lines shall be prohibited except by an Encroachment Maintenance and Removal Agreement issued by the City Engineer.

Date: 11/21/09

Grantor: *(type or print)* Joe PAEZ JR

By: *(signature)* _____
(type or print name)

This is to certify that the interest in real property conveyed by this instrument to the City of San Diego, a municipal corporation, is hereby accepted by the undersigned officer on behalf of the City of San Diego, pursuant to authority conferred by the Municipal Code, and the grantee consents to recordation thereof by its duly authorized officer.

Date: _____

For City Engineer
By: _____

NOTE: NOTARY ACKNOWLEDGMENTS FOR ALL SIGNATURES MUST BE ATTACHED, PER CIVIL CODE SEC. 1180 ET. SEQ.

EXHIBIT 'A'
LEGAL DESCRIPTION

SEWER EASEMENT

THE EASTERLY 25.00 FEET OF THE SOUTHWEST QUARTER OF THE NORTHEAST QUARTER OF SECTION 33, TOWNSHIP 18 SOUTH, RANGE ONE WEST, SAN BERNARDINO BASE AND MERIDIAN, IN THE CITY OF SAN DIEGO, COUNTY OF SAN DIEGO, STATE OF CALIFORNIA, ACCORDING TO THE OFFICIAL PLAT THEREOF.

EXCEPTING THEREFROM THAT PORTION OF LAND CONDEMNED TO THE STATE OF CALIFORNIA DEPARTMENT OF TRANSPORTATION, RECORDED JULY 13, 2007 AS DOCUMENT NO. 2007-0469983, OFFICIAL RECORDS, SAN DIEGO COUNTY, CALIFORNIA.

TOGETHER WITH A PORTION OF THE SOUTHEAST QUARTER OF SAID SECTION 33, MORE PARTICULARY DESCRIBED AS FOLLOWS:

BEGINNING AT THE SOUTHEAST CORNER OF THE SOUTHWEST QUARTER OF THE NORTHEAST QUARTER OF SAID SECTION 33, SAID POINT BEING ALSO ON THE CENTERLINE OF CONTINENTAL STREET AS SHOWN PER MAP 13498, RECORDED NOVEMBER 10, 1997 AS FILE NUMBER 97-0567091, OFFICIAL RECORDS, SAN DIEGO COUNTY, CALIFORNIA; THENCE ALONG THE CENTERLINE OF SAID CONTINENTAL STREET SOUTH 00°58'25" WEST 43.50 FEET TO THE CENTERLINE OF AIRWAY ROAD AS SHOWN PER RECORD OF SURVEY 13227, RECORDED JUNE 6, 1991 AS FILE NUMBER 91-271215, OFFICIAL RECORDS, SAN DIEGO COUNTY, CALIFORNIA;

J.O. 425575
P.T.S. 88422
DWG: XXXXX-B

EXHIBIT 'A'
LEGAL DESCRIPTION

SEWER EASEMENT

THENCE ALONG SAID CENTERLINE OF AIRWAY ROAD SOUTH 89°56'49" WEST 25.00 FEET; THENCE LEAVING SAID CENTERLINE OF AIRWAY ROAD NORTH 00°58'25" EAST 44.33 FEET; THENCE SOUTH 88°10'07" EAST 25.00 FEET TO THE SAID CENTERLINE OF CONTINENTAL STREET AND THE POINT OF BEGINNING.

THE ABOVE DESCRIBED EASEMENT CONTAINS 30,055 SQUARE FEET, MORE OR LESS.

6/10/08

MICHAEL JAMES KNAPTON
P.L.S.8012 EXPIRES 12/31/08

DATE

LICENSED LAND SURVEYOR
MICHAEL JAMES KNAPTON
No. LS8012
Exp. 12/31/08
STATE OF CALIFORNIA

J.O. 425575
P.T.S. 88422
DWG: XXXXX-B

The City of SAN DIEGO

Development Services Department

L64A-007

Invoice

Invoice Number: 984473

Status: Invoiced
Issued: 08/10/2021 11:13 am Jauregui, Aldo
Voided:
Customer: Lakq, Surlya

Development: 73016 Brown Field Tech Park Unit 1
Project: **696032** Digital Tentative Map PM: "System Managed, Pro (619)446-5000

Project Fees:

Fee Description	Quantity	Units	Fee Amount
Close Out Fee	1.00	Each	$736.45
Mapping	1.00	Each	$10.00
		Approval Total:	$746.45
		Job Total:	$746.45
		Project Total:	$746.45
		Invoice Total:	$746.45

All fees are required to be paid prior to services being rendered. Payment of invoices is required immediately upon project setup/submittal and permit issuance per the San Diego Municipal Code 112.0102(b) and 129.0213(a). Unpaid invoices for permit applications will result in cancellation of submitted project within 2 business days. For your convenience, DSD offers online payments via OPENDSD (https://opendsd.sandiego.gov/Web/Invoices/Search).

United Site Services of California, Inc.
7910 Othello Ave
SAN DIEGO, CA 92111

Salesperson Contact
Lesli O. Quintero
Mobile:
Office: +1 760-560-6505
Fax:
Lesli.Quintero@unitedsiteservices.com

Site Service Quotation

Quote No.: 414-2338978 **Quote Date:** 03/23/22 **Quote Expires:** 04/22/22

Sell To: COLRICH CONSTRUCTION STE 300
JOHN SHEPARD
444 W BEECH ST STE 300
SAN DIEGO, CA 92101-2942

Ship To: COLRICH CONSTRUCTION STE 300
PAEZ ~~PAZ~~E PROJECT
AIRWAY RD
SAN DIEGO, CA 92154

Cust. #: USS-142959
Phone: 858-395-9997

Attn: JOHN SHEPARD
Phone: 858-395-9997
Terms: Due Upon Receipt

Comments & Special Instructions

*** NOT PREVAILING WAGE PROJECT ***

Fence Pricing Terms and Conditions 17% FENCE RENTAL – (52) 28 DAY BILLING CYCLE TERM
$3.00 / FT ON 6 FT PANEL FENCE
$8.00 EA 8LP

Temporary fence pricing for long-term projects is based on the initial term listed on the agreement which will be billed on a 28 day billing cycle. All new fence orders are subject to a minimum install fee and will be listed on the corresponding agreement. If the fence is needed beyond the initial term listed on this agreement, a residual (rental) fee will apply to all fence and related products on site. This residual percentage amount will appear on your agreement and will be invoiced each billing cycle until the fence is removed. Price includes initial delivery, installation and removal. Any additional deliveries, moves or removals will be charged based on the pricing in this agreement and the schedule below. All partial deliveries and removals are subject to a minimum trip charge as outlined in the agreement. Damaged fence will be billed to the customer unless a Damage Waiver was purchased.

USS DOES NOT ENGAGE IN OR SIGN PROJECT LABOR AGREEMENTS (PLA). USS WILL, HOWEVER, PROVIDE FENCE TO OUR CUSTOMERS FOR SELF-INSTALLATION IN THESE INSTANCES.

IF THIS IS A PREVAILING WAGE PROJECT, DAVIS BACON RATES WILL BE USED TO ESTIMATE PREVAILING WAGE. RATE WILL BE CHARGED AS SITE MANDATES. CUSTOMER IS RESPONSIBLE TO PROVIDE USS WITH DIR OR CPR FORM PRIOR TO INSTALL. All installs, pickups, moves, or repairs accrue at current Davis Bacon Wage Act wages if the project is prevailing wage.

Miscellaneous Charges
Add $1.00 per ft for moves (subject to $250.00 minimum fee)
Add $1.00 per ft for rocky ground, hillside or hand carry.
Hole patching (cold patch) available in designated areas, will be a $8 per hole in asphalt and $10 per hole in concrete (subject to $250 minimum fee)
Add $225.00 per hour based on two-person crew for waiting time related to site delays, safety classes, site orientations or any other reason for delay, etc.
It is the customer's responsibility to keep fence line free of vegetation and snow. All growth and or snow must be cleared prior to

Continued..

United Site Services of California, Inc.
7910 Othello Ave
SAN DIEGO, CA 92111

Salesperson Contact
Lesli O. Quintero
Mobile:
Office: +1 760-560-6505
Fax:
Lesli.Quintero@unitedsiteservices.com

Site Service Quotation

Quote No.: 414-2338978 **Quote Date:** 03/23/22 **Quote Expires:** 04/22/22

Sell To: COLRICH CONSTRUCTION STE 300
JOHN SHEPARD
444 W BEECH ST STE 300
SAN DIEGO, CA 92101-2942

Ship To: COLRICH CONSTRUCTION STE 300
PAZE PROJECT
AIRWAY RD
SAN DIEGO, CA 92154

Cust. #: USS-142959
Phone: 858-395-9997

Attn: JOHN SHEPARD
Phone: 858-395-9997
Terms: Due Upon Receipt

Comments & Special Instructions

delivery or removal.

SHOULD YOUR FENCE REQUIRE DRIVEN POST, CUSTOMER WILL NEED TO MARK THE FENCE LINE FOR UNDERGROUND UTILITIES LOCATE COMPANY (ie: DIG ALERT) AND LET USS KNOW ONCE COMPLETED. USS WILL CALL TO SCHEDULE THE UNDERGROUND ASSESSMENT. IN SOME STATES THE LOCATE APPOINTMENT CAN BE SCHEDULED BY THE CUSTOMER, HOWEVER USS MUST BE LISTED ON THE PAPERWORK. PLEASE NOTE THIS WILL TAKE 3-5 BUSINESS DAYS TO CLEAR BASED ON LOCAL UTILITY LOCATE AVAILABILITY.

Damage Waiver
Damage waiver protects customer from loss relating to wind, vehicle collision, trees/falling objects, etc.

Without a damage waiver, damaged fence will be billed per the schedule below:
Chain Link: $6.00 per foot
Panel Fence: $12.25 per foot
Gates: 2x standard per foot charge for item. Ie, 10' gate for panel fence will be charged at $24.50 per foot.

If damaged fence has to be removed and reinstalled, customer will be billed for damaged fence AND for additional installation charges.

Damage waiver does not cover missing or stolen fence.

Item	Unit	Quantity	From	Thru	Unit Price	Total Price	
Fence - 6x12 T-Stand Panel	**FT**	**3,850**	**07/01/22**	**07/01/26**	**3.00**	**11,550.00**	one time
Environment/Energy/Compliance						0.00	one time
1,990 LF Post Driven							
1,860 LF T-Stands							
Fence - 6x12 T-Stand Panel Subtotal:						**11,550.00**	
Fence - 8FT Line Post / Core Drill	**EA**	**166**	**07/01/22**	**07/01/26**	**8.00**	**1,328.00**	one time
Environment/Energy/Compliance						0.00	one time
Fence - 8FT Line Post / Core Drill Subtotal:						**1,328.00**	

Continued..

United Site Services of California, Inc.
7910 Othello Ave
SAN DIEGO, CA 92111

Salesperson Contact
Lesli O. Quintero
Mobile:
Office: +1 760-560-6505
Fax:
Lesli.Quintero@unitedsiteservices.com

Site Service Quotation

Quote No.: 414-2338978 **Quote Date:** 03/23/22 **Quote Expires:** 04/22/22

Sell To: COLRICH CONSTRUCTION STE 300
JOHN SHEPARD
444 W BEECH ST STE 300
SAN DIEGO, CA 92101-2942

Ship To: COLRICH CONSTRUCTION STE 300
PAZE PROJECT
AIRWAY RD
SAN DIEGO, CA 92154

Cust. #: USS-142959
Phone: 858-395-9997

Attn: JOHN SHEPARD
Phone: 858-395-9997
Terms: Due Upon Receipt

Item	Unit	Quantity	From	Thru	Unit Price	Total Price	
Fence - T-Stand	**EA**	**155**	**07/01/22**	**07/01/26**	**0.00**	**0.00**	one time
Environment/Energy/Compliance						0.00	one time
Fence - T-Stand Subtotal:						**0.00**	
Fence - Trip Charge	**EA**	**1**	**07/01/22**	**07/01/26**	**150.00**	**150.00**	one time
Environment/Energy/Compliance						0.00	one time
Fence - Trip Charge Subtotal:						**150.00**	
Residual Applies Beyond Initial Term 17%	**EA**	**1**	**03/24/22**	**Indef**	**0.00**	**0.00**	per billing cycle
Environment/Energy/Compliance						0.00	per billing cycle
Residual Applies Beyond Initial Term 17% Subtotal:						**0.00**	

Total: **13,028.00**

Accepted: _____ Date: 5/8/2022

JOE PAEZ, JR

Remit To: United Site Services, PO Box 660475, Dallas, TX 75266-0475

NOTE: Total prices have been calculated for 1 billing period only. Damage Waiver is optional. Please read the terms and conditions on the last page of this document for more information.

TERMS AND CONDITIONS

Rev. 5.6.09

1. Acceptance Customer shall be deemed to have accepted these terms and conditions upon the earliest to occur of: (i) two business days after receipt of an invoice from Company; (ii) delivery of items of equipment ("Equipment") identified in the invoice to the site designated in the invoice (the "Site") and use or acceptance thereof; or (iii) acknowledgment or other conduct of Customer indicating acceptance. These terms and conditions shall supersede any inconsistent terms of any purchase order or other documents of Customer.

2. Payment Terms All agreements are subject to approval by Company. Customer shall pay all charges by Company during the term (the "Period") shown in the invoice. **All Company invoices are due and payable upon Customer's receipt of the invoice.** Customer shall be liable to Company for interest at the rate of 1.5% per month, or such lesser rate as may be the maximum lawful rate from time to time, on all overdue accounts. Customer shall pay all additional charges for services separately requested by Customer or made necessary by Customer's breach of these Terms and Conditions, including but not limited to, moving/relocation charges, special service charges, and special delivery and removal charges. In the event Customer's account becomes delinquent, Customer agrees to pay Company all collection expenses, including reasonable attorney's fees.

3. Service The Company offers servicing as an option on all portable restrooms.

4. Damage Waiver The Company offers a damage waiver program on certain Equipment. **Customer may decline the damage waiver by completing and executing the appropriate section at the end of these terms and conditions.** Unless Customer has declined the Damage Waiver in writing before the commencement of the Period or within five business days of the date of the first Invoice to Customer for any Equipment identified with a Damage Waiver on the invoice, whichever is later, Company shall impose, and Customer shall pay, any Damage Waiver fees indicated on the invoice and (provided Customer has not breached any of these terms and conditions) Customer shall have no responsibility for accidental structural damage to the Equipment, EXCEPT (i) Customer shall be liable for theft of any Equipment and for any losses resulting from any willful or grossly negligent acts or omissions of Customer or any of its agents, servants and employees, and (ii) if Customer has other insurance covering such loss or damage, Customer shall exercise all rights available to it under such insurance, take all actions necessary to process such claim and assign such claim and pay any and all proceeds from such insurance to Company. If Customer declines the Damage Waiver, Customer shall be liable for any loss or damage to the Equipment, regardless of cause or fault, except for reasonable wear and tear, and Customer shall pay Company the actual cost of repair or replacement cost thereof, and in addition thereto, for Company's loss of use of the Equipment. In the event of any loss of or damage to the Equipment, Customer shall promptly notify Company of such loss or damage and shall provide Company with copies of all reports relating to such loss or damage, including police reports, informal investigation reports and insurance reports. **The damage waiver described in this section does not apply to portable toilets and containers which become contaminated with hazardous materials or contaminants described in Paragraph 7 while in the Customer's control and possession.**

5. Equipment Location Customer warrants and represents that it has exercised due diligence and care in the selection of the location it has designated for the placing of portable toilets, temporary fencing, portable storage containers and any other Equipment provided by Company, and further agrees to give directions and supervise the placement of such temporary fencing, storage containers, portable toilets and other Equipment.

6. Equipment Responsibility Company will deliver the Equipment to the Site at the commencement of the Period and will remove the Equipment at the end of the Period. If servicing has been ordered by Customer, Company will remove any domestic septic waste ("DSW") from portable restrooms, if applicable, on the service day(s) scheduled by Company. In the event Company is unable to service the Equipment on the service day due to a holiday, inclement weather, or other interfering circumstances, Company shall service the Equipment on the earliest business day, excluding Sundays, available in accordance with Company's other service commitments. Company shall be granted access to the Equipment at any time for any servicing, maintenance or removal of Equipment. Customer shall not remove the Equipment from the Site, and shall not move the Equipment on the Site without written permission from Company. Customer shall not modify the equipment. Customer shall not sell, rent, lease or otherwise lose possession of the Equipment, nor shall Customer permit any lien to be placed on the Equipment. Customer acknowledges that Company has no control over the use of the Equipment by Customer, and Customer agrees to comply, at Customer's sole expense, with any and all applicable municipal, county, state, federal or quasi-governmental laws, ordinances, regulations and guidelines, including ANSI Standard Z4.3 and the requirements of the "Guide for Clean Portable Sanitation" published by PSAI, if applicable.

7. Equipment Contamination While portable restroom units are in Customer's possession, Customer shall prevent any contamination of such units with or from radioactive, volatile, flammable, explosive, toxic or hazardous materials (including oils, paints, adhesives and solvents). Company will not remove any waste other than DSW from portable restrooms and storage containers ("Other Waste"). In the event Other Waste is found in the Equipment, Customer shall arrange and pay for separate removal of such Other Waste. Until such Other Waste is removed, Customer may not terminate the Period and Customer is liable for all charges accrued during such period.

8. Liability Except to the extent Customer is not liable for damage to Equipment under the Damage Waiver program described in Section 5, Customer agrees to defend, indemnify and hold Company harmless to the maximum extent permitted by law from and for all claims, lawsuits, damages, expenses and other losses arising out of the rental or use of Equipment delivered to or rented by Customer. Customer's obligation will apply to the extent permitted by law to all accidents or incidents regardless of whether same occur as a result of Customer's or third party's negligence, fault or other legal liability. Customer will have no obligation to defend, indemnify or hold harmless Company if the accident or incident arises out of the sole negligence or willful misconduct of Company. Company, its officers, directors, employees and agents shall not, under any circumstances, be liable to Customer for consequential, incidental, special, exemplary or punitive damages arising out of or relating to the Equipment. Customer's sole and exclusive remedy for any claims or causes of action arising out of or related to the Equipment shall be to recover from Company direct damages in an amount not to exceed the amount paid by Customer for use of the Equipment.

9. No Prorating Agreed upon rates are the complete billing periods and are not to be prorated.

10. Termination Company may terminate this agreement and remove the Equipment immediately in the event (i) Customer fails to pay any amount when due to Company, (ii) Customer otherwise breaches or rejects any of these Terms and Conditions, (iii) there is any loss of or damage to the Equipment, (iv) any lien is placed, or is proposed to be placed, on any of the Equipment, or (v) a proceeding in bankruptcy or for other protection from creditors is commenced by or against Customer. Company shall not be responsible for loss of any personal property on the Site, which may be caused by removal of any of Company's Equipment pursuant to this paragraph.

11. Governance This agreement shall be governed by and construed in accordance with the laws of the state, shown on the invoice, in which the Company's place of business is located, without giving effect to any choice or conflict of law provision or rule that would cause the application of the laws of any jurisdiction other than such state. Each of the parties submits to the jurisdiction of any state or federal court sitting in such state, in any action or proceeding arising out of or relating to this agreement. All claims in respect of the action or proceeding may be heard and determined in any such court. No failure by Company to exercise any right hereunder shall operate as a waiver of any other right hereunder, and a waiver of any right on one occasion shall not constitute a bar to or a waiver of any such right on any future occasion. All modifications to these Terms and Conditions shall be in writing.

12. Taxes & Fees Customer shall pay any and all taxes, license fees or permit fees arising out of use of the Equipment. Customer shall pay such taxes whether such taxes are shown on the invoice or whether such taxes are later claimed by a governmental authority. In the event of a claim by a governmental authority for taxes related to the Equipment, Customer shall pay to Company such taxes on demand.

13. Additional Terms Additional Terms and Conditions apply to rental and service of Storage Containers ("Sheds") and Temporary Power equipment. These Terms & Conditions are shown on the back of your contract for these items.

14. Errors & Omissions Company reserves the right to correct any erroneous information that may appear in the invoice or may have appeared in a prior invoice including, without limitation, Customer's name or address, or billing amounts.

15. Conditional Payments Any payment check, or other form of payment that you send us for less than the full balance due that is marked "paid in full" or contains a similar notation, or that you otherwise tender in full satisfaction of a disputed amount, must be sent to United Site Services Inc., 50 Washington Street, Suite 1000, Westborough, MA 01581. We reserve all our rights regarding these payments (e.g., if it is determined there is no valid dispute, or if any such check is received at any other address, we may accept the check and you will still owe any remaining balance). We may refuse to accept any such payment by returning it to you, not cashing it or destroying it. All other payments that you make shall be sent to the address on the invoice.

APPENDIX D

Regulatory Records Documentation

The Collection At Cactus
7020 Airway Rd
San Diego, CA 92154

Inquiry Number: 07305239.2r
April 11, 2023

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	571
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

7020 AIRWAY RD
SAN DIEGO, CA 92154

COORDINATES

Latitude (North):	32.5624890 - 32° 33' 44.96''
Longitude (West):	116.9862400 - 116° 59' 10.46''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	501291.8
UTM Y (Meters):	3602596.5
Elevation:	510 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	12008255 OTAY MESA, CA
Version Date:	2018
West Map:	12016552 IMPERIAL BEACH, CA
Version Date:	2018

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140805
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
7020 AIRWAY RD
SAN DIEGO, CA 92154

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	YVETTE ALCARAZ	1942 CACTUS ROAD	RCRA NonGen / NLR	Lower	63, 0.012, West
A2	TRIPP SALVAGE LANDFI	1890 CACTUS ROAD	CPS-SLIC, DEED, CERS	Lower	66, 0.013, West
3	IRMA TATUM	1812 CACTUS RD.	RCRA NonGen / NLR	Lower	77, 0.015, NW
B4	CACTUS ROAD- AKA TRI	1700-1902 CACTUS ROA	SWF/LF	Lower	501, 0.095, NNW
B5	CALTRANS	1703 CACTUS RD	RCRA NonGen / NLR	Lower	533, 0.101, NNW
C6	MARTINEZ RANCH	2160 CACTUS RD	CPS-SLIC, San Diego Co. HMMD	Higher	534, 0.101, SSW
C7	MARTINEZ RANCH	2160 CACTUS RD	SAN DIEGO CO. SAM, AST, CERS, HWTS	Higher	534, 0.101, SSW
B8	ASSOCIATED READY MIX	1696 CACTUS RD	AST, NPDES, CIWQS, CERS	Lower	545, 0.103, NNW
B9	ASSOCIATED READY MIX	1696 CACTUS RD	San Diego Co. HMMD, CERS HAZ WASTE, CERS TANKS,...	Lower	545, 0.103, NNW
B10	ASSOCIATED READY MIX	1696 CACTUS RD	RCRA NonGen / NLR	Lower	545, 0.103, NNW
B11	SUNSET CAR RENTAL LL	1690 CACTUS RD	RCRA NonGen / NLR	Lower	661, 0.125, NNW
B12	AT&T CALIFORNIA - D3	1670 CACTUS RD	UST	Lower	769, 0.146, NNW
B13	AT&T CALIFORNIA - D3	1670 CACTUS RD	San Diego Co. HMMD, CERS HAZ WASTE, CERS TANKS,...	Lower	769, 0.146, NNW
B14	PACIFIC BELL DBA AT&	1670 CACTUS ROAD	RCRA-LQG	Lower	769, 0.146, NNW
15	ASSOCIATED READY MIX		PFAS ECHO	Lower	780, 0.148, NW
D16	T K OF SAN DIEGO	6975 CAMINO MAQUILLA	RCRA-SQG, FINDS, ECHO, HAZNET, HWTS	Lower	915, 0.173, NNW
D17	BORDER RECAPPING LLC	6975 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	915, 0.173, NNW
D18	BORDER TIRE #15	6975 CAMINO MAQUILAD	CERS HAZ WASTE, CERS	Lower	915, 0.173, NNW
D19	PINNACLE INDUSTRIAL	6975 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	915, 0.173, NNW
E20	ADESA CALIFORNIA LLC	2175 CACTUS RD	RCRA NonGen / NLR	Higher	942, 0.178, SSW
E21	ADESA SAN DIEGO	2175 CACTUS RD	San Diego Co. HMMD, CERS HAZ WASTE, HAZNET, CERS	Higher	942, 0.178, SSW
E22	DIRECT RECONDITIONIN	2175 CACTUS ROAD	RCRA NonGen / NLR	Higher	942, 0.178, SSW
D23	BAJA AUTO PARTS #2	6960 CAMINO MAQUILAD	CERS HAZ WASTE, HAZNET, CERS, HWTS	Lower	1141, 0.216, NW
D24	M RIOS TRUCKING INC	6950 CAMINO MAQUILAD	RCRA NonGen / NLR, ECHO	Lower	1141, 0.216, NW
D25	905 SMOG & AUTO REPA	6960 CAMINO MAQUILAD	San Diego Co. HMMD, CERS HAZ WASTE, CERS	Lower	1141, 0.216, NW
D26	JOSE GRACIA	6960 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1141, 0.216, NW
D27	BAJA AUTO PARTS #2	6960 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1141, 0.216, NW
D28	BROWNFIELD AUTOMOTIV	6960 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1141, 0.216, NW
D29	NAHUM LLC	6950 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1141, 0.216, NW
D30	905 SMOG & AUTO REPA	6960 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1141, 0.216, NW
D31	M RIOS TRUCKING INC	6950 CAMINO MAQUILAD	HWT	Lower	1141, 0.216, NW
F32	NOIL USA INC	1605 CACTUS RD	RCRA NonGen / NLR	Higher	1184, 0.224, NNW
F33	NOIL USA INC.	1605 CACTUS RD	San Diego Co. HMMD, CERS HAZ WASTE, CERS TANKS,...	Higher	1184, 0.224, NNW
F34	NOIL USA INC.	1605 CACTUS RD	UST	Higher	1184, 0.224, NNW
E35	LUMINA I	2230 CACTUS ROAD	RCRA-SQG	Lower	1207, 0.229, SSW
G36	UNION CHEMICAR AMERI	6940 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1215, 0.230, NW
G37	MENDEOLA TRANSAXLES	6935 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1250, 0.237, NW
G38	MENDEOLA TRANSAXLES	6935 CAMINO MAQUILAD	RCRA NonGen / NLR	Lower	1250, 0.237, NW
F39	OTAY MESA ROAD WIDEN	NONE OTAY MESA RD	CPS-SLIC, CERS	Higher	1326, 0.251, NNW

MAPPED SITES SUMMARY

Target Property Address:
7020 AIRWAY RD
SAN DIEGO, CA 92154

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
F40	TRIP LANDFILL/CACTUS	W CACTUS S OTAY MESA	SAN DIEGO CO. SAM, CPS-SLIC, San Diego Co. HMMD,...	Higher	1447, 0.274, NNW
41	U S BORDER PATROL/BR	7060 BOEING ST	SAN DIEGO CO. SAM, CPS-SLIC, San Diego Co. HMMD,...	Higher	1472, 0.279, NNW
42	BRITANNIA BOULEVARD	2133, 2155, 2177, 21	ENVIROSTOR, VCP, DEED	Lower	1699, 0.322, ESE
H43	CITY OF SAN DIEGO-BR	1424 CONTINENTAL ST	LUST	Higher	1718, 0.325, North
H44	LANCAIR CORP	1424 CONTINENTAL ST	LUST, SAN DIEGO CO. SAM, CPS-SLIC, AST, San Diego...	Higher	1718, 0.325, North
45	2380 BRITANNIA BLVD.	2380 BRITANNIA	SAN DIEGO CO. SAM, CPS-SLIC, San Diego Co. HMMD,...	Lower	2308, 0.437, SE
46	PIPER RANCH BUSINESS	6464 OTAY MESA RD	LUST, CPS-SLIC, Cortese, HIST CORTESE	Higher	2354, 0.446, NW
47	MARTINEZ FARMS, INC.	2440 CACTUS ROAD	CPS-SLIC, San Diego Co. HMMD, ENF, CIWQS, CERS	Lower	2423, 0.459, SSW
48	HONEYWELL	2055 DUBLIN DR.	RCRA-LQG, ENVIROSTOR, AST, ICIS, FINDS, ECHO,...	Lower	2724, 0.516, East
49	CORNER OF OTAY MESA	ROAD	Notify 65	Lower	2961, 0.561, NW
I50	BROWN FIELD NAAS		ENVIROSTOR	Higher	3009, 0.570, NW
I51	BROWN FIELD NAVAL AU		FUDS	Higher	3018, 0.572, NW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-VSQG ---------- RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

EXECUTIVE SUMMARY

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state- and tribal (Superfund) equivalent sites

RESPONSE ---------- State Response Sites

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

BROWNFIELDS ---------- Considered Brownfieds Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT ---------- Waste Management Unit Database
SWRCY ---------- Recycler Database
HAULERS ---------- Registered Waste Tire Haulers Listing
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
HIST Cal-Sites ---------- Historical Calsites Database
SCH ---------- School Property Evaluation Program
CDL ---------- Clandestine Drug Labs
San Diego Co. HMMD ---------- Hazardous Materials Management Division Database
Toxic Pits ---------- Toxic Pits Cleanup Act Sites
US CDL ---------- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

SWEEPS UST ---------- SWEEPS UST Listing

HIST UST	Hazardous Substance Storage Container Database
CA FID UST	Facility Inventory Database

Local Land Records

LIENS	Environmental Liens Listing
LIENS 2	CERCLA Lien Information

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
CHMIRS	California Hazardous Material Incident Report System
LDS	Land Disposal Sites Listing
MCS	Military Cleanup Sites Listing
SPILLS 90	SPILLS 90 data from FirstSearch

Other Ascertainable Records

DOD	Department of Defense Sites
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
2020 COR ACTION	2020 Corrective Action Program List
TSCA	Toxic Substances Control Act
TRIS	Toxic Chemical Release Inventory System
SSTS	Section 7 Tracking Systems
ROD	Records Of Decision
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
ICIS	Integrated Compliance Information System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US AIRS	Aerometric Information Retrieval System Facility Subsystem
US MINES	Mines Master Index File
ABANDONED MINES	Abandoned Mines
FINDS	Facility Index System/Facility Registry System
ECHO	Enforcement & Compliance History Information
UXO	Unexploded Ordnance Sites
DOCKET HWC	Hazardous Waste Compliance Docket Listing
FUELS PROGRAM	EPA Fuels Program Registered Listing
PFAS NPL	Superfund Sites with PFAS Detections Information

PFAS FEDERAL SITES	Federal Sites PFAS Information
PFAS TSCA	PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR	PFAS Contamination Site Location Listing
PFAS WQP	Ambient Environmental Sampling for PFAS
PFAS NPDES	Clean Water Act Discharge Monitoring Information
PFAS ECHO FIRE TRAINING	Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing
PFAS	PFAS Contamination Site Location Listing
AQUEOUS FOAM	Former Fire Training Facility Assessments Listing
CA BOND EXP. PLAN	Bond Expenditure Plan
CUPA Listings	CUPA Resources List
DRYCLEANERS	Cleaner Facilities
EMI	Emissions Inventory Data
ENF	Enforcement Action Listing
Financial Assurance	Financial Assurance Information Listing
ICE	ICE
HWP	EnviroStor Permitted Facilities Listing
HAZNET	Facility and Manifest Data
MINES	Mines Site Location Listing
MWMP	Medical Waste Management Program Listing
NPDES	NPDES Permits Listing
PEST LIC	Pesticide Regulation Licenses Listing
PROC	Certified Processors Database
HAZMAT	Hazardous Material Facilities
UIC	UIC Listing
UIC GEO	UIC GEO (GEOTRACKER)
WASTEWATER PITS	Oil Wastewater Pits Listing
WDS	Waste Discharge System
WIP	Well Investigation Program Case List
MILITARY PRIV SITES	MILITARY PRIV SITES (GEOTRACKER)
PROJECT	PROJECT (GEOTRACKER)
WDR	Waste Discharge Requirements Listing
SAN DIEGO CO LOP	Local Oversight Program Listing
CIWQS	California Integrated Water Quality System
CERS	CERS
NON-CASE INFO	NON-CASE INFO (GEOTRACKER)
OTHER OIL GAS	OTHER OIL & GAS (GEOTRACKER)
PROD WATER PONDS	PROD WATER PONDS (GEOTRACKER)
SAMPLING POINT	SAMPLING POINT (GEOTRACKER)
WELL STIM PROJ	Well Stimulation Project (GEOTRACKER)
HWTS	Hazardous Waste Tracking System
PFAS TRIS	List of PFAS Added to the TRI
MINES MRDS	Mineral Resources Data System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	EDR Proprietary Manufactured Gas Plants
EDR Hist Auto	EDR Exclusive Historical Auto Stations
EDR Hist Cleaner	EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF	Recovered Government Archive Solid Waste Facilities List

EXECUTIVE SUMMARY

RGA LUST---------- Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/06/2023 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PACIFIC BELL DBA AT& EPA ID:: CAR000286229	1670 CACTUS ROAD	NNW 1/8 - 1/4 (0.146 mi.)	B14	139

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/06/2023 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
T K OF SAN DIEGO EPA ID:: CAD982460347	***6975 CAMINO MAQUILLA***	***NNW 1/8 - 1/4 (0.173 mi.)***	***D16***	***179***
LUMINA I EPA ID:: CAP000318428	2230 CACTUS ROAD	SSW 1/8 - 1/4 (0.229 mi.)	E35	371

EXECUTIVE SUMMARY

Lists of state- and tribal hazardous waste facilities

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 01/23/2023 has revealed that there are 3 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BROWN FIELD NAAS Facility Id: 80000947 Status: Inactive - Needs Evaluation		NW 1/2 - 1 (0.570 mi.)	I50	568

Lower Elevation	Address	Direction / Distance	Map ID	Page
BRITANNIA BOULEVARD Facility Id: 37070001 Status: Certified O&M - Land Use Restrictions Only	***2133, 2155, 2177, 21***	***ESE 1/4 - 1/2 (0.322 mi.)***	***42***	***387***
HONEYWELL Facility Id: 71003124 Status: No Further Action	***2055 DUBLIN DR.***	***E 1/2 - 1 (0.516 mi.)***	***48***	***543***

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.

A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CACTUS ROAD- AKA TRI Database: SWF/LF (SWIS), Date of Government Version: 11/03/2022 Regulation Status: Unpermitted Facility ID: 37-CR-0011 Operational Status: Closed	1700-1902 CACTUS ROA	NNW 0 - 1/8 (0.095 mi.)	B4	15

Lists of state and tribal leaking storage tanks

SAN DIEGO CO. SAM: The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

A review of the SAN DIEGO CO. SAM list, as provided by EDR, and dated 03/23/2010 has revealed that there are 5 SAN DIEGO CO. SAM sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARTINEZ RANCH	***2160 CACTUS RD***	***SSW 0 - 1/8 (0.101 mi.)***	***C7***	***24***
Case Number: H99064-001				
Facility Status: Preliminary Assessment				
TRIP LANDFILL/CACTUS	***W CACTUS S OTAY MESA***	***NNW 1/4 - 1/2 (0.274 mi.)***	***F40***	***382***
Case Number: H32115-001				
Facility Status: Preliminary Assessment				
U S BORDER PATROL/BR	***7060 BOEING ST***	***NNW 1/4 - 1/2 (0.279 mi.)***	***41***	***384***
Case Number: H21496-001				
Facility Status: Closed Case				
LANCAIR CORP	***1424 CONTINENTAL ST***	***N 1/4 - 1/2 (0.325 mi.)***	***H44***	***398***
Case Number: H10618-001				
Case Number: H10618-002				
Case Number: H10618-003				
Case Number: H10618-004				
Case Number: H10618-005				
**Additional key fields are available in the Map Findings section*				
Facility Status: Preliminary Assessment				
Facility Status: Remedial Investigation				
Facility Status: Closed Case				

Lower Elevation	Address	Direction / Distance	Map ID	Page
2380 BRITANNIA BLVD.	***2380 BRITANNIA***	***SE 1/4 - 1/2 (0.437 mi.)***	***45***	***524***
Case Number: H39739-001				
Facility Status: Closed Case				

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there are 3 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CITY OF SAN DIEGO-BR	1424 CONTINENTAL ST	N 1/4 - 1/2 (0.325 mi.)	H43	397
Database: LUST REG 9, Date of Government Version: 03/01/2001				
Status: Preliminary site assessment underway				
Case Number: 9UT3904				
LANCAIR CORP	***1424 CONTINENTAL ST***	***N 1/4 - 1/2 (0.325 mi.)***	***H44***	***398***
Database: LUST REG 9, Date of Government Version: 03/01/2001				
Database: LUST, Date of Government Version: 03/06/2023				

Status: Completed - Case Closed
Closed Date: 3/4/87
Closed Date: 4/21/87
Closed Date: 8/16/99
Global Id: T0607301154
Global Id: T0607301159
Global Id: T0607301167
Global Id: T0607300600
Global Id: T0607300589
**Additional key fields are available in the Map Findings section*
Status: Case Closed
Status: Preliminary site assessment underway
Case Number: 9UT712
Case Number: 9UT692
Case Number: 9UT1467
Case Number: 9UT1796
Case Number: 9UT1797
**Additional key fields are available in the Map Findings section*

PIPER RANCH BUSINESS	***6464 OTAY MESA RD***	***NW 1/4 - 1/2 (0.446 mi.)***	***46***	***536***

Database: LUST REG 9, Date of Government Version: 03/01/2001
Database: LUST, Date of Government Version: 03/06/2023
Status: Completed - Case Closed
Closed Date: 2/21/95
Global Id: T0607302117
Status: Case Closed
Case Number: 9UT3356

CPS-SLIC: Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the CPS-SLIC list, as provided by EDR, has revealed that there are 9 CPS-SLIC sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARTINEZ RANCH	***2160 CACTUS RD***	***SSW 0 - 1/8 (0.101 mi.)***	***C6***	***21***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Completed - Case Closed
Global Id: T06019770242

OTAY MESA ROAD WIDEN	***NONE OTAY MESA RD***	***NNW 1/4 - 1/2 (0.251 mi.)***	***F39***	***381***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Completed - Case Closed
Global Id: T0608166754

TRIP LANDFILL/CACTUS	***W CACTUS S OTAY MESA***	***NNW 1/4 - 1/2 (0.274 mi.)***	***F40***	***382***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Completed - Case Closed
Global Id: T0608106121

U S BORDER PATROL/BR	***7060 BOEING ST***	***NNW 1/4 - 1/2 (0.279 mi.)***	***41***	***384***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Completed - Case Closed
Global Id: T0608177377

LANCAIR CORP	***1424 CONTINENTAL ST***	***N 1/4 - 1/2 (0.325 mi.)***	***H44***	***398***

Database: CPS-SLIC, Date of Government Version: 03/06/2023

Facility Status: Completed - Case Closed
Global Id: T0608160843

Lower Elevation	Address	Direction / Distance	Map ID	Page
PIPER RANCH BUSINESS	***6464 OTAY MESA RD***	***NW 1/4 - 1/2 (0.446 mi.)***	***46***	***536***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Completed - Case Closed
Global Id: T0608115400

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRIPP SALVAGE LANDFI	***1890 CACTUS ROAD***	***W 0 - 1/8 (0.013 mi.)***	***A2***	***11***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Completed - Case Closed
Global Id: SL209274202

Lower Elevation	Address	Direction / Distance	Map ID	Page
2380 BRITANNIA BLVD.	***2380 BRITANNIA***	***SE 1/4 - 1/2 (0.437 mi.)***	***45***	***524***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Completed - Case Closed
Global Id: T10000001097

Lower Elevation	Address	Direction / Distance	Map ID	Page
MARTINEZ FARMS, INC.	***2440 CACTUS ROAD***	***SSW 1/4 - 1/2 (0.459 mi.)***	***47***	***540***

Database: CPS-SLIC, Date of Government Version: 03/06/2023
Facility Status: Open - Site Assessment
Global Id: T10000006065

Lists of state and tribal registered storage tanks

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, has revealed that there are 2 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NOIL USA INC.	1605 CACTUS RD	NNW 1/8 - 1/4 (0.224 mi.)	F34	370

Database: UST, Date of Government Version: 12/02/2022
Facility Id: 37-000-216147

Lower Elevation	Address	Direction / Distance	Map ID	Page
AT&T CALIFORNIA - D3	1670 CACTUS RD	NNW 1/8 - 1/4 (0.146 mi.)	B12	124

Database: UST, Date of Government Version: 12/02/2022
Facility Id: 37-000-129788

AST: A listing of aboveground storage tank petroleum storage tank locations.

A review of the AST list, as provided by EDR, has revealed that there are 2 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARTINEZ RANCH	***2160 CACTUS RD***	***SSW 0 - 1/8 (0.101 mi.)***	***C7***	***24***

Database: AST, Date of Government Version: 07/06/2016

Lower Elevation	Address	Direction / Distance	Map ID	Page
ASSOCIATED READY MIX	*1696 CACTUS RD*	*NNW 0 - 1/8 (0.103 mi.)*	*B8*	*26*
Database: AST, Date of Government Version: 07/06/2016				

Lists of state and tribal voluntary cleanup sites

VCP: Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

A review of the VCP list, as provided by EDR, and dated 01/23/2023 has revealed that there is 1 VCP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BRITANNIA BOULEVARD	*2133, 2155, 2177, 21*	*ESE 1/4 - 1/2 (0.322 mi.)*	*42*	*387*
Status: Certified O&M - Land Use Restrictions Only				
Facility Id: 37070001				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 01/05/2023 has revealed that there are 7 CERS HAZ WASTE sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ADESA SAN DIEGO	*2175 CACTUS RD*	*SSW 1/8 - 1/4 (0.178 mi.)*	*E21*	*207*
NOIL USA INC.	*1605 CACTUS RD*	*NNW 1/8 - 1/4 (0.224 mi.)*	*F33*	*319*

Lower Elevation	Address	Direction / Distance	Map ID	Page
ASSOCIATED READY MIX	*1696 CACTUS RD*	*NNW 0 - 1/8 (0.103 mi.)*	*B9*	*34*
AT&T CALIFORNIA - D3	*1670 CACTUS RD*	*NNW 1/8 - 1/4 (0.146 mi.)*	*B13*	*125*
BORDER TIRE #15	*6975 CAMINO MAQUILAD*	*NNW 1/8 - 1/4 (0.173 mi.)*	*D18*	*197*
BAJA AUTO PARTS #2	*6960 CAMINO MAQUILAD*	*NW 1/8 - 1/4 (0.216 mi.)*	*D23*	*254*
905 SMOG & AUTO REPA	*6960 CAMINO MAQUILAD*	*NW 1/8 - 1/4 (0.216 mi.)*	*D25*	*284*

EXECUTIVE SUMMARY

Local Lists of Registered Storage Tanks

CERS TANKS: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

A review of the CERS TANKS list, as provided by EDR, and dated 01/06/2023 has revealed that there are 3 CERS TANKS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NOIL USA INC.	***1605 CACTUS RD***	***NNW 1/8 - 1/4 (0.224 mi.)***	***F33***	***319***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
ASSOCIATED READY MIX	***1696 CACTUS RD***	***NNW 0 - 1/8 (0.103 mi.)***	***B9***	***34***
AT&T CALIFORNIA - D3	***1670 CACTUS RD***	***NNW 1/8 - 1/4 (0.146 mi.)***	***B13***	***125***

Local Land Records

DEED: The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes .

A review of the DEED list, as provided by EDR, and dated 11/28/2022 has revealed that there are 2 DEED sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRIPP SALVAGE LANDFI	***1890 CACTUS ROAD***	***W 0 - 1/8 (0.013 mi.)***	***A2***	***11***
Status: COMPLETED - CASE CLOSED Envirostor ID: SL209274202				
BRITANNIA BOULEVARD	***2133, 2155, 2177, 21***	***ESE 1/4 - 1/2 (0.322 mi.)***	***42***	***387***
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY Envirostor ID: 37070001				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/06/2023 has revealed that there are 19 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ADESA CALIFORNIA LLC EPA ID:: CAL000346874	2175 CACTUS RD	SSW 1/8 - 1/4 (0.178 mi.)	E20	205
DIRECT RECONDITIONIN EPA ID:: CAL000429226	2175 CACTUS ROAD	SSW 1/8 - 1/4 (0.178 mi.)	E22	252
NOIL USA INC	1605 CACTUS RD	NNW 1/8 - 1/4 (0.224 mi.)	F32	317

EPA ID:: CAL000418575

Lower Elevation	Address	Direction / Distance	Map ID	Page
YVETTE ALCARAZ EPA ID:: CAC003145547	1942 CACTUS ROAD	W 0 - 1/8 (0.012 mi.)	A1	9
IRMA TATUM EPA ID:: CAC003026135	1812 CACTUS RD.	NW 0 - 1/8 (0.015 mi.)	3	12
CALTRANS EPA ID:: CAP000199299	1703 CACTUS RD	NNW 0 - 1/8 (0.101 mi.)	B5	18
ASSOCIATED READY MIX EPA ID:: CAL000270953	1696 CACTUS RD	NNW 0 - 1/8 (0.103 mi.)	B10	120
SUNSET CAR RENTAL LL EPA ID:: CAL000367120	1690 CACTUS RD	NNW 1/8 - 1/4 (0.125 mi.)	B11	122
BORDER RECAPPING LLC EPA ID:: CAL000466847	6975 CAMINO MAQUILAD	NNW 1/8 - 1/4 (0.173 mi.)	D17	194
PINNACLE INDUSTRIAL EPA ID:: CAL000355386	6975 CAMINO MAQUILAD	NNW 1/8 - 1/4 (0.173 mi.)	D19	202
M RIOS TRUCKING INC EPA ID:: CAR000217547	***6950 CAMINO MAQUILAD***	***NW 1/8 - 1/4 (0.216 mi.)***	***D24***	***261***
JOSE GRACIA EPA ID:: CAC003069222	6960 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.216 mi.)	D26	305
BAJA AUTO PARTS #2 EPA ID:: CAL000403322	6960 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.216 mi.)	D27	307
BROWNFIELD AUTOMOTIV EPA ID:: CAL000465125	6960 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.216 mi.)	D28	309
NAHUM LLC EPA ID:: CAC002988639	6950 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.216 mi.)	D29	312
905 SMOG & AUTO REPA EPA ID:: CAL000297004	6960 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.216 mi.)	D30	314
UNION CHEMICAR AMERI EPA ID:: CAL000376517	6940 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.230 mi.)	G36	374
MENDEOLA TRANSAXLES EPA ID:: CAC003079987	6935 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.237 mi.)	G37	376
MENDEOLA TRANSAXLES EPA ID:: CAL000456162 EPA ID:: CAC003158330	6935 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.237 mi.)	G38	379

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 11/01/2022 has revealed that there is 1 FUDS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BROWN FIELD NAVAL AU		NW 1/2 - 1 (0.572 mi.)	I51	569

EXECUTIVE SUMMARY

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 03/30/2023 has revealed that there is 1 PFAS ECHO site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ASSOCIATED READY MIX		NW 1/8 - 1/4 (0.148 mi.)	15	177

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 12/14/2022 has revealed that there are 2 Cortese sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LANCAIR CORP	***1424 CONTINENTAL ST***	***N 1/4 - 1/2 (0.325 mi.)***	***H44***	***398***
Cleanup Status: COMPLETED - CASE CLOSED				
PIPER RANCH BUSINESS	***6464 OTAY MESA RD***	***NW 1/4 - 1/2 (0.446 mi.)***	***46***	***536***
Cleanup Status: COMPLETED - CASE CLOSED				

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 2 HIST CORTESE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LANCAIR CORP	***1424 CONTINENTAL ST***	***N 1/4 - 1/2 (0.325 mi.)***	***H44***	***398***
Reg Id: 9UT3904				
Reg Id: 9UT692				
Reg Id: 9UT712				
Reg Id: 9UT1796				
Reg Id: 9UT1797				
**Additional key fields are available in the Map Findings section*				
PIPER RANCH BUSINESS	***6464 OTAY MESA RD***	***NW 1/4 - 1/2 (0.446 mi.)***	***46***	***536***
Reg Id: 9UT3356				

HWT: A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

A review of the HWT list, as provided by EDR, and dated 01/03/2023 has revealed that there is 1 HWT site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
M RIOS TRUCKING INC Reg Num: 6020	6950 CAMINO MAQUILAD	NW 1/8 - 1/4 (0.216 mi.)	D31	317

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 12/07/2022 has revealed that there is 1 Notify 65 site within approximately 1 mile of the target property.


Lower Elevation	Address	Direction / Distance	Map ID	Page
CORNER OF OTAY MESA	ROAD	NW 1/2 - 1 (0.561 mi.)	49	568

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

Site Name	Database(s)
FEDEX FREIGHT, INC. OTM	CERS HAZ WASTE
TRIP LANDFILL/CACTUS RD PROPER	RGA LUST
9630 CACTUS CT	HMIRS
6390 CACTUS CT	HMIRS

OVERVIEW MAP - 07305239.2R



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

County Boundary

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

Areas of Concern


N

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	The Collection At Cactus	CLIENT:	Hillmann Environmental Co.
ADDRESS:	7020 Airway Rd San Diego CA 92154	CONTACT:	Gabby Cyrulik
		INQUIRY #:	07305239.2r
LAT/LONG:	32.562489 / 116.98624	DATE:	April 11, 2023 4:20 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 07305239.2R



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	The Collection At Cactus	CLIENT:	Hillmann Environmental Co.
ADDRESS:	7020 Airway Rd San Diego CA 92154	CONTACT:	Gabby Cyrulik
		INQUIRY #:	07305239.2r
LAT/LONG:	32.562489 / 116.98624	DATE:	April 11, 2023 4:20 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	1	NR	NR	NR	1
RCRA-SQG	0.250		0	2	NR	NR	NR	2
RCRA-VSQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal (Superfund) equivalent sites								
RESPONSE	1.000		0	0	0	0	NR	0
Lists of state- and tribal hazardous waste facilities								
ENVIROSTOR	1.000		0	0	1	2	NR	3
Lists of state and tribal landfills and solid waste disposal facilities								
SWF/LF	0.500		1	0	0	NR	NR	1

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Lists of state and tribal leaking storage tanks								
SAN DIEGO CO. SAM	0.500		1	0	4	NR	NR	5
LUST	0.500		0	0	3	NR	NR	3
INDIAN LUST	0.500		0	0	0	NR	NR	0
CPS-SLIC	0.500		2	0	7	NR	NR	9
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250		0	2	NR	NR	NR	2
AST	0.250		2	0	NR	NR	NR	2
INDIAN UST	0.250		0	0	NR	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
INDIAN VCP	0.500		0	0	0	NR	NR	0
VCP	0.500		0	0	1	NR	NR	1
Lists of state and tribal brownfield sites								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	0	NR	NR	0
HAULERS	0.001		0	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	0	0	NR	0
SCH	0.250		0	0	NR	NR	NR	0
CDL	0.001		0	NR	NR	NR	NR	0
San Diego Co. HMMD	0.001		0	NR	NR	NR	NR	0
CERS HAZ WASTE	0.250		1	6	NR	NR	NR	7
Toxic Pits	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.250		0	0	NR	NR	NR	0
HIST UST	0.250		0	0	NR	NR	NR	0
CA FID UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CERS TANKS	0.250		1	2	NR	NR	NR	3
Local Land Records								
LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
DEED	0.500		1	0	1	NR	NR	2
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
CHMIRS	0.001		0	NR	NR	NR	NR	0
LDS	0.001		0	NR	NR	NR	NR	0
MCS	0.001		0	NR	NR	NR	NR	0
SPILLS 90	0.001		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		4	15	NR	NR	NR	19
FUDS	1.000		0	0	0	1	NR	1
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001		0	NR	NR	NR	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	1	NR	NR	NR	1
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
PFAS	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM	TP		NR	NR	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	0	NR	0
Cortese	0.500		0	0	2	NR	NR	2
CUPA Listings	0.250		0	0	NR	NR	NR	0
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
EMI	0.001		0	NR	NR	NR	NR	0
ENF	0.001		0	NR	NR	NR	NR	0
Financial Assurance	0.001		0	NR	NR	NR	NR	0
ICE	0.001		0	NR	NR	NR	NR	0
HIST CORTESE	0.500		0	0	2	NR	NR	2
HWP	1.000		0	0	0	0	NR	0
HWT	0.250		0	1	NR	NR	NR	1
HAZNET	0.001		0	NR	NR	NR	NR	0
MINES	0.250		0	0	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
PEST LIC	0.001		0	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	0	0	1	NR	1
HAZMAT	0.250		0	0	NR	NR	NR	0
UIC	0.001		0	NR	NR	NR	NR	0
UIC GEO	0.001		0	NR	NR	NR	NR	0
WASTEWATER PITS	0.500		0	0	0	NR	NR	0
WDS	0.001		0	NR	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
MILITARY PRIV SITES	0.001		0	NR	NR	NR	NR	0
PROJECT	0.001		0	NR	NR	NR	NR	0
WDR	0.001		0	NR	NR	NR	NR	0
SAN DIEGO CO LOP	0.001		0	NR	NR	NR	NR	0
CIWQS	0.001		0	NR	NR	NR	NR	0
CERS	0.001		0	NR	NR	NR	NR	0
NON-CASE INFO	0.001		0	NR	NR	NR	NR	0
OTHER OIL GAS	0.001		0	NR	NR	NR	NR	0
PROD WATER PONDS	0.001		0	NR	NR	NR	NR	0
SAMPLING POINT	0.001		0	NR	NR	NR	NR	0
WELL STIM PROJ	0.001		0	NR	NR	NR	NR	0
HWTS	TP		NR	NR	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
MINES MRDS	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	0.001		0	NR	NR	NR	NR	0
RGA LUST	0.001		0	NR	NR	NR	NR	0
- Totals --		0	13	30	21	4	0	68

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
West
< 1/8
0.012 mi.
63 ft.

YVETTE ALCARAZ
1942 CACTUS ROAD
SAN DIEGO, CA 92154

Site 1 of 2 in cluster A

RCRA NonGen / NLR | **1027073898** | **CAC003145547**

Relative:
Lower

Actual:
498 ft.

RCRA Listings:

Date Form Received by Agency:	20211027
Handler Name:	Yvette Alcaraz
Handler Address:	1942 CACTUS ROAD
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAC003145547
Contact Name:	YVETTE ALCARAZ
Contact Address:	1942 CACTUS ROAD
Contact City,State,Zip:	SAN DIEGO, CA 92154
Contact Telephone:	619-496-1226
Contact Fax:	Not reported
Contact Email:	TERRI.KLICKA@NORTH-STATE.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1942 CACTUS ROAD
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Yvette Alcaraz
Owner Type:	Other
Operator Name:	Yvette Alcaraz
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

YVETTE ALCARAZ (Continued) **1027073898**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211027
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: YVETTE ALCARAZ	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1942 CACTUS ROAD
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-496-1226
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: YVETTE ALCARAZ	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1942 CACTUS ROAD
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-496-1226
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20211027
Handler Name: YVETTE ALCARAZ	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

YVETTE ALCARAZ (Continued) **1027073898**

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A2 West < 1/8 0.013 mi. 66 ft. **TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA TRIPP** **CPS-SLIC S122829019**
1890 CACTUS ROAD **DEED N/A**
SAN DIEGO, CA 92154 **CERS**

Site 2 of 2 in cluster A

Relative: Lower
Actual: 501 ft.

CPS-SLIC:
Name: TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA TRIPP SALVAGE LANDFILL
Address: 1890 CACTUS ROAD
City,State,Zip: SAN DIEGO, CA 92154
Region: STATE
Facility Status: Completed - Case Closed
Status Date: 10/17/2017
Global Id: SL209274202
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number: Not reported
Latitude: 32.5636422854041
Longitude: -116.989181041717
Case Type: Cleanup Program Site
Case Worker: Not reported
Local Agency: Not reported
RB Case Number: 2092700
File Location: Regional Board
Potential Media Affected: Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern: Copper, Lead, Zinc
EPA Region: 9
Coordinate Source: Google Map Move
Cuf Case: NO
Quantity Released Gallons: Not reported
Begin Date: 05/01/1997
Leak Reported Date: 01/02/1965
How Discovered: * RPR
How Discovered Description: Not reported
Discharge Source: Not reported
Discharge Cause: Not reported
Stop Method: Not reported
Stop Description: Not reported
No Further Action Date: 10/17/2017
CA Water Watershed Name: Tijuana - Tijuana Valley - Water Tanks (911.12)
Dwr Groundwater Subbasin Name: Not reported
Disadvantaged Community: Not reported
CA Enviroscreen 3 Score: 56-60%
CA Enviroscreen 4 Score: 55-60%
Military DOD Site: No
Facility Project Subtype: Not reported

TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA TRIPP SALVAGE L (Continued) **S122829019**

RWQCB Region: SAN DIEGO RWQCB (REGION 9)
Site History: Part of Tripp Salvage Landfill. Automobile dismantling waste was placed on the Sesi Property from approximately 1968 to 1977, and burn ash-contaminated soil was placed in on the property in 1987. This material was covered with fill from other landfills in the area. It is estimated that the waste extends to a depth of approximately 65 feet. Groundwater samples collected from this property in 1998 reportedly contained VOCs, SVOCs, and metals. A Revegetation Plan prepared 2006 proposed excavation of a portion of the waste and placement of a soil cap over the remaining waste. According to the County LEA, soil cap design and associated grading plans have been submitted to City of San Diego for review but the cap has not yet been constructed. On September 25, 1996, the County of San Diego Department of Environmental Health (DEH) was designated by the California Environmental Protection Agency (CalEPA) Site Designation Committee as the Administering Agency for the Sesi Group / Tripp Salvage Landfill.

Click here to access the California GeoTracker records for this facility:

DEED:
Name: SESI PROPERTY - AKA TRIPP SALVAGE LANDFILL
Address: 1890 CACTUS ROAD
City,State,Zip: SAN DIEGO, CA 92154
Envirostor ID: SL209274202
Area: Not reported
Sub Area: Not reported
Site Type: SLIC
Status: COMPLETED - CASE CLOSED
Agency: SWRCB
Covenant Uploaded: Y
Deed Date(s): 11/19/2015
File Name: Geotracker Land Use/Deed Restrictions

CERS:
Name: TRIPP SALVAGE LANDFILL - SESI PROPERTY - AKA TRIPP SALVAGE LANDFILL
Address: 1890 CACTUS ROAD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 260024
CERS ID: SL209274202
CERS Description: Cleanup Program Site

---

3 **IRMA TATUM** **RCRA NonGen / NLR** **1025846333**
NW **1812 CACTUS RD.** **CAC003026135**
< 1/8 **SAN DIEGO, CA 92154**
0.015 mi.
77 ft.

Relative: **Lower**
Actual: **495 ft.**

RCRA Listings:
Date Form Received by Agency: 20190726
Handler Name: Irma Tatum
Handler Address: 1812 CACTUS RD.
Handler City,State,Zip: SAN DIEGO, CA 92154
EPA ID: CAC003026135
Contact Name: IRMA TATUM
Contact Address: 1812 CACTUS RD.
Contact City,State,Zip: SAN DIEGO, CA 92154

IRMA TATUM (Continued) **1025846333**

Contact Telephone:	619-805-6998
Contact Fax:	Not reported
Contact Email:	IBCINDY91932@YAHOO.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1812 CACTUS RD.
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Irma Tatum
Owner Type:	Other
Operator Name:	Irma Tatum
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No

IRMA TATUM (Continued) **1025846333**

Manifest Broker: No
Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: IRMA TATUM
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1812 CACTUS RD.
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-805-6998
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: IRMA TATUM
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1812 CACTUS RD.
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-805-6998
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20190726
Handler Name: IRMA TATUM
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B4 **CACTUS ROAD- AKA TRIPP SALVAGE** **SWF/LF** **S101669413**
NNW **1700-1902 CACTUS ROAD** **N/A**
< 1/8 **SAN DIEGO, CA 92154**
0.095 mi.
501 ft. **Site 1 of 9 in cluster B**

Relative:
Lower

Actual:
504 ft.

SWF/LF (SWIS):

Name:	CACTUS ROAD- AKA TRIPP SALVAGE
Address:	1700-1902 CACTUS ROAD
City,State,Zip:	SAN DIEGO, CA 92154
Region:	STATE
Facility ID:	37-CR-0011
SWIS Number:	37-CR-0011
Point of Contact:	Abel Martinez-Centeno
Is Archived:	No
Is Closed Illegal Abandoned:	Yes
Is Site Inert Debris Engineered Fill:	No
Is Financial Assurances Responsible:	No
Absorbed On:	Not reported
Operational Status:	Closed
Absorbed By:	Not reported
Closed Illegal Abandoned Category:	C1
EPA Federal Registry ID:	Not reported
ARB District:	San Diego
SWRCB Region:	San Diego
Local Government:	San Diego
Reporting Agency Legal Name:	City of San Diego
Reporting Agency Department:	Development Services Department
Enforcing Agency Legal Name:	City of San Diego
Enforcing Agency Department:	Development Services Department
Regulation Status:	Unpermitted

Activity:

SWIS Number:	37-CR-0011
Site Name:	Cactus Road- AKA Tripp Salvage
Activity:	Solid Waste Disposal Site
Activity Is Archived:	No
Category:	Disposal
Activity Classification:	Solid Waste Disposal Site
WDR Number:	Not reported
WDR Landfill Class:	Not reported
Cease Operation:	Not reported
Cease Operation Type:	Not reported
Inspection Frequency:	Annual
Throughput:	Not reported
Throughput Units:	Not reported
Remaining Capacity:	Not reported
Remaining Capacity Date:	Not reported
Capacity:	Not reported
Capacity Units:	Not reported
Total Acreage:	0
Disposal Acreage:	0
Permitted Elevation:	Not reported
Permitted Elevation Type:	Not reported
Permitted Depth:	Not reported
Permitted Depth Type:	Not reported
Point of Contact:	Abel Martinez-Centeno
Site Operational Status:	Closed
Site Regulatory Status:	Unpermitted
Site Is Archived:	No

CACTUS ROAD- AKA TRIPP SALVAGE (Continued) **S101669413**

Is Closed Illegal Abandoned:	Yes
Is Site Inert Debris Engineered Fill:	No
Is Financial Assurances Responsible:	No
Absorbed On:	Not reported
Absorbed By:	Not reported
Closed Illegal Abandoned Category:	C1
EPA Federal Registry ID:	Not reported
County:	San Diego
ARB District:	San Diego
SWRCB Region:	San Diego
Local Government:	San Diego
Street Address:	1700-1902 Cactus Road
City:	San Diego
State:	CA
ZIP Code:	92154
Reporting Agency Legal Name:	City of San Diego
Reporting Agency Department:	Development Services Department
Enforcing Agency Legal Name:	City of San Diego
Enforcing Agency Department:	Development Services Department

Owner:

SWIS Number:	37-CR-0011
Owner:	CalTrans- District 11
Owner Address:	Owen A. Chung 4050 Taylor St. MS 242
Owner City:	San Diego
Owner State:	CA
Owner Zip:	92110
Site Name:	Cactus Road- AKA Tripp Salvage
Site Operational Status:	Closed
Site Type:	Disposal Only
Site Regulatory Status:	Unpermitted
Latitude:	32.56392
Longitude:	-116.98903
Is Archived:	No
Started On:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported
Contact Phone:	(619) 688-3153

SWIS Number:	37-CR-0011
Owner:	Sesi Group
Owner Address:	Dr. Jabir Adamo-APN:646-100-4900 & 7300 2129 Furner St.
Owner City:	El Cajon
Owner State:	CA
Owner Zip:	92020
Site Name:	Cactus Road- AKA Tripp Salvage
Site Operational Status:	Closed
Site Type:	Disposal Only
Site Regulatory Status:	Unpermitted
Latitude:	32.56392
Longitude:	-116.98903
Is Archived:	No
Started On:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

CACTUS ROAD- AKA TRIPP SALVAGE (Continued) **S101669413**

Contact Phone:	(619) 933-5696
SWIS Number:	37-CR-0011
Owner:	Opper & Varco LLP
Owner Address:	Richard Opper-APN:646-100-4900 & 7300 225 Broadway St., Suite 1900
Owner City:	San Diego
Owner State:	CA
Owner Zip:	92101
Site Name:	Cactus Road- AKA Tripp Salvage
Site Operational Status:	Closed
Site Type:	Disposal Only
Site Regulatory Status:	Unpermitted
Latitude:	32.56392
Longitude:	-116.98903
Is Archived:	No
Started On:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported
Contact Phone:	(619) 231-5858
SWIS Number:	37-CR-0011
Owner:	Charles E. & Irma J. Tatum
Owner Address:	APN: 646-100-4800 737 Holly Ave.
Owner City:	Imperial
Owner State:	CA
Owner Zip:	91932
Site Name:	Cactus Road- AKA Tripp Salvage
Site Operational Status:	Closed
Site Type:	Disposal Only
Site Regulatory Status:	Unpermitted
Latitude:	32.56392
Longitude:	-116.98903
Is Archived:	No
Started On:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported
Contact Phone:	(619) 575-9599
SWIS Number:	37-CR-0011
Owner:	Sesi Group
Owner Address:	Sesi Salim-APN:646-100-4900 & 7300 747 Vista Grande Rd.
Owner City:	El Cajon
Owner State:	CA
Owner Zip:	92019
Site Name:	Cactus Road- AKA Tripp Salvage
Site Operational Status:	Closed
Site Type:	Disposal Only
Site Regulatory Status:	Unpermitted
Latitude:	32.56392
Longitude:	-116.98903
Is Archived:	No
Started On:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

CACTUS ROAD- AKA TRIPP SALVAGE (Continued) **S101669413**

Contact Phone: (619) 588-7882

B5 **CALTRANS** **RCRA NonGen / NLR** **1025880729**
NNW **1703 CACTUS RD** **CAP000199299**
< 1/8 **SAN DIEGO, CA 92154**
0.101 mi.
533 ft. **Site 2 of 9 in cluster B**

Relative: **Lower**

Actual: **504 ft.**

RCRA Listings:

Date Form Received by Agency:	20090622
Handler Name:	Caltrans
Handler Address:	1703 CACTUS RD
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAP000199299
Contact Name:	SANDRA L DURBIN
Contact Address:	4050 TAYLOR ST
Contact City,State,Zip:	SAN DIEGO, CA 92110
Contact Telephone:	619-302-4685
Contact Fax:	Not reported
Contact Email:	SANDRA.DURBIN@DOT.CA.GOV
Contact Title:	Not reported
EPA Region:	09
Land Type:	State
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4050 TAYLOR ST
Mailing City,State,Zip:	SAN DIEGO, CA 92110
Owner Name:	Caltrans District 11
Owner Type:	State
Operator Name:	Janus Corp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

CALTRANS (Continued) **1025880729**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20090622
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JANUS CORP	
Legal Status:	Private
Date Became Current:	20081031
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CALTRANS DISTRICT 11	
Legal Status:	State
Date Became Current:	20080619
Date Ended Current:	Not reported
Owner/Operator Address:	4050 TAYLOR ST
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92110
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CALTRANS DISTRICT 11	
Legal Status:	State
Date Became Current:	20080619
Date Ended Current:	Not reported
Owner/Operator Address:	4050 TAYLOR ST

CALTRANS (Continued) **1025880729**

Owner/Operator City,State,Zip: SAN DIEGO, CA 92110
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JANUS CORP
Legal Status: Private
Date Became Current: 20081031
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20090317
Handler Name: CALTRANS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090622
Handler Name: CALTRANS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23622
NAICS Description: COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

NAICS Code: 562112
NAICS Description: HAZARDOUS WASTE COLLECTION

NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

CALTRANS (Continued) **1025880729**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C6 **MARTINEZ RANCH** **CPS-SLIC S110497822**
SSW **2160 CACTUS RD** **San Diego Co. HMMD N/A**
< 1/8 **SAN DIEGO, CA 92154**
0.101 mi.
534 ft. **Site 1 of 2 in cluster C**

Relative:
Higher

Actual:
514 ft.

CPS-SLIC:

Name:	MARTINEZ RANCH
Address:	2160 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	10/29/2012
Global Id:	T06019770242
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H99064-001
Latitude:	32.559274
Longitude:	-116.989567
Case Type:	Cleanup Program Site
Case Worker:	SW
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
EPA Region:	9
Coordinate Source:	Manual Entry on Screens
Cuf Case:	NO
Quantity Released Gallons:	Not reported
Begin Date:	11/05/2004
Leak Reported Date:	Not reported
How Discovered:	Not reported
How Discovered Description:	Not reported
Discharge Source:	Not reported
Discharge Cause:	Not reported
Stop Method:	Not reported
Stop Description:	Not reported
No Further Action Date:	10/29/2012
CA Water Watershed Name:	Tijuana - Tijuana Valley - Water Tanks (911.12)
Dwr Groundwater Subbasin Name:	Not reported
Disadvantaged Community:	Not reported
CA Enviroscreen 3 Score:	66-70%
CA Enviroscreen 4 Score:	55-60%
Military DOD Site:	No
Facility Project Subtype:	Not reported
RWQCB Region:	SAN DIEGO RWQCB (REGION 9)
Site History:	Refer to "Site Maps/Documents" for Admin Closure Memo

Click here to access the California GeoTracker records for this facility:

MARTINEZ RANCH (Continued) **S110497822**

HMMD SAN DIEGO:

Name:	MARTINEZ RANCH
Address:	2160 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	199064
Business Type:	6HKAG
EPA Id Number:	Not reported
APN:	646-100-20-00
Last HMMD Inspection:	03/08/2010
Facility Telephone:	619-661-5415
Permit Status:	EXEM
Permit Expiration:	09/25/2002
Date Last Updated:	11/02/2012
Facility Owner:	JESUS MARTINEZ
Facility Mailing Address:	2160 CACTUS RD
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154-8001
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Y
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Name:	MARTINEZ RANCH
Address:	2160 CACTUS
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	211670
Business Type:	6HK26
EPA Id Number:	Not reported
APN:	646-100-20-00
Last HMMD Inspection:	01/08/2010
Facility Telephone:	619-666-3837
Permit Status:	OPEN
Permit Expiration:	04/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	JESUS MARTINEZ
Facility Mailing Address:	2160 CACTUS RD
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	211670
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 221 WASTE OIL & MIXED OIL
Other Information:	USED OIL

MARTINEZ RANCH (Continued) **S110497822**

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211670
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information: OILY RAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211670
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 211670
Update Date: 11/02/2012
Inspection Date: 01/08/2010
Violation Code: 6HV0227
Violation: HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation: Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity: ACTIVE

Permit Number: 211670
Update Date: 11/02/2012
Inspection Date: 01/08/2010
Violation Code: 6HV0131
Violation: UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation: A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity: ACTIVE

Permit Number: 211670
Update Date: 11/02/2012
Inspection Date: 01/08/2010
Violation Code: 6HV0132
Violation: EPA ID NUMBER NOT OBTAINED/MAINTAINED
Violation Citation: Generator of hazardous waste has not obtained/maintained an EPA identification number. CCR 66262.12(a)
Activity: ACTIVE

Permit Number: 211670
Update Date: 11/02/2012
Inspection Date: 01/08/2010
Violation Code: 6HV0224
Violation: MISMANAGED EMPTY CONTAINERS >5GALS.
Violation Citation: Failed to mark date on empty container larger than 5 gallons and/or manage it within one year. 66261.7(e) & (f).

MARTINEZ RANCH (Continued) **S110497822**

Activity:	ACTIVE
Permit Number:	211670
Update Date:	11/02/2012
Inspection Date:	01/08/2010
Violation Code:	6HV0407
Violation:	EMPLOYEE TRAINING NOT ADEQUATE
Violation Citation:	Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)
Activity:	ACTIVE

C7 **MARTINEZ RANCH** **SAN DIEGO CO. SAM** **S106879146**
SSW **2160 CACTUS RD** **AST** **N/A**
< 1/8 **SAN DIEGO, CA 92154** **CERS**
0.101 mi. **HWTS**
534 ft. **Site 2 of 2 in cluster C**

Relative:
Higher

Actual:
514 ft.

SAN DIEGO CO. SAM:

Name:	MARTINEZ RANCH
Address:	2160 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Case Number:	H99064-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**XV**
Facility Type:	Soils Only
Facility Status:	Preliminary Assessment
Date:	11/2/2004
Date Began:	11/5/2004

AST:

Name:	MARTINEZ RANCH
Address:	2160 CACTUS RD
City/Zip:	SAN DIEGO,
Certified Unified Program Agencies:	San Diego
Owner:	MARTINEZ RANCH
Total Gallons:	2610
CERSID:	Not reported
Facility ID:	Not reported
Business Name:	Not reported
Phone:	Not reported
Fax:	Not reported
Mailing Address:	Not reported
Mailing Address City:	Not reported
Mailing Address State:	Not reported
Mailing Address Zip Code:	Not reported
Operator Name:	Not reported
Operator Phone:	Not reported
Owner Phone:	Not reported
Owner Mail Address:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Country:	Not reported
Property Owner Name:	Not reported
Property Owner Phone:	Not reported
Property Owner Mailing Address:	Not reported
Property Owner City:	Not reported

MARTINEZ RANCH (Continued) **S106879146**

Property Owner Stat : Not reported
Property Owner Zip Code: Not reported
Property Owner Country: Not reported
EPAID: Not reported

CERS:
Name: MARTINEZ RANCH
Address: 2160 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 46918
CERS ID: T06019770242
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: SCOTT WELDON - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

HWTS:
Name: MARTINEZ RANCH
Address: 2160 CACTUS RD
Address 2: Not reported
City,State,Zip: SAN DIEGO, CA 92154
EPA ID: CAL000349334
Inactive Date: 06/30/2011
Create Date: 01/19/2010
Last Act Date: Not reported
Mailing Name: Not reported
Mailing Address: 2160 CACTUS RD
Mailing Address 2: Not reported
Mailing City,State,Zip: SAN DIEGO, CA 921548001
Owner Name: JESUS MARTINEZ
Owner Address: 4762 SEA TERN CT
Owner Address 2: Not reported
Owner City,State,Zip: SAN DIEGO, CA 921548511
Contact Name: JESSE MARTINEZ
Contact Address: 4762 SEA TERN CT
Contact Address 2: Not reported
City,State,Zip: SAN DIEGO, CA 921548511
Facility Status: Inactive
Facility Type: PERMANENT
Category: STATE
Latitude: 32.558495
Longitude: -116.98843

NAICS:
EPA ID: CAL000349334
Create Date: 2010-01-19 14:18:25.000
NAICS Code: 111998
NAICS Description: All Other Miscellaneous Crop Farming

MARTINEZ RANCH (Continued) **S106879146**

Issued EPA ID Date:	2010-01-19 14:18:25
Inactive Date:	2011-06-30 00:00:00
Facility Name:	MARTINEZ RANCH
Facility Address:	2160 CACTUS RD
Facility Address 2:	Not reported
Facility City:	SAN DIEGO
Facility County:	Not reported
Facility State:	CA
Facility Zip:	921548001

B8 **ASSOCIATED READY MIXED CONCRETE** **AST** **S108742579**
NNW **1696 CACTUS RD** **NPDES** **N/A**
< 1/8 **SAN DIEGO, CA 92154** **CIWQS**
0.103 mi. **CERS**
545 ft. **Site 3 of 9 in cluster B**

Relative: **Lower**
Actual: **504 ft.**

AST:

Name:	ASSOCIATED READY MIXED CONCRETE, INC
Address:	1696 CACTUS RD
City/Zip:	SAN DIEGO,92154
Certified Unified Program Agencies:	Not reported
Owner:	ASSOCIATED READY MIXED CONCRETE, INC
Total Gallons:	Not reported
CERSID:	10394077
Facility ID:	37-000-102446
Business Name:	A&A READY MIXED CONCRETE, INC
Phone:	619-661-7555
Fax:	Not reported
Mailing Address:	4621 TELLER AVE # 130
Mailing Address City:	NEWPORT
Mailing Address State:	CA
Mailing Address Zip Code:	92660
Operator Name:	ASSOCIATED READY MIXED CONCRETE, INC
Operator Phone:	619-661-7555
Owner Phone:	949-253-2800
Owner Mail Address:	4621 TELLER AVE 130
Owner State:	CA
Owner Zip Code:	92660
Owner Country:	United States
Property Owner Name:	LEBATA INC
Property Owner Phone:	Not reported
Property Owner Mailing Address:	4621 TELLER AVE 130
Property Owner City:	NEWPORT BEACH
Property Owner Stat :	CA
Property Owner Zip Code:	92660
Property Owner Country:	United States
EPAID:	CAL000270953

Name:	ASSOCIATED READY MIXED CONCRETE
Address:	1696 CACTUS RD
City/Zip:	SAN DIEGO,
Certified Unified Program Agencies:	San Diego
Owner:	ASSOCIATED READY MIXED CONCRETE, INC
Total Gallons:	12805
CERSID:	Not reported
Facility ID:	Not reported
Business Name:	Not reported

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Phone:	Not reported
Fax:	Not reported
Mailing Address:	Not reported
Mailing Address City:	Not reported
Mailing Address State:	Not reported
Mailing Address Zip Code:	Not reported
Operator Name:	Not reported
Operator Phone:	Not reported
Owner Phone:	Not reported
Owner Mail Address:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Country:	Not reported
Property Owner Name:	Not reported
Property Owner Phone:	Not reported
Property Owner Mailing Address:	Not reported
Property Owner City:	Not reported
Property Owner Stat :	Not reported
Property Owner Zip Code:	Not reported
Property Owner Country:	Not reported
EPAID:	Not reported

NPDES:

Name:	ASSOCIATED READY MIXED CONCRETE
Address:	1696 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Facility Status:	Active
NPDES Number:	CAS000001
Region:	9
Agency Number:	0
Regulatory Measure ID:	218851
Place ID:	Not reported
Order Number:	97-03-DWQ
WDID:	9 37I017562
Regulatory Measure Type:	Enrollee
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	11/01/2002
Termination Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Discharge Address:	2730 E Washington Blvd
Discharge Name:	Associated Ready Mixed Concrete
Discharge City:	Los Angeles
Discharge State:	California
Discharge Zip:	90023
Status:	Not reported
Status Date:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City:	Not reported
Operator State:	Not reported
Operator Zip:	Not reported

NPDES as of 03/2018:

NPDES Number:	CAS000001
Status:	Active
Agency Number:	0

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Region:	9
Regulatory Measure ID:	218851
Order Number:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place ID:	Not reported
WDID:	9 37I017562
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	11/01/2002
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Associated Ready Mixed Concrete
Discharge Address:	2730 E Washington Blvd
Discharge City:	Los Angeles
Discharge State:	California
Discharge Zip:	90023
Received Date:	Not reported
Processed Date:	Not reported
Status:	Not reported
Status Date:	Not reported
Place Size:	Not reported
Place Size Unit:	Not reported
Contact:	Not reported
Contact Title:	Not reported
Contact Phone:	Not reported
Contact Phone Ext:	Not reported
Contact Email:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City:	Not reported
Operator State:	Not reported
Operator Zip:	Not reported
Operator Contact:	Not reported
Operator Contact Title:	Not reported
Operator Contact Phone:	Not reported
Operator Contact Phone Ext:	Not reported
Operator Contact Email:	Not reported
Operator Type:	Not reported
Developer:	Not reported
Developer Address:	Not reported
Developer City:	Not reported
Developer State:	Not reported
Developer Zip:	Not reported
Developer Contact:	Not reported
Developer Contact Title:	Not reported
Constype Linear Utility Ind:	Not reported
Emergency Phone:	Not reported
Emergency Phone Ext:	Not reported
Constype Above Ground Ind:	Not reported
Constype Below Ground Ind:	Not reported
Constype Cable Line Ind:	Not reported
Constype Comm Line Ind:	Not reported
Constype Commertial Ind:	Not reported
Constype Electrical Line Ind:	Not reported
Constype Gas Line Ind:	Not reported
Constype Industrial Ind:	Not reported
Constype Other Description:	Not reported

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Constype Other Ind:	Not reported
Constype Recons Ind:	Not reported
Constype Residential Ind:	Not reported
Constype Transport Ind:	Not reported
Constype Utility Description:	Not reported
Constype Utility Ind:	Not reported
Constype Water Sewer Ind:	Not reported
Dir Discharge Uswater Ind:	Not reported
Receiving Water Name:	Not reported
Certifier:	Not reported
Certifier Title:	Not reported
Certification Date:	Not reported
Primary Sic:	Not reported
Secondary Sic:	Not reported
Tertiary Sic:	Not reported
NPDES Number:	Not reported
Status:	Not reported
Agency Number:	Not reported
Region:	9
Regulatory Measure ID:	218851
Order Number:	Not reported
Regulatory Measure Type:	Industrial
Place ID:	Not reported
WDID:	9 37I017562
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Not reported
Discharge Address:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported
Discharge Zip:	Not reported
Received Date:	05/09/2008
Processed Date:	11/01/2002
Status:	Active
Status Date:	11/01/2002
Place Size:	3.5
Place Size Unit:	Acres
Contact:	Jim Parker
Contact Title:	Plant Manager
Contact Phone:	619-661-7555
Contact Phone Ext:	Not reported
Contact Email:	jparker@assocrmc.com
Operator Name:	Associated Ready Mixed Concrete
Operator Address:	2730 E Washington Blvd
Operator City:	Los Angeles
Operator State:	California
Operator Zip:	90023
Operator Contact:	Alex Nichols
Operator Contact Title:	Not reported
Operator Contact Phone:	949-253-2800
Operator Contact Phone Ext:	Not reported
Operator Contact Email:	anichols@assocrmc.com
Operator Type:	Private Business

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Developer:	Not reported
Developer Address:	Not reported
Developer City:	Not reported
Developer State:	California
Developer Zip:	Not reported
Developer Contact:	Not reported
Developer Contact Title:	Not reported
Constype Linear Utility Ind:	Not reported
Emergency Phone:	Not reported
Emergency Phone Ext:	Not reported
Constype Above Ground Ind:	Not reported
Constype Below Ground Ind:	Not reported
Constype Cable Line Ind:	Not reported
Constype Comm Line Ind:	Not reported
Constype Commertial Ind:	Not reported
Constype Electrical Line Ind:	Not reported
Constype Gas Line Ind:	Not reported
Constype Industrial Ind:	Not reported
Constype Other Description:	Not reported
Constype Other Ind:	Not reported
Constype Recons Ind:	Not reported
Constype Residential Ind:	Not reported
Constype Transport Ind:	Not reported
Constype Utility Description:	Not reported
Constype Utility Ind:	Not reported
Constype Water Sewer Ind:	Not reported
Dir Discharge Uswater Ind:	N
Receiving Water Name:	Tijuana River
Certifier:	Jim Parker
Certifier Title:	Plant Manager
Certification Date:	29-JUN-15
Primary Sic:	3273-Ready-Mixed Concrete
Secondary Sic:	Not reported
Tertiary Sic:	Not reported

Name:	ASSOCIATED READY MIXED CONCRETE
Address:	1696 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Facility Status:	Not reported
NPDES Number:	Not reported
Region:	Not reported
Agency Number:	Not reported
Regulatory Measure ID:	Not reported
Place ID:	Not reported
Order Number:	Not reported
WDID:	9 37I017562
Regulatory Measure Type:	Industrial
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Discharge Address:	Not reported
Discharge Name:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Discharge Zip:	Not reported
Status:	Active
Status Date:	11/01/2002
Operator Name:	Associated Ready Mixed Concrete
Operator Address:	2730 E Washington Blvd
Operator City:	Los Angeles
Operator State:	California
Operator Zip:	90023

NPDES as of 03/2018:

NPDES Number:	CAS000001
Status:	Active
Agency Number:	0
Region:	9
Regulatory Measure ID:	218851
Order Number:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place ID:	Not reported
WDID:	9 37I017562
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	11/01/2002
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Associated Ready Mixed Concrete
Discharge Address:	2730 E Washington Blvd
Discharge City:	Los Angeles
Discharge State:	California
Discharge Zip:	90023
Received Date:	Not reported
Processed Date:	Not reported
Status:	Not reported
Status Date:	Not reported
Place Size:	Not reported
Place Size Unit:	Not reported
Contact:	Not reported
Contact Title:	Not reported
Contact Phone:	Not reported
Contact Phone Ext:	Not reported
Contact Email:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City:	Not reported
Operator State:	Not reported
Operator Zip:	Not reported
Operator Contact:	Not reported
Operator Contact Title:	Not reported
Operator Contact Phone:	Not reported
Operator Contact Phone Ext:	Not reported
Operator Contact Email:	Not reported
Operator Type:	Not reported
Developer:	Not reported
Developer Address:	Not reported
Developer City:	Not reported
Developer State:	Not reported
Developer Zip:	Not reported
Developer Contact:	Not reported
Developer Contact Title:	Not reported

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Constype Linear Utility Ind:	Not reported
Emergency Phone:	Not reported
Emergency Phone Ext:	Not reported
Constype Above Ground Ind:	Not reported
Constype Below Ground Ind:	Not reported
Constype Cable Line Ind:	Not reported
Constype Comm Line Ind:	Not reported
Constype Commertial Ind:	Not reported
Constype Electrical Line Ind:	Not reported
Constype Gas Line Ind:	Not reported
Constype Industrial Ind:	Not reported
Constype Other Description:	Not reported
Constype Other Ind:	Not reported
Constype Recons Ind:	Not reported
Constype Residential Ind:	Not reported
Constype Transport Ind:	Not reported
Constype Utility Description:	Not reported
Constype Utility Ind:	Not reported
Constype Water Sewer Ind:	Not reported
Dir Discharge Uswater Ind:	Not reported
Receiving Water Name:	Not reported
Certifier:	Not reported
Certifier Title:	Not reported
Certification Date:	Not reported
Primary Sic:	Not reported
Secondary Sic:	Not reported
Tertiary Sic:	Not reported
NPDES Number:	Not reported
Status:	Not reported
Agency Number:	Not reported
Region:	9
Regulatory Measure ID:	218851
Order Number:	Not reported
Regulatory Measure Type:	Industrial
Place ID:	Not reported
WDID:	9 37I017562
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Not reported
Discharge Address:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported
Discharge Zip:	Not reported
Received Date:	05/09/2008
Processed Date:	11/01/2002
Status:	Active
Status Date:	11/01/2002
Place Size:	3.5
Place Size Unit:	Acres
Contact:	Jim Parker
Contact Title:	Plant Manager
Contact Phone:	619-661-7555
Contact Phone Ext:	Not reported

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Contact Email:	jparker@assocrmc.com
Operator Name:	Associated Ready Mixed Concrete
Operator Address:	2730 E Washington Blvd
Operator City:	Los Angeles
Operator State:	California
Operator Zip:	90023
Operator Contact:	Alex Nichols
Operator Contact Title:	Not reported
Operator Contact Phone:	949-253-2800
Operator Contact Phone Ext:	Not reported
Operator Contact Email:	anichols@assocrmc.com
Operator Type:	Private Business
Developer:	Not reported
Developer Address:	Not reported
Developer City:	Not reported
Developer State:	California
Developer Zip:	Not reported
Developer Contact:	Not reported
Developer Contact Title:	Not reported
Constype Linear Utility Ind:	Not reported
Emergency Phone:	Not reported
Emergency Phone Ext:	Not reported
Constype Above Ground Ind:	Not reported
Constype Below Ground Ind:	Not reported
Constype Cable Line Ind:	Not reported
Constype Comm Line Ind:	Not reported
Constype Commertial Ind:	Not reported
Constype Electrical Line Ind:	Not reported
Constype Gas Line Ind:	Not reported
Constype Industrial Ind:	Not reported
Constype Other Description:	Not reported
Constype Other Ind:	Not reported
Constype Recons Ind:	Not reported
Constype Residential Ind:	Not reported
Constype Transport Ind:	Not reported
Constype Utility Description:	Not reported
Constype Utility Ind:	Not reported
Constype Water Sewer Ind:	Not reported
Dir Discharge Uswater Ind:	N
Receiving Water Name:	Tijuana River
Certifier:	Jim Parker
Certifier Title:	Plant Manager
Certification Date:	29-JUN-15
Primary Sic:	3273-Ready-Mixed Concrete
Secondary Sic:	Not reported
Tertiary Sic:	Not reported

CIWQS:

Name:	ASSOCIATED READY MIXED CONCRETE
Address:	1696 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Agency:	Associated Ready Mixed Concrete
Agency Address:	2730 E Washington Blvd, Los Angeles, CA 90023
Place/Project Type:	Industrial - Ready-Mixed Concrete
SIC/NAICS:	3273
Region:	9

ASSOCIATED READY MIXED CONCRETE (Continued) **S108742579**

Program:	INDSTW
Regulatory Measure Status:	Active
Regulatory Measure Type:	Storm water industrial
Order Number:	2014-0057-DWQ
WDID:	9 37I017562
NPDES Number:	CAS000001
Adoption Date:	Not reported
Effective Date:	11/01/2002
Termination Date:	Not reported
Expiration/Review Date:	Not reported
Design Flow:	Not reported
Major/Minor:	Not reported
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.566
Longitude:	-116.98831

CERS:

Name:	ASSOCIATED READY MIXED CONCRETE
Address:	1696 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Site ID:	526655
CERS ID:	208138
CERS Description:	Industrial Facility Storm Water

Affiliation:

Affiliation Type Desc:	Owner/Operator
Entity Name:	Associated Ready Mixed Concrete
Entity Title:	Operator
Affiliation Address:	2730 E Washington Blvd
Affiliation City:	Los Angeles
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90023
Affiliation Phone:	,

B9 **ASSOCIATED READY MIXED CONCRETE INC** **San Diego Co. HMMD** **S105112756**
NNW **1696 CACTUS RD** **CERS HAZ WASTE** **N/A**
< 1/8 **SAN DIEGO, CA 92154** **CERS TANKS**
0.103 mi. **WDS**
545 ft. **Site 4 of 9 in cluster B** **CERS**

Relative:
Lower

Actual:
504 ft.

HMMD SAN DIEGO:

Name:	A&A READY MIXED CONCRETE, INC
Address:	1696 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	102446
Business Type:	6HK70
EPA Id Number:	CAL000270953
APN:	646-190-18-00
Last HMMD Inspection:	09/01/2010
Facility Telephone:	619-661-7555
Permit Status:	OPEN
Permit Expiration:	06/30/2013
Date Last Updated:	11/02/2012

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Facility Owner: A&A READY MIXED CONCRETE, INC
Facility Mailing Address: 4621 TELLER AVE # 130
Facility Mailing City: NEWPORT
Facility Mailing State: CA
Facility Mailing Zip: 92660
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Y
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE
Other Information: CHROMIX L25 MEDIUM RED
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (2)
Other Information: CHROMIX LX110 HP BLACK
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (3)
Other Information: CHROMIX L30 YELLOW
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (4)
Other Information: CHROMIX L20 LT RED
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (5)
Other Information: CHROMIX L-10 BLACK
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT DISPERSING AGENT
Other Information:	POLYMER 997
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	102-71-6
Name:	CEMENT DISPERSING AGENT
Other Information:	POZZOLITH 200N
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT DISPERSING AGENT - GLENIUM 3000NS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT DISPERSING AGENT - POZZOLITH NC534
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT/HYDROLIC CEMENT
Other Information:	PORTLAND CEMENT
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	1305-78-8
Name:	COAL FLY ASH (CEMENT POWDER)
Other Information:	FLY ASH
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	68476-34-6

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Name: DIESEL FUEL #2
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: GEAR OIL/PETROLEUM HYDROCARBON
Other Information: GEAR OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: GLENIUM 3400 NV
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: PROPRIETARY
Name: HYDRAULIC OIL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: 7647-01-0
Name: HYDROCLORIC ACID, HCL
Other Information: DISOLVE
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: INORGANIC/ORGANIC SALTS
Other Information: CHROMIX ADMIXTURES FOR COLOR-CONDITIONED CONCRETE
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: PROPRIETARY
Name: MOTOR OIL
Other Information: Not reported
Material Waste: Material

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: OXYGEN GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: POSSOLITH NC 534 CONCRETE ACCELERATING
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: SULFURIC ACID
Other Information: BATTERIES
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: SURFACTANT MIXTURE, AQUEOUS SOLUTION
Other Information: MICRO-AIR
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Violations Active Permits:

Permit Number:	102446
Update Date:	11/02/2012
Inspection Date:	10/14/2008
Violation Code:	6HV0229
Violation:	HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation:	Failed to conduct weekly inspections. CFR 265.174
Activity:	ACTIVE

Permit Number:	102446
Update Date:	11/02/2012
Inspection Date:	10/14/2008
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE

Permit Number:	102446
Update Date:	11/02/2012
Inspection Date:	03/09/2007
Violation Code:	6HV0226
Violation:	HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation:	Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity:	ACTIVE

Permit Number:	102446
Update Date:	11/02/2012
Inspection Date:	03/09/2007
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE

Name:	A&A READY MIXED CONCRETE, INC
Address:	1696 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	102446
Business Type:	6HK70
EPA Id Number:	CAL000270953
APN:	646-190-18-00
Last HMMD Inspection:	09/01/2010
Facility Telephone:	619-661-7555
Permit Status:	OPEN
Permit Expiration:	06/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	A&A READY MIXED CONCRETE, INC
Facility Mailing Address:	4621 TELLER AVE # 130
Facility Mailing City:	NEWPORT
Facility Mailing State:	CA
Facility Mailing Zip:	92660
UST Owner:	Not reported
Handle Regulated Hazmat:	Y

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Own Or Operate UST: Not reported
Subject To APSA: Y
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE
Other Information: CHROMIX L25 MEDIUM RED
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (2)
Other Information: CHROMIX LX110 HP BLACK
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (3)
Other Information: CHROMIX L30 YELLOW
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (4)
Other Information: CHROMIX L20 LT RED
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: ADMIXTURE FOR COLOR CONDITIONING CONCRETE (5)
Other Information: CHROMIX L-10 BLACK
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: CEMENT DISPERSING AGENT
Other Information: POLYMER 997
Material Waste: Material

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: 102-71-6
Name: CEMENT DISPERSING AGENT
Other Information: POZZOLITH 200N
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: CEMENT DISPERSING AGENT - GLENIUM 3000NS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: CEMENT DISPERSING AGENT - POZZOLITH NC534
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: CEMENT/HYDROLIC CEMENT
Other Information: PORTLAND CEMENT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: 1305-78-8
Name: COAL FLY ASH (CEMENT POWDER)
Other Information: FLY ASH
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL #2
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	GEAR OIL/PETROLEUM HYDROCARBON
Other Information:	GEAR OIL
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	GLENIUM 3400 NV
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	PROPRIETARY
Name:	HYDRAULIC OIL
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	7647-01-0
Name:	HYDROCLORIC ACID, HCL
Other Information:	DISOLVE
Material Waste:	Material
Hazardous Categories 1:	REACTIVE
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	INORGANIC/ORGANIC SALTS
Other Information:	CHROMIX ADMIXTURES FOR COLOR-CONDITIONED CONCRETE
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	PROPRIETARY
Name:	MOTOR OIL
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	7782-44-7

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Name: OXYGEN GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: POSSOLITH NC 534 CONCRETE ACCELERATING
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: SULFURIC ACID
Other Information: BATTERIES
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: SURFACTANT MIXTURE, AQUEOUS SOLUTION
Other Information: MICRO-AIR
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 102446
Update Date: 11/02/2012
Inspection Date: 10/14/2008
Violation Code: 6HV0229
Violation: HW CONTAINERS NOT INSPECTED WEEKLY

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Violation Citation:	Failed to conduct weekly inspections. CFR 265.174
Activity:	ACTIVE
Permit Number:	102446
Update Date:	11/02/2012
Inspection Date:	10/14/2008
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	102446
Update Date:	11/02/2012
Inspection Date:	03/09/2007
Violation Code:	6HV0226
Violation:	HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation:	Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity:	ACTIVE
Permit Number:	102446
Update Date:	11/02/2012
Inspection Date:	03/09/2007
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Name:	ASSOCIATED READY MIXED CONCRETE, INC
Address:	1696 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000270953
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-661-7555
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	10/27/2022
Facility Owner:	Not reported
Facility Mailing Address:	4621 TELLER AVE # 130, NEWPORT, CA 92660
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	N
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Inspection Violation:

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-03-13T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	4010023 Failure to schedule and conduct spill prevention briefings at least once a year.; 40 CFR 1 112.7(f)(3); HSC 6.67 25270.4.5(a).

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-03-28T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	4030015 Failure to integrity test aboveground tanks by such methods as hydrostatic, nondestructive, etc.; 40 CFR 1 112.8(c)(6); HSC 6.67 25270.4.5(a).

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	2022-09-14T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-03-13T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	3020001 Failure to ensure employees are familiar with the handling and compliance of hazardous waste regulations and emergency response. 22 CCR 12 66262.34(d)(2); 40 CFR 1 262.34(d)(5)(iii)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	5611660
Return To Compliance Date:	2017-03-10T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2017-03-08T14:53:00.000
Violation Code:	4010021 Failed to address in SPCC plan/maintain complete records of: inspections, tests/procedures for 3 years. (40 CFR 112.7(e), 112.8(c)(6).) HSC 25270.4.5(a)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6124791
Return To Compliance Date:	2019-08-20T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2019-07-26T00:00:00.000
Violation Code:	1010006 Failed to update HMBP in CERS within 30 days of a substantial change to any portion of the HMBP, including inventory changes or facility information. HSC 25508.1(a-f); 19 CCR 2654(d); SDCC 68.904(c)(6)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Inspection Type:	Routine
Inspection Number:	5611660
Return To Compliance Date:	2017-03-10T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2017-03-08T14:53:00.000
Violation Code:	4010023 Failed to conduct annual discharge prevention briefings to ensure understanding of SPCC plan. (40 CFR 112.7(f)(3).) HSC 25270.4.5(a)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	6124791
Return To Compliance Date:	2019-08-02T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2019-07-26T00:00:00.000
Violation Code:	4010009 Failed to perform and properly document a five-year review of the SPCC Plan. (40 CFR 112.5(b).) HSC 25270.4.5(a)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-03-06T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	3030007 Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.; 22 CCR 12 66262.34(f).

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	6965974

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Return To Compliance Date:	2022-10-25T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	4020001 Failed to train oil-handling personnel on: operation/maintenance of equipment to prevent discharges; discharge procedure protocols; applicable laws, rules, and regulations; general facility operations; and the contents of the SPCC Plan. (40 CFR 112.7(f)(1).) HSC 25270.4.5(a)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-03-13T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	4010019 Failure to predict the extent of a discharge that could result from equipment failure within the SPCC plan; 40 CFR 1 112.7(b); HSC 6.67 25270.4.5(a).

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-02-21T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	3030017 Failure to properly close hazardous waste containers when not in active use.; 22 CCR 12 66262.34(d)(2); 40 CFR 1 265.173.

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-03-05T00:00:00.000
Nov:	No

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	HMD0224 Empty cont not managed. Failed to mark date on empty container larger than 5 gallons &/or manage it within one year. 22CCR 66261.7(e) & (f).

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS ONLY

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS AND LQGS

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	HMD0001 RECORD KEEPING/OPERATIONAL REQUIREMENTS

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	2022-10-25T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	HMD0226 Did not accumulate waste in a container or tank. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	2022-08-02T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	3030007 Failed to properly label/date hazardous waste container &/or tank. 22 CCR 66262.34(f)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	5611660
Return To Compliance Date:	2017-03-10T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2017-03-08T14:53:00.000
Violation Code:	4020001 Failed to train oil-handling personnel on operation/maintenance of equipment to prevent discharges; discharge procedure protocols; applicable laws, rules, and regulations; general facility operations; AND the contents of the SPCC Plan. (40 CFR 112.7(f)(1).) HSC 25270.4.5(a)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	6124791
Return To Compliance Date:	2019-07-30T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2019-07-26T00:00:00.000
Violation Code:	4010023 Failed to conduct annual discharge prevention briefings to ensure understanding of SPCC plan. (40 CFR 112.7(f)(3).) HSC 25270.4.5(a)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-05-11T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	1010007 Failure to submit a revised business plan upon a substantial change in the handler’s operations; HSC 6.95 25508.1(f)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-03-06T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	4010015 Failure to have an adequate facility diagram, or no facility diagram included within the SPCC plan; 40 CFR 1 112.7(a)(3); HSC 6.67 25270.4.5(a).

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	4384906

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Return To Compliance Date:	2015-03-13T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2015-02-20T00:00:00.000
Violation Code:	4020001 Employee training requirements - Failure to provide training regarding: 40 CFR 1 112.7(f)(1); HSC 6.67 25270.4.5(a).

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	2022-10-25T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	4010021 Failed to have record of inspections and integrity tests signed by the appropriate supervisor or inspector, keep written procedures and records of inspections and integrity tests for at least three years, and/or keep comparison records for bulk storage containers subject to 40 CFR 112.8(c)(6). (40 CFR 112.7(e), 112.8(c)(6).) HSC 25270.4.5(a)

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Aboveground Petroleum Storage Act
Inspection Type:	Routine
Inspection Number:	6965974
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-27T01:55:14.000
Inspection Date:	2022-08-02T00:00:00.000
Violation Code:	HMD0000 GENERAL SPCC REQUIREMENTS

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-102446
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4384906
Return To Compliance Date:	2015-02-21T00:00:00.000
Nov:	No
Violation Classification:	Class II

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2022-10-27T01:55:14.000
Inspection Date: 2015-02-20T00:00:00.000
Violation Code: 3030004 Failure to properly handle, manage, label, and recycle used oil and fuel filters.; 22 CCR 16 66266.130.

Waste and Materials:

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343638
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110/130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343639
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343640
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: EUCON NCA
Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343641
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343642
Trade Secret: N

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343643
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343644
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343645
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343646
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343647
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-27T01:55:14.000

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343648
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343649
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343650
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Automotive Wash
Common Name: Tristar All-Brite
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343651
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Water Reducer
Common Name: Plastol
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343652
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Oxygen
Common Name: Oxygen

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343653
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343654
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343655
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Not reported
Common Name: Eucon BCN
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343656
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Not reported
Common Name: Eucon SPC
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0343657
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Waste Diesel/DEF
Common Name: Waste Diesel/DEF
Case Number: Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311223
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311224
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Pulp, cellulose
Common Name: Used Rags
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311225
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-10-27T01:55:14.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Drained)
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130519
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: IN10-330
Common Name: Color-Crete Granular Black 330
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130520
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: IN10-130
Common Name: Color-Crete Granular Red 130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130521
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130522
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: IN10 920
Common Name: Color-Crete Granular Yellow 920
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130523
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name: EUCON X15 - Mid Range Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130524
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130525
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: EUCON NCA
Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130526

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130527
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130528
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130529
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: HYDROCLORIC ACID, HCL
Common Name: DISSOLVE
Case Number: 7647-01-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130530
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130531
Trade Secret: N
Hazardous Material Type: Pure

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Last Updated: 2017-10-24T00:01:32.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130532
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130533
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130534
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130535
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130536
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: Diesel Fuel No. 2

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130537
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130538
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0109018
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-10-24T00:01:32.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290054
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110/130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290056
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: EUCON NCA
Common Name: EUCON NCA
Case Number: Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0290057
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2021-06-29T02:34:22.000
Chemical Name:	EUCON SRA - Shrinking Reducing Admixture
Common Name:	EUCON SRA - Shrinking Reducing Admixture
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0290058
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2021-06-29T02:34:22.000
Chemical Name:	EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name:	EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0290059
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2021-06-29T02:34:22.000
Chemical Name:	EUCON DS
Common Name:	EUCON DS
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0290060
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2021-06-29T02:34:22.000
Chemical Name:	CEMENT
Common Name:	Cal Portland Cement
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0290061
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2021-06-29T02:34:22.000
Chemical Name:	Petroleum Hydrocarbon Distillate
Common Name:	Chevron Rando HD ISO 68
Case Number:	64742-54-7

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290062
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290063
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290064
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290065
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290070
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290071

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290073
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Drained)
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290074
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Not reported
Common Name: Eucon BCN
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290075
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Not reported
Common Name: Eucon SPC
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290055
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290066
Trade Secret: N
Hazardous Material Type: Mixture

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Pulp, cellulose
Common Name: Used Rags
Case Number: 65996-61-4

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290067
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Automotive Wash
Common Name: Tristar All-Brite
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290068
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Highly Refined Mineral Oil
Common Name: Gear Oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290069
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Water Reducer
Common Name: Plastol
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0259006
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340557
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: IN10-110

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Common Name: Color-Crete Granular Red 110/130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340558
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340559
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: EUCON NCA
Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340560
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340561
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340562
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340563
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340564
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340565
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340566
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340567
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340568
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340569
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Automotive Wash
Common Name: Tristar All-Brite
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340570
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Water Reducer
Common Name: Plastol
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340571
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340572
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340573

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340574
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Not reported
Common Name: Eucon BCN
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340575
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Not reported
Common Name: Eucon SPC
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0340576
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-09-15T01:36:22.000
Chemical Name: Waste Diesel/DEF
Common Name: Waste Diesel/DEF
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0307885
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-09-15T01:36:23.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0307886
Trade Secret: N
Hazardous Material Type: Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Last Updated: 2022-09-15T01:36:23.000
Chemical Name: Pulp, cellulose
Common Name: Used Rags
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0307887
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-09-15T01:36:23.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Drained)
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237040
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237041
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name: EUCON X15 - Mid Range Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237042
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237043
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: EUCON NCA

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237044
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237045
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237046
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237048
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237049
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237050
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237051
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237053
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Pulp, cellulose
Common Name: Used Rags
Case Number: 65996-61-4

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237054
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Automotive Wash
Common Name: Tristar All-Brite
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237055
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Highly Refined Mineral Oil
Common Name: Gear Oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237056
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Water Reducer
Common Name: Plastol
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237057
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237047
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237058
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237060
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237052

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0237059
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-25T01:35:46.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Drained)
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0208476
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-25T01:35:47.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168988
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: IN10-330
Common Name: Color-Crete Granular Black 330
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168990
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248650
Trade Secret: N
Hazardous Material Type: Mixture

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0219661
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-06-10T01:13:00.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168989
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: IN10-130
Common Name: Color-Crete Granular Red 130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168991
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: IN10 920
Common Name: Color-Crete Granular Yellow 920
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168992
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name: EUCON X15 - Mid Range Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168993
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: EUCON NW - Water Reducing Admixture

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168994
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: EUCON NCA
Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168995
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168996
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168997
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168998
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: HYDROCLORIC ACID, HCL
Common Name: DISSOLVE
Case Number: 7647-01-0

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0168999
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169000
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169001
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169002
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169004
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169005
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169006
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169007
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248642
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name: EUCON X15 - Mid Range Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248647
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248655

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Automotive Wash
Common Name: Tristar All-Brite
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248658
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248659
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248644
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: EUCON NCA
Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248645
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248646
Trade Secret: N
Hazardous Material Type: Mixture

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Last Updated: 2020-06-10T01:12:58.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248651
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248661
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Drained)
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323145
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110/130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323146
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323147
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: EUCON NCA

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323148
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323149
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323150
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323151
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323152
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0323153
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2022-03-09T00:44:28.000
Chemical Name:	Type F Flyash
Common Name:	Headwaters Flyash
Case Number:	1305-78-8

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0323154
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2022-03-09T00:44:28.000
Chemical Name:	MOTOR OIL
Common Name:	Chevron Delo 400 LE SAE 15W-40
Case Number:	64742-65-0

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0323155
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2022-03-09T00:44:28.000
Chemical Name:	Eucon ABS
Common Name:	Eucon ABS
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0323156
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2022-03-09T00:44:28.000
Chemical Name:	Ethylene Glycol
Common Name:	DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number:	107-21-1

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0323157
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2022-03-09T00:44:28.000
Chemical Name:	Automotive Wash
Common Name:	Tristar All-Brite
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323158
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: Water Reducer
Common Name: Plastol
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323159
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323160
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323161
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323162
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: Not reported
Common Name: Eucon BCN
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323163

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-09T00:44:28.000
Chemical Name: Not reported
Common Name: Eucon SPC
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0290157
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-09T00:44:29.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0290158
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-09T00:44:29.000
Chemical Name: Pulp, cellulose
Common Name: Used Rags
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0290159
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-09T00:44:29.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Drained)
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223328
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: IN10-130
Common Name: Color-Crete Granular Red 130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223329
Trade Secret: N
Hazardous Material Type: Mixture

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Last Updated: 2019-10-03T03:27:57.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223330
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name: EUCON X15 - Mid Range Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223331
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223332
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: EUCON NCA
Common Name: EUCON NCA
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223333
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: EUCON SRA - Shrinking Reducing Admixture
Common Name: EUCON SRA - Shrinking Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223334
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Common Name: EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223335
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: EUCON DS
Common Name: EUCON DS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223336
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: HYDROCLORIC ACID, HCL
Common Name: DISSOLVE
Case Number: 7647-01-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223337
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223338
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223339
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0223340
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2019-10-03T03:27:57.000
Chemical Name:	MOTOR OIL
Common Name:	Chevron Delo 400 LE SAE 15W-40
Case Number:	64742-65-0

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0223341
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-10-03T03:27:57.000
Chemical Name:	Eucon ABS
Common Name:	Eucon ABS
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0223342
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2019-10-03T03:27:57.000
Chemical Name:	Ethylene Glycol
Common Name:	DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number:	107-21-1

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0223343
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2019-10-03T03:27:57.000
Chemical Name:	Diesel Fuel No. 2
Common Name:	Diesel Fuel No. 2
Case Number:	68476-34-6

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0223344
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2019-10-03T03:27:57.000
Chemical Name:	Acetylene
Common Name:	Acetylene
Case Number:	74-86-2

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2019-HCHEM-0223345
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0193080
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-10-03T03:27:57.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0290072
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-06-29T02:34:22.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248643
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248648
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248652

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248654
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Pulp, cellulose
Common Name: Used Rags
Case Number: 65996-61-4

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248656
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Highly Refined Mineral Oil
Common Name: Gear Oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248660
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248649
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248653
Trade Secret: N
Hazardous Material Type: Pure

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248657
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: Water Reducer
Common Name: Plastol
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0143060
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0248641
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-06-10T01:12:58.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169003
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T16:00:42.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216218
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: IN10-330

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Common Name: Color-Crete Granular Black 330
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216219
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: IN10-130
Common Name: Color-Crete Granular Red 130
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216220
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: IN10-110
Common Name: Color-Crete Granular Red 110
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216221
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: IN10 920
Common Name: Color-Crete Granular Yellow 920
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216222
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: EUCON X15 - Mid Range Water Reducing Admixture
Common Name: EUCON X15 - Mid Range Water Reducing Admixture
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216223
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: EUCON NW - Water Reducing Admixture
Common Name: EUCON NW - Water Reducing Admixture
Case Number: Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0216224
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-04-10T00:46:26.000
Chemical Name:	EUCON NCA
Common Name:	EUCON NCA
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0216225
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-04-10T00:46:26.000
Chemical Name:	EUCON SRA - Shrinking Reducing Admixture
Common Name:	EUCON SRA - Shrinking Reducing Admixture
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0216226
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-04-10T00:46:26.000
Chemical Name:	EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Common Name:	EUCON AIR 40 - CONCRETE ENTRAINING AGENT
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0216227
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-04-10T00:46:26.000
Chemical Name:	EUCON DS
Common Name:	EUCON DS
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0216228
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-04-10T00:46:26.000
Chemical Name:	HYDROCLORIC ACID, HCL
Common Name:	DISSOLVE
Case Number:	7647-01-0

Record ID:	DEH2002-HUPFP-102446
Permit Status:	Permit Renewed

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216229
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: CEMENT
Common Name: Cal Portland Cement
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216230
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: Petroleum Hydrocarbon Distillate
Common Name: Chevron Rando HD ISO 68
Case Number: 64742-54-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216231
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: Type F Flyash
Common Name: Headwaters Flyash
Case Number: 1305-78-8

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216232
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: MOTOR OIL
Common Name: Chevron Delo 400 LE SAE 15W-40
Case Number: 64742-65-0

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216233
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: Eucon ABS
Common Name: Eucon ABS
Case Number: Not reported

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216234

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: Ethylene Glycol
Common Name: DELO EXTENDED LIFE COOLANT 50/50 - BITTERANT
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216235
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216236
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0216237
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-04-10T00:46:26.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-102446
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0186474
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-04-10T00:46:29.000
Chemical Name: WASTE OIL
Common Name: WASTE OIL
Case Number: Not reported

Name: A&A READY MIXED CONCRETE, INC
Address: 1696 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Permit Number: 102446
Business Type: 6HK70

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

EPA Id Number:	CAL000270953
APN:	646-190-18-00
Last HMMD Inspection:	09/01/2010
Facility Telephone:	619-661-7555
Permit Status:	OPEN
Permit Expiration:	06/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	A&A READY MIXED CONCRETE, INC
Facility Mailing Address:	4621 TELLER AVE # 130
Facility Mailing City:	NEWPORT
Facility Mailing State:	CA
Facility Mailing Zip:	92660
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	ADMIXTURE FOR COLOR CONDITIONING CONCRETE
Other Information:	CHROMIX L25 MEDIUM RED
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	ADMIXTURE FOR COLOR CONDITIONING CONCRETE (2)
Other Information:	CHROMIX LX110 HP BLACK
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	ADMIXTURE FOR COLOR CONDITIONING CONCRETE (3)
Other Information:	CHROMIX L30 YELLOW
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	ADMIXTURE FOR COLOR CONDITIONING CONCRETE (4)
Other Information:	CHROMIX L20 LT RED
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102446

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Update Date:	11/02/2012
Case Number:	Not reported
Name:	ADMIXTURE FOR COLOR CONDITIONING CONCRETE (5)
Other Information:	CHROMIX L-10 BLACK
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT DISPERSING AGENT
Other Information:	POLYMER 997
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	102-71-6
Name:	CEMENT DISPERSING AGENT
Other Information:	POZZOLITH 200N
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT DISPERSING AGENT - GLENIUM 3000NS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT DISPERSING AGENT - POZZOLITH NC534
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	CEMENT/HYDROLIC CEMENT
Other Information:	PORTLAND CEMENT
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	1305-78-8
Name:	COAL FLY ASH (CEMENT POWDER)

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Other Information:	FLY ASH
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL #2
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	GEAR OIL/PETROLEUM HYDROCARBON
Other Information:	GEAR OIL
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	GLENIUM 3400 NV
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	PROPRIETARY
Name:	HYDRAULIC OIL
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	7647-01-0
Name:	HYDROCLORIC ACID, HCL
Other Information:	DISOLVE
Material Waste:	Material
Hazardous Categories 1:	REACTIVE
Hazardous Categories 2:	Not reported
Permit Number:	102446
Update Date:	11/02/2012
Case Number:	Not reported
Name:	INORGANIC/ORGANIC SALTS
Other Information:	CHROMIX ADMIXTURES FOR COLOR-CONDITIONED CONCRETE
Material Waste:	Material
Hazardous Categories 1:	Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: PROPRIETARY
Name: MOTOR OIL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: OXYGEN GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: POSSOLITH NC 534 CONCRETE ACCELERATING
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: SULFURIC ACID
Other Information: BATTERIES
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: SURFACTANT MIXTURE, AQUEOUS SOLUTION
Other Information: MICRO-AIR
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102446

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 102446
Update Date: 11/02/2012
Inspection Date: 10/14/2008
Violation Code: 6HV0229
Violation: HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation: Failed to conduct weekly inspections. CFR 265.174
Activity: ACTIVE

Permit Number: 102446
Update Date: 11/02/2012
Inspection Date: 10/14/2008
Violation Code: 6HV1009
Violation: HMBP: INADEQUATE SITE MAP
Violation Citation: Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity: ACTIVE

Permit Number: 102446
Update Date: 11/02/2012
Inspection Date: 03/09/2007
Violation Code: 6HV0226
Violation: HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation: Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity: ACTIVE

Permit Number: 102446
Update Date: 11/02/2012
Inspection Date: 03/09/2007
Violation Code: 6HV1009
Violation: HMBP: INADEQUATE SITE MAP
Violation Citation: Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity: ACTIVE

CERS HAZ WASTE:
Name: ASSOCIATED READY MIXED CONCRETE INC
Address: 1696 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 93697
CERS ID: 10394077
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: ASSOCIATED READY MIXED CONCRETE INC

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Address: 1696 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 93697
CERS ID: 10394077
CERS Description: Aboveground Petroleum Storage

WDS:
Name: ASSOCIATED READY MIXED CONC SA
Address: 1696 Cactus Rd
City: SAN DIEGO
Facility ID: San Diego 37I017562
Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 9
Facility Telephone: 3232605350
Facility Contact: PARKER JIM
Agency Name: ASSOCIATED READY MIXED CONC
Agency Address: 2730 E Washington Blvd
Agency City,St,Zip: Los Angeles 900232636
Agency Contact: CHRIS PISANO
Agency Telephone: 3237809688
Agency Type: Private
SIC Code: 0
SIC Code 2: Not reported
Primary Waste Type: Not reported
Primary Waste: Not reported
Waste Type2: Not reported
Waste2: Not reported
Primary Waste Type: Not reported
Secondary Waste: Not reported
Secondary Waste Type: Not reported
Design Flow: 0
Baseline Flow: 0
Reclamation: Not reported
POTW: Not reported
Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

CERS:
Name: ASSOCIATED READY MIXED CONCRETE INC
Address: 1696 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 93697
CERS ID: 10394077
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Description: Failure to properly handle, manage, label, and recycle used oil and fuel filters.
Violation Notes: Returned to compliance on 02/21/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 07-26-2019
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Description: Failure to include in the SPCC plan an adequate description of employee training. Training shall address, at a minimum: operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules, and regulations; general facility operations; content of the facility SPCC plan; and annual discharge prevention briefings for oil-handling personnel to assure adequate understanding of the SPCC plan.
Violation Notes: Returned to compliance on 07/30/2019. Inspection Sequence ID:6124791
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 03-08-2017
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to provide the following training to all oil-handling personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. 5. Contents of the SPCC Plan.
Violation Notes: Returned to compliance on 03/10/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to have an adequate facility diagram, or no facility diagram included within the SPCC plan.
Violation Notes: Returned to compliance on 03/06/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: HSC 6.95 25508.1(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(f)
Violation Description: Failure to electronically update the business plan within 30 days of a substantial change.
Violation Notes: Returned to compliance on 05/11/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections
Violation Description: Haz Waste Generator Program - Operations/Maintenance - General
Violation Notes: Returned to compliance on 03/05/2015. Inspection Sequence ID:4384906;Violation:HMD0224 Empty cont not managed. Failed to mark date on empty container larger than 5 gallons &/or manage it within one year. 22CCR 66261.7(e) & (f).
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description: Failure to properly close hazardous waste containers when not in active use.
Violation Notes: Returned to compliance on 02/21/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 07-26-2019
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Description: Failure to complete a review and evaluation of the SPCC Plan at least once every five years, document the completion of the review, and sign a statement as to whether the SPCC Plan will be amended.
Violation Notes: Returned to compliance on 08/02/2019. Inspection Sequence ID:6124791
Violation Division: San Diego County Department of Env Health
Violation Program: APSA

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to integrity test aboveground tanks by such methods as hydrostatic, nondestructive, etc.
Violation Notes:	Returned to compliance on 03/28/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 03/06/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	03-08-2017
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to comply with one or more of the following requirements: 1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and integrity tests for at least three years. 3. Keep comparison records.
Violation Notes:	Returned to compliance on 03/10/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to schedule and conduct spill prevention briefings at least once a year.
Violation Notes:	Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to predict the extent of a discharge that could result from equipment failure within the SPCC plan.
Violation Notes:	Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	07-26-2019
Citation:	HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)
Violation Description:	Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that requires modification to any portion of the business plan.
Violation Notes:	Returned to compliance on 08/20/2019. Inspection Sequence ID:6124791
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	08-02-2022
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 10/25/2022. Inspection Sequence ID:6965974;Violation:HMD0226 Did not accumulate waste in a container or tank. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	08-02-2022
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 08/02/2022. Inspection Sequence ID:6965974
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Violation Date: 08-02-2022
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to provide the following training to all oil-handling personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. 5. Contents of the SPCC Plan.
Violation Notes: Returned to compliance on 10/25/2022. Inspection Sequence ID:6965974
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to provide training regarding: 1. The operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. AND 5. The contents of the SPCC Plan.
Violation Notes: Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: 40 CFR 1 262.34(d)(5)(iii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(iii)
Violation Description: Failure to ensure employees are familiar with the handling and compliance of hazardous waste regulations and emergency response.
Violation Notes: Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 03-08-2017
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to include in the SPCC plan and document discharge prevention briefings for oil-handling personnel at least once a year, including, but not limited to, known discharges, failures, and malfunctioning components.
Violation Notes: Returned to compliance on 03/10/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 08-02-2022

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes: Returned to compliance on 09/14/2022. Inspection Sequence ID:6965974;Violation:HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 08-02-2022
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to comply with one or more of the following requirements: 1. Have record of inspections and tests, including integrity tests, signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and tests, including integrity tests, for at least three years. 3. Keep comparison records.
Violation Notes: Returned to compliance on 10/25/2022. Inspection Sequence ID:6965974
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-20-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4384906
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-20-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4384906
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-26-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6124791
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-20-2015
Violations Found: Yes

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4384906
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-08-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5611660
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-08-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5611660
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6965974
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-08-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5611660
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-26-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6124791
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-26-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6124791
Eval Division: San Diego County Department of Env Health

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2022
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6965974
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6965974
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Coordinates:
Site ID: 93697
Facility Name: ASSOCIATED READY MIXED CONCRETE INC
Env Int Type Code: HWG
Program ID: 10394077
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.565730
Longitude: -116.990260

Affiliation:
Affiliation Type Desc: Company Official
Entity Name: Alexander Nichols
Entity Title: Director of Development and Compliance
Affiliation Address: 4621 TELLER AVENUE, SUITE 130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: Alex Nichols
Entity Title: Not reported
Affiliation Address: 4621 TELLER AV #130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92660
Affiliation Phone: ,

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 4621 TELLER AVE # 130

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Affiliation City: NEWPORT
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92660
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: ALEX NICHOLS
Entity Title: Director, Development & Compliance
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: ASSOCIATED READY MIXED CONCRETE, INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 661-7555,

Affiliation Type Desc: Public Contact
Entity Name: Alex Nichols
Entity Title: Not reported
Affiliation Address: 4621 TELLER AVENUE, SUITE 130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: 9492532800,

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Legal Owner
Entity Name: ASSOCIATED READY MIXED CONCRETE, INC
Entity Title: Not reported
Affiliation Address: 4621 TELLER AVE 130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 92660
Affiliation Phone: (949) 253-2800,

Affiliation Type Desc: Parent Corporation

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Entity Name: A&A READY MIXED CONCRETE, INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Document Preparer
Entity Name: Windell Jones, Jr
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Parent Company
Entity Name: CAILLIER INVESTMENTS INC
Entity Title: Not reported
Affiliation Address: 4621 TELLER AVENUE, SUITE 130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: ,

Affiliation Type Desc: Technical Contact
Entity Name: Alex Nichols
Entity Title: Not reported
Affiliation Address: 4621 TELLER AVENUE, SUITE 130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: 9492532800,

Name: ASSOCIATED READY MIXED CONCRETE INC
Address: 1696 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 93697
CERS ID: 9215WSSCTD1696C
CERS Description: Toxic Release Inventory

Violations:
Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Description: Failure to properly handle, manage, label, and recycle used oil and fuel filters.
Violation Notes: Returned to compliance on 02/21/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: HW

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	07-26-2019
Citation:	HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Description:	Failure to include in the SPCC plan an adequate description of employee training. Training shall address, at a minimum: operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules, and regulations; general facility operations; content of the facility SPCC plan; and annual discharge prevention briefings for oil-handling personnel to assure adequate understanding of the SPCC plan.
Violation Notes:	Returned to compliance on 07/30/2019. Inspection Sequence ID:6124791
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	03-08-2017
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to provide the following training to all oil-handling personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. 5. Contents of the SPCC Plan.
Violation Notes:	Returned to compliance on 03/10/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to have an adequate facility diagram, or no facility diagram included within the SPCC plan.
Violation Notes:	Returned to compliance on 03/06/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.95 25508.1(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(f)
Violation Description:	Failure to electronically update the business plan within 30 days of a substantial change.
Violation Notes:	Returned to compliance on 05/11/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections
Violation Description:	Haz Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 03/05/2015. Inspection Sequence ID:4384906;Violation:HMD0224 Empty cont not managed. Failed to mark date on empty container larger than 5 gallons &/or manage it within one year. 22CCR 66261.7(e) & (f).
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,

Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description:	Failure to properly close hazardous waste containers when not in active use.
Violation Notes:	Returned to compliance on 02/21/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,

Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	07-26-2019
Citation:	HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Description:	Failure to complete a review and evaluation of the SPCC Plan at least once every five years, document the completion of the review, and sign a statement as to whether the SPCC Plan will be amended.
Violation Notes:	Returned to compliance on 08/02/2019. Inspection Sequence ID:6124791
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,

Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to integrity test aboveground tanks by such methods as hydrostatic, nondestructive, etc.
Violation Notes:	Returned to compliance on 03/28/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,

Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers with

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

	the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 03/06/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	03-08-2017
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to comply with one or more of the following requirements: 1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and integrity tests for at least three years. 3. Keep comparison records.
Violation Notes:	Returned to compliance on 03/10/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to schedule and conduct spill prevention briefings at least once a year.
Violation Notes:	Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to predict the extent of a discharge that could result from equipment failure within the SPCC plan.
Violation Notes:	Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	07-26-2019
Citation:	HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)
Violation Description:	Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

	business name. A substantial change in the handler's operations that requires modification to any portion of the business plan.
Violation Notes:	Returned to compliance on 08/20/2019. Inspection Sequence ID:6124791
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	08-02-2022
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 10/25/2022. Inspection Sequence ID:6965974;Violation:HMD0226 Did not accumulate waste in a container or tank. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	08-02-2022
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 08/02/2022. Inspection Sequence ID:6965974
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	08-02-2022
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to provide the following training to all oil-handling personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. 5. Contents of the SPCC Plan.
Violation Notes:	Returned to compliance on 10/25/2022. Inspection Sequence ID:6965974
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	93697
Site Name:	ASSOCIATED READY MIXED CONCRETE INC
Violation Date:	02-20-2015
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to provide training regarding: 1. The operation and maintenance of equipment to prevent discharges. 2. Discharge procedure

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. AND 5. The contents of the SPCC Plan.
Violation Notes: Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 02-20-2015
Citation: 40 CFR 1 262.34(d)(5)(iii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(iii)
Violation Description: Failure to ensure employees are familiar with the handling and compliance of hazardous waste regulations and emergency response.
Violation Notes: Returned to compliance on 03/13/2015. Inspection Sequence ID:4384906
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 03-08-2017
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to include in the SPCC plan and document discharge prevention briefings for oil-handling personnel at least once a year, including, but not limited to, known discharges, failures, and malfunctioning components.
Violation Notes: Returned to compliance on 03/10/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 08-02-2022
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes: Returned to compliance on 09/14/2022. Inspection Sequence ID:6965974;Violation:HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 93697
Site Name: ASSOCIATED READY MIXED CONCRETE INC
Violation Date: 08-02-2022
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to comply with one or more of the following requirements: 1. Have record of inspections and tests, including integrity tests, signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and tests, including integrity

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

tests, for at least three years. 3. Keep comparison records.
Violation Notes: Returned to compliance on 10/25/2022. Inspection Sequence ID:6965974
Violation Division: San Diego County Department of Env Health
Violation Program: APSA
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-20-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4384906
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-20-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4384906
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-26-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6124791
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-20-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4384906
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-08-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5611660
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-08-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5611660

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6965974
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-08-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5611660
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-26-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6124791
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-26-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6124791
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2022
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6965974
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6965974
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Coordinates:

Site ID:	93697
Facility Name:	ASSOCIATED READY MIXED CONCRETE INC
Env Int Type Code:	HWG
Program ID:	10394077
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.,
Latitude:	32.565730
Longitude:	-116.990260

Affiliation:

Affiliation Type Desc:	Company Official
Entity Name:	Alexander Nichols
Entity Title:	Director of Development and Compliance
Affiliation Address:	4621 TELLER AVENUE, SUITE 130
Affiliation City:	NEWPORT BEACH
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92154
Affiliation Phone:	,
Affiliation Type Desc:	Environmental Contact
Entity Name:	Alex Nichols
Entity Title:	Not reported
Affiliation Address:	4621 TELLER AV #130
Affiliation City:	NEWPORT BEACH
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92660
Affiliation Phone:	,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	4621 TELLER AVE # 130
Affiliation City:	NEWPORT
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92660
Affiliation Phone:	,
Affiliation Type Desc:	Identification Signer
Entity Name:	ALEX NICHOLS
Entity Title:	Director, Development & Compliance
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Operator
Entity Name:	ASSOCIATED READY MIXED CONCRETE, INC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 661-7555,

Affiliation Type Desc: Public Contact
Entity Name: Alex Nichols
Entity Title: Not reported
Affiliation Address: 4621 TELLER AVENUE, SUITE 130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: 9492532800,

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Legal Owner
Entity Name: ASSOCIATED READY MIXED CONCRETE, INC
Entity Title: Not reported
Affiliation Address: 4621 TELLER AVE 130
Affiliation City: NEWPORT BEACH
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 92660
Affiliation Phone: (949) 253-2800,

Affiliation Type Desc: Parent Corporation
Entity Name: A&A READY MIXED CONCRETE, INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Document Preparer
Entity Name: Windell Jones, Jr
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Parent Company
Entity Name: CAILLIER INVESTMENTS INC

ASSOCIATED READY MIXED CONCRETE INC (Continued) **S105112756**

Entity Title:	Not reported
Affiliation Address:	4621 TELLER AVENUE, SUITE 130
Affiliation City:	NEWPORT BEACH
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92154
Affiliation Phone:	,
Affiliation Type Desc:	Technical Contact
Entity Name:	Alex Nichols
Entity Title:	Not reported
Affiliation Address:	4621 TELLER AVENUE, SUITE 130
Affiliation City:	NEWPORT BEACH
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92154
Affiliation Phone:	9492532800,

B10 **ASSOCIATED READY MIXED CONCRETE INC #62** **RCRA NonGen / NLR** **1024806776**
NNW **1696 CACTUS RD** **CAL000270953**
< 1/8 **SAN DIEGO, CA 92154**
0.103 mi.
545 ft. **Site 5 of 9 in cluster B**

Relative: **Lower**

Actual: **504 ft.**

RCRA Listings:

Date Form Received by Agency:	20030529
Handler Name:	Associated Ready Mixed Concrete Inc #62
Handler Address:	1696 CACTUS RD
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAL000270953
Contact Name:	MIKE COOK
Contact Address:	3250 E. 70TH ST.
Contact City,State,Zip:	LONG BEACH, CA 90805-1821
Contact Telephone:	562-790-3650
Contact Fax:	562-790-3655
Contact Email:	MCOOK@ASSOCRMC.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3250 E 70TH ST
Mailing City,State,Zip:	LONG BEACH, CA 90805-1821
Owner Name:	Kurt And Randy Caillier
Owner Type:	Other
Operator Name:	Mike Cook
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

ASSOCIATED READY MIXED CONCRETE INC #62 (Continued) **1024806776**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MIKE COOK	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3250 E. 70TH ST.
Owner/Operator City,State,Zip:	LONG BEACH, CA 90805-1821
Owner/Operator Telephone:	562-790-3650
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: KURT AND RANDY CAILLIER	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4621 TELLER AVE #130
Owner/Operator City,State,Zip:	NEWPORT BEACH, CA 90805-0000

ASSOCIATED READY MIXED CONCRETE INC #62 (Continued) **1024806776**

Owner/Operator Telephone: 949-253-2800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20030529
Handler Name: ASSOCIATED READY MIXED CONCRETE INC #62
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32732
NAICS Description: READY-MIX CONCRETE MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B11 **SUNSET CAR RENTAL LLC** **RCRA NonGen / NLR** **1027216755**
NNW **1690 CACTUS RD** **CAL000367120**
1/8-1/4 **SAN DIEGO, CA 92154**
0.125 mi.
661 ft. **Site 6 of 9 in cluster B**

Relative: **Lower**
Actual: **506 ft.**

RCRA Listings:
Date Form Received by Agency: 20110902
Handler Name: Sunset Car Rental Llc
Handler Address: 1690 CACTUS RD
Handler City,State,Zip: SAN DIEGO, CA 92154-8101
EPA ID: CAL000367120
Contact Name: DARIO PIAGENTINI
Contact Address: 1690 CACTUS RD
Contact City,State,Zip: SAN DIEGO, CA 92154
Contact Telephone: 619-250-1784
Contact Fax: 619-671-9575
Contact Email: DARIO@NICOMUSA.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported

SUNSET CAR RENTAL LLC (Continued) **1027216755**

State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1690 CACTUS RD
Mailing City,State,Zip:	SAN DIEGO, CA 92154-8101
Owner Name:	Sunset Car Rental Llc
Owner Type:	Other
Operator Name:	Dario Piagentini
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220308
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: DARIO PIAGENTINI	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1690 CACTUS RD

SUNSET CAR RENTAL LLC (Continued) **1027216755**

Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-250-1784
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SUNSET CAR RENTAL LLC
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1690 CACTUS RD
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154-8101
Owner/Operator Telephone: 619-270-2355
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20110902
Handler Name: SUNSET CAR RENTAL LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 532111
NAICS Description: PASSENGER CAR RENTAL

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B12 **AT&T CALIFORNIA - D3179** **UST** **U004292139**
NNW **1670 CACTUS RD** **N/A**
1/8-1/4 **SAN DIEGO, CA 92154**
0.146 mi.
769 ft. **Site 7 of 9 in cluster B**

Relative: **Lower**
Actual: **507 ft.**

UST:
Name: AT&T CALIFORNIA - D3179
Address: 1670 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Facility ID: 37-000-129788
Permitting Agency: San Diego County Department of Environmental Health
CERSID: 10394128

AT&T CALIFORNIA - D3179 (Continued) **U004292139**

Latitude:	Not reported
Longitude:	Not reported
Owner type:	Not reported
Facility type:	Not reported
Num of inuse ust:	Not reported
Num of closed ust:	Not reported
Num of oos ust:	Not reported
Epa region:	Not reported
Tribal lands:	Not reported
Tank owner name:	Not reported
Tank owner mailing address:	Not reported
Tank owner mailing city:	Not reported
Tank owner mailing zip:	Not reported
Tank owner mailing state:	Not reported
Tank operator name:	Not reported
Tank operator mailing address:	Not reported
Tank operator mailing city:	Not reported
Tank operator mailing zip:	Not reported
Tank operator mailing state:	Not reported
Tankidnumber:	Not reported
Tank status:	Not reported
Tank configuration:	Not reported
Tank closure date:	Not reported
Tank installation date:	Not reported
Tank num of compartments:	Not reported
Tank contents:	Not reported
Tank capacity gallons:	Not reported
Tank type:	Not reported
Tank pc construction:	Not reported
Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

B13 **AT&T CALIFORNIA - D3179** **San Diego Co. HMMD** **S106063060**
NNW **1670 CACTUS RD** **CERS HAZ WASTE** **N/A**
1/8-1/4 **SAN DIEGO, CA 92154** **CERS TANKS**
0.146 mi. **CERS**
769 ft. **Site 8 of 9 in cluster B**

Relative: **Lower**
Actual: **507 ft.**

HMMD SAN DIEGO:

Name:	PACIFIC BELL DBA AT&T CALIFORNIA
Address:	1670 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92173
Permit Number:	129788
Business Type:	6HK52
EPA Id Number:	CAL000116895
APN:	646-190-09-00
Last HMMD Inspection:	02/27/2012
Facility Telephone:	800-566-9347
Permit Status:	OPEN
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Facility Owner:	PACIFIC BELL DBA AT&T CALIFORNIA
Facility Mailing Address:	P O BOX 5095, ROOM 3E000
Facility Mailing City:	SAN RAMON
Facility Mailing State:	CA
Facility Mailing Zip:	94583-0995
UST Owner:	SBC ENVIRONMENTAL MGMT
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	129788
Update Date:	11/02/2012
Case Number:	Not reported
Name:	DIESEL
Other Information:	UNDERGROUND TANK 129788 T001
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	129788
Update Date:	11/02/2012
Case Number:	7664-93-9
Name:	SULFURIC ACID; BATTERY ELCTROLYTE
Other Information:	BATTERY ELECTROLYTE
Material Waste:	Material
Hazardous Categories 1:	REACTIVE
Hazardous Categories 2:	EXTREMELY HAZARDOUS

Violations Active Permits:

Permit Number:	129788
Update Date:	11/02/2012
Inspection Date:	06/12/2003
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE

Permit Number:	129788
Update Date:	11/02/2012
Inspection Date:	06/12/2003
Violation Code:	6HV3111
Violation:	CONTIN MONITOR SYSTEM NOT CERT. YRLY
Violation Citation:	Continuous monitoring system not certified annually. 25284.1(a)(4)(C; 2630(d), 2637(b).
Activity:	ACTIVE

Permit Number:	129788
Update Date:	11/02/2012
Inspection Date:	03/10/2011
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional.

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 129788
Update Date: 11/02/2012
Inspection Date: 06/10/2004
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available.
25292.2(a), 25299.33; 2809
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 129788 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 129788
Tank Type: DOUBLE WALL
Additional Id: NT2245
Capacity Gallons: 4000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2001-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

Name: AT&T CALIFORNIA - D3179
Address: 1670 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Permit Number: Not reported
Business Type: Not reported
EPA Id Number: CAL000116895
APN: Not reported
Last HMMD Inspection: Not reported
Facility Telephone: (800) 566-9347
Permit Status: Permit Renewed
Permit Expiration: Not reported
Date Last Updated: 05/25/2022
Facility Owner: Not reported
Facility Mailing Address: 308 S. Akard St., 17th Floor, Dallas, TX 75202
Facility Mailing City: Not reported
Facility Mailing State: Not reported
Facility Mailing Zip: Not reported
UST Owner: Y
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: N
Generate Medical Waste: Not reported

Inspection Violation:

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Record ID:	DEH2002-HUPFP-129788
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-129788
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6057811
Return To Compliance Date:	2018-12-06T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	28476
Container/Tank Id:	Not reported
Last Update:	2022-05-25T02:14:24.000
Inspection Date:	2018-12-06T14:52:56.000
Violation Code:	2030036 (TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. 7. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. 8. Inspected within 30 days after a repair to the overfill prevention equipment. 9. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 10. Inspected by a certified UST service technician. 11. Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)

UST DTL:

Record ID:	DEH2002-HUPFP-129788
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-129788
Facility Type (Ust Facility):	Other
Tank Owner Name:	AT&T California
Tankid:	28476
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	05
Piping System Type:	Conventional Suction
Last Updated:	2022-05-25T02:14:29.000
Tank Capacityin Gallons:	4030
Tank Contents:	Diesel
Type Of Tank:	Double Wall

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Record ID:	DEH2002-HUPFP-129788
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-129788
Facility Type (Ust Facility):	Other
Tank Owner Name:	AT&T California
Tankid:	D3179U001
Tank Status:	SEE FILE
Date Ust Permanently Closed:	04/27/2018
Tank Use:	Emergency Generator Fuel
Piping System Type:	Conventional Suction
Last Updated:	2018-04-28T02:09:07.000
Tank Capacityin Gallons:	4000
Tank Contents:	Diesel
Type Of Tank:	Double Wall

Waste and Materials:

Record ID:	DEH2002-HUPFP-129788
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0129402
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2018-01-18T11:44:44.000
Chemical Name:	Lead Acid Batteries
Common Name:	Lead Acid Batteries
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-129788
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0129403
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-01-18T11:44:44.000
Chemical Name:	Diesel Fuel No. 2
Common Name:	Diesel Fuel No. 2
Case Number:	68476-34-6

Record ID:	DEH2002-HUPFP-129788
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HWAST-0255939
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2022-01-26T02:32:41.000
Chemical Name:	Not reported
Common Name:	Engine maintenance fluids
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-129788
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0330600
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2022-05-25T02:14:29.000

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Chemical Name: Lead Acid Batteries
Common Name: Lead Acid Batteries
Case Number: Not reported

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0330601
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-05-25T02:14:29.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0297236
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-25T02:14:29.000
Chemical Name: Not reported
Common Name: Engine maintenance fluids
Case Number: Not reported

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169031
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-20T00:35:25.000
Chemical Name: Lead Acid Batteries
Common Name: Lead Acid Batteries
Case Number: Not reported

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0208654
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-08-17T00:38:45.000
Chemical Name: Lead Acid Batteries
Common Name: Lead Acid Batteries
Case Number: Not reported

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0208655
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-08-17T00:38:45.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0286991
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-01-26T02:32:41.000
Chemical Name: Lead Acid Batteries
Common Name: Lead Acid Batteries
Case Number: Not reported

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0169032
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-20T00:35:25.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-129788
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0286992
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-01-26T02:32:41.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Name: PACIFIC BELL DBA AT&T CALIFORNIA
Address: 1670 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92173
Permit Number: 129788
Business Type: 6HK52
EPA Id Number: CAL000116895
APN: 646-190-09-00
Last HMMD Inspection: 02/27/2012
Facility Telephone: 800-566-9347
Permit Status: OPEN
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: PACIFIC BELL DBA AT&T CALIFORNIA
Facility Mailing Address: P O BOX 5095, ROOM 3E000
Facility Mailing City: SAN RAMON
Facility Mailing State: CA
Facility Mailing Zip: 94583-0995
UST Owner: SBC ENVIRONMENTAL MGMT
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Generate Haz Waste: Not reported
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 129788
Update Date: 11/02/2012
Case Number: Not reported
Name: DIESEL
Other Information: UNDERGROUND TANK 129788 T001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 129788
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: SULFURIC ACID; BATTERY ELCTROLYTE
Other Information: BATTERY ELECTROLYTE
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Violations Active Permits:
Permit Number: 129788
Update Date: 11/02/2012
Inspection Date: 06/12/2003
Violation Code: 6HV3104
Violation: FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation: CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity: ACTIVE

Permit Number: 129788
Update Date: 11/02/2012
Inspection Date: 06/12/2003
Violation Code: 6HV3111
Violation: CONTIN MONITOR SYSTEM NOT CERT. YRLY
Violation Citation: Continuous monitoring system not certified annually. 25284.1(a)(4)(C; 2630(d), 2637(b).
Activity: ACTIVE

Permit Number: 129788
Update Date: 11/02/2012
Inspection Date: 03/10/2011
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 129788
Update Date: 11/02/2012
Inspection Date: 06/10/2004
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available.

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

25292.2(a), 25299.33; 2809
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 129788 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 129788
Tank Type: DOUBLE WALL
Additional Id: NT2245
Capacity Gallons: 4000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2001-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

CERS HAZ WASTE:
Name: AT&T CALIFORNIA - D3179
Address: 1670 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 433548
CERS ID: 10394128
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: AT&T CALIFORNIA - D3179
Address: 1670 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 433548
CERS ID: 10394128
CERS Description: Underground Storage Tank

CERS:
Name: AT&T CALIFORNIA - D3179
Address: 1670 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 433548
CERS ID: 10394128
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 433548
Site Name: AT&T California - D3179
Violation Date: 12-06-2018
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description: Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.

Violation Notes: Returned to compliance on 12/06/2018. Inspection Sequence ID:6057811;Tank ID:28476;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equip

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Evaluation:

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-09-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Ayala Anthony Inspection ID:6559133
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Campanella Luke Inspection ID:5799648
Eval Division: San Diego County Department of Env Health
Eval Program: HW

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-28-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4088730
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-06-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6057811
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-08-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6828190
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-08-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6828190
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-09-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Ayala Anthony Inspection ID:6559133
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Campanella Luke Inspection ID:5799648
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Eval Date: 01-09-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5571682
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5221674
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-28-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4088730
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Campanella Luke Inspection ID:5799648
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5221674
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5221674
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-13-2019
Violations Found: No
Eval Type: Routine done by local agency

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Eval Notes: Inspector: Zmily Zanalee Inspection ID:6388957
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-06-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6057811
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 308 S. Akard St., 17th Floor
Affiliation City: Dallas
Affiliation State: TX
Affiliation Country: Not reported
Affiliation Zip: 75202
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: AT&T California
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (800) 566-9347,

Affiliation Type Desc: UST Permit Applicant
Entity Name: Sarah Bullock
Entity Title: Authorized Agent to AT&T
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (800) 566-9347,

Affiliation Type Desc: UST Tank Owner
Entity Name: Pacific Bell Telephone Company dba AT&T California
Entity Title: Not reported
Affiliation Address: 308 S. Akard St., 17th Floor
Affiliation City: Dallas
Affiliation State: TX
Affiliation Country: United States
Affiliation Zip: 75202
Affiliation Phone: (800) 566-9347,

Affiliation Type Desc: Document Preparer
Entity Name: Peter Burnell, Sigma Consultants, Inc.

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Identification Signer
Entity Name:	Jeremy McGrue
Entity Title:	National EPCRA Manager
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	Pacific Bell Telephone Company dba AT&T California
Entity Title:	Not reported
Affiliation Address:	308 S. Akard St., 17th Floor
Affiliation City:	Dallas
Affiliation State:	TX
Affiliation Country:	United States
Affiliation Zip:	75202
Affiliation Phone:	(800) 566-9347,
Affiliation Type Desc:	Environmental Contact
Entity Name:	AT&T EH&S Hotline - Option #1
Entity Title:	Not reported
Affiliation Address:	308 S. Akard St., 17th Floor
Affiliation City:	Dallas
Affiliation State:	TX
Affiliation Country:	Not reported
Affiliation Zip:	75202
Affiliation Phone:	,
Affiliation Type Desc:	UST Tank Operator
Entity Name:	Pacific Bell Telephone Company dba AT&T California
Entity Title:	Not reported
Affiliation Address:	308 S. Akard St., 17th Floor
Affiliation City:	Dallas
Affiliation State:	TX
Affiliation Country:	United States
Affiliation Zip:	75202
Affiliation Phone:	(800) 566-9347,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,

AT&T CALIFORNIA - D3179 (Continued) **S106063060**

Affiliation Type Desc:	Legal Owner
Entity Name:	Pacific Bell Telephone Company dba AT&T California
Entity Title:	Not reported
Affiliation Address:	308 S. Akard St., 17th Floor
Affiliation City:	Dallas
Affiliation State:	TX
Affiliation Country:	United States
Affiliation Zip:	75202
Affiliation Phone:	(214) 464-1712,

Affiliation Type Desc:	Parent Corporation
Entity Name:	Pacific Bell Telephone Company dba AT&T California
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

B14 **PACIFIC BELL DBA AT&T OF CA** **RCRA-LQG** **1024877085**
NNW **1670 CACTUS ROAD** **CAR000286229**
1/8-1/4 **SAN DIEGO, CA 92154**
0.146 mi.
769 ft. **Site 9 of 9 in cluster B**

Relative: **Lower**
Actual: **507 ft.**

RCRA Listings:

Date Form Received by Agency:	20180702
Handler Name:	Pacific Bell Dba At&T Of Ca
Handler Address:	1670 CACTUS ROAD
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAR000286229
Contact Name:	MICHAEL JOHNSTON
Contact Address:	CACTUS ROAD
Contact City,State,Zip:	SAN DIEGO, CA 92154
Contact Telephone:	619-204-9861
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	EHS RRC RECORDKEEPER RM 3E000
Mailing City,State,Zip:	SAN RAMON, CA 94583
Owner Name:	Pacific Bell At&T Of Ca
Owner Type:	Private
Operator Name:	Pacific Bell At&T Of Ca
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	Yes

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180730
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D012
Waste Description: ENDRIN (1,2,3,4,10,10-HEXACHLORO-1,7-EPOXY-1,4,4A,5,6,7,8,8A-OCTAHYDRO-1,4-ENDO, ENDO-5,8-DIMETH-ANO-NAPHTHALENE)

Waste Code: D013
Waste Description: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

Waste Code: D014
Waste Description: METHOXYCHLOR (1,1,1-TRICHLORO-2,2-BIS [P-METHOXYPHENYL] ETHANE)

Waste Code: D015
Waste Description: TOXAPHENE (C10 H10 CL8, TECHNICAL CHLORINATED CAMPHENE, 67-69 PERCENT CHLORINE)

Waste Code: D016
Waste Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D017
Waste Description: 2,4,5-TP SILVEX (2,4,5-TRICHLOROPHENOXYPROPIONIC ACID)

Waste Code: D018
Waste Description: BENZENE

Waste Code: D019
Waste Description: CARBON TETRACHLORIDE

Waste Code: D020
Waste Description: CHLORDANE

Waste Code: D021
Waste Description: CHLOROBENZENE

Waste Code: D022
Waste Description: CHLOROFORM

Waste Code: D023
Waste Description: O-CRESOL

Waste Code: D024
Waste Description: M-CRESOL

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: D025
Waste Description: P-CRESOL

Waste Code: D026
Waste Description: CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D028
Waste Description: 1,2-DICHLOROETHANE

Waste Code: D029
Waste Description: 1,1-DICHLOROETHYLENE

Waste Code: D030
Waste Description: 2,4-DINITROTOLUENE

Waste Code: D031
Waste Description: HEPTACHLOR (AND ITS EPOXIDE)

Waste Code: D032
Waste Description: HEXACHLOROBENZENE

Waste Code: D033
Waste Description: HEXACHLOROBUTADIENE

Waste Code: D034
Waste Description: HEXACHLOROETHANE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D036
Waste Description: NITROBENZENE

Waste Code: D037
Waste Description: PENTACHLOROPHENOL

Waste Code: D038
Waste Description: PYRIDINE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Waste Code: D041
Waste Description: 2,4,5-TRICHLOROPHENOL

Waste Code: D042
Waste Description: 2,4,6-TRICHLOROPHENOL

Waste Code: D043
Waste Description: VINYL CHLORIDE

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F004
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F006
Waste Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste Code: F007
Waste Description: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Waste Code: F008
Waste Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F009
Waste Description: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F010
Waste Description: QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F011
Waste Description: SPENT CYANIDE SOLUTIONS FROM SLAT BATH POT CLEANING FROM METAL HEAT TREATING OPERATIONS.

Waste Code: F012
Waste Description: QUENCHING WASTEWATER TREATMENT SLUDGES FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F019
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE CHEMICAL CONVERSION COATING OF ALUMINUM, EXCEPT FROM ZIRCONIUM PHOSPHATING IN ALUMINUM CAN WASHING WHEN SUCH PHOSPHATING IS AN EXCLUSIVE CONVERSION COATING PROCESS.

Waste Code: F020
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- OR TETRACHLOROPHENOL OR OF INTERMEDIATES USED TO PRODUCE THEIR PESTICIDE DERIVATIVES. (THIS LISTING DOES NOT INCLUDE WASTES FROM THE PRODUCTION OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)

Waste Code: F021
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF PENTACHLOROPHENOL, OR OF INTERMEDIATES USED TO PRODUCE DERIVATIVES.

Waste Code: F022
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENES UNDER ALKALINE CONDITIONS.

Waste Code: F023
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- AND

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

TETRACHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE WASTES FROM EQUIPMENT USED ONLY FOR THE PRODUCTION OR USE OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)

Waste Code: F024
Waste Description: PROCESS WASTES INCLUDING, BUT NOT LIMITED TO, DISTILLATION RESIDUES, HEAVY ENDS, TARS, AND REACTOR CLEAN-OUT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION. (THIS LISTING DOES NOT INCLUDE WASTEWATERS, WASTEWATER TREATMENT SLUDGE, SPENT CATALYSTS, AND WASTES LISTED IN SECTIONS 261.31. OR 261.32)

Waste Code: F025
Waste Description: CONDENSED LIGHT ENDS, SPENT FILTERS AND FILTER AIDS, AND SPENT DESICCANT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION.

Waste Code: F026
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENE UNDER ALKALINE CONDITIONS.

Waste Code: F027
Waste Description: DISCARDED UNUSED FORMULATIONS CONTAINING TRI-, TETRA-, OR PENTACHLOROPHENOL OR DISCARDED UNUSED FORMULATIONS CONTAINING COMPOUNDS DERIVED FROM THESE CHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE FORMULATIONS CONTAINING HEXACHLOROPHENE SYNTHESIZED FROM PREPURIFIED 2,4,5-TRICHLOROPHENOL AS THE SOLE COMPONENT.)

Waste Code: F028
Waste Description: RESIDUES RESULTING FROM THE INCINERATION OR THERMAL TREATMENT OF SOIL CONTAMINATED WITH EPA HAZARDOUS WASTE NOS. F020, F021, F022, F023, F026, AND F027.

Waste Code: F032
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT CURRENTLY USE, OR HAVE PREVIOUSLY USED, CHLOROPHENOLIC FORMULATIONS [EXCEPT POTENTIALLY CROSS-CONTAMINATED WASTES THAT HAVE HAD THE F032 WASTE CODE DELETED IN ACCORDANCE WITH SECTION 261.35 (I.E., THE NEWLY PROMULGATED EQUIPMENT CLEANING OR REPLACEMENT STANDARDS), AND WHERE THE GENERATOR DOES NOT RESUME OR INITIATE USE OF CHLOROPHENOLIC FORMULATIONS]. (THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSE THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.)

Waste Code: F034
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE CREOSOTE FORMULATIONS. THIS LISTING DOES NOT INCLUDE K001 BOTTOM

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: F035
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE INORGANIC PRESERVATIVES CONTAINING ARSENIC OR CHROMIUM. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: F037
Waste Description: PETROLEUM REFINERY PRIMARY OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE GENERATED FROM THE GRAVITATIONAL SEPARATION OF OIL/WATER/SOLIDS DURING THE STORAGE OR TREATMENT OF PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH SLUDGES INCLUDE, BUT ARE NOT LIMITED TO, THOSE GENERATED IN OIL/WATER/SOLIDS SEPARATORS; TANKS AND IMPOUNDMENTS; DITCHES AND OTHER CONVEYANCES; SUMPS; AND STORM WATER UNITS RECEIVING DRY WEATHER FLOW. SLUDGES GENERATED IN STORM WATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Waste Code: F038
Waste Description: PETROLEUM REFINERY SECONDARY (EMULSIFIED) OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE AND/OR FLOAT GENERATED FROM THE PHYSICAL AND/OR CHEMICAL SEPARATION OF OIL/WATER/SOLIDS IN PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH WASTES INCLUDE, BUT ARE NOT LIMITED TO, ALL SLUDGES AND FLOATS GENERATED IN INDUCED AIR FLOTATION (IAF) UNITS, TANKS AND IMPOUNDMENTS, AND ALL SLUDGES GENERATED IN DAF UNITS. SLUDGES GENERATED IN STORMWATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND F037, K048, AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Waste Code: F039
Waste Description: LEACHATE RESULTING FROM THE TREATMENT, STORAGE, OR DISPOSAL OF WASTES CLASSIFIED BY MORE THAN ONE WASTE CODE UNDER SUBPART D, OR FROM A MIXTURE OF WASTES CLASSIFIED UNDER SUBPARTS C AND D OF THIS PART. (LEACHATE RESULTING FROM THE MANAGEMENT OF ONE OR MORE OF THE FOLLOWING EPA HAZARDOUS WASTES AND NO OTHER HAZARDOUS WASTES RETAINS ITS HAZARDOUS WASTE CODE(S): F020, F021, F022, F023, F026, F027, AND/OR F028.)

Waste Code: K001
Waste Description: BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATERS FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: K002
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME YELLOW AND ORANGE PIGMENTS.

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: K003
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF MOLYBDATE ORANGE PIGMENTS.

Waste Code: K004
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF ZINC YELLOW PIGMENTS.

Waste Code: K005
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME GREEN PIGMENTS.

Waste Code: K006
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS (ANHYDROUS AND HYDRATED).

Waste Code: K007
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF IRON BLUE PIGMENTS.

Waste Code: K008
Waste Description: OVEN RESIDUE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS.

Waste Code: K009
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.

Waste Code: K010
Waste Description: DISTILLATION SIDE CUTS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.

Waste Code: K011
Waste Description: BOTTOM STREAM FROM THE WASTEWATER STRIPPER IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K013
Waste Description: BOTTOM STREAM FROM THE ACETONITRILE COLUMN IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K014
Waste Description: BOTTOMS FROM THE ACETONITRILE PURIFICATION COLUMN IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K015
Waste Description: STILL BOTTOMS FROM THE DISTILLATION OF BENZYL CHLORIDE.

Waste Code: K016
Waste Description: HEAVY ENDS OR DISTILLATION RESIDUES FROM THE PRODUCTION OF CARBON TETRACHLORIDE.

Waste Code: K017
Waste Description: HEAVY ENDS (STILL BOTTOMS) FROM THE PURIFICATION COLUMN IN THE PRODUCTION OF EPICHLOROHYDRIN.

Waste Code: K018
Waste Description: HEAVY ENDS FROM THE FRACTIONATION COLUMN IN ETHYL CHLORIDE PRODUCTION.

Waste Code: K019

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: HEAVY ENDS FROM THE DISTILLATION OF ETHYLENE DICHLORIDE IN ETHYLENE DICHLORIDE PRODUCTION.

Waste Code: K020
Waste Description: HEAVY ENDS FROM THE DISTILLATION OF VINYL CHLORIDE IN VINYL CHLORIDE MONOMER PRODUCTION.

Waste Code: K021
Waste Description: AQUEOUS SPENT ANTIMONY CATALYST WASTE FROM FLUOROMETHANE PRODUCTION.

Waste Code: K022
Waste Description: DISTILLATION BOTTOM TARS FROM THE PRODUCTION OF PHENOL/ACETONE FROM CUMENE.

Waste Code: K023
Waste Description: DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.

Waste Code: K024
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.

Waste Code: K025
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF NITROBENZENE BY THE NITRATION OF BENZENE.

Waste Code: K026
Waste Description: STRIPPING STILL TAILS FROM THE PRODUCTION OF METHYL ETHYL PYRIDINES.

Waste Code: K027
Waste Description: CENTRIFUGE AND DISTILLATION RESIDUES FROM TOLUENE DIISOCYANATE PRODUCTION.

Waste Code: K028
Waste Description: SPENT CATALYST FROM THE HYDROCHLORINATOR REACTOR IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K029
Waste Description: WASTE FROM THE PRODUCT STEAM STRIPPER IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K030
Waste Description: COLUMN BOTTOMS OR HEAVY ENDS FROM THE COMBINED PRODUCTION OF TRICHLOROETHYLENE AND PERCHLOROETHYLENE.

Waste Code: K031
Waste Description: BY-PRODUCT SALTS GENERATED IN THE PRODUCTION OF MSMA AND CACODYLIC ACID.

Waste Code: K032
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHLORDANE.

Waste Code: K033
Waste Description: WASTEWATER AND SCRUB WATER FROM THE CHLORINATION OF CYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Waste Code: K034

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: FILTER SOLIDS FROM THE FILTRATION OF HEXACHLOROCYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Waste Code: K035
Waste Description: WASTEWATER TREATMENT SLUDGES GENERATED IN THE PRODUCTION OF CREOSOTE.

Waste Code: K036
Waste Description: STILL BOTTOMS FROM TOLUENE RECLAMATION DISTILLATION IN THE PRODUCTION OF DISULFOTON.

Waste Code: K037
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF DISULFOTON.

Waste Code: K038
Waste Description: WASTEWATER FROM THE WASHING AND STRIPPING OF PHORATE PRODUCTION.

Waste Code: K039
Waste Description: FILTER CAKE FROM THE FILTRATION OF DIETHYLPHOSPHORODITHIOIC ACID IN THE PRODUCTION OF PHORATE.

Waste Code: K040
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF PHORATE.

Waste Code: K041
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF TOXAPHENE.

Waste Code: K042
Waste Description: HEAVY ENDS OR DISTILLATION RESIDUES FROM THE DISTILLATION OF TETRACHLOROBENZENE IN THE PRODUCTION OF 2,4,5-T.

Waste Code: K043
Waste Description: 2,6-DICHLOROPHENOL WASTE FROM THE PRODUCTION OF 2,4-D.

Waste Code: K044
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING AND PROCESSING OF EXPLOSIVES.

Waste Code: K045
Waste Description: SPENT CARBON FROM THE TREATMENT OF WASTEWATER CONTAINING EXPLOSIVES.

Waste Code: K046
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING, FORMULATION, AND LOADING OF LEAD-BASED INITIATING COMPOUNDS.

Waste Code: K047
Waste Description: PINK/RED WATER FROM TNT OPERATIONS.

Waste Code: K048
Waste Description: DISSOLVED AIR FLOTATION (DAF) FLOAT FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K049
Waste Description: SLOP OIL EMULSION SOLIDS FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K050
Waste Description: HEAT EXCHANGER BUNDLE CLEANING SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: K051
Waste Description: API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K052
Waste Description: TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K060
Waste Description: AMMONIA STILL LIME SLUDGE FROM COKING OPERATIONS.

Waste Code: K061
Waste Description: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Waste Code: K062
Waste Description: SPENT PICKLE LIQUOR FROM STEEL FINISHING OPERATIONS OF PLANTS THAT PRODUCE IRON OR STEEL.

Waste Code: K069
Waste Description: EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.

Waste Code: K071
Waste Description: BRINE PURIFICATION MUDS FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION, IN WHICH SEPARATELY PREPURIFIED BRINE IS NOT USED.

Waste Code: K073
Waste Description: CHLORINATED HYDROCARBON WASTE FROM THE PURIFICATION STEP OF THE DIAPHRAGM CELL PROCESS USING GRAPHITE ANODES IN CHLORINE PRODUCTION.

Waste Code: K083
Waste Description: DISTILLATION BOTTOMS FROM ANILINE PRODUCTION.

Waste Code: K084
Waste Description: WASTEWATER TREATMENT SLUDGES GENERATED DURING THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K085
Waste Description: DISTILLATION OR FRACTIONATION COLUMN BOTTOMS FROM THE PRODUCTION OF CHLOROBENZENES.

Waste Code: K086
Waste Description: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

Waste Code: K087
Waste Description: DECANTER TANK TAR SLUDGE FROM COKING OPERATIONS.

Waste Code: K088
Waste Description: SPENT POTLINERS FROM PRIMARY ALUMINUM REDUCTION.

Waste Code: K093
Waste Description: DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM ORTHO-XYLENE.

Waste Code: K094
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

ORTHO-XYLENE.

Waste Code: K095
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K096
Waste Description: HEAVY ENDS FROM THE HEAVY ENDS COLUMN FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K097
Waste Description: VACUUM STRIPPER DISCHARGE FROM THE CHLORDANE CHLORINATOR IN THE PRODUCTION OF CHLORDANE.

Waste Code: K098
Waste Description: UNTREATED PROCESS WASTEWATER FROM THE PRODUCTION OF TOXAPHENE.

Waste Code: K099
Waste Description: UNTREATED WASTEWATER FROM THE PRODUCTION OF 2,4-D.

Waste Code: K100
Waste Description: WASTE LEACHING SOLUTION FROM ACID LEACHING OF EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.

Waste Code: K101
Waste Description: DISTILLATION TAR RESIDUES FROM THE DISTILLATION OF ANILINE-BASED COMPOUNDS IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K102
Waste Description: RESIDUE FROM THE USE OF ACTIVATED CARBON FOR DECOLORIZATION IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K103
Waste Description: PROCESS RESIDUES FROM ANILINE EXTRACTION FROM THE PRODUCTION OF ANILINE.

Waste Code: K104
Waste Description: COMBINED WASTEWATERS GENERATED FROM NITROBENZENE/ANILINE PRODUCTION.

Waste Code: K105
Waste Description: SEPARATED AQUEOUS STREAM FROM THE REACTOR PRODUCT WASHING STEP IN THE PRODUCTION OF CHLOROBENZENES.

Waste Code: K106
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION.

Waste Code: K107
Waste Description: COLUMN BOTTOMS FROM PRODUCT SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE (UDMH) FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K108
Waste Description: CONDENSED COLUMN OVERHEADS FROM PRODUCT SEPARATION AND CONDENSED REACTOR VENT GASES FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: K109
Waste Description: SPENT FILTER CARTRIDGES FROM PRODUCT PURIFICATION FROM THE PRODUCT OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K110
Waste Description: CONDENSED COLUMN OVERHEADS FROM INTERMEDIATE SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K111
Waste Description: PRODUCT WASHWATERS FROM THE PRODUCTION OF DINITROTOLUENE VIA NITRATION OF TOLUENE.

Waste Code: K112
Waste Description: REACTION BY-PRODUCT WATER FROM THE DRYING COLUMN IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K113
Waste Description: CONDENSED LIQUID LIGHT ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K114
Waste Description: VICINALS FROM THE PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K115
Waste Description: HEAVY ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K116
Waste Description: ORGANIC CONDENSATE FROM THE SOLVENT RECOVERY COLUMN IN THE PRODUCTION OF TOLUENE DIISOCYANATE VIA PHOSGENATION OF TOLUENEDIAMINE.

Waste Code: K117
Waste Description: WASTEWATER FROM THE REACTOR VENT GAS SCRUBBER IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K118
Waste Description: SPENT ADSORBENT SOLIDS FROM PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K123
Waste Description: PROCESS WASTEWATER (INCLUDING SUPERNATES, FILTRATES, AND WASHWATERS) FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K124
Waste Description: REACTOR VENT SCRUBBER WATER FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K125
Waste Description: FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K126
Waste Description: BAGHOUSE DUST AND FLOOR SWEEPINGS IN MILLING AND PACKAGING OPERATIONS FROM PRODUCTION OR FORMULATION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: K131
Waste Description: WASTEWATER FROM THE REACTOR AND SPENT SULFURIC ACID FROM THE ACID DRYER FROM THE PRODUCTION OF METHYL BROMIDE.

Waste Code: K132
Waste Description: SPENT ABSORBENT AND WASTEWATER SEPARATOR SOLIDS FROM THE PRODUCTION OF METHYL BROMIDE.

Waste Code: K136
Waste Description: STILL BOTTOMS FROM THE PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K141
Waste Description: PROCESS RESIDUES FROM THE RECOVERY OF COAL TAR, INCLUDING, BUT NOT LIMITED TO, TAR COLLECTING SUMP RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL. THIS LISTING DOES NOT INCLUDE K087 (DECANTER TANK SLUDGE FROM COKING OPERATIONS).

Waste Code: K142
Waste Description: TANK STORAGE RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR FROM THE RECOVERY OF COKE BY-PRODUCTS FROM COAL.

Waste Code: K143
Waste Description: PROCESS RESIDUES FROM THE RECOVERY OF LIGHT OIL, INCLUDING, BUT NOT LIMITED TO, THOSE GENERATED IN STILLS, DECANTERS, AND WASH OIL RECOVERY UNITS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K144
Waste Description: WASTEWATER SUMP RESIDUES FROM LIGHT OIL REFINING, INCLUDING, BUT NOT LIMITED TO, INTERCEPTING OR CONTAMINATION SUMP SLUDGES FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K145
Waste Description: RESIDUES FROM NAPHTHALENE COLLECTION AND RECOVERY OPERATIONS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K147
Waste Description: TAR STORAGE RESIDUES FROM COAL TAR REFINING.

Waste Code: K148
Waste Description: RESIDUES FROM COAL TAR DISTILLATION, INCLUDING, BUT NOT LIMITED TO, STILL BOTTOMS.

Waste Code: K149
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, RING-CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS. [THIS WASTE DOES NOT INCLUDE STILL BOTTOMS FROM THE DISTILLATION OF BENZOYL CHLORIDE]

Waste Code: K150
Waste Description: ORGANIC RESIDULES EXCLUDING SPENT CARBON ADSORBENT, FROM THE SPENT CHLORINE GAS AND HYDROCHLORIC ACID RECOVERY PROCESSES ASSOCIATED WITH THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: K151
Waste Description: WASTEWATER TREATMENT SLUDGES, EXCLUDING NEUTRALIZATION AND BIOLOGICAL SLUDGES, GENERATED DURING THE TREATMENT OF WASTEWATERS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.

Waste Code: K156
Waste Description: ORGANIC WASTE (INCLUDING HEAVY ENDS, STILL BOTTOMS, LIGHT ENDS, SPENT SOLVENTS, FILTRATES, AND DECANTATES) FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K157
Waste Description: WASTEWATERS (INCLUDING SCRUBBER WATERS, CONDENSER WATERS, WASHWATERS, AND SEPARATION WATERS) FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K158
Waste Description: BAG HOUSE DUSTS AND FILTER/SEPARATION SOLIDS FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K159
Waste Description: ORGANICS FROM THE TREATMENT OF THIOCARBAMATE WASTES.

Waste Code: K161
Waste Description: PURIFICATION SOLIDS (INCLUDING FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS), BAG HOUSE DUST AND FLOOR SWEEPINGS FROM THE PRODUCTION OF DITHIOCARBAMATE ACIDS AND THEIR SALTS. (THIS LISTING DOES NOT INCLUDE K125 OR K126).

Waste Code: K169
Waste Description: K169

Waste Code: K170
Waste Description: K170

Waste Code: K171
Waste Description: K171

Waste Code: K172
Waste Description: K172

Waste Code: K174
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF ETHLYENE DICHLORIDE OR VINYL CHLORIDE

Waste Code: K175
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF VINYL CHLORIDE MONOMER..

Waste Code: K176
Waste Description: BAGHOUSE FILTERS FROM THE PRODUCTION OF ANTIMONY OXIDE, INCLUDING FILTERS FROM THE PRODUCTION OF INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Waste Code: K177
Waste Description: SLAG FROM THE PRODUCTION OF ANTIMONY OXIDE THAT IS SPECULATIVELY ACCUMULATED OR DISPOSED,INCLUDING SLAG FROM THE PRODUCTION OF

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Waste Code: K178
Waste Description: RESIDUES FROM MANUFACTURING AND MANUFACTURING-SITE STORAGE OF FERRIC CHLORIDE FROM ACIDS FORMED DURING THE PRODUCTION OF TITANIUM DIOXIDE USING THE CHLORIDE-ILMENITE PROCESS.

Waste Code: K181
Waste Description: Nonwastewaters from the production of dyes and/or pigments.

Waste Code: LABP
Waste Description: LAB PACK

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P002
Waste Description: 1-ACETYL-2-THIOUREA (OR) ACETAMIDE, N-(AMINOTHIOXOMETHYL)-

Waste Code: P003
Waste Description: 2-PROPENAL (OR) ACROLEIN

Waste Code: P004
Waste Description: 1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5ALPHA, 8ALPHA, 8ABETA)- (OR) ALDRIN

Waste Code: P005
Waste Description: 2-PROPEN-1-OL (OR) ALLYL ALCOHOL

Waste Code: P006
Waste Description: ALUMINUM PHOSPHIDE (R,T)

Waste Code: P007
Waste Description: 3(2H)-ISOXAZOLONE, 5-(AMINOMETHYL)- (OR) 5-(AMINOMETHYL)-3-ISOXAZOLOL

Waste Code: P008
Waste Description: 4-AMINOPYRIDINE (OR) 4-PYRIDINAMINE

Waste Code: P009
Waste Description: AMMONIUM PICRATE (R) (OR) PHENOL, 2,4,6-TRINITRO-, AMMONIUM SALT (R)

Waste Code: P010
Waste Description: ARSENIC ACID H3ASO4

Waste Code: P011
Waste Description: ARSENIC OXIDE AS2O5 (OR) ARSENIC PENTOXIDE

Waste Code: P012
Waste Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Waste Code: P013
Waste Description: BARIUM CYANIDE

Waste Code: P014

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: BENZENETHIOL (OR) THIOPHENOL

Waste Code: P015
Waste Description: BERYLLIUM

Waste Code: P016
Waste Description: DICHLOROMETHYL ETHER (OR) METHANE, OXYBIS[CHLORO-

Waste Code: P017
Waste Description: 2-PROPANONE, 1-BROMO- (OR) BROMOACETONE

Waste Code: P018
Waste Description: BRUCINE (OR) STRYCHNIDIN-10-ONE, 2,3-DIMETHOXY-

Waste Code: P020
Waste Description: DINOSEB (OR) PHENOL, 2-(1-METHYLPROPYL)-4,6-DINITRO-

Waste Code: P021
Waste Description: CALCIUM CYANIDE (OR) CALCIUM CYANIDE CA(CN)2

Waste Code: P022
Waste Description: CARBON DISULFIDE

Waste Code: P023
Waste Description: ACETALDEHYDE, CHLORO- (OR) CHLOROACETALDEHYDE

Waste Code: P024
Waste Description: BENZENAMINE, 4-CHLORO- (OR) P-CHLORANILINE

Waste Code: P026
Waste Description: 1-(O-CHLOROPHENYL)THIOUREA (OR) THIOUREA, (2-CHLOROPHENYL)-

Waste Code: P027
Waste Description: 3-CHLOROPROPIONITRILE (OR) PROPANENITRILE, 3-CHLORO-

Waste Code: P028
Waste Description: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

Waste Code: P029
Waste Description: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

Waste Code: P030
Waste Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Waste Code: P031
Waste Description: CYANOGEN (OR) ETHANEDINITRILE

Waste Code: P033
Waste Description: CYANOGEN CHLORIDE (OR) CYANOGEN CHLORIDE (CN)CL

Waste Code: P034
Waste Description: 2-CYCLOHEXYL-4,6-DINITROPHENOL (OR) PHENOL, 2-CYCLOHEXYL-4,6-DINITRO-

Waste Code: P036
Waste Description: ARSONOUS DICHLORIDE, PHENYL- (OR) DICHLOROPHENYLARSINE

Waste Code: P037

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: 2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2AALPHA, 3BETA, 6BETA, 6AALPHA, 7BETA, 7AALPHA)- (OR) DIELDRIN

Waste Code: P038
Waste Description: ARSINE, DIETHYL- (OR) DIETHYLARSINE

Waste Code: P039
Waste Description: DISULFOTON (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[2-(ETHYLTHIO)ETHYL] ESTER

Waste Code: P040
Waste Description: O,O-DIETHYL O-PYRAZINYL PHOSPHOROTHIOATE (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL O-PYRAZINYL ESTER

Waste Code: P041
Waste Description: DIETHYL-P-NITROPHENYL PHOSPHATE (OR) PHOSPHORIC ACID, DIETHYL 4-NITROPHENYL ESTER

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P043
Waste Description: DIISOPROPYLFLUOROPHOSPHATE (DFP) (OR) PHOSPHOROFLUORIDIC ACID, BIS(1-METHYLETHYL) ESTER

Waste Code: P044
Waste Description: DIMETHOATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIMETHYL S-[2-(METHYLAMINO)-2-OXOETHYL] ESTER

Waste Code: P045
Waste Description: 2-BUTANONE, 3,3-DIMETHYL-1-(METHYLTHIO)-, O-[METHYLAMINO)CARBONYL] OXIME (OR) THIOFANOX

Waste Code: P046
Waste Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Waste Code: P047
Waste Description: 4,6-DINITRO-O-CRESOL, & SALTS (OR) PHENOL, 2-METHYL-4,6-DINITRO-, & SALTS

Waste Code: P048
Waste Description: 2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-

Waste Code: P049
Waste Description: DITHIOBIURET (OR) THIOIMIDODICARBONIC DIAMIDE [(H2N)C(S)]2NH

Waste Code: P050
Waste Description: 6,9-METHANO-2,4,3-BENZODIOXATHIEPIN,6,7,8,9,10,10-HEXACHLORO-1,5,5A,6, 9,9A-HEXAHYDRO-,3-OXIDE (OR) ENDOSULFAN

Waste Code: P051
Waste Description: 2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2ABETA, 3ALPHA, 6ALPHA, 6ABETA, 7BETA, 7AALPHA)- & METABOLITES

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

(OR) ENDRIN (OR) ENDRIN, & METABOLITES

Waste Code: P054
Waste Description: AZIRIDINE (OR) ETHYLENEIMINE

Waste Code: P056
Waste Description: FLUORINE

Waste Code: P057
Waste Description: ACETAMIDE, 2-FLUORO- (OR) FLUOROACETAMIDE

Waste Code: P058
Waste Description: ACETIC ACID, FLUORO-, SODIUM SALT (OR) FLUOROACETIC ACID, SODIUM SALT

Waste Code: P059
Waste Description: 4,7-METHANO-1H-INDENE, 1,4,5,6,7,8,8-HEPTACHLORO-3A,4,7,7A-TETRAHYDRO- (OR) HEPTACHLOR

Waste Code: P060
Waste Description: 1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5BETA, 8BETA, 8ABETA)- (OR) ISODRIN

Waste Code: P062
Waste Description: HEXAETHYL TETRAPHOSPHATE (OR) TETRAPHOSPHORIC ACID, HEXAETHYL ESTER

Waste Code: P063
Waste Description: HYDROCYANIC ACID (OR) HYDROGEN CYANIDE

Waste Code: P064
Waste Description: METHANE, ISOCYANATO- (OR) METHYL ISOCYANATE

Waste Code: P065
Waste Description: FULMINIC ACID, MERCURY(2+) SALT (R,T) (OR) MERCURY FULMINATE (R,T)

Waste Code: P066
Waste Description: ETHANIMIDOTHIOIC ACID, N-[[(METHYLAMINO)CARBONYL]OXY]-, METHYL ESTER (OR) METHOMYL

Waste Code: P067
Waste Description: 1,2-PROPYLENIMINE (OR) AZIRIDINE, 2-METHYL-

Waste Code: P068
Waste Description: HYDRAZINE, METHYL- (OR) METHYL HYDRAZINE

Waste Code: P069
Waste Description: 2-METHYLLACTONITRILE (OR) PROPANENITRILE, 2-HYDROXY-2-METHYL-

Waste Code: P070
Waste Description: ALDICARB (OR) PROPANAL, 2-METHYL-2-(METHYLTHIO)-, O-[(METHYLAMINO)CARBONYL]OXIME

Waste Code: P071
Waste Description: METHYL PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O,-DIMETHYL O-(4-NITROPHENYL) ESTER

Waste Code: P072

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: ALPHA-NAPHTHYLTHIOUREA (OR) THIOUREA, 1-NAPHTHALENYL-

Waste Code: P073
Waste Description: NICKEL CARBONYL (OR) NICKEL CARBONYL NI(CO)4, (T-4)-

Waste Code: P074
Waste Description: NICKEL CYANIDE (OR) NICKEL CYANIDE NI(CN)2

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P076
Waste Description: NITRIC OXIDE (OR) NITROGEN OXIDE NO

Waste Code: P077
Waste Description: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

Waste Code: P078
Waste Description: NITROGEN DIOXIDE (OR) NITROGEN OXIDE NO2

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P082
Waste Description: METHANIMINE, N-METHYL-N-NITROSO- (OR) N-NITROSODIMETHYLAMINE

Waste Code: P084
Waste Description: N-NITROSOMETHYLVINYLAMINE (OR) VINYLAMINE, N-METHYL-N-NITROSO-

Waste Code: P085
Waste Description: DIPHOSPHORAMIDE, OCTAMETHYL- (OR) OCTAMETHYLPYROPHOSPHORAMIDE

Waste Code: P087
Waste Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Waste Code: P088
Waste Description: 7-OXABICYCLO[2.2.1]HEPTANE-2,3-DICARBOXYLIC ACID (OR) ENDOTHALL

Waste Code: P089
Waste Description: PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL-O-(4-NITROPHENYL) ESTER

Waste Code: P092
Waste Description: MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE

Waste Code: P093
Waste Description: PHENYLTHIOUREA (OR) THIOUREA, PHENYL-

Waste Code: P094
Waste Description: PHORATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[(ETHYLTHIO)METHYL] ESTER

Waste Code: P095
Waste Description: CARBONIC DICHLORIDE (OR) PHOSGENE

Waste Code: P096

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: HYDROGEN PHOSPHIDE (OR) PHOSPHINE

Waste Code: P097
Waste Description: FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

Waste Code: P098
Waste Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Waste Code: P099
Waste Description: ARGENTATE (1-), BIS(CYANO-C)-, POTASSIUM (OR) POTASSIUM SILVER CYANIDE

Waste Code: P101
Waste Description: ETHYL CYANIDE (OR) PROPANENITRILE

Waste Code: P102
Waste Description: 2-PROPYN-1-OL (OR) PROPARGYL ALCOHOL

Waste Code: P103
Waste Description: SELENOUREA

Waste Code: P104
Waste Description: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

Waste Code: P105
Waste Description: SODIUM AZIDE

Waste Code: P106
Waste Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Waste Code: P108
Waste Description: STRYCHNIDIN-10-ONE, & SALTS (OR) STRYCHNINE, & SALTS

Waste Code: P109
Waste Description: TETRAETHYLDITHIOPYROPHOSPHATE (OR) THIODIPHOSPHORIC ACID, TETRAETHYL ESTER

Waste Code: P110
Waste Description: PLUMBANE, TETRAETHYL- (OR) TETRAETHYL LEAD

Waste Code: P111
Waste Description: DIPHOSPHORIC ACID, TETRAETHYL ESTER (OR) TETRAETHYL PYROPHOSPHATE

Waste Code: P112
Waste Description: METHANE, TETRANITRO- (R) (OR) TETRANITROMETHANE (R)

Waste Code: P113
Waste Description: THALLIC OXIDE (OR) THALLIUM OXIDE TL2O3

Waste Code: P114
Waste Description: SELENIOUS ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SELENITE

Waste Code: P115
Waste Description: SULFURIC ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SULFATE

Waste Code: P116
Waste Description: HYDRAZINECARBOTHIOAMIDE (OR) THIOSEMICARBAZIDE

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: P118
Waste Description: METHANETHIOL, TRICHLORO- (OR) TRICHLOROMETHANETHIOL

Waste Code: P119
Waste Description: AMMONIUM VANADATE (OR) VANADIC ACID, AMMONIUM SALT

Waste Code: P120
Waste Description: VANADIUM OXIDE V2O5 (OR) VANADIUM PENTOXIDE

Waste Code: P121
Waste Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Waste Code: P122
Waste Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 10% (R,T)

Waste Code: P123
Waste Description: TOXAPHENE

Waste Code: P124
Waste Description: ACTINOMYCIN D

Waste Code: P127
Waste Description: P127

Waste Code: P128
Waste Description: P128

Waste Code: P185
Waste Description: 1,3-DITHIOLANE-2-CARBOXALDEHYDE, 2,4-DIMETHYL-, O-[(METHYLAMINO)-CARBONYL]OXIME (OR) TIRPATE

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: P189
Waste Description: CARBAMIC ACID, [(DIBUTYLAMINO)-THIO]METHYL-, 2,3-DIHYDRO-2,2-DIMETHYL -7-BENZOFURANYL ESTER (OR) CARBOSULFAN

Waste Code: P190
Waste Description: CARBAMIC ACID, METHYL-, 3-METHYLPHENYL ESTER (OR) METOLCARB

Waste Code: P191
Waste Description: CARBAMIC ACID, DIMETHYL-, 1-[(DIMETHYL-AMINO)CARBONYL]- 5-METHYL-1H-PYRAZOL-3-YL ESTER (OR) DIMETILAN

Waste Code: P192
Waste Description: ISOLAN (OR) CARBAMIC ACID, DIMETHYL-, 3-METHY-L-(1-METHYLETHYL)-1H-PYRAZOL-5-YL ESTER

Waste Code: P194
Waste Description: ETHANIMIDOTHIOC ACID, 2-(DIMETHYLAMINO)-N-[[(METHYLAMINO) CARBONYL]OXY]-2-OXO-, METHYL ESTER (OR) OXAMYL

Waste Code: P196

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: MANGANESE DIMETHYLDITHIOCARBAMATE (OR) MANGANESE, BIS(DIMETHYLCARBAMODITHIOATO-S,S')-,

Waste Code: P197
Waste Description: FORMPARANATE (OR) METHANIMIDAMIDE, N,N-DIMETHYL-N'-[2-METHYL-4-[[(METHYLAMINO)CARBONYL]OXY]PHENYL]

Waste Code: P198
Waste Description: METHANIMIDAMIDE, N,N-DIMETHYL-N'-[3-[[(METHYLAMINO)-CARBONYL]OXY]PHENYL]-, MONOHYDROCHLORIDE (OR) FORMETANATE HYDROCHLORIDE

Waste Code: P199
Waste Description: P199

Waste Code: P201
Waste Description: PHENOL, 3-METHYL-5-(1-METHYLETHYL)-, METHYL CARBAMATE (OR) PROMECARB

Waste Code: P202
Waste Description: M-CUMENYL METHYLCARBAMATE (OR) 3-ISOPROPYLPHENYL N-METHYLCARBAMATE (OR) PHENOL, 3-(1-METHYLETHYL)-, METHYL CARBAMATE

Waste Code: P203
Waste Description: ALDICARB SULFONE (OR) PROPANAL, 2-METHYL-2-(METHYL-SULFONYL)-, O-[(METHYLAMINO)CARBONYL] OXIME

Waste Code: P204
Waste Description: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

Waste Code: P205
Waste Description: ZINC, BIS(DIMETHYLCARBAMODITHIOATO-S,S')-, (OR) ZIRAM

Waste Code: U001
Waste Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U003
Waste Description: ACETONITRILE (I,T)

Waste Code: U004
Waste Description: ACETOPHENONE (OR) ETHANONE, 1-PHENYL-

Waste Code: U005
Waste Description: 2-ACETYLAMINOFLUORENE (OR) ACETAMIDE, N-9H-FLUOREN-2-YL

Waste Code: U006
Waste Description: ACETYL CHLORIDE (C,R,T)

Waste Code: U007
Waste Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Waste Code: U008
Waste Description: 2-PROPENOIC ACID (I) (OR) ACRYLIC ACID (I)

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U009
Waste Description: 2-PROPENENITRILE (OR) ACRYLONITRILE

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U011
Waste Description: 1H-1,2,4-TRIAZOL-3-AMINE (OR) AMITROLE

Waste Code: U012
Waste Description: ANILINE (I,T) (OR) BENZENAMINE (I,T)

Waste Code: U014
Waste Description: AURAMINE (OR) BENZENAMINE, 4,4'-CARBONIMIDOYLBIS[N,N-DIMETHYL-

Waste Code: U015
Waste Description: AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)

Waste Code: U016
Waste Description: BENZ[C]ACRIDINE

Waste Code: U017
Waste Description: BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-

Waste Code: U018
Waste Description: BENZ[A]ANTHRACENE

Waste Code: U019
Waste Description: BENZENE (I,T)

Waste Code: U020
Waste Description: BENZENESULFONIC ACID CHLORIDE (C,R) (OR) BENZENESULFONYL CHLORIDE (C,R)

Waste Code: U021
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE (OR) BENZIDINE

Waste Code: U022
Waste Description: BENZO[A]PYRENE

Waste Code: U023
Waste Description: BENZENE, (TRICHLOROMETHYL)- (OR) BENZOTRICHLORIDE (C,R,T)

Waste Code: U024
Waste Description: DICHLOROMETHOXY ETHANE (OR) ETHANE, 1,1'-[METHYLENEBIS(OXY)]BIS[2-CHLORO-

Waste Code: U025
Waste Description: DICHLOROETHYL ETHER (OR) ETHANE, 1,1'-OXYBIS[2-CHLORO-

Waste Code: U026
Waste Description: CHLORNAPHAZIN (OR) NAPHTHALENAMINE, N,N'-BIS(2-CHLOROETHYL)-

Waste Code: U027

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: DICHLOROISOPROPYL ETHER (OR) PROPANE, 2,2'-OXYBIS[2-CHLORO-

Waste Code: U028
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, BIS(2-ETHYLHEXYL) ESTER (OR) DIETHYLHEXYL PHTHALATE

Waste Code: U029
Waste Description: METHANE, BROMO- (OR) METHYL BROMIDE

Waste Code: U030
Waste Description: 4-BROMOPHENYL PHENYL ETHER (OR) BENZENE, 1-BROMO-4-PHENOXY-

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U032
Waste Description: CALCIUM CHROMATE (OR) CHROMIC ACID H2CRO4, CALCIUM SALT

Waste Code: U033
Waste Description: CARBON OXYFLUORIDE (R,T) (OR) CARBONIC DIFLUORIDE

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U036
Waste Description: 4,7-METHANO-1H-INDENE, 1,2,4,5,6,7,8,8-OCTACHLORO-2,3,3A,4,7,7A-HEXAHYDRO- (OR) CHLORDANE, ALPHA & GAMMA ISOMERS

Waste Code: U037
Waste Description: BENZENE, CHLORO- (OR) CHLOROBENZENE

Waste Code: U038
Waste Description: BENZENEACETIC ACID, 4-CHLORO-ALPHA-(4-CHLOROPHENYL)-ALPHA-HYDROXY-, ETHYL ESTER (OR) CHLOROBENZILATE

Waste Code: U039
Waste Description: P-CHLORO-M-CRESOL (OR) PHENOL, 4-CHLORO-3-METHYL-

Waste Code: U041
Waste Description: EPICHLOROHYDRIN (OR) OXIRANE, (CHLOROMETHYL)-

Waste Code: U042
Waste Description: 2-CHLOROETHYL VINYL ETHER (OR) ETHENE, (2-CHLOROETHOXY)-

Waste Code: U043
Waste Description: ETHENE, CHLORO- (OR) VINYL CHLORIDE

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U045
Waste Description: METHANE, CHLORO- (I,T) (OR) METHYL CHLORIDE (I,T)

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U046
Waste Description: CHLOROMETHYL METHYL ETHER (OR) METHANE, CHLOROMETHOXY-

Waste Code: U047
Waste Description: BETA-CHLORONAPHTHALENE (OR) NAPHTHALENE, 2-CHLORO-

Waste Code: U048
Waste Description: O-CHLOROPHENOL (OR) PHENOL, 2-CHLORO-

Waste Code: U049
Waste Description: 4-CHLORO-O-TOLUIDINE, HYDROCHLORIDE (OR) BENZENAMINE, 4-CHLORO-2-METHYL-, HYDROCHLORIDE

Waste Code: U050
Waste Description: CHRYSENE

Waste Code: U051
Waste Description: CREOSOTE

Waste Code: U052
Waste Description: CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-

Waste Code: U053
Waste Description: 2-BUTENAL (OR) CROTONALDEHYDE

Waste Code: U055
Waste Description: BENZENE, (1-METHYLETHYL)- (I) (OR) CUMENE (I)

Waste Code: U056
Waste Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Waste Code: U057
Waste Description: CYCLOHEXANONE (I)

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U059
Waste Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Waste Code: U060
Waste Description: BENZENE, 1,1'-(2,2-DICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDD

Waste Code: U061
Waste Description: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDT

Waste Code: U062
Waste Description: CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3-DICHLORO-2-PROPENYL) ESTER (OR) DIALLATE

Waste Code: U063
Waste Description: DIBENZ[A,H]ANTHRACENE

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U064
Waste Description: BENZO[RST]PENTAPHENE (OR) DIBENZO[A,I]PYRENE

Waste Code: U066
Waste Description: 1,2-DIBROMO-3-CHLOROPROPANE (OR) PROPANE, 1,2-DIBROMO-3-CHLORO-

Waste Code: U067
Waste Description: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

Waste Code: U068
Waste Description: METHANE, DIBROMO- (OR) METHYLENE BROMIDE

Waste Code: U069
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE

Waste Code: U070
Waste Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Waste Code: U071
Waste Description: BENZENE, 1,3-DICHLORO- (OR) M-DICHLOROBENZENE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U073
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DICHLORO- (OR) 3,3'-DICHLOROBENZIDINE

Waste Code: U074
Waste Description: 1,4-DICHLORO-2-BUTENE (I,T) (OR) 2-BUTENE, 1,4-DICHLORO- (I,T)

Waste Code: U075
Waste Description: DICHLORODIFLUOROMETHANE (OR) METHANE, DICHLORODIFLUORO-

Waste Code: U076
Waste Description: ETHANE, 1,1-DICHLORO- (OR) ETHYLIDENE DICHLORIDE

Waste Code: U077
Waste Description: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

Waste Code: U078
Waste Description: 1,1-DICHLOROETHYLENE (OR) ETHENE, 1,1-DICHLORO-

Waste Code: U079
Waste Description: 1,2-DICHLOROETHYLENE (OR) ETHENE, 1,2-DICHLORO-,(E)-

Waste Code: U080
Waste Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Waste Code: U081
Waste Description: 2,4-DICHLOROPHENOL (OR) PHENOL, 2,4-DICHLORO-

Waste Code: U082
Waste Description: 2,6-DICHLOROPHENOL (OR) PHENOL, 2,6-DICHLORO-

Waste Code: U083
Waste Description: PROPANE, 1,2-DICHLORO- (OR) PROPYLENE DICHLORIDE

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U084
Waste Description: 1,3-DICHLOROPROPENE (OR) 1-PROPENE, 1,3-DICHLORO-

Waste Code: U085
Waste Description: 1,2:3,4-DIEPOXYBUTANE (I,T) (OR) 2,2'-BIOXIRANE

Waste Code: U086
Waste Description: HYDRAZINE, 1,2-DIETHYL- (OR) N,N'-DIETHYLHYDRAZINE

Waste Code: U087
Waste Description: O,O-DIETHYL S-METHYL DITHIOPHOSPHATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-METHYL ESTER

Waste Code: U088
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE

Waste Code: U089
Waste Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Waste Code: U090
Waste Description: 1,3-BENZODIOXOLE, 5-PROPYL- (OR) DIHYDROSAFROLE

Waste Code: U091
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHOXY- (OR) 3,3'-DIMETHOXYBENZIDINE

Waste Code: U092
Waste Description: DIMETHYLAMINE (I) (OR) METHANAMINE, N-METHYL- (I)

Waste Code: U093
Waste Description: BENZENAMINE, N,N-DIMETHYL-4-(PHENYLAZO)- (OR) P-DIMETHYLAMINOAZOBENZENE

Waste Code: U094
Waste Description: 7,12-DIMETHYLBENZ[A]ANTHRACENE (OR) BENZ[A]ANTHRACENE, 7,12-DIMETHYL-

Waste Code: U095
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHYL- (OR) 3,3'-DIMETHYLBENZIDINE

Waste Code: U096
Waste Description: ALPHA,ALPHA-DIMETHYLBENZYLHYDROPEROXIDE (R) (OR) HYDROPEROXIDE, 1-METHYL-1-PHENYLETHYL- (R)

Waste Code: U097
Waste Description: CARBAMIC CHLORIDE, DIMETHYL- (OR) DIMETHYLCARBAMOYL CHLORIDE

Waste Code: U098
Waste Description: 1,1-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,1-DIMETHYL-

Waste Code: U099
Waste Description: 1,2-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Waste Code: U101
Waste Description: 2,4-DIMETHYLPHENOL (OR) PHENOL, 2,4-DIMETHYL-

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U102
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIMETHYL ESTER (OR) DIMETHYL PHTHALATE

Waste Code: U103
Waste Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Waste Code: U105
Waste Description: 2,4-DINITROTOLUENE (OR) BENZENE, 1-METHYL-2,4-DINITRO-

Waste Code: U106
Waste Description: 2,6-DINITROTOLUENE (OR) BENZENE, 2-METHYL-1,3-DINITRO-

Waste Code: U107
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIOCTYL ESTER (OR) DI-N-OCTYL PHTHALATE

Waste Code: U108
Waste Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Waste Code: U109
Waste Description: 1,2-DIPHENYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Waste Code: U110
Waste Description: 1-PROPANIMINE, N-PROPYL-(I) (OR) DIPROPYLAMINE (I)

Waste Code: U111
Waste Description: 1-PROPANAMINE, N-NITROSO-N-PROPYL- (OR) DI-N-PROPYLNITROSAMINE

Waste Code: U112
Waste Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U113
Waste Description: 2-PROPENOIC ACID, ETHYL ESTER (I) (OR) ETHYL ACRYLATE (I)

Waste Code: U114
Waste Description: CARBAMODITHIOIC ACID, 1,2-ETHANEDIYLBIS-, SALTS & ESTERS (OR) ETHYLENEBISDITHIOCARBAMIC ACID, SALTS & ESTERS

Waste Code: U115
Waste Description: ETHYLENE OXIDE (I,T) (OR) OXIRANE (I,T)

Waste Code: U116
Waste Description: 2-IMIDAZOLIDINETHIONE (OR) ETHYLENETHIOUREA

Waste Code: U117
Waste Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Waste Code: U118
Waste Description: 2-PROPENOIC ACID, 2-METHYL-, ETHYL ESTER (OR) ETHYL METHACRYLATE

Waste Code: U119
Waste Description: ETHYL METHANESULFONATE (OR) METHANESULFONIC ACID, ETHYL ESTER

Waste Code: U120
Waste Description: FLUORANTHENE

Waste Code: U121
Waste Description: METHANE, TRICHLOROFLUORO- (OR) TRICHLOROMONOFLUOROMETHANE

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U123
Waste Description: FORMIC ACID (C,T)

Waste Code: U124
Waste Description: FURAN (I) (OR) FURFURAN (I)

Waste Code: U125
Waste Description: 2-FURANCARBOXALDEHYDE (I) (OR) FURFURAL (I)

Waste Code: U126
Waste Description: GLYCIDYLALDEHYDE (OR) OXIRANECARBOXYALDEHYDE

Waste Code: U127
Waste Description: BENZENE, HEXACHLORO- (OR) HEXACHLOROBENZENE

Waste Code: U128
Waste Description: 1,3-BUTADIENE, 1,1,2,3,4,4-HEXACHLORO- (OR) HEXACHLOROBUTADIENE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U130
Waste Description: 1,3-CYCLOPENTADIENE, 1,2,3,4,5,5-HEXACHLORO- (OR) HEXACHLOROCYCLOPENTADIENE

Waste Code: U131
Waste Description: ETHANE, HEXACHLORO- (OR) HEXACHLOROETHANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U133
Waste Description: HYDRAZINE (R,T)

Waste Code: U134
Waste Description: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

Waste Code: U135
Waste Description: HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S

Waste Code: U136
Waste Description: ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID

Waste Code: U137
Waste Description: INDENO[1,2,3-CD]PYRENE

Waste Code: U138
Waste Description: METHANE, IODO- (OR) METHYL IODIDE

Waste Code: U140
Waste Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Waste Code: U141

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: 1,3-BENZODIOXOLE, 5-(1-PROPENYL)- (OR) ISOSAFROLE

Waste Code: U142
Waste Description: 1,3,4-METHENO-2H-CYCLOBUTA[CD]PENTALEN-2-ONE, 1,1A,3,3A,4,5,5,5A,5B,6-DECACHLOROOCTAHYDRO- (OR) KEPONE

Waste Code: U143
Waste Description: 2-BUTENOIC ACID, 2-METHYL-, 7-[[2,3-DIHYDROXY-2-(1-METHOXYETHYL)-3-METHYL-1-OXOBUTOXY]METHYL]-2,3,5,7A-TETRAHYDRO-1H-PYRROLIZIN-1-YL ESTER, [1S-[1ALPHA(Z), 7(2S*,3R*), 7AALPHA]]- (OR) LASIOCARPINE

Waste Code: U144
Waste Description: ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE

Waste Code: U145
Waste Description: LEAD PHOSPHATE (OR) PHOSPHORIC ACID, LEAD(2+) SALT (2:3)

Waste Code: U146
Waste Description: LEAD SUBACETATE (OR) LEAD, BIS(ACETATO-O)TETRAHYDROXYTRI-

Waste Code: U147
Waste Description: 2,5-FURANDIONE (OR) MALEIC ANHYDRIDE

Waste Code: U148
Waste Description: 3,6-PYRIDAZINEDIONE, 1,2-DIHYDRO- (OR) MALEIC HYDRAZIDE

Waste Code: U149
Waste Description: MALONONITRILE (OR) PROPANEDINITRILE

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

Waste Code: U152
Waste Description: 2-PROPENENITRILE, 2-METHYL- (I,T) (OR) METHACRYLONITRILE (I,T)

Waste Code: U153
Waste Description: METHANETHIOL (I,T) (OR) THIOMETHANOL (I,T)

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U155
Waste Description: 1,2-ETHANEDIAMINE, N,N-DIMETHYL-N'-2-PYRIDINYL-N'-(2-THIENYLMETHYL)- (OR) METHAPYRILENE

Waste Code: U156
Waste Description: CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)

Waste Code: U157
Waste Description: 3-METHYLCHOLANTHRENE (OR) BENZ[J]ACEANTHRYLENE, 1,2-DIHYDRO-3-METHYL-

Waste Code: U158

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: 4,4'-METHYLENEBIS(2-CHLOROANILINE) (OR) BENZENAMINE, 4,4'-METHYLENEBIS[2-CHLORO-

Waste Code: U159
Waste Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U160
Waste Description: 2-BUTANONE, PEROXIDE (R,T) (OR) METHYL ETHYL KETONE PEROXIDE (R,T)

Waste Code: U161
Waste Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U162
Waste Description: 2-PROPENOIC ACID, 2-METHYL-, METHYL ESTER (I,T) (OR) METHYL METHACRYLATE (I,T)

Waste Code: U163
Waste Description: GUANIDINE, N-METHYL-N'-NITRO-N-NITROSO- (OR) MNNG

Waste Code: U164
Waste Description: 4(1H)-PYRIMIDINONE, 2,3-DIHYDRO-6-METHYL-2-THIOXO- (OR) METHYLTHIOURACIL

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U166
Waste Description: 1,4-NAPHTHALENEDIONE (OR) 1,4-NAPHTHOQUINONE

Waste Code: U167
Waste Description: 1-NAPTHALENAMINE (OR) ALPHA-NAPHTHYLAMINE

Waste Code: U168
Waste Description: 2-NAPTHALENAMINE (OR) BETA-NAPHTHYLAMINE

Waste Code: U169
Waste Description: BENZENE, NITRO- (OR) NITROBENZENE (I,T)

Waste Code: U170
Waste Description: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

Waste Code: U171
Waste Description: 2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)

Waste Code: U172
Waste Description: 1-BUTANAMINE, N-BUTYL-N-NITROSO- (OR) N-NITROSODI-N-BUTYLAMINE

Waste Code: U173
Waste Description: ETHANOL, 2,2'-(NITROSOIMINO)BIS- (OR) N-NITROSODIETHANOLAMINE

Waste Code: U174
Waste Description: ETHANAMINE, N-ETHYL-N-NITROSO- (OR) N-NITROSODIETHYLAMINE

Waste Code: U176
Waste Description: N-NITROSO-N-ETHYLUREA (OR) UREA, N-ETHYL-N-NITROSO-

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U177
Waste Description: N-NITROSO-N-METHYLUREA (OR) UREA, N-METHYL-N-NITROSO-

Waste Code: U178
Waste Description: CARBAMIC ACID, METHYLNITROSO-, ETHYL ESTER (OR) N-NITROSO-N-METHYLURETHANE

Waste Code: U179
Waste Description: N-NITROSOPIPERIDINE (OR) PIPERIDINE, 1-NITROSO-

Waste Code: U180
Waste Description: N-NITROSOPYRROLIDINE (OR) PYRROLIDINE, 1-NITROSO-

Waste Code: U181
Waste Description: 5-NITRO-O-TOLUIDINE (OR) BENZENAMINE, 2-METHYL-5-NITRO

Waste Code: U182
Waste Description: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

Waste Code: U183
Waste Description: BENZENE, PENTACHLORO- (OR) PENTACHLOROBENZENE

Waste Code: U184
Waste Description: ETHANE, PENTACHLORO- (OR) PENTACHLOROETHANE

Waste Code: U185
Waste Description: BENZENE, PENTACHLORONITRO- (OR) PENTACHLORONITROBENZENE (PCNB)

Waste Code: U186
Waste Description: 1,3-PENTADIENE (I) (OR) 1-METHYLBUTADIENE (I)

Waste Code: U187
Waste Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Waste Code: U188
Waste Description: PHENOL

Waste Code: U189
Waste Description: PHOSPHORUS SULFIDE (R) (OR) SULFUR PHOSPHIDE (R)

Waste Code: U190
Waste Description: 1,3-ISOBENZOFURANDIONE (OR) PHTHALIC ANHYDRIDE

Waste Code: U191
Waste Description: 2-PICOLINE (OR) PYRIDINE, 2-METHYL-

Waste Code: U192
Waste Description: BENZAMIDE, 3,5-DICHLORO-N-(1,1-DIMETHYL-2-PROPYNYL)- (OR) PRONAMIDE

Waste Code: U193
Waste Description: 1,2-OXATHIOLANE, 2,2-DIOXIDE (OR) 1,3-PROPANE SULTONE

Waste Code: U194
Waste Description: 1-PROPANAMINE (I,T) (OR) N-PROPYLAMINE (I,T)

Waste Code: U196
Waste Description: PYRIDINE

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U197
Waste Description: 2,5-CYCLOHEXADIENE-1,4-DIONE (OR) P-BENZOQUINONE

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U203
Waste Description: 1,3-BENZODIOXOLE, 5-(2-PROPENYL)- (OR) SAFROLE

Waste Code: U204
Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U206
Waste Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Waste Code: U207
Waste Description: 1,2,4,5-TETRACHLOROBENZENE (OR) BENZENE, 1,2,4,5-TETRACHLORO-

Waste Code: U208
Waste Description: 1,1,1,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,1,2-TETRACHLORO-

Waste Code: U209
Waste Description: 1,1,2,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,2,2-TETRACHLORO-

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Waste Code: U211
Waste Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Waste Code: U213
Waste Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Waste Code: U214
Waste Description: ACETIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) ACETATE

Waste Code: U215
Waste Description: CARBONIC ACID, DITHALLIUM(1+) SALT (OR) THALLIUM(I) CARBONATE

Waste Code: U216
Waste Description: THALLIUM CHLORIDE TLCL (OR) THALLIUM(I) CHLORIDE

Waste Code: U217
Waste Description: NITRIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) NITRATE

Waste Code: U218
Waste Description: ETHANETHIOAMIDE (OR) THIOACETAMIDE

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Code: U219
Waste Description: THIOUREA

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U221
Waste Description: BENZENEDIAMINE, AR-METHYL- (OR) TOLUENEDIAMINE

Waste Code: U222
Waste Description: BENZENAMINE, 2-METHYL-, HYDROCHLORIDE (OR) O-TOLUIDINE HYDROCHLORIDE

Waste Code: U223
Waste Description: BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T) (OR) TOLUENE DIISOCYANATE (R,T)

Waste Code: U225
Waste Description: BROMOFORM (OR) METHANE, TRIBROMO-

Waste Code: U226
Waste Description: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Waste Code: U227
Waste Description: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

Waste Code: U228
Waste Description: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Waste Code: U234
Waste Description: 1,3,5-TRINITROBENZENE (R,T) (OR) BENZENE, 1,3,5-TRINITRO-

Waste Code: U235
Waste Description: 1-PROPANOL, 2,3-DIBROMO-, PHOSPHATE (3:1) (OR) TRIS(2,3,-DIBROMOPROPYL) PHOSPHATE

Waste Code: U236
Waste Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO -4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Waste Code: U237
Waste Description: 2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]- (OR) URACIL MUSTARD

Waste Code: U238
Waste Description: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

Waste Code: U239
Waste Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Waste Code: U240
Waste Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Waste Code: U243
Waste Description: 1-PROPENE, 1,1,2,3,3,3-HEXACHLORO- (OR) HEXACHLOROPROPENE

Waste Code: U244

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Waste Description: THIOPEROXYDICARBONIC DIAMIDE [(H2N)C(S)]2S2, TETRAMETHYL- (OR) THIRAM

Waste Code: U246
Waste Description: CYANOGEN BROMIDE (CN)BR

Waste Code: U247
Waste Description: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-METHOXY- (OR) METHOXYCHLOR

Waste Code: U248
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Waste Code: U249
Waste Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

Waste Code: U271
Waste Description: BENOMYL (OR) CARBAMIC ACID, [1-[(BUTYLAMINO)CARBONYL]-1H-BENZIMIDAZOL-2-YL]-, METHYL ESTER

Waste Code: U278
Waste Description: BENDIOCARB (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-, METHYL CARBAMATE

Waste Code: U279
Waste Description: U279

Waste Code: U280
Waste Description: BARBAN (OR) CARBAMIC ACID, (3-CHLOROPHENYL)-, 4-CHLORO-2-BUTYNYL ESTER

Waste Code: U328
Waste Description: BENZENAMINE, 2-METHYL- (OR) O-TOLUIDINE

Waste Code: U353
Waste Description: BENZENAMINE, 4-METHYL- (OR) P-TOLUIDINE

Waste Code: U359
Waste Description: ETHANOL, 2-ETHOXY- (OR) ETHYLENE GLYCOL MONOETHYL ETHER

Waste Code: U364
Waste Description: BENDIOCARB PHENOL (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-

Waste Code: U367
Waste Description: 7-BENZOFURANOL, 2,3-DIHYDRO-2,2-DIMETHYL- (OR) CARBOFURAN PHENOL

Waste Code: U372
Waste Description: CARBAMIC ACID, 1H-BENZIMIDAZOL-2-YL, METHYL ESTER (OR) CARBENDAZIM

Waste Code: U373
Waste Description: CARBAMIC ACID, PHENYL-, 1-METHYLETHYL ESTER (OR) PROPHAM

Waste Code: U378
Waste Description: CARBAMODITHIOIC ACID, (HYDROXYMETHYL) METHYL-, MONOPOTASSIUM SALT (OR) POTASSIUM N-HYDROXYMETHYL- N-METHYLDI-THIOCARBAMATE

Waste Code: U387
Waste Description: CARBAMOTHIOIC ACID, DIPROPYL-, S-(PHENYLMETHYL) ESTER (OR)

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

PROSULFOCARB

Waste Code: U389
Waste Description: CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3,3-TRICHLORO-2-PROPENYL) ESTER (OR) TRIALLATE

Waste Code: U394
Waste Description: A2213 (OR) ETHANIMIDOTHIOIC ACID, 2-(DIMETHYLAMINO)-N-HYDROXY-2-OXO-, METHYL ESTER

Waste Code: U395
Waste Description: DIETHYLENE GLYCOL, DICARBAMATE (OR) ETHANOL, 2,2'-OXYBIS-, DICARBAMATE

Waste Code: U404
Waste Description: U404

Waste Code: U409
Waste Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Waste Code: U410
Waste Description: ETHANIMIDOTHIOIC ACID, N,N'-[THIOBIS[(METHYLIMINO)CARBONYLOXY]]BIS-, DIMETHYL ESTER (OR) THIODICARB

Waste Code: U411
Waste Description: U411

Waste Code: U480
Waste Description: 2,4,6, TRIBROMPHENOL (I.E.; DISCARDED COMMERCIAL CHEMICAL PRODUCTS, OFF-SPECIFICATION SPECIES, CONTAINER RESIDUES, AND SPILL RESIDUES THEREOF)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: PACIFIC BELL AT&T OF CA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1670 CACTUS ROAD
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PACIFIC BELL AT&T OF CA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1670 CACTUS ROAD
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

PACIFIC BELL DBA AT&T OF CA (Continued) **1024877085**

Historic Generators:
- Receive Date: 20180702
- Handler Name: PACIFIC BELL DBA AT&T OF CA
- Federal Waste Generator Description: Large Quantity Generator
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: No
- Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
- NAICS Code: 517311
- NAICS Description: WIRED TELECOMMUNICATIONS CARRIERS

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

15
NW
1/8-1/4
0.148 mi.
780 ft.

ASSOCIATED READY MIXED CONCRETE **PFAS ECHO** **1027327468** **N/A**

SAN DIEGO, CA

Relative:
Lower

Actual:
504 ft.

PFAS ECHO:
- Name: ASSOCIATED READY MIXED CONCRETE
- Address: Not reported
- City,State,Zip: SAN DIEGO, CA
- Latitude: 32.56573
- Longitude: -116.99025
- Count: 1
- County: SAN DIEGO
- Status: Inactive
- Region: 09
- Industry: Cement Mfg
- ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110055756711
- Facility Percent Minority: 89.082
- Facility Derived Tribes: Jamul Indian Village of California - 11.6 mile(s), Sycuan Band of the Kumeyaay Nation - 15.4 mile(s), Sycuan Band of the Kumeyaay Nation - 16.7 mile(s), Ewiiaapaayp Band of Kumeyaay Indians, California - 24.1 mile(s), Capitan Grande Band of Diegueno Missi
- Facility Population: 734.75
- EPA Programs: CWA
- Federal Facility: No
- Federal Agency: -
- Facility FIPS Code: 06073
- Facility Indian Country Flag: N
- Facility Collection Method: ADDRESS MATCHING-HOUSE NUMBER
- Facility Derived HUC: 18070305

ASSOCIATED READY MIXED CONCRETE (Continued) **1027327468**

Facility Derived WBD:	180703050602
Facility Derived CD113:	51
Facility Derived CB2010:	060730100151028
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	Y
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	CAZ218851
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	3273
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	9215WSSCTD1696C
TRI Releases Transfers:	23
TRI On Site Releases:	0
TRI Off Site Transfers:	23
TRI Reporter:	Y
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-116.99025,%22y%22:32.56573,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

D16 **T K OF SAN DIEGO** **RCRA-SQG** **1000473139**
NNW **6975 CAMINO MAQUILLADORA** **FINDS** **CAD982460347**
1/8-1/4 **SAN DIEGO, CA 92173** **ECHO**
0.173 mi. **HAZNET**
915 ft. **Site 1 of 13 in cluster D** **HWTS**

Relative: **Lower**
Actual: **507 ft.**

RCRA Listings:

Date Form Received by Agency:	19960901
Handler Name:	T K Of San Diego
Handler Address:	6975 CAMINO MAQUILLADORA
Handler City,State,Zip:	SAN DIEGO, CA 92173
EPA ID:	CAD982460347
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	4
Mailing Address:	6975 CAMINO MAQUILLADORA
Mailing City,State,Zip:	SAN DIEGO, CA 92173
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not Required
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

T K OF SAN DIEGO (Continued) **1000473139**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20020917
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: HAMMAN INVESTMENT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NOT REQUIRED	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19960901
Handler Name: T K OF SAN DIEGO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

T K OF SAN DIEGO (Continued) **1000473139**

Receive Date:	19901023
Handler Name: T K OF SAN DIEGO	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19930211
Actual Return to Compliance Date:	19940426
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number: Not reported	
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type: Not reported	
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number: Not reported	
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes

T K OF SAN DIEGO (Continued) **1000473139**

Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19920204
Actual Return to Compliance Date: 19930211
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19940426
Actual Return to Compliance Date: 19990426
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported

T K OF SAN DIEGO (Continued) **1000473139**

Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19930211
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19940426
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19920204
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19930211
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19940426
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19990426
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

T K OF SAN DIEGO (Continued) **1000473139**

FINDS:
Registry ID: 110008278185

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000473139
Registry ID:	110008278185
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008278185
Name:	T K OF SAN DIEGO
Address:	6975 CAMINO MAQUILLADORA
City,State,Zip:	SAN DIEGO, CA 92173

HAZNET:

Name:	T K OF SAN DIEGO
Address:	6975 CAMINO MAQUILLADORA
Address 2:	Not reported
City,State,Zip:	SAN DIEGO, CA 920730000
Contact:	BILL FORTNER
Telephone:	6196611600
Mailing Name:	Not reported
Mailing Address:	6975 CAMINO MAQUILADORA
Year:	1999
Gepaid:	CAD982460347
TSD EPA ID:	CAD008252405
CA Waste Code:	343 - Unspecified organic liquid mixture
Disposal Method:	R01 - Recycler
Tons:	0.187
Year:	1999
Gepaid:	CAD982460347
TSD EPA ID:	CAT080033681
CA Waste Code:	352 - Other organic solids
Disposal Method:	R01 - Recycler
Tons:	0.1
Year:	1999
Gepaid:	CAD982460347
TSD EPA ID:	CAT080033681
CA Waste Code:	343 - Unspecified organic liquid mixture
Disposal Method:	R01 - Recycler
Tons:	0.187
Year:	1998
Gepaid:	CAD982460347

T K OF SAN DIEGO (Continued) **1000473139**

TSD EPA ID: CAT080013352
CA Waste Code: 222 - Oil/water separation sludge
Disposal Method: R01 - Recycler
Tons: 1.251

Year: 1998
Gepaid: CAD982460347
TSD EPA ID: CAD008252405
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: R01 - Recycler
Tons: 0.187

Year: 1998
Gepaid: CAD982460347
TSD EPA ID: CAT080033681
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: R01 - Recycler
Tons: 0.1

Year: 1998
Gepaid: CAD982460347
TSD EPA ID: CAT080013352
CA Waste Code: 133 - Aqueous solution with total organic residues 10 percent or more
Disposal Method: R01 - Recycler
Tons: 0.2293

Year: 1997
Gepaid: CAD982460347
TSD EPA ID: CAT080033681
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: R01 - Recycler
Tons: 0.374

Year: 1997
Gepaid: CAD982460347
TSD EPA ID: CAD008252405
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: R01 - Recycler
Tons: 0.748

Year: 1996
Gepaid: CAD982460347
TSD EPA ID: CAT080013352
CA Waste Code: 135 - Unspecified aqueous solution
Disposal Method: R01 - Recycler
Tons: 0.42

Click this hyperlink while viewing on your computer to access
10 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:
Year: 1999
Gen EPA ID: CAD982460347

Shipment Date: 19990212
Creation Date: 5/4/1999 0:00:00

T K OF SAN DIEGO (Continued) **1000473139**

Receipt Date:	19990224
Manifest ID:	98850916
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080033681
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT080033681
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.187
Waste Quantity:	55
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19990212
Creation Date:	5/4/1999 0:00:00
Receipt Date:	19990224
Manifest ID:	98850916
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080033681
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT080033681
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.1
Waste Quantity:	200
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19990122
Creation Date:	4/20/1999 0:00:00
Receipt Date:	19990204
Manifest ID:	98850863
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD008252405

T K OF SAN DIEGO (Continued) **1000473139**

TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.187
Waste Quantity:	55
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1998
Gen EPA ID:	CAD982460347
Shipment Date:	19981210
Creation Date:	2/8/1999 0:00:00
Receipt Date:	19981214
Manifest ID:	98513395
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	133 - Aqueous solution with 10% or more total organic residues
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.2293
Waste Quantity:	55
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19981002
Creation Date:	12/7/1998 0:00:00
Receipt Date:	19981002
Manifest ID:	98164907
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT080013352
TSDF Alt Name:	Not reported
Waste Code Description:	222 - Oil/water separation sludge
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	1.251

T K OF SAN DIEGO (Continued) **1000473139**

Waste Quantity:	300
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19980706
Creation Date:	9/22/1998 0:00:00
Receipt Date:	19980714
Manifest ID:	98165224
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD008252405
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.187
Waste Quantity:	55
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19980615
Creation Date:	9/3/1998 0:00:00
Receipt Date:	19980623
Manifest ID:	98163602
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080033681
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.1
Waste Quantity:	200
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

T K OF SAN DIEGO (Continued) **1000473139**

Additional Info:

Year:	1997
Gen EPA ID:	CAD982460347
Shipment Date:	19971118
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19971126
Manifest ID:	96827975
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080033681
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT080033681
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.374
Waste Quantity:	110
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19971118
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19971201
Manifest ID:	96831974
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD008252405
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.374
Waste Quantity:	110
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970121
Creation Date:	6/26/1997 0:00:00
Receipt Date:	19970203
Manifest ID:	96784917
Trans EPA ID:	CAL000827847

T K OF SAN DIEGO (Continued) **1000473139**

Trans Name:	Not reported
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD008252405
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.374
Waste Quantity:	110
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1996
Gen EPA ID:	CAD982460347
Shipment Date:	19960301
Creation Date:	10/4/1996 0:00:00
Receipt Date:	19960304
Manifest ID:	95489080
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT080013352
TSDF Alt Name:	Not reported
Waste Code Description:	135 - Unspecified aqueous solution
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.42
Waste Quantity:	100
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1995
Gen EPA ID:	CAD982460347
Shipment Date:	19950331
Creation Date:	10/23/1995 0:00:00
Receipt Date:	19950403
Manifest ID:	95251774
Trans EPA ID:	CAD028277036

T K OF SAN DIEGO (Continued) **1000473139**

Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	135 - Unspecified aqueous solution
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.21
Waste Quantity:	50
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1994
Gen EPA ID:	CAD982460347
Shipment Date:	19940901
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940901
Manifest ID:	93494003
Trans EPA ID:	CAD076548636
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080033681
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT080033681
TSDF Alt Name:	Not reported
Waste Code Description:	611 - Contaminated soil from site clean-ups
RCRA Code:	Not reported
Meth Code:	D99 - Disposal, Other
Quantity Tons:	2.77
Waste Quantity:	5540
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940901
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940901
Manifest ID:	93494003
Trans EPA ID:	CAD076548636
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080033681
Trans Name:	Not reported

T K OF SAN DIEGO (Continued) **1000473139**

TSDF Alt EPA ID:	CAT080033681
TSDF Alt Name:	Not reported
Waste Code Description:	223 - Unspecified oil-containing waste
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	4.17
Waste Quantity:	1000
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940816
Creation Date:	10/17/1995 0:00:00
Receipt Date:	19940816
Manifest ID:	93020481
Trans EPA ID:	CAD980812978
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080011059
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	3.78
Waste Quantity:	900
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940509
Creation Date:	10/10/1995 0:00:00
Receipt Date:	19940518
Manifest ID:	93322195
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080031628
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	221 - Waste oil and mixed oil
RCRA Code:	Not reported
Meth Code:	- Not reported
Quantity Tons:	0.2622
Waste Quantity:	69
Quantity Unit:	G
Additional Code 1:	Not reported

T K OF SAN DIEGO (Continued) **1000473139**

Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940509
Creation Date:	10/10/1995 0:00:00
Receipt Date:	19940518
Manifest ID:	93322195
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080031628
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	- Not reported
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0
Waste Quantity:	0
Quantity Unit:	Not reported
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940325
Creation Date:	10/5/1995 0:00:00
Receipt Date:	19940329
Manifest ID:	92085589
Trans EPA ID:	CAD981965734
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	221 - Waste oil and mixed oil
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	4.94
Waste Quantity:	1300
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940203
Creation Date:	9/15/1995 0:00:00
Receipt Date:	19940216
Manifest ID:	92085537

T K OF SAN DIEGO (Continued) **1000473139**

Trans EPA ID:	CAD981965734
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	222 - Oil/water separation sludge
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	1.251
Waste Quantity:	300
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	T K OF SAN DIEGO
Address:	6975 CAMINO MAQUILLADORA
Address 2:	Not reported
City,State,Zip:	SAN DIEGO, CA 92073
EPA ID:	CAD982460347
Inactive Date:	06/30/1999
Create Date:	10/23/1990
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	6975 CAMINO MAQUILADORA
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SAN YSIDRO, CA 921733504
Owner Name:	CUMMINS CAL PACIFIC
Owner Address:	1939 DEERE AVE
Owner Address 2:	Not reported
Owner City,State,Zip:	IRVINE, CA 926060000
Contact Name:	BILL FORTNER
Contact Address:	INACTIVE PER VQ99 - BMI
Contact Address 2:	Not reported
City,State,Zip:	SAN DIEGO, CA 921730000
Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	FEDERAL
Latitude:	32.567017
Longitude:	-116.990222

D17 **BORDER RECAPPING LLC DBA BORDER TIRE** **RCRA NonGen / NLR** **1027093289**
NNW **6975 CAMINO MAQUILADORA** **CAL000466847**
1/8-1/4 **SAN DIEGO, CA 92154**
0.173 mi.
915 ft. **Site 2 of 13 in cluster D**

Relative: **Lower**

Actual: **507 ft.**

RCRA Listings:

Date Form Received by Agency:	20211117
Handler Name:	Border Recapping Llc Dba Border Tire
Handler Address:	6975 CAMINO MAQUILADORA

BORDER RECAPPING LLC DBA BORDER TIRE (Continued) **1027093289**

Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAL000466847
Contact Name:	MARIO HERNANDEZ
Contact Address:	6975 CAMINO MAQUILADORA
Contact City,State,Zip:	SAN DIEGO, CA 92154
Contact Telephone:	619-671-0570
Contact Fax:	Not reported
Contact Email:	MARIO.HERNANDEZ@BORDER-TIRE.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	2701 W AMADOR AVE
Mailing City,State,Zip:	LAS CRUCES, NM 88005
Owner Name:	Border Recapping Llc
Owner Type:	Other
Operator Name:	Mario Hernandez
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211122

BORDER RECAPPING LLC DBA BORDER TIRE (Continued) **1027093289**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MARIO HERNANDEZ	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6975 CAMINO MAQUILADORA
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-671-0570
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: BORDER RECAPPING LLC	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3590 W PICACHO AVE
Owner/Operator City,State,Zip:	LAS CRUCES, NM 88007
Owner/Operator Telephone:	575-636-3355
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20211117
Handler Name:	BORDER RECAPPING LLC DBA BORDER TIRE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	452319
NAICS Description:	ALL OTHER GENERAL MERCHANDISE STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

BORDER RECAPPING LLC DBA BORDER TIRE (Continued) **1027093289**

Evaluation Action Summary:
Evaluations: No Evaluations Found

D18 NNW 1/8-1/4 0.173 mi. 915 ft. **BORDER TIRE #15** **CERS HAZ WASTE S127392499**
6975 CAMINO MAQUILADORA **CERS N/A**
SAN DIEGO, CA 92154

Site 3 of 13 in cluster D

Relative: Lower

Actual: 507 ft.

CERS HAZ WASTE:
Name: BORDER TIRE #15
Address: 6975 CAMINO MAQUILADORA
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 593997
CERS ID: 10395226
CERS Description: Hazardous Waste Generator

CERS:
Name: BORDER TIRE #15
Address: 6975 CAMINO MAQUILADORA
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 593997
CERS ID: 10395226
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 593997
Site Name: Border Tire #15
Violation Date: 05-18-2015
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes: Returned to compliance on 05/18/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 593997
Site Name: Border Tire #15
Violation Date: 05-18-2015
Citation: 19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.
Violation Notes: Returned to compliance on 05/18/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 593997
Site Name: Border Tire #15
Violation Date: 05-18-2015
Citation: HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Description: Failure to electronically update business plan within 30 days of any

BORDER TIRE #15 (Continued) **S127392499**

	one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name.
Violation Notes:	Returned to compliance on 05/18/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	593997
Site Name:	Border Tire #15
Violation Date:	10-29-2021
Citation:	22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description:	Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes:	Returned to compliance on 11/16/2021. Inspection Sequence ID:6815989
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	593997
Site Name:	Border Tire #15
Violation Date:	07-31-2019
Citation:	40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description:	Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes:	Returned to compliance on 08/21/2019. Inspection Sequence ID:6139395
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	593997
Site Name:	Border Tire #15
Violation Date:	10-29-2021
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 11/16/2021. Inspection Sequence ID:6815989;Violation:HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	593997
Site Name:	Border Tire #15
Violation Date:	05-18-2015
Citation:	HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95,

BORDER TIRE #15 (Continued) **S127392499**

Section(s) 25508(d)
Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes: Returned to compliance on 05/18/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-31-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6139395
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-29-2021
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6815989
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-18-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Eivaz Chantal Inspection ID:4099147
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-03-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5663531
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-03-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5663531
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-18-2015

BORDER TIRE #15 (Continued) **S127392499**

Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Eivaz Chantal Inspection ID:4099147
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-31-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6139395
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-29-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6815989
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Affiliation:
Affiliation Type Desc: Legal Owner
Entity Name: Border Recapping, LLC, dba Border Tire
Entity Title: Not reported
Affiliation Address: 2701 W Amador Ave
Affiliation City: Las Cruces
Affiliation State: NM
Affiliation Country: United States
Affiliation Zip: 88005
Affiliation Phone: (575) 541-4259,

Affiliation Type Desc: Operator
Entity Name: Border Tire #15
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 671-0570,

Affiliation Type Desc: Parent Corporation
Entity Name: Border Recapping, LLC, dba Border Tire
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: CUPA District

BORDER TIRE #15 (Continued) **S127392499**

Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,
Affiliation Type Desc:	Document Preparer
Entity Name:	Ron Dennis
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Environmental Contact
Entity Name:	Bob Barron
Entity Title:	Not reported
Affiliation Address:	7801 E. Rosecrans Ave.
Affiliation City:	Paramount
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90723
Affiliation Phone:	,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	6975 Camino Maquiladora
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92154
Affiliation Phone:	,
Affiliation Type Desc:	Identification Signer
Entity Name:	Ron Dennis
Entity Title:	Environmental Compliance Specialist
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Property Owner
Entity Name:	Hickson Otay LLC (Rob Hickson)
Entity Title:	Not reported
Affiliation Address:	6652 Aranda Avenue
Affiliation City:	La Jolla
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92037

BORDER TIRE #15 (Continued) **S127392499**

Affiliation Phone: (619) 696-8350,

D19 **PINNACLE INDUSTRIAL SUPPLY INC** **RCRA NonGen / NLR** **1024826892**
NNW **6975 CAMINO MAQUILADORA** **CAL000355386**
1/8-1/4 **SAN DIEGO, CA 92154**
0.173 mi.
915 ft. **Site 4 of 13 in cluster D**

Relative: **Lower**

Actual: **507 ft.**

RCRA Listings:

Date Form Received by Agency:	20210825
Handler Name:	Pinnacle Industrial Supply Inc
Handler Address:	6975 CAMINO MAQUILADORA
Handler City,State,Zip:	SAN DIEGO, CA 92154-7504
EPA ID:	CAL000355386
Contact Name:	BRIAN CHIN
Contact Address:	PACIFIC RIM CT
Contact City,State,Zip:	SAN DIEGO, CA 92154
Contact Telephone:	619-710-4255
Contact Fax:	Not reported
Contact Email:	BCHIN@PINNACLECA.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Other
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PACIFIC RIM CT
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Pinnacle Industrial Supply
Owner Type:	Other
Operator Name:	Pinnacle Industrial Supply
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

PINNACLE INDUSTRIAL SUPPLY INC (Continued) **1024826892**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210915
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PINNACLE INDUSTRIAL SUPPLY	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6975 CAMINO MAQUILADORA
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154-7504
Owner/Operator Telephone:	619-710-4255
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: BRIAN CHIN	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6975 CAMINO MAQUILADORA
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-710-4255
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PINNACLE INDUSTRIAL SUPPLY	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1612 PACIFIC RIM CT
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-710-4255
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

PINNACLE INDUSTRIAL SUPPLY INC (Continued) **1024826892**

Owner/Operator Indicator: Operator
Owner/Operator Name: PINNACLE INDUSTRIAL SUPPLY
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1612 PACIFIC RIM CT
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-710-4255
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20210825
Handler Name: PINNACLE INDUSTRIAL SUPPLY INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20100803
Handler Name: PINNACLE INDUSTRIAL SUPPLY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 42184
NAICS Description: INDUSTRIAL SUPPLIES WHOLESALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E20
SSW
1/8-1/4
0.178 mi.
942 ft.

ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO
2175 CACTUS RD
SAN DIEGO, CA 92154

RCRA NonGen / NLR

1024824240
CAL000346874

Site 1 of 4 in cluster E

Relative:
Higher

Actual:
510 ft.

RCRA Listings:

Date Form Received by Agency:	20090930
Handler Name:	Adesa California Llc Dba Adesa San Diego
Handler Address:	2175 CACTUS RD
Handler City,State,Zip:	SAN DIEGO, CA 92154-8002
EPA ID:	CAL000346874
Contact Name:	JAMES WALKER
Contact Address:	13085 HAMILTON CROSSING BLVD
Contact City,State,Zip:	CARMEL, IN 46032
Contact Telephone:	317-843-4739
Contact Fax:	Not reported
Contact Email:	JAMES.WALKER@KARAUCTIONSERVICES.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	13085 HAMILTON CROSSING BLVD
Mailing City,State,Zip:	CARMEL, IN 46032-0000
Owner Name:	Adesa Californa Llc
Owner Type:	Other
Operator Name:	James Walker
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO (Continued) **1024824240**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JAMES WALKER	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	13085 HAMILTON CROSSING BLVD
Owner/Operator City,State,Zip:	CARMEL, IN 46032
Owner/Operator Telephone:	317-843-4739
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ADESA CALIFORINA LLC	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	13085 HAMILTON CROSSING BLVD
Owner/Operator City,State,Zip:	CARMEL, IN 46032-0000
Owner/Operator Telephone:	800-923-3725
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20090930
Handler Name:	ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

ADESA CALIFORNIA LLC DBA ADESA SAN DIEGO (Continued) **1024824240**

List of NAICS Codes and Descriptions:
NAICS Code: 44111
NAICS Description: NEW CAR DEALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E21 **ADESA SAN DIEGO** **San Diego Co. HMMD** **S123406707**
SSW **2175 CACTUS RD** **CERS HAZ WASTE** **N/A**
1/8-1/4 **SAN DIEGO, CA 46032** **HAZNET**
0.178 mi. **CERS**
942 ft. **Site 2 of 4 in cluster E**

Relative: Higher

Actual: 510 ft.

HMMD SAN DIEGO:
Name: ADESA SAN DIEGO
Address: 2175 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Permit Number: 129754
Business Type: 6HK26
EPA Id Number: CAL000218880
APN: 667-050-62-00
Last HMMD Inspection: 05/29/2012
Facility Telephone: 619-661-5565
Permit Status: OPEN
Permit Expiration: 08/31/2013
Date Last Updated: 11/02/2012
Facility Owner: ADESA CALIFORNIA INC
Facility Mailing Address: 2175 CACTUS RD
Facility Mailing City: SAN DIEGO
Facility Mailing State: CA
Facility Mailing Zip: 92154
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: AUCTION WHEEL CLEANER
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: BRITE SPOT

ADESA SAN DIEGO (Continued) **S123406707**

Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: GALAXY
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: MIXTURE
Name: HYDROFLUORIC ACID, SULFURIC ACID, 2 BUTOXY ETHANOL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: KLEAR GLASS CLEANER
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: OK CAR SOAP
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: 68476-85-7
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 132 AQUEOUS SOL'N WITH METALS
Other Information: SUMP WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported

ADESA SAN DIEGO (Continued) **S123406707**

Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: AES. ALSO HAULS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information: OILY ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: JULIO-C-BATTERIES
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 129754
Update Date: 11/02/2012
Inspection Date: 09/13/2005
Violation Code: 6HV1006
Violation: HMBP: INVENTORY INADEQUATE
Violation Citation: Business Plan inventory does not list all hazardous materials on site in disclosable quantities. HSC 25504(a),25503.5
Activity: ACTIVE

ADESA SAN DIEGO (Continued) **S123406707**

Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	09/13/2005
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	09/13/2005
Violation Code:	6HV1011
Violation:	TRAINING RECORDS NOT AVAILABLE
Violation Citation:	Personnel training records not available. 19 CCR 2732
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	05/29/2012
Violation Code:	6HV1004
Violation:	HMBP NOT SUBMITTED TO HMD
Violation Citation:	Hazardous Materials Handler has not submitted a completed Business Plan to the HMMD. HSC 25505(a)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	05/29/2012
Violation Code:	6HV0224
Violation:	MISMANAGED EMPTY CONTAINERS >5GALS.
Violation Citation:	Failed to mark date on empty container larger than 5 gallons and/or manage it within one year. 66261.7(e) & (f).
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	05/29/2012
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	03/09/2007
Violation Code:	6HV1002
Violation:	HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation:	Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	03/29/2004

ADESA SAN DIEGO (Continued) **S123406707**

Violation Code:	6HV1003
Violation:	HMBP NOT AMENDED W/IN 30 DAYS
Violation Citation:	Business plan was not amended within 30 days for a 100% quantity increase, new disclosable materials or a change in business info. HSC 25505
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	06/10/2009
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector's review. 25505(e)
Activity:	ACTIVE
Name:	ADESA SAN DIEGO
Address:	2175 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	129754
Business Type:	6HK26
EPA Id Number:	CAL000218880
APN:	667-050-62-00
Last HMMD Inspection:	05/29/2012
Facility Telephone:	619-661-5565
Permit Status:	OPEN
Permit Expiration:	08/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	ADESA CALIFORNIA INC
Facility Mailing Address:	2175 CACTUS RD
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	129754
Update Date:	11/02/2012
Case Number:	Not reported
Name:	AUCTION WHEEL CLEANER
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported
Permit Number:	129754
Update Date:	11/02/2012
Case Number:	Not reported
Name:	BRITE SPOT
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE

ADESA SAN DIEGO (Continued) **S123406707**

Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: GALAXY
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: MIXTURE
Name: HYDROFLUORIC ACID, SULFURIC ACID, 2 BUTOXY ETHANOL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: KLEAR GLASS CLEANER
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: OK CAR SOAP
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: 68476-85-7
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 132 AQUEOUS SOL'N WITH METALS
Other Information: SUMP WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754

ADESA SAN DIEGO (Continued) **S123406707**

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: AES. ALSO HAULS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information: OILY ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: JULIO-C-BATTERIES
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 129754
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 129754
Update Date: 11/02/2012
Inspection Date: 09/13/2005
Violation Code: 6HV1006
Violation: HMBP: INVENTORY INADEQUATE
Violation Citation: Business Plan inventory does not list all hazardous materials on site in disclosable quantities. HSC 25504(a),25503.5
Activity: ACTIVE

Permit Number: 129754
Update Date: 11/02/2012
Inspection Date: 09/13/2005

ADESA SAN DIEGO (Continued) **S123406707**

Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	09/13/2005
Violation Code:	6HV1011
Violation:	TRAINING RECORDS NOT AVAILABLE
Violation Citation:	Personnel training records not available. 19 CCR 2732
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	05/29/2012
Violation Code:	6HV1004
Violation:	HMBP NOT SUBMITTED TO HMD
Violation Citation:	Hazardous Materials Handler has not submitted a completed Business Plan to the HMMD. HSC 25505(a)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	05/29/2012
Violation Code:	6HV0224
Violation:	MISMANAGED EMPTY CONTAINERS >5GALS.
Violation Citation:	Failed to mark date on empty container larger than 5 gallons and/or manage it within one year. 66261.7(e) & (f).
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	05/29/2012
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	03/09/2007
Violation Code:	6HV1002
Violation:	HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation:	Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity:	ACTIVE
Permit Number:	129754
Update Date:	11/02/2012
Inspection Date:	03/29/2004
Violation Code:	6HV1003
Violation:	HMBP NOT AMENDED W/IN 30 DAYS
Violation Citation:	Business plan was not amended within 30 days for a 100% quantity

ADESA SAN DIEGO (Continued) **S123406707**

increase, new disclosable materials or a change in business info. HSC 25505
Activity: ACTIVE

Permit Number: 129754
Update Date: 11/02/2012
Inspection Date: 06/10/2009
Violation Code: 6HV1013
Violation: HMBP NOT AVAILABLE FOR REVIEW
Violation Citation: Copy of HMBP not onsite for inspector's review. 25505(e)
Activity: ACTIVE

CERS HAZ WASTE:
Name: ADESA SAN DIEGO
Address: 2175 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 384211
CERS ID: 10395157
CERS Description: Hazardous Waste Generator

HAZNET:
Name: ADESA SAN DIEGO
Address: 2175 CACTUS RD
Address 2: Not reported
City,State,Zip: SAN DIEGO, CA 921548002
Contact: TIM MASSINGALE
Telephone: 3178434739
Mailing Name: Not reported
Mailing Address: 11299 N ILLINOIS ST

Year: 2021
Gepaid: CAL000346874
TSD EPA ID: NED981723513
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.1

Year: 2021
Gepaid: CAL000346874
TSD EPA ID: NED981723513
CA Waste Code: 352 - Other organic solids
Disposal Method: H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.2

Year: 2020
Gepaid: CAL000346874
TSD EPA ID: UTD981552177
CA Waste Code: 352 - Other organic solids
Disposal Method: H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.1

Year: 2020
Gepaid: CAL000346874
TSD EPA ID: NED981723513
CA Waste Code: 352 - Other organic solids

ADESA SAN DIEGO (Continued) **S123406707**

Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.05
Year:	2020
Gepaid:	CAL000346874
TSD EPA ID:	UTD991301748
CA Waste Code:	352 - Other organic solids
Disposal Method:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.01
Year:	2019
Gepaid:	CAL000346874
TSD EPA ID:	CAD044429835
CA Waste Code:	133 - Aqueous solution with total organic residues 10 percent or more
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.25000
Year:	2019
Gepaid:	CAL000346874
TSD EPA ID:	CAD044429835
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.03000
Year:	2019
Gepaid:	CAL000346874
TSD EPA ID:	ARD069748192
CA Waste Code:	343 - Unspecified organic liquid mixture
Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.10000
Year:	2019
Gepaid:	CAL000346874
TSD EPA ID:	CAD044429835
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.01500
Year:	2019
Gepaid:	CAL000346874
TSD EPA ID:	NED981723513
CA Waste Code:	343 - Unspecified organic liquid mixture
Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.16500

Click this hyperlink while viewing on your computer to access
7 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:

Year:	2021
Gen EPA ID:	CAL000346874

ADESA SAN DIEGO (Continued) **S123406707**

Shipment Date:	3/23/2020
Creation Date:	5/13/2020
Receipt Date:	4/6/2020
Manifest ID:	007297698SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	Clean Harbors Environmental Services, Inc.
TSDF EPA ID:	UTD981552177
Trans Name:	Clean Harbors Aragonite LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.05
Waste Quantity:	100
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	3/23/2020
Creation Date:	5/13/2020
Receipt Date:	4/6/2020
Manifest ID:	007297700SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	Clean Harbors Environmental Services, Inc.
TSDF EPA ID:	UTD991301748
Trans Name:	Clean Harbors Grassy Mountain LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.01
Waste Quantity:	20
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	3/23/2020
Creation Date:	4/22/2020
Receipt Date:	4/2/2020
Manifest ID:	007297699SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	Clean Harbors Environmental Services, Inc.

ADESA SAN DIEGO (Continued) **S123406707**

TSDF EPA ID:	NED981723513
Trans Name:	Clean Harbors Environmental Services, Inc.
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.05
Waste Quantity:	100
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	10/27/2020
Creation Date:	12/6/2020
Receipt Date:	11/16/2020
Manifest ID:	007790489SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	TXR000081205
Trans 2 Name:	Safety-Kleen Systems, Inc.
TSDF EPA ID:	UTD981552177
Trans Name:	Clean Harbors Aragonite LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.05
Waste Quantity:	100
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2020
Gen EPA ID:	CAL000346874
Shipment Date:	3/23/2020
Creation Date:	5/13/2020
Receipt Date:	4/6/2020
Manifest ID:	007297698SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	Clean Harbors Environmental Services, Inc.
TSDF EPA ID:	UTD981552177
Trans Name:	Clean Harbors Aragonite LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids

ADESA SAN DIEGO (Continued) **S123406707**

RCRA Code:	Not reported
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.05
Waste Quantity:	100
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	3/23/2020
Creation Date:	4/22/2020
Receipt Date:	4/2/2020
Manifest ID:	007297699SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	Clean Harbors Environmental Services, Inc.
TSDF EPA ID:	NED981723513
Trans Name:	Clean Harbors Environmental Services, Inc.
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.05
Waste Quantity:	100
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	3/23/2020
Creation Date:	5/13/2020
Receipt Date:	4/6/2020
Manifest ID:	007297700SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	Clean Harbors Environmental Services, Inc.
TSDF EPA ID:	UTD991301748
Trans Name:	Clean Harbors Grassy Mountain LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.01
Waste Quantity:	20
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported

ADESA SAN DIEGO (Continued) **S123406707**

Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	10/27/2020
Creation Date:	12/6/2020
Receipt Date:	11/16/2020
Manifest ID:	007790489SKS
Trans EPA ID:	TXR000081205
Trans Name:	Safety-Kleen Systems, Inc.
Trans 2 EPA ID:	TXR000081205
Trans 2 Name:	Safety-Kleen Systems, Inc.
TSDF EPA ID:	UTD981552177
Trans Name:	Clean Harbors Aragonite LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.05
Waste Quantity:	100
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Detail Two:

Year:	2020
EM Manifest ID:	1152a83a-9978-4abc-98f8-d6f07bac23e0
Shipment Date:	3/23/2020
Receipt Date:	4/6/2020
Manifest Number:	007297700SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	UTD991301748
TSDF Name:	Clean Harbors Grassy Mountain LLC
TSDF Address 1:	3 Miles East 7 Miles North of Knolls
TSDF Address 2:	Exit 41 off I-80
TSDF City:	Grantsville
TSDF Zip:	84029
TSDF Telephone:	800-483-3718

State:

Year:	2020
EM Manifest ID:	1152a83a-9978-4abc-98f8-d6f07bac23e0

ADESA SAN DIEGO (Continued) **S123406707**

Generator EPA ID:	CAL000346874
Shipment Date:	2020-03-23
Manifest Number:	007297700SKS
Line Number:	2
Method Code:	H132
Quantity Tons:	0.01000
Quantity Waste:	20.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	aa361734-8d3e-4426-a497-e495f9186c97
Shipment Date:	3/23/2020
Receipt Date:	4/6/2020
Manifest Number:	007297698SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	UTD981552177
TSDF Name:	Clean Harbors Aragonite LLC
TSDF Address 1:	11600 North Aptus Road
TSDF Address 2:	Not reported
TSDF City:	Grantsville
TSDF Zip:	84029
TSDF Telephone:	800-483-3718

State:

Year:	2020
EM Manifest ID:	aa361734-8d3e-4426-a497-e495f9186c97
Generator EPA ID:	CAL000346874
Shipment Date:	2020-03-23
Manifest Number:	007297698SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	2
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020

ADESA SAN DIEGO (Continued) **S123406707**

EM Manifest ID:	531a5955-36b7-4a7a-b8e5-c174abf8e11a
Shipment Date:	3/23/2020
Receipt Date:	4/2/2020
Manifest Number:	007297699SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NED981723513
TSDF Name:	Clean Harbors Environmental Services, Inc.
TSDF Address 1:	2247 South Highway 71
TSDF Address 2:	Not reported
TSDF City:	Kimball
TSDF Zip:	69145
TSDF Telephone:	800-483-3718

Federal:

Year:	2020
EM Manifest ID:	531a5955-36b7-4a7a-b8e5-c174abf8e11a
Generator EPA ID:	CAL000346874
Shipment Date:	2020-03-23
Manifest Number:	007297699SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	2
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D001

State:

Year:	2020
EM Manifest ID:	531a5955-36b7-4a7a-b8e5-c174abf8e11a
Generator EPA ID:	CAL000346874
Shipment Date:	2020-03-23
Manifest Number:	007297699SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	2
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

ADESA SAN DIEGO (Continued) **S123406707**

Year:	2020
EM Manifest ID:	1c9e6c85-b1cc-4372-9ca7-40a20f05459f
Shipment Date:	10/27/2020
Receipt Date:	11/16/2020
Manifest Number:	007790489SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	TXR000081205
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	UTD981552177
TSDF Name:	Clean Harbors Aragonite LLC
TSDF Address 1:	11600 North Aptus Road
TSDF Address 2:	Not reported
TSDF City:	Grantsville
TSDF Zip:	84029
TSDF Telephone:	800-483-3718

Federal:

Year:	2020
EM Manifest ID:	1c9e6c85-b1cc-4372-9ca7-40a20f05459f
Generator EPA ID:	CAL000346874
Shipment Date:	2020-10-27
Manifest Number:	007790489SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	2
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D001

State:

Year:	2020
EM Manifest ID:	1c9e6c85-b1cc-4372-9ca7-40a20f05459f
Generator EPA ID:	CAL000346874
Shipment Date:	2020-10-27
Manifest Number:	007790489SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	2
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

ADESA SAN DIEGO (Continued) **S123406707**

Detail Two:

Year:	2019
EM Manifest ID:	15984
Shipment Date:	9/30/2019
Receipt Date:	10/17/2019
Manifest Number:	007310506SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	UTD981552177
TSDF Name:	Clean Harbors Aragonite LLC
TSDF Address 1:	PO Box 1339
TSDF Address 2:	Not reported
TSDF City:	Grantsville
TSDF Zip:	84029
TSDF Telephone:	800-483-3718

State:

Year:	2019
EM Manifest ID:	15984
Generator EPA ID:	CAL000346874
Shipment Date:	2019-09-30
Manifest Number:	007310506SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Shipment Date:	6/29/2019
Receipt Date:	7/30/2019
Manifest Number:	007036226SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George

ADESA SAN DIEGO (Continued) **S123406707**

Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NED981723513
TSDF Name:	Clean Harbors Environmental Services, Inc.
TSDF Address 1:	2247 South Highway 71
TSDF Address 2:	Not reported
TSDF City:	Kimball
TSDF Zip:	69145
TSDF Telephone:	800-483-3718

Federal:

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.40000
Quantity Waste:	800.000000
Quantity Unit:	P
Number of Containers:	8
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D001

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.17500
Quantity Waste:	350.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D001

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.17500
Quantity Waste:	350.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D005

ADESA SAN DIEGO (Continued) **S123406707**

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.17500
Quantity Waste:	350.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D006

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.17500
Quantity Waste:	350.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D007

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.17500
Quantity Waste:	350.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D008

Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.17500
Quantity Waste:	350.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Type: Pounds
Federal Code: D035

Year: 2019
EM Manifest ID: 45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID: CAL000346874
Shipment Date: 2019-06-29
Manifest Number: 007036226SKS
Line Number: 2
Method Code: H040
Quantity Tons: 0.17500
Quantity Waste: 350.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
Federal Code: D040

Year: 2019
EM Manifest ID: 45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID: CAL000346874
Shipment Date: 2019-06-29
Manifest Number: 007036226SKS
Line Number: 2
Method Code: H040
Quantity Tons: 0.17500
Quantity Waste: 350.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
Federal Code: F003

Year: 2019
EM Manifest ID: 45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID: CAL000346874
Shipment Date: 2019-06-29
Manifest Number: 007036226SKS
Line Number: 2
Method Code: H040
Quantity Tons: 0.17500
Quantity Waste: 350.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
Federal Code: F005

State:
Year: 2019
EM Manifest ID: 45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID: CAL000346874
Shipment Date: 2019-06-29
Manifest Number: 007036226SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.40000

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Waste:	800.000000
Quantity Unit:	P
Number of Containers:	8
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352
Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.17500
Quantity Waste:	350.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352
Year:	2019
EM Manifest ID:	45d47f10-a2f4-4f37-ba77-4e0be498a77a
Generator EPA ID:	CAL000346874
Shipment Date:	2019-06-29
Manifest Number:	007036226SKS
Line Number:	3
Method Code:	H040
Quantity Tons:	0.15000
Quantity Waste:	300.000000
Quantity Unit:	P
Number of Containers:	2
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	141
Year:	2019
EM Manifest ID:	006327888SKS20180529_D_1
Shipment Date:	5/29/2018
Receipt Date:	6/24/2018
Manifest Number:	006327888SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	ARD069748192

ADESA SAN DIEGO (Continued) **S123406707**

TSDF Name: CLEAN HARBORS EL DORADO LLC
TSDF Address 1: Not reported
TSDF Address 2: Not reported
TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

State:
Year: 2019
EM Manifest ID: 006327888SKS20180529_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2018-05-29
Manifest Number: 006327888SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.02500
Quantity Waste: 50.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
State Code: 343

Year: 2019
EM Manifest ID: 4b228f7a-10f8-49fb-8aff-37f1e489535f
Shipment Date: 2/26/2019
Receipt Date: 3/13/2019
Manifest Number: 006938767SKS
Generator EPA ID: CAL000346874
Name: ADESA - SAN DIEGO
Address: 2175 CACTUS RD
Address 2: Not reported
City: SAN DIEGO
Zip: 92154
Telephone: 800-483-3718
Contact: James George
Contact Telephone: 619-661-8544
Transporter 1 EPA ID: TXR000081205
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MAD039322250
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: CAD044429835
TSDF Name: Clean Harbors Wilmington LLC
TSDF Address 1: 1737 East Denni Street
TSDF Address 2: Not reported
TSDF City: Wilmington
TSDF Zip: 90744
TSDF Telephone: 800-483-3718

Federal:
Year: 2019
EM Manifest ID: 4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID: CAL000346874
Shipment Date: 2019-02-26
Manifest Number: 006938767SKS
Line Number: 1
Method Code: H141

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Tons:	0.25000
Quantity Waste:	500.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D006
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938767SKS
Line Number:	1
Method Code:	H141
Quantity Tons:	0.25000
Quantity Waste:	500.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D007
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938767SKS
Line Number:	1
Method Code:	H141
Quantity Tons:	0.25000
Quantity Waste:	500.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D008
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938767SKS
Line Number:	1
Method Code:	H141
Quantity Tons:	0.25000
Quantity Waste:	500.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D018
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26

ADESA SAN DIEGO (Continued) **S123406707**

Manifest Number:	006938767SKS
Line Number:	1
Method Code:	H141
Quantity Tons:	0.25000
Quantity Waste:	500.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D039
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938767SKS
Line Number:	1
Method Code:	H141
Quantity Tons:	0.25000
Quantity Waste:	500.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D040
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938767SKS
Line Number:	2
Method Code:	H141
Quantity Tons:	0.01500
Quantity Waste:	30.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D005
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938767SKS
Line Number:	2
Method Code:	H141
Quantity Tons:	0.01500
Quantity Waste:	30.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D006
Year:	2019

ADESA SAN DIEGO (Continued) **S123406707**

EM Manifest ID: 4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID: CAL000346874
Shipment Date: 2019-02-26
Manifest Number: 006938767SKS
Line Number: 2
Method Code: H141
Quantity Tons: 0.01500
Quantity Waste: 30.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
Federal Code: D007

Year: 2019
EM Manifest ID: 4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID: CAL000346874
Shipment Date: 2019-02-26
Manifest Number: 006938767SKS
Line Number: 2
Method Code: H141
Quantity Tons: 0.01500
Quantity Waste: 30.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
Federal Code: D008

State:
Year: 2019
EM Manifest ID: 4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID: CAL000346874
Shipment Date: 2019-02-26
Manifest Number: 006938767SKS
Line Number: 1
Method Code: H141
Quantity Tons: 0.25000
Quantity Waste: 500.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 133

Year: 2019
EM Manifest ID: 4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID: CAL000346874
Shipment Date: 2019-02-26
Manifest Number: 006938767SKS
Line Number: 2
Method Code: H141
Quantity Tons: 0.01500
Quantity Waste: 30.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Type:	Pounds
State Code:	181
Year:	2019
EM Manifest ID:	4b228f7a-10f8-49fb-8aff-37f1e489535f
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938767SKS
Line Number:	3
Method Code:	H141
Quantity Tons:	0.03000
Quantity Waste:	60.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352
Year:	2019
EM Manifest ID:	a0380652-1728-4a17-bd56-1f6932a30295
Shipment Date:	2/26/2019
Receipt Date:	3/18/2019
Manifest Number:	006938765SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	ARD069748192
TSDF Name:	Clean Harbors El Dorado LLC
TSDF Address 1:	309 American Circle
TSDF Address 2:	Not reported
TSDF City:	El Dorado
TSDF Zip:	71730
TSDF Telephone:	800-483-3718

State:

Year:	2019
EM Manifest ID:	a0380652-1728-4a17-bd56-1f6932a30295
Generator EPA ID:	CAL000346874
Shipment Date:	2019-02-26
Manifest Number:	006938765SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.07500
Quantity Waste:	150.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Type: Pounds
State Code: 343

Year: 2019
EM Manifest ID: 244183
Shipment Date: 12/10/2018
Receipt Date: 12/30/2018
Manifest Number: 006641119SKS
Generator EPA ID: CAL000346874
Name: ADESA - SAN DIEGO
Address: 2175 CACTUS RD
Address 2: Not reported
City: SAN DIEGO
Zip: 92154
Telephone: 800-483-3718
Contact: James George
Contact Telephone: 619-961-5565
Transporter 1 EPA ID: TXR000081205
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MAD039322250
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NED981723513
TSDF Name: Clean Harbors Environmental Services, Inc.
TSDF Address 1: 2247 South Highway 71
TSDF Address 2: Not reported
TSDF City: Kimball
TSDF Zip: 69145
TSDF Telephone: 800-483-3718

State:
Year: 2019
EM Manifest ID: 244183
Generator EPA ID: CAL000346874
Shipment Date: 2018-12-10
Manifest Number: 006641119SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.02500
Quantity Waste: 50.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 141

Year: 2019
EM Manifest ID: 9c47a4a7-0c30-4a55-964c-da562172866e
Shipment Date: 1/28/2019
Receipt Date: 2/20/2019
Manifest Number: 006692116SKS
Generator EPA ID: CAL000346874
Name: ADESA - SAN DIEGO
Address: 2175 CACTUS RD
Address 2: Not reported
City: SAN DIEGO
Zip: 92154

ADESA SAN DIEGO (Continued) **S123406707**

Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NED981723513
TSDF Name:	Clean Harbors Environmental Services, Inc.
TSDF Address 1:	2247 South Highway 71
TSDF Address 2:	Not reported
TSDF City:	Kimball
TSDF Zip:	69145
TSDF Telephone:	800-483-3718

State:

Year:	2019
EM Manifest ID:	9c47a4a7-0c30-4a55-964c-da562172866e
Generator EPA ID:	CAL000346874
Shipment Date:	2019-01-28
Manifest Number:	006692116SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	141

Year:	2019
EM Manifest ID:	504426
Shipment Date:	1/28/2019
Receipt Date:	3/6/2019
Manifest Number:	006692115SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	James George
Contact Telephone:	619-661-8544
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	ARD069748192
TSDF Name:	Clean Harbors El Dorado LLC
TSDF Address 1:	309 American Circle
TSDF Address 2:	Not reported
TSDF City:	El Dorado
TSDF Zip:	71730
TSDF Telephone:	800-483-3718

ADESA SAN DIEGO (Continued) **S123406707**

State:
Year: 2019
EM Manifest ID: 504426
Generator EPA ID: CAL000346874
Shipment Date: 2019-01-28
Manifest Number: 006692115SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.02500
Quantity Waste: 50.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 343

Detail Two:
Year: 2018
EM Manifest ID: 006154613SKS20170927_D_1
Shipment Date: 9/27/2017
Receipt Date: 10/16/2017
Manifest Number: 006154613SKS
Generator EPA ID: CAL000346874
Name: ADESA - SAN DIEGO
Address: Not reported
Address 2: Not reported
City: Not reported
Zip: Not reported
Telephone: Not reported
Contact: Not reported
Contact Telephone: Not reported
Transporter 1 EPA ID: TXR000081205
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MAD039322250
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: CAD044429835
TSDF Name: CLEAN HARBORS OF WILMINGTON LLC
TSDF Address 1: Not reported
TSDF Address 2: Not reported
TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

State:
Year: 2018
EM Manifest ID: 006154613SKS20170927_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2017-09-27
Manifest Number: 006154613SKS
Line Number: 1
Method Code: H141
Quantity Tons: 0.02000
Quantity Waste: 40.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Type:	NULL
State Code:	512
Year:	2018
EM Manifest ID:	006123415SKS20170831_D_1
Shipment Date:	8/31/2017
Receipt Date:	9/21/2017
Manifest Number:	006123415SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NED981723513
TSDF Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

Federal:

Year:	2018
EM Manifest ID:	006123415SKS20170831_D_1
Generator EPA ID:	CAL000346874
Shipment Date:	2017-08-31
Manifest Number:	006123415SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.08000
Quantity Waste:	160.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
Federal Code:	D006
Year:	2018
EM Manifest ID:	006123415SKS20170831_D_1
Generator EPA ID:	CAL000346874
Shipment Date:	2017-08-31
Manifest Number:	006123415SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.08000
Quantity Waste:	160.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Type: NULL
Federal Code: D007

Year: 2018
EM Manifest ID: 006123415SKS20170831_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2017-08-31
Manifest Number: 006123415SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.08000
Quantity Waste: 160.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
Federal Code: D008

State:
Year: 2018
EM Manifest ID: 006123415SKS20170831_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2017-08-31
Manifest Number: 006123415SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.08000
Quantity Waste: 160.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
State Code: 214

Year: 2018
EM Manifest ID: 006123372SKS20170831_D_1
Shipment Date: 8/31/2017
Receipt Date: 9/14/2017
Manifest Number: 006123372SKS
Generator EPA ID: CAL000346874
Name: ADESA - SAN DIEGO
Address: Not reported
Address 2: Not reported
City: Not reported
Zip: Not reported
Telephone: Not reported
Contact: Not reported
Contact Telephone: Not reported
Transporter 1 EPA ID: TXR000081205
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MAD039322250
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NED981723513
TSDF Name: CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Address 1: Not reported
TSDF Address 2: Not reported

ADESA SAN DIEGO (Continued) **S123406707**

TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

Federal:
Year: 2018
EM Manifest ID: 006123372SKS20170831_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2017-08-31
Manifest Number: 006123372SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.06500
Quantity Waste: 130.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
Federal Code: D004

Year: 2018
EM Manifest ID: 006123372SKS20170831_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2017-08-31
Manifest Number: 006123372SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.06500
Quantity Waste: 130.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
Federal Code: F001

Year: 2018
EM Manifest ID: 006123372SKS20170831_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2017-08-31
Manifest Number: 006123372SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.06500
Quantity Waste: 130.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
Federal Code: F002

Year: 2018
EM Manifest ID: 006123372SKS20170831_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2017-08-31
Manifest Number: 006123372SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.06500

ADESA SAN DIEGO (Continued) **S123406707**

Quantity Waste:	130.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
Federal Code:	F003

Year:	2018
EM Manifest ID:	006123372SKS20170831_D_1
Generator EPA ID:	CAL000346874
Shipment Date:	2017-08-31
Manifest Number:	006123372SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.06500
Quantity Waste:	130.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
Federal Code:	F005

State:

Year:	2018
EM Manifest ID:	006123372SKS20170831_D_1
Generator EPA ID:	CAL000346874
Shipment Date:	2017-08-31
Manifest Number:	006123372SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.06500
Quantity Waste:	130.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	214

Year:	2018
EM Manifest ID:	110319
Shipment Date:	8/20/2018
Receipt Date:	9/4/2018
Manifest Number:	006617488SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	Alejandro Davalos
Contact Telephone:	619-661-5565
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported

ADESA SAN DIEGO (Continued) **S123406707**

TSDF EPA ID:	CAD044429835
TSDF Name:	Clean Harbors Wilmington LLC
TSDF Address 1:	1737 East Denni Street
TSDF Address 2:	Not reported
TSDF City:	Wilmington
TSDF Zip:	90744
TSDF Telephone:	800-483-3718

Federal:

Year:	2018
EM Manifest ID:	110319
Generator EPA ID:	CAL000346874
Shipment Date:	2018-08-20
Manifest Number:	006617488SKS
Line Number:	1
Method Code:	H141
Quantity Tons:	0.01000
Quantity Waste:	20.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
Federal Code:	D009

State:

Year:	2018
EM Manifest ID:	110319
Generator EPA ID:	CAL000346874
Shipment Date:	2018-08-20
Manifest Number:	006617488SKS
Line Number:	1
Method Code:	H141
Quantity Tons:	0.01000
Quantity Waste:	20.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	181

Year:	2018
EM Manifest ID:	110319
Generator EPA ID:	CAL000346874
Shipment Date:	2018-08-20
Manifest Number:	006617488SKS
Line Number:	2
Method Code:	H141
Quantity Tons:	0.05000
Quantity Waste:	100.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
State Code:	352

Year:	2018

ADESA SAN DIEGO (Continued) **S123406707**

EM Manifest ID:	135260
Shipment Date:	8/20/2018
Receipt Date:	9/19/2018
Manifest Number:	006617487SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	Alejandro Davalos
Contact Telephone:	619-661-5565
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	ARD069748192
TSDF Name:	Clean Harbors El Dorado LLC
TSDF Address 1:	309 American Circle
TSDF Address 2:	Not reported
TSDF City:	El Dorado
TSDF Zip:	71730
TSDF Telephone:	800-483-3718

State:

Year:	2018
EM Manifest ID:	135260
Generator EPA ID:	CAL000346874
Shipment Date:	2018-08-20
Manifest Number:	006617487SKS
Line Number:	2
Method Code:	H040
Quantity Tons:	0.01000
Quantity Waste:	20.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	343

Year:	2018
EM Manifest ID:	119883
Shipment Date:	8/20/2018
Receipt Date:	9/5/2018
Manifest Number:	006617486SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	2175 CACTUS RD
Address 2:	Not reported
City:	SAN DIEGO
Zip:	92154
Telephone:	800-483-3718
Contact:	Alejandro Davalos
Contact Telephone:	619-661-5565
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported

ADESA SAN DIEGO (Continued) **S123406707**

Transporter 2 EPA ID: MAD039322250
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NED981723513
TSDF Name: Clean Harbors Environmental Services, Inc.
TSDF Address 1: 2247 South Highway 71
TSDF Address 2: Not reported
TSDF City: Kimball
TSDF Zip: 69145
TSDF Telephone: 800-483-3718

State:
Year: 2018
EM Manifest ID: 119883
Generator EPA ID: CAL000346874
Shipment Date: 2018-08-20
Manifest Number: 006617486SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.07500
Quantity Waste: 150.000000
Quantity Unit: P
Number of Containers: 2
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 141

Year: 2018
EM Manifest ID: 006327887SKS20180529_D_1
Shipment Date: 5/29/2018
Receipt Date: 6/18/2018
Manifest Number: 006327887SKS
Generator EPA ID: CAL000346874
Name: ADESA - SAN DIEGO
Address: Not reported
Address 2: Not reported
City: Not reported
Zip: Not reported
Telephone: Not reported
Contact: Not reported
Contact Telephone: Not reported
Transporter 1 EPA ID: TXR000081205
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MAD039322250
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NED981723513
TSDF Name: CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Address 1: Not reported
TSDF Address 2: Not reported
TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

State:
Year: 2018
EM Manifest ID: 006327887SKS20180529_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2018-05-29

ADESA SAN DIEGO (Continued) **S123406707**

Manifest Number: 006327887SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.05000
Quantity Waste: 100.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
State Code: 141

Year: 2018
EM Manifest ID: 006474342SKS20180326_D_1
Shipment Date: 3/26/2018
Receipt Date: 5/12/2018
Manifest Number: 006474342SKS
Generator EPA ID: CAL000346874
Name: ADESA - SAN DIEGO
Address: Not reported
Address 2: Not reported
City: Not reported
Zip: Not reported
Telephone: Not reported
Contact: Not reported
Contact Telephone: Not reported
Transporter 1 EPA ID: TXR000081205
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MAD039322250
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: ARD069748192
TSDF Name: CLEAN HARBORS EL DORADO LLC
TSDF Address 1: Not reported
TSDF Address 2: Not reported
TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

State:
Year: 2018
EM Manifest ID: 006474342SKS20180326_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2018-03-26
Manifest Number: 006474342SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.02500
Quantity Waste: 50.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
State Code: 343

Year: 2018
EM Manifest ID: 006164424SKS20180326_D_1
Shipment Date: 3/26/2018

ADESA SAN DIEGO (Continued) **S123406707**

Receipt Date:	4/23/2018
Manifest Number:	006164424SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NED981723513
TSDF Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

State:

Year:	2018
EM Manifest ID:	006164424SKS20180326_D_1
Generator EPA ID:	CAL000346874
Shipment Date:	2018-03-26
Manifest Number:	006164424SKS
Line Number:	1
Method Code:	H040
Quantity Tons:	0.03750
Quantity Waste:	75.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	141

Year:	2018
EM Manifest ID:	006164425SKS20180312_D_1
Shipment Date:	3/12/2018
Receipt Date:	4/12/2018
Manifest Number:	006164425SKS
Generator EPA ID:	CAL000346874
Name:	ADESA - SAN DIEGO
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	TXR000081205
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MAD039322250
Transporter 2 Emergency Number:	Not reported

ADESA SAN DIEGO (Continued) **S123406707**

TSDF EPA ID: ARD069748192
TSDF Name: CLEAN HARBORS EL DORADO LLC
TSDF Address 1: Not reported
TSDF Address 2: Not reported
TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

State:
Year: 2018
EM Manifest ID: 006164425SKS20180312_D_1
Generator EPA ID: CAL000346874
Shipment Date: 2018-03-12
Manifest Number: 006164425SKS
Line Number: 1
Method Code: H040
Quantity Tons: 0.05510
Quantity Waste: 50.000000
Quantity Unit: L
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
State Code: 343

CERS:
Name: ADESA SAN DIEGO
Address: 2175 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 384211
CERS ID: 10395157
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 384211
Site Name: ADESA SAN DIEGO
Violation Date: 10-07-2022
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description: Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes: Returned to compliance on 10/28/2022. Inspection Sequence ID:7078509
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 384211
Site Name: ADESA SAN DIEGO
Violation Date: 08-01-2017
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit a site map with all required content.
Violation Notes: Returned to compliance on 08/31/2017.

ADESA SAN DIEGO (Continued) **S123406707**

Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	08-01-2017
Citation:	40 CFR 1 262.34(d)(5)(iii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(iii)
Violation Description:	Failure to ensure that all employees are thoroughly familiar with proper waste handling and emergency procedures, relevant to their responsibilities during normal facility operations and emergencies.
Violation Notes:	Returned to compliance on 08/29/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	08-01-2017
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 08/31/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	08-01-2017
Citation:	22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Description:	Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes:	Returned to compliance on 08/31/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	08-01-2017
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training

ADESA SAN DIEGO (Continued) **S123406707**

	records for a minimum of three years.
Violation Notes:	Returned to compliance on 08/29/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	08-01-2017
Citation:	22 CCR 18 66268.7(a) - California Code of Regulations, Title 22, Chapter 18, Section(s) 66268.7(a)
Violation Description:	Failure to determine if the waste has to be treated before it can be land disposed and retain the documentation at least three years from the date that the waste was last sent to on-site or off-site treatment, storage, or disposal.
Violation Notes:	Returned to compliance on 08/07/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	08-01-2017
Citation:	40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.31
Violation Description:	Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or the environment.
Violation Notes:	Returned to compliance on 08/04/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	08-01-2017
Citation:	22 CCR 12 66262.11 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.11
Violation Description:	Failure to determine if wastes generated are hazardous waste by using generator knowledge or applying testing method.
Violation Notes:	Returned to compliance on 08/07/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	384211
Site Name:	ADESA SAN DIEGO
Violation Date:	10-07-2022
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 10/28/2022. Inspection Sequence ID:7078509;Violation:HMD0226 Did not accumulate waste in a container or tank. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2)
Violation Division:	San Diego County Department of Env Health

ADESA SAN DIEGO (Continued) **S123406707**

Violation Program: HW
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-22-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6229400
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-20-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4093257
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-01-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Campanella Luke Inspection ID:5703279
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 01-04-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5413011
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 01-04-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5413011
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-01-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Campanella Luke Inspection ID:5703279
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

ADESA SAN DIEGO (Continued) **S123406707**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-07-2022
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Deniz Karla Inspection ID:7078509
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-07-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Deniz Karla Inspection ID:7078509
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-20-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:4093257
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-22-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6229400
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Coordinates:
Site ID: 384211
Facility Name: ADESA SAN DIEGO
Env Int Type Code: HMBP
Program ID: 10395157
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.558070
Longitude: -116.986180

Affiliation:
Affiliation Type Desc: Environmental Contact
Entity Name: James George
Entity Title: Not reported
Affiliation Address: 2175 Cactus Road
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: ,

ADESA SAN DIEGO (Continued) **S123406707**

Affiliation Type Desc:	Identification Signer
Entity Name:	James George
Entity Title:	EHS Coordinator
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Parent Corporation
Entity Name:	ADESA SAN DIEGO
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,

Affiliation Type Desc:	Operator
Entity Name:	ADESA SAN DIEGO
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 661-5565,

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	2175 CACTUS RD
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92154
Affiliation Phone:	,

Affiliation Type Desc:	Legal Owner
Entity Name:	ADESA CALIFORNIA LLC
Entity Title:	Not reported
Affiliation Address:	13085 HAMILTON CROSSING BLVD
Affiliation City:	CARMEL
Affiliation State:	IN
Affiliation Country:	United States

ADESA SAN DIEGO (Continued) **S123406707**

Affiliation Zip: 46032
Affiliation Phone: (800) 923-3725,

E22
SSW
1/8-1/4
0.178 mi.
942 ft.

DIRECT RECONDITIONING, LLC
2175 CACTUS ROAD
SAN DIEGO, CA 92154

Site 3 of 4 in cluster E

RCRA NonGen / NLR **1024860771** **CAL000429226**

Relative:
Higher

Actual:
510 ft.

RCRA Listings:

Date Form Received by Agency:	20170717
Handler Name:	Direct Reconditioning, Llc
Handler Address:	2175 CACTUS ROAD
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAL000429226
Contact Name:	BRIAN NUTTER
Contact Address:	2175 CACTUS ROAD
Contact City,State,Zip:	SAN DIEGO, CA 92154
Contact Telephone:	615-364-1396
Contact Fax:	Not reported
Contact Email:	BNUTTER@DIRECTAUCTIONSERVICES.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 503
Mailing City,State,Zip:	HENDERSONVILLE, TN 37077
Owner Name:	David Nutter
Owner Type:	Other
Operator Name:	Brian Nutter
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

DIRECT RECONDITIONING, LLC (Continued) **1024860771**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180907
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: DAVID NUTTER	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1041 KENDRA'S RUN
Owner/Operator City,State,Zip:	GALLATIN, TN 37066
Owner/Operator Telephone:	665-594-3886
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: BRIAN NUTTER	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2175 CACTUS ROAD
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	615-364-1396
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20170717
Handler Name: DIRECT RECONDITIONING, LLC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

DIRECT RECONDITIONING, LLC (Continued) **1024860771**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811121
NAICS Description: AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D23 **BAJA AUTO PARTS #2** **CERS HAZ WASTE** **S118938137**
NW **6960 CAMINO MAQUILADORA STE E** **HAZNET** **N/A**
1/8-1/4 **SAN DIEGO, CA 92154** **CERS**
0.216 mi. **HWTS**
1141 ft. **Site 5 of 13 in cluster D**

Relative:
Lower

Actual:
507 ft.

CERS HAZ WASTE:
Name: BAJA AUTO PARTS #2
Address: 6960 CAMINO MAQUILADORA STE E
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 10666
CERS ID: 10449733
CERS Description: Hazardous Waste Generator

HAZNET:
Name: BAJA AUTO PARTS #2
Address: 6960 CAMINO MAQUILADORA STE E
Address 2: Not reported
City,State,Zip: SAN DIEGO, CA 92154
Contact: MANUEL DE LEON
Telephone: 6197100777
Mailing Name: Not reported
Mailing Address: 6960 CAMINO MAQUILADORA STE E

Year: 2017
Gepaid: CAL000403322
TSD EPA ID: CAT080013352
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.068

Year: 2015
Gepaid: CAL000403322
TSD EPA ID: CAT080013352
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.187

BAJA AUTO PARTS #2 (Continued) **S118938137**

Additional Info:

Year:	2017
Gen EPA ID:	CAL000403322
Shipment Date:	20170215
Creation Date:	5/24/2017 18:30:17
Receipt Date:	20170224
Manifest ID:	016754889JJK
Trans EPA ID:	CAD028277036
Trans Name:	ASBURY ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	DEMENNO/KERDOON
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	D001
Meth Code:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons:	0.068
Waste Quantity:	20
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2015
Gen EPA ID:	CAL000403322
Shipment Date:	20150218
Creation Date:	5/18/2015 22:15:07
Receipt Date:	20150227
Manifest ID:	014060042JJK
Trans EPA ID:	CAD028277036
Trans Name:	ASBURY ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	DEMENNO / KERDOON
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	343 - Unspecified organic liquid mixture
RCRA Code:	D001
Meth Code:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons:	0.187
Waste Quantity:	55
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported

BAJA AUTO PARTS #2 (Continued) **S118938137**

Additional Code 5: Not reported

CERS:
Name: BAJA AUTO PARTS #2
Address: 6960 CAMINO MAQUILADORA STE E
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 10666
CERS ID: 10449733
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 05-25-2021
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Description: Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes: Returned to compliance on 06/07/2021. Inspection Sequence ID:6601006
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 01-14-2019
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 02/04/2019. Inspection Sequence ID:6060102
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 12-11-2014
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes: Returned to compliance on 12/11/2014. Inspection Sequence ID:5176180
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 10666

BAJA AUTO PARTS #2 (Continued) **S118938137**

Site Name: baja auto parts #2
Violation Date: 12-11-2014
Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Description: Failure to dispose of hazardous waste within 180 days (or 270 if waste is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.
Violation Notes: Returned to compliance on 02/18/2015. Inspection Sequence ID:5176180
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 12-11-2014
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 05/01/2015. Inspection Sequence ID:5176180;Violation:HMD1001 Unified Program Facility (UPF) permit was not obtained for the handling of hazardous materials; SDCC 68.905.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 12-11-2014
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Haz Waste Generator Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 05/01/2015. Inspection Sequence ID:5176180;Violation:HMD0131 No Unified Program Facility (UPF) permit not obtained for the generation of hazardous waste. SDCC 68.905.
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 12-11-2014
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain and/or maintain an Active EPA ID.
Violation Notes: Returned to compliance on 12/26/2014. Inspection Sequence ID:5176180
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 12-11-2014
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

BAJA AUTO PARTS #2 (Continued) **S118938137**

Violation Notes: Returned to compliance on 12/11/2014. Inspection Sequence ID:5176180
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 10666
Site Name: baja auto parts #2
Violation Date: 12-11-2014
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit a site map with all required content.
Violation Notes: Returned to compliance on 12/11/2014. Inspection Sequence ID:5176180
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-11-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5176180
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-11-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5176180
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-14-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6060102
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-25-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6601006
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-25-2021
Violations Found: Yes

BAJA AUTO PARTS #2 (Continued) **S118938137**

Eval Type: Routine done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6601006
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5563726
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-14-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6060102
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5563726
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Affiliation:
Affiliation Type Desc: Operator
Entity Name: baja auto parts #2
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 710-0777,

Affiliation Type Desc: Identification Signer
Entity Name: manuel de leon
Entity Title: manueldeleon
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Property Owner
Entity Name: RAMON GARCIA
Entity Title: Not reported

BAJA AUTO PARTS #2 (Continued) **S118938137**

Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: United States
Affiliation Zip: Not reported
Affiliation Phone: (619) 846-9775,

Affiliation Type Desc: Document Preparer
Entity Name: manuel de leon
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Legal Owner
Entity Name: MANUEL DE LEON
Entity Title: Not reported
Affiliation Address: 6960 camino maquiladora #e
Affiliation City: san diego
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 92154
Affiliation Phone: (619) 710-0777,

Affiliation Type Desc: Parent Corporation
Entity Name: baja auto parts #2
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 6960 camino maquiladora #e
Affiliation City: san diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: ,

BAJA AUTO PARTS #2 (Continued) **S118938137**

HWTS:

Name:	BAJA AUTO PARTS #2
Address:	6960 CAMINO MAQUILADORA STE E
Address 2:	Not reported
City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAL000403322
Inactive Date:	Not reported
Create Date:	12/26/2014
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	6960 CAMINO MAQUILADORA STE E
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SAN DIEGO, CA 921540000
Owner Name:	MANUEL DE LEON
Owner Address:	6960 CAMINO MAQUILADORA STE E
Owner Address 2:	Not reported
Owner City,State,Zip:	SAN DIEGO, CA 92154
Contact Name:	MANUEL DE LEON
Contact Address:	6960 CAMINO MAQUILADORA STE E
Contact Address 2:	Not reported
City,State,Zip:	SAN DIEGO, CA 92154
Facility Status:	Active
Facility Type:	PERMANENT
Category:	STATE
Latitude:	32.567391
Longitude:	-116.9900415

NAICS:

EPA ID:	CAL000403322
Create Date:	2014-12-26 10:51:21.537
NAICS Code:	811111
NAICS Description:	General Automotive Repair
Issued EPA ID Date:	2014-12-26 10:51:21.52300
Inactive Date:	Not reported
Facility Name:	BAJA AUTO PARTS #2
Facility Address:	6960 CAMINO MAQUILADORA STE E
Facility Address 2:	Not reported
Facility City:	SAN DIEGO
Facility County:	Not reported
Facility State:	CA
Facility Zip:	92154

D24 **M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA** **RCRA NonGen / NLR 1014465299**
NW **6950 CAMINO MAQUILADORA** **ECHO CAR000217547**
1/8-1/4 **SAN DIEGO, CA 92154**
0.216 mi.
1141 ft. **Site 6 of 13 in cluster D**

Relative:
Lower

Actual:
507 ft.

RCRA Listings:

Date Form Received by Agency:	20131113
Handler Name:	M Rios Trucking Inc Dba Miguel Rios Rosa
Handler Address:	6950 CAMINO MAQUILADORA
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAR000217547
Contact Name:	MIGUEL RIOS ROSA
Contact Address:	6950 CAMINO MAQUILADORA
Contact City,State,Zip:	SAN DIEGO, CA 92154

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Contact Telephone:	619-661-0271
Contact Fax:	619-671-2095
Contact Email:	MRIOSTRUCKING@SBCGLOBAL.NET
Contact Title:	OWNER
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	6950 CAMINO MAQUILADORA
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Miguel Rios
Owner Type:	Private
Operator Name:	Miguel Rios
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20131121
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MIGUEL RIOS
Legal Status: Private
Date Became Current: 20030801
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MIGUEL RIOS
Legal Status: Private
Date Became Current: 20030801
Date Ended Current: Not reported
Owner/Operator Address: 6950 CAMINO MAQUILADORA
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-661-0271
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MIGUEL RIOS
Legal Status: Private
Date Became Current: 20030801
Date Ended Current: Not reported
Owner/Operator Address: 6950 CAMINO MAQUILADORAS
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-661-0271
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MIGUEL RIOS
Legal Status: Private
Date Became Current: 20030801
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20110411
Handler Name: M RIOS TRUCKING DBA MIGUEL RIOS ROSA
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131113
Handler Name: M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 484121
NAICS Description: GENERAL FREIGHT TRUCKING, LONG-DISTANCE, TRUCKLOAD

NAICS Code: 484122
NAICS Description: GENERAL FREIGHT TRUCKING, LONG-DISTANCE, LESS THAN TRUCKLOAD

NAICS Code: 48423
NAICS Description: SPECIALIZED FREIGHT (EXCEPT USED GOODS) TRUCKING, LONG-DISTANCE

NAICS Code: 562112
NAICS Description: HAZARDOUS WASTE COLLECTION

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 300
Date of Enforcement Action: 20131018
Enforcement Responsible Agency: State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - Manifest System and Recordkeeping
Date Violation was Determined: 20190304
Actual Return to Compliance Date: 20190422
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 301
Date of Enforcement Action: 20190304
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - General
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Transporters - Manifest System and Recordkeeping
Date Violation was Determined:	20131018
Actual Return to Compliance Date:	20131023
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	300
Date of Enforcement Action:	20131018
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Transporters - General
Date Violation was Determined:	20131018
Actual Return to Compliance Date:	20131023
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	300
Date of Enforcement Action:	20131018
Enforcement Responsible Agency:	State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - General
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20190304
Actual Return to Compliance Date: 20190422
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 501
Date of Enforcement Action: 20190405
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - Manifest System and Recordkeeping
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20190304
Actual Return to Compliance Date: 20190422
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 301
Date of Enforcement Action: 20190304
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 300
Date of Enforcement Action: 20131018
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 300
Date of Enforcement Action: 20131018
Enforcement Responsible Agency: State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - Manifest System and Recordkeeping
Date Violation was Determined: 20190304
Actual Return to Compliance Date: 20190422
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 301
Date of Enforcement Action: 20190304
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - Manifest System and Recordkeeping
Date Violation was Determined: 20190304
Actual Return to Compliance Date: 20190422
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 501
Date of Enforcement Action: 20190405
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - Manifest System and Recordkeeping
Date Violation was Determined: 20190304
Actual Return to Compliance Date: 20190422
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 501
Date of Enforcement Action: 20190405
Enforcement Responsible Agency: State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Transporters - General
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 500
Date of Enforcement Action: 20131216
Enforcement Responsible Agency: State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20131018
Actual Return to Compliance Date: 20131023
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 300
Date of Enforcement Action: 20131018
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Transporters - General
Date Violation was Determined:	20131018
Actual Return to Compliance Date:	20131023
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	300
Date of Enforcement Action:	20131018
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Transporters - General
Date Violation was Determined:	20131018
Actual Return to Compliance Date:	20131023
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	300
Date of Enforcement Action:	20131018
Enforcement Responsible Agency:	State

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20131018
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 20131023
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20190304
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 20190422
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20131018
Evaluation Responsible Agency: State
Found Violation: Yes

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20190304
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20190422
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20190304
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20190422
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20190304
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20190422
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20190304
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20190422
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20190304
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20190422
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA (Continued) **1014465299**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20131018
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20131023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ECHO:

Envid:	1014465299
Registry ID:	110043533888
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110043533888
Name:	M RIOS TRUCKING INC DBA MIGUEL RIOS ROSA
Address:	6950 CAMINO MAQUILADORA
City,State,Zip:	SAN DIEGO, CA 92154

D25 **905 SMOG & AUTO REPAIR** **San Diego Co. HMMD** **S106063659**
NW **6960 CAMINO MAQUILADORA** **CERS HAZ WASTE** **N/A**
1/8-1/4 **SAN DIEGO, CA 92154** **CERS**
0.216 mi.
1141 ft. **Site 7 of 13 in cluster D**

Relative:
Lower

Actual:
507 ft.

HMMD SAN DIEGO:

Name:	CYCLONE LIFT INC
Address:	6960 CAMINO MAQUILADORA
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	205698
Business Type:	6HK26
EPA Id Number:	CAL000274628
APN:	646-190-27-09
Last HMMD Inspection:	02/17/2009
Facility Telephone:	619-661-1500
Permit Status:	INAC
Permit Expiration:	12/31/2008
Date Last Updated:	11/02/2012

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Facility Owner:	CYCLONE LIFT CORPORATION
Facility Mailing Address:	6960 CAMINO MAQUILADORA, #C
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Violations Inactive Permits:

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0132
Violation:	EPA ID NUMBER NOT OBTAINED/MAINTAINED
Violation Citation:	Generator of hazardous waste has not obtained/maintained an EPA identification number. CCR 66262.12(a)
Activity:	Inactive Permit

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0201
Violation:	WASTE CONTAINER NOT CLOSED
Violation Citation:	Hazardous waste containers are not kept closed while in storage. CCR 66265.173(a)
Activity:	Inactive Permit

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	Inactive Permit

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0402
Violation:	TRAINING PROGRAM NOT ADEQUATE
Violation Citation:	Personnel training is not adequate to ensure compliance with hazardous waste regulations. CCR 66265.16(a)&(b)
Activity:	Inactive Permit

Name:	SANCHEZ TRUCK REPAIR
Address:	6960 CAMINO MAQUILADORA
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	132775
Business Type:	6HK26
EPA Id Number:	Not reported

905 SMOG & AUTO REPAIR (Continued) **S106063659**

APN:	646-190-27-09
Last HMMD Inspection:	10/14/2003
Facility Telephone:	619-671-0992
Permit Status:	INAC
Permit Expiration:	08/31/2005
Date Last Updated:	11/02/2012
Facility Owner:	JOSE SANCHEZ
Facility Mailing Address:	6960 CAMINO MAQUILADORA #G
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Violations Inactive Permits:

Permit Number:	132775
Update Date:	11/02/2012
Inspection Date:	10/14/2003
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	Inactive Permit

Permit Number:	132775
Update Date:	11/02/2012
Inspection Date:	10/14/2003
Violation Code:	6HV0201
Violation:	WASTE CONTAINER NOT CLOSED
Violation Citation:	Hazardous waste containers are not kept closed while in storage. CCR 66265.173(a)
Activity:	Inactive Permit

Permit Number:	132775
Update Date:	11/02/2012
Inspection Date:	10/14/2003
Violation Code:	6HV0401
Violation:	TRAINING RECORDS UNAVAILABLE
Violation Citation:	Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity:	Inactive Permit

Name:	CYCLONE LIFT INC
Address:	6960 CAMINO MAQUILADORA
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	205698
Business Type:	6HK26
EPA Id Number:	CAL000274628
APN:	646-190-27-09
Last HMMD Inspection:	02/17/2009

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Facility Telephone:	619-661-1500
Permit Status:	INAC
Permit Expiration:	12/31/2008
Date Last Updated:	11/02/2012
Facility Owner:	CYCLONE LIFT CORPORATION
Facility Mailing Address:	6960 CAMINO MAQUILADORA, #C
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Violations Inactive Permits:

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0132
Violation:	EPA ID NUMBER NOT OBTAINED/MAINTAINED
Violation Citation:	Generator of hazardous waste has not obtained/maintained an EPA identification number. CCR 66262.12(a)
Activity:	Inactive Permit

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0201
Violation:	WASTE CONTAINER NOT CLOSED
Violation Citation:	Hazardous waste containers are not kept closed while in storage. CCR 66265.173(a)
Activity:	Inactive Permit

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	Inactive Permit

Permit Number:	205698
Update Date:	11/02/2012
Inspection Date:	08/12/2005
Violation Code:	6HV0402
Violation:	TRAINING PROGRAM NOT ADEQUATE
Violation Citation:	Personnel training is not adequate to ensure compliance with hazardous waste regulations. CCR 66265.16(a)&(b)
Activity:	Inactive Permit

Name:	BAJA AUTO PARTS #2
Address:	6960 CAMINO MAQUILADORA

905 SMOG & AUTO REPAIR (Continued) **S106063659**

City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	200186
Business Type:	6HK26
EPA Id Number:	CAL 00026331
APN:	646-190-27-09
Last HMMD Inspection:	08/06/2009
Facility Telephone:	619-710-0777
Permit Status:	OPEN
Permit Expiration:	05/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	MANUEL DE LEON
Facility Mailing Address:	6960 CAMINO MAQUILADORA #L
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	200186
Update Date:	11/02/2012
Case Number:	7440-37-1
Name:	ARGON GAS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	200186
Update Date:	11/02/2012
Case Number:	8052-41-3
Name:	MINERAL SPIRITS
Other Information:	MINERAL SPIRITS
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	200186
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 132 AQUEOUS SOL'N WITH METALS
Other Information:	BRAKE CLEANER
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	200186
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information:	SANDBLAST WASTE
Material Waste:	Waste
Hazardous Categories 1:	Not reported

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Hazardous Categories 2: Not reported

Permit Number: 200186
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 200186
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: OILY SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 200186
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: ANTIFREEZE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 200186
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 200186
Update Date: 11/02/2012
Inspection Date: 01/23/2006
Violation Code: 6HV0208
Violation: STORAGE AREA: NO WEEKLY INSPECTION
Violation Citation: Hazardous waste storage area is not being inspected weekly for deteriorated or leaking containers CCR 66265.174
Activity: ACTIVE

Permit Number: 200186
Update Date: 11/02/2012
Inspection Date: 01/23/2006
Violation Code: 6HV0215
Violation: OIL FILTERS IMPROPERLY MANAGED
Violation Citation: Used oil filters not properly drained, stored, or labeled prior to transport for the purpose of metal reclamation. CCR 66266.130
Activity: ACTIVE

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Permit Number:	200186
Update Date:	11/02/2012
Inspection Date:	01/23/2006
Violation Code:	6HV0304
Violation:	WASTE DETERMINATION NOT MADE
Violation Citation:	Generator of a waste has not determined if that waste is a hazardous waste as defined by law. CCR 66262.11 & 66260.200(c)
Activity:	ACTIVE

Permit Number:	200186
Update Date:	11/02/2012
Inspection Date:	01/23/2006
Violation Code:	6HV0401
Violation:	TRAINING RECORDS UNAVAILABLE
Violation Citation:	Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity:	ACTIVE

Permit Number:	200186
Update Date:	11/02/2012
Inspection Date:	01/23/2006
Violation Code:	6HV0405
Violation:	AISLE SPACE IS OBSTRUCTED
Violation Citation:	An aisle space to allow unobstructed movement of personnel & emergency control equipment is not provided and maintained. CCR 66265.35
Activity:	ACTIVE

Name:	905 SMOG & AUTO REPAIR
Address:	6960 CAMINO MAQUILADORA
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	206286
Business Type:	6HK26
EPA Id Number:	CAL 00029700
APN:	646-190-27-09
Last HMMD Inspection:	08/06/2009
Facility Telephone:	619-661-8008
Permit Status:	OPEN
Permit Expiration:	05/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	MICAR INTERNATIONAL INC
Facility Mailing Address:	6960 CAMINO MAQUILADORA #G
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	206286
Update Date:	11/02/2012
Case Number:	7440-59-7

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Name:	HELIUM GAS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	PRESSURE RELEASE
Hazardous Categories 2:	ACUTE
Permit Number:	206286
Update Date:	11/02/2012
Case Number:	7727-37-9
Name:	NITROGEN GAS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	PRESSURE RELEASE
Permit Number:	206286
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 213 HYDROCARBON SOLVENTS
Other Information:	PARTS WASHER
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	206286
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 221 WASTE OIL & MIXED OIL
Other Information:	USED OIL
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	206286
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information:	OILY ABSORBENT
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	206286
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information:	ANTIFREEZE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	206286
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 888 USED OIL FILTERS
Other Information:	Not reported
Material Waste:	Waste

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 08/06/2009
Violation Code: 6HV1001
Violation: NO UPF PERMIT FOR HAZMATS
Violation Citation: A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity: ACTIVE

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 08/06/2009
Violation Code: 6HV1004
Violation: HMBP NOT SUBMITTED TO HMD
Violation Citation: Hazardous Materials Handler has not submitted a completed Business Plan to the HMMD. HSC 25505(a)
Activity: ACTIVE

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 08/06/2009
Violation Code: 6HV0131
Violation: UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation: A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity: ACTIVE

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 08/06/2009
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity: ACTIVE

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 01/25/2006
Violation Code: 6HV0131
Violation: UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation: A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity: ACTIVE

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 01/25/2006
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2);

905 SMOG & AUTO REPAIR (Continued) **S106063659**

66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 01/25/2006
Violation Code: 6HV0401
Violation: TRAINING RECORDS UNAVAILABLE
Violation Citation: Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity: ACTIVE

Permit Number: 206286
Update Date: 11/02/2012
Inspection Date: 01/25/2006
Violation Code: 6HV0406
Violation: CONT PLAN NOT PREPARED/ONSITE
Violation Citation: Owner/Operator has not prepared an Emergency Contingency Plan, or maintained a copy on site, or submitted a copy to the HMMD. CCR 66265.51(a), 66265.53(a)&(b)
Activity: ACTIVE

CERS HAZ WASTE:
Name: 905 SMOG & AUTO REPAIR
Address: 6960 CAMINO MAQUILADORA
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 88412
CERS ID: 10394407
CERS Description: Hazardous Waste Generator

CERS:
Name: 905 SMOG & AUTO REPAIR
Address: 6960 CAMINO MAQUILADORA
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 88412
CERS ID: 10394407
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 01-31-2020
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 05/21/2021. Inspection Sequence ID:6392419;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Violation Date:	02-27-2018
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 02/28/2018. Inspection Sequence ID:5915311;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.905
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	07-16-2021
Citation:	HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Description:	Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes:	Returned to compliance on 08/25/2021. Inspection Sequence ID:6772308
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	12-09-2016
Citation:	40 CFR 1 265.174 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.174
Violation Description:	Failure to inspect hazardous waste storage areas at least weekly and look for leaking and deteriorating containers.
Violation Notes:	Returned to compliance on 12/09/2016.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	02-27-2018
Citation:	HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description:	Business Plan Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 02/28/2018. Inspection Sequence ID:5915311;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 07-16-2021
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Inspection Sequence ID:6772308;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 07-16-2021
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description: Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes: Returned to compliance on 09/08/2021. Inspection Sequence ID:6772308
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 12-09-2016
Citation: 40 CFR 1 262.34(d)(5)(iii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(iii)
Violation Description: Failure to ensure that all employees are thoroughly familiar with proper waste handling and emergency procedures, relevant to their responsibilities during normal facility operations and emergencies.
Violation Notes: Returned to compliance on 02/27/2018.
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 01-31-2020
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description: Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes: Returned to compliance on 05/21/2021. Inspection Sequence ID:6392419
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 05-21-2021
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 07/16/2021. Inspection Sequence ID:6571037;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 07-16-2021
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 09/08/2021. Inspection Sequence ID:6772308
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 02-27-2018
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description: Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes: Returned to compliance on 03/09/2018. Inspection Sequence ID:5915311
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 12-12-2014
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain and/or maintain an Active EPA ID.
Violation Notes: Returned to compliance on 01/06/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 02-27-2018
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

905 SMOG & AUTO REPAIR (Continued) **S106063659**

	12, Section(s) 66262.12
Violation Description:	Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes:	Returned to compliance on 02/28/2018. Inspection Sequence ID:5915311
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	05-21-2021
Citation:	22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description:	Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes:	Returned to compliance on 07/16/2021. Inspection Sequence ID:6571037
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	05-21-2021
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 07/16/2021. Inspection Sequence ID:6571037
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	12-12-2014
Citation:	HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Description:	Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes:	Returned to compliance on 12/12/2014.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	12-12-2014
Citation:	22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Description:	Failure to dispose of hazardous waste within 180 days (or 270 if waste

905 SMOG & AUTO REPAIR (Continued) **S106063659**

	is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.
Violation Notes:	Returned to compliance on 12/30/2014.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	12-09-2016
Citation:	22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description:	Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes:	Returned to compliance on 12/09/2016.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	01-31-2020
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 05/21/2021. Inspection Sequence ID:6392419;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	07-16-2021
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 07/16/2021. Inspection Sequence ID:6772308;Violation:HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	07-16-2021
Citation:	22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description:	Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Violation Notes:	Returned to compliance on 07/27/2021. Inspection Sequence ID:6772308
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	02-27-2018
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes:	Returned to compliance on 03/12/2018. Inspection Sequence ID:5915311
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	05-21-2021
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 07/16/2021. Inspection Sequence ID:6571037;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	12-09-2016
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes:	Returned to compliance on 12/09/2016.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	88412
Site Name:	905 SMOG & AUTO REPAIR
Violation Date:	12-12-2014
Citation:	HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507
Violation Description:	Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes:	Returned to compliance on 12/12/2014.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 01-31-2020
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Description: Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes: Returned to compliance on 05/21/2021. Inspection Sequence ID:6392419
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 01-31-2020
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 05/21/2021. Inspection Sequence ID:6392419
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 12-12-2014
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes: Returned to compliance on 12/12/2014.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 05-21-2021
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Description: Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2)

905 SMOG & AUTO REPAIR (Continued) **S106063659**

The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.

Violation Notes: Returned to compliance on 07/16/2021. Inspection Sequence ID:6571037
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 02-27-2018
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 03/08/2018. Inspection Sequence ID:5915311
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 07-16-2021
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes: Inspection Sequence ID:6772308;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 88412
Site Name: 905 SMOG & AUTO REPAIR
Violation Date: 01-31-2020
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 01/31/2020. Inspection Sequence ID:6392419
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-31-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6392419
Eval Division: San Diego County Department of Env Health

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-12-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Eivaz Chantal Inspection ID:4350440
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-31-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6392419
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 05-21-2021
Violations Found: Yes
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6571037
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-09-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5564961
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-27-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Campanella Luke Inspection ID:5915311
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-27-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Campanella Luke Inspection ID:5915311
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Eval General Type: Other/Unknown
Eval Date: 07-16-2021
Violations Found: Yes
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6772308
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 07-16-2021
Violations Found: Yes
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6772308
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-12-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Eivaz Chantal Inspection ID:4350440
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 05-21-2021
Violations Found: Yes
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Cervantes Diego Inspection ID:6571037
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-09-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Drummond Rafaela Inspection ID:5564961
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Affiliation:
Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Identification Signer

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Entity Name: Miguel Carranza
Entity Title: Business owner
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Legal Owner
Entity Name: Micar International inc llc
Entity Title: Not reported
Affiliation Address: 6960 camino maquiladora ,suit G
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 92154
Affiliation Phone: (619) 748-2310,

Affiliation Type Desc: Document Preparer
Entity Name: MIGUEL A CARRANZA
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 6960 CAMINO MAQUILADORA #G
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154
Affiliation Phone: ,

Affiliation Type Desc: Parent Corporation
Entity Name: 905 SMOG & AUTO REPAIR
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: MIGUEL CARRANZA
Entity Title: Not reported
Affiliation Address: 6960 CAMINO MAQUILADORA
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92154

905 SMOG & AUTO REPAIR (Continued) **S106063659**

Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: MICAR INTERNATIONAL INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 748-2310,

D26 **JOSE GRACIA** **RCRA NonGen / NLR** **1026169174**
NW **6960 CAMINO MAQUILADORA SUITE B** **CAC003069222**
1/8-1/4 **SAN DIEGO, CA 92154**
0.216 mi.
1141 ft. **Site 8 of 13 in cluster D**

Relative: **Lower**
Actual: **507 ft.**

RCRA Listings:

Date Form Received by Agency:	20200602
Handler Name:	Jose Gracia
Handler Address:	6960 CAMINO MAQUILADORA SUITE B
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAC003069222
Contact Name:	JOSE GRACIA
Contact Address:	6960 CAMINO MAQUILADORA SUITE B
Contact City,State,Zip:	SAN DIEGO, CA 92154
Contact Telephone:	619-278-1456
Contact Fax:	Not reported
Contact Email:	HEAVYTRUCKSERVICE01@GMAIL.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	6960 CAMINO MAQUILADORA SUITE B
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Jose Gracia
Owner Type:	Other
Operator Name:	Jose Gracia
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

JOSE GRACIA (Continued) **1026169174**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200608
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOSE GRACIA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6960 CAMINO MAQUILADORA SUITE B
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-278-1456
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOSE GRACIA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6960 CAMINO MAQUILDORA SUITE B
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-278-1456
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

JOSE GRACIA (Continued) **1026169174**

Historic Generators:
Receive Date: 20200602
Handler Name: JOSE GRACIA
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811490
NAICS Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D27 **BAJA AUTO PARTS #2** **RCRA NonGen / NLR** **1024848029**
NW **6960 CAMINO MAQUILADORA STE E** **CAL000403322**
1/8-1/4 **SAN DIEGO, CA 92154**
0.216 mi.
1141 ft. **Site 9 of 13 in cluster D**

Relative: **Lower**
Actual: **507 ft.**

RCRA Listings:
Date Form Received by Agency: 20141226
Handler Name: Baja Auto Parts #2
Handler Address: 6960 CAMINO MAQUILADORA STE E
Handler City,State,Zip: SAN DIEGO, CA 92154
EPA ID: CAL000403322
Contact Name: MANUEL DE LEON
Contact Address: 6960 CAMINO MAQUILADORA STE E
Contact City,State,Zip: SAN DIEGO, CA 92154
Contact Telephone: 619-710-0777
Contact Fax: 619-710-0590
Contact Email: BAJAAUTOPARTS2@GMAIL.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: 6960 CAMINO MAQUILADORA STE E
Mailing City,State,Zip: SAN DIEGO, CA 92154-0000
Owner Name: Manuel De Leon

BAJA AUTO PARTS #2 (Continued) **1024848029**

Owner Type:	Other
Operator Name:	Manuel De Leon
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180906
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MANUEL DE LEON	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6960 CAMINO MAQUILADORA STE E
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-710-0777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BAJA AUTO PARTS #2 (Continued) **1024848029**

Owner/Operator Indicator: Operator
Owner/Operator Name: MANUEL DE LEON
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6960 CAMINO MAQUILADORA STE E
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-710-0777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20141226
Handler Name: BAJA AUTO PARTS #2
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D28 **BROWNFIELD AUTOMOTIVE SOLUTIONS** **RCRA NonGen / NLR** **1027091643**
NW **6960 CAMINO MAQUILADORA #D** **CAL000465125**
1/8-1/4 **SAN DIEGO, CA 92154**
0.216 mi.
1141 ft. **Site 10 of 13 in cluster D**

Relative:
Lower

Actual:
507 ft.

RCRA Listings:
Date Form Received by Agency: 20210827
Handler Name: Brownfield Automotive Solutions
Handler Address: 6960 CAMINO MAQUILADORA #D
Handler City,State,Zip: SAN DIEGO, CA 92154
EPA ID: CAL000465125
Contact Name: EDGAR MERINO
Contact Address: 6960 CAMINO MAQUILADORA #D
Contact City,State,Zip: SAN DIEGO, CA 92154
Contact Telephone: 619-461-8210
Contact Fax: Not reported
Contact Email: MELB04@ATT.NET
Contact Title: Not reported

BROWNFIELD AUTOMOTIVE SOLUTIONS (Continued) **1027091643**

EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	6960 CAMINO MAQUILADORA #D
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Edgar Merino
Owner Type:	Other
Operator Name:	Edgar Merino
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211018
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

BROWNFIELD AUTOMOTIVE SOLUTIONS (Continued) **1027091643**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: EDGAR MERINO	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6960 CAMINO MAQUILADORA #D
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-461-8210
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: EDGAR MERINO	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6960 CAMINO MAQUILADORA #D
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-461-8210
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20210827
Handler Name:	BROWNFIELD AUTOMOTIVE SOLUTIONS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	811111
NAICS Description:	GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

D29
NW
1/8-1/4
0.216 mi.
1141 ft.

NAHUM LLC
6950 CAMINO MAQUILADORA
SAN DIEGO, CA 92154

Site 11 of 13 in cluster D

RCRA NonGen / NLR

1024768755
CAC002988639

Relative:
Lower

Actual:
507 ft.

RCRA Listings:

Date Form Received by Agency:	20181109
Handler Name:	Nahum Llc
Handler Address:	6950 CAMINO MAQUILADORA
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAC002988639
Contact Name:	JOY LANHAM
Contact Address:	3636 4 AVE.
Contact City,State,Zip:	SAN DIEGO, CA 92103
Contact Telephone:	619-295-8376
Contact Fax:	Not reported
Contact Email:	JLANHAM@IHAPARTNERS.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3636 4 AVE.
Mailing City,State,Zip:	SAN DIEGO, CA 92103
Owner Name:	Nahum Llc
Owner Type:	Other
Operator Name:	Joy Lanham
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

NAHUM LLC (Continued) **1024768755**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181120
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NAHUM LLC	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3636 4 AVE.
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92103
Owner/Operator Telephone:	619-295-8376
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOY LANHAM	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3636 4 AVE.
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92103
Owner/Operator Telephone:	619-295-8376
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20181109
Handler Name: NAHUM LLC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

NAHUM LLC (Continued) **1024768755**

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D30 **905 SMOG & AUTO REPAIR** **RCRA NonGen / NLR** **1024811867**
NW **6960 CAMINO MAQUILADORA STE G** **CAL000297004**
1/8-1/4 **SAN DIEGO, CA 92154**
0.216 mi.
1141 ft. **Site 12 of 13 in cluster D**

Relative: **Lower**
Actual: **507 ft.**

RCRA Listings:

Date Form Received by Agency:	20210521
Handler Name:	905 Smog & Auto Repair
Handler Address:	6960 CAMINO MAQUILADORA STE G
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAL000297004
Contact Name:	MIGUEL CARRANZA
Contact Address:	SPARTA RD STE 14
Contact City,State,Zip:	CHULA VISTA, CA 91915
Contact Telephone:	619-621-4530
Contact Fax:	866-591-6519
Contact Email:	MICAR625@GMAIL.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	CAMINO MAQUILADORA STE G
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Micar International Inc
Owner Type:	Other
Operator Name:	Miguel Carranza
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes

905 SMOG & AUTO REPAIR (Continued) **1024811867**

Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210721
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MIGUEL CARRANZA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2750 SPARTA RD STE 14
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91915
Owner/Operator Telephone:	619-621-4530
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MICAR INTERNATIONAL INC	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6960 CAMINO MAQUILADORA STE G
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	619-621-4530
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

905 SMOG & AUTO REPAIR (Continued) **1024811867**

Owner/Operator Name: MIGUEL CARRANZA
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2750 SPARTA RD STE 14
Owner/Operator City,State,Zip: CHULA VISTA, CA 91915
Owner/Operator Telephone: 619-621-4530
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MICAR INTERNATIONAL INC
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6960 CAMINO MAQUILADORA STE G
Owner/Operator City,State,Zip: SAN DIEGO, CA 92154
Owner/Operator Telephone: 619-621-4530
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20050728
Handler Name: 905 SMOG & AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210521
Handler Name: 905 SMOG & AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

905 SMOG & AUTO REPAIR (Continued) **1024811867**

Evaluation Action Summary:
Evaluations: No Evaluations Found

D31
NW
1/8-1/4
0.216 mi.
1141 ft.

M RIOS TRUCKING INC **HWT** **S128987029**
6950 CAMINO MAQUILADORA STE C **N/A**
SAN DIEGO, CA 92154

Site 13 of 13 in cluster D

Relative:
Lower

Actual:
507 ft.

HWT:
Name: M RIOS TRUCKING INC
Address: 6950 CAMINO MAQUILADORA STE C
City,State,Zip: SAN DIEGO, CA 92154
Reg Num: 6020
Expiration Date: 09/30/2023

F32
NNW
1/8-1/4
0.224 mi.
1184 ft.

NOIL USA INC **RCRA NonGen / NLR** **1024855653**
1605 CACTUS RD **CAL000418575**
SAN DIEGO, CA 92154

Site 1 of 5 in cluster F

Relative:
Higher

Actual:
510 ft.

RCRA Listings:

Date Form Received by Agency:	20160630
Handler Name:	Noil Usa Inc
Handler Address:	1605 CACTUS RD
Handler City,State,Zip:	SAN DIEGO, CA 92154
EPA ID:	CAL000418575
Contact Name:	HAROLD HEKIMYAN
Contact Address:	1605 CACTUS RD
Contact City,State,Zip:	SAN DIEGO, CA 92154
Contact Telephone:	626-238-8787
Contact Fax:	Not reported
Contact Email:	JACK@NOILUSA.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1605 CACTUS RD
Mailing City,State,Zip:	SAN DIEGO, CA 92154
Owner Name:	Levon Termendzhyan
Owner Type:	Other
Operator Name:	Harold Hekimyan
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

NOIL USA INC (Continued) **1024855653**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180906
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LEVON TERMENDZHYAN	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1605 CACTUS RD
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154
Owner/Operator Telephone:	954-609-1442
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HAROLD HEKIMYAN	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1605 CACTUS RD
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92154

NOIL USA INC (Continued) **1024855653**

Owner/Operator Telephone: 626-238-8787
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160630
Handler Name: NOIL USA INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44719
NAICS Description: OTHER GASOLINE STATIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F33 **NOIL USA INC.** **San Diego Co. HMMD** **S113161624**
NNW **1605 CACTUS RD** **CERS HAZ WASTE** **N/A**
1/8-1/4 **SAN DIEGO, CA 92154** **CERS TANKS**
0.224 mi. **HAZNET**
1184 ft. **Site 2 of 5 in cluster F** **CERS**
HWTS

Relative:
Higher

Actual:
510 ft.

HMMD SAN DIEGO:
Name: 29TH STREET CACTUS OPERATING LLC
Address: 1605 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Permit Number: 216147
Business Type: 6HK28
EPA Id Number: Not reported
APN: DEH-102237
Last HMMD Inspection: 04/02/2012
Facility Telephone: 619-671-7098
Permit Status: OPEN
Permit Expiration: 02/28/2013
Date Last Updated: 11/02/2012
Facility Owner: DAVID SMITH-29TH STREET COMMERCIAL I,LP
Facility Mailing Address: 1605 CACTUS RD
Facility Mailing City: SAN DIEGO
Facility Mailing State: CA
Facility Mailing Zip: 92154
UST Owner: DAVID SMITH - 29TH ST COMMERCIAL I, LP

NOIL USA INC. (Continued) **S113161624**

Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Y
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 216147
Update Date: 11/02/2012
Case Number: MIXTURE
Name: CAR WASH CONCENTRATE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: UNDERGROUND TANK 102237 T003
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: UNDERGROUND TANK 102237 T004
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL*
Other Information: UNDERGROUND TANK 102237 T005
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 102237 T002
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEAD
Other Information: UNDERGROUND TANK 102237 T001

NOIL USA INC. (Continued) **S113161624**

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 216147
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: FUEL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

UST:
UST Name: UNDERGROUND TANK 102237 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

NOIL USA INC. (Continued) **S113161624**

UST Name:	UNDERGROUND TANK 102237 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287
Capacity Gallons:	15000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 102237 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287
Capacity Gallons:	20000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 102237 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287/DSL WEST/RT3632
Capacity Gallons:	15000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	29TH STREET CACTUS OPERATING LLC
Address:	1605 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	216147
Business Type:	6HK28

NOIL USA INC. (Continued) **S113161624**

EPA Id Number:	Not reported
APN:	DEH-102237
Last HMMD Inspection:	04/02/2012
Facility Telephone:	619-671-7098
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	DAVID SMITH-29TH STREET COMMERCIAL I,LP
Facility Mailing Address:	1605 CACTUS RD
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	DAVID SMITH - 29TH ST COMMERCIAL I, LP
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Y
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	MIXTURE
Name:	CAR WASH CONCENTRATE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL
Other Information:	UNDERGROUND TANK 102237 T003
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL
Other Information:	UNDERGROUND TANK 102237 T004
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL*
Other Information:	UNDERGROUND TANK 102237 T005
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	216147

NOIL USA INC. (Continued) **S113161624**

Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 102237 T002
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE
Permit Number:	216147
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEAD
Other Information:	UNDERGROUND TANK 102237 T001
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE
Permit Number:	216147
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	Not reported
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	216147
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information:	FUEL FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

UST:

UST Name:	UNDERGROUND TANK 102237 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287
Capacity Gallons:	5000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 102237 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL

NOIL USA INC. (Continued) **S113161624**

Additional Id:	NT2287
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 102237 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287
Capacity Gallons:	15000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 102237 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287
Capacity Gallons:	20000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 102237 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287/DSL WEST/RT3632
Capacity Gallons:	15000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported

NOIL USA INC. (Continued) **S113161624**

Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name: 29TH STREET CACTUS OPERATING LLC
Address: 1605 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Permit Number: 216147
Business Type: 6HK28
EPA Id Number: Not reported
APN: DEH-102237
Last HMMD Inspection: 04/02/2012
Facility Telephone: 619-671-7098
Permit Status: OPEN
Permit Expiration: 02/28/2013
Date Last Updated: 11/02/2012
Facility Owner: DAVID SMITH-29TH STREET COMMERCIAL I,LP
Facility Mailing Address: 1605 CACTUS RD
Facility Mailing City: SAN DIEGO
Facility Mailing State: CA
Facility Mailing Zip: 92154
UST Owner: DAVID SMITH - 29TH ST COMMERCIAL I, LP
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Not reported
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 216147
Update Date: 11/02/2012
Case Number: MIXTURE
Name: CAR WASH CONCENTRATE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: UNDERGROUND TANK 102237 T003
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: UNDERGROUND TANK 102237 T004
Material Waste: Material

NOIL USA INC. (Continued) **S113161624**

Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL*
Other Information: UNDERGROUND TANK 102237 T005
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 102237 T002
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEAD
Other Information: UNDERGROUND TANK 102237 T001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 216147
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: FUEL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

UST:
UST Name: UNDERGROUND TANK 102237 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: DIESEL

NOIL USA INC. (Continued) **S113161624**

Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 15000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 20000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A

NOIL USA INC. (Continued) **S113161624**

UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 102237 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	216147
Tank Type:	DOUBLE WALL
Additional Id:	NT2287/DSL WEST/RT3632
Capacity Gallons:	15000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-03-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	NOIL USA INC.
Address:	1605 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000418575
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-500-5601
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	06/25/2022
Facility Owner:	Not reported
Facility Mailing Address:	1605 CACTUS RD, SAN DIEGO, CA 92154
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	Y
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6135413
Return To Compliance Date:	2020-04-09T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	32548

NOIL USA INC. (Continued) **S113161624**

Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2019-04-23T00:00:00.000
Violation Code:	2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6135413
Return To Compliance Date:	2019-05-14T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	32548
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2019-04-23T00:00:00.000
Violation Code:	2030036 (TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. 7. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. 8. Inspected within 30 days after a repair to the overfill prevention equipment. 9. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 10. Inspected by a certified UST service technician. 11. Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)
Record ID:	DEH2012-HUPFP-216147

NOIL USA INC. (Continued) **S113161624**

Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6903785
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2022-04-13T00:00:00.000
Violation Code:	HMD0000 UST PRESSURIZED PIPING (DW) REQUIREMENTS

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	4280322
Return To Compliance Date:	2014-05-29T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	87
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2013-04-08T00:00:00.000
Violation Code:	2030025 Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5646866
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2017-04-27T21:11:00.000
Violation Code:	2010007 Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance. HSC 25292.2, 25299.30-25299.34; 23 CCR 2711; 2808.1, 2809-2809.2

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y

NOIL USA INC. (Continued) **S113161624**

Facility Id Number:	37-000-216147
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5076286
Return To Compliance Date:	2014-06-03T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2014-04-28T14:20:00.000
Violation Code:	1010001 Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; 19 CCR 4 2729.1(a); HSC 6.95 25503.5(a).
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5166669
Return To Compliance Date:	2015-04-28T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	91
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2015-04-28T00:00:00.000
Violation Code:	2030026 Failure of line leak detector to detect a leak and/or failure of audible and visual alarm. 23 CCR 16 2636(f)(2), 2666.
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6903785
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2022-04-13T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS ONLY
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5409617
Return To Compliance Date:	2017-12-01T00:00:00.000

NOIL USA INC. (Continued) **S113161624**

Nov:	No
Violation Classification:	Class I
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2016-04-27T12:05:00.000
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5409617
Return To Compliance Date:	2017-04-26T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2016-04-27T12:05:00.000
Violation Code:	3030010 Accumulated waste too long (>180 or 270 days) (>90 days for an acutely hazardous waste). (40 CFR 262.34(e) and (f).) HSC 25201(a); 22 CCR 66262.34(d)
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6135413
Return To Compliance Date:	2019-05-20T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2019-04-23T00:00:00.000
Violation Code:	3030007 Failed to properly label/date hazardous waste container &/or tank. 22 CCR 66262.34(f)
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6135413
Return To Compliance Date:	2019-05-20T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000

NOIL USA INC. (Continued) **S113161624**

Inspection Date:	2019-04-23T00:00:00.000
Violation Code:	3030017 Failed to properly close hazardous waste container(s). 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2), 265.173
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6903785
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2022-04-13T00:00:00.000
Violation Code:	HMD0000 UST TANK (DW/SW) - REQUIREMENT
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5409617
Return To Compliance Date:	2016-04-27T00:00:00.000
Nov:	No
Violation Classification:	Class I
Underground Storage Tank Id:	16202
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2016-04-27T12:05:00.000
Violation Code:	2030025 (RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6135413
Return To Compliance Date:	2019-05-20T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2019-04-23T00:00:00.000
Violation Code:	3030010 Accumulated waste too long (>180 or 270 days) or (>90 days). HSC 25201(a), 25123.3(h)(1); 22 CCR 66262.34(d); 40 CFR 262.34(e) and/or (f)

NOIL USA INC. (Continued) **S113161624**

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5874620
Return To Compliance Date:	2018-06-21T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2018-04-26T00:00:00.000
Violation Code:	1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5646866
Return To Compliance Date:	2017-04-27T00:00:00.000
Nov:	Yes
Violation Classification:	Not reported
Underground Storage Tank Id:	16204
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2017-04-27T21:11:00.000
Violation Code:	2030062 (RD) Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak. HSC 25299(a)(9)

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6903785
Return To Compliance Date:	2022-05-03T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	32548
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2022-04-13T00:00:00.000
Violation Code:	2030035 Failure to operate the UST system to prevent unauthorized releases including leaks, spills, and/or overfills. HSC 25292.1(a)

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank

NOIL USA INC. (Continued) **S113161624**

Inspection Type:	Routine
Inspection Number:	6903785
Return To Compliance Date:	2022-04-13T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	16201
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2022-04-13T00:00:00.000
Violation Code:	2030025 (TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch within an hour and restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5646866
Return To Compliance Date:	2019-05-17T00:00:00.000
Nov:	Yes
Violation Classification:	Class I
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2017-04-27T21:11:00.000
Violation Code:	HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. HSC 25404.1; SDCC 68.905
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5874620
Return To Compliance Date:	2019-04-23T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2018-04-26T00:00:00.000
Violation Code:	3010002 Failed to obtain &/or maintain an active EPA ID Number. 22 CCR 66262.12(a)
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4280322

NOIL USA INC. (Continued) **S113161624**

Return To Compliance Date:	2014-04-28T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2013-04-08T00:00:00.000
Violation Code:	1010005 Failure to complete and/or submit an annotated site map if required by CUPA; 19 CCR 4 2729.2(a)(3).
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5646866
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2017-04-27T21:11:00.000
Violation Code:	HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS AND LQGS
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	4280322
Return To Compliance Date:	2014-04-18T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	8791
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2013-04-08T00:00:00.000
Violation Code:	2030048 Failure to comply with one or more of the following: conduct secondary containment testing, within six months of installation and every 36 months thereafter, conducted in accordance with proper practices, protocols, or test methods. 23 CCR 16 2637
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5646866
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported

NOIL USA INC. (Continued) **S113161624**

Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2017-04-27T21:11:00.000
Violation Code:	HMD0001 RECORD KEEPING/OPERATIONAL REQUIREMENTS
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5409617
Return To Compliance Date:	2016-04-27T00:00:00.000
Nov:	No
Violation Classification:	Class I
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2016-04-27T12:05:00.000
Violation Code:	1010001 HMBP not established/ implemented. HSC 25505(a) and 25507(a)
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	4280322
Return To Compliance Date:	2013-06-01T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	87
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2013-04-08T00:00:00.000
Violation Code:	2030036 Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 16 2635(b)(2), 2665.
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5409617
Return To Compliance Date:	2016-04-27T00:00:00.000
Nov:	No
Violation Classification:	Class II

NOIL USA INC. (Continued) **S113161624**

Underground Storage Tank Id:	32548
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2016-04-27T12:05:00.000
Violation Code:	2030036 (RP) Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity; and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 2635(b)(2), 2665
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5646866
Return To Compliance Date:	2018-04-26T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	16204
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2017-04-27T21:11:00.000
Violation Code:	2030025 (RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)
Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6135413
Return To Compliance Date:	2019-05-20T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	32548
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2019-04-23T00:00:00.000
Violation Code:	2030013 (TCR 12) Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded

NOIL USA INC. (Continued) **S113161624**

to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR, 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days. 23CCR 2716 (a-e)

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6903785
Return To Compliance Date:	2022-04-13T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	16202
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2022-04-13T00:00:00.000
Violation Code:	2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6903785
Return To Compliance Date:	2022-05-03T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-06-25T01:34:57.000
Inspection Date:	2022-04-13T00:00:00.000
Violation Code:	3030010 Failed to properly dispose of hazardous waste within 180 days (or 270 days if waste is transported over 200 miles). 22 CCR 66262.34(d); HSC 6.5 25123.3(h)(1)

NOIL USA INC. (Continued) **S113161624**

UST DTL:

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	Noil USA Inc.
Tankid:	16203
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-06-25T01:34:57.000
Tank Capacityin Gallons:	20000
Tank Contents:	Diesel
Type Of Tank:	Double Wall

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	Noil USA Inc.
Tankid:	16202
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-06-25T01:34:57.000
Tank Capacityin Gallons:	15000
Tank Contents:	Premium Unleaded
Type Of Tank:	Double Wall

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	Noil USA Inc.
Tankid:	16201
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-06-25T01:34:57.000
Tank Capacityin Gallons:	20000
Tank Contents:	Regular Unleaded
Type Of Tank:	Double Wall

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-216147
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	Noil USA Inc.
Tankid:	32548
Tank Status:	Active

NOIL USA INC. (Continued) **S113161624**

Date Ust Permanently Closed: Not reported
Tank Use: 1a
Piping System Type: Pressure
Last Updated: 2022-06-25T01:34:57.000
Tank Capacityin Gallons: 5000
Tank Contents: Diesel
Type Of Tank: Double Wall

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-216147
Facility Type (Ust Facility): Motor Vehicle Fueling
Tank Owner Name: Noil USA Inc.
Tankid: 16204
Tank Status: Active
Date Ust Permanently Closed: Not reported
Tank Use: 1a
Piping System Type: Pressure
Last Updated: 2022-06-25T01:34:57.000
Tank Capacityin Gallons: 15000
Tank Contents: Diesel
Type Of Tank: Double Wall

Waste and Materials:
Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0186741
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-11-10T00:40:07.000
Chemical Name: Regular Unleaded Gasoline
Common Name: Regular Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0186742
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-11-10T00:40:07.000
Chemical Name: Supreme Unleaded Gasoline
Common Name: Supreme Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0186743
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-11-10T00:40:07.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

NOIL USA INC. (Continued) **S113161624**

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0161630
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-11-10T00:40:08.000
Chemical Name:	Waste Absorbent & Spent Dispenser Fuel Filters
Common Name:	Waste Absorbent & Spent Dispenser Fuel Filters
Case Number:	Not reported

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0161631
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-11-10T00:40:08.000
Chemical Name:	Waste Clean-up, Test Water
Common Name:	Waste Clean-up, Test Water
Case Number:	Not reported

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0288090
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2022-02-25T02:32:19.000
Chemical Name:	Unleaded Gasoline
Common Name:	Unleaded Gasoline
Case Number:	86290-81-5

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0217835
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2020-02-25T02:36:47.000
Chemical Name:	Regular Unleaded Gasoline
Common Name:	Regular Unleaded Gasoline
Case Number:	86290-81-5

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0217836
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2020-02-25T02:36:47.000
Chemical Name:	Supreme Unleaded Gasoline
Common Name:	Supreme Unleaded Gasoline
Case Number:	86290-81-5

Record ID:	DEH2012-HUPFP-216147
Permit Status:	Permit Renewed

NOIL USA INC. (Continued) **S113161624**

Active Permit: Y
Child Record Id: DEH2019-HCHEM-0217837
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-25T02:36:47.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0187874
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-25T02:36:47.000
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name: Waste Absorbent & Spent Dispenser Fuel Filters
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0187875
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-25T02:36:47.000
Chemical Name: Waste Clean-up, Test Water
Common Name: Waste Clean-up, Test Water
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0327026
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-06-25T01:34:57.000
Chemical Name: Unleaded Gasoline
Common Name: Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0327027
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-06-25T01:34:57.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0293921

NOIL USA INC. (Continued) **S113161624**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-06-25T01:34:57.000
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name: Waste Absorbent & Spent Dispenser Fuel Filters
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0293922
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-06-25T01:34:57.000
Chemical Name: Waste Clean-up, Test Water
Common Name: Waste Clean-up, Test Water
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0288091
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-02-25T02:32:19.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0256682
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-02-25T02:32:19.000
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name: Waste Absorbent & Spent Dispenser Fuel Filters
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0256683
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-02-25T02:32:19.000
Chemical Name: Waste Clean-up, Test Water
Common Name: Waste Clean-up, Test Water
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0107004
Trade Secret: N
Hazardous Material Type: Pure

NOIL USA INC. (Continued) **S113161624**

Last Updated: 2018-03-24T02:33:44.000
Chemical Name: Regular Unleaded Gasoline
Common Name: Regular Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0107005
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-03-24T02:33:44.000
Chemical Name: Supreme Unleaded Gasoline
Common Name: Supreme Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0107006
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-03-24T02:33:44.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0088253
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-03-24T02:33:44.000
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name: Waste Absorbent & Spent Dispenser Fuel Filters
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0088254
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-03-24T02:33:44.000
Chemical Name: Waste Clean-up, Test Water
Common Name: Waste Clean-up, Test Water
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0270376
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-07-25T01:01:02.000
Chemical Name: Regular Unleaded Gasoline

NOIL USA INC. (Continued) **S113161624**

Common Name: Regular Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0270377
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-07-25T01:01:02.000
Chemical Name: Supreme Unleaded Gasoline
Common Name: Supreme Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0270378
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-07-25T01:01:02.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0240484
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-07-25T01:01:02.000
Chemical Name: Waste Absorbent & Spent Dispenser Fuel Filters
Common Name: Waste Absorbent & Spent Dispenser Fuel Filters
Case Number: Not reported

Record ID: DEH2012-HUPFP-216147
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0240485
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-07-25T01:01:02.000
Chemical Name: Waste Clean-up, Test Water
Common Name: Waste Clean-up, Test Water
Case Number: Not reported

Name: 29TH STREET CACTUS OPERATING LLC
Address: 1605 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Permit Number: 216147
Business Type: 6HK28
EPA Id Number: Not reported
APN: DEH-102237
Last HMMD Inspection: 04/02/2012
Facility Telephone: 619-671-7098

NOIL USA INC. (Continued) **S113161624**

Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	DAVID SMITH-29TH STREET COMMERCIAL I,LP
Facility Mailing Address:	1605 CACTUS RD
Facility Mailing City:	SAN DIEGO
Facility Mailing State:	CA
Facility Mailing Zip:	92154
UST Owner:	DAVID SMITH - 29TH ST COMMERCIAL I, LP
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	N
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	MIXTURE
Name:	CAR WASH CONCENTRATE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL
Other Information:	UNDERGROUND TANK 102237 T003
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL
Other Information:	UNDERGROUND TANK 102237 T004
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL*
Other Information:	UNDERGROUND TANK 102237 T005
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

Permit Number:	216147
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 102237 T002

NOIL USA INC. (Continued) **S113161624**

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEAD
Other Information: UNDERGROUND TANK 102237 T001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 216147
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 216147
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: FUEL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

UST:
UST Name: UNDERGROUND TANK 102237 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED

NOIL USA INC. (Continued) **S113161624**

Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 15000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287
Capacity Gallons: 20000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 102237 T004
Last Update: 2012-11-02 14:17:38
Permit Number: 216147
Tank Type: DOUBLE WALL
Additional Id: NT2287/DSL WEST/RT3632
Capacity Gallons: 15000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-03-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A

NOIL USA INC. (Continued) **S113161624**

UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

CERS HAZ WASTE:
Name: NOIL USA INC.
Address: 1605 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 6166
CERS ID: 10395283
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: NOIL USA INC.
Address: 1605 CACTUS RD
City,State,Zip: SAN DIEGO, CA 92154
Site ID: 6166
CERS ID: 10395283
CERS Description: Underground Storage Tank

HAZNET:
Name: 1605 CACTUS INC
Address: 1605 CACTUS RD
Address 2: Not reported
City,State,Zip: SAN DIEGO, CA 921548102
Contact: DAVID SINAI
Telephone: 2132160800
Mailing Name: Not reported
Mailing Address: PO BOX 24036

Year: 2013
Gepaid: CAL000363208
TSD EPA ID: CAT080013352
CA Waste Code: 134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 1.386

Year: 2011
Gepaid: CAL000363208
TSD EPA ID: CAD981696420
CA Waste Code: 223 - Unspecified oil-containing waste
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.73055

Additional Info:
Year: 2013
Gen EPA ID: CAL000363208

Shipment Date: 20130524
Creation Date: 8/10/2013 22:15:09
Receipt Date: 20130530

NOIL USA INC. (Continued) **S113161624**

Manifest ID:	005750799FLE
Trans EPA ID:	CAT080016116
Trans Name:	NIETO & SONS TRUCKING INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	DEMENNO KERDOON
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons:	1.386
Waste Quantity:	330
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2011
Gen EPA ID:	CAL000363208
Shipment Date:	20110929
Creation Date:	12/9/2011 18:30:13
Receipt Date:	20110929
Manifest ID:	008384535JJK
Trans EPA ID:	CAD982413262
Trans Name:	EVERGREEN ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981696420
Trans Name:	EVERGREEN ENVIRONMENTAL SERVICES
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	223 - Unspecified oil-containing waste
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	1.73055
Waste Quantity:	415
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	NOIL USA INC.
Address:	1605 CACTUS RD
City,State,Zip:	SAN DIEGO, CA 92154
Site ID:	6166

NOIL USA INC. (Continued) **S113161624**

CERS ID: 10395283
CERS Description: Chemical Storage Facilities

Violations:

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-27-2016
Citation: HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507
Violation Description: Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes: Returned to compliance on 04/27/2016. Inspection Sequence ID:5409617
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-13-2022
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Description: Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes: Returned to compliance on 05/03/2022. Inspection Sequence ID:6903785
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-26-2018
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 06/21/2018. Inspection Sequence ID:5874620
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-27-2016
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release

NOIL USA INC. (Continued) **S113161624**

occurs.

Violation Notes: Returned to compliance on 04/27/2016. Inspection Sequence ID:5409617;Tank ID:16202;Violation Description:(RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-23-2019
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "
Violation Notes: Returned to compliance on 04/09/2020. Inspection Sequence ID:6135413;Tank ID:32548,16203,16204;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-08-2013
Citation: 23 CCR 16 2637 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2637
Violation Description: Failure to comply with one or more of the following: conduct secondary containment testing, within six months of installation and every 36 months thereafter, conducted in accordance with proper practices, protocols, or test methods.
Violation Notes: Returned to compliance on 04/18/2014. Inspection Sequence ID:4280322;Tank ID:8791;Violation Description:Failure to comply with one or more of the following: conduct secondary containment testing, within six months of installation and every 36 months thereafter,

NOIL USA INC. (Continued) **S113161624**

	conducted in accordance with proper practices, protocols, or test methods. 23 CCR 16 2637
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	6166
Site Name:	Noil USA Inc.
Violation Date:	04-08-2013
Citation:	19 CCR 4 2729.2(a)(3) - California Code of Regulations, Title 19, Chapter 4, Section(s) 2729.2(a)(3)
Violation Description:	Failure to complete and/or submit an annotated site map if required by CUPA.
Violation Notes:	Returned to compliance on 04/28/2014. Inspection Sequence ID:4280322
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	6166
Site Name:	Noil USA Inc.
Violation Date:	04-28-2015
Citation:	23 CCR 16 2666(c) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2666(c)
Violation Description:	Failure of line leak detector to detect a leak and/or failure of audible and visual alarm.
Violation Notes:	Returned to compliance on 04/28/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	6166
Site Name:	Noil USA Inc.
Violation Date:	04-23-2019
Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected

NOIL USA INC. (Continued) **S113161624**

by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.

Violation Notes: Returned to compliance on 05/14/2019. Inspection Sequence ID:6135413;Tank ID:32548,16201,16202,16203,16204;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the o

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-13-2022
Citation: HSC 6.7 25292.1(a) - California Health and Safety Code, Chapter 6.7, Section(s) 25292.1(a)
Violation Description: Failure to operate the UST system to prevent unauthorized releases including leaks, spills, and/or overfills.
Violation Notes: Returned to compliance on 05/03/2022. Inspection Sequence ID:6903785;Tank ID:32548,16201,16202,16203,16204;Violation Description:Failure to operate the UST system to prevent unauthorized releases including leaks, spills, and/or overfills. HSC 25292.1(a)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-08-2013
Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description: Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.
Violation Notes: Returned to compliance on 06/01/2013. Inspection Sequence ID:4280322;Tank ID:87 ,91,03,03;Violation Description:Failure of the overfill prevention system to meet one of the following requirements:

NOIL USA INC. (Continued) **S113161624**

1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 16 2635(b)(2), 2665.

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-13-2022
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "
Violation Notes: Returned to compliance on 04/13/2022. Inspection Sequence ID:6903785;Tank ID:16202;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-23-2019
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

NOIL USA INC. (Continued) **S113161624**

Violation Notes:	Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	6166
Site Name:	Noil USA Inc.
Violation Date:	04-27-2017
Citation:	HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Description:	Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.
Violation Notes:	Returned to compliance on 04/30/2017. Inspection Sequence ID:5646866;Tank ID:32548,16201,16202,16203,16204;Violation Description:Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance. HSC 25292.2, 25299.30-25299.34; 23 CCR 2711; 2808.1, 2809-2809.2
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	6166
Site Name:	Noil USA Inc.
Violation Date:	04-23-2019
Citation:	23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Description:	For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.
Violation Notes:	Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413;Tank ID:32548,16201,16202,16203,16204;Violation Description:(TCR 12) Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in

NOIL USA INC. (Continued) **S113161624**

accordance with 23 CCR, 2715(c). For designated
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-26-2018
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes: Returned to compliance on 04/23/2019. Inspection Sequence ID:5874620
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-28-2014
Citation: HSC 6.95 25503.5(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25503.5(a)
Violation Description: Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.
Violation Notes: Returned to compliance on 06/03/2014.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-27-2016
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 12/01/2017. Inspection Sequence ID:5409617;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-13-2022
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes: Returned to compliance on 04/13/2022. Inspection Sequence ID:6903785;Tank ID:16201;Violation Description:(TCR 9d) Failure of the

NOIL USA INC. (Continued) **S113161624**

line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch within an hour and restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-08-2013
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs.
Violation Notes: Returned to compliance on 06/01/2014. Inspection Sequence ID:4280322;Tank ID:87,91,03,03;Violation Description:Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-27-2017
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements:Monitor at least hourly.Be capable of detecting a release of 3.0 gallons per hour at 10 p.s.i.g. Restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes: Returned to compliance on 04/26/2018. Inspection Sequence ID:5646866;Tank ID:16204;Violation Description:(RD) Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow or product through the piping or trigger an alarm when a release occurs. 23 CCR 2636(f)(2)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-27-2017
Citation: HSC 6.7 25299(a)(9) - California Health and Safety Code, Chapter 6.7, Section(s) 25299(a)(9)
Violation Description: Leak detection equipment disabled or tampered with in a manner that

NOIL USA INC. (Continued) **S113161624**

would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak.
Violation Notes: Returned to compliance on 04/27/2017. Inspection Sequence ID:5646866;Tank ID:16204;Violation Description:(RD) Leak detection equipment disabled or tampered with in a manner that would prevent the monitoring system from detecting and/or alerting the owner/operator of a leak. HSC 25299(a)(9)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-23-2019
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description: Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes: Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-27-2016
Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Description: Failure to dispose of hazardous waste within 180 days (or 270 if waste is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.
Violation Notes: Returned to compliance on 04/26/2017. Inspection Sequence ID:5409617
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 6166
Site Name: Noil USA Inc.
Violation Date: 04-23-2019
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Description: Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes: Returned to compliance on 05/20/2019. Inspection Sequence ID:6135413
Violation Division: San Diego County Department of Env Health
Violation Program: HW

NOIL USA INC. (Continued) **S113161624**

Violation Source:	CERS,
Site ID:	6166
Site Name:	Noil USA Inc.
Violation Date:	04-27-2017
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 05/17/2019. Inspection Sequence ID:5646866;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. HSC 25404.1; SDCC 68.905
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	6166
Site Name:	Noil USA Inc.
Violation Date:	04-27-2016
Citation:	23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description:	Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.
Violation Notes:	Returned to compliance on 04/27/2016. Inspection Sequence ID:5409617;Tank ID:32548,16201,16202,16203,16204;Violation Description:(RP) Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity; and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 2635(b)(2), 2665
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	04-08-2013
Violations Found:	Yes
Eval Type:	Routine done by local agency

NOIL USA INC. (Continued) **S113161624**

Eval Notes: Inspector: Archer Veronica Inspection ID:4280322
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-23-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6135413
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-26-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5874620
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5409617
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-28-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5166669
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 05-29-2013
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5168302
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-08-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4280322
Eval Division: San Diego County Department of Env Health
Eval Program: UST

NOIL USA INC. (Continued) **S113161624**

Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-26-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5874620
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5409617
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-28-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5166669
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6611027
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-28-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5076286
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-28-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5076286
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection

NOIL USA INC. (Continued) **S113161624**

Eval Date: 04-28-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5166669
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 07-20-2020
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: "No On-site Inspection" Inspector: Kiener Michael Inspection ID:6408429
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-13-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6903785
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-13-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6903785
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-23-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6135413
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-23-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6135413
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-26-2018
Violations Found: Yes