

Appendix C
INDIVIDUAL HISTORICAL ASSESSMENT REPORT

Site Name/Facility: Reservoir Drive

Master Program Map No.: 64a

Date: January 21, 2015

Archaeologist Name: Mary Robbins-Wade

Native American Monitor Name: N/A

Instructions: This form must be completed for each target facility identified in the Annual Maintenance Needs Assessment report and prior to any work on site. Attach additional sheets as needed.

EXISTING CONDITIONS
<p>Site Conditions:</p> <p>The site of the emergency maintenance is characterized by a concrete-lined storm water channel that is 12 feet wide and 780 feet long. The channel is located on the east side of Reservoir Drive, south of Alvarado Road and north of Reservoir Lane.</p> <p>The emergency maintenance was performed with a Gradall, backhoe and skid steer on November 28, 2014. The skid steer was lowered into the channel from Reservoir Drive and pushed vegetation and sediment in the channel to central locations in the channel. Operating from Reservoir Drive, the Gradall and backhoe removed the material from the channel and loaded into dump trucks. The excavated material was taken to the Miramar landfill. Approximately 130 tons of material was removed from the channel. A vector truck was located at the downstream end of the channel to collect water and debris during maintenance.</p>
<p>Survey Methods and Date:</p> <p>Historical resources were not expected to occur within the maintenance area since it took place within a concrete-lined channel. Furthermore, equipment operated from an adjacent roadway where no historic resources would be located. Thus, no historical assessment was conducted nor required.</p>
<p>Record Search Results:</p> <p>N/A</p>
<p>Are any Native American Tribes expected to be concerned about the proposed maintenance? : Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>If yes, identify the tribe and their potential concerns?</p>
<p>Archaeological Survey Results:</p> <p>N/A</p>

