

Compostable Materials Handling Operation and Facility Inspection Report (93)

Enforcement Agency:		City of San Diego			
SWIS Facility File Number (99-xx-9999)		Inspection Date		Program Code	
37-AB-0003		8/18/2011		LEA Periodic	
Time In	10:15 AM	Time Out	12:15 PM	Inspection Time	2 hours
Facility Name			Received By		
Miramar Greenery			City Of San Diego		
Facility Location			Owner Name		
5180 Convoy Street, San Diego		92111			
Inspector			Also Present (Name)		
Jacquie Adams			C. Higgins, R. Tilaro, ESD		

THE ABOVE FACILITY WAS INSPECTED FOR COMPLIANCE WITH APPLICABLE SECTIONS OF THE DIVISION 30 OF THE PUBLIC RESOURCES CODE (PRC) AND TITLE 14 AND TITLE 27 CALIFORNIA CODE OF REGULATIONS (CCR)

<input checked="" type="checkbox"/>	No Violations or Areas of Concern	
<input type="checkbox"/>	A	Regulations
Inspection Report Comments:		
<p>During the inspection today a load from a city packer had concrete mixed in the load. Upon discovery, the staff notified the supervisor and a loader removed the debris from the feedstock pile.</p> <p>The raw mulch stock pile had a temperature reading of 137F on the south east side today. Food windrow 8F undergoing pathogen reduction had a temperature of 141F.</p> <p>Records for windrow temperatures and turning, stock pile temperature monitoring and the special occurrences log were reviewed.</p>		