



THE CITY OF SAN DIEGO

June 29, 2012

Mr. David Gibson, Executive Officer
San Diego Regional Water Quality Control Board
9174 Sky Park Court, Suite 100
San Diego, CA 92123

Attention: POTW Compliance Unit

Dear Sir:

Enclosed on CD is the 2011 Annual Receiving Waters Monitoring Report for the Point Loma Ocean Outfall as required per NPDES Permit No. CA0107409, Order No. R9-2009-0001. This report contains data summaries, analyses and interpretations of the various portions of the ocean monitoring program, including oceanographic conditions, water quality, sediment characteristics, macrobenthic communities, demersal fishes and megabenthic invertebrates, and bioaccumulation of contaminants in fish tissues.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely,

Steve Meyer
Deputy Public Utilities Director

TDS/akl

Enclosure: CD containing PDF file of this report

cc: U.S. Environmental Protection Agency, Region 9



Public Utilities Department

9192 Topaz Way • San Diego, CA 92123
Tel (858) 292-6300 Fax (858) 292-6310



