

**Pre-Project & Post-Project Photographic Survey**  
**Chollas Creek Channel Emergency Maintenance Project 2011**

**Maps 91 & 93**

**Photo Point 91-1:** Temporary dam upstream from Durant St., beginning of Map 91



BEFORE (Jan. 13, 2011 10:05am)



AFTER (Apr. 29, 2011 7:47am)

**Photo Point 91-2:** Looking downstream from the access ramp on Durant St.



\*BEFORE (Oct. 12, 2010)



AFTER (Apr. 29, 2011 7:47am)

\*Photograph from Individual Biological Assessment (IBA) Report by Rick Engineering

**Photo Point 91-3:** Looking downstream from Webster Ave. towards I-15 off-ramp



\*\*BEFORE (Sept. 1, 2010)



AFTER (Jan. 19, 2011 10:07am)

**Photo Point 91-4:** Looking upstream from Ocean View Blvd. towards I-15 off-ramp



\*BEFORE (Oct. 12, 2010)



AFTER (Apr. 29, 2011 7:54am)

\*\*Photograph from Individual Hydrologic & Hydraulic Assessment (IHHA) Report by Rick Engineering Co.

\*Photograph from IBA Report by Rick Engineering Co.

**Photo Point 91-5:** Looking downstream from Ocean View Blvd.



\*\*BEFORE (Sept. 1, 2010)



AFTER (Apr. 29, 2011 7:54am)

**Photo Point 91-6:** Looking downstream south of Ocean View Blvd.



BEFORE (Jan. 13, 2011 11:42am)



AFTER (Apr.25, 2011 12:51pm)

\*Photograph from IHHA Report by Rick Engineering Co.

**Photo Point 91-7:** Looking upstream towards Ocean View Blvd.



BEFORE (Jan. 13, 2010 11:57am)



AFTER (Apr. 25, 2011 12:46pm)

**Photo Point 91-8:** Looking downstream towards National Ave.



BEFORE (Jan. 13, 2011 11:58am)



AFTER (Apr. 25, 2011 12:46pm)

**Photo Point 91-9:** Looking downstream at end of cement-bottom channel, end of Map 91



BEFORE (Jan. 13, 2011 12:03pm)



AFTER (Apr. 25, 2011 12:41pm)

**Photo Point 91-10:** Looking upstream towards end of Map 91



BEFORE (Jan. 13, 2011 12:17pm)



AFTER (Apr. 25, 2011 12:36pm)