Pre-Project & Post-Project Photographic Survey

Chollas Creek Channel Emergency Maintenance Project 2011

Maps 91 & 93

Photo Point 91-1: Temporary dam upstream from Durant St., beginning of Map 91

BEFORE (Jan. 13, 2011 10:05am) AFTER (Apr. 29, 2011 7:47am)

Photo Point 91-2: Looking downstream from the access ramp on Durant St.

*BEFORE (Oct. 12, 2010) AFTER (Apr. 29, 2011 7:47am)

*Photograph from Individual Biological Assessment (IBA) Report by Rick Engineering

Photo Point 91-3: Looking downstream from Webster Ave. towards I-15 off-ramp

**BEFORE (Sept. 1, 2010)

AFTER (Jan. 19, 2011 10:07am)

Photo Point 91-4: Looking upstream from Ocean View Blvd. towards I-15 off-ramp



*BEFORE (Oct. 12, 2010)

AFTER (Apr. 29, 2011 7:54am)

**Photograph from Individual Hydrologic & Hydraulic Assessment (IHHA) Report by Rick Engineering Co.
*Photograph from IBA Report by Rick Engineering Co.

Photo Point 91-5: Looking downstream from Ocean View Blvd.

**BEFORE (Sept. 1, 2010)

AFTER (Apr. 29, 2011 7:54am)

Photo Point 91-6: Looking downstream south of Ocean View Blvd.

BEFORE (Jan. 13, 2011 11:42am)

AFTER (Apr.25, 2011 12:51pm)

*Photograph from IHHA Report by Rick Engineering Co.

Photo Point 91-7: Looking upstream towards Ocean View Blvd.

BEFORE (Jan. 13, 2010 11:57am)

AFTER (Apr. 25, 2011 12:46pm)

Photo Point 91-8: Looking downstream towards National Ave.

BEFORE (Jan. 13, 2011 11:58am)

AFTER (Apr. 25, 2011 12:46pm)

Photo Point 91-9: Looking downstream at end of cement-bottom channel, end of Map 91

BEFORE (Jan. 13, 2011 12:03pm)

AFTER (Apr. 25, 2011 12:41pm)

Photo Point 91-10: Looking upstream towards end of Map 91

BEFORE (Jan. 13, 2011 12:17pm)

AFTER (Apr. 25, 2011 12:36pm)