



W:\18187-B-FY18_Channel_Prioritization\GIS\Appendix_E_Culverts\Map_Janet\Map_04_2018

Legend

- Channel Area
- X City Storm Drain Structure
- City Storm Drain

Scale in Feet

North

Photos:



Assessment Results

- Channel Prioritization Score: *69.7 out of 100*
- Capacity Prior to Maintenance: *Less than 2-year storm event*
- Capacity After Maintenance (As-built Capacity) : *50-year storm event*
- Clogging Potential: *MEDIUM*
- Approximate Invasive Vegetation Coverage: *LOW*
- Surrounding Area: *Residential*
- Infrastructure Failures: *NONE*
- Site Evaluation Date: *February 22, 2018*
- Notes/Comments: *The upstream culvert is almost completely blocked by vegetation.*