



W:\18187-B-FY18\_Channel\_Prioritization\GIS\Appendix\_F\_Culverts\Map87\_Jeremiah\_04.2018

**Legend**

- Channel Area
- ⊗ City Storm Drain Structure
- City Storm Drain

Scale in Feet

North

**Photos:**



Photo 1



Photo 2



Photo 3



Photo 5



Photo 6

**Assessment Results**

- Channel Prioritization Score: 53.3 out of 100
- Capacity Prior to Maintenance: 50-year storm event
- Capacity After Maintenance (As-built Capacity): 100-year storm event
- Clogging Potential: LOW
- Approximate Invasive Vegetation Coverage: HIGH
- Surrounding Area: Residential
- Infrastructure Failures: Failed side slope
- Site Evaluation Date: February 22, 2018
- Notes/Comments: The portion of the channel near Treat street and 27th street has a dense amount of arundo and is blocking the upstream culvert.